Middleton Environmental Inc.
Environmental Consultants and Engineers

70 West Main Street, Babylon, NY 11702
(631) 321- 4300 | midenv.com

Phase I Environmental Site Assessment Report

MEI Project Number 23-0454

Property located at 3705-3727 21st Street in Long Island City, New York

July 26, 2023

Prepared for Development Site Advisors

Middleton Environmental Inc.
Environmental Consultants and Engineers

70 West Main Street, Babylon, NY 11702
(631) 321- 4300 | midenv.com

July 26, 2023

Mr. Lev Kimyagarov
Development Site Advisors
275 Madison Avenue, 16th Floor
New York, NY 10016

Re: Phase I Environmental Site Assessment Report
3705-3727 21st Street in Long Island City, NY 11101
MEI Project #: 23-0454

Middleton Environmental Incorporated (MEI), has performed a Phase I Environmental Assessment (ESA) of the above referenced property (Subject Property), in accordance with American Society of Testing and Materials (ASTM), E1527-13 and E1527-21 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process. This Phase I ESA complies with both the E1527-13 and E1527-21 standards.

We declare that to the best of our knowledge and belief, we meet the definition of Environmental Professional as defined in 40 CFR Part 312 and ASTM E 1527-21 and, we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. We have developed and performed all the appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Thank you for choosing MEI as your consultant for this project. If you have any questions, or if we can be of additional service, please contact us at (631) 321-4300.

Respectfully submitted,

Middleton Environmental Incorporated

Prepared by: John Danko
Project Manager

Reviewed by: Donald J. Middleton Jr.
President

TABLE OF CONTENTS FOR PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT (AS PER ASTM E1527-13 AND ASTM E1527-21 PROTOCOL)

1.0 EXECUTIVE SUMMARY 5

2.0 INTRODUCTION 6
2.1 Purpose 6
2.2 Scope of Services 7
2.3 Assumptions and Limitations 7
2.4 Special Terms and Conditions 8
2.5 Data Gaps 8
2.6 Deviations 8
2.7 User Reliance 8

3.0 SITE DESCRIPTION 9
3.1 Ownership and Location 9
3.2 Improvements 9
3.3 Current Use of the Subject Property 9
3.4 Services, Utilities and Roadways 9
3.5 Adjoining Property Usage 9

4.0 USER PROVIDED INFORMATION 10
4.1 Environmental Pre-Survey Questionnaire 10
4.2 Title Records 10
4.3 Environmental Liens or Activity and Use Limitation 10
4.4 Specialized Knowledge 11
4.5 Commonly Known or Reasonably Ascertainable Information 11
4.6 Valuation Reduction for Environmental Issues 11
4.7 Identification of Key Site Manager 11
4.8 Reason for Performing Phase I ESA Report 11
4.9 Prior Environmental Reports 11

5.0 RECORDS REVIEW 12
5.1 Standard Environmental Record Sources 12
5.2 Sanborn Fire Insurance Maps 17
5.3 Aerial Photographs 18
5.4 City Directories 19
5.5 Vapor Encroachment Condition 20
5.6 Local Regulatory Agency Records 20

6.0 PHYSICAL SETTING 21
6.1 Topography 21
6.2 Geology and Soils 21
6.3 Hydrogeology and Hydrology 21

7.0 SUBJECT PROPERTY RECONNAISSANCE 22
7.1 Methodology and Limited Conditions 22
7.2 Physical Observations 22

8.0 INTERVIEWS 23
8.1 Interview with Property Owner and/or Property Manager 23

9.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM PRACTICE E1527-13 and E1527-21 24
9.1 Asbestos Containing Material (ACM) 24
9.2 Lead Based Paint (LBP) 24
9.3 Lead in Drinking Water 24
9.5 Mold 25
9.6 Wetlands 25

10.0 FINDINGS, OPINIONS AND RECOMMENDATIONS 26

11.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS 26

12.0 APPENDIX 27
12.1 Site Map
12.2 USGS Topographic Map
12.3 Site Photographs
12.4 Municipal Information (Assessment Dept., Building Dept., Housing Dept., Health Dept.)
12.5 Environmental Database Report and Regulatory Agency Documentation
12.6 Historical Research Documentation (fire insurance maps, city directories, aerial photos)
12.7 Prior Environmental Reports (if any)

1.0 EXECUTIVE SUMMARY

At the request of Development Site Advisors (User), Middleton Environmental Incorporated (MEI) has performed a Phase I ESA of the property located at 3705-3727 21st Street in Long Island City, New York (Subject Property). The main objective of this ESA was to identify **Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs),** in connection with the Subject Property, as defined in ASTM Practice E1527-13 and E1527-21. This assessment has identified no evidence of CRECs or HRECs in connection with the Subject Property (any Business Environmental Risk concerns are also referenced below). This assessment has identified evidence of a REC in connection with the historic use of the Subject Property, the current condition of the Subject Property, and residual contamination associated with a former on-site spill.

The Subject Property consists of three (3) irregular-shaped parcels with an estimated area of 0.53 acres. The Subject Property is improved with four (4) 1-story slab-on grade commercial buildings. The buildings have an estimated total gross floor area of 9,032 square feet and consists of one (1) commercial tenant (Repair Guys Inc.) and two (2) vacant commercial units. A review of the New York City Building Department, Sanborn Fire Insurance Maps, and aerial photographs indicated that the Subject Property has historically consisted of auto repair/scrap yard tenants with buildings originally developed circa 1910 and 1938. A review of historic aerial photographs appear to indicate that the existing buildings (other than 3705 21st Street) were constructed circa 2004. The buildings and storage areas occupy the majority of the parcels and are bordered by landscaped areas, municipal walkways, and right-of-ways.

Below is the Assessment Summary Table presenting our recommended actions for the Subject Property. MEI's Findings and Opinions and Recommendations for further action or investigation (if any), are presented in Section 10.0.

ASSESSMENT SUMMARY TABLE			
Assessment Component	**Section(s)**	**Recommended Actions**	**Estimated Cost**
Historical Review	**5.3, 5.4 & 5.5**	**No Further Action**	
Current Occupants / Operations	**3.3**	**No Further Action**	
Hazardous Substances / Petroleum Products	**7.2**	**Phase II: investigate historic use and delineate known subsurface contamination**	**$15,000 - $20,000**
Drains, Sumps & Storm Water Drywells	**7.2**	**No Further Action**	
Storage Tanks	**7.2**	**No Further Action**	
PCBs	**7.2**	**No Further Action**	
Regulatory Agency / Database Review	**5.1**	**No Further Action**	
Vapor Encroachment Condition	**5.5**	**No Further Action**	
Asbestos Containing Materials	**9.1**	**No Further Action**	
Lead Based Paint	**9.2**	**No Further Action**	
Lead in Drinking Water	**9.3**	**No Further Action**	
Radon	**9.4**	**No Further Action**	
Mold	**9.5**	**No Further Action**	
Wetlands	**9.6**	**No Further Action**	

2.0 INTRODUCTION

2.1 Purpose

MEI has performed a Phase I ESA of property located at the Subject Property. The purpose of this Phase I ESA is to investigate and identify **RECS, CRECS, or HRECs**, as well as **de minimus conditions** and **Business Environmental Risk (BER),** associated with the Subject Property and/or surrounding property.

A REC is defined in the ASTM Standard Practice E1527-13 and E1527-21 as the following:

(1) The presence or likely presence of any hazardous substances or petroleum products in, on or at the Subject Property due to a release to the environment, (2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment or (3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment."

A CREC is defined in the ASTM Standard Practice E1527-13 and E1527-21 as the following:

A recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations)."

A HREC is defined in the ASTM Standard Practice E1527-13 and E1527-21 as the following:

A previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the subject property to any controls (for example, activity and use limitations or other property use limitations)."

ASTM E1527-13 and E1527-21 defines **de minimis condition** as the following:

A condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not RECs or CRECs.

ASTM E1527-13 and E1527-21 defines **a BER** as the following:

A Business Environmental Risk (BER) is defined as a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated as defined by ASTM.

2.2 Scope of Services

This ESA was conducted utilizing a standard of good commercial and customary practice that was consistent with the ASTM Practice E1527-13 and E1527-21. Any significant scope-of-work additions, deletions or deviations to ASTM Practice E1527-13 and E1527-21 are noted below or in the corresponding sections of this report. The scope-of-work for this assessment included an evaluation of the following:

- Physical characteristics of the Subject Property through a review of referenced sources for topographic, geologic, soils and hydrologic data.
- Subject Property history through a review of referenced sources such as land deeds, fire insurance maps, city directories, aerial photographs, prior reports and interviews.
- Current Subject Property conditions, including observations and interviews regarding the presence or absence of hazardous substances or petroleum products; generation, treatment, storage, or disposal of hazardous, regulated, or biomedical waste; equipment that utilizes oils which potentially contain PCBs; and storage tanks (aboveground and underground).
- Usage of surrounding area properties and the likelihood for releases of hazardous substances and petroleum products (if known and/or suspected) to migrate onto the Subject Property.
- Information in referenced environmental agency databases and local environmental records, within specified minimum search distances.
- Past ownership through a review of available prior reports and local municipal file review. The scope-of-work also included consideration of BERs such as the presence of asbestos-containing materials (ACM), lead-based paint (LBP), lead in drinking water, radon, mold, and wetlands.

2.3 Assumptions and Limitations

There is a possibility that even with the proper application of these methodologies there may exist on the Subject Property conditions that could not be identified within the scope of the assessment, or which were not reasonably identifiable from the available information. The information and conclusions contained in this report are based upon work undertaken by trained professional in accordance with generally accepted engineering and scientific practices current at the time the work was performed. MEI believes that the information obtained from the record reviews and site personnel interviews concerning the Subject Property is reliable. However, MEI cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete. The methodologies of this assessment are not intended to produce all-inclusive or comprehensive results, but rather to provide the User with information relating to the Subject Property. Due to the nature of this investigation and data available, MEI cannot warrant against undiscovered environmental liabilities. Should any additional information become available which differs significantly from our understanding of conditions or findings represented in this report, we request that this information be supplied (if any) to MEI so that the conclusions provided in this report may be reassessed.

The findings, opinions and conclusions of this report contain the limitations inherent in these methodologies that are referred to in ASTM E1527-13 and E1527-21. Specific limitations and exceptions to this ESA are set forth below:

Historical and environmental information pertaining to the Subject Property has been included in this report to the extent that such information is "reasonably ascertainable" as defined in the above-referenced standard practice and in accordance with the project specific timeframes.

MEI reviewed an environmental database search report. MEI's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, MEI's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the Subject Property.

With respect to conditions outside the scope of the ASTM Standard, MEI's observations are limited to physical observations and a review of published data. Unless otherwise stated, no sampling was conducted.

2.4 Special Terms and Conditions

This Phase I ESA ("the report") has been prepared to assist Development Site Advisors in its underwriting of a proposed mortgage loan, financing, or pre-acquisition environmental due diligence on the Subject Property. This report can be relied upon by only the parties stated in the transmittal letter at the front of this report. MEI's liability to a purchaser wishing to use this report is limited to the cost of the report. Amendments to MEI's limitations as stated herein that may occur after issuance of the report are considered to be included in this report. Payment for the report is made by, and MEI's contract and report extends to, Development Site Advisors only, in accordance with the Professional Service Agreement executed among Development Site Advisors and MEI and the MEI Scope of Work.

2.5 Data Gaps

A data gaps is defined ASTM Practice E1527-13 and E1527-21 as *a lack of or inability to obtain information required by this practice despite good faith efforts by the environmental professional to gather such information. Data gaps may result from incompleteness in any of the activities required by this practice, including, but not limited to, site reconnaissance (for example, an inability to conduct the site visit), and interviews (for example, an inability to interview the key site manager, regulatory officials, etc.)".*

Data Gaps are not considered to have significantly affected the ability to identify RECs, CRECs, or HRECs in connection with the Subject Property and do not alter the conclusions of this report.

2.6 Deviations

No deviations from the recommended scope of ASTM Standard E1527-13 and E1527-21 were performed as part of this Phase I ESA with the exception of any additional services noted in Section 2.2 Scope of Services.

2.7 User Reliance

This Phase I ESA is for the benefit of Development Site Advisors and this report may not be relied upon by any other person or entity without the written consent of MEI.

Only if written agreement has been executed granting the right to utilize this report, no third party which obtains all of portion of this report shall have any rights of recourse or recovery under any course of action against MEI, its officers, employees, vendors, successors, or assigns.

Reliance is provided in accordance with the Professional Service Agreement executed among Development Site Advisors and MEI and this report is for the benefit of Development Site Advisors and its successors and assigns. This report has no other purpose and may not be relied upon by any other person or entity without the written consent of MEI.

3.0 SITE DESCRIPTION

3.1 Ownership and Location

According to the records from the local Department of Finance or Department of Assessment office, the Subject Property is identified as Block 364 Lot 6, 12 & 135. The Subject Property is owned by Yardley Associates LLC.

3.2 Improvements

The Subject Property consists of three (3) irregular-shaped parcels with an estimated area of 0.53 acres. The Subject Property is improved with four (4) 1-story slab-on grade commercial buildings. A review of the New York City Building Department, Sanborn Fire Insurance Maps, and aerial photographs indicated that the Subject Property has historically consisted of auto repair/scrap yard tenants with buildings originally developed circa 1910 and 1938. A review of historic aerial photographs appear to indicate that the existing buildings (other than 3705 21st Street) were constructed circa 2004.

3.3 Current Use of the Subject Property

The buildings consist of one (1) commercial tenant (Repair Guys Inc.) and two (2) vacant commercial units..

3.4 Services, Utilities and Roadways

Street Address(es): 3705-3727 21st Street, Long Island City, New York

County: Queens

Access Roadway to site: 21st Street to the west of the Subject Property.

Electricity Provider: Consolidated Edison

Natural Gas Provider: Consolidated Edison

Potable Water: Municipal Water Supply System

Sewer Services: Municipal Sewer System

Heating System: The buildings were either not heated or heated by overhead blowers/supplemental heating units.

3.5 Adjoining Property Usage

The current use of the adjoining properties is commercial and industrial. The Subject Property borders are as follows:

North - The property is bordered to the north by a commercial building.

South - The property is bordered to the south by a commercial building.

East - The property is bordered to the east by industrial buildings.

West - The property is bordered to the west by 21st Street, a park, and a school.

4.0 USER PROVIDED INFORMATION

4.1 Environmental Pre-Survey Questionnaire

Pursuant to ASTM E1527-13 and E1527-21, MEI requested the following site information from the User of this report and from the site contact. The following section summarizes information provided Development Site Advisors with regard to this Phase I ESA.

ITEM	PROVIDED BY USER	NOT PROVIDED BY USER	DISCUSSED BELOW	DOES NOT APPLY
4.1 Environmental Pre-survey Questionnaire		X		
4.2 Title Records		X		
4.3 Environmental Liens or Activity and Use Limitation		X		
4.4 Specialized Knowledge		X		
4.5 Commonly Known or Reasonably Ascertainable Information		X		
4.6 Valuation Reduction for Environmental Issues		X		
4.7 Identification of Key Site Manager		X		
4.8 Reason for Performing Phase 1 ESA	X			
4.9 Prior Environmental Reports		X		

4.2 Title Records

Title record information associated with the Subject Property has not been provided to MEI by Development Site Advisors. Land title records provide information on previous ownership of a property. Typically, deeds signifying transfer of a land parcel are recorded in county files and can be researched to determine the identity of past owners. A "chain of title" is a continuous record of ownership for a specific parcel. A 50-year chain of title search was not included in the scope of work for this assessment.

4.3 Environmental Liens or Activity and Use Limitation

The property owner/User/key site personnel did not report any Environmental Liens or Activity/Use Limitations on the site. An environmental lien search was not included in the scope of work of this assessment and therefore was not performed. However, if the findings of a lien search performed by any other party does reveal the presence of an environmental related lien on the subject property, this information should be forwarded to MEI for review, and any significant findings will be added as an addendum to this report.

4.4 Specialized Knowledge

Development Site Advisors did not have any specialized knowledge that is material to RECs, CRECs, or HRECs at the Subject Property.

4.5 Commonly Known or Reasonably Ascertainable Information

Development Site Advisors did not have any commonly known or reasonably ascertainable information within the local community about the Subject Property that is material to RECs, CRECs, or HRECs in connection with the Subject Property.

4.6 Valuation Reduction for Environmental Issues

Development Site Advisors did not have any information regarding valuation reduction for environmental issues in connection with the Subject Property.

4.7 Identification of Key Site Manager

Development Site Advisors provided contact information for the Subject Property owner, manager and/or occupants. The Contact person for site access was Mr. Lev Kimyagarov.

4.8 Reason for Performing Phase I ESA Report

The purpose of this Phase I ESA was to identify the presence of RECs, CRECS, and HRECs, in connection with the Subject Property, as defined in ASTM Practice E1527-13 and E1527-21. This ESA was also performed to permit the User to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the "landowner liability protections," or "LLPs"). ASTM Standard E1527-13 and E1527-21 constitute "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B).

4.9 Prior Environmental Reports

Prior environmental reports were not provided for review.

5.0 RECORDS REVIEW

5.1 Standard Environmental Record Sources

Information from standard Federal and state environmental record sources was provided through EDR. Data from governmental agency lists are updated and integrated into one database, which is updated as these data are released. This integrated database also contains postal service data in order to enhance address matching. Records from one government source are compared to records from another to clarify any address ambiguities. The demographic and geographic information available provides assistance in identifying and managing risk. The accuracy of the geocoded locations is approximately +/-300 feet.

In some cases, location information supplied by the regulatory agencies is insufficient to allow the database companies to geocode facility locations. These facilities are listed under the unmappable section within the EDR report. A review of the unmappable facilities indicated that none of these facilities are within the ASTM minimum search distance from the Site. Pertinent regulatory files / records associated with the Subject Property and/or any adjoining site will be requested for review in the event the listing is associated with a facility at which a suspected or confirmed release has occurred that has not yet been closed to the satisfaction of the regulatory agency and/or if the facility represents a REC in connection with the Subject Property.

Regulatory information from the following database sources regarding possible recognized environmental conditions, within the ASTM minimum search distance from the Site, was reviewed. Specific facilities are discussed below if determined likely that a potential recognized environmental condition has resulted at the Site from the listed facilities (see appendix 12.5 for Environmental Database Report).

The following table provides a summary of the findings of the environmental database report. Specific properties identified within the database report are further discussed below.

SUMMARY OF FEDERAL, STATE, AND TRIBAL AGENCY DATABASE FINDINGS			
Regulatory Database	**Approximate Minimum Search Distance**	**Subject Property Listed**	**Off-site Listing Within Search Distance**
Federal NPL Sites	**1.0 mile**	**No**	**1**
Federal Delisted NPL Sites	**0.5 mile**	**No**	**0**
Federal SEMS Sites (formerly CERCLIS Sites)	**0.5 mile**	**No**	**0**
Federal SEMS Archive Sites (formerly CERCLIS NFRAP)	**0.5 mile**	**No**	**0**
Federal RCRA CORRACTS Sites	**1.0 mile**	**No**	**1**
Federal RCRA Generators Sites	**Property & Adjoining**	**No**	**1**
Federal RCRA Non-CORRACTS TSD Sites	**0.5 mile**	**No**	**0**
Federal Engineering / Institutional Control Sites	**Property & Adjoining**	**No**	**0**
Federal ERNS Sites	**Subject Property**	**No**	**0**
State and Tribal equivalent NPL Sites	**1.0 mile**	**No**	**14**
State and Tribal equivalent CERCLIS Sites	**0.5 mile**	**No**	**0**
State and Tribal Leaking Storage Tank Sites	**0.5 mile**	**No**	**63**
State and Tribal Spills Sites	**Property & Adjoining**	**Yes**	**2**
State and Tribal Landfill or Solid Waste Disposal Sites	**0.5 mile**	**Yes**	**3**
State and Tribal Registered Storage Tank Sites	**Property & Adjoining**	**Yes**	**1**
State and Tribal Engineering / Institutional Control Sites	**Property & Adjoining**	**No**	**0**
State and Tribal Voluntary Cleanup Sites	**0.5 mile**	**No**	**5**
State and Tribal Brownfield Sites	**0.5 mile**	**No**	**15**

- **Federal National Priority List (NPL) Sites**

The National Priorities List (NPL) is the Environmental Protection Agency (EPA) database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund Program. The Subject Property is not listed as a Federal NPL site. One (1) Federal NPL Site was identified within a mile of the Subject Property. The site is located greater than 0.125 miles from the Subject Property. Based on distance and the densely developed surrounding area, the site is unlikely to have an adverse impact on the Subject Property.

- **Federal Delisted National Priority List (NPL) Sites**

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate. The Subject Property is not listed as a Federal Delisted NPL site. No Federal Delisted NPL sites were located within a mile of the Subject Property.

- **Federal SEMS Sites (formerly CERCLIS Sites)**

The SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly known as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the SEMS List and the sites which are in the screening and assessment phase for possible inclusion on the SEMS. The Subject Property is not identified as a Federal SEMS facility. No SEMS Sites were identified within a half mile of the Subject Property.

- **Federal SEMS-ARCHIVE List (formerly CERCLIS NFRAP Sites)**

The SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the SEMS List. The Subject Property is not identified as a SEMS-ARCHIVE facility. No SEMS-ARCHIVE Sites were identified within a half mile of the Subject Property.

- **Federal RCRA CORRACTS Sites**

RCRA Corrective Action Tracking System (CORRACTS) is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information regarding sites that generate, transport, store, treat, and/or dispose of hazardous waste as defined by RCRA. The RCRA-CORRACTS database identifies Transportation, Storage or Disposal (TSD), facilities that have conducted, or are currently conducting, corrective action(s) as regulated under RCRA. The Subject Property was not identified on the RCRA CORRACTS site list. One (1) RCRA CORRACTS Site was identified within a mile radius of the Subject Property. The site is located greater than 0.125 miles from the Subject Property. Based on distance and the densely developed surrounding area, the site is unlikely to have an adverse impact on the Subject Property.

- **Federal RCRA Hazardous Waste Generators Sites**

Hazardous waste generators tracked under the Resource Conservation and Recovery Act (RCRA) are classified as either Large Quantity Generators (LQGs), Small Quantity Generators (SQGs), or Conditionally Exempt Small Quantity Generators (CESQGs). A RCRA-LQG is a facility that generates over 1,000 kilograms (Kg) of hazardous waste. A RCRA-SQG is a facility that generates between 100 Kg and 1,000 Kg of hazardous waste per month while a RCRA-CESQG generates less than 100 Kg of hazardous waste per month. The Subject Property is not listed as a Federal RCRA Hazardous Waste Generators Site. One (1) of the adjacent sites was identified as Federal RCRA Hazardous Waste Generator Sites. A west adjacent site, 37-15 13th Street, is occupied by a school and was identified as a RCRA-VSQG site with no open violations. Based on regulatory status, the type of generator, down-gradient location, and the densely developed surrounding area, the site is unlikely to have an adverse impact on the Subject Property.

- **Federal RCRA non-CORRACTS TSD Sites**

RCRA non-CORRACTS Treatment, Storage and/or Disposal (TSD) sites are required to register hazardous waste activity under the Resource Conservation and Recovery Act (RCRA). The Subject Property is not listed as a Federal RCRA non-CORRACTS TSD site. The Subject Property is not listed as a Federal RCRA non-CORRACTS TSD Site. No Federal RCRA non-CORRACTS TSD Sites were identified within a mile radius of the Subject Property.

- **Federal Engineering Control / Institutional Control Sites**

The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. Neither the Subject Property nor any of the adjoining properties were listed as a Federal Engineering Control or Institutional Control Site.

- **Federal Emergency Response Notification System (ERNS) Sites**

ERNS is a national database used to collect information regarding reported releases of petroleum products and/or hazardous substances. The database contains information from spill reports submitted to Federal agencies, including the EPA, the U.S. Coast Guard, the National Response Center, and the U.S. Department of Transportation. A review of this database was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property is not listed as a Federal ERNS site.

- **State and Tribal Equivalent NPL Sites**

State and Tribal equivalent NPL databases were searched for sites located within a mile of the Subject Property. The Subject Property is not listed as a State and Tribal Equivalent NPL Site. Fourteen (14) State and Tribal equivalent NPL Sites were identified within a mile of the Subject Property. One (1) site is located within 0.125 miles from the Subject Property. The site is not located adjacent to the Subject Property and is separated by multiple streets and other buildings. The remaining sites are located greater than 0.125 miles from the Subject Property. Based on distance and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

- **State and Tribal equivalent CERCLIS Sites**

State and Tribal equivalent CERCLIS databases were searched for sites located within a half mile of the Subject Property. The Subject Property is not listed as a State and Tribal equivalent CERCLIS Site. No State and Tribal equivalent CERCLIS sites are located within a half mile radius of the Subject Property.

- **State and Tribal Leaking Storage Tank Sites**

Leaking Storage Tank Sites are properties where releases of hazardous substances or petroleum products from underground storage tanks (USTs) and/or aboveground storage tanks (ASTs) have been identified and reported to state, tribal, or local agencies. The Subject Property is not listed as a State and Tribal Leaking Storage Tank site. Sixty-three (63) State and Tribal Leaking Storage Tank sites are located within a half mile of the Subject Property. Four (4) sites are located within 0.125 miles of the Subject Property. The four (4) sites are not located adjacent to the Subject Property and have since been remediated and the spill files closed by the NYSDEC. The remaining sites are located greater than 0.125 miles from the Subject Property. Based on distance, regulatory status, groundwater flow direction, and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

- **State and Tribal Spills Sites**

A review of the State and Tribal Spills database was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property is listed as a State and Tribal Spills Site and is identified by NYSDEC Spill Number 0230068. The release was caused by contamination of the subsurface due to the historic use of the Subject Property as an auto parts facility. The NYSDEC spill description indicated that soil borings were collected and analyzed, however, previous environmental reports were not provided for review. Analytical results indicated that there were a few VOCs and SVOCs detected in groundwater and soil below regulatory standards, and multiple heavy metals detected in soil above regulatory limits. While the spill file was closed by the NYSDEC on January 29, 2007, it appears to have been an administrative closure likely due to the presumed continued use of the Subject Property. However, the known residual contamination represents a REC. MEI recommends that a Phase II ESA be conducted to determine the extent of the remaining contamination.

Two (2) of the adjacent sites are listed as a State and Tribal Spills Site. The south adjacent site, 37-32 21st Street, is listed with a release identified during the redevelopment of the site. A southwest adjacent site 37-44 21st Street was identified with a spill caused by an equipment failure. The southwest adjacent spill has not yet been closed by the NYSDEC; however, the site is down-gradient from the Subject Property. Based on regulatory status, groundwater flow direction, and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

- **State and Tribal Landfill Sites and Solid Waste Disposal Sites**

The State and Tribal landfill and solid waste disposal site databases identify active or inactive landfill and transfer station facilities, as well as open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. The Subject Property is listed as a State and Tribal Landfill and Solid Waste Disposal Site. The Subject Property was identified as a State and Tribal Landfill Site and Solid Waste Disposal Site. The 37-25 21st Street portion of the Subject Property was identified as a vehicle dismantling facility that is inactive. While the facility is not identified with any open spills, it appears that residual contamination is present at the Subject Property due to historic use of the site (see spills above).

Three (3) State and Tribal Landfill Site and Solid Waste Disposal Sites were identified within a half mile radius of the Subject Property. Two (2) sites are located within 0.125 miles of the Subject Property; however, the sites are located down-gradient from the Subject Property and are separated by multiple streets and other buildings. The remaining site is located greater than 0.125 miles from the Subject Property. Based on distance, groundwater flow direction, and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

- **State and Tribal Registered Storage Tank Sites**

The Subject Property is listed as a State and Tribal Registered Storage Tank site. The Subject Property was identified with two (2) in-service 275-gallon ASTs, one (1) closed/removed 275-gallon AST, one (1) closed-in-place 275-gallon AST, one (1) in-service 200-gallon AST, eight (8) closed-in-place 550-gallon USTs, two (2) 4,000-gallon USTs converted to non-regulated, two (2) closed/removed 4,000-gallon USTs, one (1) closed-in-place 110 UST, one (1) out of service 180-gallon AST, and two (2) in-service 4,000-gallon USTs. While the tanks are not associated with any open spills, they likely contributed to residual contamination present at the Subject Property (see spills above).

One (1) adjacent site was identified as a State and Tribal Registered Storage Tank Site. A west adjacent site, 37-15 13th Street, was identified with two (2) closed/removed 7,500-gallon ASTs. The tanks are not associated with any open spills. Based on regulatory status, the site is unlikely to have an adverse impact on the Subject Property.

- **State and Tribal Engineering Control / Institutional Control Sites**

The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. The Subject Property was not listed as a State Engineering Control or Institutional Control Site. None of the surrounding properties were listed as a State Engineering Control or Institutional Control Site.

- **State and Tribal Voluntary Cleanup Sites**

The Subject Property is not listed as a State and Tribal Voluntary Cleanup site. Five (5) State and Tribal Voluntary Cleanup sites were identified within a half mile radius of the Subject Property. The sites are located greater than 0.125 miles from the Subject Property. Based on distance and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

- **State and Tribal Brownfield Sites**

The Subject Property is not listed as a State and Tribal Brownfield site. Fifteen (15) State and Tribal Brownfield Sites were identified within a half mile radius of the Subject Property. The sites are located greater than 0.125 miles from the Subject Property. Based on distance and the densely developed surrounding area, the sites are unlikely to have an adverse impact on the Subject Property.

5.2 Sanborn Fire Insurance Maps

Historical fire insurance maps depicting the Subject Property were reviewed and are summarized in the following table. Copies of available fire insurance maps are presented in Appendix 12.6.

FIRE INSURANCE MAP SUMMARY		
Year	**Issues Noted**	**Observations**
1898 – 1915	**No**	**Subject Property: The 1898 and 1915 Sanborn Maps show the Subject Property as several vacant lots.**
		Surrounding Area: The 1898 and 1915 Sanborn Maps show the surrounding properties as several vacant lots.
1936	**No**	**Subject Property: The 1936 Sanborn Map shows the Subject Property as developed with the 3705-3707 portion of the Subject Property and a single-story building with a scrap iron yard.**
		Surrounding Area: The 1936 Sanborn Map shows the surrounding area as vacant lots, filling stations, and an industrial building with a buried gasoline tank.
1947	**No**	**Subject Property: Conditions of the Subject Property are similar to those shown on the 1936 Sanborn Map. However, other small structures are now shown on the Subject Property. The Subject Property is labeled as an auto recking/auto repair facility.**
		Surrounding Area: Conditions of the surrounding properties are similar to those shown on the 1936 Sanborn Map. However, the north adjacent site has been developed with an industrial building and the east adjacent gasoline tank is no longer shown.
1950	**No**	**Subject Property: Conditions of the surrounding properties are similar to those shown on the 1947 Sanborn Map. However, a portion of the Subject Property is now labeled as a lumber yard.**
		Surrounding Area: Conditions of the surrounding properties are similar to those shown on the 1947 Sanborn Map. However, the west adjacent site is now shown as a school.
1970-1980	**No**	**Subject Property: Conditions of the surrounding properties are similar to those shown on the 1950 Sanborn Map. However, the buildings on the southern portion of the Subject Property have been demolished (1980).**
		Surrounding Area: Conditions of the surrounding properties are similar to those shown on the 1950 Sanborn Map.
1985-2006	**No**	**Subject Property: Conditions of the surrounding properties are similar to those shown on the 1980 Sanborn Map.**
		Surrounding Area: Conditions of the surrounding properties are similar to those shown on the 1980 Sanborn Map.

5.3 Aerial Photographs

Historical aerial photographs may be used to evaluate changes in land use and to identify visible areas of potential environmental concern. A search for historical aerial photographs depicting the Subject Property and vicinity was conducted by researching available historical aerial photographs from historicalaerials.com and other available resources. Aerial photographs depicting the Subject Property were reviewed and are summarized in the following table:

AERIAL PHOTOGRAPH SUMMARY		
Year	**Issues Noted**	**Observations**
1954	**No**	**Subject Property: The 1954 aerial photograph appears to show the Subject Property developed with some of the existing buildings. The majority of the Subject Property appears to be auto storage/wreckage.**
		Surrounding Area: The 1954 aerial photograph appears to show the surrounding area as developed with industrial and commercial buildings, and a school.
1966-1974	**No**	**Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1954 aerial photograph.**
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1954 aerial photograph.
1980 – 1984	**No**	**Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1974 aerial photograph.**
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1974 aerial photograph.
1995	**No**	**Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1984 aerial photograph.**
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1984 aerial photograph.
2004	**No**	**Subject Property: The 2004 aerial photograph appears to show the Subject Property as developed with the existing central and southern buildings.**
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1995 aerial photograph.
2006 – 2019	**No**	**Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 2009 aerial photograph.**
		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 2009 aerial photograph.

5.4 City Directories

Street directories are commercial publications containing names and addresses, and in many cases, occupations of the occupants of a particular community. The directories may also contain information pertaining to business processes conducted within a community. A search for historical street directories was conducted by MEI and EDR. Historical street directories were reviewed and are summarized in the following table. Copies of the street directories are presented in Appendix 12.6.

CITY DIRECTORY SUMMARY		
Year	**Issues Noted**	**Occupants**
1934	Yes	Burkerts Welding & Auto Repairs Frank Burket Arnold Olsen, Gray Lyman Gertrude lab, How es Elizabeth, Weinman Wm prod w kr
1939	Yes	Barts Auto Wrecking L, Chalson Bros used car parts
1945	Yes	Chalson Bros Inc Used Car Parts
1962	Yes	Bartlett Raymond C auto repairs, Eddies Body & Fender Work
1967	Yes	Eddies Auto Body & Fender Works Inc, Benl Auto Parts, Genl Auto Wreckers
1970	Yes	LIC Auto Parts Inc, Eddies Auto Body & Fender Works Inc, Genl Auto Parts, Genl Auto Wreckrs
1976	Yes	Bell Body & Fender Inc, Eddies Auto Body & Fender Works Inc
1983	Yes	Eddies Auto Body & Fender Works Inc, GETS EL EL Automotive Co Inc
1991	Yes	Highway Auto Service Center, Eddies Auto Body & Fender Works Inc, GETS El El Automotive Co Inc
1992	Yes	Eddies Auto Body & Fender Works Inc, Get Sel El Automotive Co Inc
1995	Yes	J K Auto Glass, J P Auto Salvage LTD
2000	Yes	City Used Auto Parts Incorporated, City Used Tires
2005	Yes	J K Auto Glass, Long Island City Used Auto Parts, New TJ Motor Inc, Pak Land Auto Repair & Body Shop Inc
2010	Yes	New London Auto Electric Inc, Vista Auto Center Inc, M & N, Mag Taxi Management, Qazi World Auto Parts Inc, Ricky Auto Alarm Elect Inc, Sonali Auto repair Inc, Time Collision Auto Shop, H A Transportation Inc, Rana Auto Repair
2014	Yes	All in One Automobile Repair, New Apna Automobile Repair Incorporation
2017	Yes	Repair Guys Inc, Azuay Auto Repair Co, Qazi & Sons Used Parts Inc, 21st Auto Repair, New Tarek Automobile Repair, Rana Automobile Repair
2020	Yes	Repair Guys Inc, Prime Cars Inc, Shimulauto Repair Glass & Tire, Molla Auto Sales, Qazi & Sons Inc

Based on a review of available City Directories historical uses of concern were identified at adjoining properties. However, off-site contamination at the Subject Property would likely be remediated by the responsible party and not the Subject Property. The historic use of the Subject Property as an auto wrecking facility represents a REC.

5.5 Vapor Encroachment Condition

All readily ascertainable information including all applicable Federal, State, Tribal and local database information, historical usage information, soil and groundwater sources and information from the site reconnaissance were reviewed in order to determine if there is a possibility of a Vapor Encroachment Condition regarding the Subject Property. Based upon the results of the site reconnaissance and review of readily ascertainable information, the Vapor Encroachment Condition survey is described below:

POTENTIAL AREA OF CONCERN	RESULT
Does the Subject Property have a current or past contamination concern?	**Yes**
Does the Subject Property have a suspected contamination concern?	**None identified**
Does an adjoining property have a current or past contamination concern?	**Closed NYSDEC Spill site**
Does a nearby property have a have a current or past contamination concern which may impact the Subject Property?	**Closed NYSDEC Spill Sites**
Does a regional groundwater contamination concern exist beneath the Subject Property?	**None identified**
Does there exist the possibility for vapor intrusion on the Subject Property?	**None identified**

Based upon this information, there is concern for a vapor encroachment condition (VEC) with regard to the Subject Property based on residual contamination in the subsurface.

5.6 Local Regulatory Agency Records

Local municipal offices consulted during the completion of this assessment included the New York City Building Department, the New York City Department of Finance and the New York City Fire Department. Information was reviewed in order to determine the possibility of documented adverse environmental conditions, violations or complaints associated with the Subject Property.

New York City Building Department and New York City Department of Finance

MEI reviewed information listed in the online NYC Building Information System (BIS) provided by the New York City Building Department's website, as well as information from the New York City Department of Finance website, Automated City Register Information System (ACRIS), http://a836-acris.nyc.gov/CP. Specific information provided by these websites includes lot sizes and dimensions, building zoning and usage. These websites also include information pertaining to interior renovations, building improvements and approximate date of construction. The information provided by New York City Department of Finance and New York City Department of Buildings (NYCDOB) did not identify any conditions or reported events that would indicate the presence of a recognized environmental condition.

New York City Fire Department

MEI reviewed information provided by the New York City Fire Department (NYCFD). Specific information obtained from the NYCFD includes any active and/or voided storage tank permits for the Subject Property. A review of the NYCFD storage tank files did not identify any "active" tank accounts at the Subject Property.

6.0 PHYSICAL SETTING

6.1 Topography

The Subject Property and vicinity characteristics listed below were analyzed utilizing a current USGS 7.5 Minute Topographic Map. This information is useful in determining the grade and topography of the Subject Property. The Subject Property is located at an elevation of approximately 17 feet above mean sea level (msl). The topography of the Subject Property is relatively flat and there were no slopes, depressions or rolling hills observed on the Subject Property and slopes on the Subject Property range from 0 to 3 percent.

6.2 Geology and Soils

No bedrock outcroppings were observed at the Subject Property. Near-surface geology in heavily developed areas such as the Subject Property and vicinity is considered "urban land" and is characterized by a non-homogeneous distribution of soil and fill types. Excavation and backfilling for building foundations, utility conduits, subway systems and other construction results in a varied subsurface profile. In this setting, estimation of local subsurface parameters such as permeability, moisture content, and organic fraction is not feasible without site-specific testing data.

6.3 Hydrogeology and Hydrology

No natural surface water bodies were identified on or adjoining to the Subject Property. The nearest surface water body is the East River to the west of the Subject Property.

Local groundwater gradient is expected to follow surface topography. Groundwater flow near the Subject Property is expected to flow west toward the East River. Groundwater depths and flow gradients are best evaluated by a subsurface investigation involving the installation of at least three (3) groundwater monitoring wells and precise measurements of hydrostatic pressure.

7.0 SUBJECT PROPERTY RECONNAISSANCE

The Subject Property reconnaissance was conducted by Mr. Thomas Greer, Environmental Inspector, on July 1, 2023. All proper measures were taken by MEI personnel during the site inspection to limit any Covid-19 or other exposures.

7.1 Methodology and Limited Conditions

The Subject Property reconnaissance consisted of observations of the Subject Property and improvements, adjoining properties as viewed from the Subject Property boundaries, and the surrounding area based on observations made from adjoining public thoroughfares. Building exteriors were observed along the perimeter from the ground, unless described otherwise. The commercial space, storage yard, and former vehicle dismantling lot and common areas were observed during inspection.

7.2 Physical Observations

- **Underground Storage Tanks**

  MEI did not observe any fill ports or vent pipes associated with any underground storage tanks in accessible areas of the Subject Property.

- **Aboveground Storage Tanks**

  MEI observed two (2) 275-gallon waste oil ASTs and an exterior waste oil AST in accessible areas of the Subject Property. The tanks showed no signs of chemical or petroleum staining or leakage at the time of inspection.

- **Hazardous Substances and Petroleum Products**

  MEI observed several containers of motor oil, waste oil, and general auto repair/maintenance materials in accessible areas of the Subject Property. The containers showed no signs of chemical or petroleum staining or leakage (other than what is noted below) at the time of inspection.

- **Non-Hazardous Substances and Non-Petroleum Products**

  MEI did not observe any non-hazardous substances or petroleum products in accessible areas of the Subject Property.

- **Unidentified Substances Containers**

  MEI did not observe any unidentified substance containers in accessible areas of the Subject Property.

- **Drains or Storm Water Drywells**

  MEI observed several floor drains in accessible areas of the Subject Property. The drains showed no signs of chemical or petroleum staining or leakage at the time of inspection. MEI did not observe any storm water drywells in accessible areas of the Subject Property.

- **Polychlorinated Biphenyls (PCB's)**

  MEI did not observe any PCB-containing equipment in accessible areas of the Subject Property.

- **Stains or Corrosion**

  MEI did not observe any stains or corrosion in accessible areas of the Subject Property.

- **Odors**

  MEI did not observe any strong, pungent or noxious odors in accessible areas of the Subject Property.

- **Pools of Liquid**

  MEI observed pools of unidentified liquid in accessible areas of the Subject Property. The excessive leakage and poor condition of the Subject Property, along with the historic use, represents a REC. MEI recommends that a Phase II ESA be conducted to determine if the historic use of the Subject Property has adversely impacted the subsurface (more than what is already known as described in section 5.0 above).

- **Stressed Vegetation**

  MEI did not observe any stressed vegetation in accessible areas of the Subject Property.

- **Stained Soil or Pavement**

  MEI observed excessive staining throughout the Subject Property. See above for Phase II ESA recommendations.

- **Wells**

  MEI did not observe any irrigation wells or groundwater monitoring wells in accessible areas of the Subject Property.

- **Sumps, Pits, Ponds or Lagoons**

  MEI did not observe any sumps, pits, ponds, or lagoons in accessible areas of the Subject Property.

- **Waste Water**

  MEI did not observe any improper disposal of waste water into drains, ditches or streams in accessible areas of the Subject Property.

- **Solid Wastes Disposal**

  All solid wastes generated on-site are carted away by a licensed waste hauler to an approved solid waste facility and are not disposed at on-site.

8.0 INTERVIEWS

8.1 Interview with Property Owner and/or Property Manager

A building representative was interviewed as part of the site reconnaissance. The representative did not indicate the presence of any environmental liens or was unaware of any contamination concerns regarding the Subject Property.

9.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM PRACTICE E1527-21

The following section addresses environmental issues or conditions that are not included in CERCLA's definition of hazardous substances (42 U.S.C. §9601(14)), or that do not otherwise present potential CERCLA liability at a Subject Property and are outside the scope of ASTM E1527-21. Any identified issues or conditions noted below are considered BERs.

9.1 Asbestos Containing Material (ACM)

Asbestos is a term used to describe a group of six naturally occurring crystalline fiber minerals. Asbestos has excellent thermal stability, a high degree of tensile strength, and has been used extensively in the textile, insulation, and building industries, particularly as a component in fireproofing, decorative coatings, insulation materials, and as reinforcement for plaster binders in building products. Asbestos-containing building materials are generally classified as friable or non-friable. Friable ACM are those which can be crumbled, pulverized, or reduced to powder by hand pressure, or by normal use or maintenance can be expected to emit asbestos fibers into the air. Non-friable ACM is a potential concern if it is damaged by maintenance work, demolition, or other activities, at which time it may be considered friable. It should be noted that the limited visual screening survey conducted under the scope of work for this assessment does not constitute a full asbestos inspection, in which all areas of the building would have been thoroughly surveyed and sampled. There were no signs of friable ACM observed in accessible areas of the Subject Property.

9.2 Lead Based Paint (LBP)

Use of lead in household paint was banned by the U.S. Environmental Protection Agency (EPA) effective January I, 1978. The EPA and the U.S. Department of Housing and Urban Development (HUD) consider lead based paint as containing a lead concentration equal to or greater than 1.0 milligram per square centimeter (mg/cm') or 0.5% lead by weight, as defined by Title X of the 1992 Housing and Community Development Act.

MEI observed that the painted surfaces inside the accessible areas of the building were in good condition, free of obvious flaking or chipping. A review of the New York City Department of Housing Preservation and Development's (NYCHPD) Code Enforcement Database indicated that there are no open lead-based paint violations associated with the Subject Property.

9.3 Lead in Drinking Water

Lead has historically been used in pipes, solder, and brass fixtures used in water distribution systems and building plumbing systems. In 1986, the USEPA banned the use of lead at concentrations exceeding 0.2% lead in solder and 8% lead in other plumbing materials. Lead in drinking water results primarily from corrosion of lead containing materials in service lines or from corrosion of lead containing materials in building plumbing such as lead solder, brass, bronze, and other lead containing alloys. The USEPA Action Level for lead in public drinking water supplies is 0.015 parts per million (ppm) or 0.015 milligrams per liter (mg/L). MEI did not observe any brass or lead fixtures at the Subject Property. The Property is connected to the municipal water supply provided by the City of New York and is managed by the City of New York Department of Environmental Protection (NYCDEP). According to the New York City Drinking Water Supply and Quality Report (available online from the City of New York at http://www.nyc.gov/html/dep/pdf/wsstate16.pdf), drinking water supplied to the Property is compliant with state and federal standards, including those for lead and copper. Of note, MEI did not conduct sampling of drinking water at the Property for the potential presence of lead.

9.4 Radon

Radon is a colorless, odorless, radioactive gas. Radon comes from the natural decay of uranium that is found in nearly all soils. Radon typically moves through the ground and into building through cracks and openings in the foundation. The USEPA has developed a "Map of Radon Zones" indicating the levels of radon concentrations from testing and aerial surveys conducted in all counties in New York State. The U.S. Environmental Protection Agency's Map of Radon Zones identified the Subject Property as a radon zone Level 3. Level 3 signifies that the average predicted radon level indoors is less than 2 pico-Curies per liter, and this is the lowest level in the state. This level compares favorably with the EPA action level of 4.0 pico-Curies per liter as the guideline (it should be noted that current radon information and EPA Action Levels are designated for residential spaces only and commercial and industrial facilities are not subject to EPA's Action Level of 4 pico-Curies per liter as the guideline and definitive information concerning radon gas in an individual building can only be obtained through long term testing).

9.5 Mold

Molds are a class of fungi and have been found to cause a variety of health problems in humans, including allergic, toxicological, and infectious responses. Molds are decomposers of organic materials and thrive in humid environments. As such, interior areas of buildings characterized by poor ventilation and high humidity are the most common locations of mold growth. Building materials including drywall, wallpaper, baseboards, wood framing, insulation and carpeting often play host to such growth.

As part of this assessment, MEI performed a limited visual inspection for the conspicuous presence of mold. MEI observed the accessible interior areas of the Subject Property structure(s), including interior walls and ceilings of the building for the presence of conspicuous mold or observed water intrusion or accumulation. This evaluation did not include a review of pipe chases or areas behind enclosed walls and ceilings. MEI did not observe conspicuous visual or olfactory indications of the presence of mold, nor did MEI observe obvious indications of significant water damage inside the accessible areas of the Subject Property.

9.6 Wetlands

MEI reviewed available information regarding wetlands on the Subject Property, including National Wetlands Inventory online GIS mapping. MEI additionally made general site observations for readily observable potential wetland characteristics. MEI did not observe surface water bodies or any evidence of potential wetlands on or adjoining to the Subject Property.

10.0 FINDINGS, OPINIONS AND RECOMMENDATIONS

MEI has performed this Phase I ESA of the Subject Property in conformance with the scope and limitations of ASTM Standard E1527-13 and E1527-21. This assessment has identified no evidence of CRECs or HRECs in connection with the Subject Property. This assessment has identified evidence of a REC in connection with the historic use of the Subject Property, the current condition of the Subject Property, and residual contamination associated with a former on-site spill.

The site reconnaissance, interviews and review of records have found the presence or possible presence of hazardous substances or petroleum related products in, on, or at the Subject Property due to any release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment. The Subject Property has historically been occupied by an auto repair/auto wrecking facility that was identified with a closed spill with known residual contamination. NYSDEC spill description indicated that soil borings were collected and analyzed, however, previous environmental reports were not provided for review. Analytical results indicated that there were a few VOCs and SVOCs detected in groundwater and soil below regulatory standards, and multiple heavy metals detected in soil above regulatory limits. While the spill file was closed by the NYSDEC on January 29, 2007, it appears to have been an administrative closure likely due to the presumed continued use of the Subject Property. However, the known residual contamination represents a REC. Furthermore, excessive staining and leakage of auto repair materials and equipment was observed during the site inspection. MEI recommends that a Phase II ESA be conducted to delineate the known existing contamination and to determine if further contamination has occurred due to poor maintenance and housekeeping of the site.

Lastly, no BERs or conditions outside of ASTM E1527-13 and E1527-21 were identified in connection with the Subject Property.

11.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS

This Phase I ESA Report documents the research methodology used by qualified environmental professionals of MEI to identify recognized environmental conditions using the scope and limitations of ASTM Standard E1527-13 and E1527-21.

Middleton Environmental Incorporated



Prepared by: John Danko
Project Manager

Reviewed by: Donald J. Middleton Jr.
President

12.0 APPENDIX

12.1 Site Map

3705-3727 21st Street
Long Island City, New York

12.2 USGS Topographic Map

3705-3727 21st Street
Long Island City, New York



12.3 Site Photograph (1940)



12.3 Site Photograph (1940)



12.3 Site Photograph (1940)

12.3 Site Photographs

Unidentified Pool of Liquid

275-gallon AST



275-gallon AST



Floor Drain

Vacant Commercial Space

Former Vehicle Dismantling Yard

Unidentified Pool of Liquid

Vacant Area

Storage Area and Stained Ground

55-gallon Drum and Waste Oil Container



Vacant Area

Occupied Commercial Space

12.3 Site Photographs (Borders)

The current use of the adjoining properties is commercial and industrial. The Subject Property borders are as follows:

North - The property is bordered to the north by a commercial building.

South - The property is bordered to the south by a commercial building.

East - The property is bordered to the east by industrial buildings.

West - The property is bordered to the west by 21st Street, a park, and a school.

Border to the North

Border to the South



Border to the East

Border to the West

12.4 Municipal Information (Assessment Department, Building Department, Housing Department, Health Department, etc.)

Sarah Heyne
Phone: (631) 321-4300
sarahh@midenv.com

Property Report by PropertyShark.com, for:

37-07 21st St, Long Island City, NY 11101

General

1. Overview

Address

Primary address	**37-07 21st St**
Alternate address(es)	**37-05 21st St**
Zip code	**11101**
Neighborhood	**LIC**
Borough	**Queens**
Block & lot	**00364-0012**

Owner

Name	**Yardley Associates, LLC**
Address	**1008 Cedar Park Dr Cedar Park, TX 78613**
Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

Property Taxes

Tax class	**4**
Property tax	**$33,870**

Lot

Lot sqft	**7,886**
Lot dimensions	**177 ft x 95 ft**
Ground elevation	**15 ft**
Corner lot	**No**

Zoning

Zoning districts	**M1-3**
Zoning map	**9b**
Qualified opportunity zone	**Yes (map)**

Building

Building class	**Auto Body/Collision or Auto Repair (G2)**
Square feet	**3,600**
Building dimensions	**150 ft x 24 ft**
Buildings on lot	**2**
Stories	**1**
Roof height	**12 ft**
Year built	**1910**
Year last altered	**2003**
Structure type	**Auto representation shop**
Construction type	**Light metal**
Grade	**D**

Use

Commercial units	**3**
Garage sqft	**3,600**

Floor Area Ratio (FAR)

Commercial FAR	**5**
Facility FAR	**6.5**
FAR as built	**0.46**
Allowed usable floor area	**39,430**
Usable floor area as built	**3,628**
Unused FAR	**35,802**

Violations

DOB violations	**9**
ECB violations	**1**

2. Photos

Uploaded in November, 2016 by Joe Strini

3. Maps



Community district	**1**	Closest police station	**0.77 Miles**
School district	**30**	Closest fire station	**0.14 Miles**
Census tract	**33**	Tax map	**40302**
Lat long	**40.75817, -73.93807**	Sanborn map	**401 080**

Contacts

1. Real Owners

For LLC-owned properties, our team manually researches who is the owner behind the LLC and verifies phone numbers. When the owner of a property is an individual, an algorithm extracts the best matching phone numbers from multiple sources. **Our research team is in the process of verifying all phone numbers to make sure they reach the right person.**

We have a verified phone number for the owner of this property. One of our researchers called the number and confirmed it reaches the owner.

Upgrade

Name

Address

Phone

Verified personal number

E-mail

to unlock Real Owners and their phone numbers.

2. Registered Owner

Yardley Associates, LLC
1008 Cedar Park Dr
Cedar Park, TX 78613
Source: Assessment Roll
Last recorded: 12/17/2022

Add to address book

Ownership data is aggregated from governmental sources like deeds and the assessment roll. If the registered owner is an LLC or other form of company, use our Real Owners service to find the person behind the company.

3. Contacts from Building Permits

Registration date	Role	Name	Address	Phone number	Email
05/16/2006	Owner	R G Lupo Realty	37-07 21 Street Long Island City, NY 11101		
05/16/2006	Applicant	Mohammad A Hossain			
05/16/2006	Applicant	Mohammad Hossain			
05/16/2006	Owner	R G			
05/16/2006	Superintendent	Sixto Gavilanes Goldsmith Construction & Associa			
05/16/2006	Applicant	Sixto Gavilanes Goldsmith Construction & Associa		(718) 321-2947	
05/16/2006	Owner	R G Lupo Realty			

Valuation

1. Last Sale

Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

2. Assessment History

Year	Building class	Market value	Assessed value	Taxable	Tax rate%	Base tax	Property tax
2022/23	G2	$674,000	$303,300	$303,300	10.646%	$32,289	$32,289
2021/22	G2	$562,000	$252,900	$252,900	10.755%	$27,199	$27,199
2020/21	G2	$723,000	$325,350	$307,440	10.694%	$32,878	$32,878
2019/20	G2	$722,000	$324,900	$295,380	10.537%	$31,124	$31,124
2018/19	G1	$697,000	$313,650	$282,780	10.514%	$29,731	$29,731
2017/18	G1	$650,000	$292,500	$269,730	10.514%	$28,359	$28,359
2016/17	G1	$624,000	$280,800	$256,230	10.574%	$27,094	$27,094
2015/16	G2	$589,000	$265,050	$239,940	10.656%	$25,568	$25,568
2014/15	G9	$582,000	$261,900	$234,270	10.684%	$25,029	$25,029
2013/14	G9	$552,000	$248,400	$221,580	10.323%	$22,874	$22,874
2012/13	G9	$500,000	$225,000	$204,570	10.228%	$20,923	$20,923
2011/12	G9	$443,000	$199,350	$192,240	10.152%	$19,516	$19,516
2010/11	G9	$526,000	$236,700	$181,620	10.312%	$18,729	$18,729
2009/10	G9	$441,000	$198,450	$162,810	10.426%	$16,975	$16,975
2008/09	G9	$363,000	$163,350	$148,770	10.241%	$15,236	$15,236

Documents

1. Title Documents

Export to Excel (7 records)

Date	Type	Amount	Party 1	Party 2	Doc image
01/01/2016 - D 05/10/2017 - R	Both RPTT and RETT (2017042800882005) - **M**		Lupoli Virginia 120 Beach Mountain Cove Georgetown TX 78633 Lupoli Peter 904 Skyview Drive Santa Barbara CA 93108	Lupoli Holdings Partnership 1333 Shore District Drive Apt 1653 Austin TX 78741	
02/28/2008 - D 04/10/2008 - R	Deed (2008040300634001)		Lupoli Peter N 2439 Whitney Avenue Summerland CA 93067	Yardley Associates LLC 4 Pam Lane Huntington NY 11743	
10/11/1984 - R	Deed (4080002048508)		MC Nallydonald F(admof	Esposito Vincent(exof)	
10/11/1984 - R	Deed (4070002048507)		Esposito Phyllis	Lupoli Peter N	
10/11/1984 - R	Power of attorney (4060002048506) - **M**		Ningard Dorothy L Heaton Dorothy Fka	Heaton Eugene E JR	
06/08/1977 - R	Mortgage (37740099200596)		Esposito Vincent	Donald F McNally	
06/08/1977 - R	Deed (37740099200592)		McNally Donald F (Individuall Devisee)	Vincent Esposito	

R: Record date
D: Document date

2. Liens

Export to Excel (1 record)

Active	Effective date	Expiration date	Document type	Creditor	Amount	Details
Yes	12/22/2022	12/22/2023	Mechanics lien	Big Apple Group NY LLC	$2,050	

Financials

1. Mortgage Summary

No active mortgages for this property.

to unlock the property's mortgage balance, maturity date, interest rate and much more.

Occupancy

1. Phone Records of Residents

Name	Unit	First seen	Phone number
Shimulauto Repair Glass & Tire		2016	(917) 600-2528

2. Businesses

Entity	Contact	Phone number	Email	Website
Autocraft Industrial CORP. 3707 21st St Long Is City, NY 11101		(718) 606-1767		
Kim, Chong Uk DBA J K Auto Glass 3707 21st St Long Is City, NY 11101		(718) 937-2626		
London Auto Electric INC. 3705 21st St Long Is City, NY 11101		(917) 518-5018		
New London Tire Shop, INC. 3705 21st St Long Is City, NY 11101		(718) 361-8611		
Pak Gujrat Automotive INC 3705 21st St Long Island City, NY 11101		(718) 786-4266		
Repairguys INC 3707 21st St Long Island City, NY 11101		(718) 707-0475		
Shimul INC. 3707 21st St Long Is City, NY 11101		(917) 600-2528		
Vista Auto Center INC. 3705 21st St Long Is City, NY 11101		(718) 786-8580		

Taxes

1. Tax Bill

Property tax bill for 7/1/2023 to 6/30/2024	**$33,870**

2. Key Values in Calculating the Bill

Tax class	**4**
Market value	**$854,000**
Assessed value	**$384,300**
Exemptions granted by city	**$0**
Transitional value	**$318,150**
Transitional exemption value	**$0**
Tax abatements	**$0**

3. Assessed Value Evolution

The state law requires to phase in any changes to the assessed value over a five-year period. In any given year, multiple transitions are being applied to the property, which result in different assessed and transitional values each year. The law requires the use of the lowest value between the two - assessed or transitional - to calculate the property tax bill. For this property, the transitional value has reached the assessed value.



4. Property Tax Calculation

Market Value

The first step is for the City Assessor to determine the *market value* of the property. While the term *market value* would seemingly refer to how much the property would sell for on the open market, in reality the *market value* established by the City Assessor is almost always substantially lower.

Land market value		$473,000
Building market value	+	$381,000
Market value	**=**	**$854,000**

Assessed Value

Next, the market value is used to compute the assessed value, which is a percentage of the market value. The exact percentage is determined by the tax class of the property. Tax class 1 is assessed at 6% of the market value, and tax classes 2,3 and 4 are assessed at 45%.

Market value		$854,000
Assessment ratio	x	45%
Maximum assessed value	**=**	**$384,300**

Transitional Value

To protect property owners from sudden large increases in property tax, the state limits how quickly the city can increase the assessed value. Typically these limits are applied when the City Assessor makes a big increase to the market value. Without the limits the assessed value would increase by a similar percentage. Instead, the change to the assessed value is phased in over a number of years.

The market value of this property was increased in previous years and the assessed value is currently being phased in. Because this property is in **tax class 4**, the assessment cannot be raised more than 8% from the year before or 30% over five years. Assessed value cannot be raised more than 45% from market value.

Assessed value		$384,300
Exemptions granted by city	-	$0
Net assessed value	**=**	**$384,300**

Transitional value		$318,150
Transitional exemption value	-	$0
Transitional net value	**=**	**$318,150**

Taxable Value

The *taxable value*, for 23/24, is the smaller of the city's net assessed value and the transitional net assessed value.

Taxable value	=	$318,150

Property Tax

Current tax is calculated by multiplying the taxable value (the assessed value minus any exemptions) by the tax rate.
The city also grants some properties incentives called tax abatements, which are subtracted directly from the current tax. This results in the property tax, the amount the current owner pays.

Note that **2022-2023** tax abatements are displayed since **2023-2024** values are not available yet.

Tax description	Billable value 23/24		Tax rate 22/23		Tax bill 23/24
Current tax	$318,150	x	10.6460%	=	$33,870
Total abatements				-	$0
Property tax				**=**	**$33,870**

For more information, you can view this property's assessment, tax bill, and account statements by clicking here and entering the Borough, Block, & Lot.

This map shows property tax in correlation with square footage of the property.

Above $10.00	$4.00 - $5.00
$9.00 - $10.00	$3.00 - $4.00
$8.00 - $9.00	$2.00 - $3.00
$7.00 - $8.00	$1.00 - $2.00
$6.00 - $7.00	Below $1.00
$5.00 - $6.00	No Data

Property tax	**$33,870**
Tax year	**2023-2024**
Square feet	**3,600**
Tax per sqft	**$9**

Permits

1. Permits

Filing date	Job number	Job type	Job status	Work type	Initial cost
05/16/2006	402384754-01	Alteration type 2	Permit issued - entire job/work (05/16/2006)		$4,500
05/16/2006	402384754-01	Alteration type 2	Permit issued - entire job/work (05/16/2006)		$4,500

For more information on Job filings, please visit the DOB NOW and BIS websites.

Development

1. Zoning

New York City is divided into three basic *zoning districts:* residential (R), commercial (C) and manufacturing (M). These basic zoning districts are subdivided by the intensity of use. Development is governed by the use, bulk, and parking requirements of the zoning district.

R Residential district
C Commercial district
M Manufacturing district

Rezoning Proposal Active
Rezoning Recently Adopted

This map was created from the NYC Department of City Planning's online zoning map files. It includes updates found in those files through 04/22/2020.

Zoning Designation

Manufacturing	**M1-3**

Parcel Vicinity

Frontage(s)	**21 St (wide)**

Rezoning Projects

Since	**2014**
Project	**Western Queens**
Status	**Active**

For more information about zoning district regulations, click here.

Manufacturing — M1-3



M1 districts range from the Garment District in Manhattan and Port Morris in the Bronx with multistory lofts, to parts of Red Hook or College Point with one- or two-story warehouses characterized by loading bays. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. M1-1, M1-2 and M1-3 districts are subject to parking requirements based on the type of use and size of an establishment. More info

Map Disclaimer: Our maps are not official zoning maps. The print version of the NYC Zoning Resolution, which includes the zoning maps, together with any amendments adopted by the City Council subsequent to the most recent update to the print version, remains the official version of the Zoning Resolution. All zoning descriptions have been taken from the NYC Planning official source.

2. Building Class

The *building class* specifies how a property is used or what type of building is present on that property. Building classes range from A to Z (excluding X). There are at most 10 different sub-classes within each building class (ranging from 0 to 10). These building classes cover all property uses from residential and commercial to government buildings and parks.

The full list of building classes can be found here.

Building class: **Auto Body/Collision or Auto Repair (G2)**

3. Floor Area Ratio & Air Rights

There are many rules that limit what you can build on a lot and how large it can be. But the most important is the Floor Area Ratio, or FAR. The FAR is expressed as a ratio of the size of the building in square feet to the size of the lot in square feet. For example, if a lot is 2,000 square feet and has an allowable FAR of 4.0, then you cannot build a building larger than 8,000 square feet. Max FAR depends on several factors including zoning, location and use.

The maximum usable floor area is calculated by multiplying the size of the lot by the larger of the residential or commercial FAR.

Area of lot in square feet		**7,886**
FAR	x	**5**
Maximum usable floor area of building	=	**39,430**

Available Air Rights by Parcel

The building on this lot is smaller than the maximum set by the FAR. Thus it may be possible to add to the building (either more floors or an extension) or it may be possible to sell the "air rights" to a developer who owns a nearby lot. (Note: other factors may limit what you can do.)

Maximum usable floor area		**39,430**
Usable floor area	-	**3,628**
Unused buildable square feet ("air rights")	=	**35,802**



Commercial FAR	**5**
Facility FAR	**6.5**
FAR as built	**0.46**

4. Urban Landscape Maps

Click on the map to expand.

Year built: **1910**

On this color-coded map, view the year each property was built.

- >2020
- 2011-2020
- 2001-2010
- 1981-2000
- 1961-1980
- 1941-1960
- 1900-1940
- <1900



Click on the map to expand.

Stories: **1**

On this map, view the number of stories per building.

- 10 & Up stories
- 7 to 9 Stories
- 5 to 6 Stories
- 4 Stories
- 3 Stories
- 2 Stories
- 1 Story
- No data

5. Planimetric Map

This planimetric map shows features such as retaining walls, sidewalks, medians, curbs, and roadbeds that have been digitized from aerial photography. These features must be taken into consideration when determining how a new building, or extensions to an existing building, are situated within the lot. They can also affect the maximum height that can be built.

BIN	Building name	Type	Status	Roof height	Ground elevation
4004423		Building	Constructed	12 ft	15 ft
4615979		Building	Constructed	20 ft	16 ft
4615983		Building	Constructed	20 ft	16 ft

6. HPD Alternative Enforcement Program

The HPD Alternative Enforcement Program map is based on the current month's HPD violations in a building divided by the number of units in the building. It takes in consideration the open hazardous and immediately hazardous violations (I/B/C class) in the last 5 years.

For more information, visit the HPD website.

Neighborhood

1. Transportation

On this color-coded map, view the nearest subway station for each building.



Closest station	**21st St & 41st Ave at NE Corner**
Station lines	**F**
Distance (miles)	**0.338**

On this map, view the closest local or express bus routes and stations.



Name	**21 ST/37 Av**
Distance (miles)	**0.029**

2. Distance to Schools

Elementary School Proximity

This map shows zoned Elementary School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Elementary schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **P.S. 111 Jacob Blackwell**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
P.S. 111 Jacob Blackwell	4	Yes	Public	PK-8	334	0.07
Voice Charter School of New York	7	No	Charter	K-8	684	0.17
P.S. 112 Dutch Kills	6	No	Public	PK-5	455	0.22
P.S. 76 William Hallett	3	No	Public	PK-5	442	0.25
Growing Up Green Ii	NR	No	Charter	K-1		0.37
Growing Up Green Charter School	6	No	Charter	K-8	826	0.37
P.S. 166 Henry Gradstein	8	No	Public	PK-5	998	0.62
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.66
The Child School	NR	No	Private	K-12	340	0.66
P.S. 384	NR	No	Public	K	35	0.70
Ideal Islamic School	NR	No	Private	PK-6	41	0.72
Queens Paideia School	NR	No	Private		28	0.73
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.75
Lagcc Early Childhood Learning	NR	No	Private	PK-3		0.86
The Town School	NR	No	Private	PK-8	402	0.93

Find more info at NYC Department of Education



Middle School Proximity

This map shows zoned Middle School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Middle schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Is 204 Oliver W Holmes**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Is 204 Oliver W Holmes	6	Yes	Public	6-8	460	0.30
P.S. 111 Jacob Blackwell	4	No	Public	PK-8	334	0.07
Voice Charter School of New York	7	No	Charter	K-8	684	0.17
Growing Up Green Charter School	6	No	Charter	K-8	826	0.37
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.62
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.66
The Child School	NR	No	Private	K-12	340	0.66
Albert Shanker School For Visual And Performing Ar	6	No	Public	6-8	688	0.69
Queens Paideia School	NR	No	Private		28	0.73
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.75
The Town School	NR	No	Private	PK-8	402	0.93
Most Precious Blood School	NR	No	Private	PK-8	312	0.98
Evangel Christian School	NR	No	Private	PK-12	463	0.98
Academy For New Americans	6	No	Public	6-8	109	0.99

Find more info at NYC Department of Education



High School Proximity

This map shows zoned High School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

High schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Long Island City High School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Long Island City High School	3	Yes	Public	9-12	2,263	0.58

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Energy Tech High School	4	No	Public	9-12	534	0.30
Academy of American Studies	7	No	Public	9-12	1,002	0.47
Newcomers High School	4	No	Public	9-12	824	0.47
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.62
The Child School	NR	No	Private	K-12	340	0.66
Frank Sinatra School Of The Arts High School	6	No	Public	9-12	856	0.69
Queens Paideia School	NR	No	Private		28	0.73
Information Technology High School	4	No	Public	9-12	1,005	0.81
Bard High School Early College Queens	8	No	Public	9-12	643	0.93
Academy of Finance and Enterprise	8	No	Public	9-12	646	0.94
High School Of Applied Communications	5	No	Public	9-12	404	0.94
Evangel Christian School	NR	No	Private	PK-12	463	0.98
Lycee Francais De New York	NR	No	Private	PK-12	1,362	1.02
International High School at Laguardia Community College	3	No	Public	9-12	510	1.05

Find more info at NYC Department of Education

3. Traffic Map



Estimated average daily traffic volume on a route segment at a particular count location.

Average daily traffic
75001 - 300000
25001 - 75000
10001 - 25000
4001 - 10000
1501 - 4000
1 - 1500

4. Demographics By Zip Code

Demographic data shown in this section was gathered from the 2021 American Community Survey and refers to zip code **11101**.

Population Demographics

Total population	**33,789**
Female population	**49.4%**
Male population	**50.6%**
Median age	**34**
Male median age	**34.8**
Female median age	**33.4**

Education

No highschool	**5.4%**
Some highschool or college	**31.4%**
Bachelors degree	**34.0%**

Other

Citizens	**80.3%**
Citizens born in US	**59.5%**
English speakers	**94.2%**

Journey to Work

Work in a metropolitan area	**99.9%**
Work in a micropolitan area	**0.1%**
Work at home	**17.9%**
Go to work by car	**13.2%**
Go to work after 10 am	**12.2%**

Economic/Employment

Average household income	**$130,719**
White collar	**90.6%**
Blue collar	**9.4%**

Housing

Family households	**44.3%**
Households with kids	**20.4%**
Housing units	**23,015**
Occupied housing units	**15,764**
Owner occupied units	**15.5%**
Average number of people per household	**2.1**
Median year structure built	**2002**
Houses with mortgages	**74.8%**

Wealth

Median value for units with a mortgage	**$977,200**
Median value for units without a mortgage	**$937,500**
Median gross rent	**$2,221**
Median mobile home values	**$0**
Median housing costs per month	**$2,343**
Population in poverty	**12.9%**

Violations

1. HPD Violations

When excessive violations are present, this can adversely affect the support given by The NYC Department of Housing Preservation and Development (HPD). These violations can result in building-wide inspections, fees, and the requirement of extensive repair work to correct underlying conditions. In some cases, outstanding violations may result in a lien being placed on the property. It is also substantially more difficult to mortgage a building with extensive violations.

We do not have any record of violations in our database. Status can be verified here.

2. 311 Complaints

Created	Agency	Type	Descriptor	Disposition	Closed
06/20/2019	DCA	Consumer complaint	Exchange/refund/return	The Department of Consumer Affairs has already mailed you a complaint form. In order for DCA to be able to help, you must complete that form and return it to DCA along with requested documentation. DCA will contact you approximately 30 days after receiving your complete complaint which we must forward to the reported business for its response. If you do not receive the complaint form within 15 days from the date of your initial request, please call 311 back.	
08/02/2013	TLC	For hire vehicle complaint	Car service company complaint	The Taxi and Limousine Commission will send a confirmation letter in 14 days to confirm your complaint details. At the hearing you may be required to provide information regarding this complaint. Please note your Service Request number for future reference.	08/08/2013
02/17/2013	TLC	For hire vehicle complaint	Car service company complaint	Because you live outside the tri-state area, the Taxi and Limousine Commission will send instructions on how to submit written testimony in 14 days. Please note your Service Request number for future reference.	04/24/2013

Complaint status can be verified here.

3. DOB Complaints

Date entered	Complaint	Complaint category	Disposition	Inspection
04/24/2008	4349241	Construction - contrary/beyond approved plans/permits	Buildings violations(s) served	04/23/2008
05/11/2006	4264219	Permit - none (building/PA/demo etc.)	No violation warranted for complaint at time of inspection	06/13/2006

Complaint status can be verified here.

4. DOB Violations

Violation ID	Issue date	Type	Status
V100115LBLVIO14334	10/01/2015	Lblvio-low pressure boiler	Active
Violation issued for failure to file annual boiler 2014 inspection report			
V030315LBLVIO13996	03/03/2015	Lblvio-low pressure boiler	Active
Violation issued for failure to file annual boiler 2013 inspection report			
V051514LBLVIO18995	05/15/2014	Lblvio-low pressure boiler	Active
Violation issued for failure to file annual boiler 2012 inspection report			
V030113LBLVIO16846	03/01/2013	Lblvio-low pressure boiler	Active
Violation issued for failure to file annual boiler 2011 inspection report			
V121311LBLVIO22274	12/13/2011	Lblvio-low pressure boiler	Active
Violation issued for failure to file annual boiler 2010 inspection report			
V123109LBLVIO25533	12/31/2009	Lblvio-low pressure boiler	Active
V010109LL629125599	01/01/2009	Ll6291-local law 62/91 - boilers	Active
V042308C0103WT	04/23/2008	C-construction	Active
V010308LL629125715	01/03/2008	Ll6291-local law 62/91 - boilers	Active

Please note: the NYC Department of Buildings is the only authoritative source for information on DOB violations. Verify the status of the violation on DOB website.

Records are obtained from DOB and updated daily.

5. ECB Violations

There are eleven city agencies that administer the City's quality-of-life laws and issue Notices of Violation (NOVs) for alleged violations. The ECB is a separate and independent agency that hears challenges to those NOVs. The agencies that issue the most violations for real estate are:

- Department of Buildings (DOB)
- Department of Environmental Protection (DEP)
- Fire Department (FDNY)
- Landmarks Preservation Commission (LPC)
- Department of Sanitation (DSNY)

Violation ID	Issue date	Type	Severity	Status	Link to violation
34645459N	04/23/2008	Construction	Hazardous	Active	
Failure to sign off tr1 upon completion of controlled work. For alt iijob 402384754 of which permit has expired @ 4/26/07. Work of temporarysteel shed is complete. No engineer or architect has taken the					

Please note: the NYC Department of Buildings is the only authoritative source for information on ECB violations. Verify the status of the violation on DOB website.

Records are obtained from ECB and updated weekly.

6. Neighborhood Complaints

Created	Agency	Type	Descriptor	Disposition	Closed
06/28/2023	NYPD	Illegal parking	Unauthorized bus layover	The Police Department responded to the complaint and took action to fix the condition.	06/28/2023
06/06/2023	NYPD	Illegal parking	Unauthorized bus layover	The Police Department responded and upon arrival those responsible for the condition were gone.	06/06/2023
01/17/2023	NYPD	Illegal parking	Posted parking sign violation	The Police Department responded to the complaint and took action to fix the condition.	01/17/2023
12/05/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded and upon arrival those responsible for the condition were gone.	12/05/2022
12/01/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded and upon arrival those responsible for the condition were gone.	12/01/2022
12/01/2022	NYPD	Illegal parking	Blocked crosswalk	The Police Department issued a summons in response to the complaint.	12/01/2022
09/13/2022	NYPD	Illegal parking	Blocked sidewalk	The Police Department responded to the complaint and took action to fix the condition.	09/13/2022
06/02/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and took action to fix the condition.	06/02/2022
04/02/2022	NYPD	Illegal parking	Blocked sidewalk	The Police Department responded and upon arrival those responsible for the condition were gone.	04/02/2022
02/28/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and took action to fix the condition.	02/28/2022
02/09/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and with the information available observed no evidence of the violation at that time.	02/09/2022
01/29/2022	NYPD	Blocked driveway	No access	The Police Department issued a summons in response to the complaint.	01/29/2022
10/31/2021	NYPD	Illegal parking	Blocked sidewalk	The Police Department issued a summons in response to the complaint.	10/31/2021
10/31/2021	NYPD	Illegal parking	Blocked sidewalk		
09/28/2021	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and took action to fix the condition.	09/28/2021

Risk

1. Toxic Sites

Get a Phase I environmental report Site Assessment or a Home Environmental Database Report for this property directly from Toxics Targeting.

This screening map, provided to by Toxics Targeting, shows environmental hazards such as toxic dumps, garbage landfills, leaking tanks, hazardous waste sites, and pollution discharges reported by local, state and federal government authorities.

Call 800-2-TOXICS (800-286-9427 NYS only) or 607-273-3391 for more info.



Toxic Sites on the Property

Petroleum bulk storage	1
Total toxic sites on the property	1

Toxic Sites near the Property

Petroleum bulk storage	4
Solid waste facility	1
Spill greater than 25 gal/lbs	1
Haz waste generator or transporter	4
Spill	1
Gasoline spill	1
Total neighboring toxic sites	12

Map Disclaimer: Mapped locations are approximate; sites are identified based on current and/or historic information. Regulatory status of sites may have changed. Site symbols can refer to large properties, additional toxic sites are not mapped. Contamination problems can impact properties far from toxic sources. Sites include known and potential hazards.

2. FEMA Flood Zones

Use this map to determine if the property is in a flood zone.



Link to the map for this property at **FEMA's Map Service Center** (may not be available in all locations).

FEMA Flood Zoning

FEMA flood zone(s)	**X**
Coastal barrier resources system area (COBRA)	**Out**
Floodway	**Out**
FEMA special flood hazard area	**Out**
Map panel ID	**3604970089F**
Map quaderant ID	**40073-G8**

Distance to...

Nearest distance to coastline (miles)	**0.452**
Compass direction to coastline	**148**
Nearest distance to 100 year flood zone area (ft)	**351**
Angle100	**183**

3. Hurricane Evacuation Zones



Zone: **4**

This map shows hurricane evacuation zones. In the case of coastal storms, the City may order the evacuation of neighborhoods in danger of flooding, the most critical being Zone 1.

Hurricane evacuation zones
- Zone 1
- Zone 2
- Zone 3
- Zone 4
- Zone 5
- Zone 6

Disclaimer

Copyright 2003-2023 by Property Research Partners LLC

All data comes from government sources. No attempt has been made to validate it. No attempt has been made to validate the accuracy of the programming of this web site. Do not rely on this report to support investment decisions. The only authoritative source for the information in this report is the government agencies from which the data was acquired.



Sarah Heyne
Phone: **(631) 321-4300**
sarahh@midenv.com

Property Report by PropertyShark.com, for:

3712 Rear 22nd St, Long Island City, NY 11101

General

1. Overview

Address

Primary address	**3712 REAR 22nd St**
Zip code	**11101**
Neighborhood	**LIC**
Borough	**Queens**
Block & lot	**00364-0135**

Owner

Name	**Yardley Associates, LLC**
Address	**1008 Cedar Park Dr Cedar Park, TX 78613**
Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

Property Taxes

Tax class	**4**
Property tax	**$1,006**

Lot

Lot sqft	**300**
Lot dimensions	**20 ft x 30 ft**
Corner lot	**No**

Zoning

Zoning districts	**M1-3**
Zoning map	**9b**
Qualified opportunity zone	**Yes (map)**

Building

Building class	**Zoned Commercial or Manhattan Residential (V1)**

Floor Area Ratio (FAR)

Commercial FAR	**5**
Facility FAR	**6.5**
Allowed usable floor area	**1,495**
Unused FAR	**1,495**

2. Photos

Uploaded in November, 2016 by Joe Strini

3. Maps



Community district	**1**	Closest police station	**0.76 Miles**
School district	**30**	Closest fire station	**0.16 Miles**
Census tract	**33**	Tax map	**40302**
Lat long	**40.75808, -73.93777**	Sanborn map	**401 080**

Contacts

1. Real Owners

For LLC-owned properties, our team manually researches who is the owner behind the LLC and verifies phone numbers. When the owner of a property is an individual, an algorithm extracts the best matching phone numbers from multiple sources. **Our research team is in the process of verifying all phone numbers to make sure they reach the right person.**

We have a verified phone number for the owner of this property. One of our researchers called the number and confirmed it reaches the owner.

Upgrade

Name

Address

Phone

Verified personal number

E-mail

to unlock Real Owners and their phone numbers.

2. Registered Owner

Yardley Associates, LLC

1008 Cedar Park Dr
Cedar Park, TX 78613
Source: Assessment Roll
Last recorded: 12/17/2022

Add to address book

Ownership data is aggregated from governmental sources like deeds and the assessment roll. If the registered owner is an LLC or other form of company, use our Real Owners service to find the person behind the company.

Valuation

1. Last Sale

Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

2. Assessment History

Year	Building class	Market value	Assessed value	Taxable	Tax rate%	Base tax	Property tax
2022/23	V1	$23,000	$10,350	$7,560	10.646%	$805	$805
2021/22	V1	$20,000	$9,000	$6,267	10.755%	$674	$674
2020/21	V1	$17,000	$7,650	$5,115	10.694%	$547	$547
2019/20	V1	$15,000	$6,750	$4,123	10.537%	$434	$434
2018/19	V1	$9,000	$4,050	$3,224	10.514%	$339	$339
2017/18	V1	$8,640	$3,888	$2,955	10.514%	$311	$311
2016/17	V1	$7,200	$3,240	$2,718	10.574%	$287	$287
2015/16	V1	$6,000	$2,700	$2,520	10.656%	$269	$269
2014/15	V1	$5,000	$2,250	$2,250	10.684%	$240	$240
2013/14	V1	$6,000	$2,700	$2,298	10.323%	$237	$237
2012/13	V1	$6,000	$2,700	$2,144	10.228%	$219	$219
2011/12	V1	$5,000	$2,250	$1,990	10.152%	$202	$202
2010/11	V1	$4,280	$1,926	$1,795	10.312%	$185	$185
2009/10	V1	$4,280	$1,926	$1,651	10.426%	$172	$172
2008/09	V1	$4,280	$1,926	$1,475	10.241%	$151	$151

Documents

1. Title Documents

Export to Excel (5 records)

Date	Type	Amount	Party 1	Party 2	Doc image
01/01/2016 - D 05/10/2017 - R	Both RPTT and RETT (2017042800882005) - **M**		Lupoli Virginia 120 Beach Mountain Cove Georgetown TX 78633 Lupoli Peter 904 Skyview Drive Santa Barbara CA 93108	Lupoli Holdings Partnership 1333 Shore District Drive Apt 1653 Austin TX 78741	
01/16/2008 - D 04/10/2008 - R	Deed (2008040300519001)		Lupoli Peter N 2439 Whitney Avenue Summerland CA 93067	Yardley Associates LLC 4 Pam Lane Huntington NY 11743	
06/21/1990 - R	Deed (4860002672786)		City of New York	Lupoli Peter N	
07/07/1987 - D 07/09/1987 - R	Deed (FT_4620002346462) - **M**		NYC Commissioner of Finance Municipal BLDG NY NY	City of New York City Hall NY NY	
07/07/1987 - D 07/09/1987 - R	Deed (4620002346462) - **M**		NYC Comm Finance Municipal BLDG NY NY	City of New York City Hall NY NY	

R: Record date
D: Document date

Financials

1. Mortgage Summary

No active mortgages for this property.

to unlock the property's mortgage balance, maturity date, interest rate and much more.

Occupancy

Taxes

1. Tax Bill

Property tax bill for 7/1/2023 to 6/30/2024	**$1,006**

2. Key Values in Calculating the Bill

Tax class	**4**
Market value	**$30,000**
Assessed value	**$13,500**
Exemptions granted by city	**$0**
Transitional value	**$9,450**
Transitional exemption value	**$0**
Tax abatements	**$0**

3. Assessed Value Evolution

The state law requires to phase in any changes to the assessed value over a five-year period. In any given year, multiple transitions are being applied to the property, which result in different assessed and transitional values each year. The law requires the use of the lowest value between the two - assessed or transitional - to calculate the property tax bill.Please note that assessment changes due to physical alterations/renovations to the property are not phased in. Additionally, if a tax class change has occurred in the past two years, we are unable to estimate value increases for the next 5 years.



4. Property Tax Calculation

Market Value

The first step is for the City Assessor to determine the *market value* of the property. While the term *market value* would seemingly refer to how much the property would sell for on the open market, in reality the *market value* established by the City Assessor is almost always substantially lower.

Land market value		$30,000
Building market value	+	$0
Market value	**=**	**$30,000**

Assessed Value

Next, the market value is used to compute the assessed value, which is a percentage of the market value. The exact percentage is determined by the tax class of the property. Tax class 1 is assessed at 6% of the market value, and tax classes 2,3 and 4 are assessed at 45%.

Market value		$30,000
Assessment ratio	x	45%
Maximum assessed value	**=**	**$13,500**

Transitional Value

To protect property owners from sudden large increases in property tax, the state limits how quickly the city can increase the assessed value. Typically these limits are applied when the City Assessor makes a big increase to the market value. Without the limits the assessed value would increase by a similar percentage. Instead, the change to the assessed value is phased in over a number of years.

The market value of this property was increased in previous years and the assessed value is currently being phased in. Because this property is in **tax class 4**, the assessment cannot be raised more than 8% from the year before or 30% over five years. Assessed value cannot be raised more than 45% from market value.

Assessed value		$13,500
Exemptions granted by city	-	$0
Net assessed value	**=**	**$13,500**

Transitional value		$9,450
Transitional exemption value	-	$0
Transitional net value	**=**	**$9,450**

Taxable Value

The *taxable value*, for 23/24, is the smaller of the city's net assessed value and the transitional net assessed value.

Taxable value	=	$9,450

Property Tax

Current tax is calculated by multiplying the taxable value (the assessed value minus any exemptions) by the tax rate.
The city also grants some properties incentives called tax abatements, which are subtracted directly from the current tax. This results in the property tax, the amount the current owner pays.

Note that **2022-2023** tax abatements are displayed since **2023-2024** values are not available yet.

Tax description	Billable value 23/24		Tax rate 22/23		Tax bill 23/24
Current tax	$9,450	x	10.6460%	=	$1,006
Total abatements				-	$0
Property tax				**=**	**$1,006**

For more information, you can view this property's assessment, tax bill, and account statements by clicking here and entering the Borough, Block, & Lot.

This map shows property tax in correlation with square footage of the property.

Above $10.00	$4.00 - $5.00
$9.00 - $10.00	$3.00 - $4.00
$8.00 - $9.00	$2.00 - $3.00
$7.00 - $8.00	$1.00 - $2.00
$6.00 - $7.00	Below $1.00
$5.00 - $6.00	No Data

Development

1. Zoning

New York City is divided into three basic *zoning districts:* residential (R), commercial (C) and manufacturing (M). These basic zoning districts are subdivided by the intensity of use. Development is governed by the use, bulk, and parking requirements of the zoning district.

R Residential district
C Commercial district
M Manufacturing district

Rezoning Proposal Active
Rezoning Recently Adopted

This map was created from the NYC Department of City Planning's online zoning map files. It includes updates found in those files through 04/22/2020.

Zoning Designation

Manufacturing	**M1-3**

Rezoning Projects

Since	**2014**
Project	**Western Queens**
Status	**Active**

For more information about zoning district regulations, click here.

Parcel Vicinity

Nearest wide street	**21 St (Wide)**
Distance to wide street	**133 ft**

Manufacturing — M1-3



M1 districts range from the Garment District in Manhattan and Port Morris in the Bronx with multistory lofts, to parts of Red Hook or College Point with one- or two-story warehouses characterized by loading bays. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. M1-1, M1-2 and M1-3 districts are subject to parking requirements based on the type of use and size of an establishment. More info

Map Disclaimer: Our maps are not official zoning maps. The print version of the NYC Zoning Resolution, which includes the zoning maps, together with any amendments adopted by the City Council subsequent to the most recent update to the print version, remains the official version of the Zoning Resolution. All zoning descriptions have been taken from the NYC Planning official source.

2. Building Class

The *building class* specifies how a property is used or what type of building is present on that property. Building classes range from A to Z (excluding X). There are at most 10 different sub-classes within each building class (ranging from 0 to 10). These building classes cover all property uses from residential and commercial to government buildings and parks.

The full list of building classes can be found here.



Building class: **Zoned Commercial or Manhattan Residential (V1)**

3. Floor Area Ratio & Air Rights

There are many rules that limit what you can build on a lot and how large it can be. But the most important is the Floor Area Ratio, or FAR. The FAR is expressed as a ratio of the size of the building in square feet to the size of the lot in square feet. For example, if a lot is 2,000 square feet and has an allowable FAR of 4.0, then you cannot build a building larger than 8,000 square feet. Max FAR depends on several factors including zoning, location and use.

The maximum usable floor area is calculated by multiplying the size of the lot by the larger of the residential or commercial FAR.

Area of lot in square feet		**299**
FAR	x	**5**
Maximum usable floor area of building	=	**1,495**

Available Air Rights by Parcel

The building on this lot is smaller than the maximum set by the FAR. Thus it may be possible to add to the building (either more floors or an extension) or it may be possible to sell the "air rights" to a developer who owns a nearby lot. (Note: other factors may limit what you can do.)

Maximum usable floor area		**1,495**
Usable floor area	-	**0**
Unused buildable square feet ("air rights")	=	**1,495**



Commercial FAR	**5**
Facility FAR	**6.5**

4. Urban Landscape Maps



Click on the map to expand.

On this color-coded map, view the year each property was built.

- >2020
- 2011-2020
- 2001-2010
- 1981-2000
- 1961-1980
- 1941-1960
- 1900-1940
- <1900



Click on the map to expand.

On this map, view the number of stories per building.

- 10 & Up stories
- 7 to 9 Stories
- 5 to 6 Stories
- 4 Stories
- 3 Stories
- 2 Stories
- 1 Story
- No data

5. HPD Alternative Enforcement Program

The HPD Alternative Enforcement Program map is based on the current month's HPD violations in a building divided by the number of units in the building. It takes in consideration the open hazardous and immediately hazardous violations (I/B/C class) in the last 5 years.



Properties over the HPD-AEP threshold
- More than 600% over
- 300% to 600% over
- Up to 300% over

Properties below the HPD-AEP threshold
- 80% to 99%
- 60% to 80%
- 50% to 60%

HPD-AEP threshold for buildings having:
- 3 to 14 units = 5 violations/unit
- 15 units or more = 3 violations/unit

For more information, visit the HPD website.

Neighborhood

1. Transportation

On this color-coded map, view the nearest subway station for each building.



Closest station	**21st St & 41st Ave at NE Corner**
Station lines	**F**
Distance (miles)	**0.343**

On this map, view the closest local or express bus routes and stations.



Name	**21 ST/37 Av**
Distance (miles)	**0.039**

2. Distance to Schools

Elementary School Proximity

This map shows zoned Elementary School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Elementary schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **P.S. 111 Jacob Blackwell**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
P.S. 111 Jacob Blackwell	4	Yes	Public	PK-8	334	0.09
Voice Charter School of New York	7	No	Charter	K-8	684	0.18
P.S. 112 Dutch Kills	6	No	Public	PK-5	455	0.20
P.S. 76 William Hallett	3	No	Public	PK-5	442	0.27
Growing Up Green Ii	NR	No	Charter	K-1		0.36
Growing Up Green Charter School	6	No	Charter	K-8	826	0.36
P.S. 166 Henry Gradstein	8	No	Public	PK-5	998	0.60
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.68
The Child School	NR	No	Private	K-12	340	0.68
P.S. 384	NR	No	Public	K	35	0.70
Ideal Islamic School	NR	No	Private	PK-6	41	0.72
Queens Paideia School	NR	No	Private		28	0.73
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.73
Lagcc Early Childhood Learning	NR	No	Private	PK-3		0.86
The Town School	NR	No	Private	PK-8	402	0.95

Find more info at NYC Department of Education



Middle School Proximity

This map shows zoned Middle School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Middle schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Is 204 Oliver W Holmes**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Is 204 Oliver W Holmes	6	Yes	Public	6-8	460	0.28
P.S. 111 Jacob Blackwell	4	No	Public	PK-8	334	0.09
Voice Charter School of New York	7	No	Charter	K-8	684	0.18
Growing Up Green Charter School	6	No	Charter	K-8	826	0.36
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.60
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.68
The Child School	NR	No	Private	K-12	340	0.68
Albert Shanker School For Visual And Performing Ar	6	No	Public	6-8	688	0.68
Queens Paideia School	NR	No	Private		28	0.73
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.73
The Town School	NR	No	Private	PK-8	402	0.95
Most Precious Blood School	NR	No	Private	PK-8	312	0.96
Evangel Christian School	NR	No	Private	PK-12	463	0.98
Academy For New Americans	6	No	Public	6-8	109	0.98

Find more info at NYC Department of Education



High School Proximity

This map shows zoned High School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

High schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Long Island City High School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Long Island City High School	3	Yes	Public	9-12	2,263	0.58

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Energy Tech High School	4	No	Public	9-12	534	0.28
Academy of American Studies	7	No	Public	9-12	1,002	0.46
Newcomers High School	4	No	Public	9-12	824	0.46
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.60
The Child School	NR	No	Private	K-12	340	0.68
Frank Sinatra School Of The Arts High School	6	No	Public	9-12	856	0.68
Queens Paideia School	NR	No	Private		28	0.73
Information Technology High School	4	No	Public	9-12	1,005	0.81
Bard High School Early College Queens	8	No	Public	9-12	643	0.92
Academy of Finance and Enterprise	8	No	Public	9-12	646	0.93
High School Of Applied Communications	5	No	Public	9-12	404	0.94
Evangel Christian School	NR	No	Private	PK-12	463	0.98
Lycee Francais De New York	NR	No	Private	PK-12	1,362	1.04
International High School at Laguardia Community College	3	No	Public	9-12	510	1.04

Find more info at NYC Department of Education

3. Traffic Map



Estimated average daily traffic volume on a route segment at a particular count location.

Average daily traffic
- 75001 - 300000
- 25001 - 75000
- 10001 - 25000
- 4001 - 10000
- 1501 - 4000
- 1 - 1500

4. Demographics By Zip Code

Demographic data shown in this section was gathered from the 2021 American Community Survey and refers to zip code **11101**.

Population Demographics

Total population	**33,789**
Female population	**49.4%**
Male population	**50.6%**
Median age	**34**
Male median age	**34.8**
Female median age	**33.4**

Education

No highschool	**5.4%**
Some highschool or college	**31.4%**
Bachelors degree	**34.0%**

Other

Citizens	**80.3%**
Citizens born in US	**59.5%**
English speakers	**94.2%**

Journey to Work

Work in a metropolitan area	**99.9%**
Work in a micropolitan area	**0.1%**
Work at home	**17.9%**
Go to work by car	**13.2%**
Go to work after 10 am	**12.2%**

Economic/Employment

Average household income	**$130,719**
White collar	**90.6%**
Blue collar	**9.4%**

Housing

Family households	**44.3%**
Households with kids	**20.4%**
Housing units	**23,015**
Occupied housing units	**15,764**
Owner occupied units	**15.5%**
Average number of people per household	**2.1**
Median year structure built	**2002**
Houses with mortgages	**74.8%**

Wealth

Median value for units with a mortgage	**$977,200**
Median value for units without a mortgage	**$937,500**
Median gross rent	**$2,221**
Median mobile home values	**$0**
Median housing costs per month	**$2,343**
Population in poverty	**12.9%**

Violations

1. HPD Violations

When excessive violations are present, this can adversely affect the support given by The NYC Department of Housing Preservation and Development (HPD). These violations can result in building-wide inspections, fees, and the requirement of extensive repair work to correct underlying conditions. In some cases, outstanding violations may result in a lien being placed on the property. It is also substantially more difficult to mortgage a building with extensive violations.

We do not have any record of violations in our database. Status can be verified here.

Risk

1. Toxic Sites

Get a Phase I environmental report Site Assessment or a Home Environmental Database Report for this property directly from Toxics Targeting.

This screening map, provided to by Toxics Targeting, shows environmental hazards such as toxic dumps, garbage landfills, leaking tanks, hazardous waste sites, and pollution discharges reported by local, state and federal government authorities.

Call 800-2-TOXICS (800-286-9427 NYS only) or 607-273-3391 for more info.



Toxic Sites on the Property

None reported.

Toxic Sites near the Property

Spill greater than 25 gal/lbs	1
Spill	1
Petroleum bulk storage	5
Haz waste generator or transporter	1
Solid waste facility	1
Gasoline spill	1
Total neighboring toxic sites	10

Map Disclaimer: Mapped locations are approximate; sites are identified based on current and/or historic information. Regulatory status of sites may have changed. Site symbols can refer to large properties, additional toxic sites are not mapped. Contamination problems can impact properties far from toxic sources. Sites include known and potential hazards.

2. FEMA Flood Zones

Use this map to determine if the property is in a flood zone.

Link to the map for this property at **FEMA's Map Service Center** (may not be available in all locations).

FEMA Flood Zoning

FEMA flood zone(s)	**X**
Coastal barrier resources system area (COBRA)	**Out**
Floodway	**Out**
FEMA special flood hazard area	**Out**
Map panel ID	**3604970089F**
Map quaderant ID	**40073-G8**

Distance to...

Nearest distance to coastline (miles)	**0.475**
Compass direction to coastline	**150**
Nearest distance to 100 year flood zone area (ft)	**348**
Angle100	**278**

3. Hurricane Evacuation Zones



Zone: **4**

This map shows hurricane evacuation zones. In the case of coastal storms, the City may order the evacuation of neighborhoods in danger of flooding, the most critical being Zone 1.

Hurricane evacuation zones
- Zone 1
- Zone 2
- Zone 3
- Zone 4
- Zone 5
- Zone 6

Disclaimer

Copyright 2003-2023 by Property Research Partners LLC

All data comes from government sources. No attempt has been made to validate it. No attempt has been made to validate the accuracy of the programming of this web site. Do not rely on this report to support investment decisions. The only authoritative source for the information in this report is the government agencies from which the data was acquired.



Sarah Heyne
Phone: **(631) 321-4300**
sarahh@midenv.com

Property Report by PropertyShark.com, for:

37-25 21st St, Long Island City, NY 11101

General

1. Overview

Address

Primary address	**37-25 21st St**
Alternate address(es)	**37-25 B 21st St** **37-27 21st St**
Zip code	**11101**
Neighborhood	**LIC**
Borough	**Queens**
Block & lot	**00364-0006**

Owner

Name	**Yardley Associates, LLC**
Address	**1008 Cedar Park Dr** **Cedar Park, TX 78613**
Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

Property Taxes

Tax class	**4**
Property tax	**$99,062**

Lot

Lot sqft	**15,000**
Lot dimensions	**95 ft x 130 ft**
Ground elevation	**16 ft**
Corner lot	**No**

Zoning

Zoning districts	**M1-3**
Zoning map	**9b**
Qualified opportunity zone	**Yes (map)**

Building

Building class	**Auto Body/Collision or Auto Repair (G2)**
Square feet	**5,432**
Building dimensions	**95 ft x 28.6 ft**
Buildings on lot	**2**
Stories	**1**
Roof height	**16 ft**
Year built	**1938**
Year last altered	**2004**
Structure type	**Auto representation shop**
Construction type	**Light metal**
Grade	**C**

Use

Class A units (HPD)	**1**
Commercial units	**1**
Garage sqft	**5,432**

Floor Area Ratio (FAR)

Commercial FAR	**5**
Facility FAR	**6.5**
FAR as built	**0.36**
Allowed usable floor area	**75,000**
Usable floor area as built	**5,400**
Unused FAR	**69,600**

Violations

DOB violations	**1**
ECB violations	**6**
Marshals evictions in building	**Yes**

2. Photos

Uploaded in November, 2016 by Joe Strini

3. Maps



Community district	**1**	Closest police station	**0.76 Miles**
School district	**30**	Closest fire station	**0.14 Miles**
Census tract	**33**	Tax map	**40302**
Lat long	**40.75788, -73.93815**	Sanborn map	**401 080**

Contacts

1. Real Owners

For LLC-owned properties, our team manually researches who is the owner behind the LLC and verifies phone numbers. When the owner of a property is an individual, an algorithm extracts the best matching phone numbers from multiple sources. **Our research team is in the process of verifying all phone numbers to make sure they reach the right person.**

We have a verified phone number for the owner of this property. One of our researchers called the number and confirmed it reaches the owner.

Upgrade

Name

Address

Phone

Verified personal number

E-mail

to unlock Real Owners and their phone numbers.

2. Registered Owner

Yardley Associates, LLC

Address: 1008 Cedar Park Dr
Cedar Park, TX 78613
Source: Assessment Roll
Last recorded: 12/17/2022

Add to address book

Ownership data is aggregated from governmental sources like deeds and the assessment roll. If the registered owner is an LLC or other form of company, use our Real Owners service to find the person behind the company.

3. Contacts from Building Permits

Registration date	Role	Name	Address	Phone number	Email
12/11/2018	Applicant	Sankar Shil Green Power Electric Corp			
12/11/2018	Owner	Jahir Uddin			
12/29/2009	Applicant	Thomas W Bury William Hird & Co Inc		(718) 499-4881	
12/29/2009	Owner	Magdy Elghonami All In One Auto Repair	37-25b 21st Long Island City, NY 11101	(719) 392-8294	
12/08/2009	Applicant	Igor Gurevich			
07/31/2008	Owner	Magdy Elghonami All In One Auto Repair	37-25b 21st Street Long Island City, NY 11101	(718) 392-8294	
07/31/2008	Applicant	Stanley Wald			
07/31/2008	Owner	Magdy Elghonami All In One Auto Repair		(718) 392-8294	
12/18/2003	Applicant	Abdul Q Mohammad C/O Abdul Q Mohammad Aqm Engineerng Consulting	216 Forbell St Brooklyn, NY 11208	(718) 647-3010	
09/16/2003	Applicant	Abdul Q Mohammad C/O Abdul Q Mohammad Aqm Engineerng Consulting	216 Forbell St Brooklyn, NY 11208	(718) 647-3010	
05/06/2003	Applicant	Ahmet Sangiray P.S.I Mechanical; P.S.I. Mechanical		(718) 699-8005	
05/06/2003	Applicant	Ahmet Sangiray Tp S I Mechanical; Tp. S.I. Mechanical	4704 108st Corona, NY 11368	(718) 699-8005	
05/06/2003	Superintendent	Ahmet Sangiray P.S.I Mechanical; P S I Mechanical; Psi Mechanical			

Valuation

1. Last Sale

Purchase date	**01/01/2016**
Purchase price	**$0**
Special factors	**Multiple parcels**

2. Assessment History

Year	Building class	Market value	Assessed value	Taxable	Tax rate%	Base tax	Property tax
2022/23	G2	$2,752,000	$1,238,400	$772,380	10.646%	$82,228	$82,228
2021/22	G2	$1,537,000	$691,650	$640,890	10.755%	$68,928	$68,928
2020/21	G2	$1,678,000	$755,100	$587,880	10.694%	$62,868	$62,868
2019/20	G2	$1,324,000	$595,800	$504,810	10.537%	$53,192	$53,192
2018/19	G2	$1,291,000	$580,950	$443,790	10.514%	$46,660	$46,660
2017/18	G2	$1,291,000	$580,950	$384,390	10.514%	$40,415	$40,415
2016/17	G2	$948,000	$426,600	$322,560	10.574%	$34,107	$34,107
2015/16	G2	$755,000	$339,750	$316,260	10.656%	$33,701	$33,701
2014/15	G9	$646,000	$290,700	$290,700	10.684%	$31,058	$31,058
2013/14	G9	$631,000	$283,950	$283,950	10.323%	$29,312	$29,312
2012/13	G9	$604,000	$271,800	$271,800	10.228%	$27,800	$27,800
2011/12	G9	$878,000	$395,100	$372,150	10.152%	$37,781	$37,781
2010/11	G9	$860,000	$387,000	$357,480	10.312%	$36,863	$36,863
2009/10	G9	$869,000	$391,050	$343,980	10.426%	$35,863	$35,863
2008/09	G9	$761,000	$342,450	$319,770	10.241%	$32,748	$32,748

Documents

1. Title Documents

Export to Excel (6 records)

Date	Type	Amount	Party 1	Party 2	Doc image
01/01/2016 - D 05/10/2017 - R	Both RPTT and RETT (2017042800882005) - **M**		Lupoli Virginia 120 Beach Mountain Cove Georgetown TX 78633 Lupoli Peter 904 Skyview Drive Santa Barbara CA 93108	Lupoli Holdings Partnership 1333 Shore District Drive Apt 1653 Austin TX 78741	
01/15/2013 - R	Initial UCC1 (2013011101396001)		All in One Auto Repair Incorporated 37-25B 21 Street Astoria NY 11101	Financial Pacific Leasing LLC PO Box 4568 Federal Way WA 980634568 Wells Fargo Capital Finance LLC PO Box 4568 Federal Way WA 98001	
03/12/2008 - D 04/10/2008 - R	Deed (2008040300680001)		Lupo Realty C O 4 Pam Lane Huntington NY 11743	Yardley Associates LLC 4 Pam Lane Huntington NY 11743	
11/15/1976 - D 12/03/1990 - R	Deed (4880002716388)		Farwell Realty Cp 21-13 39 Ave Lic NY	Lupo Realty CO 68 Cove Neck Rd Cove Neck NY	
06/28/1967 - R	Deed (36740044800018)		Lupoli Peter	Farwell Realty CORP	
06/28/1967 - R	Deed (36740044800014)		Lupoli Charles	Peter Lupoli	

R: Record date
D: Document date

Financials

1. Mortgage Summary

No active mortgages for this property.

to unlock the property's mortgage balance, maturity date, interest rate and much more.

Occupancy

1. Phone Records of Residents

Name	Unit	First seen	Phone number
Azuay Auto Repair Co	F	2017	(718) 482-1373
Molla Auto Sales		2003	(718) 729-9519
Qazi & Son S Inc		2014	(718) 361-6660

2. Businesses

Entity	Contact	Phone number	Email	Website
All in One Auto Repair Incorporated 3725B 21st St Long Island City, NY 11101		(718) 392-5079		
City Used Auto Center INC. 3725 21st St Long Is City, NY 11101		(718) 729-9519		
Gam Automotive LLC 3725 21st St Long Is City, NY 11101		(347) 996-2903		
International Auto Supply INC. 3725 21st St Long Is City, NY 11101		(718) 999-9999		
L.I.C. Used Auto Parts, INC 3725 21st St Long Is City, NY 11101		(718) 729-9519		
M&N Auto Glass & Tire, INC. 3725 21st St Long Is City, NY 11101		(917) 575-2374		
Mark Deli and More INC 3727 21st St Astoria, NY 11101		(646) 261-2803		
Molla Auto Sales INC 3727 21st St Long Island City, NY 11101		(718) 729-9527		
Morales Beristain, Felipe DBA Morales Tire Shop 3725 21st St Long Island City, NY 11101		(347) 761-2232		
New Bangla Motor INC. 3725 21st St Long Is City, NY 11101		(718) 707-9440		
New Qazi World Auto Parts INC. 3727 21st St Long Is City, NY 11101		(718) 729-9519		
Qazi & Sons Used Parts INC. 3727 21st St Long Island City, NY 11101		(718) 728-9519		
Qazi & Sons Used Parts INC. 3727 21st St Long Is City, NY 11101		(718) 728-9519		
Qazi Auto Repairs INC. 3727 21st St Long Is City, NY 11101		(718) 482-7830		
Ricky Auto Alarm Electronic INC. 3725 21st St Long Is City, NY 11101		(718) 461-8599		

Taxes

1. Tax Bill

Property tax bill for 7/1/2023 to 6/30/2024	**$99,062**

2. Key Values in Calculating the Bill

Tax class	**4**
Market value	**$3,048,000**
Assessed value	**$1,371,600**
Exemptions granted by city	**$0**
Transitional value	**$930,510**
Transitional exemption value	**$0**
Tax abatements	**$0**

3. Assessed Value Evolution

The state law requires to phase in any changes to the assessed value over a five-year period. In any given year, multiple transitions are being applied to the property, which result in different assessed and transitional values each year. The law requires the use of the lowest value between the two - assessed or transitional - to calculate the property tax bill.Please note that assessment changes due to physical alterations/renovations to the property are not phased in. Additionally, if a tax class change has occurred in the past two years, we are unable to estimate value increases for the next 5 years.



4. Property Tax Calculation

Market Value

The first step is for the City Assessor to determine the *market value* of the property. While the term *market value* would seemingly refer to how much the property would sell for on the open market, in reality the *market value* established by the City Assessor is almost always substantially lower.

Land market value		$1,200,000
Building market value	+	$1,848,000
Market value	**=**	**$3,048,000**

Assessed Value

Next, the market value is used to compute the assessed value, which is a percentage of the market value. The exact percentage is determined by the tax class of the property. Tax class 1 is assessed at 6% of the market value, and tax classes 2,3 and 4 are assessed at 45%.

Market value		$3,048,000
Assessment ratio	x	45%
Maximum assessed value	**=**	**$1,371,600**

Transitional Value

To protect property owners from sudden large increases in property tax, the state limits how quickly the city can increase the assessed value. Typically these limits are applied when the City Assessor makes a big increase to the market value. Without the limits the assessed value would increase by a similar percentage. Instead, the change to the assessed value is phased in over a number of years.

The market value of this property was increased in previous years and the assessed value is currently being phased in. Because this property is in **tax class 4**, the assessment cannot be raised more than 8% from the year before or 30% over five years. Assessed value cannot be raised more than 45% from market value.

Assessed value		$1,371,600
Exemptions granted by city	-	$0
Net assessed value	**=**	**$1,371,600**

Transitional value		$930,510
Transitional exemption value	-	$0
Transitional net value	**=**	**$930,510**

Taxable Value

The *taxable value*, for 23/24, is the smaller of the city's net assessed value and the transitional net assessed value.

Taxable value	=	$930,510

Property Tax

Current tax is calculated by multiplying the taxable value (the assessed value minus any exemptions) by the tax rate.
The city also grants some properties incentives called tax abatements, which are subtracted directly from the current tax. This results in the property tax, the amount the current owner pays.

Note that **2022-2023** tax abatements are displayed since **2023-2024** values are not available yet.

Tax description	Billable value 23/24		Tax rate 22/23		Tax bill 23/24
Current tax	$930,510	x	10.6460%	=	$99,062
Total abatements				-	$0
Property tax				**=**	**$99,062**

For more information, you can view this property's assessment, tax bill, and account statements by clicking here and entering the Borough, Block, & Lot.

This map shows property tax in correlation with square footage of the property.

Above $10.00	$4.00 - $5.00
$9.00 - $10.00	$3.00 - $4.00
$8.00 - $9.00	$2.00 - $3.00
$7.00 - $8.00	$1.00 - $2.00
$6.00 - $7.00	Below $1.00
$5.00 - $6.00	No Data

Property tax	**$99,062**
Tax year	**2023-2024**
Square feet	**5,432**
Tax per sqft	**$18**

Permits

1. Permits

Filing date	Job number	Job type	Job status	Work type	Initial cost
12/11/2018	Q00109133-I1	Alteration	Permit issued	Electrical	
12/08/2009	420112461-01	Alteration type 2	Permit issued - entire job/work (12/29/2009)	Fire suppression	$10,000
07/31/2008	410145221-01	Alteration type 2	Plan exam - approved (09/04/2008)	Plumbing, mechanical	$20,000
12/18/2003	401448260-08	Alteration type 1	Plan exam - approved (12/18/2003)	Plumbing, mechanical	
09/16/2003	401448260-07	Alteration type 1	Plan exam - approved (09/16/2003)	Mechanical	
06/13/2003	401448260-06	Alteration type 1	Plan exam - approved (06/20/2003)	Plumbing, mechanical	
04/15/2003	401448260-05	Alteration type 1	Plan exam - approved (04/17/2003)	Plumbing	
04/14/2003	401448260-04	Alteration type 1	Paa fee due (04/14/2003)	Plumbing	
04/03/2003	401448260-03	Alteration type 1	Paa fee due (04/03/2003)	Plumbing	
04/17/2002	401448260-02	Alteration type 1	Permit issued - partial job (05/06/2003)	Plumbing	
04/17/2002	401448260-01	Alteration type 1	Permit issued - partial job (05/06/2003)		$17,000
05/11/2000	401098423-01	Alteration type 2	Signed-off (09/15/2000)		$30,000
03/27/1998	400838876-01	Alteration type 2	Plan exam - approved (04/28/1998)	Plumbing	$15,000

For more information on Job filings, please visit the DOB NOW and BIS websites.

2. Boiler Permits

Issue date	Request type	Expiration date	Primary fuel	Link to permit
01/11/2021	Certificate to operate	10/21/2023		PB033508
05/03/2010	Work permit	11/04/2010	None	PB014410

Development

1. Zoning

New York City is divided into three basic *zoning districts:* residential (R), commercial (C) and manufacturing (M). These basic zoning districts are subdivided by the intensity of use. Development is governed by the use, bulk, and parking requirements of the zoning district.

R Residential district
C Commercial district
M Manufacturing district

Rezoning Proposal Active
Rezoning Recently Adopted

This map was created from the NYC Department of City Planning's online zoning map files. It includes updates found in those files through 04/22/2020.

Zoning Designation

Manufacturing	**M1-3**

Parcel Vicinity

Frontage(s)	**21 St (wide)**

Rezoning Projects

Since	**2014**
Project	**Western Queens**
Status	**Active**

For more information about zoning district regulations, click here.

Manufacturing — M1-3



M1 districts range from the Garment District in Manhattan and Port Morris in the Bronx with multistory lofts, to parts of Red Hook or College Point with one- or two-story warehouses characterized by loading bays. M1 districts are often buffers between M2 or M3 districts and adjacent residential or commercial districts. M1 districts typically include light industrial uses, such as woodworking shops, repair shops, and wholesale service and storage facilities. M1-1, M1-2 and M1-3 districts are subject to parking requirements based on the type of use and size of an establishment. More info

Map Disclaimer: Our maps are not official zoning maps. The print version of the NYC Zoning Resolution, which includes the zoning maps, together with any amendments adopted by the City Council subsequent to the most recent update to the print version, remains the official version of the Zoning Resolution. All zoning descriptions have been taken from the NYC Planning official source.

2. Building Class

The *building class* specifies how a property is used or what type of building is present on that property. Building classes range from A to Z (excluding X). There are at most 10 different sub-classes within each building class (ranging from 0 to 10). These building classes cover all property uses from residential and commercial to government buildings and parks.

The full list of building classes can be found here.



Building class: **Auto Body/Collision or Auto Repair (G2)**

3. Floor Area Ratio & Air Rights

There are many rules that limit what you can build on a lot and how large it can be. But the most important is the Floor Area Ratio, or FAR. The FAR is expressed as a ratio of the size of the building in square feet to the size of the lot in square feet. For example, if a lot is 2,000 square feet and has an allowable FAR of 4.0, then you cannot build a building larger than 8,000 square feet. Max FAR depends on several factors including zoning, location and use.

The maximum usable floor area is calculated by multiplying the size of the lot by the larger of the residential or commercial FAR.

Area of lot in square feet		**15,000**
FAR	x	**5**
Maximum usable floor area of building	=	**75,000**

Available Air Rights by Parcel

The building on this lot is smaller than the maximum set by the FAR. Thus it may be possible to add to the building (either more floors or an extension) or it may be possible to sell the "air rights" to a developer who owns a nearby lot. (Note: other factors may limit what you can do.)

Maximum usable floor area		**75,000**
Usable floor area	-	**5,400**
Unused buildable square feet ("air rights")	=	**69,600**





Commercial FAR	**5**
Facility FAR	**6.5**
FAR as built	**0.36**

4. Urban Landscape Maps



Click on the map to expand.

Year built: **1938**

On this color-coded map, view the year each property was built.

- >2020
- 2011-2020
- 2001-2010
- 1981-2000
- 1961-1980
- 1941-1960
- 1900-1940
- <1900



Click on the map to expand.

Stories: **1**

On this map, view the number of stories per building.

- 10 & Up stories
- 7 to 9 Stories
- 5 to 6 Stories
- 4 Stories
- 3 Stories
- 2 Stories
- 1 Story
- No data

5. Planimetric Map

This planimetric map shows features such as retaining walls, sidewalks, medians, curbs, and roadbeds that have been digitized from aerial photography. These features must be taken into consideration when determining how a new building, or extensions to an existing building, are situated within the lot. They can also affect the maximum height that can be built.



BIN	**4004422**
Type	**Building**
Status	**Constructed**
Roof height	**16 ft**
Ground elevation	**16 ft**

6. HPD Alternative Enforcement Program

The HPD Alternative Enforcement Program map is based on the current month's HPD violations in a building divided by the number of units in the building. It takes in consideration the open hazardous and immediately hazardous violations (I/B/C class) in the last 5 years.



For more information, visit the HPD website.

Neighborhood

1. Transportation

On this color-coded map, view the nearest subway station for each building.



Closest station	**21st St & 41st Ave at NE Corner**
Station lines	**F**
Distance (miles)	**0.32**

On this map, view the closest local or express bus routes and stations.



Name	**21 ST/37 Av**
Distance (miles)	**0.048**

2. Distance to Schools

Elementary School Proximity

This map shows zoned Elementary School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Elementary schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **P.S. 111 Jacob Blackwell**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
P.S. 111 Jacob Blackwell	4	Yes	Public	PK-8	334	0.08
Voice Charter School of New York	7	No	Charter	K-8	684	0.18
P.S. 112 Dutch Kills	6	No	Public	PK-5	455	0.22
P.S. 76 William Hallett	3	No	Public	PK-5	442	0.26
Growing Up Green Ii	NR	No	Charter	K-1		0.35
Growing Up Green Charter School	6	No	Charter	K-8	826	0.36
P.S. 166 Henry Gradstein	8	No	Public	PK-5	998	0.62
The Child School	NR	No	Private	K-12	340	0.67
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.67
P.S. 384	NR	No	Public	K	35	0.68
Queens Paideia School	NR	No	Private		28	0.71
Ideal Islamic School	NR	No	Private	PK-6	41	0.74
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.75
Lagcc Early Childhood Learning	NR	No	Private	PK-3		0.84
The Town School	NR	No	Private	PK-8	402	0.95

Find more info at NYC Department of Education



Middle School Proximity

This map shows zoned Middle School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

Middle schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Is 204 Oliver W Holmes**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Is 204 Oliver W Holmes	6	Yes	Public	6-8	460	0.30
P.S. 111 Jacob Blackwell	4	No	Public	PK-8	334	0.08
Voice Charter School of New York	7	No	Charter	K-8	684	0.18
Growing Up Green Charter School	6	No	Charter	K-8	826	0.36
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.62
The Child School	NR	No	Private	K-12	340	0.67
P.S. Is 217 Roosevelt Island	8	No	Public	PK-8	615	0.67
Albert Shanker School For Visual And Performing Ar	6	No	Public	6-8	688	0.71
Queens Paideia School	NR	No	Private		28	0.71
Our World Neighborhood Charter School	7	No	Charter	K-8	734	0.75
The Town School	NR	No	Private	PK-8	402	0.95
Evangel Christian School	NR	No	Private	PK-12	463	0.96
Most Precious Blood School	NR	No	Private	PK-8	312	0.96
Academy For New Americans	6	No	Public	6-8	109	1.01

Find more info at NYC Department of Education



High School Proximity

This map shows zoned High School and other public and private schools available in the area, with exact distances from the subject property to the school of interest.

High schools
District boundary
Attendance zone
Unzoned area

School locations
Zoned
Other public
Charter
Private

Name **Long Island City High School**

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Long Island City High School	3	Yes	Public	9-12	2,263	0.60

Name	Rating	Att. zoned	Type	Grade range	No of students	Distance to school (mi)
Energy Tech High School	4	No	Public	9-12	534	0.30
Academy of American Studies	7	No	Public	9-12	1,002	0.45
Newcomers High School	4	No	Public	9-12	824	0.45
Baccalaureate School for Global Education	6	No	Public	7-12	536	0.62
The Child School	NR	No	Private	K-12	340	0.67
Frank Sinatra School Of The Arts High School	6	No	Public	9-12	856	0.69
Queens Paideia School	NR	No	Private		28	0.71
Information Technology High School	4	No	Public	9-12	1,005	0.79
Bard High School Early College Queens	8	No	Public	9-12	643	0.91
Academy of Finance and Enterprise	8	No	Public	9-12	646	0.92
High School Of Applied Communications	5	No	Public	9-12	404	0.92
Evangel Christian School	NR	No	Private	PK-12	463	0.96
Middle College High School At Laguardia Community	4	No	Public	9-12	509	1.03
International High School at Laguardia Community College	3	No	Public	9-12	510	1.03

Find more info at NYC Department of Education

3. Traffic Map



Estimated average daily traffic volume on a route segment at a particular count location.

Average daily traffic
- 75001 - 300000
- 25001 - 75000
- 10001 - 25000
- 4001 - 10000
- 1501 - 4000
- 1 - 1500

4. Demographics By Zip Code

Demographic data shown in this section was gathered from the 2021 American Community Survey and refers to zip code **11101**.

Population Demographics

Total population	**33,789**
Female population	**49.4%**
Male population	**50.6%**
Median age	**34**
Male median age	**34.8**
Female median age	**33.4**

Education

No highschool	**5.4%**
Some highschool or college	**31.4%**
Bachelors degree	**34.0%**

Other

Citizens	**80.3%**
Citizens born in US	**59.5%**
English speakers	**94.2%**

Journey to Work

Work in a metropolitan area	**99.9%**
Work in a micropolitan area	**0.1%**
Work at home	**17.9%**
Go to work by car	**13.2%**
Go to work after 10 am	**12.2%**

Economic/Employment

Average household income	**$130,719**
White collar	**90.6%**
Blue collar	**9.4%**

Housing

Family households	**44.3%**
Households with kids	**20.4%**
Housing units	**23,015**
Occupied housing units	**15,764**
Owner occupied units	**15.5%**
Average number of people per household	**2.1**
Median year structure built	**2002**
Houses with mortgages	**74.8%**

Wealth

Median value for units with a mortgage	**$977,200**
Median value for units without a mortgage	**$937,500**
Median gross rent	**$2,221**
Median mobile home values	**$0**
Median housing costs per month	**$2,343**
Population in poverty	**12.9%**

Violations

1. HPD Violations

When excessive violations are present, this can adversely affect the support given by The NYC Department of Housing Preservation and Development (HPD). These violations can result in building-wide inspections, fees, and the requirement of extensive repair work to correct underlying conditions. In some cases, outstanding violations may result in a lien being placed on the property. It is also substantially more difficult to mortgage a building with extensive violations.

We do not have any record of violations in our database. Status can be verified here.

2. 311 Complaints

Created	Agency	Type	Descriptor	Disposition	Closed
01/04/2022	DEP	Water system	Hydrant knocked over/missing (WC)		
09/27/2021	DEP	Water system	Hydrant defective (WC2)		
10/20/2020	DEP	Hazardous materials	Oil spill on street, large (HQL)	The Department of Environmental Protection investigated this complaint and determined that no further action is required.	10/20/2020
10/20/2020	DEP	Hazardous materials	Oil spill on street, large (HQL)		
11/04/2019	DCA	Consumer complaint	Garage/parking lot	The Department of Consumer Affairs has already mailed you a complaint form. In order for DCA to be a	
10/10/2017	NYPD	Non-emergency police matter	Other (complaint details)	The Police Department responded to the complaint and took action to fix the condition.	10/10/2017
12/23/2016	DCA	Consumer complaint	Unlicensed	The Department of Consumer Affairs has determined that this issue is not within its jurisdiction. It has been referred to the New York Police Department.	12/27/2016
03/23/2016	DCA	Consumer complaint	Non-delivery goods/services	The Department of Consumer Affairs mailed you a complaint form. If you received the form and have not yet completed it, please do so. Be sure to follow the instructions on the form and return it to DCA with all required documentation. 311 can assist those who have not received the complaint form by creating a new Service Request. Additionally, 311 can assist those who returned the form but want to inquire about the status of the filed complaint.	04/08/2016
07/21/2015	DCA	Consumer complaint	Overcharge	The Department of Consumer Affairs has determined that this issue is not within its jurisdiction. It has been referred to the Department of Motor Vehicles.	07/27/2015
03/20/2015	DCA	Consumer complaint	Overcharge	The Department of Consumer Affairs mailed you a complaint form. If you received the form and have not yet completed it, please do so. Be sure to follow the instructions on the form and return it to DCA with all required documentation. 311 can assist those who have not received the complaint form by creating a new Service Request. Additionally, 311 can assist those who returned the form but want to inquire about the status of the filed complaint.	04/05/2015
11/13/2014	DCA	Consumer complaint	Damaged/defective goods	The Department of Consumer Affairs mailed you a complaint form. If you received the form and have not yet completed it, please do so. Be sure to follow the instructions on the form and return it to DCA with all	11/29/2014

Created	Agency	Type	Descriptor	Disposition	Closed
				required documentation. 311 can assist those who have not received the complaint form by creating a new Service Request. Additionally, 311 can assist those who returned the form but want to inquire about the status of the filed complaint.	
08/06/2014	DCA	Consumer complaint	Exchange/refund/return	The Department of Consumer Affairs mailed you a complaint form. If you received the form and have not yet completed it, please do so. Be sure to follow the instructions on the form and return it to DCA with all required documentation. 311 can assist those who have not received the complaint form by creating a new Service Request. Additionally, 311 can assist those who returned the form but want to inquire about the status of the filed complaint.	08/22/2014
05/23/2014	TLC	For hire vehicle complaint	Car service company complaint	The Taxi and Limousine Commission will send a confirmation letter in 14 days to confirm your complaint details. At the hearing you may be required to provide information regarding this complaint. Please note your Service Request number for future reference.	07/14/2014
07/25/2012	DCA	Consumer complaint	Cars parked on sidewalk/street	The Department of Consumer Affairs is scheduling an inspection which will take place within 35 days. Please do not file duplicate complaints or call to check results during this time. After 35 days, call 311 with your Service Request Number and ask for Service Request Status - DCA.	07/26/2012
03/01/2012	DEP	Water system	Hydrant defective (WC2)	The Department of Environmental Protection investigated this complaint and repaired or replaced the hydrant.	03/08/2012

Complaint status can be verified here.

3. DOB Complaints

Date entered	Complaint	Complaint category	Disposition	Inspection
11/04/2020	4828103	Failure to comply with vacate order	ECB violation served	11/04/2020
01/18/2019	4760745	Electrical wiring defective/exposed, in progress	No violation warranted for complaint at time of inspection	01/23/2019
12/04/2018	4756569	Electrical wiring defective/exposed, in progress	ECB violation served	12/05/2018
08/23/2018	4745226	Electrical wiring defective/exposed, in progress	ECB violation served	09/04/2018
07/03/2018	4738758	Electrical wiring defective/exposed, in progress	Partial stop work order	07/05/2018
06/20/2018	4737188	Permit - none (building/PA/demo etc.)	ECB violation served	08/02/2018
06/05/2018	4735321	Permit - none (building/PA/demo etc.)	ECB violation served	07/14/2018
05/24/2018	4733955	Permit - none (building/PA/demo etc.)	No violation warranted for complaint at time of inspection	06/25/2018
08/02/2017	4701183	Construction - contrary/beyond approved plans/permits	No violation warranted for complaint at time of inspection	09/26/2017
06/10/2011	4483815	Building shaking/vibrating/struct stability affected	Violation served for disobeying vacate order	06/10/2011
05/26/2011	4482282	Certificate of occupancy - none/illegal/contrary to CO	Partial vacate order served	06/03/2011
09/14/2007	4322671	Permit - none (building/PA/demo etc.)	No violation warranted for complaint at time of inspection	10/26/2007
05/15/1997	4064348	Permit - none (building/PA/demo etc.)	Buildings violations(s) served	06/13/1997

Complaint status can be verified here.

4. DOB Violations

Violation ID	Issue date	Type	Status
V100318AEUHAZ100501	10/03/2018	Aeuhaz1-fail to certify class 1	
Failure to certify correction on immediately hazardous (class 1) ecb violation 06/14/2021 - 000810 paid invoice 90445405			
V*082411AEUHAZ100315	08/24/2011	Aeuhaz1-fail to certify class 1	Dismissed
Failure to certify correction on immediately hazardous (class 1) ecb violation 11/22/2011 - ECB dismissed			
V082411AEUHAZ100316	08/24/2011	Aeuhaz1-fail to certify class 1	Active
Failure to certify correction on immediately hazardous (class 1) ecb violation			
VPW*061397CC01K03	06/13/1997	C-construction	Dismissed

Please note: the NYC Department of Buildings is the only authoritative source for information on DOB violations. Verify the status of the violation on DOB website.

Records are obtained from DOB and updated daily.

5. ECB Violations

There are eleven city agencies that administer the City's quality-of-life laws and issue Notices of Violation (NOVs) for alleged violations. The ECB is a separate and independent agency that hears challenges to those NOVs. The agencies that issue the most violations for real estate are:

- Department of Buildings (DOB)
- Department of Environmental Protection (DEP)
- Fire Department (FDNY)
- Landmarks Preservation Commission (LPC)
- Department of Sanitation (DSNY)

Violation ID	Issue date	Type	Severity	Status	Link to violation
39031537P	11/04/2020	Construction		Active	
Observed wood shelf structure erected with wood posts, wood beams, and plywood at right side of the garage bay #4 used for storage of automobile tires. Ecb summons issued., obtain all permits					
39031540X	11/04/2020	Construction		Active	
Observed illegal construction at garage bay # 3. Wood studs and wood frame and sheet rock structure constructed and used as office space at the rear of the garage. Work done no permit., obtain all permits					
35358730X	12/05/2018	Construction		Active	
An unlawful act. Failure to comply w/ an order of the commissioner. Failure to correct and certify summons#35313582y which was issued to youon 7/5/18 for electrical work w/o a permit. Remedy:obtain permit/compl					
35074728M	04/12/2016	Construction		Active	
Altered/changed bldg occupied w/o a valid certificate of occupancy as per subsection 28-118.3.1 - 28-118.3.2. Noted: building occupied consistent with alt#1 application, job #40144260 last inspected for constru					
34909364R	05/25/2011	Construction		Resolve	
Failure to maintain.noted:improper storage of flammable paints.also noted:exhaust fan blowing out side of bldg w/ no filters.also no permit for spraybooth.rem:make safe conform to bldg code.					
34909362N	05/25/2011	Unknown		Active	
28-118.1)altered bldg occupied w/o valid c of o appl#401448260 filed in 2003 prior to new code.to erect metal shed bldg.now bldg occupied as mechanical shops w/ offices in shipping containers.rem:vacate bldg.pr					
34909363P	05/25/2011	Construction		Active	
Work w/o permit.illegal work noted:shipping containers stack 2 high making offices 3pcs bathroom shower,toilet,sink,gas heater,q-deck roof.stop all work!rem:obtain permit contact this office before returning to					

Please note: the NYC Department of Buildings is the only authoritative source for information on ECB violations. Verify the status of the violation on DOB website.

Records are obtained from ECB and updated weekly.

6. Marshals Evictions

Executed date	Court index	Docket	Eviction apartment	Ejectment	Removal type
09/28/2017	75201/16-1	292221		No	Legal possession

Find more info at NYC Department of Investigation.

7. Neighborhood Complaints

Created	Agency	Type	Descriptor	Disposition	Closed
07/05/2023	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and determined that police action was not necessary.	07/05/2023
07/05/2023	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and determined that police action was not necessary.	07/05/2023
05/09/2023	NYPD	Illegal parking	Blocked crosswalk	The Police Department responded to the complaint and took action to fix the condition.	05/09/2023
04/05/2023	NYPD	Illegal parking	Blocked crosswalk	The Police Department responded and upon arrival those responsible for the condition were gone.	04/05/2023
04/04/2023	NYPD	Illegal parking	Blocked crosswalk		
03/06/2023	NYPD	Illegal parking	Posted parking sign violation	The Police Department responded and upon arrival those responsible for the condition were gone.	03/06/2023
02/12/2023	NYPD	Blocked driveway	No access	The Police Department issued a summons in response to the complaint.	02/12/2023
07/31/2022	NYPD	Blocked driveway	No access	The Police Department issued a summons in response to the complaint.	07/31/2022
07/21/2022	NYPD	Illegal parking	Double parked blocking traffic	The Police Department responded to the complaint and took action to fix the condition.	07/21/2022
02/12/2022	NYPD	Illegal parking	Blocked hydrant	The Police Department responded to the complaint and with the information available observed no evidence of the violation at that time.	02/12/2022
02/11/2022	NYPD	Illegal parking	Blocked sidewalk	The Police Department responded to the complaint and took action to fix the condition.	02/11/2022
12/24/2021	NYPD	Blocked driveway	No access	The Police Department responded to the complaint and took action to fix the condition.	12/24/2021
11/13/2021	NYPD	Blocked driveway	No access	The Police Department issued a summons in response to the complaint.	11/13/2021
11/11/2021	NYPD	Blocked driveway	No access	The Police Department issued a summons in response to the complaint.	11/11/2021
09/16/2021	NYPD	Illegal parking	Blocked sidewalk	The Police Department responded to the complaint and took action to fix the condition.	09/16/2021

Risk

1. Toxic Sites

Get a Phase I environmental report Site Assessment or a Home Environmental Database Report for this property directly from Toxics Targeting.

This screening map, provided to by Toxics Targeting, shows environmental hazards such as toxic dumps, garbage landfills, leaking tanks, hazardous waste sites, and pollution discharges reported by local, state and federal government authorities.

Call 800-2-TOXICS (800-286-9427 NYS only) or 607-273-3391 for more info.



Toxic Sites on the Property

Spill	1
Petroleum bulk storage	4
Haz waste generator or transporter	1
Gasoline spill	1
Spill greater than 25 gal/lbs	1
Solid waste facility	1
Total toxic sites on the property	9

Toxic Sites near the Property

Air discharge facility	1
Petroleum bulk storage	1
Haz waste generator or transporter	2
Spill	1
Total neighboring toxic sites	5

Map Disclaimer: Mapped locations are approximate; sites are identified based on current and/or historic information. Regulatory status of sites may have changed. Site symbols can refer to large properties, additional toxic sites are not mapped. Contamination problems can impact properties far from toxic sources. Sites include known and potential hazards.

2. FEMA Flood Zones

Use this map to determine if the property is in a flood zone.



Link to the map for this property at **FEMA's Map Service Center** (may not be available in all locations).

FEMA Flood Zoning

FEMA flood zone(s)	**X**
Coastal barrier resources system area (COBRA)	**Out**
Floodway	**Out**
FEMA special flood hazard area	**Out**
Map panel ID	**3604970089F**
Map quaderant ID	**40073-G8**

Distance to...

Nearest distance to coastline (miles)	**0.451**
Compass direction to coastline	**147**
Nearest distance to 100 year flood zone area (ft)	**208**
Angle100	**278**

3. Hurricane Evacuation Zones



Zone: **4**

This map shows hurricane evacuation zones. In the case of coastal storms, the City may order the evacuation of neighborhoods in danger of flooding, the most critical being Zone 1.

Hurricane evacuation zones
- Zone 1
- Zone 2
- Zone 3
- Zone 4
- Zone 5
- Zone 6

Disclaimer

Copyright 2003-2023 by Property Research Partners LLC

All data comes from government sources. No attempt has been made to validate it. No attempt has been made to validate the accuracy of the programming of this web site. Do not rely on this report to support investment decisions. The only authoritative source for the information in this report is the government agencies from which the data was acquired.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

37-05 21 STREET — **QUEENS 11101** — **BIN# 4004423**

21 STREET 37-05 - 37-05

Health Area	: 710	**Tax Block**	: 364
Census Tract	: 33.02	**Tax Lot**	: 12
Community Board	: 401	**Condo**	: NO
Buildings on Lot	: 2	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	37 AVENUE, 14 STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO

Additional BINs for Building: NONE
Additional Designation(s): IBZ - INDUSTRIAL BUSINESS ZONE

HPD Multiple Dwelling: No

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	0	0
Violations-OATH/ECB	0	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Total Actions	0	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

37-07 21 STREET — **QUEENS 11101** — **BIN# 4615979**

21 STREET 37-07 - 37-07

Health Area	: 710	**Tax Block**	: 364
Census Tract	: 33.02	**Tax Lot**	: 12
Community Board	: 401	**Condo**	: NO
Buildings on Lot	: 2	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	37 AVENUE, 14 STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	2	0
Violations-DOB	5	1
Violations-OATH/ECB	1	1
Jobs/Filings	1	
ARA / LAA Jobs	0	
Total Jobs	1	
Actions	5	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 37-07 21 STREET QUEENS **BIN: 4615979 Block: 364 Lot: 12**

NUMBER		TYPE	FILE DATE
ALT 1850-57		ALTERATION	00/00/0000
ALT 805-78		ALTERATION	00/00/1978
COQ 128871	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	05/15/1959
LNO 5912		LETTER OF NO OBJECTION	06/01/2011
LNO Use: DENIED REPAIR SHOP			
LNO Floor: FLOOR (LNO#3699)			
Comments: FILE BIS APPLICATION WITH DOB TO LEGALIZE USE.			
PRS 6651-58		PLUMBING REPAIR SLIP	00/00/1958
V* 051276C442R		DOB VIOLATION - DISMISSED	08/08/1976
DISMISSAL DATE: 01/24/1985			**BADGE NO.:** 0000
V* 051276C443R		DOB VIOLATION - DISMISSED	08/08/1976
DISMISSAL DATE: 01/24/1985			**BADGE NO.:** 0000
V* 060677ES018-LEGAL		DOB VIOLATION - CLOSED	00/00/1977
CLOSURE DATE: 09/28/2011			
V* 100577C447RLEGAL		DOB VIOLATION - DISMISSED	01/24/1977
DISMISSAL DATE: 01/24/1984			**BADGE NO.:** 0000
V 042308C0103WT		DOB VIOLATION - ACTIVE	04/23/2008
VECL 042308C01WT02		VIOLATION ECB LIEN - ACTIVE	04/23/2008

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

37-11 21 STREET — **QUEENS 11101** — **BIN# 4801041**

21 STREET 37-11 - 37-11

Health Area	: 710	**Tax Block**	: 364
Census Tract	: 33.02	**Tax Lot**	: 12
Community Board	: 401		

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	37 AVENUE, 14 STREET		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO

Additional BINs for Building: NONE
Additional Designation(s): IBZ - INDUSTRIAL BUSINESS ZONE

HPD Multiple Dwelling: No

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	0	0
Violations-DOB	16	16
Violations-OATH/ECB	1	0
Jobs/Filings	5	
ARA / LAA Jobs	0	
Total Jobs	5	
Actions	9	

OR Enter Action Type:
OR Select from List: Select...
AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 37-11 21 STREET QUEENS **BIN: 4801041 Block: 364 Lot: 12**

NUMBER		TYPE	FILE DATE
ALT 2770-46		ALTERATION	00/00/1946
ALT 1850-57		ALTERATION	00/00/1957
ALT 1805-64		ALTERATION	00/00/1964
ALT 805-78		ALTERATION	00/00/1978
COQ 25529	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	08/08/1942
COQ 128871	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	00/00/1957
COQ 159720	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	00/00/1964
MISC 1558-42		MISCELLANEOUS	00/00/1942
NB 1489-32		NEW BUILDING	00/00/1932
V 082995LL629139553		DOB VIOLATION - ACTIVE	08/29/1995
V 050498LL629128692		DOB VIOLATION - ACTIVE	05/04/1998
V 031699LL629124901		DOB VIOLATION - ACTIVE	03/16/1999
V 020700LL629125177		DOB VIOLATION - ACTIVE	02/07/2000
V 022701LL629124790		DOB VIOLATION - ACTIVE	02/27/2001
V 013105LL629126529		DOB VIOLATION - ACTIVE	01/31/2005
V 010606LL629125196		DOB VIOLATION - ACTIVE	01/06/2006
V 011907LL629125727		DOB VIOLATION - ACTIVE	01/19/2007
V 010308LL629125715		DOB VIOLATION - ACTIVE	01/03/2008
V 010109LL629125599		DOB VIOLATION - ACTIVE	01/01/2009
V 123109LBLVIO25533		DOB VIOLATION - ACTIVE	12/31/2009
V 121311LBLVIO22274		DOB VIOLATION - ACTIVE	12/13/2011
V 030113LBLVIO16846		DOB VIOLATION - ACTIVE	03/01/2013
V 051514LBLVIO18995		DOB VIOLATION - ACTIVE	05/15/2014
V 030315LBLVIO13996		DOB VIOLATION - ACTIVE	03/03/2015
V 100115LBLVIO14334		DOB VIOLATION - ACTIVE	10/01/2015

Next

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 37-11 21 STREET QUEENS **BIN: 4801041 Block: 364 Lot: 12**

NUMBER	TYPE	FILE DATE
VEC* 033000C401RR02	ECB VIOLATION DISMISSED	03/30/2000

Previous

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

37-25 21 STREET — **QUEENS 11101** — **BIN# 4615983**

21 STREET 37-25 - 37-25

Health Area	: 710	**Tax Block**	: 364
Census Tract	: 33.02	**Tax Lot**	: 6
Community Board	: 401	**Condo**	: NO
Buildings on Lot	: 2	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

Cross Street(s):	14 STREET, 38 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
Additional BINs for Building:	NONE		
HPD Multiple Dwelling:	No		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	7	0
Violations-DOB	1	0
Violations-OATH/ECB	5	0
Jobs/Filings	0	
ARA / LAA Jobs	0	
Total Jobs	0	
Total Actions	0	

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Property Profile Overview

37-27 21 STREET **QUEENS 11101** **BIN# 4004422**

21 STREET	37-25 B - 37-25 B	**Health Area**	: 710	**Tax Block**	: 364
21 STREET	37-27 - 37-27	**Census Tract**	: 33.02	**Tax Lot**	: 6
		Community Board	: 401	**Condo**	: NO
		Buildings on Lot	: 2	**Vacant**	: NO

View DCP Addresses... Browse Block

View Zoning Documents | View Challenge Results | Pre - BIS PA | View Certificates of Occupancy

PARTIAL VACATE EXISTS ON THIS PROPERTY

VIOLATION FOR FAILURE TO CERTIFY CORRECTION OF CLASS 1 VIOLATION EXISTS ON THIS PROPERTY - DOB CIVIL PENALTIES DUE

Cross Street(s):	14 STREET, 38 AVENUE		
DOB Special Place Name:			
DOB Building Remarks:			
Landmark Status:		**Special Status:**	N/A
Local Law:	NO	**Loft Law:**	NO
SRO Restricted:	NO	**TA Restricted:**	NO
UB Restricted:	NO		
Environmental Restrictions:	N/A	**Grandfathered Sign:**	NO
Legal Adult Use:	NO	**City Owned:**	NO
LL 158/17 Pro Cert Restriction until:	N/A		
LL 158/17 Enhanced Civil Penalties:	Yes		
Additional BINs for Building:	4615983		
Additional Designation(s):	IBZ - INDUSTRIAL BUSINESS ZONE		
HPD Multiple Dwelling:	No		
Number of Dwelling Units:	0		

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. Click here for more information

Department of Finance Building Classification: G2-GARAGE/GAS STAT'N

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open
Complaints	8	0
Violations-DOB	5	1
Violations-OATH/ECB	7	6

This property has **4** open OATH/ECB "Work Without A Permit" Violations and may be subject to DOB civil penalties upon application for a permit. After obtaining the permit, a certificate of correction must be filed on the ECB violations.

Jobs/Filings	14
ARA / LAA Jobs	2
Total Jobs	16
Actions	11

OR Enter Action Type:

OR Select from List: Select...

AND Show Actions

Elevator Records
Electrical Applications
Permits In-Process / Issued
Illuminated Signs Annual Permits
Plumbing Inspections
Open Plumbing Jobs / Work Types
Facades
Marquee Annual Permits
Boiler Records
DEP Boiler Information
Crane Information
After Hours Variance Permits

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Actions

Premises: 37-27 21 STREET QUEENS **BIN: 4004422 Block: 364 Lot: 6**

NUMBER		TYPE	FILE DATE
ALT 1923-37		ALTERATION	00/00/1937
ALT 1388-50EX		ALTERATION	08/08/1950
ALT 1702-55		ALTERATION	08/08/1955
ALT 1805-64		ALTERATION	08/08/1964
ALT 587-76		ALTERATION	00/00/1976
COQ 131910	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	08/08/1955
COQ 125635	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	08/08/1955
COQ 159720	(PDF)	CERTIFICATE OF OCCUPANCY - QUEENS	08/08/1964
LNO 2416		LETTER OF NO OBJECTION	02/06/2007
LNO Use: APPROVED USED CAR SALES			
LNO Floor: OSP			
Comments: AS PER C OF O NO. Q159720.			
PRS 4062-51		PLUMBING REPAIR SLIP	08/08/1951
V* 061681C442B1LEGAL		DOB VIOLATION - DISMISSED	08/08/1981
DISMISSAL DATE: 12/30/1983			**BADGE NO.:** 0000
V* 010885C444E2		DOB VIOLATION - CLOSED	00/00/1985
CLOSURE DATE: 09/28/2011			
VACP Q363/11.RESCINDED.ERROR			05/30/2011
VPW* 061397CC01K03		VIOLATION UNSERVED ECB-WORK WITHOUT PERMIT-DISMI	06/13/1997
V* 082411AEUHAZ100315		DOB VIOLATION - DISMISSED	08/24/2011
V 082411AEUHAZ100316		DOB VIOLATION - ACTIVE	08/24/2011
VECL 052511CSTFGM20		VIOLATION ECB LIEN - ACTIVE	05/25/2011
VECL 041216C01RB01		VIOLATION ECB LIEN - ACTIVE	04/12/2016
VECL 052511CSTFGM21		VIOLATION ECB LIEN - ACTIVE	05/25/2011
VECL 071418C01MA03		VIOLATION ECB LIEN - ACTIVE	07/14/2018
VECL		VIOLATION ECB LIEN - ACTIVE	11/04/2020
VECL		VIOLATION ECB LIEN - ACTIVE	11/04/2020
VEC* 052511CSTFGM22		ECB VIOLATION DISMISSED	05/25/2011

Select Violation Type: Show All Violations Refresh

If you have any questions please review these Frequently Asked Questions, the Glossary, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.

3707 21ST ST, LONG ISLAND CITY, NY 11101-3502



Property Detail Report

For Property Located At :
3707 21ST ST, LONG ISLAND CITY, NY 11101-3502

CoreLogic RealQuest Professional

Owner Information

Owner Name:	**YARDLEY ASSOCIATES LLC**
Mailing Address:	**PO BOX 237, COLD SPRING HARBOR NY 11724-0237 B002 C/O YARDLY ASSOCIATES LLC**
Vesting Codes:	/ / CO

Location Information

Legal Description:			
County:	QUEENS, NY	APN:	00364-0012
Census Tract / Block:	33.02 / 2	Alternate APN:	
Township-Range-Sect:	02-00-03	Subdivision:	
Legal Book/Page:		Map Reference:	03-02-01 /
Legal Lot:	12	Tract #:	
Legal Block:	364	School District:	3620580
Market Area:		School District Name:	NYC DEPT OF ED
Neighbor Code:		Munic/Township:	ASTORIA-LONG ISLAND CITY

Owner Transfer Information

Recording/Sale Date:	04/10/2008 / 02/28/2008	Deed Type:	DEED (REG)
Sale Price:		1st Mtg Document #:	
Document #:	143929		

Last Market Sale Information

Recording/Sale Date:	10/11/1984 / 08/08/1984	1st Mtg Amount/Type:	/
Sale Price:		1st Mtg Int. Rate/Type:	/
Sale Type:		1st Mtg Document #:	
Document #:	1753-1660	2nd Mtg Amount/Type:	/
Deed Type:	DEED (REG)	2nd Mtg Int. Rate/Type:	/
Transfer Document #:		Price Per SqFt:	
New Construction:		Multi/Split Sale:	
Title Company:			
Lender:			
Seller Name:			

Prior Sale Information

Prior Rec/Sale Date:	10/11/1984 / 09/25/1984	Prior Lender:	
Prior Sale Price:		Prior 1st Mtg Amt/Type:	/
Prior Doc Number:	1753-1658	Prior 1st Mtg Rate/Type:	/
Prior Deed Type:	DEED (REG)		

Property Characteristics

Year Built / Eff:	1910 /	Total Rooms/Offices		Garage Area:	
Gross Area:	3,600	Total Restrooms:		Garage Capacity:	
Building Area:	3,600	Roof Type:		Parking Spaces:	
Tot Adj Area:		Roof Material:		Heat Type:	
Above Grade:	2,160	Construction:		Air Cond:	
# of Stories:	1	Foundation:		Pool:	
Other Improvements:		Exterior wall:		Quality:	
		Basement Area:		Condition:	

Site Information

Zoning:	M1-3	Acres:	0.39	County Use:	GARAGE 1 STRY SEMI-FIREPROOF (G2)
Lot Area:	16,815	Lot Width/Depth:	177 x 95	State Use:	
Land Use:	GARAGE	Res/Comm Units:	3 / 3	Water Type:	
Site Influence:				Sewer Type:	

Tax Information

Total Value:	$303,300	Assessed Year:	2022	Property Tax:	$21,222.57
Land Value:	$212,850	Improved %:	30%	Tax Area:	4
Improvement Value:	$90,450	Tax Year:	2022	Tax Exemption:	
Total Taxable Value:	$303,300				

Property Detail Report

For Property Located At :
3712 22ND ST REAR, LONG ISLAND CITY, NY 11101

CoreLogic RealQuest Professional

Owner Information

Owner Name:	**YARDLEY ASSOCIATES LLC**
Mailing Address:	**PO BOX 237, COLD SPRING HARBOR NY 11724-0237 B002**
Vesting Codes:	/ / CO

Location Information

Legal Description:			
County:	QUEENS, NY	APN:	00364-0135
Census Tract / Block:	33.02 / 2	Alternate APN:	
Township-Range-Sect:	02-00-03	Subdivision:	
Legal Book/Page:		Map Reference:	03-02-01 /
Legal Lot:	135	Tract #:	
Legal Block:	364	School District:	3620580
Market Area:		School District Name:	NYC DEPT OF ED
Neighbor Code:		Munic/Township:	ASTORIA-LONG ISLAND CITY

Owner Transfer Information

Recording/Sale Date:	04/10/2008 / 01/16/2008	Deed Type:	DEED (REG)
Sale Price:		1st Mtg Document #:	
Document #:	143932		

Last Market Sale Information

Recording/Sale Date:	06/21/1990 / 06/13/1990	1st Mtg Amount/Type:	/
Sale Price:		1st Mtg Int. Rate/Type:	/
Sale Type:		1st Mtg Document #:	
Document #:	3014-1367	2nd Mtg Amount/Type:	/
Deed Type:	DEED (REG)	2nd Mtg Int. Rate/Type:	/
Transfer Document #:		Price Per SqFt:	
New Construction:		Multi/Split Sale:	
Title Company:			
Lender:			
Seller Name:			

Prior Sale Information

Prior Rec/Sale Date:	07/09/1987 / 07/07/1987	Prior Lender:	
Prior Sale Price:		Prior 1st Mtg Amt/Type:	/
Prior Doc Number:	2402-1890	Prior 1st Mtg Rate/Type:	/
Prior Deed Type:	DEED (REG)		

Property Characteristics

Year Built / Eff:	/	Total Rooms/Offices		Garage Area:	
Gross Area:		Total Restrooms:		Garage Capacity:	
Building Area:		Roof Type:		Parking Spaces:	
Tot Adj Area:		Roof Material:		Heat Type:	
Above Grade:		Construction:		Air Cond:	
# of Stories:		Foundation:		Pool:	
Other Improvements:		Exterior wall:		Quality:	
		Basement Area:		Condition:	

Site Information

Zoning:	M1-3	Acres:	0.01	County Use:	VACANT NOT ZONED RESIDENTIAL (V1)
Lot Area:	600	Lot Width/Depth:	20 x 30	State Use:	
Land Use:	VACANT LAND (NEC)	Res/Comm Units:	/	Water Type:	
Site Influence:				Sewer Type:	

Tax Information

Total Value:	$10,350	Assessed Year:	2022	Property Tax:	$700.10
Land Value:	$10,350	Improved %:		Tax Area:	4
Improvement Value:		Tax Year:	2022	Tax Exemption:	
Total Taxable Value:	$7,560				

Property Detail Report

For Property Located At :
3725 21ST ST, LONG ISLAND CITY, NY 11101-6049

CoreLogic RealQuest Professional

Owner Information

Owner Name:	**YARDLEY ASSOCIATES LLC**
Mailing Address:	**PO BOX 237, COLD SPRING HARBOR NY 11724-0237 B002**
Vesting Codes:	/ / CO

Location Information

Legal Description:			
County:	QUEENS, NY	APN:	00364-0006
Census Tract / Block:	33.02 / 2	Alternate APN:	
Township-Range-Sect:	02-00-03	Subdivision:	PROPERTY/ELIZABETH FREEMAN REV
Legal Book/Page:		Map Reference:	03-02-01 /
Legal Lot:	6	Tract #:	
Legal Block:	364	School District:	3620580
Market Area:		School District Name:	NYC DEPT OF ED
Neighbor Code:		Munic/Township:	ASTORIA-LONG ISLAND CITY

Owner Transfer Information

Recording/Sale Date:	04/10/2008 / 03/12/2008	Deed Type:	DEED (REG)
Sale Price:		1st Mtg Document #:	
Document #:	143673		

Last Market Sale Information

Recording/Sale Date:	12/03/1990 / 11/19/1990	1st Mtg Amount/Type:	/
Sale Price:	$74,500	1st Mtg Int. Rate/Type:	/
Sale Type:		1st Mtg Document #:	
Document #:	3092-2004	2nd Mtg Amount/Type:	/
Deed Type:	DEED (REG)	2nd Mtg Int. Rate/Type:	/
Transfer Document #:		Price Per SqFt:	$13.72
New Construction:		Multi/Split Sale:	
Title Company:			
Lender:			
Seller Name:	FARWELL REALTY CORP		

Prior Sale Information

Prior Rec/Sale Date:	/	Prior Lender:	
Prior Sale Price:		Prior 1st Mtg Amt/Type:	/
Prior Doc Number:		Prior 1st Mtg Rate/Type:	/
Prior Deed Type:			

Property Characteristics

Year Built / Eff:	1938 /	Total Rooms/Offices		Garage Area:	
Gross Area:	5,432	Total Restrooms:		Garage Capacity:	
Building Area:	5,432	Roof Type:		Parking Spaces:	
Tot Adj Area:		Roof Material:		Heat Type:	
Above Grade:	500	Construction:		Air Cond:	
# of Stories:	1	Foundation:		Pool:	
Other Improvements:		Exterior wall:		Quality:	
		Basement Area:		Condition:	

Site Information

Zoning:	M1-3	Acres:	0.28	County Use:	GARAGE 1 STRY SEMI-FIREPROOF (G2)
Lot Area:	12,350	Lot Width/Depth:	95 x 130	State Use:	
Land Use:	GARAGE	Res/Comm Units:	1 / 1	Water Type:	
Site Influence:				Sewer Type:	

Tax Information

Total Value:	$1,238,400	Assessed Year:	2022	Property Tax:	$54,271.73
Land Value:	$540,000	Improved %:	56%	Tax Area:	4
Improvement Value:	$698,400	Tax Year:	2022	Tax Exemption:	
Total Taxable Value:	$772,380				

12.5 Environmental Database Report and Regulatory Agency Documentation

23-0454
3705 21st Street
Long Island City, NY 11101

Inquiry Number: 7390563.2s
July 17, 2023

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	1376
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-9
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

3705 21ST STREET
LONG ISLAND CITY, NY 11101

COORDINATES

Latitude (North):	40.7581820 - 40° 45' 29.45''
Longitude (West):	73.9380680 - 73° 56' 17.04''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589638.9
UTM Y (Meters):	4512244.5
Elevation:	17 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	14115942 CENTRAL PARK, NY
Version Date:	2019
South Map:	14115940 BROOKLYN, NY
Version Date:	2019

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20190830
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	LONDON AUTO ELECTRIC	37-05 21ST STREET	NY AST		TP
Reg	NEWTOWN CREEK	SOUTH END OF IVY HIL	NPL, SEMS, RCRA-SQG, ROD, PRP, NY MANIFEST	Same	5262, 0.997, South
A2	CON EDISON	37-25 21 ST	NY MANIFEST	Higher	1 ft.
A3	CITY USED AUTO CENTE	37-25 21ST STREET	NY SWF/LF, NY Spills	Higher	1 ft.
A4	LIC USED AUTO PARTS	37-25 21ST ST	NY AST	Higher	1 ft.
A5	LI CITY GAS & CONVEN	3725 21ST ST	NY AST	Higher	1 ft.
A6	NEW BANGLA MOTOR INC	37-25 21ST STREET	NY AST	Higher	1 ft.
A7	LI CITY GAS & CONVEN	3725 21ST ST	NY UST	Higher	1 ft.
A8	ERRA METAL INDUSTRIE	37-35 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	21, 0.004, SSW
A9	37-35 21ST STREET	37-35 21ST STREET	NY Spills	Higher	21, 0.004, SSW
A10	QAZI AUTO REPAIRS IN	37-27 21ST STREET	NY AST	Higher	24, 0.005, NNW
A11	DDC- (FORMER PS 111)	37-44 21ST STREET	NY Spills	Lower	64, 0.012, NNW
B12	NICOSIA SERVICE STAT	3745 21ST ST	EDR Hist Auto	Higher	83, 0.016, SSW
B13	MICOSIA SERVICE CENT	37-45 21ST ST	RCRA NonGen / NLR, US AIRS	Higher	83, 0.016, SSW
A14	LE CLAIRE VALET SERV	19-44 37TH ST	EDR Hist Cleaner	Lower	96, 0.018, North
A15	CONSOLIDATED EDISON	37 AVE & 21ST ST	NY MANIFEST	Higher	98, 0.019, NNE
A16	NYC DEP HAZ MAT	21ST ST & 37TH AVE	NY MANIFEST	Higher	98, 0.019, NNE
B17	BROTHERS AUTO REPAIR	21-15 38 AVE	NY Spills	Higher	106, 0.020, South
B18	TONYS TOWING SERVICE	2115 38TH AVE	EDR Hist Auto	Higher	106, 0.020, South
B19	VAULT 0763	42-32 22ND ST	NY Spills	Higher	119, 0.023, South
B20	DELANE RESIDENCE	21-70 38TH ST	NY Spills	Higher	180, 0.034, SSW
B21	NYNEX	21ST ST & 38TH AVE	NY MANIFEST	Higher	180, 0.034, SW
B22	FEEDER 31281	21ST ST & 38TH AVE	NY Spills	Higher	180, 0.034, SW
B23	FEEDER 21ST ST & 38T	21ST ST & 38TH AVE	NY Spills	Higher	180, 0.034, SW
B24	FEEDER # 31281	21ST ST & 38TH AVE	NY Spills	Higher	180, 0.034, SW
B25	21ST ST & 38TH AVE	21ST ST & 38TH AVE	NY Spills	Higher	181, 0.034, SW
B26	21ST ST/38TH AVE	21ST ST/38TH AVE	NY Spills	Higher	181, 0.034, SW
B27	38TH AVE & 21ST ST	MANHOLE #499- 38TH A	NY Spills	Higher	181, 0.034, SW
A28	CONSOLIDATED EDISON	14 ST & 37 AVE MH223	NY MANIFEST	Lower	186, 0.035, NNW
A29	DRUM RUN	37TH AVE AND 14TH ST	NY Spills	Lower	186, 0.035, NNW
A30	37TH AVE / 14TH ST.	14TH ST SOUTH OF 37T	NY Spills	Lower	186, 0.035, NNW
A31	MANHOLE 5499	37TH AVE/14TH ST	NY Spills	Lower	186, 0.035, NNW
A32	MANHOLE 5499	37TH AVE/14TH ST	NY Spills	Lower	186, 0.035, NNW
A33	NEW YORK CITY D.E.P	37TH/14TH STREET	NY MANIFEST	Lower	186, 0.035, NNW
B34	NEW YORK AUTO LIC, I	21-10 38TH AVENUE	NY AST	Higher	189, 0.036, SW
C35	T.J. AUTO BODY & REP	37-09 22ND STREET	NY AST	Higher	191, 0.036, ESE
C36	37-11 22 ST	37-11 22ND STREET	NY AST	Higher	192, 0.036, SE
C37	CONSOLIDATED EDISON	22 ST & 37 AVE OP EX	NY MANIFEST	Higher	202, 0.038, East
C38	POLE #89064	93-09 22ND ST	NY Spills	Higher	205, 0.039, ESE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B39	MAN HOLE 12775	EAST 22 ST AND 38 AV	NY Spills	Higher	205, 0.039, South
B40	CONSOLIDATED EDISON	22 ST & 38 AVE OP EX	NY MANIFEST	Higher	205, 0.039, South
B41	CON EDISON - EXC 111	22ND ST., 245‘ N/O 3	RCRA NonGen / NLR, NY MANIFEST	Higher	205, 0.039, South
D42	CON EDISON	36-37 21 ST	NY MANIFEST	Higher	206, 0.039, NNE
D43	H & M SERVICE STATIO	3642 21ST ST	EDR Hist Auto	Lower	215, 0.041, North
B44	38-02 22ND STREET	38-02 22ND ST.	NY Spills	Higher	216, 0.041, South
B45	PAKAM AUTO REPAIR &	3802 22ND ST	EDR Hist Auto	Higher	220, 0.042, South
B46	7096681 N.Y. AUTO BO	38-02 22ND STREET	NY AST	Higher	220, 0.042, South
C47	CONSOLIDATED EDISON	V3671-300 E 22ND ST	NY MANIFEST	Higher	267, 0.051, ENE
B48	KING OF QUEENS AUTO	38-03 21ST STREET	NY AST	Higher	270, 0.051, SW
B49	KING OF QUEENS AUTO	3803 21ST STREET	NY AST	Higher	270, 0.051, SW
E50	22-11 38TH AVE	22-11 38TH AVE	NY UST	Higher	277, 0.052, SSE
E51	CON EDISON	22-11 38TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	277, 0.052, SSE
E52	CON EDISON	22-11 38TH AVE	NJ MANIFEST	Higher	277, 0.052, SSE
C53	CON EDISON	22-08 37TH AVE	NJ MANIFEST	Higher	278, 0.053, ESE
C54	QUALITY CAR TECH INC	22-08 37TH AVENUE	NY AST	Higher	278, 0.053, ESE
C55	CON EDISON	22-08 37TH AVE	RCRA NonGen / NLR, ECHO	Higher	278, 0.053, ESE
C56	BELLO LNG ISLND CY A	22-08 37TH AVE	EDR Hist Auto	Higher	278, 0.053, ESE
C57	G. CHANAB AUTO & BOD	22-01 37TH AVE	NY AST	Higher	285, 0.054, East
F58	SAVEWAY ASTORIA INC	3802 21ST ST	EDR Hist Auto	Higher	305, 0.058, SW
F59	MERIT OIL CORP	3802 21ST ST	RCRA NonGen / NLR, US AIRS	Higher	305, 0.058, SW
F60	SHELL SERVICE STATIO	38-02 21ST STREET	NY UST	Higher	305, 0.058, SW
C61	A1 COLLISION INC.	2207 37 AVE	NY AST	Higher	320, 0.061, East
D62	ULTIMATE AUTO CARE	36-37 21ST STREET	NY AST	Higher	325, 0.062, NNE
D63	ULTIMATE AUTO CARE O	3637 21ST ST	EDR Hist Auto	Higher	325, 0.062, NNE
D64	ULTIMATE AUTO CARE	36-37 21ST STREET	NY UST	Higher	325, 0.062, NNE
G65	36-28 14TH STREET	36-28 14TH STREET	NY Spills	Lower	329, 0.062, North
D66	CON EDISON - SERVICE	36-40 22ND ST	RCRA-LQG	Higher	334, 0.063, ENE
D67	CON EDISON - SERVICE	36-40 22ND ST	NY MANIFEST	Higher	334, 0.063, ENE
D68	VIVIENNE SOIL REMOVA	36-22 21ST ST	NY MANIFEST	Higher	339, 0.064, NNE
D69	VIVIENNE REALTY LLC	36-22 21ST ST	RCRA NonGen / NLR	Higher	339, 0.064, NNE
F70	38-11 21TH ST.	38011 21TH ST.	NY Spills	Higher	351, 0.066, SSW
G71	PROMO-PRO LTD	13-07 37TH AVE TRANS	RCRA NonGen / NLR	Lower	356, 0.067, NNW
G72	ELIT GREEN BUILDERS	13-07 37TH AVE ROOM	RCRA NonGen / NLR, FINDS, ECHO	Lower	356, 0.067, NNW
G73	ENVIRO CONTRACTING C	13-07 37TH AVE ROOM	RCRA NonGen / NLR	Lower	356, 0.067, NNW
C74	AAD AUTO REPAIR & BO	22-15 37TH AVENUE	NY AST	Higher	357, 0.068, East
C75	BETWEEN 37 & 38TH AV	3722 23RD. ST.	NY Spills	Higher	360, 0.068, SE
G76	GE-TSELEL AUTOMOTIVE	36-28 14TH STREET	NY SWF/LF	Lower	363, 0.069, North
G77	ASTORIA USED AUTO PA	36-28 14TH STREET	NY SWF/LF	Lower	363, 0.069, North

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C78	BASEMENT	2217 37TH ST	NY Spills	Higher	368, 0.070, East
H79	NYC BD OF ED - PUBLI	37-15 13TH ST	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Lower	370, 0.070, WNW
H80	PUBLIC SCHOOL 111 -	37-15 13TH STREET	NY AST	Lower	370, 0.070, WNW
C81	PERDIDO PRODS CONSTR	37-22 23RD ST GRD WH	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	372, 0.070, ESE
D82	AUTO CARE LUBE, LTD	36-21 21ST STREET	NY AST	Higher	374, 0.071, NE
I83	BMI AUTO BODY CENTER	36-33/35 22ND STREET	NY AST	Higher	392, 0.074, ENE
C84	DRUM RUN	23RD ST BET 37TH AND	NY Spills	Higher	396, 0.075, SE
C85	M & B AUTO BODY INC	22-19 37TH AVE	RCRA-SQG, FINDS, ECHO, NY MANIFEST, NJ MANIFEST	Higher	399, 0.076, East
G86	14TH STREET BETWEEN	36TH + 37TH	NY Spills	Lower	405, 0.077, North
D87	DIESEL SPILL BUCKET	36-02 21ST STREET	NY Spills	Higher	416, 0.079, NNE
D88	GETTY	36-02 21ST ST	NY Spills	Higher	416, 0.079, NNE
F89	HERTZ PARKING LOT	38-15 21 ST	NY UST	Higher	420, 0.080, SW
C90	CONSOLIDATED EDISON	37 AVE & 23 AT MH174	NY MANIFEST	Higher	423, 0.080, ESE
F91	PEP BOYS #437	38-50 21ST STREET	NY AST	Higher	424, 0.080, SW
E92	23RD ST & 38TH AVENU	23RD ST & 38TH AVENU	NY Spills	Higher	426, 0.081, SSE
H93	CON EDISON	37-14 13TH ST	NY MANIFEST	Lower	427, 0.081, WNW
E94	CONSOLIDATED EDISON	23RD ST & 38TH AVE M	NY MANIFEST	Higher	428, 0.081, SSE
G95	CHRISTIAN ECKHOFF TR	36-22 14TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	447, 0.085, North
G96	CHRISTIAN ECKHOFF TR	36-22 14TH STREET	NY UST	Lower	447, 0.085, North
H97	CON EDISON	12-20 37 AV	NY MANIFEST	Lower	449, 0.085, NW
D98	SAV-ON PETROLEUM INC	36-11 21ST ST	EDR Hist Auto	Higher	457, 0.087, NE
J99	JUNG SUN LAUNDRY SIT	37-11 23RD ST	RCRA-LQG	Higher	459, 0.087, SE
J100	JUNG SUN LAUNDRY SIT	37-11 23RD ST	NY MANIFEST	Higher	459, 0.087, SE
J101	JUNG SUN LAUNDRY SIT	37-11 23RD ST	NJ MANIFEST	Higher	459, 0.087, SE
F102	PEP BOYS STORE #1072	38-19 21ST ST	RCRA-VSQG, FINDS, ECHO	Higher	471, 0.089, SW
F103	PEP BOYS STORE #1072	38-19 21ST STREET	NY AST	Higher	471, 0.089, SW
I104	JIANGS REALTY INC	36-21 22ND STREET	NY UST	Higher	472, 0.089, ENE
J105	SAN ANTON SERVICE ST	23-02 37 AVE	EDR Hist Auto	Higher	482, 0.091, ESE
K106	ABC CONSTRUCTION CON	36-11 19TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	484, 0.092, NE
K107	SUNOCO SERVICE STATI	36-02 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	490, 0.093, NNE
K108	SEVIM MGMT BP PRODUC	36-42 21ST STREET	NY UST	Higher	497, 0.094, NNE
H109	VACANT BUILDING	12-12 37TH AVE	NY LTANKS	Lower	513, 0.097, NW
H110	1212 37TH AVENUE	12-12 37TH AVENUE	NY UST	Lower	513, 0.097, NW
L111	SEGUNDO'S AUTO REPAI	38-38 22ND STREET	NY AST	Higher	530, 0.100, SSW
K112	GETTY #568	21ST/36 AVE	NY Spills	Higher	533, 0.101, NNE
K113	GETTY STATION#568	21ST STREET/36 AVE	NY Spills	Higher	533, 0.101, NNE
K114	GETTY#568	36-02 21 STREET	NY Spills	Higher	533, 0.101, NNE
K115	GETTY 568	21ST STREET AND 36TH	NY Spills	Higher	533, 0.101, NNE
K116	GETTY # 568	36-21 21ST STREET	NY Spills	Higher	533, 0.101, NNE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K117	GETTY #568	21ST STREET AND 36TH	NY Spills	Higher	533, 0.101, NNE
K118	GETTY #568	21ST/36 AVE	NY Spills	Higher	533, 0.101, NNE
K119	GLOBAL MONTELLO GROU	36-02 21ST STREET	NY AST	Higher	534, 0.101, NNE
K120	3602 21ST STREET	3602 21ST STREET	NY Spills	Higher	534, 0.101, NNE
K121	GLOBAL MONTELLO GROU	36-02 21ST STREET	NY UST	Higher	534, 0.101, NNE
K122	T J MOTORS INC	36-02 21ST ST	EDR Hist Auto	Higher	534, 0.101, NNE
E123	CON EDISON	23-02 38 AV	NY MANIFEST	Higher	542, 0.103, SSE
E124	ONE STOP SERVICE	23-02 38TH AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	542, 0.103, SSE
F125	PS# 111 DISTRICT 30	38-15 13TH STREET	NY Spills	Lower	545, 0.103, WSW
L126	NEW HIGH TECH AUTO R	38-25 21ST STREET	NY AST	Higher	546, 0.103, SW
L127	LUPOLI SERVICE STATI	38-25 21ST STREET	NY UST	Higher	546, 0.103, SW
L128	CIOFFI & FERRARA	38-25 21ST ST	EDR Hist Auto	Higher	546, 0.103, SW
M129	MARVIC TRANSMISSION	23-12 38TH AVENUE	NY AST	Higher	554, 0.105, SSE
M130	MARVIC TRANSMISSION	2312 38TH AVE	EDR Hist Auto	Higher	554, 0.105, SSE
M131	MAR-VIC TRANSMISSION	23-12 38TH AVENUE	RCRA NonGen / NLR, FINDS, ECHO	Higher	554, 0.105, SSE
N132	38-21 12TH ST/QUEENS	38-21 12TH ST.	NY LTANKS	Lower	557, 0.105, West
J133	OIL IN WELL	37-10 24TH STREET	NY Spills	Higher	565, 0.107, ESE
J134	37-10 24TH STREET	37-10 24TH STREET	NY Spills	Higher	565, 0.107, ESE
O135	JACKSON DEVELOPMENTA	3602 14TH ST	NY UST	Higher	567, 0.107, North
H136	AUDAX CONSTRUCTION C	12-04 37TH AVENUE	NY UST	Lower	574, 0.109, NW
H137	COMMERCIAL BUILDING	1204 37TH AVE	NY LTANKS	Lower	574, 0.109, NW
L138	NEW YOGI TRANSMISSIO	21-10 39TH AVENUE	NY AST	Higher	576, 0.109, SSW
L139	CON EDISON	OPP 21-16 39 AV	NY MANIFEST	Higher	577, 0.109, SSW
M140	CON EDISON	OPP 38-15 23 ST	NY MANIFEST	Higher	577, 0.109, South
L141	GRANT INT'L CO., INC	21-24 39TH AVENUE	NY UST	Higher	577, 0.109, SSW
L142	KOCH & LOW	21-24 39TH AVE	NY CBS, NY AST, NY CBS AST, RCRA NonGen / NLR,...	Higher	577, 0.109, SSW
J143	JUNG SUN LAUNDRY SIT	37-10 24TH STREET	NY SHWS	Higher	579, 0.110, ESE
J144	JUNG SUN LAUNDRY COR	37-10 24TH ST	NY DRYCLEANERS	Higher	579, 0.110, ESE
J145	JUNG SUN LAUNDRY PLU	37-10 24TH ST	RCRA-SQG, US AIRS, NY MANIFEST, NJ MANIFEST	Higher	579, 0.110, ESE
J146	COMMERCIAL	37-10 24TH ST	NY Spills	Higher	579, 0.110, ESE
J147	CON EDISON	37-24 24TH ST	RCRA NonGen / NLR, ECHO	Higher	583, 0.110, SE
J148	SILKS BUILDING	37-24 24TH ST	NY UST	Higher	583, 0.110, SE
J149	SCALAMANDRE	37-24 24TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	583, 0.110, SE
J150	CON EDISON	37-24 24TH ST	NJ MANIFEST	Higher	583, 0.110, SE
K151	LUCKY CLEANERS	2120 36TH AVE	EDR Hist Cleaner	Higher	595, 0.113, NE
K152	LUCKY CLEANERS	21-20 36TH AVE	RCRA-SQG, US AIRS, NY MANIFEST, RI MANIFEST	Higher	595, 0.113, NE
K153	LUCKY CLEANERS	21-20 36TH AVE	NY DRYCLEANERS	Higher	595, 0.113, NE
N154	CONTAMINATED SOIL AT	12-02 38TH AVENUE	NY Spills	Lower	600, 0.114, West
L155	21-24 39TH AVE/QUEEN	21-24 39TH AVENUE	NY Spills	Higher	611, 0.116, SSW

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
K156	VAULT #9358	36TH AVE/ 21ST STREE	NY Spills	Higher	620, 0.117, NNE
L157	CON ED - V 0599	22-01 39TH AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	624, 0.118, South
L158	CON EDISON	2112 39TH AVE	NY MANIFEST	Higher	624, 0.118, SSW
P159	MTA NYCT - BEEBE SIG	39TH AVE & 21ST ST	RCRA NonGen / NLR, NY MANIFEST	Higher	629, 0.119, SW
L160	QUEENSBRIDGE CENTRAL	22-09 39TH AVENUE	NY UST	Higher	630, 0.119, South
L161	QUEENSBRIDGE SUB STA	22-09 39TH AVENUE	NY Spills	Higher	630, 0.119, South
L162	CON EDISON - QUEENSB	2209 39TH ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Higher	630, 0.119, South
L163	QUEENSBRIDGE CENTRAL	22-09 39TH AVENUE	NY AST	Higher	630, 0.119, South
L164	QUEENS BRIDGE SUB ST	2209 39TH AVE	NY Spills	Higher	630, 0.119, South
L165	QUEENS BRINDGE SUBST	22-09 39TH AVE	NY Spills	Higher	630, 0.119, South
L166	ONE PINT DIESEL LEAK	22-09 39 AVENUE (AT	NY Spills	Higher	630, 0.119, South
P167	CON EDISON EXCAVATIO	21ST ST BETWN 38TH &	RCRA NonGen / NLR, NY MANIFEST	Higher	631, 0.120, SW
P168	SERVICE STATION	38-25 21ST ST & 39TH	RCRA NonGen / NLR, FINDS, ECHO	Higher	634, 0.120, SW
J169	37-24 24TH ST/QUEENS	37-24 24TH STREET	NY LTANKS	Higher	636, 0.120, ESE
Q170	LOT 1,TAXBLOCK 351	12-01 37 AVENUE	NY E DESIGNATION	Lower	643, 0.122, NW
N171	COMMERCIAL BUSINESS	38-21 12TH STREET	NY Spills	Lower	644, 0.122, WSW
R172	CON EDISON	38-21 23RD ST	NJ MANIFEST	Higher	645, 0.122, South
R173	CON EDISON	38-21 23RD ST	NY MANIFEST	Higher	645, 0.122, South
R174	CON EDISON	38-21 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	645, 0.122, South
R175	CON EDISON	38-21 23RD ST	NJ MANIFEST	Higher	645, 0.122, South
R176	B&F AUTO CARE INC.	38-21 23RD STREET	NY AST	Higher	645, 0.122, South
R177	CON EDISON	38-21 23RD ST	RCRA NonGen / NLR	Higher	645, 0.122, South
R178	CON EDISON	38-21 23RD ST	NY MANIFEST	Higher	645, 0.122, South
R179	CON EDISON	OPP 38-21 23 ST	NY MANIFEST	Higher	645, 0.122, South
Q180	LOT 6,TAXBLOCK 351	36-31 12 STREET	NY E DESIGNATION	Lower	653, 0.124, NNW
L181	UNKNOWN	22-09 39TH AVE QUEEN	NY Spills	Higher	654, 0.124, South
R182	CON EDISON	OPP 38-31 23 ST	NY MANIFEST	Higher	655, 0.124, South
O183	CONSOLIDATED EDISON	36TH AVE & 14TH ST	NY MANIFEST	Higher	656, 0.124, NNE
S184	D. MOY & SONS	36-44 24 STREET	NY CBS, NY AST	Higher	663, 0.126, ESE
T185	CLEO MANAGEMENT	36-15 23RD ST	NY MANIFEST	Higher	685, 0.130, East
T186	CON EDISON	36-15A 23 ST	NY MANIFEST	Higher	685, 0.130, East
T187	CLEO MANAGEMENT	36-15 23RD ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	685, 0.130, East
U188	CON EDISON	37-18 12TH ST	NY MANIFEST	Lower	688, 0.130, WNW
U189	CON EDISON SERVICE B	37-18 12TH ST	RCRA NonGen / NLR, FINDS	Lower	688, 0.130, WNW
P190	CITY AUTO SERVICE IN	39-01 21ST STREET	NY AST	Higher	695, 0.132, SW
P191	CITY AUTO SERVICE IN	39-01 21ST STREET	NY UST	Higher	695, 0.132, SW
S192	TRI STAR LUMBER CORP	37-01 24TH ST	NY UST	Higher	711, 0.135, ESE
O193	DRAPEMASTERS OF AMER	36-02 13TH ST	RCRA-VSQG	Lower	714, 0.135, NNW
T194	VACANT INDUSTRIAL PR	36-15 23RD STREET	NY UST	Higher	718, 0.136, ENE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
S195	HEPHAISTOS BUILDING	24-02 37TH AVENUE	NY UST	Higher	719, 0.136, ESE
R196	38-24 24 ST. LLC	38-24 24TH STREET	NY AST	Higher	735, 0.139, SSE
Q197	ENGINE COMPANY 260	11-15 37TH AVENUE	NY AST	Lower	750, 0.142, NW
Q198	ENGINE COMPANY 260	11-15 37TH AVENUE	NY UST	Lower	750, 0.142, NW
199	CONSOLIDATED EDISON	V2253-43-23 36TH AVE	NY MANIFEST	Higher	757, 0.143, ENE
M200	ADVANCE AUTO ELECTRI	38-01 24TH ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	757, 0.143, SSE
R201	CON EDISON	OPP 23-02 39 AV	NY MANIFEST	Higher	762, 0.144, South
P202	PEP BOYS #0437	3850 21ST ST	NY CBS, NY AST	Higher	768, 0.145, SW
P203	AMAZON.COM SERVICES	38-50 21ST ST	RCRA NonGen / NLR	Higher	768, 0.145, SW
M204	P & A AUTO SERVICE,	38-09 24TH STREET	NY AST	Higher	774, 0.147, SSE
V205	KTR LAUNDRY & DRY CL	38-38 13TH ST	NY DRYCLEANERS	Lower	779, 0.148, WSW
V206	MIDNIGHT EXPRESS	38-38 13TH ST	RCRA-SQG, ICIS, US AIRS, FINDS, ECHO	Lower	779, 0.148, WSW
V207	MIDNIGHT EXPRESS	38-38 13TH ST	NY MANIFEST	Lower	779, 0.148, WSW
V208	38-21 12TH STREET	38-21 12TH STREET	RCRA-LQG, NY MANIFEST	Lower	788, 0.149, WSW
V209	DOT RELOCATION SITE	38-21 12TH STREET	NY BROWNFIELDS	Lower	788, 0.149, WSW
V210	38-21 12 ST PARTNERS	38-21 12TH ST	NY UST	Lower	788, 0.149, WSW
W211	WELL DUN FRENCH DRY	12-14 36TH AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	790, 0.150, North
W212	WELL DUN CLEANERS	12-14 36TH AVENUE	NY DRYCLEANERS	Lower	790, 0.150, North
U213	NYCDEP	37-31 11TH ST	NY MANIFEST	Lower	794, 0.150, WNW
V214	IMOG AUTOMOTIVE INC	38-44 13TH ST	RCRA-VSQG, FINDS, ECHO	Higher	797, 0.151, WSW
P215	39-15 21ST STREET	39-15 21ST STREET	NY LTANKS	Higher	807, 0.153, SW
T216	NYC DEPT OF ENVIRONM	36 AVE & 23RD ST	NY MANIFEST	Higher	815, 0.154, ENE
X217	CHECKER MANAGEMENT C	11-05 38 AVE.	NY AST	Lower	820, 0.155, West
X218	2-612682	11-05 38TH AVENUE	NY AST	Lower	820, 0.155, West
W219	36-05 12TH ST	36-05 12TH STREET	NY UST	Lower	821, 0.155, NNW
Y220	CON EDISON - MANHOLE	37-46 CRESCENT ST	NY MANIFEST	Higher	838, 0.159, SE
Z221	ST RITA SCHOOL	36-22 12TH STREET	NY UST	Lower	848, 0.161, NNW
AA222	CON EDISON - SERVICE	35-51 21ST ST	NY MANIFEST	Higher	850, 0.161, NNE
V223	QUEENS AUTO & BODY S	38-56 13TH STREET	NY AST	Higher	856, 0.162, WSW
Y224	MC ACROPOLIS, LLC	24-16 38TH AVENUE	NY AST	Higher	861, 0.163, SSE
V225	PEP BOYS #437	38-50 21ST ST	NY MANIFEST	Higher	867, 0.164, SW
V226	CON ED VS 7598	21 ST ST E 38 S 43RD	RCRA NonGen / NLR, NY MANIFEST	Higher	867, 0.164, SW
W227	VOICE CHARTER SCHOOL	36-14 12TH STREET	NY UST	Lower	873, 0.165, NNW
X228	CON ED	11 ST & 38 AVE EXCAV	NY MANIFEST	Lower	878, 0.166, West
X229	CONSOLIDATED EDISON	38TH AVE & 11TH ST	NY MANIFEST	Lower	878, 0.166, West
X230	CON ED - 38TH AVE &	38TH AVE & 11TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	878, 0.166, West
S231	AROON SUKRANICHANNE	36-46 CRESCENT STREE	NY LTANKS	Higher	903, 0.171, ESE
AA232	NYCHA - RAVENSWOOD H	35-32 21ST ST	NJ MANIFEST	Higher	903, 0.171, NNE
AA233	NYCHA - RAVENSWOOD H	35-32 21ST ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	903, 0.171, NNE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AA234	NYCHA - RAVENSWOOD H	35-32 21ST ST	NY MANIFEST	Higher	903, 0.171, NNE
AB235	CONSOLIDATED EDISON	11TH ST & 37TH AVE	NY MANIFEST	Lower	914, 0.173, NW
236	MONARCH CONSTRUCTION	39-16 23RD STREET	NY UST, NY Spills	Higher	916, 0.173, SSW
W237	CON EDISON	36TH AVE & 12TH ST	NJ MANIFEST	Lower	918, 0.174, NNW
W238	CON EDISON	36TH AVE & 12TH ST	RCRA NonGen / NLR	Lower	918, 0.174, NNW
AC239	CON ED	39-26 21ST ST	NY MANIFEST	Higher	918, 0.174, SW
AC240	CON EDISON	39-26 21ST ST	RCRA NonGen / NLR	Higher	918, 0.174, SW
AC241	CON EDISON	39-26 21ST ST	NJ MANIFEST	Higher	918, 0.174, SW
AB242	CON EDISON SERVICE B	462 11TH AVE & 37TH	RCRA NonGen / NLR, FINDS	Lower	921, 0.174, NW
AD243	CON EDISON	36-15 24TH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	928, 0.176, East
AE244	SPILL NUMBER 0005416	CRESCENT ST/37TH AV	NY LTANKS	Higher	947, 0.179, ESE
AB245	3712 11TH STREET	3712 11TH STREET	NY LTANKS	Lower	950, 0.180, WNW
V246	LUIS WINSTON INC	38-66 13TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	952, 0.180, WSW
AB247	CON EDISON	37-10 11TH ST	NJ MANIFEST	Lower	961, 0.182, WNW
AB248	CON EDISON	37-10 11TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	961, 0.182, WNW
AB249	CON EDISON	37-10 11TH ST	NY MANIFEST	Lower	961, 0.182, WNW
AE250	25-05 37TH AVE	25-05 37TH AVE	NY LTANKS	Higher	966, 0.183, ESE
AE251	NYC DEPT OF EDUCATIO	25-05 37TH AVE	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	966, 0.183, ESE
AE252	PUBLIC SCHOOL 112 -	25-05 37TH AVENUE	NY AST	Higher	967, 0.183, ESE
AE253	PUBLIC SCHOOL 112 -	25-05 37TH AVENUE	NY UST	Higher	967, 0.183, ESE
Z254	ST RITA RECTORY	36-25 11 ST	NY UST	Lower	974, 0.184, NW
Y255	37-27 CRESCENT ST	37-27 CRESCENT ST	NY AST	Higher	989, 0.187, SE
AE256	37-23 CRESCENT AVENU	37-23 CRESCENT AVENU	NY LTANKS	Higher	991, 0.188, SE
AD257	CON EDISON - SERVICE	36-24 CRESCENT ST	NY MANIFEST	Higher	992, 0.188, East
AD258	CON EDISON - SERVICE	36-24 CRESCENT ST	RCRA-LQG	Higher	992, 0.188, East
V259	BEST DDK CLEANERS	38-68 13TH STREET	NY BROWNFIELDS	Higher	993, 0.188, WSW
V260	D D K PRO CLEANERS	38-68 13TH ST	RCRA-SQG, NY MANIFEST, RI MANIFEST	Higher	993, 0.188, WSW
V261	BEST-DDK CLEANERS	38-68 13TH STREET	NY SHWS	Higher	993, 0.188, WSW
V262	LA MODE QUEENS INC	38-68 13TH ST	RCRA-SQG, US AIRS, NY MANIFEST	Higher	993, 0.188, WSW
V263	BEST CLEANERS	38-68 13TH ST	NY DRYCLEANERS	Higher	993, 0.188, WSW
W264	CON EDISON SERVICE B	35-58 12TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1010, 0.191, NNW
Y265	38-05 CRESCENT STREE	38-05 CRESCENT STREE	NY AST	Higher	1014, 0.192, SSE
AB266	10-12 37TH AVE	10-12 37TH AVE	NY LTANKS	Lower	1042, 0.197, WNW
AC267	CON EDISON	39-40 21ST ST	NY MANIFEST	Higher	1052, 0.199, SW
AC268	CON ED	39-40 21 ST	NY MANIFEST	Higher	1052, 0.199, SW
AC269	CON EDISON	39-40 21ST ST	RCRA NonGen / NLR	Higher	1052, 0.199, SW
AC270	CON EDISON	39-40 21ST ST	NJ MANIFEST	Higher	1052, 0.199, SW
Y271	ACCARDI ELECTRIC CO	25-10 38TH AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1054, 0.200, SE
AF272	CON EDISON	83-19 39 AVE	NY MANIFEST	Higher	1055, 0.200, SSE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG273	CON EDISON GAS MAIN:	37-47 10TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1062, 0.201, WNW
AC274	WOODHAVEN FINISHING	38-79 13TH ST	RCRA NonGen / NLR	Higher	1065, 0.202, SW
AH275	BETHEL WELDING	38-59 12TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1080, 0.205, WSW
AF276	ORKIN PEST CONTROL C	38-31 CRESCENT ST	RCRA NonGen / NLR	Higher	1104, 0.209, SSE
AF277	ORKIN	38-31 CRESENT STREET	NY MANIFEST	Higher	1104, 0.209, SSE
AF278	38-31 CRESCENT ST	38-31 CRESCENT ST	NY LTANKS	Higher	1108, 0.210, SSE
AI279	39-23 REALTY LLC	39-23 24TH STREET	NY AST	Higher	1114, 0.211, South
AJ280	CON EDISON - TRANSFO	11TH ST & 36TH AVE	NY MANIFEST	Lower	1116, 0.211, NNW
AK281	CON EDISON	21-07 40 AVE FRNT	NY MANIFEST	Higher	1121, 0.212, SSW
282	UNITED HOISTING COMP	38-51 11TH ST	NY UST	Lower	1136, 0.215, WSW
AL283	CON EDISON	35-49 24TH ST	NY MANIFEST	Higher	1138, 0.216, ENE
AL284	CON EDISON	35-49 24TH ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1138, 0.216, ENE
AC285	CON EDISON	13-01 40TH AV	NY Spills, NY MANIFEST	Higher	1142, 0.216, SW
AC286	DE MAMS, LLC	13-09 40TH AVENUE	NY UST	Higher	1146, 0.217, SW
AH287	WORLD WIDE RECOVERY	38-65 12TH ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1147, 0.217, WSW
AM288	CON EDISON SERVICE B	36-31 10TH ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1152, 0.218, NW
AK289	22-11 40 AVENUE	22-11 40 AV	NY UST	Higher	1174, 0.222, SSW
AM290	PARISI - WAREHOUSE	36-21 10TH STREET	NY LTANKS	Lower	1175, 0.223, NW
AH291	38-70 12TH STREET	38-70 12TH STREET	NY UST	Lower	1175, 0.223, WSW
AI292	39-31 24TH ST	39-31 24TH STREET	NY AST	Higher	1179, 0.223, South
AG293	APLINE STORE EQUIPME	37-10 10TH AVE	NY AST	Lower	1179, 0.223, WNW
AN294	BLACK OX METAL FINIS		PFAS ECHO	Higher	1181, 0.224, SE
295	CON EDISON	35-05 21ST ST	NY MANIFEST	Higher	1188, 0.225, NE
296	CON EDISON	35TH AVE & 35TH ST 5	NY MANIFEST	Higher	1189, 0.225, NNE
AH297	DAWNEX INDUSTRIES IN	38-61 11TH STREET	NY AST	Lower	1208, 0.229, WSW
AH298	DAWNEX INDUSTRIES IN	38-61 11TH STREET	NY UST	Lower	1208, 0.229, WSW
299	CONSOLIDATED EDISON	CRESCENT ST & 36TH A	NY MANIFEST	Higher	1209, 0.229, East
AO300	37-15 27 STREET CORP	37-15 27 STREET	NY AST	Higher	1231, 0.233, SE
AN301	CON EDISON	27-03 38TH AVE	NY MANIFEST	Higher	1237, 0.234, SE
AP302	CONSOLIDATED EDISON	31-01 20TH. AVE.	NY MANIFEST	Higher	1251, 0.237, SSE
AK303	GIACOMELLI & MAZZA I	40-05 21ST ST	RCRA-SQG, NY MANIFEST	Higher	1265, 0.240, SW
304	WEGNER MACHINERY COR	35-41 11TH ST	NY AST, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	1273, 0.241, NNW
AN305	CON EDISON	38-11 27TH ST	RCRA NonGen / NLR	Higher	1278, 0.242, SSE
AN306	CON EDISON	38-11 27TH ST	NJ MANIFEST	Higher	1278, 0.242, SSE
AQ307	ATLANTIC PRECIOUS ME	22-12 40TH AVE	RCRA-VSQG, FINDS, ECHO, NY MANIFEST	Higher	1280, 0.242, SSW
AO308	UNDERGROUND LINE	27-10 37TH AVE	NY LTANKS, NY Spills	Higher	1285, 0.243, ESE
AM309	P.S. 76 - QUEENS Q07	36-36 10TH STREET	NY AST	Lower	1285, 0.243, NW
AK310	ORLANDO FINISHING CO	40-09 21 STREET	US AIRS, FINDS, ECHO, PFAS ECHO	Higher	1287, 0.244, SW
AK311	SCHMIT MACHINE INC	40-09 21ST ST - GROU	RCRA NonGen / NLR, FINDS, ECHO	Higher	1287, 0.244, SW

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AJ312	CENTRAL COLLISION IN	10-12 36TH AVE	RCRA-VSQG, NY MANIFEST	Lower	1287, 0.244, NNW
AQ313	WALKER E WHYTE INC	22-14 40TH AVE	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	1292, 0.245, SSW
AQ314	22-14 40TH AVENUE	22-14 40TH AVENUE	NY AST	Higher	1292, 0.245, SSW
AR315	3707 9TH AVENUE	3707 9TH AVENUE	NY LTANKS	Lower	1336, 0.253, WNW
AS316	PATANO BROTHERS;INC	38-36 10 STREET	NY SWF/LF	Lower	1355, 0.257, West
AT317	PERETTE HALL	38-62 11TH STREET	NY LTANKS	Lower	1400, 0.265, WSW
AP318	ABANDONED BLDG	38-28 28TH ST	NY LTANKS	Higher	1433, 0.271, SSE
AS319	NATIONAL RUBBER ADHE	38-25/51 9TH STREET	NY VCP	Lower	1438, 0.272, West
AS320	NATIONAL RUBBER ADHE	38-25/51 9TH STREET	NY BROWNFIELDS	Lower	1438, 0.272, West
AS321	NATIONAL RUBBER & BA	38-31 9TH ST	NY SHWS, NY CBS, NY VCP, NY Spills, RCRA NonGen /...	Lower	1484, 0.281, West
AU322	QUEENSBRIDGE PLANT B	40001 12TH ST	NY LTANKS	Lower	1492, 0.283, SW
AR323	8-14 37TH AVE.	8-14 37TH AVE.	NY LTANKS	Lower	1493, 0.283, WNW
AU324	QUEENSBRIDGE PLANT A	40013 12TH STREET	NY LTANKS	Lower	1505, 0.285, SW
AV325	NAVAL SHIPYARD QUEEN		FUDS	Lower	1587, 0.301, WNW
326	QUEENS WEST 01 DOS -	34-28 21ST STREET	NY LTANKS, NY Spills	Higher	1614, 0.306, NNE
AW327	COMMERCIAL BUILDING	40-23 24TH ST'	NY LTANKS	Higher	1620, 0.307, South
AV328	RAINEY	38TH ST & VERNON BLV	NY LTANKS	Lower	1641, 0.311, WNW
AT329	QUEENSBRIDGE PLANT D	41004 10TH STREET	NY LTANKS	Lower	1642, 0.311, WSW
AV330	3809 VERNON BLVD	3809 VERNON BLVD	NY LTANKS	Lower	1642, 0.311, West
AX331	CENTRAL SERVICE BUIL	10-06 35TH AVENUE	NY LTANKS	Higher	1651, 0.313, NNW
AY332	FORMER HYGRADE POLIS	22-07 41ST AVENUE	NY BROWNFIELDS	Higher	1699, 0.322, SSW
AY333	DOUBLE E PLATING CO	22-07 41ST AVE	RCRA-LQG, NY ENG CONTROLS, NY INST CONTROL, NY...	Higher	1699, 0.322, SSW
AX334	NYS DEPT. OF CORRECT	10-06 35TH AVE	NY LTANKS	Higher	1731, 0.328, NNW
AZ335	RAVENWOOD GAS TURBIN	38-54 VERNON BOULEVA	NY MOSF UST, NY MOSF AST	Lower	1738, 0.329, West
AZ336	RAVENSWOOD GENERATIN	38-54 VERNON BOULEVA	NY SHWS, NY LTANKS, NY MOSF UST, NY MOSF, NY CBS,...	Lower	1738, 0.329, West
AZ337	RAVENSWOOD GENERATIN	38-54 VERNON BOULEVA	NY MOSF AST	Lower	1738, 0.329, West
AZ338	RAVENSWOOD PCB STORA	40TH AVE & VERNON BL	CORRACTS, RCRA-LQG, PADS	Lower	1738, 0.329, West
AY339	GULF STATION	23-01 41ST AVE	NY LTANKS, NY Spills	Higher	1748, 0.331, SSW
AY340	23-01 41ST AVENUE	23-01 41ST AVENUE	NY VCP	Higher	1753, 0.332, SSW
BA341	35-41 11TH ST/QUEENS	35-41 11TH ST	NY LTANKS	Lower	1778, 0.337, North
AW342	CLOSED-LACKOF RECENT	40-40 CRESCENT ST	NY LTANKS	Higher	1800, 0.341, South
343	29-05 38TH AVENUE SI	29-05 38TH AVENUE	NY BROWNFIELDS	Higher	1822, 0.345, SE
AW344	24-03 41ST AVE	24-03 41ST AVE	NY LTANKS, NY UST	Higher	1847, 0.350, SSW
AW345	APRT	2403 41ST AVE	NY LTANKS	Higher	1852, 0.351, SSW
BB346	41ST AVENUE & 12ST S	41ST AVE/12TH STREET	NY LTANKS	Lower	1865, 0.353, SW
347	25-13 35TH AVENUE	25-13 35TH AVENUE	NY LTANKS	Higher	1871, 0.354, ENE
348	2912 36TH AVE	2912 36TH AVE	NY LTANKS	Higher	1880, 0.356, ESE
BC349	CLOSED-LACKOF RECENT	39038 29TH ST.	NY LTANKS	Higher	1900, 0.360, SSE
BC350	CHURCH	39-38 29TH STREET	NY LTANKS	Higher	1925, 0.365, SSE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BA351	CHUCK'S PLACE - QNS	34-59 11TH ST	NY LTANKS	Lower	1945, 0.368, North
BA352	34-24 11TH ST	34-24 11TH ST	NY LTANKS	Lower	1945, 0.368, North
BD353	SEE FACTOR INDUSTRY	37-11 30TH ST	NY LTANKS	Higher	1971, 0.373, SE
BD354	37-11 30TH STREET	37-11 30TH STREET AN	NY BROWNFIELDS	Higher	1971, 0.373, SE
BE355	EMPIRE VENTALATION	35-39 VERNON BLVD	NY LTANKS	Higher	1978, 0.375, NNW
BE356	CONSTRUCTION SITE	35-38 JUNCTION BLVD	NY LTANKS	Higher	1978, 0.375, NNW
BB357	QUEENSBRIDGE PLANT B	41001 12TH STREET	NY LTANKS	Lower	1990, 0.377, SW
BF358	LOVOUR HOME	2512 41ST AVE	NY LTANKS	Higher	2105, 0.399, South
BG359	BRIDGE CLEANERS - OF	39-26 30TH STREET	NY BROWNFIELDS	Higher	2113, 0.400, SSE
BG360	BRIDGE CLEANERS	39-26 30TH STREET	NY BROWNFIELDS	Higher	2113, 0.400, SSE
BG361	FRESH CLEANERS & LAU	39-26 30TH ST	RCRA-SQG, NY SHWS, NY ENG CONTROLS, NY INST...	Higher	2113, 0.400, SSE
BF362	27-01 41ST AVENUE	27-01 41ST AVENUE	NY VCP	Higher	2114, 0.400, South
BH363	RAINEY SUBSTATION	35 ST / VERNON BLVD	NY LTANKS	Higher	2124, 0.402, NNW
364	34-19 11TH STREET /	34-19 11TH STREET	NY LTANKS	Lower	2137, 0.405, North
365	QUEENSBRIDGE PLANT E	40009 VERNON BLVD	NY LTANKS	Lower	2141, 0.405, West
BH366	35-01 VERNON BLVD	35-01 VERNON BLVD	NY LTANKS	Higher	2158, 0.409, NNW
BG367	FORMER UNION WIRE DI	39-40 30TH STREET	NY ENG CONTROLS, NY INST CONTROL, NY BROWNFIELDS	Higher	2160, 0.409, SSE
BG368	FORMER UNION WIRE DI	39-40 30TH STREET	NY BROWNFIELDS	Higher	2160, 0.409, SSE
BI369	34-44 9TH ST	34-44 9TH ST	NY LTANKS	Higher	2181, 0.413, NNW
370	NORTH QUEENS VIEW HO	33-60 21ST STREET	NY LTANKS	Higher	2203, 0.417, NNE
BJ371	31/32 LIC LLC	37-29 31ST STREET	NY BROWNFIELDS	Higher	2241, 0.424, SE
BJ372	31/32 LIC LLC - OFF-	37-29 31ST STREET	NY BROWNFIELDS	Higher	2241, 0.424, SE
BG373	CLOSED-LACKOF RECENT	29024 40TH AVENUE	NY LTANKS	Higher	2275, 0.431, SSE
BI374	UNKNOWN TTF	34-25 VERNON BLVD	NY LTANKS	Higher	2301, 0.436, NNW
375	22-09 QUEENS PLAZA N	22-09 QUEENS PLAZA N	NY BROWNFIELDS	Higher	2312, 0.438, SSW
376	KAL REALTY	29-24 40TH AVE	NY LTANKS	Higher	2317, 0.439, SSE
377	MANHOLE 14413	QUEENS PLAZA NORTH	NY LTANKS, NY Spills	Higher	2406, 0.456, SW
378	APARTMENT BLDG	21-50 33RD ROAD	NY LTANKS	Higher	2450, 0.464, NE
379	QUEENSBRIDGE PLANT F	4105 VERNON BLVD.	NY LTANKS	Lower	2458, 0.466, WSW
BK380	QUEENSBORO LANES SIT	25-01 QUEENS PLAZA N	NY BROWNFIELDS	Higher	2460, 0.466, South
381	BENIGNO FERNANEZ (P	31-01 NORTHERN BLVD	NY LTANKS, NY UST	Higher	2475, 0.469, SSE
BL382	MOTOR AND IRON WORKS	37-21 32ND STREET	NY SHWS, NY Spills	Higher	2496, 0.473, SE
BL383	32-10 37TH AV	32-10 37TH AVE	NY LTANKS	Higher	2537, 0.480, ESE
BL384	32-15 37TH AVE	32-15 37TH AVE	NY LTANKS	Higher	2537, 0.480, ESE
BK385	FALIDAS ASSCOCIATES	25-01 QUEENS PLAZA N	RCRA-VSQG, NY LTANKS, NY MANIFEST, NJ MANIFEST	Higher	2537, 0.480, South
386	HALKIDIKI AUTO CENTE	33-21 21ST STREET	NY LTANKS, NY UST	Higher	2568, 0.486, NE
BL387	CLOSED-LACKOF RECENT	37-14 33RD STREET	NY LTANKS	Higher	2634, 0.499, SE
388	34-14 31ST STREET	34-14 31ST STREET	NY SHWS	Higher	2804, 0.531, East
389	FORMER LUFT CO. INC.	34-12 36TH AVENUE	NY SHWS, NY Spills	Higher	2943, 0.557, ESE

MAPPED SITES SUMMARY

Target Property Address:
3705 21ST STREET
LONG ISLAND CITY, NY 11101

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
390	AMTRAK SUNNYSIDE YAR	39-29 HONEYWELL STRE	NY SHWS, NY LTANKS, NY TANKS, NY Spills	Higher	2957, 0.560, SE
391	THE WILLS BUILDING	43-01 21ST STREET	NY SHWS, NY INST CONTROL, NY BROWNFIELDS	Higher	3269, 0.619, SW
392	TEITELBAUM DRY CLEAN	35-45 35TH ST	NY SHWS, NY BROWNFIELDS, RCRA NonGen / NLR, ICIS,...	Higher	3367, 0.638, ESE
393	WILSON HANLEY, INC.	21-11 44TH AVENUE	NY SHWS, NY AST	Higher	3623, 0.686, SW
394	ARMY PICTURIAL CEN		FUDS	Higher	3724, 0.705, East
395	STANDARD MOTOR PRODU	37-18 NORTHERN BLVD	RCRA-SQG, NY SHWS, NY LTANKS, NY CBS, NY VCP, NY...	Higher	3878, 0.734, SE
396	LEVCO METALS	34-11 36TH STREET	NY SHWS, NY AST, NY INST CONTROL, NY VCP, NY...	Higher	3964, 0.751, East

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
LONDON AUTO ELECTRIC 37-05 21ST STREET LONG ISLAND CITY, NY 11101	NY AST Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609204	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL ---------- National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY ---------- Federal Facility Site Information listing

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Lists of Federal RCRA TSD facilities

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

Lists of state and tribal leaking storage tanks

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

Lists of state and tribal registered storage tanks

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

Lists of state and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---------- Registered Recycling Facility List
NY SWTIRE ---------- Registered Waste Tire Storage & Facility List
INDIAN ODI ---------- Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 ---------- Torres Martinez Reservation Illegal Dump Site Locations
ODI ---------- Open Dump Inventory
IHS OPEN DUMPS ---------- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---------- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---------- Delisted Registry Sites
US CDL ---------- National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST ---------- Historical Petroleum Bulk Storage Database
NY HIST AST ---------- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---------- Spill Liens Information
LIENS 2 ---------- CERCLA Lien Information

EXECUTIVE SUMMARY

Records of Emergency Release Reports

HMIRS	Hazardous Materials Information Reporting System
NY Hist Spills	SPILLS Database
NY SPILLS 90	SPILLS 90 data from FirstSearch
NY SPILLS 80	SPILLS 80 data from FirstSearch

Other Ascertainable Records

DOD	Department of Defense Sites
SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR	Financial Assurance Information
EPA WATCH LIST	EPA WATCH LIST
2020 COR ACTION	2020 Corrective Action Program List
TSCA	Toxic Substances Control Act
TRIS	Toxic Chemical Release Inventory System
SSTS	Section 7 Tracking Systems
RMP	Risk Management Plans
RAATS	RCRA Administrative Action Tracking System
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS	Material Licensing Tracking System
COAL ASH DOE	Steam-Electric Plant Operation Data
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER	PCB Transformer Registration Database
RADINFO	Radiation Information Database
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS	Incident and Accident Data
CONSENT	Superfund (CERCLA) Consent Decrees
INDIAN RESERV	Indian Reservations
FUSRAP	Formerly Utilized Sites Remedial Action Program
UMTRA	Uranium Mill Tailings Sites
LEAD SMELTERS	Lead Smelter Sites
US MINES	Mines Master Index File
ABANDONED MINES	Abandoned Mines
DOCKET HWC	Hazardous Waste Compliance Docket Listing
UXO	Unexploded Ordnance Sites
FUELS PROGRAM	EPA Fuels Program Registered Listing
PFAS NPL	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES	Federal Sites PFAS Information
PFAS TSCA	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR	PFAS Contamination Site Location Listing
PFAS WQP	Ambient Environmental Sampling for PFAS
PFAS NPDES	Clean Water Act Discharge Monitoring Information
PFAS ECHO FIRE TRAINING	Facilities in Industries that May Be Handling PFAS Listing
PFAS PART 139 AIRPORT	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC	Aqueous Foam Related Incidents Listing
NY COAL ASH	Coal Ash Disposal Site Listing
NY Financial Assurance	Financial Assurance Information Listing
NY HSWDS	Hazardous Substance Waste Disposal Site Inventory
NY LEAD	Lead-based Paint Testing Results
NY VAPOR REOPENED	Vapor Intrusion Legacy Site List
NY UIC	Underground Injection Control Wells

NY COOLING TOWERS Registered Cooling Towers
MINES MRDS Mineral Resources Data System
PFAS TRIS List of PFAS Added to the TRI

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP EDR Proprietary Manufactured Gas Plants

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 04/26/2023 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK Cerclis ID:: 206282 EPA Id: NYN000206282	***SOUTH END OF IVY HIL***	***S 1/2 - 1 (0.997 mi.)***	***0***	***10***

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 03/06/2023 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RAVENSWOOD PCB STORA EPA ID:: NYD003917960	***40TH AVE & VERNON BL***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ338***	***1043***

Lists of Federal RCRA generators

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/06/2023 has revealed that there are 5 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - SERVICE EPA ID:: NYP005102660	36-40 22ND ST	ENE 0 - 1/8 (0.063 mi.)	D66	189
JUNG SUN LAUNDRY SIT EPA ID:: NYR000219006	37-11 23RD ST	SE 0 - 1/8 (0.087 mi.)	J99	285
CON EDISON - QUEENSB EPA ID:: NYR000020834	***2209 39TH ST***	***S 0 - 1/8 (0.119 mi.)***	***L162***	***490***
CON EDISON - SERVICE EPA ID:: NYP005132196	36-24 CRESCENT ST	E 1/8 - 1/4 (0.188 mi.)	AD258	708

Lower Elevation	Address	Direction / Distance	Map ID	Page
38-21 12TH STREET EPA ID:: NYD003401205	***38-21 12TH STREET***	***WSW 1/8 - 1/4 (0.149 mi.)***	***V208***	***598***

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/06/2023 has revealed that there are 9 RCRA-SQG sites within approximately 0.25 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
M & B AUTO BODY INC EPA ID:: NYR000037325	***22-19 37TH AVE***	***E 0 - 1/8 (0.076 mi.)***	***C85***	***236***
JUNG SUN LAUNDRY PLU EPA ID:: NYD981081847	***37-10 24TH ST***	***ESE 0 - 1/8 (0.110 mi.)***	***J145***	***419***
LUCKY CLEANERS EPA ID:: NYD986886828	***21-20 36TH AVE***	***NE 0 - 1/8 (0.113 mi.)***	***K152***	***445***
NYC DEPT OF EDUCATIO EPA ID:: NYR000104331	***25-05 37TH AVE***	***ESE 1/8 - 1/4 (0.183 mi.)***	***AE251***	***692***
D D K PRO CLEANERS EPA ID:: NYR000164277	***38-68 13TH ST***	***WSW 1/8 - 1/4 (0.188 mi.)***	***V260***	***712***
LA MODE QUEENS INC EPA ID:: NYR000001917	***38-68 13TH ST***	***WSW 1/8 - 1/4 (0.188 mi.)***	***V262***	***739***
GIACOMELLI & MAZZA I EPA ID:: NYR000057778	***40-05 21ST ST***	***SW 1/8 - 1/4 (0.240 mi.)***	***AK303***	***849***
WALKER E WHYTE INC EPA ID:: NY0000915165	***22-14 40TH AVE***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AQ313***	***887***

Lower Elevation	Address	Direction / Distance	Map ID	Page
MIDNIGHT EXPRESS EPA ID:: NYD986953693	***38-38 13TH ST***	***WSW 1/8 - 1/4 (0.148 mi.)***	***V206***	***589***

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 03/06/2023 has revealed that there are 7 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
PERDIDO PRODS CONSTR EPA ID:: NYR000090720	***37-22 23RD ST GRD WH***	***ESE 0 - 1/8 (0.070 mi.)***	***C81***	***223***
PEP BOYS STORE #1072 EPA ID:: NYR000207662	***38-19 21ST ST***	***SW 0 - 1/8 (0.089 mi.)***	***F102***	***304***
IMOG AUTOMOTIVE INC EPA ID:: NYR000043778	***38-44 13TH ST***	***WSW 1/8 - 1/4 (0.151 mi.)***	***V214***	***616***
ATLANTIC PRECIOUS ME EPA ID:: NYR000022699	***22-12 40TH AVE***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AQ307***	***865***

Lower Elevation	Address	Direction / Distance	Map ID	Page
NYC BD OF ED - PUBLI EPA ID:: NYR000010801	***37-15 13TH ST***	***WNW 0 - 1/8 (0.070 mi.)***	***H79***	***215***
DRAPEMASTERS OF AMER	36-02 13TH ST	NNW 1/8 - 1/4 (0.135 mi.)	O193	555

EPA ID:: NYN008017998

CENTRAL COLLISION IN	***10-12 36TH AVE***	***NNW 1/8 - 1/4 (0.244 mi.)***	***AJ312***	***882***

EPA ID:: NYD045428125

Lists of state- and tribal hazardous waste facilities

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 02/06/2023 has revealed that there are 14 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JUNG SUN LAUNDRY SIT	37-10 24TH STREET	ESE 0 - 1/8 (0.110 mi.)	J143	416
Site Code: 374812				
Class Code: Significant threat to the public health or environment - action required.				
BEST-DDK CLEANERS	38-68 13TH STREET	WSW 1/8 - 1/4 (0.188 mi.)	V261	737
Site Code: 439625				
FRESH CLEANERS & LAU	***39-26 30TH ST***	***SSE 1/4 - 1/2 (0.400 mi.)***	***BG361***	***1103***
Site Code: 440982				
Class Code: Significant threat to the public health or environment - action required.				
MOTOR AND IRON WORKS	***37-21 32ND STREET***	***SE 1/4 - 1/2 (0.473 mi.)***	***BL382***	***1213***
Site Code: 532999				
34-14 31ST STREET	34-14 31ST STREET	E 1/2 - 1 (0.531 mi.)	388	1242
Site Code: 514253				
FORMER LUFT CO. INC.	***34-12 36TH AVENUE***	***ESE 1/2 - 1 (0.557 mi.)***	***389***	***1244***
Site Code: 460318				
AMTRAK SUNNYSIDE YAR	***39-29 HONEYWELL STRE***	***SE 1/2 - 1 (0.560 mi.)***	***390***	***1247***
Site Code: 57794				
Class Code: Significant threat to the public health or environment - action required.				
THE WILLS BUILDING	***43-01 21ST STREET***	***SW 1/2 - 1 (0.619 mi.)***	***391***	***1267***
Site Code: 477031				
TEITELBAUM DRY CLEAN	***35-45 35TH ST***	***ESE 1/2 - 1 (0.638 mi.)***	***392***	***1291***
Site Code: 481508				
WILSON HANLEY, INC.	***21-11 44TH AVENUE***	***SW 1/2 - 1 (0.686 mi.)***	***393***	***1324***
Site Code: 384281				
STANDARD MOTOR PRODU	***37-18 NORTHERN BLVD***	***SE 1/2 - 1 (0.734 mi.)***	***395***	***1328***
Site Code: 58682				
Class Code: Significant threat to the public health or environment - action required.				
LEVCO METALS	***34-11 36TH STREET***	***E 1/2 - 1 (0.751 mi.)***	***396***	***1355***
Site Code: 58675				

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL RUBBER & BA	***38-31 9TH ST***	***W 1/4 - 1/2 (0.281 mi.)***	***AS321***	***906***

Site Code: 58713
Class Code: Significant threat to the public health or environment - action required.

RAVENSWOOD GENERATIN	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ336***	***1014***

Site Code: 416958

Lists of state and tribal landfills and solid waste disposal facilities

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 03/31/2023 has revealed that there are 4 NY SWF/LF sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CITY USED AUTO CENTE	***37-25 21ST STREET***	***0 - 1/8 (0.000 mi.)***	***A3***	***20***

Lower Elevation	Address	Direction / Distance	Map ID	Page
GE-TSELEL AUTOMOTIVE	36-28 14TH STREET	N 0 - 1/8 (0.069 mi.)	G76	211
ASTORIA USED AUTO PA	36-28 14TH STREET	N 0 - 1/8 (0.069 mi.)	G77	212
PATANO BROTHERS;INC	38-36 10 STREET	W 1/4 - 1/2 (0.257 mi.)	AS316	901

Lists of state and tribal leaking storage tanks

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 02/06/2023 has revealed that there are 63 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
37-24 24TH ST/QUEENS Spill Number/Closed Date: 8905393 / 1992-10-02 Site ID: 177843 Spill Date: 1989-08-31	37-24 24TH STREET	ESE 0 - 1/8 (0.120 mi.)	J169	508
39-15 21ST STREET Spill Number/Closed Date: 9308729 / 2003-03-14 Site ID: 149681 Spill Date: 1993-10-19	39-15 21ST STREET	SW 1/8 - 1/4 (0.153 mi.)	P215	619
AROON SUKRANICHANNE Spill Number/Closed Date: 9414758 / 1995-02-09 Site ID: 311462 Spill Date: 1995-02-08	36-46 CRESCENT STREE	ESE 1/8 - 1/4 (0.171 mi.)	S231	648
SPILL NUMBER 0005416 Spill Number/Closed Date: 0005416 / 2003-03-04 Site ID: 115362	CRESCENT ST/37TH AV	ESE 1/8 - 1/4 (0.179 mi.)	AE244	678

Spill Date: 2000-08-06				
25-05 37TH AVE	25-05 37TH AVE	ESE 1/8 - 1/4 (0.183 mi.)	AE250	688
Spill Number/Closed Date: 9301138 / 2005-03-14				
Spill Number/Closed Date: 9900152 / 2006-01-05				
Spill Number/Closed Date: 9900153 / 2004-01-15				
Site ID: 150419				
Site ID: 150420				
Site ID: 150421				
Spill Date: 1993-04-23				
Spill Date: 1999-04-05				
37-23 CRESCENT AVENU	37-23 CRESCENT AVENU	SE 1/8 - 1/4 (0.188 mi.)	AE256	707
Spill Number/Closed Date: 9410285 / 1994-11-02				
Site ID: 77942				
Spill Date: 1994-11-02				
38-31 CRESCENT ST	38-31 CRESCENT ST	SSE 1/8 - 1/4 (0.210 mi.)	AF278	795
Spill Number/Closed Date: 0011444 / 2001-10-23				
Site ID: 123310				
Spill Date: 2001-01-22				
UNDERGROUND LINE	***27-10 37TH AVE***	***ESE 1/8 - 1/4 (0.243 mi.)***	***AO308***	***870***
Spill Number/Closed Date: 9712733 / 2003-02-19				
Site ID: 168989				
Spill Date: 1998-02-13				
ABANDONED BLDG	38-28 28TH ST	SSE 1/4 - 1/2 (0.271 mi.)	AP318	902
Spill Number/Closed Date: 9805230 / 1999-04-27				
Site ID: 271765				
Spill Date: 1998-07-27				
QUEENS WEST 01 DOS -	***34-28 21ST STREET***	***NNE 1/4 - 1/2 (0.306 mi.)***	***326***	***923***
Spill Number/Closed Date: 9809914 / 2005-12-20				
Spill Number/Closed Date: 0001441 / 2016-06-10				
Spill Number/Closed Date: 0012293 / 2017-04-03				
Site ID: 174749				
Site ID: 174744				
Site ID: 174746				
Spill Date: 1998-11-06				
Spill Date: 2000-05-04				
Spill Date: 2001-02-15				
COMMERCIAL BUILDING	40-23 24TH ST'	S 1/4 - 1/2 (0.307 mi.)	AW327	934
Spill Number/Closed Date: 0506977 / 2006-01-05				
Site ID: 352289				
Spill Date: 2005-09-08				
CENTRAL SERVICE BUIL	10-06 35TH AVENUE	NNW 1/4 - 1/2 (0.313 mi.)	AX331	941
Spill Number/Closed Date: 0904512 / 2009-10-15				
Spill Number/Closed Date: 0904516 / 2013-06-10				
Site ID: 416679				
Site ID: 416683				
Spill Date: 2009-07-17				
NYS DEPT. OF CORRECT	10-06 35TH AVE	NNW 1/4 - 1/2 (0.328 mi.)	AX334	995
Spill Number/Closed Date: 0403872 / 2005-07-11				
Site ID: 325773				
Spill Date: 2004-07-12				
GULF STATION	***23-01 41ST AVE***	***SSW 1/4 - 1/2 (0.331 mi.)***	***AY339***	***1060***

Spill Number/Closed Date: 0808735 / 2009-08-28
Spill Number/Closed Date: 0308076 / 2004-01-07
Site ID: 406141
Site ID: 237638
Spill Date: 2008-11-03
Spill Date: 2003-10-30

CLOSED-LACKOF RECENT	40-40 CRESCENT ST	S 1/4 - 1/2 (0.341 mi.)	AW342	1065
Spill Number/Closed Date: 9105613 / 2003-03-14 Site ID: 271352 Spill Date: 1991-08-23				
24-03 41ST AVE	***24-03 41ST AVE***	***SSW 1/4 - 1/2 (0.350 mi.)***	***AW344***	***1070***
Spill Number/Closed Date: 8709565 / 1993-02-25 Site ID: 174701 Spill Date: 1988-02-10				
APRT	2403 41ST AVE	SSW 1/4 - 1/2 (0.351 mi.)	AW345	1073
Spill Number/Closed Date: 0711618 / 2008-04-02 Site ID: 393128 Spill Date: 2008-02-04				
25-13 35TH AVENUE	25-13 35TH AVENUE	ENE 1/4 - 1/2 (0.354 mi.)	347	1076
Spill Number/Closed Date: 9500610 / 1995-04-17 Site ID: 212947 Spill Date: 1995-04-14				
2912 36TH AVE	2912 36TH AVE	ESE 1/4 - 1/2 (0.356 mi.)	348	1077
Spill Number/Closed Date: 9511910 / 1995-12-20 Site ID: 273864 Spill Date: 1995-12-20				
CLOSED-LACKOF RECENT	39038 29TH ST.	SSE 1/4 - 1/2 (0.360 mi.)	BC349	1078
Spill Number/Closed Date: 8705823 / 2003-03-04 Site ID: 186869 Spill Date: 1987-10-09				
CHURCH	39-38 29TH STREET	SSE 1/4 - 1/2 (0.365 mi.)	BC350	1079
Spill Number/Closed Date: 0411422 / 2006-01-17 Spill Number/Closed Date: 0411423 / 2005-03-28 Site ID: 336615 Site ID: 336616 Spill Date: 2005-01-21				
SEE FACTOR INDUSTRY	37-11 30TH ST	SE 1/4 - 1/2 (0.373 mi.)	BD353	1085
Spill Number/Closed Date: 9801491 / 2004-09-15 Site ID: 208588 Spill Date: 1998-04-21				
EMPIRE VENTALATION	35-39 VERNON BLVD	NNW 1/4 - 1/2 (0.375 mi.)	BE355	1090
Spill Number/Closed Date: 9516793 / 1996-03-28 Site ID: 235467 Spill Date: 1996-03-28				
CONSTRUCTION SITE	35-38 JUNCTION BLVD	NNW 1/4 - 1/2 (0.375 mi.)	BE356	1091
Spill Number/Closed Date: 0501160 / 2005-05-27 Site ID: 344316 Spill Date: 2005-04-28				
LOVOUR HOME	2512 41ST AVE	S 1/4 - 1/2 (0.399 mi.)	BF358	1096
Spill Number/Closed Date: 0700688 / 2010-02-17 Site ID: 380071				

Spill Date: 2007-04-18

RAINEY SUBSTATION | 35 ST / VERNON BLVD | NNW 1/4 - 1/2 (0.402 mi.) | BH363 | 1148
Spill Number/Closed Date: 9807334 / 2007-03-01
Spill Number/Closed Date: 9514765 / 2001-09-19
Site ID: 190317
Site ID: 252596
Spill Date: 1998-09-15
Spill Date: 1996-02-18

35-01 VERNON BLVD | 35-01 VERNON BLVD | NNW 1/4 - 1/2 (0.409 mi.) | BH366 | 1154
Spill Number/Closed Date: 8603127 / 1987-08-21
Site ID: 276285
Spill Date: 1986-08-11

34-44 9TH ST | 34-44 9TH ST | NNW 1/4 - 1/2 (0.413 mi.) | BI369 | 1179
Spill Number/Closed Date: 9414006 / 1995-01-20
Site ID: 134017
Spill Date: 1995-01-20

NORTH QUEENS VIEW HO | 33-60 21ST STREET | NNE 1/4 - 1/2 (0.417 mi.) | 370 | 1180
Spill Number/Closed Date: 1009673 / 2010-12-10
Site ID: 443237
Spill Date: 2010-12-01

CLOSED-LACKOF RECENT | 29024 40TH AVENUE | SSE 1/4 - 1/2 (0.431 mi.) | BG373 | 1186
Spill Number/Closed Date: 8709369 / 2003-03-13
Site ID: 125139
Spill Date: 1988-02-03

UNKNOWN TTF | 34-25 VERNON BLVD | NNW 1/4 - 1/2 (0.436 mi.) | BI374 | 1187
Spill Number/Closed Date: 1010069 / 2015-10-01
Site ID: 443655
Spill Date: 2010-12-22

KAL REALTY | 29-24 40TH AVE | SSE 1/4 - 1/2 (0.439 mi.) | 376 | 1192
Spill Number/Closed Date: 9806658 / 2005-06-15
Site ID: 172099
Spill Date: 1998-08-28

MANHOLE 14413 | ***QUEENS PLAZA NORTH*** | ***SW 1/4 - 1/2 (0.456 mi.)*** | ***377*** | ***1193***
Spill Number/Closed Date: 0100062 / 2003-06-16
Site ID: 63771
Spill Date: 2001-04-03

APARTMENT BLDG | 21-50 33RD ROAD | NE 1/4 - 1/2 (0.464 mi.) | 378 | 1195
Spill Number/Closed Date: 1200162 / 2012-12-11
Site ID: 462778
Spill Date: 2012-04-05

BENIGNO FERNANEZ (P | ***31-01 NORTHERN BLVD*** | ***SSE 1/4 - 1/2 (0.469 mi.)*** | ***381*** | ***1203***
Spill Number/Closed Date: 8700671 / 2006-08-30
Site ID: 149864
Spill Date: 1987-04-22

32-10 37TH AV | 32-10 37TH AVE | ESE 1/4 - 1/2 (0.480 mi.) | BL383 | 1220
Spill Number/Closed Date: 0200301 / 2005-06-16
Site ID: 147177
Spill Date: 2002-04-09

32-15 37TH AVE | 32-15 37TH AVE | ESE 1/4 - 1/2 (0.480 mi.) | BL384 | 1221
Spill Number/Closed Date: 9212707 / 1993-03-10
Site ID: 220254

Spill Date: 1993-02-10

FALIDAS ASSCOCIATES ***25-01 QUEENS PLAZA N*** ***S 1/4 - 1/2 (0.480 mi.)*** ***BK385*** ***1222***
Spill Number/Closed Date: 0305348 / 2007-05-21
Spill Number/Closed Date: 8905133 / 1992-11-19
Site ID: 66252
Site ID: 237933
Spill Date: 2003-08-01
Spill Date: 1989-08-23

HALKIDIKI AUTO CENTE ***33-21 21ST STREET*** ***NE 1/4 - 1/2 (0.486 mi.)*** ***386*** ***1230***
Spill Number/Closed Date: 8809261 / 2003-07-29
Site ID: 296241
Spill Date: 1989-02-28

CLOSED-LACKOF RECENT 37-14 33RD STREET SE 1/4 - 1/2 (0.499 mi.) BL387 1241
Spill Number/Closed Date: 8905637 / 2003-03-06
Site ID: 221353
Spill Date: 1989-09-08

Lower Elevation	Address	Direction / Distance	Map ID	Page
VACANT BUILDING Spill Number/Closed Date: 9604477 / 1996-09-16 Site ID: 79310 Spill Date: 1996-07-03	12-12 37TH AVE	NW 0 - 1/8 (0.097 mi.)	H109	325
38-21 12TH ST/QUEENS Spill Number/Closed Date: 8706722 / 1994-02-07 Site ID: 321182 Spill Date: 1987-11-07	38-21 12TH ST.	W 0 - 1/8 (0.105 mi.)	N132	389
COMMERCIAL BUILDING Spill Number/Closed Date: 0511360 / 2006-06-28 Site ID: 357496 Spill Date: 2005-12-29	1204 37TH AVE	NW 0 - 1/8 (0.109 mi.)	H137	397
3712 11TH STREET Spill Number/Closed Date: 9416667 / 1995-03-24 Site ID: 313687 Spill Date: 1995-03-24	3712 11TH STREET	WNW 1/8 - 1/4 (0.180 mi.)	AB245	679
10-12 37TH AVE Spill Number/Closed Date: 9406565 / 1994-08-15 Site ID: 132553 Spill Date: 1994-08-15	10-12 37TH AVE	WNW 1/8 - 1/4 (0.197 mi.)	AB266	765
PARISI - WAREHOUSE Spill Number/Closed Date: 0513981 / 2006-04-18 Site ID: 360577 Spill Date: 2006-03-07	36-21 10TH STREET	NW 1/8 - 1/4 (0.223 mi.)	AM290	824
3707 9TH AVENUE Spill Number/Closed Date: 9315059 / 1994-03-24 Site ID: 167949 Spill Date: 1994-03-23	3707 9TH AVENUE	WNW 1/4 - 1/2 (0.253 mi.)	AR315	900
PERETTE HALL Spill Number/Closed Date: 0602016 / 2006-05-24 Site ID: 364400 Spill Date: 2006-05-24	38-62 11TH STREET	WSW 1/4 - 1/2 (0.265 mi.)	AT317	901
QUEENSBRIDGE PLANT B	40001 12TH ST	SW 1/4 - 1/2 (0.283 mi.)	AU322	918

Spill Number/Closed Date: 9205290 / 1995-08-16
Site ID: 213263
Spill Date: 1992-08-07

8-14 37TH AVE. | 8-14 37TH AVE. | WNW 1/4 - 1/2 (0.283 mi.) | AR323 | 920
Spill Number/Closed Date: 9207231 / 1992-12-10
Site ID: 316906
Spill Date: 1992-09-22

QUEENSBRIDGE PLANT A | 40013 12TH STREET | SW 1/4 - 1/2 (0.285 mi.) | AU324 | 921
Spill Number/Closed Date: 9008034 / 1995-08-16
Site ID: 67975
Spill Date: 1990-10-23

RAINEY | 38TH ST & VERNON BLV | WNW 1/4 - 1/2 (0.311 mi.) | AV328 | 936
Spill Number/Closed Date: 9313425 / 2000-08-07
Site ID: 224933
Spill Date: 1994-02-15

QUEENSBRIDGE PLANT D | 41004 10TH STREET | WSW 1/4 - 1/2 (0.311 mi.) | AT329 | 937
Spill Number/Closed Date: 9314508 / 2013-08-07
Site ID: 310358
Spill Date: 1990-11-13

3809 VERNON BLVD | 3809 VERNON BLVD | W 1/4 - 1/2 (0.311 mi.) | AV330 | 940
Spill Number/Closed Date: 9406830 / 2003-02-28
Site ID: 210092
Spill Date: 1994-08-19

RAVENSWOOD GENERATIN | ***38-54 VERNON BOULEVA*** | ***W 1/4 - 1/2 (0.329 mi.)*** | ***AZ336*** | ***1014***
Spill Number/Closed Date: 9601426 / 1996-05-30
Spill Number/Closed Date: 9613378 / 1997-02-13
Site ID: 239166
Site ID: 239188
Spill Date: 1996-04-28
Spill Date: 1997-02-12

35-41 11TH ST/QUEENS | 35-41 11TH ST | N 1/4 - 1/2 (0.337 mi.) | BA341 | 1064
Spill Number/Closed Date: 8708941 / 1992-10-07
Site ID: 165876
Spill Date: 1988-01-20

41ST AVENUE & 12ST S | 41ST AVE/12TH STREET | SW 1/4 - 1/2 (0.353 mi.) | BB346 | 1075
Spill Number/Closed Date: 9313090 / 2003-03-11
Site ID: 223819
Spill Date: 1994-02-17

CHUCK'S PLACE - QNS | 34-59 11TH ST | N 1/4 - 1/2 (0.368 mi.) | BA351 | 1082
Spill Number/Closed Date: 8908538 / 2005-06-20
Site ID: 163382
Spill Date: 1989-11-29

34-24 11TH ST | 34-24 11TH ST | N 1/4 - 1/2 (0.368 mi.) | BA352 | 1084
Spill Number/Closed Date: 0209381 / 2005-11-07
Site ID: 155841
Spill Date: 2002-12-10

QUEENSBRIDGE PLANT B | 41001 12TH STREET | SW 1/4 - 1/2 (0.377 mi.) | BB357 | 1093
Spill Number/Closed Date: 9009185 / 1995-08-16
Spill Number/Closed Date: 9305924 / 1995-08-16
Site ID: 178671
Site ID: 178672

Spill Date: 1990-11-21
Spill Date: 1993-08-12

34-19 11TH STREET / 34-19 11TH STREET N 1/4 - 1/2 (0.405 mi.) 364 1151
Spill Number/Closed Date: 8606945 / 1987-03-02
Site ID: 249079
Spill Date: 1987-02-12

QUEENSBRIDGE PLANT E 40009 VERNON BLVD W 1/4 - 1/2 (0.405 mi.) 365 1152
Spill Number/Closed Date: 9008149 / 2018-09-26
Site ID: 294984
Spill Date: 1990-10-25

QUEENSBRIDGE PLANT F 4105 VERNON BLVD. WSW 1/4 - 1/2 (0.466 mi.) 379 1197
Spill Number/Closed Date: 9314507 / 1995-08-16
Site ID: 212252
Spill Date: 1990-11-16

Lists of state and tribal registered storage tanks

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 33 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LI CITY GAS & CONVEN Database: UST, Date of Government Version: 02/14/2023	3725 21ST ST	0 - 1/8 (0.000 mi.)	A7	31
22-11 38TH AVE Database: UST, Date of Government Version: 02/14/2023	22-11 38TH AVE	SSE 0 - 1/8 (0.052 mi.)	E50	135
SHELL SERVICE STATIO Database: UST, Date of Government Version: 02/14/2023	38-02 21ST STREET	SW 0 - 1/8 (0.058 mi.)	F60	153
ULTIMATE AUTO CARE Database: UST, Date of Government Version: 02/14/2023	36-37 21ST STREET	NNE 0 - 1/8 (0.062 mi.)	D64	184
HERTZ PARKING LOT Database: UST, Date of Government Version: 02/14/2023	38-15 21 ST	SW 0 - 1/8 (0.080 mi.)	F89	264
JIANGS REALTY INC Database: UST, Date of Government Version: 02/14/2023	36-21 22ND STREET	ENE 0 - 1/8 (0.089 mi.)	I104	309
SEVIM MGMT BP PRODUC Database: UST, Date of Government Version: 02/14/2023	36-42 21ST STREET	NNE 0 - 1/8 (0.094 mi.)	K108	321
GLOBAL MONTELLO GROU Database: UST, Date of Government Version: 02/14/2023	36-02 21ST STREET	NNE 0 - 1/8 (0.101 mi.)	K121	353
LUPOLI SERVICE STATI Database: UST, Date of Government Version: 02/14/2023	38-25 21ST STREET	SW 0 - 1/8 (0.103 mi.)	L127	373
JACKSON DEVELOPMENTA Database: UST, Date of Government Version: 02/14/2023	3602 14TH ST	N 0 - 1/8 (0.107 mi.)	O135	393
GRANT INT'L CO., INC Database: UST, Date of Government Version: 02/14/2023	21-24 39TH AVENUE	SSW 0 - 1/8 (0.109 mi.)	L141	408
SILKS BUILDING Database: UST, Date of Government Version: 02/14/2023	37-24 24TH ST	SE 0 - 1/8 (0.110 mi.)	J148	435

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
QUEENSBRIDGE CENTRAL Database: UST, Date of Government Version: 02/14/2023	22-09 39TH AVENUE	S 0 - 1/8 (0.119 mi.)	L160	484
CITY AUTO SERVICE IN Database: UST, Date of Government Version: 02/14/2023	39-01 21ST STREET	SW 1/8 - 1/4 (0.132 mi.)	P191	542
TRI STAR LUMBER CORP Database: UST, Date of Government Version: 02/14/2023	37-01 24TH ST	ESE 1/8 - 1/4 (0.135 mi.)	S192	553
VACANT INDUSTRIAL PR Database: UST, Date of Government Version: 02/14/2023	36-15 23RD STREET	ENE 1/8 - 1/4 (0.136 mi.)	T194	558
HEPHAISTOS BUILDING Database: UST, Date of Government Version: 02/14/2023	24-02 37TH AVENUE	ESE 1/8 - 1/4 (0.136 mi.)	S195	560
MONARCH CONSTRUCTION Database: UST, Date of Government Version: 02/14/2023	***39-16 23RD STREET***	***SSW 1/8 - 1/4 (0.173 mi.)***	***236***	***656***
PUBLIC SCHOOL 112 - Database: UST, Date of Government Version: 02/14/2023	25-05 37TH AVENUE	ESE 1/8 - 1/4 (0.183 mi.)	AE253	700
DE MAMS, LLC Database: UST, Date of Government Version: 02/14/2023	13-09 40TH AVENUE	SW 1/8 - 1/4 (0.217 mi.)	AC286	809
22-11 40 AVENUE Database: UST, Date of Government Version: 02/14/2023	22-11 40 AV	SSW 1/8 - 1/4 (0.222 mi.)	AK289	819

Lower Elevation	Address	Direction / Distance	Map ID	Page
CHRISTIAN ECKHOFF TR Database: UST, Date of Government Version: 02/14/2023	36-22 14TH STREET	N 0 - 1/8 (0.085 mi.)	G96	281
1212 37TH AVENUE Database: UST, Date of Government Version: 02/14/2023	12-12 37TH AVENUE	NW 0 - 1/8 (0.097 mi.)	H110	326
AUDAX CONSTRUCTION C Database: UST, Date of Government Version: 02/14/2023	12-04 37TH AVENUE	NW 0 - 1/8 (0.109 mi.)	H136	395
ENGINE COMPANY 260 Database: UST, Date of Government Version: 02/14/2023	11-15 37TH AVENUE	NW 1/8 - 1/4 (0.142 mi.)	Q198	567
38-21 12 ST PARTNERS Database: UST, Date of Government Version: 02/14/2023	38-21 12TH ST	WSW 1/8 - 1/4 (0.149 mi.)	V210	607
36-05 12TH ST Database: UST, Date of Government Version: 02/14/2023	36-05 12TH STREET	NNW 1/8 - 1/4 (0.155 mi.)	W219	628
ST RITA SCHOOL Database: UST, Date of Government Version: 02/14/2023	36-22 12TH STREET	NNW 1/8 - 1/4 (0.161 mi.)	Z221	631
VOICE CHARTER SCHOOL Database: UST, Date of Government Version: 02/14/2023	36-14 12TH STREET	NNW 1/8 - 1/4 (0.165 mi.)	W227	642
ST RITA RECTORY Database: UST, Date of Government Version: 02/14/2023	36-25 11 ST	NW 1/8 - 1/4 (0.184 mi.)	Z254	702
UNITED HOISTING COMP Database: UST, Date of Government Version: 02/14/2023	38-51 11TH ST	WSW 1/8 - 1/4 (0.215 mi.)	282	800
38-70 12TH STREET Database: UST, Date of Government Version: 02/14/2023	38-70 12TH STREET	WSW 1/8 - 1/4 (0.223 mi.)	AH291	825
DAWNEX INDUSTRIES IN Database: UST, Date of Government Version: 02/14/2023	38-61 11TH STREET	WSW 1/8 - 1/4 (0.229 mi.)	AH298	841

EXECUTIVE SUMMARY

NY MOSF UST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF UST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 2 NY MOSF UST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RAVENWOOD GAS TURBIN	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ335***	***997***
RAVENSWOOD GENERATIN	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ336***	***1014***

NY MOSF: These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

A review of the NY MOSF list, as provided by EDR, and dated 02/14/2023 has revealed that there is 1 NY MOSF site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RAVENSWOOD GENERATIN	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ336***	***1014***
Tank Status: Active				
Tank Status: Unregulated/Closed				
Facility Id: 2-1960				
Facility Id: 2-1980				

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 02/14/2023 has revealed that there are 3 NY CBS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KOCH & LOW	***21-24 39TH AVE***	***SSW 0 - 1/8 (0.109 mi.)***	***L142***	***409***
Facility Status: Unregulated/Closed				
CBS Number: 2-000131				
D. MOY & SONS	***36-44 24 STREET***	***ESE 1/8 - 1/4 (0.126 mi.)***	***S184***	***529***
Facility Status: Unregulated/Closed				
CBS Number: 2-000262				
PEP BOYS #0437	***3850 21ST ST***	***SW 1/8 - 1/4 (0.145 mi.)***	***P202***	***576***
Facility Status: Unregulated/Closed				
CBS Number: 2-000421				

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 49 NY AST sites within approximately 0.25 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LIC USED AUTO PARTS Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609133	37-25 21ST ST	0 - 1/8 (0.000 mi.)	A4	24
LI CITY GAS & CONVEN Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-601352	3725 21ST ST	0 - 1/8 (0.000 mi.)	A5	26
NEW BANGLA MOTOR INC Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609202	37-25 21ST STREET	0 - 1/8 (0.000 mi.)	A6	28
QAZI AUTO REPAIRS IN Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-610365	37-27 21ST STREET	NNW 0 - 1/8 (0.005 mi.)	A10	46
NEW YORK AUTO LIC, I Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-604092	21-10 38TH AVENUE	SW 0 - 1/8 (0.036 mi.)	B34	109
T.J. AUTO BODY & REP Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609180	37-09 22ND STREET	ESE 0 - 1/8 (0.036 mi.)	C35	111
37-11 22 ST Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-607956	37-11 22ND STREET	SE 0 - 1/8 (0.036 mi.)	C36	113
7096681 N.Y. AUTO BO Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-604088	38-02 22ND STREET	S 0 - 1/8 (0.042 mi.)	B46	127
KING OF QUEENS AUTO Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-611279	38-03 21ST STREET	SW 0 - 1/8 (0.051 mi.)	B48	129
KING OF QUEENS AUTO Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-613200	3803 21ST STREET	SW 0 - 1/8 (0.051 mi.)	B49	132
QUALITY CAR TECH INC Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609179	22-08 37TH AVENUE	ESE 0 - 1/8 (0.053 mi.)	C54	142
G. CHANAB AUTO & BOD Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-607943	22-01 37TH AVE	E 0 - 1/8 (0.054 mi.)	C57	147
A1 COLLISION INC. Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612877	2207 37 AVE	E 0 - 1/8 (0.061 mi.)	C61	179
ULTIMATE AUTO CARE Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-188484	36-37 21ST STREET	NNE 0 - 1/8 (0.062 mi.)	D62	181
AAD AUTO REPAIR & BO Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609381	22-15 37TH AVENUE	E 0 - 1/8 (0.068 mi.)	C74	208
AUTO CARE LUBE, LTD Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609550	36-21 21ST STREET	NE 0 - 1/8 (0.071 mi.)	D82	227
BMI AUTO BODY CENTER Database: AST, Date of Government Version: 02/14/2023	36-33/35 22ND STREET	ENE 0 - 1/8 (0.074 mi.)	I83	232

Facility Id: 2-607959

PEP BOYS #437	38-50 21ST STREET	SW 0 - 1/8 (0.080 mi.)	F91	272
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-603131				
PEP BOYS STORE #1072	38-19 21ST STREET	SW 0 - 1/8 (0.089 mi.)	F103	307
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612278				
SEGUNDO'S AUTO REPAI	38-38 22ND STREET	SSW 0 - 1/8 (0.100 mi.)	L111	328
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609132				
GLOBAL MONTELLO GROU	36-02 21ST STREET	NNE 0 - 1/8 (0.101 mi.)	K119	340
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-146048				
NEW HIGH TECH AUTO R	38-25 21ST STREET	SW 0 - 1/8 (0.103 mi.)	L126	371
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609972				
MARVIC TRANSMISSION	23-12 38TH AVENUE	SSE 0 - 1/8 (0.105 mi.)	M129	382
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-604521				
NEW YOGI TRANSMISSIO	21-10 39TH AVENUE	SSW 0 - 1/8 (0.109 mi.)	L138	402
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609047				
KOCH & LOW	***21-24 39TH AVE***	***SSW 0 - 1/8 (0.109 mi.)***	***L142***	***409***
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-000131				
QUEENSBRIDGE CENTRAL	22-09 39TH AVENUE	S 0 - 1/8 (0.119 mi.)	L163	497
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-452920				
B&F AUTO CARE INC.	38-21 23RD STREET	S 0 - 1/8 (0.122 mi.)	R176	518
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-610326				
D. MOY & SONS	***36-44 24 STREET***	***ESE 1/8 - 1/4 (0.126 mi.)***	***S184***	***529***
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-000262				
CITY AUTO SERVICE IN	39-01 21ST STREET	SW 1/8 - 1/4 (0.132 mi.)	P190	540
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-600273				
38-24 24 ST. LLC	38-24 24TH STREET	SSE 1/8 - 1/4 (0.139 mi.)	R196	562
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609203				
PEP BOYS #0437	***3850 21ST ST***	***SW 1/8 - 1/4 (0.145 mi.)***	***P202***	***576***
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-000421				
P & A AUTO SERVICE,	38-09 24TH STREET	SSE 1/8 - 1/4 (0.147 mi.)	M204	582
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609145				
QUEENS AUTO & BODY S	38-56 13TH STREET	WSW 1/8 - 1/4 (0.162 mi.)	V223	633
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609693				
MC ACROPOLIS, LLC	24-16 38TH AVENUE	SSE 1/8 - 1/4 (0.163 mi.)	Y224	635
Database: AST, Date of Government Version: 02/14/2023				

Facility Id: 2-326143

PUBLIC SCHOOL 112 -	25-05 37TH AVENUE	ESE 1/8 - 1/4 (0.183 mi.)	AE252	697
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-478741				
37-27 CRESCENT ST	37-27 CRESCENT ST	SE 1/8 - 1/4 (0.187 mi.)	Y255	704
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-114464				
38-05 CRESCENT STREE	38-05 CRESCENT STREE	SSE 1/8 - 1/4 (0.192 mi.)	Y265	763
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-249289				
39-23 REALTY LLC	39-23 24TH STREET	S 1/8 - 1/4 (0.211 mi.)	AI279	796
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-609677				
39-31 24TH ST	39-31 24TH STREET	S 1/8 - 1/4 (0.223 mi.)	AI292	828
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-611437				
37-15 27 STREET CORP	37-15 27 STREET	SE 1/8 - 1/4 (0.233 mi.)	AO300	844
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-130060				
22-14 40TH AVENUE	22-14 40TH AVENUE	SSW 1/8 - 1/4 (0.245 mi.)	AQ314	897
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-611861				

Lower Elevation	Address	Direction / Distance	Map ID	Page
PUBLIC SCHOOL 111 -	37-15 13TH STREET	WNW 0 - 1/8 (0.070 mi.)	H80	220
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-355186				
ENGINE COMPANY 260	11-15 37TH AVENUE	NW 1/8 - 1/4 (0.142 mi.)	Q197	564
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-600525				
CHECKER MANAGEMENT C	11-05 38 AVE.	W 1/8 - 1/4 (0.155 mi.)	X217	621
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612682				
2-612682	11-05 38TH AVENUE	W 1/8 - 1/4 (0.155 mi.)	X218	625
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-612689				
APLINE STORE EQUIPME	37-10 10TH AVE	WNW 1/8 - 1/4 (0.223 mi.)	AG293	830
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-601911				
DAWNEX INDUSTRIES IN	38-61 11TH STREET	WSW 1/8 - 1/4 (0.229 mi.)	AH297	839
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-116637				
WEGNER MACHINERY COR	***35-41 11TH ST***	***NNW 1/8 - 1/4 (0.241 mi.)***	***304***	***855***
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-243957				
P.S. 76 - QUEENS Q07	36-36 10TH STREET	NW 1/8 - 1/4 (0.243 mi.)	AM309	873
Database: AST, Date of Government Version: 02/14/2023 Facility Id: 2-355089				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
KOCH & LOW	***21-24 39TH AVE***	***SSW 0 - 1/8 (0.109 mi.)***	***L142***	***409***
Facility Status: 2				
Facility Status: 2				
CBS Number: 2-000131				

NY MOSF AST: Major Oil Storage Facilities Database. Facilities are licensed pursuant to Article 12 of the Navigation Law, 6 NYCRR Part 610 and 17 NYCRR Part 30. These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater. Includes MOSF's licensed or closed since April 1, 1986, (responsibility was transferred from DOT on October 13, 1985) plus available data obtained from DOT facilities licensed since Article 12 became law on April 1, 1978.

A review of the NY MOSF AST list, as provided by EDR, and dated 01/01/2002 has revealed that there are 2 NY MOSF AST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
RAVENWOOD GAS TURBIN	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ335***	***997***
Facility Status: 3				
Facility Status: 4				
Facility Status: 5				
RAVENSWOOD GENERATIN	38-54 VERNON BOULEVA	W 1/4 - 1/2 (0.329 mi.)	AZ337	1036
Facility Status: 1				
Facility Status: 1				
Facility Status: 3				
Facility Status: 5				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 02/06/2023 has revealed that there are 3 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOUBLE E PLATING CO	***22-07 41ST AVE***	***SSW 1/4 - 1/2 (0.322 mi.)***	***AY333***	***945***
Site Code: 499923				
FRESH CLEANERS & LAU	***39-26 30TH ST***	***SSE 1/4 - 1/2 (0.400 mi.)***	***BG361***	***1103***
Site Code: 440982				
FORMER UNION WIRE DI	***39-40 30TH STREET***	***SSE 1/4 - 1/2 (0.409 mi.)***	***BG367***	***1156***
Site Code: 492945				

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 02/06/2023 has revealed that there are 3 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DOUBLE E PLATING CO Site Code: 499923	***22-07 41ST AVE***	***SSW 1/4 - 1/2 (0.322 mi.)***	***AY333***	***945***
FRESH CLEANERS & LAU Site Code: 440982	***39-26 30TH ST***	***SSE 1/4 - 1/2 (0.400 mi.)***	***BG361***	***1103***
FORMER UNION WIRE DI Site Code: 492945	***39-40 30TH STREET***	***SSE 1/4 - 1/2 (0.409 mi.)***	***BG367***	***1156***

Lists of state and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there are 5 NY VCP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
23-01 41ST AVENUE Database: VCP NYC, Date of Government Version: 03/06/2023	23-01 41ST AVENUE	SSW 1/4 - 1/2 (0.332 mi.)	AY340	1063
27-01 41ST AVENUE Database: VCP NYC, Date of Government Version: 03/06/2023	27-01 41ST AVENUE	S 1/4 - 1/2 (0.400 mi.)	BF362	1148

Lower Elevation	Address	Direction / Distance	Map ID	Page
NATIONAL RUBBER ADHE Database: VCP, Date of Government Version: 02/06/2023 Site Code: 57542	38-25/51 9TH STREET	W 1/4 - 1/2 (0.272 mi.)	AS319	904
NATIONAL RUBBER & BA Database: VCP, Date of Government Version: 02/06/2023 Site Code: 57620	***38-31 9TH ST***	***W 1/4 - 1/2 (0.281 mi.)***	***AS321***	***906***
RAVENSWOOD GENERATIN Database: VCP, Date of Government Version: 02/06/2023 Site Code: 56967	***38-54 VERNON BOULEVA***	***W 1/4 - 1/2 (0.329 mi.)***	***AZ336***	***1014***

Lists of state and tribal brownfield sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 02/06/2023 has revealed that there are 15 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BEST DDK CLEANERS	38-68 13TH STREET	WSW 1/8 - 1/4 (0.188 mi.)	V259	711

Site Code: 617151				
FORMER HYGRADE POLIS Site Code: 520289	22-07 41ST AVENUE	SSW 1/4 - 1/2 (0.322 mi.)	AY332	943
DOUBLE E PLATING CO Site Code: 499923	***22-07 41ST AVE***	***SSW 1/4 - 1/2 (0.322 mi.)***	***AY333***	***945***
29-05 38TH AVENUE SI Site Code: 613402	29-05 38TH AVENUE	SE 1/4 - 1/2 (0.345 mi.)	343	1066
37-11 30TH STREET Site Code: 567680	37-11 30TH STREET AN	SE 1/4 - 1/2 (0.373 mi.)	BD354	1087
BRIDGE CLEANERS - OF Site Code: 480014	39-26 30TH STREET	SSE 1/4 - 1/2 (0.400 mi.)	BG359	1098
BRIDGE CLEANERS Site Code: 464609	39-26 30TH STREET	SSE 1/4 - 1/2 (0.400 mi.)	BG360	1101
FORMER UNION WIRE DI Site Code: 492945	***39-40 30TH STREET***	***SSE 1/4 - 1/2 (0.409 mi.)***	***BG367***	***1156***
FORMER UNION WIRE DI Site Code: 517267	39-40 30TH STREET	SSE 1/4 - 1/2 (0.409 mi.)	BG368	1176
31/32 LIC LLC Site Code: 520356	37-29 31ST STREET	SE 1/4 - 1/2 (0.424 mi.)	BJ371	1181
31/32 LIC LLC - OFF- Site Code: 534977	37-29 31ST STREET	SE 1/4 - 1/2 (0.424 mi.)	BJ372	1184
22-09 QUEENS PLAZA N Site Code: 607949	22-09 QUEENS PLAZA N	SSW 1/4 - 1/2 (0.438 mi.)	375	1189
QUEENSBORO LANES SIT Site Code: 619390	25-01 QUEENS PLAZA N	S 1/4 - 1/2 (0.466 mi.)	BK380	1199

Lower Elevation	Address	Direction / Distance	Map ID	Page
DOT RELOCATION SITE Site Code: 569681	38-21 12TH STREET	WSW 1/8 - 1/4 (0.149 mi.)	V209	603
NATIONAL RUBBER ADHE Site Code: 57426	38-25/51 9TH STREET	W 1/4 - 1/2 (0.272 mi.)	AS320	905

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 02/06/2023 has revealed that there are 49 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CITY USED AUTO CENTE	***37-25 21ST STREET***	***0 - 1/8 (0.000 mi.)***	***A3***	***20***

Spill Number/Closed Date: 0230068 / 2007-01-29 Site ID: 175236 Spill Date: 2003-03-11				
37-35 21ST STREET Spill Number/Closed Date: 1606143 / 2016-10-14 Site ID: 532744 Spill Date: 2016-09-20	37-35 21ST STREET	SSW 0 - 1/8 (0.004 mi.)	A9	44
BROTHERS AUTO REPAIR Spill Number/Closed Date: 1800085 / 2018-04-11 Site ID: 568566 Spill Date: 2018-04-04	21-15 38 AVE	S 0 - 1/8 (0.020 mi.)	B17	70
VAULT 0763 Spill Number/Closed Date: 0410911 / 2005-06-03 Site ID: 335996 Spill Date: 2005-01-05	42-32 22ND ST	S 0 - 1/8 (0.023 mi.)	B19	72
DELANE RESIDENCE Spill Number/Closed Date: 1108053 / 2011-10-11 Site ID: 455767 Spill Date: 2011-09-23	21-70 38TH ST	SSW 0 - 1/8 (0.034 mi.)	B20	74
FEEDER 31281 Spill Number/Closed Date: 9307497 / 2018-12-07 Site ID: 71925 Spill Date: 1993-09-21	21ST ST & 38TH AVE	SW 0 - 1/8 (0.034 mi.)	B22	76
FEEDER 21ST ST & 38T Spill Number/Closed Date: 2009869 / 2021-05-05 Site ID: 616886 Spill Date: 2021-03-06	21ST ST & 38TH AVE	SW 0 - 1/8 (0.034 mi.)	B23	78
FEEDER # 31281 Spill Number/Closed Date: 9401387 / 2019-09-26 Site ID: 71926 Spill Date: 1994-04-28	21ST ST & 38TH AVE	SW 0 - 1/8 (0.034 mi.)	B24	85
21ST ST & 38TH AVE Spill Number/Closed Date: 8912492 / Not Reported Site ID: 71924 Spill Date: 1989-05-18	21ST ST & 38TH AVE	SW 0 - 1/8 (0.034 mi.)	B25	89
21ST ST/38TH AVE Spill Number/Closed Date: 9403515 / 2019-09-26 Site ID: 125759 Spill Date: 1994-06-13	21ST ST/38TH AVE	SW 0 - 1/8 (0.034 mi.)	B26	94
38TH AVE & 21ST ST Spill Number/Closed Date: 9409876 / 1995-03-07 Site ID: 113307 Spill Date: 1994-10-24	MANHOLE #499- 38TH A	SW 0 - 1/8 (0.034 mi.)	B27	97
POLE #89064 Spill Number/Closed Date: 0806425 / 2008-10-20 Site ID: 403707 Spill Date: 2008-09-08	93-09 22ND ST	ESE 0 - 1/8 (0.039 mi.)	C38	117
MAN HOLE 12775 Spill Number/Closed Date: 1203425 / 2013-03-08 Site ID: 466239 Spill Date: 2012-07-09	EAST 22 ST AND 38 AV	S 0 - 1/8 (0.039 mi.)	B39	118
38-02 22ND STREET	38-02 22ND ST.	S 0 - 1/8 (0.041 mi.)	B44	125

Spill Number/Closed Date: 9312589 / 1994-01-26 Site ID: 146633 Spill Date: 1994-01-26				
38-11 21TH ST. Spill Number/Closed Date: 9312713 / 1994-04-13 Site ID: 77944 Spill Date: 1994-01-28	38011 21TH ST.	SSW 0 - 1/8 (0.066 mi.)	F70	196
BETWEEN 37 & 38TH AV Spill Number/Closed Date: 0401764 / 2004-06-28 Site ID: 209236 Spill Date: 2004-05-18	3722 23RD. ST.	SE 0 - 1/8 (0.068 mi.)	C75	210
BASEMENT Spill Number/Closed Date: 1708548 / 2018-02-13 Site ID: 564958 Spill Date: 2017-12-11	2217 37TH ST	E 0 - 1/8 (0.070 mi.)	C78	213
DRUM RUN Spill Number/Closed Date: 0702865 / 2007-08-09 Site ID: 382677 Spill Date: 2007-06-08	23RD ST BET 37TH AND	SE 0 - 1/8 (0.075 mi.)	C84	235
DIESEL SPILL BUCKET Spill Number/Closed Date: 1504119 / 2015-07-17 Site ID: 510451 Spill Date: 2015-07-17	36-02 21ST STREET	NNE 0 - 1/8 (0.079 mi.)	D87	260
GETTY Spill Number/Closed Date: 9805206 / 2004-12-03 Site ID: 210089 Spill Date: 1998-06-26	36-02 21ST ST	NNE 0 - 1/8 (0.079 mi.)	D88	262
23RD ST & 38TH AVENU Spill Number/Closed Date: 9311067 / 1993-12-13 Site ID: 179043 Spill Date: 1993-12-13	23RD ST & 38TH AVENU	SSE 0 - 1/8 (0.081 mi.)	E92	274
GETTY #568 Spill Number/Closed Date: 0511107 / 2005-12-23 Site ID: 357194 Spill Date: 2005-12-22	21ST/36 AVE	NNE 0 - 1/8 (0.101 mi.)	K112	331
GETTY STATION#568 Spill Number/Closed Date: 0504524 / 2005-07-15 Site ID: 349382 Spill Date: 2005-07-15	21ST STREET/36 AVE	NNE 0 - 1/8 (0.101 mi.)	K113	332
GETTY#568 Spill Number/Closed Date: 0511739 / 2006-01-11 Spill Number/Closed Date: 0703759 / 2007-09-11 Site ID: 357955 Site ID: 383767 Spill Date: 2006-01-11 Spill Date: 2007-07-02	36-02 21 STREET	NNE 0 - 1/8 (0.101 mi.)	K114	333
GETTY 568 Spill Number/Closed Date: 0505775 / 2005-08-16 Site ID: 350866 Spill Date: 2005-08-10	21ST STREET AND 36TH	NNE 0 - 1/8 (0.101 mi.)	K115	335
GETTY # 568	36-21 21ST STREET	NNE 0 - 1/8 (0.101 mi.)	K116	336

Spill Number/Closed Date: 0512432 / 2006-01-27
Site ID: 358750
Spill Date: 2006-01-26

GETTY #568	21ST STREET AND 36TH	NNE 0 - 1/8 (0.101 mi.)	K117	337
Spill Number/Closed Date: 9801243 / 2006-02-07 Site ID: 249309 Spill Date: 1998-04-29				
GETTY #568	21ST/36 AVE	NNE 0 - 1/8 (0.101 mi.)	K118	338
Spill Number/Closed Date: 0505641 / 2005-10-18 Site ID: 350690 Spill Date: 2005-08-08				
3602 21ST STREET	3602 21ST STREET	NNE 0 - 1/8 (0.101 mi.)	K120	342
Spill Number/Closed Date: 0807017 / 2010-11-30 Site ID: 404330 Spill Date: 2008-09-22				
OIL IN WELL	37-10 24TH STREET	ESE 0 - 1/8 (0.107 mi.)	J133	391
Spill Number/Closed Date: 0711317 / 2010-06-23 Site ID: 392775 Spill Date: 2008-01-28				
37-10 24TH STREET	37-10 24TH STREET	ESE 0 - 1/8 (0.107 mi.)	J134	392
Spill Number/Closed Date: 9503873 / 1995-06-29 Site ID: 262434 Spill Date: 1995-06-29				
COMMERCIAL	37-10 24TH ST	ESE 0 - 1/8 (0.110 mi.)	J146	431
Spill Number/Closed Date: 1810563 / Not Reported Site ID: 581465 Spill Date: 2019-01-17				
21-24 39TH AVE/QUEEN	21-24 39TH AVENUE	SSW 0 - 1/8 (0.116 mi.)	L155	474
Spill Number/Closed Date: 8909695 / 1994-11-15 Site ID: 261027 Spill Date: 1990-01-09				
VAULT #9358	36TH AVE/ 21ST STREE	NNE 0 - 1/8 (0.117 mi.)	K156	475
Spill Number/Closed Date: 0404359 / 2004-10-08 Site ID: 114657 Spill Date: 2004-07-22				
QUEENSBRIDGE SUB STA	22-09 39TH AVENUE	S 0 - 1/8 (0.119 mi.)	L161	485
Spill Number/Closed Date: 1006239 / 2010-09-24 Spill Number/Closed Date: 9405052 / 2003-01-22 Spill Number/Closed Date: 0701543 / 2007-05-23 Spill Number/Closed Date: 1702498 / 2018-09-18 Spill Number/Closed Date: 1403712 / 2014-09-26 Site ID: 439587 Site ID: 191147 Site ID: 381078 Site ID: 551638 Site ID: 497079 Spill Date: 2010-09-08 Spill Date: 1994-07-13 Spill Date: 2007-05-07 Spill Date: 2017-06-13 Spill Date: 2014-07-07				
QUEENS BRIDGE SUB ST	2209 39TH AVE	S 0 - 1/8 (0.119 mi.)	L164	498

Spill Number/Closed Date: 0901118 / 2009-06-03
Site ID: 413084
Spill Date: 2009-04-28

QUEENS BRINDGE SUBST — 22-09 39TH AVE — S 0 - 1/8 (0.119 mi.) — L165 — 499
Spill Number/Closed Date: 1500748 / 2017-02-28
Site ID: 506914
Spill Date: 2015-04-22

ONE PINT DIESEL LEAK — 22-09 39 AVENUE (AT — S 0 - 1/8 (0.119 mi.) — L166 — 500
Spill Number/Closed Date: 0707385 / 2007-11-27
Site ID: 388081
Spill Date: 2007-10-04

UNKNOWN — 22-09 39TH AVE QUEEN — S 0 - 1/8 (0.124 mi.) — L181 — 525
Spill Number/Closed Date: 1403711 / 2014-07-08
Site ID: 497078
Spill Date: 2014-07-07

Lower Elevation	Address	Direction / Distance	Map ID	Page
DDC- (FORMER PS 111) Spill Number/Closed Date: 9901712 / Not Reported Site ID: 126573 Spill Date: 1999-05-13	37-44 21ST STREET	NNW 0 - 1/8 (0.012 mi.)	A11	48
DRUM RUN Spill Number/Closed Date: 1200655 / 2012-06-21 Site ID: 463307 Spill Date: 2012-04-20	37TH AVE AND 14TH ST	NNW 0 - 1/8 (0.035 mi.)	A29	99
37TH AVE / 14TH ST. Spill Number/Closed Date: 9308351 / 2015-09-03 Site ID: 303968 Spill Date: 1993-10-09	14TH ST SOUTH OF 37T	NNW 0 - 1/8 (0.035 mi.)	A30	100
MANHOLE 5499 Spill Number/Closed Date: 0004791 / 2001-10-22 Site ID: 176618 Spill Date: 2000-07-21	37TH AVE/14TH ST	NNW 0 - 1/8 (0.035 mi.)	A31	106
MANHOLE 5499 Spill Number/Closed Date: 0004487 / 2001-10-19 Site ID: 176617 Spill Date: 2000-07-14	37TH AVE/14TH ST	NNW 0 - 1/8 (0.035 mi.)	A32	107
36-28 14TH STREET Spill Number/Closed Date: 9305907 / 2006-08-31 Site ID: 158536 Spill Date: 1993-08-12	36-28 14TH STREET	N 0 - 1/8 (0.062 mi.)	G65	187
14TH STREET BETWEEN Spill Number/Closed Date: 9611523 / 2005-06-16 Site ID: 126717 Spill Date: 1996-12-19	36TH + 37TH	N 0 - 1/8 (0.077 mi.)	G86	259
PS# 111 DISTRICT 30 Spill Number/Closed Date: 0402366 / 2004-06-03 Site ID: 244867 Spill Date: 2004-06-03	38-15 13TH STREET	WSW 0 - 1/8 (0.103 mi.)	F125	370
CONTAMINATED SOIL AT	12-02 38TH AVENUE	W 0 - 1/8 (0.114 mi.)	N154	470

Spill Number/Closed Date: 1702829 / Not Reported
Site ID: 552979
Spill Date: 2017-06-21

COMMERCIAL BUSINESS | 38-21 12TH STREET | WSW 0 - 1/8 (0.122 mi.) | N171 | 510
Spill Number/Closed Date: 0413143 / 2005-10-26
Site ID: 338992
Spill Date: 2005-03-17

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/06/2023 has revealed that there are 51 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ERRA METAL INDUSTRIE EPA ID:: NYR000207761	***37-35 21ST ST***	***SSW 0 - 1/8 (0.004 mi.)***	***A8***	***41***
MICOSIA SERVICE CENT EPA ID:: NYR000064501	***37-45 21ST ST***	***SSW 0 - 1/8 (0.016 mi.)***	***B13***	***65***
CON EDISON - EXC 111 EPA ID:: NYP004109476	***22ND ST., 245' N/O 3***	***S 0 - 1/8 (0.039 mi.)***	***B41***	***120***
CON EDISON EPA ID:: NYP004884694	***22-11 38TH AVE***	***SSE 0 - 1/8 (0.052 mi.)***	***E51***	***137***
CON EDISON EPA ID:: NYP004879072	***22-08 37TH AVE***	***ESE 0 - 1/8 (0.053 mi.)***	***C55***	***144***
MERIT OIL CORP EPA ID:: NYD982185977	***3802 21ST ST***	***SW 0 - 1/8 (0.058 mi.)***	***F59***	***149***
VIVIENNE REALTY LLC EPA ID:: NYR000235325	36-22 21ST ST	NNE 0 - 1/8 (0.064 mi.)	D69	193
ABC CONSTRUCTION CON EPA ID:: NYR000093666	***36-11 19TH AVE***	***NE 0 - 1/8 (0.092 mi.)***	***K106***	***312***
SUNOCO SERVICE STATI EPA ID:: NYD000707547	***36-02 21ST ST***	***NNE 0 - 1/8 (0.093 mi.)***	***K107***	***317***
ONE STOP SERVICE EPA ID:: NYD986942076	***23-02 38TH AVE***	***SSE 0 - 1/8 (0.103 mi.)***	***E124***	***367***
MAR-VIC TRANSMISSION EPA ID:: NYD982794265	***23-12 38TH AVENUE***	***SSE 0 - 1/8 (0.105 mi.)***	***M131***	***386***
KOCH & LOW EPA ID:: NYD175220573	***21-24 39TH AVE***	***SSW 0 - 1/8 (0.109 mi.)***	***L142***	***409***
CON EDISON EPA ID:: NYP004881757	***37-24 24TH ST***	***SE 0 - 1/8 (0.110 mi.)***	***J147***	***433***
SCALAMANDRE	***37-24 24TH ST***	***SE 0 - 1/8 (0.110 mi.)***	***J149***	***437***

EPA ID:: NYD986899953				
CON ED - V 0599 EPA ID:: NYP004011565	***22-01 39TH AVE***	***S 0 - 1/8 (0.118 mi.)***	***L157***	***476***
MTA NYCT - BEEBE SIG EPA ID:: NYR000099002	***39TH AVE & 21ST ST***	***SW 0 - 1/8 (0.119 mi.)***	***P159***	***481***
CON EDISON EXCAVATIO EPA ID:: NYP004232625	***21ST ST BETWN 38TH &***	***SW 0 - 1/8 (0.120 mi.)***	***P167***	***502***
SERVICE STATION EPA ID:: NYD000698639	***38-25 21ST ST & 39TH***	***SW 0 - 1/8 (0.120 mi.)***	***P168***	***505***
CON EDISON EPA ID:: NYP004819045	***38-21 23RD ST***	***S 0 - 1/8 (0.122 mi.)***	***R174***	***514***
CON EDISON EPA ID:: NYP004819060	38-21 23RD ST	S 0 - 1/8 (0.122 mi.)	R177	520
CLEO MANAGEMENT EPA ID:: NYR000049015	***36-15 23RD ST***	***E 1/8 - 1/4 (0.130 mi.)***	***T187***	***532***
ADVANCE AUTO ELECTRI EPA ID:: NYD987037744	***38-01 24TH ST***	***SSE 1/8 - 1/4 (0.143 mi.)***	***M200***	***570***
AMAZON.COM SERVICES EPA ID:: NYR000033902	38-50 21ST ST	SW 1/8 - 1/4 (0.145 mi.)	P203	577
CON ED VS 7598 EPA ID:: NYP004015152	***21 ST ST E 38 S 43RD***	***SW 1/8 - 1/4 (0.164 mi.)***	***V226***	***639***
NYCHA - RAVENSWOOD H EPA ID:: NYR000221325	***35-32 21ST ST***	***NNE 1/8 - 1/4 (0.171 mi.)***	***AA233***	***650***
CON EDISON EPA ID:: NYP004832875	39-26 21ST ST	SW 1/8 - 1/4 (0.174 mi.)	AC240	668
CON EDISON EPA ID:: NYP004211876	***36-15 24TH ST***	***E 1/8 - 1/4 (0.176 mi.)***	***AD243***	***674***
LUIS WINSTON INC EPA ID:: NYR000066290	***38-66 13TH ST***	***WSW 1/8 - 1/4 (0.180 mi.)***	***V246***	***680***
CON EDISON EPA ID:: NYP004821241	39-40 21ST ST	SW 1/8 - 1/4 (0.199 mi.)	AC269	769
ACCARDI ELECTRIC CO EPA ID:: NYD012316667	***25-10 38TH AVE***	***SE 1/8 - 1/4 (0.200 mi.)***	***Y271***	***772***
WOODHAVEN FINISHING EPA ID:: NYN008023673	38-79 13TH ST	SW 1/8 - 1/4 (0.202 mi.)	AC274	782
ORKIN PEST CONTROL C EPA ID:: NYD987028198	38-31 CRESCENT ST	SSE 1/8 - 1/4 (0.209 mi.)	AF276	788
CON EDISON EPA ID:: NYP004720348	***35-49 24TH ST***	***ENE 1/8 - 1/4 (0.216 mi.)***	***AL284***	***804***
CON EDISON EPA ID:: NYP004879635	38-11 27TH ST	SSE 1/8 - 1/4 (0.242 mi.)	AN305	862
SCHMIT MACHINE INC EPA ID:: NYD987011368	***40-09 21ST ST - GROU***	***SW 1/8 - 1/4 (0.244 mi.)***	***AK311***	***878***

Lower Elevation	Address	Direction / Distance	Map ID	Page
PROMO-PRO LTD	13-07 37TH AVE TRANS	NNW 0 - 1/8 (0.067 mi.)	G71	197

EPA ID:: NYR000093849				
ELIT GREEN BUILDERS EPA ID:: NYR000093831	***13-07 37TH AVE ROOM***	***NNW 0 - 1/8 (0.067 mi.)***	***G72***	***201***
ENVIRO CONTRACTING C EPA ID:: NYR000170605	13-07 37TH AVE ROOM	NNW 0 - 1/8 (0.067 mi.)	G73	205
CHRISTIAN ECKHOFF TR EPA ID:: NYR000006783	***36-22 14TH ST***	***N 0 - 1/8 (0.085 mi.)***	***G95***	***277***
CON EDISON SERVICE B EPA ID:: NYP004555041	***37-18 12TH ST***	***WNW 1/8 - 1/4 (0.130 mi.)***	***U189***	***537***
WELL DUN FRENCH DRY EPA ID:: NYD981086713	***12-14 36TH AVE***	***N 1/8 - 1/4 (0.150 mi.)***	***W211***	***610***
CON ED - 38TH AVE & EPA ID:: NYP004010591	***38TH AVE & 11TH ST***	***W 1/8 - 1/4 (0.166 mi.)***	***X230***	***645***
CON EDISON EPA ID:: NYP004833444	36TH AVE & 12TH ST	NNW 1/8 - 1/4 (0.174 mi.)	W238	665
CON EDISON SERVICE B EPA ID:: NYP004527784	***462 11TH AVE & 37TH***	***NW 1/8 - 1/4 (0.174 mi.)***	***AB242***	***672***
CON EDISON EPA ID:: NYP004805909	***37-10 11TH ST***	***WNW 1/8 - 1/4 (0.182 mi.)***	***AB248***	***684***
CON EDISON SERVICE B EPA ID:: NYP004443644	***35-58 12TH ST***	***NNW 1/8 - 1/4 (0.191 mi.)***	***W264***	***760***
CON EDISON GAS MAIN: EPA ID:: NYP004363057	***37-47 10TH ST***	***WNW 1/8 - 1/4 (0.201 mi.)***	***AG273***	***779***
BETHEL WELDING EPA ID:: NYR000097568	***38-59 12TH ST***	***WSW 1/8 - 1/4 (0.205 mi.)***	***AH275***	***785***
WORLD WIDE RECOVERY EPA ID:: NYD088493481	***38-65 12TH ST***	***WSW 1/8 - 1/4 (0.217 mi.)***	***AH287***	***812***
CON EDISON SERVICE B EPA ID:: NYP004448783	***36-31 10TH ST***	***NW 1/8 - 1/4 (0.218 mi.)***	***AM288***	***816***
WEGNER MACHINERY COR EPA ID:: NYD986950210	***35-41 11TH ST***	***NNW 1/8 - 1/4 (0.241 mi.)***	***304***	***855***

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 05/08/2023 has revealed that there are 2 FUDS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ARMY PICTURIAL CEN		E 1/2 - 1 (0.705 mi.)	394	1328

Lower Elevation	Address	Direction / Distance	Map ID	Page
NAVAL SHIPYARD QUEEN		WNW 1/4 - 1/2 (0.301 mi.)	AV325	923

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 04/26/2023 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NEWTOWN CREEK	***SOUTH END OF IVY HIL***	***S 1/2 - 1 (0.997 mi.)***	***0***	***10***

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 03/30/2023 has revealed that there are 2 PFAS ECHO sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BLACK OX METAL FINIS		SE 1/8 - 1/4 (0.224 mi.)	AN294	835
ORLANDO FINISHING CO	***40-09 21 STREET***	***SW 1/8 - 1/4 (0.244 mi.)***	***AK310***	***875***

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 03/06/2023 has revealed that there are 5 NY DRYCLEANERS sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JUNG SUN LAUNDRY COR Facility Id: 2-6304-00393	37-10 24TH ST	ESE 0 - 1/8 (0.110 mi.)	J144	418
LUCKY CLEANERS Facility Id: 2-6304-00550	21-20 36TH AVE	NE 0 - 1/8 (0.113 mi.)	K153	464
BEST CLEANERS Facility Id: 2-6304-01304	38-68 13TH ST	WSW 1/8 - 1/4 (0.188 mi.)	V263	745

Lower Elevation	Address	Direction / Distance	Map ID	Page
KTR LAUNDRY & DRY CL Facility Id: 2-6304-01501	38-38 13TH ST	WSW 1/8 - 1/4 (0.148 mi.)	V205	584
WELL DUN CLEANERS Facility Id: 2-6304-01108	12-14 36TH AVENUE	N 1/8 - 1/4 (0.150 mi.)	W212	614

NY E DESIGNATION: Lots designation with an ?E? on the Zoning Maps of the City of New York for potential hazardous material contamination, air and/or noise quality impacts.

A review of the NY E DESIGNATION list, as provided by EDR, and dated 10/27/2022 has revealed that there are 2 NY E DESIGNATION sites within approximately 0.125 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
LOT 1,TAXBLOCK 351	12-01 37 AVENUE	NW 0 - 1/8 (0.122 mi.)	Q170	510
LOT 6,TAXBLOCK 351	36-31 12 STREET	NNW 0 - 1/8 (0.124 mi.)	Q180	525

EXECUTIVE SUMMARY

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 88 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID: NYP004627857	37-25 21 ST	0 - 1/8 (0.000 mi.)	A2	18
CONSOLIDATED EDISON EPA ID: NYP004094165	37 AVE & 21ST ST	NNE 0 - 1/8 (0.019 mi.)	A15	68
NYC DEP HAZ MAT EPA ID: NYP003662350	21ST ST & 37TH AVE	NNE 0 - 1/8 (0.019 mi.)	A16	69
NYNEX EPA ID: NYP000917450	21ST ST & 38TH AVE	SW 0 - 1/8 (0.034 mi.)	B21	75
CONSOLIDATED EDISON EPA ID: NYP004109443	22 ST & 37 AVE OP EX	E 0 - 1/8 (0.038 mi.)	C37	116
CONSOLIDATED EDISON EPA ID: NYP004109468	22 ST & 38 AVE OP EX	S 0 - 1/8 (0.039 mi.)	B40	119
CON EDISON - EXC 111 EPA ID: NYP004109476	***22ND ST., 245' N/O 3***	***S 0 - 1/8 (0.039 mi.)***	***B41***	***120***
CON EDISON EPA ID: NYP004716809	36-37 21 ST	NNE 0 - 1/8 (0.039 mi.)	D42	123
CONSOLIDATED EDISON EPA ID: NYP004016796	V3671-300 E 22ND ST	ENE 0 - 1/8 (0.051 mi.)	C47	129
CON EDISON - SERVICE EPA ID: NYP005102660	36-40 22ND ST	ENE 0 - 1/8 (0.063 mi.)	D67	191
VIVIENNE SOIL REMOVA EPA ID: NYR000235325	36-22 21ST ST	NNE 0 - 1/8 (0.064 mi.)	D68	192
PERDIDO PRODS CONSTR EPA ID: NYR000090720	***37-22 23RD ST GRD WH***	***ESE 0 - 1/8 (0.070 mi.)***	***C81***	***223***
M & B AUTO BODY INC EPA ID: NYR000037325	***22-19 37TH AVE***	***E 0 - 1/8 (0.076 mi.)***	***C85***	***236***
CONSOLIDATED EDISON EPA ID: NYP004110599	37 AVE & 23 AT MH174	ESE 0 - 1/8 (0.080 mi.)	C90	271
CONSOLIDATED EDISON EPA ID: NYP004096848	23RD ST & 38TH AVE M	SSE 0 - 1/8 (0.081 mi.)	E94	277
JUNG SUN LAUNDRY SIT EPA ID: NYR000219006	37-11 23RD ST	SE 0 - 1/8 (0.087 mi.)	J100	288
ABC CONSTRUCTION CON EPA ID: NYR000093666	***36-11 19TH AVE***	***NE 0 - 1/8 (0.092 mi.)***	***K106***	***312***
CON EDISON EPA ID: NYP004663431	23-02 38 AV	SSE 0 - 1/8 (0.103 mi.)	E123	365
CON EDISON EPA ID: NYP004663340	OPP 21-16 39 AV	SSW 0 - 1/8 (0.109 mi.)	L139	405
CON EDISON EPA ID: NYP004663407	OPP 38-15 23 ST	S 0 - 1/8 (0.109 mi.)	M140	406
KOCH & LOW	***21-24 39TH AVE***	***SSW 0 - 1/8 (0.109 mi.)***	***L142***	***409***

EPA ID: NYD175220573				
JUNG SUN LAUNDRY PLU EPA ID: NYD981081847	***37-10 24TH ST***	***ESE 0 - 1/8 (0.110 mi.)***	***J145***	***419***
SCALAMANDRE EPA ID: NYD986899953	***37-24 24TH ST***	***SE 0 - 1/8 (0.110 mi.)***	***J149***	***437***
LUCKY CLEANERS EPA ID: NYD986886828	***21-20 36TH AVE***	***NE 0 - 1/8 (0.113 mi.)***	***K152***	***445***
CON ED - V 0599 EPA ID: NYP004011565	***22-01 39TH AVE***	***S 0 - 1/8 (0.118 mi.)***	***L157***	***476***
CON EDISON EPA ID: NYP004625075	2112 39TH AVE	SSW 0 - 1/8 (0.118 mi.)	L158	479
MTA NYCT - BEEBE SIG EPA ID: NYR000099002	***39TH AVE & 21ST ST***	***SW 0 - 1/8 (0.119 mi.)***	***P159***	***481***
CON EDISON - QUEENSB EPA ID: NYR000020834	***2209 39TH ST***	***S 0 - 1/8 (0.119 mi.)***	***L162***	***490***
CON EDISON EXCAVATIO EPA ID: NYP004232625	***21ST ST BETWN 38TH &***	***SW 0 - 1/8 (0.120 mi.)***	***P167***	***502***
CON EDISON EPA ID: NYP004819060	38-21 23RD ST	S 0 - 1/8 (0.122 mi.)	R173	513
CON EDISON EPA ID: NYP004819045	38-21 23RD ST	S 0 - 1/8 (0.122 mi.)	R178	522
CON EDISON EPA ID: NYP004663339	OPP 38-21 23 ST	S 0 - 1/8 (0.122 mi.)	R179	523
CON EDISON EPA ID: NYP004663381	OPP 38-31 23 ST	S 0 - 1/8 (0.124 mi.)	R182	526
CONSOLIDATED EDISON EPA ID: NYP004155644	36TH AVE & 14TH ST	NNE 0 - 1/8 (0.124 mi.)	O183	528
CLEO MANAGEMENT EPA ID: NYR000049015	36-15 23RD ST	E 1/8 - 1/4 (0.130 mi.)	T185	530
CON EDISON EPA ID: NYP004630331	36-15A 23 ST	E 1/8 - 1/4 (0.130 mi.)	T186	531
CONSOLIDATED EDISON EPA ID: NYP004016408	V2253-43-23 36TH AVE	ENE 1/8 - 1/4 (0.143 mi.)	199	569
ADVANCE AUTO ELECTRI EPA ID: NYD987037744	***38-01 24TH ST***	***SSE 1/8 - 1/4 (0.143 mi.)***	***M200***	***570***
CON EDISON EPA ID: NYP004663365	OPP 23-02 39 AV	S 1/8 - 1/4 (0.144 mi.)	R201	575
NYC DEPT OF ENVIRONM EPA ID: NYP003661394	36 AVE & 23RD ST	ENE 1/8 - 1/4 (0.154 mi.)	T216	621
CON EDISON - MANHOLE EPA ID: NYP004935159	37-46 CRESCENT ST	SE 1/8 - 1/4 (0.159 mi.)	Y220	630
CON EDISON - SERVICE EPA ID: NYP004885980	35-51 21ST ST	NNE 1/8 - 1/4 (0.161 mi.)	AA222	633
PEP BOYS #437 EPA ID: NYR000033902	38-50 21ST ST	SW 1/8 - 1/4 (0.164 mi.)	V225	638
CON ED VS 7598	***21 ST ST E 38 S 43RD***	***SW 1/8 - 1/4 (0.164 mi.)***	***V226***	***639***

EPA ID: NYP004015152				
NYCHA - RAVENSWOOD H EPA ID: NYR000221325	35-32 21ST ST	NNE 1/8 - 1/4 (0.171 mi.)	AA234	654
CON ED EPA ID: NYP004832875	39-26 21ST ST	SW 1/8 - 1/4 (0.174 mi.)	AC239	667
CON EDISON EPA ID: NYP004211876	***36-15 24TH ST***	***E 1/8 - 1/4 (0.176 mi.)***	***AD243***	***674***
NYC DEPT OF EDUCATIO EPA ID: NYR000104331	***25-05 37TH AVE***	***ESE 1/8 - 1/4 (0.183 mi.)***	***AE251***	***692***
CON EDISON - SERVICE EPA ID: NYP005132196	36-24 CRESCENT ST	E 1/8 - 1/4 (0.188 mi.)	AD257	708
D D K PRO CLEANERS EPA ID: NYR000164277	***38-68 13TH ST***	***WSW 1/8 - 1/4 (0.188 mi.)***	***V260***	***712***
LA MODE QUEENS INC EPA ID: NYR000001917	***38-68 13TH ST***	***WSW 1/8 - 1/4 (0.188 mi.)***	***V262***	***739***
CON EDISON EPA ID: NYP004821241	39-40 21ST ST	SW 1/8 - 1/4 (0.199 mi.)	AC267	766
CON ED EPA ID: NYP004832883	39-40 21 ST	SW 1/8 - 1/4 (0.199 mi.)	AC268	768
ACCARDI ELECTRIC CO EPA ID: NYD012316667	***25-10 38TH AVE***	***SE 1/8 - 1/4 (0.200 mi.)***	***Y271***	***772***
CON EDISON EPA ID: NYP004623864	83-19 39 AVE	SSE 1/8 - 1/4 (0.200 mi.)	AF272	777
ORKIN EPA ID: NYP000886580	38-31 CRESENT STREET	SSE 1/8 - 1/4 (0.209 mi.)	AF277	794
CON EDISON EPA ID: NYP004625059	21-07 40 AVE FRNT	SSW 1/8 - 1/4 (0.212 mi.)	AK281	799
CON EDISON EPA ID: NYP004720348	35-49 24TH ST	ENE 1/8 - 1/4 (0.216 mi.)	AL283	803
CON EDISON EPA ID: NYP004630820	***13-01 40TH AV***	***SW 1/8 - 1/4 (0.216 mi.)***	***AC285***	***807***
CON EDISON EPA ID: NYP004670790	35-05 21ST ST	NE 1/8 - 1/4 (0.225 mi.)	295	836
CON EDISON EPA ID: NYP004733416	35TH AVE & 35TH ST 5	NNE 1/8 - 1/4 (0.225 mi.)	296	838
CONSOLIDATED EDISON EPA ID: NYP004069050	CRESCENT ST & 36TH A	E 1/8 - 1/4 (0.229 mi.)	299	843
CON EDISON EPA ID: NYP004683926	27-03 38TH AVE	SE 1/8 - 1/4 (0.234 mi.)	AN301	846
CONSOLIDATED EDISON EPA ID: NYD980593636	31-01 20TH. AVE.	SSE 1/8 - 1/4 (0.237 mi.)	AP302	848
GIACOMELLI & MAZZA I EPA ID: NYR000057778	***40-05 21ST ST***	***SW 1/8 - 1/4 (0.240 mi.)***	***AK303***	***849***
ATLANTIC PRECIOUS ME EPA ID: NYR000022699	***22-12 40TH AVE***	***SSW 1/8 - 1/4 (0.242 mi.)***	***AQ307***	***865***
WALKER E WHYTE INC	***22-14 40TH AVE***	***SSW 1/8 - 1/4 (0.245 mi.)***	***AQ313***	***887***

EPA ID: NY0000915165

Lower Elevation	Address	Direction / Distance	Map ID	Page
CONSOLIDATED EDISON EPA ID: NYP004093209	14 ST & 37 AVE MH223	NNW 0 - 1/8 (0.035 mi.)	A28	98
NEW YORK CITY D.E.P EPA ID: NYP010001246	37TH/14TH STREET	NNW 0 - 1/8 (0.035 mi.)	A33	108
NYC BD OF ED - PUBLI EPA ID: NYR000010801	***37-15 13TH ST***	***WNW 0 - 1/8 (0.070 mi.)***	***H79***	***215***
CON EDISON EPA ID: NYP004701603	37-14 13TH ST	WNW 0 - 1/8 (0.081 mi.)	H93	275
CON EDISON EPA ID: NYP004632246	12-20 37 AV	NW 0 - 1/8 (0.085 mi.)	H97	283
CON EDISON EPA ID: NYP004555041	37-18 12TH ST	WNW 1/8 - 1/4 (0.130 mi.)	U188	536
MIDNIGHT EXPRESS EPA ID: NYD986953693	38-38 13TH ST	WSW 1/8 - 1/4 (0.148 mi.)	V207	597
38-21 12TH STREET EPA ID: NYD003401205	***38-21 12TH STREET***	***WSW 1/8 - 1/4 (0.149 mi.)***	***V208***	***598***
WELL DUN FRENCH DRY EPA ID: NYD981086713	***12-14 36TH AVE***	***N 1/8 - 1/4 (0.150 mi.)***	***W211***	***610***
NYCDEP EPA ID: NYP003661063	37-31 11TH ST	WNW 1/8 - 1/4 (0.150 mi.)	U213	615
CON ED EPA ID: NYP004107447	11 ST & 38 AVE EXCAV	W 1/8 - 1/4 (0.166 mi.)	X228	644
CONSOLIDATED EDISON EPA ID: NYP004124947	38TH AVE & 11TH ST	W 1/8 - 1/4 (0.166 mi.)	X229	645
CON ED - 38TH AVE & EPA ID: NYP004010591	***38TH AVE & 11TH ST***	***W 1/8 - 1/4 (0.166 mi.)***	***X230***	***645***
CONSOLIDATED EDISON EPA ID: NYP004024394	11TH ST & 37TH AVE	NW 1/8 - 1/4 (0.173 mi.)	AB235	655
CON EDISON EPA ID: NYP004805909	37-10 11TH ST	WNW 1/8 - 1/4 (0.182 mi.)	AB249	687
CON EDISON SERVICE B EPA ID: NYP004443644	***35-58 12TH ST***	***NNW 1/8 - 1/4 (0.191 mi.)***	***W264***	***760***
CON EDISON GAS MAIN: EPA ID: NYP004363057	***37-47 10TH ST***	***WNW 1/8 - 1/4 (0.201 mi.)***	***AG273***	***779***
CON EDISON - TRANSFO EPA ID: NYP004909426	11TH ST & 36TH AVE	NNW 1/8 - 1/4 (0.211 mi.)	AJ280	798
CON EDISON SERVICE B EPA ID: NYP004448783	***36-31 10TH ST***	***NW 1/8 - 1/4 (0.218 mi.)***	***AM288***	***816***
WEGNER MACHINERY COR EPA ID: NYD986950210	***35-41 11TH ST***	***NNW 1/8 - 1/4 (0.241 mi.)***	***304***	***855***
CENTRAL COLLISION IN EPA ID: NYD045428125	***10-12 36TH AVE***	***NNW 1/8 - 1/4 (0.244 mi.)***	***AJ312***	***882***

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 12/31/2020 has revealed that there are 2 RI MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LUCKY CLEANERS	***21-20 36TH AVE***	***NE 0 - 1/8 (0.113 mi.)***	***K152***	***445***
EPA Id: NYD986886828				
Manifest Document Number: 002718111SKS				
D D K PRO CLEANERS	***38-68 13TH ST***	***WSW 1/8 - 1/4 (0.188 mi.)***	***V260***	***712***
EPA Id: NYR000164277				
Manifest Document Number: 002747056SKS				

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 14 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	22-11 38TH AVE	SSE 0 - 1/8 (0.052 mi.)	E52	139
EPA Id: NYP004884694				
CON EDISON	22-08 37TH AVE	ESE 0 - 1/8 (0.053 mi.)	C53	140
EPA Id: NYP004879072				
M & B AUTO BODY INC	***22-19 37TH AVE***	***E 0 - 1/8 (0.076 mi.)***	***C85***	***236***
EPA Id: NYR000037325				
JUNG SUN LAUNDRY SIT	37-11 23RD ST	SE 0 - 1/8 (0.087 mi.)	J101	290
EPA Id: NYR000219006				
JUNG SUN LAUNDRY PLU	***37-10 24TH ST***	***ESE 0 - 1/8 (0.110 mi.)***	***J145***	***419***
EPA Id: NYD981081847				
CON EDISON	37-24 24TH ST	SE 0 - 1/8 (0.110 mi.)	J150	443
EPA Id: NYP004881757				
CON EDISON	38-21 23RD ST	S 0 - 1/8 (0.122 mi.)	R172	511
EPA Id: NYP004819045				
CON EDISON	38-21 23RD ST	S 0 - 1/8 (0.122 mi.)	R175	517
EPA Id: NYP004819060				
NYCHA - RAVENSWOOD H	35-32 21ST ST	NNE 1/8 - 1/4 (0.171 mi.)	AA232	649
EPA Id: NYR000221325				
CON EDISON	39-26 21ST ST	SW 1/8 - 1/4 (0.174 mi.)	AC241	670
EPA Id: NYP004832875				
CON EDISON	39-40 21ST ST	SW 1/8 - 1/4 (0.199 mi.)	AC270	771
EPA Id: NYP004821241				
CON EDISON	38-11 27TH ST	SSE 1/8 - 1/4 (0.242 mi.)	AN306	864
EPA Id: NYP004879635				

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON	36TH AVE & 12TH ST	NNW 1/8 - 1/4 (0.174 mi.)	W237	664
EPA Id: NYP004833444				
CON EDISON	37-10 11TH ST	WNW 1/8 - 1/4 (0.182 mi.)	AB247	683

EXECUTIVE SUMMARY

EPA Id: NYP004805909

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 12 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NICOSIA SERVICE STAT	3745 21ST ST	SSW 0 - 1/8 (0.016 mi.)	B12	64
TONYS TOWING SERVICE	2115 38TH AVE	S 0 - 1/8 (0.020 mi.)	B18	72
PAKAM AUTO REPAIR &	3802 22ND ST	S 0 - 1/8 (0.042 mi.)	B45	126
BELLO LNG ISLND CY A	22-08 37TH AVE	ESE 0 - 1/8 (0.053 mi.)	C56	146
SAVEWAY ASTORIA INC	3802 21ST ST	SW 0 - 1/8 (0.058 mi.)	F58	149
ULTIMATE AUTO CARE O	3637 21ST ST	NNE 0 - 1/8 (0.062 mi.)	D63	183
SAV-ON PETROLEUM INC	36-11 21ST ST	NE 0 - 1/8 (0.087 mi.)	D98	285
SAN ANTON SERVICE ST	23-02 37 AVE	ESE 0 - 1/8 (0.091 mi.)	J105	311
T J MOTORS INC	36-02 21ST ST	NNE 0 - 1/8 (0.101 mi.)	K122	364
CIOFFI & FERRARA	38-25 21ST ST	SW 0 - 1/8 (0.103 mi.)	L128	381
MARVIC TRANSMISSION	2312 38TH AVE	SSE 0 - 1/8 (0.105 mi.)	M130	385

Lower Elevation	Address	Direction / Distance	Map ID	Page
H & M SERVICE STATIO	3642 21ST ST	N 0 - 1/8 (0.041 mi.)	D43	125

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 2 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
LUCKY CLEANERS	2120 36TH AVE	NE 0 - 1/8 (0.113 mi.)	K151	444

Lower Elevation	Address	Direction / Distance	Map ID	Page
LE CLAIRE VALET SERV	19-44 37TH ST	N 0 - 1/8 (0.018 mi.)	A14	68

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 16 records.

Site Name	Database(s)
FLEMM LEAD CO.	SEMS-ARCHIVE, LEAD SMELTERS
QUEENS MEDALLION LEASING	NY SHWS
21-03 44TH AVENUE	NY SHWS
44TH ROAD EAST OF 21ST STREET PLUM	NY SHWS
27-09 40TH AVENUE	NY SHWS, NY BROWNFIELDS
PURVES STREET GROUNDWATER	NY SHWS
1ST AVE. AND E. 76TH STREET GW	NY SHWS
CE - YORK AVE STATION	NY SHWS
QUEENS WEST - SOUTH	NY SHWS
OUTLET CITY	NY SHWS
2701 CLEANERS	NY DRYCLEANERS
UNITED CLEANERS	NY DRYCLEANERS
WORLD CLASS GARMENT CARE	NY DRYCLEANERS
CON ED ASTORIA	NY LTANKS
CLOSED-LACKOF RECENT INFO	NY LTANKS
APARTMENT BUILDING	NY LTANKS

OVERVIEW MAP - 7390563.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 23-0454	CLIENT: Middleton Environmental Inc.
ADDRESS: 3705 21st Street Long Island City NY 11101	CONTACT: Sarah Heyne
LAT/LONG: 40.758182 / 73.938068	INQUIRY #: 7390563.2s DATE: July 17, 2023 8:32 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 7390563.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: 23-0454	CLIENT: Middleton Environmental Inc.
ADDRESS: 3705 21st Street Long Island City NY 11101	CONTACT: Sarah Heyne INQUIRY #: 7390563.2s
LAT/LONG: 40.758182 / 73.938068	DATE: July 17, 2023 8:33 am

Copyright © 2023 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Lists of Federal NPL (Superfund) sites								
NPL	1.000		0	0	0	1	NR	1
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Lists of Federal Delisted NPL sites								
Delisted NPL	1.000		0	0	0	0	NR	0
Lists of Federal sites subject to CERCLA removals and CERCLA orders								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Lists of Federal CERCLA sites with NFRAP								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA facilities undergoing Corrective Action								
CORRACTS	1.000		0	0	1	0	NR	1
Lists of Federal RCRA TSD facilities								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Lists of Federal RCRA generators								
RCRA-LQG	0.250		3	2	NR	NR	NR	5
RCRA-SQG	0.250		3	6	NR	NR	NR	9
RCRA-VSQG	0.250		3	4	NR	NR	NR	7
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
Lists of state- and tribal hazardous waste facilities								
NY SHWS	1.000		1	1	4	8	NR	14
Lists of state and tribal landfills and solid waste disposal facilities								
NY SWF/LF	0.500		3	0	1	NR	NR	4
Lists of state and tribal leaking storage tanks								
INDIAN LUST	0.500		0	0	0	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LTANKS	0.500		4	10	49	NR	NR	63
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
Lists of state and tribal registered storage tanks								
FEMA UST	0.250		0	0	NR	NR	NR	0
NY UST	0.250		16	17	NR	NR	NR	33
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	2	NR	NR	2
NY MOSF	0.500		0	0	1	NR	NR	1
NY CBS	0.250		1	2	NR	NR	NR	3
NY AST	0.250	1	28	21	NR	NR	NR	50
NY CBS AST	0.250		1	0	NR	NR	NR	1
NY MOSF AST	0.500		0	0	2	NR	NR	2
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	3	NR	NR	3
NY INST CONTROL	0.500		0	0	3	NR	NR	3
Lists of state and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	5	NR	NR	5
INDIAN VCP	0.500		0	0	0	NR	NR	0
Lists of state and tribal brownfield sites								
NY BROWNFIELDS	0.500		0	2	13	NR	NR	15
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125		49	NR	NR	NR	NR	49
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		24	27	NR	NR	NR	51
FUDS	1.000		0	0	1	1	NR	2
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	1	NR	1
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	2	NR	NR	NR	2
PFAS ECHO FIRE TRAINING	0.250		0	0	NR	NR	NR	0
PFAS PART 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
NY PFAS	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		2	3	NR	NR	NR	5
NY E DESIGNATION	0.125		2	NR	NR	NR	NR	2
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
NY MANIFEST	0.250		39	49	NR	NR	NR	88
PA MANIFEST	0.250		0	0	NR	NR	NR	0
RI MANIFEST	0.250		1	1	NR	NR	NR	2
NJ MANIFEST	0.250		8	6	NR	NR	NR	14
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		12	NR	NR	NR	NR	12
EDR Hist Cleaner	0.125		2	NR	NR	NR	NR	2
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		1	202	153	85	11	0	452

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **LONDON AUTO ELECTRIC** **NY AST** **A100294862**
Target **37-05 21ST STREET** **N/A**
Property **LONG ISLAND CITY, NY 11101**

Site 1 of 20 in cluster A

Actual:
17 ft.

AST:

Name:	LONDON AUTO ELECTRIC
Address:	37-05 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609204
Program Type:	PBS
UTM X:	589645.25333
UTM Y:	4512498.84782
Expiration Date:	08/18/2008
Site Type:	Unknown

Affiliation Records:

Site Id:	31049
Affiliation Type:	Facility Owner
Company Name:	MOHMMAD ASLAM
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	25-02 STEINWAY STREET
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11103
Country Code:	001
Phone:	(718) 721-6890
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31049
Affiliation Type:	Mail Contact
Company Name:	LONDON AUTO ELECTRIC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	37-05 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-8580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31049
Affiliation Type:	Facility Operator
Company Name:	LONDON AUTO ELECTRIC
Contact Type:	Not reported
Contact Name:	MOHMMAD ASLAM

LONDON AUTO ELECTRIC (Continued) **A100294862**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-8580
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31049
Affiliation Type:	Emergency Contact
Company Name:	MOHMMAD ASLAM
Contact Type:	Not reported
Contact Name:	MOHMMAD ASLAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(646) 729-9582
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank Id:	66770
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	G00 - Tank Secondary Containment - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	D00 - Pipe Type - No Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	J00 - Dispenser - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	200
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

LONDON AUTO ELECTRIC (Continued) **A100294862**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

NPL Region South 1/2-1 5262 ft.

NEWTON CREEK
SOUTH END OF IVY HILL ROAD
BROOKLYN, QUEENS, NY 11222

NPL 1011845384
SEMS NYN000206282
RCRA-SQG
ROD
PRP
NY MANIFEST

NPL:

EPA Region:	2
EPA ID:	NYN000206282
Site ID:	206282
Name:	NEWTOWN CREEK
Address:	SOUTH END OF IVY HILL ROAD
City,State,Zip:	BROOKLYN, QUEENS, NY 11222
Federal:	N
Final Date:	2010-09-29 00:00:00
Latitude:	40.715192
Longitude:	-73.930762
Site Score:	50
NAI:	Not reported
Native American Entity:	Not reported

Narr:

Site Name:	Newtown Creek
Site EPA ID:	NYN000206282
Listing Date:	9/29/2010
Site Score:	50
Federal Facility Indicator:	No
Site List URL:	https://semspub.epa.gov/src/document/02/363175
Site Progress URL:	https://cumulis.epa.gov/supercpad/cursites/csitinfo.cfm?id=0206282
Federal Register URL:	http://www.gpo.gov/fdsys/pkg/FR-2010-09-29/pdf/2010-24313.pdf
Site Location URL:	https://epa.maps.arcgis.com/apps/webappviewer/index.html?id=33cebcdfdd1b4c3a8b51d416956c41f1&query=Superfund_National_Priorities_List__NPL__Sites_with_Status_Information_7557,SITE_EPA_ID=%27NYN000206282%27

SEMS:

Site ID:	0206282
EPA ID:	NYN000206282
Name:	NEWTOWN CREEK
Address:	SOUTH END OF IVY HILL ROAD
Address 2:	Not reported
City,State,Zip:	BROOKLYN, QUEENS, NY 11222
Cong District:	12
FIPS Code:	Not reported
Latitude:	+40.715192
Longitude:	-073.930762
FF:	N
NPL:	Currently on the Final NPL
Non NPL Status:	Not reported

NEWTOWN CREEK (Continued) **1011845384**

SEMS Detail:

Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	00
Action Code:	NP
Action Name:	PROPOSED
SEQ:	1
Start Date:	2009-09-23 04:00:00
Finish Date:	2009-09-23 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	00
Action Code:	HR
Action Name:	HAZRANK
SEQ:	1
Start Date:	2009-06-01 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	00
Action Code:	NF
Action Name:	NPL FINL
SEQ:	1
Start Date:	2010-09-29 04:00:00
Finish Date:	2010-09-29 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf

Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	00
Action Code:	DS
Action Name:	DISCVRY
SEQ:	1
Start Date:	2008-08-15 05:00:00

NEWTOWN CREEK (Continued) **1011845384**

Finish Date:	2008-08-15 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	CO
Action Name:	RI/FS
SEQ:	1
Start Date:	2010-02-05 05:00:00
Finish Date:	2011-07-07 05:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	1
Start Date:	2014-09-11 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	TA
Action Name:	TECH ASSIST
SEQ:	2
Start Date:	2014-10-31 04:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	02
Action Code:	RO

NEWTOWN CREEK (Continued) **1011845384**

Action Name:	ROD
SEQ:	3
Start Date:	2021-04-12 04:00:00
Finish Date:	2021-04-12 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Perf
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	01
Action Code:	BD
Action Name:	PRP RI/FS
SEQ:	1
Start Date:	2011-07-07 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	04
Action Code:	NK
Action Name:	PRP FS
SEQ:	3
Start Date:	2022-12-06 06:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F
FF:	N
OU:	02
Action Code:	NK
Action Name:	PRP FS
SEQ:	1
Start Date:	2018-12-20 06:00:00
Finish Date:	2021-04-12 04:00:00
Qual:	Not reported
Current Action Lead:	EPA Ovrsght
Region:	02
Site ID:	0206282
EPA ID:	NYN000206282
Site Name:	NEWTOWN CREEK
NPL:	F

NEWTOWN CREEK (Continued) **1011845384**

FF:	N
OU:	02
Action Code:	GM
Action Name:	GWTRMON
SEQ:	1
Start Date:	2022-09-29 05:00:00
Finish Date:	Not reported
Qual:	Not reported
Current Action Lead:	EPA Ovrsght

RCRA Listings:

Date Form Received by Agency:	20120321
Handler Name:	Newtown Creek Superfund Site
Handler Address:	NEWTOWN CRK
Handler City,State,Zip:	NEW YORK, NY 99999
EPA ID:	NYN000206282
Contact Name:	JIM QUADRINI
Contact Address:	W GRAND AVE STE 300
Contact City,State,Zip:	MONTVALE, NJ 07645-1813
Contact Telephone:	201-930-9890 x1012
Contact Fax:	201-930-9805
Contact Email:	JQUADRINI@ANCHORQEA.COM
Contact Title:	PARTNER ANCHOR QEA
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	W GRAND AVE STE 300
Mailing City,State,Zip:	MONTVALE, NJ 07645-1813
Owner Name:	Caroline Kwan-Us Epa
Owner Type:	Private
Operator Name:	Day Pitney Llp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

NEWTOWN CREEK (Continued) **1011845384**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211122
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D015
Waste Description:	Toxaphene (C10 H10 Cl8, Technical Chlorinated Camphene, 67-69 Percent Chlorine)
Waste Code:	D020
Waste Description:	Chlordane
Waste Code:	D031
Waste Description:	Heptachlor (And Its Epoxide)

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CAROLINE KWAN-US EPA

NEWTOWN CREEK (Continued) **1011845384**

Legal Status:	Private
Date Became Current:	19800101
Date Ended Current:	Not reported
Owner/Operator Address:	290 BROADWAY
Owner/Operator City,State,Zip:	NEW YORK, NY 10007
Owner/Operator Telephone:	212-637-4275
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

Owner/Operator Name: DAY PITNEY LLP

Legal Status:	Private
Date Became Current:	20120416
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20120321
Handler Name:	NEWTOWN CREEK SUPERFUND SITE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	54162
NAICS Description:	ENVIRONMENTAL CONSULTING SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

ROD:

No Details:	No Details

PRP:

PRP Name:	APOLLO PETROLEUM TRANSPORT LLC
	APOLLO PIPELINE LLC
	APOLLO TRANSPORT INC
	BP AMERICA HEADQUARTERS

NEWTOWN CREEK (Continued) **1011845384**

BP AMERICA HEADQUARTERS
BP AMERICA HEADQUARTERS
BROOKLYN UNION GAS
BROOKLYN UNION GAS
BROOKLYN UNION GAS
EXXONMOBIL CORPORATION
EXXONMOBIL CORPORATION
EXXONMOBIL CORPORATION
GETTY PETROLEUM MARKETING INC
GETTY TERMINALS CORP
KINGS LAND REALTY INC
METRO BIOFUELS LLC
METRO ENERGY GROUP LLC
METRO FUEL OIL CO.
METRO PLUMBING SERVICES CORP
METRO TERMINALS CORP

Click this hyperlink while viewing on your computer to access
11 additional PRP: record(s) in the EDR Site Report.

NY MANIFEST:

Name:	NEWTOWN CREEK SUPERFUND SITE
Address:	NEWTOWN CRK - N LAT 40.715192
City,State,Zip:	NEW YORK, NY 99999
Country:	USA
EPA ID:	NYN000206282
Facility Status:	Not reported
Location Address 1:	- VERNON BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYN000206282
Mailing Name:	NEWTOWN CREEK SUPERFUND SITE
Mailing Contact:	C/O ANCHOR QEA LLC
Mailing Address 1:	TICE BLVD - SUITE
Mailing Address 2:	Not reported
Mailing City:	WO0ODCLIFF LAKE
Mailing State:	NJ
Mailing Zip:	07677
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2015710912

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD021816889
Trans2 State ID:	Not reported
Generator Ship Date:	10/31/2014
Trans1 Recv Date:	10/31/2014

NEWTOWN CREEK (Continued) **1011845384**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYN000206282
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	013301186JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	55
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A2 **CON EDISON** **NY MANIFEST** **S117315600**
37-25 21 ST **N/A**
< 1/8 **QUEENS, NY 11101**
1 ft.

Site 2 of 20 in cluster A

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	37-25 21 ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYP004627857
Facility Status:	Not reported
Location Address 1:	37-25 21 ST
Code:	BP
Location Address 2:	SB 19819
Total Tanks:	Not reported

Actual:
17 ft.

CON EDISON (Continued) **S117315600**

Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004627857
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/14/2014
Trans1 Recv Date:	08/14/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/14/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004627857
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615893GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1

CON EDISON (Continued) **S117315600**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A3 **CITY USED AUTO CENTER INC** **NY SWF/LF** **S108145769**
37-25 21ST STREET **NY Spills** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
1 ft.

Site 3 of 20 in cluster A

Relative: SWF/LF:
Higher

Actual:
17 ft.

Name:	CITY USED AUTO CENTER INC
Address:	37-25 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	589636
North Coordinate:	4512470
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

SPILLS:

Name:	LIC USED AUTO PARTS
Address:	37-25 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0230068 / 2007-01-29

CITY USED AUTO CENTER INC (Continued) **S108145769**

Facility ID:	0230068
Facility Type:	ER
DER Facility ID:	147330
Site ID:	175236
DEC Region:	2
Spill Cause:	Deliberate
Spill Class:	B2
SWIS:	4101
Spill Date:	2003-03-11
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2003-03-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-11
Spill Record Last Update:	2007-01-29
Spiller Name:	Not reported
Spiller Company:	LIC USED AUTO PARTS
Spiller Address:	37-25 21ST STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 3/11/2003 Sangesland responded to the site of an ECO/Police action at a junk yard. Site has been an active Auto Parts facility for approx 2 years. Site is an irregular T shaped lot (approx 120' x 200') Cement/asphalt appears to cover majority of the lot, unknown if this ground cover is complete and impervious to surface spills. No obvious floor drains could be seen. Unknown if rainwater, auto fluids run into the ground or directly off site. Central area of the yard appears to be the car dismantling area and contains the majority of the spilled auto fluids (oil, transmission fluid, etc.) There is no controled spill containment area (no curbing, collection tank etc). Perimeter of yard was lined primarily with automobile racks (3 cars high). Ground staining appeared weathered and less severe than in the central area. Along with automotive liquids, the yard contained a large number of engines, transmissions, various engine parts and multiple automobile batteries (several appeared damaged and overturned). DEC Requirements: 1) Surface of the yard must be cleaned down to the cement/asphalt level. An integrity inspection will be made to determine if there are any floor drains or open cracks directly to the ground below. 2) A Site Delineation will be required at the

CITY USED AUTO CENTER INC (Continued) **S108145769**

property. A series of soil borings will be taken in a grid pattern over the area of the yard and soil/water samples tested to EPA Method 8260, 8770 & heavy metals. 3) Based on the results of the Site Delineation , a Site Remediation Plan will need to be prepared which will identify the procedure to clean up the contamination identified in the delineation. 4/11/2003 - The owner of the property is believed to be Virginia 516-383-9358. She is somehow associated with Yardley Associates . A call was made to this number in an attempt to get a mailing address, but no response was recieved. Lease holder to the site is: Jussain Zulfiqar and/or Anwar Javed. 5/7/2003 Sangesland spoke with Virginia Lupoli (owner) She inherited the property from her father. Yardley Associates LLC is the corporate name for the owner. Sangesland outlined the work which will be required on this site. 1) Power wash the lot to determine the condition of the black top or cement pavement 2) Geo Probe of site to determine the subsurface condition of the site. 3) A 60 day limit will be put in the letter. 4) A list of state contractors will be forwarded with the letter Contact info: Yardley Associates LLC Attn: Virginia Lupoli P.O. Box 237 Cold Spring Harbor, NY 11724 Fax # 631-385-4477 11/4/2003 Sangesland reviewed an Environmental Site Assessment for this site prepared by Dr. Norman Munroe (917-497-0190) of Astem Labs Inc. Report states that the entire site is capped with a cement pad between 8 and 24 thick. There did not appear to be any open preferential pathways directly to the soil. The report did not outline the path for rain water runoff or recharge. Report outlines soil boring work done on the site along with some ground water sampling. Some minor soil VOC hits (BTEX) in BH-2, BH-4 and BH-9 One minor groundwater hit for Benzene & MTBE in BH-4 SVOC's for soil and water were below regulatory limits Heavy metal concentrations in soil samples exceeded regulatory limits for several metals including: lead arsenic, cadmium, chromium and copper. Based on this information, the case is closed with no further action required."

Remarks: "DEC SPILLS GROUP CALLED TO SITE OF POLICE ACTION AT A JUNK YARD. SITE HAD SPILLS OF AUTO RELATED LIQUIDS OVER ENTIRE YARD AREA."

All Materials:

Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509720
Material Code:	0044A
Material Name:	battery acid
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G

CITY USED AUTO CENTER INC (Continued) **S108145769**

Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509717
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509718
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509719
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509716
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

CITY USED AUTO CENTER INC (Continued) **S108145769**

Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	175236
Operable Unit ID:	866828
Operable Unit:	01
Material ID:	509715
Material Code:	0005A
Material Name:	auto waste fluids
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A4 **LIC USED AUTO PARTS** **NY AST** **A100486840**
37-25 21ST ST **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
1 ft.

Site 4 of 20 in cluster A

Relative: Higher
Actual: 17 ft.

AST:

Name:	LIC USED AUTO PARTS
Address:	37-25 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609133
Program Type:	PBS
UTM X:	589596.63921
UTM Y:	4512407.79658
Expiration Date:	07/23/2008
Site Type:	Other

Affiliation Records:

Site Id:	30979
Affiliation Type:	Facility Owner
Company Name:	ZULFIQAR HUSSAIN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	32-42 75TH STREET
Address2:	Not reported
City:	EAST ELMHURST
State:	NY
Zip Code:	11370-1808
Country Code:	001
Phone:	(718) 729-9527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	30979
Affiliation Type:	Mail Contact

LIC USED AUTO PARTS (Continued) **A100486840**

Company Name:	LIC USED AUTO PARTS
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	37-25 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-9519
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30979
Affiliation Type:	Facility Operator
Company Name:	LIC USED AUTO PARTS
Contact Type:	Not reported
Contact Name:	RICHARD ORTIZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-9519
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	30979
Affiliation Type:	Emergency Contact
Company Name:	ZULFIQAR HUSSAIN
Contact Type:	Not reported
Contact Name:	K.K.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-9440
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	66531
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

LIC USED AUTO PARTS (Continued) **A100486840**

Equipment Records:

	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	G00 - Tank Secondary Containment - None
	J00 - Dispenser - None
	C01 - Pipe Location - Aboveground
	D00 - Pipe Type - No Piping
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

A5 **LI CITY GAS & CONVENIENCE INC.** **NY AST** **U001330054**
3725 21ST ST **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
1 ft.

Site 5 of 20 in cluster A

Relative: Higher
Actual: 17 ft.

AST:

Name:	LI CITY GAS & CONVENIENCE INC.
Address:	3725 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-601352
Program Type:	PBS
UTM X:	589622.14176
UTM Y:	4512394.51341
Expiration Date:	03/04/2028
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23319
Affiliation Type:	Emergency Contact
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	CHRIS CONSTANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

LI CITY GAS & CONVENIENCE INC. (Continued) **U001330054**

Phone:	(718) 729-9850
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-30

Site Id:	23319
Affiliation Type:	Mail Contact
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	PRESIDENT
Contact Name:	CHRIS CONSTANT
Address1:	37-45 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-9850
EMail:	SANDHU025@YAHOO.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-30

Site Id:	23319
Affiliation Type:	Facility Operator
Company Name:	KIMCO GAS, INC
Contact Type:	Not reported
Contact Name:	CHARANJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 856-4082
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-14

Site Id:	23319
Affiliation Type:	Facility Owner
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	PRESIDENT
Contact Name:	NICOSIA SERVICE STATION INC
Address1:	37-45 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-3858
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-14

LI CITY GAS & CONVENIENCE INC. (Continued) **U001330054**

Tank Info:

Tank Number:	004
Tank Id:	219425
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	K00 - Spill Prevention - None
	E00 - Piping Secondary Containment - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	D00 - Pipe Type - No Piping
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	L00 - Piping Leak Detection - None
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	11/01/1997
Capacity Gallons:	180
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/14/2022
Material Name:	lube oil

A6 **NEW BANGLA MOTOR INC.** **NY AST** **A100486841**
37-25 21ST STREET **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
1 ft.

Site 6 of 20 in cluster A

Relative: Higher
Actual: 17 ft.

AST:

Name:	NEW BANGLA MOTOR INC.
Address:	37-25 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-609202
Program Type:	PBS
UTM X:	589629.81370
UTM Y:	4512477.12233
Expiration Date:	N/A
Site Type:	Other

Affiliation Records:

NEW BANGLA MOTOR INC. (Continued) **A100486841**

Site Id:	31047
Affiliation Type:	Facility Owner
Company Name:	MD ABDUL KADIR
Contact Type:	PRESIDENT
Contact Name:	MD ABDUL KADIR
Address1:	37-25 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-9440
EMail:	Not reported
Fax Number:	Not reported
Modified By:	AAANASTA
Date Last Modified:	2005-01-18

Site Id:	31047
Affiliation Type:	Mail Contact
Company Name:	NEW BANGLA MOTOR INC.
Contact Type:	Not reported
Contact Name:	MR. KADIR
Address1:	37-25 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 707-9440
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-09-01

Site Id:	31047
Affiliation Type:	Facility Operator
Company Name:	NEW BANGLA MOTOR INC.
Contact Type:	Not reported
Contact Name:	KADIR MD ABDUL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 707-9440
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31047
Affiliation Type:	Emergency Contact
Company Name:	MD. ABDUL KADIR
Contact Type:	Not reported
Contact Name:	MR RAHMAN
Address1:	Not reported

NEW BANGLA MOTOR INC. (Continued) **A100486841**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 207-8085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank Id:	66767
Material Code:	0000
Common Name of Substance:	Empty

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
J00 - Dispenser - None

Tank Location:	Aboveground in subterranean vault with access for inspections..... Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	07/01/2003
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	empty

Tank Number:	2
Tank Id:	66768
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

NEW BANGLA MOTOR INC. (Continued) **A100486841**

G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
J00 - Dispenser - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/01/2003
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/2004
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

A7 **LI CITY GAS & CONVENIENCE INC.** **NY UST** **U004063742**
3725 21ST ST **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
1 ft.

Site 7 of 20 in cluster A

Relative: **Higher**
Actual: **17 ft.**

UST:

Name:	LI CITY GAS & CONVENIENCE INC.
Address:	3725 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-601352 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/04/2028
UTM X:	589622.14176
UTM Y:	4512394.51341
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	23319
Affiliation Type:	Emergency Contact
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	Not reported
Contact Name:	CHRIS CONSTANT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 729-9850
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-30

Site Id: 23319

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Affiliation Type:	Mail Contact
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	PRESIDENT
Contact Name:	CHRIS CONSTANT
Address1:	37-45 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-9850
EMail:	SANDHU025@YAHOO.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-01-30

Site Id:	23319
Affiliation Type:	Facility Operator
Company Name:	KIMCO GAS, INC
Contact Type:	Not reported
Contact Name:	CHARANJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 856-4082
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-14

Site Id:	23319
Affiliation Type:	Facility Owner
Company Name:	NICOSIA SERVICE STATION, INC.
Contact Type:	PRESIDENT
Contact Name:	NICOSIA SERVICE STATION INC
Address1:	37-45 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-3858
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-14

Tank Info:

Tank Number:	0001
Tank ID:	45701
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None

Tank Number:	0002
Tank ID:	45702
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Tank Number:	0003
Tank ID:	45703
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	0004
Tank ID:	45704
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/14/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	0005
Tank ID:	45705
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	0006
Tank ID:	45706
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	0007
Tank ID:	45707
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	0008
Tank ID:	45708
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	09/01/1992
Date Tank Closed:	09/01/1992
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I00 - Overfill - None

Tank Number:	0009
Tank ID:	45709
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	03
Date Test:	05/01/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	001
Tank ID:	55933
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	11/01/1991
Date Tank Closed:	Not reported

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	05/09/1998
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/14/2022

Equipment Records:

D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
F03 - Pipe External Protection - Original Impressed Current
F04 - Pipe External Protection - Fiberglass
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B03 - Tank External Protection - Original Impressed Current
I03 - Overfill - Automatic Shut-Off
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B05 - Tank External Protection - Jacketed
G04 - Tank Secondary Containment - Double-Walled (Underground)
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	002
Tank ID:	55934
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	11/01/1984
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	21
Date Test:	04/07/2015
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/14/2022

Equipment Records:

F08 - Pipe External Protection - Retrofitted Impressed Current
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
K01 - Spill Prevention - Catch Basin

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

B07 - Tank External Protection - Retrofitted Sacrificial Anode
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B08 - Tank External Protection - Retrofitted Impressed Current
A00 - Tank Internal Protection - None
I03 - Overfill - Automatic Shut-Off
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number:	003
Tank ID:	55935
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	110
Install Date:	01/01/1997
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/14/2022

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
B05 - Tank External Protection - Jacketed
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
J00 - Dispenser - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

Tank Number:	10
Tank ID:	45710
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	4000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 05/01/1998
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 11
Tank ID: 45711
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: Not reported
Date Tank Closed: 03/01/1990
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 12
Tank ID: 45712
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000

LI CITY GAS & CONVENIENCE INC. (Continued) **U004063742**

Install Date:	Not reported
Date Tank Closed:	03/01/1990
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

A8 **ERRA METALINDUSTRIES INC** **RCRA NonGen / NLR** **1016455671**
SSW **37-35 21ST ST** **FINDS** **NYR000207761**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.004 mi.
21 ft. **Site 8 of 20 in cluster A**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20140611
Handler Name:	Erra Metal Industries Inc
Handler Address:	37-35 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000207761
Contact Name:	JOHN ERRA
Contact Address:	LARKIN ST
Contact City,State,Zip:	HUNGTINGTON STATION, NY 11746
Contact Telephone:	347-723-5500
Contact Fax:	Not reported
Contact Email:	JOHNERRA1@VERIZON.NET
Contact Title:	PARTNER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	LARKIN ST
Mailing City,State,Zip:	HUNGTINGTON STATION, NY 11746
Owner Name:	John Erra
Owner Type:	Private

ERRA METAL INDUSTRIES INC (Continued) **1016455671**

Operator Name:	John Erra
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160708
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOHN ERRA	
Legal Status:	Private
Date Became Current:	19881219
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported

ERRA METAL INDUSTRIES INC (Continued) **1016455671**

Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOHN ERRA
Legal Status: Private
Date Became Current: 19881219
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JOHN ERRA
Legal Status: Private
Date Became Current: 19881219
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: JOHN ERRA
Legal Status: Private
Date Became Current: 19881219
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140611
Handler Name: ERRA METAL INDUSTRIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140218
Handler Name: ERRA METAL INDUSTRIES INC

ERRA METAL INDUSTRIES INC (Continued) **1016455671**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 423510
NAICS Description: METAL SERVICE CENTERS AND OTHER METAL MERCHANT WHOLESALERS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058879995

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016455671
Registry ID:	110058879995
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058879995
Name:	ERRA METAL INDUSTRIES INC
Address:	37-35 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

A9 **37-35 21ST STREET** **NY Spills** **S118951822**
SSW **37-35 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.004 mi.
21 ft. **Site 9 of 20 in cluster A**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	37-35 21ST STREET
Address:	37-35 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Spill Number/Closed Date:	1606143 / 2016-10-14

37-35 21ST STREET (Continued) **S118951822**

Facility ID:	1606143
Facility Type:	ER
DER Facility ID:	486725
Site ID:	532744
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	4101
Spill Date:	2016-09-20
Investigator:	JKKANN
Referred To:	Not reported
Reported to Dept:	2016-09-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2016-09-20
Spill Record Last Update:	2016-10-14
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	NONE
DEC Memo:	"9/20/16: J.Kann - received call from anonymous male and created the spill report. Caller indicated that the work is being done now. Spoke with Jeff/Kumar and Ryan agreed to go out to the site to see what was on going on. Ryan visited the site and met with the site safety officer: Vincent Wong (718)810-7170 email PrecisionSafetySolutionsLLC@gmail.com Owner info: 21st Street Hospitality LLC, 37-35 21st Street, LIC (718)925-9700 Ryan took photos and indicated that no oil was present. Ryan left a message for the owner requesting a call back. Spill will be assigned to Tim as he was the runner for the day. Spill will be left in my name until a letter is sent to the owner, if necessary. 10/14/16: J.Kann - spoke with Ryan again. Confirmed that he was unable to corroborate the anonymous callers complaints. He did not observe any petroleum odors at the time of his site visit. Spill closed. "
Remarks:	"Caller states property owner is taking out contaminated soils without reporting to appropriate authorities. Owner is using own trucks to remove the contaminated soils. Called smells petroleum and says its visually contaminated. Building already demolished and"

All Materials:

Site ID:	532744
Operable Unit ID:	1281484
Operable Unit:	01
Material ID:	2286757

37-35 21ST STREET (Continued) **S118951822**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

A10 **QAZI AUTO REPAIRS INC** **NY AST** **A100300280**
NNW **37-27 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.005 mi.
24 ft. **Site 10 of 20 in cluster A**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	QAZI AUTO REPAIRS INC
Address:	37-27 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610365
Program Type:	PBS
UTM X:	589660.16178
UTM Y:	4511786.04134
Expiration Date:	10/04/2011
Site Type:	Other

Affiliation Records:

Site Id:	371414
Affiliation Type:	Facility Owner
Company Name:	QAZI AUTO REPAIRS INC.
Contact Type:	PRESIDENT
Contact Name:	ABID HUSSAIN
Address1:	37-27 21ST ST.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-9527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-10-04

Site Id:	371414
Affiliation Type:	Mail Contact
Company Name:	QAZI AUTO REPAIRS INC.
Contact Type:	Not reported
Contact Name:	ABID HUSSAIN
Address1:	37-27 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY

QAZI AUTO REPAIRS INC (Continued) **A100300280**

Zip Code:	11101
Country Code:	001
Phone:	(718) 729-9527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-10-04

Site Id:	371414
Affiliation Type:	Facility Operator
Company Name:	QAZI AUTO REPAIRS INC
Contact Type:	Not reported
Contact Name:	ABID HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-9527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-10-04

Site Id:	371414
Affiliation Type:	Emergency Contact
Company Name:	QAZI AUTO REPAIRS INC.
Contact Type:	Not reported
Contact Name:	ABID HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-9527
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2006-10-04

Tank Info:

Tank Number:	001
Tank Id:	213891
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	G05 - Tank Secondary Containment - Synthetic Liner
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported

QAZI AUTO REPAIRS INC (Continued) **A100300280**

Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

A11 **DDC- (FORMER PS 111) - LIC LIBRARY** **NY Spills** **S103937265**
NNW **37-44 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.012 mi.
64 ft. **Site 11 of 20 in cluster A**

Relative: **Lower**
Actual: **16 ft.**

SPILLS:

Name:	DDC- (FORMER PS 111) - LIC LIBRARY
Address:	37-44 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9901712 / Not Reported
Facility ID:	9901712
Facility Type:	ER
DER Facility ID:	109409
Site ID:	126573
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	1999-05-13
Investigator:	AXDORONO
Referred To:	REPORT REVIEWED
Reported to Dept:	1999-05-13
CID:	233
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	1999-05-13
Spill Record Last Update:	2022-06-22
Spiller Name:	Not reported
Spiller Company:	FORMER GAS STATION
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ANGELO ELMI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL DEC (Sigona) reassigned from DEC (Sangesland) on 6/28/99. DEC Sigona Received phase II site investigation perfromed by Metcalf & Edddy, dated May 1999. DDC building a library on site of former gas station. Further background investigation to be performed by City. DEC (Sigona spoke

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

with Angelo Elmi (718)391-2123
on 5/18/1999. Metcalf & Eddy does not have proposed remediation plan. No imminent threat to public
according to consultant. The contamination lies deep below grade. Did not find USTs. Conducted
limited phase I investigation. Could not locate any records with Fire Department, only indication
was listing on Sandbourne fire maps and soil testing. 10/14/04 Reassigned from Rommel to Sun.
1/19/06 - Obligado - reassigned from Sun to Obligado 09/15/06: This spill is transferred from Mr.
koon Tang to Q.Abidi 09/19/06: Called Mr. James A. Merlo at (718)349-5738 he is on vacation. He
will come back after two weeks. His Secretary told me that he will remind him for Phase II
Investigation report and Mr. Merlo will call me back regarding spill. -QA 03/14/07: Called Mr.
James A. Merlo he was not available. Left message to call me back. -QA

6/25/08: Reassigned from Vadim Brevdo to Kartik chanda. (Chanda) 7/29/08: Chanda reviewed this
spill related documents and sent a letter to RP (NYC Dept. of Education), requiring that a
Subsurface Investigation Report be submitted to DEC by 9/16/08 for review and approval. (see eDocs)
9/11/08: Chanda received a letter from NYCDOE (James Merrlo) dated 9/10/08. The letter stated that
his office does not have any information pertaining to this spill.Chanda discussed with Mark
Tibbe(NYSDEC) regarding the NYCDOE's letter. (see eDocs) 9/22/08: Chanda sent a letter to Ms Lee
guterman (NYCSCA) requiring that a brief work plan with boring and monitoring well locations, and
an implementation schedule, be submitted to DEC by 10/22/08 for review and approval. (see eDocs)
10/23/08: A meeting was held on 10/21/08 among DER staff, the NYCSCA representative to discuss the
site status and updated information for this site. The meeting s consensus was that the NYCSCA will
submit a tine extension request to submit the investigation work plan for this site. 11/3/08:
Chanda received a Site Investigation Report dated 5/1999 from NYCSCA. 05/13/2009: This spill case
was transferred to A. Doronova. - AD 08/2009: Reviewed the Site Investigation Report dated May
1999. It states that the historical data indicate that this site was used as a filling station from
1930 untill 1948, when the station was demolished and PS-111 was constructed. The site
investigation was performed by Metcalf & Eddy of NY, Inc. on behalf of DDC on March 12, 1999 for
New Long Island City Library. The work was performed to evaluate the potential for environmnetal
concerns related to historical uses of the property. Four soil borings were advanced with
collection of soil samples. All soil samples were analyzed for VOCs

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

and SVOCs. GW was encountered
at depth of 8 to 10 feet bgs. Petroleum sheen and odor were detected
in the soil within one foot
and below the water table in SB-2 and SB-4 at 10-15 feet bgs.
Analytical soil results indicated
elevated levels of VOCs and SVOCs. Based on these data, the consultant
recommended additional soil
and groundwater investigation to delineate the contamination plume. AD
06/23/2011: Contacted Drew
Pardus and Lee Guterman of NYCSCA regarding the site. They said that
DDC handles this property.
Called and spoke with Afsar Samani of DDC. She informed me that DDC
was involved only on the early
stage of the project and gave me contact info of assistant
commissioner on libraries - Sergio
Silveira. Phone: (718)391-1041. Called and spoke with him. He
confirmed that library was
constructed at the site and addressed me to the director of
maintenance - Dennis Verriello (phone:
718-480-4282). Called and left a message. AD 06/29/2011: Received a
phone call from Mr. Verriello.
Told him about situation with the spill. He promised to look in the
files regarding any info that
the contaminated soil was removed during construction of the library.
He cofirmed that the library
was constructed by DDC and also said that the building was constructed
on a slab, and does not have
a basement. AD 07/14/2011: On a quarterly meeting with DDC requested
contact info for this case
from A. Samani. She promised to help with that. AD 08/15/2011: Spoke
with A. Samani of DDC
regarding contact info. She gave me a phone number of Sandra Roberto
of technical support
(718)391-2214. Called and spoke with Ms. Roberto. She found the info
in their system that Phase II
investigation was performed for DDC. She said that additional info if
remediation was done at the
site may be in the archive. She promised that someone will contact us
soon regarding this matter.
Later received a phone call from Antony Sigona, who works for DDC. He
asked for a DEC letter
requiring additional info. Will prepare a letter. AD 08/24/2011: Sent
an e-mail to Mr. Sigona
regarding the report and asked for a contact info of a person, to whom
such a letter should be
addressed. 09/06/2011: Received an e-mail from Mr. Sigona with a
contact person info: Rebecca
Tummon Section Chief, NYCDDC Bureau of Environmental and Geotechnical
Services NYC DDC 30-30
THOMSON AVENUE LONG ISLAND CITY, N.Y. 11101 (718) 391-1799 AD
09/09/2011: Called and spoke with Ms.
Tummon of DDC. She told me that A. Sigona is no longer works for DDC.
Ms. Tummon said that she will
get back to us after reviewing all related files. AD 09/26/2011:
Received a call from Dennis Askins
of DDC (718-391-1338, e-mail: (askinsd@ddc.nyc.gov). He is collecting
information for this case and

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

asked for the investigation report prepared for DDC back in 1999. AD 10/17/2011: Received an e-mail from Rebecca Tummon of DDC saying: Aina, Attached is all the information found regarding any soils removed at long island city library. Please let us know if there are any questions. Thank you -Rebecca Tummon 718 391 1799 DL data to eDocs. Will review. AD 11/02/2011: Reviewed the data. The data submitted is a analytical results for what it seems to be a one composite soil sample for waste characterization. It was collected in 2006. This data is not sufficient to make any decision. To require site investigation. AD 11/15/2011: Received a call from Dennis Askins of DDC. Told him that I looked at the submitted data, and it is not enough to make a decision regarding case closure. A work plan is needed for soil and GW investigation around the library building. Asked Dennis to send me a site layout with a building footprint to determine number of soil borings. AD 12/06/2011: Received an e-mail from Mr. Askins saying: Ainura, See attached as-built plans with reference to additional environmental borings needed to close this spill. If you need anything else please let me know. Thank you, Dennis Askins, P.G. DL the attached plans to eDocs. Investigation work plan should be submitted. AD 12/08/2011: Called and spoke with Ms. Tummon of DDC. Asked her to check feasibility of soil borings installation around the library building. Ms. Tummon asked for an official request from DEC for site investigation. Issued and sent Investigation Needed letter to Ms. Tummon. DL pdf copy of the letter to eDocs. IWP is due. AD 01/18/2012: Received an e-mail from Steve Frank of LiRo saying: Hi Ainura, The work plan we prepared to investigate spill #9901712 under the BEGS program is attached for your review. Please let us know if you have any comments and if you would like a hard copy of the work plan sent to your office. Thanks, Steve DL the work plan to eDocs. Reviewed the work plan. LiRo proposes eight soil borings (LSB-01 through LSB-08) to further investigate the spill. Additionally, three groundwater samples (GW-01 through GW-03) will also be collected from the three boring locations. The proposed depth of the borings will be 20 ft bgs utilizing the Geoprobe direct push drill rig through the concrete sidewalk in the proposed locations. Soil from each boring will be screened for VOCs along the vertical length of the soil column using a PID and visual/olfactory senses. One grab sample will be collected from each boring (LSB-01 through LSB-08). Groundwater is anticipated to be approximately 8 to 12 ft bgs, based on the previous subsurface investigation completed at the Site. Assessment of groundwater quality will include the collection of 3 groundwater samples (GW-01 through GW-03)

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

from temporary well points
(TWPs) installed during the soil boring activities at soil borings
LSB-01, LSB-04, and LSB-06.
LSB-04 and LSB-06 are assumed to be up-gradient of the previously
identified impacted soil while
LSB-01 is assumed to be down-gradient of the previously identified
impacted soil. If groundwater is
not encountered at the maximum boring depth of 20 ft bgs, groundwater
samples will not be
collected. If free product is found, LiRo will notify NYCDDC and
fingerprint analysis will be
completed. Upon completion of the sampling, each TWP will be removed
and the borehole will be
backfilled with drill cuttings, and surface repaired in kind. A Phase
II ESA Report with conclusion
and recommendations for further actions will be prepared and submitted
to DEC. TWP should be
converted into permanent monitoring wells if contamination or free
product will be discovered
during TWP installation. Soil sampling intervals are questionable. Two
soil samples should be
collected per each soil boring. To diccuss with J. Kolleeny of DEC. AD
01/19/2012: Discussed the
work plan with J. Kolleeny. Issued an approval letter to Ms. Tummon of
DDC with the following
comments: Two soil samples should be collected for analysis per
boring/well: one sample from
directly above the water table and a second from the sampling interval
with the highest PID
reading. In the absence of any field indications of contamination, a
single soil sample should be
collected from just above the water table. Any temporary well point
showing significant field
indications of contamination during installation should be converted
into a permanent monitoring
well. DL PDF copy of the letter to eDocs. AD 04/18/2012: received an
e-mail from R. Tummon saying:
Ainura, Please find attached the Phase II report for the spill no.
9901712 at LIC Library located
at 37-21 21st Street in Queens NY prepared by our consultant Liro. We
can have them send you a
hardcopy if needed. We are requesting that the spill be closed based
on the results of the Phase
II. Please let us know if a hardcopy or anything else is needed and if
there are any questions.
Thank you Rebecca Tummon, LEED GA Section Chief, NYCDDC Bureau of
Environmental and Geotechnical
Services (718) 391-1799 DL the report to eDocs. Will review. AD
05/02/2012: Reviewed the report. It
states that LiRo completed a site subsurface investigation from
January 25, 2012 through February
7, 2012 which included the following: - The advancement of eight soil
borings to a depth of up to
approximately 20 ft bgs and the collection of two soil samples from
each boring; - The installation
of groundwater monitoring wells within each of the soil borings. The
collection of one groundwater

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

sample from each of the eight monitoring wells installed. Subsurface soil sampling was performed on
February 1 and 2, 2012. Field screening identified visual and/or olfactory evidence of petroleum
impacted soils within each of the soil borings. Elevated PID readings were identified in borings
LSB-01, LSB-02, LSB-05, LSB-06, LSB-07, and LSB-08 generally at a depth of 10 ft bgs to 20 ft bgs.
Petroleum staining was observed in association with the elevated PID readings. No free product was
observed. Benzene, ethylbenzene, isopropylbenzene, p-isopropylbenzene, naphthalene, npropylbenzene,
toluene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, and total xylenes were detected at
concentrations above CP-51 SCLs. VOC exceedances were detected within samples LSB-02-10-15,
LSB-05-16-17, LSB-07-10-11, LSB-07-12-13, LSB-08-9-10, and LSB-08-13-14. 1,2,4-trimethylbenzene and
total xylenes were detected in the soil samples at concentrations above NYSDEC Part 375 Protection
of Public Health Commercial Use SCOs. These VOC exceedances were detected within sample
LSB-07-10-11. LiRo states that the detected concentrations of VOCs in these soil samples are
significantly higher than previous investigation results and the source of the contamination is
unknown as the increase of contamination concentrations from previous studies and the presence of
the soil contamination at the groundwater soil interface in soils located up-gradient to the
current groundwater flow direction suggests an off-site sources may be affecting the Site.
Groundwater sampling was done on February 7, 2012. Benzene, ethylbenzene, isopropylbenzene, MTBE,
naphthalene, n-propylbenzene, toluene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, 0-xylenes,
and p-&m-xylenes were detected at concentrations above NYSDEC Class GA Groundwater standards in all
eight groundwater samples. Total VOCs ranged from 26 ug/L in LSB-04-GW to 771 ug/L in LSB-08-GW.
Based on the results of the Phase II ESI, LiRo made the following conclusions: - The site was
developed with a gasoline station from the 1920 s or early 1930 s through 1948. In addition,
several historic and active gasoline stations are located across 21st Street to the east and across
38th Avenue to the south of the Site. - The site ceased use as a filling station prior to 1951 and
MTBE was not added to fuel until 1979. The presence of MTBE in groundwater clearly indicates that
MTBE is from an off-site source. - According to the NYSDEC Spills Database,in addition to a current
onsite open spill (#9901712), there are two (2) additional open oil spills (Spill #9307497 and
Spill #9403515) listed for the corner of 21st Street and 38th Avenue. These spills occurred on
September 21, 1993 and June 13, 1994, respectively, and involved

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

non-PCB oil that affected soil.
Based on the spill dates (prior to 1999) it is possible that they impacted the Site. Based on the
type of oil released, it is unlikely that these spills contributed to the MTBE contamination
observed at the site. - Elevated PID readings were identified in several borings at depths that
were generally below the water table. The lack of vadose zone (i.e., the portion of the soil column
above the water table) soil contamination indicates that much of the contamination migrated to the
boring locations via groundwater transport. - VOCs were detected in the soil samples, generally at
depths below the water table with only two borings showing contamination in the deeper portion of
the vadose zone. In addition, the detected VOC concentrations were significantly higher than M&E s
previous testing at the site. - SVOCs were detected in the soil samples at every boring location.
The widespread SVOCs indicate that the contamination is likely attributable to contaminants in fill
material (i.e., coal, ash) placed at the Site which may be comingled with petroleum release(s). -
VOCs were detected at concentrations above NYSDEC Class GA Groundwater standards in all eight
groundwater samples collected. MTBE is present in groundwater indicating that an off-site source is
present as MTBE was not added to gasoline until 1979, long after the Site use as a gasoline station
ceased. - SVOCs were detected at concentrations above the corresponding NYSDEC Class GA Groundwater
standards in a majority of the groundwater samples. The SVOCs are likely attributable to the
coal/ash present in the fill which may be co-mingled with petroleum releases(s). - The depth to
groundwater ranged from 11.12 ft bgs at LSB-06 to 13.76 ft bgs at LSB-02. The interpreted Site
groundwater flow appears to be eastward based on surveyed well elevations and depth to water
obtained on February 7, 2012. Based on the data LiRo states that the results of the investigation
show evidence of petroleum impacted soil and groundwater at the site. Based on the increased levels
of contamination compared to M&E s testing conducted in 1999, the presence of MTBE in groundwater,
and the presence of off-site sources (open spills and gasoline stations) it appears that the site
is not the source of the contamination and, therefore, Spill Number 9901712 should be closed. Due
to the VOC contamination present on-site, a soil vapor intrusion evaluation is warranted for the
library building, unless there are records which indicate that the library was constructed with a
sub-slab vapor barrier. The soil vapor intrusion evaluation should be conducted for the library
building following the NYSDOH Guidance for Evaluating Soil Vapor Intrusion in the State of New York

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

dated October 2006. Will discuss the site with J. Kolleeny of DEC. AD 05/08/2012: Discussed the spill closure request with J. Kolleeny. Some additional information is needed (such as: potential off-site source of contamination; current heating fuel for the library; any documentation that the USTs were removed from the site; if GPR survey was ever done at the site). Called and left a message to Mr. Frank of LiRo. AD 05/15/2012: Received a call from S. Frank. He said that the library is on a natural gas. Additional data will be provided. AD 06/28/2012: Received a call from S. Frank of LiRo. Reminded him regarding additional data submission. Told him that I am preparing a letter approving recommendation to perform indoor quality sampling. AD 07/27/2012: Received the following e-mail from S. frank: Dear Ainura, As a follow-up to our phone conversation on June 28, 2012, LiRo and NYCDDC conducted additional research to address your questions and concerns. 1 You inquired if a GPR survey was ever conducted at the site. -There was not. 2 You asked if we have any documentation that the tanks were removed or closed in place. -There are no PBS records for the tanks and FDNY did not have any records of tank removal. The Sanborn maps that were attached to our report show that the gas station was removed between 1947 and 1950 and do not indicate the presence of tanks at the site after 1947. NYCDDC contacted their project manager for the Library construction project and he was certain that no tanks were encountered during construction. I have attached a Figure Foundation Plan for the library showing the approximate location of the tanks shown on the 1947 Sanborn map. Based on the number and placement of the footings, we are confident that tanks, if present, would have been encountered during library construction. Based on these findings and observations we are confident that the tanks were, in fact, removed 3 You asked how the building is currently heated -The building is heated with natural gas no history of heating oil use at the Library 4 You asked which nearby gasoline station could pose an off-site source. -The greatest level of contamination was observed along 38th street at location LSB-08. The closest potential source to this location is the Shell gas station at the southwest corner of 38th Avenue and 21st Street. The edge of the tank farm at that gas station is approximately 75 feet southwest of location LSB-08. See attached Figure, Off-site Potential Source locations Based on this information, please let us know if the spill can be closed. Please let us know if you need further information or have additional questions. Sincerely, Steve Frank LiRo Engineers, Inc. 718-321-3136 x236 AD 07/31/2012: Discussed the provided info and spill closure

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

request with J. Kolleeny. Will
approve recommedation for indoor air quality sampling. Issued and sent an approval letter to R.
Tummon of DDC. DL pdf copy of the letter to eDocs. Changed site priority to P2. AD 08/21/2012:
received the following e-mail from S. frank: Hi Ainura, We prepared a Work Plan for air testing at
the Long Island City Library site which I have attached for your review as you requested in your
letter dated July 31, 2012. We have mailed a paper copy of the work plan and a CD to your office as
well. Thanks, Steve Frank LiRo Engineers, Inc Will review. AD 09/18/2012: Reviewed the work plan.
LiRo recommends an air quality investigation to evaluate potential vapor intrusion in the library
building. The purpose of the air quality investigation is to determine if the petroleum
constituents in soil and groundwater are adversely affecting air quality within the library
building. LiRo proposes to collect for the air quality investigation, a total of two (2) indoor air
samples and one (1) outdoor ambient air sample for laboratory analysis. Number and locations of the
proposed samples are questionable. To discuss the plan with J. Kolleeny of DEC. AD 09/24/2012:
Discussed the proposed work plan with J. Kolleeny of DEC. The work plan should be revised to meet
DOH procedure. Called and left a message to S. Frank of LiRo. 09/25/2012: Received a call back from
S. Frank. Explained to him that the work plan cannot be approved as it is, and what kind of changes
should be done. The work plan will be re-submitted. AD 10/10/2012; Received the following e-mail
from S. Frank: Hi Ainura, We revised the Work Plan for LIC Library vapor testing to include a
subslab sample in addition to the indoor air sample. Because of the Library construction, the only
place we feel we might be able to get a probe hole through the floor is in a utility room near the
southwest corner of the building. Please let us know if this plan is acceptable. Thanks, Steve
Frank LiRo Engineers, Inc. DL the work plan to eDocs. Will review. AD 10/18/2012; Reviewed the work
plan. It states that the Site consists of a two-story library structure that was constructed in
1999. There is no basement associated with this structure and the ground floor is of slab on grade
construction. The exterior portions of the Site include concrete sidewalks. For the air
quality/vapor intrusion investigation, liRo proposes to collect one (1) indoor air sample, one (1)
sub-slab sample, and one (1) outdoor ambient air sample for laboratory analysis. Drilling through
the Library floor will be limited to a utility room. The indoor air sample and the sub-slab sample
will be collected from within the utility room located at the southwest corner of the structure

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

within the first floor. The sub-slab soil vapor probe point will be installed using a rotary hammer drill to create a small diameter hole through the floor slab and approximately two (2) inches into the underlying substrate. Water will be used to minimize the amount of dust generated during the drilling. A temporary probe constructed with inert polyethylene or teflon tubing will be installed in the probe hole and then sealed with a non-VOC emitting surface seal constructed of modeling clay. Upon completion of sub-slab soil vapor sampling, the probe holes will be sealed using concrete. Once installed, one (1) to three (3) probe volumes will be purged prior to collecting the subslab sample. The indoor and outdoor samples will be collected at a height of approximately three (3) to five (5) feet (normal sitting/standing height) above the floor or ground surface. The ambient air sample is proposed to determine the potential influence, if any, of outdoor air on the indoor air sample. Prior to the testing, sample locations and adjacent spaces will be inspected to determine if any materials are present (i.e., equipment, cleaning supplies, etc.) with the potential to affect the samples. Any identified materials will be documented by completing a Building Inventory form. The anticipated schedule for conducting the field work is for sampling at the site in early to mid-November 2012, dependent upon weather conditions to coincide with the heating season operation. Will discuss the work plan with J. Kolleeny of DEC. AD 10/22/2012: Discussed the revised work plan with J. Kolleeny. It was decided to approve the proposed work plan with the following comment: If elevated levels of VOCs detected in the indoor/sub-slab samples, additional investigation may be required by DEC. The approval letter was sent to R. Tummon of DDC. DL pdf copy of the letter to edocs. AD 11/19/2012: Called and spoke with S. Frank of LiRo regarding additional data to support off-site source claim. Requested to install one monitoring well on a sidewalk next to Shell gas station to collect soil and GW data. AD 11/21/2012: Sent the following e-mail to S. Frank: Hi Steve. As per our phone conversation, DEC needs additional soil and groundwater data to support an off-site source claim. One temporary well should be installed on a sidewalk in front of Shell Station which is located across 38th Avenue from the site. A brief work plan for this investigation should be submitted to DEC for review. Thank you, Ainura AD 01/09/2012: Received the following e-mail from S. Frank: Hi Ainura, In response to the request from the New York State Department of Environmental Conservation (NYSDEC), LiRo Engineering (LiRo) have prepared this scope of work on behalf of New York City Department of Design and

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

Construction (DDC) for the
supplemental Phase II ESI activities to delineate the open spill case number 9901712. LiRo proposes
to install a monitoring well LSB-09/GW-09 in the sidewalk along 38th Avenue adjacent to the Shell
gas station. The approximate location is shown on the attached figure. To ensure clearance of
subsurface utilities the boring will be visually cleared to a depth of a minimum of six (6) feet
below ground surface (ft bgs) in accordance with the DDC protocols using vacuum utility clearance.
The boring will subsequently be advanced from the bottom of the vactroned borehole to the terminal
depth of 20 ft bgs utilizing a Geoprobe unit equipped with a 4-foot long Macro Core subsurface
sampler with an acetate liner for continuous sampling of the subsurface soil. Two (2) grab soil
samples will be collected from directly above the water table and from the interval with the
highest PID reading. In the absence of any field indications of contamination, a single soil sample
will be collected directly above the water table. Soil samples will be analyzed for NYSDEC CP-51
parameters for gasoline and fuel oil contaminated soil for VOCs via United States Environmental
Protection Agency (USEPA) Method 8260B and semi-volatile organic compounds (SVOCs) via USEPA Method
8270C. Consistent with the Phase II investigation work at the LIC Library property, a monitoring
well consisting of 2-inch PVC casing and screen (10 ft length) will be installed to 20 ft bgs. The
well will be purged of 3 to 5 well volumes and sampled using a dedicated disposable bailer for
CP-51 VOCs and SVOCs using the analytical methods noted above. Although this work may help identify
one potential off-site location for the MTBE contamination observed at the LIC Library, it is not
the City s intent to conduct further off-site investigations of other potential sources. In
addition to the proposed scope of work, the NYSDEC has previously approved a work plan for sub-slab
vapor and indoor air sampling. In accordance with that plan, LiRo attempted to install a sub-slab
vapor probe on December 18, 2012 in a utility room adjacent to the 38th Street sidewalk. Due to
thickness of the concrete (greater than 17 inches) sub-slab the soil vapor point could not be
installed. This was the lowest point in the Library building floor and the only location that a
sub-slab probe could be installed. Based on that condition, LiRo is requesting approval from the
NYSDEC to install a soil vapor point outside of the utility room door adjacent to the library
within the sidewalk on 21st Street. LiRo will collect soil vapor and companion indoor and ambient
air samples for TO-15 analysis. The results of the vapor evaluation and off-site well sampling will

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

be reported in an addendum to our Phase II Investigation report. Please advise if this plan is acceptable and we will schedule the work. Sincerely, Steve Frank Will review. AD 01/11/2012: Reviewed the work plan. the proposed location for the off-site well is acceptable. Discussed the work plan with J. Kolleeny of DEC. Called and left a message to S. Frank. Issued an approval letter to R. Tummon of DDC. DL pdf copy of the letter to eDocs. AD 05/22/2013: Received an investigation report. DL to eDocs. Will review. AD 07/01/2013: Reviewed the report. It states that this Supplemental Phase II ESI was completed based upon the subsequent findings of the Phase II ESI report completed by LiRo and dated April 16, 2012. The approved air quality/vapor intrusion investigation included the collection of one (1) indoor air sample, one (1) soil vapor sample, and one (1) outdoor ambient air sample. The indoor air sample was collected from within the utility room located at the southwest corner of the first floor of the Library. Both the soil vapor point and the ambient air sample were collected directly outside the exterior door to the first floor utility room within the 38th Avenue sidewalk. The soil vapor probe was installed in accordance with the Final Guidance for Evaluating Soil Vapor Intrusion in New York, New York State Department of Health (NYSDOH), October 2006. The air samples were collected and analyzed for VOCs using USEPA Method TO-15. The air and soil vapor sample results were compared to NYSDOH Air Guideline Values (AGVs) and to background levels of VOCs in indoor and outdoor air presented in the NYSDOH Soil Vapor Intrusion Guidance Document. Based on the laboratory analytical results from the air quality investigation, the indoor air quality sample reported no exceedances of AGVs and the concentrations of fuel-related constituents in indoor air did not exceed background levels published by NYSDOH. The soil vapor sample also reported no exceedances of AGVs. In the soil vapor sample, acetone, 2-butanone, and 4-methyl-2-pentanone were detected above the indoor air background levels published by NYSDOH. These compounds are not fuel-related. The indoor air results for these compounds indicate no significant vapor intrusion is present. The off-site investigation included the installation of one (1) monitoring well, LSB-09/GW-09, in the sidewalk along 38th Avenue adjacent to the Shell gas station across 38th Avenue from the Library to support off-site source claim. In addition, LiRo collected water level measurements from the monitoring wells installed during the initial Phase II ESI. One (1) grab soil sample was collected from LSB-09/GW-09 directly above the water table and analyzed for NYSDEC CP-51 parameters for gasoline and

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

fuel oil contaminated soil
for VOCs via USEPA Method 8260B and semi-volatile organic compounds (SVOCs) via USEPA Method 8270C.
Field screening did not identify petroleum impacted soils within the newly installed soil boring.
No visual or olfactory evidence of impacts were detected within LSB-09/GW-09. The highest
photoionization detector (PID) reading was recorded from 12 to 12.5 ft bgs at 29.8 ppm. No VOC
exceedances above NYSDEC CP-51 Soil Cleanup Levels (SCLs) were detected within the soil sample
collected within LSB-09. One (1) SVOC, indeno[1,2,3-cd]pyrene, was detected in the soil sample at a
concentration that exceeded the NYSDEC CP-51 SCL. This SVOC concentration was detected from the
depth interval of 12 to 12.5 ft bgs. One (1) VOC, benzene, was detected in the groundwater sample
from LSB-09/GW-09 at a concentration that exceeded the applicable NYSDEC TOGS 1.1.1 Ambient Water
Quality Standard and Guidance Value (AWQSGV). No SVOC concentrations were reported above the NYSDEC
Class TOGS 1.1.1 AWQSGV for the groundwater sample collected from LSB-09/GW-09. All groundwater
monitoring wells at the Library were gauged using an electronic water/oil interface probe. During
the well gauging event, evidence of free phase product was detected within GW-07, GW-08, and GW-09.
Only well GW-07 contained a measurable product layer (0.02 feet thick) while a sheen was observed
on groundwater at wells GW-08 and GW-09. A sample of the product was collected from GW-07 for
petroleum identification using USEPA Method 8015. The chemical analysis of oil sample
LIC-LIB-LSB-07(GW-07)-GTAB suggests that the product is characteristic of lubricating oil. The oil
was light yellowish in color and semi-translucent suggesting that the oil was relatively fresh.
Conclusions: Based on the findings of this air quality and additional groundwater sampling event,
the following conclusions are presented by LiRo: - While acetone, 2-butanone, and
4-methyl-2-pentanone were detected above the NYSDOH Fuel Oil 2003 Upper Fence Limit, USEPA BASE
Data 90th Percentile, and HEI RIOPA 2005 95th Percentile in the soil vapor sample collected, these
compounds are not fuel-related and there was no elevated concentrations of five (5) fuel-related
compounds detected within the air sample collected from within the Library. Therefore, VOCs in soil
and groundwater at the Site do not appear to be impacting air quality within the Library building.
- Field screening did not identify petroleum impacted soils within the newly installed soil boring.
No visual or olfactory evidence of impacts were detected within LSB-09/GW-09. The highest PID
reading was recorded from 12 to 12.5 ft bgs at 29.8 ppm. - One (1) SVOC, indeno[1,2,3-cd]pyrene,

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

was detected in the soil sample at a concentration that exceeded the NYSDEC CP-51 SCL. This SVOC concentration was detected from the depth interval of 12 to 12.5 ft bgs. One (1) VOC, benzene, was detected in the groundwater sample from LSB-09/GW-09 at a concentration that exceeded the applicable NYSDEC TOGS 1.1.1 AWQSGV. - Based on the soil and groundwater analytical results from the boring well installed on the south side of 38th Avenue, the fueling station across from the Library does not appear to be a source of contamination observed the Site. - The chemical analysis of oil sample collected from one (1) of the on-site monitoring wells (LSB-07/GW-07) indicates that the contamination is characteristic of lubricating oil. The source of this product is currently unknown; however, based on the appearance of the oil, it can be concluded that it is not related to historical operation of a gasoline filling station that ceased prior to 1950. The area surrounding the Site was historically and is currently an industrial area with multiple gasoline stations and subsurface public utility lines. Recommendations by LiRo: LiRo states that although residual petroleum-related contamination is present in soil and groundwater at the Site, the air quality investigation showed no impacts within the Library from the residual petroleum contamination. The presence of MTBE and lubricating oil in the 38th Avenue sidewalk area wells supports the previous conclusion that contaminant sources unrelated to the former Site use are evident. Because the residual contamination is not adversely impacting indoor air quality at the Site, it is recommended that Spill No. 9901712 should be closed. There is not enough GW dat to make a comparison, so probably one more round of GW sampling will be needed since the most recent and only GW data is dated February, 2012. Will discuss the spill closure request with J. Kolleeny of DEC. AD 07/19/2013: Discussed the spill closure request fro this site with J. Kolleeny of DEC. It was decided to require one more round of GW sampling to ensure decreasing trend of VOCs levels. Issued and sent a letter to R. Tummon of DDC. DL pdf copy of the letter to eDocs. AD 03/04/2014: Received Final Supplemental Groundwater Sampling Report. DL the report to eDocs. Will review. AD 04/07/2014: Reviewed the report. It states that on September 19, 2013 LiRo conducted gauging of all nine monitoring wells using an electronic oil/water interface probe. The surveyed well elevations and depth to groundwater measurements collected during this groundwater sampling event were used to prepare a groundwater elevation contour map which indicates groundwater flow to the east and southeast with a horizontal hydraulic gradient of 0.02 ft/ft. GW

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

sampling: LiRo also completed GW
sampling from the wells LSB-01, LSB-02 and LSB-08 for comparison to previous GW gauging and
sampling results. LSB-07 was not sampled due to the presence of the free product in the well
(0.29'). The groundwater samples were analyzed for NYSDEC petroleum-related VOCs and SVOCs using
USEPA Methods 8260B and 8270C, respectively. Groundwater analytical results from these three wells
reported that VOCs and SVOCs present in detectable concentrations in all three locations. TVOCs
ranged from 839ppb in LBS-01 to 83ppb in LBS-02. Total SVOCs ranged from 839 ugIL in well
LSB-01(GW-01) to 8 ugiL in well LSB-08(GW-08). Free product: At the time of the September 19,2013
groundwater sampling event, a distinct free-product layer (0.29 ft thick) was detected within
GW-07. Free-product was also detected within GW-07 during the March 2013 groundwater sampling
event, but at a thickness of only 0.02 ft. The increasing thickness and unweathered appearance of
the oil suggest a relatively recent release. Based on the February 2013 Soil Vapor and Groundwater
Investigation, TPH fmgerprint analysis of the free-product sample collected from GW-07 indicated
that the free-product signature is characteristic of lubricating oil. There is no on-site source of
lubricating oil. GW data: Current sample results report VOCs at concentrations greater than AWQSGVs
in all three (3) wells. Benzene was the only VOC detected in all three (3) wells at concentrations
above AWQSGVs. Benzene concentrations ranged from 100 ug/L in well LSB-01(GW-01) to 4.6 ug/L in
well LSB-08(GW-08). MTBE was detected in well LSB-08(GW-08) at a concentration of 350 ug/L, which
is above the AWQSGV. Ethylbenzene, Isopropylbenzene, p-Isopropyltoluene, Naphthalene,
n-Propylbenzene, 1,2,4Trimethylbenzene, and 1,3,5-TrimetWybenezen were detected in well
LSB-01(GW-01) at concentrations greater than AWQSGVs. Of these VOCs, the greatest concentration
reported was for Napthalene at 630 ug/L. SVOCs with concentrations above AWQSGVs were reported in
only well LSB-01(GW-01). All detected SVOCS in LSB-02(GW-02) and LSB-08(GW-08) were at
concentrations less than AWQSGVs. SVOCs at concentrations greater than AWQSGVs in LSB-01(GW-01)
include: Acenaphthene, Benzo (a) anthracene, Chrysene, Naphthalene and Phenanthrene. The
contamination observed in the current investigation is qualitatively similar to the results
observed in 2012 with variation in the total concentrations. The current investigation VOC and SVOC
levels were generally higher in LSB-01(GW-01) and lower in LSB-02(GW-02) and LSB-08(GW-08) compared
to the 2012 sample results. Recommendation: Based on the results of the recent and previous

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

groundwater sampling events of the New Long Island City Branch Library monitoring wells, VOCs and SVOCs are present at detectable concentrations at all three well locations. According to LiRo, the presence of MTBE and lubricating oil in the 38th Avenue sidewalk area wells supports theer previous conclusion that contaminant sources unrrelated to the former Site use are evident. There are several large open spill numbers in the immediate area of the site including Spill #9307497 (a 600-gallon release at the adjacent corner 21st Street/38th Avenue) and Spill #9307883 (a 10,000-gallon release approximately 900 feet northwest of the libraly which impacted sewers). The source of the MTBE contamination and lubricating oil in well GW-07 is unknown, however, numerous current and historical filling/services stations are located within the area and the product may have migrated via utility bedding. There is no known on-site source of lubricating oil and the gasoline station use was terminated long before MTBE was introduced as a gasoline additive. The contamination is not a result of the Library activity and the residual contamination is not adversely impacting indoor air quality at the Site. Based on these conditions, LiRo concludes that the City/library are not responsible for the lube oil/MTBE contamination and that no further action by the City/library is warranted for Spill No. 9901712. Will discuss the spill closure request with J. Kolleeny of DEC. AD 04/17/2014: Discussed the site and spill closure request with J. Kolleeny of DEC. There is a concern regarding increase in TVOC levels and free product in some wells. Will look into info regarding possible off-site sources. AD 07/2014: Called and left a message to LiRo regarding the site. 12/2018: called and left a message to LiRo. AD 06/22/22: Called and spoke with Steve Frank of LiRo. He said that they are lo longer managing this site. Asked him for a contact info for RP. AD"

Remarks: "Property assessment was done. Soil tests show contaimination school was built on the site of a former gas station and that may be the cause of the readings "

All Materials:

Site ID:	126573
Operable Unit ID:	1080480
Operable Unit:	01
Material ID:	305243
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil

DDC- (FORMER PS 111) - LIC LIBRARY (Continued) **S103937265**

Oxygenate: Not reported

B12 **NICOSIA SERVICE STATION** **EDR Hist Auto** **1021117836**
SSW **3745 21ST ST** **N/A**
< 1/8 **LONG IS CY, NY 11101**
0.016 mi.
83 ft. **Site 1 of 22 in cluster B**

Relative: EDR Hist Auto
Higher

Actual:
17 ft.

Year:	Name:	Type:
1969	ROYAL SERVICE STATION INC	Gasoline Service Stations
1969	ROYAL SERVICE STATION INC	Gasoline Service Stations
1970	ROYAL SERVICE STATION INC	Gasoline Service Stations
1987	NICOSIA SERVICE STATION	Gasoline Service Stations
1988	NICOSIA SERVICE STATION	Gasoline Service Stations
1989	NICOSIA SERVICE STATION	Gasoline Service Stations
1990	NICOSIA SERVICE STATION	Gasoline Service Stations
1991	NICOSIA SERVICE STATION	Gasoline Service Stations
1992	NICOSIA SERVICE STATION	Gasoline Service Stations
1993	NICOSIA SERVICE STATION	Gasoline Service Stations
1994	NICOSIA SERVICE STATION	Gasoline Service Stations
1995	NICOSIA SERVICE STATION	Gasoline Service Stations
1996	NICOSIA SERVICE STATION	Gasoline Service Stations
1997	NICOSIA SERVICE STATION	Gasoline Service Stations
1998	NICOSIA SERVICE STATION	Gasoline Service Stations
1999	NICOSIA SERVICE STATION	Gasoline Service Stations
2000	NICOSIA SERVICE STATION	Gasoline Service Stations
2001	NICOSIA SERVICE STATION	Gasoline Service Stations
2002	NICOSIA SERVICE STATION	Gasoline Service Stations
2003	NICOSIA SERVICE STATION	Gasoline Service Stations
2004	NICOSIA SERVICE STATION	Gasoline Service Stations
2005	NICOSIA SERVICE STATION	Gasoline Service Stations
2005	STA AUTO CENTER INC	General Automotive Repair Shops
2006	NICOSIA SERVICE STATION	Gasoline Service Stations
2006	STA AUTO CENTER INC	General Automotive Repair Shops
2007	NICOSIA SERVICE STATION	Gasoline Service Stations
2007	STA AUTO CENTER INC	General Automotive Repair Shops
2008	STA AUTO CENTER INC	General Automotive Repair Shops
2008	NICOSIA SERVICE STATION	Gasoline Service Stations
2009	NICOSIA SERVICE STATION	Gasoline Service Stations
2010	NICOSIA SERVICE STATION	Gasoline Service Stations
2011	NICOSIA SERVICE STATION	Gasoline Service Stations
2012	NICOSIA SERVICE STATION	Gasoline Service Stations
2013	NICOSIA SERVICE STATION	Gasoline Service Stations
2014	NICOSIA SERVICE STATION	Gasoline Service Stations

B13 **MICOSIA SERVICE CENTER** **RCRA NonGen / NLR** **1004760905**
SSW **37-45 21ST ST** **US AIRS** **NYR000064501**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.016 mi.
83 ft. **Site 2 of 22 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Micosia Service Center
Handler Address:	37-45 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000064501
Contact Name:	JON HALPERIN
Contact Address:	21ST ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	516-546-8414
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	21ST ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Lakatamia Realty Corp
Owner Type:	Private
Operator Name:	Lakatamia Realty Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

MICOSIA SERVICE CENTER (Continued) **1004760905**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: LAKATAMIA REALTY CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-45 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-729-9850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: LAKATAMIA REALTY CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-45 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-729-9850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: LAKATAMIA REALTY CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	37-45 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-729-9850
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

MICOSIA SERVICE CENTER (Continued) **1004760905**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: MICOSIA SERVICE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MICOSIA SERVICE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19981210
Handler Name: MICOSIA SERVICE CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1004760905
Region Code: 02

MICOSIA SERVICE CENTER (Continued) **1004760905**

Programmatic ID:	AIR NY0000002630400220
Facility Registry ID:	110004549524
D and B Number:	Not reported
Primary SIC Code:	5541
NAICS Code:	999999
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002630400220
Facility Registry ID:	110004549524
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-01-01 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

A14 **LE CLAIRE VALET SERVICE INC** **EDR Hist Cleaner** **1020025751**
North **19-44 37TH ST** **N/A**
< 1/8 **LONG IS CY, NY 11101**
0.018 mi.
96 ft. **Site 12 of 20 in cluster A**

Relative: EDR Hist Cleaner
Lower

Actual:
16 ft.

Year:	Name:	Type:
1974	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1975	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1976	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1977	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1978	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1979	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1980	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1982	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs
1983	LE CLAIRE VALET SERVICE INC	Drycleaning Plants, Except Rugs

---

A15 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241072**
NNE **37 AVE & 21ST ST** **N/A**
< 1/8 **QUEENS, NY**
0.019 mi.
98 ft. **Site 13 of 20 in cluster A**

Relative: NY MANIFEST:
Higher

Actual:
17 ft.

Name:	CONSOLIDATED EDISON
Address:	37 AVE & 21ST ST
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004094165
Facility Status:	Not reported
Location Address 1:	37 AVE & 21ST ST

CONSOLIDATED EDISON (Continued) **1009241072**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004094165
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

A16 **NYC DEP HAZ MAT** **NY MANIFEST** **1009235749**
NNE **21ST ST & 37TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11105**
0.019 mi.
98 ft. **Site 14 of 20 in cluster A**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:
Name: NYC DEP HAZ MAT
Address: 21ST ST & 37TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11105
Country: USA
EPA ID: NYP003662350
Facility Status: Not reported
Location Address 1: 21ST ST & 37TH AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND CITY
Location State: NY
Location Zip: 11105
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP003662350
Mailing Name: NYC DEP HAZ MAT
Mailing Contact: JEAN SAINT
Mailing Address 1: 21ST ST & 37TH AVE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11105
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: N/S

B17 **BROTHERS AUTO REPAIR** **NY Spills** **S121984634**
South **21-15 38 AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.020 mi.
106 ft. **Site 3 of 22 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	BROTHERS AUTO REPAIR
Address:	21-15 38 AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1800085 / 2018-04-11
Facility ID:	1800085
Facility Type:	ER
DER Facility ID:	521870
Site ID:	568566
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2018-04-04
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2018-04-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2018-04-04
Spill Record Last Update:	2018-04-11
Spiller Name:	Not reported
Spiller Company:	BROTHERS AUTO REPAIR
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	FRANK
DEC Memo:	"4/4/18- DEC Piper- Spoke WIth Frank Galdun of Merritt. Phase II due to refi. Frank will submit to DEC Patel. DEC Lin was responder for day. 04/09/18-Hiralkumar Patel. 12:28 PM:- received email from Maryann Wegh from Merritt Eng. including Phase II report. summary: - the site is located in an area that historically (and currently) has been used for industrial and vehicle repair purposes (gas station, auto repair facilities, car dealer, substation) - site contains a single-story 17,500 sq. ft. building used for vehicle repairs and painting - two small partial basements are present beneath the site building - estimated construction date of the southern section of the site building was constructed in 1943 (approx. one-half of the current structure). northern section of the building was formerly an open vehicle paring yard that was enclosed within roughly the past five years - one inactive heating oil fill port located in the 22nd St

BROTHERS AUTO REPAIR (Continued) **S121984634**

sidewalk adjacent to one of
the small partial basements - noted storage tank petrometer gauge affixed to the wall of the
basement - historical city directories reviewed identify an apparent former gasoline station at the
site, but this information was not confirmed by other reviewed sources of historical information or
by regulatory agency databases - numerous hydraulic lifts were formerly present within the southern
half of the site, but as per site representative, these lifts were equipped with aboveground fluid
reservoirs - observed two steel plates on the floor in the southern section of the site building,
are floor drains that appear to be connected to the local sewer system - site elevation is approx.
20 ft above mean sea level - historical maps of Long Island City shows that the site is located at
(or in close proximity of) the head of a former stream known as Sunswick Creek which flowed from
southeast to northwest, emptying into the East River and tidal fluctuation was present
---------- - installed four soil borings (B1 through B4) in building interior, to a maximum
depth of 15 ft bg - water table was encountered at depths ranging from 11.2 ft to 11.9 ft bg -
highest PID reading recorded was 14 ppm in sample collected from 6 ft bg in boring B1 - fill
material, consisting of sand, clinker, crushed brick and rock fragments was identified to
termination depth at all borings - four soil samples were collected for analysis - physical
evidence of petroleum impact was observed on groundwater at one sampling location B2 in the form of
a slight sheen and slight to moderate petroleum odors - groundwater samples were collected from all
borings by inserting 1-in dia. well screen to a depth of 15 ft bg - no contamination noted in
samples, except 110 ppb Naphthalene in groundwater sample from boring B3 Maryann Wegh Merritt
Environmental Consulting Corp. Ph. (631) 617-6200 Fax (631) 617-6201 email: mwegh@merrittec.com
04/11/18-Hiralkumar Patel. 3:23 PM:- spoke with Maryann. she mentioned that Phase I and Phase II
investigations were conducted as part of refinance and there is no planned redevelopment. informed
her that no further investigation is needed and case is closed based on review of all available
information (soil/gw sample results, site's location in an industrial area, and no planned
redevelopment). case closed."

Remarks: "contamination based on lab results"

All Materials:
Site ID: 568566
Operable Unit ID: 1316443
Operable Unit: 01
Material ID: 2324192
Material Code: 0066A

BROTHERS AUTO REPAIR (Continued) **S121984634**

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Groundwater
Oxygenate:	Not reported

B18 **TONYS TOWING SERVICE INC** **EDR Hist Auto** **1020609185**
South **2115 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.020 mi.
106 ft. **Site 4 of 22 in cluster B**

Relative: EDR Hist Auto
Higher

Actual:
17 ft.

Year:	Name:	Type:
2006	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2006	SALAMIS	Gasoline Service Stations
2007	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2008	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2009	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2010	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2011	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2012	SALAMIS SERVICE STATION INC	General Automotive Repair Shops
2013	SALAMIS SERVICE STATION INC	General Automotive Repair Shops

---

B19 **VAULT 0763** **NY Spills** **S106736625**
South **42-32 22ND ST** **N/A**
< 1/8 **QUEENS, NY**
0.023 mi.
119 ft. **Site 5 of 22 in cluster B**

Relative: SPILLS:
Higher

Actual:
18 ft.

Name:	VAULT 0763
Address:	42-32 22ND ST
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0410911 / 2005-06-03
Facility ID:	0410911
Facility Type:	ER
DER Facility ID:	271320
Site ID:	335996
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2005-01-05
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2005-01-06
CID:	74
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party

VAULT 0763 (Continued) **S106736625**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-07
Spill Record Last Update:	2005-06-03
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	40 ELDRIDGE AV
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis 156789 1/05/2005 13:20 HRS. R. SEIDLER #54605, SR. FIELD OPERATOR WITH F.O.D., REPORTS AT 13:00 HRS. FOUND APPROX. 1 GAL. UNKNOWN OIL ON CONCRETE FLOOR OF VS-0763 (1Q06). NO WATER IN STRUCTURE. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. ENV STOP TAG #40744 PLACED. SEIDLER USED HOCKEY PUCK AND FOUND OIL LEVEL BELOW MINIMUM. F.O.D. O/G/S B.WHITE REPORTS EQUIPMENT GROUP WAS NOTIFIED AND IS RESPONDING. DUE TO OIL LEVEL BELOW MIN., OIL SAMPLE AND PRESSURE TEST CANNOT BE DONE UNTIL FEEDER IS OFF. CLEANUP PENDING PRESSURE TEST AND PCB RESULTS. ** TRANSFORMER INFORMATION FROM E.C.C. WAREHOUSE: ** Serial ID: C376947, MFG Code: GE, KVA: 500, Install Date: 01/01/1956, Mfr Date: 07/01/1956. ** HISTORICAL PCB RESULTS: SAMPLE DATE 05/10/1993, 37 PPM, LAB SEQ # 930264. UPDATE 05-JAN-2004 14:40 HRS. BQE DEPT. O.S. G.ROSADO EMP# 83708 REPORTS: ON LOCATION AND CONFIRMED UNIT IS BELOW MIN. UNIT CANNOT BE PRESSURE TESTED AT THIS TIME DUE TO EQUIPMENT IS STILL ENERGIZED AND BELOW MIN. 1/05/2005 18:53 -- PCB RESULTS: 33 PPM, AROCLOR 1260, LAB SEQ # 05-00119. -- W.W. #17344 1/05/2005 19:30 HRS. -- TRANSFORMER SCHEDULED FOR REPLACEMENT, BUT HAS NOT YET BEEN PRESSURE TESTED. AS PER FEEDER CONTROL REP C. MONTANA, THERE ARE NO EQUIPMENT GROUP CREWS AVAILABLE UNTIL TOMORROW MORNING. AS PER ENV DESK SUPERVISOR E. VESCE, CURRENT PLAN IS TO HAVE UNIT PRESSURE TESTED IN MORNING AND THE INCIDENT WILL REMAIN ON 24-HOUR DEMINIMIS AT THIS TIME. UPDATE: 1/6/04 - 0915 J. GRANT - BQE, REPORTS UNIT FAILED PRESSURE TEST. TRANSFORMER WAS DIPPED AND 18 GALS WAS FOUND MISSING (NOT SEEN IN VAULT). DRAINING OF UNIT TO COMMENCE. UPDATE: 1/6/05 - 1030 J. GRANT - BQE, REPORTS 287 GALS OF DIELECTRIC FLUID REMOVED FROM TRANSF BY ASTORIA TANKER. PLATE READS 295 GALS. UPDATE: 1/6/05 - 1110 M. KNOX - ENV. OPS., REPORTS TRANSFORMER IS NOT EVEN CUT YET. THERE IS NO WAY POSSIBLE TO HAVE THIS CLEANUP COMPLETED BY 1300. THIS INCIDENT, THEREFORE, IS NOW OFF THE 24 HR CLOCK. 1/6/05 1430 HRS T.VALLONE ENVIR OPPS REPORTS WHILE CLEANUING VS-0763. FOUND EARTHEN SUMP IN STRUCTURE. CLEANUP CONTINUES. 1/6/05 1535HRS T.VALLONE ENVIR OPPS

VAULT 0763 (Continued) **S106736625**

REPORTS CLEANUP COMPLETED DOULBED WASHED STRUCTURCTURE USING BIO-GEN 760.CEMENTED EARTHEN
SUMP.TRANSF CREW REMOVED AND INSTALLED NEW UNIT.REMOVED ENVIR TAG#40744."

Remarks: "Con Ed needs to de-energize the feeder/transformer. Will be cleaning up. No smoke fire sewers or waterways. Transformer will be replaced. Ref. 156789 "

All Materials:

Site ID:	335996
Operable Unit ID:	1098044
Operable Unit:	01
Material ID:	578234
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B20 **DELANE RESIDENCE** **NY Spills** **S111239201**
SSW **21-70 38TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
180 ft. **Site 6 of 22 in cluster B**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	DELANE RESIDENCE
Address:	21-70 38TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1108053 / 2011-10-11
Facility ID:	1108053
Facility Type:	ER
DER Facility ID:	410336
Site ID:	455767
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2011-09-23
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2011-09-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-23

DELANE RESIDENCE (Continued) **S111239201**

Spill Record Last Update:	2011-10-11
Spiller Name:	CHARLES DELANE
Spiller Company:	HOMEOWNER
Spiller Address:	21-70 38TH ST
Spiller Company:	999
Contact Name:	CHARLES DELANE
DEC Memo:	"09/23/11-Hiralkumar Patel. DEC Veronica went for inspection. 09/23/11- Zhune inspected the site and found no visual evidence of oil contamination. thank was not dripping. No stain and no smell. Spill closed."
Remarks:	"tank wet on bottom - customer refuse pumpout - tank enclosed inside the basement -"

All Materials:

Site ID:	455767
Operable Unit ID:	1205918
Operable Unit:	01
Material ID:	2202898
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

B21 **NYNEX** **NY MANIFEST** **1009233586**
SW **21ST ST & 38TH AVE** **N/A**
< 1/8 **QUEENS, NY**
0.034 mi.
180 ft. **Site 7 of 22 in cluster B**

Relative: Higher
Actual: 17 ft.

NY MANIFEST:

Name:	NYNEX
Address:	21ST ST & 38TH AVE
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP000917450
Facility Status:	Not reported
Location Address 1:	21ST ST & 38TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000917450
Mailing Name:	NYNEX
Mailing Contact:	STEVE HUDAK
Mailing Address 1:	221 E 37TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

NYNEX (Continued) **1009233586**

Mailing State:	NY
Mailing Zip:	10016
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2123387126

B22 **FEEDER 31281** **NY Spills** **S102147027**
SW **21ST ST & 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
180 ft. **Site 8 of 22 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	FEEDER 31281
Address:	21ST ST & 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9307497 / 2018-12-07
Facility ID:	9307497
Facility Type:	ER
DER Facility ID:	357888
Site ID:	71925
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1993-09-21
Investigator:	RCARNOLD
Referred To:	SIR COMMENT LETTER
Reported to Dept:	1993-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-22
Spill Record Last Update:	2018-12-07
Spiller Name:	Not reported
Spiller Company:	CON-ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL APPENDIX BE SITE NO. 4. TRANSFERRED FROM ENGELHARDT TO O'CONNELL. 9/21/93: Mr. Giangrande (Con Ed UT) - feeder is out of service. Pressure has been reduced from 240 psi to 80 psi. Will use freeze and pressurizzation technique starting tomorrow to isolate leak. (CAE) 9/29/93: Mr. Giangrande - leak at 21st st & 38th Ave. Soil excavated and removed. Leak clamped. (CAE) 1/28/13 - review of the spill investigation conducted as part of Appendix B Site 4 will be included in the

FEEDER 31281 (Continued) **S102147027**

Department's response comments on
the site investigation report. (JOC) 6/25/14 - This spill is included
in Appendix B Site 4 as spill
4-6. Investigation activities at this site were conducted under the
Site 79 SIWP. The scope for
Site 79 SIWP included spills that were in all of the Appendix B sites
that were in the larger Long
Island City area in Queens, includings Site 1 (18 spills), Site 4 (16
spills), Site 26 (6 spills),
Site 40 (1 spill) and Site 79 (28 spills). The investigation
activities for this spill were
reported on in the Site 4 Site Investigation Report (while the SIWP
was combined, reporting for the
sites was done separately). The Department sent a comment letter on
the Site 4 SIR , to which Con
Edison's consultant CDM Smith responded. The Department reviewed this
letter from CDM Smith
(5/1/14) and responded in a letter (6/23/14). This spill was reported
to the Department at the time
it was determined that there was a feeder leak ongoing with an initial
estimate of 600 gallons
released at that point. The leak location was identified in Con Edison
documents as on 21st Street
60 feet north of the northern curb of 39th Avenue, and the total
volume spills as 3000 gallons. The
Department had questions about location investigated as reported in
the SIR, which included
locations north of 38th Avenue. Con Edison conducted additional
investigation in the same area
north of 38th Avenue. Based on the information available, additional
investigation is warranted in
the area of the spill as described in the historic documentation.
(JOC) 10/26/2016 - V. Brevdo Due
to Project Manager Joe O'Connell's promotion to the DMM, and per
discussions between Chiefs of
Spill Prevention and Response and Remediation Section B, this spill
case is re-assigned to
Remediation Section B. VB 1/20/2017 Spill transferred to R. Arnold
06/22/17: Reviewed May 2017 Site
Investigation Work Plan for Appendix B Site 4 spills by CDM Smith (in
DecDocs under spill number
8710979). The 2005 work plan did not correctly locate the borings for
the investigation. The
current SIWP proposes drilling one boring/well down gradient of the
documented leak location along
feeder 31281M, 60 feet north of 39th Avenue. The plan states that if
soil sample results exceed the
applicable cleanup criteria for dielectric fluids, a groundwater
sample will be collected at that
location and analyzed for TPH. I sent a letter to Mr. Mao of Con
Edison approving the work plan,
but requiring collection of a groundwater sample if any dielectric
fluid impacts to soil are
identified. Rachel Arnold 12/7/2018 - Reviewed Con Edison s 8/11/2018
closure request. The
dielectric fluid released at the spill site was Sun #6 mineral oil. A
site investigation was

FEEDER 31281 (Continued) **S102147027**

performed at the spill site between 6/24/2017 and 8/22/2017, in accordance with the approved May 2017 Site Investigation Work Plan (SIWP). One boring was advanced, two soil samples were collected, and a temporary monitoring well was installed. Screening of the soil showed no field evidence (PID readings, odors, sheen or staining) of residual dielectric fluid. TPH was detected in the soil sample collected just above the water table at 25.7 mg/kg, below the 7,400 mg/kg cleanup criterion for mineral oils. No LNAPL was detected in the temporary well. As per the May 2017 SIWP, no groundwater sample was collected due to the absence of field evidence of dielectric fluid and the absence of LNAPL in the temporary well. Based on the investigation results, Con Ed recommended spill closure. I closed the spill and sent a spill closure letter to Libin Mao and Neil O Halloran of Con Edison on 12/7/2018. Con Ed s closure request and my spill closure letter have been uploaded to DecDocs. R. Arnold "

Remarks: "ARE CHECKING MANHOLE TO DETERMINE LEAK AREA ~80 GAL PER HOUR - WILL REMOVE LINE FROM SERVICE - NO WATER OR SEWERS INVOLVED AS YET."

All Materials:

Site ID:	71925
Operable Unit ID:	986088
Operable Unit:	01
Material ID:	393760
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	600.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B23 **FEEDER 21ST ST & 38TH AVE** **NY Spills** **S127480355**
SW **21ST ST & 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
180 ft. **Site 9 of 22 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	FEEDER 21ST ST & 38TH AVE
Address:	21ST ST & 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	2009869 / 2021-05-05
Facility ID:	2009869
Facility Type:	ER
DER Facility ID:	357888
Site ID:	616886
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

SWIS:	4101
Spill Date:	2021-03-06
Investigator:	EJKIM
Referred To:	Not reported
Reported to Dept:	2021-03-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2021-03-06
Spill Record Last Update:	2021-05-05
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE BECKER
DEC Memo:	"3/9/21-Lin- Dielectric Fluid Leak Committee Conference Call, March 9, 2021 @ 14:00 The leak on Feeder 31281 L was TERMINATED on 3/9/2021@03:16 when a clamp was successfully placed onto the feeder pipe in an excavation under bar hole 6S, located 51 feet n/o north curb of 39th Avenue and 21st Street, Queens. As of March 9, 2021@10:52, the total loss on feeder 31281 L is 4,261 gallons. EMIS 279225 has been updated for this incident. There will be no additional Leak Committee conference calls associated with this incident. Dielectric Fluid Leak Committee Conference Call, March 9, 2021 @ 07:00 Feeder 31281 L was taken out of service OOE on 3/9/2021@00:53 due to failure to maintain oil pressure. The leak on Feeder 31281 L was TERMINATED on 3/9/2021@03:16 when a clamp was successfully placed onto the feeder pipe in an excavation under bar hole 6S, located 51 feet n/o north curb of 39th Avenue and 21st Street, Queens. The estimated dielectric fluid loss as of midnight is 1,778 and will be updated for the next DFLC conference call. The feeder pipe is resting on bedrock and thus jackhammering will be necessary to provide space to place the final repair barrel. A Feeder Restoration Plan is in place and will be executed after Pothead inspections are completed. EMIS 279225 has been updated for this incident. Safety Message: Operate as a team and identify the procedures and PPE associated with the task. Maintain a high level of focus when conducting all tasks. Utilize defensive driving techniques on all roadways. Maintain a questioning attitude as conditions change. Be aware of pedestrian and vehicular traffic when setting up cones, stanchions and advanced warning signs. Maintain Social Distancing and

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

use approved facial
coverings. The next Leak Committee conference call will be March 9, 2021 at 14:00.

_ Dielectric Fluid Leak Committee Conference Call, March 8, 2021 @ 20:00 The estimated dielectric
fluid loss is 1,650 gallons with an estimated leak rate of 29 gallons per hour. Chem Lab PFT van
had high indications at bar hole 6 south and at 18:45 an excavation was requested located at 51
feet n/o north curb of 39th Avenue and 21st Street, Queens. Currently the excavation is 4 feet deep
and oil has been reported. Further excavation work will continue to expose the feeder. A total of
2,650 gallons of dielectric fluid are in the tanker ready for delivery and will be completed on the
overnight to Queens Bridge, Vernon, and Brownsville Substations and any leftover will be
transported back to Astoria. ChemLab PFT van will be available to sample end walls of excavation
and any additional bar holes if needed. EMIS 279225 has been updated for this incident. Safety
Message: Ensure proper lighting is utilized on the overnight. Keep members of the public away from
work areas. Utilize flaggers as needed and ensure they are fully engaged. Report any changes in
work area. Ensure drivers remain fully engaged and passengers are used as spotters. The next Leak
Committee conference call will be March 9, 2021 at 07:00.

_ Dielectric Fluid Leak Committee Conference Call, March 8, 2021 @ 14:00 The estimated dielectric
fluid loss is 1455 gallons with an estimated leak rate of 29 gallons per hour. The 20 foot long
excavation under bar holes 26 and 27 on 21st Street has been backfilled, concreted and protected.
The oil absorbent pads that were installed in the sewer manhole located on 21st Street and 39th
Avenue show no signs of oil but there is still significant PFT in the ambient air. The ChemLab has
requested bar holes on 21st Street, 5 to the north of the sewer manhole and 1 to the south. ChemLab
Van crew will bag sample by mid-afternoon. The contractor will remain on site to support the
ChemLab PFT crew findings. The ChemLab PFT van will plan and staff for continuous patrol through
the midnight shift and a TO crew will be scheduled to support it round the clock. Oil deliveries to
substations Vernon, Queens Bridge and Brownsville are in process. PFT Tech will be scheduled to be
patrolling tomorrow on a priority basis determined by the ChemLab van findings. EMIS 279225 has
been updated for this incident. Safety Message: Maintain a high level of focus and Situational
Awareness at all times and eliminate distractions. Use cones,

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

stanchions and flaggers to keep
pedestrians and vehicles away from our work areas. Utilize adequate lighting and signage to warn
vehicular traffic and pedestrians of the work area. Maintain Social Distancing and use approved
facial coverings. The next Leak Committee conference call will be March 8, 2021 at 20:00.

_ Dielectric Fluid Leak Committee Conference Call, March 8, 2021 @ 07:00 The estimated dielectric
fluid loss is 1242 gallons with an estimated leak rate of 28 gallons per hour. TO crews and ChemLab
conducted subsurface inspections and discovered oil flowing through a DEP sewer manhole on 21st
Street 150 feet south of 38th Avenue, Queens. Bar holes were installed and the highest PFT count
was at bar hole 27 which initiated an excavation to expose the feeder. On March 7 @ 17:30 an
excavation was made at bar hole 27 (on 21st Street, 150 ft south of 38th Avenue) and no sign of oil
was found. End wall sampling results under bar hole 27 extended the excavation another 10 feet East
under bar hole 26 resulting in a total 20 foot long excavation. End wall sampling was conducted
again and no actionable PFT was found. The ChemLab PFT van completed a full patrol of the feeder
with indications found only in the 21st Street and 38th Avenue location and up to 23rd Street and
39th Avenue. Pads were installed in the sewer manhole located on 21st Street and 39th Avenue which
will be checked this morning. Crews will also plasticize all subsurface structures in the area to
force PFT to remain and emanate from the location of the leak. ChemLab stated that the feeder is
under a thick concrete layer (18) thus diminishing the PFT readings. Bar hole 27 penetrated into
dirt but all other bar holes need to be confirmed to have penetrated the concrete layer. Contractor
is to refresh all barholes and confirm that the concrete layer has been penetrated. ChemLab will
conduct additional bag sampling after refresh is completed. Oil deliveries to substations Vernon,
Queens Bridge and Brownsville are in process. EMIS 279225 has been updated for this incident.
Safety Message: Maintain a high level of focus and Situational Awareness at all times and eliminate
distractions. Check that vehicle alarms and warning lights are operating correctly. Use cones,
stanchions and flaggers to keep pedestrians and vehicles away from our work areas. Communicate with
spotters/flaggers to eliminate blind spots. Maintain Social Distancing and use approved facial
coverings. The next Leak Committee conference call will be March 8, 2021 at 14:00.

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

_ Dielectric Fluid Leak Committee Conference Call, March 7, 2021 @ 20:00 The estimated dielectric fluid loss is 925 gallons with an estimated leak rate of 28 gallons per hour. TO crews and ChemLab conducted subsurface inspections and discovered oil flowing through a DEP sewer manhole on 21st Street 150 feet south of 38th Avenue, Queens. Bar holes were installed and the highest PFT count was at bar hole 27 which initiated an excavation to expose the feeder. Ken s Marine was requested as a precaution due to proximity to East River; five passes were made and four outfalls were checked with no oil observations; feeder oil in sewer should be going to treatment facility. The ChemLab PFT van crew will remain on site to assist Transmission Ops crews and the contractor on site excavating. There was 800 gallons of feeder oil delivered to Queens Bridge Substation today bringing the tank up to 1,035 gallons. All agencies were updated on the sewer impact. EMIS 279225 has been updated for this incident. Safety Message: Ensure Work Area Protection is in place and effective for our crews and the public s protection. Ensure stations are around work areas to protect the public. Utilize the 2-Minute HPI Tool to stop and evaluate when conditions or direction of the operation changes. Perform necessary testing prior to and during excavation and subsurface structure entries. Maintain Social Distancing and use approved facial coverings. The next Leak Committee conference call will be March 8, 2021 at 07:00.

_ Dielectric Fluid Leak Committee Conference Call, March 7, 2021 @ 14:00 The estimated dielectric fluid loss is 813 gallons with an estimated leak rate of 28 gallons per hour. The feeder has been requested Out-On-Emergency Category #2 and is Pending Approval. TO crews conducted subsurface inspections last night with no oil found. Fifteen bar holes were installed at intersection of 21st Street & 38th Avenue and bag sample analysis results were clean. Airborne PFT at this intersection remains high and thus TO will work toward staffing another round of subsurface inspections tonight. The ChemLab PFT van will continue to investigate the intersection of 21st Street and 38th Avenue as well as to run the feeder route tonight and on the Midnight shift. There is a 500 gallon oil delivery scheduled at Queens Bridge Substation today. EMIS 279225 has been updated for this incident. Safety Message: Ensure Work Area Protection signage is effective for our crews and the public. Scan equipment and work areas for any signs of potential hazards. Utilize HPI Tools and proper PPE to protect crews. Perform stray voltage testing prior to and after closing subsurface

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

structures. Use continuous monitoring when entering subsurface structures. Use three points of
contact when ascending and descending ladders. Maintain Social Distancing and use approved facial
coverings. The next Leak Committee conference call will be March 7, 2021 at 20:00.

_ Dielectric Fluid Leak Committee Conference Call, March 7, 2021 @ 08:00 The estimated dielectric
fluid loss is 630 gallons with an estimated leak rate of 28 gallons per hour. The feeder has been
requested Out-On-Emergency Category #2 and is Pending Approval. The ChemLab PFT van ran the feeder
and located PFT indications at the intersection of 21st Street & 38th Avenue. The contractor will
install bar holes at this intersection and the ChemLab PFT van will analyze. EMIS 279225 has been
updated for this incident. Safety Message: Ensure Work Area Protection signage is effective for our
crews and the public. Scan equipment and work areas for any signs of potential hazards. Utilize HPI
Tools and proper PPE to protect crews. Perform stray voltage testing prior to and after closing
subsurface structures. Use continuous monitoring when entering subsurface structures. Use three
points of contact when ascending and descending ladders. Maintain Social Distancing and use
approved facial coverings. The next Leak Committee conference call will be March 7, 2021 at 14:00.

_ Dielectric Fluid Leak Committee Conference Call, March 6, 2021 @ 20:00 The estimated dielectric
fluid loss is 320 gallons with an estimated leak rate of 28 gallons per hour. The subsurface
structures on the feeder run were inspected by Transmission Operations crews with the exception of
MH 22366 (Freeze pit location) which will be pumped down to remove the water for inspection; all
structures were negative for oil observances. The Vernon and Queens Bridge Substations (pump houses
and pot heads) were inspected and negative for oil observances. The feeder has been requested
Out-On-Emergency Category #2. The ChemLab PFT van ran the feeder and had no PFT indications except
near the freeze pit on 14th Street by MH 22366. Transmission Operations crews will inspect all
subsurface structures within the area of MH 22366 and ChemLab PFT van will perform stop and sits
near this manhole. Construction contractor will be available if bar holes are requested. EMIS
279225 has been updated for this incident. Safety Message: Ensure employees are fully engaged in
their tasks to eliminate distractions and that they communicate openly. Utilize proper Work Area
Protection and safety vests while performing work in the roadways.

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

Utilize HPI Tools appropriate to
the situation at hand to ensure everyone is in sync with the operation being performed. Wear
approved facial coverings, maintain social distancing and wear appropriate PPE. The next Leak
Committee conference call will be March 7, 2021 at 08:00.

_ Dielectric Fluid Leak Committee Conference Call, March 6, 2021 @ 16:30 The Dielectric Fluid Leak
Committee declared a Leak Declared on March 6, 2021 at 16:36 on 138 kV Feeder 31281L based on a 220
gallon tank level loss at Vernon Substation pump house #3 and a rapid psi drop during a drop check.
The estimated dielectric fluid loss is 220 gallons with an estimated leak rate of 40 gallons per
hour. The subsurface structures on the feeder run will be inspected. The Vernon and Queens Bridge
Substations will be inspected. The feeder will be requested Out-On-Emergency Category #2. The
ChemLab PFT van and Transmission Operations crews will be pulled from feeder 38M12/14 to inspect
the subsurface structures and feeder run on this feeder. EMIS 279225 has been created for this
incident and appropriate agencies have been notified. Safety Message: Ensure employees are fully
engaged in their tasks to eliminate distractions and that they communicate openly. Utilize proper
Work Area Protection when checking subsurface structures. Use defensive driving techniques while
operating the vehicles during feeder search activities. Adjust vehicle speed to pedestrian and
vehicle traffic conditions and drive defensively. Wear approved facial coverings, maintain social
distancing and wear appropriate PPE. The next Leak Committee conference call will be March 6, 2021
at 20:00. 3/10/21 - Kim - On 3/6/21, the Con Ed Dielectric Fluid Leak Committee reported a Leak
Declared on 138 kV Feeder 31281L based on a 220 gallon tank level loss at Vernon Substation pump
house #3 and a rapid pressure drop. Con Ed inspected subsurface structures on the feeder run and
the Vernon and Queens Bridge Substations. Feeder 31281L was taken out of service on 3/9/21 due to
the failure to maintain oil pressure. Con Ed found the feeder leak and successfully terminated the
leak on 3/9/21 when a clamp was successfully placed onto the feeder pipe in an excavation located
at 39th Ave and 21st St, Queens. As of 3/9/21, the total loss from the feeder leak was estimated to
be 4,261 gallons. On 3/9/21, I visited the excavation site and confirmed that the feeder pipe had
been successfully clamped. The feeder pipe is resting on bedrock and further excavation and
jackhammering will be required to provide access for the installation of the final repair barrel.
5/5/21 - Kim - I received a copy of Con Ed report on Remediation of

FEEDER 21ST ST & 38TH AVE (Continued) **S127480355**

21st Street and 38th Avenue
345Kv Feeder 31281L Queens, NY and accompanying EMIS 279225. Con Ed reported that impacted soils
were removed from the area surrounding the leak location and 5 post-excavation soil samples (four
sidewalls and floor) were collected from the excavation (EX-1) and analyzed for total petroleum
hydrocarbon (TPH) using EPA 8015 method. 3/15/21, Ex - 1 North Wall: 127 PPM TPH 4/13/21, Ex - 1
South Wall: <10.2 PPM TPH 3/15/21, Ex - 1 East Wall: 40.8 PPM TPH 3/15/21, Ex - 1 West Wall: 4,540
PPM TPH 3/15/21, Floor: 11,400 PPM TPH Based on the lab analysis results of the post-excavation
soil samples, this spill case is closed."

Remarks: "4.0 gph. leak search is ongoing."

All Materials:

Site ID:	616886
Operable Unit ID:	1364018
Operable Unit:	01
Material ID:	2376388
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	220.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

B24 **FEEDER # 31281** **NY Spills** **S102148179**
SW **21ST ST & 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
180 ft. **Site 10 of 22 in cluster B**

Relative: Higher
Actual: 17 ft.

SPILLS:

Name:	FEEDER # 31281
Address:	21ST ST & 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9401387 / 2019-09-26
Facility ID:	9401387
Facility Type:	ER
DER Facility ID:	357888
Site ID:	71926
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1994-04-28
Investigator:	RCARNOLD
Referred To:	CLOSED TO CONSOLIDATE WITH SP 9408172
Reported to Dept:	1994-04-28
CID:	Not reported
Water Affected:	RATE OF CALL
Spill Source:	Commercial/Industrial

FEEDER # 31281 (Continued) **S102148179**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-03
Spill Record Last Update:	2019-10-25
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL APPENDIX B SITE NO. 4. TRANSFERRED FROM ENGELHARDT TO O'CONNELL. 4/28/94: John Hegerty - just repaired M-leg leak last week, still have Tracer gas in line. Will begin gas sniffing tomorrow. (CAE) 4/29/94, 3:38 PM: Nothing in manholes. Picking up gas from M-leg leak. Also picking up gas from feeder 62 whihc is a 1/2 block away. (CAE) 5/4/94: injecting additional Tracer gas - should be done tonight. Feeder still leaking at 2.5 to 3 gph. (CAE) 5/10/94: Still have not found leak. If Tracer does not work within a day, they will do freeze pits. They are getting a lot of interference of Tracer gas from the M-leg spill a couple of weeks ago. (CAE) 9/26/2019 After review of Appendix B Site 4 spills, this spill case is closed to consolidate with spill no. 9408172, which occurred at the same location and is being addressed by the same actions. Further investigation and/or remediation of this spill will continue to be tracked under spill no. 9408172. I sent an email to Neil O Halloran and Libin Mao of Con Edison informing them of this spill closure by consolidation. - R. Arnold 5/24/94, 3:00 PM: John Hegerty - leak located at 21st St/38th Ave. Leak amount about 2000 gallons. Leak was located on 5/19/94. (CAE) 6/17/94: letter from Con Ed (Cheryl Payne) outlining history of spill and providing soil sample results for TCLP Oil & Grease and TCLP TPH. 10/26/2016 - V. Brevdo Due to Project Manager Joe O'Connell's promotion to the DMM, and per discussions between Chiefs of Spill Prevention and Response and Remediation Section B, this spill case is re-assigned to Remediation Section B. VB 12/28/2016 - Spill case re-assigned from V. Brevdo to R. Arnold. 06/22/17: Reviewed May 2017 Site Investigation Work Plan for Appendix B Site 4 spills by CDM Smith (in DecDocs under spill number 8710979). This spill investigation is being combined with the investigation of spill nos. 8912492 (Con Ed spill 4-3), 9403515 (Con Ed spill 4-10) and 9408172 (Con Ed spill 4-11), since these spills all occurred at the same

FEEDER # 31281 (Continued) **S102148179**

intersection. The SIWP proposes
drilling two borings and installing two temporary wells. Further delineation may be necessary based
on the results of the two borings/wells. The plan states that if soil sample results exceed the
applicable cleanup criteria for dielectric fluids, a groundwater sample will be collected at that
location and analyzed for TPH. I sent a letter to Mr. Mao of Con Edison approving the work plan,
but requiring collection of a groundwater sample if any dielectric fluid impacts to soil are
identified at a drilling location. Rachel Arnold 8/15/2018 I reviewed Con Edison s Remedial
Investigation Report and Work Plan (RIRWP), submitted by Libin Mao of Con Edison on 7/18/2018. The
report summarizes a site investigation performed between 6/24/17 and 8/22/17 to determine if
residual dielectric fluid impacts remain in soil and groundwater at the spill site. The
investigation was conducted in accordance with the approved 5/30/17 Site Investigation Work Plan.
Three borings were drilled at the site and temporary monitoring wells were installed. Evidence of
LNAPL was detected in all three wells during installation and sampling. Sun #6 mineral oil was
detected in LNAPL samples at concentrations up to 1,330,000 mg/L, in well 4?7TW01. Petroleum
hydrocarbons were detected at TPH concentrations of 13,400, 12,500, and 15,400 mg/kg in the soil
samples, exceeding the DEC cleanup criterion of 7,400 mg/kg for mineral-oil-based dielectric
fluids. To further delineate the spill impacts, the work plan recommends installing six more
temporary monitoring wells. Based on observations during installation, locations will be chosen for
installation of three 4-inch recovery wells. If LNAPL is not identified in the delineation wells,
the recovery wells will be installed at the previous well locations where LNAPL was found. As a
contingency, supplemental borings and/or wells may be installed to further delineate the extent of
the dielectric fluid impacts. I sent a letter approving the work plan to Libin Mao and Neil O
Halloran of Con Edison on 8/15/2018. Con Ed s RIRWP and my approval letter have both been uploaded
to DecDocs. R. Arnold 6/20/2019 - On 4/24/2019 Con Ed submitted a Remedial Investigation Letter
Report. The report summarized a remedial investigation performed between 10/22/2018 and 11/21/2018
to delineate residual dielectric fluid impacts at the site. The investigation involved advancement
of eight soil borings, installation of eight temporary monitoring wells, and installation of four
permanent recovery wells at locations where LNAPL was detected in this and earlier investigations.
Eleven soil samples and two LNAPL samples were collected. Six of the soil samples had TPH detected

FEEDER # 31281 (Continued) **S102148179**

at levels above the 7,400 mg/kg criterion; two of these samples and one of the LNAPL samples were identified as Sun #6 Cable Oil; the other LNAPL sample was Sun #6 Cable Oil mixed with other petroleum products. On 1/22/19, the four recovery wells were gauged and a VEFR event was performed, recovering 30-100 gallons of oil/water mixture from each well. On 2/5/19, the recovery wells were gauged to evaluate LNAPL recharge into the wells; no LNAPL was detected in well 4-3RW-01, 0.01 ft of viscous yellow LNAPL was detected in well 4-3RW-02, viscous yellow LNAPL was detected in well 4-3RW-03 but could not be measured; and well 4-3RW-04 had 4.56 ft of LNAPL. On 2/19/19, the recovery wells were gauged and absorbent socks were installed. On 3/5/19 and 3/19/19, the wells were gauged and the absorbent socks were replaced. The report included an Interim Remedial Measure (IRM) Plan which proposed that monthly product recovery events continue until a decrease in LNAPL is observed on the oil-absorbent socks in the affected wells. If there is no reduction in LNAPL after three months, a VEFR event will be scheduled. One month following the VEFR event, water level elevations and LNAPL measurements will be taken at each well. On 6/20/2019, I sent a letter approving the IRM Plan to Libin Mao and Neil O Halloran of Con Edison. The Remedial Investigation Letter Report and my approval letter have been uploaded to DecDocs. R. Arnold 9/26/2019 After review of Appendix B Site 4 spills, this spill case is closed to consolidate with spill no. 9408172, which occurred at the same location and is being addressed by the same actions. Further investigation and/or remediation of this spill will continue to be tracked under spill no. 9408172. I sent an email to Neil O Halloran and Libin Mao of Con Edison informing them of this spill closure by consolidation. - R. Arnold"

Remarks: "TO INVEST FURTHER."

All Materials:

Site ID:	71926
Operable Unit ID:	995168
Operable Unit:	01
Material ID:	385144
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	265.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B25
SW
< 1/8
0.034 mi.
181 ft.

21ST ST & 38TH AVE
21ST ST & 38TH AVE
QUEENS, NY

Site 11 of 22 in cluster B

NY Spills **S103483461**
N/A

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	21ST ST & 38TH AVE
Address:	21ST ST & 38TH AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	8912492 / Not Reported
Facility ID:	8912492
Facility Type:	ER
DER Facility ID:	67976
Site ID:	71924
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1989-05-18
Investigator:	RCARNOLD
Referred To:	Not reported
Reported to Dept:	1995-05-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	Not reported
Spill Record Last Update:	2022-07-21
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL APPENDIX B SITE NO. 4 10/26/2016 - V. Brevdo Due to Project Manager Joe O'Connell's promotion to the DMM, and per discussions between Chiefs of Spill Prevention and Response and Remediation Section B, this spill case is re-assigned to Remediation Section B. VB 12/28/2016 - Spill case re-assigned from V. Brevdo to R. Arnold. 3/17/2017-On March 14th 2017, NYSDEC received a summary letter dated March 14th, 2017, of the site walk for Con Edison Site 4 in Long Island City, January 19th 2017. A formal work plan will be submitted for each of the spills which warrant further investigation. The letter included a request to revise the work plan for spill 9206118, instead of 6 borings along the feeder, Con Ed requested to start with outer and center ones and bracket long the feeder alignment. For spills recommended for closure, Con Edison proposes a combined

21ST ST & 38TH AVE (Continued) **S103483461**

closure report to be submitted
in the last quarter of 2017. The letter also included an attached table detailing the status of the
spills based on the site walk through in January 2017. Of the 16 spills addressed on the table 12
spills warranted further investigation, 2 spills were requested for closure, 1 spill was
recommended for closure and Con Ed requested confirmation that 1 spill had been closed. DEC
confirmed that the spill had been closed via email. The letter was uploaded into DecDocs. R.
Arnold 3/17/2017 - Replied to Con Edison with the following email: Dear Mr. Mao: Thank you for your
3/14/17 letter summarizing the January 19, 2017 walk-through of Appendix B Site 4. The Site 4
status table attached to the letter requested confirmation of the closure of spill 9603337 (Con
Edison Spill 4-12). NYSDEC closed spill 9603337 on 6/10/96; a copy of the spill report is attached.
The different approach proposed in your letter for Con Edison Spill 4-5 (NYSDEC Spill No. 9206118)
is not entirely clear to us. Please express your proposal more clearly in the site-specific work
plan you will be submitting for further investigation of this spill. The site walk-through summary
letter does not provide a date or dates by which Con Edison will submit work plans for the Site 4
spills which warrant further investigation. In the interest of expediting the investigation and
closure of these spills, NYSDEC requests that the work plans be submitted by the end of April 2017.
Finally, your letter states that a combined closure report for several Site 4 spills recommended
for closure will be submitted by the last quarter of 2017. This is too long of a time frame for
this task. NYSDEC requests that the closure report be submitted by the end of June 2017. Please
feel free to contact me if you have any questions. Sincerely, Rachel 06/22/17: Reviewed May 2017
Site Investigation Work Plan for Appendix B Site 4 spills by CDM Smith (in DecDocs under spill
number 8710979). Investigation of this spill will be combined with investigation of spill 9401387
(Con Ed spill 4-8), 9403515 (Con Ed spill 4-10) and 9408172 (Con Ed spill 4-11), which occurred at
the same intersection. Investigations in 2008 and 2009 identified contamination. The current SIWP
proposes drilling two borings and installing temporary wells to confirm the earlier findings.
Further delineation may be necessary based on the results of the two borings/wells. The plan states
that if soil sample results exceed the applicable cleanup criteria for dielectric fluids, a
groundwater sample will be collected from the temporary well at that location and analyzed for TPH.
I sent a letter to Mr. Mao of Con Edison approving the work plan, but requiring collection of a

21ST ST & 38TH AVE (Continued) **S103483461**

groundwater sample if any dielectric fluid impacts to soil are identified at a drilling location.
Rachel Arnold 8/15/2018 I reviewed Con Edison s Remedial Investigation Report and Work Plan
(RIRWP), submitted by Libin Mao of Con Edison on 7/18/2018. The report summarizes a site
investigation performed between 6/24/17 and 8/22/17 to determine if residual dielectric fluid
impacts remain in soil and groundwater at the spill site. The investigation was conducted in
accordance with the approved 5/30/17 Site Investigation Work Plan. Three borings were drilled at
the site and temporary monitoring wells were installed. Evidence of LNAPL was detected in all three
wells during installation and sampling. Sun #6 mineral oil was detected in LNAPL samples at
concentrations up to 1,330,000 mg/L, in well 4?7TW01. Petroleum hydrocarbons were detected at TPH
concentrations of 13,400, 12,500, and 15,400 mg/kg in the soil samples, exceeding the DEC cleanup
criterion of 7,400 mg/kg for mineral-oil-based dielectric fluids. To further delineate the spill
impacts, the work plan recommends installing six more temporary monitoring wells. Based on
observations during installation, locations will be chosen for installation of three 4-inch
recovery wells. If LNAPL is not identified in the delineation wells, the recovery wells will be
installed at the previous well locations where LNAPL was found. As a contingency, supplemental
borings and/or wells may be installed to further delineate the extent of the dielectric fluid
impacts. I sent a letter approving the work plan to Libin Mao and Neil O Halloran of Con Edison on
8/15/2018. Con Ed s RIRWP and my approval letter have both been uploaded to DecDocs. R. Arnold
6/20/2019 - On 4/24/2019 Con Ed submitted a Remedial Investigation Letter Report. The report
summarized a remedial investigation performed between 10/22/2018 and 11/21/2018 to delineate
residual dielectric fluid impacts at the site. The investigation involved advancement of eight soil
borings, installation of eight temporary monitoring wells, and installation of four permanent
recovery wells at locations where LNAPL was detected in this and earlier investigations. Eleven
soil samples and two LNAPL samples were collected. Six of the soil samples had TPH detected at
levels above the 7,400 mg/kg criterion; two of these samples and one of the LNAPL samples were
identified as Sun #6 Cable Oil; the other LNAPL sample was Sun #6 Cable Oil mixed with other
petroleum products. On 1/22/19, the four recovery wells were gauged and a VEFR event was performed,
recovering 30-100 gallons of oil/water mixture from each well. On 2/5/19, the recovery wells were
gauged to evaluate LNAPL recharge into the wells; no LNAPL was

21ST ST & 38TH AVE (Continued) **S103483461**

detected in well 4-3RW-01, 0.01 ft
of viscous yellow LNAPL was detected in well 4-3RW-02, viscous yellow LNAPL was detected in well
4-3RW-03 but could not be measured; and well 4-3RW-04 had 4.56 ft of LNAPL. On 2/19/19, the
recovery wells were gauged and absorbent socks were installed. On 3/5/19 and 3/19/19, the wells
were gauged and the absorbent socks were replaced. The report included an Interim Remedial Measure
(IRM) Plan which proposed that monthly product recovery events continue until a decrease in LNAPL
is observed on the oil-absorbent socks in the affected wells. If there is no reduction in LNAPL
after three months, a VEFR event will be scheduled. One month following the VEFR event, water level
elevations and LNAPL measurements will be taken at each well. On 6/20/2019, I sent a letter
approving the IRM Plan to Libin Mao and Neil O Halloran of Con Edison. The Remedial Investigation
Letter Report and my approval letter have been uploaded to DecDocs. R. Arnold 2/19/2020 I
reviewed Interim Remedial Measure Progress Report by Con Edison dated 2/11/20, submitted by Richard
Knob of Con Ed on 2/12/20. The report documents IRM activities at site from July to December 2019.
The report said that since 1/22/2019, water levels and free product thicknesses have been measured
in the four recovery wells at spill sites 8912492 and 9408172 during IRM events. On 10/24/19,
absorbent socks were removed from the wells and VEFR was performed; about 1,025 gallons of
water-product mixture were recovered from the wells. New socks were then placed in the wells. On
11/8/19, the absorbent socks were removed from the wells to allow LNAPL to recharge and stabilize;
all socks were stained with product. On 12/13/2019 the recovery wells were gauged to measure
groundwater elevations and LNAPL thicknesses. LNAPL was detected in all four recovery wells, with
an overall increase in LNAPL thicknesses in the wells. Well 4?3RW?01 had 0.38 feet of free product,
well 4-3RW-02 had ~1.09 feet of LNAPL, and well 4-3RW-03 had ~1.45 feet of LNAPL. The LNAPL in well
4-3RW-04 could not be accurately measured. The report notes that the largest accumulation of LNAPL
occurred in recovery wells 4-3RW-03 and 4?3RW?04. When the socks are removed from the wells during
the first IRM event in 2020, if they are fully saturated with LNAPL, a VEFR event will be
scheduled. The IRM Progress Report has been uploaded to DecDocs. R. Arnold 1/24/2022 I reviewed
an Interim Remedial Measure Progress Report by Con Edison dated 1/19/22, submitted by Richard Knob
of Con Ed on that date. A previous IRM report documented site activities through 2019. The current
report states that VEFR events were performed in May, June and October of 2020 and in April, August

21ST ST & 38TH AVE (Continued) **S103483461**

and October of 2021. The report focuses on IRM activities at the site from August to December 2021.
During this time, absorbent socks were not placed in wells after VEFR events, to evaluate LNAPL
recharge. Monthly well gauging showed LNAPL thicknesses ranged up to 0.65 ft in well 4-3RW-02
(9/17/21), up to 2.79 ft in 4-3RW-03 (10/22/21), and up to 3.48 ft in 4-3RW-04 (10/22/21); no LNAPL
was detected in well 4-3RW-01 during this time. VEFR was performed on all 4 wells on 8/23/21 and on
10/22/21, removing 1,070 gals and 1,010 gals of total fluids, respectively. Well gauging on
12/17/21, two months after the last VEFR event, showed LNAPL thicknesses were 33% lower in well
4-3RW-02 and 69% lower in well 4-3RW-03 compared with pre-VEFR levels. The report states that
monthly IRM will continue at the site, with the next VEFR event scheduled for January 2022. Con
Edison requested approval to discontinue monitoring of well 4-3RW-01 since no product has been
observed in this well for 9 consecutive months (since 0.03 ft was detected on 3/19/21). On
1/24/2022, I sent an email to Richard Knob and Neil O Halloran of Con Edison approving this request
but stating that the well should remain open for future monitoring in case site conditions change.
R. Arnold 7/21/2022 I reviewed an Interim Remedial Measure Progress Report by Con Edison dated
7/12/22, submitted by Richard Knob of Con Ed on that date. The report focuses on IRM activities
conducted at the site from January through June 2022, including six monthly well gauging events and
two quarterly VEFR events (in January and April 2022). During this time, absorbent socks were not
placed in wells after VEFR events, to evaluate LNAPL recharge. Monthly well gauging showed LNAPL
thicknesses ranged up to 1.96 ft in well 4-3RW-02 (6/17/2022), up to 2.10 ft in 4-3RW-03
(5/20/2022) and up to 1.44 ft in 4-3RW-04 (5/20/2022). No LNAPL was detected in well 4-3RW-01
during for 11 consecutive gauging events through 2/18/22, and gauging of this well was discontinued
with DEC approval. A VEFR event on 1/21/2022 recovered 1,000 gallons of an oil/water mixture from
wells 4-3RW-02, 4-3RW-03 and 4-3RW-04; VEFR on 4/14/22 recovered 1,445 gallons of oil/water from
these three wells. On 4/14/22, product samples were collected from wells 4-3RW-03 and 4-3RW-04 for
fingerprint analysis; the product was identified as Sun #6 Cable Oil (however, the report notes
that the analyses show higher levels of Diesel Range Organics than typically found in Sun #6 Cable
Oil, suggesting that oils from another source may be mingling with oil from the Con Ed release).
The report notes that as of June 17, 2022, two months after the last VEFR event, product
thicknesses measured in the three impacted wells were greater than

21ST ST & 38TH AVE (Continued) **S103483461**

their pre-VEFR measurements. The report states that IRM activities consisting of monthly well gauging and quarterly VEFR events will continue at the site, with the next VEFR event scheduled for July 2022. On 7/21/2022, I responded to the IRM progress report with a letter to Richard Knob of Con Edison, cc to Neil O Halloran of Con Ed, which required Con Edison to increase the frequency of VEFR events at the site from quarterly to monthly based on the well gauging data in the report. The report and the letter have been uploaded to DecDocs. R. Arnold"

Remarks: "Reported by Con Ed as required under Consent Order."

All Materials:

Site ID:	71924
Operable Unit ID:	939210
Operable Unit:	01
Material ID:	438417
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	13200.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B26 **21ST ST/38TH AVE** **NY Spills** **S102148358**
SW **21ST ST/38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
181 ft. **Site 12 of 22 in cluster B**

Relative: Higher
Actual: 17 ft.

SPILLS:

Name:	21ST ST/38TH AVE
Address:	21ST ST/38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9403515 / 2019-09-26
Facility ID:	9403515
Facility Type:	ER
DER Facility ID:	108767
Site ID:	125759
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1994-06-13
Investigator:	RCARNOLD
Referred To:	CLOSED TO CONSOLIDATE WITH SP 9408172
Reported to Dept:	1994-06-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

21ST ST/38TH AVE (Continued) **S102148358**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-07-20
Spill Record Last Update:	2019-10-25
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL APPENDIX B SITE NO. 4. TRANSFERRED FROM ENGELHARDT TO O'CONNELL. 6/14/94, 3:00 PM: John Hegerty (Con Ed UT) - had excavation fro feeder 31281 M-leg open. They were going to fill it in and repair road and found another leak & oil in excavation. JH said they have to get OK from Con Ed Env Affairs before they can backfill. (CAE) 10/10/95: This is additional information about material spilled from the translation of the old spill file: DIELETRIC FLUID. 10/26/2016 - V. Brevdo Due to Project Manager Joe O'Connell's promotion to the DMM, and per discussions between Chiefs of Spill Prevention and Response and Remediation Section B, this spill case is re-assigned to Remediation Section B. VB 12/28/2016 - Spill case re-assigned from V. Brevdo to R. Arnold. 06/22/17: Reviewed May 2017 Site Investigation Work Plan for Appendix B Site 4 spills by CDM Smith (in DecDocs under spill number 8710979). This spill investigation is being combined with the investigation of spill nos. 8912492 (Con Ed spill 4-3), 9401387 (Con Ed spill 4-8) and 9408172 (Con Ed spill 4-11), since these spills all occurred at the same intersection. Investigations in 2008 and 2009 identified contamination at the spill site. The current SIWP proposes drilling two borings and installing two temporary wells. Further delineation may be necessary based on the results of the two borings/wells. The plan states that if soil sample results exceed the applicable cleanup criteria for dielectric fluids, a groundwater sample will be collected at that location and analyzed for TPH. I sent a letter to Mr. Mao of Con Edison approving the work plan, but requiring collection of a groundwater sample if any dielectric fluid impacts to soil are identified at a drilling location. Rachel Arnold 8/15/2018 I reviewed Con Edison s Remedial Investigation Report and Work Plan (RIRWP), submitted by Libin Mao of Con Edison on 7/18/2018. The report summarizes a site investigation performed between 6/24/17 and 8/22/17 to determine if residual dielectric fluid impacts remain in soil and groundwater at the spill site. The investigation was conducted in accordance with the

21ST ST/38TH AVE (Continued) **S102148358**

approved 5/30/17 Site
Investigation Work Plan. Three borings were drilled at the site and temporary monitoring wells were
installed. Evidence of LNAPL was detected in all three wells during installation and sampling. Sun
#6 mineral oil was detected in LNAPL samples at concentrations up to 1,330,000 mg/L, in well
4?7TW01. Petroleum hydrocarbons were detected at TPH concentrations of 13,400, 12,500, and 15,400
mg/kg in the soil samples, exceeding the DEC cleanup criterion of 7,400 mg/kg for mineral-oil-based
dielectric fluids. To further delineate the spill impacts, the work plan recommends installing six
more temporary monitoring wells. Based on observations during installation, locations will be
chosen for installation of three 4-inch recovery wells. If LNAPL is not identified in the
delineation wells, the recovery wells will be installed at the previous well locations where LNAPL
was found. As a contingency, supplemental borings and/or wells may be installed to further
delineate the extent of the dielectric fluid impacts. I sent a letter approving the work plan to
Libin Mao and Neil O Halloran of Con Edison on 8/15/2018. Con Ed s RIRWP and my approval letter
have both been uploaded to DecDocs. R. Arnold 6/20/2019 - On 4/24/2019 Con Ed submitted a
Remedial Investigation Letter Report. The report summarized a remedial investigation performed
between 10/22/2018 and 11/21/2018 to delineate residual dielectric fluid impacts at the site. The
investigation involved advancement of eight soil borings, installation of eight temporary
monitoring wells, and installation of four permanent recovery wells at locations where LNAPL was
detected in this and earlier investigations. Eleven soil samples and two LNAPL samples were
collected. Six of the soil samples had TPH detected at levels above the 7,400 mg/kg criterion; two
of these samples and one of the LNAPL samples were identified as Sun #6 Cable Oil; the other LNAPL
sample was Sun #6 Cable Oil mixed with other petroleum products. On 1/22/19, the four recovery
wells were gauged and a VEFR event was performed, recovering 30-100 gallons of oil/water mixture
from each well. On 2/5/19, the recovery wells were gauged to evaluate LNAPL recharge into the
wells; no LNAPL was detected in well 4-3RW-01, 0.01 ft of viscous yellow LNAPL was detected in well
4-3RW-02, viscous yellow LNAPL was detected in well 4-3RW-03 but could not be measured; and well
4-3RW-04 had 4.56 ft of LNAPL. On 2/19/19, the recovery wells were gauged and absorbent socks were
installed. On 3/5/19 and 3/19/19, the wells were gauged and the absorbent socks were replaced. The
report included an Interim Remedial Measure (IRM) Plan which proposed that monthly product recovery

21ST ST/38TH AVE (Continued) **S102148358**

events continue until a decrease in LNAPL is observed on the oil-absorbent socks in the affected wells. If there is no reduction in LNAPL after three months, a VEFR event will be scheduled. One month following the VEFR event, water level elevations and LNAPL measurements will be taken at each well. On 6/20/2019, I sent a letter approving the IRM Plan to Libin Mao and Neil O Halloran of Con Edison. The Remedial Investigation Letter Report and my approval letter have been uploaded to DecDocs. R. Arnold 9/26/2019 After review of Appendix B Site 4 spills, this spill case is closed to consolidate with spill no. 9408172, which occurred at the same location and is being addressed by the same actions. Further investigation and/or remediation of this spill will continue to be tracked under spill no. 9408172. I sent an email to Neil O Halloran and Libin Mao of Con Edison informing them of this spill closure by consolidation. - R. Arnold"

Remarks: "ELECTRIC FEEDER CABLE-LEAK IN PIPE-WILL PUMP AT EXCACATION SITE"

All Materials:

Site ID:	125759
Operable Unit ID:	1000594
Operable Unit:	01
Material ID:	567184
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B27 **38TH AVE & 21ST ST** **NY Spills** **S102148912**
SW **MANHOLE #499- 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.034 mi.
181 ft. **Site 13 of 22 in cluster B**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	38TH AVE & 21ST ST
Address:	MANHOLE #499- 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9409876 / 1995-03-07
Facility ID:	9409876
Facility Type:	ER
DER Facility ID:	98880
Site ID:	113307
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	1994-10-24

38TH AVE & 21ST ST (Continued) **S102148912**

Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-10-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-01
Spill Record Last Update:	1997-08-13
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE CLEANED BY NYNEX. "
Remarks:	"1/2 INCH OIL IN MANHOLE-PUTTING INTO DRUMS & TAKEN AWAY"

All Materials:

Site ID:	113307
Operable Unit ID:	1007624
Operable Unit:	01
Material ID:	375750
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A28 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241022**
NNW **14 ST & 37 AVE MH22366** **N/A**
< 1/8 **QUEENS, NY**
0.035 mi.
186 ft. **Site 15 of 20 in cluster A**

Relative: **Lower**
Actual: **16 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	14 ST & 37 AVE MH22366
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004093209
Facility Status:	Not reported
Location Address 1:	14 ST & 37 AVE MH22366
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS

CONSOLIDATED EDISON (Continued) **1009241022**

Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004093209
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

A29 **DRUM RUN** **NY Spills** **S111835677**
NNW **37TH AVE AND 14TH ST** **N/A**
< 1/8 **ASTORIA, NY**
0.035 mi.
186 ft. **Site 16 of 20 in cluster A**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:
Name: DRUM RUN
Address: 37TH AVE AND 14TH ST
City,State,Zip: ASTORIA, NY
Spill Number/Closed Date: 1200655 / 2012-06-21
Facility ID: 1200655
Facility Type: ER
DER Facility ID: 417711
Site ID: 463307
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C4
SWIS: 4101
Spill Date: 2012-04-20
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2012-04-20
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: DEC
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-04-20
Spill Record Last Update: 2012-06-21
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: JEFFREY VOUGHT

DRUM RUN (Continued) **S111835677**

DEC Memo: "55 gal pumped on 6/20/12. closed. "
Remarks: "Abandoned 55 gallon drum, no leaking found in front of a school."

All Materials:
Site ID: 463307
Operable Unit ID: 1213404
Operable Unit: 01
Material ID: 2211349
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

A30 **37TH AVE / 14TH ST.** **NY Spills** **S102147129**
NNW **14TH ST SOUTH OF 37TH AVE** **N/A**
< 1/8 **QUEENS, NY**
0.035 mi.
186 ft. **Site 17 of 20 in cluster A**

Relative: **Lower**
Actual: **16 ft.**

SPILLS:
Name: 37TH AVE / 14TH ST.
Address: 14TH ST SOUTH OF 37TH AVE
City,State,Zip: QUEENS, NY
Spill Number/Closed Date: 9308351 / 2015-09-03
Facility ID: 9308351
Facility Type: ER
DER Facility ID: 245594
Site ID: 303968
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 4101
Spill Date: 1993-10-09
Investigator: JMOCONNE
Referred To: Not reported
Reported to Dept: 1993-10-09
CID: Not reported
Water Affected: Not reported
Spill Source: Major Facility (MOSF) > 400,000 gal
Spill Notifier: Federal Government
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1993-10-13
Spill Record Last Update: 2015-09-03
Spiller Name: Not reported
Spiller Company: CON-ED.
Spiller Address: Not reported
Spiller Company: 001

37TH AVE / 14TH ST. (Continued) **S102147129**

Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Appendix B site 1.
10/9/93, 8:45 PM: called USCG Lt. Trabocchi - she said nothing got into East River. FDNY has dammed
it up. 9:00 PM: spoke with Joe Cuzzo (NYCDEP Sewers) - he said his guy is at scene. 10:00 PM:
arrived at scene - NYCDEP, NYPD, FDNY, NYC Sanitation Police, Con Ed, American Red Cross, AAA and
MEG on site already. Original call came in as 5,000 gallons of #2 fuel oil (wrong). Actually low
pour #6 oil. Met with Carmine Sabatasso and John Mitchell (Con Ed), Steve (AAA) and Bobby (MEG).
AAA had a 3,000 gallon vac truck, 2 more bigger trucks coming. MEG had 6,000 gallon vac truck (1
more coming). Spill is contained on 14th Street between 21st St. and 37th Ave.Possible broken check
valve. 20 inch pipeline. Sanitation applied sand and diked off. Oil is all over street, but none in
East River of in sewage treatment plant yet. Storm drain clogged with sorbents. Pipeline runs from
Ravenswood to N. 1st Street. 11:00 PM: Spoke to Randy Austin - need to modify AAA 364 permit so
they can bring oil to Con Ed Astoria and empty product into tank. MEG is already permitted to do
so. 11:30 PM: Call from RA - got verbal approval for Emergency Authorization to 364 permit to
transport oil to Astoria. (KO'D) 10/10/93, 10:35 AM: Got spill update from Brett Putnam - 8,000 to
9,000 gallons #6 oil. 2:15 PM: Arrived at site. Met with Jerry (Con Ed) and Bobby (MEG). 4 vac
trucks still on site. Most free product sucked up. Applying more sand. Clean Up Plan: apply sand
and pick up (2x); steam clean (cosmetic) - hopefully before Tuesday morning (school opening). ConE
d fixed valve and pipeline is running. No accurate estimate of how much oil recovered. (KO'D)
10/13/93: spoke with Pete from AAA. They have recovered 27,000 gallons of #6 oil so far. (CAE)
10/19/93: spoke with Barry Vucca of NYC Parks - he said that Con Ed still has to brng in some clean
topsoil but so far he is very satisfied with clean up. (CAE) 10/20/93: Notice of Violation issued
by FDNY to Con Ed for failure to monitor pipeline operations. 3/4/03: transferred from Engelhardt
to O'Connell. 1/6/14 - pipeline 7 work is underway in the area of this spill. Went to location
today. It had been snowing during the day, so some of the exposed surfaces were not visible due to
the snow cover. CDM Smith and Posilico on site. Long section of 14th Street excavated, top of valve
pit #1 has been removed, top of the pipeline is just exposed. Interior walls of vault, what is
exposed, appears clean and in good condition. The nature of any sealing around the pipeline
penetrations is not too clear. Shoring in place in some locations. No contamination is noted. They

37TH AVE / 14TH ST. (Continued) **S102147129**

have short time window for work (9-2) under NYCDOT permit due to the nearby schoool. The plan is to continue to expose the pipeline in the area and to remove the valve from the pit. Pictures taken.(JOC) 2/10/15 - received proposed sampling plan on January 8th, conditionally approved on January 9th for sampling around the vault area; figure showing sampling locations received on January 12th and approved same day; at site location on January 13th with Con Edison, Posillico, CDM Smith in late AM; had not yet broken through bottom of valve pit slab so no sampling at that time; returned in afternoon - Posillico had already collected samples from beneath the vault and was collecting a sample from the western side of the northern pipeline penetration out of the vault; CDM Smith processing samples from bowls to sample containers. Recevied draft data for samples collected which included those collected on January 13th plus samples taken earlier from the sections where they had exposed the pipeline north and south of the vault; all sample results, while draft, were relatively low in target compounds,with a few marginal excursions of CP-51 Table 3 concentrations. Samples east and west of vault not yet collected; in January 26 email advised Con Edison that the additional samples per the plan remained warranted. (JOC) 4/3/15 - received email request 3/26 requesting to meet at the location, which was discussed in telecon 3/27, raising whether the addtional samples were needed; met there March 30 with Con Edison, CDM Smith, and Posillico. Was advised that the adjacent school has indicated to Con Ed that for numerous reasons the continued closure of the street has been problematic for them and requested resolution. Con Edison had utility markouts refreshed around the former valve pit; much of the previous equipment was now out of the way, while the street excavation/trench remains open and the street mostly closed. Con Edison advised that there is a feeder running along the east side of the valve pit as was marked out on the street. The interior of the structure and its construction were now more readily observable - it is a substantial, rebar reinforced poured concrete vault. No other penetrations from the valve pit, other than those for the pipeline previously sampled, were evident. Based on the overall condition and the circumstances of the event, in an email on 3/30 agreed that the additional samples to the east and west were not needed. Con Edison will have CDM put together letter documenting the actions and sampling completed. (JOC) 6/5/15 - received email from Con Edison PM today confirming that they do not need to wait for this section of the pipeline to be closed (grouted) before they submit the investigation report.

37TH AVE / 14TH ST. (Continued) **S102147129**

Responded by email that they do
not need to wait. Received follow-up email that they are working on finalizing data review and will
submit report (JOC) 9/3/15 - report received on 7/8 from CDM Smith (Beattie); in review of report,
noted that laboratory data packages not included, sent email to Ms. Beattie 8/21 requesting the
documents, which she provided through the Department's FTS later that day. The reports are under
review. (JOC) 9/3/15 - This spill is among the spills being addressed by Con Edison under Order on
Consent. This spill has been referred to as spill 1-11 in Order Appendix B Site 1 (i.e., spill
number 11 in site 1). Site 1 consists of multiple spills in the Long Island City area from Con
Edison subsurface equipment including electric transmission feeders and the fuel oil pipeline.
Based on available information, the release occurred during a transfer of No. 6 fuel oil between
Con Edison s Rainey and North 1st Street facilities. The release occurred when a cap came off a 3
inch bypass valve off the main 20 inch fuel oil pipeline (Con Edison s Fuel Oil Pipeline No. 7)
within the valve pit structure. The valve pit is located on 14th Street south of 37th Avenue in
Long Island City. The street location is between a public school (PS 111) and a NYC park (Sixteen
Oaks Grove). The valve pit is essentially a subsurface concrete manhole in which a valve was
located which could close the 20 inch pipeline at that location. NYFD observed fuel oil to be
exiting the manhole at that location. Con Edison staff reported that the differential flow between
the two ends of the pipeline during that ongoing transfer was 126 gallons per minute. When
observed, the transfer of oil was stopped, abating the discharge. The oil exiting the valve pit
flowed over the surface of the street impacting ground surfaces in that area. The response at the
time included removal of free product from the street (via vacuum trucks), through sand and other
media applied to the surfaces with subsequent removal, followed by steam cleaning impacted
surfaces. The sidewalk and curb area along the school side were subsequently cleaned, and no
residual impacts are presently noted. The school grounds are primarily hard surfaces (e.g.,
concrete and asphalt) with small areas for vegetation (e.g., around sidewalk trees, area of
property line shrubbery). Remediation in the park area was also needed. The Department received
confirmation from NYC Parks at the time that it was satisfied with the remedial work completed. No
present impacts within the park are noted. The park area is also most hard surfaces with concrete
sidewalk and a large central area with concrete-like pavers with narrow strip grassy areas along

37TH AVE / 14TH ST. (Continued) **S102147129**

two lines of oak trees along the park perimeter. Additional investigation was conducted to determine whether any releases to the subsurface occurred from the valve pit and along penetrations for the pipeline from the valve pit. Initially, investigation was conducted following a 2005 work plan prepared by environmental consultant Clayton/BVNA for Con Edison. The narrative of the work plan called for borings to be located at a radial distance of 25 feet around the manhole location which was mis-identified as being in the intersection of 14th Street and 37th Avenue. Con Edison switched consultants and the field work was implemented by CDM, as reported in CDM s 12/08 Site Investigation Report (SIR). The SIR includes that four borings were completed around the intersection of 14th Street and 37th Avenue. SIR Figure 3-28 also shows the valve pit and provides the distance to the center of the valve pit as on 14th Street 139 feet south of the south curb of 37th Avenue, with the pipeline depicted as running roughly in the middle of 14th Street. The borings were all at least 10 feet away from the pipeline, but more importantly, they were all more than 100 feet away from the valve pit. As such, they were not informative as to whether contamination was released out through the valve pit to the subsurface. In the sampling completed around the intersection, no impacts were observed, but in one soil sample, collected at 11 feet below grade near the southeast corner of the intersection, several PAHs and phenol were noted in the 1-2 ppm range. In addition, a temporary monitoring well point was installed at the boring near the southwest corner of the intersection. The groundwater sample found 1,2,4-trimethyl benzene at 10 ug/L (vs. GA standard of 5 ug/L). Based on these results, the SIR recommendation was to do additional investigation during closure work for Fuel Oil Pipeline No. 7. CDM s July 8, 2015 report describes this additional work. As part of investigation of this incident as part of preparatory work for abandoning the pipeline, this section of the pipeline was exposed via excavation along 14th Street both north and south of the valve pit for much of the street. Shoring excavations were completed 17 feet north and 10 feet south of the valve pit and excavations were completed on the north and south ends of the vault to below the pipeline penetrations out of the vault. No visible contamination or odors along the pipeline or around the vault were encountered. Two soil samples were collected from each of the north and south shoring excavation locations and from beneath the pipeline where it exited the north and south ends of the valve pit. The valve pit itself was in very good condition, with no staining noted and no obvious other

37TH AVE / 14TH ST. (Continued) **S102147129**

cracks or penetrations. The floor
of the valve pit was opened by breaking up the concrete, and five soil samples were collected from
beneath the valve pit (~each corner and center). All samples were analyzed for VOCs, SVOCs and TPH.
Some of the samples were additionally analyzed for PCBs. The included data usability summary report
(DUSR) documents the review of the laboratory data and finds it acceptable for use. DUSR Table 1
which lists the project samples is mislabeled as Ainslie Samples which is a different project,
however, the sample numbers and information are correct as related to the investigation around
valve pit 1. There was one detection of one PCB in one sample, at an estimated concentration of
0.03 mg/kg as compared to the unrestricted use soil cleanup of 0.1 mg/kg. In some sections of the
SIR it is indicated that all soil samples were analyzed for PCBs (e.g., Table 1), however, only the
four samples collected on 1/7/15 were. As PCBs are not a contaminant of concern for this spill,
additional PCB analyses were not necessary. Where detected, the laboratory fingerprinted TPH
results as lubricating oil, with detections of up to approximately 400 mg/kg. The Department has no
soil cleanup objective for TPH, but does have an SCO of 7,400 mg/kg for mineral oil based
dielectric fluid which is the closest to lubricating oil for comparison purposes. There were
limited detections of VOCs, but none was in excess of CP-51 Table 3 SCOs for fuel oil contaminants.
There were detections of SVOCs (PAHs) in most of the samples with results up to a maximum of 2.4
mg/kg in excess of CP51 SCOs ranging from 0.33 to 1 mg/kg. CDM concludes that similar PAHs were
detected in site soils at relatively low concentrations collected during the 2008 site
investigation, and that based on the relatively low concentrations of TPH and PAHs detected in the
soil samples and the absence of any staining or product observed, these compounds are concluded to
be originated from urban fill and not from a release from the pipeline. The pipeline is no longer
in service and is undergoing final closure, which included removal of the valve and replacement
with a section of pipe, cleaning the pipeline via pigging and filling the pipeline with
cement/grout. Considering all the information available, the SIR s conclusion is accepted and no
further action is required, and as such the spill is closed. (JOC) "

Remarks: "MAJOR LINE RUPTURED AT CON-ED. NYC FD & NYC DEP AT SCENE TRYING TO CONTAIN IT CALLED VAC TRUCK TO SUCK UP MATERIAL NOTIFIED EPA WANT A CALL BACK. O'DOWD"

All Materials:
Site ID: 303968
Operable Unit ID: 989886
Operable Unit: 01

37TH AVE / 14TH ST. (Continued) **S102147129**

Material ID:	394580
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	9000.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A31 **MANHOLE 5499** **NY Spills** **S104787495**
NNW **37TH AVE/14TH ST** **N/A**
< 1/8 **QUEENS, NY**
0.035 mi.
186 ft. **Site 18 of 20 in cluster A**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:

Name:	MANHOLE 5499
Address:	37TH AVE/14TH ST
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0004791 / 2001-10-22
Facility ID:	0004791
Facility Type:	ER
DER Facility ID:	148433
Site ID:	176618
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2000-07-21
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-07-21
CID:	397
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-21
Spill Record Last Update:	2001-10-22
Spiller Name:	Not reported
Spiller Company:	UNKNONW
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 7/21/00 Found 200gal water in structure with an oily black substance on the walls. Taken PCB and ID sample. Previous cleanup completed 7/15/00 using truck 60443 which was involved in an

MANHOLE 5499 (Continued) **S104787495**

indident(e2mis #132429) at Farrington WWTF. Results of sampling will be compared to both incidents.
Sample returned 9ppm. 8/11/00 Water and oil coming into structure from top duct. Cemented sump and
will have structure reinspected. 10/29/00 Reinspection of structure found no trace of oil. Flush
employees recleaned structure and removed tag."

Remarks: "discovered oil on the walls of the manhole. cleanup pending results coned 132490"

All Materials:

Site ID:	176618
Operable Unit ID:	825858
Operable Unit:	01
Material ID:	549522
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A32 **MANHOLE 5499** **NY Spills** **S104787235**
NNW **37TH AVE/14TH ST** **N/A**
< 1/8 **QUEENS, NY**
0.035 mi.
186 ft. **Site 19 of 20 in cluster A**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:

Name:	MANHOLE 5499
Address:	37TH AVE/14TH ST
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0004487 / 2001-10-19
Facility ID:	0004487
Facility Type:	ER
DER Facility ID:	148433
Site ID:	176617
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2000-07-14
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	2000-07-14
CID:	389
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

MANHOLE 5499 (Continued) **S104787235**

Remediation Phase:	0
Date Entered In Computer:	2000-07-14
Spill Record Last Update:	2001-10-19
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis Notes: 7/14/00 1qt unknown oil on 200gal water in manhole. Sample returned 11ppm PCB. Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. "
Remarks:	"caller reporting a spill of material from unk source samples taken cleanup pending lab results coned#132379 no callback necessary"

All Materials:

Site ID:	176617
Operable Unit ID:	825691
Operable Unit:	01
Material ID:	549225
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

A33 **NEW YORK CITY D.E.P** **NY MANIFEST** **1009244287**
NNW **37TH/14TH STREET** **N/A**
< 1/8 **ELMHURST, NY**
0.035 mi.
186 ft. **Site 20 of 20 in cluster A**

Relative: **Lower**
Actual: **16 ft.**

NY MANIFEST:

Name:	NEW YORK CITY D.E.P
Address:	37TH/14TH STREET
City,State,Zip:	ELMHURST, NY
Country:	USA
EPA ID:	NYP010001246
Facility Status:	Not reported
Location Address 1:	37TH/14TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	ELMHURST
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP010001246
Mailing Name:	NEW YORK CITY D.E.P
Mailing Contact:	STAN SIEBENBERG

NEW YORK CITY D.E.P (Continued) **1009244287**

Mailing Address 1: 59-17 JUNCTION BLVD
Mailing Address 2: Not reported
Mailing City: ELMHURST
Mailing State: NY
Mailing Zip: 11373
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7185954681

B34 **NEW YORK AUTO LIC, INC.** **NY AST** **A100514947**
SW **21-10 38TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.036 mi.
189 ft. **Site 14 of 22 in cluster B**

Relative:
Higher

Actual:
17 ft.

AST:
Name: NEW YORK AUTO LIC, INC.
Address: 21-10 38TH AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-604092
Program Type: PBS
UTM X: 589568.04006
UTM Y: 4512366.23068
Expiration Date: 05/23/2026
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 25977
Affiliation Type: Facility Owner
Company Name: AGA DATA SERVICE 954 HOLLY COURT FRANKLIN SQUARE N
Contact Type: Not reported
Contact Name: Not reported
Address1: 21-10 38TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 729-7788
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2021-06-18

Site Id: 25977
Affiliation Type: Mail Contact
Company Name: NEW YORK AUTO LIC, INC.
Contact Type: Not reported
Contact Name: KASAM SHAHZAD
Address1: 21-10 38TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101

NEW YORK AUTO LIC, INC. (Continued) **A100514947**

Country Code:	001
Phone:	(718) 729-5515
EMail:	NEWYORKAUTOLIC@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-06-18

Site Id:	25977
Affiliation Type:	Facility Operator
Company Name:	NEW YORK AUTO LIC, INC.
Contact Type:	Not reported
Contact Name:	NEW YORK AUTO LIC, INC.
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-7788
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-06-18

Site Id:	25977
Affiliation Type:	Emergency Contact
Company Name:	KING KHAN AUTO LIC, INC.
Contact Type:	Not reported
Contact Name:	KASAM SHAHZAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 729-7788
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2021-06-18

Tank Info:

Tank Number:	1
Tank Id:	56655
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J00 - Dispenser - None
K00 - Spill Prevention - None

NEW YORK AUTO LIC, INC. (Continued) **A100514947**

A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2001
Capacity Gallons:	225
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)

C35 **T.J. AUTO BODY & REPAIR** **NY AST** **A100296239**
ESE **37-09 22ND STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.036 mi.
191 ft. **Site 1 of 18 in cluster C**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	T.J. AUTO BODY & REPAIR
Address:	37-09 22ND STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609180
Program Type:	PBS
UTM X:	589719.05146
UTM Y:	4512442.00892
Expiration Date:	08/05/2008
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	31025
Affiliation Type:	Facility Owner
Company Name:	SAINI MOHAN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	37-09 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

T.J. AUTO BODY & REPAIR (Continued) **A100296239**

Site Id:	31025
Affiliation Type:	Mail Contact
Company Name:	T.J. AUTO BODY & REPAIR
Contact Type:	Not reported
Contact Name:	SAINI MOHAN
Address1:	37-09 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31025
Affiliation Type:	Facility Operator
Company Name:	T.J. AUTO BODY & REPAIR
Contact Type:	Not reported
Contact Name:	SAINI MOHAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	31025
Affiliation Type:	Emergency Contact
Company Name:	SAINI MOHAN
Contact Type:	Not reported
Contact Name:	SAINI MOHAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	66673
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

T.J. AUTO BODY & REPAIR (Continued) **A100296239**

Equipment Records:

	A00 - Tank Internal Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	G00 - Tank Secondary Containment - None
	D00 - Pipe Type - No Piping
	J00 - Dispenser - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C36 **37-11 22 ST** **NY AST** **A100296240**
SE **37-11 22ND STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.036 mi.
192 ft. **Site 2 of 18 in cluster C**

Relative: Higher
Actual: 18 ft.

AST:

Name:	37-11 22 ST
Address:	37-11 22ND STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607956
Program Type:	PBS
UTM X:	589364.08733
UTM Y:	4512509.66142
Expiration Date:	07/01/2015
Site Type:	Other

Affiliation Records:

Site Id:	29808
Affiliation Type:	Emergency Contact
Company Name:	TJ AUTO BODY & REPAIR SHOP INC.
Contact Type:	Not reported
Contact Name:	MOHAN SAINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999

37-11 22 ST (Continued) **A100296240**

Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-01

Site Id:	29808
Affiliation Type:	Facility Owner
Company Name:	TJ AUTO BODY & REPAIR SHOP INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	37-11 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-12-21

Site Id:	29808
Affiliation Type:	Facility Operator
Company Name:	T.J. AUTO BODY & REPAIR SHOP
Contact Type:	Not reported
Contact Name:	MOHAN SAINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-01

Site Id:	29808
Affiliation Type:	Mail Contact
Company Name:	TJ AUTO BODY & REPAIR SHOP INC.
Contact Type:	PRESIDENT
Contact Name:	MOHAN SAINI
Address1:	37-11 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 389-0005
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-07-01

37-11 22 ST (Continued) **A100296240**

Tank Info:

Tank Number:	001
Tank Id:	63937
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	G05 - Tank Secondary Containment - Synthetic Liner
	J00 - Dispenser - None
	A00 - Tank Internal Protection - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	D00 - Pipe Type - No Piping
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/15/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	63938
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	A00 - Tank Internal Protection - None
	D00 - Pipe Type - No Piping
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	G05 - Tank Secondary Containment - Synthetic Liner
	J00 - Dispenser - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	50

37-11 22 ST (Continued) **A100296240**

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/15/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	OO1
Tank Id:	196588
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	G05 - Tank Secondary Containment - Synthetic Liner
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/22/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C37 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242187**
East **22 ST & 37 AVE OP EXCAV** **N/A**
< 1/8 **ASTORIA, NY 11102**
0.038 mi.
202 ft. **Site 3 of 18 in cluster C**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	22 ST & 37 AVE OP EXCAV
City,State,Zip:	ASTORIA, NY 11102
Country:	USA
EPA ID:	NYP004109443
Facility Status:	Not reported
Location Address 1:	22 ST & 37 AVE OP EXCAV
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	ASTORIA
Location State:	NY
Location Zip:	11102
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004109443
Mailing Name:	CONSOLIDATED EDISON

CONSOLIDATED EDISON (Continued) **1009242187**

Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

C38 **POLE #89064** **NY Spills** **S109371165**
ESE **93-09 22ND ST** **N/A**
< 1/8 **QUEENS VILLAGE, NY**
0.039 mi.
205 ft. **Site 4 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	POLE #89064
Address:	93-09 22ND ST
City,State,Zip:	QUEENS VILLAGE, NY
Spill Number/Closed Date:	0806425 / 2008-10-20
Facility ID:	0806425
Facility Type:	ER
DER Facility ID:	352925
Site ID:	403707
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2008-09-08
Investigator:	asnagi
Referred To:	Not reported
Reported to Dept:	2008-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-08
Spill Record Last Update:	2008-10-20
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	93-09 22ND ST
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"10/20/08 - See eDocs for Con Ed report detailing cleanup and closure. "
Remarks:	"CALLER STATES THAT 2 PINTS OF TRANSFORMER OIL SPILLED ON THE SIDE WALK BETWEEN THE STREET AND THE GRASS. CLEAN UP IS PENDING."

All Materials:

Site ID:	403707

POLE #89064 (Continued) **S109371165**

Operable Unit ID:	1160394
Operable Unit:	01
Material ID:	2151565
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Not reported
Oxygenate:	Not reported

B39 **MAN HOLE 12775** **NY Spills** **S112147545**
South **EAST 22 ST AND 38 AVE** **N/A**
< 1/8 **QUEENS, NY**
0.039 mi.
205 ft. **Site 15 of 22 in cluster B**

Relative: SPILLS:
Higher

Actual:
18 ft.

Name:	MAN HOLE 12775
Address:	EAST 22 ST AND 38 AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	1203425 / 2013-03-08
Facility ID:	1203425
Facility Type:	ER
DER Facility ID:	420576
Site ID:	466239
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2012-07-09
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2012-07-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-07-09
Spill Record Last Update:	2013-03-08
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"3/8/13 - Austin - 15 gal. cable oil leak from faulty coupling in vault - Con Ed contained and cleaned up the spill - See documents in eDocs file for further details - Spill closed - end"

MAN HOLE 12775 (Continued) **S112147545**

Remarks: "spill to man hole/ investigation underway"

All Materials:

Site ID:	466239
Operable Unit ID:	1216245
Operable Unit:	01
Material ID:	2214411
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

B40 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242189**
South **22 ST & 38 AVE OP EXCAV** **N/A**
< 1/8 **QUEENS, NY**
0.039 mi.
205 ft. **Site 16 of 22 in cluster B**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	22 ST & 38 AVE OP EXCAV
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004109468
Facility Status:	Not reported
Location Address 1:	22 ST & 38 AVE OP EXCAV
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004109468
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

B41 **CON EDISON - EXC 11101F** **RCRA NonGen / NLR** **1008195592**
South **22ND ST., 245‘ N/O 38TH AVE.** **NY MANIFEST** **NYP004109476**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.039 mi.
205 ft. **Site 17 of 22 in cluster B**

Relative:
Higher

Actual:
18 ft.

RCRA Listings:

Date Form Received by Agency:	20040227
Handler Name:	Con Edison - Exc 11101f
Handler Address:	22ND ST., 245‘ N/O 38TH AVE.
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004109476
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	4 IRVING PLACE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	4 IRVING PLACE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - EXC 11101F (Continued) **1008195592**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2003

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D018
Waste Description: Benzene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20030405
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20030405
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE
Owner/Operator City,State,Zip:	NEW YORK, NY 10003
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private
Date Became Current:	20030405
Date Ended Current:	Not reported
Owner/Operator Address:	4 IRVING PLACE

CON EDISON - EXC 11101F (Continued) **1008195592**

Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20030405
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20040225
Handler Name: CON EDISON - EXC 11101F
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040226
Handler Name: CON EDISON - EXC 11101F
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040227
Handler Name: CON EDISON - EXC 11101F
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CON EDISON - EXC 11101F (Continued) **1008195592**

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON - FEEDER 28242
Address: 22ND ST., 245‘ N/O 38TH AVE.
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004109476
Facility Status: Not reported
Location Address 1: 22ND ST BTW 37TH AVE & 38TH
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND CITY
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004109476
Mailing Name: CONSOLIDATED EDISON - FEEDER 28242
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

D42 **CON EDISON** **NY MANIFEST** **S117738614**
NNE **36-37 21 ST** **N/A**
< 1/8 **QUEENS, NY 11101**
0.039 mi.
206 ft. **Site 1 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:
Name: CON EDISON
Address: 36-37 21 ST
City,State,Zip: QUEENS, NY 11101
Country: USA
EPA ID: NYP004716809
Facility Status: Not reported
Location Address 1: 36-37 21 ST
Code: BP

CON EDISON (Continued) **S117738614**

Location Address 2: SB8866
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004716809
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FLR
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 01/20/2015
Trans1 Recv Date: 01/20/2015
Trans2 Recv Date: 01/28/2015
TSD Site Recv Date: 01/28/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004716809
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002620688GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100

CON EDISON (Continued) **S117738614**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D43 **H & M SERVICE STATION** **EDR Hist Auto** **1021311812**
North **3642 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.041 mi.
215 ft. **Site 2 of 13 in cluster D**

Relative: EDR Hist Auto
Lower

Actual: **16 ft.**

Year:	Name:	Type:
2002	H & M SERVICE STATION	Gasoline Service Stations
2003	H & M SERVICE STATION	Gasoline Service Stations
2004	H & M SERVICE STATION	Gasoline Service Stations
2005	H & M SERVICE STATION	Gasoline Service Stations
2006	H & M SERVICE STATION	Gasoline Service Stations
2007	H & M SERVICE STATION	Gasoline Service Stations
2008	H & M SERVICE STATION	Gasoline Service Stations
2009	H & M SERVICE STATION	Gasoline Service Stations
2010	H & M SERVICE STATION	Gasoline Service Stations
2011	H & M SERVICE STATION	Gasoline Service Stations
2012	H & M SERVICE STATION	Gasoline Service Stations
2013	H & M SERVICE STATION	Gasoline Service Stations
2014	H & M SERVICE STATION	Gasoline Service Stations

B44 **38-02 22ND STREET** **NY Spills** **S102147647**
South **38-02 22ND ST.** **N/A**
< 1/8 **QUEENS, NY**
0.041 mi.
216 ft. **Site 18 of 22 in cluster B**

Relative: SPILLS:
Higher

Actual: **17 ft.**

Name:	38-02 22ND STREET
Address:	38-02 22ND ST.
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9312589 / 1994-01-26
Facility ID:	9312589
Facility Type:	ER
DER Facility ID:	124854
Site ID:	146633
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	1994-01-26

38-02 22ND STREET (Continued) **S102147647**

Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1994-01-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	1994-01-26
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-28
Spill Record Last Update:	2007-12-26
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"POSSIBLE CON-ED GAS LINE EXPLOSION - 5 INJURIES."

All Materials:

Site ID:	146633
Operable Unit ID:	994590
Operable Unit:	01
Material ID:	388011
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

B45 **PAKAM AUTO REPAIR & BODY SHOP** **EDR Hist Auto** **1020438843**
South **3802 22ND ST** **N/A**
< 1/8 **ASTORIA, NY 11101**
0.042 mi.
220 ft. **Site 19 of 22 in cluster B**

Relative: EDR Hist Auto
Higher

Actual:
17 ft.

Year:	Name:	Type:
1985	M G A MECHANICAL INC	General Automotive Repair Shops
1986	M G A MECHANICAL INC	General Automotive Repair Shops
1987	NOTOS AUTO BODY REPAIR CO INC	Not reported
1987	M G A MECHANICAL INC	General Automotive Repair Shops
1988	NOTOS AUTO BODY REPAIR CO INC	Not reported
1988	M G A MECHANICAL INC	General Automotive Repair Shops
1989	M G A MECHANICAL INC	General Automotive Repair Shops
1991	K&S AUTO REPR	General Automotive Repair Shops
1992	K&S AUTO REPR	General Automotive Repair Shops
1993	K&S AUTO REPR	General Automotive Repair Shops

PAKAM AUTO REPAIR & BODY SHOP (Continued) **1020438843**

1996	PAKAM AUTO REPAIR & BODY SHOP	General Automotive Repair Shops
1997	PAKAM AUTO REPAIR & BODY SHOP	General Automotive Repair Shops
1998	PAKAM AUTO REPAIR & BODY SHOP	General Automotive Repair Shops
1998	SUPRE AUTO TRANSMISSION	Automotive Transmission Repair Shops
1999	PAKAM AUTO REPAIR & BODY SHOP	General Automotive Repair Shops
1999	SUPRE AUTO TRANSMISSION	Automotive Transmission Repair Shops
2000	PAKAM AUTO REPAIR & BODY SHOP	General Automotive Repair Shops

---

B46 **7096681 N.Y. AUTO BODY REPAIR INC.** **NY AST** **A100147097**
South **38-02 22ND STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.042 mi.
220 ft. **Site 20 of 22 in cluster B**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	7096681 N.Y. AUTO BODY REPAIR INC.
Address:	38-02 22ND STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604088
Program Type:	PBS
UTM X:	589621.62646
UTM Y:	4512323.47717
Expiration Date:	05/06/2009
Site Type:	Other

Affiliation Records:

Site Id:	25973
Affiliation Type:	Mail Contact
Company Name:	7096681 N.Y. AUTO BODY REPAIR INC.
Contact Type:	Not reported
Contact Name:	AKHTAR AHMAD
Address1:	38-02 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-9188
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-05-06

Site Id:	25973
Affiliation Type:	Facility Operator
Company Name:	7096681 N.Y. AUTO BODY REPAIR INC.
Contact Type:	Not reported
Contact Name:	AKHTAR AHMAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-9188

7096681 N.Y. AUTO BODY REPAIR INC. (Continued) **A100147097**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-05-06

Site Id:	25973
Affiliation Type:	Emergency Contact
Company Name:	FIAZ KHAN
Contact Type:	Not reported
Contact Name:	FIAZ KHAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 729-7788
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-05-06

Site Id:	25973
Affiliation Type:	Facility Owner
Company Name:	FIAZ KHAN
Contact Type:	MANAGER
Contact Name:	AKHTAR AHMAD
Address1:	21-10 38 AVE.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-7788
EMail:	Not reported
Fax Number:	Not reported
Modified By:	cgfreedm
Date Last Modified:	2004-05-06

Tank Info:

Tank Number:	001
Tank Id:	56647
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

7096681 N.Y. AUTO BODY REPAIR INC. (Continued) **A100147097**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C47 **CONSOLIDATED EDISON** **NY MANIFEST** **1009236520**
ENE **V3671-300 E 22ND ST** **N/A**
< 1/8 **QUEENS, NY 11428**
0.051 mi.
267 ft. **Site 5 of 18 in cluster C**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	V3671-300 E 22ND ST
City,State,Zip:	QUEENS, NY 11428
Country:	USA
EPA ID:	NYP004016796
Facility Status:	Not reported
Location Address 1:	V3671-300 E 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11428
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004016796
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

B48 **KING OF QUEENS AUTO SERVICES CORP.** **NY AST** **A100349541**
SW **38-03 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.051 mi.
270 ft. **Site 21 of 22 in cluster B**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	KING OF QUEENS AUTO SERVICES CORP.
Address:	38-03 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611279
Program Type:	PBS
UTM X:	588703.02778

KING OF QUEENS AUTO SERVICES CORP. (Continued) **A100349541**

UTM Y: 4510672.44894
Expiration Date: 03/12/2025
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 425842
Affiliation Type: Facility Owner
Company Name: LUPO REALTY CO.
Contact Type: PRESIDENT
Contact Name: JOHN PALADINI
Address1: 1008 CEDAR PARK DRIVE
Address2: Not reported
City: CEDAR PARK
State: TX
Zip Code: 78613
Country Code: 001
Phone: (516) 449-3759
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2022-04-12

Site Id: 425842
Affiliation Type: Emergency Contact
Company Name: KING OF QUEENS AUTO SERVICES CORP.
Contact Type: Not reported
Contact Name: JOHN PALADINI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 786-0010
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2022-04-12

Site Id: 425842
Affiliation Type: Facility Operator
Company Name: NEW USA AUTO BODY SHOP INC.
Contact Type: Not reported
Contact Name: JOHN PALADINI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 786-0010
EMail: Not reported
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2022-04-12

Site Id: 425842
Affiliation Type: Mail Contact

KING OF QUEENS AUTO SERVICES CORP. (Continued) **A100349541**

Company Name:	KING OF QUEENS AUTO SERVICES CORP.
Contact Type:	Not reported
Contact Name:	JOHN PALADINI
Address1:	38-03 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-0010
EMail:	JOHNEPALADINICPA@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-04-12

Tank Info:

Tank Number:	001
Tank Id:	233328
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G02 - Tank Secondary Containment - Vault (w/access)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2010
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	294929

Equipment Records:

H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None

KING OF QUEENS AUTO SERVICES CORP. (Continued) **A100349541**

I04 - Overfill - Product Level Gauge (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
J02 - Dispenser - Suction Dispenser
G02 - Tank Secondary Containment - Vault (w/access)
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/2018
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

B49 **KING OF QUEENS AUTO SERVICE CORP.** **NY AST** **A100511783**
SW **3803 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.051 mi.
270 ft. **Site 22 of 22 in cluster B**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	KING OF QUEENS AUTO SERVICE CORP.
Address:	3803 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-613200
Program Type:	PBS
UTM X:	Not reported
UTM Y:	Not reported
Expiration Date:	11/13/2025
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	613191
Affiliation Type:	Facility Owner
Company Name:	LUPO REALTY CO.
Contact Type:	PRESIDENT
Contact Name:	JOHN PALADINI
Address1:	1008 CEDAR PARK DRIVE
Address2:	Not reported
City:	CEDAR PARK
State:	TX
Zip Code:	78613-2140
Country Code:	001
Phone:	(631) 385-9354

KING OF QUEENS AUTO SERVICE CORP. (Continued) **A100511783**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-13

Site Id:	613191
Affiliation Type:	Mail Contact
Company Name:	KING OF QUEENS AUTO SERVICE CORP.
Contact Type:	Not reported
Contact Name:	JOHN PALADINI
Address1:	3803 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(347) 507-
EMail:	JOHN E PALADINI@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-13

Site Id:	613191
Affiliation Type:	Facility Operator
Company Name:	KING OF QUEENS AUTO SERVICE CORP.
Contact Type:	Not reported
Contact Name:	JOHN PALADINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-13

Site Id:	613191
Affiliation Type:	Emergency Contact
Company Name:	LUPO REALTY CO.
Contact Type:	Not reported
Contact Name:	JOHN PALADINI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(631) 568-4451
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-11-13

KING OF QUEENS AUTO SERVICE CORP. (Continued) **A100511783**

Tank Info:

Tank Number:	001
Tank Id:	287897

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2018
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	287898

Equipment Records:

D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	11/01/2018
Capacity Gallons:	250

KING OF QUEENS AUTO SERVICE CORP. (Continued) **A100511783**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

E50 **22-11 38TH AVE** **NY UST** **U004045212**
SSE **22-11 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.052 mi.
277 ft. **Site 1 of 7 in cluster E**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	22-11 38TH AVE
Address:	22-11 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-607916 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588736.89039
UTM Y:	4511665.36616
Site Type:	Other

Affiliation Records:

Site Id:	29768
Affiliation Type:	Facility Owner
Company Name:	JOAN GALLANT/ MICHAEL ROSEN C/O LTD MANAGEMENT
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	19-02 WHITESTONE EXPRESSWAY SUITE 405
Address2:	Not reported
City:	WHITESTONE
State:	NY
Zip Code:	11357
Country Code:	001
Phone:	(718) 747-8700
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29768
Affiliation Type:	Mail Contact
Company Name:	MCLAUGHLIN & STERN LLP
Contact Type:	Not reported
Contact Name:	PETER S. HERMAN
Address1:	260 MADISON AVENUE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10016
Country Code:	001
Phone:	(212) 448-6212

22-11 38TH AVE (Continued) **U004045212**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29768
Affiliation Type:	Facility Operator
Company Name:	22-11 38TH AVE
Contact Type:	Not reported
Contact Name:	WAREHOUSE DISTRIBUTORS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-4060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29768
Affiliation Type:	Emergency Contact
Company Name:	JOAN GALLANT/ MICHAEL ROSEN C/O LTD MANAGEMENT
Contact Type:	Not reported
Contact Name:	WAREHOUSE DISTRIBUTORS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-4060
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	#1
Tank ID:	63826
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	07/09/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported

22-11 38TH AVE (Continued) **U004045212**

Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J00 - Dispenser - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

E51 **CON EDISON** **RCRA NonGen / NLR** **1019909427**
SSE **22-11 38TH AVE** **FINDS** **NYP004884694**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.052 mi.
277 ft. **Site 2 of 7 in cluster E**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20151229
Handler Name:	Con Edison
Handler Address:	22-11 38TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004884694
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

CON EDISON (Continued) **1019909427**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151229
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151229
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

CON EDISON (Continued) **1019909427**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069661486

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019909427
Registry ID: 110069661486
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069661486
Name: CON EDISON
Address: 22-11 38TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11101

E52 **CON EDISON** **NJ MANIFEST** **S120678573**
SSE **22-11 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.052 mi.
277 ft. **Site 3 of 7 in cluster E**

Relative: **Higher**
Actual: **18 ft.**

NJ MANIFEST:
EPA Id: NYP004884694
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY081
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported

CON EDISON (Continued) **S120678573**

TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014086081JJK
EPA ID:	NYP004884694
Date Shipped:	12/29/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C53 **CON EDISON** **NJ MANIFEST** **S120678121**
ESE **22-08 37TH AVE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.053 mi.
278 ft. **Site 6 of 18 in cluster C**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004879072
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003

Actual:
18 ft.

CON EDISON (Continued) **S120678121**

Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015320906JJK
EPA ID:	NYP004879072
Date Shipped:	12/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C54 **QUALITY CAR TECH INC.** **NY AST** **A100295812**
ESE **22-08 37TH AVENUE** **N/A**
< 1/8 **QUEENS, NY 11101**
0.053 mi.
278 ft. **Site 7 of 18 in cluster C**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	QUALITY CAR TECH INC.
Address:	22-08 37TH AVENUE
City,State,Zip:	QUEENS, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609179
Program Type:	PBS
UTM X:	589729.64293
UTM Y:	4512453.43849
Expiration Date:	04/17/2027
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	31024
Affiliation Type:	Facility Owner
Company Name:	BOHEMIA 22, LLC
Contact Type:	EXEC. ASSISTANT
Contact Name:	ALEXANDER MILLER
Address1:	2553 EAST 6TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235
Country Code:	001
Phone:	(718) 646-7057
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-10-28

Site Id:	31024
Affiliation Type:	Facility Operator
Company Name:	QUALITY CAR TECH INC.
Contact Type:	Not reported
Contact Name:	PARVINDAR MATHARU
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-2160
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-10-28

Site Id:	31024
Affiliation Type:	Mail Contact
Company Name:	ROBERT MILLER / BOHEMIA 22, LLC
Contact Type:	Not reported
Contact Name:	PARVINDAR MATHARU

QUALITY CAR TECH INC. (Continued) **A100295812**

Address1:	2553 EAST 6TH STREET
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235
Country Code:	001
Phone:	(718) 646-7057
EMail:	MONTDALE@VERIZON.NET
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Site Id:	31024
Affiliation Type:	Emergency Contact
Company Name:	BOHEMIA 22, LLC
Contact Type:	Not reported
Contact Name:	ALEXANDER LOUIE MILLER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 538-8187
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2022-03-03

Tank Info:

Tank Number:	001
Tank Id:	66672
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J00 - Dispenser - None
E01 - Piping Secondary Containment - Diking (AG only)

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/01/1997
Capacity Gallons:	275
Tightness Test Method:	-

QUALITY CAR TECH INC. (Continued) **A100295812**

Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C55 **CON EDISON** **RCRA NonGen / NLR** **1019908924**
ESE **22-08 37TH AVE** **ECHO** **NYP004879072**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.053 mi.
278 ft. **Site 8 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20151214
Handler Name:	Con Edison
Handler Address:	22-08 37TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004879072
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N

CON EDISON (Continued) **1019908924**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220919
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151214
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151214
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

CON EDISON (Continued) **1019908924**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

ECHO:
Envid: 1019908924
Registry ID: 110069701139
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069701139
Name: CON EDISON
Address: 22-08 37TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11101

C56 **BELLO LNG ISLND CY ATO RPR** **EDR Hist Auto** **1021018158**
ESE **22-08 37TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.053 mi.
278 ft. **Site 9 of 18 in cluster C**

Relative: EDR Hist Auto
Higher

Actual: **18 ft.**

Year:	Name:	Type:
1991	BLACK & YELLOW AUTO TEC INC	General Automotive Repair Shops
1992	BLACK & YELLOW AUTO TEC INC	General Automotive Repair Shops
1993	BLACK & YELLOW AUTO TEC INC	General Automotive Repair Shops
1994	BELLO LNG ISLND CY ATO RPR	General Automotive Repair Shops
1994	BLACK & YELLOW AUTO TEC INC	General Automotive Repair Shops
1995	BELLO LNG ISLND CY ATO RPR	General Automotive Repair Shops
1995	BLACK & YELLOW AUTO TEC INC	General Automotive Repair Shops
1996	BELLO LONG ISLAND CY AUTO REPR	General Automotive Repair Shops
1997	BELLO LONG ISLAND CY AUTO REPR	General Automotive Repair Shops
2001	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2002	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2003	RMR TRANSMISSION CORP	Automotive Transmission Repair Shops
2003	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2004	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2004	RMR TRANSMISSION CORP	Automotive Transmission Repair Shops
2005	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2005	RMR TRANSMISSION CORP	Automotive Transmission Repair Shops
2005	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2006	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2006	RMR TRANSMISSION CORP	Automotive Transmission Repair Shops
2006	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2007	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2007	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2008	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2008	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2009	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2009	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2010	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2010	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2011	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2011	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2012	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops

BELLO LNG ISLND CY ATO RPR (Continued) **1021018158**

2012	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2013	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops
2013	THIRTY SEVENTH AVE AUTO REPAIR	General Automotive Repair Shops
2014	PAL AUTO REPAIR & BODY SHOP IN	General Automotive Repair Shops

---

C57 **G. CHANAB AUTO & BODY INC** **NY AST** **A100294115**
East **22-01 37TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.054 mi.
285 ft. **Site 10 of 18 in cluster C**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	G. CHANAB AUTO & BODY INC
Address:	22-01 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607943
Program Type:	PBS
UTM X:	589734.83258
UTM Y:	4512463.40567
Expiration Date:	07/22/2007
Site Type:	Other

Affiliation Records:

Site Id:	29795
Affiliation Type:	Facility Owner
Company Name:	SHAIDA PARVEEN
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	2679 ATLANTIC AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11207
Country Code:	001
Phone:	(718) 485-1012
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-12-12

Site Id:	29795
Affiliation Type:	Mail Contact
Company Name:	G. CHANAB AUTO & BODY INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	22-01 37 AVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 937-7117
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT

G. CHANAB AUTO & BODY INC (Continued) **A100294115**

Date Last Modified:	2004-03-04
Site Id:	29795
Affiliation Type:	Facility Operator
Company Name:	G. CHANAB AUTO & BODY INC
Contact Type:	Not reported
Contact Name:	MOHAMMAD BASHIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-7117
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29795
Affiliation Type:	Emergency Contact
Company Name:	SHAIDA PARVEEN
Contact Type:	Not reported
Contact Name:	MOHAMMAD BASHIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 805-6397
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	63894
Material Code:	2642
Common Name of Substance:	Used Oil (Heating, On-Site Consumption)

Equipment Records:

	C01 - Pipe Location - Aboveground
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G00 - Tank Secondary Containment - None
	B00 - Tank External Protection - None
	F00 - Pipe External Protection - None
	J01 - Dispenser - Pressurized Dispenser
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron

G. CHANAB AUTO & BODY INC (Continued) **A100294115**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	used oil (heating, on-site consumption)

F58 **SAVEWAY ASTORIA INC** **EDR Hist Auto** **1021156554**
SW **3802 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.058 mi.
305 ft. **Site 1 of 9 in cluster F**

Relative: EDR Hist Auto
Higher

Actual:
17 ft.

Year:	Name:	Type:
1969	M S R OLYMPIC CORP	Gasoline Service Stations
1970	M S R OLYMPIC CORP	Gasoline Service Stations
1971	M S R OLYMPIC CORP	Gasoline Service Stations
1972	M S R OLYMPIC CORP	Gasoline Service Stations
1973	M S R OLYMPIC CORP	Gasoline Service Stations
1974	M S R OLYMPIC CORP	Gasoline Service Stations
1975	M S R OLYMPIC CORP	Gasoline Service Stations
1992	SAVEWAY ASTORIA INC	Gasoline Service Stations
1993	SAVEWAY ASTORIA INC	Gasoline Service Stations
1994	SAVEWAY ASTORIA INC	Gasoline Service Stations

F59 **MERIT OIL CORP** **RCRA NonGen / NLR** **1000263802**
SW **3802 21ST ST** **US AIRS** **NYD982185977**
< 1/8 **ASTORIA, NY 11101**
0.058 mi.
305 ft. **Site 2 of 9 in cluster F**

Relative: RCRA Listings:
Higher

Actual:
17 ft.

Date Form Received by Agency:	20070101
Handler Name:	Merit Oil Corp
Handler Address:	3802 21ST ST
Handler City,State,Zip:	ASTORIA, NY 11101-3604
EPA ID:	NYD982185977
Contact Name:	Not reported
Contact Address:	W LANCASTER AVE
Contact City,State,Zip:	HAVERFORD, NY 19041
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

MERIT OIL CORP (Continued) **1000263802**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	W LANCASTER AVE
Mailing City,State,Zip:	HAVERFORD, NY 19041
Owner Name:	Merit Oil Corp
Owner Type:	Private
Operator Name:	Merit Oil Corp
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

MERIT OIL CORP (Continued) **1000263802**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MERIT OIL CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: MERIT OIL CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

MERIT OIL CORP (Continued) **1000263802**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19870511
Handler Name: MERIT OIL CORP
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

US AIRS MINOR:
Envid: 1000263802
Region Code: 02
Programmatic ID: AIR NY0000002630400211
Facility Registry ID: 110001581556
D and B Number: Not reported
Primary SIC Code: 5541
NAICS Code: 999999
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported

MERIT OIL CORP (Continued) **1000263802**

HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002630400211
Facility Registry ID: 110001581556
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

F60 **SHELL SERVICE STATION** **NY UST** **U001835739**
SW **38-02 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.058 mi.
305 ft. **Site 3 of 9 in cluster F**

Relative:
Higher

Actual:
17 ft.

UST:
Name: SHELL SERVICE STATION
Address: 38-02 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-297674 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 01/12/2025
UTM X: 589543.09471
UTM Y: 4512376.91638
Site Type: Retail Gasoline Sales

Affiliation Records:
Site Id: 13757
Affiliation Type: Mail Contact
Company Name: 38-02 21ST ST GASOLINE CORP.
Contact Type: Not reported
Contact Name: CARY WOLF
Address1: 100 JERICHO QUADRANGLE
Address2: SUITE 209
City: JERICHO
State: NY
Zip Code: 11753
Country Code: 001
Phone: (516) 997-9300
EMail: CWOLF@BWPETROLEUM.COM
Fax Number: Not reported
Modified By: DAFRANCI
Date Last Modified: 2017-09-26

Site Id: 13757
Affiliation Type: Emergency Contact
Company Name: 38-02 21ST STREET GASOLINE CORP
Contact Type: Not reported
Contact Name: CARY WOLF
Address1: Not reported

SHELL SERVICE STATION (Continued) **U001835739**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 997-9300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JMKRIMGO
Date Last Modified:	2006-03-30

Site Id:	13757
Affiliation Type:	Facility Operator
Company Name:	SHELL SERVICE STATION
Contact Type:	Not reported
Contact Name:	SYED HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 433-0478
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-09-26

Site Id:	13757
Affiliation Type:	Facility Owner
Company Name:	38-02 21ST STREET GASOLINE CORP.
Contact Type:	PRESIDENT
Contact Name:	CARY WOLF
Address1:	100 JERICHO QUADRANGLE, SUITE 209
Address2:	Not reported
City:	JERICHO
State:	NY
Zip Code:	11753
Country Code:	001
Phone:	(516) 997-9300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-10-25

Tank Info:

Tank Number:	001
Tank ID:	57568
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	12/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology

SHELL SERVICE STATION (Continued) **U001835739**

Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TankSys
Last Modified: 12/15/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
L99 - Piping Leak Detection - Other
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Tank Number: 002
Tank ID: 57569
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 10000
Install Date: 12/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TankSys
Last Modified: 12/15/2022

Equipment Records:

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
L99 - Piping Leak Detection - Other

SHELL SERVICE STATION (Continued) **U001835739**

H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	57570
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	10000
Install Date:	12/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2710
Common Name of Substance:	Biodiesel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	TankSys
Last Modified:	12/15/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
L99 - Piping Leak Detection - Other
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser

Tank Number:	0A1
Tank ID:	15950
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

SHELL SERVICE STATION (Continued) **U001835739**

Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 0A2
Tank ID: 15951
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 0A3
Tank ID: 15952
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN

SHELL SERVICE STATION (Continued) **U001835739**

Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

Tank Number: 0A4
Tank ID: 15953
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 0A5
Tank ID: 15954
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel

SHELL SERVICE STATION (Continued) **U001835739**

Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 0A6
Tank ID: 15955
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: 0A7
Tank ID: 15956
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969

SHELL SERVICE STATION (Continued) **U001835739**

Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 0A8
Tank ID: 15957
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: 0W7
Tank ID: 15949

SHELL SERVICE STATION (Continued) **U001835739**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	04/01/1981
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	33
Tank ID:	15943
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	04/01/1981
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
J02 - Dispenser - Suction Dispenser

SHELL SERVICE STATION (Continued) **U001835739**

C02 - Pipe Location - Underground/On-ground

Tank Number: 34
Tank ID: 15944
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 04/01/1981
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: 35
Tank ID: 15945
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 04/01/1981
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

SHELL SERVICE STATION (Continued) **U001835739**

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	36
Tank ID:	15946
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	4000
Install Date:	04/01/1981
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other

Tank Number:	37
Tank ID:	15947
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	04/01/1981
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	20
Date Test:	04/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported

SHELL SERVICE STATION (Continued) **U001835739**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser

Tank Number: 38
Tank ID: 15948
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 04/01/1981
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G99 - Tank Secondary Containment - Other

Tank Number: 42
Tank ID: 43891
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 12/01/1991
Date Tank Closed: 12/01/1998
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 9999

SHELL SERVICE STATION (Continued) **U001835739**

Common Name of Substance: Other

Tightness Test Method: 20
Date Test: 04/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J00 - Dispenser - None
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I00 - Overfill - None
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
G04 - Tank Secondary Containment - Double-Walled (Underground)
H99 - Tank Leak Detection - Other

Tank Number: A16
Tank ID: 15958
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: A17
Tank ID: 15959
Tank Status: Closed - Removed
Material Name: Closed - Removed

SHELL SERVICE STATION (Continued) **U001835739**

Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Number:	A18
Tank ID:	15960
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

SHELL SERVICE STATION (Continued) **U001835739**

Tank Number:	A19
Tank ID:	15961
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	A20
Tank ID:	15962
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None

SHELL SERVICE STATION (Continued) **U001835739**

I00 - Overfill - None
D00 - Pipe Type - No Piping

Tank Number: A21
Tank ID: 15963
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: A22
Tank ID: 15964
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

SHELL SERVICE STATION (Continued) **U001835739**

F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	A23
Tank ID:	15965
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	A24
Tank ID:	15966
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

SHELL SERVICE STATION (Continued) **U001835739**

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

Tank Number:	A25
Tank ID:	15967
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number:	A26
Tank ID:	15968
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported

SHELL SERVICE STATION (Continued) **U001835739**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: A27
Tank ID: 15969
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: A28
Tank ID: 15970
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999

SHELL SERVICE STATION (Continued) **U001835739**

Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Number: A29
Tank ID: 15971
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

Tank Number: A30
Tank ID: 15973
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999

SHELL SERVICE STATION (Continued) **U001835739**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number: A31
Tank ID: 15974
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number: A32
Tank ID: 15975
Tank Status: Closed - Removed

SHELL SERVICE STATION (Continued) **U001835739**

Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	A33
Tank ID:	15976
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

SHELL SERVICE STATION (Continued) **U001835739**

Tank Number:	A34
Tank ID:	15977
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	A35
Tank ID:	15978
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

SHELL SERVICE STATION (Continued) **U001835739**

D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

Tank Number: A36
Tank ID: 15979
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

Tank Number: A37
Tank ID: 15980
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1969
Date Tank Closed: 12/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None

SHELL SERVICE STATION (Continued) **U001835739**

I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	A38
Tank ID:	15981
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	A39
Tank ID:	15982
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1969
Date Tank Closed:	12/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

SHELL SERVICE STATION (Continued) **U001835739**

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number:	OF8
Tank ID:	15972
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	12/01/1991
Date Tank Closed:	01/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	OL10
Tank ID:	43892
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	275
Install Date:	10/01/1969
Date Tank Closed:	12/01/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0013
Common Name of Substance:	Lube Oil
Tightness Test Method:	ZZ
Date Test:	12/01/1991

SHELL SERVICE STATION (Continued) **U001835739**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G04 - Tank Secondary Containment - Double-Walled (Underground)
J00 - Dispenser - None
K01 - Spill Prevention - Catch Basin
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
A00 - Tank Internal Protection - None

C61 **A1 COLLISION INC.** **NY AST** **A100462490**
East **2207 37 AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.061 mi.
320 ft. **Site 11 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

AST:
Name: A1 COLLISION INC.
Address: 2207 37 AVE
City,State,Zip: LONG ISLAND CITY, NY 11101
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-612877
Program Type: PBS
UTM X: Not reported
UTM Y: Not reported
Expiration Date: 04/13/2023
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 568947
Affiliation Type: Facility Owner
Company Name: MORNING GLORY 37TH REALTY LLC
Contact Type: Not reported
Contact Name: Not reported
Address1: 82 EENCLID ST
Address2: Not reported
City: VALLEY STREAM
State: NY
Zip Code: 11580
Country Code: 001
Phone: (917) 951-5513
EMail: Not reported
Fax Number: Not reported
Modified By: TLYE
Date Last Modified: 2018-04-13

Site Id: 568947
Affiliation Type: Mail Contact
Company Name: Not reported
Contact Type: Not reported
Contact Name: DABARA SINGH

A1 COLLISION INC. (Continued) **A100462490**

Address1:	2207 37TH AVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 392-1101
EMail:	YUGANTAR@YAHOO.COM
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2018-04-13

Site Id:	568947
Affiliation Type:	Facility Operator
Company Name:	A1 COLLISION INC.
Contact Type:	Not reported
Contact Name:	DABARA SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-1101
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2018-04-13

Site Id:	568947
Affiliation Type:	Emergency Contact
Company Name:	MORNING GLORY 37TH REALTY LLC
Contact Type:	Not reported
Contact Name:	DABARA SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 902-9536
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TLYE
Date Last Modified:	2018-04-13

Tank Info:

Tank Number:	001
Tank Id:	275750

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping
E00 - Piping Secondary Containment - None
L00 - Piping Leak Detection - None

A1 COLLISION INC. (Continued) **A100462490**

G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2013
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

D62 **ULTIMATE AUTO CARE** **NY AST** **A100296234**
NNE **36-37 21ST STREET** **N/A**
< 1/8 **ASTORIA, NY 11106**
0.062 mi.
325 ft. **Site 3 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	ULTIMATE AUTO CARE
Address:	36-37 21ST STREET
City,State,Zip:	ASTORIA, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-188484
Program Type:	PBS
UTM X:	589712.60856
UTM Y:	4512593.00925
Expiration Date:	06/05/2027
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	5706
Affiliation Type:	Mail Contact
Company Name:	ULTIMATE AUTO CARE
Contact Type:	Not reported
Contact Name:	MIHALIS BOUKAS
Address1:	36-37 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 392-2757
EMail:	ULTIMATEAUTO21@GMAIL.COM
Fax Number:	Not reported

ULTIMATE AUTO CARE (Continued) **A100296234**

Modified By:	JSMACRI
Date Last Modified:	2022-08-31
Site Id:	5706
Affiliation Type:	Facility Operator
Company Name:	T&V AUTO SERVICE
Contact Type:	Not reported
Contact Name:	ULTIMATE AUTO CARE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-2757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31
Site Id:	5706
Affiliation Type:	Emergency Contact
Company Name:	THEODOSSIOS PONTIKIS
Contact Type:	Not reported
Contact Name:	MIHALIS BOUKAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 406-2118
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31
Site Id:	5706
Affiliation Type:	Facility Owner
Company Name:	T & V AUTO SERVICE CENTER, INC.
Contact Type:	BUSINESS OWNWER/ PRES
Contact Name:	MIHALIS BOUKAS
Address1:	204 NEWBURGH AVENUE
Address2:	Not reported
City:	MEDFORD
State:	NY
Zip Code:	11763
Country Code:	001
Phone:	(718) 392-2757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31

Tank Info:

Tank Number:	004

ULTIMATE AUTO CARE (Continued) **A100296234**

Tank Id: 180481
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

G00 - Tank Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 07/01/2009
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: JSMACRI
Last Modified: 08/31/2022
Material Name: waste oil/used oil

D63 **ULTIMATE AUTO CARE OF 21 ST** **EDR Hist Auto** **1020629450**
NNE **3637 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.062 mi.
325 ft. **Site 4 of 13 in cluster D**

Relative: **Higher**

EDR Hist Auto

Actual: **17 ft.**

Year:	Name:	Type:
1982	T & V AUTO SERVICE INC	Gasoline Service Stations
1983	T & V AUTO SERVICE INC	Gasoline Service Stations
1985	T & V AUTO SERVICE INC	Gasoline Service Stations
1986	T & V AUTO SERVICE INC	Gasoline Service Stations
1987	T & V AUTO SERVICE INC	Gasoline Service Stations
1988	T & V AUTO SERVICE INC	Gasoline Service Stations
1989	T & V AUTO SERVICE INC	Gasoline Service Stations
1991	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1992	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1993	T & V AUTO SERVICE INC	Gasoline Service Stations
1993	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1994	T & V AUTO SERVICE INC	Gasoline Service Stations
1994	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1995	T & V AUTO SERVICE INC	Gasoline Service Stations
1995	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1996	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1996	T & V AUTO SERVICE INC	Gasoline Service Stations

ULTIMATE AUTO CARE OF 21 ST (Continued) **1020629450**

1997	ULTIMATE AUTO CARE OF 21ST ST	General Automotive Repair Shops
1998	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
1999	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2000	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2001	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2002	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2003	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2004	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2005	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2006	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2007	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2008	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2009	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2010	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2011	ULTIMATE AUTO CARE OF 21 ST	Gasoline Service Stations, NEC
2012	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2013	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops
2014	ULTIMATE AUTO CARE OF 21 ST	General Automotive Repair Shops

---

D64 **ULTIMATE AUTO CARE** **NY UST** **U004314605**
NNE **36-37 21ST STREET** **N/A**
< 1/8 **ASTORIA, NY 11106**
0.062 mi.
325 ft. **Site 5 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	ULTIMATE AUTO CARE
Address:	36-37 21ST STREET
City,State,Zip:	ASTORIA, NY 11106
Id/Status:	2-188484 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	06/05/2027
UTM X:	589712.60856
UTM Y:	4512593.00925
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	5706
Affiliation Type:	Mail Contact
Company Name:	ULTIMATE AUTO CARE
Contact Type:	Not reported
Contact Name:	MIHALIS BOUKAS
Address1:	36-37 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 392-2757
EMail:	ULTIMATEAUTO21@GMAIL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31

Site Id:	5706
Affiliation Type:	Facility Operator

ULTIMATE AUTO CARE (Continued) **U004314605**

Company Name:	T&V AUTO SERVICE
Contact Type:	Not reported
Contact Name:	ULTIMATE AUTO CARE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-2757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31

Site Id:	5706
Affiliation Type:	Emergency Contact
Company Name:	THEODOSSIOS PONTIKIS
Contact Type:	Not reported
Contact Name:	MIHALIS BOUKAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 406-2118
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31

Site Id:	5706
Affiliation Type:	Facility Owner
Company Name:	T & V AUTO SERVICE CENTER, INC.
Contact Type:	BUSINESS OWNWER/ PRES
Contact Name:	MIHALIS BOUKAS
Address1:	204 NEWBURGH AVENUE
Address2:	Not reported
City:	MEDFORD
State:	NY
Zip Code:	11763
Country Code:	001
Phone:	(718) 392-2757
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-31

Tank Info:

Tank Number:	001
Tank ID:	5886
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	12/01/1971

ULTIMATE AUTO CARE (Continued) **U004314605**

Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 08/26/2014
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 08/31/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
D02 - Pipe Type - Galvanized Steel
G99 - Tank Secondary Containment - Other
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
C02 - Pipe Location - Underground/On-ground
J02 - Dispenser - Suction Dispenser
F08 - Pipe External Protection - Retrofitted Impressed Current
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Number: 002
Tank ID: 5887
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2000
Install Date: 12/01/1971
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 21
Date Test: 08/26/2014
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 08/31/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
I02 - Overfill - High Level Alarm

ULTIMATE AUTO CARE (Continued) **U004314605**

L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

Tank Number:	003
Tank ID:	5888
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	12/01/1971
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	21
Date Test:	08/26/2014
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	08/31/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G99 - Tank Secondary Containment - Other
A03 - Tank Internal Protection - Fiberglass Liner (FRP)
B08 - Tank External Protection - Retrofitted Impressed Current
D02 - Pipe Type - Galvanized Steel
F08 - Pipe External Protection - Retrofitted Impressed Current
I02 - Overfill - High Level Alarm
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

G65 **36-28 14TH STREET** **NY Spills** **S102146857**
North **36-28 14TH STREET** **N/A**
< 1/8 **QUEENS, NY**
0.062 mi.
329 ft. **Site 1 of 9 in cluster G**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:

Name:	36-28 14TH STREET
Address:	36-28 14TH STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9305907 / 2006-08-31
Facility ID:	9305907
Facility Type:	ER
DER Facility ID:	133968
Site ID:	158536
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	B3
SWIS:	4101
Spill Date:	1993-08-12
Investigator:	RWAUSTIN

36-28 14TH STREET (Continued) **S102146857**

Referred To:	Not reported
Reported to Dept:	1993-08-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2006-08-31
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-19
Spill Record Last Update:	2006-09-14
Spiller Name:	Not reported
Spiller Company:	AAA OIL POLLUTION SPECIAL
Spiller Address:	39-44 PURVES ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN DEC INSPECTOR NOTES This is additional information about material spilled from the translation of the old spill file: PCBs 3/23/04 - AUSTIN - ORIG. ASSIGNED TO ENGELHARDT - NEEDS REVIEW OF FILES TO DETERMINE STATUS OF THIS SITE, A FORMER CLEANUP CONTRACTOR'S YARD - END 8/31/06 - Austin - Checked site, found walled in wrecking yard - reassigned spill to Ketani under Spill # 9306917, for inspection of wrecking yard - see that spill report - Spill # 9305907 closed and referred to #9306917 - end"
Remarks:	"ANONYMOUS LETTER RECEIVED COMPLAING THAT AAA HAS BEEN DUMPING WASTE OIL @ THE FACILITY. FOUND THERE TO BE CONTAMINATED SOIL AND SPEEDY DRY A SITE. ALEX ISELOR ARRANGED TO HAVE AAA REMOVE CONTAMINATED"

All Materials:

Site ID:	158536
Operable Unit ID:	984063
Operable Unit:	01
Material ID:	395809
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D66 **CON EDISON - SERVICE BOX 7568** **RCRA-LQG** **1024891370**
ENE **36-40 22ND ST** **NYP005102660**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.063 mi.
334 ft. **Site 6 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Service Box 7568
Handler Address:	36-40 22ND ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYP005102660
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON - SERVICE BOX 7568 (Continued) **1024891370**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170626
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170626
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX 7568
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny

CON EDISON - SERVICE BOX 7568 (Continued) **1024891370**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	221122
NAICS Description:	ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

D67 **CON EDISON - SERVICE BOX 7568** **NY MANIFEST** **S121968293**
ENE **36-40 22ND ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.063 mi.
334 ft. **Site 7 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 7568
Address:	36-40 22ND ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYP005102660
Facility Status:	Not reported
Location Address 1:	36-40 22ND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005102660
Mailing Name:	CON EDISON - SERVICE BOX 7568
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

D68 **VIVIENNE SOIL REMOVAL** **NY MANIFEST** **S122483133**
NNE **36-22 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.064 mi.
339 ft. **Site 8 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	VIVIENNE SOIL REMOVAL
Address:	36-22 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYR000235325
Facility Status:	Not reported
Location Address 1:	36-22 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000235325
Mailing Name:	VIVIENNE SOIL REMOVAL
Mailing Contact:	VIVIENNE REALTY LLC
Mailing Address 1:	42-50 24TH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5165768844

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR986653780
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2018
Trans1 Recv Date:	06/12/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/12/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000235325
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	018863328JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N

VIVIENNE SOIL REMOVAL (Continued) **S122483133**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30440
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D69 **VIVIENNE REALTY LLC** **RCRA NonGen / NLR** **1024891952**
NNE **36-22 21ST ST** **NYR000235325**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.064 mi.
339 ft. **Site 9 of 13 in cluster D**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20190503
Handler Name:	Vivienne Realty Llc
Handler Address:	36-22 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYR000235325
Contact Name:	THOMAS BROWN
Contact Address:	DUPONT ST
Contact City,State,Zip:	PLAINVIEW, NY 11830
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	24TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Not reported
Owner Type:	Not reported

VIVIENNE REALTY LLC (Continued) **1024891952**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20211228
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: VIVIENNE REALTY LLC	
Legal Status:	Private
Date Became Current:	20160101
Date Ended Current:	Not reported
Owner/Operator Address:	42-50 24TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101

VIVIENNE REALTY LLC (Continued) **1024891952**

Owner/Operator Telephone: 718-937-2080
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: VIVIENNE REALTY LLC
Legal Status: Private
Date Became Current: 20160101
Date Ended Current: Not reported
Owner/Operator Address: 42-50 24TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-937-2080
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20190503
Handler Name: VIVIENNE REALTY LLC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20180314
Handler Name: VIVIENNE REALTY LLC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 236220
NAICS Description: COMMERCIAL AND INSTITUTIONAL BUILDING CONSTRUCTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

F70 **38-11 21TH ST.** **NY Spills** **S102147670**
SSW **38011 21TH ST.** **N/A**
< 1/8 **ASTORIA, NY**
0.066 mi.
351 ft. **Site 4 of 9 in cluster F**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	38-11 21TH ST.
Address:	38011 21TH ST.
City,State,Zip:	ASTORIA, NY
Spill Number/Closed Date:	9312713 / 1994-04-13
Facility ID:	9312713
Facility Type:	ER
DER Facility ID:	72630
Site ID:	77944
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	4101
Spill Date:	1994-01-28
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1994-01-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-31
Spill Record Last Update:	1998-01-26
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/10/95: This is additional information about material spilled from the translation of the old spill file: CRUDE OIL ~4' DEEP. CLEANED BY NYNEX."
Remarks:	"CLEAN UP VENDOR CLEAN HARBORS (908)248-1997 - SHOULD BE ON SITE 1600 HRS."

All Materials:

Site ID:	77944
Operable Unit ID:	994699
Operable Unit:	01
Material ID:	570132
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00

38-11 21TH ST. (Continued) **S102147670**

Resource Affected: Sewer
Oxygenate: Not reported

G71 **PROMO-PRO LTD** **RCRA NonGen / NLR** **1004762131**
NNW **13-07 37TH AVE TRANSPORTER** **NYR000093849**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.067 mi.
356 ft. **Site 2 of 9 in cluster G**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20170525
Handler Name:	Promo-Pro Ltd
Handler Address:	13-07 37TH AVE TRANSPORTER
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000093849
Contact Name:	GEORGE MILTIADOUS
Contact Address:	37TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-937-7272
Contact Fax:	Not reported
Contact Email:	GEORGE@PROMOPRO.US
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	37TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	George Miltiadous
Owner Type:	Private
Operator Name:	George Miltiadous
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

PROMO-PRO LTD (Continued) **1004762131**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170831
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: GEORGE MILTIADOUS	
Legal Status:	Private
Date Became Current:	19881005
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GEORGE MILTIADOUS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	22-26 35TH ST
Owner/Operator City,State,Zip:	ASTORIA, NY 11105
Owner/Operator Telephone:	917-939-0019
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GEORGE MILTIADOUS	
Legal Status:	Private
Date Became Current:	19881005
Date Ended Current:	Not reported

PROMO-PRO LTD (Continued) **1004762131**

Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GEORGE MILTIADOUS
Legal Status: Private
Date Became Current: 19881005
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GEORGE MILTIADOUS
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 22-26 35TH ST
Owner/Operator City,State,Zip: ASTORIA, NY 11105
Owner/Operator Telephone: 917-939-0019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GEORGE MILTIADOUS
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 22-26 35TH ST
Owner/Operator City,State,Zip: ASTORIA, NY 11105
Owner/Operator Telephone: 917-939-0019
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GEORGE MILTIADOUS
Legal Status: Private
Date Became Current: 19881005
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101

PROMO-PRO LTD (Continued) **1004762131**

Handler Name:	PROMO-PRO LTD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	PROMO-PRO LTD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20170525
Handler Name:	PROMO-PRO LTD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20010201
Handler Name:	PROMO-PRO LTD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20090731
Handler Name:	PROMO-PRO LTD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

PROMO-PRO LTD (Continued) **1004762131**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

G72 **ELIT GREEN BUILDERS CORP** **RCRA NonGen / NLR** **1004762130**
NNW **13-07 37TH AVE ROOM 103** **FINDS** **NYR000093831**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.067 mi.
356 ft. **Site 3 of 9 in cluster G**

Relative:
Lower

Actual:
16 ft.

RCRA Listings:
Date Form Received by Agency: 20091014
Handler Name: Elit Green Builders Corp
Handler Address: 13-07 37TH AVE ROOM 103
Handler City,State,Zip: LONG ISLAND CITY, NY 11101
EPA ID: NYR000093831
Contact Name: ELISAVET TZOUMAKA
Contact Address: 37TH AVE
Contact City,State,Zip: LONG ISLAND CITY, NY 11101
Contact Telephone: 718-482-7262
Contact Fax: Not reported
Contact Email: ELISAVET@ELITGREENBUILDERS.US
Contact Title: OWNER
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: Ny
State District: NYSDEC R2
Mailing Address: 37TH AVE ROOM 103
Mailing City,State,Zip: LONG ISLAND CITY, NY 11101
Owner Name: Elisavet Tzoumaka
Owner Type: Private
Operator Name: Elisavet Tzoumaka
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: Yes

ELIT GREEN BUILDERS CORP (Continued) **1004762130**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: KONSTANTINOS TSIDAVIS	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	124-07 6TH AVE
Owner/Operator City,State,Zip:	COLLEGE POINT, NY 11356
Owner/Operator Telephone:	718-353-8551
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner

ELIT GREEN BUILDERS CORP (Continued) **1004762130**

Owner/Operator Name: ELISAVET TZOUMAKA
Legal Status: Private
Date Became Current: 20090430
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: KONSTANTINOS TSIDAVIS
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 124-07 6TH AVE
Owner/Operator City,State,Zip: COLLEGE POINT, NY 11356
Owner/Operator Telephone: 718-353-8551
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: KONSTANTINOS TSIDAVIS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 124-07 6TH AVE
Owner/Operator City,State,Zip: COLLEGE POINT, NY 11356
Owner/Operator Telephone: 718-353-8551
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ELISAVET TZOUMAKA
Legal Status: Private
Date Became Current: 20090430
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: PROMO-PRO CONSTRUCTION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

ELIT GREEN BUILDERS CORP (Continued) **1004762130**

Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PROMO-PRO CONSTRUCTION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010201
Handler Name: PROMO-PRO CONSTRUCTION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091014
Handler Name: ELIT GREEN BUILDERS CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:

ELIT GREEN BUILDERS CORP (Continued) **1004762130**

Registry ID: 110004566942

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762130
Registry ID:	110004566942
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004566942
Name:	ELIT GREEN BUILDERS CORP
Address:	13-07 37TH AVE ROOM 103
City,State,Zip:	LONG ISLAND CITY, NY 11101

G73 **ENVIRO CONTRACTING CORP** **RCRA NonGen / NLR** **1012187195**
NNW **13-07 37TH AVE ROOM 101** **NYR000170605**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.067 mi.
356 ft. **Site 4 of 9 in cluster G**

Relative: **Lower**

Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20170525
Handler Name:	Enviro Contracting Corp
Handler Address:	13-07 37TH AVE ROOM 101
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000170605
Contact Name:	ROSEMARIE TSIDAVIS
Contact Address:	37TH AVE ROOM 101
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-937-7208
Contact Fax:	Not reported
Contact Email:	RTSIDAVIS@YAHOO.COM
Contact Title:	OWNER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	37TH AVE ROOM 101
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Rosemarie Tsidavis
Owner Type:	Private
Operator Name:	Rosemarie Tsidavis
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

ENVIRO CONTRACTING CORP (Continued) **1012187195**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170622
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROSEMARIE TSIDAVIS	
Legal Status:	Private
Date Became Current:	20091015
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ENVIRO CONTRACTING CORP (Continued) **1012187195**

Owner/Operator Indicator: Operator
Owner/Operator Name: ROSEMARIE TSIDAVIS
Legal Status: Private
Date Became Current: 20091015
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROSEMARIE TSIDAVIS
Legal Status: Private
Date Became Current: 20091015
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ROSEMARIE TSIDAVIS
Legal Status: Private
Date Became Current: 20091015
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20170525
Handler Name: ENVIRO CONTRACTING CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20091119
Handler Name: ENVIRO CONTRACTING CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No

ENVIRO CONTRACTING CORP (Continued) **1012187195**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

C74 **AAD AUTO REPAIR & BODY SHOP INC.** **NY AST** **A100295201**
East **22-15 37TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.068 mi.
357 ft. **Site 12 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

AST:
Name: AAD AUTO REPAIR & BODY SHOP INC.
Address: 22-15 37TH AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-609381
Program Type: PBS
UTM X: 589742.66423
UTM Y: 4512458.06038
Expiration Date: 10/22/2020
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 31225
Affiliation Type: Mail Contact
Company Name: AAD AUTO REPAIR & BODY SHOP INC.
Contact Type: Not reported
Contact Name: SHAMSUL ALAM
Address1: 22-15 37TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 392-7977
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-10-22

Site Id: 31225
Affiliation Type: Facility Operator

AAD AUTO REPAIR & BODY SHOP INC. (Continued) **A100295201**

Company Name:	AAD AUTO REPAIR & BODY SHOP INC.
Contact Type:	Not reported
Contact Name:	SHAMSUL ALAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 392-7977
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-10-22

Site Id:	31225
Affiliation Type:	Emergency Contact
Company Name:	AAD AUTO REPAIR & BODY SHOP INC.
Contact Type:	Not reported
Contact Name:	SHAMSUL ALAM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 392-7977
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-10-22

Site Id:	31225
Affiliation Type:	Facility Owner
Company Name:	AAD AUTO REPAIR & BODY SHOP INC.
Contact Type:	Not reported
Contact Name:	SHAMSUL ALAM
Address1:	22-15 37TH AVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 392-7977
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MRBARROW
Date Last Modified:	2017-10-12

Tank Info:

Tank Number:	001
Tank Id:	67265
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

AAD AUTO REPAIR & BODY SHOP INC. (Continued) **A100295201**

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
K00 - Spill Prevention - None
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
I04 - Overfill - Product Level Gauge (A/G)
G05 - Tank Secondary Containment - Synthetic Liner
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/01/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C75 **BETWEEN 37 & 38TH AVE.** **NY Spills** **S106469156**
SE **3722 23RD. ST.** **N/A**
< 1/8 **QUEENS, NY**
0.068 mi.
360 ft. **Site 13 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	BETWEEN 37 & 38TH AVE.
Address:	3722 23RD. ST.
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0401764 / 2004-06-28
Facility ID:	0401764
Facility Type:	ER
DER Facility ID:	173512
Site ID:	209236
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	D4
SWIS:	4101
Spill Date:	2004-05-18
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2004-05-18
CID:	406
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Citizen

BETWEEN 37 & 38TH AVE. (Continued) **S106469156**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-18
Spill Record Last Update:	2004-06-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	AFROFA AMIN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEMEO add to drum run list 6/29/04 TJD Drum emptied during drum run on 6/23/04. No further action required. Spill closed. "
Remarks:	"Material is contained in a drum. No clean up at this time.(45gal of material in an 85 gal. overpack.)"

All Materials:

Site ID:	209236
Operable Unit ID:	883596
Operable Unit:	01
Material ID:	492955
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	45.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

G76 **GE-TSELEL AUTOMOTIVE INC** **NY SWF/LF** **S128178144**
North **36-28 14TH STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.069 mi.
363 ft. **Site 5 of 9 in cluster G**

Relative: SWF/LF:
Lower

Actual: Name:	GE-TSELEL AUTOMOTIVE INC
16 ft. Address:	36-28 14TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11106
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported

GE-TSELEL AUTOMOTIVE INC (Continued) **S128178144**

Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	589648
North Coordinate:	4512643
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

G77 **ASTORIA USED AUTO PARTS INC** **NY SWF/LF** **S128177746**
North **36-28 14TH STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.069 mi.
363 ft. **Site 6 of 9 in cluster G**

Relative: SWF/LF:
Lower

Actual:
16 ft.

Name:	ASTORIA USED AUTO PARTS INC
Address:	36-28 14TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11106
Flag:	INACTIVE
Region Code:	2
Phone Number:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Vehicle Dismantling Facility
Activity Number:	Not reported
Active:	No
East Coordinate:	589648
North Coordinate:	4512643
Accuracy Code:	Not reported
Regulatory Status:	Not reported
Waste Type:	Not reported
Authorization #:	Not reported
Authorization Date:	Not reported
Expiration Date:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported

ASTORIA USED AUTO PARTS INC (Continued) **S128177746**

Laste Date: Not reported

C78 **BASEMENT** **NY Spills** **S121462946**
East **2217 37TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.070 mi.
368 ft. **Site 14 of 18 in cluster C**

Relative: **Higher**

Actual: **18 ft.**

SPILLS:

Name:	BASEMENT
Address:	2217 37TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1708548 / 2018-02-13
Facility ID:	1708548
Facility Type:	ER
DER Facility ID:	518489
Site ID:	564958
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	4101
Spill Date:	2017-12-11
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2017-12-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-12-11
Spill Record Last Update:	2018-02-13
Spiller Name:	CHERYL
Spiller Company:	UNKNOWN
Spiller Address:	2217 37TH ST
Spiller Company:	999
Contact Name:	CHERYL
DEC Memo:	"12/12/17 TJD Site Inspection, misdelivery to house with no fuel tank. Improperly abandoned fill pipe. House has been on firm gas for approximately 20 years. Spoke with owner's daughter (Teresa) - she is onsite with spiller Skaggs Walsh. FDNY previously responded and removed a sheetrock wall to access piping. Basement is occupied by tenant who will be moving upstairs until cleanup is complete. Property owner is a 94 year old recovering from a recent stroke - with a 24 hour home health aide. Milro Associates has been retained to complete required clean-up actions. 12/12/17 TJD @ 11:24 AM Email received from Milro (Mike Vizzini). Below is narrative: Milro has been contracted for an additional clean up at the above referenced spill. Milro will be onsite later today to start

BASEMENT (Continued) **S121462946**

the remediation. I will follow tomorrow with site photos and additional information as it unfolds.
Its my understanding you re the case manager assigned to the spill per the property owners.
Follow-up email sent to Mike at Milro. Below is narrative: Yes, I am the PM for this site.
Misdelivery by Skaggs Walsh. Skaggs Walsh started a cleanup last night, including the removal of
floor coverings, at the time of my site visit the underlying floor was exposed and is believed to
be ACM (9x9 tiles). Skaggs personnel were advised of the asbestos concerns and directed to retain
the services of a qualified contractor to safely remove the suspected asbestos tiles. The indoor
air quality is very poor due to the excessive use of Sweet Air powder. The 94 year old owner is
staying on second floor recovering from a stroke, and is under 24 hour care by a home health aide.
Please install and continuously operate adequate ventilation equipment to control vapors. Unknown
volume of oil discharged as Skaggs Walsh driver did not close ticket but completed delivery to the
adjoining property which was the intended delivery location using the open ticket. Estimated
discharge volume is less than 10 gallons. There is a basement tenant that has been relocated to the
first floor temporarily. Please keep me updated on the progress of clean-up. Owner s daughter
states the second floor space is unaffected by odors, this is where her elderly father spends most
of his time. 12/12/17 TJD Follow-up inspection. Air mover installed by Skaggs Walsh with no
discharge hose to exterior. Fan is not effective. Milro enroute to install proper ventilation.
12/13/17 TJD Email received from Mike at Milro, Narrative as follows: Air equipment was installed
for residual odors. The oil impacted sheetrock and wood flooring was removed. The spill area was
washed and degreased to help relieve odors. Milro will test the ACM tile to confirm if its asbestos
or not. Oil impacted soil was observed in the sewer trap. Cracks were observed within the spill
area. I will update you on the vinyl flooring once I have the results. 12/14/17 TJD Email received
from Mike at Milro, Narrative as follows: Milro is contracted to return today to remove the black
mastic for residual odors and clean up the sewer traps by hand. Air equipment will remain onsite.
Per the property owners. They is always someone at the home for an inspection. Are you available to
perform an additional site inspection either when the crew is working today or at a later date? I
have included the manager for Skaggs Walsh. George Hamilton on the email. TJD response as follows:
Mike, Thank you for the update. What time will your crew be onsite today? I can perform a site
inspection today in the mid-afternoon around 2:30 or 3 o clock if that

BASEMENT (Continued) **S121462946**

works for you. Please let me
know? Milro response: Thank you. The crew will be onsite for your inspection. Please let me know
your findings. 2/13/18 TJD File review - closure report received. As per report, Milro Associates,
Inc. was contacted to respond to a #2 fuel oil spill at the above referenced location. The release
was caused during delivery to a disconnected fill pipe leading to the finished basement of the
residence. A reported 1 gallon of fuel oil was released onto the concrete slab in the boiler room
of the residence. As part of the cleanup on December 12th, 2017, Milro installed ventilation and
air scrubbing equipment in the residence, removed 1.25 yards of oil contaminated materials
including wood flooring, tile and sheetrock, and repeatedly washed the spill area of the basement
concrete slab using degreaser. A sewer trap impacted with fuel oil was cleaned of oil impacted
material and washed using degreaser. Upon approval from the New York State Department of
Environmental Conservation, further remediation was not required. Milro encapsulated the. spill
area of the concrete slab using a two-part epoxy paint. Oil contaminated debris and water were
properly disposed of in accordance with all federal, state, and local regulations. Non-hazardous
waste manifests are attached. Based upon the documentation provided, no further action is required.
All documentation has been uploaded to DECDOCS. Spill closed."

Remarks: "clean up is on going wrong house delivery"

All Materials:

Site ID:	564958
Operable Unit ID:	1312898
Operable Unit:	01
Material ID:	2320265
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

H79 **NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS** **RCRA-VSQG** **1004759451**
WNW **37-15 13TH ST** **FINDS** **NYR000010801**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.070 mi. **NY MANIFEST**
370 ft. **Site 1 of 8 in cluster H**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Nyc Bd Of Ed - Public School 111 Queens
Handler Address:	37-15 13TH ST

NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS (Continued) **1004759451**

Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000010801
Contact Name:	ROBERT GUASTA
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-349-5590
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Board Of Education
Owner Type:	Municipal
Operator Name:	Nyc Board Of Education
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220920

NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS (Continued) **1004759451**

Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 28-11 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-349-5600
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS

NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS (Continued) **1004759451**

Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19950808
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110008091625

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS (Continued) **1004759451**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004759451
Registry ID:	110008091625
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008091625
Name:	NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS
Address:	37-15 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	NYC BOARD OF EDUCATION
Address:	37-15 13TH ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYR000010801
Facility Status:	Not reported
Location Address 1:	37-15 13TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000010801
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	JACK BRUCCULERI
Mailing Address 1:	28-11 QUEENS PLAZA NORTH
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183616094

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD985286988
Trans2 State ID:	Not reported
Generator Ship Date:	12/20/2010
Trans1 Recv Date:	12/20/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

NYC BD OF ED - PUBLIC SCHOOL 111 QUEENS (Continued) **1004759451**

Generator EPA ID:	NYR000010801
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	002489601FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H80 **PUBLIC SCHOOL 111 - QUEENS Q111** **NY AST** **A100320324**
WNW **37-15 13TH STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.070 mi.
370 ft. **Site 2 of 8 in cluster H**

Relative: AST:
Lower

Actual:
16 ft.

Name:	PUBLIC SCHOOL 111 - QUEENS Q111
Address:	37-15 13TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-355186
Program Type:	PBS
UTM X:	589532.78391
UTM Y:	4512535.34657
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

PUBLIC SCHOOL 111 - QUEENS Q111 (Continued) **A100320324**

Site Id:	17691
Affiliation Type:	Facility Operator
Company Name:	PUBLIC SCHOOL 111 - QUEENS
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2013-04-10

Site Id:	17691
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	GDBREEN
Date Last Modified:	2014-09-10

Site Id:	17691
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Site Id:	17691
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS-FUEL DIVISION

PUBLIC SCHOOL 111 - QUEENS Q111 (Continued) **A100320324**

Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-04

Tank Info:

Tank Number:	001
Tank Id:	34613
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/24/1949
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/15/2011
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34614
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)

PUBLIC SCHOOL 111 - QUEENS Q111 (Continued) **A100320324**

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
K00 - Spill Prevention - None
F01 - Pipe External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	05/24/1949
Capacity Gallons:	7500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/15/2011
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#6 fuel oil (on-site consumption)

C81 **PERDIDO PRODS CONSTRUCTION SHOP** **RCRA-VSQG** **1004761819**
ESE **37-22 23RD ST GRD WHSE** **FINDS** **NYR000090720**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.070 mi. **NY MANIFEST**
372 ft. **Site 15 of 18 in cluster C**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Perdido Prods Construction Shop
Handler Address:	37-22 23RD ST GRD WHSE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000090720
Contact Name:	CHINYERE RYAN
Contact Address:	W 57TH ST #48
Contact City,State,Zip:	NEW YORK, NY 10019
Contact Telephone:	718-361-8324
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	W 57TH ST #48
Mailing City,State,Zip:	NEW YORK, NY 10019

PERDIDO PRODS CONSTRUCTION SHOP (Continued) **1004761819**

Owner Name:	Irvjoy Partners
Owner Type:	Private
Operator Name:	Irvjoy Partners
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D005
Waste Description:	Barium

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	IRVJOY PARTNERS

PERDIDO PRODS CONSTRUCTION SHOP (Continued) **1004761819**

Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 52 VANDERBILT AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-557-6700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: IRVJOY PARTNERS
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 52 VANDERBILT AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-557-6700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: IRVJOY PARTNERS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 52 VANDERBILT AVE
Owner/Operator City,State,Zip: NEW YORK, NY 10017
Owner/Operator Telephone: 212-557-6700
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: PERDIDO PRODS CONSTRUCTION SHOP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PERDIDO PRODS CONSTRUCTION SHOP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

PERDIDO PRODS CONSTRUCTION SHOP (Continued) **1004761819**

Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20001002
Handler Name: PERDIDO PRODS CONSTRUCTION SHOP
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004565186

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004761819
Registry ID: 110004565186
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004565186
Name: PERDIDO PRODS CONSTRUCTION SHOP
Address: 37-22 23RD ST GRD WHSE
City,State,Zip: LONG ISLAND CITY, NY 11101

NY MANIFEST:
Name: PERDIDO PRODS CONSTRUCTION
Address: 37-22 23RD ST GRD WHSE
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA

PERDIDO PRODS CONSTRUCTION SHOP (Continued) **1004761819**

EPA ID:	NYR000090720
Facility Status:	Not reported
Location Address 1:	37-22 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000090720
Mailing Name:	PERDIDO PRODS CONSTRUCTION
Mailing Contact:	JIM SORICE
Mailing Address 1:	140 W57TH ST
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10019
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183618324

D82 **AUTO CARE LUBE, LTD** **NY AST** **A100293136**
NE **36-21 21ST STREET** **N/A**
< 1/8 **ASTORIA, NY 11106**
0.071 mi.
374 ft. **Site 10 of 13 in cluster D**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	AUTO CARE LUBE, LTD
Address:	36-21 21ST STREET
City,State,Zip:	ASTORIA, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609550
Program Type:	PBS
UTM X:	589726.53066
UTM Y:	4512613.64692
Expiration Date:	05/13/2024
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	55597
Affiliation Type:	Mail Contact
Company Name:	AUTO CARE LUBE, LTD.
Contact Type:	Not reported
Contact Name:	MICHAEL LAGE
Address1:	4391 BOSTON POST RD.
Address2:	Not reported
City:	PELHAM MANOR
State:	NY
Zip Code:	10803
Country Code:	001
Phone:	(914) 637-3895
EMail:	MICHAELLAGELMC@GMAIL.COM

AUTO CARE LUBE, LTD (Continued) **A100293136**

Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2015-02-19

Site Id:	55597
Affiliation Type:	Facility Operator
Company Name:	AUTO CARE LUBE, LTD
Contact Type:	Not reported
Contact Name:	DONALD MOODY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-6228
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LSZINOMA
Date Last Modified:	2015-02-19

Site Id:	55597
Affiliation Type:	Emergency Contact
Company Name:	JOHN LAGE.
Contact Type:	Not reported
Contact Name:	MICHAEL LAGE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 804-6934
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2009-03-02

Site Id:	55597
Affiliation Type:	Facility Owner
Company Name:	LAGE PROPERTIES CORP
Contact Type:	MANAGER
Contact Name:	DONALD MODDIE
Address1:	36-21 21ST STREET
Address2:	Not reported
City:	L.I.C.
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 786-8910
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-04-30

Tank Info:

AUTO CARE LUBE, LTD (Continued) **A100293136**

Tank Number: 27
Tank Id: 178772
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J03 - Dispenser - Gravity
G04 - Tank Secondary Containment - Double-Walled (Underground)
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
B01 - Tank External Protection - Painted/Asphalt Coating
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 01/01/1989
Capacity Gallons: 500
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

Tank Number: 34
Tank Id: 178771
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
J03 - Dispenser - Gravity
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
D02 - Pipe Type - Galvanized Steel
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground

Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type: Steel/Carbon Steel/Iron

AUTO CARE LUBE, LTD (Continued) **A100293136**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	1000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	40
Tank Id:	178773
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J03 - Dispenser - Gravity
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	43
Tank Id:	178774
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J03 - Dispenser - Gravity

AUTO CARE LUBE, LTD (Continued) **A100293136**

G04 - Tank Secondary Containment - Double-Walled (Underground)
K01 - Spill Prevention - Catch Basin
A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
L02 - Piping Leak Detection - Interstitial - Manual Monitoring
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
B01 - Tank External Protection - Painted/Asphalt Coating
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

Tank Number:	44
Tank Id:	178775
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
K01 - Spill Prevention - Catch Basin
J03 - Dispenser - Gravity
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
G04 - Tank Secondary Containment - Double-Walled (Underground)
B01 - Tank External Protection - Painted/Asphalt Coating
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported

AUTO CARE LUBE, LTD (Continued) **A100293136**

Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil
Tank Number:	45
Tank Id:	178776
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

J03 - Dispenser - Gravity
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
G04 - Tank Secondary Containment - Double-Walled (Underground)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
B01 - Tank External Protection - Painted/Asphalt Coating
L02 - Piping Leak Detection - Interstitial - Manual Monitoring

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

I83 **BMI AUTO BODY CENTER INC** **NY AST** **A100293287**
ENE **36-33/35 22ND STREET** **N/A**
< 1/8 **ASTORIA, NY 11106**
0.074 mi.
392 ft. **Site 1 of 2 in cluster I**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	BMI AUTO BODY CENTER INC
Address:	36-33/35 22ND STREET
City,State,Zip:	ASTORIA, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-607959
Program Type:	PBS
UTM X:	589793.28272
UTM Y:	4512550.44622

BMI AUTO BODY CENTER INC (Continued) **A100293287**

Expiration Date: 07/30/2007
Site Type: Other

Affiliation Records:

Site Id: 29811
Affiliation Type: Facility Owner
Company Name: BMI AUTO BODY CENTER INC
Contact Type: Not reported
Contact Name: Not reported
Address1: 36-33135 22ND STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11106
Country Code: 001
Phone: (718) 482-6818
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 29811
Affiliation Type: Mail Contact
Company Name: BMI AUTO BODY CENTER INC
Contact Type: Not reported
Contact Name: REMUS M. ILIESCU
Address1: 36-33/35 22 STREET
Address2: 36-33 22 STREET
City: LONG ISLAND CITY
State: NY
Zip Code: 11106
Country Code: 001
Phone: (718) 482-6818
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 29811
Affiliation Type: Facility Operator
Company Name: BMI AUTO BODY CENTER INC
Contact Type: Not reported
Contact Name: REMUS M. ILESCY
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 482-6818
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 29811
Affiliation Type: Emergency Contact
Company Name: BMI AUTO BODY CENTER INC

BMI AUTO BODY CENTER INC (Continued) **A100293287**

Contact Type:	Not reported
Contact Name:	REMUS M. ILESCY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 482-6818
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	01
Tank Id:	63972
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	A00 - Tank Internal Protection - None
	G10 - Tank Secondary Containment - Impervious Underlayment
	D00 - Pipe Type - No Piping
	J00 - Dispenser - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Temporarily Out of Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	55
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

C84 **DRUM RUN** **NY Spills** **S108637953**
SE **23RD ST BET 37TH AND 38T** **N/A**
< 1/8 **QUEENS, NY**
0.075 mi.
396 ft. **Site 16 of 18 in cluster C**

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name:	DRUM RUN
Address:	23RD ST BET 37TH AND 38T
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0702865 / 2007-08-09
Facility ID:	0702865
Facility Type:	ER
DER Facility ID:	332120
Site ID:	382677
DEC Region:	2
Spill Cause:	Abandoned Drums
Spill Class:	C3
SWIS:	4101
Spill Date:	2007-06-08
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2007-06-08
CID:	410
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-08
Spill Record Last Update:	2007-08-09
Spiller Name:	MICHAEL WORDON
Spiller Company:	UNKNOWN
Spiller Address:	23RD ST BET 37TH AND 38T
Spiller Company:	001
Contact Name:	MICHAEL WORDON
DEC Memo:	"DEP inspected the drum and determined it was waste oil. Sharif stopped by the site on 06/28/07, the drum is there on east side. 07/26/07-Vought-On way to work was stopped by local resident who expressed concern over drum. Vought insepcted drum and drum not leaking but does not have 1 cap. Vought covered drum with plastic and noted that it was set for drum run. 08/09/07 Drum was found on 08/07/07, was pumped out, list was sent to Sanitation to pick up the empty drum."
Remarks:	"REPORTING A 55 GALLON DRUM LEFT ON SIDEWALK AT ABOVE LOCATION. ACROSS FROM 37-22 23RD STREET':"

All Materials:

Site ID:	382677
Operable Unit ID:	1140063
Operable Unit:	01
Material ID:	2130891
Material Code:	0064A
Material Name:	unknown material

DRUM RUN (Continued) **S108637953**

Case No.:	Not reported
Material FA:	Other
Quantity:	55.00
Units:	G
Recovered:	55.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	382677
Operable Unit ID:	1140063
Operable Unit:	01
Material ID:	2130111
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	55.00
Units:	G
Recovered:	55.00
Resource Affected:	Soil
Oxygenate:	Not reported

C85 **M & B AUTO BODY INC** **RCRA-SQG** **1004760250**
East **22-19 37TH AVE** **FINDS** **NYR000037325**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.076 mi. **NY MANIFEST**
399 ft. **Site 17 of 18 in cluster C** **NJ MANIFEST**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	M & B Auto Body Inc
Handler Address:	22-19 37TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000037325
Contact Name:	MANNY VARELA
Contact Address:	37TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-784-1321
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	37TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Manuel Varela
Owner Type:	Private
Operator Name:	Manuel Varela
Operator Type:	Private
Short-Term Generator Activity:	No

M & B AUTO BODY INC (Continued) **1004760250**

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still

M & B AUTO BODY INC (Continued) **1004760250**

Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: MANUEL VARELA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-19 37TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-1321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MANUEL VARELA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-19 37TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-1321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MANUEL VARELA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-19 37TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-1321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: M & B AUTO BODY INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

M & B AUTO BODY INC (Continued) **1004760250**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: M & B AUTO BODY INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19970404
Handler Name: M & B AUTO BODY INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Unknown
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Evaluation Action Summary:

Evaluation Date:	20170504
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20230223
Evaluation Responsible Agency:	State
Found Violation:	Undetermined
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYYCI
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004533443

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
Registry ID: 110019507194

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
FIS (New York - Facility Information System) is New York's Department

M & B AUTO BODY INC (Continued) **1004760250**

of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004760250
Registry ID:	110004533443
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004533443
Name:	M & B AUTO BODY INC
Address:	22-19 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

Envid:	1004760250
Registry ID:	110019507194
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110019507194
Name:	M&B TWINS COLLISION
Address:	22-19 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	M&B AUTO BODY INC
Address:	22-19 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000037325
Facility Status:	Not reported
Location Address 1:	22-19 37TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000037325
Mailing Name:	M&B AUTO BODY INC
Mailing Contact:	MANNY VARELA
Mailing Address 1:	22-19 37TH AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187841321

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD080631369

M & B AUTO BODY INC (Continued) **1004760250**

Trans2 State ID:	Not reported
Generator Ship Date:	12/18/2017
Trans1 Recv Date:	12/18/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/20/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000037325
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000968769VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	720
Units:	P - Pounds
Number of Containers:	6
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	F005
Waste Code 1_5:	D035
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYR000037325
Mail Address:	Not reported
Mail City/State/Zip:	Not reported
Facility Phone:	7187841321
Emergency Phone:	Not reported
Contact:	VARELA MANNY
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X

M & B AUTO BODY INC (Continued) **1004760250**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5319114
EPA ID:	NYR000037325
Date Shipped:	03/02/2006
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/02/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/02/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	05010621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	001336199VES
EPA ID:	NYR000037325
Date Shipped:	3/12/2018
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	M & B AUTO BODY INC
Transporter-1 EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS CORP
TSDF EPA Facility Name:	VEOLIA ES TECHNICAL SOLUTIONS LLC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	3/12/2018
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	3/12/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000181441VES
EPA ID:	NYR000037325
Date Shipped:	08/14/2009
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/14/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/21/2009

M & B AUTO BODY INC (Continued) **1004760250**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	1100 P

Manifest Number:	000204512VES
EPA ID:	NYR000037325
Date Shipped:	09/26/2008
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	09/26/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/26/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H061
Quantity:	150 G

Manifest Number:	000201705VES
EPA ID:	NYR000037325
Date Shipped:	02/20/2009
TSDF EPA ID:	NJD002454544
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/20/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/20/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H061

M & B AUTO BODY INC (Continued) **1004760250**

Quantity: 150 G

Manifest Number: 000346931VES
EPA ID: NYR000037325
Date Shipped: 05/17/2010
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 05/17/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 05/21/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F003
Hand Code: H141
Quantity: 800 P

Manifest Number: 000160872VES
EPA ID: NYR000037325
Date Shipped: 11/08/2007
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	11/08/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	11/08/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	000969668VES
EPA ID:	NYR000037325
Date Shipped:	4/23/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NYD064748304
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000720642VES
EPA ID:	NYR000037325
Date Shipped:	10/15/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F003 D001 F005 D035
Hand Code: Not reported
Quantity: 800.00 Pounds

Manifest Number: 000845190VES
EPA ID: NYR000037325
Date Shipped: 10/9/2015
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: Not reported
Reason Load Was Rejected: Not reported

Manifest Number: 000346550VES
EPA ID: NYR000037325
Date Shipped: 10/23/2009
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/23/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/23/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	400 P

Manifest Number:	000847406VES
EPA ID:	NYR000037325
Date Shipped:	8/12/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	NJA5320329
EPA ID:	NYR000037325
Date Shipped:	08/22/2006
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/22/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/22/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09210621
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Manifest Number:	000972014VES
EPA ID:	NYR000037325
Date Shipped:	11/24/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Manifest Number:	000433218VES
EPA ID:	NYR000037325
Date Shipped:	6/17/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	1,200.00 Pounds

Manifest Number:	000111844VES
EPA ID:	NYR000037325
Date Shipped:	08/16/2007
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/16/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/16/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H14
Quantity:	1200 P

Manifest Number:	000400748VES
EPA ID:	NYR000037325
Date Shipped:	8/29/2011
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	Not reported
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H141
Quantity:	400.00 Pounds

Manifest Number:	000020909VES
EPA ID:	NYR000037325
Date Shipped:	04/23/2007
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJD080631369
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/23/2007
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/23/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No

M & B AUTO BODY INC (Continued) **1004760250**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F003
Hand Code: H14
Quantity: 800 P

Manifest Number: NJA5265018
EPA ID: NYR000037325
Date Shipped: 11/10/2005
TSDF EPA ID: NJD980536593
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 11/10/2005
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 11/10/2005
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 12150535
Was Load Rejected: No
Reason Load Was Rejected: Not reported

Manifest Number: 000884079JJK
EPA ID: NYR000037325
Date Shipped: 02/18/2008
TSDF EPA ID: NJD002454544
Transporter EPA ID: NJD080631369
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported

M & B AUTO BODY INC (Continued) **1004760250**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/18/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/18/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	No
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F003
Hand Code:	H061
Quantity:	165 G

G86 **14TH STREET BETWEEN** **NY Spills** **S102446763**
North **36TH + 37TH** **N/A**
< 1/8 **QUEENS, NY**
0.077 mi.
405 ft. **Site 7 of 9 in cluster G**

Relative: **Lower**

Actual: **16 ft.**

SPILLS:

Name:	14TH STREET BETWEEN
Address:	36TH + 37TH
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9611523 / 2005-06-16
Facility ID:	9611523
Facility Type:	ER
DER Facility ID:	109498
Site ID:	126717
DEC Region:	2
Spill Cause:	Unknown

14TH STREET BETWEEN (Continued) **S102446763**

Spill Class:	C4
SWIS:	4101
Spill Date:	1996-12-19
Investigator:	LNKLAAS
Referred To:	Not reported
Reported to Dept:	1996-12-19
CID:	351
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-19
Spill Record Last Update:	2005-06-16
Spiller Name:	Not reported
Spiller Company:	GE TSELEL AUTOMTIVE
Spiller Address:	36-28 14TH ST
Spiller Company:	001
Contact Name:	NYC FD HAZ MAT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE SEE ALSO 9611520. 06/16/05 Duplicate of spill #9611520 - cleanup complete, already closed. Closed. LNK."
Remarks:	"LARGE OIL SLICK IN STREET - BELIEVED TO BE RUN OFF FROM THE JUNK YARD ON 14TH ST - NYC FD HAZ MAT LEAVING SCENE DOES RECOMMEND DEC RESPOND AND INVESTIGATE - OIL CLEANED OFF OF STREET WITH SAND"

All Materials:

Site ID:	126717
Operable Unit ID:	1039533
Operable Unit:	01
Material ID:	340165
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

D87 **DIESEL SPILL BUCKET** **NY Spills** **S117975590**
NNE **36-02 21ST STREET** **N/A**
< 1/8 **QUEENS, NY**
0.079 mi.
416 ft. **Site 11 of 13 in cluster D**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	DIESEL SPILL BUCKET
Address:	36-02 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	1504119 / 2015-07-17

DIESEL SPILL BUCKET (Continued) **S117975590**

Facility ID:	1504119
Facility Type:	ER
DER Facility ID:	465027
Site ID:	510451
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2015-07-17
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2015-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-07-17
Spill Record Last Update:	2015-07-17
Spiller Name:	DAVE WENT
Spiller Company:	ALLIANCE AND GLOBAL
Spiller Address:	36-02 21ST STREET
Spiller Company:	999
Contact Name:	DAVE WENT
DEC Memo:	"07/17/15-Hiralkumar Patel. 2:12 PM:- spoke with Star at ECS Eclipse. she mentioned that Douglas from her office inspected site today. during inspection, he found approx. 2 gal diesel in spill bucket which was cleaned out immediately. she confirmed that product collected in spill bucket due to overfill during delivery and there was no leak from the system. case closed. "
Remarks:	"An overfill caused diesel to spill to a spill bucket. Clean up is complete via pump out."

All Materials:

Site ID:	510451
Operable Unit ID:	1259715
Operable Unit:	01
Material ID:	2263059
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

D88 **GETTY** **NY Spills** **S103482991**
NNE **36-02 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.079 mi.
416 ft. **Site 12 of 13 in cluster D**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	GETTY
Address:	36-02 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9805206 / 2004-12-03
Facility ID:	9805206
Facility Type:	ER
DER Facility ID:	174164
Site ID:	210089
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	4101
Spill Date:	1998-06-26
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	1998-07-27
CID:	266
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1998-07-27
Spill Record Last Update:	2004-12-03
Spiller Name:	LOUIS OCHOTORENA
Spiller Company:	GETTY PETROLEUM CORPORATI
Spiller Address:	3023 GREENPOINT AVENUE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 3/14/03 REASSIGNED FROM ROMMEL TO VOUGHT. 10/2/2003-Vought-File review by Vought: Tank Closure Report-June 1999-Tyree Org. Tank closed as part of EPA mandated upgrade. Removal of ten (550-gallon) gasoline USTs, one (1000-gallon) fuel oil and one (550-gallon) waste oil. Groundwater not encountered during removal. Eleven endpoint soil samples collected from gasoline excavation and one endpoint soil sample was collected from waste oil excavation. Soil analyticals show 14.4ppb benzene(SW4), 4960ppb toluene(SW3), 29400ppb napthalene(SW3), 50200ppb toluene(B1), 102000ppb napthalene(B1), 7820ppb xylene(B3), 1960ppb MTBE(B3), and 2960ppb xylene(W/O), 669ppb MTBE(W/O). A total of 105.04 tons of soil was excavated (disposal manifest provided). Quarterly Monitoring Reports-July 2000 thru March 2003-Tyree Org. Four monitoring wells on-site. Groundwater flow from

GETTY (Continued) **S103482991**

July 2000 to April 2002 is to
the southwest. Groundwater flow from April 2002 to March 2003 is tidally influenced . Groundwater
at depths of 10.5'to 11.5'. Groundwater analyticals for March 3003 show 238ppb benzene(W2).
Historical Data Compilation (Tyree Org)-December 2001. Compilation including Request for No Further
Action. 10/2/03-Vought-DEC received NFA request via email. NFA request denied and DEC requires:
1)borings/monitoring wells in areas of highest historical contamination (former sampling location
B1, SW3), downgradient of B1/SW3, northeast of MW2 and northwest of service station buiilding
2)surrounding property sketch. Vought sent letter with above requirements on 10/3. Quarterly
Monitoring Reports-August 2003 thru December 2003-Tyree Org. Four monitoring wells on-site.
Groundwater flow is tidally influenced . Groundwater at depths of 10.5'to 12'. Groundwater
analyticals show 123ppb benzene(W-2) and 136ppb ethylbenzene(W-2).
Subsurface Investigation Report
(Tyree Org)-March 2004. Residential apartment buildings to the north and west and restaurants to
the southwest and southeast of the subject property . Five Geoprobe borings performed on 2/25/04.
Tyree requests no further action. Soil analyticals show 7360ppb 1,3,5-trimethylbenzene(SB3 0-4').
Groundwater analyticals show no Groundwater Standard Criteria exceedences. Borings performed
included required boring at former B1/SW3 location and downgradient. Surrounding area sketch
included with report. DEC requires: 1)continued quarterly monitoring due to exceedences in W-2.
Vought sent letter with above requirement on 3/19/04.
12/3/04-Vought-Received email from Tyree
(Pachan). I need to know if we will be required to perform anymore sampling or if we can get this
site closed . Vought reviewed site with Rommel and spill closed due to containment of groundwater
contamination within W-2 and adjacent wells showing concentrations below method detection limits.
Spill closed by Vought. "

Remarks: "PRE-CLASS SAMPLES TAKEN ON DATE LISTED. REPORT RECEIVED TODAY INDICATES THAT THERE IS SOIL CONTAMINATION. TANK REMOVAL IS PLANNED AND SOIL WILL BE STOCKPILED AT THAT TIME."

All Materials:

Site ID:	210089
Operable Unit ID:	1066373
Operable Unit:	01
Material ID:	319957
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

GETTY (Continued) **S103482991**

Resource Affected: Soil
Oxygenate: Not reported

F89 **HERTZ PARKING LOT** **NY UST** **U000411126**
SW **38-15 21 ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.080 mi.
420 ft. **Site 5 of 9 in cluster F**

Relative:
Higher

Actual:
17 ft.

UST:
Name: HERTZ PARKING LOT
Address: 38-15 21 ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-478881 / Inactive
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589538.94786
UTM Y: 4512353.67498
Site Type: Unknown

Affiliation Records:
Site Id: 21303
Affiliation Type: Facility Owner
Company Name: LUPOLI, PETER
Contact Type: Not reported
Contact Name: Not reported
Address1: 68 COVE NECK RD
Address2: Not reported
City: OYSTER BAY
State: NY
Zip Code: 11771
Country Code: 001
Phone: (516) 624-9272
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21303
Affiliation Type: Mail Contact
Company Name: LUPOLI, PETER
Contact Type: Not reported
Contact Name: Not reported
Address1: 68 COVE NECK RD
Address2: Not reported
City: OYSTER BAY
State: NY
Zip Code: 11771
Country Code: 001
Phone: (516) 624-9272
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

HERTZ PARKING LOT (Continued) **U000411126**

Site Id:	21303
Affiliation Type:	Facility Operator
Company Name:	HERTZ PARKING LOT
Contact Type:	Not reported
Contact Name:	PETER LUPOLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 624-9272
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	21303
Affiliation Type:	Emergency Contact
Company Name:	LUPOLI, PETER
Contact Type:	Not reported
Contact Name:	P LUPOLI
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 624-9272
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	38585
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	06/01/1952
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

HERTZ PARKING LOT (Continued) **U000411126**

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 002
Tank ID: 38586
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 003
Tank ID: 38587
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported

HERTZ PARKING LOT (Continued) **U000411126**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 38588
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

Tank Number: 005
Tank ID: 38589
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground

HERTZ PARKING LOT (Continued) **U000411126**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 006
Tank ID: 38590
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 007
Tank ID: 38591
Tank Status: Tank Converted to Non-Regulated Use

HERTZ PARKING LOT (Continued) **U000411126**

Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	06/01/1952
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	008
Tank ID:	38592
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	06/01/1952
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None

HERTZ PARKING LOT (Continued) **U000411126**

D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 009
Tank ID: 38593
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 010
Tank ID: 38594
Tank Status: Tank Converted to Non-Regulated Use
Material Name: Tank Converted to Non-Regulated Use
Capacity Gallons: 1000
Install Date: 06/01/1952
Date Tank Closed: 08/01/1997
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None

HERTZ PARKING LOT (Continued) **U000411126**

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	011
Tank ID:	38595
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	1000
Install Date:	06/01/1952
Date Tank Closed:	08/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

C90 **CONSOLIDATED EDISON** **NY MANIFEST** **1009242248**
ESE **37 AVE & 23 AT MH17488** **N/A**
< 1/8 **QUEENS, NY**
0.080 mi.
423 ft. **Site 18 of 18 in cluster C**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	37 AVE & 23 AT MH17488
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004110599
Facility Status:	Not reported
Location Address 1:	37 AVE & 23 AT MH17488
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS

CONSOLIDATED EDISON (Continued) **1009242248**

Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004110599
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

F91 **PEP BOYS #437** **NY AST** **U003397005**
SW **38-50 21ST STREET** **N/A**
< 1/8 **QUEENS, NY 11128**
0.080 mi.
424 ft. **Site 6 of 9 in cluster F**

Relative:
Higher

Actual:
17 ft.

AST:
Name: PEP BOYS #437
Address: 38-50 21ST STREET
City,State,Zip: QUEENS, NY 11128
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-603131
Program Type: PBS
UTM X: 589501.62500
UTM Y: 4512323.50000
Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 25083
Affiliation Type: Mail Contact
Company Name: THE PEP BOYS - MANNY, MOE, & JACK
Contact Type: Not reported
Contact Name: ANGELA BANKS, ENVIRONMENTAL
Address1: 3111 WEST ALLEGHENY AVENUE
Address2: Not reported
City: PHILADELPHIA
State: PA
Zip Code: 19132
Country Code: 001
Phone: (215) 430-9000
EMail: Not reported
Fax Number: Not reported
Modified By: MABARTLE
Date Last Modified: 2005-03-29

Site Id: 25083
Affiliation Type: Facility Operator
Company Name: PEP BOYS #437

PEP BOYS #437 (Continued) **U003397005**

Contact Type:	Not reported
Contact Name:	PEP BOYS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-1414
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-29

Site Id:	25083
Affiliation Type:	Emergency Contact
Company Name:	THE PEP BOYS - MANNY, MOE, & JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(215) 430-9645
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-03-29

Site Id:	25083
Affiliation Type:	Facility Owner
Company Name:	THE PEP BOYS - MANNY, MOE, & JACK
Contact Type:	DIR. OF ENVIRONMENTAL COMPLIANCE
Contact Name:	ANGELA BANKS
Address1:	3111 WEST ALLEGHENY AVENUE
Address2:	Not reported
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 430-9000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-11-17

Tank Info:

Tank Number:	001
Tank Id:	53190
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

PEP BOYS #437 (Continued) **U003397005**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
E00 - Piping Secondary Containment - None
F02 - Pipe External Protection - Original Sacrificial Anode
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1997
Capacity Gallons:	250
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	09/05/2014
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

E92 **23RD ST & 38TH AVENUE** **NY Spills** **S102147425**
SSE **23RD ST & 38TH AVENUE** **N/A**
< 1/8 **QUEENS, NY**
0.081 mi.
426 ft. **Site 4 of 7 in cluster E**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	23RD ST & 38TH AVENUE
Address:	23RD ST & 38TH AVENUE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9311067 / 1993-12-13
Facility ID:	9311067
Facility Type:	ER
DER Facility ID:	150288
Site ID:	179043
DEC Region:	2
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	4101
Spill Date:	1993-12-13
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1993-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1993-12-13
Cleanup Meets Std:	True
Last Inspection:	Not reported

23RD ST & 38TH AVENUE (Continued) **S102147425**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-14
Spill Record Last Update:	2003-11-13
Spiller Name:	Not reported
Spiller Company:	SCHRIEE BROS. TRKG.
Spiller Address:	81 BLACK ROCK TPKE.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"LIFTED MANHOLE COVERED/TRUCK RAN OVER IT AND IT RUPTURED SADDLE TANK. SEWERS WERE DIKED. DEPT SANITATION SOLT SPRAYER WILL SAND DOWN RD."

All Materials:

Site ID:	179043
Operable Unit ID:	992950
Operable Unit:	01
Material ID:	390123
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	90.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

H93 **CON EDISON** **NY MANIFEST** **S117537585**
WNW **37-14 13TH ST** **N/A**
< 1/8 **QUEENS, NY 11106**
0.081 mi.
427 ft. **Site 3 of 8 in cluster H**

Relative: **Lower**
Actual: **16 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	37-14 13TH ST
City,State,Zip:	QUEENS, NY 11106
Country:	USA
EPA ID:	NYP004701603
Facility Status:	Not reported
Location Address 1:	37-14 13TH ST
Code:	BP
Location Address 2:	SB 57979
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004701603
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported

CON EDISON (Continued) **S117537585**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	12/02/2014
Trans1 Recv Date:	12/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/16/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004701603
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002416832GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

E94 **CONSOLIDATED EDISON** **NY MANIFEST** **1009241279**
SSE **23RD ST & 38TH AVE MH13268** **N/A**
< 1/8 **QUEENS, NY**
0.081 mi.
428 ft. **Site 5 of 7 in cluster E**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	23RD ST & 38TH AVE MH13268
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004096848
Facility Status:	Not reported
Location Address 1:	23RD ST & 38TH AVE MH13268
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004096848
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

G95 **CHRISTIAN ECKHOFF TRUCK BODIES** **RCRA NonGen / NLR** **1004759333**
North **36-22 14TH ST** **FINDS** **NYR000006783**
< 1/8 **LONG ISLAND CITY, NY 11106** **ECHO**
0.085 mi.
447 ft. **Site 8 of 9 in cluster G**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Christian Eckhoff Truck Bodies
Handler Address:	36-22 14TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYR000006783
Contact Name:	PETER ECKHOFF
Contact Address:	14TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11106
Contact Telephone:	718-784-8714
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CHRISTIAN ECKHOFF TRUCK BODIES (Continued) **1004759333**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	14TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner Name:	Peter C Eckhoff
Owner Type:	Private
Operator Name:	Peter C Eckhoff
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035

CHRISTIAN ECKHOFF TRUCK BODIES (Continued) **1004759333**

Waste Description: Methyl Ethyl Ketone

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: PETER C ECKHOFF
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 36-22 14TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11106
Owner/Operator Telephone: 718-784-8714
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PETER C ECKHOFF
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 36-22 14TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11106
Owner/Operator Telephone: 718-784-8714
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: PETER C ECKHOFF
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 36-22 14TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11106
Owner/Operator Telephone: 718-784-8714
Owner/Operator Telephone Ext: Not reported

CHRISTIAN ECKHOFF TRUCK BODIES (Continued) **1004759333**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CHRISTIAN ECKHOFF TRUCK BODIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CHRISTIAN ECKHOFF TRUCK BODIES
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950616
Handler Name: CHRISTIAN ECKHOFF TRUCK BODIES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004514758

CHRISTIAN ECKHOFF TRUCK BODIES (Continued) **1004759333**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004759333
Registry ID:	110004514758
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004514758
Name:	CHRISTIAN ECKHOFF TRUCK BODIES
Address:	36-22 14TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106

G96 **CHRISTIAN ECKHOFF TRUCK BODY** **NY UST** **U003127698**
North **36-22 14TH STREET** **N/A**
< 1/8 **ASTORIA, NY 11106**
0.085 mi.
447 ft. **Site 9 of 9 in cluster G**

Relative:
Lower

Actual:
16 ft.

UST:

Name:	CHRISTIAN ECKHOFF TRUCK BODY
Address:	36-22 14TH STREET
City,State,Zip:	ASTORIA, NY 11106
Id/Status:	2-249270 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589660.22053
UTM Y:	4512647.95290
Site Type:	Other

Affiliation Records:

Site Id:	9892
Affiliation Type:	Mail Contact
Company Name:	CHRISTIAN ECKHOFF TRUCK BODY
Contact Type:	Not reported
Contact Name:	PETER ECKHOFF
Address1:	36-22 14TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 784-8714
EMail:	ETBLIC@AOL.COM
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-03

CHRISTIAN ECKHOFF TRUCK BODY (Continued) **U003127698**

Site Id:	9892
Affiliation Type:	Facility Operator
Company Name:	CHRISTIAN ECKHOFF TRUCK BODY
Contact Type:	Not reported
Contact Name:	PETER ECKHOFF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-8714
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9892
Affiliation Type:	Emergency Contact
Company Name:	HULDAH ECKHOFF
Contact Type:	Not reported
Contact Name:	PETER ECKHOFF
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 736-1992
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	9892
Affiliation Type:	Facility Owner
Company Name:	HULDAH ECKHOFF
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	82 E. EUCLID ST.
Address2:	Not reported
City:	VALLEY STREAM
State:	NY
Zip Code:	11580
Country Code:	001
Phone:	(516) 561-1899
EMail:	Not reported
Fax Number:	Not reported
Modified By:	HDDUPIGN
Date Last Modified:	2015-11-03

Tank Info:

Tank Number:	001
Tank ID:	10385
Tank Status:	Closed - In Place
Material Name:	Closed - In Place

CHRISTIAN ECKHOFF TRUCK BODY (Continued) **U003127698**

Capacity Gallons:	5000
Install Date:	12/01/1967
Date Tank Closed:	05/13/2015
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	04/09/2012
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

K00 - Spill Prevention - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
L00 - Piping Leak Detection - None
J05 - Dispenser - On Site Heating System (Supply/Return)
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
I05 - Overfill - Vent Whistle

H97 **CON EDISON** **NY MANIFEST** **S117316000**
NW **12-20 37 AV** **N/A**
< 1/8 **QUEENS, NY 11101**
0.085 mi.
449 ft. **Site 4 of 8 in cluster H**

Relative:
Lower

Actual:
16 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	12-20 37 AV
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYP004632246
Facility Status:	Not reported
Location Address 1:	12-20 37 AV
Code:	BP
Location Address 2:	SB49007
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004632246
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK

CON EDISON (Continued) **S117316000**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/19/2014
Trans1 Recv Date:	08/19/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004632246
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616475GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

D98 **SAV-ON PETROLEUM INC** **EDR Hist Auto** **1021845290**
NE **36-11 21ST ST** **N/A**
< 1/8 **LONG IS CY, NY 11106**
0.087 mi.
457 ft. **Site 13 of 13 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: Year: Name: Type:
17 ft. 1979 SAV-ON PETROLEUM INC Gasoline Service Stations
1982 SAV-ON PETROLEUM INC Gasoline Service Stations
1983 SAV-ON PETROLEUM INC Gasoline Service Stations

J99 **JUNG SUN LAUNDRY SITE** **RCRA-LQG** **1017788161**
SE **37-11 23RD ST** **NYR000219006**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.087 mi.
459 ft. **Site 1 of 15 in cluster J**

Relative: RCRA Listings:
Higher

Actual:
19 ft.

Date Form Received by Agency:	20160603
Handler Name:	Jung Sun Laundry Site
Handler Address:	37-11 23RD ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000219006
Contact Name:	SADIQUE AHMED
Contact Address:	23RD ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-347-3200
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	PROJECT MANAFER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	24TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Sadique Ahmed
Owner Type:	Private
Operator Name:	Sadique Ahmed
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

JUNG SUN LAUNDRY SITE (Continued) **1017788161**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161107
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: SADIQUE AHMED	
Legal Status:	Private
Date Became Current:	19000101
Date Ended Current:	Not reported
Owner/Operator Address:	3711 23RD ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **1017788161**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GURPAL CHEEMA
Legal Status: Private
Date Became Current: 20120919
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NFEW GENERATION DEVELOPMENT LLC
Legal Status: Private
Date Became Current: 20120919
Date Ended Current: Not reported
Owner/Operator Address: 111-26 VAN WYCK EXPWY
Owner/Operator City,State,Zip: SOUTH OZONE PARK, NY 11420
Owner/Operator Telephone: 516-474-6030
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SADIQUE AHMED
Legal Status: Private
Date Became Current: 19000101
Date Ended Current: Not reported
Owner/Operator Address: 3711 23RD ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-347-3200
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20160603
Handler Name: JUNG SUN LAUNDRY SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150326
Handler Name: JUNG SUN LAUNDRY SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

JUNG SUN LAUNDRY SITE (Continued) **1017788161**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	56291
NAICS Description:	REMEDIATION SERVICES
NAICS Code:	721110
NAICS Description:	HOTELS (EXCEPT CASINO HOTELS) AND MOTELS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

J100 **JUNG SUN LAUNDRY SITE** **NY MANIFEST** **S118260210**
SE **37-11 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.087 mi.
459 ft. **Site 2 of 15 in cluster J**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	JUNG SUN LAUNDRY SITE
Address:	37-11 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000219006
Facility Status:	Not reported
Location Address 1:	37-11 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000219006
Mailing Name:	JUNG SUN LAUNDRY SITE
Mailing Contact:	JUNG SUN LAUNDRY SITE
Mailing Address 1:	3710 24TH ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183473200

JUNG SUN LAUNDRY SITE (Continued) **S118260210**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2015
Trans1 Recv Date:	10/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000219006
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	014894109JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	42980
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J101 **JUNG SUN LAUNDRY SITE** **NJ MANIFEST** **S122377735**
SE **37-11 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.087 mi.
459 ft. **Site 3 of 15 in cluster J**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYR000219006
Mail Address:	24TH ST
Mail City/State/Zip:	LONG ISLAND CITY, NY 11101
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	SADIQUE AHMED
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014894109JJK
EPA ID:	NYR000219006
Date Shipped:	10/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730300JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730313JJK
EPA ID:	NYR000219006
Date Shipped:	7/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730318JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730324JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014894111JJK

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

EPA ID:	NYR000219006
Date Shipped:	10/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730295JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730299JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730302JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730317JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730321JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730301JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Manifest Number:	014730312JJK
EPA ID:	NYR000219006
Date Shipped:	7/24/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014894110JJK
EPA ID:	NYR000219006
Date Shipped:	10/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730294JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730297JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported
Manifest Number:	014730323JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730298JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJR000029967
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Manifest Number:	014730320JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101

JUNG SUN LAUNDRY SITE (Continued) **S122377735**

Reason Load Was Rejected:	Not reported
Manifest Number:	014730322JJK
EPA ID:	NYR000219006
Date Shipped:	7/22/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	PAD146714878
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

F102 **PEP BOYS STORE #1072** **RCRA-VSQG** **1016455661**
SW **38-19 21ST ST** **FINDS** **NYR000207662**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.089 mi.
471 ft. **Site 7 of 9 in cluster F**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20140218
Handler Name:	Pep Boys Store #1072
Handler Address:	38-19 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000207662
Contact Name:	YOLANDA GALLARDO
Contact Address:	ENVIRONMENTAL DEPT

PEP BOYS STORE #1072 (Continued) **1016455661**

Contact City,State,Zip:	PHILADELPHIA, PA 19132
Contact Telephone:	215-430-9017
Contact Fax:	215-430-4639
Contact Email:	YOLANDA_GALLARDO@PEPBOYS.COM
Contact Title:	ENVIRONMENTAL COORDINATOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ENVIRONMENTAL DEPT
Mailing City,State,Zip:	PHILADELPHIA, PA 19132
Owner Name:	Lupo Realty Co
Owner Type:	Private
Operator Name:	Pep Boys - Manny Moe & Jack Of Delaware
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20151020
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

PEP BOYS STORE #1072 (Continued) **1016455661**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: LUPO REALTY CO
Legal Status: Private
Date Became Current: 20130108
Date Ended Current: Not reported
Owner/Operator Address: 141 E MAIN ST
Owner/Operator City,State,Zip: HUNTINGTON, NY 11724
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: PEP BOYS - MANNY MOE & JACK OF DELAWARE
Legal Status: Private
Date Became Current: 20140108
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140218
Handler Name: PEP BOYS STORE #1072
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 44131
NAICS Description: AUTOMOTIVE PARTS AND ACCESSORIES STORES

NAICS Code: 811111
NAICS Description: GENERAL AUTOMOTIVE REPAIR

PEP BOYS STORE #1072 (Continued) **1016455661**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058879897

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016455661
Registry ID:	110058879897
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058879897
Name:	PEP BOYS STORE #1072
Address:	38-19 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

F103 **PEP BOYS STORE #1072** **NY AST** **A100394255**
SW **38-19 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.089 mi.
471 ft. **Site 8 of 9 in cluster F**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	PEP BOYS STORE #1072
Address:	38-19 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612278
Program Type:	PBS
UTM X:	589540.90060
UTM Y:	4512351.50619
Expiration Date:	08/19/2024
Site Type:	Other

Affiliation Records:

Site Id:	498861
Affiliation Type:	Emergency Contact
Company Name:	LUPO REALTY CO % ROBERT A. ROSS ESQ
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	Not reported

PEP BOYS STORE #1072 (Continued) **A100394255**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(215) 430-9645
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-08-19

Site Id:	498861
Affiliation Type:	Facility Operator
Company Name:	PEP BOYS STORE #1072
Contact Type:	Not reported
Contact Name:	PEP BOYS - MANNY, MOE & JACK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 706-7830
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2014-08-19

Site Id:	498861
Affiliation Type:	Facility Owner
Company Name:	LUPO REALTY CO % ROBERT A. ROSS ESQ
Contact Type:	ENVIRONMENTAL COORDINATOR
Contact Name:	ALANA PERSAD
Address1:	141 EAST MAIN ST
Address2:	Not reported
City:	HUNTINGTON
State:	NY
Zip Code:	11724
Country Code:	001
Phone:	(631) 385-9354
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-08-15

Site Id:	498861
Affiliation Type:	Mail Contact
Company Name:	PEP BOYS - MANNY, MOE & JACK
Contact Type:	Not reported
Contact Name:	ANGELA BANKS
Address1:	ATTN: ENVIRONMENTAL DEPT.
Address2:	3111 WEST ALLEGHENY AVENUE
City:	PHILADELPHIA
State:	PA
Zip Code:	19132
Country Code:	001
Phone:	(215) 430-9645

PEP BOYS STORE #1072 (Continued) **A100394255**

EMail:	ANGELA_BANKS@PEPBOYS.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2019-08-15

Tank Info:

Tank Number:	001
Tank Id:	252786

Equipment Records:

L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
E00 - Piping Secondary Containment - None
G12 - Tank Secondary Containment - Double-Walled (AG only)
H02 - Tank Leak Detection - Interstitial - Manual Monitoring
J01 - Dispenser - Pressurized Dispenser
F00 - Pipe External Protection - None
I01 - Overfill - Float Vent Valve
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/25/2014
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

I104 **JIANGS REALTY INC** **NY UST** **U004047267**
ENE **36-21 22ND STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.089 mi.
472 ft. **Site 2 of 2 in cluster I**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	JIANGS REALTY INC
Address:	36-21 22ND STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-607676 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	588867.39859
UTM Y:	4511390.25975
Site Type:	Other

JIANGS REALTY INC (Continued) **U004047267**

Affiliation Records:

Site Id:	29528
Affiliation Type:	Facility Owner
Company Name:	JIANGS REALTY INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	41-29 74 STREET
Address2:	Not reported
City:	ELMHURST
State:	NY
Zip Code:	11373
Country Code:	001
Phone:	(212) 995-9616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29528
Affiliation Type:	Mail Contact
Company Name:	Not reported
Contact Type:	Not reported
Contact Name:	JIANGS REALTY INC
Address1:	41-29 74 STREET
Address2:	Not reported
City:	ELMHURST
State:	NY
Zip Code:	11373
Country Code:	001
Phone:	(212) 995-9616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29528
Affiliation Type:	Facility Operator
Company Name:	JIANGS REALTY INC
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	29528
Affiliation Type:	Emergency Contact
Company Name:	JIANGS REALTY INC
Contact Type:	Not reported
Contact Name:	M.C.

JIANGS REALTY INC (Continued) **U004047267**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 995-9616
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	63360
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	2500
Install Date:	Not reported
Date Tank Closed:	07/03/2002
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)

J105 **SAN ANTON SERVICE STATION INC** **EDR Hist Auto** **1020373244**
ESE **23-02 37 AVE** **N/A**
< 1/8 **LONG IS CY, NY 11101**
0.091 mi.
482 ft. **Site 4 of 15 in cluster J**

Relative: EDR Hist Auto
Higher

Actual:
19 ft.

Year:	Name:	Type:
1969	SAN ANTON SERVICE STATION INC	Gasoline Service Stations
1969	SAN ANTON SERVICE STATION INC	Gasoline Service Stations
1970	SAN ANTON SERVICE STATION INC	Gasoline Service Stations
1975	J A P SERVICE STATION INC	Gasoline Service Stations

SAN ANTON SERVICE STATION INC (Continued) **1020373244**

1976	J A P SERVICE STATION INC	Gasoline Service Stations
1991	ANDREAS AUTO REPR SHOP INC	General Automotive Repair Shops
1992	ANDREAS AUTO REPR SHOP INC	General Automotive Repair Shops
1993	ANDREAS AUTO REPR SHOP INC	General Automotive Repair Shops
1994	ANDREAS AUTO REPR SHOP INC	General Automotive Repair Shops
1996	HI TECH AUTO DIAGNSTC CTR CORP	General Automotive Repair Shops
1997	HI TECH AUTO DIAGNSTC CTR CORP	General Automotive Repair Shops
1998	HI TECH AUTO DIAGNSTC CTR CORP	General Automotive Repair Shops
1999	HI TECH AUTO DIAGNOSTIC CENTER	General Automotive Repair Shops
2000	HI TECH AUTO DIAGNOSTIC CENTER	General Automotive Repair Shops
2001	HI TECH AUTO DIAGNOSTIC CENTER	General Automotive Repair Shops
2002	HI TECH AUTO DIAGNOSTIC CENTER	General Automotive Repair Shops
2003	HI TECH AUTO DIAGNOSTIC CENTER	General Automotive Repair Shops
2004	WONG 3 AUTO REPAIR CORP	General Automotive Repair Shops
2005	WONG 3 AUTO REPAIR CORP	General Automotive Repair Shops
2006	WONG 3 AUTO REPAIR CORP	General Automotive Repair Shops
2007	WONG 3 AUTO REPAIR CORP	General Automotive Repair Shops
2008	WONG 3 AUTO REPAIR CORP	General Automotive Repair Shops

K106 **ABC CONSTRUCTION CONTRACTING INC** **RCRA NonGen / NLR** **1004762113**
NE **36-11 19TH AVE** **FINDS** **NYR000093666**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.092 mi. **NY MANIFEST**
484 ft. **Site 1 of 18 in cluster K**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20180921
Handler Name:	Abc Construction Contracting Inc
Handler Address:	36-11 19TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000093666
Contact Name:	SPIRIDON KOKKOSIS
Contact Address:	19TH AVE
Contact City,State,Zip:	ASTORIA, NY 11105
Contact Telephone:	718-729-2501
Contact Fax:	718-729-2509
Contact Email:	SPIROS@ABCCCI.COM
Contact Title:	COO
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	19TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	36-16 19th Avenue Llc
Owner Type:	Private
Operator Name:	Abc Construction Contracting Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	Yes

ABC CONSTRUCTION CONTRACTING INC (Continued) **1004762113**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20191211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2001

Click Here for Biennial Reporting System Data:

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: STANKO KORONSOVAC	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	279 SQUAWBROOK DR
Owner/Operator City,State,Zip:	WYCKOFF, NJ 07482
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: STANKO KORONSOVAC	

ABC CONSTRUCTION CONTRACTING INC (Continued) **1004762113**

Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	279 SQUAWBROOK DR
Owner/Operator City,State,Zip:	WYCKOFF, NJ 07482
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	STANKO KORONSOVAC
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	279 SQUAWBROOK DR
Owner/Operator City,State,Zip:	WYCKOFF, NJ 07482
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ABC CONSTRUCTION CONTRACTING INC
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	36-11 19TH AVE
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	STANKO KORONSOVAC
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	279 SQUAWBROOK DR
Owner/Operator City,State,Zip:	WYCKOFF, NJ 07482
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	STANKO KORONSOVAC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	279 SQUAWBROOK DR
Owner/Operator City,State,Zip:	WYCKOFF, NJ 07482
Owner/Operator Telephone:	718-729-2501
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

ABC CONSTRUCTION CONTRACTING INC (Continued) **1004762113**

Owner/Operator Indicator: Owner
Owner/Operator Name: 36-16 19TH AVENUE LLC
Legal Status: Private
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 36-11 19TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-729-2501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: STANKO@ABCCCI.COM

Historic Generators:
Receive Date: 20060101
Handler Name: ABC CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ABC CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20170525
Handler Name: ABC CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20010129
Handler Name: A B C CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

ABC CONSTRUCTION CONTRACTING INC (Continued) **1004762113**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180921
Handler Name: ABC CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20020513
Handler Name: ABC CONSTRUCTION CONTRACTING INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004566844

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

ABC CONSTRUCTION CONTRACTING INC (Continued) **1004762113**

corrective action activities required under RCRA.
HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762113
Registry ID:	110004566844
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004566844
Name:	ABC CONSTRUCTION CONTRACTING INC
Address:	36-11 19TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	ABC CORPORATION
Address:	36-11 STARR AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000093666
Facility Status:	Not reported
Location Address 1:	36-11 STARR AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000093666
Mailing Name:	ABC CORPORATION
Mailing Contact:	N/S
Mailing Address 1:	36-11 STARR AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187292501

K107 **SUNOCO SERVICE STATION** **RCRA NonGen / NLR** **1000328878**
NNE **36-02 21ST ST** **FINDS** **NYD000707547**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.093 mi.
490 ft. **Site 2 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Sunoco Service Station
Handler Address:	36-02 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD000707547
Contact Name:	HOWARD ALGEO
Contact Address:	21ST ST

SUNOCO SERVICE STATION (Continued) **1000328878**

Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	215-688-8200
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	21ST ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Sun Oil Company Of Pennsylvania
Owner Type:	Private
Operator Name:	Sun Oil Company Of Pennsylvania
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

SUNOCO SERVICE STATION (Continued) **1000328878**

Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: SUN OIL COMPANY OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUN OIL COMPANY OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUN OIL COMPANY OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SUNOCO SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

SUNOCO SERVICE STATION (Continued) **1000328878**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SUNOCO SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: SUNOCO SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110009463570

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SUNOCO SERVICE STATION (Continued) **1000328878**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000328878
Registry ID:	110009463570
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009463570
Name:	SUNOCO SERVICE STATION
Address:	36-02 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

K108 **SEVIM MGMT BP PRODUCTS** **NY UST** **U000400997**
NNE **36-42 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.094 mi.
497 ft. **Site 3 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	SEVIM MGMT BP PRODUCTS
Address:	36-42 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-280410 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	10/06/2027
UTM X:	589697.27999
UTM Y:	4512592.08620
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	12250
Affiliation Type:	Mail Contact
Company Name:	SPARTAN PETROLEUM CORP.
Contact Type:	Not reported
Contact Name:	JAY SEMELMACHER
Address1:	3333 NEW HYDE PARK ROAD
Address2:	SUITE 201
City:	NEW HYDE PARK
State:	NY
Zip Code:	11042
Country Code:	001
Phone:	(516) 365-8700
EMail:	JZ@SPARTANPETRO.COM
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2020-07-01

Site Id:	12250
Affiliation Type:	Emergency Contact
Company Name:	SEVIM MANAGMENT
Contact Type:	Not reported
Contact Name:	SALLY GORUR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

SEVIM MGMT BP PRODUCTS (Continued) **U000400997**

Country Code:	999
Phone:	(516) 301-7521
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-10-19
Site Id:	12250
Affiliation Type:	Facility Operator
Company Name:	SEVIM MGMT BP PRODUCTS
Contact Type:	Not reported
Contact Name:	OZGUR ERDEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-1183
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2016-11-17
Site Id:	12250
Affiliation Type:	Facility Owner
Company Name:	SEVIM MANAGMENT
Contact Type:	PROPERTY MANAGER
Contact Name:	OZGUR ERDEN
Address1:	34-42 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 978-7046
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-30

Tank Info:

Tank Number:	001
Tank ID:	14581
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	12/01/1982
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	34

SEVIM MGMT BP PRODUCTS (Continued) **U000400997**

Date Test: 06/19/2020
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/26/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B08 - Tank External Protection - Retrofitted Impressed Current
G00 - Tank Secondary Containment - None
C02 - Pipe Location - Underground/On-ground
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
F08 - Pipe External Protection - Retrofitted Impressed Current
L99 - Piping Leak Detection - Other
A00 - Tank Internal Protection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
J01 - Dispenser - Pressurized Dispenser
D02 - Pipe Type - Galvanized Steel

Tank Number: 002
Tank ID: 14582
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1982
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 06/19/2020
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/26/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
A00 - Tank Internal Protection - None
L99 - Piping Leak Detection - Other
D02 - Pipe Type - Galvanized Steel
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F08 - Pipe External Protection - Retrofitted Impressed Current
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
B08 - Tank External Protection - Retrofitted Impressed Current
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin

SEVIM MGMT BP PRODUCTS (Continued) **U000400997**

Tank Number: 003
Tank ID: 14583
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1982
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 06/19/2020
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/26/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)
B08 - Tank External Protection - Retrofitted Impressed Current
C02 - Pipe Location - Underground/On-ground
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
F08 - Pipe External Protection - Retrofitted Impressed Current
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
G00 - Tank Secondary Containment - None
L99 - Piping Leak Detection - Other
J01 - Dispenser - Pressurized Dispenser
E00 - Piping Secondary Containment - None
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None

Tank Number: 004
Tank ID: 14584
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 12/01/1982
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 06/19/2020
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: LABATIST
Last Modified: 05/26/2022

Equipment Records:

H05 - Tank Leak Detection - In-Tank System (ATG)

SEVIM MGMT BP PRODUCTS (Continued) **U000400997**

B08 - Tank External Protection - Retrofitted Impressed Current
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F08 - Pipe External Protection - Retrofitted Impressed Current
A00 - Tank Internal Protection - None
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
D02 - Pipe Type - Galvanized Steel

H109 **VACANT BUILDING** **NY LTANKS** **S102232696**
NW **12-12 37TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.097 mi.
513 ft. **Site 5 of 8 in cluster H**

Relative: **Lower**
Actual: **15 ft.**

LTANKS:

Name:	VACANT BUILDING
Address:	12-12 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9604477 / 1996-09-16
Facility ID:	9604477
Site ID:	79310
Spill Date:	1996-07-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	O'DOWD
Referred To:	Not reported
Reported to Dept:	1996-07-03
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-03
Spill Record Last Update:	2008-02-01
Spiller Name:	MICHAEL VELLA
Spiller Company:	VACANT BUILDING
Spiller Address:	1212 37TH AVE.
Spiller County:	001
Spiller Contact:	MICHAEL VELLA
Spiller Phone:	(718) 417-8491
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	73724
DEC Memo:	""
Remarks:	"building is a old vacant factory"

All TTF:

Facility ID:	9604477

VACANT BUILDING (Continued) **S102232696**

Spill Number:	9604477
Spill Tank Test:	1544618
Site ID:	79310
Tank Number:	001
Tank Size:	1300
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	79310
Operable Unit ID:	1032129
Operable Unit:	01
Material ID:	347240
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

H110 **1212 37TH AVENUE** **NY UST** **U003127186**
NW **12-12 37TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11100**
0.097 mi.
513 ft. **Site 6 of 8 in cluster H**

Relative: **Lower**
Actual: **15 ft.**

UST:

Name:	1212 37TH AVENUE
Address:	12-12 37TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11100
Id/Status:	2-602746 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589099.51494
UTM Y:	4511936.60457
Site Type:	Other

Affiliation Records:

Site Id:	24702
Affiliation Type:	Facility Owner
Company Name:	TRUST UNDER THE WILL ARNOLD LEVIN/PHILIP LEVIEN
Contact Type:	Not reported
Contact Name:	Not reported

1212 37TH AVENUE (Continued) **U003127186**

Address1:	43 DEER PARK ROAD
Address2:	Not reported
City:	KINGSPOINT
State:	NY
Zip Code:	11024
Country Code:	001
Phone:	(516) 466-4459
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24702
Affiliation Type:	Mail Contact
Company Name:	TRUST UNDER THE WILL ARNOLD LEVIN/PHILIP LEVIEN
Contact Type:	Not reported
Contact Name:	PHILIP LEVIEN
Address1:	43 DEER PARK ROAD
Address2:	Not reported
City:	KINGSPOINT
State:	NY
Zip Code:	11024
Country Code:	001
Phone:	(516) 466-4459
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24702
Affiliation Type:	Facility Operator
Company Name:	1212 37TH AVENUE
Contact Type:	Not reported
Contact Name:	PHILIP LEVIEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 466-4459
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	24702
Affiliation Type:	Emergency Contact
Company Name:	TRUST UNDER THE WILL ARNOLD LEVIN/PHILIP LEVIEN
Contact Type:	Not reported
Contact Name:	PHILIP LEVIEN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001

1212 37TH AVENUE (Continued) **U003127186**

Phone:	(516) 466-4459
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	51367
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1300
Install Date:	Not reported
Date Tank Closed:	08/01/1996
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
A00 - Tank Internal Protection - None

L111 **SEGUNDO'S AUTO REPAIR, INC.** **NY AST** **A100295990**
SSW **38-38 22ND STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.100 mi.
530 ft. **Site 1 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	SEGUNDO'S AUTO REPAIR, INC.
Address:	38-38 22ND STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609132
Program Type:	PBS
UTM X:	589596.86345
UTM Y:	4512285.90572
Expiration Date:	04/01/2015
Site Type:	Auto Service/Repair (No Gasoline Sales)

SEGUNDO'S AUTO REPAIR, INC. (Continued) **A100295990**

Affiliation Records:

Site Id:	30978
Affiliation Type:	Mail Contact
Company Name:	SEGUNDOS AUTO REPAIR
Contact Type:	Not reported
Contact Name:	PAULA CRUZ
Address1:	38-38 22ND STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-8875
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-04-01

Site Id:	30978
Affiliation Type:	Facility Operator
Company Name:	SEGUNDOS AUTO REPAIR, INC.
Contact Type:	Not reported
Contact Name:	PAULA CRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 706-8875
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-04-01

Site Id:	30978
Affiliation Type:	Emergency Contact
Company Name:	PAULA CRUZ
Contact Type:	Not reported
Contact Name:	PAULA CRUZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 703-6723
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-04-01

Site Id:	30978
Affiliation Type:	Facility Owner
Company Name:	PAULA CRUZ
Contact Type:	Not reported
Contact Name:	Not reported

SEGUNDO'S AUTO REPAIR, INC. (Continued) **A100295990**

Address1:	38-38 22ND ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-8875
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-04-01

Tank Info:

Tank Number:	001
Tank Id:	66530
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	J00 - Dispenser - None
	D00 - Pipe Type - No Piping
	L00 - Piping Leak Detection - None
	G00 - Tank Secondary Containment - None
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	K00 - Spill Prevention - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	03/12/1993
Capacity Gallons:	27
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

K112 **GETTY #568** **NY Spills** **S107521456**
NNE **21ST/36 AVE** **N/A**
< 1/8 **LONG ISLAND, NY**
0.101 mi.
533 ft. **Site 4 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	GETTY #568
Address:	21ST/36 AVE
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0511107 / 2005-12-23
Facility ID:	0511107
Facility Type:	ER
DER Facility ID:	297164
Site ID:	357194
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	4101
Spill Date:	2005-12-22
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2005-12-22
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-22
Spill Record Last Update:	2005-12-23
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #568
Spiller Address:	21ST /36 AVE
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"cleaned up:"

All Materials:

Site ID:	357194
Operable Unit ID:	1114472
Operable Unit:	01
Material ID:	2104548
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K113 **GETTY STATION#568** **NY Spills** **S106969730**
NNE **21ST STREET/36 AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.101 mi.
533 ft. **Site 5 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	GETTY STATION#568
Address:	21ST STREET/36 AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0504524 / 2005-07-15
Facility ID:	0504524
Facility Type:	ER
DER Facility ID:	295820
Site ID:	349382
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2005-07-15
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2005-07-15
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-15
Spill Record Last Update:	2005-07-15
Spiller Name:	CAILYN DINAN
Spiller Company:	GETTY STATION#568
Spiller Address:	21ST STREET/36 AVE
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	"7/15/2005. All cleaned up by Tyree with speedy-dry. YK."
Remarks:	"ITS A STAIN LOCATED BY WASTE OIL TANK ON CONCRETE."

All Materials:

Site ID:	349382
Operable Unit ID:	1106977
Operable Unit:	01
Material ID:	2096301
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K114 **GETTY#568** **NY Spills** **S107521903**
NNE **36-02 21 STREET** **N/A**
< 1/8 **LONG ISLAND, NY**
0.101 mi.
533 ft. **Site 6 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	GETTY #568
Address:	36-02 21 STREET
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0511739 / 2006-01-11
Facility ID:	0511739
Facility Type:	ER
DER Facility ID:	307987
Site ID:	357955
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	4101
Spill Date:	2006-01-11
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-01-11
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-01-11
Spill Record Last Update:	2006-01-11
Spiller Name:	Not reported
Spiller Company:	CUTOMER OVERFILL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE CARRIER
DEC Memo:	""
Remarks:	"ALL CLEANED UP: NO RELEASE TO ENVIROMENT"

All Materials:

Site ID:	357955
Operable Unit ID:	1115219
Operable Unit:	01
Material ID:	2105275
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	GETTY#568

GETTY#568 (Continued) **S107521903**

Address:	36-02 21 STREET
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0703759 / 2007-09-11
Facility ID:	0703759
Facility Type:	ER
DER Facility ID:	307987
Site ID:	383767
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	4101
Spill Date:	2007-07-02
Investigator:	smsanges
Referred To:	Not reported
Reported to Dept:	2007-07-02
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-07-02
Spill Record Last Update:	2007-09-11
Spiller Name:	MIKE CARR\\
Spiller Company:	GETTY#568
Spiller Address:	36-02 21 STREET
Spiller Company:	001
Contact Name:	MIKE CARR\\
DEC Memo:	"Tyree writeup says: Water with sheen in tank top. Sumps vaced out by bac truck Sheen most likely from residual product on fittings within tank top sump, historical in nature. Spill Closed"
Remarks:	"VAC TRUCK SCHEDULED"

All Materials:

Site ID:	383767
Operable Unit ID:	1141095
Operable Unit:	01
Material ID:	2131248
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	383767
Operable Unit ID:	1141095
Operable Unit:	01
Material ID:	2131249
Material Code:	0008

GETTY#568 (Continued) **S107521903**

Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported
Site ID:	383767
Operable Unit ID:	1141095
Operable Unit:	01
Material ID:	2131250
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K115 **GETTY 568** **NY Spills** **S106970509**
NNE **21ST STREET AND 36TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.101 mi.
533 ft. **Site 7 of 18 in cluster K**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	GETTY 568
Address:	21ST STREET AND 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0505775 / 2005-08-16
Facility ID:	0505775
Facility Type:	ER
DER Facility ID:	297772
Site ID:	350866
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	4101
Spill Date:	2005-08-10
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2005-08-10
CID:	408
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-10

GETTY 568 (Continued) **S106970509**

Spill Record Last Update:	2005-08-16
Spiller Name:	CAILYN DINAN
Spiller Company:	GETTY 568
Spiller Address:	21ST STREET AND 36TH AVE
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	"8/16/05-Vought-Called and spoke to Dinan and spill on concrete and no sewers or drains affected. Spill cleaned using adsorbent material. Spill closed by Vought."
Remarks:	"ABOUT 1/2 GALLON AND WAS CLEANED UP"

All Materials:

Site ID:	350866
Operable Unit ID:	1108407
Operable Unit:	01
Material ID:	2098343
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

K116 **GETTY # 568** **NY Spills** **S107522419**
NNE **36-21 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.101 mi.
533 ft. **Site 8 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

SPILLS:

Name:	GETTY # 568
Address:	36-21 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0512432 / 2006-01-27
Facility ID:	0512432
Facility Type:	ER
DER Facility ID:	308743
Site ID:	358750
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2006-01-26
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-01-26
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

GETTY # 568 (Continued) **S107522419**

UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2009-12-07
Spiller Name:	Not reported
Spiller Company:	LEAKING AUTO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"Appears to be waste oil leaking from a car. Spill was cleaned up."
Remarks:	"and is all cleaned up: less then 1 cup"

All Materials:

Site ID:	358750
Operable Unit ID:	1115977
Operable Unit:	01
Material ID:	2106088
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K117 **GETTY #568** **NY Spills** **S103273938**
NNE **21ST STREET AND 36TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.101 mi.
533 ft. **Site 9 of 18 in cluster K**

Relative: Higher

Actual: 17 ft.

SPILLS:

Name:	GETTY #568
Address:	21ST STREET AND 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9801243 / 2006-02-07
Facility ID:	9801243
Facility Type:	ER
DER Facility ID:	297772
Site ID:	249309
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	4101
Spill Date:	1998-04-29
Investigator:	rjfeng
Referred To:	Not reported
Reported to Dept:	1998-04-29
CID:	267
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

GETTY #568 (Continued) **S103273938**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-29
Spill Record Last Update:	2006-02-07
Spiller Name:	JIM MASSONE
Spiller Company:	GETTY
Spiller Address:	30-23 GREEN POINT AVE
Spiller Company:	001
Contact Name:	JIM MASSONE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT 2/18/04 - AUSTIN - REASSIGNED FROM TOMASELLO TO VOUGHT - END 08/31/2005 - Feng - Project transferred from Vought to Feng. 10/18/2005 - Feng - Spill#: 05-05641 has been consolidated into this spill#. 10/26/2005 - Feng - nothing on file yet 2/7/2006 - Feng - according to the caller, 4 gallons spilled unto pavement and was cleaned up with opps kit and sand, so spill closed. (RJF)"
Remarks:	"DURING A FILL AT THE GAS STATION AT ABOVE LOCATION 4 GALLONS SPILLED UNTO PAVEMENT AND WAS CLEANED UP WITH AN OPPS KIT AND SAND"

All Materials:

Site ID:	249309
Operable Unit ID:	1061916
Operable Unit:	01
Material ID:	323177
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	4.00
Resource Affected:	Soil
Oxygenate:	Not reported

K118 **GETTY #568** **NY Spills** **S106971060**
NNE **21ST/36 AVE** **N/A**
< 1/8 **LONG ISLAND, NY**
0.101 mi.
533 ft. **Site 10 of 18 in cluster K**

Relative: **Higher**
Actual: **17 ft.**

SPILLS:

Name:	GETTY #568
Address:	21ST/36 AVE
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0505641 / 2005-10-18
Facility ID:	0505641
Facility Type:	ER
DER Facility ID:	297164
Site ID:	350690
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	4101

GETTY #568 (Continued) **S106971060**

Spill Date:	2005-08-08
Investigator:	rjfeng
Referred To:	Not reported
Reported to Dept:	2005-08-08
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-08
Spill Record Last Update:	2005-10-18
Spiller Name:	CAILYN DINAN
Spiller Company:	GETTY #568
Spiller Address:	21ST/36 AVE
Spiller Company:	001
Contact Name:	CAILYN DINAN
DEC Memo:	"08/31/2005 - Feng - Project transferred from Vought to Feng. 10/18/2005 - Feng - spill consolidated with spill #: 98-01243 in same location."
Remarks:	"STAINING OF DIESEL ALSO: ALL CLEANED UP:"

All Materials:

Site ID:	350690
Operable Unit ID:	1108247
Operable Unit:	01
Material ID:	2098181
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Site ID:	350690
Operable Unit ID:	1108247
Operable Unit:	01
Material ID:	2098182
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K119 **GLOBAL MONTELLO GROUP CORP. #5432** **NY AST** **U000407912**
NNE **36-02 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.101 mi.
534 ft. **Site 11 of 18 in cluster K**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	GLOBAL MONTELLO GROUP CORP. #5432
Address:	36-02 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-146048
Program Type:	PBS
UTM X:	589732.08506
UTM Y:	4512643.68591
Expiration Date:	04/08/2024
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	4215
Affiliation Type:	Mail Contact
Company Name:	ATLAS
Contact Type:	Not reported
Contact Name:	MEGAN KAZMIERCZAK
Address1:	685 GRANDVIEW AVENUE
Address2:	Not reported
City:	COLUMBUS
State:	OH
Zip Code:	43215
Country Code:	001
Phone:	(614) 433-0170
EMail:	GLOBALPARTNERS@ONEATLAS.COM
Fax Number:	Not reported
Modified By:	KXLIU
Date Last Modified:	2022-12-28

Site Id:	4215
Affiliation Type:	Facility Operator
Company Name:	GLOBAL MONTELLO GROUP CORP. #5432
Contact Type:	Not reported
Contact Name:	DAVID WENT
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-0250
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-11-16

Site Id:	4215
Affiliation Type:	Facility Owner
Company Name:	LEEMILTS PETROLEUM, INC.
Contact Type:	AUTHORIZED REPRESENTATIVE
Contact Name:	MEGAN KAZMIERCZAK

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U000407912**

Address1:	292 MADISON AVENUE, 9TH FLOOR
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10017-6318
Country Code:	001
Phone:	(646) 349-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-12-24

Site Id:	4215
Affiliation Type:	Emergency Contact
Company Name:	LEEMILTS.
Contact Type:	Not reported
Contact Name:	CALL CENTER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(888) 674-7601
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2013-05-09

Tank Info:

Tank Number:	018
Tank Id:	56354
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
D10 - Pipe Type - Copper
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1998
Capacity Gallons:	240

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U000407912**

Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	019
Tank Id:	54322
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

G12 - Tank Secondary Containment - Double-Walled (AG only)
J00 - Dispenser - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
I02 - Overfill - High Level Alarm
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
F00 - Pipe External Protection - None
C00 - Pipe Location - No Piping

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1998
Capacity Gallons:	240
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

K120 **3602 21ST STREET** **NY Spills** **S109371707**
NNE **3602 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 10016**
0.101 mi.
534 ft. **Site 12 of 18 in cluster K**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	3602 21ST STREET
Address:	3602 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 10016
Spill Number/Closed Date:	0807017 / 2010-11-30
Facility ID:	0807017
Facility Type:	ER

3602 21ST STREET (Continued) **S109371707**

DER Facility ID:	353592
Site ID:	404330
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2008-09-22
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2008-09-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-22
Spill Record Last Update:	2011-02-17
Spiller Name:	MATT DOMINICK
Spiller Company:	UNKNOWN
Spiller Address:	3602 21ST STREET
Spiller Company:	999
Contact Name:	MATT DOMINICK
DEC Memo:	"09/23/08-Hiralkumar Patel. spoke with Mr. Dominick at DEP. they were repairing water main leak and during excavation they found contaminated soil above water main location. once they reach to water main line, water filled excavation and sheen was observed on top of water. no odors inside excavation. suggest Mr. Dominick to backfill excavation once they repair water line. Mr. Dominick mentioned that contaminated soil found in front of property 3602 21st street and that is Getty gas station. multiple spills found at the site. spill #: 9801243 reported 4 gal gasoline spill in Apr. 1998 and spill closed in Feb. 2006. spill #: 9805206 reported contamianted soil while tank removal and spill closed in Dec. 2004. spill #: 0505775 reported 1 gal motor oil spill in Aug. 2005 and spill closed in Aug. 2005. PBS #: 2-146048. alternate addresses: 14-08 to 14-14 36th Ave visited site. met Mr. Singh, operator of gas station. Mr. Singh showed location where DEP was working. DEP worked on street near fire hydrant on 21st street. this hydrant is about 20 ft away from dispenser islands. Mr. Singh mentioned that tank system including pipings and dispenser islands were upgraded in 1998. and old dispenser islands were located at same location where existing dispenser islands are. Tejinter Singh **gas station owner** 36-02 21st Street Long Island City, NY 11105 Ph. (718) 392-0250 Fax (718) 392-2665 email: narkeet@aol.com reviwed available documents for spill #:

3602 21ST STREET (Continued) **S109371707**

9805206. removed ten 550 gal gasoline USTs, one 1000 gal fuel oil UST and one 550 gal waste oil
tank from the site. after removing tanks, collected endpoint samples from tank field excavation.
found high contamination in endpoint samples. no contamination found in endpoint sample taken close
to previous dispenser island location (SW-4). no indication about dispenser island removal. no
sampling around dispenser island. from PBS record, property owner is Getty Petroleum Marketing Inc.
left message for Mr. Hanley to confirm ownership of the site. sent email to Mr. Hanley.
10/01/08-Hiralkumar Patel. left message for Mr. Hanley to provide property owner's information.
11/21/08-Hiralkumar Patel. left message for Bob Walsh (??) at Getty to confirm ownership.
11/25/08-Hiralkumar Patel. spoke with person in tax department at Getty, who confirmed that Mr.
Hanley is environmental incharge for subject getty station. left message for Mr. Hanley to call
back by end of 11/26/08. Scott Hanley Ph. (516) 542-5022 left message for Mr. Hatcher at Tyree
(environmental consultant for Getty). Paul Hatcher Tyree Ph. (631) 249-3150 12/02/08-Hiralkumar
Patel. received call from Mr. Hanley from Getty petroleum marketing. Mr. Hanley mentioned that
getty petroleum marketing ownes tanks at the site and site owner is Getty Realty. he asked to
contact Mr. Shea at Getty Realty. Getty Petroleum Marketing Inc. **tank owner** 1500 Hempstead
Turnpike East Meadow, NY 11554 Attn.: Scott Hanley Ph. (516) 542-4900 (914) 646-1869 email:
shanley@getty.com Mr. Hanley mentioned that contamination under sidewalk could be result of old
spill in 1998 and at that time, Getty Realty corp. was owner. spoke with Chuk Levy (516-478-5426)
at Getty. he confirmed site ownership with following information: Leemilt's Petroleum, Inc. **site
owner and previous tank owner** 125 Jericho Turnpike, Suite # 103 Jericho, NY 11753 Attn.: Kevin
Shea PH. (516) 478-5480 Fax (516) 478-5490 email: kshea@gettyrealty.com sent letter to Mr. Hanley
and Mr. Shea requiring soil delineation between fire hydrant along 21st street and on-site
dispensers. letter emailed to Mr. Hanley and Mr. Shea.
12/18/08-Hiralkumar Patel. received call
from Matt from Tyree. they have been hired for required work. will call back with work schedule.
Matt Boeckel Tyree Ph. (508) 922-9044 (C) (631) 249-3150 Ext. 241 email: mboeckel@tyreeorg.com
01/21/09-Hiralkumar Patel. received email from Matt with letter. Matt mentioned that dispensing
lines and leak detectors were tested on 07/25/03, 09/27/04, 11/21/05, 09/01/06, 09/04/07 and
08/18/08 and all tests passed. tanks were also tested on 09/04/07 and found tight. he also
mentioned that there were no investigation/remediation work done in

3602 21ST STREET (Continued) **S109371707**

area between dispenser island
and street. based on these informations, he believes that contamination found recently under the
sidewalk could be result of old leak in 1998 and Getty REalty Corp. (previous owner) is responsible
for required investigation. spoke with Matt. explained him that the department requires
investigation for soil contamination that might be originated from the gas station and as no record
whether this contamination from old spill or any spill on-site under new ownership, the department
requires current owner to perform investigation (to justify their claim). received email from Matt
at 3:50 PM. he spoke with Getty marketing and current tank owner will conduct soil delineation.
will also collect samples for figerprint analysis and age dating analysis. will send work schedule.
01/27/09-Hiralkumar Patel. received call from Matt. they are at the site doing soil investigation.
02/26/09-Hiralkumar Patel. spoke with Matt. he is waiting for lab data. will submit report.
03/23/09-Hiralkumar Patel. spoke with Matt. he got analyticals and will submit report by 03/31/09.
04/23/09-Hiralkumar Patel. received report from Matt. abstract: - four soil/groundwater borings
were installed to depth of 15 ft bg in area between dispenser islands and fire hydrant along 21st
street - soil samples collected at highest PID or at groundwater interface if no PID found above it
- no PID readings found in soil from 0 to 10 ft depth - found high PID readings at groundwater
interface in boring B2 (45 ppm) and B3 (225 ppm) - found odor and staining in soil at water
interface in boring B2 and B3 - soil samples from each borings were collected at depth of 10-12 ft
bg - groundwater encountered at 12 ft bg <------- - found high VOC contamination in samples from B2
and B3 - SVOC contamination found in B-2 - minor contamination found in groundwater samples (21 ppb
Xylene in B3) - percent aging was conducted on sample from boring B3 and results indicate that this
is from an older spill and approx. 90% of the original contaminants have degraded <--------- soil
analyticals ----------B-2----------B-3
Benzene----------900----------470
Toluene----------1,430
Ethylbenzene----------33,900--------81,500
Xylene----------54,700--------80,500
Naphthalene----------364,000-------169,000
1,2,4-Trimethylbenzene---37,600--------50,200
1,3,5-Trimethylbenzene---12,000--------14,900 04/29/09-Hiralkumar Patel. spoke with Matt. he
confirmed that all previous monitoring wells have been abandoned.
05/06/09-Hiralkumar Patel. review
of old file for spill # 9805206:
--*-

3602 21ST STREET (Continued) **S109371707**

report: - dated June 11, 1999 - tanks removed as part of EPA mandated upgrade - one pump island
located adjacet to 21st street <------- - removed ten 550 gal single wall steel, concrete encased
gasoline UST located east of station building - removed one 1000 gal single wall steel, concrete
encased fuel oil UST located northeast of station building - removed one 550 gal single wall steel
waste oil UST located adjacent to, and southeast of station building - soils found fine to medium
grained sand, dark grey clayey silt <--------- - groundwater was not encountered during tanks
removal - 12 endpoint samples collected: eleven samples collected (SW-1 to SW-8 and B-1 to B-3))
from excavation of gasoline and fuel oil tank and one endpoint sample collected (waste oil) after
removal of waste oil tank - sidewall samples collected at 9 ft depth and bottom samples collected
at 11 ft depth from gasoline tank excavation - one endpoint bottom sample was collected at 9 ft
depth from waste oil tank excavation - 1,135 gal liquid removed from tanks - 105.04 tons of soil
removed - 550 gal gasoline tanks were 3.5 ft in diameter and 8 ft long <---------- - 1000 gal
fuel oil tank was 4 ft in diameter and 10 ft 8 inch long <----------
- 550 gal waste oil tank was
4 ft in diameter and 6 ft long <---------- - no holes found in tanks after removal - found heavy
contamination in endpoint sidewall and bottom samples - found high PID in endpoint samples PID
readings in endpoint samples: ----------depth in ft--------PID value in ppm
SW-1----------9----------294
SW-2----------9----------421
SW-3----------9----------1,200
SW-4----------9----------184
SW-5----------9----------235
SW-6----------6----------87
SW-7----------9----------192
SW-8----------3.5----------4
B-1----------11----------2,250
B-2----------11----------321
B-3----------11----------2,105 waste oil----------9----------443
endpoint soil analyticals:
----------SW-3---------B-1--------B-3-------waste oil
Toluene----------4,960------50,200------1,000
Ethylbenzene----------34,600
Xylene----------356,000-----309,500------7,820---------2,960
1,2,4-Trimethylbenzene---392,000-----304,000
1,3,5-Trimethylbenzene---135,000------10,300
Naphthalene----------29,400-----102,000 MTBE values in endpoint samples: ----------MTBE
SW-2----------152 SW-3---------5,490 SW-4----------165
SW-5----------573 SW-6----------453
B-1---------17,000 B-2----------435 B-3----------1,960 waste

3602 21ST STREET (Continued) **S109371707**

oil------669 well logs: - four
monitoring wells installed on 05/25/2000 - wells were installed to
depth of 25 ft bg with screen
from 5 to 25 ft - groundwater found at 10 ft depth <----------
July-Sep. 2000 quarterly monitoring
report: - no LNAPL found in any wells - groundwater was found at depth
ranging from 10.72 ft (MW-1)
to 12.23 ft (MW-4) - groundwater flow towards southwest <--------- -
contamination found in MW-2
Oct.-Dec. 2000 quarterly monitoring report: - no LNAPL found in any
wells - groundwater was found
at depth ranging from 10.75 ft (MW-1) to 11.85 ft (MW-4) - groundwater
flow towards southwest
<--------- - contamination found in MW-2 Jan-Mar 2001 quarterly
monitoring report: - no LNAPL found
in any wells - groundwater was found at depth ranging from 9.40 ft
(MW-1) to 11.25 ft (MW-4) -
groundwater flow towards southwest <--------- - contamination found in
MW-2 Apr-Jun 2001 quarterly
monitoring report: - no LNAPL found in any wells - groundwater was
found at depth ranging from 9.37
ft (MW-1) to 9.60 ft (MW-4) - groundwater flow towards southwest
<--------- - contamination found
in MW-2 Jul-Sep 2001 quarterly monitoring report: - no LNAPL found in
any wells - groundwater was
found at depth ranging from 10.38 ft (MW-1) to 11.51 ft (MW-4) -
groundwater flow towards southwest
<--------- - contamination found in MW-2 Oct-Dec 2001 quarterly
monitoring report: - no LNAPL found
in any wells - groundwater was found at depth ranging from 10.83 ft
(MW-1) to 12.96 ft (MW-4) -
groundwater flow towards southwest <--------- - no contamination found
in MW-2 - contamination
found in MW-3 Jan-Mar 2002 quarterly monitoring report: - no LNAPL
found in any wells - groundwater
was found at depth ranging from 10.97 ft (MW-1) to 12.02 ft (MW-4) -
groundwater flow towards
southwest <--------- - contamination found in MW-2 - no contamination
found in MW-3 Apr-Jun 2002
quarterly monitoring report: - no LNAPL found in any wells -
groundwater was found at depth ranging
from 10.67 ft (MW-1) to 11.78 ft (MW-4) - groundwater flow found
tidally influenced <--------- -
contamination found in MW-2 Jul-Sep 2002 quarterly monitoring report:
- no LNAPL found in any wells
- groundwater was found at depth ranging from 10.63 ft (MW-1) to 11.76
ft (MW-4) - groundwater flow
found tidally influenced <--------- - contamination found in MW-2
Oct-Dec 2002 quarterly monitoring
report: - no LNAPL found in any wells - groundwater was found at depth
ranging from 10.54 ft (MW-1)
to 11.70 ft (MW-4) - groundwater flow found tidally influenced
<--------- - contamination found in
MW-1 - no contamination found in MW-2 Jan-Mar 2003 quarterly
monitoring report: - no LNAPL found in
any wells - groundwater was found at depth ranging from 10.40 ft
(MW-1) to 11.58 ft (MW-4) -

3602 21ST STREET (Continued) **S109371707**

groundwater flow found tidally influenced <--------- - contamination found in MW-2 & MW-4 - MW-3
was not accessible Aug-Oct 2003 quarterly monitoring report: - no LNAPL found in any wells -
groundwater was found at depth ranging from 10.87 ft (MW-3) to 11.97 ft (MW-4) - groundwater flow
found tidally influenced <--------- - contamination found in MW-2 (B-172 ppb, E-127 ppb) DEC Vought
sent letter on Oct. 3, 2003 requiring complete soil and groundwater delineation at former endpoint
locations SW3 and B1, southwest of SW3 and B1, northwest of service station building and northeast
of MW-2. also required surrounding property sketch. Oct-Dec 2003 quarterly monitoring report: - no
LNAPL found in any wells - groundwater was found at depth ranging from 10.77 ft (MW-1) to 11.90 ft
(MW-4) - groundwater flow found tidally influenced <--------- - contamination found in MW-2 (B-123
ppb, E-136 ppb) Tyree sent letter to the department proposing to install five borings for
delineation requirement as per letter dated Oct. 3, 2003. Feb. 25, 2004 subsurface investigation
report: - one pump island located adjacent to 21st street - four 4,000 gal gasoline USTs on site -
installed five borings, borings were terminated at depth of 16 ft bg - dark brown to brown, medium
to coarse grained sand found in borings - groundwater found at 13.5 ft (SB-1), 11 ft (SB-2), 12 ft
(SB-3), 12 ft (SB-4) and 13 ft (SB-5) - five soil and five groundwater samples collected for
analysis - found high PID in soil from SB-3 at 0-4 ft depth (152 ppm) and at 4-8 ft (48 ppm); no
PID readings found in other borings - minor contamination found in soil from SB-3 at 0-4 ft depth
(X-1,071 ppb, 1,2,4-7,360 ppb and 1,3,5-3,700 ppb) DEC Vought sent letter on Mar. 19, 2004
requiring continued quarterly groundwater monitoring based on Aug-Oct 2003 monitoring report.
Jan-Jun 2004 quarterly monitoring report: - no LNAPL found in any wells - groundwater was found at
depth ranging from 10.99 ft (MW-1) to 12.06 ft (MW-4) - groundwater flow found tidally influenced
<--------- - groundwater samples in Mar 2004 and in Jun 2004 - contamination found in MW-2 (B-142
ppb, E-95 ppb) during sampling in Mar. 2004. DEC Vought sent NFA letter on Dec. 03, 2004 (wrong
date on letter Dec. 3, 2003). groundwater data:
----------MW-1----------MW-2----------MW-3----------MW-4
----------BTEX-----MTBE-------BTEX-----MTBE-------BTEX-----MTBE-------BTEX-----MTBE Jul-Sep
2000----------746------499 Oct-Dec
2000----------573------106
Jan-Mar 2001----------259 Apr-Jun
2001----------126 Jul-Sep
2001----------98--------8 Oct-Dec
2001----------385 Jan-Mar

3602 21ST STREET (Continued) **S109371707**

2002----------376
Apr-Jun 2002----------396 Jul-Sep
2002----------265-------16
Oct-Dec 2002-----1,105----2,890 Jan-Mar
2003----------495-------13----------
----------25 Aug-Oct
2003----------322 Oct-Dec
2003----------282 Mar.
2004----------254 Jun.
2004----------79
--*-

3602 21ST STREET (Continued) **S109371707**

interface, its site owner's
(Leemilt's Petroleum, Inc.) responsibility. after discussing with DEC legal, sent STIP letter to
Mr. Shea requiring to submit signed STIP and investigation work plan by the end of 12/31/09. letter
emailed to Mr. Shea, Mr. Hanley, Matt and Mr. Lindell.
03/31/10-Hiralkumar Patel. 10:27 AM:- called
for Mr. Shea, but receiptionist transferred call to Brad Fisher at Delta consultants who was in Mr.
Shea's office. Mr. Fisher mentioned that he represents Getty Realty and the department should talk
to him instead of Mr. Shea. Mr. Fisher mentioned that he just took over project and doesn't know
much about this spill. Mr. Fisher requested copy of investigation report prepared in Apr. 2009 by
Getty Marketing. discussed case with DEC legal. 11:21 AM:- spoke with Mr. Fisher and asked him to
submit written response, from Getty Realty, for letter dated 12/04/09. informed Mr. Fisher that
reponse must be submitted by the end of 04/02/10. Brad Fisher Delta Consultants Ph. (914) 495-9936
email: bfisher@deltaenv.com 11:36 AM:- sent email to Mr. Fisher and Mr. Shea with copy of
investigation report (dated Apr. 2009) and asked to submit written response to letter dated
12/04/09, by the end of 04/02/10. 04/02/10-Hiralkumar Patel. 11:13 AM:- received call from Mr.
Fisher. he mentioned that attorneys for Getty Marketing and Getty Realty are discussing this matter
and need some extra time to resolve this. asked Mr. Fisher to provide final answer, about STIP
signature and who is going to do work, by end of 04/08/10.
04/08/10-Hiralkumar Patel. 9:28 AM:-
received message from Mr. Fisher. he mentioned that Getty Realty has signed STIP, but he wants to
discuss time line on CAP before he forward signed STIP to the Department. 04/09/10-Hiralkumar
Patel. 8:40 AM:- left message for Mr. Fisher. 1:48 PM:- received call from Mr. Fisher. he asked
about modification in CAP. informed him that the only change in CAP will be deadline for submission
of an investigation work plan. 2:58 PM:- sent modified CAP to Mr. Shea via email. email copied to
Mr. Fisher. 04/15/10-Hiralkumar Patel. received two copies of signed STIP (at 12:20 PM on 04/14/10)
from Getty realty. 04/16/10-Hiralkumar Patel. 10:08 AM:- forwarded STIP to DEC Lou for regional
director's signature. 04/19/10-Hiralkumar Patel. 12:19 PM:- received email from DEC Lou with copy
of fully signed STIP. 2:20 PM:- sent email to Mr. Shea with copy of fully executed STIP. email
copied to Mr. Fisher, Mr. Hanley and Matt. 05/18/10-Hiralkumar Patel. 4:51 PM:- sent email to Mr.
Shea reminding him to submit investigation work plan by tomorrow, as per signed STIP. email copied
to Mr. Fisher, Mr. Hanley and Matt. 4:58 PM:- received email from Mr. Fisher requesting deadline

3602 21ST STREET (Continued) **S109371707**

extension to 05/28/10. 05/20/10-Hiralkumar Patel. 3:23 PM:- sent email to Mr. Fisher. informed him
that the work plan must be submitted by the end of 05/24/10 (final notice). 05/21/10-Hiralkumar
Patel. 11:47 AM:- received email from Mr. Fisher. he is out of office on 05/24/10, so he requested
to extend one more day to submit work plan (on 05/25/10). 11:48 AM:- sent email to Mr. Fisher
approving his request. 06/01/10-Hiralkumar Patel. received work plan from Mr. Fisher (at 4:09 PM on
05/25/10). abstract: - five soil borings will be installed to 17 ft bg - soil samples will be
collected at highest PID or above water table (with PID less than 10 ppm) - three soil borings will
be converted into 2 inch permanent wells with 15 ft of screen - well development water will be
treated with granulated activated carbon and discharged on site <-------- - work will start within
30 days of approval and report will be submitted within 45 days following receipt of lab results
the submitted work plan is not acceptable for following reasons: - proposes to collect soil samples
at highest PID or above water table {the department requires collection of soil samples from
highest PID, deepest dry and/or deepest clean zone (if soil contamination extends below water
table)} - proposes to discharge well development water on-site after treating with activated carbon
(the department requires proper dishcarge - either off-site at regulated facility as contaminated
water or into city sewer system with proper permit from city department) 11:35 AM:- left message
for Mr. Fisher. 1:05 PM:- sent email to Mr. Fisher requiring to submit revised work plan with
following changes: - Soil samples from borings must be collected at the highest PID and the deepest
dry zone. If soil contamination extends below the water table, then soil samples must be collected
at the deepest clean zone also. - Well development water must be discharged properly - either at
off-site regulated facility as contaminated water or into city sewer system with proper
permit/approval from city agency. email copied to Mr. Shea and Mr. Hanley. 06/02/10-Hiralkumar
Patel. 4:29 PM:- received email from Mr. Fisher with revised work plan. this revised work plan is
not acceptable as proposes to discharge well development water onto grassy area. work plan doesn't
include anything about water sampling prior to discharge onto grassy area. 06/03/10-Hiralkumar
Patel. 1:35 PM:- sent email to Ms. Fisher informing that the revised work plan is not acceptable
due to disposal of well development water onto grassy area without confirming its cleanliness via
sampling. asked him to submit re-revised work plan. email copied to Mr. Shea and Mr. Hanley. 4:25
PM:- received email from Mr. Fisher with re-revised work plan prepared

3602 21ST STREET (Continued) **S109371707**

by Kleinfelder.
06/04/10-Hiralkumar Patel. 1:08 PM:- spoke with Richard Swedborg (631-218-0612) at Kleinfelder
regarding their involvement with the project. Kleinfelder has been hired by Delta as
sub-contractor. 1:33 PM:- sent work plan approval letter to Mr. Shea. letter emailed to Mr. Shea,
Mr. Hanley and Mr. Fisher. 08/31/10-Hiralkumar Patel. received email from Kleinfelder (at 7:50 PM
on 08/30/10) including investigation report. abstract: - installed five borings (SB-A, SB-B, MW-A,
MB-B and MW-C) to 17 ft bg except boring SB-B where refusal found at 7 ft bg - borings were hand
cleared to 6 ft depth - samples were collected from 6 to 17 ft bg at five ft depth intervals - two
soil samples were collected from each boring except SB-B due to refusal at 7 ft bg - soil
encountered during investigation consisted predominately of fine to coarse grained sand soil with
varying amounts of gravel and debris - bedrock was not encountered during borings - installed three
2 inch wells at three boring locations, with 15 ft of screen - groundwater was encountered between
11.17 through 11.33 ft bg - groundwater was interpreted to flow southerly at the site - no VOC
contamination found in soil samples - found SVOC contamination in soil samples with heavy
contamination at 6-11 ft in MW-C - no VOC or SVOC contamination found in groundwater samples - will
collect additional round of groundwater samples in Oct. 2010 Yanira DePuy Kleinfelder PH. (845)
567-6530 Ext. 133 (845) 721-8784 (C) Fax (845) 567-6542 email: YDePuy@kleinfelder.com
11/22/10-Hiralkumar Patel. 12:39 PM:- received quarterly groundwater sampling report from
Kleinfelder. groundwater samples were collected from three wells MW-A, MW-B and MW-C. no free
product found in any well. no contamination found in any groundwater sample. 11/30/10-Hiralkumar
Patel. discussed with DEC Austin. due to heavy soil contamination found in boring B-2 and B-3,
Austin required a monitoring well downgradient from these two borings and collection of groundwater
sample. reviewed former investigation reports. borings B-2 and B-3 were installed near the
dispenser island. during groundwater investigation, groundwater flow was towards the south. based
on groundwater flow direction, boring SB-A was installed downgradient from former borings B-2 and
B-3. found 109 ppm on PID at 6-11 ft depth, but no VOC or SVOC contamination found in soil sample
at 6-11 ft in SB-A. discussed again with DEC Austin and case closed based on following: - no PID
readings from 0-10 ft in boring B-2 and B-3 - no contamination in groundwater samples from boring
B-2 and B-3 - no contamination in soil sample at water interface in boring SB-A which was installed

3602 21ST STREET (Continued) **S109371707**

downgradient from boring B-2 and B-3 4:13 PM:- sent spill closure letter to Mr. Shea. letter
emailed to Mr. Shea and Mr. Hanley. 02/14/11-Hiralkumar Patel. 5:03 PM:- received well closure
report from Kleinfelder."

Remarks: "CALLER STATES THAT THEY WERE REPAIRING A WATER MAIN AND ENCOUNTERED SOME OILY SOIL. THERE IS A NOW A SHEEN IN THE PUDDLE. CLEAN UP IS PENDING."

All Materials:

Site ID:	404330
Operable Unit ID:	1160995
Operable Unit:	01
Material ID:	2152183
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

K121 **GLOBAL MONTELLO GROUP CORP. #5432** **NY UST** **U004062913**
NNE **36-02 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.101 mi.
534 ft. **Site 13 of 18 in cluster K**

Relative: **Higher**

Actual: **17 ft.**

UST:

Name:	GLOBAL MONTELLO GROUP CORP. #5432
Address:	36-02 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-146048 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	04/08/2024
UTM X:	589732.08506
UTM Y:	4512643.68591
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	4215
Affiliation Type:	Mail Contact
Company Name:	ATLAS
Contact Type:	Not reported
Contact Name:	MEGAN KAZMIERCZAK
Address1:	685 GRANDVIEW AVENUE
Address2:	Not reported
City:	COLUMBUS
State:	OH
Zip Code:	43215
Country Code:	001
Phone:	(614) 433-0170
EMail:	GLOBALPARTNERS@ONEATLAS.COM
Fax Number:	Not reported

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Modified By: KXLIU
Date Last Modified: 2022-12-28

Site Id: 4215
Affiliation Type: Facility Operator
Company Name: GLOBAL MONTELLO GROUP CORP. #5432
Contact Type: Not reported
Contact Name: DAVID WENT
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 392-0250
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-11-16

Site Id: 4215
Affiliation Type: Facility Owner
Company Name: LEEMILTS PETROLEUM, INC.
Contact Type: AUTHORIZED REPRESENTATIVE
Contact Name: MEGAN KAZMIERCZAK
Address1: 292 MADISON AVENUE, 9TH FLOOR
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10017-6318
Country Code: 001
Phone: (646) 349-6000
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-12-24

Site Id: 4215
Affiliation Type: Emergency Contact
Company Name: LEEMILTS.
Contact Type: Not reported
Contact Name: CALL CENTER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (888) 674-7601
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2013-05-09

Tank Info:

Tank Number: 001

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Tank ID:	28226
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	28227
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number:	003
Tank ID:	28228
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	28229
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number:	005
Tank ID:	28230
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	006
Tank ID:	28231
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	07/01/1961
Date Tank Closed:	10/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	14
Date Test:	08/01/1994

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number: 007
Tank ID: 28232
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 008
Tank ID: 28233
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 009
Tank ID: 28234
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number: 010
Tank ID: 28235
Tank Status: Closed - Removed

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 011
Tank ID: 28236
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

C00 - Pipe Location - No Piping

Tank Number: 012
Tank ID: 28237
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1994
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
H00 - Tank Leak Detection - None
G03 - Tank Secondary Containment - Vault (w/o access)
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number: 013
Tank ID: 28238
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 07/01/1961
Date Tank Closed: 10/01/1998
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 14
Date Test: 08/01/1993
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

I00 - Overfill - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Tank Number:	015A
Tank ID:	54318
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	01/19/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number:	015B
Tank ID:	54319
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	0
Install Date:	01/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	2712
Common Name of Substance:	Gasoline/Ethanol

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Tightness Test Method: 20
Date Test: 07/26/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

Tank Number: 016
Tank ID: 54320
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/1999
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Material Code: 2712
Common Name of Substance: Gasoline/Ethanol

Tightness Test Method: 34
Date Test: 07/26/1999
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
C02 - Pipe Location - Underground/On-ground
F04 - Pipe External Protection - Fiberglass
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

GLOBAL MONTELLO GROUP CORP. #5432 (Continued) **U004062913**

Tank Number:	017
Tank ID:	54321
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	01/01/1999
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Equivalent technology
Material Code:	0008
Common Name of Substance:	Diesel
Tightness Test Method:	34
Date Test:	07/26/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F04 - Pipe External Protection - Fiberglass
C02 - Pipe Location - Underground/On-ground
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
K01 - Spill Prevention - Catch Basin
I02 - Overfill - High Level Alarm
B04 - Tank External Protection - Fiberglass
D06 - Pipe Type - Fiberglass Reinforced Plastic (FRP)
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
E04 - Piping Secondary Containment - Double walled UG
G04 - Tank Secondary Containment - Double-Walled (Underground)

K122 **T J MOTORS INC** **EDR Hist Auto** **1020496684**
NNE **36-02 21ST ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.101 mi.
534 ft. **Site 14 of 18 in cluster K**

Relative: EDR Hist Auto
Higher

Actual:
17 ft.

Year:	Name:	Type:
1969	RAVENSWOOD SUNOCO STATION	Gasoline Service Stations
1970	RAVENSWOOD SUNOCO STATION	Gasoline Service Stations
1976	RAVENSWOOD SUNOCO SERVICE STN	Gasoline Service Stations
1977	RAVENSWOOD SUNOCO STAT	Gasoline Service Stations
1978	RAVENSWOOD SUNOCO STAT	Gasoline Service Stations
1983	T J MOTORS INC	Gasoline Service Stations
1985	T J MOTORS INC	Gasoline Service Stations
1986	T J MOTORS INC	Gasoline Service Stations
1987	T J MOTORS INC	Gasoline Service Stations
1988	T J MOTORS INC	Gasoline Service Stations
1989	T J MOTORS INC	Gasoline Service Stations
1990	T J MOTORS INC	Gasoline Service Stations
1991	T J MOTORS INC	Gasoline Service Stations

T J MOTORS INC (Continued) **1020496684**

1992	T J MOTORS INC	Gasoline Service Stations
1993	T J MOTORS INC	Gasoline Service Stations
1994	T J MOTORS INC	Gasoline Service Stations
1995	T J MOTORS INC	Gasoline Service Stations
1997	D ALL AUTO REPAIR	General Automotive Repair Shops
1998	D ALL AUTO REPAIR	General Automotive Repair Shops
1999	D ALL AUTO REPAIR	General Automotive Repair Shops
2000	D ALL AUTO REPAIR	General Automotive Repair Shops
2001	D ALL AUTO REPAIR	General Automotive Repair Shops
2001	T J MOTORS INC	Gasoline Service Stations
2002	TJ AUTO REPAIRS & SERVICE INC	Gasoline Service Stations
2002	D ALL AUTO REPAIR	General Automotive Repair Shops
2003	TJ AUTO REPAIRS & SERVICE INC	Gasoline Service Stations
2004	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2005	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2006	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2007	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2008	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2009	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2010	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2011	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2012	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2013	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations
2014	T R AUTO REPAIR & TOWING INC	Gasoline Service Stations
2014	D M S AUTO REPAIRS & SERVICE	Gasoline Service Stations

E123 **CON EDISON** **NY MANIFEST** **S117318768**
SSE **23-02 38 AV** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.103 mi.
542 ft. **Site 6 of 7 in cluster E**

Relative: **Higher**
Actual: **19 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	23-02 38 AV
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004663431
Facility Status:	Not reported
Location Address 1:	23-02 38 AV
Code:	BP
Location Address 2:	SB52506
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663431
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S117318768**

Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: NJD003812047
Generator Ship Date: 09/22/2014
Trans1 Recv Date: 09/22/2014
Trans2 Recv Date: 09/24/2014
TSD Site Recv Date: 09/24/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004663431
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002617520GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1
Waste Code: D008
Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

E124 **ONE STOP SERVICE** **RCRA NonGen / NLR** **1000551840**
SSE **23-02 38TH AVE** **FINDS** **NYD986942076**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.103 mi.
542 ft. **Site 7 of 7 in cluster E**

Relative: **Higher**
Actual: **19 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	One Stop Service
Handler Address:	23-02 38TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-3511
EPA ID:	NYD986942076
Contact Name:	Not reported
Contact Address:	NORTHERN BLVD
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	NORTHERN BLVD
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	One Stop Service
Owner Type:	Private
Operator Name:	One Stop Service
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

ONE STOP SERVICE (Continued) **1000551840**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: ONE STOP SERVICE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ONE STOP SERVICE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ONE STOP SERVICE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

ONE STOP SERVICE (Continued) **1000551840**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: ONE STOP SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ONE STOP SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ONE STOP SERVICE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910222
Handler Name: ONE STOP SERVICE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

ONE STOP SERVICE (Continued) **1000551840**

NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004461172

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000551840
Registry ID:	110004461172
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004461172
Name:	ONE STOP SERVICE
Address:	23-02 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

F125 **PS# 111 DISTRICT 30** **NY Spills** **S106469674**
WSW **38-15 13TH STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.103 mi.
545 ft. **Site 9 of 9 in cluster F**

Relative: **Lower**
Actual: **16 ft.**

SPILLS:

Name:	PS# 111 DISTRICT 30
Address:	38-15 13TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0402366 / 2004-06-03
Facility ID:	0402366
Facility Type:	ER
DER Facility ID:	201142
Site ID:	244867
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	4101
Spill Date:	2004-06-03
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2004-06-03
CID:	444

PS# 111 DISTRICT 30 (Continued) **S106469674**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-03
Spill Record Last Update:	2009-03-04
Spiller Name:	ROGER ROMANCE
Spiller Company:	PS# 111 DISTRICT 30
Spiller Address:	38-15 13 TH STREET
Spiller Company:	001
Contact Name:	ROGER ROMANCE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND Sangesland spoke with Roger Romance of Metro Fuel. He said the spill was minor and was all cleaned up. Sangesland then spoke with Denis Belokostolsky of Division of School Facilities. He was on site and he also said the spill was minor and can be closed out. "
Remarks:	"FILLED WRONG TANK, CUSTODIAN HOOKED UP TO WRONG TANK, DRIVER TURNED OFF IMMEDIATELY"

All Materials:

Site ID:	244867
Operable Unit ID:	884045
Operable Unit:	01
Material ID:	489989
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

L126 **NEW HIGH TECH AUTO REPAIR & BODY SHOP INC.** **NY AST** **A100295239**
SW **38-25 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.103 mi.
546 ft. **Site 2 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	NEW HIGH TECH AUTO REPAIR & BODY SHOP INC.
Address:	38-25 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609972
Program Type:	PBS
UTM X:	589536.15449

NEW HIGH TECH AUTO REPAIR & BODY SHOP INC. (Continued) **A100295239**

UTM Y: 4512345.81043
Expiration Date: 06/28/2010
Site Type: Other

Affiliation Records:
Site Id: 348397
Affiliation Type: Facility Owner
Company Name: NEW HI TECH AUTO REPAIR & BODY SHOP INC.
Contact Type: PRESIDENT
Contact Name: MOHAMMAD NAWAZ
Address1: 38-25 21ST STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-5648
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-06-28

Site Id: 348397
Affiliation Type: Mail Contact
Company Name: NEW HI TECH AUTO REPAIR & BODY SHOP INC.
Contact Type: PRESIDENT
Contact Name: MOHAMMAD NAWAZ
Address1: 38-25 21ST STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-5648
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-06-28

Site Id: 348397
Affiliation Type: Facility Operator
Company Name: NEW HIGH TECH AUTO REPAIR & BODY SHOP INC.
Contact Type: Not reported
Contact Name: MOHAMMAD NAWAZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 361-5648
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2005-06-28

Site Id: 348397
Affiliation Type: Emergency Contact

NEW HIGH TECH AUTO REPAIR & BODY SHOP INC. (Continued) **A100295239**

Company Name:	NEW HI TECH AUTO REPAIR & BODY SHOP INC.
Contact Type:	Not reported
Contact Name:	MOHAMMAD NAWAZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-5648
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2005-06-28

Tank Info:

Tank Number:	001
Tank Id:	207022
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	G01 - Tank Secondary Containment - Diking (Aboveground)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

L127 **LUPOLI SERVICE STATION** **NY UST** **U001840962**
SW **38-25 21ST STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.103 mi.
546 ft. **Site 3 of 19 in cluster L**

Relative: UST:
Higher

Actual: Name:	LUPOLI SERVICE STATION
18 ft. Address:	38-25 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-479969 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589531.55465
UTM Y:	4512343.70449

LUPOLI SERVICE STATION (Continued) **U001840962**

Site Type: Retail Gasoline Sales

Affiliation Records:

Site Id: 21397
Affiliation Type: Emergency Contact
Company Name: LUPOLI, MATTHEW
Contact Type: Not reported
Contact Name: MATTHEW JUPOLI, JR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 539-0622
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21397
Affiliation Type: Facility Operator
Company Name: LUPOLI SERVICE STATION
Contact Type: Not reported
Contact Name: RAY LUPOLI
Address1: Not reported
Address2: Not reported
City: Not reported
State: NY
Zip Code: Not reported
Country Code: 001
Phone: (718) 784-9233
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-06-08

Site Id: 21397
Affiliation Type: Mail Contact
Company Name: LUPOLI, MATTHEW
Contact Type: Not reported
Contact Name: Not reported
Address1: 144-10 45 AV
Address2: Not reported
City: FLUSHING
State: NY
Zip Code: 11355
Country Code: 001
Phone: (718) 539-0551
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-06-08

Site Id: 21397
Affiliation Type: Facility Owner
Company Name: LUPOLI, MATTHEW
Contact Type: Not reported

LUPOLI SERVICE STATION (Continued) **U001840962**

Contact Name:	Not reported
Address1:	144-10 45 AV
Address2:	Not reported
City:	FLUSHING
State:	NY
Zip Code:	11355
Country Code:	001
Phone:	(718) 539-0551
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2009-06-08

Tank Info:

Tank Number:	001
Tank ID:	38787
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1978
Date Tank Closed:	10/30/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	01
Date Test:	08/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number:	002
Tank ID:	38788
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1978
Date Tank Closed:	10/30/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999

LUPOLI SERVICE STATION (Continued) **U001840962**

Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping

Tank Number: 003
Tank ID: 38789
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Number: 004
Tank ID: 38790
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991

LUPOLI SERVICE STATION (Continued) **U001840962**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number: 005
Tank ID: 38791
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping

Tank Number: 006
Tank ID: 38792
Tank Status: Closed - Removed

LUPOLI SERVICE STATION (Continued) **U001840962**

Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number: 007
Tank ID: 38793
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

LUPOLI SERVICE STATION (Continued) **U001840962**

Tank Number:	008
Tank ID:	38794
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1978
Date Tank Closed:	10/30/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	01
Date Test:	08/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
D00 - Pipe Type - No Piping

Tank Number:	009
Tank ID:	38795
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1978
Date Tank Closed:	10/30/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	01
Date Test:	08/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
A00 - Tank Internal Protection - None

LUPOLI SERVICE STATION (Continued) **U001840962**

G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

Tank Number: 010
Tank ID: 38796
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
D00 - Pipe Type - No Piping

Tank Number: 011
Tank ID: 38797
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 09/01/1978
Date Tank Closed: 10/30/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: 01
Date Test: 08/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None

LUPOLI SERVICE STATION (Continued) **U001840962**

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping

Tank Number:	012
Tank ID:	38798
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	09/01/1978
Date Tank Closed:	10/30/1991
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other
Tightness Test Method:	01
Date Test:	08/01/1988
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
D00 - Pipe Type - No Piping

L128 **CIOFFI & FERRARA** **EDR Hist Auto** **1020580108**
SW **38-25 21ST ST** **N/A**
< 1/8 **LONG IS CY, NY 11101**
0.103 mi.
546 ft. **Site 4 of 19 in cluster L**

Relative: EDR Hist Auto
Higher

Actual:
18 ft.

Year:	Name:	Type:
1969	CIOFFI & FERRARA	Gasoline Service Stations
1970	CIOFFI & FERRARA	Gasoline Service Stations
1971	CIOFFI & FERRARA	Gasoline Service Stations
1972	CIOFFI & FERRARA	Gasoline Service Stations
1973	CIOFFI & FERRARA	Gasoline Service Stations
1974	CIOFFI & FERRARA	Gasoline Service Stations
1975	CIOFFI & FERRARA SERVICE STN	Gasoline Service Stations
1976	CIOFFI & FERRARA SERVICE STN	Gasoline Service Stations
1977	CIOFFI & FERRARA SERVICE STN	Gasoline Service Stations
1978	CIOFFI & FERRARA	Gasoline Service Stations
1979	CIOFFI & FERRARA	Gasoline Service Stations

CIOFFI & FERRARA (Continued) **1020580108**

1980	CIOFFI & FERRARA	Gasoline Service Stations
1982	CIOFFI & FERRARA	Gasoline Service Stations
1983	CIOFFI & FERRARA	Gasoline Service Stations
1991	BUNJAB AUTO REPAIR	Automotive Repair Shops, NEC
1992	BUNJAB AUTO REPAIR	Automotive Repair Shops, NEC
1993	BUNJAB AUTO REPAIR	Automotive Repair Shops, NEC
1994	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
1995	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
1996	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
1997	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
1998	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
1999	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2000	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2001	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2002	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2003	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2004	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2005	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2006	HI-TECH AUTO REPAIR & BODY	General Automotive Repair Shops
2007	ALL IN ONE AUTO REPAIR	General Automotive Repair Shops
2008	ALL IN ONE AUTO REPAIR	General Automotive Repair Shops
2010	COMPLETE AUTO SERVICE	Automotive Repair Shops, NEC
2011	COMPLETE AUTO SERVICE	Automotive Repair Shops, NEC
2011	HIGH TEK AUTO REPAI	General Automotive Repair Shops
2012	HIGH TEK AUTO REPAI	General Automotive Repair Shops
2013	HIGH TEK AUTO REPAIR	General Automotive Repair Shops
2014	HIGH TEK AUTO REPAIR	General Automotive Repair Shops

M129 **MARVIC TRANSMISSION INC.** **NY AST** **A100166666**
SSE **23-12 38TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.105 mi.
554 ft. **Site 1 of 6 in cluster M**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	MARVIC TRANSMISSION INC.
Address:	23-12 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-604521
Program Type:	PBS
UTM X:	589706.72911
UTM Y:	4512271.30776
Expiration Date:	05/16/2010
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	26393
Affiliation Type:	Mail Contact
Company Name:	MARVIC TRANSMISSION INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	23-12 38TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY

MARVIC TRANSMISSION INC. (Continued) **A100166666**

Zip Code:	11101
Country Code:	001
Phone:	(718) 361-7428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-04-14

Site Id:	26393
Affiliation Type:	Facility Operator
Company Name:	MARVIC TRANSMISSION INC.
Contact Type:	Not reported
Contact Name:	D. GOMEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 361-7428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-04-14

Site Id:	26393
Affiliation Type:	Emergency Contact
Company Name:	MARVIC TRANSMISSION INC.
Contact Type:	Not reported
Contact Name:	D. GOMEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 361-7428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE
Date Last Modified:	2005-04-14

Site Id:	26393
Affiliation Type:	Facility Owner
Company Name:	MARVIC TRANSMISSION INC.
Contact Type:	MANAGER
Contact Name:	DANIEL GOMEZ
Address1:	23-12 38TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-7428
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MABARTLE

MARVIC TRANSMISSION INC. (Continued) **A100166666**

Date Last Modified: 2005-04-14

Tank Info:

Tank Number: 001
Tank Id: 58057
Material Code: 0013
Common Name of Substance: Lube Oil

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy
Tank Status: In Service
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 270
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: lube oil

Tank Number: 002
Tank Id: 58058
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A99 - Tank Internal Protection - Other
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Stainless Steel Alloy

MARVIC TRANSMISSION INC. (Continued) **A100166666**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

M130 **MARVIC TRANSMISSION** **EDR Hist Auto** **1020439465**
SSE **2312 38TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.105 mi.
554 ft. **Site 2 of 6 in cluster M**

Relative: EDR Hist Auto
Higher

Actual:
19 ft.

Year:	Name:	Type:
1991	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1992	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1993	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1994	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1995	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1996	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1997	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1998	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
1999	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2000	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2001	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2002	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2003	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2004	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2005	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2006	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2007	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2008	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2009	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2010	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2011	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2012	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2013	MARVIC TRANSMISSION	Automotive Transmission Repair Shops
2014	MARVIC TRANSMISSION	Automotive Transmission Repair Shops

M131 **MAR-VIC TRANSMISSION** **RCRA NonGen / NLR** **1000267316**
SSE **23-12 38TH AVENUE** **FINDS** **NYD982794265**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.105 mi.
554 ft. **Site 3 of 6 in cluster M**

Relative:
Higher

Actual:
19 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Mar-Vic Transmission
Handler Address:	23-12 38TH AVENUE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD982794265
Contact Name:	Not reported
Contact Address:	38TH AVE
Contact City,State,Zip:	QUEENS, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	38TH AVE
Mailing City,State,Zip:	QUEENS, NY 11101
Owner Name:	A. Matiz
Owner Type:	Private
Operator Name:	A. Matiz
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

MAR-VIC TRANSMISSION (Continued) **1000267316**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: A. MATIZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: A. MATIZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: A. MATIZ	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

MAR-VIC TRANSMISSION (Continued) **1000267316**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990708
Handler Name: MAR-VIC TRANSMISSION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MAR-VIC TRANSMISSION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MAR-VIC TRANSMISSION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890817
Handler Name: MAR-VIC TRANSMISSION
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

MAR-VIC TRANSMISSION (Continued) **1000267316**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004434577

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000267316
Registry ID:	110004434577
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004434577
Name:	MAR-VIC TRANSMISSION
Address:	23-12 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101

N132 **38-21 12TH ST/QUEENS/ CHE** **NY LTANKS** **S100144861**
West **38-21 12TH ST.** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.105 mi.
557 ft. **Site 1 of 3 in cluster N**

Relative: LTANKS:
Lower

Name:	38-21 12TH ST/QUEENS/ CHE
Address:	38-21 12TH ST.
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8706722 / 1994-02-07
Facility ID:	8706722
Site ID:	321182
Spill Date:	1987-11-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1994-02-07
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1987-11-07
CID:	Not reported

Actual:
15 ft.

38-21 12TH ST/QUEENS/ CHE (Continued) **S100144861**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-16
Spill Record Last Update:	1994-02-07
Spiller Name:	Not reported
Spiller Company:	PATTON SCAFFOLDING
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	258752
DEC Memo:	""
Remarks:	"1500 GALLON TANK COULDN'T MAINTAIN LEVEL IN THE STANDPIPE, WILL EXPOSE."

All TTF:

Facility ID:	8706722
Spill Number:	8706722
Spill Tank Test:	1532198
Site ID:	321182
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	321182
Operable Unit ID:	912596
Operable Unit:	01
Material ID:	465723
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

J133 **OIL IN WELL** **NY Spills** **S108982479**
ESE **37-10 24TH STREET** **N/A**
< 1/8 **LONG ISLAND, NY**
0.107 mi.
565 ft. **Site 5 of 15 in cluster J**

Relative:
Higher

Actual:
19 ft.

SPILLS:

Name:	OIL IN WELL
Address:	37-10 24TH STREET
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0711317 / 2010-06-23
Facility ID:	0711317
Facility Type:	ER
DER Facility ID:	342366
Site ID:	392775
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2008-01-28
Investigator:	sxahmed
Referred To:	Not reported
Reported to Dept:	2008-01-28
CID:	444
Water Affected:	NONE
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-28
Spill Record Last Update:	2010-06-23
Spiller Name:	CLAIRE HUNT
Spiller Company:	ON STREET
Spiller Address:	37-10 24TH STREET
Spiller Company:	001
Contact Name:	CLAIRE HUNT
DEC Memo:	"4/26/2010: Current status: During Site Characterization at the Jung Sun Laundry Plume (241102) site, oil like substance was found in one of the existing monitoring well (MW-3). During phase I and 2, two times gw samples collected from this well and no VOCs were detected. Spill will be closed soon. S.Ahmed 06/23/2010: Groundwater samples were collected from MW-3 on 2/21/2008 and 2/8/2009. Based on the laboratory data, no voc's were detected in the samples from this well. The spill is closed. S. Ahmed"
Remarks:	"SADIQUE AHNED - DEC REP WAS ON SITE- FOUND PETRO IN WELL"

All Materials:

Site ID:	392775
Operable Unit ID:	1149763
Operable Unit:	01
Material ID:	2140315
Material Code:	0066A
Material Name:	unknown petroleum

OIL IN WELL (Continued) **S108982479**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

J134 **37-10 24TH STREET** **NY Spills** **S102150393**
ESE **37-10 24TH STREET** **N/A**
< 1/8 **QUEENS, NY**
0.107 mi.
565 ft. **Site 6 of 15 in cluster J**

Relative: **Higher**
Actual: **19 ft.**

SPILLS:

Name:	37-10 24TH STREET
Address:	37-10 24TH STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9503873 / 1995-06-29
Facility ID:	9503873
Facility Type:	ER
DER Facility ID:	214248
Site ID:	262434
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	1995-06-29
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1995-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-06-29
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-08-01
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	METRO OIL OIL CO
Spiller Address:	500 KINGSLAND AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"AREA CLEANED BY SPILLER - FD ON SCENE - NO NEED FOR DEC TO RESPOND"

All Materials:

Site ID:	262434
Operable Unit ID:	1015109
Operable Unit:	01
Material ID:	365382

37-10 24TH STREET (Continued) **S102150393**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

O135 **JACKSON DEVELOPMENTAL CENTER** **NY UST** **U004248215**
North **3602 14TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.107 mi.
567 ft. **Site 1 of 3 in cluster O**

Relative:
Higher

Actual:
17 ft.

UST:

Name:	JACKSON DEVELOPMENTAL CENTER
Address:	3602 14TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Id/Status:	2-612540 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	School

Affiliation Records:

Site Id:	524652
Affiliation Type:	Facility Owner
Company Name:	JACKSON SERVICES, LLC
Contact Type:	MEMBER
Contact Name:	JOSEPH M. GELMAN
Address1:	3136 88TH ST
Address2:	Not reported
City:	JACKSON HEIGHTS
State:	NY
Zip Code:	11369
Country Code:	001
Phone:	(718) 205-1919
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-03-14

Site Id:	524652
Affiliation Type:	Mail Contact
Company Name:	JACKSON SERVICES, LLC
Contact Type:	Not reported
Contact Name:	ARI KOHN
Address1:	3136 88TH ST
Address2:	Not reported
City:	JACKSON HEIGHTS
State:	NY
Zip Code:	11369

JACKSON DEVELOPMENTAL CENTER (Continued) **U004248215**

Country Code:	001
Phone:	(718) 205-1919
EMail:	JACKDEVCTR@AOL.COM
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-03-14

Site Id:	524652
Affiliation Type:	Facility Operator
Company Name:	JACKSON DEVELOPMENTAL CENTER
Contact Type:	Not reported
Contact Name:	N/A
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-2510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-03-14

Site Id:	524652
Affiliation Type:	Emergency Contact
Company Name:	JACKSON SERVICES, LLC
Contact Type:	Not reported
Contact Name:	ARI KOHN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 309-3897
EMail:	Not reported
Fax Number:	Not reported
Modified By:	CGFREEDM
Date Last Modified:	2016-03-14

Tank Info:

Tank Number:	001
Tank ID:	260949
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	01/01/1960
Date Tank Closed:	09/08/2010
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported

JACKSON DEVELOPMENTAL CENTER (Continued) **U004248215**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J05 - Dispenser - On Site Heating System (Supply/Return)
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None

H136 **AUDAX CONSTRUCTION CORP** **NY UST** **1000547801**
NW **12-04 37TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
574 ft. **Site 7 of 8 in cluster H**

Relative:
Lower

Actual:
15 ft.

UST:
Name: AUDAX CONSTRUCTION CORP
Address: 12-04 37TH AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-090492 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589478.14233
UTM Y: 4512585.97929
Site Type: Other

Affiliation Records:
Site Id: 2209
Affiliation Type: Facility Owner
Company Name: AUDAX CONSTRUCTION CORP
Contact Type: Not reported
Contact Name: Not reported
Address1: 12-04 37TH AVENUE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-3056
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 2209
Affiliation Type: Mail Contact
Company Name: AUDAX CONSTRUCTION CORP
Contact Type: Not reported
Contact Name: Not reported

AUDAX CONSTRUCTION CORP (Continued) **1000547801**

Address1:	12-04 37TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2209
Affiliation Type:	Facility Operator
Company Name:	AUDAX CONSTRUCTION CORP
Contact Type:	Not reported
Contact Name:	AUDAX CONSTRUCTION CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	2209
Affiliation Type:	Emergency Contact
Company Name:	AUDAX CONSTRUCTION CORP
Contact Type:	Not reported
Contact Name:	AUDAX CONSTRUCTION CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-3056
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	3500
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	3000
Install Date:	11/01/1980
Date Tank Closed:	03/01/1995
Registered:	True
Tank Location:	Underground

AUDAX CONSTRUCTION CORP (Continued) **1000547801**

Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I00 - Overfill - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

H137 **COMMERCIAL BUILDING** **NY LTANKS** **S107523279**
NW **1204 37TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.109 mi.
574 ft. **Site 8 of 8 in cluster H**

Relative: LTANKS:
Lower

Actual: Name:	COMMERCIAL BUILDING
15 ft. Address:	1204 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0511360 / 2006-06-28
Facility ID:	0511360
Site ID:	357496
Spill Date:	2005-12-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	HRPATEL
Referred To:	Not reported
Reported to Dept:	2005-12-30
CID:	408
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-12-30
Spill Record Last Update:	2006-06-28
Spiller Name:	LEVENT ESKICAKIC
Spiller Company:	Not reported
Spiller Address:	1204 37TH AVE
Spiller County:	001

COMMERCIAL BUILDING (Continued) **S107523279**

Spiller Contact: LEVENT ESKICAKIC
Spiller Phone: (718) 784-7490
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 307531
DEC Memo: "12/30/05-Hiralkumar Patel. I spoke with Levent Eskicakit at Athenica Enviromental, who is handling environmental investigation of this site. Levent is doing Phase-I and Phase-II investigation of site. During phase II, he found contamination. this is an empty building, previously used as office and in back of building there are 3 tanks of 275 gal capacity above ground, and 1 underground tank capacity of 3000 gal. this building is financed by State Bank of Long Island and owned by Metro B.C. LLC. Levent took samples at points 8 to 9 ft apart and about 15 ft deep. From the samples of whole area, they found contamination in backyard where the tanks are. Levent found contamination in the area of 10ft*10ft*9ft. After investigation, the building will be demolished for further use. At financing bank, the further use of this site is noted as commercial use. Levent: Ph. (718) 784-7490 Fax. (718) 784-4085 Email: leskicakit@athenica.com Contact Person in Metro LLC: Demetrios Demetrios (718) 937-5353 Fax. (718) 937-8743 Cell (347) 203-9923 Address of Metro LLC: 11-20 30th Ave. Long Island City, NY I have sent soil contamination letter today and also faxed it. 1/17/06-Hiralkumar Patel. I got letter back because of wrong address. Letter with corrected address has been sent out. Correct Address: 1120 37th Ave Long Island City, NY 11101 1/20/06-Hiralkumar Patel. Spoke with Levent at Athenica Environmental and as per his knowledge, the Metro LLC is now selling this property. and the new owner will do all the required remediation work. Until now Levent has not heared anything from Metro LLC or the new buyer. as soon as he get some information, he will inform me. I have asked him to send soil investigation report in email. 1/24/06-Hiralkumar Patel. Talked with Levent at Athenica. He will send me report today in email. Received site plan, soil results and groundwater results in an emil from Levent. Reviewing report. { c:\\hiralkumar\\1204 37th ave } - 6 soil samples, 1 groundwater sample close to UST. - found contamination at soil sample no. 1 and 3, which are close to UST and contamination in groundwater close to tank. - from the plan, property has 5 AST of capacity 275 gal. Left message for Mr. Demetrios at Metro LLC. Received call from Demetrios, and he will call me back with latest information regarding cleanup on this case once he reach his office. Received email from Levent at Athenica.

---------- Hiralkumar: As I mentioned to you earlier, at the request of Metro LLC, Athenica Environmental Services (AES) conducted a Phase II Focused Subsurface Site Investigation on December 2005 at the above referenced property. The results of this investigation revealed followings: * Field investigation indicated that Site soils (B-1 & B-3) located along the former abandoned 3,000-gallon UST area (or former cesspool area), contained field evidence of petroleum contamination. The field evidence suggests that petroleum contamination soils occur at depths of approximately four (4) feet bgs to the water table, which was encountered between ten (10) and twelve (12) feet bgs. * There was no evidence of any VOC or SVOC contamination observed within the remaining soil samples (B-2, B-4, B-5 and B-6) collected from the Site. * The laboratory analytical results indicated that, with the exception of soil samples B-1 and B-2 collected within the vicinity of the former abandoned

COMMERCIAL BUILDING (Continued) **S107523279**

UST, none of the remaining soil samples (B-2, B-4, B-5 and B-6) from the Site had concentrations above the NYSDEC STARS Memo Alternative Soil Guidance Values. Soil Samples collected from B-1 and B-2 contained concentration of VOCs and SVOCs above the NYSDEC STARS Memo Alternative Soil Guidance Values. * Laboratory results of groundwater sample GW-1 collected from the soil boring B-1 indicated that concentration of benzene and MTBE were 1.7 ppb and 24 ppb, respectively. These concentrations exceed the NYSDEC TOGS Memo Groundwater Cleanup Criteria of 1 ppb for benzene and 10 ppb for MTBE. Based upon the field evidence and the laboratory data, AES concluded that the Site has been impacted by old petroleum-related VOCs and SVOCs in the former abandoned UST (or cesspool) area. However, based on the fact that this is a historical spill and is located approximately 4 feet below ground surface (bgs) and the fact that the entire area is covered with 6 inches of concrete floor, there are no immediate thread to the environment and the occupants of the Site. Further, the Site is not a residential and the entire area is used solely for parking and storage. My conversation with Mr. Demetrios of Metro LLC (the Site owner) indicated that the Site will go under construction for the development of a new building approximately sometimes in 2007. AES recommended that when the proposed construction activities should take a place, environmental engineering controls including remedial action work plans, and health & safety plan should be prepared in order to protect the workers and environment and submitted to the NYSDEC for review and approval. Regards, Levent LEVENT ESKICAKIT, P.G., E.P. Phone: 718-784-7490 Fax: 718-784-4085 Email: <mailto:leskicakit@athenica.com> leskicakit@athenica.com ATHENICA ENVIRONMENTAL SERVICES INC. Environmental Engineering Consultants 45-09 Greenpoint Avenue Long Island City, New York 11103

---------- 01/25/06-Hiralkumar Patel. Received email from Levent. This UST was abandoned in place sometimes 20 years ago. It's supposed to be filled with sand. As i discussed with Vought, if this tank is empty, we can wait till they start construction in 2007. 05/03/06-Hiralkumar Patel. Received email from Levent.

---------- Kumar:

How are you doing? Finally, I have a signed proposal to conduct required remediation activities for this Site. Right now, I am putting the contractors together to excavate the impacted areas at the site. Please do not hesitate to contact me with any questions. Levent LEVENT ESKICAKIT, P.G., E.P. Phone: 718-784-7490 Fax: 718-784-4085 Email: leskicakit@athenica.com ATHENICA ENVIRONMENTAL SERVICES INC. Environmental Engineering Consultants 45-09 Greenpoint Avenue Long Island City, New York 11103

---------- Tried

Levent's number, but it is out of service. replied email and asked to send work plan including contractor's information. Received eamil from Levent and he will send RAP shortly. 05/04/06-Hiralkumar Patel. received eamil from Levent.

---------- Kumar:

Attached is the Remedial Action Work Plan (RAWP) along with a Site Specific Health and Safety Plan (HASP) for the above referenced property. We are looking to schedule this project for next week. Eastern Environmental Solutions, Inc., a NYFD certified environmental contractor, will be subcontractor for the excavation of the soils and/or removal of the UST (if discovered). Please confirm. Thanks

COMMERCIAL BUILDING (Continued) **S107523279**

Levent LEVENT ESKICAKIT, P.G., E.P. Phone: 718-784-7490 Fax: 718-784-4085 Email: <mailto:leskicakit@athenica.com> leskicakit@athenica.com ATHENICA ENVIRONMENTAL SERVICES INC. Environmental Engineering Consultants 45-09 Greenpoint Avenue Long Island City, New York 11103

---

abstract of RAP: - result of dye test confirmed that all 10 floor drains located at the site building, the onsite drywell (1) and two trench drains are interconnected and the final destination of these drains is the NYC municipal sewer located on 37th Ave. - geophysical survey didn't identiy the presence of any additional USTs or former septic system other than an anomaly that might be the former abandoned UST or former septic sywtem located at the site. - site soils consist of approx. nine ft of fill material containing brick, concrete, fly ahs, slag, fine silty sands, clay and fine gravels. native material, consisting of fine to medium sands with some silt, was observed at depths greateer than nine ft bg. - field evidence suggests that petroleum impacted soils occur at depths of approx. four ft bg to the water table, which was encountered between ten and twelve ft bg. - based on the field evidence and the laboratory data, AES concludes that the site has been impacted by petroleum related VOCs and SVOCs in the area where the anomaly identified during the former abandoned UST area. - petroleum impacted material indentified during the previous investigations will be excavated and removed from the site. based on the results of the Phase-II investigation approx. 30 to 50 cubic yards of material will require excavation and subsequent disposal. - once the required remediation activities completed at the site, AES will collect endpoint samples from the excavation. - three groundwater monitoring wells will be installed at selected locations on the site. - it is anticipated that two of the wells loctaion will be located in downgradient area of the release (along site boundry), one well will be located in a portion of the site upgradient of the former suspect UST or former cesspool area. - wells will be completed to an anticipated depth of 15 ft bg. - based on the outcome of the remediation activities at the site, minimum of two sets of groundwater samples will be collected from the monitoring well network. first set will be collected approx. one week following the completion of moniotring well installation efforts. the remaining set will be collected approx. 12 weeks from the date of initial sampling event. COMMUNITY AIR MONITORING PLAN - during the site excavation procedures, AES will perform monitoring of ambient air for VOCs and airborne particulates. - CAMP requires real time monitoring for VOCs and particulates (i.e. dust) at the downwind perimeter of each designated work area when certain activities are in progress at a contaminated site. - action level specified herein require increased monitoring, corrective actions to abate emissions, and/or work shut down. - real time air monitoring for VOCs and particulate levels will occur at the perimeter of the exclusion zone. continuous monitoring will be implemented for all ground intrusive activities. ground intrusive activities include, but are not limited to, soil/waste excavation and handling, test pitting or trenching, and the installation of soil borings or monitoring wells. - VOCs will be monitored at the downwind perimeter of the immediate work area. upwind concentrations will be measured at the start of each work day and periodically thereafter to establish background conditions. - if ambient air concentration of total VOCs at the downwind perimeter of the work area or exclusion zone exceeds 5 ppm above background for

COMMERCIAL BUILDING (Continued) **S107523279**

the 15-minute averate, work activities will be temporarily halted and monitoring continued. - if the VOC level is above 25 ppm at hte perimeter of the work area, activities will be shut down. - if the downwind PM-10 particulate level is 100 mcg/m3 greater than the background (upwind perimeter) for the 15 minute period of if airborne dust is observed leaving the work area, then dust suppression techniques will be employed. - if, after implementation of dust suppression techniques, downwind PM-10 particulate levels are greater then 150 mcg/m3 above the upwind level, work will be stopped and a re-evaluation of activities initiated. spoke to Levent (Cell: 347-556-7787). they are planning to remove all contaminated material from site including suspected abandoned UST and any associated area. he will email me figure 2 of RAWP and phase-II investigation report. Received figure 2 in email. 05/08/06-Hiralkumar Patel. Received call from Levent and he was asking about written approval of proposed RAWP. send email with such approval. 06/21/06-Hiralkumar Patel. REceived email from Levent.

Gentlemen: Finally, we have received our groundwater sample results for the above referenced property. As the analytical results indicate, none of the groundwater samples collected from site contained volatile organic compounds above laboratory methods detection limits or NYSDEC TAGM groundwater cleanup criteria. In summary, we have excavated and disposed of a total of approximately 40 tons of petroleum impacted soil from the site. Confirmatory soil samples have already indicated that no compounds were detected above the NYSDEC TAGM Soil Cleanup Criteria. Following up the excavation, we have installed a total of three groundwater monitoring wells, where we the results are presented within attached report. Upon completion of Remedial Action Report (RAR) for the site, we will submitted it to Mr. Patel of NYCDEP requesting closure of the case number and No Further Action Required letter be issued for the Site. If you have any questions, please do not hesitate to contact me. LEVENT ESKICAKIT, P.G., E.P. Phone: 718-784-7490 Fax: 718-784-4085 Email: <mailto:leskicakit@athenica.com> leskicakit@athenica.com ATHENICA ENVIRONMENTAL SERVICES INC. Environmental Engineering Consultants 45-09 Greenpoint Avenue Long Island City, New York 11103 ---------- no contamination found in groundwater samples. i haven't received soil test results yet. send email to Levent to send soil data with site plan with sampling locations. 06/28/06-Hiralkumar Patel. Received email from Levent.
---------- Kumar:
Attached is the Remedial Action Report (RAR) which summarizes soil excavation, remediation, groundwater sampling, laboratory analytical results, field logs and waste manifests for the above referenced property. The hard copy of the report with all attachments will follow via US Mail. In summary, as the RAR indicated, all petroleum impacted soils have been excavated and disposed of the Site and confirmatory soil and groundwater samples with no detected compounds above the NYSDEC TAGM or TOGS Soil and Groundwater quality Criteria. Consequently, AES requests that the NYSDEC Case Number 05-11360 be closed and a No Further Action Required letter be issued for the Site. If you have any questions, please do not hesitate to contact me. Regards LEVENT ESKICAKIT, P.G., E.P. Phone: 718-784-7490 Fax: 718-784-4085 Email: <mailto:leskicakit@athenica.com> leskicakit@athenica.com ATHENICA ENVIRONMENTAL SERVICES INC.

COMMERCIAL BUILDING (Continued) **S107523279**

Environmental Engineering Consultants 45-09 Greenpoint Avenue Long Island City, New York 11103
---------- no contamination found in any endpoint sample from excavation pit. no contamination found in groundwater also. based on available information, case is closed. NFA letter sent out to Mr. Demetrois. faxed to Mr. Demetrois and to Levent."

Remarks: "SOIL SAMPLES CAME BACK POSITIVE FOR PETROLEUM IMPACT"

All Materials:

Site ID:	357496
Operable Unit ID:	1114771
Operable Unit:	01
Material ID:	2104833
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

L138 **NEW YOGI TRANSMISSION SHOP, INC.** **NY AST** **A100294821**
SSW **21-10 39TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
576 ft. **Site 5 of 19 in cluster L**

Relative: **Higher**

Actual: **18 ft.**

AST:

Name:	NEW YOGI TRANSMISSION SHOP, INC.
Address:	21-10 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609047
Program Type:	PBS
UTM X:	589478.90667
UTM Y:	4512252.98406
Expiration Date:	03/08/2025
Site Type:	Other

Affiliation Records:

Site Id:	30894
Affiliation Type:	Mail Contact
Company Name:	NEW YOGI TRANSMISSION SHOP, INC.
Contact Type:	Not reported
Contact Name:	SURJIT SINGH
Address1:	DBA YOGI TRANSMISSION SHOP
Address2:	21-10 39TH AVENUE
City:	ASTORIA
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 392-6320
EMail:	Not reported

NEW YOGI TRANSMISSION SHOP, INC. (Continued) **A100294821**

Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-06-07
Site Id:	30894
Affiliation Type:	Facility Operator
Company Name:	NEW YOGI TRANSMISSION SHOP, INC.
Contact Type:	Not reported
Contact Name:	SURJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-6320
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KAKYER
Date Last Modified:	2013-06-07
Site Id:	30894
Affiliation Type:	Emergency Contact
Company Name:	LI CITY TRNSMSN SHOP INC/DBE YOGI TRANSMSN SHOP
Contact Type:	Not reported
Contact Name:	SURJIT SINGH
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-6320
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04
Site Id:	30894
Affiliation Type:	Facility Owner
Company Name:	MARGUERITE LUPOLI
Contact Type:	OFFICER
Contact Name:	SURJIT SINGH
Address1:	155-18 COYCLERS LANE
Address2:	Not reported
City:	WHITESTONE
State:	NY
Zip Code:	11357
Country Code:	001
Phone:	(718) 539-0622
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-01-09

Tank Info:

NEW YOGI TRANSMISSION SHOP, INC. (Continued) **A100294821**

Tank Number:	001
Tank Id:	66233
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
J00 - Dispenser - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	66234
Material Code:	0013
Common Name of Substance:	Lube Oil

Equipment Records:

J00 - Dispenser - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron

NEW YOGI TRANSMISSION SHOP, INC. (Continued) **A100294821**

Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	lube oil

L139 **CON EDISON** **NY MANIFEST** **S117318762**
SSW **OPP 21-16 39 AV** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
577 ft. **Site 6 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 21-16 39 AV
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004663340
Facility Status:	Not reported
Location Address 1:	OPP 21-16 39 AV
Code:	BP
Location Address 2:	SB50539
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663340
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/24/2014

CON EDISON (Continued) **S117318762**

TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004663340
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617521GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M140 **CON EDISON** **NY MANIFEST** **S117318765**
South **OPP 38-15 23 ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
577 ft. **Site 4 of 6 in cluster M**

Relative: **Higher**
Actual: **19 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 38-15 23 ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004663407
Facility Status:	Not reported
Location Address 1:	OPP 38-15 23 ST
Code:	BP
Location Address 2:	SB48697
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY

CON EDISON (Continued) **S117318765**

Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663407
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/24/2014
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004663407
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617525GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117318765**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L141 **GRANT INT'L CO., INC.** **NY UST** **U004198724**
SSW **21-24 39TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.109 mi.
577 ft. **Site 7 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	GRANT INT'L CO., INC.
Address:	21-24 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-114111 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589489.96836
UTM Y:	4512245.80742
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	001
Tank ID:	4043
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	6000
Install Date:	12/01/1970
Date Tank Closed:	11/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	03
Date Test:	11/11/1999
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

L142 **KOCH & LOW** **NY CBS** **1000237438**
SSW **21-24 39TH AVE** **NY AST** **NYD175220573**
< 1/8 **LONG ISLAND CITY, NY 11101** **NY CBS AST**
0.109 mi. **RCRA NonGen / NLR**
577 ft. **Site 8 of 19 in cluster L** **FINDS**
ECHO
Relative: **NY MANIFEST**
Higher

Actual: **18 ft.**

CBS:

Name:	KOCH & LOWY
Address:	21-24 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
CBS Number:	2-000131
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	589489.96836
UTMY:	4512245.80742

AST:

Name:	KOCH & LOWY
Address:	21-24 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000131
Program Type:	CBS
UTM X:	589489.96836
UTM Y:	4512245.80742
Expiration Date:	N/A
Site Type:	Unknown

Tank Info:

Tank Number:	1
Tank Id:	187568
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1989
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	08/01/1991
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

CBS AST:

CBS Number:	2-000131
ICS Number:	2-125794
PBS Number:	Not reported
MOSF Number:	Not reported

KOCH & LOW (Continued) **1000237438**

SPDES Number:	Not reported
Facility Status:	TEMPORARILY OUT-OF-SERVICE
Facility Type:	Not reported
Telephone:	(718) 786-3520
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	07/18/1991
Total Capacity of All Active Tanks(gal):	0
Operator:	JESSE REED
Emergency Contact:	GARY BERNICE
Emergency Phone:	(718) 786-3520
Owner Name:	KOCH & LOWY
Owner Address:	21-24 39TH AVENUE
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Telephone:	(718) 786-3520
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	KOCH & LOWY
Mail Contact Addr:	400 LONG BEACH BOULEVARD
Mail Contact Addr2:	Not reported
Mail Contact Contact:	KEITH FREY
Mail Contact City,St,Zip:	STRATFORD, CT 06497
Mail Phone:	(203) 378-4000

Tank Id:	1
CAS Number:	71556
Federal ID:	Not reported
Tank Status:	0
Install Date:	01/89
Tank Closed:	08/91
Capacity (Gal):	250
Chemical:	1,1,1-Trichloroethane
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	3
Date Entered:	07/18/1989
Certified Date:	07/18/1989
Substance:	Not reported
Internal Protection:	Not reported
External Protection:	Not reported
Pipe Location:	Not reported
Pipe Type:	Steel/Iron
Pipe Internal:	Not reported
Pipe External:	Not reported
Pipe Flag:	False
Leak Detection:	Not reported
Overfill Protection:	Not reported
Haz Percent:	0
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	09/13/91

KOCH & LOW (Continued) **1000237438**

Is It There:	False
Delinquent:	False
Date Expired:	07/18/91
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	09/13/1991

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Koch & Low
Handler Address:	21-24 39TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-3608
EPA ID:	NYD175220573
Contact Name:	Not reported
Contact Address:	39TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	39TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Chartwell Group
Owner Type:	Private
Operator Name:	Chartwell Group
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No

KOCH & LOW (Continued) **1000237438**

Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of

KOCH & LOW (Continued) **1000237438**

One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: CHARTWELL GROUP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: CHARTWELL GROUP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: CHARTWELL GROUP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: KOCH & LOW	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101

KOCH & LOW (Continued) **1000237438**

Handler Name: KOCH & LOW
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: KOCH & LOW
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19890213
Handler Name: KOCH & LOW
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004386129

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

KOCH & LOW (Continued) **1000237438**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000237438
Registry ID:	110004386129
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004386129
Name:	KOCH & LOW
Address:	21-24 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	KOCH & LOWEY
Address:	21-24 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101-3608
Country:	USA
EPA ID:	NYD175220573
Facility Status:	Not reported
Location Address 1:	2124 39TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	3608

NY MANIFEST:

EPAID:	NYD175220573
Mailing Name:	KOCH & LOWEY
Mailing Contact:	KOCH & LOWEY
Mailing Address 1:	2124 39TH AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	3608
Mailing Country:	USA
Mailing Phone:	7187863520

J143 **JUNG SUN LAUNDRY SITE** **NY SHWS** **S110246984**
ESE **37-10 24TH STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.110 mi.
579 ft. **Site 7 of 15 in cluster J**

Relative: **Higher**

Actual: **20 ft.**

SHWS:

Name:	JUNG SUN LAUNDRY SITE
Address:	37-10 24TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101-3520
Program:	HW
Site Code:	374812
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	0.480
HW Code:	241102
Record Add:	12/13/2006
Record Upd:	07/18/2022
Updated By:	WBBENNET
Site Description:	"Location: The Site is located in a mixed residential/commercial/light industrial area of Long Island City (Borough of Queens), NY. The location of the Site is the west corner of the intersection of 24th Street and 37th Avenue. Site Features: The site consists of four lots. Current owner owns three lots and the other lot foreclosed by NYC as tax lien property. Recently the other lot (lot 26) was bought by a different owner who demolished the single-story old building that was existed on this lot. The main current site features include a newly built eleven story building on one lot which is being developed, and in other two lots began excavation under an IRM. Excavation initiated in absence of consultant's oversight. During excavation an water main break happened in Dec of 2018, since then no work has been going on until early May of 2022 when newly hired consultant initiated Site Characterization sampling. The whole site is currently secured with a fence and a lockable gate. Current Zoning and Land Use: The site s property is zoned for commercial use. The surrounding parcels are currently used for a combination of commercial, light industrial and utility rights-of-way. The nearest residential area is located north (up gradient) of the site, on the other side of 37th Avenue. There is also a residential area approximately 500 feet south (downgradient) of the Site, on the south side of 38th Avenue. Past Use of the Site: From the 1930 s to the late 1980 s, the Site was used as a commercial laundry. The Site was utilized as a commercial dry cleaner from the late 1980 s to the mid 1990 s. It appears that site contamination resulted from poor housekeeping and spills associated with the dry-cleaning operation. Site Geology and Hydrogeology: Subsurface material consists of sand and some silt and urban fill. The depth to the groundwater varies from approximately 13 to 15 feet below the ground surface. On-site groundwater flow direction is relatively flat; the general flow direction appears to be towards the south-southeast. "
Env Problem:	"Nature and Extent of Contamination: The primary contaminants of concern at the site are tetrachloroethene (PCE) and its degradation products trichloroethene (TCE), cis-1,2-dichloroethene (cis-1,2-DCE), trans-1,2-dichloroethene (trans-1,2-DCE) and vinyl chloride (VC). Soil - During the remedial investigation, PCE, TCE and cis-1,2-DCE were found in on-site soils at concentrations up to 83 parts per million (ppm), 0.22 ppm and 0.17 ppm respectively. The concentration

JUNG SUN LAUNDRY SITE (Continued) **S110246984**

of PCE on-site significantly exceeded the Soil Cleanup Objective (SCO) for unrestricted use as well as for protection of groundwater (1.3 ppm). Groundwater - PCE, TCE, cis-1,2-DCE, trans-1,2-DCE and VC were detected in on-site shallow groundwater at concentrations up to 4,000 parts per billion (ppb), 1200 ppb, 12000 ppb, 130 ppb and 240 ppb respectively. Groundwater standards have been exceeded for PCE, TCE, cis-1,2-dichloroethene, trans-1,2-Dichloroethene, vinyl chloride and chloroform. As per April and June 2012 and March 2014 groundwater data, the PCE plume in groundwater has migrated approximately 400 feet down gradient from the site (off-site) towards southeast. Soil Vapor - PCE and TCE were detected in on-site soil vapor at levels up to 2,800,000 microgram per cubic meter (g/m3) and 130,000 g/m3 respectively and off-site at levels up to 13,000 g/m3 and 420 g/m3, respectively. Soil Vapor Intrusion (SVI) evaluation As part of SVI evaluation, vapor samples were collected from under the basement slab and basement indoor air from 5 surrounding structures. Two structures need mitigation and one structure needs monitoring or mitigation. To mitigate one of the structures located adjacent to the site an SSDS system has installed which currently in operation. "

Health Problem: "Contact with contaminated soil is not expected since it is located at depth and covered by buildings, asphalt and concrete. Ingestion of contaminated groundwater is not likely since the area is served with public water. Site-related contaminants are present in soil vapor. Therefore, there is a potential for soil vapor intrusion to occur in on-site and off-site structures. Investigation of this potential pathway is recommended. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2010-05-06 15:30:00
Record Upd: 2013-09-19 15:00:00
Updated By: kbdilige
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library: Long Island City Branch
Owner Address: 37-44 21 Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 02
Owner Name: Preet Dhillon
Owner Company: Charan Electrical Enterprises Inc.
Owner Address: 9-11 40th Avenue
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: 241102
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN

JUNG SUN LAUNDRY SITE (Continued) **S110246984**

Waste Code:	Not reported
HW Code:	241102
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241102
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	0711317
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2009-03-31 11:06:00
Record Updated:	2009-03-31 11:06:00
Updated By:	JAAVERSA
Crossref ID:	1810563
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-29 10:48:00
Record Updated:	2021-05-29 10:48:00
Updated By:	JHOCONNE

J144 **JUNG SUN LAUNDRY CORP** **NY DRYCLEANERS** **S128782057**
ESE **37-10 24TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.110 mi.
579 ft. **Site 8 of 15 in cluster J**

Relative:
Higher

Actual:
20 ft.

DRYCLEANERS:

Name:	JUNG SUN LAUNDRY CORP
Address:	37-10 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 3520
Facility ID:	2-6304-00393
Phone Number:	7189370428
Region:	Not reported
Registration Effective Date:	1999-05-05 14:33:10
Inspection Date:	2001-05-03 09:50:00
Install Date:	Not reported
Expiration Date:	09/21/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	JUNG SUN LAUNDRY CORP
Address:	37-10 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 3520
Facility ID:	2-6304-00393
Phone Number:	7189370428
Region:	Not reported
Registration Effective Date:	1999-05-05 14:33:10
Inspection Date:	2000-04-06 14:00:00
Install Date:	Not reported
Expiration Date:	09/21/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

JUNG SUN LAUNDRY CORP (Continued) **S128782057**

Alternate Solvent: Not reported
Current Business: Not reported

J145 **JUNG SUN LAUNDRY PLUME** **RCRA-SQG** **1000232222**
ESE **37-10 24TH ST** **US AIRS** **NYD981081847**
< 1/8 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.110 mi. **NJ MANIFEST**
579 ft. **Site 9 of 15 in cluster J**

Relative: **Higher**
Actual: **20 ft.**

RCRA Listings:

Date Form Received by Agency:	20080107
Handler Name:	Jung Sun Laundry Plume
Handler Address:	37-10 24TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD981081847
Contact Name:	SADIQUE AHMED
Contact Address:	BROADWAY 12TH FLOOR
Contact City,State,Zip:	ALBANY, NY 12233-7016
Contact Telephone:	518-402-9775
Contact Fax:	Not reported
Contact Email:	SXAHMED@GW.DEC.STATE.NY.US
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 12TH FLOOR
Mailing City,State,Zip:	ALBANY, NY 12233-7016
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	U210
Waste Description:	Ethene, Tetrachloro- (Or) Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JUNG SUN LAUNDRY	
Legal Status:	Private
Date Became Current:	19840927

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: MOY STEVEN	
Legal Status:	Private
Date Became Current:	19840927
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990714
Handler Name: JUNG SUN LAUNDRY INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20060101
Handler Name: JUNG SUN LAUNDRY INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Electronic Manifest Broker: Not reported

Receive Date: 20080107
Handler Name: JUNG SUN LAUNDRY PLUME
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850514
Handler Name: JUNG SUN LAUNDRY INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080108
Handler Name: JUNG SUN LAUNDRY PLUME
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 333312
NAICS Description: COMMERCIAL LAUNDRY, DRYCLEANING, AND PRESSING MACHINE MANUFACTURING

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19960227
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20140331
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20020828
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CFP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

US AIRS MINOR:

Envid:	1000232222
Region Code:	02
Programmatic ID:	AIR NY0000002630400393
Facility Registry ID:	110001583233
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002630400393
Facility Registry ID:	110001583233
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2000-04-06 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Region Code: 02
Programmatic ID: AIR NY0000002630400393
Facility Registry ID: 110001583233
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400393
Facility Registry ID: 110001583233
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-04-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400393
Facility Registry ID: 110001583233
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-05-03 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400393
Facility Registry ID: 110001583233
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-09-21 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
Name: JUNG SUN LAUNDRY INCORPORATED
Address: 37-10 24TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYD981081847
Facility Status: Not reported
Location Address 1: 37-10 24 STREET

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981081847
Mailing Name:	JUNG SUN LAUNDRY INCORPORATED
Mailing Contact:	EDWARD MOY
Mailing Address 1:	37-10 24 STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189370428

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	06/20/2014
Trans1 Recv Date:	06/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981081847
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000723420VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Quantity:	1600
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD981081847
Mail Address:	24TH ST
Mail City/State/Zip:	LONG ISLAND CITY, NY 11101
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003634739JJK
EPA ID:	NYD981081847
Date Shipped:	02/27/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/27/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Date TSDF Received Waste:	02/27/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	55 G

Manifest Number:	003531090JJK
EPA ID:	NYD981081847
Date Shipped:	01/29/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	01/29/2008
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	01/29/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	115 P

Manifest Year:	Not reported
Waste Code:	F002
Hand Code:	H141
Quantity:	110 G

Manifest Number:	003633982JJK
EPA ID:	NYD981081847
Date Shipped:	03/13/2009
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/13/2009
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/13/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11101

JUNG SUN LAUNDRY PLUME (Continued) **1000232222**

Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 1200 P

Manifest Year: Not reported
Waste Code: F002
Hand Code: H141
Quantity: 55 G

J146 **COMMERCIAL** **NY Spills** **S123660259**
ESE **37-10 24TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.110 mi.
579 ft. **Site 10 of 15 in cluster J**

Relative: **Higher**
Actual: **20 ft.**

SPILLS:
Name: COMMERCIAL
Address: 37-10 24TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Spill Number/Closed Date: 1810563 / Not Reported
Facility ID: 1810563
Facility Type: ER
DER Facility ID: 534037
Site ID: 581465
DEC Region: 2
Spill Cause: Abandoned Drums
Spill Class: C4
SWIS: 4101
Spill Date: 2019-01-17
Investigator: SXAHMED
Referred To: Not reported
Reported to Dept: 2019-01-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2019-01-17
Spill Record Last Update: 2022-03-31
Spiller Name: Not reported
Spiller Company: PROPERTY OWNER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: KEITH BUTLER
DEC Memo: "The property is currently undeveloped and is a NYSDEC Class 2 site (No. 241102). During the

COMMERCIAL (Continued) **S123660259**

installation of shoring and lagging today as part of the proposed redevelopment activities at the
site, the contractor discovered one underground storage tank at the north-central portion of the
site. The tank appears to be between 550 and 1,000-gallons and was reported filled with water (not
sure if it was abandoned with water or its just and accumulation of rainwater. Some of the water
spilled out when the tank was uncovered. The property owner has the names/numbers of several tank
contractors and he is making arrangements to have someone come to pump out and remove the tank
ASAP. The NYSDEC HazWaste project manager (Sadique Ahmed) for the project has also been notified
07/21/2020: This is a class 2 site. PRP supposed to initiate the excavation at lot-32 under IRM
which delayed due to cancellation of their permit by NYCDOB to build a Hotel. This spill will be
closed once the cleanup of the site is complete by the PRP. S. Ahmed 01/19/2021: This is a class 2
site. PRP supposed to initiate the excavation at lot-32 under IRM which delayed due to cancellation
of their permit by NYCDOB to build a Hotel. Negotiation of consent order still ongoing. This spill
will be closed once the cleanup of the site is complete by the PRP. S. Ahmed 03/29/2021: This is a
class 2 site. PRP supposed to initiate the excavation at lot-32 under IRM which delayed due to
cancellation of their permit by NYCDOB to build a Hotel. Negotiation of consent order still
ongoing. This spill will be closed once the cleanup of the site is complete by the PRP. S. Ahmed
03/31/2022: This is a class 2 site. PRP supposed to initiate the excavation at lot-32 under IRM
which delayed due to cancellation of their permit by NYCDOB to build a Hotel. CO for NOV executed.
This spill will be closed once the cleanup of the site is complete by the PRP. S. Ahmed 5/29/21 -
Related to Jung Sun Laundry - site no. 241102. (JHO)"

Remarks: "excavation at site discovered underground tank"

All Materials:

Site ID:	581465
Operable Unit ID:	1329155
Operable Unit:	01
Material ID:	2338211
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

J147 **CON EDISON** **RCRA NonGen / NLR** **1019909167**
SE **37-24 24TH ST** **ECHO** **NYP004881757**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.110 mi.
583 ft. **Site 11 of 15 in cluster J**

Relative: **Higher**
Actual: **20 ft.**

RCRA Listings:

Date Form Received by Agency:	20151218
Handler Name:	Con Edison
Handler Address:	37-24 24TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004881757
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019909167**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220919
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151218
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20151218
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON (Continued) **1019909167**

ECHO:
- Envid: 1019909167
- Registry ID: 110069650844
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069650844
- Name: CON EDISON
- Address: 37-24 24TH ST
- City,State,Zip: LONG ISLAND CITY, NY 11101

J148 **SILKS BUILDING** **NY UST** **U004314666**
SE **37-24 24TH ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.110 mi.
583 ft. **Site 12 of 15 in cluster J**

Relative:
Higher

Actual:
20 ft.

UST:
- Name: SILKS BUILDING
- Address: 37-24 24TH ST
- City,State,Zip: LONG ISLAND CITY, NY 11101
- Id/Status: 2-477893 / Active
- Program Type: PBS
- Region: STATE
- DEC Region: 2
- Expiration Date: 03/06/2027
- UTM X: 589789.40096
- UTM Y: 4512297.13213
- Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:
- Site Id: 21217
- Affiliation Type: Facility Operator
- Company Name: , SILKS BUILDING
- Contact Type: Not reported
- Contact Name: WALTER JONES
- Address1: Not reported
- Address2: Not reported
- City: Not reported
- State: NN
- Zip Code: Not reported
- Country Code: 001
- Phone: (718) 706-0484
- EMail: Not reported
- Fax Number: Not reported
- Modified By: JSMACRI
- Date Last Modified: 2022-03-07

- Site Id: 21217
- Affiliation Type: Emergency Contact
- Company Name: 37-24 STREET EQUITIES LLC
- Contact Type: Not reported
- Contact Name: WALTER JONES
- Address1: Not reported
- Address2: Not reported
- City: Not reported
- State: NN
- Zip Code: Not reported
- Country Code: 999
- Phone: (917) 939-8249
- EMail: Not reported

SILKS BUILDING (Continued) **U004314666**

Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-03-07

Site Id:	21217
Affiliation Type:	Facility Owner
Company Name:	37-24 STREET EQUITIES LLC
Contact Type:	AGENT
Contact Name:	ROBERT SINGER
Address1:	C/O TIME EQUITIES,INC 55 FIFTH AVE
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 206-6000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-03-07

Site Id:	21217
Affiliation Type:	Mail Contact
Company Name:	TIME EQUITIES LLC
Contact Type:	Not reported
Contact Name:	ROBERT SINGER
Address1:	55 FIFTH AVE
Address2:	15TH FLOOR
City:	NEW YORK
State:	NY
Zip Code:	10003
Country Code:	001
Phone:	(212) 206-6000
EMail:	RSINGER@TIMEEQUITIES.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-03-07

Tank Info:

Tank Number:	001
Tank ID:	38444
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	8000
Install Date:	12/01/1948
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	21
Date Test:	07/18/2013
Next Test Date:	10/11/2016
Pipe Model:	Not reported

SILKS BUILDING (Continued) **U004314666**

Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A01 - Tank Internal Protection - Epoxy Liner
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

J149 **SCALAMANDRE** **RCRA NonGen / NLR** **1000276461**
SE **37-24 24TH ST** **FINDS** **NYD986899953**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.110 mi. **NY MANIFEST**
583 ft. **Site 13 of 15 in cluster J**

Relative: **Higher**
Actual: **20 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Scalamandre Silks Inc
Handler Address:	37-24 24TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD986899953
Contact Name:	Not reported
Contact Address:	24TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	24TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Gaff Realty Co
Owner Type:	Private
Operator Name:	Gaff Realty Co
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

SCALAMANDRE (Continued) **1000276461**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator

SCALAMANDRE (Continued) **1000276461**

Owner/Operator Name: GAFF REALTY CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GAFF REALTY CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GAFF REALTY CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19941108
Handler Name: SCALAMANDRE SILKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SCALAMANDRE SILKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

SCALAMANDRE (Continued) **1000276461**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SCALAMANDRE SILKS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900525
Handler Name: SCALAMANDRE SILKS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19910501
Actual Return to Compliance Date: 19910619
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19910601
Enforcement Identifier: 000
Date of Enforcement Action: 19910501
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported

SCALAMANDRE (Continued) **1000276461**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSAN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19910405
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 19910619
Scheduled Compliance Date: 19910601
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004446467

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
Registry ID: 110069650844

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

SCALAMANDRE (Continued) **1000276461**

corrective action activities required under RCRA.

~~Click this hyperlink~~ while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000276461
Registry ID:	110004446467
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004446467
Name:	SCALAMANDRE
Address:	37-24 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	SCALAMANDRE SILKS
Address:	37-24 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYD986899953
Facility Status:	Not reported
Location Address 1:	37-24 24TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986899953
Mailing Name:	SCALAMANDRE SILKS
Mailing Contact:	PATRICK LONG
Mailing Address 1:	37-24 24TH STREET
Mailing Address 2:	Not reported
Mailing City:	QUEENS
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9183618500

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD082785429
Trans2 State ID:	PAD982661381
Generator Ship Date:	02/21/2014
Trans1 Recv Date:	02/21/2014
Trans2 Recv Date:	02/25/2014
TSD Site Recv Date:	02/26/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986899953
Trans1 EPA ID:	Not reported

SCALAMANDRE (Continued) **1000276461**

Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	006692606FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1450
Units:	P - Pounds
Number of Containers:	7
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	D039
Waste Code 1_3:	D040
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J150 **CON EDISON** **NJ MANIFEST** **S120678326**
SE **37-24 24TH ST** **N/A**
< 1/8 **QUEENS, NY 11101**
0.110 mi.
583 ft. **Site 14 of 15 in cluster J**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004881757
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Actual:
20 ft.

CON EDISON (Continued) **S120678326**

Manifest:

Manifest Number:	015320365JJK
EPA ID:	NYP004881757
Date Shipped:	12/18/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

K151 **LUCKY CLEANERS** **EDR Hist Cleaner** **1018426556**
NE **2120 36TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.113 mi.
595 ft. **Site 15 of 18 in cluster K**

Relative: EDR Hist Cleaner
Higher

Actual:
18 ft.

Year:	Name:	Type:
1991	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1992	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1993	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1994	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC

LUCKY CLEANERS (Continued) **1018426556**

1995	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1996	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1997	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
1999	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2000	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2001	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2002	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2003	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2004	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2005	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2006	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2009	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2010	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2011	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2012	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2013	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC
2014	LUCKY CLEANERS	Drycleaning Plants, Except Rugs, NEC

K152 **LUCKY CLEANERS** **RCRA-SQG 1000273341**
NE **21-20 36TH AVE** **US AIRS NYD986886828**
< 1/8 **ASTORIA, NY 11106** **NY MANIFEST**
0.113 mi. **RI MANIFEST**
595 ft. **Site 16 of 18 in cluster K**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Lucky Cleaners
Handler Address:	21-20 36TH AVE
Handler City,State,Zip:	ASTORIA, NY 11106
EPA ID:	NYD986886828
Contact Name:	Not reported
Contact Address:	36TH AVE
Contact City,State,Zip:	ASTORIA, NY 11106
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	36TH AVE
Mailing City,State,Zip:	ASTORIA, NY 11106
Owner Name:	Young Yoon
Owner Type:	Private
Operator Name:	Young Yoon
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

LUCKY CLEANERS (Continued) **1000273341**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20221011
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	NONE

LUCKY CLEANERS (Continued) **1000273341**

Waste Description: Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: YOUNG YOON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: YOUNG YOON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: YOUNG YOON	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19950317
Handler Name: LUCKY CLEANERS	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: LUCKY CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator

LUCKY CLEANERS (Continued) **1000273341**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LUCKY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19900116
Handler Name: LUCKY CLEANERS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19981102
Actual Return to Compliance Date: 19990107
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19990124
Enforcement Identifier: 000
Date of Enforcement Action: 19981219
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

LUCKY CLEANERS (Continued) **1000273341**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2CFP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20071025
Actual Return to Compliance Date: 20071126
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20071025
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

LUCKY CLEANERS (Continued) **1000273341**

Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	20061101
Actual Return to Compliance Date:	20061201
Return to Compliance Qualifier:	Unverifiable
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20070108
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R2RV
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20061101
Actual Return to Compliance Date: 20061201
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20071025
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported

LUCKY CLEANERS (Continued) **1000273341**

Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20061101
Actual Return to Compliance Date: 20061201
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20070108
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20061101
Actual Return to Compliance Date: 20061201
Return to Compliance Qualifier: Unverifiable
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20071025
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported

LUCKY CLEANERS (Continued) **1000273341**

Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: VERBAL INFORMAL
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19981102
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2CFP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 19990107
Scheduled Compliance Date: 19990124
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20071025
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2RV
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20071126
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20061101
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2RV
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20061201
Scheduled Compliance Date: Not reported

LUCKY CLEANERS (Continued) **1000273341**

Date of Request:	20070108
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110818
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20061101
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20061201
Scheduled Compliance Date:	Not reported
Date of Request:	20070108
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20070702
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20061201
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20070702
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20061201
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

US AIRS MINOR:
Envid: 1000273341
Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-11-01 00:00:00
Activity Status Date: 2007-04-16 00:00:00
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Active

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-11-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-01-14 00:00:00

LUCKY CLEANERS (Continued) **1000273341**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-01-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2002-01-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2006-11-01 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-02-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR

LUCKY CLEANERS (Continued) **1000273341**

Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2009-06-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-01-14 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-01-13 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-01-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400550
Facility Registry ID: 110008036464
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2009-02-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02

LUCKY CLEANERS (Continued) **1000273341**

Programmatic ID:	AIR NY0000002630400550
Facility Registry ID:	110008036464
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2009-06-10 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

NY MANIFEST:

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	QUEENS, NY 11106
Country:	USA
EPA ID:	NYD986886828
Facility Status:	Not reported
Location Address 1:	21 20 36TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986886828
Mailing Name:	LUCKY CLEANERS
Mailing Contact:	LUCKY CLEANERS
Mailing Address 1:	21 20 36TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	QUEENS
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7124828842

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD000584803
Trans2 State ID:	MIK814282374
Generator Ship Date:	12/28/2016
Trans1 Recv Date:	12/28/2016
Trans2 Recv Date:	01/04/2017
TSD Site Recv Date:	01/04/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986886828
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	016192382JJK
Import Indicator:	N
Export Indicator:	Y
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	650
Units:	P - Pounds
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

RI MANIFEST:

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	QUEENS, NY 11106
EPA Id:	NYD986886828
GEN Cert Date:	12/8/2011
Manifest Document Number:	002718111SKS
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	440
WT/Vol Units:	P
TSDF Date:	12/15/2011
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	12/15/2011
Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	12/8/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029

LUCKY CLEANERS (Continued) **1000273341**

Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	12/8/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD986886828
Manifest Docket Number:	002718111SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	440
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/8/2011
Facility Receipt Date:	Not reported
Fee:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

Transporter 2 Receipt Date:	12/15/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	12/15/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/14/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD986886828
Manifest Docket Number:	003785135FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	400
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/14/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/14/2011
Number Of Containers:	1
Container Type:	DM
Waste Code1:	Not reported
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD986886828
Manifest Docket Number:	003785135FLE
Quarter:	Not reported
Waste Description:	HAZARDOUS WASTE LIQUID NOS
Transporter Contact Name:	Not reported
Quantity:	100
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/14/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/14/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD986886828
Manifest Docket Number:	003785135FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	400
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported

LUCKY CLEANERS (Continued) **1000273341**

Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/14/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/14/2011
Number Of Containers:	1
Container Type:	DM
Waste Code1:	Not reported
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD986886828
Manifest Docket Number:	003785135FLE
Quarter:	Not reported
Waste Description:	HAZARDOUS WASTE LIQUID NOS
Transporter Contact Name:	Not reported
Quantity:	100
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/14/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

K153 **LUCKY CLEANERS** **NY DRYCLEANERS** **S128782062**
NE **21-20 36TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11106**
0.113 mi.
595 ft. **Site 17 of 18 in cluster K**

Relative:
Higher

Actual:
18 ft.

DRYCLEANERS:

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2000-01-14 13:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2022-01-31 07:10:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2002-01-12 13:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550

LUCKY CLEANERS (Continued) **S128782062**

Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2003-01-13 11:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2004-01-13 08:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2005-01-13 08:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2006-01-13 08:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

LUCKY CLEANERS (Continued) **S128782062**

Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2007-01-10 08:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2008-01-09 08:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2009-03-04 14:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported

LUCKY CLEANERS (Continued) **S128782062**

Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2010-01-08 11:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2011-01-04 11:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2012-01-06 07:50:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2013-01-21 07:50:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

LUCKY CLEANERS (Continued) **S128782062**

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2014-01-08 08:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2015-01-09 08:20:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2016-01-05 08:00:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2017-01-03 08:20:00
Install Date:	Not reported

LUCKY CLEANERS (Continued) **S128782062**

Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2018-01-02 08:00:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2019-01-02 07:50:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106
Facility ID: 2-6304-00550
Phone Number: 7184828842
Region: Not reported
Registration Effective Date: 2003-05-08 15:15:01
Inspection Date: 2020-01-02 08:15:00
Install Date: Not reported
Expiration Date: Not reported
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: LUCKY CLEANERS
Address: 21-20 36TH AVE

LUCKY CLEANERS (Continued) **S128782062**

City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2021-01-13 07:20:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	LUCKY CLEANERS
Address:	21-20 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Facility ID:	2-6304-00550
Phone Number:	7184828842
Region:	Not reported
Registration Effective Date:	2003-05-08 15:15:01
Inspection Date:	2001-01-13 09:30:00
Install Date:	Not reported
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

N154 **CONTAMINATED SOIL AT INDUSTRIAL PROPERTY** **NY Spills** **S121099872**
West **12-02 38TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.114 mi.
600 ft. **Site 2 of 3 in cluster N**

Relative: **Lower**
Actual: **15 ft.**

SPILLS:

Name:	CONTAMINATED SOIL AT INDUSTRIAL PROPERTY
Address:	12-02 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1702829 / Not Reported
Facility ID:	1702829
Facility Type:	ER
DER Facility ID:	506589
Site ID:	552979
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2017-06-21
Investigator:	AGFISCHE
Referred To:	Not reported
Reported to Dept:	2017-06-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported

CONTAMINATED SOIL AT INDUSTRIAL PROPERTY (Continued) **S121099872**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2017-06-21
Spill Record Last Update:	2021-05-27
Spiller Name:	ELIZABETH KLEINHAF-PROPERTY REP
Spiller Company:	INDUSTRIAL PROPERTY
Spiller Address:	12-02 38TH AVE
Spiller Company:	999
Contact Name:	ELIZABETH KLEINHAF-PROPERTY REP
DEC Memo:	"6/27/17-Vought-During routine performance of weekly statistics, Vought noted this spill as Unassigned . DEC Piper who was primary responder when spill was received is currently out of office and Vought spoke to Secondary Responder (Lakhani) and spill assigned to Lakhani for followup and possible sending of requirement letter. 06/28/17 - Lakhani Spoke to AKRF Patrick Diggins (646-388-9784) and he could not divulge much information as per AKRF's attorney's. Clearly, the site does not seem like a cut and dry discovery of historic petroleum contamination. AKRF performed a Phase II on the site for the client who intends to buy the property from principal owner Elysabeth Kleinhans (ek@59E59.org, 212-753-5959 ext:111, 917-699-2658). Patrick did inform that the contamination that was found was minimal. He also informed that the client intends to raze the buildings and redevelop the property. Apparently the site is being reported about on the EDC website. DEC Lakhani calls Elysabeth who informs that the client is T.F. Cornerstone and that they have signed on the property yesterday. The property is mostly open space utilized by 3-4 tenants: Hyundai of LIC (uses space to store used cars), Nutropia (a food preparation operation), Amadeus Marble and Granite Corporation. There also is a vacant building on the property. Elysabeth informed that T.F. Cornerstone is planning on completing the remediation with OER. She offered a contact for AKRF Mark Godick (914-922-2356) and for T.F. Cornerstone Acquisition & Development Derek Marcus (212-901-8121). DEC Lakhani called Derek who confirmed that T.F. Cornerstone has entered the contract to buy the site. They will be redeveloping the site no sooner than February 2018. Derek referred DEC Lakhani to AKRF Mark Godick with whom a message was left. 06/30/17 - Lakhani AKRF Patrick called to inform that after speaking to attorneys that AKRF can release soil and groundwater data from Phase II to DEC. He informed that the contamination found at the site was minimal with respect to the contamination of the overall site. The entire site is intended to be remediated. The current excavation is 20'x20'. The excavation was the

CONTAMINATED SOIL AT INDUSTRIAL PROPERTY (Continued) **S121099872**

location of a former UST that
was removed with residual contamination remaining. T.F. Cornerstone is also entering a contract
with the city - most probably will be conducting cleanup with OER.
07/05/17 - Lakhani Received
email from WCD Group LLC Scott Spitzer who represents Elysabeth Kleinhans. AKRF has stated that
they identified staining, odors, and elevated PID readings approx.
8.5' below sidewalk grade
consistent with petroleum, during drilling and sampling at one boring location. Soil and
groundwater samples collected from the boring and associated temporary groundwater monitoring well
confirmed the presence of VOCs and SVOCs consistent with a petroleum release at boring location
SB/MW/SV-5. The petroleum release appears to be relatively confined to the area of SB/MW/SV-5. Soil
samples are as follow: 1,2,4-trimethylbenzene 23000 ppb(SB-5, 11'-12'bg), 1,2,5-trimethylbenzene
12000 ppb(SB-5, 11'-12'bg), benzene 770 ppb(SB-5, 11'-12'bg), MTBE 770 ppb(SB-5, 11'-12'bg), xylene
13000 ppb(SB-5, 11'-12'bg), toluene 770 ppb(SB-5, 11'-12'bg), benzene 220 ppb(SB-12, 8'-9'bg), MTBE
220 ppb(SB-12, 8'-9'bg), xylene 670 ppb(SB-12, 8'-9'bg). SB-5 also had PAH exceedances. Groundwater
results from MW-5 were as follow: 1,2,4-trimethylbenzene 29 ug/L, 1,3,5-trimethylbenzene 14 ug/L,
benzene 2.2 ug/L, xylene 39 ug/L. 07/07/17 - Lakhani WCD Scott Spitzer emailed informing that the
available data set was created during a due diligence investigation by a third party (the property
owner and WCD did not conduct the fieldwork). Since the investigation resulted in the reporting of
a petroleum spill event, the property owner has authorized the release od investigative findings to
NYSDEC. A RAWP has not yet been developed. ECD is currently in discussions with all parties
regarding the appropriate next steps, which could include enrollment in the city VCP or State BCP.
08/04/17 - Lakhani AFRF Marc Godick sent an email clarifying information regarding the property
owner of the site: TFC 38-21 Twelfth LLC is the contract vendee for the property, but neither it
nor TF Cornerstone Inc. is the current property owner. The current owner is: EK 38th Avenue LLC and
220 LIC LLC, as tenants-in-common 240 Central Park South, Apt 13A New York, NY 10019 Attn:
Elysabeth Kleinhans email: EK@59e59.org Phone: (212) 753-5959 x111 Closing is anticipated to occur
in early October 2017, with an expected outside date of February 28, 2018. The redevelopment of the
site would solely be restricted to commercial use (with no retail). There is no intended
residential use. 12/19/17 - Lakhani Emailed AKRF Mark Goddick, WCD Scott Spitzer and TFC regarding
submission of additional data. 12/27/17 - Lakhani AKRF Marc Goddick sent the following email on

CONTAMINATED SOIL AT INDUSTRIAL PROPERTY (Continued) **S121099872**

12/21/17: As mentioned previously, we represent TFC 38-21 Twelfth LLC (an affiliate of TF
Cornerstone Inc.), who is the prospective purchaser of the property. Our client is scheduled to
close on the property on January 4, 2018. On behalf of the current property owner and our client,
attached is the Phase II investigation report conducted for the entire site. Following closing, our
client plans to initiate the investigation and remediation of the site in an expeditious manner.
Furthermore, based upon the findings of the Phase II investigation, it is our opinion that
site-wide remediation should be conducted in the BCP rather than the Spills Program. We plan to
reach out to you and Jane O'Connell in early January 2018 to set up a BCP pre-app meeting. With
this email response, we would hope that this submission is satisfactory and would allow you to halt
consideration for referring this site for enforcement. Please feel free to contact me at (914)
922-2356. Subsurface (Phase II) Investigation (AKRF, 07/2017) - The site is approx. 70,200 sq. ft.
and comprises of three (3) one-story buildings and two (2) partially covered parking lots. The site
is occupied by commercial and industrial businesses including: a piping fitting shop, two (2)
leased commercial parking lots, Amadeus Marble and Granite Manufacturing, a carpentry shop, and
Nutropia. A storage space and vacant shop (former metal works) were located on the site. The scope
of work included the advancement of 24 soil borings with the collection and analysis of 30 soil
samples; the collection of two (2) sediment samples from an on-site trench system; the installation
of ten (10) temporary wells with the collection and analysis of ten (10) groundwater samples; and
installation of eleven (11) temporary soil vapor points with the collection of eleven (11) soil
vapor samples and one (1) ambient air quality sample. Soil borings, advanced between 10' and 15'bg,
encountered historic fill material (sand, silt, coal ash, concrete, brick, plastic, and/or glass)
underlain by brown or silty-sand and gravel. Groundwater was encountered between 8' and 10'bg and
is expected to flow in the southwesterly direction. Soil is contaminated. Max. concentrations in
soil are as follow: 1,2,4-trimethylbenzene 300,000 ppb(SB-4, 8'-9'bg), 1,3,5-trimethylbenzene
110,000 ppb(SB-4, 8'-9'bg), benzene 190,000 ppb(SB-22, 8'-9'bg), ethylbenzene 170,000 ppb(SB-22,
8'-9'bg), MTBE 12,000 ppb(SB-4, 8'-9'bg), toluene 960,000 ppb(SB-22, 8'-9'bg), xylene 1,440,000
ppb(SB-22, 8'-9'bg), PCE 12,000 ppb(SB-4, 8'-9'bg), TCE 12,000 ppb(SB-4, 8'-9'bg), naphthalene
360,000 ppb(SB-22, 8'-9'bg). Groundwater is contaminated. Max. concentrations in groundwater are as
follow: 1,2,4-trimethylbenzene 29 ug/L(MW-5), 1,3,5-trimethylbenzene

CONTAMINATED SOIL AT INDUSTRIAL PROPERTY (Continued) **S121099872**

14 ug/L(MW-5), benzene 2.8
ug/L(MW-20), toluene 7.9 ug/L(MW-4), xylene 39 ug/L(MW-5), PCE 3.9 ug/L(MW-2/21), TCE 5.2
ug/L(MW-5), naphthalene 132 ug/L(MW-5). Soil vapor is also contaminated with PCE, TCE and other
VOCs. Max. PCE and TCE concentrations are 430 ug/m3 and 4.9 ug/m3 respectively. As per the DOH
Matrices, these concentrations call for monitoring or mitigation.
06/25/18 - Lakhani The site has
been applied to the BCP program. C241213 (38-21 12th Street) DEC Requires: 1) delineation of soil
and groundwater 6/26/18 - Spill has been rolled into BCP site DOT Relocation (C241213) 5/27/21 -
reassigned from Jim Drumm to Aaron Fischer (JHO)"

Remarks: "Phase II investigation discovered contaminated soil. Cleanup pending further investigation."

All Materials:

Site ID:	552979
Operable Unit ID:	1301067
Operable Unit:	01
Material ID:	2307412
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil, Groundwater
Oxygenate:	Not reported

L155 **21-24 39TH AVE/QUEENS** **NY Spills** **S102142113**
SSW **21-24 39TH AVENUE** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.116 mi.
611 ft. **Site 9 of 19 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	21-24 39TH AVE/QUEENS
Address:	21-24 39TH AVENUE
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8909695 / 1994-11-15
Facility ID:	8909695
Facility Type:	ER
DER Facility ID:	213176
Site ID:	261027
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	4101
Spill Date:	1990-01-09
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1990-01-09
CID:	Not reported
Water Affected:	Not reported

21-24 39TH AVE/QUEENS (Continued) **S102142113**

Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1994-11-15
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-01-23
Spill Record Last Update:	1994-11-15
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SUSPECT NEARBY GAS STATION, DEC (SIGONA) INVESTIGATED TRAP, OBSERVED HIGH READINGS WITH THE HNU METER, NOTIFIED NYCDEP HAZMAT IWCS."

All Materials:

Site ID:	261027
Operable Unit ID:	934617
Operable Unit:	01
Material ID:	442848
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

K156 **VAULT #9358** **NY Spills** **S106471382**
NNE **36TH AVE/ 21ST STREET** **N/A**
< 1/8 **QUEENS, NY**
0.117 mi.
620 ft. **Site 18 of 18 in cluster K**

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name:	VAULT #9358
Address:	36TH AVE/ 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0404359 / 2004-10-08
Facility ID:	0404359
Facility Type:	ER
DER Facility ID:	99996
Site ID:	114657
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	4101
Spill Date:	2004-07-22
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-07-23

VAULT #9358 (Continued) **S106471382**

CID:	64
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-23
Spill Record Last Update:	2004-10-08
Spiller Name:	ERT DESK
Spiller Company:	CON EDISON
Spiller Address:	IRIVING PLACE
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"e2mis no 154471 WIKANE REPORTS FINDING APPROX 1/2 PT OF TRANSFORMER OIL ON CONCRETE IN VS9358. THE SPILL CAME FROM THE NETWORK PROTECTOR DOOR. IT APPEARS TO BE A BUSHING LEAK WHICH CANT BE FIXED AND UNIT IS TO BE REPLACED. THE UNIT WAS PRESSURE TESTED AND PASSED, AND THE OIL LEVEL WAS GOOD. THERE WERE NO SEWER CONNECTIONS, AND THERE IS A CONCRETE SUMP. ONE LIQUID SAMPLE TAKEN FOR PCB. LAB SEQ# 04-05760-00: < 1.0 PPM. 7/24/04 1240HRS W.LONG ENVIR OPPS REPORTS CLEANUP COMPLETED DOULBED WASHED STRUCTURE USING BIO-GEN 760. FOUND SUMP SEALED. REMOVED ENVIR TAG#14920."
Remarks:	".5 pint of transformer oil. Transformer was tested and does not appear to be leaking. Con-Ed# 154471"

All Materials:

Site ID:	114657
Operable Unit ID:	887293
Operable Unit:	01
Material ID:	488362
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

L157 **CON ED - V 0599** **RCRA NonGen / NLR 1007206534**
South **22-01 39TH AVE** **NY MANIFEST NYP004011565**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.118 mi.
624 ft. **Site 10 of 19 in cluster L**

Relative: **Higher**

Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - V 0599
Handler Address:	22-01 39TH AVE

CON ED - V 0599 (Continued) **1007206534**

Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-0000
EPA ID:	NYP004011565
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414

CON ED - V 0599 (Continued) **1007206534**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED - V 0599	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980228
Handler Name: CON ED - V 0599	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED - V 0599	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

CON ED - V 0599 (Continued) **1007206534**

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 22-01 39TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11101-0000
Country: USA
EPA ID: NYP004011565
Facility Status: Not reported
Location Address 1: V 0599 - 22-01 39 AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004011565
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

L158 **CON EDISON** **NY MANIFEST** **S117315350**
SSW **2112 39TH AVE** **N/A**
< 1/8 **QUEENS, NY 11361**
0.118 mi.
624 ft. **Site 11 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:
Name: CON EDISON
Address: 2112 39TH AVE
City,State,Zip: QUEENS, NY 11361
Country: USA
EPA ID: NYP004625075
Facility Status: Not reported
Location Address 1: 2112 39TH AVE
Code: BP
Location Address 2: SB 52387
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11361

CON EDISON (Continued) **S117315350**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004625075
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/12/2014
Trans1 Recv Date: 08/12/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004625075
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002616334GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: G - Gallons (liquids only)* (8.3 pounds)
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON (Continued) **S117315350**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P159 **MTA NYCT - BEEBE SIGNAL TOWER N LINE** **RCRA NonGen / NLR** **1004762642**
SW **39TH AVE & 21ST ST** **NY MANIFEST** **NYR000099002**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.119 mi.
629 ft. **Site 1 of 8 in cluster P**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Mta Nyct - Beebe Signal Tower N Line
Handler Address:	39TH AVE & 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000099002
Contact Name:	WILLIAM JEHLE
Contact Address:	BROADWAY 3RD FLOOR
Contact City,State,Zip:	NEW YORK, NY 10004
Contact Telephone:	646-252-3500
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Other
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BROADWAY 3RD FLOOR
Mailing City,State,Zip:	NEW YORK, NY 10004
Owner Name:	Mta New York City Transit
Owner Type:	Other
Operator Name:	Mta New York City Transit
Operator Type:	Other
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N

MTA NYCT - BEEBE SIGNAL TOWER N LINE (Continued) **1004762642**

Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220920
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 3RD FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 3RD FLOOR
Owner/Operator City,State,Zip:	NEW YORK, NY 10004
Owner/Operator Telephone:	646-252-3500
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MTA NEW YORK CITY TRANSIT	
Legal Status:	Other
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2 BROADWAY 3RD FLOOR

MTA NYCT - BEEBE SIGNAL TOWER N LINE (Continued) **1004762642**

Owner/Operator City,State,Zip: NEW YORK, NY 10004
Owner/Operator Telephone: 646-252-3500
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: MTA NYCT - BEEBE SIGNAL TOWER N LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MTA NYCT - BEEBE SIGNAL TOWER N LINE
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20010713
Handler Name: MTA NYCT - BEEBE SIGNAL TOWER N LINE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

MTA NYCT - BEEBE SIGNAL TOWER N LINE (Continued) **1004762642**

NY MANIFEST:

Name:	NYCTA CPM ENVIRONMENTAL ENGINEERING
Address:	39TH AVE & 21ST ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYR000099002
Facility Status:	Not reported
Location Address 1:	QUEENSBORO PLAZA 39TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000099002
Mailing Name:	NYCTA CPM ENVIRONMENTAL ENGINEERING
Mailing Contact:	N/S
Mailing Address 1:	2 BROADWAY 2ND FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	6462523500

L160 **QUEENSBRIDGE CENTRAL SUBSTA.** **NY UST** **U004198790**
South **22-09 39TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.119 mi.
630 ft. **Site 12 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	QUEENSBRIDGE CENTRAL SUBSTA.
Address:	22-09 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-452920 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589565.03145
UTM Y:	4512207.32781
Site Type:	Utility (Other than Municipal)

Tank Info:

Tank Number:	D01
Tank ID:	35610
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1080
Install Date:	12/01/1980
Date Tank Closed:	09/01/1998

QUEENSBRIDGE CENTRAL SUBSTA. (Continued) **U004198790**

Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

L161 **QUEENSBRIDGE SUB STATION** **NY Spills** **S110540408**
South **22-09 39TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.119 mi.
630 ft. **Site 13 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name:	QUEENS BRIDGE SUBSTATION
Address:	22-09 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1006239 / 2010-09-24
Facility ID:	1006239
Facility Type:	ER
DER Facility ID:	394589
Site ID:	439587
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2010-09-08
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2010-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-08
Spill Record Last Update:	2010-09-24
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"9/24/10 - Austin - 3 gal. leak onto bluestone - Con Ed contained and removed spill - see documents in eDocs for further information - spill closed - end"
Remarks:	"onto blue stone - cleanup pending"

All Materials:

Site ID:	439587
Operable Unit ID:	1190223

QUEENSBRIDGE SUB STATION (Continued) **S110540408**

Operable Unit:	01
Material ID:	2185201
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	QUEENSBRIDGE SUB STATION
Address:	22-09 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9405052 / 2003-01-22
Facility ID:	9405052
Facility Type:	ER
DER Facility ID:	159442
Site ID:	191147
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	4101
Spill Date:	1994-07-13
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1994-07-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-06
Spill Record Last Update:	2006-06-29
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 7/18/94, 3:07 PM: HEGARTY - TRANSFORMER OIL FROM PUMP. 15 TO 20 GALLONS. 1/22/03: close out - spill to be remediated under spill # 0200329."
Remarks:	"SPILL ON PAD & BLUE STONE . CLEAN UP IN PROGRESS."

All Materials:

Site ID:	191147
Operable Unit ID:	1002257
Operable Unit:	01
Material ID:	381656

QUEENSBRIDGE SUB STATION (Continued) **S110540408**

Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	QUEENSBRIDGE SUBSTATION
Address:	22-09 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0701543 / 2007-05-23
Facility ID:	0701543
Facility Type:	ER
DER Facility ID:	159442
Site ID:	381078
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2007-05-07
Investigator:	gdbreen
Referred To:	Not reported
Reported to Dept:	2007-05-07
CID:	408
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-07
Spill Record Last Update:	2008-04-01
Spiller Name:	ERTSDESK
Spiller Company:	CON EDISON
Spiller Address:	22-09 39TH AVE
Spiller Company:	999
Contact Name:	ERTSDESK
DEC Memo:	"05/23/07 - See e-docs for Con Ed report detailing cleanup and closure. 205710. see eDocs 5-9-07. Inspected site with Pete Sudol and Joe Flores. Impacted area had been remediated. Bluestone replaced. Pressure on Pothead had been reduced, four bolts securing pothead to feeder were then tightened, when full pressure was restored the oozing of fluid had stopped. Breen See eDocs for 2008 Substation Inspection Findings and for response from Con Edison relative to this spill. "
Remarks:	"NOT YET CLEANED; 1 DRIP EVERY FOUR SECONDS; BLUE STONE EFFECTED; REF#205710; ON GOING SPILL"

QUEENSBRIDGE SUB STATION (Continued) **S110540408**

All Materials:

Site ID:	381078
Operable Unit ID:	1138543
Operable Unit:	01
Material ID:	2128535
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	QUEENS BRIDGE SUBSTATION
Address:	22-09 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1702498 / 2018-09-18
Facility ID:	1702498
Facility Type:	ER
DER Facility ID:	394589
Site ID:	551638
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2017-06-13
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2017-06-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-06-13
Spill Record Last Update:	2018-09-18
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PAUL
DEC Memo:	"9/18/18 Austin Lead found in excavated soil from excavation at the Queensbridge substation - based upon volume estimations, Con Ed determined ex-situ soil contained upwards of 59 lbs of elemental lead - Con Ed disposed of the 243 tons of lead contaminated soil at Bayshore Soil Mgt. See document files for further information Spill closed end "
Remarks:	"3 piles containing avg of 20 pounds per pile - cleanup pending

QUEENSBRIDGE SUB STATION (Continued) **S110540408**

contractor to remove piles"

All Materials:

Site ID:	551638
Operable Unit ID:	1299723
Operable Unit:	01
Material ID:	2305956
Material Code:	9999
Material Name:	other - lead
Case No.:	Not reported
Material FA:	Other
Quantity:	60.00
Units:	L
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	MANHOLE 12777 - QUEENS BRIDGE SUBSTATION
Address:	22-09 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1403712 / 2014-09-26
Facility ID:	1403712
Facility Type:	ER
DER Facility ID:	394589
Site ID:	497079
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	4101
Spill Date:	2014-07-07
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2014-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-07-07
Spill Record Last Update:	2014-09-26
Spiller Name:	ERT
Spiller Company:	CON EDISON
Spiller Address:	22-09 39TH AVE
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	".emis-237368 9/26/14 - Austin - 8 gals cable oil (by lab analysis) atop 300 gals water in vault - Con Ed contained and cleaned up the spill; no source identified - See the document files for further information - Spill closed - end"
Remarks:	"8 gals on top of 300 gals of water on manhole. Cleanup is pending."

QUEENSBRIDGE SUB STATION (Continued) **S110540408**

All Materials:

Site ID:	497079
Operable Unit ID:	1246551
Operable Unit:	01
Material ID:	2247723
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	8.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

L162 **CON EDISON - QUEENSBRIDGE SERVICE STATION** **RCRA-LQG** **1004759788**
South **2209 39TH ST** **FINDS** **NYR000020834**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.119 mi. **NY MANIFEST**
630 ft. **Site 14 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

RCRA Listings:

Date Form Received by Agency:	20220222
Handler Name:	Con Edison - Queensbridge Service Station
Handler Address:	2209 39TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000020834
Contact Name:	ALEX PIZZANO
Contact Address:	IRVING PL ROOM 300
Contact City,State,Zip:	NEW YORK, NY 10003-3598
Contact Telephone:	718-392-0539
Contact Fax:	Not reported
Contact Email:	PIZZANOA@CONED.COM
Contact Title:	SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2021
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL ROOM 300
Mailing City,State,Zip:	NEW YORK, NY 10003-3598
Owner Name:	Con Edison Co Of New York Inc
Owner Type:	Private
Operator Name:	Con Edison Co Of New York Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220915
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2021

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D008
Waste Description: Lead

Waste Code: D018
Waste Description: Benzene

Waste Code: X002
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CON EDISON CO OF NEW YORK INC
Legal Status: Private

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL ROOM 300
Owner/Operator City,State,Zip: NEW YORK, NY 10003-3598
Owner/Operator Telephone: 212-460-4833
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CON EDISON CO OF NEW YORK INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL ROOM 300
Owner/Operator City,State,Zip: NEW YORK, NY 10003-3598
Owner/Operator Telephone: 212-460-4833
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CON EDISON CO OF NEW YORK INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL ROOM 300
Owner/Operator City,State,Zip: NEW YORK, NY 10003-3598
Owner/Operator Telephone: 212-460-4833
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CON EDISON CO OF NEW YORK INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL ROOM 300
Owner/Operator City,State,Zip: NEW YORK, NY 10003-3598
Owner/Operator Telephone: 212-460-4833
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CON EDISON CO OF NEW YORK INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PL ROOM 300
Owner/Operator City,State,Zip: NEW YORK, NY 10003-3598
Owner/Operator Telephone: 212-460-4833
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Historic Generators:

Receive Date:	20220222
Handler Name:	CON EDISON - QUEENSBRIDGE SERVICE STATION
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	20060101
Handler Name:	CON EDISON - QUEENSBRIDGE SS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	CON EDISON - QUEENSBRIDGE SS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	19960308
Handler Name:	CON EDISON - QUEENSBRIDGE SS
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	22112
NAICS Description:	ELECTRIC POWER TRANSMISSION, CONTROL, AND DISTRIBUTION

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20041117
Actual Return to Compliance Date:	20041129
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20041129
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYYWG
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20041117
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYYWG
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20041129
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20030421
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110008094025

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004759788
Registry ID:	110008094025
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110008094025
Name:	CON EDISON - QUEENSBRIDGE SERVICE STATION
Address:	2209 39TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	2209 39TH ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYR000020834
Facility Status:	Not reported
Location Address 1:	2209 39TH ST-QUEENSBRIDGE S/S
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000020834
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2008
Trans1 Recv Date:	12/23/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/29/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON - QUEENSBRIDGE SERVICE STATION (Continued) **1004759788**

Generator EPA ID:	NYR000020834
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433724FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	5
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	B005
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L163 **QUEENSBRIDGE CENTRAL SUBSTA.** **NY AST** **A100382344**
South **22-09 39TH AVENUE** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.119 mi.
630 ft. **Site 15 of 19 in cluster L**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	QUEENSBRIDGE CENTRAL SUBSTA.
Address:	22-09 39TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-452920
Program Type:	PBS
UTM X:	589565.03145
UTM Y:	4512207.32781
Expiration Date:	N/A
Site Type:	Utility (Other than Municipal)

Tank Info:

QUEENSBRIDGE CENTRAL SUBSTA. (Continued) **A100382344**

Tank Number:	D02
Tank Id:	35611
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1980
Capacity Gallons:	50
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

Tank Number:	D03
Tank Id:	54339
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1998
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

L164 **QUEENS BRIDGE SUB STATION** **NY Spills** **S109582329**
South **2209 39TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.119 mi.
630 ft. **Site 16 of 19 in cluster L**

Relative: SPILLS:
Higher

Actual:
18 ft.

Name:	QUEENS BRIDGE SUB STATION
Address:	2209 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0901118 / 2009-06-03
Facility ID:	0901118
Facility Type:	ER
DER Facility ID:	362233
Site ID:	413084
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2009-04-28
Investigator:	Con Ed Unassigned

QUEENS BRIDGE SUB STATION (Continued) **S109582329**

Referred To:	Not reported
Reported to Dept:	2009-04-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-28
Spill Record Last Update:	2009-06-03
Spiller Name:	Not reported
Spiller Company:	Con Edison
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"06/03/09 - See eDocs for Con Ed report detailing cleanup and closure. "
Remarks:	"1 gallon spilled on to Blue stone-drip rate of 1 drop every 10 seconds - clean up requires outage-pending of that detirmination."

All Materials:

Site ID:	413084
Operable Unit ID:	1169535
Operable Unit:	01
Material ID:	2161191
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

L165 **QUEENS BRINDGE SUBSTATION TRANSFORMER #6** **NY Spills** **S117852392**
South **22-09 39TH AVE** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.119 mi.
630 ft. **Site 17 of 19 in cluster L**

Relative: **Higher**
Actual: **18 ft.**

SPILLS:

Name:	QUEENS BRINDGE SUBSTATION TRANSFORMER #6
Address:	22-09 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1500748 / 2017-02-28
Facility ID:	1500748
Facility Type:	ER
DER Facility ID:	394589
Site ID:	506914
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4

QUEENS BRINDGE SUBSTATION TRANSFORMER #6 (Continued) **S117852392**

SWIS:	4101
Spill Date:	2015-04-22
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	2015-04-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-04-22
Spill Record Last Update:	2017-02-28
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"4/23/15-Ahmed- While ConEd crew attempting to close a breaker on transformer #6, 7 gallons dielectric fluid spilled (5 gallons on concrete pad and 2 gallons on bluestone), all contained on substation property. 2/28/17 - Austin - Con Ed contained and cleaned up the spill, and the transformer was replaced - See document files for further information - Spill closed - end"
Remarks:	"leak has been contained and clean up pending resources."

All Materials:

Site ID:	506914
Operable Unit ID:	1256255
Operable Unit:	01
Material ID:	2259072
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

L166 **ONE PINT DIESEL LEAK FROM VEH 41303** **NY Spills** **S108955452**
South **22-09 39 AVENUE (AT 22 STREET)** **N/A**
< 1/8 **LONG ISLAND CITY, NY**
0.119 mi.
630 ft. **Site 18 of 19 in cluster L**

Relative: SPILLS:
Higher

Name:	ONE PINT DIESEL LEAK FROM VEH 41303
Address:	22-09 39 AVENUE (AT 22 STREET)
City,State,Zip:	LONG ISLAND CITY, NY

Actual:
18 ft.

ONE PINT DIESEL LEAK FROM VEH 41303 (Continued) **S108955452**

Spill Number/Closed Date:	0707385 / 2007-11-27
Facility ID:	0707385
Facility Type:	ER
DER Facility ID:	337587
Site ID:	388081
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2007-10-04
Investigator:	gdbreen
Referred To:	Not reported
Reported to Dept:	2007-10-04
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-10-04
Spill Record Last Update:	2007-11-27
Spiller Name:	ERTSDESK
Spiller Company:	CON EDISON
Spiller Address:	39TH & 22ND STREET
Spiller Company:	999
Contact Name:	ERTSDESK
DEC Memo:	"11/27/07 - See eDocs for Con Ed report detailing cleanup and closure. 208386. see eDocs"
Remarks:	"CONED VEHICLE#41303 = 20 DROPS PER MINUTE: =WILL BE REPAIRED: CONED # 208386"

All Materials:

Site ID:	388081
Operable Unit ID:	1145264
Operable Unit:	01
Material ID:	2135595
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

P167 **CON EDISON EXCAVATION 11106** **RCRA NonGen / NLR** **1014919108**
SW **21ST ST BETWN 38TH & 39TH AVE** **NY MANIFEST** **NYP004232625**
< 1/8 **ASTORIA, NY 11106**
0.120 mi.
631 ft. **Site 2 of 8 in cluster P**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20110426
Handler Name:	Con Edison Excavation 11106
Handler Address:	21ST ST BETWN 38TH & 39TH AVE
Handler City,State,Zip:	ASTORIA, NY 11106
EPA ID:	NYP004232625
Contact Name:	CHARLES CARRILLO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-204-4455
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLAZA RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON EXCAVATION 11106 (Continued) **1014919108**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20111026
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20110327
Handler Name:	CON EDISON EXCAVATION 11106
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20110426
Handler Name:	CON EDISON EXCAVATION 11106
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON EXCAVATION 11106 (Continued) **1014919108**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	21ST ST BETWN 38TH & 39TH AVE
City,State,Zip:	ASTORIA, NY 11106
Country:	USA
EPA ID:	NYP004232625
Facility Status:	Not reported
Location Address 1:	21ST ST & 38 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004232625
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/28/2011
Trans1 Recv Date:	03/28/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/29/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004232625
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	003206891FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON EXCAVATION 11106 (Continued) **1014919108**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	D007
Waste Code 1_3:	D006
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P168 **SERVICE STATION** **RCRA NonGen / NLR** **1000432448**
SW **38-25 21ST ST & 39TH AVE** **FINDS** **NYD000698639**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.120 mi.
634 ft. **Site 3 of 8 in cluster P**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Service Station
Handler Address:	38-25 21ST ST & 39TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD000698639
Contact Name:	HOWARD ALGEO
Contact Address:	21ST ST & 39TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	215-688-8200
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	21ST ST & 39TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Sun Oil Company Of Pennsylvania
Owner Type:	Private
Operator Name:	Sun Oil Company Of Pennsylvania
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

SERVICE STATION (Continued) **1000432448**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	SUN OIL COMPANY OF PENNSYLVANIA
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212

SERVICE STATION (Continued) **1000432448**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: SUN OIL COMPANY OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: SUN OIL COMPANY OF PENNSYLVANIA
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SERVICE STATION
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: SERVICE STATION

SERVICE STATION (Continued) **1000432448**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110007992431

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000432448
Registry ID:	110007992431
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110007992431
Name:	SERVICE STATION
Address:	38-25 21ST ST & 39TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

J169 **37-24 24TH ST/QUEENS** **NY LTANKS** **S100167722**
ESE **37-24 24TH STREET** **N/A**
< 1/8 **NEW YORK CITY, NY**
0.120 mi.
636 ft. **Site 15 of 15 in cluster J**

Relative: **Higher**
Actual: **21 ft.**

LTANKS:

Name:	37-24 24TH ST/QUEENS
Address:	37-24 24TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8905393 / 1992-10-02
Facility ID:	8905393

37-24 24TH ST/QUEENS (Continued) **S100167722**

Site ID:	177843
Spill Date:	1989-08-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-02
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1989-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-09-06
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	149431
DEC Memo:	""
Remarks:	"8K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL EXCAVATE & INVESTIGATE."

All TTF:

Facility ID:	8905393
Spill Number:	8905393
Spill Tank Test:	1535945
Site ID:	177843
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	177843
Operable Unit ID:	930616
Operable Unit:	01
Material ID:	445825

37-24 24TH ST/QUEENS (Continued) **S100167722**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Q170 **LOT 1,TAXBLOCK 351** **NY E DESIGNATION** **S110541031**
NW **12-01 37 AVENUE** **N/A**
< 1/8 **QUEENS, NY**
0.122 mi.
643 ft. **Site 1 of 4 in cluster Q**

Relative: **Lower**
Actual: **15 ft.**

E DESIGNATION:

Name:	LOT 1,TAXBLOCK 351
Address:	12-01 37 AVENUE
City,State,Zip:	QUEENS, NY
Tax Lot(s):	1
Tax Block:	351
Borough Code:	Not reported
E-No:	E-250
Effective Date:	2010-09-16
Satisfaction Date:	Not reported
Ceqr Number:	10DCP014Q
Ulurp Number:	100145ZMQ
Zoning Map No:	9a 9b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

N171 **COMMERCIAL BUSINESS** **NY Spills** **S106867274**
WSW **38-21 12TH STREET** **N/A**
< 1/8 **QUEENS, NY**
0.122 mi.
644 ft. **Site 3 of 3 in cluster N**

Relative: **Lower**
Actual: **16 ft.**

SPILLS:

Name:	COMMERCIAL BUSINESS
Address:	38-21 12TH STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0413143 / 2005-10-26
Facility ID:	0413143
Facility Type:	ER
DER Facility ID:	285612
Site ID:	338992
DEC Region:	2
Spill Cause:	Other
Spill Class:	C4
SWIS:	4101
Spill Date:	2005-03-17
Investigator:	SMSANGES
Referred To:	Not reported

COMMERCIAL BUSINESS (Continued) **S106867274**

Reported to Dept:	2005-03-17
CID:	44
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2005-03-17
Spill Record Last Update:	2005-10-26
Spiller Name:	MARLIN JOSEPH
Spiller Company:	COMMERCIAL BUSINESS
Spiller Address:	38-21 12TH STREET
Spiller Company:	001
Contact Name:	MARLIN JOSEPH
DEC Memo:	"sent ttf ltr on 3/25/2005 10/26/2005 Sangesland reviewed a submittal from Petroleum Tank Cleaners dated Sept 13, 2005 (received by DEC on 10/24/2005) Letter states that the tank was uncovered and a remote fill line was traced back to the area under a new sidewalk. This line was open and probably caused the test failure. No contaminateion was found in the sidewalk location. The tank was fully excavated and removed, no contmaination was found. End point soil samples were taken and were all below detection levels. Spill Closed"
Remarks:	"SYSTEM TEST AND FOUND LEAK: (AN ABOVE LIQUID TEST) SIZE 1500"

All Materials:

Site ID:	338992
Operable Unit ID:	1100911
Operable Unit:	01
Material ID:	581041
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

R172 **CON EDISON** **NJ MANIFEST** **S120675017**
South **38-21 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 1 of 11 in cluster R**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004819045
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

Actual:
19 ft.

CON EDISON (Continued) **S120675017**

Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619501GBF
EPA ID:	NYP004819045
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R173 **CON EDISON** **NY MANIFEST** **S119077031**
South **38-21 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 2 of 11 in cluster R**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	38-21 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004819060
Facility Status:	Not reported
Location Address 1:	OPP 38-31 23RD ST
Code:	BP
Location Address 2:	SB 63538
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004819060
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2015
Trans1 Recv Date:	08/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004819060
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619502GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119077031**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R174 **CON EDISON** **RCRA NonGen / NLR** **1019906255**
South **38-21 23RD ST** **FINDS** **NYP004819045**
< 1/8 **LONG ISLAND CITY, NY 11101** **ECHO**
0.122 mi.
645 ft. **Site 3 of 11 in cluster R**

Relative: **Higher**
Actual: **19 ft.**

RCRA Listings:

Date Form Received by Agency:	20150805
Handler Name:	Con Edison
Handler Address:	38-21 23RD ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004819045
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON (Continued) **1019906255**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019906255**

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069643979

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906255
Registry ID:	110069643979
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069643979
Name:	CON EDISON
Address:	38-21 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

R175 **CON EDISON** **NJ MANIFEST** **S120675019**
South **38-21 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 4 of 11 in cluster R**

Relative:
Higher

Actual:
19 ft.

NJ MANIFEST:

EPA Id:	NYP004819060
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619502GBF
EPA ID:	NYP004819060
Date Shipped:	8/5/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120675019**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R176 **B&F AUTO CARE INC.** **NY AST** **A100298699**
South **38-21 23RD STREET** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 5 of 11 in cluster R**

Relative:
Higher

Actual:
19 ft.

AST:

Name:	B&F AUTO CARE INC.
Address:	38-21 23RD STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610326
Program Type:	PBS
UTM X:	589687.92587
UTM Y:	4512253.33060
Expiration Date:	03/18/2015
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	369929
Affiliation Type:	Mail Contact
Company Name:	B&F AUTO CARE INC.
Contact Type:	Not reported
Contact Name:	AHSAN ULLAHA
Address1:	38-21 23RD STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-3052
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-03-18

Site Id:	369929
Affiliation Type:	Facility Operator
Company Name:	B&F AUTO CARE INC.
Contact Type:	Not reported
Contact Name:	AHSAN ULLAHA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-3052

B&F AUTO CARE INC. (Continued) **A100298699**

EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-03-18

Site Id: 369929
Affiliation Type: Emergency Contact
Company Name: B&F AUTO CARE INC.
Contact Type: Not reported
Contact Name: AHSAN ULLAHA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (646) 250-9062
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-03-18

Site Id: 369929
Affiliation Type: Facility Owner
Company Name: B&F AUTO CARE INC.
Contact Type: Not reported
Contact Name: Not reported
Address1: 38-21 23RD ST.
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-3052
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-03-18

Tank Info:

Tank Number: 001
Tank Id: 213430
Material Code: 0022
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping

B&F AUTO CARE INC. (Continued) **A100298699**

	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	E00 - Piping Secondary Containment - None
	G02 - Tank Secondary Containment - Vault (w/access)
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	04/01/2004
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

R177 **CON EDISON** **RCRA NonGen / NLR** **1019906257**
South **38-21 23RD ST** **NYP004819060**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 6 of 11 in cluster R**

Relative: **Higher**

Actual: **19 ft.**

RCRA Listings:

Date Form Received by Agency:	20150805
Handler Name:	Con Edison
Handler Address:	38-21 23RD ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004819060
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No

CON EDISON (Continued) **1019906257**

Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150805
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019906257**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

R178 **CON EDISON** **NY MANIFEST** **S119077029**
South **38-21 23RD ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 7 of 11 in cluster R**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 38-21 23RD ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004819045
Facility Status: Not reported
Location Address 1: OPP 38-21 23RD ST
Code: BP
Location Address 2: SB 48825
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004819045
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON (Continued) **S119077029**

Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/05/2015
Trans1 Recv Date:	08/05/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004819045
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619501GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R179 **CON EDISON** **NY MANIFEST** **S117318761**
South **OPP 38-21 23 ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 11101**
0.122 mi.
645 ft. **Site 8 of 11 in cluster R**

Relative: NY MANIFEST:
Higher

Name:	CON EDISON
Address:	OPP 38-21 23 ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004663339

Actual:
19 ft.

CON EDISON (Continued) **S117318761**

Facility Status:	Not reported
Location Address 1:	OPP 38-21 23 ST
Code:	BP
Location Address 2:	SB48825
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663339
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/24/2014
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004663339
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617524GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117318761**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q180
NNW
< 1/8
0.124 mi.
653 ft.

LOT 6,TAXBLOCK 351 **NY E DESIGNATION** **S110541042**
36-31 12 STREET **N/A**
QUEENS, NY

Site 2 of 4 in cluster Q

Relative:
Lower

Actual:
15 ft.

E DESIGNATION:

Name:	LOT 6,TAXBLOCK 351
Address:	36-31 12 STREET
City,State,Zip:	QUEENS, NY
Tax Lot(s):	6
Tax Block:	351
Borough Code:	Not reported
E-No:	E-250
Effective Date:	2010-09-16
Satisfaction Date:	Not reported
Ceqr Number:	10DCP014Q
Ulurp Number:	100145ZMQ
Zoning Map No:	9a 9b
Description:	Hazardous Materials* Phase I and Phase II Testing Protocol
Lot Remediation Date:	Not reported

L181
South
< 1/8
0.124 mi.
654 ft.

UNKNOWN **NY Spills** **S117268302**
22-09 39TH AVE QUEENS AND 38-54 VERNON BLVD IN QUE **N/A**
QUEENS, NY

Site 19 of 19 in cluster L

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name:	UNKNOWN
Address:	22-09 39TH AVE QUEENS AND 38-54 VERNON BLVD IN QUE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	1403711 / 2014-07-08
Facility ID:	1403711
Facility Type:	ER
DER Facility ID:	452094
Site ID:	497078
DEC Region:	2
Spill Cause:	Unknown

UNKNOWN (Continued) **S117268302**

Spill Class:	D3
SWIS:	4101
Spill Date:	2014-07-07
Investigator:	RMPIPER
Referred To:	Not reported
Reported to Dept:	2014-07-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-07-07
Spill Record Last Update:	2014-07-08
Spiller Name:	CHRIS
Spiller Company:	CON ED
Spiller Address:	22-09 39TH AVE QUEENS AND 38-54 VERNON BLVD IN QUE
Spiller Company:	999
Contact Name:	CHRIS
DEC Memo:	"duplicate spill. see 1403710"
Remarks:	"22-09 39th ave queens and 38-54 Vernon blvd in queens unknown leak point at this time"

All Materials:

Site ID:	497078
Operable Unit ID:	1246550
Operable Unit:	01
Material ID:	2247722
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

R182 **CON EDISON** **NY MANIFEST** **S117318764**
South **OPP 38-31 23 ST** **N/A**
< 1/8 **LONG ISLAND CITY, NY 10001**
0.124 mi.
655 ft. **Site 9 of 11 in cluster R**

Relative: **Higher**
Actual: **19 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 38-31 23 ST
City,State,Zip:	LONG ISLAND CITY, NY 10001
Country:	USA
EPA ID:	NYP004663381
Facility Status:	Not reported
Location Address 1:	OPP 38-31 23 ST
Code:	BP

CON EDISON (Continued) **S117318764**

Location Address 2:	SB63538
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	10001
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663381
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/24/2014
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004663381
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617523GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40

CON EDISON (Continued) **S117318764**

Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O183 **CONSOLIDATED EDISON** **NY MANIFEST** **S108980670**
NNE **36TH AVE & 14TH ST** **N/A**
< 1/8 **QUEENS, NY**
0.124 mi.
656 ft. **Site 2 of 3 in cluster O**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	36TH AVE & 14TH ST
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004155644
Facility Status:	Not reported
Location Address 1:	36TH AVE & 14TH ST
Code:	BP
Location Address 2:	MH8649
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004155644
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/07/2008
Trans1 Recv Date:	01/07/2008
Trans2 Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S108980670**

TSD Site Recv Date:	01/08/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004155644
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001451326FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S184 **D. MOY & SONS** **NY CBS S126289997**
ESE **36-44 24 STREET** **NY AST N/A**
1/8-1/4 **QUEENS, NY 11106**
0.126 mi.
663 ft. **Site 1 of 4 in cluster S**

Relative:
Higher

Actual:
19 ft.

CBS:

Name:	D. MOY & SONS
Address:	36-44 24 STREET
City,State,Zip:	QUEENS, NY 11106
CBS Number:	2-000262
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	589909.40577
UTMY:	4512453.79773

D. MOY & SONS (Continued) **S126289997**

AST:

Name:	D. MOY & SONS
Address:	36-44 24 STREET
City,State,Zip:	QUEENS, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000262
Program Type:	CBS
UTM X:	589909.40577
UTM Y:	4512453.79773
Expiration Date:	N/A
Site Type:	Other

Tank Info:

Tank Number:	001
Tank Id:	190633
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Plastic
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/01/1993
Capacity Gallons:	1490
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

T185 **CLEO MANAGEMENT** **NY MANIFEST** **S117564760**
East **36-15 23RD ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.130 mi.
685 ft. **Site 1 of 5 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CLEO MANAGEMENT
Address:	36-15 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYR000049015
Facility Status:	Not reported
Location Address 1:	202-03 32ND AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BAYSIDE
Location State:	NY
Location Zip:	11361
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000049015

CLEO MANAGEMENT (Continued) **S117564760**

Mailing Name:	CLEO MANAGEMENT
Mailing Contact:	EDMOND
Mailing Address 1:	202-03 32ND AVENUE
Mailing Address 2:	Not reported
Mailing City:	BAYSIDE
Mailing State:	NY
Mailing Zip:	11361
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189561721

T186 **CON EDISON** **NY MANIFEST** **S117315827**
East **36-15A 23 ST** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.130 mi.
685 ft. **Site 2 of 5 in cluster T**

Relative: **Higher**

Actual: **18 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	36-15A 23 ST
City,State,Zip:	QUEENS, NY 11106
Country:	USA
EPA ID:	NYP004630331
Facility Status:	Not reported
Location Address 1:	36-15A 23 ST
Code:	BP
Location Address 2:	SB 53168
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004630331
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/18/2014
Trans1 Recv Date:	08/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/21/2014

CON EDISON (Continued) **S117315827**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004630331
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002615952GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

T187 **CLEO MANAGEMENT** **RCRA NonGen / NLR** **1004760555**
East **36-15 23RD ST** **FINDS** **NYR000049015**
1/8-1/4 **LONG ISLAND CITY, NY 11106** **ECHO**
0.130 mi.
685 ft. **Site 3 of 5 in cluster T**

Relative: **Higher**

Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Cleo Management
Handler Address:	36-15 23RD ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYR000049015
Contact Name:	EDMOND ARSENIAN
Contact Address:	32ND AVE
Contact City,State,Zip:	BAYSIDE, NY 11361
Contact Telephone:	718-956-1721
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported

CLEO MANAGEMENT (Continued) **1004760555**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	32ND AVE
Mailing City,State,Zip:	BAYSIDE, NY 11361
Owner Name:	Edmond Arsenian
Owner Type:	Private
Operator Name:	Edmond Arsenian
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

CLEO MANAGEMENT (Continued) **1004760555**

Hazardous Waste Summary:
Waste Code: D001
Waste Description: Ignitable Waste

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: EDMOND ARSENIAN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 202-03 32ND AVE
Owner/Operator City,State,Zip: BAYSIDE, NY 11361
Owner/Operator Telephone: 718-956-1721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: EDMOND ARSENIAN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 202-03 32ND AVE
Owner/Operator City,State,Zip: BAYSIDE, NY 11361
Owner/Operator Telephone: 718-956-1721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: EDMOND ARSENIAN
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 202-03 32ND AVE
Owner/Operator City,State,Zip: BAYSIDE, NY 11361
Owner/Operator Telephone: 718-956-1721
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CLEO MANAGEMENT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101

CLEO MANAGEMENT (Continued) **1004760555**

Handler Name: CLEO MANAGEMENT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980116
Handler Name: CLEO MANAGEMENT
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004539688

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004760555
Registry ID: 110004539688
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004539688
Name: CLEO MANAGEMENT

CLEO MANAGEMENT (Continued) **1004760555**

Address: 36-15 23RD ST
City,State,Zip: LONG ISLAND CITY, NY 11106

U188 **CON EDISON** **NY MANIFEST** **S117063102**
WNW **37-18 12TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.130 mi.
688 ft. **Site 1 of 3 in cluster U**

Relative:
Lower

Actual:
15 ft.

NY MANIFEST:
Name: CON EDISON
Address: 37-18 12TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004555041
Facility Status: Not reported
Location Address 1: 37-18 12TH ST
Code: BP
Location Address 2: SB 31067
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004555041
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193
Trans2 State ID: Not reported
Generator Ship Date: 06/05/2014
Trans1 Recv Date: 06/05/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/09/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004555041
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 013246185JJK
Import Indicator: N

CON EDISON (Continued) **S117063102**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

U189 **CON EDISON SERVICE BOX: 31060** **RCRA NonGen / NLR** **1017777607**
WNW **37-18 12TH ST** **FINDS** **NYP004555041**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.130 mi.
688 ft. **Site 2 of 3 in cluster U**

Relative: **Lower**

Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	20140705
Handler Name:	Con Edison Service Box: 31060
Handler Address:	37-18 12TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004555041
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2

CON EDISON SERVICE BOX: 31060 (Continued) **1017777607**

Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140605
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON SERVICE BOX: 31060 (Continued) **1017777607**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140605
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20140705
Handler Name: CON EDISON SERVICE BOX: 31060
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063818588

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

P190 **CITY AUTO SERVICE INC.** **NY AST** **A100429463**
SW **39-01 21ST STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.132 mi.
695 ft. **Site 4 of 8 in cluster P**

Relative:
Higher

Actual:
18 ft.

AST:

Name:	CITY AUTO SERVICE INC.
Address:	39-01 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-600273
Program Type:	PBS
UTM X:	589473.86654
UTM Y:	4512257.11811
Expiration Date:	03/12/2024
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	22256
Affiliation Type:	Facility Operator
Company Name:	PUNJAB AUTO CENTER - PUNJAB GASOLINE CORP
Contact Type:	Not reported
Contact Name:	MUNNAWAR HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-1114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-20

Site Id:	22256
Affiliation Type:	Emergency Contact
Company Name:	PETER LUPOLI ADMINISTRATOR CTA BOB ROSS
Contact Type:	Not reported
Contact Name:	MUNNAWAR HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 582-4463
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-20

Site Id:	22256
Affiliation Type:	Facility Owner
Company Name:	WOLFE REALTY LLC
Contact Type:	PRESIDENT
Contact Name:	MUNNAWAR HUSSAIN

CITY AUTO SERVICE INC. (Continued) **A100429463**

Address1:	167-16 NORTHERN BLVD
Address2:	Not reported
City:	FLUSHING
State:	NY
Zip Code:	11358
Country Code:	001
Phone:	(718) 392-1114
EMail:	MUNNAWAR786@ICLOUD.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-26

Site Id:	22256
Affiliation Type:	Mail Contact
Company Name:	WOLFE REALTY LLC
Contact Type:	PRESIDENT
Contact Name:	MUNNAWAR HUSSAIN
Address1:	167-16 NORTHERN BLVD
Address2:	Not reported
City:	FLUSHING
State:	NY
Zip Code:	11358
Country Code:	001
Phone:	(718) 392-1114
EMail:	MUNNAWAR786@ICLOUD.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-26

Tank Info:

Tank Number:	4
Tank Id:	264535

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
E00 - Piping Secondary Containment - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G10 - Tank Secondary Containment - Impervious Underlayment
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/22/2016
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

CITY AUTO SERVICE INC. (Continued) **A100429463**

Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/26/2022
Material Name:	waste oil/used oil

P191 **CITY AUTO SERVICE INC.** **NY UST** **U001841374**
SW **39-01 21ST STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.132 mi.
695 ft. **Site 5 of 8 in cluster P**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	CITY AUTO SERVICE INC.
Address:	39-01 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-600273 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/12/2024
UTM X:	589473.86654
UTM Y:	4512257.11811
Site Type:	Retail Gasoline Sales

Affiliation Records:

Site Id:	22256
Affiliation Type:	Facility Operator
Company Name:	PUNJAB AUTO CENTER - PUNJAB GASOLINE CORP
Contact Type:	Not reported
Contact Name:	MUNNAWAR HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-1114
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY
Date Last Modified:	2016-10-20

Site Id:	22256
Affiliation Type:	Emergency Contact
Company Name:	PETER LUPOLI ADMINISTRATOR CTA BOB ROSS
Contact Type:	Not reported
Contact Name:	MUNNAWAR HUSSAIN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 582-4463
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MXLAY

CITY AUTO SERVICE INC. (Continued) **U001841374**

Date Last Modified: 2016-10-20

Site Id: 22256
Affiliation Type: Facility Owner
Company Name: WOLFE REALTY LLC
Contact Type: PRESIDENT
Contact Name: MUNNAWAR HUSSAIN
Address1: 167-16 NORTHERN BLVD
Address2: Not reported
City: FLUSHING
State: NY
Zip Code: 11358
Country Code: 001
Phone: (718) 392-1114
EMail: MUNNAWAR786@ICLOUD.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-09-26

Site Id: 22256
Affiliation Type: Mail Contact
Company Name: WOLFE REALTY LLC
Contact Type: PRESIDENT
Contact Name: MUNNAWAR HUSSAIN
Address1: 167-16 NORTHERN BLVD
Address2: Not reported
City: FLUSHING
State: NY
Zip Code: 11358
Country Code: 001
Phone: (718) 392-1114
EMail: MUNNAWAR786@ICLOUD.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-09-26

Tank Info:

Tank Number: 001
Tank ID: 41764
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

CITY AUTO SERVICE INC. (Continued) **U001841374**

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	002
Tank ID:	41765
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None

Tank Number:	003
Tank ID:	41766
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

CITY AUTO SERVICE INC. (Continued) **U001841374**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 004
Tank ID: 41767
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 005
Tank ID: 41768
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999

CITY AUTO SERVICE INC. (Continued) **U001841374**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 006
Tank ID: 41769
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 007

CITY AUTO SERVICE INC. (Continued) **U001841374**

Tank ID:	41770
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number:	008
Tank ID:	41771
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None

CITY AUTO SERVICE INC. (Continued) **U001841374**

J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

Tank Number:	009
Tank ID:	41772
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	010
Tank ID:	41773
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	10/01/1965
Date Tank Closed:	01/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

CITY AUTO SERVICE INC. (Continued) **U001841374**

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 011
Tank ID: 41774
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None

Tank Number: 012
Tank ID: 41775
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: 01/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: NN
Date Test: Not reported

CITY AUTO SERVICE INC. (Continued) **U001841374**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 013
Tank ID: 41776
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 550
Install Date: 10/01/1965
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 34
Date Test: 03/02/2022
Next Test Date: 03/02/2023
Pipe Model: Not reported
Modified By: TankSys
Last Modified: 12/15/2022

Equipment Records:

J04 - Dispenser - On Site Heating System (Suction)
I05 - Overfill - Vent Whistle
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping

Tank Number: 014
Tank ID: 255409
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 10/01/1965

CITY AUTO SERVICE INC. (Continued) **U001841374**

Date Tank Closed:	09/21/2016
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	21
Date Test:	04/16/2015
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

J00 - Dispenser - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
I05 - Overfill - Vent Whistle
G00 - Tank Secondary Containment - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number:	1
Tank ID:	57794
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	4000
Install Date:	01/01/2000
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Fiberglass coated steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	09/26/2022

Equipment Records:

D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F05 - Pipe External Protection - Jacketed
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
B04 - Tank External Protection - Fiberglass

CITY AUTO SERVICE INC. (Continued) **U001841374**

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L07 - Piping Leak Detection - Pressurized Piping Leak Detector

Tank Number: 2
Tank ID: 57795
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
L07 - Piping Leak Detection - Pressurized Piping Leak Detector
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
F05 - Pipe External Protection - Jacketed

Tank Number: 3
Tank ID: 57796
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 4000
Install Date: 01/01/2000
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Fiberglass coated steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported

CITY AUTO SERVICE INC. (Continued) **U001841374**

Pipe Model: Not reported
Modified By: JSMACRI
Last Modified: 09/26/2022

Equipment Records:

L07 - Piping Leak Detection - Pressurized Piping Leak Detector
D11 - Pipe Type - Flexible Piping
G04 - Tank Secondary Containment - Double-Walled (Underground)
B04 - Tank External Protection - Fiberglass
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
C02 - Pipe Location - Underground/On-ground
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
E04 - Piping Secondary Containment - Double walled UG
J01 - Dispenser - Pressurized Dispenser
A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
I03 - Overfill - Automatic Shut-Off
F05 - Pipe External Protection - Jacketed

S192 **TRI STAR LUMBER CORP** **NY UST** **U000408353**
ESE **37-01 24TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.135 mi.
711 ft. **Site 2 of 4 in cluster S**

Relative:
Higher

Actual:
21 ft.

UST:
Name: TRI STAR LUMBER CORP
Address: 37-01 24TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-339407 / Inactive
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589855.39975
UTM Y: 4512358.06221
Site Type: Other Wholesale/Retail Sales

Affiliation Records:
Site Id: 16351
Affiliation Type: Facility Owner
Company Name: ALFRED HARNON BERNARD HARNON
Contact Type: Not reported
Contact Name: Not reported
Address1: 445 NORTHERN BLVD
Address2: Not reported
City: GREAT NECK
State: NY
Zip Code: 11021
Country Code: 001
Phone: (516) 466-9110
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 16351
Affiliation Type: Mail Contact

TRI STAR LUMBER CORP (Continued) **U000408353**

Company Name:	TRI STAR LUMBER CORP
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	37-01 24TH ST.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-3344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16351
Affiliation Type:	Facility Operator
Company Name:	TRI STAR LUMBER CORP
Contact Type:	Not reported
Contact Name:	TRI STAR LUMBER CORP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-3344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	16351
Affiliation Type:	Emergency Contact
Company Name:	ALFRED HARNON BERNARD HARNON
Contact Type:	Not reported
Contact Name:	ALLIED HARMON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 481-2002
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	30986
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	2000
Install Date:	Not reported

TRI STAR LUMBER CORP (Continued) **U000408353**

Date Tank Closed:	10/01/1999
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
D00 - Pipe Type - No Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

O193 **DRAPEMASTERS OF AMERICA INC** **RCRA-VSQG** **1010787316**
NNW **36-02 13TH ST** **NYN008017998**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.135 mi.
714 ft. **Site 3 of 3 in cluster O**

Relative: **Lower**
Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	20080201
Handler Name:	Drapemasters Of America Inc
Handler Address:	36-02 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYN008017998
Contact Name:	PETER ROUMEL
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11106
Contact Telephone:	718-446-6666
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported

DRAPEMASTERS OF AMERICA INC (Continued) **1010787316**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20080219
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D009
Waste Description:	Mercury

Historic Generators:

Receive Date:	20080201
Handler Name:	DRAPEMASTERS OF AMERICA INC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

DRAPEMASTERS OF AMERICA INC (Continued) **1010787316**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20080131
Handler Name: DRAPEMASTERS OF AMERICA INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported

DRAPEMASTERS OF AMERICA INC (Continued) **1010787316**

Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20070925
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

T194 **VACANT INDUSTRIAL PROPERTIES** **NY UST** **U003241879**
ENE **36-15 23RD STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11102**
0.136 mi.
718 ft. **Site 4 of 5 in cluster T**

Relative:
Higher

Actual:
18 ft.

UST:

Name:	VACANT INDUSTRIAL PROPERTIES
Address:	36-15 23RD STREET
City,State,Zip:	LONG ISLAND CITY, NY 11102
Id/Status:	2-603201 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589866.68372
UTM Y:	4512534.39423
Site Type:	Other

Affiliation Records:

Site Id:	25137
Affiliation Type:	Facility Owner
Company Name:	CLEO MANAGEMENT, INC.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	202-03 32ND AVENUE
Address2:	Not reported
City:	BAYSIDE
State:	NY
Zip Code:	11361
Country Code:	001
Phone:	(718) 956-1721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25137
Affiliation Type:	Mail Contact

VACANT INDUSTRIAL PROPERTIES (Continued) **U003241879**

Company Name:	CLEO MANAGEMENT, INC.
Contact Type:	Not reported
Contact Name:	MR. EDMOND ARSENIAN
Address1:	202-03 32ND AVENUE
Address2:	Not reported
City:	BAYSIDE
State:	NY
Zip Code:	11361
Country Code:	001
Phone:	(718) 956-1721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25137
Affiliation Type:	Facility Operator
Company Name:	VACANT INDUSTRIAL PROPERTIES
Contact Type:	Not reported
Contact Name:	MR. EDMOND ARSENIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 956-1721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	25137
Affiliation Type:	Emergency Contact
Company Name:	CLEO MANAGEMENT, INC.
Contact Type:	Not reported
Contact Name:	MR. EDMOND ARSENIAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 956-1721
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	53455
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1000
Install Date:	Not reported

VACANT INDUSTRIAL PROPERTIES (Continued) **U003241879**

Date Tank Closed:	10/01/1997
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
I00 - Overfill - None
H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

S195 **HEPHAISTOS BUILDING SUPPLIES** **NY UST** **U003697810**
ESE **24-02 37TH AVENUE** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.136 mi.
719 ft. **Site 3 of 4 in cluster S**

Relative:
Higher

Actual:
20 ft.

UST:

Name:	HEPHAISTOS BUILDING SUPPLIES
Address:	24-02 37TH AVENUE
City,State,Zip:	QUEENS, NY 11106
Id/Status:	2-604236 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	09/22/2024
UTM X:	589857.07886
UTM Y:	4512364.18907
Site Type:	Other Wholesale/Retail Sales

Affiliation Records:

Site Id:	26116
Affiliation Type:	Facility Owner
Company Name:	MICHAEL KARANTINIDIS
Contact Type:	PRESIDENT
Contact Name:	MICHAEL KARANTINIDIS
Address1:	24-02 37TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 726-2226
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG

HEPHAISTOS BUILDING SUPPLIES (Continued) **U003697810**

Date Last Modified: 2004-09-30

Site Id: 26116
Affiliation Type: Mail Contact
Company Name: HEPHAISTOS BUILDING SUPPLIES
Contact Type: Not reported
Contact Name: MICHAEL KARANTINIDIS
Address1: 34-01 BROADWAY
Address2: Not reported
City: ASTORIA
State: NY
Zip Code: 11105
Country Code: 001
Phone: (718) 726-2226
EMail: INTERNATIONALGEO@GMAIL.COM
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2020-06-05

Site Id: 26116
Affiliation Type: Facility Operator
Company Name: HEPHAISTOS BUILDING SUPPLIES
Contact Type: Not reported
Contact Name: MICHAEL KARANTINIDIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 482-0800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 26116
Affiliation Type: Emergency Contact
Company Name: MICHAEL KARANTINIDIS
Contact Type: Not reported
Contact Name: MICHAEL KARANTINIDIS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 482-0800
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 001
Tank ID: 57056

HEPHAISTOS BUILDING SUPPLIES (Continued) **U003697810**

Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	2000
Install Date:	09/30/2004
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None

R196 **38-24 24 ST. LLC** **NY AST** **A100296211**
SSE **38-24 24TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.139 mi.
735 ft. **Site 10 of 11 in cluster R**

Relative:
Higher

Actual:
20 ft.

AST:

Name:	38-24 24 ST. LLC
Address:	38-24 24TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609203
Program Type:	PBS
UTM X:	589738.89827
UTM Y:	4512212.39959
Expiration Date:	01/05/2025
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	31048
Affiliation Type:	Mail Contact
Company Name:	24 ST. LEGACY AUTO
Contact Type:	Not reported
Contact Name:	AMJAD IQBAL
Address1:	38-24 24TH STREET
Address2:	Not reported

38-24 24 ST. LLC (Continued) **A100296211**

City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-4978
EMail:	AMJADIGBA786@GMAIL.COM
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-10-29

Site Id:	31048
Affiliation Type:	Facility Operator
Company Name:	BIG SUPER PUNJAB AUTO INC
Contact Type:	Not reported
Contact Name:	AMJAD IQBAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 902-8232
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-03-04

Site Id:	31048
Affiliation Type:	Emergency Contact
Company Name:	BIG SUPER PUNJAB AUTO INC
Contact Type:	Not reported
Contact Name:	AMJAD IQBAL
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(347) 944-3449
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-10-29

Site Id:	31048
Affiliation Type:	Facility Owner
Company Name:	38-24 24 ST. LLC
Contact Type:	PARTNER
Contact Name:	AMJAD IQBAL
Address1:	38-24 24 STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-4978
EMail:	Not reported

38-24 24 ST. LLC (Continued) **A100296211**

Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2020-10-29

Tank Info:

Tank Number:	001
Tank Id:	66769
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
J00 - Dispenser - None
I04 - Overfill - Product Level Gauge (A/G)
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
E00 - Piping Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	200
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Q197 **ENGINE COMPANY 260** **NY AST** **A100194022**
NW **11-15 37TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.142 mi.
750 ft. **Site 3 of 4 in cluster Q**

Relative: **Lower**
Actual: **15 ft.**

AST:

Name:	ENGINE COMPANY 260
Address:	11-15 37TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-600525
Program Type:	PBS
UTM X:	589421.09656
UTM Y:	4512626.03610

ENGINE COMPANY 260 (Continued) **A100194022**

Expiration Date: N/A
Site Type: Other

Affiliation Records:
Site Id: 22506
Affiliation Type: Mail Contact
Company Name: FIRE DEPARTMENT
Contact Type: Not reported
Contact Name: DIRECTOR; BLDGS MAINT DIV
Address1: 48-34 35TH STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 784-6510
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 22506
Affiliation Type: Facility Operator
Company Name: ENGINE COMPANY 260
Contact Type: Not reported
Contact Name: COMPANY OFFICER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 476-6260
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 22506
Affiliation Type: Facility Owner
Company Name: F.D.N.Y.
Contact Type: Not reported
Contact Name: Not reported
Address1: 9 METROTECH
Address2: Not reported
City: BROOKLYN
State: NY
Zip Code: 11201-3857
Country Code: 001
Phone: (718) 999-2094
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 22506
Affiliation Type: Emergency Contact
Company Name: F.D.N.Y.

ENGINE COMPANY 260 (Continued) **A100194022**

Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	001
Tank Id:	42909
Material Code:	0008
Common Name of Substance:	Diesel

Equipment Records:

H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D00 - Pipe Type - No Piping
I05 - Overfill - Vent Whistle

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/1978
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	diesel

Q198 **ENGINE COMPANY 260** **NY UST** **U004081900**
NW **11-15 37TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.142 mi.
750 ft. **Site 4 of 4 in cluster Q**

Relative:
Lower

Actual:
15 ft.

UST:

Name:	ENGINE COMPANY 260
Address:	11-15 37TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-600525 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589421.09656
UTM Y:	4512626.03610
Site Type:	Other

Affiliation Records:

Site Id:	22506
Affiliation Type:	Mail Contact
Company Name:	FIRE DEPARTMENT
Contact Type:	Not reported
Contact Name:	DIRECTOR; BLDGS MAINT DIV
Address1:	48-34 35TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-6510
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22506
Affiliation Type:	Facility Operator
Company Name:	ENGINE COMPANY 260
Contact Type:	Not reported
Contact Name:	COMPANY OFFICER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 476-6260
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22506
Affiliation Type:	Facility Owner
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	9 METROTECH

ENGINE COMPANY 260 (Continued) **U004081900**

Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11201-3857
Country Code:	001
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	22506
Affiliation Type:	Emergency Contact
Company Name:	F.D.N.Y.
Contact Type:	Not reported
Contact Name:	EOC/NOTIFICATION DESK
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 999-2094
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-01-07

Tank Info:

Tank Number:	002
Tank ID:	42910
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2500
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

ENGINE COMPANY 260 (Continued) **U004081900**

C00 - Pipe Location - No Piping
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	54457
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	275
Install Date:	Not reported
Date Tank Closed:	02/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

199
ENE
1/8-1/4
0.143 mi.
757 ft.

CONSOLIDATED EDISON
V2253-43-23 36TH AVENUE
QUEENS, NY 11428

NY MANIFEST **1009236481**
N/A

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	V2253-43-23 36TH AVENUE
City,State,Zip:	QUEENS, NY 11428
Country:	USA
EPA ID:	NYP004016408
Facility Status:	Not reported
Location Address 1:	V2253-43-23 36TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11428
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004016408

CONSOLIDATED EDISON (Continued) **1009236481**

Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

M200 **ADVANCE AUTO ELECTRIC LTD** **RCRA NonGen / NLR** **1000872560**
SSE **38-01 24TH ST** **FINDS** **NYD987037744**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.143 mi. **NY MANIFEST**
757 ft. **Site 5 of 6 in cluster M**

Relative: **Higher**
Actual: **26 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Advance Auto Electric Ltd
Handler Address:	38-01 24TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD987037744
Contact Name:	EDWARD SCHNITZLER
Contact Address:	24TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-361-1645
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	24TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Advance Auto Electric Ltd
Owner Type:	Private
Operator Name:	Advance Auto Electric Ltd
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

ADVANCE AUTO ELECTRIC LTD (Continued) **1000872560**

Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: ADVANCE AUTO ELECTRIC LTD	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-01 24TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-361-1645
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ADVANCE AUTO ELECTRIC LTD	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-01 24TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-361-1645
Owner/Operator Telephone Ext:	Not reported

ADVANCE AUTO ELECTRIC LTD (Continued) **1000872560**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ADVANCE AUTO ELECTRIC LTD
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 38-01 24TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-361-1645
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: ADVANCE AUTO ELECTRIC LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ADVANCE AUTO ELECTRIC LTD
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930720
Handler Name: ADVANCE AUTO ELECTRIC LTD
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

ADVANCE AUTO ELECTRIC LTD (Continued) **1000872560**

NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19980818
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

ADVANCE AUTO ELECTRIC LTD (Continued) **1000872560**

FINDS:
Registry ID: 110004506847

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000872560
Registry ID:	110004506847
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004506847
Name:	ADVANCE AUTO ELECTRIC LTD
Address:	38-01 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	ADVANCE ELECTRIC
Address:	38-01 24TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYD987037744
Facility Status:	Not reported
Location Address 1:	38-01 24TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987037744
Mailing Name:	ADVANCE ELECTRIC
Mailing Contact:	EDWARD SCHNITZER
Mailing Address 1:	38-01 24TH ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183611645

R201 **CON EDISON** **NY MANIFEST** **S117318763**
South **OPP 23-02 39 AV** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.144 mi.
762 ft. **Site 11 of 11 in cluster R**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	OPP 23-02 39 AV
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004663365
Facility Status:	Not reported
Location Address 1:	OPP 23-02 39 AV
Code:	BP
Location Address 2:	SB54982
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004663365
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	NJD003812047
Generator Ship Date:	09/22/2014
Trans1 Recv Date:	09/22/2014
Trans2 Recv Date:	09/24/2014
TSD Site Recv Date:	09/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004663365
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002617522GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117318763**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

P202 **PEP BOYS #0437** **NY CBS S108410819**
SW **3850 21ST ST** **NY AST N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.145 mi.
768 ft. **Site 6 of 8 in cluster P**

Relative:
Higher

Actual:
17 ft.

CBS:

Name:	PEP BOYS #0437
Address:	3850 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
CBS Number:	2-000421
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	589506.31660
UTMY:	4512323.45192

AST:

Name:	PEP BOYS #0437
Address:	3850 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-000421
Program Type:	CBS
UTM X:	589506.31660
UTM Y:	4512323.45192
Expiration Date:	N/A
Site Type:	Other Wholesale/Retail Sales

PEP BOYS #0437 (Continued) **S108410819**

Tank Info:

Tank Number:	2
Tank Id:	207216
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/21/1997
Capacity Gallons:	280
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	10/29/2005
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	Not reported

P203 **AMAZON.COM SERVICES LLC - ZYO1** **RCRA NonGen / NLR** **1026498329**
SW **38-50 21ST ST** **NYR000033902**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.145 mi.
768 ft. **Site 7 of 8 in cluster P**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20220829
Handler Name:	Amazon.Com Services Llc - Zyo1
Handler Address:	38-50 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000033902
Contact Name:	PAUL WILSON
Contact Address:	PO BOX 80842
Contact City,State,Zip:	SEATTLE, WA 98108
Contact Telephone:	951-445-7785
Contact Fax:	Not reported
Contact Email:	PAULRWIL@AMAZON.COM
Contact Title:	NA ENVIRONMENTAL LEADER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PO BOX 80842
Mailing City,State,Zip:	SEATTLE, WA 98108
Owner Name:	Queens Plaza Venture, Llc
Owner Type:	Private
Operator Name:	Amazon.Com Services Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

AMAZON.COM SERVICES LLC - ZYO1 (Continued) **1026498329**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220831
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium

AMAZON.COM SERVICES LLC - ZYO1 (Continued) **1026498329**

Waste Code: D008
Waste Description: Lead

Waste Code: D009
Waste Description: Mercury

Waste Code: D010
Waste Description: Selenium

Waste Code: D011
Waste Description: Silver

Waste Code: D016
Waste Description: 2,4-D (2,4-Dichlorophenoxyacetic Acid)

Waste Code: D018
Waste Description: Benzene

Waste Code: D024
Waste Description: M-Cresol

Waste Code: D027
Waste Description: 1,4-Dichlorobenzene

Waste Code: D035
Waste Description: Methyl Ethyl Ketone

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U159
Waste Description: 2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)

Waste Code: U205
Waste Description: Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: AMAZON.COM SERVICES LLC
Legal Status: Private
Date Became Current: 20201103
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 80842
Owner/Operator City,State,Zip: SEATTLE, WA 98108
Owner/Operator Telephone: 206-266-1036
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: AMAZON-EAP-NORTHAMERICA@AMAZON.COM

Owner/Operator Indicator: Operator

AMAZON.COM SERVICES LLC - ZYO1 (Continued) **1026498329**

Owner/Operator Name: AMAZON.COM SERVICES LLC
Legal Status: Private
Date Became Current: 20201103
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 80842
Owner/Operator City,State,Zip: SEATTLE, WA 98108
Owner/Operator Telephone: 469-400-4322
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: AMAZON-EAP-NORTHAMERICA@AMAZON.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-227-9193
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-227-9193
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: QUEENS PLAZA VENTURE, LLC
Legal Status: Private
Date Became Current: 20200221
Date Ended Current: Not reported
Owner/Operator Address: 112-15 NORTHERN BLVD., SUITE CF2
Owner/Operator City,State,Zip: CORONA, NY 11368
Owner/Operator Telephone: 646-508-5218
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: DAVID@UNITEDGROUPNY.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: THE PEP BOYS - MANNY MOE & JACK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 3111 W ALLEGHENY AVE
Owner/Operator City,State,Zip: PHILADELPHIA, PA 19132
Owner/Operator Telephone: 215-227-9193
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

AMAZON.COM SERVICES LLC - ZYO1 (Continued) **1026498329**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: QUEENS PLAZA VENTURE, LLC
Legal Status: Private
Date Became Current: 20200221
Date Ended Current: Not reported
Owner/Operator Address: 112-15 NORTHERN BLVD., SUITE CF2
Owner/Operator City,State,Zip: CORONA, NY 11368
Owner/Operator Telephone: 646-508-5218
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: DAVID@UNITEDGROUPNY.COM

Historic Generators:
Receive Date: 20220829
Handler Name: AMAZON.COM SERVICES LLC - ZYO1
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 20060101
Handler Name: PEP BOYS #437
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: PEP BOYS #437
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970106
Handler Name: PEP BOYS #437
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator

AMAZON.COM SERVICES LLC - ZYO1 (Continued) **1026498329**

State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20200929
Handler Name:	AMAZON.COM SERVICES LLC - ZYO1
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	493110
NAICS Description:	GENERAL WAREHOUSING AND STORAGE

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

M204 **P & A AUTO SERVICE, INC.** **NY AST** **A100295415**
SSE **38-09 24TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.147 mi.
774 ft. **Site 6 of 6 in cluster M**

Relative:
Higher

Actual:
25 ft.

AST:

Name:	P & A AUTO SERVICE, INC.
Address:	38-09 24TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609145
Program Type:	PBS
UTM X:	589761.35145
UTM Y:	4512223.18113
Expiration Date:	07/24/2023
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	30991
Affiliation Type:	Emergency Contact

P & A AUTO SERVICE, INC. (Continued) **A100295415**

Company Name:	P & A AUTO SERVICE, INC.
Contact Type:	Not reported
Contact Name:	PAOLO MANGINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 706-6059
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-05-29

Site Id:	30991
Affiliation Type:	Facility Operator
Company Name:	P & A AUTO SERVICE, INC.
Contact Type:	Not reported
Contact Name:	PAOLO MANGINO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 706-6059
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-05-29

Site Id:	30991
Affiliation Type:	Mail Contact
Company Name:	P & A AUTO SERVICE, INC.
Contact Type:	Not reported
Contact Name:	MR. PAOLO MANGINO
Address1:	38-09 24TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-6059
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-05-29

Site Id:	30991
Affiliation Type:	Facility Owner
Company Name:	P & A AUTO SERVICE, INC.
Contact Type:	PRESIDENT
Contact Name:	PAOLO MANGINO
Address1:	38-09 24TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY

P & A AUTO SERVICE, INC. (Continued) **A100295415**

State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 706-6059
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMMOLOUG
Date Last Modified:	2013-05-29

Tank Info:

Tank Number:	001
Tank Id:	66582
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

	F00 - Pipe External Protection - None
	I01 - Overfill - Float Vent Valve
	K00 - Spill Prevention - None
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	H00 - Tank Leak Detection - None
	E00 - Piping Secondary Containment - None
	L00 - Piping Leak Detection - None
	D00 - Pipe Type - No Piping
	G00 - Tank Secondary Containment - None
	J00 - Dispenser - None
	C01 - Pipe Location - Aboveground
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/24/2002
Capacity Gallons:	258
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

V205 **KTR LAUNDRY & DRY CLEANING** **NY DRYCLEANERS** **S128782082**
WSW **38-38 13TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.148 mi.
779 ft. **Site 1 of 16 in cluster V**

Relative: **Lower**
Actual: **16 ft.**

DRYCLEANERS:

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327

KTR LAUNDRY & DRY CLEANING (Continued) **S128782082**

Region:	Not reported
Registration Effective Date:	2004-11-15 13:59:50
Inspection Date:	2007-11-01 08:00:00
Install Date:	Not reported
Expiration Date:	11/25/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2008-11-25 17:25:24
Inspection Date:	2010-11-29 08:00:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2004-11-15 13:59:50
Inspection Date:	2006-11-09 08:20:00
Install Date:	Not reported
Expiration Date:	11/25/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2004-11-15 13:59:50
Inspection Date:	2005-11-09 08:00:00
Install Date:	Not reported
Expiration Date:	11/25/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported

KTR LAUNDRY & DRY CLEANING (Continued) **S128782082**

Current Business: Not reported

Name: KTR LAUNDRY & DRY CLEANING
Address: 38-38 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01501
Phone Number: 2123197327
Region: Not reported
Registration Effective Date: 2004-11-15 13:59:50
Inspection Date: 2004-11-05 08:00:00
Install Date: Not reported
Expiration Date: 11/25/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: KTR LAUNDRY & DRY CLEANING
Address: 38-38 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01501
Phone Number: 2123197327
Region: Not reported
Registration Effective Date: 2008-11-25 17:25:24
Inspection Date: 2009-12-29 07:50:00
Install Date: Not reported
Expiration Date: 04/10/2013
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: KTR LAUNDRY & DRY CLEANING
Address: 38-38 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01501
Phone Number: 2123197327
Region: Not reported
Registration Effective Date: 2004-11-15 13:59:50
Inspection Date: 2008-12-10 14:00:00
Install Date: Not reported
Expiration Date: 11/25/2008
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: KTR LAUNDRY & DRY CLEANING
Address: 38-38 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01501
Phone Number: 2123197327
Region: Not reported
Registration Effective Date: 2008-11-25 17:25:24

KTR LAUNDRY & DRY CLEANING (Continued) **S128782082**

Inspection Date:	2007-11-01 08:00:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2008-11-25 17:25:24
Inspection Date:	2006-11-09 08:20:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2008-11-25 17:25:24
Inspection Date:	2005-11-09 08:00:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2008-11-25 17:25:24
Inspection Date:	2004-11-05 08:00:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

KTR LAUNDRY & DRY CLEANING (Continued) **S128782082**

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2004-11-15 13:59:50
Inspection Date:	2010-11-29 08:00:00
Install Date:	Not reported
Expiration Date:	11/25/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2004-11-15 13:59:50
Inspection Date:	2009-12-29 07:50:00
Install Date:	Not reported
Expiration Date:	11/25/2008
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01501
Phone Number:	2123197327
Region:	Not reported
Registration Effective Date:	2008-11-25 17:25:24
Inspection Date:	2008-12-10 14:00:00
Install Date:	Not reported
Expiration Date:	04/10/2013
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

V206 **MIDNIGHT EXPRESS** **RCRA-SQG** **1000552963**
WSW **38-38 13TH ST** **ICIS** **NYD986953693**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **US AIRS**
0.148 mi. **FINDS**
779 ft. **Site 2 of 16 in cluster V** **ECHO**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Midnight Express
Handler Address:	38-38 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD986953693
Contact Name:	Not reported
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Midnight Express
Owner Type:	Private
Operator Name:	Midnight Express
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

MIDNIGHT EXPRESS (Continued) **1000552963**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MIDNIGHT EXPRESS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: MIDNIGHT EXPRESS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

MIDNIGHT EXPRESS (Continued) **1000552963**

Owner/Operator Indicator: Operator
Owner/Operator Name: MIDNIGHT EXPRESS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: MIDNIGHT EXPRESS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: MIDNIGHT EXPRESS
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: MIDNIGHT EXPRESS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19910509
Handler Name: MIDNIGHT EXPRESS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

MIDNIGHT EXPRESS (Continued) **1000552963**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20000817
Actual Return to Compliance Date: 20001113
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20001013
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2CFP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20000817
Actual Return to Compliance Date: 20001113
Return to Compliance Qualifier: Documented

MIDNIGHT EXPRESS (Continued) **1000552963**

Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20001026
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	R2CFP
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported

MIDNIGHT EXPRESS (Continued) **1000552963**

SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20000817
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2CFP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20001113
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20000817
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2CFP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20001113
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 19960227
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2AHJ
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

ICIS:
Enforcement Action ID: NY000A0000263040150100307

MIDNIGHT EXPRESS (Continued) **1000552963**

FRS ID:	110004467416
Action Name:	KTR LAUNDRY & DRY CLEANING 36081R336400307
Facility Name:	KTR LAUNDRY & DRY CLEANING
Facility Address:	38-38 13TH ST LONG ISLAND CITY, NY 111016120
Enforcement Action Type:	Notice of Violation
Facility County:	QUEENS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.75738
Longitude in Decimal Degrees:	-73.940417
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002630401501
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000552963
Region Code:	02
Programmatic ID:	AIR NY0000002630401501
Facility Registry ID:	110004467416
D and B Number:	Not reported
Primary SIC Code:	7216
NAICS Code:	812320
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	02
Programmatic ID:	AIR NY0000002630401501
Facility Registry ID:	110004467416
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2004-11-16 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	02
Programmatic ID:	AIR NY0000002630401501
Facility Registry ID:	110004467416
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2007-08-24 00:00:00
Activity Status Date:	2007-08-24 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

MIDNIGHT EXPRESS (Continued) **1000552963**

Region Code:	02
Programmatic ID:	AIR NY0000002630401501
Facility Registry ID:	110004467416
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2004-11-16 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:
Registry ID: 110004467416

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000552963
Registry ID:	110004467416
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004467416
Name:	KTR LAUNDRY & DRY CLEANING
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

V207 **MIDNIGHT EXPRESS** **NY MANIFEST** **S117563024**
WSW **38-38 13TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.148 mi.
779 ft. **Site 3 of 16 in cluster V**

Relative:
Lower

Actual:
16 ft.

NY MANIFEST:

Name:	MIDNIGHT EXPRESS
Address:	38-38 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYD986953693
Facility Status:	Not reported
Location Address 1:	3838 13TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986953693
Mailing Name:	MIDNIGHT EXPRESS
Mailing Contact:	ROBERT
Mailing Address 1:	3838 13TH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY QUEENS
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183929200

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	10/26/2006
Trans1 Recv Date:	10/26/2006
Trans2 Recv Date:	11/03/2006
TSD Site Recv Date:	11/06/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986953693
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	000106305CEX
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

MIDNIGHT EXPRESS (Continued) **S117563024**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	320
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D039
Waste Code 1_4:	D040
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V208 **38-21 12TH STREET** **RCRA-LQG** **1000208587**
WSW **38-21 12TH STREET** **NY MANIFEST** **NYD003401205**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.149 mi.
788 ft. **Site 4 of 16 in cluster V**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20210430
Handler Name:	38-21 12th Street
Handler Address:	38-21 12TH STREET
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD003401205
Contact Name:	JOHN P DIGGINS IV
Contact Address:	PARK AVENUE SOUTH
Contact City,State,Zip:	NEW YORK, NY 10016
Contact Telephone:	646-388-9784
Contact Fax:	Not reported
Contact Email:	JDIGGINS@AKRF.COM
Contact Title:	TECHNICAL DIRECTOR
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PARK AVENUE SOUTH
Mailing City,State,Zip:	NEW YORK, NY 10016
Owner Name:	Tfc 38-21 Twelfth Llc
Owner Type:	Private

38-21 12TH STREET (Continued) **1000208587**

Operator Name:	Tfc 38-21 Twelfth Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	Yes
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20210501
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: HARSCO CORP	
Legal Status:	Private
Date Became Current:	Not reported

38-21 12TH STREET (Continued) **1000208587**

Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: TFC 38-21 TWELFTH LLC	
Legal Status:	Private
Date Became Current:	20180109
Date Ended Current:	Not reported
Owner/Operator Address:	387 PARK AVENUE SOUTH
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-984-1743
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	BRIAN.MILLS@TFCORNERSTONE.COM
Owner/Operator Indicator:	Owner
Owner/Operator Name: HARSCO CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: HARSCO CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: TFC 38-21 TWELFTH LLC	
Legal Status:	Private
Date Became Current:	20180109
Date Ended Current:	Not reported
Owner/Operator Address:	387 PARK AVENUE SOUTH
Owner/Operator City,State,Zip:	NEW YORK, NY 10016
Owner/Operator Telephone:	212-984-1743
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	BRIAN.MILLS@TFCORNERSTONE.COM

38-21 12TH STREET (Continued) **1000208587**

Historic Generators:

Receive Date:	19990708
Handler Name:	PATENT SCAFFOLDING CO HARSCO CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	PATENT SCAFFOLDING CO HARSCO CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	PATENT SCAFFOLDING CO HARSCO CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19821027
Handler Name:	PATENT SCAFFOLDING CO HARSCO CORP
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20210430
Handler Name:	38-21 12TH STREET
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny

38-21 12TH STREET (Continued) **1000208587**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	562910
NAICS Description:	REMEDIATION SERVICES

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	PATENT SCAFFOLDING COMPANY
Address:	38-21 12TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101-6115
Country:	USA
EPA ID:	NYD003401205
Facility Status:	Not reported
Location Address 1:	38-21 12TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD003401205
Mailing Name:	PATENT SCAFFOLDING COMPANY
Mailing Contact:	PATENT SCAFFOLDING COMPANY
Mailing Address 1:	HARSCO CORP=38-21 12TH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183611866

V209 **DOT RELOCATION SITE** **NY BROWNFIELDS** **S122449236**
WSW **38-21 12TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.149 mi.
788 ft. **Site 5 of 16 in cluster V**

Relative: **Lower**
Actual: **16 ft.**

BROWNFIELDS:

Name:	DOT RELOCATION SITE
Address:	38-21 12TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	569681
Acres:	1.610
HW Code:	C241213
SWIS:	4101
Town:	New York City
Record Added Date:	05/02/2018
Record Updated Date:	11/29/2022
Update By:	HMDUDEK
Site Description:	"LOCATION The site is located at 38-21 12th Street and includes the addresses 38-01 12th Street through 38-33 12th Street, 38-02 13th Street through 38-36 13th Street, and 12-02 38th Avenue through 12-20 38th Avenue. The site is located in the Long Island City section of Queens, NY. The site consists of one tax lot on an approximately 70,200-sf (1.6 acre) parcel. The site is bounded to the northwest by 38th Avenue, followed by a taxi garage; to the northeast by 38th Avenue, followed by a scaffolding manufacturer; to the east by a 13th Street, followed by an auto body and paint shop, car wash and parking lot; to the south by an auto repair shop and church; and to the west by 12th Street, followed by a commercial building, scaffolding company, and a construction site. SITE FEATURES The site contains three one-story buildings, constructed around 1936, and two partially covered parking lots. The site is currently vacant but was recently occupied by commercial and industrial businesses including: a pipe fitting shop, two leased commercial parking lots, a marble and granite fabricator, a carpentry shop, and a commercial kitchen. CURRENT ZONING AND LAND USE The current zoning designation of the site is M1-3 (manufacturing district). The surrounding area is largely developed with industrial and commercial uses with residential and commercial uses located to the south and east. The site has an open spill number (0413143) related to petroleum contamination. PAST USE OF THE SITE The site has had numerous historical commercial, industrial, and automotive uses. The site was a rag shop in 1915 and was developed in 1936 with three one-story buildings that were operated by Chesebro-Whitman Co. Inc. as a wood working facility. In 1970, Chesebro-Whitman Co. Inc. became a scaffolding manufacturing and repair facility, and on-site uses changed to include a metal workshop, with a garage and gasoline tank. An office and a storage area were also constructed in the former vacant parcel on the southern portion of the site in 1970. SITE GEOLOGY AND HYDROLOGY The site is approximately 15 feet above mean sea level. Groundwater is present at the site between approximately 8 and 10 feet below sidewalk grade and flows in a southwesterly direction towards the East River, approximately 0.3 miles away. Soil borings, which were advanced between 10 and 15 feet below sidewalk grade across the site, encountered historic fill material (coal ash, concrete, brick, plastic, and/or glass) underlain by native brown sand or silty-sand and gravel. "
Env Problem:	"Nature and Extent of Contamination: Soil and groundwater were

DOT RELOCATION SITE (Continued) **S122449236**

analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substances (PFAS), and pesticides. Soil vapor was analyzed for VOCs. Based upon investigations conducted to date, the primary contaminants of concern include petroleum VOCs, SVOCs and metals in soil, petroleum VOCs in groundwater, and chlorinated VOCs in soil vapor. Soil: Soil data were compared to Commercial Use Soil Cleanup Objectives (CSCOs) and Protection of Groundwater Soil Clean up Objectives (PoGWSCOs). Contaminants of concern are VOCs, SVOCs and metals to a depth of approximately 9 feet below grade. VOCs identified include benzene, at a maximum concentration of 190 parts per million (ppm) which exceeds its 44 ppm CSCO and PoGWSCO of 0.06 ppm, and toluene at a maximum concentration of 1,100 ppm (CSCO: 500 ppm and PoGWSCO: 0.7 ppm). SVOCs identified include benzo(a)anthracene at a maximum concentration of 200 ppm (CSCO: 1 ppm),benzo(a)pyrene at a maximum concentration of 120 ppm (CSCO: 1 ppm), benzo(b)fluoranthene at a maximum concentration of 130 ppm (CSCO: 5.6 ppm), and naphthalene at a maximum concentration of 1,500 ppm (CSCO: 500 ppm). Metals detected include barium at a maximum concentration of 1,330 ppm (CSCO: 400 ppm), lead at a maximum concentration of 2,330 ppm (CSCO: 1,000 ppm) and mercury at a maximum concentration of 1.8 ppm (CSCO: 2.8 ppm). Waste classification samples analyzed for lead exhibited levels exceeding the hazardous waste threshold on-site in one location. Soils containing gGrossly cContaminated material as defined in 6-NYCRR Part 375 and non-aqueous phase liquids were identified on-site. No PCBs or pesticides were detected at concentrations exceeding the CUSCOs. Data does not indicate any off-site impacts in soil related to this site. PFAS compounds were not sampled as part of the remedial investigation. The presence of PFAS in soil will be determined during the remedial action. Groundwater: Groundwater data was compared to the Department s TOGS Ambient Water Quality Standards (NY-AWQS). The VOC benzene was detected at a maximum concentration of 1.5 parts per billion (ppb) compared to the ambient water quality standard of 1ppb. Elevated levels of the naturally occurring metals iron, manganese and sodium were also detected in the groundwater on-site; however, these are not considered to be site-specific contaminants of concern. Perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 85.1 and 37.8 parts per trillion (ppt), respectively, exceeding the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater. Concentrations of PFOA and PFOS were relatively consistent across the e site. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor: Six soil vapor samples were collected throughout the site during the RI. Tetrachloroethene (PCE) was detected at a maximum concentration of 36 micrograms per cubic meter (ug/m3). Trichloroethene (TCE) was detected a maximum concentration of 2.6 ug/m3). Toluene was detected at a maximum concentration of 29 ug/m3. Data does not indicate any off-site impacts in soil vapor related to this site. "

Health Problem: "Since the site is fenced and covered by asphalt or concrete, people will not come into direct contact with site-related contamination is unless they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor (air spaces within the soil) may move into buildings and

DOT RELOCATION SITE (Continued) **S122449236**

affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is currently vacant; however, the potential exists for people to inhale site contaminants in indoor air due to soil vapor intrusion in any future onsite building development and occupancy. Environmental sampling indicates soil vapor intrusion is not a concern for offsite buildings."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-08-03 13:18:00
Record Upd:	2019-05-28 10:03:00
Updated By:	SMQUANDT
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Library at Long Island City
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Bruce M. Weill
Owner Company:	TFC 38-21 TWELFTH LLC
Owner Address:	c/o TF Cornerstone
Owner Addr2:	387 Park Avenue South
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Bruce M. Weill
Owner Company:	TFC 38-21 TWELFTH LLC
Owner Address:	c/o TF Cornerstone
Owner Addr2:	387 Park Avenue South
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Community Board District 1
Owner Address:	45-02 Ditmars Boulevard, Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Brett Richer
Owner Company:	38-21 12th Street Last Touch LLC
Owner Address:	1800 Wazee Street, Suite 500

DOT RELOCATION SITE (Continued) **S122449236**

Owner Addr2:	Not reported
Owner City,St,Zip:	Denver, CO 80202
Owner Country:	United States of America
HW Code:	C241213
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	toluene

DOT RELOCATION SITE (Continued) **S122449236**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241213
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1702829
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-06-13 13:28:00
Record Updated:	2018-06-13 13:28:00
Updated By:	JJDRUMM
Crossref ID:	0413143
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-06-12 14:42:00
Record Updated:	2018-06-12 14:42:00
Updated By:	JJDRUMM

V210 **38-21 12 ST PARTNERS LLC** **NY UST** **U001836621**
WSW **38-21 12TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.149 mi.
788 ft. **Site 6 of 16 in cluster V**

Relative: **Lower**

Actual: **16 ft.**

UST:

Name:	38-21 12 ST PARTNERS LLC
Address:	38-21 12TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-290122 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589370.45765
UTM Y:	4512390.14354
Site Type:	Other

Affiliation Records:

Site Id:	13096
Affiliation Type:	Mail Contact
Company Name:	38-21 12 STREET PARTNERS LLC

38-21 12 ST PARTNERS LLC (Continued) **U001836621**

Contact Type:	Not reported
Contact Name:	JOHN GONZALEZ
Address1:	35-01 VERNON BLVD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 726-0517
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-04

Site Id:	13096
Affiliation Type:	Facility Operator
Company Name:	38-21 12 ST PARTNERS LLC
Contact Type:	Not reported
Contact Name:	38-21 12 ST PARTNERS LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 726-0517
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-04

Site Id:	13096
Affiliation Type:	Emergency Contact
Company Name:	38-21 12 ST PARTNERS LLC
Contact Type:	Not reported
Contact Name:	JOHN GONZALEZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 440-8030
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-04

Site Id:	13096
Affiliation Type:	Facility Owner
Company Name:	38-21 12 ST PARTNERS LLC
Contact Type:	PARTNER
Contact Name:	JOHN GONZALEZ
Address1:	35-01 VERNON BLVD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY

38-21 12 ST PARTNERS LLC (Continued) **U001836621**

Zip Code:	11106
Country Code:	001
Phone:	(718) 726-0517
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2005-10-04

Tank Info:

Tank Number:	001
Tank ID:	18947
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	09/01/2005
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	03
Date Test:	03/30/2000
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I05 - Overfill - Vent Whistle
L00 - Piping Leak Detection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	18948
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	9999
Common Name of Substance:	Other

38-21 12 ST PARTNERS LLC (Continued) **U001836621**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None

W211 **WELL DUN FRENCH DRY CLEANERS** **RCRA NonGen / NLR** **1000274103**
North **12-14 36TH AVE** **NY MANIFEST** **NYD981086713**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.150 mi.
790 ft. **Site 1 of 7 in cluster W**

Relative:
Lower

Actual:
16 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Well Dun French Dry Cleaners
Handler Address:	12-14 36TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106-4724
EPA ID:	NYD981086713
Contact Name:	Not reported
Contact Address:	36TH AVE
Contact City,State,Zip:	QUEENS, NY 11106
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	36TH AVE
Mailing City,State,Zip:	QUEENS, NY 11106
Owner Name:	In Taek Ma
Owner Type:	Private
Operator Name:	In Taek Ma
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

WELL DUN FRENCH DRY CLEANERS (Continued) **1000274103**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And

WELL DUN FRENCH DRY CLEANERS (Continued) **1000274103**

F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: IN TAEK MA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	41-31 51ST ST
Owner/Operator City,State,Zip:	WOODSIDE, NY 11377
Owner/Operator Telephone:	718-784-9541
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: IN TAEK MA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	41-31 51ST ST
Owner/Operator City,State,Zip:	WOODSIDE, NY 11377
Owner/Operator Telephone:	718-784-9541
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: IN TAEK MA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	41-31 51ST ST
Owner/Operator City,State,Zip:	WOODSIDE, NY 11377
Owner/Operator Telephone:	718-784-9541
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name:	WELL DUN FRENCH DRY CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name:	WELL DUN FRENCH DRY CLEANERS

WELL DUN FRENCH DRY CLEANERS (Continued) **1000274103**

Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: WELL DUN FRENCH DRY CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19950222
Handler Name: WELL DUN FRENCH DRY CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: WELL DUN FRENCH DRY CLEANERS
Address: 12-14 36TH AVE
City,State,Zip: LONG ISLAND CITY, NY 11106-4724
Country: USA
EPA ID: NYD981086713
Facility Status: Not reported
Location Address 1: 12-14 36TH AVENUE

WELL DUN FRENCH DRY CLEANERS (Continued) **1000274103**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND CITY
Location State: NY
Location Zip: 11106
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD981086713
Mailing Name: WELL DUN FRENCH DRY CLEANERS
Mailing Contact: WELL DUN FRENCH DRY CLEANERS
Mailing Address 1: 12-14 36TH AVENUE
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11106
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187849541

W212 **WELL DUN CLEANERS** **NY DRYCLEANERS** **S128782067**
North **12-14 36TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.150 mi.
790 ft. **Site 2 of 7 in cluster W**

Relative:
Lower

Actual:
16 ft.

DRYCLEANERS:
Name: WELL DUN CLEANERS
Address: 12-14 36TH AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11106 4724
Facility ID: 2-6304-01108
Phone Number: 7187849541
Region: Not reported
Registration Effective Date: 2002-01-15 13:54:42
Inspection Date: 2000-04-03 12:00:00
Install Date: Not reported
Expiration Date: 07/08/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: WELL DUN CLEANERS
Address: 12-14 36TH AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11106 4724
Facility ID: 2-6304-01108
Phone Number: 7187849541
Region: Not reported
Registration Effective Date: 2002-01-15 13:54:42
Inspection Date: 2003-03-20 09:30:00
Install Date: Not reported
Expiration Date: 07/08/2003
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported

WELL DUN CLEANERS (Continued) **S128782067**

Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	WELL DUN CLEANERS
Address:	12-14 36TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11106 4724
Facility ID:	2-6304-01108
Phone Number:	7187849541
Region:	Not reported
Registration Effective Date:	2002-01-15 13:54:42
Inspection Date:	2002-03-29 09:00:00
Install Date:	Not reported
Expiration Date:	07/08/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	WELL DUN CLEANERS
Address:	12-14 36TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11106 4724
Facility ID:	2-6304-01108
Phone Number:	7187849541
Region:	Not reported
Registration Effective Date:	2002-01-15 13:54:42
Inspection Date:	2001-04-11 14:00:00
Install Date:	Not reported
Expiration Date:	07/08/2003
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

U213 **NYCDEP** **NY MANIFEST** **1009235634**
WNW **37-31 11TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.150 mi.
794 ft. **Site 3 of 3 in cluster U**

Relative: **Lower**

Actual: **14 ft.**

NY MANIFEST:

Name:	NYCDEP
Address:	37-31 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Country:	USA
EPA ID:	NYP003661063
Facility Status:	Not reported
Location Address 1:	37-31 11TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

NYCDEP (Continued) **1009235634**

EPAID:	NYP003661063
Mailing Name:	NYCDEP
Mailing Contact:	ROSS POLONETSKY
Mailing Address 1:	59-17 JUNCTION BLVD
Mailing Address 2:	Not reported
Mailing City:	FLUSHING
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954784

V214 **IMOG AUTOMOTIVE INC** **RCRA-VSQG** **1001203050**
WSW **38-44 13TH ST** **FINDS** **NYR000043778**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.151 mi.
797 ft. **Site 7 of 16 in cluster V**

Relative: **Higher**

Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Imog Automotive Inc
Handler Address:	38-44 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-6120
EPA ID:	NYR000043778
Contact Name:	Not reported
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Walter Hines
Owner Type:	Private
Operator Name:	Walter Hines
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

IMOG AUTOMOTIVE INC (Continued) **1001203050**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALTER HINES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-44 13TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	516-796-7649
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: WALTER HINES	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-44 13TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	516-796-7649

IMOG AUTOMOTIVE INC (Continued) **1001203050**

Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WALTER HINES
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 38-44 13TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 516-796-7649
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: IMOG AUTOMOTIVE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: IMOG AUTOMOTIVE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: IMOG AUTOMOTIVE INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970820

IMOG AUTOMOTIVE INC (Continued) **1001203050**

Handler Name: IMOG AUTOMOTIVE INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004536672

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001203050
Registry ID: 110004536672
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004536672
Name: IMOG AUTOMOTIVE INC
Address: 38-44 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101

P215 **39-15 21ST STREET** **NY LTANKS** **S100781937**
SW **39-15 21ST STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.153 mi.
807 ft. **Site 8 of 8 in cluster P**

Relative: **Higher**
Actual: **18 ft.**

LTANKS:
Name: 39-15 21ST STREET
Address: 39-15 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9308729 / 2003-03-14

39-15 21ST STREET (Continued) **S100781937**

Facility ID:	9308729
Site ID:	149681
Spill Date:	1993-10-19
Spill Cause:	Tank Failure
Spill Source:	Unknown
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1993-10-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-10-21
Spill Record Last Update:	2003-08-20
Spiller Name:	Not reported
Spiller Company:	GRAND INTERNATION INC.
Spiller Address:	21-24 39TH AVENUE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127293
DEC Memo:	""
Remarks:	"TEST NOT COMPLETED 6000 COULD NOT OFF TANK."

All Materials:

Site ID:	149681
Operable Unit ID:	990265
Operable Unit:	01
Material ID:	391420
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

T216 **NYC DEPT OF ENVIRONMENTAL PROTECTION** **NY MANIFEST** **1009235665**
ENE **36 AVE & 23RD ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.154 mi.
815 ft. **Site 5 of 5 in cluster T**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Address:	36 AVE & 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY
Country:	USA
EPA ID:	NYP003661394
Facility Status:	Not reported
Location Address 1:	36 AVE & 23RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP003661394
Mailing Name:	NYC DEPT OF ENVIRONMENTAL PROTECTION
Mailing Contact:	CHRIS HAAS
Mailing Address 1:	5917 JUNCTION BLVD
Mailing Address 2:	Not reported
Mailing City:	CORONA
Mailing State:	NY
Mailing Zip:	11368
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7185954784

X217 **CHECKER MANAGEMENT CORP.** **NY AST** **A100433670**
West **11-05 38 AVE.** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.155 mi.
820 ft. **Site 1 of 5 in cluster X**

Relative:
Lower

Actual:
15 ft.

AST:

Name:	CHECKER MANAGEMENT CORP.
Address:	11-05 38 AVE.
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregistered
Facility Id:	2-612682
Program Type:	PBS
UTM X:	Not reported
UTM Y:	Not reported
Expiration Date:	N/A
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	541602
Affiliation Type:	Facility Owner
Company Name:	VANKO LLC
Contact Type:	MANAGER

CHECKER MANAGEMENT CORP. (Continued) **A100433670**

Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	11-05 38 AVE.
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-03-01

Site Id:	541602
Affiliation Type:	Mail Contact
Company Name:	VANKO LLC
Contact Type:	Not reported
Contact Name:	SOPHIA KONSTANTINIDES
Address1:	34-20 31 STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(719) 361-5555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-03-01

Site Id:	541602
Affiliation Type:	Facility Operator
Company Name:	CHECKER MANAGEMENT CORP.
Contact Type:	Not reported
Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2017-03-01

Site Id:	541602
Affiliation Type:	Emergency Contact
Company Name:	VANKO LLC
Contact Type:	Not reported
Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported

CHECKER MANAGEMENT CORP. (Continued) **A100433670**

Country Code:	999
Phone:	(917) 881-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-24

Tank Info:

Tank Number:	01
Tank Id:	266972

Equipment Records:

C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
E00 - Piping Secondary Containment - None
B01 - Tank External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Unregistered
Pipe Model:	Not reported
Install Date:	12/15/2016
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	02
Tank Id:	266973

Equipment Records:

D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

CHECKER MANAGEMENT CORP. (Continued) **A100433670**

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Unregistered
Pipe Model:	Not reported
Install Date:	12/15/2016
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/15/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Tank Number:	03
Tank Id:	266974

Equipment Records:

C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	12/15/2016
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/15/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

Tank Number:	04
Tank Id:	266975

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
L09 - Piping Leak Detection - Exempt Suction Piping
E00 - Piping Secondary Containment - None

CHECKER MANAGEMENT CORP. (Continued) **A100433670**

H00 - Tank Leak Detection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
K00 - Spill Prevention - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Tank Converted to Non-Regulated Use
Pipe Model:	Not reported
Install Date:	12/15/2016
Capacity Gallons:	275
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	12/15/2016
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	motor oil

X218 **2-612682** **NY AST** **A100433674**
West **11-05 38TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.155 mi.
820 ft. **Site 2 of 5 in cluster X**

Relative: **Lower**
Actual: **15 ft.**

AST:

Name:	2-612682
Address:	11-05 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-612689
Program Type:	PBS
UTM X:	589393.00000
UTM Y:	4512477.00000
Expiration Date:	05/05/2026
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	543260
Affiliation Type:	Facility Owner
Company Name:	VANKO LLC
Contact Type:	MANAGER
Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	11-05 38TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 361-6300
EMail:	Not reported

2-612682 (Continued) **A100433674**

Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-03-21

Site Id:	543260
Affiliation Type:	Mail Contact
Company Name:	VANKO LLC
Contact Type:	Not reported
Contact Name:	SOPHIA KONSTANTINIDES
Address1:	34-20 31ST STREET
Address2:	LONG ISLAND CITY
City:	QUEENS
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-5555
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-03-21

Site Id:	543260
Affiliation Type:	Facility Operator
Company Name:	2-612682
Contact Type:	Not reported
Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-6300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-03-21

Site Id:	543260
Affiliation Type:	Emergency Contact
Company Name:	VANKO LLC
Contact Type:	Not reported
Contact Name:	PANAGIOTIS PAPADOPOULOS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 881-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DAFRANCI
Date Last Modified:	2017-03-24

Tank Info:

2-612682 (Continued) **A100433674**

Tank Number: 01
Tank Id: 267218

Equipment Records:

G01 - Tank Secondary Containment - Diking (Aboveground)
L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/05/2016
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: waste oil/used oil

Tank Number: 02
Tank Id: 267219

Equipment Records:

L00 - Piping Leak Detection - None
D00 - Pipe Type - No Piping
G01 - Tank Secondary Containment - Diking (Aboveground)
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
J00 - Dispenser - None
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: In Service
Pipe Model: Not reported
Install Date: 12/15/2016
Capacity Gallons: 275
Tightness Test Method: -
Date Test: Not reported

2-612682 (Continued) **A100433674**

Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: waste oil/used oil

W219 **36-05 12TH ST** **NY UST** **U004190179**
NNW **36-05 12TH STREET** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.155 mi.
821 ft. **Site 3 of 7 in cluster W**

Relative: **Lower**
Actual: **15 ft.**

UST:
Name: 36-05 12TH ST
Address: 36-05 12TH STREET
City,State,Zip: ASTORIA, NY 11106
Id/Status: 2-303984 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 09/30/2024
UTM X: 589543.69308
UTM Y: 4512734.33454
Site Type: Other Wholesale/Retail Sales

Affiliation Records:
Site Id: 13836
Affiliation Type: Facility Operator
Company Name: 36-05 12TH ST
Contact Type: Not reported
Contact Name: JOHNSON WU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (917) 519-0776
EMail: Not reported
Fax Number: Not reported
Modified By: NTFREEMA
Date Last Modified: 2015-11-13

Site Id: 13836
Affiliation Type: Emergency Contact
Company Name: ERUGO BUILDING LLC
Contact Type: Not reported
Contact Name: JOHNSON WU
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (917) 519-0776
EMail: Not reported
Fax Number: Not reported

36-05 12TH ST (Continued) **U004190179**

Modified By:	NTFREEMA
Date Last Modified:	2015-11-13

Site Id:	13836
Affiliation Type:	Mail Contact
Company Name:	ERUGO BUILDING LLC
Contact Type:	PRESIDENT
Contact Name:	JOHNSON WU
Address1:	5607 208TH STREET
Address2:	Not reported
City:	OAKLAND GARDENS
State:	NY
Zip Code:	11364
Country Code:	001
Phone:	(917) 519-0776
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-07-16

Site Id:	13836
Affiliation Type:	Facility Owner
Company Name:	ERUGO BUILDING LLC
Contact Type:	PRESIDENT
Contact Name:	JOHNSON WU
Address1:	5607 208TH STREET
Address2:	Not reported
City:	OAKLAND GARDENS
State:	NY
Zip Code:	11364
Country Code:	001
Phone:	(917) 519-0776
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-07-16

Tank Info:

Tank Number:	001
Tank ID:	16250
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1500
Install Date:	05/20/1954
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	34
Date Test:	05/05/2020
Next Test Date:	05/05/2021
Pipe Model:	Not reported
Modified By:	MJGRIFFI

36-05 12TH ST (Continued) **U004190179**

Last Modified: 05/09/2022

Equipment Records:

C03 - Pipe Location - Aboveground/Underground Combination
B00 - Tank External Protection - None
J00 - Dispenser - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I05 - Overfill - Vent Whistle

Y220 **CON EDISON - MANHOLE M18003** **NY MANIFEST** **S120958409**
SE **37-46 CRESCENT ST** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.159 mi.
838 ft. **Site 1 of 5 in cluster Y**

Relative:
Higher

Actual:
31 ft.

NY MANIFEST:

Name:	CON EDISON - MANHOLE M18003
Address:	37-46 CRESCENT ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYP004935159
Facility Status:	Not reported
Location Address 1:	37-46 CRESCENT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004935159
Mailing Name:	CON EDISON - MANHOLE M18003
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Z221 **ST RITA SCHOOL** **NY UST** **U001329937**
NNW **36-22 12TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.161 mi.
848 ft. **Site 1 of 2 in cluster Z**

Relative:
Lower

Actual:
15 ft.

UST:

Name:	ST RITA SCHOOL
Address:	36-22 12TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11106
Id/Status:	2-601219 / Inactive
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589373.61735
UTM Y:	4511966.18061
Site Type:	School

Affiliation Records:

Site Id:	23189
Affiliation Type:	Facility Owner
Company Name:	ST RITA CHURCH
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	36-25 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23189
Affiliation Type:	Mail Contact
Company Name:	ST RITA CHURCH
Contact Type:	Not reported
Contact Name:	REV. HARRINGTON
Address1:	36-25 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23189
Affiliation Type:	Facility Operator
Company Name:	ST RITA SCHOOL
Contact Type:	Not reported
Contact Name:	REV. HARRINGTON
Address1:	Not reported

ST RITA SCHOOL (Continued) **U001329937**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	23189
Affiliation Type:	Emergency Contact
Company Name:	ST RITA CHURCH
Contact Type:	Not reported
Contact Name:	REV. HARRINGTON
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	1
Tank ID:	44962
Tank Status:	Tank Converted to Non-Regulated Use
Material Name:	Tank Converted to Non-Regulated Use
Capacity Gallons:	5000
Install Date:	Not reported
Date Tank Closed:	06/06/2003
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Tightness Test Method:	03
Date Test:	08/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

ST RITA SCHOOL (Continued) **U001329937**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
I05 - Overfill - Vent Whistle

AA222 **CON EDISON - SERVICE BOX 31050** **NY MANIFEST** **S120957826**
NNE **35-51 21ST ST** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.161 mi.
850 ft. **Site 1 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX 31050
Address:	35-51 21ST ST
City,State,Zip:	QUEENS, NY 11106
Country:	USA
EPA ID:	NYP004885980
Facility Status:	Not reported
Location Address 1:	35-51 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004885980
Mailing Name:	CON EDISON - SERVICE BOX 31050
Mailing Contact:	THERESA BURKARD
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602262

V223 **QUEENS AUTO & BODY SHOP INC D/B/A NEW BANGLA MOTOR** **NY AST** **A100295691**
WSW **38-56 13TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.162 mi.
856 ft. **Site 8 of 16 in cluster V**

Relative:
Higher

Actual:
17 ft.

AST:

Name:	QUEENS AUTO & BODY SHOP INC D/B/A NEW BANGLA MOTOR
Address:	38-56 13TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609693
Program Type:	PBS
UTM X:	589372.44376
UTM Y:	4512278.57882

QUEENS AUTO & BODY SHOP INC D/B/A NEW BANGLA MOTOR (Continued) **A100295691**

Expiration Date: 09/01/2014
Site Type: Other

Affiliation Records:

Site Id: 59113
Affiliation Type: Facility Owner
Company Name: MD ABDUL KADIR
Contact Type: OWNER
Contact Name: MD ABDUL KADIR
Address1: 38-56 13TH STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-9440
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2004-09-01

Site Id: 59113
Affiliation Type: Mail Contact
Company Name: QUEENS AUTO & BODY SHOP INC
Contact Type: Not reported
Contact Name: MD ABDUL KADIR
Address1: D/B/A NEW BANGLA MOTOR INC
Address2: 38-56 13TH STREET
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 707-9440
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2004-09-01

Site Id: 59113
Affiliation Type: Facility Operator
Company Name: QUEENS AUTO & BODY SHOP INC D/B/A NEW BANGLA MOTOR
Contact Type: Not reported
Contact Name: MD ABDUL KADIR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 707-9440]
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2004-09-01

Site Id: 59113
Affiliation Type: Emergency Contact
Company Name: MD ABDUL KADIR

QUEENS AUTO & BODY SHOP INC D/B/A NEW BANGLA MOTOR (Continued) **A100295691**

Contact Type:	Not reported
Contact Name:	MD ABDUL KADIR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	7182) 078-085
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2004-09-01

Tank Info:

Tank Number:	001
Tank Id:	179978
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2003
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	waste oil/used oil

Y224 **MC ACROPOLIS, LLC** **NY AST** **U003393257**
SSE **24-16 38TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.163 mi.
861 ft. **Site 2 of 5 in cluster Y**

Relative:
Higher

Actual:
30 ft.

AST:

Name:	MC ACROPOLIS, LLC
Address:	24-16 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-326143
Program Type:	PBS
UTM X:	589773.81431
UTM Y:	4512225.69062
Expiration Date:	07/17/2023
Site Type:	Apartment Building/Office Building

MC ACROPOLIS, LLC (Continued) **U003393257**

Affiliation Records:

Site Id:	15183
Affiliation Type:	Mail Contact
Company Name:	MC ACROPOLIS, LLC
Contact Type:	Not reported
Contact Name:	NICHOLAS CORITSIDIS
Address1:	P.O. BOX 610530
Address2:	Not reported
City:	FLUSHING
State:	NY
Zip Code:	11361
Country Code:	001
Phone:	(718) 423-6900
EMail:	NICHOLAS@AMERICAREALTYLLC.COM
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-09

Site Id:	15183
Affiliation Type:	Facility Operator
Company Name:	MC ACROPOLIS, LLC
Contact Type:	Not reported
Contact Name:	JULIO PEGUERO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 423-6900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-09

Site Id:	15183
Affiliation Type:	Emergency Contact
Company Name:	MC ACROPOLIS, LLC
Contact Type:	Not reported
Contact Name:	NICHOLAS CORITSIDIS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(516) 761-0977
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-09

Site Id:	15183
Affiliation Type:	Facility Owner
Company Name:	MC ACROPOLIS, LLC
Contact Type:	MANAGEMENT
Contact Name:	ILIAS THEODOROPOULOS

MC ACROPOLIS, LLC (Continued) **U003393257**

Address1:	38-08 BELL BOULEVARD
Address2:	Not reported
City:	BAYSIDE
State:	NY
Zip Code:	11361
Country Code:	001
Phone:	(718) 423-6900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-04-09

Tank Info:

Tank Number:	001
Tank Id:	26434
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

A00 - Tank Internal Protection - None
H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
I05 - Overfill - Vent Whistle
J03 - Dispenser - Gravity
L00 - Piping Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1927
Capacity Gallons:	5000
Tightness Test Method:	34
Date Test:	06/29/2020
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

V225 **PEP BOYS #437** **NY MANIFEST** **1004760151**
SW **38-50 21ST ST** **N/A**
1/8-1/4 **QUEENS, NY 11128**
0.164 mi.
867 ft. **Site 9 of 16 in cluster V**

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	PEP BOYS #437
Address:	38-50 21ST ST
City,State,Zip:	QUEENS, NY 11128
Country:	USA
EPA ID:	NYR000033902
Facility Status:	Not reported
Location Address 1:	38-50 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000033902
Mailing Name:	PEP BOYS #437
Mailing Contact:	PEP BOYS #437
Mailing Address 1:	38-50 21ST ST
Mailing Address 2:	Not reported
Mailing City:	QUEENS
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CTD983872698
Trans2 State ID:	NJD054126164
Generator Ship Date:	11/28/2012
Trans1 Recv Date:	11/28/2012
Trans2 Recv Date:	11/30/2012
TSD Site Recv Date:	12/05/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000033902
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	INR000110197
TSDF ID 2:	Not reported
Manifest Tracking Number:	005843513FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

PEP BOYS #437 (Continued) **1004760151**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	23
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V226 **CON ED VS 7598** **RCRA NonGen / NLR** **1007206732**
SW **21 ST ST E 38 S 43RD AVE** **NY MANIFEST** **NYP004015152**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.164 mi.
867 ft. **Site 10 of 16 in cluster V**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed Vs 7598
Handler Address:	21 ST ST E 38 S 43RD AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-0000
EPA ID:	NYP004015152
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CON EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CON EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported

CON ED VS 7598 (Continued) **1007206732**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name: CON ED VS 7598	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON ED VS 7598 (Continued) **1007206732**

Receive Date:	19980228
Handler Name: CON ED VS 7598	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19980226
Handler Name: CON ED VS 7598	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	2211
NAICS Description:	ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code:	22111
NAICS Description:	ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	21 ST ST E 38 S 43RD AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101-0000
Country:	USA
EPA ID:	NYP004015152
Facility Status:	Not reported
Location Address 1:	7598 - 21ST & 43 AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

CON ED VS 7598 (Continued) **1007206732**

NY MANIFEST:

EPAID:	NYP004015152
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

W227 **VOICE CHARTER SCHOOL OF NY** **NY UST** **U001833963**
NNW **36-14 12TH STREET** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.165 mi.
873 ft. **Site 4 of 7 in cluster W**

Relative:
Lower

Actual:
15 ft.

UST:

Name:	VOICE CHARTER SCHOOL OF NY
Address:	36-14 12TH STREET
City,State,Zip:	ASTORIA, NY 11106
Id/Status:	2-249424 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	07/07/2022
UTM X:	589525.95612
UTM Y:	4512725.06071
Site Type:	School

Affiliation Records:

Site Id:	9906
Affiliation Type:	Facility Owner
Company Name:	ST. RITA CHURCH
Contact Type:	PASTOR
Contact Name:	JOSE CARLOS DESILVA
Address1:	36-25 11TH ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-09-20

Site Id:	9906
Affiliation Type:	Mail Contact
Company Name:	ST. RITA R.C.CHURCH
Contact Type:	Not reported
Contact Name:	JOSE CARLOS DESILVA
Address1:	36-24 11TH ST
Address2:	Not reported

VOICE CHARTER SCHOOL OF NY (Continued) **U001833963**

City: LONG ISLAND CITY
State: NY
Zip Code: 11106
Country Code: 001
Phone: (718) 361-1694 1010
EMail: PFORD@VOICECHARTERSCHOOL.ORG
Fax Number: Not reported
Modified By: DMPOKRZY
Date Last Modified: 2018-04-04

Site Id: 9906
Affiliation Type: Facility Operator
Company Name: VOICE CHARTER SCHOOL OF NY
Contact Type: Not reported
Contact Name: HAKEEN MIR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 361-1694
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-09-20

Site Id: 9906
Affiliation Type: Emergency Contact
Company Name: ST. RITA CHURCH
Contact Type: Not reported
Contact Name: JOSE CARLOS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 361-1884
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-09-20

Tank Info:

Tank Number: 001
Tank ID: 10399
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 5000
Install Date: 01/01/1950
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0001

VOICE CHARTER SCHOOL OF NY (Continued) **U001833963**

Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 10/20/2017
Next Test Date: 10/20/2018
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle

X228 **CON ED** **NY MANIFEST** **1009242087**
West **11 ST & 38 AVE EXCAV** **N/A**
1/8-1/4 **QUEENS, NY**
0.166 mi.
878 ft. **Site 3 of 5 in cluster X**

Relative: **Lower**

Actual: **15 ft.**

NY MANIFEST:
Name: CON ED
Address: 11 ST & 38 AVE EXCAV
City,State,Zip: QUEENS, NY
Country: USA
EPA ID: NYP004107447
Facility Status: Not reported
Location Address 1: 11 ST & 38 AVE EXCAV
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004107447
Mailing Name: CON ED
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

X229 **CONSOLIDATED EDISON** **NY MANIFEST** **1009243142**
West **38TH AVE & 11TH ST** **N/A**
1/8-1/4 **QUEENS, NY**
0.166 mi.
878 ft. **Site 4 of 5 in cluster X**

Relative: **Lower**
Actual: **15 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	38TH AVE & 11TH ST
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004124947
Facility Status:	Not reported
Location Address 1:	38TH AVE & 11TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004124947
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

X230 **CON ED - 38TH AVE & 11TH ST** **RCRA NonGen / NLR** **1007206482**
West **38TH AVE & 11TH ST** **NY MANIFEST** **NYP004010591**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.166 mi.
878 ft. **Site 5 of 5 in cluster X**

Relative: **Lower**
Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	19980228
Handler Name:	Con Ed - 38th Ave & 11th St
Handler Address:	38TH AVE & 11TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106-0000
EPA ID:	NYP004010591
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON ED - 38TH AVE & 11TH ST (Continued) **1007206482**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	19980227
Handler Name:	CON ED - 38TH AVE & 11TH ST
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny

CON ED - 38TH AVE & 11TH ST (Continued) **1007206482**

Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980228
Handler Name: CON ED - 38TH AVE & 11TH ST
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - 38TH AVE & 11TH ST
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON CO OF NY INC
Address: 38TH AVE & 11TH ST
City,State,Zip: LONG ISLAND CITY, NY 11106-0000
Country: USA
EPA ID: NYP004010591

CON ED - 38TH AVE & 11TH ST (Continued) **1007206482**

Facility Status:	Not reported
Location Address 1:	(No street address in conversion)
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004010591
Mailing Name:	CONSOLIDATED EDISON CO OF NY INC
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

S231 **AROON SUKRANICHANNE** **NY LTANKS** **S102672819**
ESE **36-46 CRESCENT STREET** **N/A**
1/8-1/4 **ASTORIA, NY**
0.171 mi.
903 ft. **Site 4 of 4 in cluster S**

Relative:
Higher

Actual:
24 ft.

LTANKS:

Name:	AROON SUKRANICHANNE
Address:	36-46 CRESCENT STREET
City,State,Zip:	ASTORIA, NY
Spill Number/Closed Date:	9414758 / 1995-02-09
Facility ID:	9414758
Site ID:	311462
Spill Date:	1995-02-08
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1995-02-09
SWIS:	4101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1995-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-09
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	PETRO

AROON SUKRANICHANNE (Continued) **S102672819**

Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	251287
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"TANK WAS FULL BEFORE DELIVERY."

All Materials:

Site ID:	311462
Operable Unit ID:	1008257
Operable Unit:	01
Material ID:	373483
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

AA232 **NYCHA - RAVENSWOOD HOUSES** **NJ MANIFEST** **S120679135**
NNE **35-32 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.171 mi.
903 ft. **Site 2 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

NJ MANIFEST:

EPA Id:	NYR000221325
Mail Address:	35TH AVE
Mail City/State/Zip:	LONG ISLAND CITY, NY 11106
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	TYRONE GORDILS
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014162431JJK
EPA ID:	NYR000221325
Date Shipped:	9/9/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

NYCHA - RAVENSWOOD HOUSES (Continued) **S120679135**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	LONG ISLAND CITY, NY 11106
Reason Load Was Rejected:	Not reported

AA233 **NYCHA - RAVENSWOOD HOUSES** **RCRA NonGen / NLR** **1018159055**
NNE **35-32 21ST ST** **FINDS** **NYR000221325**
1/8-1/4 **LONG ISLAND CITY, NY 11106** **ECHO**
0.171 mi.
903 ft. **Site 3 of 4 in cluster AA**

Relative: **Higher**

Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20170418
Handler Name:	Nycha - Ravenswood Houses
Handler Address:	35-32 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYR000221325
Contact Name:	TYRONE GORDILS
Contact Address:	49TH ST 5TH FL
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-707-5865
Contact Fax:	Not reported
Contact Email:	TYRONE.GORDILS@NYCHA.NYC.GOV
Contact Title:	DEPUTY CORDINATOR OF ENVIRON HEALTH & SAFETY
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified

NYCHA - RAVENSWOOD HOUSES (Continued) **1018159055**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	35TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner Name:	New York City Housing Authority
Owner Type:	Municipal
Operator Name:	New York City Housing Authority
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20170509
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	Lead

NYCHA - RAVENSWOOD HOUSES (Continued) **1018159055**

Waste Code: K052
Waste Description: Tank Bottoms (Leaded) From The Petroleum Refining Industry.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: 19510731
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: 19510731
Date Ended Current: Not reported
Owner/Operator Address: 250 BROADWAY
Owner/Operator City,State,Zip: NEW YORK
Owner/Operator Telephone: 212-306-3000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NEW YORK CITY HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: 19510731
Date Ended Current: Not reported
Owner/Operator Address: 250 BROADWAY
Owner/Operator City,State,Zip: NEW YORK
Owner/Operator Telephone: 212-306-3000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: NEW YORK CITY HOUSING AUTHORITY
Legal Status: Municipal
Date Became Current: 19510731
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20170418
Handler Name: NYCHA - RAVENSWOOD HOUSES
Federal Waste Generator Description: Not a generator, verified

NYCHA - RAVENSWOOD HOUSES (Continued) **1018159055**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150820
Handler Name: NYCHA - RAVENSWOOD HOUSES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 562910
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110066949618

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018159055
Registry ID: 110066949618
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110066949618
Name: NYCHA - RAVENSWOOD HOUSES
Address: 35-32 21ST ST

NYCHA - RAVENSWOOD HOUSES (Continued) **1018159055**

City,State,Zip: LONG ISLAND CITY, NY 11106

AA234 **NYCHA - RAVENSWOOD HOUSES** **NY MANIFEST** **S118260263**
NNE **35-32 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.171 mi.
903 ft. **Site 4 of 4 in cluster AA**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	NYCHA - RAVENSWOOD HOUSES
Address:	35-32 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYR000221325
Facility Status:	Not reported
Location Address 1:	35-32 21ST ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000221325
Mailing Name:	NYCHA - RAVENSWOOD HOUSES
Mailing Contact:	NYCHA - RAVENSWOOD HOUSES
Mailing Address 1:	35-32 21ST ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/09/2015
Trans1 Recv Date:	09/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000221325
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014162431JJK
Import Indicator:	N
Export Indicator:	N

NYCHA - RAVENSWOOD HOUSES (Continued) **S118260263**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AB235 **CONSOLIDATED EDISON** **NY MANIFEST** **1009237201**
NW **11TH ST & 37TH AVE** **N/A**
1/8-1/4 **QUEENS, NY**
0.173 mi.
914 ft. **Site 1 of 7 in cluster AB**

Relative:
Lower

Actual:
14 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	11TH ST & 37TH AVE
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004024394
Facility Status:	Not reported
Location Address 1:	11TH ST & 37TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004024394
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CONSOLIDATED EDISON (Continued) **1009237201**

Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

236
SSW
1/8-1/4
0.173 mi.
916 ft.

MONARCH CONSTRUCTION CORP. **NY UST** **U001835510**
39-16 23RD STREET **NY Spills** **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Higher

Actual:
20 ft.

UST:
Name: MONARCH CONSTRUCTION CORP.
Address: 39-16 23RD STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-283207 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 589606.02469
UTM Y: 4512133.65963
Site Type: Other

Affiliation Records:
Site Id: 12493
Affiliation Type: Facility Owner
Company Name: SALIBA PROPERTIES
Contact Type: Not reported
Contact Name: Not reported
Address1: 10-57 JACKSON AVENUE
Address2: Not reported
City: LIC
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 392-3764
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 12493
Affiliation Type: Mail Contact
Company Name: SALIBA PROPERTIES
Contact Type: Not reported
Contact Name: CHARLES J. SALIBA
Address1: 39-16 23RD STREET
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 392-3764
EMail: Not reported
Fax Number: Not reported

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12493
Affiliation Type:	Facility Operator
Company Name:	MONARCH CONSTRUCTION CORP.
Contact Type:	Not reported
Contact Name:	CHARLES J. SALIBA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 392-3764
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	12493
Affiliation Type:	Emergency Contact
Company Name:	SALIBA PROPERTIES
Contact Type:	Not reported
Contact Name:	CHARLES J. SALIBA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-7766
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	007
Tank ID:	47639
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	550
Install Date:	01/01/1989
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
I00 - Overfill - None
J00 - Dispenser - None
D00 - Pipe Type - No Piping
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 008
Tank ID: 47640
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 01/01/1989
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
J00 - Dispenser - None
A01 - Tank Internal Protection - Epoxy Liner
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 0D1
Tank ID: 14868
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 0D2
Tank ID: 14869
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0008
Common Name of Substance: Diesel

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 0G1
Tank ID: 14866
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 0G2
Tank ID: 14867
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A01 - Tank Internal Protection - Epoxy Liner
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 0H1

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Tank ID: 14870
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: 0H2
Tank ID: 14871
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 03
Date Test: 10/01/1997
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
F00 - Pipe External Protection - None

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: OD3
Tank ID: 56873
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

Tank Number: OG3
Tank ID: 56874
Tank Status: Closed - In Place
Material Name: Closed - In Place
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 06/01/1999
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
F00 - Pipe External Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating

SPILLS:

Name:	MONARCH CONSTRUCTION
Address:	39-16 23RD ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9903169 / 1999-12-23
Facility ID:	9903169
Facility Type:	ER
DER Facility ID:	109058
Site ID:	126106
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	4101
Spill Date:	1999-06-09
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1999-06-18
CID:	384
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-18
Spill Record Last Update:	2004-02-20
Spiller Name:	CHARLES SALIBA
Spiller Company:	MONARCH CONSTRUCTION
Spiller Address:	39-16 23RD ST
Spiller Company:	001
Contact Name:	CHARLES SALIBA
DEC Memo:	""
Remarks:	"CALLER STATES TEST ON AN UNDERGROUND TANK SHOWED CONTAMINATION. CLEAN UP WILL BE DONE AFTER A RESPONSE FROM THE STATE."

All Materials:

Site ID:	126106
Operable Unit ID:	1077774
Operable Unit:	01
Material ID:	303095
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

MONARCH CONSTRUCTION CORP. (Continued) **U001835510**

Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

W237 **CON EDISON** **NJ MANIFEST** **S120676248**
NNW **36TH AVE & 12TH ST** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.174 mi.
918 ft. **Site 5 of 7 in cluster W**

Relative:
Lower

Actual:
15 ft.

NJ MANIFEST:

EPA Id:	NYP004833444
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469093JJK
EPA ID:	NYP004833444
Date Shipped:	9/2/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported

CON EDISON (Continued) **S120676248**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W238 **CON EDISON** **RCRA NonGen / NLR** **1019907380**
NNW **36TH AVE & 12TH ST** **NYP004833444**
1/8-1/4 **ASTORIA, NY 11106**
0.174 mi.
918 ft. **Site 6 of 7 in cluster W**

Relative: **Lower**
Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	20150902
Handler Name:	Con Edison
Handler Address:	36TH AVE & 12TH ST
Handler City,State,Zip:	ASTORIA, NY 11106
EPA ID:	NYP004833444
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON (Continued) **1019907380**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150902
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20150902
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON (Continued) **1019907380**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC239 **CON ED** **NY MANIFEST** **S119077518**
SW **39-26 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.174 mi.
918 ft. **Site 1 of 10 in cluster AC**

Relative: **Higher**
Actual: **18 ft.**

NY MANIFEST:
Name: CON ED
Address: 39-26 21ST ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004832875
Facility Status: Not reported
Location Address 1: 39-26 21 ST
Code: BP
Location Address 2: SB 19244
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004832875
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJ0000027193

CON ED (Continued) **S119077518**

Trans2 State ID:	Not reported
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004832875
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014470899JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC240 **CON EDISON** **RCRA NonGen / NLR** **1019907335**
SW **39-26 21ST ST** **NYP004832875**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.174 mi.
918 ft. **Site 2 of 10 in cluster AC**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20150901
Handler Name:	Con Edison
Handler Address:	39-26 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004832875
Contact Name:	THOMAS TEELING
Contact Address:	Not reported

CON EDISON (Continued) **1019907335**

Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1019907335**

Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150901
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150901
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC241 **CON EDISON** **NJ MANIFEST** **S120676193**
SW **39-26 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.174 mi.
918 ft. **Site 3 of 10 in cluster AC**

Relative: **Higher**
Actual: **18 ft.**

NJ MANIFEST:
EPA Id: NYP004832875
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported

CON EDISON (Continued) **S120676193**

SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014470899JJK
EPA ID:	NYP004832875
Date Shipped:	9/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB242 **CON EDISON SERVICE BOX: 33123** **RCRA NonGen / NLR** **1017774958**
NW **462 11TH AVE & 37TH ST N OF** **FINDS** **NYP004527784**
1/8-1/4 **NEW YORK, NY 10018**
0.174 mi.
921 ft. **Site 2 of 7 in cluster AB**

Relative: **Lower**
Actual: **14 ft.**

RCRA Listings:

Date Form Received by Agency:	20140609
Handler Name:	Con Edison Service Box: 33123
Handler Address:	462 11TH AVE & 37TH ST N OF
Handler City,State,Zip:	NEW YORK, NY 10018
EPA ID:	NYP004527784
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 33123 (Continued) **1017774958**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150211
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140509
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140509
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140609
Handler Name: CON EDISON SERVICE BOX: 33123	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON SERVICE BOX: 33123 (Continued) **1017774958**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063800793

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AD243 **CON EDISON** **RCRA NonGen / NLR** **1014398817**
East **36-15 24TH ST** **NY MANIFEST** **NYP004211876**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.176 mi.
928 ft. **Site 1 of 3 in cluster AD**

Relative:
Higher

Actual:
20 ft.

RCRA Listings:

Date Form Received by Agency:	20200413
Handler Name:	Con Edison
Handler Address:	36-15 24TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004211876
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported

CON EDISON (Continued) **1014398817**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20200413
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20100721
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1014398817**

Electronic Manifest Broker: Not reported

Receive Date: 20200413
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 36-15 24TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004211876
Facility Status: Not reported
Location Address 1: 36-15 24TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004211876
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:

CON EDISON (Continued) **1014398817**

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/21/2010
Trans1 Recv Date:	07/21/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/22/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004211876
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001442361FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	40
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE244 **SPILL NUMBER 0005416** **NY LTANKS** **S104782024**
ESE **CRESCENT ST/37TH AV** **N/A**
1/8-1/4 **JAMAICA, NY**
0.179 mi.
947 ft. **Site 1 of 6 in cluster AE**

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name:	SPILL NUMBER 0005416
Address:	CRESCENT ST/37TH AV
City,State,Zip:	JAMAICA, NY
Spill Number/Closed Date:	0005416 / 2003-03-04
Facility ID:	0005416
Site ID:	115362
Spill Date:	2000-08-06
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SACCACIO
Referred To:	Not reported
Reported to Dept:	2000-08-06
CID:	312
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-06
Spill Record Last Update:	2003-03-04
Spiller Name:	CALLER
Spiller Company:	ABC TRANSPORT
Spiller Address:	1 QUINBY ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	100526
DEC Memo:	""
Remarks:	"FD ON SCENE - CONTAINED - COMPANY WILL CLEANING THEMSELVES"

All Materials:

Site ID:	115362
Operable Unit ID:	826470
Operable Unit:	01
Material ID:	550142
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	40.00
Resource Affected:	Soil
Oxygenate:	Not reported

AB245 **3712 11TH STREET** **NY LTANKS** **S102672878**
WNW **3712 11TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.180 mi.
950 ft. **Site 3 of 7 in cluster AB**

Relative: **Lower**
Actual: **14 ft.**

LTANKS:

Name:	3712 11TH STREET
Address:	3712 11TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9416667 / 1995-03-24
Facility ID:	9416667
Site ID:	313687
Spill Date:	1995-03-24
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1995-03-24
SWIS:	4101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1995-03-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-04-27
Spill Record Last Update:	1995-05-01
Spiller Name:	Not reported
Spiller Company:	OIL COMPANY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	252926
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was C. TOMASELLO "
Remarks:	"OUTSIDE SPILL SPEEDY DRY APPLIED."

All Materials:

Site ID:	313687
Operable Unit ID:	1013781
Operable Unit:	01
Material ID:	371814
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

V246 **LUIS WINSTON INC** **RCRA NonGen / NLR** **1004760942**
WSW **38-66 13TH ST** **FINDS** **NYR000066290**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.180 mi.
952 ft. **Site 11 of 16 in cluster V**

Relative:
Higher

Actual:
17 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Luis Winston Inc
Handler Address:	38-66 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000066290
Contact Name:	STEVE HESS
Contact Address:	ASTORIA BLVD
Contact City,State,Zip:	ASTORIA, NY 11102
Contact Telephone:	718-267-7320
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	ASTORIA BLVD
Mailing City,State,Zip:	ASTORIA, NY 11102
Owner Name:	Hess & Hess Realty
Owner Type:	Private
Operator Name:	Hess & Hess Realty
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

LUIS WINSTON INC (Continued) **1004760942**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: HESS & HESS REALTY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	14-30 ASTORIA BLVD
Owner/Operator City,State,Zip:	ASTORIA, NY 11102
Owner/Operator Telephone:	718-267-7320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: HESS & HESS REALTY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	14-30 ASTORIA BLVD
Owner/Operator City,State,Zip:	ASTORIA, NY 11102
Owner/Operator Telephone:	718-267-7320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: HESS & HESS REALTY	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	14-30 ASTORIA BLVD
Owner/Operator City,State,Zip:	ASTORIA, NY 11102
Owner/Operator Telephone:	718-267-7320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported

LUIS WINSTON INC (Continued) **1004760942**

Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: LUIS WINSTON INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LUIS WINSTON INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19990128
Handler Name: LUIS WINSTON INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004550600

LUIS WINSTON INC (Continued) **1004760942**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004760942
Registry ID:	110004550600
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004550600
Name:	LUIS WINSTON INC
Address:	38-66 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

AB247 **CON EDISON** **NJ MANIFEST** **S120673807**
WNW **37-10 11TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.182 mi.
961 ft. **Site 4 of 7 in cluster AB**

Relative:
Lower

Actual:
14 ft.

NJ MANIFEST:

EPA Id:	NYP004805909
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002619698GBF
EPA ID:	NYP004805909
Date Shipped:	7/13/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

CON EDISON (Continued) **S120673807**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AB248 **CON EDISON** **RCRA NonGen / NLR** **1019905104**
WNW **37-10 11TH ST** **FINDS** **NYP004805909**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.182 mi.
961 ft. **Site 5 of 7 in cluster AB**

Relative: **Lower**
Actual: **14 ft.**

RCRA Listings:

Date Form Received by Agency:	20150713
Handler Name:	Con Edison
Handler Address:	37-10 11TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004805909
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny

CON EDISON (Continued) **1019905104**

State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150713
Handler Name: CON EDISON	
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON (Continued) **1019905104**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20150713
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069667685

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019905104
Registry ID:	110069667685
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069667685
Name:	CON EDISON
Address:	37-10 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

AB249 **CON EDISON** **NY MANIFEST** **S119076444**
WNW **37-10 11TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.182 mi.
961 ft. **Site 6 of 7 in cluster AB**

Relative:
Lower

Actual:
14 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	37-10 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004805909
Facility Status:	Not reported
Location Address 1:	OPP 37-10 11TH ST
Code:	BP
Location Address 2:	SB 48830
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004805909
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	07/13/2015
Trans1 Recv Date:	07/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004805909
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002619698GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S119076444**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE250 **25-05 37TH AVE** **NY LTANKS** **S103824906**
ESE **25-05 37TH AVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.183 mi.
966 ft. **Site 2 of 6 in cluster AE**

Relative: **Higher**
Actual: **26 ft.**

LTANKS:

Name:	25-05 37TH AVE
Address:	25-05 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9301138 / 2005-03-14
Facility ID:	9301138
Site ID:	150419
Spill Date:	1993-04-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1993-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-27
Spill Record Last Update:	2005-03-14

25-05 37TH AVE (Continued) **S103824906**

Spiller Name:	Not reported
Spiller Company:	NYC BOARD OF EDUCATION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127909
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN 7/6/04 - AUSTIN - TRANSFERRRED FROM KOON TANG FOR REASSIGNMENT - END 3/14/05 - Austin - spill closed and consolidated with spill #9900152 - end"
Remarks:	""

All TTF:

Facility ID:	9301138
Spill Number:	9301138
Spill Tank Test:	1541450
Site ID:	150419
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	150419
Operable Unit ID:	979735
Operable Unit:	01
Material ID:	401864
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	PS #112
Address:	25-05 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9900152 / 2006-01-05
Facility ID:	9900152
Site ID:	150420
Spill Date:	1999-04-05

25-05 37TH AVE (Continued) **S103824906**

Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	AJWHITE
Referred To:	Not reported
Reported to Dept:	1999-04-05
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-05
Spill Record Last Update:	2006-01-05
Spiller Name:	CHARLIE GRUDER
Spiller Company:	PS #112
Spiller Address:	25-05 37TH AVE
Spiller County:	001
Spiller Contact:	CHARLIE GRUDER
Spiller Phone:	(516) 873-3854
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127909
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE 7/15/05 - Mike H left message at Board of Education - also spoke with Albert Cardino (718-784-5250), School Fireman and in charge of fuel oil tanks. On 9/2 - Bob C - spoke with Al Cardino, who said to call the school custodian (Tom Logan) at 718-937-8214, who would have the records and could fax them. Called Tom on 9/7 & left message. 11/15/2005: Lead transfered to Joe White as part of the Spill Initiaative Project. 12/08/2005: Mr. James Merlo contacted Joe White and is checking to see if a new tank test has been performed on this tank. He will provide documentation so spill can be closed. 1/5/2006: Tha associated PBS# 2-478741 indicates that the tanks 001 and 002 have ben closed in place as of 6/1/2001. The remaining tank 003 is an above ground tank that does not require a tank test. Given that the spill was a tank failure and the underground tanks are no longer in service I am closing out this spill -------- joe white "
Remarks:	""

All Materials:

Site ID:	150420
Operable Unit ID:	1078941
Operable Unit:	01
Material ID:	307294
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

25-05 37TH AVE (Continued) **S103824906**

Name:	PS #112
Address:	25-05 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9900153 / 2004-01-15
Facility ID:	9900153
Site ID:	150421
Spill Date:	1999-04-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1999-04-05
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-05
Spill Record Last Update:	2004-01-15
Spiller Name:	CHARLIE GRUDER
Spiller Company:	PS #12
Spiller Address:	25-05 37TH AVE
Spiller County:	001
Spiller Contact:	CHARLIE GRUDER
Spiller Phone:	(516) 873-3854
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127909
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"Duplicate spill. See original spill # 9900152. YK. "

All Materials:

Site ID:	150421
Operable Unit ID:	1078943
Operable Unit:	01
Material ID:	307295
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AE251 **NYC DEPT OF EDUCATION - PS 112Q** **RCRA-SQG** **1005417307**
ESE **25-05 37TH AVE** **FINDS** **NYR000104331**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.183 mi. **NY MANIFEST**
966 ft. **Site 3 of 6 in cluster AE**

Relative: **Higher**
Actual: **26 ft.**

RCRA Listings:

Date Form Received by Agency:	20141021
Handler Name:	Nyc Dept Of Education - Ps 112q
Handler Address:	25-05 37TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000104331
Contact Name:	ALEXANDER LEMPERT
Contact Address:	THOMSON AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-472-8501
Contact Fax:	718-472-8500
Contact Email:	ALEMPERT@NYCSCA.ORG
Contact Title:	DIRECTOR
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	THOMSON AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Nyc Dept Of Education
Owner Type:	Municipal
Operator Name:	Nyc Dept Of School Facilities
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

NYC DEPT OF EDUCATION - PS 112Q (Continued) **1005417307**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141204
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-391-6475
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: NYC DEPT OF SCHOOL FACILITIES	
Legal Status:	Municipal
Date Became Current:	19530317
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name: NYC BOARD OF EDUCATION	
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2811 QUEENS PLZ N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101

NYC DEPT OF EDUCATION - PS 112Q (Continued) **1005417307**

Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC BOARD OF EDUCATION
Legal Status: Municipal
Date Became Current: 20010101
Date Ended Current: Not reported
Owner/Operator Address: 2811 QUEENS PLZ N
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-391-6475
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NYC DEPT OF EDUCATION
Legal Status: Municipal
Date Became Current: 19530317
Date Ended Current: Not reported
Owner/Operator Address: 30-30 THOMSON AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-472-8501
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 112Q
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: NYC BD OF ED - PUBLIC SCHOOL 112Q
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020301

NYC DEPT OF EDUCATION - PS 112Q (Continued) **1005417307**

Handler Name: NYC BD OF ED - PUBLIC SCHOOL 112Q
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20141021
Handler Name: NYC DEPT OF EDUCATION - PS 112Q
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 611110
NAICS Description: ELEMENTARY AND SECONDARY SCHOOLS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012262666

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and

NYC DEPT OF EDUCATION - PS 112Q (Continued) **1005417307**

it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1005417307
Registry ID:	110012262666
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012262666
Name:	P S 112 DUTCH KILLS SCHOOL
Address:	25-05 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	NYC BOARD OF EDUCATION
Address:	25-05 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000104331
Facility Status:	Not reported
Location Address 1:	25-05 37TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000104331
Mailing Name:	NYC BOARD OF EDUCATION
Mailing Contact:	N/S
Mailing Address 1:	25-05 37TH AVE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187267917

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	09/28/2017
Trans1 Recv Date:	09/28/2017
Trans2 Recv Date:	Not reported

NYC DEPT OF EDUCATION - PS 112Q (Continued) **1005417307**

TSD Site Recv Date:	10/06/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000104331
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	009436769FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	31
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AE252 **PUBLIC SCHOOL 112 - QUEENS (Q112)** **NY AST** **U001840906**
ESE **25-05 37TH AVENUE** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.183 mi.
967 ft. **Site 4 of 6 in cluster AE**

Relative: **Higher**
Actual: **26 ft.**

AST:

Name:	PUBLIC SCHOOL 112 - QUEENS (Q112)
Address:	25-05 37TH AVENUE
City,State,Zip:	QUEENS, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-478741
Program Type:	PBS
UTM X:	589935.56984
UTM Y:	4512324.57513
Expiration Date:	12/01/2024

PUBLIC SCHOOL 112 - QUEENS (Q112) (Continued) **U001840906**

Site Type: School

Affiliation Records:

Site Id: 21290
Affiliation Type: Facility Owner
Company Name: NEW YORK CITY DEPT. OF EDUCATION
Contact Type: MANAGER, FUEL DIVISION
Contact Name: JOSEPH YOUNGHESE
Address1: 44-36 VERNON BOULVARD
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5751
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-11

Site Id: 21290
Affiliation Type: Mail Contact
Company Name: N Y C DEPARTMENT OF EDUCATION
Contact Type: Not reported
Contact Name: JOSEPH YOUNGHESE
Address1: FIELD OPERATIONS-FUEL DIVISION
Address2: 44-36 VERNON BOULVARD
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 349-5779
EMail: JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2021-01-11

Site Id: 21290
Affiliation Type: Facility Operator
Company Name: PUBLIC SCHOOL 112 - QUEENS (Q112)
Contact Type: Not reported
Contact Name: PETER SCHUMACHER
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 937-8214
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-11

Site Id: 21290
Affiliation Type: Emergency Contact
Company Name: NEW YORK CITY DEPT. OF EDUCATION
Contact Type: Not reported

PUBLIC SCHOOL 112 - QUEENS (Q112) (Continued) **U001840906**

Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2022-03-28

Tank Info:

Tank Number:	003
Tank Id:	61313
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G02 - Tank Secondary Containment - Vault (w/access)
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
	H01 - Tank Leak Detection - Interstitial - Electronic Monitoring
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	I04 - Overfill - Product Level Gauge (A/G)
	C01 - Pipe Location - Aboveground
	J02 - Dispenser - Suction Dispenser
	I02 - Overfill - High Level Alarm
	K01 - Spill Prevention - Catch Basin
	E00 - Piping Secondary Containment - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/01/2001
Capacity Gallons:	5000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AE253 **PUBLIC SCHOOL 112 - QUEENS (Q112)** **NY UST** **U004077843**
ESE **25-05 37TH AVENUE** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.183 mi.
967 ft. **Site 5 of 6 in cluster AE**

Relative:
Higher

Actual:
26 ft.

UST:

Name:	PUBLIC SCHOOL 112 - QUEENS (Q112)
Address:	25-05 37TH AVENUE
City,State,Zip:	QUEENS, NY 11106
Id/Status:	2-478741 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	12/01/2024
UTM X:	589935.56984
UTM Y:	4512324.57513
Site Type:	School

Affiliation Records:

Site Id:	21290
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPT. OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	JOSEPH YOUNGHESE
Address1:	44-36 VERNON BOULVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5751
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-11

Site Id:	21290
Affiliation Type:	Mail Contact
Company Name:	N Y C DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-11

Site Id:	21290
Affiliation Type:	Facility Operator
Company Name:	PUBLIC SCHOOL 112 - QUEENS (Q112)
Contact Type:	Not reported
Contact Name:	PETER SCHUMACHER
Address1:	Not reported

PUBLIC SCHOOL 112 - QUEENS (Q112) (Continued) **U004077843**

Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-8214
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-11

Site Id:	21290
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPT. OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2022-03-28

Tank Info:

Tank Number:	001
Tank ID:	38562
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	06/01/2001
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty

Tightness Test Method:	03
Date Test:	04/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
I04 - Overfill - Product Level Gauge (A/G)
C03 - Pipe Location - Aboveground/Underground Combination

PUBLIC SCHOOL 112 - QUEENS (Q112) (Continued) **U004077843**

G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None

Tank Number:	002
Tank ID:	38563
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	10000
Install Date:	Not reported
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	11
Date Test:	11/01/1993
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
A00 - Tank Internal Protection - None
I04 - Overfill - Product Level Gauge (A/G)
J02 - Dispenser - Suction Dispenser
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
H00 - Tank Leak Detection - None

Z254 **ST RITA RECTORY** **NY UST** **U001832035**
NW **36-25 11 ST** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.184 mi.
974 ft. **Site 2 of 2 in cluster Z**

Relative: **Lower**
Actual: **14 ft.**

UST:

Name:	ST RITA RECTORY
Address:	36-25 11 ST
City,State,Zip:	ASTORIA, NY 11106
Id/Status:	2-085081 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	03/24/2027
UTM X:	589459.82972
UTM Y:	4512736.79316
Site Type:	Other

Affiliation Records:

Site Id:	2018
Affiliation Type:	Facility Owner

ST RITA RECTORY (Continued) **U001832035**

Company Name:	ST RITA RECTORY
Contact Type:	PASTOR
Contact Name:	REV JOSE CARLOS DASILVA
Address1:	36-25 11 ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Site Id:	2018
Affiliation Type:	Facility Operator
Company Name:	ST RITA RECTORY
Contact Type:	Not reported
Contact Name:	TIAGO MARTINS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-02-27

Site Id:	2018
Affiliation Type:	Emergency Contact
Company Name:	ST RITA RECTORY
Contact Type:	Not reported
Contact Name:	JOSE CARLOS DESILVA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 361-1884
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DMPOKRZY
Date Last Modified:	2017-04-12

Site Id:	2018
Affiliation Type:	Mail Contact
Company Name:	ST. RITA R.C. CHURCH
Contact Type:	Not reported
Contact Name:	REV JOSE CARLOS DASILVA
Address1:	36-25 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY

ST RITA RECTORY (Continued) **U001832035**

State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 361-1884
EMail:	RECTORY@STRITALIC.ORG
Fax Number:	Not reported
Modified By:	BVCAMPBE
Date Last Modified:	2012-02-27

Tank Info:

Tank Number:	001
Tank ID:	3279
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	7500
Install Date:	01/01/1966
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	21
Date Test:	06/06/2012
Next Test Date:	10/11/2016
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C02 - Pipe Location - Underground/On-ground
F06 - Pipe External Protection - Wrapped
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I05 - Overfill - Vent Whistle
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Y255 **37-27 CRESCENT ST** **NY AST** **U003384606**
SE **37-27 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.187 mi.
989 ft. **Site 3 of 5 in cluster Y**

Relative:
Higher

Actual:
37 ft.

AST:

Name:	37-27 CRESCENT ST
Address:	37-27 CRESCENT ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-114464
Program Type:	PBS

37-27 CRESCENT ST (Continued) **U003384606**

UTM X: 589885.81830
UTM Y: 4512237.47441
Expiration Date: 05/10/2025
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 3743
Affiliation Type: Mail Contact
Company Name: KINGDOM CRESCENT REALTY
Contact Type: Not reported
Contact Name: DOMINIC CASAMENTO
Address1: 14-38 31 DRIVE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11106
Country Code: 001
Phone: (201) 259-1434
EMail: DCANDS@AOL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-02-12

Site Id: 3743
Affiliation Type: Facility Operator
Company Name: 37-27 CRESCENT ST
Contact Type: Not reported
Contact Name: RAGIB CJONBALAJ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (646) 327-1634
EMail: Not reported
Fax Number: Not reported
Modified By: DXLIVING
Date Last Modified: 2007-05-15

Site Id: 3743
Affiliation Type: Emergency Contact
Company Name: KINGDOM CRESCENT REALTY
Contact Type: Not reported
Contact Name: DOMINIC CASAMENTO
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (201) 259-1434
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2012-12-07

Site Id: 3743

37-27 CRESCENT ST (Continued) **U003384606**

Affiliation Type:	Facility Owner
Company Name:	KINGDOM CRESCENT REALTY
Contact Type:	OWNER
Contact Name:	DOMINIC CASAMENTO
Address1:	14-38 31 DRIVE
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(201) 259-1434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-02-12

Tank Info:

Tank Number:	001
Tank Id:	4091
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	H99 - Tank Leak Detection - Other
	L09 - Piping Leak Detection - Exempt Suction Piping
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	G99 - Tank Secondary Containment - Other
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	J02 - Dispenser - Suction Dispenser
	I04 - Overfill - Product Level Gauge (A/G)
Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	12/01/1950
Capacity Gallons:	2500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AE256 **37-23 CRESCENT AVENUE** **NY LTANKS** **S102672660**
SE **37-23 CRESCENT AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.188 mi.
991 ft. **Site 6 of 6 in cluster AE**

Relative:
Higher

Actual:
35 ft.

LTANKS:

Name:	37-23 CRESCENT AVENUE
Address:	37-23 CRESCENT AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9410285 / 1994-11-02
Facility ID:	9410285
Site ID:	77942
Spill Date:	1994-11-02
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1994-11-02
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1994-11-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-12-05
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	KEVIN BROWN-RES
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	72628
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"SPILL ON CONCRETE AT FILL-CLEAN UP BY DRIVER."

All Materials:

Site ID:	77942
Operable Unit ID:	1008050
Operable Unit:	01
Material ID:	376158
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AD257 **CON EDISON - SERVICE BOX M14578** **NY MANIFEST** **S121968596**
East **36-24 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.188 mi.
992 ft. **Site 2 of 3 in cluster AD**

Relative:
Higher

Actual:
24 ft.

NY MANIFEST:

Name:	CON EDISON - SERVICE BOX M14578
Address:	36-24 CRESCENT ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYP005132196
Facility Status:	Not reported
Location Address 1:	36-24 CRESCENT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP005132196
Mailing Name:	CON EDISON - SERVICE BOX M14578
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AD258 **CON EDISON - SERVICE BOX M14578** **RCRA-LQG** **1024891665**
East **36-24 CRESCENT ST** **NYP005132196**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.188 mi.
992 ft. **Site 3 of 3 in cluster AD**

Relative:
Higher

Actual:
24 ft.

RCRA Listings:

Date Form Received by Agency:	20180410
Handler Name:	Con Edison - Service Box M14578
Handler Address:	36-24 CRESCENT ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYP005132196
Contact Name:	ALYSSA SOTTO
Contact Address:	IRVING PLACE, 15TH FL NE
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-2757
Contact Fax:	Not reported
Contact Email:	SOTTOA@CONED.COM
Contact Title:	ASSOCIATE SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2017

CON EDISON - SERVICE BOX M14578 (Continued) **1024891665**

Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PLACE, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Consolidated Edison Company Of Ny, Inc.
Owner Type:	Private
Operator Name:	Consolidated Edison Company Of Ny, Inc.
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20181106
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2017

Click Here for Biennial Reporting System Data:

CON EDISON - SERVICE BOX M14578 (Continued) **1024891665**

Hazardous Waste Summary:
Waste Code: D008
Waste Description: Lead

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170829
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 20170829
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: 212-460-2757
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20180410
Handler Name: CON EDISON - SERVICE BOX M14578
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

V259 **BEST DDK CLEANERS** **NY BROWNFIELDS** **S127990262**
WSW **38-68 13TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.188 mi.
993 ft. **Site 12 of 16 in cluster V**

Relative: **Higher**

Actual: **17 ft.**

BROWNFIELDS:

Name:	BEST DDK CLEANERS
Address:	38-68 13TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	617151
Acres:	0.110
HW Code:	C241126
SWIS:	4101
Town:	New York City
Record Added Date:	03/16/2021
Record Updated Date:	09/03/2021
Update By:	AMSERVIS
Site Description:	"Location: The Best DDK Cleaner site is located in an urban area on 13th street in Long Island City, New York. Site Features: The site is relatively flat and includes no buildings except brick walls on three sides and a gate at the front which restricts access to the side. The site is covered by a concrete floor. Current Zoning and Land Use: The site is currently vacant except for vehicle parking. The site is zoned M1-3 for industrial and manufacturing use. The surrounding parcels are used for a combination of commercial and industrial uses. Past Use of the Site: The site has been vacant since a fire occurred in 2016. The site was a residential building with garages beginning in 1898. From 1947 to 1950, the site was vacant, after which it was used for sheet metal work from 1967 to 1983. The site was converted to a commercial dry -leaning facility in 1997. The one story building dry-cleaning building consisted of slab on grade construction with a small sub-cellar in the front of the building which housed the boiler. The building contained dry cleaning machines, garment storage area, storage, office, customer service area, and a bathroom. The building covered the entire footprint of the site. The facility operated three 4th generation dry cleaning machines on a secondary containment concrete slab, five washers and a dryer, a spotting stand, ten press machines, three sets of shirt machines, four air compressors, two refrigerated dryers and a sump. In April 2016, a fire caused signification structural damage to the building and contents. Site Geology and Hydrogeology: Subsurface soil at the site consists of historic fill characterized by sand comingled with brick and coal ash to a depth of up to 10 feet, followed by native sand and silt. Refusal (possible bedrock) was encountered between 14 and 20 feet below grade. Groundwater was encountered at depths of 8.5 9.5 ft below ground surface. The groundwater flow direction is west-northwest towards the East River, which is located approximately 2000 feet from the site. "
Env Problem:	"Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available."
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	True
Lagoon:	False

BEST DDK CLEANERS (Continued) **S127990262**

Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-08-27 14:09:00
Record Upd:	2021-08-27 14:09:00
Updated By:	JHOCONNE
Own Op:	1
Sub Type:	P02
Owner Name:	Maryuhn Young Moon
Owner Company:	Best DDK Cleaners
Owner Address:	105 Reldyes Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Leonia, NY 07605
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Maryuhn Young Moon
Owner Company:	n/a
Owner Address:	105 Reldyes Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Leonia, NJ 07605
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

V260 **D D K PRO CLEANERS** **RCRA-SQG** **1012186566**
WSW **38-68 13TH ST** **NY MANIFEST** **NYR000164277**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **RI MANIFEST**
0.188 mi.
993 ft. **Site 13 of 16 in cluster V**

Relative: **Higher**

Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20090429
Handler Name:	D D K Pro Cleaners
Handler Address:	38-68 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000164277
Contact Name:	YONG KEN WU
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-784-2407
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator

D D K PRO CLEANERS (Continued) **1012186566**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Wen Xiu Wu
Owner Type:	Private
Operator Name:	Yong Ken Wu
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D007
Waste Description:	Chromium

D D K PRO CLEANERS (Continued) **1012186566**

Waste Code: D029
Waste Description: 1,1-Dichloroethylene

Waste Code: D039
Waste Description: Tetrachloroethylene

Waste Code: D040
Waste Description: Trichlorethylene

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: WEN XIU WU	
Legal Status:	Private
Date Became Current:	20090401
Date Ended Current:	Not reported
Owner/Operator Address:	25-10 150TH ST
Owner/Operator City,State,Zip:	FLUSHING, NY 11354
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: YONG KEN WU	
Legal Status:	Private
Date Became Current:	20090401
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20090429
Handler Name: D D K PRO CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

D D K PRO CLEANERS (Continued) **1012186566**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111012
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111007
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012

D D K PRO CLEANERS (Continued) **1012186566**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111007
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

D D K PRO CLEANERS (Continued) **1012186566**

SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20110930
Actual Return to Compliance Date:	20111012
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20111012
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20110930
Actual Return to Compliance Date:	20111007
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20111012

D D K PRO CLEANERS (Continued) **1012186566**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111007
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

D D K PRO CLEANERS (Continued) **1012186566**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111012
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111109
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012

D D K PRO CLEANERS (Continued) **1012186566**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111007
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

D D K PRO CLEANERS (Continued) **1012186566**

SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	20110930
Actual Return to Compliance Date:	20111007
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20111012
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20110930
Actual Return to Compliance Date:	20111007
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20111012

D D K PRO CLEANERS (Continued) **1012186566**

Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: LDR - General
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111109
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

D D K PRO CLEANERS (Continued) **1012186566**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: State Statute or Regulation
Date Violation was Determined: 20110930
Actual Return to Compliance Date: 20111109
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20111012
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20110930
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20111012
Scheduled Compliance Date: Not reported
Date of Request: Not reported

D D K PRO CLEANERS (Continued) **1012186566**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111012
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930

D D K PRO CLEANERS (Continued) **1012186566**

Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111012
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2

D D K PRO CLEANERS (Continued) **1012186566**

Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111007
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110930
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20111109
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

NY MANIFEST:

Name:	D D K PRO CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000164277
Facility Status:	Not reported
Location Address 1:	38-68 13TH ST
Code:	BP
Location Address 2:	Not reported

D D K PRO CLEANERS (Continued) **1012186566**

Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000164277
Mailing Name:	D D K PRO CLEANERS
Mailing Contact:	KYAW
Mailing Address 1:	38-68 13TH ST
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187842407

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	12/08/2010
Trans1 Recv Date:	12/08/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000164277
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID084802842
TSDF ID 2:	Not reported
Manifest Tracking Number:	003785022FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1330
Units:	P - Pounds

D D K PRO CLEANERS (Continued) **1012186566**

Number of Containers:	7
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D029
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

RI MANIFEST:

Name:	DDK PROCLEANER
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA Id:	NYR000164277
GEN Cert Date:	5/7/2012
Manifest Document Number:	002747056SKS
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	240
WT/Vol Units:	P
TSDF Date:	5/11/2012
Transporter 2 Id:	NJD071629976
Item Number:	1
Transporter 2 Name:	5/11/2012
Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	5/7/2012
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

D D K PRO CLEANERS (Continued) **1012186566**

RI MANIFEST:

Transporter Receipt Date:	7/11/2012
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207459SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	240
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	3
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	7/11/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	7/16/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	7/16/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Transporter Receipt Date:	6/1/2012
Number Of Containers:	6
Container Type:	DM
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported

D D K PRO CLEANERS (Continued) **1012186566**

Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207291SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	660
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	3
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/1/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	6/12/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	6/12/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	5/7/2012
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	002747056SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	240
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported

D D K PRO CLEANERS (Continued) **1012186566**

Time Paid:	Not reported
GEN Cert Date:	5/7/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	5/11/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	5/11/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	6/1/2012
Number Of Containers:	2
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207291SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	120
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/1/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	6/12/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	6/12/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	6/1/2012
Number Of Containers:	5
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039

D D K PRO CLEANERS (Continued) **1012186566**

Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207291SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	550
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	6/1/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	6/12/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	6/12/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	10/11/2012
Number Of Containers:	3
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003309458SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	330

D D K PRO CLEANERS (Continued) **1012186566**

Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/11/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	10/19/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	10/19/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	10/11/2012
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003309458SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	240
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	10/11/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	10/19/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	10/19/2012

D D K PRO CLEANERS (Continued) **1012186566**

Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	7/11/2012
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D029
Waste Code2:	D039
Waste Code3:	D040
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207459SKS
Quarter:	Not reported
Waste Description:	HAZARDOUS WASTE LIQUID NOS
Transporter Contact Name:	Not reported
Quantity:	80
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	7/11/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	7/16/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	7/16/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	7/11/2012
Number Of Containers:	5
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842

D D K PRO CLEANERS (Continued) **1012186566**

Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	003207459SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	550
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	7/11/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	7/16/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	7/16/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/12/2012
Number Of Containers:	1
Container Type:	DF
Waste Code1:	D029
Waste Code2:	D039
Waste Code3:	D040
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	002595134SKS
Quarter:	Not reported
Waste Description:	HAZARDOUS WASTE LIQUID NOS
Transporter Contact Name:	Not reported
Quantity:	80
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported

D D K PRO CLEANERS (Continued) **1012186566**

Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/12/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/19/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/19/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	1/12/2012
Number Of Containers:	6
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYR000164277
Manifest Docket Number:	002595134SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	660
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	1/12/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/19/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/19/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Click this hyperlink while viewing on your computer to access
14 additional RI_MANIFEST: record(s) in the EDR Site Report.

V261 **BEST-DDK CLEANERS** **NY SHWS** **S109826034**
WSW **38-68 13TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.188 mi.
993 ft. **Site 14 of 16 in cluster V**

Relative: **Higher**

Actual: **17 ft.**

SHWS:
Name: BEST-DDK CLEANERS
Address: 38-68 13TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Program: HW
Site Code: 439625
Classification: N
Region: 2
Acres: 0.110
HW Code: 241126
Record Add: 09/08/2010
Record Upd: 12/10/2021
Updated By: JHOCONNE
Site Description: "Location: The site is a 0.11 acre lot located at 38 68 13th Street, between 38th Avenue and 40th Avenue in the Long Island City section of Queens, NY. Site Features: The site is relatively flat and includes no buildings except brick walls on three sides and a gate at the front which restricts access to the side. The site is covered by a concrete floor . Current Zoning and Land Use: The site is zoned M1-3 for industrial and manufacturing use. The surrounding parcels are currently used for a combination of commercial and light industrial. The site has been vacant since a fire in 2016. Past Use of the Site: The site was a residential building with garages beginning in 1898. From 1947 to 1950, the site was vacant, after which it was used for sheet metal work from 1967 1983. The site was converted to a commercial dry -leaning facility in 1997. The one story building dry-cleaning building consisted of slab on grade construction with a small sub-cellar in the front of the building which housed the boiler. The building contained dry cleaning machines, garment storage area, storage, office, customer service area, and a bathroom. The building covered the entire footprint of the site. The facility operated three 4th generation dry cleaning machines on a secondary containment concrete slab, five washers and a dryer, a spotting stand, ten press machines, three sets of shirt machines, four air compressors, two refrigerated dryers and a sump. In April 2016, a fire caused signification structural damage to the building and contents. Site Geology and Hydrogeology: Subsurface soil at the site consists of historic fill characterized by sand comingled with brick and coal ash to a depth of up to 10 feet, followed by native sand and silt. Refusal (possible bedrock) was encountered between 14 and 20 feet below grade. Groundwater was encountered at depths of 8.5 9.5 ft below ground surface. The groundwater flow direction is west-northwest towards the East River, which is located approximately 2000 feet from the site. This site is now being managed under the BCP site #C241126. "
Env Problem: "Nature and Extent of Contamination: Soil, groundwater and soil vapor were analyzed for volatile organic compounds (VOCs) as part of the site characterization. Based upon investigations conducted to date, the primary contaminants of concern include tetrachloroethene (PCE) and its degradation products. Soil PCE was found at a maximum concentration up to 490 parts per million (ppm) as compared to the commercial use soil cleanup objective (SCO) of 150 ppm and the protection of groundwater SCO of 1.3 ppm. Additional investigation is

BEST-DDK CLEANERS (Continued) **S109826034**

needed to fully delineate the extent of soil contamination. Groundwater PCE is found at a maximum concentration of 72,000 parts per billion (ppb) which exceeds the Ambient Water Quality Standard (AWQS) of 5 ppb; TCE was found at a maximum concentration of 150 ppb (AWQS is 5 ppb), and cis-1,2-dichloroethylene (cis-1,2-DCE) was found at a maximum concentration of 210 ppb (AWQS is 5 ppb). Data indicates the potential for off site impacts in groundwater related to this site. Sub slab Vapor Sub slab soil vapor samples were collected from beneath the existing remnant concrete floor. PCE was found at a maximum concentrations of 2,100,000 micrograms per cubic meter (g/m3), TCE was found at a maximum concentration of 14,000 g/m3 and cis-1,2-DCE is found at concentrations up to 95 g/m3. Data indicates the potential for off site impacts in soil vapor related to this site. "

Health Problem:	"As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	01
Owner Name:	Maryuhn Young Moon
Owner Company:	Best DDK Cleaners
Owner Address:	471 Tulane Court
Owner Addr2:	Not reported
Owner City,St,Zip:	Paramus, NJ 07654
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

V262 **LA MODE QUEENS INC** **RCRA-SQG** **1000990232**
WSW **38-68 13TH ST** **US AIRS** **NYR000001917**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.188 mi.
993 ft. **Site 15 of 16 in cluster V**

Relative: **Higher**
Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	La Mode Queens Inc
Handler Address:	38-68 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000001917
Contact Name:	SUNG AHN
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-729-2844
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	La Mode Queens Inc
Owner Type:	Private
Operator Name:	La Mode Queens Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

LA MODE QUEENS INC (Continued) **1000990232**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220920
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: LA MODE QUEENS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-68 13TH ST
Owner/Operator City,State,Zip:	QUEENS, NY 11101
Owner/Operator Telephone:	718-729-2844
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: LA MODE QUEENS INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	38-68 13TH ST
Owner/Operator City,State,Zip:	QUEENS, NY 11101
Owner/Operator Telephone:	718-729-2844
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

LA MODE QUEENS INC (Continued) **1000990232**

Owner/Operator Indicator: Owner
Owner/Operator Name: LA MODE QUEENS INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 38-68 13TH ST
Owner/Operator City,State,Zip: QUEENS, NY 11101
Owner/Operator Telephone: 718-729-2844
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: LA MODE QUEENS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: LA MODE QUEENS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: Not reported
Recognized Trader Exporter: Not reported
Spent Lead Acid Battery Importer: Not reported
Spent Lead Acid Battery Exporter: Not reported
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19950317
Handler Name: LA MODE QUEENS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

LA MODE QUEENS INC (Continued) **1000990232**

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20000817
Actual Return to Compliance Date: 20001127
Return to Compliance Qualifier: Documented
Violation Responsible Agency: EPA
Scheduled Compliance Date: 20001126
Enforcement Identifier: 001
Date of Enforcement Action: 20001026
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2CFP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20000817
Evaluation Responsible Agency: EPA
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2CFP
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: 20001127
Scheduled Compliance Date: 20001126
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

US AIRS MINOR:
Envid: 1000990232

LA MODE QUEENS INC (Continued) **1000990232**

Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: Not reported
Activity Status Date: 2014-10-19 00:00:00
Activity Group: Case File
Activity Type: Case File
Activity Status: Case File Data Entered

Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2000-02-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2001-02-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-02-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

LA MODE QUEENS INC (Continued) **1000990232**

Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630401304
Facility Registry ID: 110008089031
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2001-02-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

NY MANIFEST:
Name: LAMODE QUEENS
Address: 38-68 13TH ST
City,State,Zip: QUEENS, NY 11101
Country: USA
EPA ID: NYR000001917
Facility Status: Not reported
Location Address 1: 38-68 13TH STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000001917
Mailing Name: LAMODE QUEENS
Mailing Contact: SUNS WON AHN
Mailing Address 1: 38-68 13TH ST
Mailing Address 2: Not reported
Mailing City: QUEENS
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7187292844

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD000564906
Trans2 State ID: Not reported
Generator Ship Date: 12/05/2006
Trans1 Recv Date: 12/05/2006
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/08/2006
Part A Recv Date: Not reported
Part B Recv Date: Not reported

LA MODE QUEENS INC (Continued) **1000990232**

Generator EPA ID:	NYR000001917
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CDX107000000
TSDF ID 2:	Not reported
Manifest Tracking Number:	001303386JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	520
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D039
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

V263 **BEST CLEANERS** **NY DRYCLEANERS** **S128782072**
WSW **38-68 13TH ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.188 mi.
993 ft. **Site 16 of 16 in cluster V**

Relative:
Higher

Actual:
17 ft.

DRYCLEANERS:

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2001-02-16 10:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported

BEST CLEANERS (Continued) **S128782072**

Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2004-05-12 14:33:43
Inspection Date: 2002-02-16 11:00:00
Install Date: Not reported
Expiration Date: 06/26/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2004-05-12 14:33:43
Inspection Date: 2003-02-21 09:00:00
Install Date: Not reported
Expiration Date: 06/26/2009
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2009-06-26 16:27:27
Inspection Date: 2010-02-12 08:30:00
Install Date: Not reported
Expiration Date: 05/02/2016
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2009-06-26 16:27:27

BEST CLEANERS (Continued) **S128782072**

Inspection Date:	2011-02-11 08:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2012-04-05 08:30:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2013-04-11 07:30:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2014-04-17 09:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

BEST CLEANERS (Continued) **S128782072**

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2015-04-16 08:30:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2008-02-12 08:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2001-02-16 10:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2002-02-16 11:00:00
Install Date:	Not reported

BEST CLEANERS (Continued) **S128782072**

Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2003-02-21 09:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2004-02-20 08:20:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2004-02-20 08:20:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST

BEST CLEANERS (Continued) **S128782072**

City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2005-02-17 09:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2006-02-14 08:30:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2007-02-13 09:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2008-02-12 08:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported

BEST CLEANERS (Continued) **S128782072**

Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2009-02-10 08:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2009-06-30 08:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2010-02-12 08:30:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304

BEST CLEANERS (Continued) **S128782072**

Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2011-02-11 08:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2012-04-05 08:30:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2013-04-11 07:30:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2014-04-17 09:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

BEST CLEANERS (Continued) **S128782072**

Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2015-04-16 08:30:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2000-02-18 13:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2001-02-16 10:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported

BEST CLEANERS (Continued) **S128782072**

Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2002-02-16 11:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2003-02-21 09:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2004-02-20 08:20:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2005-02-17 09:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

BEST CLEANERS (Continued) **S128782072**

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2006-02-14 08:30:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2007-02-13 09:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2008-02-12 08:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2009-02-10 08:00:00
Install Date:	Not reported

BEST CLEANERS (Continued) **S128782072**

Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2009-06-26 16:27:27
Inspection Date:	2009-06-30 08:00:00
Install Date:	Not reported
Expiration Date:	05/02/2016
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2005-02-17 09:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2006-02-14 08:30:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST

BEST CLEANERS (Continued) **S128782072**

City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2007-02-13 09:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2000-02-18 13:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2009-02-10 08:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2009-06-30 08:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported

BEST CLEANERS (Continued) **S128782072**

Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2000-12-14 11:07:52
Inspection Date: 2010-02-12 08:30:00
Install Date: Not reported
Expiration Date: 05/12/2004
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2000-12-14 11:07:52
Inspection Date: 2011-02-11 08:00:00
Install Date: Not reported
Expiration Date: 05/12/2004
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304
Phone Number: 7187292844
Region: Not reported
Registration Effective Date: 2000-12-14 11:07:52
Inspection Date: 2012-04-05 08:30:00
Install Date: Not reported
Expiration Date: 05/12/2004
Removal Date: Not reported
Drop Shop: Not reported
Shutdown: Not reported
Alternate Solvent: Not reported
Current Business: Not reported

Name: BEST CLEANERS
Address: 38-68 13TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101 6120
Facility ID: 2-6304-01304

BEST CLEANERS (Continued) **S128782072**

Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2013-04-11 07:30:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2014-04-17 09:00:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2000-12-14 11:07:52
Inspection Date:	2015-04-16 08:30:00
Install Date:	Not reported
Expiration Date:	05/12/2004
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported
Alternate Solvent:	Not reported
Current Business:	Not reported

Name:	BEST CLEANERS
Address:	38-68 13TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101 6120
Facility ID:	2-6304-01304
Phone Number:	7187292844
Region:	Not reported
Registration Effective Date:	2004-05-12 14:33:43
Inspection Date:	2000-02-18 13:00:00
Install Date:	Not reported
Expiration Date:	06/26/2009
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Not reported

BEST CLEANERS (Continued) **S128782072**

Alternate Solvent: Not reported
Current Business: Not reported

W264 **CON EDISON SERVICE BOX: 53255** **RCRA NonGen / NLR** **1016970648**
NNW **35-58 12TH ST** **NY MANIFEST** **NYP004443644**
1/8-1/4 **ASTORIA, NY 11106**
0.191 mi.
1010 ft. **Site 7 of 7 in cluster W**

Relative: **Lower**
Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	20140317
Handler Name:	Con Edison Service Box: 53255
Handler Address:	35-58 12TH ST
Handler City,State,Zip:	ASTORIA, NY 11106
EPA ID:	NYP004443644
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No

CON EDISON SERVICE BOX: 53255 (Continued) **1016970648**

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140217
Handler Name: CON EDISON SERVICE BOX:	53255
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140317
Handler Name: CON EDISON SERVICE BOX:	53255
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON SERVICE BOX: 53255 (Continued) **1016970648**

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON ED
Address:	35-58 12TH ST
City,State,Zip:	ASTORIA, NY 11106
Country:	USA
EPA ID:	NYP004443644
Facility Status:	Not reported
Location Address 1:	35-58 12 ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	ASTORIA
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004443644
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2014
Trans1 Recv Date:	02/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004443644
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002219759GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CON EDISON SERVICE BOX: 53255 (Continued) **1016970648**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	350
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Y265 **38-05 CRESCENT STREET** **NY AST** **U003127699**
SSE **38-05 CRESCENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.192 mi.
1014 ft. **Site 4 of 5 in cluster Y**

Relative:
Higher

Actual:
38 ft.

AST:

Name:	38-05 CRESCENT STREET
Address:	38-05 CRESCENT STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-249289
Program Type:	PBS
UTM X:	589831.00897
UTM Y:	4512182.22058
Expiration Date:	12/08/2021
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	9893
Affiliation Type:	Facility Operator
Company Name:	38-05 CRESCENT STREET
Contact Type:	Not reported
Contact Name:	JIMMY ESPINOZA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(212) 721-5500

38-05 CRESCENT STREET (Continued) **U003127699**

EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-05-17

Site Id: 9893
Affiliation Type: Emergency Contact
Company Name: 38-05 CRESCENT STREET, LLC
Contact Type: Not reported
Contact Name: RAFAEL LORA
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 932-2070
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-05-17

Site Id: 9893
Affiliation Type: Facility Owner
Company Name: 38-05 CRESCENT STREET, LLC
Contact Type: PROPERTY MANAGER
Contact Name: BRIAN GARLAND
Address1: 5 BRYANT PARK, 31ST FLOOR
Address2: Not reported
City: MANHATTAN
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 721-5500
EMail: Not reported
Fax Number: Not reported
Modified By: ACDANIEL
Date Last Modified: 2017-05-17

Site Id: 9893
Affiliation Type: Mail Contact
Company Name: A&E REAL ESTATE MANAGEMENT
Contact Type: Not reported
Contact Name: BRIAN GARLAND
Address1: 5 BRYANT PARK
Address2: 31ST FLOOR
City: NEW YORK
State: NY
Zip Code: 10018
Country Code: 001
Phone: (212) 721-5500
EMail: BRIAN.GARLAND@AE-RE.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2020-10-05

38-05 CRESCENT STREET (Continued) **U003127699**

Tank Info:

Tank Number:	001
Tank Id:	10386
Material Code:	0002
Common Name of Substance:	#4 Fuel Oil (On-Site Consumption)

Equipment Records:

L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/30/1989
Capacity Gallons:	5000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AB266 **10-12 37TH AVE** **NY LTANKS** **S102619664**
WNW **10-12 37TH AVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.197 mi.
1042 ft. **Site 7 of 7 in cluster AB**

Relative: LTANKS:
Lower

Actual:
14 ft.

Name:	10-12 37TH AVE
Address:	10-12 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9406565 / 1994-08-15
Facility ID:	9406565
Site ID:	132553
Spill Date:	1994-08-15
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	1994-08-15
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported

10-12 37TH AVE (Continued) **S102619664**

Reported to Dept:	1994-08-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-20
Spill Record Last Update:	2003-03-17
Spiller Name:	Not reported
Spiller Company:	MR. BHAQWARDIN-OWNER
Spiller Address:	10-12 37TH AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	114116
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"CONTAINED ON CONCRETE FLOOR- SORBENT APPLIED BY PETRO PERSONNEL."

All Materials:

Site ID:	132553
Operable Unit ID:	1000983
Operable Unit:	01
Material ID:	379601
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AC267 **CON EDISON** **NY MANIFEST** **S119077129**
SW **39-40 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.199 mi.
1052 ft. **Site 4 of 10 in cluster AC**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	39-40 21ST ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004821241
Facility Status:	Not reported
Location Address 1:	39-40 21ST ST
Code:	BP
Location Address 2:	SB 19245
Total Tanks:	Not reported
Location City:	QUEENS

CON EDISON (Continued) **S119077129**

Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004821241
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/10/2015
Trans1 Recv Date: 08/10/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 08/14/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004821241
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD991291105
TSDF ID 2: Not reported
Manifest Tracking Number: 002624781GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks

CON EDISON (Continued) **S119077129**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC268 **CON ED** **NY MANIFEST** **S118259495**
SW **39-40 21 ST** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.199 mi.
1052 ft. **Site 5 of 10 in cluster AC**

Relative:
Higher

Actual:
18 ft.

NY MANIFEST:

Name:	CON ED
Address:	39-40 21 ST
City,State,Zip:	QUEENS, NY 11101
Country:	USA
EPA ID:	NYP004832883
Facility Status:	Not reported
Location Address 1:	39-40 21 ST
Code:	BP
Location Address 2:	SB 19245
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004832883
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	09/01/2015
Trans1 Recv Date:	09/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/04/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON ED (Continued) **S118259495**

Generator EPA ID:	NYP004832883
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014470900JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC269 **CON EDISON** **RCRA NonGen / NLR** **1019906455**
SW **39-40 21ST ST** **NYP004821241**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.199 mi.
1052 ft. **Site 6 of 10 in cluster AC**

Relative:
Higher

Actual:
18 ft.

RCRA Listings:

Date Form Received by Agency:	20150901
Handler Name:	Con Edison
Handler Address:	39-40 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004821241
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

CON EDISON (Continued) **1019906455**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160909
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20150901

CON EDISON (Continued) **1019906455**

Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150901
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AC270 **CON EDISON** **NJ MANIFEST** **S120675221**
SW **39-40 21ST ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.199 mi.
1052 ft. **Site 7 of 10 in cluster AC**

Relative: **Higher**
Actual: **18 ft.**

NJ MANIFEST:
EPA Id: NYP004821241
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY081
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported

CON EDISON (Continued) **S120675221**

Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	002624781GBF
EPA ID:	NYP004821241
Date Shipped:	8/10/2015
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Y271 **ACCARDI ELECTRIC CO INC** **RCRA NonGen / NLR** **1000155056**
SE **25-10 38TH AVE** **FINDS** **NYD012316667**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.200 mi. **NY MANIFEST**
1054 ft. **Site 5 of 5 in cluster Y**

Relative: **Higher**

Actual: **40 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Accardi Electric Co Inc
Handler Address:	25-10 38TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101

ACCARDI ELECTRIC CO INC (Continued) **1000155056**

EPA ID:	NYD012316667
Contact Name:	JACK ACCARDI
Contact Address:	38TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-937-0330
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	38TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Accardi Electric Co Inc
Owner Type:	Private
Operator Name:	Accardi Electric Co Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No

ACCARDI ELECTRIC CO INC (Continued) **1000155056**

Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F004
Waste Description:	The Following Spent Nonhalogenated Solvents: Cresols, Cresylic Acid, And Nitrobenzene; And The Still Bottoms From The Recovery Of These Solvents; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ACCARDI ELECTRIC CO INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: ACCARDI ELECTRIC CO INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ACCARDI ELECTRIC CO INC	
Legal Status:	Private

ACCARDI ELECTRIC CO INC (Continued) **1000155056**

Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: ACCARDI ELECTRIC CO INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: ACCARDI ELECTRIC CO INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19891107
Handler Name: ACCARDI ELECTRIC CO INC	
Federal Waste Generator Description:	Not reported
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported

ACCARDI ELECTRIC CO INC (Continued) **1000155056**

Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19910516
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: SA
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004344148

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource

ACCARDI ELECTRIC CO INC (Continued) **1000155056**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000155056
Registry ID:	110004344148
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004344148
Name:	ACCARDI ELECTRIC CO INC
Address:	25-10 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	ACCARDI ELECTRIC MOTOR COMPANY
Address:	25-10 38TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYD012316667
Facility Status:	Not reported
Location Address 1:	25-10 38TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD012316667
Mailing Name:	ACCARDI ELECTRIC MOTOR COMPANY
Mailing Contact:	ACCARDI ELECTRIC MOTOR COMPANY
Mailing Address 1:	25-10 38TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189370330

AF272 **CON EDISON** **NY MANIFEST** **S117315246**
SSE **83-19 39 AVE** **N/A**
1/8-1/4 **QUEENS, NY 11377**
0.200 mi.
1055 ft. **Site 1 of 4 in cluster AF**

Relative:
Higher

Actual:
27 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	83-19 39 AVE
City,State,Zip:	QUEENS, NY 11377
Country:	USA

CON EDISON (Continued) **S117315246**

EPA ID:	NYP004623864
Facility Status:	Not reported
Location Address 1:	83-19 39 AVE
Code:	BP
Location Address 2:	SB 21690
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11377
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004623864
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/11/2014
Trans1 Recv Date:	08/11/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/11/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004623864
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616213GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S117315246**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG273 **CON EDISON GAS MAIN: MAIN** **RCRA NonGen / NLR** **1016963284**
WNW **37-47 10TH ST** **NY MANIFEST** **NYP004363057**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.201 mi.
1062 ft. **Site 1 of 2 in cluster AG**

Relative: **Lower**
Actual: **14 ft.**

RCRA Listings:

Date Form Received by Agency:	20131019
Handler Name:	Con Edison Gas Main: Main
Handler Address:	37-47 10TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004363057
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON GAS MAIN: MAIN (Continued) **1016963284**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20140701
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20130919
Handler Name:	CON EDISON GAS MAIN: MAIN
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20131019
Handler Name:	CON EDISON GAS MAIN: MAIN
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

CON EDISON GAS MAIN: MAIN (Continued) **1016963284**

Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 37-47 10TH ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYP004363057
Facility Status: Not reported
Location Address 1: 38TH AVE & 10TH ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004363057
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/19/2013
Trans1 Recv Date: 09/19/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/20/2013

CON EDISON GAS MAIN: MAIN (Continued) **1016963284**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004363057
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	004807406FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	6
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	B007
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC274 **WOODHAVEN FINISHING SERVICES** **RCRA NonGen / NLR** **1014472880**
SW **38-79 13TH ST** **NYN008023673**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.202 mi.
1065 ft. **Site 8 of 10 in cluster AC**

Relative: **Higher**

Actual: **17 ft.**

RCRA Listings:

Date Form Received by Agency:	20110322
Handler Name:	Woodhaven Finishing Services
Handler Address:	38-79 13TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYN008023673
Contact Name:	ALEX AGUDO
Contact Address:	13TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	PART-OWNER

WOODHAVEN FINISHING SERVICES (Continued) **1014472880**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	13TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

WOODHAVEN FINISHING SERVICES (Continued) **1014472880**

Historic Generators:

Receive Date:	20110322
Handler Name:	WOODHAVEN FINISHING SERVICES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

WOODHAVEN FINISHING SERVICES (Continued) **1014472880**

Evaluation Action Summary:

Evaluation Date:	20100413
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

AH275 **BETHEL WELDING** **RCRA NonGen / NLR** **1004762500**
WSW **38-59 12TH ST** **FINDS** **NYR000097568**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.205 mi.
1080 ft. **Site 1 of 5 in cluster AH**

Relative: **Lower**
Actual: **16 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Bethel Welding
Handler Address:	38-59 12TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101-6115
EPA ID:	NYR000097568
Contact Name:	DAL-YOUNG PAIK
Contact Address:	12TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101-6115
Contact Telephone:	718-361-2665
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	12TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101-6115
Owner Name:	Joseph Seung Paik
Owner Type:	Private
Operator Name:	Joseph Seung Paik
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

BETHEL WELDING (Continued) **1004762500**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	Corrosive Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: JOSEPH SEUNG PAIK	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported
Owner/Operator Address:	38-59 12TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101-6115
Owner/Operator Telephone:	718-707-9393
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: JOSEPH SEUNG PAIK	
Legal Status:	Private
Date Became Current:	20010101
Date Ended Current:	Not reported

BETHEL WELDING (Continued) **1004762500**

Owner/Operator Address: 38-59 12TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101-6115
Owner/Operator Telephone: 718-707-9393
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: JOSEPH SEUNG PAIK
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 38-59 12TH ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101-6115
Owner/Operator Telephone: 718-707-9393
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: BETHEL WELDING
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: BETHEL WELDING
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010531
Handler Name: BETHEL WELDING
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

BETHEL WELDING (Continued) **1004762500**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110006539932

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762500
Registry ID:	110006539932
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006539932
Name:	BETHEL WELDING
Address:	38-59 12TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

AF276 **ORKIN PEST CONTROL CO INC** **RCRA NonGen / NLR** **1000791313**
SSE **38-31 CRESCENT ST** **NYD987028198**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.209 mi.
1104 ft. **Site 2 of 4 in cluster AF**

Relative: Higher
Actual: 33 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Orkin Pest Control Co Inc
Handler Address:	38-31 CRESCENT ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD987028198
Contact Name:	ROBERT HAMPTON
Contact Address:	CRESCENT ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	404-888-2624
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	CRESCENT ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	William Konz
Owner Type:	Private
Operator Name:	William Konz
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:
Waste Code: D000

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: U129
Waste Description: Cyclohexane, 1,2,3,4,5,6-Hexachloro-, (1alpha, 2alpha, 3beta, 4alpha, 5alpha, 6beta)- (Or) Lindane

Waste Code: U240
Waste Description: 2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: WILLIAM KONZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1825 MOORING LINE DR #2E
Owner/Operator City,State,Zip: VERO BEACH, FL 32963
Owner/Operator Telephone: 305-234-4903
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WILLIAM KONZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1825 MOORING LINE DR #2E
Owner/Operator City,State,Zip: VERO BEACH, FL 32963
Owner/Operator Telephone: 305-234-4903
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WILLIAM KONZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 1825 MOORING LINE DR #2E
Owner/Operator City,State,Zip: VERO BEACH, FL 32963
Owner/Operator Telephone: 305-234-4903
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: ORKIN PEST CONTROL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ORKIN PEST CONTROL CO INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930217
Handler Name: ORKIN PEST CONTROL CO INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19950106
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MH
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19950106
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	R2MH

ORKIN PEST CONTROL CO INC (Continued) **1000791313**

Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19980728
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

AF277 **ORKIN** **NY MANIFEST** **1009232670**
SSE **38-31 CRESENT STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.209 mi.
1104 ft. **Site 3 of 4 in cluster AF**

Relative:
Higher

Actual:
33 ft.

NY MANIFEST:

Name:	ORKIN
Address:	38-31 CRESENT STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP000886580
Facility Status:	Not reported
Location Address 1:	38-31 CRESENT STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000886580
Mailing Name:	ORKIN
Mailing Contact:	ORKIN
Mailing Address 1:	38-31 CRESENT STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183612750

AF278 **38-31 CRESCENT ST** **NY LTANKS** **S105230180**
SSE **38-31 CRESCENT ST** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.210 mi.
1108 ft. **Site 4 of 4 in cluster AF**

Relative:
Higher

Actual:
33 ft.

LTANKS:

Name:	38-31 CRESCENT ST
Address:	38-31 CRESCENT ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0011444 / 2001-10-23
Facility ID:	0011444
Site ID:	123310
Spill Date:	2001-01-22
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	2001-01-22
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-22
Spill Record Last Update:	2001-11-02
Spiller Name:	M BARKAN
Spiller Company:	38-31 CRESCENT ST
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	M BARKAN
Spiller Phone:	(631) 981-2122
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	106893
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE 10/23/01 - Reviewed file, report recieved 10/10/01, no further action necessary. Letter sent to Don Carlo Environmental Sevrices Inc dated 10/23/01. M.J. Hinton Region 9, temp assignment to R2"
Remarks:	"LOCATION IS A 2 STORY COMMERCIAL. EXCAVATE, ISOLATE AND RETEST."

All TTF:

Facility ID:	0011444
Spill Number:	0011444
Spill Tank Test:	1526057
Site ID:	123310
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

38-31 CRESCENT ST (Continued) **S105230180**

Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	123310
Operable Unit ID:	832837
Operable Unit:	01
Material ID:	541755
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AI279 **39-23 REALTY LLC** **NY AST** **A100292290**
South **39-23 24TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.211 mi.
1114 ft. **Site 1 of 2 in cluster AI**

Relative:
Higher

Actual:
27 ft.

AST:

Name:	39-23 REALTY LLC
Address:	39-23 24TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-609677
Program Type:	PBS
UTM X:	589666.68379
UTM Y:	4512084.53665
Expiration Date:	03/29/2027
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	59055
Affiliation Type:	Facility Operator
Company Name:	39-23 REALTY LLC
Contact Type:	Not reported
Contact Name:	GINO MIRANDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 472-9134
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS

39-23 REALTY LLC (Continued) **A100292290**

Date Last Modified: 2009-07-03

Site Id: 59055
Affiliation Type: Emergency Contact
Company Name: 39-23 REALTY LLC
Contact Type: Not reported
Contact Name: VASILIOS KONTOROUHAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 242-6515
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2009-07-03

Site Id: 59055
Affiliation Type: Facility Owner
Company Name: 39-23 REALTY LLC
Contact Type: MEMBER
Contact Name: VASILIOS KONTOROUHAS
Address1: 30-73 CRESCENT STREET
Address2: Not reported
City: ASTORIA
State: NY
Zip Code: 11102
Country Code: 001
Phone: (718) 932-1242
EMail: VKREALTY3073@GMAIL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-01-20

Site Id: 59055
Affiliation Type: Mail Contact
Company Name: 39-23 REALTY LLC
Contact Type: MEMBER
Contact Name: VASILIOS KONTOROUHAS
Address1: 30-73 CRESCENT STREET
Address2: Not reported
City: ASTORIA
State: NY
Zip Code: 11102
Country Code: 001
Phone: (718) 932-1242
EMail: VKREALTY3073@GMAIL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-01-20

Tank Info:

Tank Number: 001
Tank Id: 179756

39-23 REALTY LLC (Continued) **A100292290**

Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I05 - Overfill - Vent Whistle
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
F00 - Pipe External Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
C01 - Pipe Location - Aboveground
D10 - Pipe Type - Copper
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel Tank in Concrete
Tank Status:	In Service
Pipe Model:	F
Install Date:	01/01/1933
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AJ280 **CON EDISON - TRANSFORMER MANHOLE 3048** **NY MANIFEST** **S120958070**
NNW **11TH ST & 36TH AVE** **N/A**
1/8-1/4 **QUEENS, NY 11106**
0.211 mi.
1116 ft. **Site 1 of 2 in cluster AJ**

Relative: **Lower**
Actual: **14 ft.**

NY MANIFEST:

Name:	CON EDISON - TRANSFORMER MANHOLE 3048
Address:	11TH ST & 36TH AVE
City,State,Zip:	QUEENS, NY 11106
Country:	USA
EPA ID:	NYP004909426
Facility Status:	Not reported
Location Address 1:	11TH ST & 36TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004909426
Mailing Name:	CON EDISON - TRANSFORMER MANHOLE 3048
Mailing Contact:	CON EDISON

CON EDISON - TRANSFORMER MANHOLE 3048 (Continued) **S120958070**

Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

AK281 **CON EDISON** **NY MANIFEST** **S117737235**
SSW **21-07 40 AVE FRNT** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.212 mi.
1121 ft. **Site 1 of 5 in cluster AK**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	21-07 40 AVE FRNT
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP004625059
Facility Status:	Not reported
Location Address 1:	21-07 40 AVE FRNT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004625059
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	08/12/2014
Trans1 Recv Date:	08/12/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

CON EDISON (Continued) **S117737235**

Generator EPA ID:	NYP004625059
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616346GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

282
WSW
1/8-1/4
0.215 mi.
1136 ft.

UNITED HOISTING COMPANY INC **NY UST** **U001831367**
38-51 11TH ST **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Lower

Actual:
15 ft.

UST:

Name:	UNITED HOISTING COMPANY INC
Address:	38-51 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-043966 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589259.15918
UTM Y:	4512361.11546
Site Type:	Other

Affiliation Records:

Site Id:	437

UNITED HOISTING COMPANY INC (Continued) **U001831367**

Affiliation Type:	Facility Owner
Company Name:	UNITED HOISTING COMPANY INC
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	38-61 11TH ST
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-3338
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	437
Affiliation Type:	Mail Contact
Company Name:	UNITED HOISTING COMPANY INC
Contact Type:	Not reported
Contact Name:	JOSEPH H. BOPP, JR.
Address1:	38-61 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 786-3338
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	437
Affiliation Type:	Facility Operator
Company Name:	UNITED HOISTING COMPANY INC
Contact Type:	Not reported
Contact Name:	JOE H. BOPP
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-3338
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	437
Affiliation Type:	Emergency Contact
Company Name:	UNITED HOISTING COMPANY INC
Contact Type:	Not reported
Contact Name:	JOE H. BOPP
Address1:	Not reported
Address2:	Not reported

UNITED HOISTING COMPANY INC (Continued) **U001831367**

City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 786-3338
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	1196
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	2000
Install Date:	06/01/1983
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	01
Date Test:	11/01/1997
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	002
Tank ID:	1197
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	12/01/1998
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0008
Common Name of Substance:	Diesel

UNITED HOISTING COMPANY INC (Continued) **U001831367**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

J02 - Dispenser - Suction Dispenser
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

AL283 **CON EDISON** **NY MANIFEST** **S117738952**
ENE **35-49 24TH ST** **N/A**
1/8-1/4 **ASTORIA, NY 11103**
0.216 mi.
1138 ft. **Site 1 of 2 in cluster AL**

Relative:
Higher

Actual:
19 ft.

NY MANIFEST:
Name: CON EDISON
Address: 35-49 24TH ST
City,State,Zip: ASTORIA, NY 11103
Country: USA
EPA ID: NYP004720348
Facility Status: Not reported
Location Address 1: 35-49 24TH ST
Code: BP
Location Address 2: SB59718
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11432
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004720348
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018

CON EDISON (Continued) **S117738952**

Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2015
Trans1 Recv Date:	01/29/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004720348
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014086641JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL284 **CON EDISON** **RCRA NonGen / NLR** **1018277505**
ENE **35-49 24TH ST** **FINDS** **NYP004720348**
1/8-1/4 **ASTORIA, NY 11103** **ECHO**
0.216 mi.
1138 ft. **Site 2 of 2 in cluster AL**

Relative: **Higher**
Actual: **19 ft.**

RCRA Listings:

Date Form Received by Agency:	20150129
Handler Name:	Con Edison
Handler Address:	35-49 24TH ST
Handler City,State,Zip:	ASTORIA, NY 11103
EPA ID:	NYP004720348
Contact Name:	THOMAS TEELING

CON EDISON (Continued) **1018277505**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20160502
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1018277505**

Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Historic Generators:
Receive Date: 20150129
Handler Name: CON EDISON
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20150129
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067689399

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1018277505**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277505
Registry ID:	110067689399
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067689399
Name:	CON EDISON
Address:	35-49 24TH ST
City,State,Zip:	ASTORIA, NY 11103

AC285 **CON EDISON** **NY Spills S109583461**
SW **13-01 40TH AV** **NY MANIFEST N/A**
1/8-1/4 **QUEENS, NY 11103**
0.216 mi.
1142 ft. **Site 9 of 10 in cluster AC**

Relative: **Higher**

Actual: **17 ft.**

SPILLS:

Name:	SIDEWALK
Address:	13-01 40TH AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0902601 / 2009-06-04
Facility ID:	0902601
Facility Type:	ER
DER Facility ID:	363798
Site ID:	414650
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2009-06-03
Investigator:	jbvought
Referred To:	Not reported
Reported to Dept:	2009-06-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-06-03
Spill Record Last Update:	2009-06-04
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	TONY FELTON
DEC Memo:	"06/04/09-Vought-Site visit by Vought and small insignificant stains found however no fill port or vent pipe and no free product found. Vought inspected adjacent sewers and found no spill. Also note rains during previous night however not even a sheen was found. Spill closed by Vought."

CON EDISON (Continued) **S109583461**

Remarks: "Unk oil spilled onto sidewalk from unk source. Unk if cleaned up because Mr. Felton was unavailable when DEP called back."

All Materials:
Site ID: 414650
Operable Unit ID: 1171034
Operable Unit: 01
Material ID: 2162822
Material Code: 9999
Material Name: other - unk oil
Case No.: Not reported
Material FA: Other
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Resource Affected: Not reported
Oxygenate: Not reported

NY MANIFEST:
Name: CON EDISON
Address: 13-01 40TH AV
City,State,Zip: QUEENS, NY 11103
Country: USA
EPA ID: NYP004630820
Facility Status: Not reported
Location Address 1: 13-01 40TH AV
Code: BP
Location Address 2: SB29798
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: 11103
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004630820
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 08/18/2014
Trans1 Recv Date: 08/18/2014

CON EDISON (Continued) **S109583461**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004630820
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002608959GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AC286 **DE MAMS, LLC** **NY UST** **U001832411**
SW **13-09 40TH AVENUE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.217 mi.
1146 ft. **Site 10 of 10 in cluster AC**

Relative: UST:
Higher

Actual: Name:	DE MAMS, LLC
18 ft. Address:	13-09 40TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-093882 / Active
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	04/19/2024
UTM X:	589314.56594
UTM Y:	4512171.47455

DE MAMS, LLC (Continued) **U001832411**

Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 2512
Affiliation Type: Emergency Contact
Company Name: ION GHEGELIU
Contact Type: Not reported
Contact Name: JENNIFER KIM
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 461-6464
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-06-15

Site Id: 2512
Affiliation Type: Facility Owner
Company Name: DE MAMS, LLC
Contact Type: PRESIDENT
Contact Name: ANTHONY H. JUNG
Address1: 3 WILSON LANE
Address2: Not reported
City: ROCKVILLE CENTRE
State: NY
Zip Code: 11570
Country Code: 001
Phone: (516) 780-1388
EMail: ANTHJUNG@GMAIL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-06-15

Site Id: 2512
Affiliation Type: Mail Contact
Company Name: DE MAMS, LLC
Contact Type: PRESIDENT
Contact Name: ANTHONY H. JUNG
Address1: 3 WILSON LANE
Address2: Not reported
City: ROCKVILLE CENTRE
State: NY
Zip Code: 11570
Country Code: 001
Phone: (516) 780-1388
EMail: ANTHJUNG@GMAIL.COM
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-06-15

Site Id: 2512
Affiliation Type: Facility Operator
Company Name: DE MAMS, LLC
Contact Type: Not reported

DE MAMS, LLC (Continued) **U001832411**

Contact Name:	ANTHONY H. JUNG
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(917) 295-6344
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-06-15

Tank Info:

Tank Number:	001
Tank ID:	4381
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1500
Install Date:	02/01/1945
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	34
Date Test:	01/21/2019
Next Test Date:	01/21/2020
Pipe Model:	Not reported
Modified By:	JSMACRI
Last Modified:	06/15/2022

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
D00 - Pipe Type - No Piping
L00 - Piping Leak Detection - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
C03 - Pipe Location - Aboveground/Underground Combination
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AH287 **WORLD WIDE RECOVERY SYSTEMS INC** **RCRA NonGen / NLR** **1000278444**
WSW **38-65 12TH ST** **FINDS** **NYD088493481**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.217 mi.
1147 ft. **Site 2 of 5 in cluster AH**

Relative:
Lower

Actual:
16 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	World Wide Recovery Systems Inc
Handler Address:	38-65 12TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD088493481
Contact Name:	GLENN OTT
Contact Address:	12TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-729-0656
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	12TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Ownername
Owner Type:	Private
Operator Name:	Ownername
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

WORLD WIDE RECOVERY SYSTEMS INC (Continued) **1000278444**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	K009
Waste Description:	Distillation Bottoms From The Production Of Acetaldehyde From Ethylene.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

WORLD WIDE RECOVERY SYSTEMS INC (Continued) **1000278444**

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 20060101
Handler Name: WORLD WIDE RECOVERY SYSTEMS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: WORLD WIDE RECOVERY SYSTEMS INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19850221
Handler Name: WORLD WIDE RECOVERY SYSTEMS INC
Federal Waste Generator Description: Not reported
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

WORLD WIDE RECOVERY SYSTEMS INC (Continued) **1000278444**

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19891228
Actual Return to Compliance Date: 19900327
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19900226
Enforcement Identifier: 001
Date of Enforcement Action: 19900126
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19891228
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYDEC
Evaluation Responsible Sub-Organization: Not reported
Actual Return to Compliance Date: 19900327
Scheduled Compliance Date: 19900226
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004373419

WORLD WIDE RECOVERY SYSTEMS INC (Continued) **1000278444**

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000278444
Registry ID:	110004373419
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004373419
Name:	WORLD WIDE RECOVERY SYSTEMS INC
Address:	38-65 12TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

AM288 **CON EDISON SERVICE BOX: 44643** **RCRA NonGen / NLR** **1016971144**
NW **36-31 10TH ST** **NY MANIFEST** **NYP004448783**
1/8-1/4 **ASTORIA, NY 11106**
0.218 mi.
1152 ft. **Site 1 of 3 in cluster AM**

Relative: **Lower**
Actual: **13 ft.**

RCRA Listings:

Date Form Received by Agency:	20140322
Handler Name:	Con Edison Service Box: 44643
Handler Address:	36-31 10TH ST
Handler City,State,Zip:	ASTORIA, NY 11106
EPA ID:	NYP004448783
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No

CON EDISON SERVICE BOX: 44643 (Continued) **1016971144**

Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20141014
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20140222
Handler Name: CON EDISON SERVICE BOX:	44643
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20140322
Handler Name: CON EDISON SERVICE BOX:	44643
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny

CON EDISON SERVICE BOX: 44643 (Continued) **1016971144**

Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	36-31 10TH ST
City,State,Zip:	ASTORIA, NY 11106
Country:	USA
EPA ID:	NYP004448783
Facility Status:	Not reported
Location Address 1:	WEST 10 ST & 37 AVE
Code:	BP
Location Address 2:	SB44643
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	11432
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004448783
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported

CON EDISON SERVICE BOX: 44643 (Continued) **1016971144**

Generator Ship Date:	02/22/2014
Trans1 Recv Date:	02/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004448783
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011697875JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK289 **22-11 40 AVENUE** **NY UST** **U001840813**
SSW **22-11 40 AV** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.222 mi.
1174 ft. **Site 2 of 5 in cluster AK**

Relative: UST:
Higher

Actual:
21 ft.

Name:	22-11 40 AVENUE
Address:	22-11 40 AV
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-476668 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A

22-11 40 AVENUE (Continued) **U001840813**

UTM X: 588736.89039
UTM Y: 4511665.36616
Site Type: Other

Affiliation Records:

Site Id: 21112
Affiliation Type: Facility Owner
Company Name: JOHN BELO/RICHARD KAPLAN
Contact Type: Not reported
Contact Name: Not reported
Address1: 24-16 QUEENS PLAZA SOUTH,RM408
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 392-3456
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2004-12-14

Site Id: 21112
Affiliation Type: Mail Contact
Company Name: JOHN BELO/RICHARD KAPLAN
Contact Type: Not reported
Contact Name: Not reported
Address1: 24-16 QUEENS PLAZA SOUTH,RM408
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 392-3456
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2004-12-14

Site Id: 21112
Affiliation Type: Facility Operator
Company Name: 22-11 40 AVENUE
Contact Type: Not reported
Contact Name: JOHN BELO/ RICHARD KAPLAN
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 392-3456
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 21112
Affiliation Type: Emergency Contact

22-11 40 AVENUE (Continued) **U001840813**

Company Name:	JOHN BELO/RICHARD KAPLAN
Contact Type:	Not reported
Contact Name:	JOHN BELO / RICHARD KAPLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(516) 253-0900
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	41006
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None

Tank Number:	002
Tank ID:	41007
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

22-11 40 AVENUE (Continued) **U001840813**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 003
Tank ID: 41008
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 11/01/1952
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 004
Tank ID: 41009
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550

22-11 40 AVENUE (Continued) **U001840813**

Install Date:	11/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	005
Tank ID:	41010
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number: 006

22-11 40 AVENUE (Continued) **U001840813**

Tank ID:	41011
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	11/01/1952
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None

AM290 **PARISI - WAREHOUSE** **NY LTANKS** **S107658718**
NW **36-21 10TH STREET** **N/A**
1/8-1/4 **ASTORIA, NY**
0.223 mi.
1175 ft. **Site 2 of 3 in cluster AM**

Relative: **Lower**

Actual: **14 ft.**

LTANKS:

Name:	PARISI - WAREHOUSE
Address:	36-21 10TH STREET
City,State,Zip:	ASTORIA, NY
Spill Number/Closed Date:	0513981 / 2006-04-18
Facility ID:	0513981
Site ID:	360577
Spill Date:	2006-03-07
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	rmpiper
Referred To:	Not reported
Reported to Dept:	2006-03-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	Not reported
Meets Standard:	True
UST Involvement:	True

PARISI - WAREHOUSE (Continued) **S107658718**

Remediation Phase:	0
Date Entered In Computer:	2006-03-07
Spill Record Last Update:	2006-04-21
Spiller Name:	DEB PARISA
Spiller Company:	PARISA HOME
Spiller Address:	36-21 10TH STREET
Spiller County:	001
Spiller Contact:	DEB PARISA
Spiller Phone:	(516) 369-6448
Spiller Extention:	CELL
DEC Region:	2
DER Facility ID:	310746
DEC Memo:	"need to send CSL 3/8/06- DEC Piper visited site. Fenley and Nichol on site. One tank was uncovered, partially filled w/ sand/water. Was not properly done. Sheen on water in tank. F& N to remove and collect endpoint samples. 3/10/06- DEC Piper informed that there are two (2) 1,000 gal tanks, not two (2) 550 gal. 4/18/06- DEC Piper reviewed tank closure report. Based on report, soil analytical, and tank/ vault conditions, this case is closed. NFA required. See E-Docs if warranted."
Remarks:	"REMOVING TWO 500 GALLON TANKS AT THIS LOCATION AND FOUND CONTAMINATED SOIL, THEY LOOKED LIKE SOMEONE TRIED TO ABANDON AND DINT FINISH OR DO RIGHT:"

All Materials:

Site ID:	360577
Operable Unit ID:	1117721
Operable Unit:	01
Material ID:	2108230
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AH291 **38-70 12TH STREET** **NY UST** **U004272327**
WSW **38-70 12TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.223 mi.
1175 ft. **Site 3 of 5 in cluster AH**

Relative: **Lower**
Actual: **16 ft.**

UST:

Name:	38-70 12TH STREET
Address:	38-70 12TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-612727 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	Not reported
UTM Y:	Not reported
Site Type:	Apartment Building/Office Building

38-70 12TH STREET (Continued) **U004272327**

Affiliation Records:

Site Id:	552946
Affiliation Type:	Facility Owner
Company Name:	PEACHY ENTERPRISE, LLC
Contact Type:	OWNER'S REPRESANTIVE
Contact Name:	RUDY QUIAMBAO
Address1:	38-74 12TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 218-3333
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-06-21

Site Id:	552946
Affiliation Type:	Mail Contact
Company Name:	11-11 LIC DEVELOPMENT, LLC
Contact Type:	Not reported
Contact Name:	HENRY ZHAO
Address1:	136-19 FRANKLIN AVENUE # 6A
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	11355
Country Code:	001
Phone:	(718) 938-1216
EMail:	HENRY@AMPIERA.COM
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-06-21

Site Id:	552946
Affiliation Type:	Facility Operator
Company Name:	38-70 12TH STREET
Contact Type:	Not reported
Contact Name:	U-BIULD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	Not reported
EMail:	Not reported
Fax Number:	Not reported
Modified By:	LXZIELIN
Date Last Modified:	2017-06-21

Tank Info:

Tank Number:	001
Tank ID:	269733

38-70 12TH STREET (Continued) **U004272327**

Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/28/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
C02 - Pipe Location - Underground/On-ground
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
L00 - Piping Leak Detection - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Number:	002
Tank ID:	269734
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/28/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

J00 - Dispenser - None
G04 - Tank Secondary Containment - Double-Walled (Underground)
C02 - Pipe Location - Underground/On-ground
H00 - Tank Leak Detection - None
I00 - Overfill - None
E00 - Piping Secondary Containment - None
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
L00 - Piping Leak Detection - None
K00 - Spill Prevention - None

38-70 12TH STREET (Continued) **U004272327**

A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Number:	003
Tank ID:	269735
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	02/28/2017
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
F00 - Pipe External Protection - None
J00 - Dispenser - None
C02 - Pipe Location - Underground/On-ground
L00 - Piping Leak Detection - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
G04 - Tank Secondary Containment - Double-Walled (Underground)

AI292 **39-31 24TH ST** **NY AST** **A100354083**
South **39-31 24TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.223 mi.
1179 ft. **Site 2 of 2 in cluster AI**

Relative:
Higher

Actual:
28 ft.

AST:

Name:	39-31 24TH ST
Address:	39-31 24TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-611437
Program Type:	PBS
UTM X:	589659.22910
UTM Y:	4512073.60950
Expiration Date:	11/02/2025
Site Type:	Apartment Building/Office Building

Affiliation Records:

Site Id:	441089
Affiliation Type:	Facility Operator
Company Name:	39-31 24TH ST

39-31 24TH ST (Continued) **A100354083**

Contact Type:	Not reported
Contact Name:	MODICA MANAGEMENT LLC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 721-2339
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-13

Site Id:	441089
Affiliation Type:	Emergency Contact
Company Name:	MODICA MANAGEMENT, LLC
Contact Type:	Not reported
Contact Name:	VICTOR LORENZO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 945-9804
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-02-13

Site Id:	441089
Affiliation Type:	Facility Owner
Company Name:	MODICA MANAGEMENT, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	GINETTA MODICA
Address1:	P.O. BOX 5205
Address2:	Not reported
City:	ASTORIA
State:	NY
Zip Code:	11105
Country Code:	001
Phone:	(718) 721-2339
EMail:	GINETTA@PROPERTYMANAGEMENTGRP.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-09-03

Site Id:	441089
Affiliation Type:	Mail Contact
Company Name:	MODICA MANAGEMENT, LLC
Contact Type:	MANAGING MEMBER
Contact Name:	GINETTA MODICA
Address1:	P.O. BOX 5205
Address2:	Not reported
City:	ASTORIA
State:	NY

39-31 24TH ST (Continued) **A100354083**

Zip Code:	11105
Country Code:	001
Phone:	(718) 721-2339
EMail:	GINETTA@PROPERTYMANAGEMENTGRP.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2020-09-03

Tank Info:

Tank Number:	01
Tank Id:	236396
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J00 - Dispenser - None
	H00 - Tank Leak Detection - None
	I00 - Overfill - None
	C00 - Pipe Location - No Piping
	L00 - Piping Leak Detection - None
	D00 - Pipe Type - No Piping
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	06/15/1935
Capacity Gallons:	2000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AG293 **APLINE STORE EQUIPMENT CORP.** **NY AST** **U003396366**
WNW **37-10 10TH AVE** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.223 mi.
1179 ft. **Site 2 of 2 in cluster AG**

Relative: **Lower**
Actual: **13 ft.**

AST:

Name:	APLINE STORE EQUIPMENT CORP.
Address:	37-10 10TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-601911
Program Type:	PBS
UTM X:	589319.32613
UTM Y:	4512644.82999
Expiration Date:	N/A

APLINE STORE EQUIPMENT CORP. (Continued) **U003396366**

Site Type: Other

Affiliation Records:

Site Id: 23873
Affiliation Type: Facility Owner
Company Name: ALPINE STORE EQUIPMENT CORP.
Contact Type: Not reported
Contact Name: Not reported
Address1: 37-10 10TH ST.
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-1213
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2004-12-14

Site Id: 23873
Affiliation Type: Mail Contact
Company Name: AKPINE STORE EQUIPMENT
Contact Type: Not reported
Contact Name: MERYLIN MECKLER
Address1: 37-10 10TH ST.
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11101
Country Code: 001
Phone: (718) 361-1213
EMail: Not reported
Fax Number: Not reported
Modified By: CGFREEDM
Date Last Modified: 2004-12-14

Site Id: 23873
Affiliation Type: Facility Operator
Company Name: APLINE STORE EQUIPMENT CORP.
Contact Type: Not reported
Contact Name: GERALD CARR
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 361-1213
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 23873
Affiliation Type: Emergency Contact
Company Name: ALPINE STORE EQUIPMENT CORP.
Contact Type: Not reported

APLINE STORE EQUIPMENT CORP. (Continued) **U003396366**

Contact Name:	GERALD CARR
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-1213
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank Id:	48283
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	48284
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None

APLINE STORE EQUIPMENT CORP. (Continued) **U003396366**

D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	003
Tank Id:	48285
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
G99 - Tank Secondary Containment - Other
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	004
Tank Id:	48286
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

APLINE STORE EQUIPMENT CORP. (Continued) **U003396366**

Equipment Records:
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	005
Tank Id:	48287
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:
I02 - Overfill - High Level Alarm
C01 - Pipe Location - Aboveground
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G99 - Tank Secondary Containment - Other
B00 - Tank External Protection - None
F00 - Pipe External Protection - None
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AN294 **BLACK OX METAL FINISHING INC** **PFAS ECHO** **1027332752**
SE **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.224 mi.
1181 ft. **Site 1 of 4 in cluster AN**

Relative:
Higher

Actual:
46 ft.

PFAS ECHO:

Name:	BLACK OX METAL FINISHING INC
Address:	Not reported
City,State,Zip:	LONG ISLAND CITY, NY
Latitude:	40.75539
Longitude:	-73.93504
Count:	1
County:	QUEENS
Status:	Active
Region:	02
Industry:	Metal Coating
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110014449739
Facility Percent Minority:	46.489
Facility Derived Tribes:	-
Facility Population:	43388.07
EPA Programs:	RCRA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36081
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-BLOCK FACE
Facility Derived HUC:	02030201
Facility Derived WBD:	020301010405
Facility Derived CD113:	12
Facility Derived CB2010:	360810031001001
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	N
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	Y
TRI Flag:	N
GHG Flag:	N
AIR IDS:	-
CAA Permit Types:	-
CAA NAICS:	-
CAA SICS:	-
NPDES IDS:	-

BLACK OX METAL FINISHING INC (Continued) **1027332752**

CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	NYN008007114 NYR000114538
RCRA Permit Types:	Other, VSQG
RCRA NAICS:	332813
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.93504,%22y%22:40.75539,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

---

295 NE 1/8-1/4 0.225 mi. 1188 ft. **CON EDISON** **NY MANIFEST** **S117319352**
35-05 21ST ST **N/A**
QUEENS, NY

Relative: Higher
Actual: 19 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	35-05 21ST ST
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004670790
Facility Status:	Not reported
Location Address 1:	35-05 21ST ST
Code:	BP
Location Address 2:	STRUCTURE # 27797
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004670790
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported

CON EDISON (Continued) **S117319352**

Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/02/2014
Trans1 Recv Date:	10/02/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004670790
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002616991GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

296
NNE
1/8-1/4
0.225 mi.
1189 ft.

CON EDISON
35TH AVE & 35TH ST 50 FEET E
ASTORIA, NY 11106

NY MANIFEST **S117740182**
N/A

Relative:
Higher

Actual:
17 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	35TH AVE & 35TH ST 50 FEET E
City,State,Zip:	ASTORIA, NY 11106
Country:	USA
EPA ID:	NYP004733416
Facility Status:	Not reported
Location Address 1:	35TH AVE & 35TH ST
Code:	BP
Location Address 2:	V 3825
Total Tanks:	Not reported
Location City:	ASTORIA
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004733416
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	02/18/2015
Trans1 Recv Date:	02/18/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733416
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014088695JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S117740182**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AH297 **DAWNEX INDUSTRIES INC** **NY AST** **U001832336**
WSW **38-61 11TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.229 mi.
1208 ft. **Site 4 of 5 in cluster AH**

Relative: **Lower**
Actual: **15 ft.**

AST:

Name:	DAWNEX INDUSTRIES INC
Address:	38-61 11TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-116637
Program Type:	PBS
UTM X:	589244.20795
UTM Y:	4512340.10706
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	3935
Affiliation Type:	Facility Owner
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	PRESIDENT
Contact Name:	WILLIAM PYMM
Address1:	38-61 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001

DAWNEX INDUSTRIES INC (Continued) **U001832336**

Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-01-24

Site Id:	3935
Affiliation Type:	Mail Contact
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	PRESIDENT
Contact Name:	WILLIAM PYMM
Address1:	38-61 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-01-24

Site Id:	3935
Affiliation Type:	Facility Operator
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	DAWNEX INDUSTRIES INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-13

Site Id:	3935
Affiliation Type:	Emergency Contact
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	WILLIAM PYMM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-13

DAWNEX INDUSTRIES INC (Continued) **U001832336**

Tank Info:

Tank Number:	002
Tank Id:	4152
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	J02 - Dispenser - Suction Dispenser
	G03 - Tank Secondary Containment - Vault (w/o access)
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	I05 - Overfill - Vent Whistle
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	09/01/1987
Capacity Gallons:	1500
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	11/17/2010
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AH298 **DAWNEX INDUSTRIES INC** **NY UST** **U004076339**
WSW **38-61 11TH STREET** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.229 mi.
1208 ft. **Site 5 of 5 in cluster AH**

Relative: **Lower**

Actual: **15 ft.**

UST:

Name:	DAWNEX INDUSTRIES INC
Address:	38-61 11TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Id/Status:	2-116637 / Unregulated/Closed
Program Type:	PBS
Region:	STATE
DEC Region:	2
Expiration Date:	N/A
UTM X:	589244.20795
UTM Y:	4512340.10706
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	3935
Affiliation Type:	Facility Owner
Company Name:	DAWNEX INDUSTRIES INC

DAWNEX INDUSTRIES INC (Continued) **U004076339**

Contact Type:	PRESIDENT
Contact Name:	WILLIAM PYMM
Address1:	38-61 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-01-24

Site Id:	3935
Affiliation Type:	Mail Contact
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	PRESIDENT
Contact Name:	WILLIAM PYMM
Address1:	38-61 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	KXTANG
Date Last Modified:	2007-01-24

Site Id:	3935
Affiliation Type:	Facility Operator
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	DAWNEX INDUSTRIES INC
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-13

Site Id:	3935
Affiliation Type:	Emergency Contact
Company Name:	DAWNEX INDUSTRIES INC
Contact Type:	Not reported
Contact Name:	WILLIAM PYMM
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN

DAWNEX INDUSTRIES INC (Continued) **U004076339**

Zip Code:	Not reported
Country Code:	999
Phone:	(718) 784-3690
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2011-12-13

Tank Info:

Tank Number:	001
Tank ID:	4151
Tank Status:	Closed - In Place
Material Name:	Closed - In Place
Capacity Gallons:	1500
Install Date:	Not reported
Date Tank Closed:	10/01/1987
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)

---

299 East 1/8-1/4 0.229 mi. 1209 ft. **CONSOLIDATED EDISON**
CRESCENT ST & 36TH AVE
QUEENS, NY

NY MANIFEST **1009240072**
N/A

Relative: Higher
Actual: 24 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	CRESCENT ST & 36TH AVE
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004069050
Facility Status:	Not reported
Location Address 1:	CRESCENT ST & 36TH AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

CONSOLIDATED EDISON (Continued) **1009240072**

Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004069050
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

AO300 **37-15 27 STREET CORP.** **NY AST** **U003385322**
SE **37-15 27 STREET** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.233 mi.
1231 ft. **Site 1 of 2 in cluster AO**

Relative:
Higher

Actual:
42 ft.

AST:
Name: 37-15 27 STREET CORP.
Address: 37-15 27 STREET
City,State,Zip: ASTORIA, NY 11106
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-130060
Program Type: PBS
UTM X: 589976.15737
UTM Y: 4512257.09295
Expiration Date: 06/05/2027
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 4067
Affiliation Type: Mail Contact
Company Name: 37-15 27 STREET CORP.
Contact Type: Not reported
Contact Name: SUPER FACILITY MANAGER
Address1: 45-11 LITTLE NECK PKWY
Address2: Not reported
City: LITTLE NECK
State: NY
Zip Code: 11362
Country Code: 001
Phone: (718) 897-6277
EMail: BEZDIKIANS@YAHOO.COM
Fax Number: Not reported
Modified By: JAAVERSA
Date Last Modified: 2023-01-27

Site Id: 4067
Affiliation Type: Facility Operator

37-15 27 STREET CORP. (Continued) **U003385322**

Company Name:	37-15 27 STREET CORP.
Contact Type:	Not reported
Contact Name:	SENAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-2386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Site Id:	4067
Affiliation Type:	Emergency Contact
Company Name:	37-15 TWENTY SEVEN STR. CORPORATION
Contact Type:	Not reported
Contact Name:	SENAD
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 937-2386
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-07-18

Site Id:	4067
Affiliation Type:	Facility Owner
Company Name:	37-15 TWENTY SEVENTH STREET CORP.
Contact Type:	PRESIDENT
Contact Name:	KARL ALAJAJIAN
Address1:	45-11 LITTLE NECK PKWY
Address2:	Not reported
City:	LITTLE NECK
State:	NY
Zip Code:	11362
Country Code:	001
Phone:	(718) 961-9550
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JAAVERSA
Date Last Modified:	2023-01-27

Tank Info:

Tank Number:	001
Tank Id:	5552
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

37-15 27 STREET CORP. (Continued) **U003385322**

Equipment Records:

J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	02/06/1986
Capacity Gallons:	4000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JAAVERSA
Last Modified:	01/27/2023
Material Name:	#2 fuel oil (on-site consumption)

AN301 **CON EDISON** **NY MANIFEST** **S117535956**
SE **27-03 38TH AVE** **N/A**
1/8-1/4 **QUEENS, NY**
0.234 mi.
1237 ft. **Site 2 of 4 in cluster AN**

Relative:
Higher

Actual:
49 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	27-03 38TH AVE
City,State,Zip:	QUEENS, NY
Country:	USA
EPA ID:	NYP004683926
Facility Status:	Not reported
Location Address 1:	27-03 38TH AVE
Code:	BP
Location Address 2:	SB 44018
Total Tanks:	Not reported
Location City:	QUEENS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004683926
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **S117535956**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD003812047
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2014
Trans1 Recv Date:	10/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/29/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004683926
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	002618087GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AP302 **CONSOLIDATED EDISON** **NY MANIFEST** **S122482424**
SSE **31-01 20TH. AVE.** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11105**
0.237 mi.
1251 ft. **Site 1 of 2 in cluster AP**

Relative:
Higher

Actual:
41 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	31-01 20TH. AVE.
City,State,Zip:	LONG ISLAND CITY, NY 11105-2048
Country:	USA
EPA ID:	NYD980593636
Facility Status:	Not reported
Location Address 1:	31-01 20TH AVE & 27TH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11105
Location Zip 4:	2048

NY MANIFEST:

EPAID:	NYD980593636
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/31/2008
Trans1 Recv Date:	12/31/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/31/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD980593636
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001449136FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CONSOLIDATED EDISON (Continued) **S122482424**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	8
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	B005
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK303 **GIACOMELLI & MAZZA INC** **RCRA-SQG** **1001224560**
SW **40-05 21ST ST** **NY MANIFEST** **NYR000057778**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.240 mi.
1265 ft. **Site 3 of 5 in cluster AK**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Giacomelli & Mazza Inc
Handler Address:	40-05 21ST ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000057778
Contact Name:	ROBERT SPADAFORA
Contact Address:	21ST ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-937-6293
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	21ST ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Robert Spadafora
Owner Type:	Private

GIACOMELLI & MAZZA INC (Continued) **1001224560**

Operator Name:	Robert Spadafora
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still

GIACOMELLI & MAZZA INC (Continued) **1001224560**

Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: ROBERT SPADAFORA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	40-05 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-6293
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROBERT SPADAFORA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	40-05 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-6293
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: ROBERT SPADAFORA	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	40-05 21ST ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-937-6293
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: GIACOMELLI & MAZZA INC	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

GIACOMELLI & MAZZA INC (Continued) **1001224560**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: GIACOMELLI & MAZZA INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980708
Handler Name: GIACOMELLI & MAZZA INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported

GIACOMELLI & MAZZA INC (Continued) **1001224560**

Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20101213
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2OSK
Evaluation Responsible Sub-Organization: RCB
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

NY MANIFEST:
Name: GIACOMELLI MAZZA
Address: 40-05 21ST ST
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYR000057778
Facility Status: Not reported
Location Address 1: 40-05 21ST ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LIC
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000057778
Mailing Name: GIACOMELLI MAZZA
Mailing Contact: ROBERT SPADAFORA
Mailing Address 1: 40-05 21ST ST
Mailing Address 2: Not reported
Mailing City: LIC

GIACOMELLI & MAZZA INC (Continued) **1001224560**

Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7189376293

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	NYD982792814
Generator Ship Date:	11/05/2014
Trans1 Recv Date:	11/05/2014
Trans2 Recv Date:	11/11/2014
TSD Site Recv Date:	11/13/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000057778
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	KYD985073196
TSDF ID 2:	Not reported
Manifest Tracking Number:	007885056FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1800
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

304
NNW
1/8-1/4
0.241 mi.
1273 ft.

WEGNER MACHINERY CORP
35-41 11TH ST
LONG ISLAND CITY, NY 11106

NY AST **1000552620**
RCRA NonGen / NLR **NYD986950210**
FINDS
ECHO
NY MANIFEST

Relative:
Lower

Actual:
15 ft.

AST:

Name:	ACS OF LONG ISLAND CITY REALTY CORP.
Address:	35-41 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-243957
Program Type:	PBS
UTM X:	589111.31595
UTM Y:	4512111.19783
Expiration Date:	N/A
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	9420
Affiliation Type:	Mail Contact
Company Name:	ACS OF LONG ISLAND CITY REALTY CORP.
Contact Type:	Not reported
Contact Name:	JOAN WITTLINGER
Address1:	35-41 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 956-7244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-03-16

Site Id:	9420
Affiliation Type:	Facility Operator
Company Name:	ACS OF LONG ISLAND CITY REALTY CORP.
Contact Type:	Not reported
Contact Name:	JOAN WITTLINGER
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 956-7244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-03-16

Site Id:	9420
Affiliation Type:	Emergency Contact
Company Name:	ACS OF LONG ISLAND CITY REALTY CORP.
Contact Type:	Not reported
Contact Name:	JOAN WITTLINGER

WEGNER MACHINERY CORP (Continued) **1000552620**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 956-7244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-03-16

Site Id:	9420
Affiliation Type:	Facility Owner
Company Name:	ACS OF LONG ISLAND CITY REALTY CORP.
Contact Type:	PRESIDENT
Contact Name:	PETER TSIMOYIANIS
Address1:	35-41 11TH STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 956-7244
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-03-16

Tank Info:

Tank Number:	001
Tank Id:	25389
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
	H00 - Tank Leak Detection - None
	L09 - Piping Leak Detection - Exempt Suction Piping
	I04 - Overfill - Product Level Gauge (A/G)
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	B00 - Tank External Protection - None
	C00 - Pipe Location - No Piping
	F00 - Pipe External Protection - None
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	06/01/1990
Capacity Gallons:	2000
Tightness Test Method:	03
Date Test:	06/01/1990

WEGNER MACHINERY CORP (Continued) **1000552620**

Next Test Date: Not reported
Date Tank Closed: 12/01/2000
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 002
Tank Id: 25390
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
J02 - Dispenser - Suction Dispenser
I04 - Overfill - Product Level Gauge (A/G)
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location: Aboveground in subterranean vault with access for inspections.....
Tank in subterranean vault but accessible for inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed Prior to Micro Conversion, 03/91
Pipe Model: Not reported
Install Date: Not reported
Capacity Gallons: 5000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 08/01/1990
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: #2 fuel oil (on-site consumption)

RCRA Listings:

Date Form Received by Agency: 20070101
Handler Name: Wegner Machinery Corp
Handler Address: 35-41 11TH ST
Handler City,State,Zip: LONG ISLAND CITY, NY 11106-5013
EPA ID: NYD986950210
Contact Name: Not reported
Contact Address: PO BOX 427
Contact City,State,Zip: COLD SPRING HARBOR, NY 11724
Contact Telephone: Not reported
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Not reported
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported

WEGNER MACHINERY CORP (Continued) **1000552620**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	PO BOX 427
Mailing City,State,Zip:	COLD SPRING HARBOR, NY 11724
Owner Name:	Walter Grill Executive
Owner Type:	Private
Operator Name:	Walter Grill Executive
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

WEGNER MACHINERY CORP (Continued) **1000552620**

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name: WALTER GRILL EXECUTIVE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALTER GRILL EXECUTIVE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: WALTER GRILL EXECUTIVE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19990708
Handler Name: WEGNER MACHINERY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20060101
Handler Name: WEGNER MACHINERY CORP	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No

WEGNER MACHINERY CORP (Continued) **1000552620**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	WEGNER MACHINERY CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19910405
Handler Name:	WEGNER MACHINERY CORP
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

WEGNER MACHINERY CORP (Continued) **1000552620**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19990331
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSAN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

FINDS:
Registry ID: 110004465542

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000552620
Registry ID: 110004465542
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004465542
Name: WEGNER MACHINERY CORP
Address: 35-41 11TH ST

WEGNER MACHINERY CORP (Continued) **1000552620**

City,State,Zip: LONG ISLAND CITY, NY 11106

NY MANIFEST:

Name:	WEGNER MACHINERY CORPORATION
Address:	35-41 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106-5013
Country:	USA
EPA ID:	NYD986950210
Facility Status:	Not reported
Location Address 1:	35-41 11TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986950210
Mailing Name:	WEGNER MACHINERY CORPORATION
Mailing Contact:	WALTER GRILL
Mailing Address 1:	35-41 11TH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7182787202

AN305 **CON EDISON** **RCRA NonGen / NLR** **1019908975**
SSE **38-11 27TH ST** **NYP004879635**
1/8-1/4 **LONG ISLAND CITY, NY 11101**
0.242 mi.
1278 ft. **Site 3 of 4 in cluster AN**

Relative:
Higher

Actual:
45 ft.

RCRA Listings:

Date Form Received by Agency:	20151215
Handler Name:	Con Edison
Handler Address:	38-11 27TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYP004879635
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

CON EDISON (Continued) **1019908975**

State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20220919
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	20151215
Handler Name: CON EDISON	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019908975**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	20151215
Handler Name: CON EDISON	
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	Not reported
Recognized Trader Exporter:	Not reported
Spent Lead Acid Battery Importer:	Not reported
Spent Lead Acid Battery Exporter:	Not reported
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AN306 **CON EDISON** **NJ MANIFEST** **S120678156**
SSE **38-11 27TH ST** **N/A**
1/8-1/4 **QUEENS, NY 11101**
0.242 mi.
1278 ft. **Site 4 of 4 in cluster AN**

Relative: Higher
Actual: 45 ft.

NJ MANIFEST:

EPA Id:	NYP004879635
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY081
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015320345JJK
EPA ID:	NYP004879635

CON EDISON (Continued) **S120678156**

Date Shipped:	12/15/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AQ307 **ATLANTIC PRECIOUS METAL** **RCRA-VSQG** **1001090432**
SSW **22-12 40TH AVE** **FINDS** **NYR000022699**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.242 mi. **NY MANIFEST**
1280 ft. **Site 1 of 3 in cluster AQ**

Relative: **Higher**
Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Atlantic Precious Metal
Handler Address:	22-12 40TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000022699
Contact Name:	Not reported
Contact Address:	40TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported

ATLANTIC PRECIOUS METAL (Continued) **1001090432**

Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	40TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Ricky Barbieri
Owner Type:	Private
Operator Name:	Ricky Barbieri
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

ATLANTIC PRECIOUS METAL (Continued) **1001090432**

Hazardous Waste Summary:
Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: NONE
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: RICKY BARBIERI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-12 40TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-8321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: RICKY BARBIERI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-12 40TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-8321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RICKY BARBIERI
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 22-12 40TH AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-784-8321
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19960924
Handler Name: ATLANTIC PRECIOUS METAL
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

ATLANTIC PRECIOUS METAL (Continued) **1001090432**

Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: ATLANTIC PRECIOUS METAL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: ATLANTIC PRECIOUS METAL
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960424
Handler Name: ATLANTIC PRECIOUS METAL
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported

ATLANTIC PRECIOUS METAL (Continued) **1001090432**

Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20150826
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110004524239

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ATLANTIC PRECIOUS METAL (Continued) **1001090432**

ECHO:
- Envid: 1001090432
- Registry ID: 110004524239
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004524239
- Name: ATLANTIC PRECIOUS METAL
- Address: 22-12 40TH AVE
- City,State,Zip: LONG ISLAND CITY, NY 11101

NY MANIFEST:
- Name: ATLANTIC PRECIOUS METALS CASTING INC.
- Address: 22-12 40TH AVE
- City,State,Zip: LONG ISLAND CITY, NY 11101
- Country: USA
- EPA ID: NYR000022699
- Facility Status: Not reported
- Location Address 1: 41-32 27TH STREET
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: LONG ISLAND CITY
- Location State: NY
- Location Zip: 11101
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYR000022699
- Mailing Name: ATLANTIC PRECIOUS METALS CASTING INC.
- Mailing Contact: HANIF M KAHN
- Mailing Address 1: 4132 27TH STREET
- Mailing Address 2: Not reported
- Mailing City: LONG ISLAND CITY
- Mailing State: NY
- Mailing Zip: 11101
- Mailing Zip 4: Not reported
- Mailing Country: USA
- Mailing Phone: 7189377100

AO308 **UNDERGROUND LINE** **NY LTANKS** **S104514679**
ESE **27-10 37TH AVE** **NY Spills** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY**
0.243 mi.
1285 ft. **Site 2 of 2 in cluster AO**

Relative:
Higher

Actual:
39 ft.

LTANKS:
- Name: RESIDENCE
- Address: 27-10 37TH AVE
- City,State,Zip: LONG ISLAND CITY, NY
- Spill Number/Closed Date: 9712733 / 2003-02-19
- Facility ID: 9712733
- Site ID: 168989
- Spill Date: 1998-02-13
- Spill Cause: Tank Overfill
- Spill Source: Private Dwelling
- Spill Class: C4
- Cleanup Ceased: Not reported
- SWIS: 4101

UNDERGROUND LINE (Continued) **S104514679**

Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1998-02-13
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-13
Spill Record Last Update:	2003-02-19
Spiller Name:	VENTURA PASION
Spiller Company:	PETRO ASTORIA
Spiller Address:	36-16 19AV
Spiller County:	001
Spiller Contact:	MR S LEANO
Spiller Phone:	(718) 784-3530
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	142316
DEC Memo:	""
Remarks:	"DRIVER NEVER HEARD VENT ALARM CAUSING A SPILL OF APPROX 4 GALS WHICH WAS BEING CLEANED UP. THEY FEEL THAT PERHAPS ONE GAL MAY HAVE GONE INTO SEWER."

All Materials:

Site ID:	168989
Operable Unit ID:	1058951
Operable Unit:	01
Material ID:	327325
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

SPILLS:

Name:	UNDERGROUND LINE
Address:	27-10 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1111515 / 2012-02-24
Facility ID:	1111515
Facility Type:	ER
DER Facility ID:	142316
Site ID:	459415
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2011-12-28

UNDERGROUND LINE (Continued) **S104514679**

Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2011-12-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-12-28
Spill Record Last Update:	2012-02-24
Spiller Name:	MIKE KATULIS
Spiller Company:	MARIA LEANO
Spiller Address:	27-10 37TH AVE
Spiller Company:	999
Contact Name:	MIKE KATULIS
DEC Memo:	"12/28/11- Zhune visited the site. RR Plumbing Sevice Corp. was going to replace the sewer line at this site. While digging they noiced oil smell. They stopped digging with the machine and started doing hand digging when they found soil contamination coming from a leaking return line. The line was shut down. AB Environmental is going to do the clean up. Violeta Leano 718-784-3530 -- Owner tleano@yahoo.com 02/24/12- On 02/15/12 AB Environmental emailed the report dated 02/9/12. The soil contaminated in the impacted area was removed. The excavation was completed as best that could be accomplished with out compromising the foundation. One endpoint sample was collected at the bottom of the excavation(7feet). The endpoint sample analytical result indicated that all detected constituents are within acceptable limit. Spill Closed. Report eDocs. "
Remarks:	"Found line broken. Been leaking for years"

All Materials:

Site ID:	459415
Operable Unit ID:	1209506
Operable Unit:	01
Material ID:	2206980
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

AM309 **P.S. 76 - QUEENS Q076** **NY AST** **U003394261**
NW **36-36 10TH STREET** **N/A**
1/8-1/4 **ASTORIA, NY 11106**
0.243 mi.
1285 ft. **Site 3 of 3 in cluster AM**

Relative:
Lower

Actual:
13 ft.

AST:

Name:	P.S. 76 - QUEENS Q076
Address:	36-36 10TH STREET
City,State,Zip:	ASTORIA, NY 11106
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-355089
Program Type:	PBS
UTM X:	589371.13612
UTM Y:	4512757.10027
Expiration Date:	06/28/2023
Site Type:	School

Affiliation Records:

Site Id:	17682
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	MANAGER, FUEL DIVISION
Contact Name:	MUNENDRA SHARMA
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	ACDANIEL
Date Last Modified:	2018-07-17

Site Id:	17682
Affiliation Type:	Mail Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	JOSEPH YOUNGHESE
Address1:	FIELD OPERATIONS - FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONGISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5779
EMail:	JYOUNGHESE@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2021-01-19

Site Id:	17682
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	KEN MAHADEO

P.S. 76 - QUEENS Q076 (Continued) **U003394261**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(646) 210-7918
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-08-03

Site Id:	17682
Affiliation Type:	Facility Operator
Company Name:	P.S. 76 - QUEENS Q076
Contact Type:	Not reported
Contact Name:	SALVATORE CALDERONE
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 361-0210
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2018-02-22

Tank Info:

Tank Number:	001
Tank Id:	34607
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G02 - Tank Secondary Containment - Vault (w/access)
	I04 - Overfill - Product Level Gauge (A/G)
	E00 - Piping Secondary Containment - None
	K01 - Spill Prevention - Catch Basin
	I02 - Overfill - High Level Alarm
	C03 - Pipe Location - Aboveground/Underground Combination
	J02 - Dispenser - Suction Dispenser
	L00 - Piping Leak Detection - None
	H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	F01 - Pipe External Protection - Painted/Asphalt Coating
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	05/23/1966

P.S. 76 - QUEENS Q076 (Continued) **U003394261**

Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	002
Tank Id:	34608
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

G02 - Tank Secondary Containment - Vault (w/access)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
H00 - Tank Leak Detection - None
E00 - Piping Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L00 - Piping Leak Detection - None
F01 - Pipe External Protection - Painted/Asphalt Coating
K00 - Spill Prevention - None
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	01/13/1999
Capacity Gallons:	7500
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	04/20/2015
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AK310 **ORLANDO FINISHING CORP** **US AIRS** **1007803073**
SW **40-09 21 STREET** **FINDS** **N/A**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.244 mi. **PFAS ECHO**
1287 ft. **Site 4 of 5 in cluster AK**

Relative: **Higher**
Actual: **18 ft.**

US AIRS (AFS):

Region Code:	02
County Code:	NY081
Programmatic ID:	AIR NY0000002630400558
Facility Registry ID:	110019656013
D and B Number:	Not reported

ORLANDO FINISHING CORP (Continued) **1007803073**

Facility Site Name: ORLANDO FINISHING CORP
Primary SIC Code: 7641
NAICS Code: 811420
Default Air Classification Code: SMI
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS (AFS):
Region Code: 02
Programmatic ID: AIR NY0000002630400558
Facility Registry ID: 110019656013
Air Operating Status Code: OPR
Default Air Classification Code: SMI

Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-11-06 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

FINDS:
Registry ID: 110019656013

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
AIR SYNTHETIC MINOR
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1007803073
Registry ID: 110019656013
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110019656013
Name: ORLANDO FINISHING CORP
Address: 40-09 21 STREET
City,State,Zip: LONG ISLAND CITY, NY 11101

PFAS ECHO:
Name: ORLANDO FINISHING CORP

ORLANDO FINISHING CORP (Continued) **1007803073**

Address:	Not reported
City,State,Zip:	LONG ISLAND CITY, NY
Latitude:	40.754605
Longitude:	-73.941835
Count:	1
County:	QUEENS
Status:	Active
Region:	02
Industry:	Furniture and Carpet
ECHO Facility Report:	https://echo.epa.gov/detailed-facility-report?fid=110019656013
Facility Percent Minority:	43.116
Facility Derived Tribes:	-
Facility Population:	46564.63
EPA Programs:	CAA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	36081
Facility Indian Country Flag:	N
Facility Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Facility Derived HUC:	02030201
Facility Derived WBD:	020301010405
Facility Derived CD113:	12
Facility Derived CB2010:	360810033002000
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	0
Facility Date Last Inspection:	-
Facility Days Last Inspection:	-
Facility Informal Count:	0
Facility Date Last Informal Action:	-
Facility Formal Action Count:	0
Facility Date Last Formal Action:	-
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	-
Facility Last Penalty AMT:	-
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	Y
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	NY0000002630400558
CAA Permit Types:	Synthetic Minor Emissions
CAA NAICS:	811420
CAA SICS:	7641
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-

ORLANDO FINISHING CORP (Continued) **1007803073**

SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-
EJSCREEN Flag US:	Y
EJSCREEN Report:	https://ejscreen.epa.gov/mapper/mobile/EJSCREEN_mobile.aspx?geometry=%7B%22x%22:-73.941835,%22y%22:40.754605,%22spatialReference%22:%7B%22wkid%22:4326%7D%7D&unit=9035&areatype=&areaid=&basemap=streets&distance=1

AK311 **SCHMIT MACHINE INC** **RCRA NonGen / NLR** **1000789675**
SW **40-09 21ST ST - GROUND ST** **FINDS** **NYD987011368**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.244 mi.
1287 ft. **Site 5 of 5 in cluster AK**

Relative: **Higher**
Actual: **18 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Schmit Machine Inc
Handler Address:	40-09 21ST ST - GROUND ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD987011368
Contact Name:	Not reported
Contact Address:	21ST ST - GROUND ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	21ST ST - GROUND ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Abraham Mathews
Owner Type:	Private
Operator Name:	Abraham Mathews
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

SCHMIT MACHINE INC (Continued) **1000789675**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D039
Waste Description:	Tetrachloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: ABRAHAM MATHEWS	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	406 CHARLES ST
Owner/Operator City,State,Zip:	EAST WILLISTON, NY 11596
Owner/Operator Telephone:	516-747-6883
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

SCHMIT MACHINE INC (Continued) **1000789675**

Owner/Operator Indicator: Operator
Owner/Operator Name: ABRAHAM MATHEWS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 406 CHARLES ST
Owner/Operator City,State,Zip: EAST WILLISTON, NY 11596
Owner/Operator Telephone: 516-747-6883
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ABRAHAM MATHEWS
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 406 CHARLES ST
Owner/Operator City,State,Zip: EAST WILLISTON, NY 11596
Owner/Operator Telephone: 516-747-6883
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19990708
Handler Name: SCHMIT MACHINE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: SCHMIT MACHINE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: SCHMIT MACHINE INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

SCHMIT MACHINE INC (Continued) **1000789675**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	19920806
Handler Name: SCHMIT MACHINE INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004493646

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000789675
Registry ID:	110004493646
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004493646
Name:	SCHMIT MACHINE INC
Address:	40-09 21ST ST - GROUND ST
City,State,Zip:	LONG ISLAND CITY, NY 11101

AJ312 **CENTRAL COLLISION INC** **RCRA-VSQG** **1000432498**
NNW **10-12 36TH AVE** **NY MANIFEST** **NYD045428125**
1/8-1/4 **LONG ISLAND CITY, NY 11106**
0.244 mi.
1287 ft. **Site 2 of 2 in cluster AJ**

Relative: **Lower**
Actual: **15 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Central Collision Inc
Handler Address:	10-12 36TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYD045428125
Contact Name:	MICHAEL TORRE
Contact Address:	36TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11106
Contact Telephone:	718-729-2867
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	36TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner Name:	Michael Torre
Owner Type:	Private
Operator Name:	Michael Torre
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CENTRAL COLLISION INC (Continued) **1000432498**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: MICHAEL TORRE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name: MICHAEL TORRE	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

CENTRAL COLLISION INC (Continued) **1000432498**

Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: MICHAEL TORRE
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: CENTRAL COLLISION INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: CENTRAL COLLISION INC
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19860326
Handler Name: CENTRAL COLLISION INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

CENTRAL COLLISION INC (Continued) **1000432498**

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20190620
Evaluation Responsible Agency: State
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSR
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: Not reported
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

CENTRAL COLLISION INC (Continued) **1000432498**

NY MANIFEST:

Name:	CENTRAL COLLISION INCORPORATED
Address:	10-12 36TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYD045428125
Facility Status:	Not reported
Location Address 1:	10-12 36TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD045428125
Mailing Name:	CENTRAL COLLISION INCORPORATED
Mailing Contact:	CENTRAL COLLISION INCORPORATED
Mailing Address 1:	10-12 36TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187292867

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD080631369
Trans2 State ID:	Not reported
Generator Ship Date:	12/06/2007
Trans1 Recv Date:	12/06/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/06/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD045428125
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD980536593
TSDF ID 2:	Not reported
Manifest Tracking Number:	000161550VES
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CENTRAL COLLISION INC (Continued) **1000432498**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	760
Units:	P - Pounds
Number of Containers:	4
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	F003
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	F005
Waste Code 1_5:	D035
Waste Code 1_6:	Not reported

AQ313 **WALKER E WHYTE INC** **RCRA-SQG** **1004755983**
SSW **22-14 40TH AVE** **FINDS** **NY0000915165**
1/8-1/4 **LONG ISLAND CITY, NY 11101** **ECHO**
0.245 mi. **NY MANIFEST**
1292 ft. **Site 2 of 3 in cluster AQ**

Relative: **Higher**

Actual: **25 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Walker E Whyte Inc
Handler Address:	22-14 40TH AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NY0000915165
Contact Name:	PETER DUGGAN
Contact Address:	40TH AVE
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-786-9897
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	40TH AVE
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Kuos Realty Inc
Owner Type:	Private
Operator Name:	Kuos Realty Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

WALKER E WHYTE INC (Continued) **1004755983**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: KUOS REALTY INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	36-32 34TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner/Operator Telephone:	718-937-5011
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

WALKER E WHYTE INC (Continued) **1004755983**

Owner/Operator Indicator:	Operator
Owner/Operator Name: KUOS REALTY INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	36-32 34TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner/Operator Telephone:	718-937-5011
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: KUOS REALTY INC	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	36-32 34TH ST
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11106
Owner/Operator Telephone:	718-937-5011
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: WALKER E WHYTE INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name: WALKER E WHYTE INC	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19941103
Handler Name: WALKER E WHYTE INC	
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

WALKER E WHYTE INC (Continued) **1004755983**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19960915
Handler Name:	WALKER & WHYTE INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	54138
NAICS Description:	TESTING LABORATORIES AND SERVICES

Has the Facility Received Notices of Violations:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20201022
Actual Return to Compliance Date:	20201201
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

WALKER E WHYTE INC (Continued) **1004755983**

SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20090604
Actual Return to Compliance Date: 20090717
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20090827
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20201022
Actual Return to Compliance Date: 20201201
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported

WALKER E WHYTE INC (Continued) **1004755983**

Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Listing - General
Date Violation was Determined:	20090604
Actual Return to Compliance Date:	20090717
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20090618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20090827
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYHHN
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported

WALKER E WHYTE INC (Continued) **1004755983**

SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Listing - General
Date Violation was Determined: 20090604
Actual Return to Compliance Date: 20090717
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20090618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20090827
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYHHN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20201022
Actual Return to Compliance Date: 20201201
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported

WALKER E WHYTE INC (Continued) **1004755983**

Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20201022
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYSC
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20201201
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20090604
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYHHN
Evaluation Responsible Sub-Organization: R2
Actual Return to Compliance Date: 20090717
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 20201022
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE

WALKER E WHYTE INC (Continued) **1004755983**

Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20201201
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090604
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090717
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20090604
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20090717
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20201022
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSC
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20201201
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:
Registry ID: 110000805914

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

WALKER E WHYTE INC (Continued) **1004755983**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004755983
Registry ID:	110000805914
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110000805914
Name:	WALKER E WHYTE INC
Address:	22-14 40TH AVE
City,State,Zip:	LONG ISLAND CITY, NY 11101

NY MANIFEST:

Name:	WALKER & WHYTE INC
Address:	22-14 40TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101-4825
Country:	USA
EPA ID:	NY0000915165
Facility Status:	Not reported
Location Address 1:	22-14 40TH AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000915165
Mailing Name:	WALKER & WHYTE INC
Mailing Contact:	PETER DUGGAN
Mailing Address 1:	22-14 40 TH AVENUE
Mailing Address 2:	Not reported
Mailing City:	LONG ISLANDCITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7187869897

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NJD054126164
Trans2 State ID:	Not reported
Generator Ship Date:	12/14/2006
Trans1 Recv Date:	12/14/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2006
Part A Recv Date:	Not reported

WALKER E WHYTE INC (Continued) **1004755983**

Part B Recv Date:	Not reported
Generator EPA ID:	NY0000915165
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	001878800JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3500
Units:	P - Pounds
Number of Containers:	10
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AQ314 **22-14 40TH AVENUE** **NY AST** **A100362306**
SSW **22-14 40TH AVENUE** **N/A**
1/8-1/4 **LIC, NY 11101**
0.245 mi.
1292 ft. **Site 3 of 3 in cluster AQ**

Relative: **Higher**
Actual: **25 ft.**

AST:

Name:	22-14 40TH AVENUE
Address:	22-14 40TH AVENUE
City,State,Zip:	LIC, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Inactive
Facility Id:	2-611861
Program Type:	PBS
UTM X:	589464.86248
UTM Y:	4512057.31075
Expiration Date:	N/A
Site Type:	Apartment Building/Office Building

22-14 40TH AVENUE (Continued) **A100362306**

Affiliation Records:

Site Id:	467032
Affiliation Type:	Facility Owner
Company Name:	KOU
Contact Type:	MGR
Contact Name:	KAREN
Address1:	36-32 34TH STREET
Address2:	Not reported
City:	LIC
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 937-5011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-07-27

Site Id:	467032
Affiliation Type:	Mail Contact
Company Name:	KOUS REALTY
Contact Type:	Not reported
Contact Name:	KAREN
Address1:	36-32 34TH STREET
Address2:	36-32 34TH STREET
City:	LIC
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 937-5011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-07-27

Site Id:	467032
Affiliation Type:	Facility Operator
Company Name:	22-14 40TH AVENUE
Contact Type:	Not reported
Contact Name:	KAREN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-5011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-07-27

Site Id:	467032
Affiliation Type:	Emergency Contact
Company Name:	KOU
Contact Type:	Not reported
Contact Name:	KAREN

22-14 40TH AVENUE (Continued) **A100362306**

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 937-5011
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MSBAPTIS
Date Last Modified:	2012-07-27

Tank Info:

Tank Number:	001
Tank Id:	244960
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	G00 - Tank Secondary Containment - None
	I00 - Overfill - None
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	L00 - Piping Leak Detection - None
	F00 - Pipe External Protection - None
	B00 - Tank External Protection - None
	J00 - Dispenser - None
	C01 - Pipe Location - Aboveground
	K00 - Spill Prevention - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	A00 - Tank Internal Protection - None
Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Galvanized Steel Alloy
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1955
Capacity Gallons:	4000
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)

AR315 **3707 9TH AVENUE** **NY LTANKS** **S101102946**
WNW **3707 9TH AVENUE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.253 mi.
1336 ft. **Site 1 of 2 in cluster AR**

Relative: **Lower**

Actual: **13 ft.**

LTANKS:

Name:	3707 9TH AVENUE
Address:	3707 9TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9315059 / 1994-03-24
Facility ID:	9315059
Site ID:	167949
Spill Date:	1994-03-23
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1994-03-24
SWIS:	4101
Investigator:	CAMMISA
Referred To:	Not reported
Reported to Dept:	1994-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-25
Spill Record Last Update:	2004-09-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	141499
DEC Memo:	""
Remarks:	"SPILL CONTAINED ON CONCRETE FLOOR - CLEAN UP WITH SORBENT."

All Materials:

Site ID:	167949
Operable Unit ID:	996993
Operable Unit:	01
Material ID:	386832
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-2.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AS316 **PATANO BROTHERS;INC** **NY SWF/LF** **S105841789**
West **38-36 10 STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.257 mi.
1355 ft. **Site 1 of 4 in cluster AS**

Relative: **Lower**
Actual: **14 ft.**

SWF/LF:

Name:	PATANO BROTHERS;INC
Address:	38-36 10 STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Flag:	INACTIVE
Region Code:	2
Phone Number:	5167946690
Owner Name:	Not reported
Owner Type:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	JOHN PATANO
Contact Address:	Not reported
Contact Addr2:	Not reported
Contact City,St,Zip:	Not reported
Contact Email:	Not reported
Contact Phone:	Not reported
Activity Desc:	Transfer station - permit
Activity Number:	[41T19]
Active:	No
East Coordinate:	589200
North Coordinate:	4512500
Accuracy Code:	Not reported
Regulatory Status:	Permit
Waste Type:	Not reported
Authorization #:	2-6304-00112
Authorization Date:	2/12/1990
Expiration Date:	2/12/1995
Operator Name:	Not reported
Operator Type:	Not reported
Laste Date:	Not reported

AT317 **PERETTE HALL** **NY LTANKS** **S107789477**
WSW **38-62 11TH STREET** **N/A**
1/4-1/2 **LONG ISLAND, NY**
0.265 mi.
1400 ft. **Site 1 of 2 in cluster AT**

Relative: **Lower**
Actual: **15 ft.**

LTANKS:

Name:	PERETTE HALL
Address:	38-62 11TH STREET
City,State,Zip:	LONG ISLAND, NY
Spill Number/Closed Date:	0602016 / 2006-05-24
Facility ID:	0602016
Site ID:	364400
Spill Date:	2006-05-24
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101

PERETTE HALL (Continued) **S107789477**

Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2006-05-24
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-24
Spill Record Last Update:	2006-05-24
Spiller Name:	ROSE
Spiller Company:	PETRO
Spiller Address:	5560 58TH STREET
Spiller County:	001
Spiller Contact:	KATHERINE
Spiller Phone:	(212) 545-0378
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	314626
DEC Memo:	""
Remarks:	"CREW ENROUTE TO CLEAN UP"

All Materials:

Site ID:	364400
Operable Unit ID:	1122425
Operable Unit:	01
Material ID:	2111899
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AP318 **ABANDONED BLDG** **NY LTANKS** **S103478191**
SSE **38-28 28TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.271 mi.
1433 ft. **Site 2 of 2 in cluster AP**

Relative:
Higher

Actual:
44 ft.

LTANKS:

Name:	ABANDONED BLDG
Address:	38-28 28TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9805230 / 1999-04-27
Facility ID:	9805230
Site ID:	271765
Spill Date:	1998-07-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3

ABANDONED BLDG (Continued) **S103478191**

Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1998-07-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-27
Spill Record Last Update:	1999-06-08
Spiller Name:	YELLOWSTONE INDUSTRIES
Spiller Company:	ABANDONED BLDG
Spiller Address:	38-28 28TH ST
Spiller County:	001
Spiller Contact:	YELLOWSTONE INDUSTRIES
Spiller Phone:	(516) 485-0000
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	221178
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE SEE FILE."
Remarks:	"2 TANKS ON SITE UNK SIZE / BOTH TANKS FAILED"

All TTF:

Facility ID:	9805230
Spill Number:	9805230
Spill Tank Test:	1546107
Site ID:	271765
Tank Number:	1
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271765
Operable Unit ID:	1066395
Operable Unit:	01
Material ID:	319979
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

ABANDONED BLDG (Continued) **S103478191**

Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AS319 **NATIONAL RUBBER ADHESIVES, INC.** **NY VCP** **S113922106**
West **38-25/51 9TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.272 mi.
1438 ft. **Site 2 of 4 in cluster AS**

Relative: VCP:
Lower

Actual:
13 ft.

Name:	NATIONAL RUBBER ADHESIVES, INC.
Address:	38-25/51 9TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101-
Program Type:	VCP
Site Code:	57542
HW Code:	V00662
Site Class:	N
SWIS:	4101
Region:	2
Town:	New York City
Acres:	0.500
Date Record Added:	08/01/2003
Date Record Updated:	04/23/2021
Updated By:	SMQUANDT
Site Description:	"See Registry Site # 241028"
Env Problem:	"See Registry Site # 241028 "
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported

NATIONAL RUBBER ADHESIVES, INC. (Continued) **S113922106**

Record Updated: Not reported
Updated By: Not reported

AS320 **NATIONAL RUBBER ADHESIVES, INC.** **NY BROWNFIELDS** **S113916537**
West **38-25/51 9TH STREET** **N/A**
1/4-1/2 **QUEENS, NY 11101**
0.272 mi.
1438 ft. **Site 3 of 4 in cluster AS**

Relative: **Lower**

Actual: **13 ft.**

BROWNFIELDS:

Name:	NATIONAL RUBBER ADHESIVES, INC.
Address:	38-25/51 9TH STREET
City,State,Zip:	QUEENS, NY 11101
Program:	BCP
Site Code:	57426
Acres:	0.500
HW Code:	C241028
SWIS:	4101
Town:	New York City
Record Added Date:	05/28/2004
Record Updated Date:	04/23/2021
Update By:	SMQUANDT
Site Description:	"Transition from Site #V00662 The property is located within an urban industrialized section of Long Island City. The site extends 335 feet from the north to the south and 117 feet from the west to the east. The entire site is occupied by a 30,000 square feet, one story building. There is a small courtyard in the central portion of the building, on it's western side. The site is approximately 15 to 20 feet above mean sea level. The nearest surface water body is the East River, approximately one quarter mile west of the site. Site ownership changed in 2002. The new owners originally entered the Volunteer Cleanup Program to address hazardous waste contamination but transitioned to the Brownfield Cleanup Program (BCP). A BCP application was approved in 2004 and the proposed future use is industrial, including warehousing. BCA Terminated - Letter dated 8/30/07. See Registry Site # 241028."
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported

NATIONAL RUBBER ADHESIVES, INC. (Continued) **S113916537**

HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AS321 **NATIONAL RUBBER & BACKING CORP** **NY SHWS** **1000259753**
West **38-31 9TH ST** **NY CBS** **NYD990690190**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY VCP**
0.281 mi. **NY Spills**
1484 ft. **Site 4 of 4 in cluster AS** **RCRA NonGen / NLR**

Relative: **Lower**
Actual: **13 ft.**

SHWS:

Name:	NATIONAL RUBBER ADHESIVES, INC.
Address:	38-31 9TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW
Site Code:	58713
Classification:	Significant threat to the public health or environment - action required.
Region:	2
Acres:	1.000
HW Code:	241028
Record Add:	11/18/1999
Record Upd:	07/25/2022
Updated By:	SMQUANDT

Site Description: "LOCATION: The site is located in an urban/industrial section of Long Island City at the intersection of 9th Street between 38th Avenue and 40th Avenue. It is located on the east side of 9th Street, approximately 0.4 miles north of the Queensboro Bridge. SITE FEATURES: The property extends 335 feet from north-to-south, and 117 feet from west-to-east. The former location of Buildings 2 through 4 were demolished for the construction of a hotel. Building 1 is still standing and has a slab-on-grade masonry building. The site and surrounding areas are generally level. CURRRENT ZONING AND LAND USE: The site is currently zoned commercial. The site originally consisted of multiple lots but they have recently been merged into one lot (Lot 19). Building 1 along the northern portion of the site is still in place and was most recently used as a granite and marble fabrication shop. A developer purchased the entire site and is building a hotel on the former location of buildings 2 through 4. The tenant in Building 1 will operate their business until they find another location to relocate to. PAST USE OF SITE: National Rubber Adhesives, Inc. operated a manufacturing facility for adhesives until 1995 and operated at this location for 62 years. (National Rubber Adhesives, Inc. occupied the northern two-thirds of the building.) Five underground storage tanks (USTs) were closed in-place, including one toluene, two gasoline, one methyl ethyl ketone (MEK) and one heptane UST. Six additional 500 gallon USTs, which were previously closed in place, were removed in April 2014. During construction of the foundation for the hotel, nine USTs were removed from the site along with all soils above bedrock within the footprint of the hotel. OPERABLE UNIT(S): The site is being managed through two operable

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

units (OU). OU1 is for off-site work and OU2 is for on-site work. Each OU will include investigation of soil, groundwater, and soil vapor contamination. Building 1 was sold to the owner of the Marble fabrication business previously located in Building 2. Buildings 2-4 have been demolished, and 9th Street LIC LLC has signed a Consent Order with NYSDEC for remediation of former Lots 14 and 19 (Building 2 through 4) and that work is ongoing. 9th Street LIC recently signed onto another Consent Order for implementing a remedial program for the remaining site (incl. Building 1), and off-site. SITE GEOLOGY AND HYDROGEOLOGY: The site is approximately 15 to 20 feet above mean sea level. The nearest surface water body is the East River, approximately one quarter mile west of the site. Groundwater was observed approximately 5 to 10 feet below ground surface and flows in a westerly direction toward the East River. The depth to bedrock varies across the investigation area from 10 to 15 feet below surface."

Env Problem: "Nature and Extent of Contamination: For OU 2: On-Site Areas Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, pesticides, and poly chlorinated biphenyls (PCBs). On-site soil vapor has been analyzed for VOCs. Groundwater - Based on investigations conducted to date, the primary contaminant of concern for OU 2 is toluene. However, BTEX and chlorinated solvents also have been found above standards on-site. Toluene has been detected at levels as high as 280,000,000 parts per billion (ppb) (NYSDEC groundwater quality standard is 5 ppb). Latest sampling results (collected August 2018) revealed the highest toluene concentrations at 32,500 ppb, down from 749,000 ppb, detected in March 2015. Additional contaminants are also present in groundwater, including concentrations of benzene up to 24.2 ppb (standard is 1 ppb), ethylbenzene up to 36.5 ppb (standard is 5 ppb), and xylenes up to 59 ppb (standard is 5 ppb) as of August 2018. These additional contaminants were present at concentrations an order of magnitude greater than samples collected in March 2015. August 2018 groundwater sampling detected concentrations of tetrachloroethene (PCE) up to 65 ppb (standard is 5 ppb) in the southeast corner (PCE was detected in the northeast corner of the site at 336 ppb in March 2015; however, this location was inaccessible during the August 2018 sampling effort), trichloroethene (TCE) up to 17 ppb (standard is 5 ppb) in the southeast corner (TCE was detected in the northeast corner at 26 ppb in March 2015), cis-1,2-dichloroethene (cis-1,2-DCE) up to 33 ppb (standard is 5 ppb) in the southeast corner (previously detected at 122 ppb in the northeast portion of the site in March 2015), and vinyl chloride up to 4 ppb (standard is 2 ppb) (previously detected at 77 ppb in northeast corner of the site in March 2015). Soil - Previous investigations have detected toluene at concentrations as high as 1,600 parts per million (ppm) (industrial use soil cleanup objective (IUSCO) is 1,000 ppm) in the vicinity of the 5 closed USTs at depths of 5 - 7 feet below ground surface (bgs). Toluene was also detected in the former location of the six 500 gallon USTs at concentrations as high as 500 ppm at 1.5 feet bgs. Soil Vapor - Benzene and toluene were detected in indoor air and sub-slab soil vapor; however, the indoor air concentrations were higher for both constituents suggesting an indoor source. PCE and TCE have also been detected in indoor air, sub-slab, and deeper soil vapor. 2014 data revealed indoor air concentrations of TCE inside building #2 at 10 micrograms per cubic meter (ug/m^3), and PCE at 30 ug/m^3. November 2014 sub-slab data revealed concentrations of PCE up

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

to 53,000 ug/m^3, and TCE at concentrations up to 2,200 ug/m^3. A sub slab depressurization system was installed beneath the newly constructed hotel that occupies the former footprint of building 2, 3 and 4. For OU 1: Off-Site Areas Soil and groundwater have been analyzed for VOCs, SVOCs, and metals. Off-site soil vapor has been analyzed for VOCs. Groundwater - Based on investigations conducted to date, the off-site (OU 1) groundwater plume appears to be migrating to the east, but has not reached the East River. The most recent sampling event from November 2018 revealed toluene at a maximum concentration of 11,000 ppb (standard is 5 ppb) in a down-gradient well across 9th Street. Off-site impacts have been delineated and toluene does not appear to be migrating across Vernon Boulevard, possibly due to regional geology/bedrock formations preventing widespread off-site migration of contaminated groundwater. Additional VOCs have been detected; latest sample results (November 2018) detected concentrations of benzene up to 370 ppb (standard is 1 ppb), cis-1,2-DCE up to 45 ppb (standard is 5 ppb), TCE up to 7.1 ppb (standard is 5 ppb), and vinyl chloride up to 10 ppb (standard is 2 ppb). Soil - No off-site soil impacts have been detected above standards. Soil Vapor - A soil vapor intrusion evaluation in nearby buildings was performed in March 2016. The buildings to the south east of OU2 had detections of site-related VOCs (PCE and TCE) in indoor air and sub-slab vapor samples; however indoor air concentrations do not warrant mitigation provided the on-site source is addressed."

Health Problem:	"Elevated levels of volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals have been identified in soil and groundwater at this site. The area is paved and served by pubic water so exposures to contaminated soils and groundwater are unlikely. Due to the high levels of VOCs in on-site groundwater, there is the potential for exposures related to soil vapor intrusion in surrounding buildings. A soil vapor investigation is planned as part of the ongoing remedial investigation."
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	unknown
Lat/Long:	40:45:30:0 / 73:56:39:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2013-09-19 15:05:00
Updated By:	kbdilige
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queensboro Public Library
Owner Address:	Long Island City Branch
Owner Addr2:	37-44 21st Street
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Debra Markell Kleinert
Owner Company:	Queens Community Board #2

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Owner Address:	43-22 50th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Woodside, NY 11377
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	Brian G. Wrynn
Owner Company:	9th Street LIC LLC
Owner Address:	420 Great Neck Road
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
HW Code:	241028
Waste Type:	TOLUENE U-220 (F005 WASTE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	TOLUENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	dichloroethene (cis-1,2-)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241028
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1306971
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2013-10-04 10:30:00
Record Updated:	2013-10-04 10:30:00

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Updated By: RXKEATIN
Crossref ID: C241028
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2008-05-27 11:08:00
Record Updated: 2008-05-27 11:08:00
Updated By: DMMOLOUG
Crossref ID: 9602231
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2021-05-27 09:19:00
Record Updated: 2021-05-27 09:19:00
Updated By: JHOCONNE
Crossref ID: V00662
Cross Ref Type Code: 04
Cross Ref Type: VC Site ID
Record Added Date: 2003-08-04 13:42:00
Record Updated: 2003-08-04 13:42:00
Updated By: ajsylves
Crossref ID: NYD990690190
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS

CBS:
Name: NATIONAL RUBBER BACKING CORP.
Address: 38-31 9TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
CBS Number: 2-000015
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 590155.69052
UTMY: 4512021.40769

VCP:
Name: NATIONAL RUBBER ADHESIVES INC.
Address: 38-31 9TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Program Type: VCP
Site Code: 57620
HW Code: V00173
Site Class: N
SWIS: 4101
Region: 2
Town: New York City
Acres: Not reported
Date Record Added: 11/30/2000
Date Record Updated: 04/23/2021
Updated By: SMQUANDT
Site Description: "The property is located within an urban industrialized section of Long Island City. The site extends 335 feet from the north to the south and 117 feet from the west to the east. The entire site is

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

occupied by a 30,000 square feet, one story building. There is a small courtyard in the central portion of the building, on its western side. The site is approximately 15 to 20 feet above mean sea level. The nearest surface water body is the East River, approximately one quarter mile west of the site. See Registry Site # 241028 and Brownfield Cleanup Program Site # C241028. "

Env Problem:	"See Registry Site # 241028 and Brownfield Cleanup Program Site # C241028"
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	NATIONAL RUBBER ADHESIVES
Address:	38-31 9TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9602231 / 2021-06-01
Facility ID:	9602231
Facility Type:	ER
DER Facility ID:	109736
Site ID:	127024
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	4101
Spill Date:	1996-03-01
Investigator:	KMFORSTE
Referred To:	Not reported
Reported to Dept:	1996-05-16

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-05-16
Spill Record Last Update:	2021-06-01
Spiller Name:	YALE BLOCK
Spiller Company:	NATIONAL RUBBER ADHESIVES
Spiller Address:	38-31 9TH STREET
Spiller Company:	001
Contact Name:	YALE BLOCK
DEC Memo:	"5/27/21 - Spill is associated with site no. 241028. Reassigned to Kyle Forster (JHO) 6/1/2021 - Spill closed and being tracked under 241028. (KMF)"
Remarks:	"PHASE 1 AND PARTIAL PHASE 2 SITE ASSESSMENT PERFORMED AT SPILLER'S REQUEST. CALLER KNEW THAT THERE WERE UNDERGROUND STORAGE TANKS THAT HAD BEEN CLOSED IN PLACE. SOME OF THIS CONTAMINATION POSSIBLY DATE BACK 50 YEARS OR MORE. CALLER WILL CONTACT REGION 2 OFFICE FOR FURTHER INFORMATION."

All Materials:

Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01
Material ID:	352038
Material Code:	0041B
Material Name:	toluol
Case No.:	00108883
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01
Material ID:	352039
Material Code:	0042A
Material Name:	xylene (mixed)
Case No.:	01330207
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Site ID:	127024
Operable Unit ID:	1033794
Operable Unit:	01

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Material ID:	352040
Material Code:	0230A
Material Name:	ethylbenzene
Case No.:	00100414
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	National Rubber & Backing Corp
Handler Address:	38-31 9TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD990690190
Contact Name:	MARC HALPERN
Contact Address:	9TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-784-7945
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	9TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Ownername
Owner Type:	Private
Operator Name:	Ownername
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: OWNERNAME	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: OWNERNAME	

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name:	NATIONAL RUBBER & BACKING CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	20070101
Handler Name:	NATIONAL RUBBER & BACKING CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19851108
Handler Name:	NATIONAL RUBBER & BACKING CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	19920221
Handler Name:	NATIONAL RUBBER AND BACKING
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960822
Handler Name: NATIONAL RUBBER ADHESIVES INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 325212
NAICS Description: SYNTHETIC RUBBER MANUFACTURING

NAICS Code: 32552
NAICS Description: ADHESIVE MANUFACTURING

NAICS Code: 326299
NAICS Description: ALL OTHER RUBBER PRODUCT MANUFACTURING

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 19980819
Evaluation Responsible Agency: EPA
Found Violation: No
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: R2MD
Evaluation Responsible Sub-Organization: RCB

NATIONAL RUBBER & BACKING CORP (Continued) **1000259753**

Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19870803
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

AU322 **QUEENSBRIDGE PLANT B** **NY LTANKS** **S100493845**
SW **40001 12TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.283 mi.
1492 ft. **Site 1 of 2 in cluster AU**

Relative: **Lower**
Actual: **16 ft.**

LTANKS:

Name:	QUEENSBRIDGE PLANT B
Address:	40001 12TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9205290 / 1995-08-16
Facility ID:	9205290
Site ID:	213263
Spill Date:	1992-08-07
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	1995-08-16
SWIS:	4101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1992-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-08-10
Spill Record Last Update:	1995-08-16
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported

QUEENSBRIDGE PLANT B (Continued) **S100493845**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 176686
DEC Memo: ""
Remarks: "15K; HORNER EZ CHECK - GROSS. UPDATE: TANK REMOVED IN 1994"

All TTF:
Facility ID: 9205290
Spill Number: 9205290
Spill Tank Test: 1540358
Site ID: 213263
Tank Number: 001
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Facility ID: 9205290
Spill Number: 9205290
Spill Tank Test: 1540359
Site ID: 213263
Tank Number: 002
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 213263
Operable Unit ID: 972694
Operable Unit: 01
Material ID: 554247
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported
Recovered: .00
Resource Affected: Soil

QUEENSBRIDGE PLANT B (Continued) **S100493845**

Oxygenate: Not reported

AR323 **8-14 37TH AVE.** **NY LTANKS** **S100494048**
WNW **8-14 37TH AVE.** **N/A**
1/4-1/2 **QUEENS, NY**
0.283 mi.
1493 ft. **Site 2 of 2 in cluster AR**

Relative: **Lower**

Actual: **12 ft.**

LTANKS:

Name:	8-14 37TH AVE.
Address:	8-14 37TH AVE.
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9207231 / 1992-12-10
Facility ID:	9207231
Site ID:	316906
Spill Date:	1992-09-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-12-10
SWIS:	4101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1992-09-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-09-23
Spill Record Last Update:	1992-12-17
Spiller Name:	Not reported
Spiller Company:	PRIVATE CORP.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	255498
DEC Memo:	""
Remarks:	"INCONCLUSIVE TEST-SEEMS TO BE LEAKING PIPE-NOTIFIED NYCFD INSPECTOR-LOWERED PRODUCT LEVEL WILL EXCAVATE AND REPAIR NO CALLBACK."

All TTF:

Facility ID:	9207231
Spill Number:	9207231
Spill Tank Test:	1540609
Site ID:	316906
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported

8-14 37TH AVE. (Continued) **S100494048**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	316906
Operable Unit ID:	970866
Operable Unit:	01
Material ID:	407883
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AU324 **QUEENSBRIDGE PLANT A** **NY LTANKS** **S100168059**
SW **40013 12TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.285 mi.
1505 ft. **Site 2 of 2 in cluster AU**

Relative: **Lower**

Actual: **16 ft.**

LTANKS:

Name:	QUEENSBRIDGE PLANT A
Address:	40013 12TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9008034 / 1995-08-16
Facility ID:	9008034
Site ID:	67975
Spill Date:	1990-10-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-08-16
SWIS:	4101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-10-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-02
Spill Record Last Update:	1995-08-16

QUEENSBRIDGE PLANT A (Continued) **S100168059**

Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 64877
DEC Memo: ""
Remarks: "(2) 15K TANK MANIFOLDED FAILED HORNER EZY CHECK WITH A GROSS LEAK. UPDATE: TANK REMOVED 1994"

All TTF:
Facility ID: 9008034
Spill Number: 9008034
Spill Tank Test: 1537748
Site ID: 67975
Tank Number: 001
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Facility ID: 9008034
Spill Number: 9008034
Spill Tank Test: 1537749
Site ID: 67975
Tank Number: 002
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 67975
Operable Unit ID: 948688
Operable Unit: 01
Material ID: 431866
Material Code: 0002A
Material Name: #4 fuel oil

QUEENSBRIDGE PLANT A (Continued) **S100168059**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AV325 **NAVAL SHIPYARD QUEENS** **FUDS** **1024899195**
WNW **N/A**
1/4-1/2 **LONG ISLAND, NY**
0.301 mi.
1587 ft. **Site 1 of 3 in cluster AV**

Relative: **Lower**
Actual: **12 ft.**

FUDS:

EPA Region:	02
Installation ID:	NY29799F759800
Congressional District Number:	7
Name:	NAVAL SHIPYARD QUEENS
FUDS Number:	C02NY0039
City:	LONG ISLAND
State:	NY
County:	QUEENS
Object ID:	5521
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	PRIV: PRIVATE CON EDISON -- A POWER UTILITY
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=62685
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not reported
Project Required:	No
Feature Description:	In April 1942 the U.S. Government obtained 3.71 acres fee for New York Naval Shipyard - Queens Annex. The site was utilized by the Department of Navy as a shipbuilding and ship repair facility. In June 1958 the Department of Navy transferred the site to General Service Administration (GSA), which subsequently conveyed the 3.71 acres fee site in March 1960 to the Consolidated Edison Company of New York (Con Edison) - the current owner.
Latitude:	40.75944444
Longitude:	-73.94388889

---

326 **QUEENS WEST 01 DOS -DDC** **NY LTANKS** **S104952980**
NNE **34-28 21ST STREET** **NY Spills** **N/A**
1/4-1/2 **QUEENS, NY**
0.306 mi.
1614 ft.

Relative: **Higher**
Actual: **18 ft.**

LTANKS:

Name:	QUEENS WEST 1 GARAGE DOS -DDC
Address:	34-28 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9809914 / 2005-12-20
Facility ID:	9809914

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

Site ID:	174749
Spill Date:	1998-11-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	1998-11-06
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1998-11-06
Spill Record Last Update:	2005-12-20
Spiller Name:	Not reported
Spiller Company:	DEPT OF SANITATION
Spiller Address:	QUEENS WEST 1
Spiller County:	001
Spiller Contact:	ERIKA POWER
Spiller Phone:	(212) 922-0077
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	110935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY IT Corp./Shaw has installed and is operating a dual-phase & soil vapor extraction system at the site to address soil & groundwater contamination and small amounts of free product. Site is currently in O&M phase. This spill transferred from Kolleeny to A. Zhitomirsky on 4/6/05. - JK 05/05/2005 I have reviewed quaterly status report received from JK. It presented remedial system performance monitoring data. The report stated that based on the site monitoring data, the dual phase extraction (DPE) system deem no longer necessary, since asymptotic levels of dissolved phase concentrations have been achieved. However, a few wells still contain VOCs at low concentrations above the TOGS values. Shaw has proposed to turn off the DPE part of the system and install ORC socks in wells with VOC concentrations above the TOGS values. The Department concured with this proposal.AZ 12/20/2005 Reviewed report submitted by Shaw and dated November 9, 2005. The report stated that no VOCs or SVOCs were detected above TOGS GUidance values during March or June 2005 sampling events. Results of the confirmatory soil borings taken from August 30 to Septmeber 1, 2005, showed that VOCs were below TAGM Guidance values, with only one exceedance, W-17A (8'-11'). SVOC concentrations were considered to be at background levels, as former SVOC contamination in the area had been attributed to fill material contamination in the November 2000 RDWP. Shaw recommended NFA status for this site. DEC concurred. NFA letter for this spill was issued on 12/20/2005. AZ"
Remarks:	"during tank removal caller found contaminated soil"

All Materials:

Site ID:	174749

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

Operable Unit ID:	1070950
Operable Unit:	01
Material ID:	313806
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	QUEENS WEST 01 DOS -DDC
Address:	34-28 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0001441 / 2016-06-10
Facility ID:	0001441
Site ID:	174744
Spill Date:	2000-05-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	2000-05-04
CID:	207
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-04
Spill Record Last Update:	2016-06-10
Spiller Name:	Not reported
Spiller Company:	NYC DEPT. OF SANITATION
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	110935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY PMS IS CM FOR SITE REMEDIATION, BUT LIRO IS DOING TESTING OF EPA TANKS, VIA TYREE AND DRY AS A BONE. LIRO WILL FOLLOW UP WITH REPAIR/RETEST. TANK WILL ULTIMATELY BE REMOVED (WITH POST-EXC. SAMPLING) AND REPLACED. IT Corp./Shaw installed and is operating an extensive dual-phase/SVE system at the site to address soil and groundwater contamination. Unknown if location of tanks involved in this spill is targeted by the system. Spill transferred from Kolleeny to A. Zhitomirsky on 4/6/05. - JK 05/05/2005 I have reviewed quaterly

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

status report received from JK. It presented remedial system performance monitoring data. The report stated that based on the site monitoring data, the dual phase extraction (DPE) system deem no longer necessary, since asymptotic levels of dissolved phase concentrations have been achieved. However, a few wells still contain VOCs at low concentrations above the TOGS values. Shaw has proposed to turn off the DPE part of the system and install ORC socks in wells with VOC concentrations above the TOGS values. The Department concured with this proposal.AZ 12/20/2005 Reviewed report submitted by Shaw and dated November 9, 2005 related to a motor fuel spill. The report stated that no VOCs or SVOCs were detected above TOGS GUidance values during March or June 2005 sampling events in the diesel spill area. Results of the confirmatory soil borings taken from August 30 to Septmeber 1, 2005, showed that VOCs were below TAGM Guidance values, with only one exceedance, W-17A (8'-11'). SVOC concentrations were considered to be at background levels, as former SVOC contamination in the area had been attributed to fill material contamination in the November 2000 RDWP. Shaw recommended NFA status for diesel spill. DEC concurred. NFA letter for motor fuel (diesel) spill was issued on 12/20/2005. As Jon Kolleeny previously indicated in this spill report, unknown if location of tanks involved in this spill is targeted by the system which addressed a motor fuel spill (diesel). AZ 12/22/2006 At the meeting with DDC/Greyhawk on 12/12/2006 the remedial progress was discussed. Greyhawk will update information for this site and will forward it to DEC. Greyhawk will obtain info from PMS. AZ 3-17-09 Requested an update via e-mail from B. Morrissey. AZ 3-24-2009 An e-mail was sent to DDC/Roux: You stated that an NFA letter was issued on 12/20/05 for the motor oil (diesel) spill. However, this spill is related to the motor oil tank spill which is a different petroleum product from diesel. NFA letter was indeed issued for the diesel tank. However, spill related to the motor oil tank gross test failure should be investigated. AZ 2-17-2012 Tank failure of a motor oil tank. I called S. Frank and requested a map with tanks shown. The current work does not contain all relevant info. Complete tank inventory should be created. AZ 1-7--2015 Reviewed Investigation Summary Report dated May 12, 2014. The report stated that spills 0001441 and 0111368 are related to UST-007. Spill No.0001441 was opened upon tank testing failure of UST-007 and Spill No.0111368 was opened upon receipt of soil sample results reporting elevated TPH concentrations for UST-007. The following e-mail was sent to S. Frank/V. Brevdo: Dear Steve, I have reviewed an Investigation Summary Report for the above site. The report stated that spills No.0001441 and No.0111368 are both related to UST-007. Spill No.0001441 was opened upon tank testing failure of UST-007 and Spill No.0111368 was opened upon receipt of soil sample results reporting elevated TPH concentrations for UST-007. LiRo proposed combining both spill numbers Also, LiRo proposed a supplemental investigation for these two spills and UST-07. We have discussed this site today over the phone. As per our discussion, the spills will be combined when the investigation is completed. The work plan is approved with the following addition: an additional well should be installed down-gradient of UST-007, if feasible. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site. Sincerely, Alex Zhitomirsky 10-7-2015 Reviewed an Investigation Summary Report dated April 7, 2015. The report stated that spills 0001441 and 0111368 are related to UST-007. LiRo will conduct a supplemental

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

investigation for this spill. The investigation will include the installation of an additional groundwater monitoring well downgradient of UST-007, as requested by DEC. Two spills might be combined after results of the investigation are received and reviewed by DEC.AZ 6-10-2016 Reviewed a semi-annual report dated Dec. 15, 2015. The report stated that spills #0001441 and #0111368 are related to UST -007, LiRo recommended consolidation of these spill numbers. I concur. This spill is consolidated with spill #0111368. AZ "

Remarks: "GROSS FAIL TANK CONTAINED MOTOR OIL"

All TTF:

Facility ID:	0001441
Spill Number:	0001441
Spill Tank Test:	1525555
Site ID:	174744
Tank Number:	4
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Name:	QUEENS WEST 1 DOS GARAGE -DDC
Address:	34-28 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0012293 / 2017-04-03
Facility ID:	0012293
Site ID:	174746
Spill Date:	2001-02-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	2001-02-15
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-15
Spill Record Last Update:	2017-04-05
Spiller Name:	ROBERT JOHNSON
Spiller Company:	DEPT OF SANITATION
Spiller Address:	Not reported

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

Spiller County:	001
Spiller Contact:	PHILIP FAZIN
Spiller Phone:	(516) 939-2959
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	110935
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND This spill called in for tightness test failure of a heating oil tank. The tank was subsequently closed in place, but no closure samples could be collected due to subsurface utilities and other site constraints. IT Corp./Shaw installed and is currently operating a dual-phase and soil vapor extraction system at the site, but unknown if the system adequately targets the area of this spill. Spill transferred from Kolleeny to A. Zhitomirsky on 4/6/05. - JK 05/05/2005 I have reviewed quaterly status report received from JK. It presented remedial system performance monitoring data. The report stated that based on the site monitoring data, the dual phase extraction (DPE) system deem no longer necessary, since asymptotic levels of dissolved phase concentrations have been achieved. However, a few wells still contain VOCs at low concentrations above the TOGS values. Shaw has proposed to turn off the DPE part of the system and install ORC socks in wells with VOC concentrations above the TOGS values. The Department concured with this proposal. AZ 11/7/2005 Shaw suggested to advance soil borings in order to verify the remaining soil impact and to determine if the operation of SVE system is still necessary. DEC concurred. AZ 12/22/2006 At the meeting with DDC/Greyhawk on 12/12/2006 the remedial progress was discussed. Greyhawk will update information for this site and will forward it to DEC. Greyhawk will obtain info from PMS. AZ 6-4-2008 Upon DEC's request Roux submitted information regarding this spill number. The spill was issued when a 10,000 gallon tank containing #2 fuel oil failed the Horner EZ check system tightness test. This tank was closed in place on March 20, 2002. According to Roux, soil samples could not be collected because of the site access limitations. One of the DPE wells is located within five feet of the fuel tank location. Two other spill numbers at this location related to diesel spills were closed. AZ 8-11-2008 An e-mail was sent to DDC/Roux/Greyhawk: I have reviewed Request for Spill Closure for the above site dated May 22, 2008. Spill #0012293 was issued when a 10,000 gallon tank containing #2 fuel oil failed the Horner EZ check system tightness test. This tank was closed in place on March 20, 2002. According to Roux, soil samples could not be collected because of the site access limitations. The request for closure is disapproved. Request for the spill closure should include a site plan with shown locations of the tanks in question and locations of borings and wells installed in the tank area. Also, the request should contain soil and groundwater laboratory data collected from the tank area in question. If such information does not exist, an investigation should be performed and report summarizing the findings should be submitted to DEC for review. AZ 2-17-2012 Contacted S.Frank (LiRo). This spill was caused by #2 oil tank. LiRo submitted an investigation plan on January 18-2012. AZ 3-30-2012 The following e-mail was sent to S.Frank/F.Ashkan/V. Brevdo: Dear Steve, I have reviewed a Site Specific Investigation Plan for the above site dated January 18, 2012. The plan proposed investigation of a 10,000 gal UST which contained #2 fuel oil. this tank failed a tightness test and was closed in place. No post closure samples were taken. The

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

Investigation Plan is approved with the following changes/comments: 1. All borings (four) should be finished as wells. 2. Split spoon sampling must be continuous. The Responsible Party and its contractors are solely responsible for the safe execution of all invasive work performed at the site, and in particular, are responsible for identifying subsurface utilities and safeguarding the structural integrity of any excavations, buildings, utilities, and other structures both on- and off-site that may be adversely affected by the work. The Responsible Party and its contractors must obtain any local, state or federal permits or approvals that may be required to perform the work necessary to address this spill. Furthermore, the Responsible Party and its contractors are solely responsible for the implementation of all appropriate health and safety measures during the performance of this work. AZ 10-7-2015 Reviewed an Investigation Summary Report dated April 7, 2015. According to the report, 10,000 gallon#2 Fuel Oil tank failed tightness testing in 20012. Between September 2013 and March 2014, LiRo completed a soil and groundwater sampling at the site. Groundwater analytical resulted VOC concentrations exceeding groundwater standards in two wells. Total VOC concentrations in LMW-04 were 276 ppb. AZ 4-30-2017 Reviewed a semi-annual monitoring report for this site dated 12-22-2016. The report stated that four groundwater monitoring wells were installed at the site. Soil sample results from four well locations showed minimal impact to soils which was limited to two of the four locations. Seven rounds of groundwater sampling results fro the four well locations showed minimal impact at three of the four well locations. Total VOC concentrations at the one well location reporting standard exceedances have steadily declined. The consultant stated that the soil and groundwater investigation results support closure of spill #0012293. AZ 4-3-2017 The following eltter was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed a Spill Closure Report for the above site dated December 22, 2016. The report stated that six groundwater monitoring wells were installed to investigate spills #0012293 and #0111368. Soil sample results showed minimal impact to soils. Seven rounds of groundwater sampling were performed. Groundwater sampling results from the majority of wells reported minimal impact and steadily declining exceedances from two wells. Based on this information, LiRo recommended closure of these spills. This recommendation is approved and spills #0012293 and #0111368 are closed. The Department hereby reserves all of its rights concerning, and such forbearance shall not extend to, any further investigation or remedial action the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was unknown at the time of this closure. II. Environmental conditions related to this spill case which were unknown to the Department at the time of this closure. III. Information received, in whole or part, after the Department’s spill case closure, which indicates that corrective action was not sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill case closure determination. As a precaution, we must bring your attention to our concerns for the future use of this site. If subsurface contamination is encountered while excavating for any construction activity, appropriate remedial and vapor mitigation efforts may need to be taken to fully prevent vapor intrusion into any site development and to ensure human health and safety. This spill closure does not exempt the Responsible Parties from compliance with any applicable laws and regulations. Please be advised that you should

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

maintain a permanent file of all documentation and correspondence regarding this case for future use as the Department's files may not be maintained indefinitely. Sincerely, Alex Zhitomirsky - Engineering Geologist 2 NYS Department of Environmental Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390 Email: alexander.zhitomirsky@dec.ny.gov "

Remarks: ""

All TTF:

Facility ID:	0012293
Spill Number:	0012293
Spill Tank Test:	1526100
Site ID:	174746
Tank Number:	12
Tank Size:	10000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	174746
Operable Unit ID:	834191
Operable Unit:	01
Material ID:	542569
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	QUEENS WEST 01 DOS -DDC
Address:	34-28 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0111368 / 2017-04-03
Facility ID:	0111368
Facility Type:	ER
DER Facility ID:	110935
Site ID:	128606
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	4101
Spill Date:	2002-03-01

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

Investigator:	ADZHITOM
Referred To:	Not reported
Reported to Dept:	2002-03-01
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-01
Spill Record Last Update:	2017-04-03
Spiller Name:	HARRY TAKOURIAN
Spiller Company:	NYC DEPT SANATATION
Spiller Address:	34-28 21ST STREET
Spiller Company:	001
Contact Name:	HARRY TAKOURIAN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY This spill may be for so-called EPA tanks (?). Unknown if dual-phase/SVE system installed and operated at site by IT Corp./Shaw targets the area of these tanks and this spill. Spill transferred from Kolleeny to A. Zhitomirsky on 4/6/05. - JK 05/05/2005 I have reviewed quaterly status report received from JK. It presented remedial system performance monitoring data. The report stated that based on the site monitoring data, the dual phase extraction (DPE) system deem no longer necessary, since asymptotic levels of dissolved phase concentrations have been achieved. However, a few wells still contain VOCs at low concentrations above the TOGS values. Shaw has proposed to turn off the DPE part of the system and install ORC socks in wells with VOC concentrations above the TOGS values. The Department concured with this proposal.AZ 12/22/2006 At the meeting with DDC/Greyhawk on 12/12/2006 the remedial progress was discussed. Greyhawk will update information for this site and will forward it to DEC. Greyhawk will obtain info from PMS. AZ 3-17-09 Requested an update via e-mail from B. Morrissey. AZ 3-23-2009 Response was received from Craig Werle(Roux): This spill no. is on the GH master list, but no work has been done on this spill. In OCt 2008, Roux took out the DPE system that had been running at this site AZ 3-24-2009 An e-mail was sento to DDC/Roux: This spill is probably related to so called EPA tanks . Soil contamination was confirmed. It's unknown if the former remedial system targeted the area of these tanks and this spill. The spill should be investigated by NYCDDC. AZ 2-17-2012 Contacted S. Frank LiRo. Requested to collected information about this tank. Gave LiRo all relevant info from DEC records. A full

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

tank inventory and and a site
plan with all USTs is needed. AZ 1-8-2015 Reviewed an Investigation Summary Report dated May 12,
2014. The report stated that spills 0001441 and 0111368 are related to UST-007. Spill No.0001441
was opened upon tank testing failure of UST-007 and Spill No.0111368 was opened upon receipt of
soil sample results reporting elevated TPH concentrations for UST-007. An investigation was
proposed and approved by DEC on Dec. 8, 2015, in a phone conversation with S. Frank. AZ 10-7-2015
Reviewed an Investigation Summary Report dated April 7, 2015. The report stated that spills 0001441
and 0111368 are related to UST-007. LiRo will conduct a supplemental investigation for this spill.
The investigation will include the installation of an additional groundwater monitoring well
downgradient of UST-007, as requested by DEC. AZ 6-10-2016 Reviewed a semi-annual report dated Dec.
15, 2015. The report stated that spills #0001441 and #0111368 are related to UST -007, LiRo
recommended consolidation of these spill numbers. I concurred with this proposal and closed
spill#0001441. Remediation of spill 0001441 will be tracked under spill #0111368 AZ 4-30-2016
Reviewed a semi-annual monitoring report dated 12-22-2018. The report stated that two groundwater
monitoring wells installed to investigate this spill. Soil samples from the two well locations
showed no exceedances. Seven rounds of groundwater sampling results from the two well locations
reported no detectable VOCs at one location and steadily declined Total VOC results at the other
location. The consultant recommended closure of this spill number. AZ 4-3-2017 The following letter
was sent to S. Frank and V. Brevdo: Dear Steve, I have reviewed a Spill Closure Report for the
above site dated December 22, 2016. The report stated that six groundwater monitoring wells were
installed to investigate spills #0012293 and #0111368. Soil sample results showed minimal impact to
soils. Seven rounds of groundwater sampling were performed. Groundwater sampling results from the
majority of wells reported minimal impact and steadily declining exceedances from two wells. Based
on this information, LiRo recommended closure of these spills. This recommendation is approved and
spills #0012293 and #0111368 are closed. The Department hereby reserves all of its rights
concerning, and such forbearance shall not extend to, any further investigation or remedial action
the Department deems necessary due to: I. The off-site migration of petroleum contaminants that was
unknown at the time of this closure. II. Environmental conditions related to this spill case which
were unknown to the Department at the time of this closure. III. Information received, in whole or

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

part, after the Department's spill case closure, which indicates that corrective action was not
sufficiently protective of human health and/or the environment. IV. Fraud in obtaining this spill
case closure determination. As a precaution, we must bring your attention to our concerns for the
future use of this site. If subsurface contamination is encountered while excavating for any
construction activity, appropriate remedial and vapor mitigation efforts may need to be taken to
fully prevent vapor intrusion into any site development and to ensure human health and safety. This
spill closure does not exempt the Responsible Parties from compliance with any applicable laws and
regulations. Please be advised that you should maintain a permanent file of all documentation and
correspondence regarding this case for future use as the Department's files may not be maintained
indefinitely. Sincerely, Alex Zhitomirsky - Engineering Geologist 2 NYS Department of Environmental
Conservation 47-40 21st Street, Long Island City, NY 11101 Phone: 718.482.6387 - Fax: 718.482.6390
Email: alexander.zhitomirsky@dec.ny.gov "

Remarks: "they got the analytical results back today and showed high level of tph."

All Materials:

Site ID:	128606
Operable Unit ID:	848439
Operable Unit:	01
Material ID:	525399
Material Code:	9999
Material Name:	other -
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	QUEENS WEST 01 DOS -DDC
Address:	34-28 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9513868 / 2004-12-16
Facility ID:	9513868
Facility Type:	ER
DER Facility ID:	110935
Site ID:	174748
DEC Region:	2
Spill Cause:	Other
Spill Class:	B3
SWIS:	4101
Spill Date:	1996-01-31
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	1996-01-31

QUEENS WEST 01 DOS -DDC (Continued) **S104952980**

CID:	252
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-01-31
Spill Record Last Update:	2005-07-07
Spiller Name:	PETER CASLER
Spiller Company:	NYC SANITATION DEPT
Spiller Address:	110 EAST 131ST ST
Spiller Company:	001
Contact Name:	PETER CASLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY This site being investigated and remediated under the DDC Consent Order by PMS Construction Management Corp. A dual-phase extraction system has been installed to address soil and groundwater contamination and small amounts of free product. This spill closed on 12/16/04 by J. Kolleeny to consolidate spills. Refer to spill number 9809914. "
Remarks:	"under ground tanks with unk petroleum or waste oil have caused soil to be contaminated-still under investigation"

All Materials:

Site ID:	174748
Operable Unit ID:	1028352
Operable Unit:	01
Material ID:	357573
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AW327 **COMMERCIAL BUILDING** **NY LTANKS** **S107410496**
South **40-23 24TH ST'** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.307 mi.
1620 ft. **Site 1 of 4 in cluster AW**

Relative:
Higher

Actual:
34 ft.

LTANKS:

Name:	COMMERCIAL BUILDING
Address:	40-23 24TH ST'
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0506977 / 2006-01-05
Facility ID:	0506977
Site ID:	352289

COMMERCIAL BUILDING (Continued) **S107410496**

Spill Date:	2005-09-08
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2005-09-08
CID:	409
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-08
Spill Record Last Update:	2006-02-03
Spiller Name:	VINNY LOVARI
Spiller Company:	COMMERCIAL BUILDING
Spiller Address:	40-23 24TH ST’
Spiller County:	001
Spiller Contact:	VINNY LOVARI
Spiller Phone:	(718) 967-9424
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	299586
DEC Memo:	"11/30/2005 Sangesland spoke to rep at Island tank. She said the site was dug out and endpoints were clean. She said a closure report would be sent ASAP. 1/4/06-Hiralkumar Patel. Here is the summary of the report from Island Environmental Tank, Inc. * According to owner, the tank has previously been used for the purpose of storing #2 heating oil and owner doesn’t know when this tank was installed. * UST was installed horizontally in the backfill material, with the top of the tank located approximately 4’ below the surface. * A 1080 gal. capacity tank was removed in the presence of Mr. Vinny Lovari of Island Tank Enviromental. After removal from cavity, tank has been cut and washed and removed oil and water mixture with vac/truck. * No groundwater or static surface water was encountered in the tank cavity. * Tank had pits and holes. * Tank cavity was excavated approximately 30 cubic yard of soil in 55 gal. drums and disposed at Jamaica Recycling Inc. Jamaica, NY. * Tank cavity was backfilled and compacted in place. * 6 samples were taken out from cavity and tested at Severn Trent Laboratory, Edison, NJ. * The metal tank and all metal tank system components were removed from teh owner’s property and disposed of as scrap metal at John Iron & Metal Co.,Inc. 33 Arthur Kill Road, Staten Island, NY. 1/5/06-Hiralkumar Patel. No Further Action required letter has been sent to Mr. John Domenico. Case closed as per Mr. Jeff Vought. 02/03/06-Hiralkumar Patel. Send out NFA again through fax (212-689-6082) as per John’s request."
Remarks:	"tnak removal found oil on the tank. THERE IS 3 OR 4 DRUMS THAT NEES TO BE REMOVED. THE TANK HAS BEEN CUT UP."

All Materials:

Site ID:	352289
Operable Unit ID:	1109795
Operable Unit:	01

COMMERCIAL BUILDING (Continued) **S107410496**

Material ID:	2099814
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AV328 **RAINEY** **NY LTANKS** **S105053991**
WNW **38TH ST & VERNON BLVD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.311 mi.
1641 ft. **Site 2 of 3 in cluster AV**

Relative: **Lower**

Actual: **12 ft.**

LTANKS:

Name:	RAINEY
Address:	38TH ST & VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9313425 / 2000-08-07
Facility ID:	9313425
Site ID:	224933
Spill Date:	1994-02-15
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1994-02-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-16
Spill Record Last Update:	2000-08-07
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	185665
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT 2/15/94: SIGONA NOTES - FIRE DEPT. ORDER - 3 WEEKS AGO ~FEB. 1. FIRE DEPT. ORDERED CON EDISON NOT TO CONDUCT TRANSFER AND TO DISCONTINUE USE OF THE TANK. THEY[CON ED] DID NOT FOLLOW THEIR ORDERS AND OVERFILLED THE TANK. THE TANK OVERFILL ALARM FAILED - OPERATOR

RAINEY (Continued) **S105053991**

ERROR. 01/06/95: REASSIGNED FROM SIGONA TO ENGELHARDT ON 01/06/95.
8/7/2000 - results of site investigation indicate that all
contamination on roof of tank remediated. Still some seepage of water
and possibly oil into moat through bedrock - unrelated to this spill.
See spill #9009327. "

Remarks: "OVERFILLED TANK WHILE FILLING. FD WAS NOTIFIED. RICH ROCHE CALLED ON 11/2/94 TO UPDATE TOTAL RECOVERED OIL = 185,00 TO 200,000 GALLONS. HIS NUMBER IS (212)580-6763."

All Materials:

Site ID:	224933
Operable Unit ID:	991875
Operable Unit:	01
Material ID:	388807
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	600.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AT329 **QUEENSBRIDGE PLANT D -NYCHA** **NY LTANKS** **S101103122**
WSW **41004 10TH STREET** **N/A**
1/4-1/2 **QUEENS, NY**
0.311 mi.
1642 ft. **Site 2 of 2 in cluster AT**

Relative: **Lower**

Actual: **14 ft.**

LTANKS:

Name:	QUEENSBRIDGE PLANT D -NYCHA
Address:	41004 10TH STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9314508 / 2013-08-07
Facility ID:	9314508
Site ID:	310358
Spill Date:	1990-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	jkkann
Referred To:	Not reported
Reported to Dept:	1994-03-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-21
Spill Record Last Update:	2013-08-07
Spiller Name:	Not reported

QUEENSBRIDGE PLANT D -NYCHA (Continued) **S101103122**

Spiller Company:	NYCHA (JOE MONTELLA)
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	250512
DEC Memo:	"01/10/06: This spill transferred from J.Kolleeny to S.Kraszewski. Two 15K tanks, both failed a tank test in 1993 and both were closed in place in 1996. An ISRP from 1995 shows that 5 soil borings were taken and 2 MWs installed at this site. B-1,2,3 showed evidence of SVOC concentrations above HHGVs and soil guidance values. B-1,2,3,4 detected VOCs, as many as 13 different compounds. MW-1 had a sheen but no volatiles of semi-volatiles were detected. DEC suggested among other options, to close the tanks which was done by NYCHA as a condition for approval of the ISRP. Close monitoring of the GW to detected movement of contaminants was proposed and agreed upon. Lab results from 2 soil samples taken in 1997 were performed to legally abandon these two tanks. These anlysis methods did not meet EPA methods 8270 and 8021 as recommended in SPOTS Memo #14 for Site Assessments. A letter dated May 1, 1997 from Jane Healy noted this discrepancy but she mentioned that in light of the previous site investigation (ISRP) by SBE/H2M additional SOIL samples were not required. However, the ISRP stipulated that the GW would be monitored through the 2 existing MWs and no records of monitoring activity are on file. DEC approved a remedial design plan dated April 1997 to address the seepage of free product in to the boiler room. No technical draft plans of this proposed remediation are on file, so it is not clear what activiy has taken place. Need: GW monitoring results and documentation of any remedial activity. - SK 03/14/06: This spill reassigned to K.Tang. - SK 09/23/10: J.Kann - spill transferred from K. Tang to J.Kann. 12/27/11: J.Kann - visited site on June 2, 2011. Report submitted to DEC on 8/30/11. Reviewed report and discussed with Linda Ross on December 19. Minor SVOCs detected in soils below CP-51. Comments sent in an email dated December 23. Additional information needed to clarify the PBS record for the site. 5/29/12: J.Kann - revised report received in april 2011 and briefly reviewed. Additional information necessary. site assigned P3, because no major concerns. 8/7/13: J.Kann - visited site on July 31. confirmed that new boilers were installed. No seepage on boiler room walls. Based on the review of all information submitted to the Department, historic and current, the spill has been closed. This is based on the following: -The September 1995 SBE ISRP indicated an area around B-2 which contained saturated soils . This contamination was likely No. 6 fuel oil. Groundwater samples analyzed were not impacted (STARS SVOCs and VOCs). At that time 5 borings were advanced and 3 monitoring wells installed. USTs at this site were subsequently closed in place. (Plant B feeds the boiler at Plant D) - As a part of boiler upgrade work in 2010, soils in the area around B-2 were excavated to allow for the installation of new boilers in the basement of Plant D. - No endpoints were taken as a part of boiler replacement, however, Boring B-7 was advanced by ALC in the vicinity of B-2 in 2011. The B-7 boring log did not show any indications of oil impacts and the soil sample collected did not exceed CP-51 soil guidance values. -The ALC report included the advancement of 6 soil borings and the collection of one groundwater sample. All samples met

QUEENSBRIDGE PLANT D -NYCHA (Continued) **S101103122**

CP-51 and TOGS 1.1.1 criteria with the exception of methylene chloride which was likely a lab derivative. -Site currently operates on firm gas. -NFA"

Remarks: "LEAK RATE OF -0.07 GPH REPORTED AS PASSED BY TESTER."

All TTF:

Facility ID:	9314508
Spill Number:	9314508
Spill Tank Test:	1542488
Site ID:	310358
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	9314508
Spill Number:	9314508
Spill Tank Test:	1542489
Site ID:	310358
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	310358
Operable Unit ID:	996448
Operable Unit:	01
Material ID:	386304
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AV330 **3809 VERNON BLVD** **NY LTANKS** **S101341003**
West **3809 VERNON BLVD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.311 mi.
1642 ft. **Site 3 of 3 in cluster AV**

Relative: **Lower**

Actual: **12 ft.**

LTANKS:

Name:	3809 VERNON BLVD
Address:	3809 VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9406830 / 2003-02-28
Facility ID:	9406830
Site ID:	210092
Spill Date:	1994-08-19
Spill Cause:	Tank Test Failure
Spill Source:	Railroad Car
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1994-08-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-10-21
Spill Record Last Update:	2003-02-28
Spiller Name:	Not reported
Spiller Company:	STATE ENV. SERVICES
Spiller Address:	1801 STILLWELL AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	174167
DEC Memo:	""
Remarks:	"2 TANKS 1 ABOUT 4,000 GAL., 1 ABOUT 2,500 GAL. -PUMPING OUT TANKS WILL RE-TEST."

All TTF:

Facility ID:	9406830
Spill Number:	9406830
Spill Tank Test:	1543067
Site ID:	210092
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

3809 VERNON BLVD (Continued) **S101341003**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 210092
Operable Unit ID: 1004255
Operable Unit: 01
Material ID: 379860
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: L
Recovered: .00
Resource Affected: Air
Oxygenate: Not reported

AX331 **CENTRAL SERVICE BUILDING TTF** **NY LTANKS** **U001839593**
NNW **10-06 35TH AVENUE** **N/A**
1/4-1/2 **QUEENS, NY 11106**
0.313 mi.
1651 ft. **Site 1 of 2 in cluster AX**

Relative:
Higher

Actual:
17 ft.

LTANKS:
Name: CENTRAL SERVICE BUILDING TTF
Address: 10-06 35TH AVENUE
City,State,Zip: QUEENS, NY 11106
Spill Number/Closed Date: 0904512 / 2009-10-15
Facility ID: 0904512
Site ID: 416679
Spill Date: 2009-07-17
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: JMKRIMGO
Referred To: Not reported
Reported to Dept: 2009-07-17
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2009-07-17
Spill Record Last Update: 2013-06-10
Spiller Name: Not reported
Spiller Company: CENTRAL SERVICE BUILDIING
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: MICHAEL

CENTRAL SERVICE BUILDING TTF (Continued) **U001839593**

Spiller Phone:	(845) 735-8300
Spiller Extention:	311
DEC Region:	2
DER Facility ID:	17001
DEC Memo:	"8/5/2009 ttf letter sent to PBS Contact: Mr. Herbert Daley NY City Central Administration 10-06 35th Ave. Long Island City, NY 11106 10/15/09. J.Krimgold reviewed the report submitted by HDR and dated 09/02/09. According to the report tank #002 utilized to store #2 heating oil failed the test. Subsequently the tank and associated piping were removed. Post excavation samples show contaminant concentrations in soil at or below TAGM levels. Case closed. 6/10/13 TJD Duplicate spill associated with this site (0904516) - closed and cross-referenced."
Remarks:	"1407 The caller advised dispatch of a tank test failure."

All Materials:

Site ID:	416679
Operable Unit ID:	1172971
Operable Unit:	01
Material ID:	2164851
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	DEPT. OF CORRECTIONS - TTF
Address:	10-06 35TH AVE
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0904516 / 2013-06-10
Facility ID:	0904516
Site ID:	416683
Spill Date:	2009-07-17
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	TJDEMEO
Referred To:	Not reported
Reported to Dept:	2009-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-07-17
Spill Record Last Update:	2013-06-10
Spiller Name:	Not reported
Spiller Company:	DEPT. OF CORRECTIONS

CENTRAL SERVICE BUILDING TTF (Continued) **U001839593**

Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MARLON
Spiller Phone:	(718) 624-4842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	365750
DEC Memo:	"Sangesland spoke to PTC. PTC was hired to test this tank and it failed. City Dept of Corrections demo project managed by G & M Mechanical TTF Letter sent to Demo Project Company: G & M Mechanical 1866 Seaford Ave Wantugh, NY 11793 08/13/12 - LZ As Randy Austin requested, the spill has been reassigned to Tim DeMeo 1/3/13 AFrischeisen Previous TTF mailed on 12/13/12 returned as undeliverable. New TTF sent and upped to eDocs. 6/10/13 Duplicate report - primary spill number associated with this site is 0904512. Multiple phone calls and e-mails have been exchanged between DEC and NYS DOC regarding this spill site. Record review reveals spill was reported twice once by DOC and again by consultant (HDR). Original spill was closed by Krimgold on 10/15/09. Spills are associated with TTF associated with a wet leak on 7,500 gallon UST. A total of 1,564 gallons of #2 Fuel Oil was removed from tank prior to removal. A total of 51.11 tons of petroleum contaminated soils were excavated and properly transported and disposed of durring the remedial process. Laboratory analysis of endpoint samples taken following tank removal and soil excavation are within acceptable concentrations. Spill 0904516 is administratively closed and cross referenced to spill 0904512. No further action is required at this time. "
Remarks:	"1511 The caller advised the tank test failed."

All Materials:

Site ID:	416683
Operable Unit ID:	1172975
Operable Unit:	01
Material ID:	2164855
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

AY332 **FORMER HYGRADE POLISHING AND PLATING CO - OFF-SITE** **NY BROWNFIELDS** **S118372395**
SSW **22-07 41ST AVENUE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.322 mi.
1699 ft. **Site 1 of 4 in cluster AY**

Relative: **Higher**
Actual: **24 ft.**

BROWNFIELDS:

Name:	FORMER HYGRADE POLISHING AND PLATING CO - OFF-SITE
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	520289
Acres:	Not reported

FORMER HYGRADE POLISHING AND PLATING CO - OFF-SITE (Continued) **S118372395**

HW Code:	C241148A
SWIS:	4101
Town:	New York City
Record Added Date:	12/23/2015
Record Updated Date:	03/04/2020
Update By:	JHOCONNE
Site Description:	"The area of concern subject to this work is considered off-site from Brownfield Cleanup Program (BCP) Site No. C241148 and reflects the investigation and possible remediation of contamination that may have migrated from that site. This work is being carried out as provided for under the Environmental Conservation Law Section 27-1411.5. Please see C241148 for further information regarding the status of the site in the BCP. Location: The area is located in the Long Island City section of Queens County (Borough of Queens, NY). Site Features: The site does not have definite boundaries since it is an off-site project associated with an on-site BCP. The area of concern includes the properties surrounding the BCP site. Current Zoning and Land Use: The area is zoned M1-3 (manufacturing). The surrounding area is generally used for commercial purposes. Since the site is a collection of properties surrounding the BCP project, it includes both public and private land (public sidewalk and private residences). Past Use of the Site: The on-site BCP property was formerly occupied by a metal shop, metal polishing, and electroplating facility. The on-site property owner undertook a limited cleanup pursuant to a NYCDEP Commissioners order prior to entry into the BCP. This work began in April 2013 and included: (a) emptying and removal of all the plating baths and tanks; (b) removal of all the 55-gallon drums; and (c) removal of all grossly-contaminated concrete flooring and walls. This work was completed in June 2013. In May 2015, the site entered into the BCP. Additional remediation of the on-site property is being completed under a BCP agreement. Site Geology and Hydrogeology: The on-site BCP property soils consist of medium to fine-grained sand to about 10' below grade, followed by a layer of silty clay of an undetermined thickness. Groundwater was found ~13' below grade. Groundwater flow direction was determined to be a westerly direction towards the East River. "
Env Problem:	"Chlorinated solvents, primarily tetrachloroethylene (PCE) and trichloroethene (TCE) were detected in soil, groundwater, and soil vapor samples from the on-site BCP project. All contamination is being addressed within the property boundaries under the BCP. The off-site properties were suspected to be contaminated based on soil vapor data collected during the on-site investigation. The Responsible Party conducted an off-site investigation and included collection of off-site soil vapor, sub-slab soil vapor, and indoor air samples. The results of this sampling event showed the maximum concentration of PCE at 6.4 ug/m3 and TCE at 37 ug/m3 in sidewalk soil vapor samples in front of the BCP site. Sapling conducted at the multi-story hotel adjacent to the west of the BCP site detected PCE at a concentration 3.9 ug/m3 in sub-slab soil vapor and 3 ug/m3 in indoor air, and TCE at a concentration of 18 ug/m3 in sub-slab soil vapor and 0.28 ug/m3 in indoor air. The results of the off-site investigation did not identify concentrations of contaminants that require mitigation; therefore, no off-site remedial program was implemented."
Health Problem:	"Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that

FORMER HYGRADE POLISHING AND PLATING CO - OFF-SITE (Continued) **S118372395**

obtains water from a different source not affected by this contamination. Volatile organic compounds in the soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A subslab depressurization system (system that ventilates/removes the air beneath the building) was installed in the onsite building to address the identified indoor air quality impacts from the contaminated soil vapor. Sampling indicates soil vapor intrusion is not a concern for one adjacent offsite building."

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Estate of Larry Levine
Owner Address:	2 Estate Drive
Owner Addr2:	Not reported
Owner City,St,Zip:	Boynton Beach, FL 33436
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AY333 **DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATIN** **RCRA-LQG** **1009218042**
SSW **22-07 41ST AVE** **NY ENG CONTROLS** **NYD001531094**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY INST CONTROL**
0.322 mi. **NY BROWNFIELDS**
1699 ft. **Site 2 of 4 in cluster AY** **NY PFAS**

Relative: **Higher**
Actual: **24 ft.**

RCRA Listings:

Date Form Received by Agency:	20140214
Handler Name:	Double E Plating Co Dba Hygrade Polishing & Plating
Handler Address:	22-07 41ST AVE
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD001531094
Contact Name:	ROBERT BIRNBAUM
Contact Address:	NORTHERN BLVD
Contact City,State,Zip:	GREAT NECK, NY 11021
Contact Telephone:	516-829-7912
Contact Fax:	631-208-0233

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Contact Email:	Not reported
Contact Title:	OWNER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2013
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	NORTHERN BLVD
Mailing City,State,Zip:	GREAT NECK, NY 11021
Owner Name:	Stalingrad Ventures Llc
Owner Type:	Private
Operator Name:	Stalingrad Ventures Llc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Biennial: List of Years
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D003
Waste Description:	Reactive Waste
Waste Code:	D004
Waste Description:	Arsenic
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.
Waste Code:	F006
Waste Description:	Wastewater Treatment Sludges From Electroplating Operations, Except From The Following Processes: (1) Sulfuric Acid Anodizing Of Aluminum;

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

(2) Tin Plating On Carbon Steel; (3) Zinc Plating (Segregated Basis) On Carbon Steel; (4) Aluminum Or Zinc-Aluminum Plating On Carbon Steel; (5) Cleaning/Stripping Associated With Tin, Zinc, And Aluminum Plating On Carbon Steel; And (6) Chemical Etching And Milling Of Aluminum.

Waste Code: F007
Waste Description: Spent Cyanide Plating Bath Solutions From Electroplating Operations.

Waste Code: F008
Waste Description: Plating Bath Residues From The Bottom Of Plating Baths From Electroplating Operations In Which Cyanides Are Used In The Process.

Waste Code: P029
Waste Description: Copper Cyanide (Or) Copper Cyanide Cu(Cn)

Waste Code: P121
Waste Description: Zinc Cyanide (Or) Zinc Cyanide Zn(Cn)2

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ED BYERS
Legal Status: Private
Date Became Current: 19930120
Date Ended Current: Not reported
Owner/Operator Address: 22-07 41ST AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-392-4082
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ED BYERS
Legal Status: Private
Date Became Current: 19930120
Date Ended Current: Not reported
Owner/Operator Address: 22-07 41ST AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-392-4082
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STALINGRAD VENTURES LLC
Legal Status: Private
Date Became Current: 20130311
Date Ended Current: Not reported
Owner/Operator Address: 320 NORTHERN BLVD
Owner/Operator City,State,Zip: GREAT NECK, NY 11021
Owner/Operator Telephone: 516-829-7912
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: STALINGRAD VENTURES LLC
Legal Status: Private
Date Became Current: 20130311
Date Ended Current: Not reported
Owner/Operator Address: 320 NORTHERN BLVD
Owner/Operator City,State,Zip: GREAT NECK, NY 11021
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ED BYERS
Legal Status: Private
Date Became Current: 19930120
Date Ended Current: Not reported
Owner/Operator Address: 22-07 41ST AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-392-4082
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ED BYERS
Legal Status: Private
Date Became Current: 19930120
Date Ended Current: Not reported
Owner/Operator Address: 22-07 41ST AVE
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-392-4082
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20140214
Handler Name: DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930120
Handler Name: HYGRADE POLISHING & POLISHING CO
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20000329
Handler Name: HYGRADE POLISHING & POLISHING CO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: HYGRADE POLISHING & POLISHING CO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: HYGRADE POLISHING & POLISHING CO
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 531312
NAICS Description: NONRESIDENTIAL PROPERTY MANAGERS

Has the Facility Received Notices of Violations:
Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	19930128
Actual Return to Compliance Date:	19931215
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	19931115
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20000210
Evaluation Responsible Agency: EPA
Found Violation: No

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2MD
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930128
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2JI
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19931215
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20150901
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2STP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ENG CONTROLS:

Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	499923
HW Code:	C241148
Control Code:	13
Control Type:	ENG
Date Record Added:	07/24/2020
Date Rec Updated:	08/02/2022
Updated By:	WYZHENG
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

	of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	trichloroethene (TCE)

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1204146
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-08-17 11:01:00
Record Updated:	2018-08-17 11:01:00
Updated By:	WYZHENG
Crossref ID:	NYD001531094
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-04-01 12:49:00
Record Updated:	2015-04-01 12:49:00
Updated By:	DKHARRIN
Crossref ID:	241148
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-07-27 10:09:00
Record Updated:	2020-07-27 10:09:00
Updated By:	WYZHENG
Crossref ID:	C241148-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 09:12:00
Record Updated:	2020-02-10 09:12:00
Updated By:	WYZHENG
Crossref ID:	2019000161926
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-06-06 15:06:00
Record Updated:	2019-06-20 15:13:00
Updated By:	WYZHENG
Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	499923
HW Code:	C241148
Control Code:	15
Control Type:	ENG
Date Record Added:	07/24/2020
Date Rec Updated:	08/02/2022
Updated By:	WYZHENG
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

	the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Code:	Not reported
HW Code:	C241148
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1204146
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-08-17 11:01:00
Record Updated:	2018-08-17 11:01:00
Updated By:	WYZHENG
Crossref ID:	NYD001531094
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-04-01 12:49:00
Record Updated:	2015-04-01 12:49:00
Updated By:	DKHARRIN
Crossref ID:	241148
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-07-27 10:09:00
Record Updated:	2020-07-27 10:09:00
Updated By:	WYZHENG
Crossref ID:	C241148-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 09:12:00
Record Updated:	2020-02-10 09:12:00
Updated By:	WYZHENG
Crossref ID:	2019000161926
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-06-06 15:06:00
Record Updated:	2019-06-20 15:13:00
Updated By:	WYZHENG

Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	499923
HW Code:	C241148

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Control Code:	12
Control Type:	ENG
Date Record Added:	07/24/2020
Date Rec Updated:	08/02/2022
Updated By:	WYZHENG
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

HW Code:	C241148
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1204146
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-08-17 11:01:00
Record Updated:	2018-08-17 11:01:00
Updated By:	WYZHENG
Crossref ID:	NYD001531094
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-04-01 12:49:00
Record Updated:	2015-04-01 12:49:00
Updated By:	DKHARRIN
Crossref ID:	241148
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-07-27 10:09:00
Record Updated:	2020-07-27 10:09:00
Updated By:	WYZHENG
Crossref ID:	C241148-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 09:12:00
Record Updated:	2020-02-10 09:12:00
Updated By:	WYZHENG
Crossref ID:	2019000161926
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-06-06 15:06:00
Record Updated:	2019-06-20 15:13:00

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Updated By:	WYZHENG
Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	499923
HW Code:	C241148
Control Code:	36
Control Type:	ENG
Date Record Added:	07/24/2020
Date Rec Updated:	08/02/2022
Updated By:	WYZHENG
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1204146
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-08-17 11:01:00
Record Updated:	2018-08-17 11:01:00
Updated By:	WYZHENG
Crossref ID:	NYD001531094
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-04-01 12:49:00
Record Updated:	2015-04-01 12:49:00
Updated By:	DKHARRIN
Crossref ID:	241148
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-07-27 10:09:00
Record Updated:	2020-07-27 10:09:00
Updated By:	WYZHENG
Crossref ID:	C241148-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 09:12:00

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

INST CONTROL:
Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Environmental Easement
HW Code: C241148
Control Code: J
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

	and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Soil Management Plan
HW Code: C241148
Control Code: 14
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00
Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Landuse Restriction
HW Code: C241148
Control Code: 25
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00
Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Ground Water Use Restriction
HW Code: C241148
Control Code: 08
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "

Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00
Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: O&M Plan
HW Code: C241148
Control Code: 33
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: IC/EC Plan
HW Code: C241148
Control Code: 34
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump: False
Structure: True

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00
Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Site Management Plan
HW Code: C241148
Control Code: 32
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-09-17 11:51:00
Record Upd: 2020-10-30 10:03:00
Updated By: GWBURKE
Own Op: 1
Sub Type: E
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Robert Birnbaum
Owner Company: Stalingrad Ventures LLC
Owner Address: 320 Northern Blvd.
Owner Addr2: Not reported
Owner City,St,Zip: Great Neck, NY 11021
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library, Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG
Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

Name: FORMER HYGRADE POLISHING AND PLATING CO.
Address: 22-07 41ST AVENUE
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 499923
Control Name: Monitoring Plan
HW Code: C241148
Control Code: 31
Control Type: INST
Dt record added: 07/24/2020
Dt rec updated: 08/02/2022
Updated By: WYZHENG
Site Code: 499923
Site Description: "Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

	was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
HW Code: C241148
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CADMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: CHROMIUM
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: NICKEL
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: cis-1,2-dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: Perfluorooctane Sulfonic Acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: vinyl chloride
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: perfluorooctanoic acid
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241148
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 1204146
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2018-08-17 11:01:00
Record Updated: 2018-08-17 11:01:00
Updated By: WYZHENG

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Crossref ID: NYD001531094
Cross Ref Type Code: 06
Cross Ref Type: RCRA EPA ID No.
Record Added Date: 2015-04-01 12:49:00
Record Updated: 2015-04-01 12:49:00
Updated By: DKHARRIN
Crossref ID: 241148
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2020-07-27 10:09:00
Record Updated: 2020-07-27 10:09:00
Updated By: WYZHENG
Crossref ID: C241148-03-15
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2020-02-10 09:12:00
Record Updated: 2020-02-10 09:12:00
Updated By: WYZHENG
Crossref ID: 2019000161926
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-06-06 15:06:00
Record Updated: 2019-06-20 15:13:00
Updated By: WYZHENG

BROWNFIELDS:

Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	499923
Acres:	0.057
HW Code:	C241148
SWIS:	4101
Town:	New York City
Record Added Date:	09/17/2014
Record Updated Date:	12/30/2020
Update By:	AMSERVIS
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

	containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "
Env Problem:	"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-09-17 11:51:00
Record Upd:	2020-10-30 10:03:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	E
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Robert Birnbaum
Owner Company:	Stalingrad Ventures LLC
Owner Address:	320 Northern Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Great Neck, NY 11021
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library, Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	C241148
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CYANIDES(SOLUBLE CYANIDE SALTS)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CADMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	CHROMIUM
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	NICKEL
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	Perfluorooctane Sulfonic Acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241148
Waste Type:	perfluorooctanoic acid
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

HW Code:	C241148
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	1204146
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2018-08-17 11:01:00
Record Updated:	2018-08-17 11:01:00
Updated By:	WYZHENG
Crossref ID:	NYD001531094
Cross Ref Type Code:	06
Cross Ref Type:	RCRA EPA ID No.
Record Added Date:	2015-04-01 12:49:00
Record Updated:	2015-04-01 12:49:00
Updated By:	DKHARRIN
Crossref ID:	241148
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2020-07-27 10:09:00
Record Updated:	2020-07-27 10:09:00
Updated By:	WYZHENG
Crossref ID:	C241148-03-15
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 09:12:00
Record Updated:	2020-02-10 09:12:00
Updated By:	WYZHENG
Crossref ID:	2019000161926
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-06-06 15:06:00
Record Updated:	2019-06-20 15:13:00
Updated By:	WYZHENG

PFAS 3:

Name:	FORMER HYGRADE POLISHING AND PLATING CO.
Address:	22-07 41ST AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	499923
HW Code:	C241148
Program:	BCP
Class Code:	C
Region:	2
Acres:	0.057
Date Record Added:	09/17/2014
Date Record Updated:	12/30/2020
Water Quantity:	UNKNOWN
Updated By:	AMSERVIS
Site Description:	"Location: The site is located in the Long Island City section of Queens (Borough of Queens, New York City). The site is located along the north side of 41st Avenue between 22nd and 23rd Streets. Site Features: The site is approximately 2,500 square feet (0.058 acres) in size and is currently improved with a four-story building and basement that covers the entire property. The building was recently renovated to convert the former factory to an occupied professional office space. To the west of the site is a multi-story hotel, and a

DOUBLE E PLATING CO DBA HYGRADE POLISHING & PLATING (Continued) **1009218042**

parking area and a multi-story commercial building are located east of the site. Metropolitan Transportation Authority property (the F train) runs directly underneath 41st Avenue along the southern side of the property. Current Zoning and Land Use: The site is zoned M1-3 (manufacturing) which also allows for commercial uses. The current land use is commercial. The upper four floors of the building were recently renovated for use as professional office space. The surrounding area is mixed-use commercial and residential. Past Use of the Site: The property was occupied by an electroplating facility from 1962 to 2012. During an August 2012 inspection, NYSDEC discovered over a hundred 55-gallon drums in various states of decay containing numerous chemicals, several plating baths and rinsate tanks, and heavily stained walls and floors. Pursuant to a NYC Department of Environmental Protection Commissioners order, the new property owner undertook a limited clean up in 2013. Site Geology and Hydrogeology: The soil below the basement consists of a permeable sand and gravel fill to a depth of approximately 5 feet below the basement slab. The soils underlying the fill are Pleistocene age and consist of gray clays and silts to a depth of approximately 12 to 16 ft below grade (bg), followed by brown clayey sand. The depth to bedrock is believed to be approximately 32 to 35 ft bg. Groundwater was found approximately 6 to 7 ft bg. The property is situated approximately one-half mile east of the East River. Groundwater flows west direction towards the East River. "

Summary: "Remedial actions are complete and measures are in place to address the potential for exposure to residual site related contaminants. "

Summary: "Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern in groundwater and soil vapors consist of chlorinated related VOCs and Perfluorooctane sulfonic acid (PFOS) in groundwater. Prior to the site entering into the BCP, 581 tons of soil was removed and VOCs, SVOCs, pesticides, PCBs, or metals at concentrations exceeding the protection of groundwater or commercial soil cleanup objectives (SCOs) were not identified. Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination in the soil is being managed under a Site Management Plan. "

Water Type: Perfluorooctane Sulfonic Acid

PFAS 3:
Water Type: perfluorooctanoic acid

AX334 **NYS DEPT. OF CORRECTIONS** **NY LTANKS** **S106472077**
NNW **10-06 35TH AVE** **N/A**
1/4-1/2 **LONG ISLAND, NY**
0.328 mi.
1731 ft. **Site 2 of 2 in cluster AX**

Relative: **Higher**
Actual: **18 ft.**

LTANKS:
Name: NYS DEPT. OF CORRECTIONS
Address: 10-06 35TH AVE
City,State,Zip: LONG ISLAND, NY
Spill Number/Closed Date: 0403872 / 2005-07-11
Facility ID: 0403872

NYS DEPT. OF CORRECTIONS (Continued) **S106472077**

Site ID:	325773
Spill Date:	2004-07-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JAKOLLEE
Referred To:	Not reported
Reported to Dept:	2004-07-12
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-12
Spill Record Last Update:	2005-07-11
Spiller Name:	HERB DAILEY
Spiller Company:	NYS DEPT. OF CORRECTIONS
Spiller Address:	10-06 35TH AVE
Spiller County:	001
Spiller Contact:	HERB DAILEY
Spiller Phone:	(718) 626-1710
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	262426
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KOLLEENY TTF letter sent another TTF ltr sent 3/25/2005 - SS 6/17/05. Passed TT on 3/17/05. See PBS 2-347442."
Remarks:	"RECOMMENDATIONS NONE:"

All TTF:

Facility ID:	0403872
Spill Number:	0403872
Spill Tank Test:	1529429
Site ID:	325773
Tank Number:	Not reported
Tank Size:	7000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	325773
Operable Unit ID:	887145
Operable Unit:	01

NYS DEPT. OF CORRECTIONS (Continued) **S106472077**

Material ID:	491424
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AZ335 **RAVENWOOD GAS TURBINES TANK FARM** **NY MOSF UST** **S102634330**
West **38-54 VERNON BOULEVARD** **NY MOSF AST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.329 mi.
1738 ft. **Site 1 of 4 in cluster AZ**

Relative:
Lower

Actual:
12 ft.

MOSF UST:

Id/Status:	2-1980 / NO LONGER A MAJOR FACILITY
SWIS Code:	63
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 706-2703
Emergency Contact:	CIG
Emergency Telephone:	(212) 580-6763
CBS Number:	Not reported
SPDES Num:	0-005193
Total Tanks:	0
Total Capacity:	0
Avg Throughput:	2142
License Stat:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Prod Xfer Options:	AC
Expiration Date:	03/31/2000
Applic Rcvd:	01/08/1998
Operator:	AL PINKALL
Owner Name:	CONSOLIDATED EDISON COMPANY OF N.Y., INC.
Owner Address:	4 IRVING PLACE, ROOM 300
Owner City,St,Zip:	NEW YORK, NY 10003-
Owner Telephone:	(212) 460-3968
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mail To Name:	CONSOLIDATED EDISON COMPANY OF N.Y., INC.
Mail To Address:	4 IRVING PLACE, ROOM 300
Mail To Address 2:	Not reported
Mail City,St,Zip:	NEW YORK, NY 10003-
Mail To Contact:	W. ALAN HOMYK,DIRECTOR -COMPLI
Mail To Telephone:	(212) 460-3968
Legal Agent Name:	OFFICE OF THE SECRETARY OF THE COMPANY
Legal Agent Address:	4 IRVING PLACE, ROOM 1618-S
Legal Agent City,St,Zip:	NEW YORK, NY 10003-
Date Filed:	09/84
Latitude:	40|45|42
Longitude:	73|56|41

Tank ID:	GT04
Tank Location:	UNDERGROUND

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Install Date:	12/70
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT04-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT05
Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT05-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT06
Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT06-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT07
Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	None
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT07-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT08
Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Tank ID:	GT08-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT09
Tank Location:	UNDERGROUND
Install Date:	12/74
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT09-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT10
Tank Location:	UNDERGROUND
Install Date:	12/74
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispenser:	Not reported
Test Date:	09/97

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT10-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT11
Tank Location:	UNDERGROUND
Install Date:	12/74
Capacity (Gal):	550
Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Underground
Pipe Type:	STEEL/IRON

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Pipe Internal:	None
Pipe External:	None
Second Contain:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispenser:	Not reported
Test Date:	09/97
Date Closed:	10/98
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	GT11-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	10/98
Capacity (Gal):	533
Product:	KEROSENE
Tank Status:	0
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	Fiberglass
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	10
Second Contain:	21
Leak Detection:	10
Overfill Protection:	20
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	T04
Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	1000

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Product:	KEROSENE
Tank Status:	0
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	8
Leak Detection:	None
Overfill Protection:	42
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Inspected Date:	04/15/1997
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/1998
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	04/05/1999
Federal Id No:	Not reported
COI Date:	/ /

MOSF AST:

MOSF Number:	2-1980
SWIS Code:	63
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 706-2703
Emergency Contact Name:	CIG
Emergency Contact Phone:	(212) 580-6763
Total Tanks:	0
Total Capacity:	0
Daily Throughput:	2142
License Status:	1
Facility Type:	STORAGE TERMINAL/PETROLEUM DISTRIBUTOR
Product Transfer Operation:	AC
Facility Status:	ABANDONED/REMOVED
Operator Name:	AL PINKALL
Owner Name:	CONSOLIDATED EDISON COMPANY OF N.Y., INC.
Owner Address:	4 IRVING PLACE, ROOM 300
Owner City,St,Zip:	NEW YORK, NY 10003-
Owner Phone:	(212) 460-3968
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	First Owner
Mailing Name:	CONSOLIDATED EDISON COMPANY OF N.Y., INC.
Mailing Address:	4 IRVING PLACE, ROOM 300
Mailing Address 2:	Not reported
Mailing City,St,Zip:	NEW YORK, NY 10003-
Mailing Contact:	W. ALAN HOMYK,DIRECTOR -COMPLI
Mailing Phone:	(212) 460-3968
Legal Agent Name:	OFFICE OF THE SECRETARY OF THE COMPANY
Legal Agent Address:	4 IRVING PLACE, ROOM 1618-S

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Legal Agent City,St,Zip: NEW YORK, NY 10003-
LIC Expires: 03/31/2000

Tank ID: BOT-1
Tank Location: ABOVEGROUND
Install Date: 00/00
Product: NOS 1,2, OR 4 FUEL OIL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 00
Pipe Location: Underground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 00
Leak Detection: 00
Overfill Protection: None
Dispensing Mthd: 0
Test Date: Not reported
Date Closed: 11/98
Status of Data: Complete
Capacity (gal): 9000
Lat/Long: 40|45|42 / 73|56|41
Federal ID: Not reported
Inspected Date: 04/15/1997
Inspector: AS
Renew Date: 04/05/1999
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: 0
COI Date: / /
Date License Issued: 04/01/1998
Date License Application Received: 01/08/1998
Chemical Bulk Storage Number: Not reported
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 09/84

Tank ID: GT-7
Tank Location: ABOVEGROUND
Install Date: 00/00
Product: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 00
Pipe Location: Underground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 00
Leak Detection: 00
Overfill Protection: None
Dispensing Mthd: 0
Test Date: Not reported
Date Closed: 11/98

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Status of Data:	Complete
Capacity (gal):	55
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	GE-L1
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	1700
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Tank ID:	GE-L2
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	1700
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	GE-L3
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	1700
Lat/Long:	40|45|42 / 73|56|41

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	GE-L4
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	1700
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	P&W-L5
Tank Location:	ABOVEGROUND
Install Date:	12/70

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	100
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	P&W-L6
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	100
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	P&W-L7
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	100
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Tank ID:	P&W-L8
Tank Location:	ABOVEGROUND
Install Date:	12/70
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None

RAVENWOOD GAS TURBINES TANK FARM (Continued) **S102634330**

Tank External:	NONE
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	None
Leak Detection:	None
Overfill Protection:	None
Dispensing Mthd:	Not reported
Test Date:	Not reported
Date Closed:	00/00
Status of Data:	Minor Errors
Capacity (gal):	100
Lat/Long:	40|45|42 / 73|56|41
Federal ID:	Not reported
Inspected Date:	04/15/1997
Inspector:	AS
Renew Date:	04/05/1999
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	0
COI Date:	/ /
Date License Issued:	04/01/1998
Date License Application Received:	01/08/1998
Chemical Bulk Storage Number:	Not reported
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	09/84

Click this hyperlink while viewing on your computer to access
9 additional NY_AST_MOS: record(s) in the EDR Site Report.

AZ336 **RAVENSWOOD GENERATING STATION** **NY SHWS** **S102239646**
West **38-54 VERNON BOULEVARD** **NY LTANKS** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY MOSF UST**
0.329 mi. **NY MOSF**
1738 ft. **Site 2 of 4 in cluster AZ** **NY CBS**
NY AST
Relative: **NY CBS AST**
Lower **NY VCP**
Actual: **NY MANIFEST**
12 ft. **NY SPDES**

SHWS:

Name:	RAVENSWOOD FORMER MGP
Address:	38-54 VERNON BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW
Site Code:	416958
Classification:	P
Region:	2
Acres:	Not reported
HW Code:	241119
Record Add:	07/23/2009
Record Upd:	12/06/2021
Updated By:	DJEATON
Site Description:	"Location: The Ravenswood former MGP site is located at 38-54 Vernon

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Boulevard in the Long Island City section of the Borough of Queens. The property is noted as Tax Lot 1 in part of block 357 on the Tax Map of the City of New York, Queens County The site is located within the boundary of a complex of active electric and steam generating facilities in a predominantly industrial and commercial area. The site is bordered on the east by light industrial and commercial buildings and on the west by the East River. The site formerly housed a Manufactured Gas Plant operated by Con Edison and its predecessor companies. The precise location of the MGP structures has not been fully established because of the extensive reworking of the property associated with construction of the power plants which now occupy and surround the original MGP site. Remedial History: A portion of the site was remediated under the Voluntary Cleanup Program. See site V000368. The principal VCP issue was the presence of a No. 6 oil spill from an in-plant pipeline. Petroleum-impacted soil was excavated in 2005. No MGP tar-contaminated soil was identified at that time, but MGP related structures or soil contamination may remain in other portions of the site or at depth. "

Env Problem:	"Extensive soil removal has taken place on the site, both for the construction of the power plants that occupy the site, and for remediation of a No. 6 oil spill. Although it appears that significant portions of the former MGP have been excavated down to bedrock, it is not known to what extent MGP structures and MGP soil contamination may remain in the deep subsurface. A bedrock steam tunnel lies beneath the East River at this location, allowing waste steam from the turbine plants to be provided to the steam-heat distribution system in Manhattan. Tar from the former MGP can be seen dripping from the roof of this tunnel, roughly 150 feet below ground surface. The source of the tar has not been determined. The tunnel cannot be accessed by the public and is only occasionally used by utility workers. Engineering controls are in place to prevent direct contact with the tar by utility workers."
Health Problem:	"As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	SE Ravenswood Trust
Owner Address:	37-20 37th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

LTANKS:

Name:	38-54 VERNON BLVD
Address:	38-54 VERNON BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9601426 / 1996-05-30
Facility ID:	9601426
Site ID:	239166
Spill Date:	1996-04-28
Spill Cause:	Tank Failure
Spill Source:	Passenger Vehicle
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-04-28
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-28
Spill Record Last Update:	1996-06-27
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	(0) -
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	244873
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks:	"hole in gas tank - cleaned up"

All Materials:

Site ID:	239166
Operable Unit ID:	1029072
Operable Unit:	01
Material ID:	566843
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Quantity: 5.00
Units: G
Recovered: 5.00
Resource Affected: Soil
Oxygenate: Not reported

Name: RAVENSWOOD GENERATING STA
Address: 38-54 VERNON BOULEVARD
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9613378 / 1997-02-13
Facility ID: 9613378
Site ID: 239188
Spill Date: 1997-02-12
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1997-02-12
CID: 252
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-02-12
Spill Record Last Update: 2003-11-12
Spiller Name: TIM SOILCH
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller County: 001
Spiller Contact: STEVE ROMERO
Spiller Phone: (212) 580-6763
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 244873
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT "
Remarks: "UPON FILLING AIR COMPRESSOR DIESEL FUEL SPILLED ON TO PAVEMENT SPILL HAS BEEN CLEANED UP"

All Materials:
Site ID: 239188
Operable Unit ID: 1040956
Operable Unit: 01
Material ID: 338486
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 8.00
Units: G
Recovered: 8.00

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Resource Affected: Soil
Oxygenate: Not reported

MOSF UST:

Id/Status:	2-1960 / ACTIVE FACILITY
SWIS Code:	63
Facility Town:	NEW YORK CITY
Contact Phone:	(718) 706-2707
Emergency Contact:	SHIFT SUPERVISOR
Emergency Telephone:	(718) 706-2753
CBS Number:	2-000063
SPDES Num:	0-005193
Total Tanks:	24
Total Capacity:	4337274
Avg Throughput:	149854
License Stat:	1
Facility Type:	MANUFACTURING
Prod Xfer Options:	AC
Expiration Date:	03/31/2003
Applic Rcvd:	01/05/2001
Operator:	DOMINIC DI GIORGIO
Owner Name:	KEYSPAN-RAVENSWOOD SERVICES CORPORATION
Owner Address:	ONE METROTECH CENTER
Owner City,St,Zip:	BROOKLYN, NY 11201-3851
Owner Telephone:	(631) 391-6140
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	Second Owner
Mail To Name:	KEYSPAN ENERGY
Mail To Address:	445 BROADHOLLOW ROAD
Mail To Address 2:	Not reported
Mail City,St,Zip:	MELVILLE, NY 11747-
Mail To Contact:	ROBERT D. TEETZ
Mail To Telephone:	(631) 391-6140
Legal Agent Name:	OFFICE OF THE SECRETARY OF THE COMPANY
Legal Agent Address:	ONE METROTECH CENTER
Legal Agent City,St,Zip:	BROOKLYN, NY 11201-3851
Date Filed:	03/99
Latitude:	40|45|30
Longitude:	73|56|56

Tank ID:	F06-1
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS
Install Date:	02/63
Capacity (Gal):	858022
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	20
Second Contain:	10
Leak Detection:	None

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Overfill Protection: 23
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 08/05/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/27/2000
Federal Id No: Not reported
COI Date: / /

Tank ID: F06-2
Tank Location: UNDERGROUND, VAULTED, WITH ACCESS
Install Date: 02/63
Capacity (Gal): 842175
Product: NOS 5 OR 6 FUEL OIL
Tank Status: Temporarily Out Of Service
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: None
Pipe Location: Aboveground/Underground Combination
Pipe Type: STEEL/IRON
Pipe Internal: None
Pipe External: 20
Second Contain: 10
Leak Detection: None
Overfill Protection: 23
Dispenser: Suction
Test Date: Not reported
Date Closed: Not reported
Status of Data: Complete
Inspected Date: 08/05/1999
Inspector Initials: AS
Inspector Status: Not reported
Pipe Flag: True
License Issued: 04/01/2001
Vessel Id: Not reported
Renew Flag: True
Renew Date: 11/27/2000
Federal Id No: Not reported
COI Date: / /

Tank ID: F06-3
Tank Location: UNDERGROUND
Install Date: 12/48
Capacity (Gal): 741465
Product: NOS 5 OR 6 FUEL OIL
Tank Status: Temporarily Out Of Service
Tank Type: Steel/carbon steel
Tank Internal: None

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Tank External:	None
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	20
Second Contain:	50
Leak Detection:	None
Overfill Protection:	23
Dispenser:	Suction
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	RGSPIPELINE
Tank Location:	Not reported
Install Date:	00/00
Capacity (Gal):	362000
Product:	NOS 5 OR 6 FUEL OIL
Tank Status:	Temporarily Out Of Service
Tank Type:	Not reported
Tank Internal:	Not reported
Tank External:	Not reported
Pipe Location:	Underground
Pipe Type:	Not reported
Pipe Internal:	Fiberglass Liner (FRP)
Pipe External:	Not reported
Second Contain:	None
Leak Detection:	Other
Overfill Protection:	Not reported
Dispenser:	Not reported
Test Date:	Not reported
Date Closed:	02/00
Status of Data:	Major Errors
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

Tank ID:	T04

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Tank Location:	UNDERGROUND
Install Date:	12/70
Capacity (Gal):	1000
Product:	KEROSENE
Tank Status:	Temporarily Out Of Service
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	None
Pipe Location:	Aboveground
Pipe Type:	STEEL/IRON
Pipe Internal:	None
Pipe External:	None
Second Contain:	8
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Dispenser:	Suction
Test Date:	/
Date Closed:	Not reported
Status of Data:	Complete
Inspected Date:	08/05/1999
Inspector Initials:	AS
Inspector Status:	Not reported
Pipe Flag:	True
License Issued:	04/01/2001
Vessel Id:	Not reported
Renew Flag:	True
Renew Date:	11/27/2000
Federal Id No:	Not reported
COI Date:	/ /

MOSF:

Name:	RAVENSWOOD GENERATING STATION
Address:	38-54 VERNON BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Facility ID:	2-1960
Program Type:	MOSF
Tank Status:	Active
Expiration Date:	03/31/2023
Dec Region:	2
UTMX:	589041.39688
UTMY:	4512702.29952

Name:	RAVENWOOD GAS TURBINES TANK FARM
Address:	38-54 VERNON BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Facility ID:	2-1980
Program Type:	MOSF
Tank Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	588348.02693
UTMY:	4510881.19851

CBS:

Name:	RAVENSWOOD GENERATING STATION
Address:	38 VERNON BOULEVARD

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

City,State,Zip: LONG ISLAND CITY, NY 11101
CBS Number: 2-000063
Program Type: CBS
Facility Status: Active
Expiration Date: 06/28/2024
Dec Region: 2
UTMX: 589068.21733
UTMY: 4512477.61120

Name: RAVENSWOOD GENERATING STATION
Address: 38-54 VERNON BOULEVARD
City,State,Zip: LONG ISLAND CITY, NY 11101
CBS Number: 2-000366
Program Type: CBS
Facility Status: Unregulated/Closed
Expiration Date: Not reported
Dec Region: 2
UTMX: 589121.10397
UTMY: 4512564.93051

AST:
Name: RAVENSWOOD GENERATING STATION
Address: 38-54 VERNON BOULEVARD
City,State,Zip: LONG ISLAND CITY, NY 11101
Region: STATE
DEC Region: 2
Site Status: Unregulated/Closed
Facility Id: 2-000366
Program Type: CBS
UTM X: 589121.10397
UTM Y: 4512564.93051
Expiration Date: N/A
Site Type: Utility (Other than Municipal)

Tank Info:

Tank Number: A-10
Tank Id: 193890
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 05/01/1978
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/20/2008
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: A-20
Tank Id: 193891

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 05/01/1978
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/20/2008
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: C-1020
Tank Id: 193893
Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1962
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 02/20/2008
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

Tank Number: C-30
Tank Id: 193892
Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type: Steel/Carbon Steel/Iron
Tank Status: Closed - Removed
Pipe Model: Not reported
Install Date: 12/01/1965
Capacity Gallons: 2000
Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Date Tank Closed: 12/01/1999
Register: True
Modified By: MJGRIFFI
Last Modified: 05/09/2022
Material Name: Not reported

CBS AST:
CBS Number: 2-000063
ICS Number: 2-125848

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

PBS Number:	Not reported
MOSF Number:	2-1960
SPDES Number:	0-005193
Facility Status:	IN SERVICE
Facility Type:	E
Telephone:	(718) 706-2707
Facility Town:	NEW YORK CITY
Region:	STATE
Expiration Date:	03/28/2002
Total Capacity of All Active Tanks(gal):	14330
Operator:	DOMINIC DIGIORGIO
Emergency Contact:	SHIFT SUPERVISOR
Emergency Phone:	(718) 706-2753
Owner Name:	KEY SPAN-RAVENSWOOD SERVICES CORP.
Owner Address:	ONE METROTECH CENTER
Owner City,St,Zip:	BROOKLYN, NY 11201-3851
Owner Telephone:	(631) 391-6140
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	KEY SPAN ENERGY
Mail Contact Addr:	445 BROADHOLLOW ROAD
Mail Contact Addr2:	Not reported
Mail Contact Contact:	ROBERT D. TEETZ
Mail Contact City,St,Zip:	MELVILLE, NY 11747
Mail Phone:	(631) 391-6140

Tank Id:	EH30
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Belowground
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	C-30
CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99
Capacity (Gal):	2000
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	00
Overfill Protection:	04
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 77|56|49
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	40|45|39 / 77|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 77|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 77|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 77|56|49

Tank Id:	WH30
CAS Number:	7681529

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Belowground
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	A30
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/65
Tank Closed:	04/97
Capacity (Gal):	2000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	EH12
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/62
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Belowground
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	WH12
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/62
Tank Closed:	12/99
Capacity (Gal):	4000
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Belowground
Tank Type:	Other
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	06/15/1989
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Other
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	Product Level Gauge
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

Tank Id:	C-1020

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

CAS Number:	1310732
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	12/62
Tank Closed:	Not reported
Capacity (Gal):	2000
Chemical:	Sodium hydroxide
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Fiberglass Liner (FRP
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	Painted/Asphalt Coating
Pipe Flag:	Painted/Asphalt Coating
Leak Detection:	None
Overfill Protection:	42
Haz Percent:	50
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 77|56|49
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	40|45|39 / 77|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 77|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 77|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 77|56|49

Tank Id:	A-20
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	05/78
Tank Closed:	Not reported
Capacity (Gal):	2000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	24
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 77|56|49
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	40|45|39 / 77|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 77|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 77|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 77|56|49

Tank Id:	A-10
CAS Number:	7664939
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	05/78
Tank Closed:	Not reported
Capacity (Gal):	2000
Chemical:	Sulfuric acid
Tank Location:	Indoors, Aboveground
Tank Type:	Steel/carbon steel
Total Tanks:	3
Tank Secret:	False
Tank Secondary Containment:	Vault
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Wrapped Steel
Pipe Internal:	None
Pipe External:	00
Pipe Flag:	00
Leak Detection:	00
Overfill Protection:	24
Haz Percent:	93
Last Test:	Not reported
Due Date:	Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

SWIS Code:	6301
Lat/Long:	40|45|39 / 77|56|49
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	40|45|39 / 77|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 77|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 77|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 77|56|49

Tank Id:	SH30
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	In Service
Install Date:	01/00
Tank Closed:	Not reported
Capacity (Gal):	6000
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Belowground
Tank Type:	Steel/carbon steel
Total Tanks:	5
Tank Secret:	False
Tank Secondary Containment:	01
Tank Error Status:	No Missing Data
Date Entered:	03/28/2000
Certified Date:	03/28/2000
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	Rubber Liner
External Protection:	None,Painted/Asphalt Coating
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	Other
Pipe External:	01
Pipe Flag:	01
Leak Detection:	00
Overfill Protection:	24
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	6301
Lat/Long:	40|45|39 / 73|56|49
Is Updated:	False
Renew Date:	03/01/93
Is It There:	False
Delinquent:	False
Date Expired:	06/15/95
Owner Mark:	2
Certificate Needs to be Printed:	40|45|39 / 73|56|49
Fiscal Amt for Registration Fee Correct:	40|45|39 / 73|56|49
Renewal Has Been Printed for Facility:	40|45|39 / 73|56|49
Pre-Printed Renewal App Last Printed:	40|45|39 / 73|56|49

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Click this hyperlink while viewing on your computer to access
4 additional NY_AST_CBS: record(s) in the EDR Site Report.

VCP:

Name:	RAVENSWOOD GENERATING STATION
Address:	38-54 VERNON BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program Type:	VCP
Site Code:	56967
HW Code:	V00368
Site Class:	C
SWIS:	4101
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	04/05/2007
Updated By:	dcwalsh
Site Description:	"The proposed Ravenswood 250-Megawatt (MW) Combined Cycle Generating Station site is located at 38-54 Vernon Boulevard in the Long Island City section of the Borough and County of Queens, New York and denoted as Tax Lot 1 in part of block 357 on the Tax Map of the City of New York, Queens County. The site is located within the boundary of an active electric and steam generating facility in a predominantly industrial and commercial area. The area addressed by this Voluntary Cleanup Agreement is the footprint of a proposed 250-MW combined cycle electric generating plant. The site is bordered on the east by light industrial and commercial buildings; on the south by the existing Ravenswood Generating Station; on the north by the existing Ravenswood Gas Turbine facility; and on the west by the existing Ravenswood Steam Plant and the East River. The site was formerly a Manufactured Gas Plant operated by Con Edison and its predecessor companies. The site is currently occupied by a paved parking lot for Ravenswood employees. Site investigation has been completed at the site."
Env Problem:	"The Site investigation conducted at the site revealed the presence of petroleum contamination related to a release from an on-site no. 6 oil pipeline. In addition, the site is underlain by former MGP facilities, including gas holders, piping and drip pots. Investigation has not revealed any areas of discrete coal tar deposits, however, the volunteer has proposed to open all encountered pipes and drip pots, drain them and permanently closed them in place or remove them if they interfere with future construction activities. The area of petroleum contamination will be excavated and removed. The volunteer submitted and the Department approved a Remedial Action Work Plan for the site which consisted of the above remedies. This RAWP has been implemented, and the volunteer has submitted the Remedial Action Summary Report, which is under review by NYSDEC and NYSDOH."
Health Problem:	"Human exposures to contaminated soil and groundwater are unlikely. Most of the contaminated soil has been removed, the site is fenced and secured, and the site will be covered with buildings and pavement. Exposure to groundwater is unlikely since the area is served by a public water supply."
Dump:	Not reported
Structure:	Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	KeySpan Ravenswood Services Corp.
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
HW Code:	V00368
Waste Type:	COAL TAR PITCH VOLATILES
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	00-TEMP-02-80(R
Cross Ref Type Code:	20
Cross Ref Type:	Haz. Substance ID
Record Added Date:	2000-11-30 16:07:00
Record Updated:	2005-02-24 15:54:00
Updated By:	VCPTRANS

NY MANIFEST:

Name:	KEYSPAN
Address:	38-54 VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYP000072447
Facility Status:	Not reported
Location Address 1:	38-54 VERNON BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000072447
Mailing Name:	KEYSPAN
Mailing Contact:	KEYSPAN
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Name:	CONSOLIDATED EDISION /VERNON SUBSTATION
Address:	38 - 54 VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Country:	USA
EPA ID:	NYR000145078
Facility Status:	Not reported
Location Address 1:	38-54 VERNON BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11101
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000145078
Mailing Name:	CONSOLIDATED EDISION /VERNON SUBSTATION
Mailing Contact:	franklyn murray
Mailing Address 1:	4 irving pl rm 828
Mailing Address 2:	Not reported
Mailing City:	new york
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/29/2009
Trans1 Recv Date:	12/29/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/30/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000145078
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001440817FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	B007
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

SPDES:

Name:	RAVENSWOOD GENERATING STATION
Address:	38-54 VERNON BLVD
City,State,Zip:	QUEENS, NY 11101
Permit Number:	NY0005193
State-Region:	2
Expiration Date:	10/31/2017
Current Major Minor Status:	Major
Primary Facility SIC Code:	4911
State Water Body Name:	EAST R
Limit Set Status Flag:	Active
Total Actual Average Flow(MGD):	1390.893
Total App Design Flow(MGD):	Not reported
UDF1:	DMR
Lat/Long:	40.759670 / 73.9460469
DMR Cognizant Official:	MICHAEL P TUCKER
UDF2:	001702
UDF3:	I
FIPS County Code:	NY081

Non-Gov Permit Affiliation Type Desc:	DMR Mailing Address
Non-Gov Permit Org Formal Name:	HELIX RAVENSWOOD LLC
Non-Gov Permit Street Address:	38-54 VERNON BLVD
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	LONG ISLAND CITY
Non-Gov Permit State Code:	NY
Non-Gov Permit Zip Code:	11101
Non-Gov Facility Affiliation Type Desc:	Mailing Address
Non-Gov Facility Org Formal Name:	HELIX RAVENSWOOD, LLC
Non-Gov Facility Street Address:	RAVENSWOOD GENERATING STATION
Non-Gov Facility Supplemental Location:	38-54 VERNON BLVD
Non-Gov Facility City:	LONG ISLAND CITY

RAVENSWOOD GENERATING STATION (Continued) **S102239646**

Non-Gov Facility State Code:	NY
Non-Gov Facility Zip Code:	11101
State Water Body:	02030201020
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Not reported
Affiliation Type Description:	Not reported
Name:	Not reported
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	Not reported

AZ337 **RAVENSWOOD GENERATING STATION** **NY MOSF AST** **S102633680**
West **38-54 VERNON BOULEVARD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.329 mi.
1738 ft. **Site 3 of 4 in cluster AZ**

Relative: **Lower**
Actual: **12 ft.**

MOSF AST:

MOSF Number:	2-1960
SWIS Code:	63
Facility Town:	NEW YORK CITY
Facility Phone:	(718) 706-2707
Emergency Contact Name:	SHIFT SUPERVISOR
Emergency Contact Phone:	(718) 706-2753
Total Tanks:	24
Total Capacity:	4337274
Daily Throughput:	149854
License Status:	1
Facility Type:	MANUFACTURING
Product Transfer Operation:	AC
Facility Status:	IN SERVICE
Operator Name:	DOMINIC DI GIORGIO
Owner Name:	KEYSPAN-RAVENSWOOD SERVICES CORPORATION
Owner Address:	ONE METROTECH CENTER
Owner City,St,Zip:	BROOKLYN, NY 11201-3851
Owner Phone:	(631) 391-6140
Owner Type:	Corporate/Commercial
Owner Status:	1
Owner Mark:	Second Owner
Mailing Name:	KEYSPAN ENERGY
Mailing Address:	445 BROADHOLLOW ROAD
Mailing Address 2:	Not reported
Mailing City,St,Zip:	MELVILLE, NY 11747-
Mailing Contact:	ROBERT D. TEETZ
Mailing Phone:	(631) 391-6140
Legal Agent Name:	OFFICE OF THE SECRETARY OF THE COMPANY
Legal Agent Address:	ONE METROTECH CENTER
Legal Agent City,St,Zip:	BROOKLYN, NY 11201-3851
LIC Expires:	03/31/2003

Tank ID:	GT1-DT
Tank Location:	ABOVEGROUND
Install Date:	07/67
Product:	DIESEL
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	10
Pipe Location:	Aboveground

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	10
Secondary Containment:	00
Leak Detection:	00
Overfill Protection:	None
Dispensing Mthd:	0
Test Date:	Not reported
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	150
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000063
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	03/99

Tank ID:	K01
Tank Location:	ABOVEGROUND
Install Date:	12/71
Product:	KEROSENE
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	None
Secondary Containment:	Concrete Dike
Leak Detection:	00
Overfill Protection:	Automatic Shut-off
Dispensing Mthd:	Suction
Test Date:	08/95
Date Closed:	Not reported
Status of Data:	Complete
Capacity (gal):	1840062
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Tank Status: Temporarily Out-of-Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000063
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: SOT-5
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/75
Product: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: NONE
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: None
Secondary Containment: None
Leak Detection: 00
Overfill Protection: Product Level Gauge
Dispensing Mthd: Not reported
Test Date: /
Date Closed: Not reported
Status of Data: Minor Errors
Capacity (gal): 1500
Lat/Long: 40|45|30 / 73|56|56
Federal ID: Not reported
Inspected Date: 08/05/1999
Inspector: AS
Renew Date: 11/27/2000
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: Temporarily Out-of-Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000063
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: GT04-1
Tank Location: ABOVEGROUND
Install Date: 10/98
Product: KEROSENE
Tank Type: Fiberglass coated steel
Tank Internal: None
Tank External: 04
Pipe Location: Aboveground/Underground Combination
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 10

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Secondary Containment:	20
Leak Detection:	10
Overfill Protection:	20
Dispensing Mthd:	Not reported
Test Date:	/
Date Closed:	Not reported
Status of Data:	Minor Errors
Capacity (gal):	550
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000063
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	03/99

Tank ID:	GT05-1
Tank Location:	ABOVEGROUND
Install Date:	10/98
Product:	KEROSENE
Tank Type:	Fiberglass coated steel
Tank Internal:	None
Tank External:	04
Pipe Location:	Aboveground/Underground Combination
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	10
Secondary Containment:	20
Leak Detection:	10
Overfill Protection:	20
Dispensing Mthd:	Not reported
Test Date:	/
Date Closed:	Not reported
Status of Data:	Minor Errors
Capacity (gal):	550
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000063
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: LUB-4
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/87
Product: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: NONE/CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 01
Leak Detection: 00
Overfill Protection: Product Level Gauge
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: 12/00
Status of Data: Complete
Capacity (gal): 275
Lat/Long: 40|45|30 / 73|56|56
Federal ID: Not reported
Inspected Date: 08/05/1999
Inspector: AS
Renew Date: 11/27/2000
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: Temporarily Out-of-Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000063
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: LUB-5
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/87
Product: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: NONE/CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 01
Leak Detection: 00
Overfill Protection: Product Level Gauge

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	06/01
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000063
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	03/99

Tank ID:	LUB-6
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date:	12/87
Product:	UNKNOWN
Tank Type:	Steel/carbon steel
Tank Internal:	None
Tank External:	NONE/CATHODIC PROTECTION
Pipe Location:	Aboveground
Pipe Type:	Steel/Iron
Pipe Internal:	None
Pipe External:	00
Secondary Containment:	01
Leak Detection:	00
Overfill Protection:	Product Level Gauge
Dispensing Mthd:	Suction
Test Date:	Not reported
Date Closed:	06/01
Status of Data:	Complete
Capacity (gal):	275
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000063
Pollution Discharge Elimination System Num:	0-005193

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: LUB-7
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/87
Product: UNKNOWN
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: NONE/CATHODIC PROTECTION
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 01
Leak Detection: 00
Overfill Protection: Product Level Gauge
Dispensing Mthd: Suction
Test Date: Not reported
Date Closed: 12/00
Status of Data: Complete
Capacity (gal): 275
Lat/Long: 40|45|30 / 73|56|56
Federal ID: Not reported
Inspected Date: 08/05/1999
Inspector: AS
Renew Date: 11/27/2000
Inspected State: Not reported
Pipe Flag: True
Vessel ID: Not reported
Reserve Flag: True
Tank Status: Temporarily Out-of-Service
COI Date: / /
Date License Issued: 04/01/2001
Date License Application Received: 01/05/2001
Chemical Bulk Storage Number: 2-000063
Pollution Discharge Elimination System Num: 0-005193
Date Legal Agent Filed with Secretary of State: 03/99

Tank ID: EDG-SH-1
Tank Location: ABOVEGROUND
Install Date: 00/00
Product: DIESEL
Tank Type: Steel/carbon steel
Tank Internal: None
Tank External: 00
Pipe Location: Aboveground
Pipe Type: Steel/Iron
Pipe Internal: None
Pipe External: 00
Secondary Containment: 09
Leak Detection: 00
Overfill Protection: None
Dispensing Mthd: Not reported
Test Date: Not reported
Date Closed: Not reported

RAVENSWOOD GENERATING STATION (Continued) **S102633680**

Status of Data:	Minor Errors
Capacity (gal):	275
Lat/Long:	40|45|30 / 73|56|56
Federal ID:	Not reported
Inspected Date:	08/05/1999
Inspector:	AS
Renew Date:	11/27/2000
Inspected State:	Not reported
Pipe Flag:	True
Vessel ID:	Not reported
Reserve Flag:	True
Tank Status:	Temporarily Out-of-Service
COI Date:	/ /
Date License Issued:	04/01/2001
Date License Application Received:	01/05/2001
Chemical Bulk Storage Number:	2-000063
Pollution Discharge Elimination System Num:	0-005193
Date Legal Agent Filed with Secretary of State:	03/99

Click this hyperlink while viewing on your computer to access
19 additional NY_AST_MOS: record(s) in the EDR Site Report.

AZ338 **RAVENSWOOD PCB STORAGE FAC** **CORRACTS** **1015757895**
West **40TH AVE & VERNON BLVD** **RCRA-LQG** **NYD003917960**
1/4-1/2 **LONG ISLAND, NY 11101** **PADS**
0.329 mi.
1738 ft. **Site 4 of 4 in cluster AZ**

Relative: **Lower**
Actual: **12 ft.**

CORRACTS:

Name:	CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Address:	3854 VERNON BLVD NW CORNER
Address 2:	Not reported
EPA ID:	NYD003917960
Area Name:	SITEWIDE
Corrective Action:	RFA COMPLETED
Actual Date:	19941201
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

Name:	CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Address:	3854 VERNON BLVD NW CORNER
Address 2:	Not reported
EPA ID:	NYD003917960
Area Name:	SITEWIDE
Corrective Action:	DETERMINATION OF NEED FOR AN INVESTIGATION-INVESTIGATION IS NOT NECESSARY
Actual Date:	19941201
Air Release Indicator:	Not reported
Groundwater Release Indicator:	Not reported
Soil Release Indicator:	Not reported
Surface Water Release Indicator:	Not reported

RCRA Listings:

Date Form Received by Agency:	20070311
Handler Name:	Con Edison - Ravenswood Tunnel Headhouse

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Handler Address:	3854 VERNON BLVD NW CORNER
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD003917960
Contact Name:	WARREN MILLER
Contact Address:	VERNON BLVD NW CORNER
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	978-578-9757
Contact Fax:	Not reported
Contact Email:	MILLERW@CONED.COM
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	VERNON BLVD NW CORNER
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Biennial: List of Years
Year: 2005

Click Here for Biennial Reporting System Data:
Year: 2003

Click Here for Biennial Reporting System Data:
Year: 2001

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status:	Private

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON CO OF NY INC
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Legal Status: Private
Date Became Current: 19570402
Date Ended Current: Not reported
Owner/Operator Address: 4 IRVING PLACE
Owner/Operator City,State,Zip: NEW YORK, NY 10003
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 19910923
Handler Name: CON EDISON - RAVENSWOOD GENERATING STA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19930315
Handler Name: CON EDISON - RAVENSWOOD GENERATING STA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070311
Handler Name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070311
Handler Name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19800818
Handler Name: CON EDISON - RAVENSWOOD GENERATING STA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070312
Handler Name: CON EDISON - RAVENSWOOD TUNNEL HEADHOUSE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Electronic Manifest Broker: Not reported

Receive Date: 19920228
Handler Name: CON ED - RAVENSWOOD STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940328
Handler Name: CON EDISON - RAVENSWOOD GENERATING STA
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960329
Handler Name: CON EDISON-RAVENSWOOD GENERATING STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980226
Handler Name: CON ED - REVENSWOOD GENERATING STATION
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20010101
Handler Name: RAVENSWOOD GENERATING STATION
Federal Waste Generator Description: Large Quantity Generator

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20020531
Handler Name: CON EDISION - RAVENSWOOD SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040225
Handler Name: CON EDISON - RAVENSWOOD SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060221
Handler Name: CON EDISON - RAVENSWOOD SITE
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 221122
NAICS Description: ELECTRIC POWER DISTRIBUTION

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Has the Facility Received Notices of Violations:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19940830
Actual Return to Compliance Date:	19971023
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	000
Date of Enforcement Action:	19971023
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	NYR2
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: NYSAN
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19930929
Actual Return to Compliance Date: 19931108
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19931029
Enforcement Identifier: 000
Date of Enforcement Action: 19930929
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYADS
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19910508
Actual Return to Compliance Date:	19911015
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19910621
Enforcement Identifier:	000
Date of Enforcement Action:	19910508
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYLH
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19900131
Actual Return to Compliance Date: 19900517
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19900409
Enforcement Identifier: 003
Date of Enforcement Action: 19900309
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	LDR - General
Date Violation was Determined:	19880314
Actual Return to Compliance Date:	19880621
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	19881230
Enforcement Identifier:	002
Date of Enforcement Action:	19880512
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19880314
Actual Return to Compliance Date: 19880621
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: 19880612
Enforcement Identifier: 002
Date of Enforcement Action: 19880512
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYDEC
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Evaluation Action Summary:

Evaluation Date:	20070118
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSAN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19940830
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSAN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19971023
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19930824
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYADS
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19931108
Scheduled Compliance Date:	19931029
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19910312
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYLH
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19911015
Scheduled Compliance Date:	19910621
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870422
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19900131
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19900517
Scheduled Compliance Date:	19900409
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19880314
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19880621
Scheduled Compliance Date:	19881230
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19860513
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19880314
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19880621
Scheduled Compliance Date:	19880612
Date of Request:	Not reported

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

PADS:

Name:	RAVENSWOOD PCB STORAGE FAC
Address:	40TH AVE & VERNON BLVD
Address 2:	Not reported
City,State,Zip:	LONG ISLAND, NY 11101
EDR ID:	1015757895
EPAID:	NYD003917960
Region:	02
Generator:	Y
Storer:	N
Disposer:	N
Transporter:	N
Smelter:	N
Research Facility:	N
Mailing Address:	4 IRVING PLACE ROOM 300
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Country:	US
Owner Name:	CONSOLIDATED EDISON OF NY INC
Certification Date:	03/28/1990
Contact Name:	ROBERT T KEEGAN
Contact Title:	Not reported
Contact Telephone:	212-460-4833

RAVENSWOOD PCB STORAGE FAC (Continued) **1015757895**

Contact Text: Not reported
Contact Email: Not reported

AY339 **GULF STATION** **NY LTANKS** **S106124280**
SSW **23-01 41ST AVE** **NY Spills** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.331 mi.
1748 ft. **Site 3 of 4 in cluster AY**

Relative:
Higher

Actual:
28 ft.

LTANKS:

Name:	GULF STATION
Address:	23-01 41ST AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0808735 / 2009-08-28
Facility ID:	0808735
Site ID:	406141
Spill Date:	2008-11-03
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	2008-11-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-11-03
Spill Record Last Update:	2009-08-28
Spiller Name:	TJ OCONNOR
Spiller Company:	GULF STATION
Spiller Address:	23-01 41ST AVE
Spiller County:	999
Spiller Contact:	TJ OCONNOR
Spiller Phone:	(516) 678-5115
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195731
DEC Memo:	"TTF 1/15/09. J.Krimgold reviewed the letter-report submitted by Energy Fueling systems Corp and dated 12/22/08. According to the information provided in this letter, a 2000 gal tank failed the test due to a damaged (cut)vent pipe. The failed pipe was abbendoned in place and new pipe run was installed. Tank with pipe was retested and passed the test. NFA. "
Remarks:	"TANK TEST FAILURE ON A 2000 GALLON UST. UNK IF ANY PRODUCT WAS SPILLED."

All TTF:

Facility ID:	0808735
Spill Number:	0808735
Spill Tank Test:	2486875
Site ID:	406141

GULF STATION (Continued) **S106124280**

Tank Number:	1
Tank Size:	2000
Material:	0009
EPA UST:	True
UST:	True
Cause:	99
Source:	03
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	JMKRIMGO
Last Modified Date:	Not reported

All Materials:

Site ID:	406141
Operable Unit ID:	1162749
Operable Unit:	01
Material ID:	2154029
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	GULF STATION
Address:	23-01 41ST AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0308076 / 2004-01-07
Facility ID:	0308076
Site ID:	237638
Spill Date:	2003-10-30
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2003-10-30
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-10-30
Spill Record Last Update:	2004-02-06
Spiller Name:	Not reported
Spiller Company:	CUMBERLAND FARMS

GULF STATION (Continued) **S106124280**

Spiller Address:	777 DEDHAM ST
Spiller County:	001
Spiller Contact:	BRIAN BERKLE
Spiller Phone:	(610) 278-7203
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195731
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was K FOLEY 12/15/03 Letter addressed to Sigona from Environmental Systems Group. On 10/30/03, Crompco conducted precision test on tanks. One 4000gal diesel UST failed the test. Energy Storage Systems reviewed the test data and suggested the test technician failed to plug the air eliminator on the pumps and therefore the tanks failed. On 12/9/03, Crompco retested the tanks and plugged the air eliminator and the tank passed. 12/19/03 Spoke to Andy at Energy Storage systems. As per Sigona's recommendation, he will submit a report summarizing the first and second testing episodes. Rommel 12/23/03 Received letter from Mort Turoff at Energy Storage systems summarizing first and second tests. Diesel tank passed on 12/9/03 retest. Results on file. (KMF) 1/9/04 Sent NFA. (KMF)"
Remarks:	"liquid level failure"

All Materials:

Site ID:	237638
Operable Unit ID:	874384
Operable Unit:	01
Material ID:	568462
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

SPILLS:

Name:	GULF MOKIN GAS
Address:	23-01 41ST AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9611967 / 1997-01-10
Facility ID:	9611967
Facility Type:	ER
DER Facility ID:	195731
Site ID:	298938
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	1997-01-03
Investigator:	KATZ
Referred To:	Not reported
Reported to Dept:	1997-01-03
CID:	267
Water Affected:	Not reported

GULF STATION (Continued) **S106124280**

Spill Source:	Tank Truck
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-01-03
Spill Record Last Update:	2009-09-23
Spiller Name:	MR GOODE
Spiller Company:	C DAVISON TRUCKING
Spiller Address:	2824 AVE X
Spiller Company:	001
Contact Name:	FF REGAN
DEC Memo:	""
Remarks:	"tank truck making a delivery to gas station and spilled 25 gallons due to air in the line gasoline is now in the sewer system req dec call back ff regan at 917-769-0483"

All Materials:

Site ID:	298938
Operable Unit ID:	1039826
Operable Unit:	01
Material ID:	340614
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

AY340 **23-01 41ST AVENUE** **NY VCP** **S118943521**
SSW **23-01 41ST AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.332 mi.
1753 ft. **Site 4 of 4 in cluster AY**

Relative:
Higher

Actual:
28 ft.

VCP NYC:

Project ID:	15TMP0357Q,15EHAZ357Q,15CVCP133Q
Name:	23-01 41ST AVENUE
Address:	23-01 41ST AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Queens
BBL:	4.0040800054003999E+19
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Site Management
Latitude:	40.752985
Longitude:	-73.940497
Postcode:	1
Community Board:	26
Council District:	33
Census Tract:	4618929
BIN:	4004087501

23-01 41ST AVENUE (Continued) **S118943521**

NTA: Queensbridge-Ravenswood-Long Island City

BA341 **35-41 11TH ST/QUEENS** **NY LTANKS** **S100144960**
North **35-41 11TH ST** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.337 mi.
1778 ft. **Site 1 of 3 in cluster BA**

Relative: **Lower**
Actual: **15 ft.**

LTANKS:

Name:	35-41 11TH ST/QUEENS
Address:	35-41 11TH ST
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8708941 / 1992-10-07
Facility ID:	8708941
Site ID:	165876
Spill Date:	1988-01-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-10-07
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-01-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-26
Spill Record Last Update:	1994-02-15
Spiller Name:	Not reported
Spiller Company:	WEGNER MACHINES
Spiller Address:	35-41 11TH ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	139782
DEC Memo:	""
Remarks:	"5K TANK SYSTEM FAILED PETRO TITE TEST AT AN UNREADABLE RATE, PIPING LEAK. CONTACT: KEN SMITH (718)-278-8408."

All TTF:

Facility ID:	8708941
Spill Number:	8708941
Spill Tank Test:	1533043
Site ID:	165876
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

35-41 11TH ST/QUEENS (Continued) **S100144960**

Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	165876
Operable Unit ID:	913893
Operable Unit:	01
Material ID:	464292
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

AW342 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100153363**
South **40-40 CRESCENT ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.341 mi.
1800 ft. **Site 2 of 4 in cluster AW**

Relative: **Higher**

Actual: **35 ft.**

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	40-40 CRESCENT ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9105613 / 2003-03-14
Facility ID:	9105613
Site ID:	271352
Spill Date:	1991-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1991-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-09-17
Spill Record Last Update:	2003-10-24
Spiller Name:	Not reported

CLOSED-LACKOF RECENT INFO (Continued) **S100153363**

Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	220855
DEC Memo:	""
Remarks:	"THREE 2K TANKS SIPHONED. PETROTITE. CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	9105613
Spill Number:	9105613
Spill Tank Test:	1538951
Site ID:	271352
Tank Number:	Not reported
Tank Size:	0
Material:	0066A
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	271352
Operable Unit ID:	956119
Operable Unit:	01
Material ID:	421399
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

343
SE
1/4-1/2
0.345 mi.
1822 ft.

29-05 38TH AVENUE SITE
29-05 38TH AVENUE
LONG ISLAND CITY, NY 11101

NY BROWNFIELDS **S127282808**
N/A

Relative:
Higher

Actual:
38 ft.

BROWNFIELDS:

Name:	29-05 38TH AVENUE SITE
Address:	29-05 38TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP

29-05 38TH AVENUE SITE (Continued) **S127282808**

Site Code: 613402
Acres: 0.240
HW Code: C241250
SWIS: 4101
Town: New York City
Record Added Date: 11/20/2020
Record Updated Date: 03/11/2022
Update By: WBBENNET
Site Description: "Location: The 29-05 38th Avenue Site is located in an urban area of Queens County, and consists of a single parcel with addresses of 29-05 38th Avenue and 29-05A 38th Avenue. Site Features: Currently, the site is vacant. Prior to demolition, the parcel contained a 1.5-story warehouse building with a partial basement that was formerly occupied by a biofuel generator rental company, a single-story vacant commercial building, a 2-story residential building with a basement, a single-single story residential building with a basement, and two, non-contiguous paved parking areas. Current Zoning and Land Use: The current zoning designation for the site is M1-2/R6A5D, allowing for mixed residential, facility, commercial, and light industrial uses. The site is bounded by a vacant lot that formerly maintained an industrial building to the north, 30th Street to the east, 38th Avenue to the south, and Old Ridge Road to the west. One sensitive receptor was identified within a 500-foot radius of the site; Oliver Wendell Holmes Intermediate School 204 is located approximately 490 feet to the northwest of the site at 36-41 28th Street. In addition, the adjacent property to the north (37-24 to 37-28 30th Street) has been investigated and was remediated under the New York State Brownfield Cleanup Program (BCP), as BCP Site Number C241214. This parcel and the adjacent parcel to the north were historically used as commercial dry cleaning and laundry facilities, and previous investigations identified elevated levels of the dry cleaning solvent tetrachloroethene and its daughter product trichloroethene in soil vapor. Past Use of the Site: According to a Phase I Environmental Site Assessment (ESA) report dated March 8, 2020, the former structures at the site (1.5-story warehouse, single-story vacant building, two-story residential building, and single-story residential building) were all constructed between 1898 and 1936. According to the Sanborn Fire Insurance maps, the 1.5-story warehouse was listed as a carpet cleaning facility from 1936 until 2006. Additionally, the vacant single-story building located on the eastern portion of the site was shown to have been an automotive service facility and gasoline station from 1947 until at least 1950. The single-story and two-story residential buildings located on the western portion of the site were constructed circa 1898 and 1936, respectively. They have reportedly maintained residential occupancy since construction. Site Geology and Hydrogeology: The stratigraphy of the site, from the surface down, consists of approximately 10 feet of coarse-to-fine grained sand with silt and clay underlain by 10 feet of poorly-graded sand and clay. Historic fill material, as determined predominantly by the presence of brick pieces, was identified at two sample locations to a depth of 2 feet below ground surface (bgs) and at a third sample locations to a depth of 7 feet bgs. The average depth to groundwater at the site ranged in depth from 23.83 feet bgs to 28.13 feet bgs. Groundwater flow beneath the site is from east to west. "
Env Problem: "Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic

29-05 38TH AVENUE SITE (Continued) **S127282808**

compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, per- and polyfluoroalkyl substances (PFAS), and 1,4-dioxane. Based upon investigations conducted to date, the primary contaminants of concern for the site include VOCs and SVOCs. Soil: twenty two soil samples were collected during the Remedial Investigation (RI). There were no exceedances of VOCs. Several SVOCs exceed the restricted residential use soil cleanup objectives (RRSCOs) across the site, including, but not limited to benzo(a)anthracene at 2.14 parts per million (ppm), benzo(a)pyrene at 2.17 ppm, benzo(b)fluoranthene at 1.9 ppm compared to their RRSCO of 1 ppm; and indeno(1,2,3-CD)pyrene at 1.21 ppm versus the RRSCO of 0.5 ppm. There were no exceedances of metal, pesticides, PFAS or PCBs above RRSCOs. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Fifteen groundwater samples were obtained as part of the RI. Fifteen samples detected VOCs including, but not limited to, maximum concentration of tetrachloroethene (PCE) at 120 parts per billion (ppb) compared to its ambient water quality standard (AWQS) of 5 ppb. One sample detected SVOCs Bis(2-ethylhexyl)phthalate at a concentration of 13 ppb, compared to their ambient water quality standard (AWQS) of 5 ppb. Metals detected include, but are not limited to, manganese, magnesium, selenium and sodium, however these levels are consistent with regional levels. There were no exceedances of PCBs or pesticides. The highest detection of PFOA was 35.2 parts per trillion (ppt), and the highest detection of PFOS was 15.9 ppt, which both exceed the maximum contaminant level (MCL) of 10 ppt in drinking water for each compound. There were no detections of 1,4-dioxane. Data does not indicate any off-site impacts in groundwater related to this site. Soil Vapor: Eleven soil vapor points were sampled during the RI. Multiple VOCs were detected in each soil vapor sample collected from the subject property. Petroleum related compounds, such as benzene and toluene were detected in each soil vapor sample at relatively low concentrations. Chlorinated VOCs were detected at maximum concentrations including, but not limited to, PCE at 23,000 ug/m3, and trichloroethene (TCE) at 1,700 ug/m3. Data indicates there is potential for off-site impacts in soil vapor related to this site. "

Health Problem: "The site buildings have been demolished and the site contains a small fenced off parking area which has a paved surface, therefore it is not expected that people will come into contact with site related contamination unless they disturb the surface. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Since the site is vacant, soil vapor intrusion is not a current concern, however the potential exists for indoor air impacts in any future on-site development and occupancy. Also, the potential exists for indoor air impacts from site contaminants in off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

29-05 38TH AVENUE SITE (Continued) **S127282808**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-02-16 16:43:00
Record Upd:	2022-02-24 10:59:00
Updated By:	SJWALSH
Own Op:	1
Sub Type:	E
Owner Name:	Jack Fang
Owner Company:	FH 2BRO Builder Corp.
Owner Address:	40-39 27th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library of Long Island City
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Jack Fang
Owner Company:	FH 2BRO Builder Corp.
Owner Address:	40-39 27th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard, LL Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	C241250
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241250
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AW344 **24-03 41ST AVE** **NY LTANKS** **U003066518**
SSW **24-03 41ST AVE** **NY UST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.350 mi.
1847 ft. **Site 3 of 4 in cluster AW**

Relative:
Higher

Actual:
30 ft.

LTANKS:

Name:	24-03 41ST STREET
Address:	24-03 41ST STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8709565 / 1993-02-25
Facility ID:	8709565
Site ID:	174701
Spill Date:	1988-02-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1993-02-25
SWIS:	4101
Investigator:	BATTISTA
Referred To:	Not reported
Reported to Dept:	1988-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-23
Spill Record Last Update:	1994-05-12
Spiller Name:	Not reported
Spiller Company:	LAMBERT PETA
Spiller Address:	24-03 41ST. STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	146914
DEC Memo:	""
Remarks:	"-0.491 G.P.H. DETECTED LEAK RATE COMING FROM A 1500 GALLON TANK . THE COMPANY OWNING THE TANK HAS BEEN NOTIFIED BUT HAS NOT CONFIRMED ANY ACTIONS REGARDING THIS FAILURE."

All TTF:

Facility ID:	8709565
Spill Number:	8709565
Spill Tank Test:	1533215
Site ID:	174701
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

24-03 41ST AVE (Continued) **U003066518**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 174701
Operable Unit ID: 914644
Operable Unit: 01
Material ID: 464893
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

UST:
Name: 24-03 41ST AVE
Address: 24-03 41ST AVE
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-095265 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 06/12/2027
UTM X: 589498.39777
UTM Y: 4511842.39771
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 2629
Affiliation Type: Facility Owner
Company Name: 2403 41ST LLC
Contact Type: OWNER
Contact Name: DOMINIC CASAMARO
Address1: 14-38 31 DRIVE
Address2: Not reported
City: LONG ISLAND CITY
State: NY
Zip Code: 11106
Country Code: 001
Phone: (718) 278-0806
EMail: Not reported
Fax Number: Not reported
Modified By: MSBAPTIS
Date Last Modified: 2012-03-27

Site Id: 2629
Affiliation Type: Mail Contact
Company Name: 2403 41ST LLC
Contact Type: Not reported
Contact Name: DOMINIC CASAMENTO

24-03 41ST AVE (Continued) **U003066518**

Address1:	14-38 31 DRIVE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 278-0806
EMail:	DCANDS@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-03-28

Site Id:	2629
Affiliation Type:	Facility Operator
Company Name:	24-03 41ST AVE
Contact Type:	Not reported
Contact Name:	MANUEL MUNOZ
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 228-7882
EMail:	Not reported
Fax Number:	Not reported
Modified By:	DXLIVING
Date Last Modified:	2007-04-05

Site Id:	2629
Affiliation Type:	Emergency Contact
Company Name:	2403 41ST LLC
Contact Type:	Not reported
Contact Name:	DOMINIC CASAMENTO
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(201) 259-1434
EMail:	Not reported
Fax Number:	Not reported
Modified By:	TRANSLAT
Date Last Modified:	2004-03-04

Tank Info:

Tank Number:	001
Tank ID:	4513
Tank Status:	In Service
Material Name:	In Service
Capacity Gallons:	1500
Install Date:	12/01/1950
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground

24-03 41ST AVE (Continued) **U003066518**

Tank Type: Steel/carbon steel
Material Code: 0001
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 21
Date Test: 08/09/2017
Next Test Date: 08/09/2018
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H99 - Tank Leak Detection - Other
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
L09 - Piping Leak Detection - Exempt Suction Piping
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

AW345 **APRT** **NY LTANKS** **S108983070**
SSW **2403 41ST AVE** **N/A**
1/4-1/2 **QUEENS, NY**
0.351 mi.
1852 ft. **Site 4 of 4 in cluster AW**

Relative: **Higher**

Actual: **30 ft.**

LTANKS:
Name: APRT
Address: 2403 41ST AVE
City,State,Zip: QUEENS, NY
Spill Number/Closed Date: 0711618 / 2008-04-02
Facility ID: 0711618
Site ID: 393128
Spill Date: 2008-02-04
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: bkfalvey
Referred To: Not reported
Reported to Dept: 2008-02-04
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-02-04
Spill Record Last Update: 2009-03-30
Spiller Name: MARLIN JOSEPH

APRT (Continued) **S108983070**

Spiller Company:	APRT
Spiller Address:	2403 41ST AVE
Spiller County:	001
Spiller Contact:	MARLIN JOSEPH
Spiller Phone:	(718) 624-4842
Spiller Extention:	112
DEC Region:	2
DER Facility ID:	342746
DEC Memo:	"2/21/08 Called Dominic Casamento (718)278-0806. left message to call me back. Sent ttf letter to: Dominic Casamento 2403 41st LLC 14-38 31st Drive Long Island City, NY 11106 Mr. Casamento called back later in the day. He said Petroleum Tank Cleaners will be coming back on Monday to make necessary repairs. He said they told him it was a dry leak. I confirmed the above address as his mailing address. He is on vacation and will be returning Monday. bf 4/2/08 received fax from M. Salamack of PTC. Tank was emptied and lines and tank were isolated. vent line was hit by a vehicle as tank is under a driveway area. Vent line was replaced to a different area to prevent future accidents. Tank was retesed 3/10/08 and passed. Test results attached. NFA. bf"
Remarks:	"DRY PORTION LEAK"

All TTF:

Facility ID:	0711618
Spill Number:	0711618
Spill Tank Test:	2384605
Site ID:	393128
Tank Number:	Not reported
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	393128
Operable Unit ID:	1150101
Operable Unit:	01
Material ID:	2140683
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BB346 **41ST AVENUE & 12ST STREET** **NY LTANKS** **S100879201**
SW **41ST AVE/12TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.353 mi.
1865 ft. **Site 1 of 2 in cluster BB**

Relative: **Lower**
Actual: **16 ft.**

LTANKS:

Name:	41ST AVENUE & 12ST STREET
Address:	41ST AVE/12TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9313090 / 2003-03-11
Facility ID:	9313090
Site ID:	223819
Spill Date:	1994-02-17
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1994-02-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-02-07
Spill Record Last Update:	2003-03-11
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	87665
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL 10/10/95: This is additional information about material spilled from the translation of the old spill file: LT. HEATING OIL. 3/11/03: See spill # 8707045. (JHO)"
Remarks:	"TRANSIT PERSONNEL TO INVESTIGATE FURTHER. TANK WORK BEING DONE ABOVE AT QUEENSBRIDGE HOUSES. NYC DEP WAS NOTIFIED - WOULD LIKE CALL BACK WITH ANY UPDATE INFO. STILL HAVE LEAKING AT SITE. REPORTING SAM"

All Materials:

Site ID:	223819
Operable Unit ID:	994968
Operable Unit:	01
Material ID:	388482
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L

41ST AVENUE & 12ST STREET (Continued) **S100879201**

Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

347
ENE
1/4-1/2
0.354 mi.
1871 ft.

25-13 35TH AVENUE **NY LTANKS** **S102672895**
25-13 35TH AVENUE **N/A**
ASTORIA, NY

Relative:
Higher

Actual:
31 ft.

LTANKS:

Name:	25-13 35TH AVENUE
Address:	25-13 35TH AVENUE
City,State,Zip:	ASTORIA, NY
Spill Number/Closed Date:	9500610 / 1995-04-17
Facility ID:	9500610
Site ID:	212947
Spill Date:	1995-04-14
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1995-04-17
SWIS:	4101
Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1995-04-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-05-15
Spill Record Last Update:	1995-05-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	176417
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIBBE "
Remarks:	"SPILL CAUSED BY TANK OVERFILL - VENT ALARM DEFECTIVE - HAS BEEN CORRECTED AND SPILL IS CONTAINED WITH DRYSOL - CONCRETE BASEMENT FLOOR"

All Materials:

Site ID:	212947
Operable Unit ID:	1011358
Operable Unit:	01
Material ID:	369230
Material Code:	0001A

25-13 35TH AVENUE (Continued) **S102672895**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

348
ESE
1/4-1/2
0.356 mi.
1880 ft.

2912 36TH AVE **NY LTANKS** **S102673136**
2912 36TH AVE **N/A**
ASTORIA, NY

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	2912 36TH AVE
Address:	2912 36TH AVE
City,State,Zip:	ASTORIA, NY
Spill Number/Closed Date:	9511910 / 1995-12-20
Facility ID:	9511910
Site ID:	273864
Spill Date:	1995-12-20
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JMKRIMGO
Referred To:	Not reported
Reported to Dept:	1995-12-20
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-20
Spill Record Last Update:	1996-01-17
Spiller Name:	Not reported
Spiller Company:	BAERENKLU
Spiller Address:	740 JAMAICA AV
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(718) 784-4623
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	222771
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was KRIMGOLD "
Remarks:	"DRIVER OVERFILLED TANK AND CLEANED UP SPILL"

All Materials:

Site ID:	273864
Operable Unit ID:	1022579

2912 36TH AVE (Continued) **S102673136**

Operable Unit:	01
Material ID:	359235
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

BC349 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100167437**
SSE **39038 29TH ST.** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.360 mi.
1900 ft. **Site 1 of 2 in cluster BC**

Relative: **Higher**

Actual: **37 ft.**

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	39038 29TH ST.
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8705823 / 2003-03-04
Facility ID:	8705823
Site ID:	186869
Spill Date:	1987-10-09
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1987-10-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-10-15
Spill Record Last Update:	2003-03-14
Spiller Name:	Not reported
Spiller Company:	ST. PATRICK'S CHURCH
Spiller Address:	39-38 29TH ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	156182
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/04/2003-Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"4K TANK FAILED TEST WITH HIGH VOLUME LEAK, WILL EXCAVATE, ISOLATE,

CLOSED-LACKOF RECENT INFO (Continued) **S100167437**

AND RETEST. CONTACT: FRANK FLORIO (718) 729-6060.CLOSED DUE TO LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8705823
Spill Number:	8705823
Spill Tank Test:	1531886
Site ID:	186869
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	186869
Operable Unit ID:	909654
Operable Unit:	01
Material ID:	468390
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

BC350 **CHURCH** **NY LTANKS** **S106737888**
SSE **39-38 29TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.365 mi.
1925 ft. **Site 2 of 2 in cluster BC**

Relative: **Higher**
Actual: **37 ft.**

LTANKS:

Name:	CHURCH
Address:	39-38 29TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0411422 / 2006-01-17
Facility ID:	0411422
Site ID:	336615
Spill Date:	2005-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	Con Ed Unassigned

CHURCH (Continued) **S106737888**

Referred To:	Not reported
Reported to Dept:	2005-01-21
CID:	408
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-21
Spill Record Last Update:	2006-01-17
Spiller Name:	PETROLEUM TANK CLEANERS
Spiller Company:	CHURCH
Spiller Address:	39-38 29TH STREET
Spiller County:	001
Spiller Contact:	PETROLEUM TANK CLEANERS
Spiller Phone:	(646) 772-7949
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	271936
DEC Memo:	"need to send ttf ltr 3/28/05 see also spill # 04-11423//closed out two tank test failures at same site, both above product level..MT////////////////////////// 12/19/05 Feroze. Spill is transferred from Ketani to Feroze. 12/27/05. TTf is sent to: ST. Patrick R.C. Church 39-38, 29 Th Street, LIC. NY 11101 Ph:718-729-6060 12/30/05 Owner representative Mr. Parmel Ernest called and told me that they will send DEC the Tank Test result shortly. Tank Test is passed. 01/17/06. Feroze received documents from Mr. Parmel Ernest that they replaced the vent pipe and they system tank test. The system Tank Test passed. Consultation with DEC Steve Sangesland the spill is closed. "
Remarks:	"Above liquid leak. Test method was ez3 locator plus."

All TTF:

Facility ID:	0411422
Spill Number:	0411422
Spill Tank Test:	1548522
Site ID:	336615
Tank Number:	4
Tank Size:	2500
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MXTIPPLE
Last Modified Date:	Not reported

Facility ID:	0411422
Spill Number:	0411422
Spill Tank Test:	1548732
Site ID:	336615
Tank Number:	1

CHURCH (Continued) **S106737888**

Tank Size:	4000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	MXTIPPLE
Last Modified Date:	Not reported

All Materials:

Site ID:	336615
Operable Unit ID:	1098635
Operable Unit:	01
Material ID:	578806
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	CHURCH
Address:	39-38 29TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0411423 / 2005-03-28
Facility ID:	0411423
Site ID:	336616
Spill Date:	2005-01-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2005-01-21
CID:	408
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-01-21
Spill Record Last Update:	2005-03-28
Spiller Name:	PETROLIUM TANK CLEANERS
Spiller Company:	CHURCH
Spiller Address:	39-38 29TH STREET

CHURCH (Continued) **S106737888**

Spiller County: 001
Spiller Contact: PETROLIUM TANK CLEANERS
Spiller Phone: (718) 624-4842
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 271936
DEC Memo: "need to send a ttf ltr 3/28/05 this spill 3 closed and referred to spill # 0411422//two tank test failures inconclusive/above product level//dry leaks...MT//////////////////////////////////"
Remarks: "Test method was ez 3 locator plus. Inconclusive failure."

All TTF:
Facility ID: 0411423
Spill Number: 0411423
Spill Tank Test: 1548523
Site ID: 336616
Tank Number: 1
Tank Size: 4000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 336616
Operable Unit ID: 1098636
Operable Unit: 01
Material ID: 578807
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

BA351 **CHUCK'S PLACE - QNS** **NY LTANKS** **S106703396**
North **34-59 11TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.368 mi.
1945 ft. **Site 2 of 3 in cluster BA**

Relative: **Lower**
Actual: **15 ft.**

LTANKS:
Name: CHUCK'S PLACE - QNS
Address: 34-59 11TH ST
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 8908538 / 2005-06-20
Facility ID: 8908538

CHUCK'S PLACE - QNS (Continued) **S106703396**

Site ID:	163382
Spill Date:	1989-11-29
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	GWHEITZM
Referred To:	Not reported
Reported to Dept:	1989-11-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Federal Government
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-11-29
Spill Record Last Update:	2005-06-20
Spiller Name:	Not reported
Spiller Company:	CHUCK'S PLACE - QNS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	137810
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL 4/12/04-Vought-Spill transferred from Sullivan to Rommel as per Rommel. 6/16/05 Heitzman: PBS 2-479187, 5 550-gallon gasoline tanks closed in place 9/90. Site is now listed as 3 C's Auto Collision, no active tanks. The NRC case number pre-dates EPA's database, and no information is available concerning EPA's response action. Based on the age of the spill and the closure of the tanks in 1990, this spill can be closed."
Remarks:	"NRC CASE # 21264 - NYFD RESPONDED - VERIFIED THAT FUMES WERE GASOLINE CON ED CONTACTED - ONGOING FOR OVER A YEAR."

All Materials:

Site ID:	163382
Operable Unit ID:	935869
Operable Unit:	01
Material ID:	445273
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Air
Oxygenate:	Not reported

BA352 **34-24 11TH ST** **NY LTANKS** **S105997582**
North **34-24 11TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.368 mi.
1945 ft. **Site 3 of 3 in cluster BA**

Relative: **Lower**

Actual: **15 ft.**

LTANKS:

Name:	34-24 11TH ST
Address:	34-24 11TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0209381 / 2005-11-07
Facility ID:	0209381
Site ID:	155841
Spill Date:	2002-12-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	GWHEITZM
Referred To:	Not reported
Reported to Dept:	2002-12-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-12
Spill Record Last Update:	2005-11-07
Spiller Name:	ALAN
Spiller Company:	GLOBE ELECTRIC
Spiller Address:	34-24 11TH ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	131927
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 1/7/04-Vought-Spill transferred from Vought to Austin. 1/27/04 - Sawyer - Spill transferred from Austin to Sawyer. 4/07/04 - Sawyer - Called Globe Electric, but was no table to speak to anyone. I will call back. 11/07/05 Heitzman: See PBS # 2-605840. Tank was re-tested 5/14/03 and passed. Close spill."
Remarks:	""

All TTF:

Facility ID:	0209381
Spill Number:	0209381
Spill Tank Test:	1527820
Site ID:	155841
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported

34-24 11TH ST (Continued) **S105997582**

Source:	Not reported
Test Method:	14
Test Method 2:	VacuTest
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	155841
Operable Unit ID:	860747
Operable Unit:	01
Material ID:	516355
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BD353 **SEE FACTOR INDUSTRY** **NY LTANKS** **S103238355**
SE **37-11 30TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.373 mi.
1971 ft. **Site 1 of 2 in cluster BD**

Relative: **Higher**
Actual: **40 ft.**

LTANKS:

Name:	SEE FACTOR INDUSTRY
Address:	37-11 30TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9801491 / 2004-09-15
Facility ID:	9801491
Site ID:	208588
Spill Date:	1998-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	1998-05-05
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-05-05
Spill Record Last Update:	2004-09-15
Spiller Name:	COASTAL COMBUSTION

SEE FACTOR INDUSTRY (Continued) **S103238355**

Spiller Company:	SEE FACTOR INDUSTRY
Spiller Address:	37-11 30TH ST
Spiller County:	001
Spiller Contact:	COASTAL COMBUSTION
Spiller Phone:	(800) 734-4328
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	173083
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 8/18/2004 Sangesland spoke to Manny Caruana, Building Supervisor at See Factor Industry Inc. to discuss the specifics of what the DEC needs to close out this spill 9/13/2004 Sangesland spoke again with Manny Caruana and asked him to send in the soil borings he has along with the tank closure documents. 9/15/2004 Mr. Caruana hand delivered a package of documents to the DEC office. Included was a summary letter outlining the testing and closure of the tank. After the tank failed the tank test in 1998, it was not retested, however Mr. Caruana says he inspected the interior of the tank and said it was still secure. He states that the initial test was faulty because of a dry leak on the vent line. In 2000 the tank was abandoned by USA tanks and an abandonment certification was forwarded to the NYC Fire Dept. The building now operates on natural gas. In Feb 2000 several soil borings were taken on the site (3 in the tank area) as part of a structural investigation for a possible building expansion. Three of these borings were approx. 10 ft from the abandoned tank and went down to 20 ft depth. There was no evidence of any soil contamination. Based on this information, the DEC believes that there was no actual petroleum spill at this site and this case has been closed out effective 9/15/2004. "
Remarks:	""

All TTF:

Facility ID:	9801491
Spill Number:	9801491
Spill Tank Test:	1545865
Site ID:	208588
Tank Number:	001
Tank Size:	5000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BD354 **37-11 30TH STREET** **NY BROWNFIELDS** **S121933807**
SE **37-11 30TH STREET AND 30-14 37TH AVENUE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.373 mi.
1971 ft. **Site 2 of 2 in cluster BD**

Relative:
Higher

Actual:
40 ft.

BROWNFIELDS:

Name:	37-11 30TH STREET
Address:	37-11 30TH STREET AND 30-14 37TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	567680
Acres:	0.616
HW Code:	C241211
SWIS:	4101
Town:	New York City
Record Added Date:	03/07/2018
Record Updated Date:	01/13/2021
Update By:	AMSERVIS
Site Description:	"Location: The site is located in an urban area at 37-11 30th Street and 30-14 37th Avenue in the Long Island City neighborhood of Queens and is identified on the Queens Borough Tax Map as Block 372, Lot 107 and Lot 121. The 26,853 square-foot (0.616-acre) site is situated on the northwest corner of the block bound by 37th Avenue to the north, 31st Street to the east, 38th Avenue to the south, and 30th Street to the west. The elevated N and Q subway tracks run north-south above 31st Street, which are about 100 feet east of the site. Site Features: The site was developed with a two-story residential building on Lot 21 (30-14 37th Avenue) and a one-story and partial three-story warehouse building with multiple partial cellar levels and a stockyard/storage area in the northern portion of Lot 8 (37-11 30th Street). All on-site buildings were demolished. Current Zoning and Land Use: The site is located within the Long Island City Special Mixed Use Paired District (M1-2/R6A). This paired district promotes development and expansion of the longstanding mix of residential, commercial, industrial, and cultural use throughout the area. M1 districts typically include retail and light industrial uses such as woodworking shops, repair shops, and wholesale service and storage facilities, and R6A districts promote residential development. Zoning is consistent with the proposed mixed-use development. The surrounding area is primarily commercial and industrial, but also includes residential buildings, public facilities, day care centers, and schools. As a result of the CEQR process, Block 372, Lot 21 was assigned an E-Designation (E-218) on October 7, 2008 by the NYCDCP as part of the Dutch Kills Rezoning (CEQR No. 08DCP021Q). The E-Designation requires coordination with NYC OER to obtain a building permit. Past Use of the Site: The site was an undeveloped vacant lot until at least 1915. The existing warehouse building at Lot 8 was constructed around 1920 and historically operated as a plastics manufacturer (The Marblette Corp. Mfg. of Plastic Materials) from at least 1930 to about 1980. Following 1980, the site operated as a warehouse for audio and lighting equipment. Lot 21 was developed with a two-story residential dwelling as early as 1898. From the 1930s through the 1980s, Marblette Corp. manufactured plastics, which primarily included production of synthetic resins. During this time, plastic was typically made using a mixture of synthetic chemicals, solvents, and petroleum products. An abandoned water supply well was observed in the northwest portion of the site during the June/July 2014 Limited Subsurface Investigation by Merritt Environmental

37-11 30TH STREET (Continued) **S121933807**

Consulting Corp. The water supply well was reportedly abandoned prior to 1980 when the site transitioned from plastics manufacturing to warehousing. Site Geology and Hydrogeology: The site consists of a historic fill layer beneath concrete-paved surfaces that is predominately brown, medium-grained sand with varying amounts of gravel, silt, brick, coal, metal, clay, slag, glass, ceramics and concrete to depths ranging from 2 to 8.5 feet below ground surface (bgs). Fill material is underlain by a native brown fine- to coarse-grained sand layer observed to depths of about 32 to 69 feet bgs, with occasional layers of silt. In one deep boring advanced to 70 feet bgs, the sand layer is underlain by an olive clay layer, which was observed to depths of about 59 to 70 feet bgs. In a second deep boring advanced in the northern portion of the site, weathered rock fragments, potentially indicative of weathered bedrock or glacial till, were observed between 69 and 72 feet bgs. Bedrock was not encountered in any of the soil borings. Depth to groundwater was measured between about 22.76 to 27.77 feet bgs. The groundwater elevation is highest in the northern region of the site and flows south toward Sunnyside Yards and Newtown Creek. "

Env Problem:

"Nature and Extent of Contamination: Remediation at the site is complete. Prior to remediation, the primary contaminants of concern include benzo(a)anthracene, benzo(a)pyrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, chromium, lead, tetrachloroethene (PCE) and trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for unrestricted use. Residual contamination in the groundwater is being managed under a Site Management Plan. Prior to Completion of Remediation: Soil and groundwater were analyzed for Target Compound List (TCL) volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), Target Analyte List (TAL) metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater was also analyzed for Per- and Polyfluoroalkyl Substances (PFAS) and 1,4-dioxane. Based upon investigations conducted to date, the primary contaminants of concern include benzo(a)anthracene, benzo(a)ayrene, benzo(b)fluoranthene, benzo(k)fluoranthene, chrysene, chromium, lead, tetrachloroethene (PCE) and trichloroethene (TCE). Soil - SVOCs present at the site include benzo(a)anthracene, which is found at a concentration up to 6.1 parts per million, or ppm (as compared to the unrestricted use soil cleanup objective, or UUSCO of 1 ppm), benzo(a)pyrene at a concentration up to 4.5 ppm (UUSCO is 1 ppm), benzo(a)fluoranthene at a concentration up to 6.2 ppm (UUSCO is 1 ppm), and chrysene at a concentration up to 5.2 ppm (UUSCO is 1 ppm). Metals including chromium were detected in the central eastern portion of the site above their hazardous waste threshold in an 18-foot by 15-foot area of shallow fill up to 8 feet. Hexavalent chromium is present at a concentration up to 1,080 ppm, which exceeds the UUSCO of 1 ppm. Lead is found at a concentration up to 8,750 ppm (UUSCO is 63 ppm). Data does not indicate any off-site impacts in soil related to this site. Groundwater - Total chromium is found at a concentration up to 1,146 parts per billion (ppb) which exceeds the Ambient Water Quality Standard (AWQS) of 50 ppb; hexavalent chromium is found at a concentration up to 654 ppb (groundwater standard is 50 ppb); perfluorooctanoic acid (PFOA) is found at a concentration up to 34.8 parts per trillion (ppt) and perfluorooctanesulfonic acid (PFOS) is found at a concentration up to 11.3 ppt. Data does not indicate any off-site impacts in groundwater related to this site. Sub-slab, Soil Vapor and Indoor Air - In sub-slab soil vapor, TCE is found at a

37-11 30TH STREET (Continued) **S121933807**

	concentration up to 22.3 micrograms per cubic meter (g/m3), PCE is found at a concentration up to 12,000 g/m3. In indoor air, TCE is found at a concentration up to 0.296 g/m3 and PCE is found at a concentration up to 6.66 g/m3. In soil vapor, TCE was not detected, PCE is found at a concentration up to 26.9 g/m3. Data does not indicate any off-site impacts in soil vapor related to this site. "
Health Problem:	"Remedial actions are complete and measures are in place to prevent people from coming in contact with any residual contamination at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2018-05-31 08:42:00
Record Upd:	2020-12-30 11:51:00
Updated By:	SMQUANDT
Own Op:	1
Sub Type:	NNN
Owner Name:	david schwartz
Owner Company:	37-11 30th Street Holdings LLC
Owner Address:	38 east 29th street, 9th floor
Owner Addr2:	Not reported
Owner City,St,Zip:	new york, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Library at Long Island City
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Queens, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	David Schwartz
Owner Company:	37-11 30th Street Holdings LLC
Owner Address:	38 East 29th Street, 9th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Queens, NY 11106
Owner Country:	United States of America
HW Code:	C241211
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

37-11 30TH STREET (Continued) **S121933807**

HW Code:	C241211
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241211
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2-094242
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2020-12-10 13:10:00
Record Updated:	2020-12-10 13:10:00
Updated By:	LXZIELIN
Crossref ID:	C241211-05-18
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-01 15:35:00
Record Updated:	2020-10-01 15:35:00
Updated By:	HRAHMED

BE355 **EMPIRE VENTALATION** **NY LTANKS** **1001751418**
NNW **35-39 VERNON BLVD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.375 mi.
1978 ft. **Site 1 of 2 in cluster BE**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	EMPIRE VENTALATION
Address:	35-39 VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9516793 / 1996-03-28
Facility ID:	9516793
Site ID:	235467
Spill Date:	1996-03-28
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4

EMPIRE VENTALATION (Continued) **1001751418**

Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SMMARTIN
Referred To:	Not reported
Reported to Dept:	1996-03-28
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-03-28
Spill Record Last Update:	1996-04-03
Spiller Name:	Not reported
Spiller Company:	PETRO IN ASTORIA
Spiller Address:	3616 19TH AVENUE
Spiller County:	001
Spiller Contact:	NO
Spiller Phone:	(718) 728-2143
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	193949
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT "
Remarks:	"about 2 gal over fill cleanup crew is cleaning up now"

All Materials:

Site ID:	235467
Operable Unit ID:	1027699
Operable Unit:	01
Material ID:	353306
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Resource Affected:	Soil
Oxygenate:	Not reported

BE356 **CONSTRUCTION SITE** **NY LTANKS** **S106869298**
NNW **35-38 JUNCTION BLVD** **N/A**
1/4-1/2 **QUEENS, NY**
0.375 mi.
1978 ft. **Site 2 of 2 in cluster BE**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	CONSTRUCTION SITE
Address:	35-38 JUNCTION BLVD
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0501160 / 2005-05-27
Facility ID:	0501160
Site ID:	344316
Spill Date:	2005-04-28

CONSTRUCTION SITE (Continued) **S106869298**

Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	KMFOLEY
Referred To:	Not reported
Reported to Dept:	2005-04-28
CID:	444
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-04-28
Spill Record Last Update:	2006-06-20
Spiller Name:	KIRK BOYD
Spiller Company:	CONSTRUCTION SITE
Spiller Address:	35-38 JUNCTION BLVD
Spiller County:	001
Spiller Contact:	KIRK BOYD
Spiller Phone:	(347) 613-6537
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	290994
DEC Memo:	"Sangesland tried calling the Contact number for Mr Boyd - Not working Sangesland spoke to Afrosa Amin at NYC DEP Hazmat - She said DEP did NOT go to the site, only received a phone call about the spill. According to Property Shark, the property is owned by: Kentucky Fried Chicken - KFC National, 1441 Gardiner Lane, Louisville KY 40232 Site was a Kentucky Fried Chicken Store and has now been leveled and is under new construction. KFC Contact is: Debbie Hardin 502-874-8027 Contaminated Soil Letter sent to Ms. Hardin at KFC 4/29/05 Transferred from Rahman to Foley. Spoke to Rich Parrish, Impact Environmental. Current owner was doing work and found old tanks. Has not been a gas station in over 25 years. Impact pulled tanks and excavation caused rats to evacuate the KFC. NYCDOH was on site. Impact will be doing site assessment for Hank Alpert, owner of the former gas station. 5/27/05 Received UST site assessment from Impact Environmental for Sheldon Rodbell Trust #2, 3333 New Hyde Park, NY. Site is to be redeveloped with a five story residential building, with a basement at 17'bgs. On 4/28/05, during excavation, two five hundred and fifty gallon steel USTs were discovered. Both tanks were encased in concrete and contained gasoline/water solution. The tanks were cleaned and removed. Contamination was discovered in underlying soil. Soil excavation was started on 5/4/05 and continued until clean soil was identified by PID. On 5/5/05 and 5/6/05, remanants of a remote fill line were identified from the tanks to the edge of the property. At the conclusion of excavation on 5/9/05, field screening activities of the base and side walls indicated no residual contamination existed on site. Kept digging 10' beyond where the PID indicated it was clean, and then took endpoints. The areas where the pump islands were was also screened and excavated. Soil in these areas exhibited no signs of contamination. 20 soil samples were obtained below and around the tanks, the lines and the associated

CONSTRUCTION SITE (Continued) **S106869298**

pump islands. All soil samples returned non-detect for VOCs and SVOCs. DTW approx 60'bgs. Issued NFA."

Remarks: "CALLER STATES THAT AT THIS LOCATION , THEY WERE PULLING TANK AND OIL GUSHED OUT INTO GROUND:"

All Materials:

Site ID:	344316
Operable Unit ID:	1102963
Operable Unit:	01
Material ID:	583179
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BB357 **QUEENSBRIDGE PLANT B** **NY LTANKS** **S100146537**
SW **41001 12TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.377 mi.
1990 ft. **Site 2 of 2 in cluster BB**

Relative: **Lower**
Actual: **16 ft.**

LTANKS:

Name:	QUEENSBRIDGE PLANT B
Address:	41001 12TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	9009185 / 1995-08-16
Facility ID:	9009185
Site ID:	178671
Spill Date:	1990-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-08-16
SWIS:	4101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1990-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-10
Spill Record Last Update:	1995-08-16
Spiller Name:	Not reported
Spiller Company:	NYCHA
Spiller Address:	250 BROADWAY
Spiller County:	001
Spiller Contact:	Not reported

QUEENSBRIDGE PLANT B (Continued) **S100146537**

Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 150020
DEC Memo: ""
Remarks: "(2) 15K MANIFOLDED TANKS FAILED HORNER EZY CHECK, VISUAL GROSS LEAK, LEAK FOUND AT HEATER FLANGE AT TANK TOP, WILL REPAIR & RETEST. UPDATE: TANKS REMOVED 1994."

All TTF:
Facility ID: 9009185
Spill Number: 9009185
Spill Tank Test: 1537914
Site ID: 178671
Tank Number: 001
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

Facility ID: 9009185
Spill Number: 9009185
Spill Tank Test: 1537915
Site ID: 178671
Tank Number: 002
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 178671
Operable Unit ID: 949682
Operable Unit: 01
Material ID: 432952
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: Not reported

QUEENSBRIDGE PLANT B (Continued) **S100146537**

Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

Name: QUEENSBRIDGE PLANT B
Address: 41001 12TH STREET
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9305924 / 1995-08-16
Facility ID: 9305924
Site ID: 178672
Spill Date: 1993-08-12
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1995-08-16
SWIS: 4101
Investigator: HEALY
Referred To: Not reported
Reported to Dept: 1993-08-13
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-08-16
Spill Record Last Update: 1995-08-16
Spiller Name: Not reported
Spiller Company: NYC HOUSING AUTHORITY
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 284651
DEC Memo: ""
Remarks: "TO REPAIR RETEST. UPDATE: TANK REMOVED 1994"

All TTF:
Facility ID: 9305924
Spill Number: 9305924
Spill Tank Test: 1541876
Site ID: 178672
Tank Number: 001
Tank Size: 0
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported

QUEENSBRIDGE PLANT B (Continued) **S100146537**

Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9305924
Spill Number:	9305924
Spill Tank Test:	1541877
Site ID:	178672
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	178672
Operable Unit ID:	987382
Operable Unit:	01
Material ID:	395823
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BF358 **LOVOUR HOME** **NY LTANKS** **S108639404**
South **2512 41ST AVE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.399 mi.
2105 ft. **Site 1 of 2 in cluster BF**

Relative: **Higher**

Actual: **35 ft.**

LTANKS:

Name:	LOVOUR HOME
Address:	2512 41ST AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0700688 / 2010-02-17
Facility ID:	0700688
Site ID:	380071
Spill Date:	2007-04-18
Spill Cause:	Tank Test Failure
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	bkfalvey

LOVOUR HOME (Continued) **S108639404**

Referred To:	Not reported
Reported to Dept:	2007-04-18
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2007-04-18
Spill Record Last Update:	2010-02-17
Spiller Name:	ERIC LOVOUR
Spiller Company:	LOVOUR HOME
Spiller Address:	2512 41ST AVE
Spiller County:	001
Spiller Contact:	ERIC LOVOUR
Spiller Phone:	(718) 392-2123
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	329555
DEC Memo:	"4/25/07 bf: sent ttf letter to: Eric Levor Queens Plaza Realty Corp. 25-12 41 Avenue Long Island City, NY 11101-3882 5/25/07 received passing tightness test results by fax from Eric Lovor. Tried calling him at number on fax:(718)392-2123. No answer. To close this spill, he needs to submit a response to ttf letter. bf 5/29/07 Called E. Levor again and there was no answer. Called Emergency Contact # from PBS facility info (718)263-2418 and left message to call me back. bf 6/4/07 Called E. Levor at (718)392-2123. The number is no longer in service. I then left a message at (718)263-2418. bf 6/5/07 Received 2 messages from Edith Levor to call back. (718)392-2123. Called her at 3:45 Pm and she said that the tank failed the test because there were two sets of vent pipes. The old vent pipe was never disconnected. She said she will call Advanced Tank after she hangs up with me and have them prepare a response to the ttf letter. bf 11/8/07 Called E. Levor. Left message that i still have not received letter from Advanced Tank and to call me back. Called Vinnie the Tank Doctor (718)727-0666. He said that there was an open line from a hot water heater and he plugged the line. No contaminated soil was found. He faxed paperwork to E. Levor. He was not in his office and requested I call him Monday. He will check to see if he still has the fax. bf 11/26/07 Received message from E. Levor. Called her back and left message on her machine. bf 1/22/10 Inspected site and issued NOV for expired registration, failure to monitor unmetered tank for leaks, and failure to contain/reomve petroleum discharge. Administrative settlement conference is scheduled for 2/17/10 at 10:30 AM. bf 2/17/10 PBS Settlement Conference held today. Attended by Edith and Eric levor. Provided 6/7/07 letter from Tank Doctor Inc. stating that 2 unused lines from top of tank were disconnected in building. Removed lines and tank retested and passed. NFA. bf "
Remarks:	"PBS No: 2-607688"

All TTF:

Facility ID:	0700688
Spill Number:	0700688
Spill Tank Test:	1550766
Site ID:	380071
Tank Number:	1

LOVOUR HOME (Continued) **S108639404**

Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	380071
Operable Unit ID:	1137562
Operable Unit:	01
Material ID:	2127510
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BG359 **BRIDGE CLEANERS - OFF-SITE** **NY BROWNFIELDS** **S128906165**
SSE **39-26 30TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.400 mi.
2113 ft. **Site 1 of 6 in cluster BG**

Relative:
Higher

Actual:
30 ft.

BROWNFIELDS:

Name:	BRIDGE CLEANERS - OFF-SITE
Address:	39-26 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	480014
Acres:	Not reported
HW Code:	C241127A
SWIS:	4101
Town:	New York City
Record Added Date:	03/21/2013
Record Updated Date:	05/31/2017
Update By:	BXANDERS
Site Description:	"LOCATION: This is an off-site investigation of the area downgradient of the Bridge Cleaners site, Site Number C241127, which located at 39-26 30th Street in Long Island City, an urban area. SITE FEATURES: The investigation area encompasses sidewalks along 29th Street from 39th Ave to 40th Road, along 30th Street from 39th Avenue to approximately 40th Ave, and along 40th Ave to 31st Street. CURRENT ZONING: This section of Long Island City is zoned Special Purpose District which allows mixed residential and commercial use. The specific designation for the site is M1-3/R7X. Buildings within the

BRIDGE CLEANERS - OFF-SITE (Continued) **S128906165**

city block are primarily commercial. There are residential units including a three story apt building along 29th Street. The downgradient block also contains a limited number of residential buildings.Recent construction in the area includes a self-storage facility and hotels. HISTORICAL USES: This area of Long Island City has historically included mixed residential and light manufacturing. Formerly the area included a printing operation, commercial laundry and drycleaner, wire die manufacturer, gas station, and distribution points for a variety of products. SITE HYDROLOGY/GEOLOGY: Groundwater elevation levels vary from 11.04 AMSL to 10.01 AMSL, which is about 20 feet below land surface in the vicinity of the site. Soils in the area are expected to be primarily sand and silty sand. C241127A projects for the off-site portion of this site are being tracked under site 241127 OU2."

Env Problem:

"NATURE AND EXTENT OF CONTAMINATION: In October 2010, a property location in this block was identified as a potential site (P-site) due to soil vapor and groundwater results collected by an adjacent property owner. After unsuccessfully attempting to obtain access for a more thorough investigation, NYSDEC conducted a limited offsite investigation in February 2012. Groundwater and soil samples were taken. Based on this investigation, the Bridge Cleaners Site (C241127) was determined to be causing a significant threat to public health and the environment. The site entered the NYS Brownfield Cleanup Program and remained in the Program until December 2016. Groundwater: Groundwater elevations show groundwater flow from northeast to southwest. Concentrations of tetrachloroethylene (PCE) and trichloroethylene (TCE) upgradient of the site were approximately 21 ppb and 1 ppb respectively. Downgradient concentrations were 440 ppb and 32 ppb respectively. The groundwater standard for both PCE and TCE is 5 ppb. Soil: One of 14 soil samples, at a side gradient monitoring well MW-4, contained PCE at 3.3 ppm. The depth of this contamination was 29-30 feet below grade. Scope of Off-Site Investigation 2016: This 2016 Remedial Investigation will define the nature and extent of contamination emanating from the Bridge Cleaners Site in groundwater, soil vapor and any other parts of the environment that may be affected. Shallow and deep groundwater wells will be installed upgradient and downgradient of the Bridge Cleaners site (C241127). After well installation, two sets of samples will be collected. Based on the initial sampling, groundwater samples will be collected for Compound Specific Isotope Analysis (CSIA). This analysis will be used to determine whether the source of the Tetrachloroethene (PCE) and Trichloroethene (TCE) groundwater contamination is exclusively from the Bridge Cleaners site or from other sources in the immediate area. Eleven soil vapor samples will also be collected initially. After the results are obtained, the Department may request access from owners of eight structures along 29th Street for sub-slab and indoor air sampling. OU2 Off-Site Investigation Results Soil: Groundwater: Eight groundwater wells were installed in addition to seven pre-existing sidewalk wells. Two rounds of sampling were completed. PCE was present at a maximum value of 389 ppb in MW-3. TCE was present at a maximum of 181 ppb in MW-3. Historically, MW-3 also contained the highest amount of PCE (440 ppb) during the 2012 site characterization. The groundwater standard for both PCE and TCE is 5 ppb. PCE and TCE were not observed in the 4 deep wells installed. Soil Vapor: Eleven soil vapor points were installed in the investigation area. The highest soil gas result at SV-104 was 4400 ug/m3 TCE and 2400 ug/m3 PCE on the south side of

BRIDGE CLEANERS - OFF-SITE (Continued) **S128906165**

	40th Ave, across from MW-6. During the second set of sampling, the highest levels were also located at SV104, though the levels decreased to 1300 ug/m3 TCE and 590 ug/m3 PCE. Sub-slab and indoor air samples were completed in 4 structures. The highest sub-slab level was 9500 ug/m3 PCE and 7.2 ug/m3 in the indoor air. This structure was designated as Mitigate. One other was also designated as mitigate. C241127A projects for the off-site portion of this site are being tracked under site 241127 OU2."
Health Problem:	"People may come into contact with contaminated groundwater or soil if they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that actions are needed to address potential exposures to site related contaminants via soil vapor intrusion both on and off-site. "
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Community Board 1- Queens
Owner Address:	45-02 Ditmars Ave, Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library - Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported

BRIDGE CLEANERS - OFF-SITE (Continued) **S128906165**

Updated By: Not reported

BG360 **BRIDGE CLEANERS** **NY BROWNFIELDS** **S128906157**
SSE **39-26 30TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.400 mi.
2113 ft. **Site 2 of 6 in cluster BG**

Relative: **Higher**
Actual: **30 ft.**

BROWNFIELDS:

Name:	BRIDGE CLEANERS
Address:	39-26 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	464609
Acres:	0.173
HW Code:	C241127
SWIS:	4101
Town:	New York City
Record Added Date:	05/25/2012
Record Updated Date:	03/01/2018
Update By:	MJKOMORO
Site Description:	"Location: The Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features: A 7500 square foot one-story slab-on-grade building occupies the entire lot. Adjacent buildings to the north and west appear to contain residential units. To the south is a paved driveway used by the neighboring commercial structure. To the east is 30th street. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. Prior to that, the building was used as a distribution point for electrical components, bottled water and a courier service. Site Hydrology/Geology: The depth to groundwater near the site is about 18-22 feet. Soils in the area are primarily fine to medium sand with some traces of silt. One location indicated a clay layer at 6 to 9 feet below grade."
Env Problem:	"NATURE AND EXTENT OF CONTAMINATION: Samples collected in 2009 on the property adjacent to the Bridge Cleaners site identified dry-cleaning related compounds trichloroethene (TCE)and tetrachloroethene (PCE) in the soil vapor and groundwater. There was no evidence of PCE use on the adjacent property. The higher results were closer to the common property line. PCE was found at 910 ppb in groundwater along the common property boundary, decreasing to 120 ppb approximately 100 feet away. PCE was measured at 16,900 ug/m3 in the soil vapor. The groundwater standard for both PCE and TCE is 5 ppb. In April 2011, the site operator obtained 2 soil samples from beneath the Bridge Cleaners slab and found tetrachloroethene (PCE) at 3.45 ppm and 0.757 ppm. The unrestricted soil cleanup objective is 1.3ppm for PCE. In September 2011, the owner independently obtained samples of soils and groundwater under the building,and provided results to DEC in November 2011. The three groundwater results under the building were 537 ppb, 841 ppb and 1470 ppb PCE. Fifteen soil samples were below the unrestricted soil cleanup objectives for PCE. Groundwater samples also contained TCE in the 11-12.5 ppb range. After unsuccessfully attempting to obtain site access for a more thorough investigation, NYSDEC conducted an offsite investigation in February 2012.

BRIDGE CLEANERS (Continued) **S128906157**

Groundwater elevations show groundwater flow from northeast to southwest. Concentrations of PCE and TCE upgradient of the site were approximately 21 ppb and 1 ppb respectively. Downgradient concentrations were 440 ppb and 32 ppb respectively. One of 14 soil samples, at side gradient monitoring well MW-4, contained PCE at 3.3 ppm. The depth of this contamination was 29-30 feet below grade, and below the water table at 25.5 feet. In the first quarter of 2014, after entering the Brownfield Program, additional groundwater, soil and soil vapor samples were obtained from within the building. Five groundwater samples ranged from 165 to 340 ppb for PCE, and TCE concentrations from 2-7 ppb. Soil samples obtained from the same 5 locations did not exceed unrestricted soil cleanup objectives. Sub-slab soil vapor, however, ranged from approximately 20,000 ug/m3 to 668,000 ug/m3 below the slab (PCE) and up to 2140 ug/m3 TCE. PCE in indoor air was 270 ug/m3. Based on the soil vapor results, there is a need to mitigate the building. In Nov 2014, a new consultant was hired by the BCP applicant. Soil in the NW corner of the building was found at 1.8-9.6 ppm (exceeding the protection of groundwater SCOs) for PCE (1.3ppm). An IRM design has been developed to address the source area. "

Health Problem:	"People may come into contact with contaminated groundwater or soil if they dig below the surface. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air or buildings, is referred to as soil vapor intrusion. Environmental sampling indicates that actions are needed to address potential exposures to site related contaminants via soil vapor intrusion both on and off-site."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	P03
Owner Name:	Qi Hong Lin
Owner Company:	Zhong Chuang Properties LLC
Owner Address:	37-24 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Library
Owner Address:	37-44 21 Street

BRIDGE CLEANERS (Continued) **S128906157**

Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	c/o Periconi LLC
Owner Company:	Zhong Chuang Properties LLC
Owner Address:	260 Madison Avenue, 17th Fl.
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10016
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BG361 **FRESH CLEANERS & LAUNDRY INC** **RCRA-SQG** **1001125032**
SSE **39-26 30TH ST** **NY SHWS** **NYR000034363**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY ENG CONTROLS**
0.400 mi. **NY INST CONTROL**
2113 ft. **Site 3 of 6 in cluster BG**

Relative: **Higher**
Actual: **30 ft.**

RCRA Listings:

Date Form Received by Agency:	20070430
Handler Name:	Fresh Cleaners & Laundry Inc
Handler Address:	39-26 30TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000034363
Contact Name:	MOON S PARK
Contact Address:	30TH ST
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-786-9734
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	30TH ST
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichlorethylene
Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane,

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: FRESH CLEANERS & LAUNDRY INC	
Legal Status:	Private
Date Became Current:	20070316
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: MOON S PARK	
Legal Status:	Private
Date Became Current:	20070316
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: BRIDGE CLEANERS CORP	
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	39-26 30TH ST
Owner/Operator City,State,Zip:	QUEENS, NY 11101
Owner/Operator Telephone:	718-706-1077
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20060101
Handler Name: BRIDGE CLEANERS	
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Ny
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Electronic Manifest Broker: Not reported

Receive Date: 20070430
Handler Name: FRESH CLEANERS & LAUNDRY INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19970113
Handler Name: BRIDGE CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070501
Handler Name: FRESH CLEANERS & LAUNDRY INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 81232
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20060427
Actual Return to Compliance Date: 20070702
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20121116

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Enforcement Responsible Agency: EPA
Enforcement Docket Number: 02-2007-7109
Enforcement Attorney: R2CH
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: FINAL 3008(A) COMPLIANCE ORDER
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: 35098
Paid Amount: Not reported
Final Count: 1
Final Amount: 35098

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 20060427
Actual Return to Compliance Date: 20070702
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20060518
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2RV
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - General
Date Violation was Determined:	20060427
Actual Return to Compliance Date:	20070702
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20070329
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	02-2007-7109
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20111001
Disposition Status:	DR
Disposition Status Description:	DROPPED
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	INITIAL 3008(A) COMPLIANCE
Enforcement Responsible Person:	R2RV
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	35098
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	20060427
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20070702
Scheduled Compliance Date:	Not reported
Date of Request:	20060518

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060529
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20060427
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20070702
Scheduled Compliance Date:	Not reported
Date of Request:	20060518
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20140331
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20070702
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20110818

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20111001
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	NOT A SIGNIFICANT NON-COMPLIER
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20060427
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2RV
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20070702
Scheduled Compliance Date:	Not reported
Date of Request:	20060518
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20020828
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CFP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

SHWS:

Name:	BRIDGE CLEANERS
Address:	39-26 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Site Code: 440982
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 0.173
HW Code: 241127
Record Add: 10/15/2010
Record Upd: 03/28/2022
Updated By: GWBURKE
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "
Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

(SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3,

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner Company:	Bridge Cleaners
Owner Address:	39-26 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY
Owner Country:	United States of America
Own Op:	4
Sub Type:	05
Owner Name:	Lillian Shi
Owner Company:	Spring Cutting Inc.
Owner Address:	318 W 39th St Fl 11
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris, District Manager
Owner Company:	Community Board 1 - Queens
Owner Address:	45-02 Ditmars Blvd, Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria,, NY 11105
Owner Country:	United States of America
HW Code:	241127
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241127
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2019031200379001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-01 10:48:00
Record Updated:	2019-07-01 10:48:00
Updated By:	RECURLEY

ENG CONTROLS:

Name:	BRIDGE CLEANERS
Address:	39-26 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	440982
HW Code:	241127
Control Code:	15
Control Type:	ENG
Date Record Added:	09/17/2018
Date Rec Updated:	04/18/2022
Updated By:	RECURLEY
Site Description:	"Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-03-15 13:30:00
Record Upd:	2018-03-14 10:47:00
Updated By:	RECURLEY
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library
Owner Address:	Long Island CIty Branch
Owner Addr2:	37-44 21st Street
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	c/o Lillian Shi, Spring Cutting Inc.
Owner Company:	Zhong Chaung Properties LLC
Owner Address:	318 W. 39th St Fl 11
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	4
Sub Type:	03
Owner Name:	Bridge Cleaners
Owner Company:	Bridge Cleaners
Owner Address:	39-26 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY
Owner Country:	United States of America
Own Op:	4
Sub Type:	05
Owner Name:	Lillian Shi
Owner Company:	Spring Cutting Inc.
Owner Address:	318 W 39th St Fl 11
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris, District Manager
Owner Company:	Community Board 1 - Queens
Owner Address:	45-02 Ditmars Blvd, Suite 1025
Owner Addr2:	Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner City,St,Zip:	Astoria,, NY 11105
Owner Country:	United States of America
HW Code:	241127
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241127
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2019031200379001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-01 10:48:00
Record Updated:	2019-07-01 10:48:00
Updated By:	RECURLEY

Name:	BRIDGE CLEANERS
Address:	39-26 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	440982
HW Code:	241127
Control Code:	35
Control Type:	ENG
Date Record Added:	09/17/2018
Date Rec Updated:	04/18/2022
Updated By:	RECURLEY
Site Description:	"Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Library
Owner Address:	Long Island CIty Branch
Owner Addr2:	37-44 21st Street
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	c/o Lillian Shi, Spring Cutting Inc.
Owner Company:	Zhong Chaung Properties LLC
Owner Address:	318 W. 39th St Fl 11
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	4
Sub Type:	03
Owner Name:	Bridge Cleaners
Owner Company:	Bridge Cleaners
Owner Address:	39-26 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY
Owner Country:	United States of America
Own Op:	4
Sub Type:	05
Owner Name:	Lillian Shi
Owner Company:	Spring Cutting Inc.
Owner Address:	318 W 39th St Fl 11
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10018
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris, District Manager
Owner Company:	Community Board 1 - Queens
Owner Address:	45-02 Ditmars Blvd, Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria,, NY 11105
Owner Country:	United States of America
HW Code:	241127
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241127
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	2019031200379001
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-01 10:48:00
Record Updated:	2019-07-01 10:48:00
Updated By:	RECURLEY

INST CONTROL:

Name:	BRIDGE CLEANERS
Address:	39-26 30TH STREET

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: Monitoring Plan
HW Code: 241127
Control Code: 31
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "
Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor,

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens
Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00
Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

Name: BRIDGE CLEANERS
Address: 39-26 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: IC/EC Plan
HW Code: 241127
Control Code: 34
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00
Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

Name: BRIDGE CLEANERS
Address: 39-26 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: O&M Plan
HW Code: 241127
Control Code: 33
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens
Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00
Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Name: BRIDGE CLEANERS
Address: 39-26 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: Environmental Easement
HW Code: 241127
Control Code: J
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "
Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens
Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00
Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

Name: BRIDGE CLEANERS
Address: 39-26 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: Ground Water Use Restriction
HW Code: 241127
Control Code: 08
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens
Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00
Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

Name: BRIDGE CLEANERS
Address: 39-26 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 440982
Control Name: Site Management Plan
HW Code: 241127
Control Code: 32
Control Type: INST
Dt record added: 09/17/2018
Dt rec updated: 04/18/2022
Updated By: RECURLEY
Site Code: 440982
Site Description: "Location: The 0.173-acre Bridge Cleaners site is located at 39-26 30th Street in Long Island City, an urban area. Site Features : A 7500 square foot (sf) one-story slab-on-grade building occupies the entire lot. It is used for storage and is infrequently occupied. Adjacent buildings to the north and west appear to contain residential units. To the south and east across 30th Street are recently constructed multi-story residential structures. Current Zoning and Land Use: The site is zoned M1-3/R7X (Manufacturing and Residential) under the special Long Island City Mixed Use District. The surrounding area is a mix of residential and commercial uses. The site is currently being used for fabric storage and fabric cutting. Past use of the Site: The site was occupied by a commercial laundry and dry cleaner until 2011. Records indicate at least 10 years of use as a commercial dry-cleaner. The site was a small quantity generator of solvent wastes under the Resource Conservation and Recovery Action (RCRA) hazardous waste program from 1997-2010. Prior to that, the building was used as a distribution point for electrical components, bottled water and as a courier service. Operable Units: The site was divided into two operable units (OUs). An operable unit represents a portion of a remedial program for a site that, for technical or administrative reasons, can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. OU1 is the on-site area, consisting of a 7500 sf lot completely covered by a one-story

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

cement block building. OU2 is the off-site area. The off-site investigation area includes the sidewalks from 39th Avenue to 40th Road, between 29th Street and 30th Street. Site Hydrology/Geology: The depth to groundwater beneath and in the vicinity of the site is about 18-22 feet below grade (ftbg). Soils in the area are primarily fine to medium sand with some traces of silt. One boring location indicated a clay layer at 6 to 9 ftbg. In the larger OU2 investigation area, groundwater ranged from 11 to 30 ftbg, with deeper groundwater closer to 29th Street, and shallower groundwater southeast of 30th Street. In one location, in the southeast corner of the investigation area, a clay layer was noted from 32 to 38 feet below grade. Groundwater flow is generally to the south/southwest. Operable Unit (OU) Numbers 01 and 02 are the subject of this document. "

Env Problem: "OU1: On-Site Remediation at OU1 has resulted in the site being protective of public health and the environment. Prior to remediation, the primary contaminant of concern was PCE in soil, soil vapor and groundwater. TCE was present in soil vapor only. Residual contamination is being addressed through active treatment. Residual contamination in the soil, groundwater and soil vapor is being managed under an Interim Site Management Plan. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below. During the RI, prior to the IRM, soil and groundwater were analyzed for VOCs, semi-volatile organic compounds (SVOC), Metals, and PCBs/Pesticides. Soil Vapor was analyzed for VOCs. The maximum concentration of PCE in soil at the site was 9.6 parts per million (ppm), compared to the protection of groundwater soil cleanup objective of 1.3 ppm. Five groundwater wells on site contained a maximum concentration of 340 parts per billion (ppb) PCE and 6.9 ppb TCE in groundwater, compared to the AWQS of 5 ppb for both PCE and TCE. Sub-slab soil vapor ranged up to 668,000 micrograms per cubic meter (ug/m3) PCE, 2140 ug/m3 TCE. PCE in indoor air was detected at 270 micrograms per cubic meter (g/m3) above the NYSDOH air guideline for PCE of 30 g/m3. Post IRM groundwater analysis for VOCs indicates VOC concentrations have significantly been reduced and continue to decline. Of the five on-site wells, three remain above the 5 ppb AWQS for PCE. The most recent concentrations are 12 ppb, 29 ppb and 62 ppb in 2021. TCE levels are below 5 ppb. The data is shown on Figure 4. In November 2018, after construction of the AS/SVE system IRM, soil vapor monitoring was conducted. The concentrations in soil vapor ranged from 69.8 - 1,890 ug/m3 for PCE and 3.1 - 72 ug/m3 for TCE. Preliminary results from sub-slab soil vapor sampling in January 2022 indicate PCE in the range of 23-685 ug/m3 and TCE 3.1 to 8.8 ug/m3. Corresponding indoor air values are 0.26-0.54 ug/m3 PCE and non-detectable for TCE. OU2: Off-Site Remediation at OU2 is complete. Prior to remediation, the primary contaminants of concern were PCE and TCE in soil vapor and groundwater, which were suspected of migrating off-site. Soil was not sampled during the off-site work. The off-site investigation occurred during 2016. Activities at an adjacent, downgradient Brownfield Cleanup Site (C241163 Former Union Wire) also contributed to reductions in off-site contamination. In late 2016, the Former Union Wire site designed and installed an SVE system. The SVE system was installed to address indoor air issues by removing any source material in soil below the existing building, and it remained in use until September 2019. After September 2019, the building was demolished and excavation took place in accordance with a NYSDEC-approved excavation workplan. Soil endpoints samples taken

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

to ensure any potential source of VOCs was removed from the adjacent site. The investigation results, prior to implementation of the IRM described in Section 6.2, are discussed below During the OU2 RI, prior to the IRM, groundwater and soil vapor were analyzed for VOCs. Groundwater was also analyzed for emerging contaminants, as a screening tool. Of the fifteen wells sample, the maximum concentration was PCE at 369 ppb, and TCE at 272 ppb, in one well (MW-3). The AWQS for both PCE and TCE is 5 ppb. Groundwater samples at MW-3 in late 2019 identified PCE at 7 ppb and TCE at 2 ppb. For emerging contaminants, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations of up to 53 and 7 parts per trillion (ppt), respectively. PFOA exceeded the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater, while PFOS did not. 1,4 dioxane was detected in one sample at 0.2 ug/l which is below the guidance value of 0.35 ug/l. Also, during the OU2 RI, prior to the IRM, soil vapor, indoor air and sub-slab soil vapor were analyzed for VOCs. Eleven soil vapor points were sampled in 2016. The highest soil vapor result was 4400 ug/m3 TCE and 2400 ug/m3 PCE. Soil vapor data were used to define the area where property owners were offered sub-slab and indoor air sampling, which occurred in January 2017. Sub-slab and indoor air samples were completed in four (4) off-site structures, and one owner allowed access for indoor air sampling only. In the sub-slab vapor, the TCE concentrations ranged from non-detect (ND) to 440 ug/m3, while PCE ranged from 64 ug/m3 to 9500 ug/m3. In indoor air, TCE was detected at a maximum concentration of 1.4 ug/m3 and PCE was detected a maximum of 7.2 ug/m3. Both of these are below the corresponding NYSDOH Air Guidance Value (AGV) of 2 ug/m3 (TCE) and 30 ug/m3 (PCE). One structure indicated the need for vapor intrusion mitigation, and a sub-slab depressurization system (SSDS) was installed as an IRM. The SSDS is inspected and maintained by NYSDEC. Subsequent to the IRM, an additional structure requested sampling in 2018. Samples were performed in July and December. Based on the result of the sampling, no action was necessary at that structure. "

Health Problem: "People are not expected to come into contact with contaminated soil since the site is covered with buildings and pavement. People are not drinking site-related contaminants in the groundwater since the area is served by a public water supply not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of site contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for inhalation of site contaminants due to soil vapor intrusion for any future on-site development or occupancy Actions have been taken to address exposures related to soil vapor intrusion where necessary and where access has been granted offsite. Additional investigation/evaluation is needed in the event that access is granted at other offsite structures."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-03-15 13:30:00
Record Upd: 2018-03-14 10:47:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Library
Owner Address: Long Island CIty Branch
Owner Addr2: 37-44 21st Street
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: 01
Owner Name: c/o Lillian Shi, Spring Cutting Inc.
Owner Company: Zhong Chaung Properties LLC
Owner Address: 318 W. 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Bridge Cleaners
Owner Company: Bridge Cleaners
Owner Address: 39-26 30th Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY
Owner Country: United States of America
Own Op: 4
Sub Type: 05
Owner Name: Lillian Shi
Owner Company: Spring Cutting Inc.
Owner Address: 318 W 39th St Fl 11
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10018
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Florence Koulouris, District Manager
Owner Company: Community Board 1 - Queens
Owner Address: 45-02 Ditmars Blvd, Suite 1025
Owner Addr2: Not reported
Owner City,St,Zip: Astoria,, NY 11105
Owner Country: United States of America
HW Code: 241127
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241127
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2019031200379001
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-01 10:48:00

FRESH CLEANERS & LAUNDRY INC (Continued) **1001125032**

Record Updated: 2019-07-01 10:48:00
Updated By: RECURLEY

BF362 **27-01 41ST AVENUE** **NY VCP** **S118943297**
South **27-01 41ST AVENUE** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.400 mi.
2114 ft. **Site 2 of 2 in cluster BF**

Relative:
Higher

Actual:
39 ft.

VCP NYC:

Project ID:	13TMP0245Q,13EHAZ245Q,14CVCP158Q
Name:	27-01 41ST AVENUE
Address:	27-01 41ST AVENUE
City,State,Zip:	NEW YORK CITY, NY
Borough:	Queens
BBL:	4004050005
OER Program:	VCP (Enrolled), E/RD (Review)
Phase:	Completed
Latitude:	40.751765
Longitude:	-73.93821
Postcode:	1
Community Board:	26
Council District:	33
Census Tract:	4000000
BIN:	4004057501
NTA:	Queensbridge-Ravenswood-Long Island City

BH363 **RAINEY SUBSTATION** **NY LTANKS** **S102673278**
NNW **35 ST / VERNON BLVD** **N/A**
1/4-1/2 **QUEENS, NY**
0.402 mi.
2124 ft. **Site 1 of 2 in cluster BH**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	RAINEY - AMOCO PROPERTY
Address:	35 VERNON BLVD
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9807334 / 2007-03-01
Facility ID:	9807334
Site ID:	190317
Spill Date:	1998-09-15
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1998-09-15
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

RAINEY SUBSTATION (Continued) **S102673278**

Remediation Phase:	0
Date Entered In Computer:	1998-09-15
Spill Record Last Update:	2007-03-01
Spiller Name:	STEVE ROMERO
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	STEVE ROMERO
Spiller Phone:	(212) 580-6763
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	158768
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Clean Harbors is contracted to remove 20 mounded tanks at property adjacent to the Rainey Substation. Contamination was found near the easternmost 5 tanks as they were being uncovered for emptying and cleaning. 3/1/07: track under DEC spill no. 9810671. (JHO) ~~~~~~~~~~~~~~~~~~~ E2MIS 119758 13:36 9/15/98 H.SULESKI #54128 INSP. CONS. MGT. REPORTED CLEAN HARBORS CONTR. UNCOVERING FUEL OIL TANKS IN RAINEY SUB STATION FOUND FUEL OIL IN SOIL. PUT ABOUT 10 SQ. CUBIC YARDS OF DIRT ON TARPS. CLEAN HARBORS TO REMOVE DIRT AND DO CLEAN UP. THIS JOB WILL BE GOING ON TILL ABOUT DECEMBER DUE TO UNCOVERING AND REMOVAL OF OIL TANKS. OIL SAMPLES WILL BE TAKEN BY CLEAN HARBORS AND SENT TO PRIVATE CONTRACTORS. 1.30 9/15/98 CRISTINE KOVARI NOTIFIED GENE OCONNELL AT D.E.C . CLEAN HARBORS WIIL RESPOND 9/16/98. THIS JOB WAS SCHED. BY RAINEY SUB STATION. ***update 10-29-98 11:00hrs D. Sfriuodis #02756 Insp const mgmt- reports in Rainey yard found contaminated soil in quadrant 1 tank aka tank 10 &11-which is an area 50'x6'x6-no sewers or waterways effected-took sample-4-6 hour priority-stockpiled on plastic and covered. UPDATE 11/4/98 H.STILESKI INSP. ENV. CONST. -CM REPORTED WHILE CUTING OIL TANKS CLEAN HARBORS FOUND 10-20 YARDS OF CONTAMINATED SOIL LEAVING IN PLACE COVERED WITH TARP ADJACENT TO TANKS 10/12 & 14. UPDATE 11/5/98 1400 H.STILESKI INSP. WITH ENV. CONS. CM REPORTED CLEAN HARBORS FOUND 5-10 YARDS CONTAMINATED SOIL NEXT TO TANK #14 WHICH IS BEING REMOVED . COVERED WITH TARP LEAVING IN PLACE FOR NOW. UPDATE 11-6-98 H.SULESKI #54128 REPORT IN RAINEY S.S. HE FOUND BET TANKS #16 & #18 CONTAINATED SOIL. THEY PLACE A PLASTIC TARP TO PROTECT AREA. 11-7-98 1215 HRS D.SFIROUDIS #02756 REPORTS THAT TANK # 18 WAS REMOVED (CONTAINATED SOIL). UPDATE 10:00 4/16/99 H.SULESKI # 119758 CALLED REPORTING 100 YARDS OF SOIL WERE REMOVED FROM SECT #1 AND PUT IN STAGING AREA AND COVERED WITH PLASTIC TARPS. UPDATE 4/26/99 10:48HRS-H. SULESKI-54128 REPORTS MOVED APPROX 100 YARDS NON-HAZARDOUS SOIL FROM SECTION 1 TO HOLDING AREA PENDING ANALYSIS 5/21/99-1315HRS--H.SULESKI REPORTS MOVED 150 YARDS OF SOIL TO HOLDING AREA PENDING ANALYSIAS. UPDATE 5/25/99 1430HRS - HENRY SULESKI #54128 REPORTS THEY MOVED 200 YARDS OF SOIL TO HOLDING PEN PENDING ANALYSIS OF SOIL. 03-AUG-2000 19:20 DOCUMENTATION RECEIVED FROM CHRISTINE KOEHLER INDICATES THAT THE TANKS WERE REMOVED IN 1998, AND THAT STATE-WIDE REMEDIATION IS ONGOING. POST-EX SAMPLES HAVE BEEN APPROVED BY NYSDEC FOR MOST OF THE SITE, AND THESE AREAS HAVE BEEN PARTIALLY BACKFILLED. REMEDIATION REMAINS IN QUADRANT 1A (TOWARD VERNON BLVD-EASTERN PORTION). FOR MORE INFORMATION, REFER TO E2MIS # 121461. "
Remarks:	"APPROX 10 YARDS OF SOIL IS CONTAMINATED DUE TO TANK REMOVAL. CONTRACTOR ON SITE FOR TANK REMOVAL AND CLEAN UP."

RAINEY SUBSTATION (Continued) **S102673278**

All Materials:

Site ID:	190317
Operable Unit ID:	1064908
Operable Unit:	01
Material ID:	560863
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	RAINEY SUBSTATION
Address:	35 ST / VERNON BLVD
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9514765 / 2001-09-19
Facility ID:	9514765
Site ID:	252596
Spill Date:	1996-02-18
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	CAENGELH
Referred To:	Not reported
Reported to Dept:	1996-02-18
CID:	211
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-18
Spill Record Last Update:	2001-09-19
Spiller Name:	LISA PRIMEGGIA
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	206914
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT DEC Inspector Notes: 8/7/01 Foley inspected transformer 3W contactor compartment and vent pipe. Only indication of oil was seen coming from wet valve. Con Ed will extend marriage roll and call in as deminimus. (KMF 9/19/01)"
Remarks:	"caller states employee was filling transformer when product leaked out vent - pcb count less than 50 ppm's - clean up crew on scene"

RAINEY SUBSTATION (Continued) **S102673278**

All Materials:

Site ID:	252596
Operable Unit ID:	1025867
Operable Unit:	01
Material ID:	556544
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

---

364 **34-19 11TH STREET / DELEK** **NY LTANKS** **S102671144**
North **34-19 11TH STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.405 mi.
2137 ft.

Relative:
Lower

Actual:
14 ft.

LTANKS:

Name:	34-19 11TH STREET / DELEK
Address:	34-19 11TH STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8606945 / 1987-03-02
Facility ID:	8606945
Site ID:	249079
Spill Date:	1987-02-12
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1987-03-02
SWIS:	4101
Investigator:	RWAUSTIN
Referred To:	Not reported
Reported to Dept:	1987-02-12
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-03-03
Spill Record Last Update:	1988-02-17
Spiller Name:	Not reported
Spiller Company:	DELEK OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	204241

34-19 11TH STREET / DELEK (Continued) **S102671144**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was AUSTIN "
Remarks: "SPILL IN STREET - TRUCK DELIVERY OF OIL TO ABOVE ADDRESS CAUSED OVER-FLOW OF TANK THROUGH VENT PIPES."

All Materials:
Site ID: 249079
Operable Unit ID: 903691
Operable Unit: 01
Material ID: 472495
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: -1.00
Units: G
Recovered: .00
Resource Affected: Soil
Oxygenate: Not reported

---

365 West 1/4-1/2 0.405 mi. 2141 ft. **QUEENSBRIDGE PLANT E -NYCHA** **NY LTANKS** **S100146423**
40009 VERNON BLVD **N/A**
NEW YORK CITY, NY

Relative: Lower
Actual: 12 ft.

LTANKS:
Name: QUEENSBRIDGE PLANT E -NYCHA
Address: 40009 VERNON BLVD
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 9008149 / 2018-09-26
Facility ID: 9008149
Site ID: 294984
Spill Date: 1990-10-25
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: AAOBLIGA
Referred To: Not reported
Reported to Dept: 1990-10-25
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1990-11-02
Spill Record Last Update: 2018-09-26
Spiller Name: Not reported
Spiller Company: NYCHA
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported

QUEENSBRIDGE PLANT E -NYCHA (Continued) **S100146423**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	238697
DEC Memo:	"01/25/06: This spill transferred from J.Kolleeny to S.Kraszewski. Two 15K tanks installed in 1940 falied a tank test in 1990 and were never retested. According to the PBS report the tanks were closed in place in 1993, elminating any additional source for contamination. A 1995 ISRP discovered 9 SVOC compounds above STARS guidance values from two soil samples. Four volatile compounds were also detected but no concentration is mentioned. TPH was detected at a maximum of 103ppm. No GW was encountered during the subsurface investigation: borings were exteneded to 28 fbg. A heavy clay layer was encountered also during the boring activities. No action was proposed but any contamination encountered during tank removal or abandonment activities must be removed. Some time in 1996, several MWs were drilled around the tanks. One bailing record from November 1996 gives depth to water but doesn't record any oil in the MWs. The site map attached to the record only shows the location of one MW and not of the other three. An additional site investigation was performed either late 1996 or early 1997 because lab analysis sheets are on file for several soil samples. The samples were not analyzed via the proper EPA method for VOCs and SVOCs. Need GW samples with proper analysis. - SK 03/22/06: This spill transferred to K.Tang - SK 5/27/14: J.Kann reassigned spill. NYCHA requested closure. Reviewed the file and confirmed the info above. Email sent to Yelena Tkach stating the following The Department is reviewing the file for the referenced site. The file indicates that wells were installed at the site around 1996. Please confirm if any of the wells are still present, and if so, please gauge and sample them. If no wells are present, please let me know. 06/05/17: J.Kann - GSIP for investigation at this site was approved in 2016. As per NYCHA at May 31, 2017 meeting, contractor has been selected for this work and will start work in summer 2017. Spill reassigned to Andre Obligado. 9/26/18 - Obligado - I reviewed the Phase II Subsurface Investigation Report. 6 borings have been advanced around the USTs and underground piping. No visual or olfactory evidence of contamination or PID readings were detected. All soil samples were below CP51 USCOs for VOCs and SVOCs. This spill is closed. "
Remarks:	"(2) 15K TANKS FAILED HORNER EZY CHECK WITH A GROSS LEAK, WILL EXCAVATE, ISOLATE & RETEST."

All TTF:

Facility ID:	9008149
Spill Number:	9008149
Spill Tank Test:	1537766
Site ID:	294984
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

QUEENSBRIDGE PLANT E -NYCHA (Continued) **S100146423**

Modified By:	Spills
Last Modified Date:	Not reported
Facility ID:	9008149
Spill Number:	9008149
Spill Tank Test:	1537767
Site ID:	294984
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	294984
Operable Unit ID:	945364
Operable Unit:	01
Material ID:	431981
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

BH366 **35-01 VERNON BLVD** **NY LTANKS** **S100166878**
NNW **35-01 VERNON BLVD** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.409 mi.
2158 ft. **Site 2 of 2 in cluster BH**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	35-01 VERNON BLVD
Address:	35-01 VERNON BLVD
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8603127 / 1987-08-21
Facility ID:	8603127
Site ID:	276285
Spill Date:	1986-08-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1987-08-21
SWIS:	4101
Investigator:	UNASSIGNED

35-01 VERNON BLVD (Continued) **S100166878**

Referred To:	Not reported
Reported to Dept:	1986-08-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1986-09-10
Spill Record Last Update:	1987-08-21
Spiller Name:	Not reported
Spiller Company:	LAWRENCE AVAITION
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	224627
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 10/10/95: This is additional information about material spilled from the translation of the old spill file: UNK. AMOUNT."
Remarks:	"3K TANK .326GAL/HR OWNER WILL GET BACK TO"

All TTF:

Facility ID:	8603127
Spill Number:	8603127
Spill Tank Test:	1530118
Site ID:	276285
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	276285
Operable Unit ID:	900392
Operable Unit:	01
Material ID:	475961
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

35-01 VERNON BLVD (Continued) **S100166878**

Resource Affected: Groundwater
Oxygenate: Not reported

BG367 **FORMER UNION WIRE DIE CORP.** **NY ENG CONTROLS** **S116349304**
SSE **39-40 30TH STREET** **NY INST CONTROL** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY BROWNFIELDS**
0.409 mi.
2160 ft. **Site 4 of 6 in cluster BG**

Relative: **Higher**
Actual: **29 ft.**

ENG CONTROLS:

Name:	FORMER UNION WIRE DIE CORP.
Address:	39-40 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	492945
HW Code:	C241163
Control Code:	15
Control Type:	ENG
Date Record Added:	05/10/2017
Date Rec Updated:	05/02/2019
Updated By:	LSZINOMA
Site Description:	"Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

	remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-03-24 16:38:00
Record Upd:	2017-10-12 11:43:00
Updated By:	RECURLEY
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Long Island City Library
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Mr. Joseph Stern
Owner Company:	LIC Owner LLC
Owner Address:	5-26 46th Avenue Suite 2A
Owner Addr2:	Not reported
Owner City,St,Zip:	Long island city, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	JOSEPH STERN
Owner Company:	LIC OWNER LLC
Owner Address:	5-26 46TH AVENUE Suite 2a
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Ave, Suite 125
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	C241163
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C241163
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	C241163-06-14
Cross Ref Type Code:	23

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-11-27 11:14:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-05-11 09:02:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2019000183656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-02 11:21:00
Record Updated:	2019-07-02 11:21:00
Updated By:	RECURLEY

Name:	FORMER UNION WIRE DIE CORP.
Address:	39-40 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	492945
HW Code:	C241163
Control Code:	13
Control Type:	ENG
Date Record Added:	05/10/2017
Date Rec Updated:	05/02/2019
Updated By:	LSZINOMA
Site Description:	"Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

	Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-03-24 16:38:00
Record Upd:	2017-10-12 11:43:00
Updated By:	RECURLEY
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Long Island City Library
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Mr. Joseph Stern
Owner Company:	LIC Owner LLC
Owner Address:	5-26 46th Avenue Suite 2A
Owner Addr2:	Not reported
Owner City,St,Zip:	Long island city, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	JOSEPH STERN
Owner Company:	LIC OWNER LLC
Owner Address:	5-26 46TH AVENUE Suite 2a
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Ave, Suite 125
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Owner Country:	United States of America
HW Code:	C241163
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C241163
Cross Ref Type Code:	22
Cross Ref Type:	BCP Site ID
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	C241163-06-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-11-27 11:14:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-05-11 09:02:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2019000183656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-02 11:21:00
Record Updated:	2019-07-02 11:21:00
Updated By:	RECURLEY

INST CONTROL:

Name:	FORMER UNION WIRE DIE CORP.
Address:	39-40 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	492945
Control Name:	Monitoring Plan
HW Code:	C241163
Control Code:	31
Control Type:	INST
Dt record added:	05/10/2017
Dt rec updated:	05/02/2019
Updated By:	LSZINOMA
Site Code:	492945
Site Description:	"Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments).

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC
Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

Name: FORMER UNION WIRE DIE CORP.
Address: 39-40 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 492945
Control Name: Site Management Plan

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

HW Code: C241163
Control Code: 32
Control Type: INST
Dt record added: 05/10/2017
Dt rec updated: 05/02/2019
Updated By: LSZINOMA
Site Code: 492945
Site Description: "Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC
Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

Name: FORMER UNION WIRE DIE CORP.
Address: 39-40 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 492945
Control Name: O&M Plan
HW Code: C241163
Control Code: 33
Control Type: INST
Dt record added: 05/10/2017
Dt rec updated: 05/02/2019
Updated By: LSZINOMA
Site Code: 492945
Site Description: "Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC
Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

Name: FORMER UNION WIRE DIE CORP.
Address: 39-40 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 492945
Control Name: Environmental Easement
HW Code: C241163
Control Code: J
Control Type: INST
Dt record added: 05/10/2017
Dt rec updated: 05/02/2019
Updated By: LSZINOMA
Site Code: 492945
Site Description: "Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC
Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

Name: FORMER UNION WIRE DIE CORP.
Address: 39-40 30TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 492945
Control Name: Ground Water Use Restriction
HW Code: C241163
Control Code: 08
Control Type: INST
Dt record added: 05/10/2017
Dt rec updated: 05/02/2019
Updated By: LSZINOMA
Site Code: 492945
Site Description: "Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

Name: FORMER UNION WIRE DIE CORP.
Address: 39-40 30TH STREET

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 492945
Control Name: IC/EC Plan
HW Code: C241163
Control Code: 34
Control Type: INST
Dt record added: 05/10/2017
Dt rec updated: 05/02/2019
Updated By: LSZINOMA
Site Code: 492945
Site Description: "Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Record Add: 2014-03-24 16:38:00
Record Upd: 2017-10-12 11:43:00
Updated By: RECURLEY
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Long Island City Library
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: NNN
Owner Name: Mr. Joseph Stern
Owner Company: LIC Owner LLC
Owner Address: 5-26 46th Avenue Suite 2A
Owner Addr2: Not reported
Owner City,St,Zip: Long island city, NY 11101
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: JOSEPH STERN
Owner Company: LIC OWNER LLC
Owner Address: 5-26 46TH AVENUE Suite 2a
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11101
Owner Country: United States of America
Own Op: Document Repository
Sub Type: C01
Owner Name: Not reported
Owner Company: Queens Community Board 1
Owner Address: 45-02 Ditmars Ave, Suite 125
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: C241163
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241163
Cross Ref Type Code: 22
Cross Ref Type: BCP Site ID
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: C241163-06-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-10-12 10:27:00
Record Updated: 2017-10-12 10:27:00
Updated By: RECURLEY
Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-11-27 11:14:00
Updated By: RECURLEY

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Crossref ID: CRFN: 2017000171134
Cross Ref Type Code: 31
Cross Ref Type: Environmental Easement No.
Record Added Date: 2017-05-11 09:02:00
Record Updated: 2017-05-11 09:02:00
Updated By: RECURLEY
Crossref ID: CRFN: 2019000183656
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2019-07-02 11:21:00
Record Updated: 2019-07-02 11:21:00
Updated By: RECURLEY

BROWNFIELDS:

Name:	FORMER UNION WIRE DIE CORP.
Address:	39-40 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	492945
Acres:	0.325
HW Code:	C241163
SWIS:	4101
Town:	New York City
Record Added Date:	03/24/2014
Record Updated Date:	01/13/2023
Update By:	DKMACNEA
Site Description:	"Location: The site is located in Long Island City, Queens at the corner of 30th Street and 40th Ave. Site Features: Since the COC was issued in 2017, the site has been re-developed in accordance with the Site Management Plan. A multi-story apartment building was built. Previously,there was a 2-story building on-site. The first floor was storage and the second floor was office space. Current Zoning and Land Use: The site is zoned M1-3/R7X. M1 indicates light industrial use while R7X is a higher-density residential district (apartments). The building is a combination of commercial and restricted residential use. Past Use of the Site: The site was undeveloped until sometime between 1915 and 1936. By 1936, a gas station occupied the site. The property was redeveloped by 1947 into a 2-story warehouse utilized by Optical Products Corporation for manufacturing, shipping and as an office. Other occupants of the building include Union Wire Die Corp. (1960s - 1980s), National Tea Packaging Co. Inc. (1962 - 1991) and a warehouse (1991 - 2006). Site Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by a silty-sand. A coarse sand was noted at two of the boring locations in place of the silty-sand. The bedrock is an igneous intrusive classified as Ravenswood granodiorite of middle Ordovician to middle Cambrian age. Unconsolidated sediments overlie the bedrock and consist of Pleistocene aged sand, gravel and silty clays. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants were metals and semi-volatile organic compounds

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

	in shallow soils, and chlorinated volatile organic compounds (VOCS) in groundwater and soil vapor. Remedial actions have been implemented at the Site. Residual contamination in the soil, groundwater and soil vapor is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-03-24 16:38:00
Record Upd:	2017-10-12 11:43:00
Updated By:	RECURLEY
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Long Island City Library
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	NNN
Owner Name:	Mr. Joseph Stern
Owner Company:	LIC Owner LLC
Owner Address:	5-26 46th Avenue Suite 2A
Owner Addr2:	Not reported
Owner City,St,Zip:	Long island city, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	JOSEPH STERN
Owner Company:	LIC OWNER LLC
Owner Address:	5-26 46TH AVENUE Suite 2a
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Ave, Suite 125
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	C241163
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C241163
Cross Ref Type Code:	22

FORMER UNION WIRE DIE CORP. (Continued) **S116349304**

Cross Ref Type:	BCP Site ID
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	C241163-06-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-10-12 10:27:00
Record Updated:	2017-10-12 10:27:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-11-27 11:14:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2017000171134
Cross Ref Type Code:	31
Cross Ref Type:	Environmental Easement No.
Record Added Date:	2017-05-11 09:02:00
Record Updated:	2017-05-11 09:02:00
Updated By:	RECURLEY
Crossref ID:	CRFN: 2019000183656
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2019-07-02 11:21:00
Record Updated:	2019-07-02 11:21:00
Updated By:	RECURLEY

BG368 **FORMER UNION WIRE DIE CORP. - OFF-SITE** **NY BROWNFIELDS** **S118372391**
SSE **39-40 30TH STREET** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11101**
0.409 mi.
2160 ft. **Site 5 of 6 in cluster BG**

Relative: **Higher**
Actual: **29 ft.**

BROWNFIELDS:

Name:	FORMER UNION WIRE DIE CORP. - OFF-SITE
Address:	39-40 30TH STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	517267
Acres:	Not reported
HW Code:	C241163A
SWIS:	4101
Town:	New York City
Record Added Date:	11/23/2015
Record Updated Date:	06/28/2017
Update By:	MJKOMORO
Site Description:	"Location: This is an off-site investigation of the area downgradient of the Former Union Wire Site, Site Number C241163, which located at the corner of 30th Street and 40th Ave, in Long Island City, an urban area. Site Features: The investigation area encompasses sidewalks along 29th Street from 39th Ave to 40th Road, along 30th Street from 39th Avenue to approximately 40th Ave, and along 40th Ave to 31st Street. Current Zoning and Land Use: This section of Long Island City is zoned Special Purpose District which allows mixed residential and commercial use. The specific designation for the site is M1-3/R7X. Buildings within the city block are primarily commercial. There are

FORMER UNION WIRE DIE CORP. - OFF-SITE (Continued) **S118372391**

residential units including several three-story apt buildings along 29th Street. The downgradient block also contains a limited number of residential buildings, parking, self-storage, hotel and auto repair businesses. Past Use of the Site: This area of Long Island City has historically included mixed residential and light manufacturing. Formerly the area included a printing operation, commercial laundry and drycleaner, wire die manufacturer, gas station, warehouse operations, and churches occupied the site. Geology and Hydrogeology: Subsurface soils at the site consist of a mixture of a silty non-native fill to a depth ranging from 0 to 6 feet below grade (fbg). The fill is followed by intermixed layers of sand and silty-sand. A clay layer was encountered in one location at approximately 32-38 feet. Bedrock was not encountered although reference material indicates bedrock is glacial and alluvial deposits from the Cenozoic age. The elevation of the site is 28 feet above the National Geodetic Vertical Datum. The area topography gradually slopes to the southeast. Groundwater at the site is present under water table conditions at a depth of approximately 20 feet below grade. Investigation at the site indicates groundwater flow to the south-southeast."

Env Problem: "Nature and Extent of Contamination: Based on investigations conducted to date, the primary contaminant is TCE. The off-site investigation focused on groundwater and soil vapor. Soil: Based on soil analysis from nearby off-site wells, off-site soil contamination was not expected. Groundwater: On-site, TCE was identified in groundwater with a maximum concentration of 280 ppb (parts per billion). Percholorethylene (PCE), a chemical commonly used at drycleaners, is present in groundwater (up to 730 ppb) but is believed to be from an adjacent off-site source. Off-site wells sampled at the downgradient edge of the site indicate low concentrations of TCE (11 ppb in MW6, 3.1 ppb in MW7) and PCE (99 ppb in MW6, 64 ppb in MW7) migrating off-site. In addition, a well, located immediately adjacent to the site and side-gradient, and installed by the Department for an investigation, also contained PCE at 369 ppb and TCE at 272 ppb. Soil Vapor: Eleven soil vapor points were installed as part of the adjacent site's off-site investigation. The highest soil vapor (4400 ug/m3 TCE) was located across 40th Avenue from the site, across from MW-6. During the second set of sampling, the highest levels were also located at SV104, though the level decreased to 1300 ug/m3 TCE. Sub Slab and Indoor Air: Four buildings were sampled for sub-slab and indoor air. One of them was classified as mitigate due to both PCE and TCE in the sub-slab and indoor air. A second structure was classified mitigate or monitor only based on PCE, not TCE. "

Health Problem: "People may come into contact with contaminated groundwater or soil if they dig below the surface. Contaminated groundwater off-site is not used for drinking or other purposes and the area is served by a public water supply that obtains its water from a different source that is not affected by this contamination. Volatile organic compounds in the groundwater and soil may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Environmental sampling, as part of the off-site investigation at the adjacent Bridge Cleaners site (C241127), indicated soil vapor intrusion is a concern at several off-site structures and actions have been recommended."

FORMER UNION WIRE DIE CORP. - OFF-SITE (Continued) **S118372391**

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	E
Owner Name:	Gary Gopalani
Owner Company:	Personal COmmunications Inc
Owner Address:	39-40 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Long Island City Library
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Gary Gopalani
Owner Company:	Ganesh Management LLC
Owner Address:	39-40 30th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	C01
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45--02 Ditmars Ave, Suite 125
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BI369 **34-44 9TH ST** **NY LTANKS** **S102672795**
NNW **34-44 9TH ST** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.413 mi.
2181 ft. **Site 1 of 2 in cluster BI**

Relative:
Higher

Actual:
19 ft.

LTANKS:

Name:	34-44 9TH ST
Address:	34-44 9TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9414006 / 1995-01-20
Facility ID:	9414006
Site ID:	134017
Spill Date:	1995-01-20
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	1995-01-20
SWIS:	4101
Investigator:	TOMASELLO
Referred To:	Not reported
Reported to Dept:	1995-01-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-17
Spill Record Last Update:	1995-03-30
Spiller Name:	Not reported
Spiller Company:	MANGANELLO/ PETRO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	115149
DEC Memo:	""
Remarks:	"DRIVER BURT VEGA, WAS FILLING OIL TANK AT PRIVATE DWELLING WHEN OVERFILL THE TANK AND 3/4 OF A GALLON CAME OUT OF THE VENT PIPE. CLEANUP BY PETRO- USING SPEEDY DRY"

All Materials:

Site ID:	134017
Operable Unit ID:	1007581
Operable Unit:	01
Material ID:	372753
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Resource Affected:	Soil
Oxygenate:	Not reported

370
NNE
1/4-1/2
0.417 mi.
2203 ft.

NORTH QUEENS VIEW HOMES
33-60 21ST STREET
QUEENS, NY

NY LTANKS **S110762235**
N/A

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	NORTH QUEENS VIEW HOMES
Address:	33-60 21ST STREET
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	1009673 / 2010-12-10
Facility ID:	1009673
Site ID:	443237
Spill Date:	2010-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	hrpatel
Referred To:	Not reported
Reported to Dept:	2010-12-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-12-10
Spill Record Last Update:	2010-12-10
Spiller Name:	DONNA BIGILIO
Spiller Company:	NORTH QUEENS VIEW HOMES
Spiller Address:	33 -60 21ST
Spiller County:	999
Spiller Contact:	DONNA BIGILIO
Spiller Phone:	(718) 274-4767
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	398187
DEC Memo:	"case closed. refer to spill #: 9007887."
Remarks:	"Kumar Patel has been notified of tank failure. old spill #: 9007887"

All Materials:

Site ID:	443237
Operable Unit ID:	1193706
Operable Unit:	01
Material ID:	2189188
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

BJ371 **31/32 LIC LLC** **NY BROWNFIELDS** **S118457875**
SE **37-29 31ST STREET** **N/A**
1/4-1/2 **QUEENS, NY 11101**
0.424 mi.
2241 ft. **Site 1 of 2 in cluster BJ**

Relative:
Higher

Actual:
39 ft.

BROWNFIELDS:

Name:	31/32 LIC LLC
Address:	37-29 31ST STREET
City,State,Zip:	QUEENS, NY 11101
Program:	BCP
Site Code:	520356
Acres:	0.400
HW Code:	C241182
SWIS:	4101
Town:	New York City
Record Added Date:	12/28/2015
Record Updated Date:	12/30/2021
Update By:	RKCORCOR
Site Description:	"Location - The 31/32 LIC LLC site is a 0.40-acre parcel located in a well-developed urban area with a mix of commercial and residential buildings. The site address is 37-29 31st Street, Long Island City, NY (formerly 37-26 32nd Street and 37-27 31st Street). The site fronts both 31st Street and 32nd Street and is located between 37th and 38th Avenue. Elevated New York City Subway tracks are located along the 31st Street frontage of the property. Site Features - Previously the site was developed with two one-story structures. Prior to demolition, there was no open space on the property as the buildings fully covered the lot. The structures were both slab on grade with small partial cellars. The slab was left in place during demolition activities until it could be tested and disposed of properly. Current Zoning and Land Use The current zoning designation is M1-2/R6A which includes light manufacturing and residential use. The site has been dug out completely, a vapor barrier placed and a parking garage & business building has been erected. The proposed use is consistent with existing zoning for the property. Past Uses of the Site The site and its surrounding properties were undeveloped until about 1915 when 3rd Avenue traversed the site from northeast to southwest until 1936. Since 1936, the property has hosted multiple tenants which included: tool manufacturing and plating works (1947-1950); lighting factory (1953); welding equipment warehouse (1970-1979); food cart manufacturer, refrigeration facility, and metal shop (1977- 2015); and an auto body facility (1980 present). Past uses most likely contaminated the property through on-site disposal of materials through historic drains, sumps, and pits. Site Geology and Hydrogeology - The property is underlain by glacial and alluvial deposits with Harrison Gneiss underlying. Medium grain sand and fill extend to three feet below grade and medium grain sand from three to 23 feet below grade. The site is relatively level and has no natural or artificial surface water bodies or impoundments. The depth of the shallow groundwater ranges from 22 to 23 feet below grade. Shallow groundwater beneath the site flows to the southwest towards the East River and Dutch Kills. Underlying groundwater in this area of Queens is not used for potable supply purposes. Potable water is provided to the residents by the NYC Department of Environmental Protection. "
Env Problem:	"Remediation at the site is complete and a Track 1 (unrestricted) cleanup was achieved. A full sitewide excavation was conducted in preparation for new construction. Prior to remediation, the primary

31/32 LIC LLC (Continued) **S118457875**

	contaminants of concern were trichloroethene (TCE) in soil vapor, SVOCs, and various metals consistent with historic fill identified in the top 5 feet of soil. Remedial actions have successfully achieved soil cleanup objectives for residential & commercial use. "
Health Problem:	"Remedial actions are complete and have addressed the potential for contact with site-related contaminants. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2016-06-06 11:35:00
Record Upd:	2021-06-09 11:24:00
Updated By:	TLRUTLAN
Own Op:	6
Sub Type:	P03
Owner Name:	Fredrick Oliver
Owner Company:	31/32 LIC LLC
Owner Address:	100 RING ROAD WEST - Suite 101
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Library - Astoria Branch
Owner Address:	14-01 Astoria Blvd.
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11102
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Yi Hua (Gary) Chen
Owner Company:	37-29 31st St LLC
Owner Address:	35-22 Linden Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11354
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Blvd
Owner Addr2:	LL Suite 1025
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Yi Hua (Gary) Chen
Owner Company:	166 Manhattan CM LLC
Owner Address:	35-22 Linden Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11354

31/32 LIC LLC (Continued) **S118457875**

Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Yi Hua (Gary) Chen
Owner Company:	37-29 31st Street LLC
Owner Address:	35-22 Linden Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11354
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Yi Hua (Gary) Chen
Owner Company:	166 Manhattan CM LLC
Owner Address:	35-22 Linden Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Flushing, NY 11354
Owner Country:	United States of America
HW Code:	C241182
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	copper
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	chromium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	zinc
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241182
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

31/32 LIC LLC (Continued) **S118457875**

Crossref ID:	2-603604
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2020-02-05 13:39:00
Record Updated:	2020-02-05 13:39:00
Updated By:	JAAVERSA
Crossref ID:	C241182-02-16
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-10-05 09:22:00
Record Updated:	2020-10-05 09:22:00
Updated By:	RKCORCOR

BJ372 **31/32 LIC LLC - OFF-SITE** **NY BROWNFIELDS** **S121933768**
SE **37-29 31ST STREET** **N/A**
1/4-1/2 **QUEENS, NY 11101**
0.424 mi.
2241 ft. **Site 2 of 2 in cluster BJ**

Relative: **Higher**

Actual: **39 ft.**

BROWNFIELDS:

Name:	31/32 LIC LLC - OFF-SITE
Address:	37-29 31ST STREET
City,State,Zip:	QUEENS, NY 11101
Program:	BCP
Site Code:	534977
Acres:	Not reported
HW Code:	C241182A
SWIS:	4101
Town:	New York City
Record Added Date:	10/26/2016
Record Updated Date:	06/02/2021
Update By:	RKCORCOR
Site Description:	"The area of concern subject to this work is considered off-site from BCP site C241182 and reflects the investigation and possible remediation of contamination that may have migrated from that site. This work is being carried out as provided for under the Environmental Conservation Law Section 27-1411.5. Please see C241182 for further information regarding the status of the site in the Brownfield Cleanup program. Location- The 31/32 LIC LLC site is a 0.40-acre parcel located in a well-developed urban area with a mix of commercial and residential buildings. The site address is 37-29 31st Street, Long Island City, NY, 11101 (formerly 37-26 32nd Street and 37-27 31st Street). The site fronts both 31st Street and 32nd Street and is located between 37th and 38th Avenue. Elevated New York City Subway tracks are located along the 31st Street frontage of the property. Site Features- Previously the site was developed with two one-story structures. Prior to demolition, there was no open space on the property as the buildings fully covered the tax lot. The structures were both slab on grade with small partial cellars. The slab was left in place during demolition activities. Current Zoning and Land Use The current zoning designation is M1-2/R6A which includes light manufacturing and residential use. The site is currently vacant. The proposed use is consistent with existing zoning for the property. Past Uses of the Site The site and its surrounding properties were undeveloped until about 1915 when 3rd Avenue traversed the site from northeast to southwest until 1936. Since 1936, the property has hosted multiple tenants which included: tool manufacturing and plating works (1947-1950); lighting factory (1953);

31/32 LIC LLC - OFF-SITE (Continued) **S121933768**

welding equipment warehouse (1970-1979); food cart manufacturer, refrigeration facility, and metal shop (1977- 2015); and an auto body facility (1980 present). Past uses most likely contaminated the property through on-site disposal of materials through historic drains, sumps, and pits. Site Geology and Hydrogeology - Medium grain sand and fill extend to three feet below grade and medium grain sand from three to 23 feet below grade. The site is relatively level and has no natural or artificial surface water bodies or impoundments. The depth of the shallow groundwater ranges from 22 to 23 feet below grade. Shallow groundwater beneath the site flows to the southwest towards the East River and Dutch Kills. Underlying groundwater in this area of Queens is not used for potable supply purposes. Potable water is provided to the residents by the NYC Department of Environmental Protection."

Env Problem: "Nature and Extent of Contamination: Based upon the remedial investigation at the BCP site #C241182, the primary contaminants of concern are expected to be trichloroethene (TCE) which was found in the BCP site soil vapor. The BCP site soils also contained semi-volatile organic compounds (SVOCs) and metals, such as benzo(a)pyrene, benzo(a) anthracene and benzo(b)fluoranthene, indenp(1,2,3-CD)pyrene, dibenz[a,h]anthracene, lead, copper, chromium, and zinc. The off-site investigation has not begun, therefore this section will be updated to reflect the investigation results as data become available. Significant Threat: It is not yet known whether there is a significant off-site environmental threat due to contamination at the BCP site. This section will be updated as data become available. "

Health Problem: "People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants due to soil vapor intrusion at off-site structures."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
HW Code: C241182A

31/32 LIC LLC - OFF-SITE (Continued) **S121933768**

Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BG373 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100144984**
SSE **29024 40TH AVENUE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.431 mi.
2275 ft. **Site 6 of 6 in cluster BG**

Relative:
Higher

Actual:
27 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	29024 40TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8709369 / 2003-03-13
Facility ID:	8709369
Site ID:	125139
Spill Date:	1988-02-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1988-02-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	2003-03-13
Spiller Name:	Not reported
Spiller Company:	KAL REALTY (OWNER)
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	108274
DEC Memo:	""
Remarks:	"CONTACT: CLIFFORD WENGLIM AT KAL REALTY. 3K TANK SYSTEM FAILED PETROTITE/ LEAK RATE = -.673GPH CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS."

All TTF:

Facility ID:	8709369

CLOSED-LACKOF RECENT INFO (Continued) **S100144984**

Spill Number:	8709369
Spill Tank Test:	1533169
Site ID:	125139
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	125139
Operable Unit ID:	914629
Operable Unit:	01
Material ID:	464694
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	-1.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

BI374 **UNKNOWN TTF** **NY LTANKS** **S110762249**
NNW **34-25 VERNON BLVD** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.436 mi.
2301 ft. **Site 2 of 2 in cluster BI**

Relative: **Higher**
Actual: **19 ft.**

LTANKS:

Name:	UNKNOWN TTF
Address:	34-25 VERNON BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1010069 / 2015-10-01
Facility ID:	1010069
Site ID:	443655
Spill Date:	2010-12-22
Spill Cause:	Tank Test Failure
Spill Source:	Unknown
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	RMOMAR
Referred To:	Not reported
Reported to Dept:	2010-12-22
CID:	Not reported
Water Affected:	Not reported

UNKNOWN TTF (Continued) **S110762249**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-12-22
Spill Record Last Update:	2015-10-01
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CLEARVEIW ENVIROMENTAL
Spiller Phone:	(631) 455-1905
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	398577
DEC Memo:	"8/05/2015: Rashad Spill transferred from Sangesland to Rashad as per RSE. 8/13/2015: Rashad As per NYC building records 34-25 Vernon Blvd. has alternate addresses of 34-20 9 street, 34 9 street, 34-13 Vernon Blvd., and 34-39 Vernon Blvd. According to PBS#2-084107 there is a 7,500 gallon #2 fuel oil underground tank. The last test date was 7/23/2007, next test date was 7/23/12, and reg. expired on 8/28/2012. No other spills were found for this site. No documents found in D2. Property owner according to PBS and NYC building records: Phoenix House Foundation INC. 164 West 74th Street New York, NY 10023 8/14/2015: Rashad Called Ed Neyland at 631-205-1340, he was not in spoke to secretary who gave me his email. Emailed Ed: After reviewing the spill report for 34-25 Vernon Blvd, Queens NY spill#1010069 dated 12/22/2010, I would like to request the following information: Copy of failed tank test report. Test results for supply/return and vent/fill lines. Property owner and contact information. Ed replied: Now you ask for this ? This is from more than five years ago. This file is been long been closed and we no longer have this information. You will need to contact whatever company to clean up. Called Phoenix House at 212-595-5810 and left message. 9/14/2015: Rashad As per NYC building records on 8/14/2012 there was a work order to replace oil burner on existing low pressure heating boiler with gas burner. Also found in PBS records is passing tightness test (tank and system) dated 2/8/2011. Test has been uploaded to D2. 9/17/2015: Rashad Phoenix House email addresses found on work order from 9/5/2014 Virgilio Lamont: vlamont@phoenixhouse.org, Michael Lam VP mlam@phoenixhouse.org. 9/28/2015: Rashad Sent email to vlamont@phoenixhouse.org: I am currently reviewing an old spill case for 34-25 Vernon Boulevard, Queens NY dated 12/22/2010 spill#1010069 where a tank test failure was reported. I am trying to locate information in regards to the initial tank test failure. If you have copy of the failed tank test reported on 12/22/2010 I would appreciate a copy of it, I also have a few questions regarding the failure: What portion of the tank/tank system failed? What repairs were made? Was any soil contamination found? Although I have a passing tank system report dated 2/8/2011, I will need this additional information to ensure a spill did not occur. Any information you could provide is appreciated. He replied: I m out the office today, will send you whatever information I have tomorrow 9/29/2015: Rashad Virgilio emailed back I m so sorry I don t have any information on the failed tank test, we had a fire at our local

UNKNOWN TTF (Continued) **S110762249**

office in 2013 and a lot of records got damage. I remember that we had a company retest and repaired the tank and it was something to do with the seal of the cover, there were no soil contamination and the tank pass after the repairs to the cover. Attached are some files that was sent to me via email after the repairs and before the second test. Proposal and test result. I hope this can help, if you need any other information let me know. He also sent 2 attachments one of them is the passing tank and system test which I already had, the other attachment is an Approved Oil Company proposal, it has been uploaded to D2. Review of Approved Oils proposal is as follows: Tank preparation involved opening manway cover to access manway to tank, pumping out product in tank by vacuum truck into a an Approved Oil truck to temporarily store it until the tank was cleaned. They properly disposed of all bottoms, sludge, and water in each of the two tanks and entered each tank to squeegee clean the interior. Other sections in the proposal included discussion of tank testing, possible need for temp tank, workers insurance and cost of procedure. 10/1/2015: Rashad Spoke to Tim, due to repairs being made on manway cover and no soil contamination according to Virgilio's email spill will be closed. Closure letter uploaded to D2 and sent to Virgilio Lamont. "

Remarks: "Tank teset failure 7500g tank 2860 in tank now."

All Materials:

Site ID:	443655
Operable Unit ID:	1194108
Operable Unit:	01
Material ID:	2189787
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

---

375 SSW 1/4-1/2 0.438 mi. 2312 ft.

22-09 QUEENS PLAZA NORTH
22-09 QUEENS PLAZA NORTH
LONG ISLAND CITY, NY 11101

NY BROWNFIELDS **S127012993**
N/A

Relative: Higher

Actual: 20 ft.

BROWNFIELDS:

Name:	22-09 QUEENS PLAZA NORTH
Address:	22-09 QUEENS PLAZA NORTH
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	607949
Acres:	2.560
HW Code:	C241246
SWIS:	4101
Town:	New York City
Record Added Date:	06/26/2020
Record Updated Date:	10/31/2022
Update By:	HMDUDEK

22-09 QUEENS PLAZA NORTH (Continued) **S127012993**

Site Description: "Location The site is located at 22-09 Queens Plaza North (Lot 1) and 22-09 41st Avenue (Lot 25), in the Long Island City section of Queens, New York. The site is bound to the north by 41st Avenue and underground train tracks for the Metropolitan Transit Authority (MTA) F line, followed by a commercial building occupied by a printing and graphics facility and an electrical supply company, an office building, and a hotel; to the east by 23rd Street, followed by mixed residential and commercial buildings; to the south by Queens Plaza North, the Queensboro Bridge roadway, and aboveground railroad tracks for the MTA N line, followed by parking areas; and to the west by 22nd Street, followed by a commercial building, vacant land, and a warehouse for a lighting facility. Site Features The site consists of two tax lots on an approximately 2.56-acre parcel. Lot 1 contains an approximately 67,600-square foot, one- to two-story building, currently occupied by commercial office space and storage. The northern portion of Lot 1 contains a concrete- and asphalt-paved yard occupied by vehicles and storage of construction equipment. The yard and storage area extend further north into Lot 25. Current Zoning and Land Use The current zoning designation of the site is M1-5 (manufacturing). The proposed rezoning plan would change the site zoning to M1-6/R9/R10; however, this is currently under review by the New York City Department of City Planning (NYCDCP) as part of the Uniform Land Use Review Procedure (ULURP). The surrounding area is largely developed with industrial and commercial uses with residential uses located further west and east. Past Use of the Site Available records indicate the site was used for residential purposes from the late 1800s through the early 1900s. Broadway Maintenance Corporation and Water House occupied the site from the 1950s through approximately 1985. A 1971 Certificate of Occupancy identified electrical and machine repair, and engine rebuilding in the southern portion of the site. Electric motor repair rooms, automotive garage and service station operations, and related activities have remained ongoing at the site for over the last 30 years. Other industrial uses included a lumber yard between approximately 1936 and 1947. A pump station first associated with the Broadway Maintenance Corp. and Water House was located in the central portion of the site from approximately 1950 through 1986 (this location is generally consistent with five 4,000-gallon USTs closed-removed in 2013). Tenants following operations by Broadway Maintenance Corp. included Mahrco Printer and Stationers (approximately 1985 to 1991) and a taxi storage and maintenance yard (approximately 1991 to 2000). More recent site occupants between approximately 2000 and 2015 have included Petrocelli Electric Company, Welsbach Electric Corp., Ronart Leasing Corp., and Grace Industries Corp. Site Geology and Hydrology Based on reports compiled by the U.S. Geological Survey Central Park Quadrangle map, the site lies at an elevation of approximately 20 to 25 feet above the National Geodetic Vertical Datum of 1988 (an approximation of mean sea level) and slopes slightly down toward the west to southwest. Groundwater elevation ranges from approximately 41.4 to 42.0 feet above NAVD 88 (approximately 8.5 to 10.2 feet bgs). Groundwater is expected to flow in a southwesterly direction toward the East River, located approximately 0.5 mile west of the site. During MECC s February 2019 FSSI, subsurface materials beneath the site consisted of approximately 5 feet to 10 feet of fill material (predominantly sand with varying amounts of clay, brick, ash, wood, and cinder), underlain by sand and clay down to the maximum boring terminus of 15 feet below grade. The fill thickness was thinner

22-09 QUEENS PLAZA NORTH (Continued) **S127012993**

	beneath the site building."
Env Problem:	"Site conditions present a variety of environmental concerns. There have been spills and underground storage tanks reported on the site previously. There was an onsite petroleum spill that was treated with soil vapor extraction. Site conditions need further evaluation to determine if there are further petroleum impacts. A variety of industrial facilities existed on the site (including a lumberyard, machine and engine repair, car repair, service station, and a pump station). In the soil, the contaminants of concern are semi-volatile organic compounds (SVOCs) and metals. The metals include arsenic, barium, lead, and mercury. These contaminants are located on the eastern side of the site. The contaminants of concern in the groundwater are volatile organic compounds (VOCs) including chlorinated solvents and SVOCs, including polycyclic aromatic hydrocarbons. Soil vapor data was not provided or available for the application. "
Health Problem:	"Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2020-10-05 12:57:00
Record Upd:	2020-10-05 12:57:00
Updated By:	GWBURKE
Own Op:	1
Sub Type:	P03
Owner Name:	Matthew Lawrence
Owner Company:	Queensboro Tower, LLC
Owner Address:	28-28 Steinway Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 10022
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 ditmars Boulevard, LL Suite 1025
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Hardik Parekh
Owner Company:	Queensboro Tower, LLC
Owner Address:	28-18 steinway Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11103-3349
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

22-09 QUEENS PLAZA NORTH (Continued) **S127012993**

Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	1301128
Cross Ref Type Code:	01
Cross Ref Type:	Spill No.
Record Added Date:	2021-05-28 16:47:00
Record Updated:	2021-05-28 16:47:00
Updated By:	JHOCONNE

---

376 **KAL REALTY** **NY LTANKS** **S103478273**
SSE **29-24 40TH AVE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.439 mi.
2317 ft.

Relative:
Higher

Actual:
26 ft.

LTANKS:

Name:	KAL REALTY
Address:	29-24 40TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9806658 / 2005-06-15
Facility ID:	9806658
Site ID:	172099
Spill Date:	1998-08-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	GWHEITZM
Referred To:	Not reported
Reported to Dept:	1998-08-31
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-31
Spill Record Last Update:	2005-06-15
Spiller Name:	CLIFF WENGLEN
Spiller Company:	KAL REALTY
Spiller Address:	29-24 40TH AV
Spiller County:	001
Spiller Contact:	CLIFF WENGLEN
Spiller Phone:	(718) 784-2842
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	144848
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was M TIBBE NO PREVIOUS SPILL REPORT 6/15/05 Heitzman: See PBS #2-23865. 3000-gallon #2 fuel tank closed January 1999, and replaced with 1500-gallon above ground, suction piped #2 fuel tank. Spill closed."
Remarks:	"TANK PREVIOUSLY TESTED AND FAILED - ON RETEST FAILED AGAIN"

All TTF:

Facility ID:	9806658

KAL REALTY (Continued) **S103478273**

Spill Number:	9806658
Spill Tank Test:	1546206
Site ID:	172099
Tank Number:	1
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	172099
Operable Unit ID:	1067880
Operable Unit:	01
Material ID:	317808
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

377
SW
1/4-1/2
0.456 mi.
2406 ft.

MANHOLE 14413
QUEENS PLAZA NORTH
QUEENS, NY

NY LTANKS **S104950693**
NY Spills **N/A**

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	SPILL NUMBER 0100062
Address:	QUEENS PLAZA N/21ST ST
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0100062 / 2003-06-16
Facility ID:	0100062
Site ID:	63771
Spill Date:	2001-04-03
Spill Cause:	Tank Failure
Spill Source:	Commercial Vehicle
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2001-04-03
CID:	382
Water Affected:	Not reported

MANHOLE 14413 (Continued) **S104950693**

Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-03
Spill Record Last Update:	2003-06-16
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	FIREFIGHTER GIORDANO
Spiller Phone:	(917) 769-0483
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	61550
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND "
Remarks:	"saddle tank on tractor trailer became dislodged and spilled oil onto roadway and did enter sewer system. hazmat on scene"

All Materials:

Site ID:	63771
Operable Unit ID:	838626
Operable Unit:	01
Material ID:	539338
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Resource Affected:	Sewer
Oxygenate:	Not reported

SPILLS:

Name:	MANHOLE 14413
Address:	QUEENS PLAZA NORTH
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	0403163 / 2004-09-23
Facility ID:	0403163
Facility Type:	ER
DER Facility ID:	162666
Site ID:	195222
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	2004-06-22
Investigator:	SKARAKHA
Referred To:	Not reported
Reported to Dept:	2004-06-22
CID:	41
Water Affected:	Not reported

MANHOLE 14413 (Continued) **S104950693**

Spill Source:	Unknown
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-22
Spill Record Last Update:	2004-09-23
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT DESK
DEC Memo:	"e2mis no 153985 U.G. REPORTS FINDING APPROX 2 QTS OF AN UNKNOWN OIL ON APPROX 1000 GALS OF WATER. PCB SAMPLE TAKEN. Lab Sequence Number: 04-04877-001 PCBs < 1 ppm THE SAMPLE HAD THE PCB SURROGATE OUT OF THE QC LIMITS. RE-EXTRACTION AND RE-ANALYSIS WAS NOT POSSIBLE SINCE ALL OF THE ORIGINAL SAMPLE WAS UTILIZED. THE REPORTED PCB VALUE IS THE MINIMUM CONCENTRATION DETECTED IN THE SAMPLE. STANFORD ENVIROMENTAL OPS REPORTS EATHREN SUMP IN STRUCTURE. UPDATE: 22-JUN-2004 STANFORD REPORTS DOUBLE WASHED STRUCTURE WITH BIO GEN 760. REMOVED ALL LIQUIDS. SEALED SUMP."
Remarks:	"2 quarts unknown oil - earthen sump found in manhole. Queens Plaza North at Crescent Street."

All Materials:

Site ID:	195222
Operable Unit ID:	886628
Operable Unit:	01
Material ID:	490758
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

378
NE
1/4-1/2
0.464 mi.
2450 ft.

APARTMENT BLDG
21-50 33RD ROAD
QUEENS, NY

NY LTANKS **S111836477**
N/A

Relative:
Higher

Actual:
22 ft.

LTANKS:

Name:	APARTMENT BLDG
Address:	21-50 33RD ROAD
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	1200162 / 2012-12-11
Facility ID:	1200162

APARTMENT BLDG (Continued) **S111836477**

Site ID:	462778
Spill Date:	2012-04-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	MXAJOKU
Referred To:	Not reported
Reported to Dept:	2012-04-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-05
Spill Record Last Update:	2012-12-11
Spiller Name:	FRANK MARCOVITZ
Spiller Company:	QUEENSVIEW INC
Spiller Address:	21-66 33RD ST
Spiller County:	999
Spiller Contact:	ROB HILLL
Spiller Phone:	(718) 855-7272
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	417195
DEC Memo:	"RiteWay tank pumped out the tank, 3000 gallon UST. PBS: 2-606823. TTF was sent to Queensview, Inc Attn: Frank Marcovitz 21-66 33rd Road Long Island City, NY 11106(sr) 05/23/12-Hiralkumar Patel. DEC Sangesland received a vapor complaint from one of the resident. 12:50 PM:- visited site. found a tank removal work in progress in the southwestern corner of the building 21-50. minor odors detected in proximity to the work area. a nursery school (Queensview Nursery and Kindergarten) is located across the 3 ft wide walkway from the tank excavation area. kids were playing outside in courtyard. spoke with teachers at the nursery school who confirmed no vapor issues in school or in courtyard. Helen Varsam Director Queensview Nursery and Kindergarten Ph. (718) 728-4164 met with Frank Marcovitz, property manager. he mentioned that NY Plumbing is removing the 25,000 gal #6 oil UST and will install a new double wall 20,000 gal #4 oil UST in same location. informed him that based on possible vapor issues from the tank removal work and a nursery school in close proximity, the department requires PID monitoring of the area during working hours. Frank Marcovitz **property manager** Queensview, Inc. 21-66 33rd Road Long Island City, NY 11106 Ph. (718) 728-5090 Fax (718) 274-0567 email: frank@queensvw.com spoke with Greg at NY Plumbing. informed him that the department requires air monitoring (PID screening) in/around the work zone during working hours. asked him to include air monitoring data in final report. also asked him to secure excavation site at the end of the day. he mentioned that there was some contamination observed in area where old pipes might be located before replaced by the most recent ones. he also mentioned that no contamination was observed around the tank. Gregory Quattlander NY Plumbing Ph. (718) 441-6800 (718) 441-7400 Fax (718) 849-2905

APARTMENT BLDG (Continued) **S111836477**

12/11/12: Tank Closure Report dated July 24, 2012 prepared for the RP was received on July 30, 2012. Based on the reviewed report, which could be found in the eDoc, the spill no. associated with this site is closed. Please, check eDoc for details. (M .A)"

Remarks: "Test failed. Repir & Removal pending owner's actions. Cleanup also pending."

All Materials:

Site ID:	462778
Operable Unit ID:	1212878
Operable Unit:	01
Material ID:	2210749
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

379
WSW
1/4-1/2
0.466 mi.
2458 ft.

QUEENSBRIDGE PLANT F **NY LTANKS** **S101103121**
4105 VERNON BLVD. **N/A**
QUEENS, NY

Relative:
Lower

Actual:
12 ft.

LTANKS:

Name:	QUEENSBRIDGE PLANT F
Address:	4105 VERNON BLVD.
City,State,Zip:	QUEENS, NY
Spill Number/Closed Date:	9314507 / 1995-08-16
Facility ID:	9314507
Site ID:	212252
Spill Date:	1990-11-16
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1995-08-16
SWIS:	4101
Investigator:	HEALY
Referred To:	Not reported
Reported to Dept:	1994-03-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-21
Spill Record Last Update:	1995-08-16
Spiller Name:	Not reported
Spiller Company:	NYCHA (JOE MONTELLA)
Spiller Address:	Not reported

QUEENSBRIDGE PLANT F (Continued) **S101103121**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	175891
DEC Memo:	""
Remarks:	"LEAK RATE OF -0.06 GPH - REPORTED AS PASSED BY TESTER. UPDATE: TANK REMOVED 1994"

All TTF:

Facility ID:	9314507
Spill Number:	9314507
Spill Tank Test:	1542486
Site ID:	212252
Tank Number:	001
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	9314507
Spill Number:	9314507
Spill Tank Test:	1542487
Site ID:	212252
Tank Number:	002
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	212252
Operable Unit ID:	992782
Operable Unit:	01
Material ID:	386303
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00

QUEENSBRIDGE PLANT F (Continued) **S101103121**

Units:	Not reported
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

BK380 **QUEENSBORO LANES SITE** **NY BROWNFIELDS** **S127750706**
South **25-01 QUEENS PLAZA NORTH AND N/A 25TH STREET** **N/A**
1/4-1/2 **QUEENS, NY 11101**
0.466 mi.
2460 ft. **Site 1 of 2 in cluster BK**

Relative: **Higher**
Actual: **27 ft.**

BROWNFIELDS:

Name:	QUEENSBORO LANES SITE
Address:	25-01 QUEENS PLAZA NORTH AND N/A 25TH STREET
City,State,Zip:	QUEENS, NY 11101
Program:	BCP
Site Code:	619390
Acres:	0.699
HW Code:	C241257
SWIS:	4101
Town:	New York City
Record Added Date:	05/24/2021
Record Updated Date:	11/30/2022
Update By:	DKMACNEA
Site Description:	"Site Location: The site is located at 25-01 Queens Plaza North, Queens, NY 11101 and is identified as Tax Block 415, Lot 4. The site is located in a mixed-use urban area. The site is bordered to the north by multi-story mixed-use residential and commercial buildings, to the south by Queens Plaza North and Queensboro Bridge Greenway, to the east by 27th Street and to the west by Crescent Street. Site Features: The 0.699-acre site consisted of two adjacent lots (Lots 4 and 10) in Queens, New York, which were merged in 2022. The combined lot faces Queens Plaza North and Crescent Street. The former two-story commercial building was recently demolished. The building was heated by an oil-fired boiler, fueled by a 5,000-gallon underground storage tank, that remains on site after demolition. The remainder of the site is used as a parking lot. Current Zoning and Land Use: The site is currently located in an M1-5/R9 (manufacturing/residential) district within the Special Long Island City Mixed Use (LIC) Zoning District, which allows for light industrial uses and residences developed under height factor regulations. The former commercial building was divided into multiple uses, including restaurants, and stores. The surrounding properties are multi-story residential and commercial buildings. Queens Plaza Subway Station is located to the south 100 feet from the site. Past Use of the Site: Former Lot 4 (25-01 Queens Plaza North): According to a 1936 map, three gasoline tanks were located at the southeast corner of the site. The pedestrian bridge to the Queens Plaza subway station platform was added in 1941. The building has been used for commercial and manufacturing purposes since 1947. In the 1950's the basement of the building was occupied by a bowling alley and a restaurant. The three gas tanks at the southern corner of the site were removed prior to 1950. Manufacturing occurred from the 1970s-1980s. Products included garments, magnetic cassette tapes, and plastic processing. The building was heated by an oil-fired boiler, fueled by a 5000 gallon underground storage tank (UST). Three petroleum spills have been reported at the site. In 1989, a tank test

QUEENSBORO LANES SITE (Continued) **S127750706**

failure occurred at the site, and was associated with the fill line for the UST. The incident was assigned Spill No. 8905133 by NYSDEC and closed in November 1992. In 1994, the fuel oil UST on the site was changed from No. 4 to No. 2 fuel oil. In 1997, a traffic accident occurred at the intersection of Crescent Street and Queens Plaza, causing a 50-gallon spill of diesel fuel. The spill was assigned Spill No. 9612175 and was closed on the same day. In 2003, a spill was of No. 2 fuel oil occurred at the site due to a tank test failure. It was assigned Spill No. 0305348 by the NYSDEC, and closed in May of 2007. Former Lot 10 - 25th Street: Between 1898 and 1936, historical maps indicate residential usage. A private garage and small store were present on a 1936 map. Lot 10 is depicted as a single paved lot in 1970. It is likely that contaminated historic fill may have been used to level the site. Site Geology and Hydrogeology: The elevation of the site is approximately 26 feet above mean sea level. The site is generally flat, and the area slopes slightly to the west towards the East River. The East River is approximately 0.67 miles northwest of the site. Newtown Creek is approximately 0.62 miles to the south of the site. Based on the remedial investigation, groundwater appears to flow to the south/southeast. Groundwater depth at the Site range from approximately 15 to 18 ft below surface grade (bsg). Subsurface stratigraphy observed during the remedial investigation generally consisted of historic fill composed of varying amounts of sand, gravel, silt, and varying amounts of anthropogenic materials (brick, slag, and glass) extending to depths ranging from 0 to 7 feet bsg in former Lot 10; historic fill was not observed in former Lot 4. The historic fill layer is underlain by native soil consisting of varying amounts of sand, silt, clay and grave. Bedrock is approximately 54.5 ft bgs at the site."

Env Problem:

"Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), pesticides, and the emerging contaminants per- and polyfluoroalkyl substances (PFAS) and 1,4-dioxane. Soil vapor was analyzed for VOCs. Based on the investigations conducted to date, the primary contaminants of concern are SVOCs in soil, and stained and odorous soil related to past petroleum releases in soil, and petroleum VOCs in groundwater. Soil: During RI sampling, SVOCs exceeding the restricted residential soil clean-up objectives (RRSCOs) were identified in one location. The maximum concentration was benzo(b)fluoranthene at 9.1 parts per million (ppm), compared to the RRSCO of 1 ppm. Five other SVOCs (benzo(a)anthracene (8.2 ppm), benzo(a)pyrene (6.8 ppm), chrysene (7.7 ppm), dibenz[a,h]anthracene (1 ppm) and indeno (1,2,3-cd) pyrene (4.6 ppm)) exceeded the RRSCO at this location. No exceedances of restricted residential soil clean-up objectives (RRSCOs) for VOCs, metals, pesticides, PCBs or emerging contaminants were noted. Field notes indicate petroleum staining and odors were noted in 3 locations during sampling. The maximum PID (photoionization detector) reading for these locations was 297 ppm. Data does not indicate any off-site impacts in soil related to this site. Groundwater: Petroleum-related VOCs were detected at concentrations exceeding the Ambient Water Quality Standards (AWQS). The highest exceedance was 1,2,4-trimethylbenzene at 82 parts per billion (ppb) above the NYSDEC AWQS of 5 ppb. Other petroleum related compounds include 1,3,5-trimethylbenzene (6.1 ppb), benzene (8 ppb), naphthalene (64 ppb) and xylene (16 ppb). The maximum concentration

QUEENSBORO LANES SITE (Continued) **S127750706**

of any of these compounds was 64 ppb, and the highest total VOC concentration was 250 ppb. Dissolved metals exceeded the AWQS for barium, iron, magnesium, manganese and sodium. These are naturally occurring in groundwater, are not site related and will not be addressed by the remedy. For PFAs, perfluorooctanoic acid (PFOA) and perfluorooctanesulfonic acid (PFOS) were reported at concentrations up to 52.2 and 82.8 parts per trillion (ppt) respectively exceeding the Maximum Contaminant Level (drinking water standard) of 10 ppt in groundwater. 1,4 dioxane was reported at concentrations up to 0.383 parts per billion (ppb), which is below the Maximum Contaminant Level (drinking water standard) of 1 ppb in groundwater. Data does not indicate any off-site impacts in groundwater related to this site.
Sub-Slab Vapor: Tetrachloroethene (PCE) was detected in soil vapor samples up to 9.7 micrograms per cubic meter (ug/m3). Petroleum-related compounds were identified in soil vapor at the site. Data does not indicate any off-site impacts in soil vapor related to this site. "

Health Problem: "The site is covered by a vacant building and pavement so people are not expected to come in contact with site contaminants in soil. However, persons who enter the site could contact contaminants in the soil by digging or otherwise disturbing the soil. Contaminated groundwater is not used for drinking and the site and surrounding areas are served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Because the site is vacant, inhalation of site contaminants in indoor air due to soil vapor intrusion does not represent a concern for the site in its current condition, however the potential exists for indoor air impacts in future on-site buildings. Environmental sampling indicates soil vapor intrusion from site contamination is not a concern for off-site buildings."

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2021-08-31 10:38:00
Record Upd:	2022-09-29 08:38:00
Updated By:	RECURLEY
Own Op:	6
Sub Type:	P02
Owner Name:	James M. Hochman
Owner Company:	Queens Plaza North New York, LLC
Owner Address:	C/O Grubb Properties
Owner Addr2:	4061 Park Road, Suite 450
Owner City,St,Zip:	Charlotte, NC 28209
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported

QUEENSBORO LANES SITE (Continued) **S127750706**

Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
Own Op:	1
Sub Type:	P02
Owner Name:	James M. Hochman
Owner Company:	Queens Plaza North New York, LLC
Owner Address:	C/O Grubb Properties
Owner Addr2:	4061 Park Road, Suite 450
Owner City,St,Zip:	Charlotte, NC 28209
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Public Library at Long Island City
Owner Address:	3744 21st Street, 1st Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	John FalidaS c/o Jennifer Appel
Owner Company:	Estia Realty LLC
Owner Address:	31-44 Steinway street, Apt. 2F
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11103
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Paul Falidas
Owner Company:	Vadiel Properties LLC
Owner Address:	31-19 Newtown Avenue, Suite 1000
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11102
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Vasilios G. Falidas
Owner Company:	VVI Properties LLC
Owner Address:	31-19 Newtown Avenue, Suite 1000
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11102
Owner Country:	United States of America
HW Code:	C241257
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	indeno(1,2,3-cd)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

QUEENSBORO LANES SITE (Continued) **S127750706**

HW Code:	C241257
Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241257
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

381
SSE
1/4-1/2
0.469 mi.
2475 ft.

BENIGNO FERNANEZ (P & G S/S) **NY LTANKS** **U000396231**
31-01 NORTHERN BLVD **NY UST** **N/A**
LONG ISLAND CITY, NY 11101

Relative:
Higher

Actual:
25 ft.

LTANKS:

Name:	EXXONMOBIL -NYCT
Address:	31-01 NORTHERN BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8700671 / 2006-08-30
Facility ID:	8700671
Site ID:	149864
Spill Date:	1987-04-22
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Investigator:	MCTIBBE
Referred To:	Not reported
Reported to Dept:	1987-04-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-04-24
Spill Record Last Update:	2006-10-19
Spiller Name:	MELISSA WINSOR
Spiller Company:	EXXONMOBIL
Spiller Address:	3225 GALLOWS ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	127449
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ROMMEL This spill case was reassigned from DEC (Sigona) to Rommel on 02/10/2004. 02/28/05: Transfered from Rommel to Tibbe. Site being investigated by NYCT. Bureau B, unassigned, due to low priority. Transferred from R-2 on April 27, 2005. Formerly R-2, unassigned. 12/15/05: Transfered back to Tibbe from Bureau B. 08-30-06: NYCT attempted to perform a subsurface investigation but continually encountered refusal. A new subway tunnel, ventilation bulding and utilities were constructed in the area of the former tanks and associated contamination. It would appear that the contamination was removed during construction becuase of the large excavation that was required to construct these facilities, but NYCT has no reports or mainfests to indicate how much was removed. Further investigation does not appear to be possible due to the ubderground structures and utilities. "
Remarks:	"Free product found in groundwater monitoring well"

All Materials:

Site ID:	149864
Operable Unit ID:	905168
Operable Unit:	01
Material ID:	470656
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

UST:

Name:	BENIGNO FERNANEZ (P & G S/S)

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Address: 31-01 NORTHERN BLVD
City,State,Zip: LONG ISLAND CITY, NY 11101
Id/Status: 2-188506 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: N/A
UTM X: 590007.46796
UTM Y: 4511739.20802
Site Type: Unknown

Affiliation Records:

Site Id: 5708
Affiliation Type: Facility Operator
Company Name: BENIGNO FERNANEZ (P & G S/S)
Contact Type: Not reported
Contact Name: BENIGNO FERNANDEZ
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (000) 784-9672
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 5708
Affiliation Type: Facility Owner
Company Name: EXXON COMPANY USA
Contact Type: Not reported
Contact Name: Not reported
Address1: 4550 DACOMA STREET
Address2: Not reported
City: HOUSTON
State: TX
Zip Code: 77092
Country Code: 001
Phone: (800) 992-3647
EMail: Not reported
Fax Number: Not reported
Modified By: BKFALVEY
Date Last Modified: 2007-04-25

Site Id: 5708
Affiliation Type: Mail Contact
Company Name: EXXON COMPANY USA
Contact Type: Not reported
Contact Name: Not reported
Address1: 4550 DACOMA STREET
Address2: Not reported
City: HOUSTON
State: TX
Zip Code: 77092
Country Code: 001
Phone: (800) 992-3647

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2007-04-25

Site Id:	5708
Affiliation Type:	Emergency Contact
Company Name:	EXXON COMPANY, USA
Contact Type:	Not reported
Contact Name:	EXXON COMPANY USA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(800) 992-3647
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BKFALVEY
Date Last Modified:	2007-04-25

Tank Info:

Tank Number:	001
Tank ID:	40229
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1947
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 002

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Tank ID:	40230
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1947
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number:	003
Tank ID:	40231
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1947
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 40232
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 005
Tank ID: 40233
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None

Tank Number:	006
Tank ID:	40234
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1947
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number:	007
Tank ID:	40235
Tank Status:	Closed Prior to Micro Conversion, 03/91
Material Name:	Closed Prior to Micro Conversion, 03/91
Capacity Gallons:	550
Install Date:	12/01/1947
Date Tank Closed:	Not reported
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 008
Tank ID: 40236
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
A00 - Tank Internal Protection - None

Tank Number: 009
Tank ID: 40237
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

H00 - Tank Leak Detection - None
I00 - Overfill - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Number: 010
Tank ID: 40238
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

A00 - Tank Internal Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 011
Tank ID: 40239
Tank Status: Closed Prior to Micro Conversion, 03/91

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None

Tank Number: 012
Tank ID: 40240
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None

BENIGNO FERNANEZ (P & G S/S) (Continued) **U000396231**

J02 - Dispenser - Suction Dispenser

Tank Number: 013
Tank ID: 40241
Tank Status: Closed Prior to Micro Conversion, 03/91
Material Name: Closed Prior to Micro Conversion, 03/91
Capacity Gallons: 550
Install Date: 12/01/1947
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
A00 - Tank Internal Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

BL382 **MOTOR AND IRON WORKS** **NY SHWS** **S118705940**
SE **37-21 32ND STREET** **NY Spills** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY 11120**
0.473 mi.
2496 ft. **Site 1 of 4 in cluster BL**

Relative:
Higher

Actual:
37 ft.

SHWS:
Name: MOTOR AND IRON WORKS
Address: 37-21 32ND STREET
City,State,Zip: LONG ISLAND CITY, NY 11120
Program: HW
Site Code: 532999
Classification: N
Region: 2
Acres: 0.471
HW Code: 241191
Record Add: 09/27/2016
Record Upd: 03/30/2021
Updated By: SMQUANDT
Site Description: "Location: The 20,500 square-foot lot is surrounded by commercial, industrial, and mixed use residential and commercial buildings. Commercial and industrial buildings are located to the south, 33rd street followed by a commercial building to the east, and 32nd street followed by mixed-use residential and commercial buildings to the

MOTOR AND IRON WORKS (Continued) **S118705940**

west. The site was a vacant lot prior to redevelopment. Site Features: The site has recently been developed with a 7-story residential apartment building with retail stores on the first floor Current Zoning and Land Use: The property is zoned as M1-2/R6A, which allows for mixed residential and commercial buildings. Past Use of the Site: As of 1898, the subject property contained a two-story bottling and laboratory facility occupied by Hiscox & Company Patent Medicines. By 1915, the building was occupied by Mercury Motor Works and two two-story dwellings were constructed in the western portion. By 1936, the main building expanded, occupying more of the property and was occupied by Renner-Maras Inc. Ornamental Iron Works. In addition, one of the dwellings was identified as an office. By 1947, the building was identified as a loft and electro-plating facility. By 1970, the western building was built-out to the property and was identified as Bliss Display Corp, a manufacturer. The eastern portion was used for painting and the southern was used for woodworking. By 1995, the property was occupied by one manufacturer. By 1996, a small portion was used for parking. The property remained substantially unchanged through 2006. Site Geology and Hydrogeology: The topography of the site is generally level and is approximately 36 feet above mean sea level. The site is located approximately 0.87 miles northeast of Dutch Kills and 1.1 miles east of the East River. Depth to groundwater is approximately 30 feet below ground surface (bgs). Groundwater flows to the west towards Dutch Kills. The major aquifer systems beneath the subject property are the Upper Glacial and Lloyd aquifers. The subsurface beneath the site consists of unconsolidated sand and gravel layers from the ground surface to approximately 50 ft bgs where the Raritan confining unit is encountered. Bedrock beneath the subject property is located approximately 200 ft bgs. The lithology generally consisted of up to five feet of fill material underlain by a silt or clay lens extending to a maximum observed depth of seven feet followed by poorly graded sand to the terminal depth of the investigation at 23 ft bgs. The historic fill encountered was evidenced by brick and concrete, which predominantly was embedded in a silty sand matrix."

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were petroleum-related volatile organic compounds in soil and groundwater, and trichloroethene and tetrachloroethene in soil vapor. Post excavation samples collected at 14 feet below grade demonstrated achievement of soil cleanup objectives for residential use, and a sub-slab depressurization system was installed to mitigate building occupant exposures related to soil vapor intrusion. Residual contamination in the soil, groundwater, and sediment is being managed under a Site Management Plan."

Health Problem: ""
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported

MOTOR AND IRON WORKS (Continued) **S118705940**

Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	OER - VACANT LOT
Address:	37-21 32ND ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1603003 / 2021-03-29
Facility ID:	1603003
Facility Type:	ER
DER Facility ID:	483547
Site ID:	529439
DEC Region:	2
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2016-06-27
Investigator:	KMFORSTE
Referred To:	Not reported
Reported to Dept:	2016-06-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-06-27
Spill Record Last Update:	2021-04-01
Spiller Name:	MARK GELBAND
Spiller Company:	UNKNOWN
Spiller Address:	37-21 32ND ST
Spiller Company:	999
Contact Name:	MARK GELBAND
DEC Memo:	"6/27/2016: Rashad 37-21 32 Street has an alternate address of 37-13 - 37-23 32 Street and 37-12 - 37-18 33 Street. No additional spills or PBS registrations found for

MOTOR AND IRON WORKS (Continued) **S118705940**

this site. Called Mark, this
site is an OER site and they found contamination during RIR field work. Shaminder contacted us this
morning with regards to this site: I am reviewing an RIR which indicated VOCs in soils at 20 feet
depths. Groundwater was not sampled due to refusal at 27 feet depths. Soil/fill samples results
were compared to New York State Department of Conservation (NYSDEC) Unrestricted Use Soil Cleanup
Objectives and Restricted Residential Use Soil Cleanup Objectives (SCOs) as presented in 6NYCRR
Part 375-6.8 and CP51. Soil/fill samples collected during the RI showed that no PCBs were detected
in any of the soil samples. VOCs including 1,2,4-Trimethylbenzene (42,000 ug/kg),
1,3,5-Trimethylbenzene (13,000 ug/kg), Ethyl Benzene (3,800 ug/kg), n-Propylbenzene (6,700 ug/kg)
and total Xylenes (19,000 ug/kg) were detected above Unrestricted Use SCO in one deep soil sample
SB-9 (21-23). The email had two documents attached. First document has site maps with soil
concentrations as well as soil vapor results. Soil vapor results are as follows: SV-1:
Tetrachloroethene-150ug/m3, SV-2: tetrachloroethene-230ug/m3, SV-3: Tetrachloroethene-170ug/m3,
SV-4 Tetrachloroethene-160ug/m3, trichloroethene-400ug/m3, SV-5: tetrachloroethene-260ug/m3,
trichloroethene-170ug/m3, SV-6 tetrachloroethene-220ug/m3, trichloroethene-200ug/m3, SV-7
tetrachloroethene-96ug/m3, trichloroethene-420ug/m3. Soil analyticals found contamination at SB-9
21-23 feet: 1,2,4 Trimethylbenzene-42,000ppb, 1,3,5 Trimethylbenzene-13,000ppb, Ethyl
Benzene-3,800ppb, n-propylbenzene-6,700ppb, and total xylene-19,000ppb. 7/7/2016: Rashad Sent
contaminated soil letter to NYCOER for site, it has been uploaded to D2 and mailed to owner.
9/6/2016: Rashad Received call from Paul Stewart of Advanced Cleanup Technologies. He said that he
is working with OER on site and that the RAWP is in the final stages of approval. Received email
from Shaminder: Above spill was recently called in during Site investigations. Since then, RIR and
RAWP have been prepared. A copy of RAWP is attached for your review. Development includes
excavations of full footprint of property to more than 22 feet deep for cellar and sub-cellar (to
be used as parking garage) and a seven story residential building. Remedy includes: 1. Excavation
and removal of soil/fill exceeding Track 4 Site Specific SCOs. 2. Performance of a remedial action
for the petroleum spill #16-03003 under New York State Department of Environmental Conservation
(NYSDEC) Spill program. 3. Collection and analysis of end-point samples to determine the
performance of the remedy with respect to attainment of SCOs. End point samples for spill closure

MOTOR AND IRON WORKS (Continued) **S118705940**

will be performed per DER-10 requirements. 4. Construction of an engineered composite cover 5. Installation of a vapor barrier system 6. Installation of a passive sub-slab depressurization system (SSDS) 7. parking garage with high volume air exchange in conformance with NYC Building Code. Attached to email was RIR and summary. It has been uploaded to D2. Review or RAWP is as follows: Site is in VCP. The proposed future use of site will be a seven story mixed use building with retail stores on first floor, and residential apartments on the upper six floors. The cellar will be built to a max depth of 10 feet bgs, the subcellar will be built to a depth of 20 feet bgs. The majority of the property will be excavated to a depth of 22 ftbgs. Elevator pits will be excavated to depth of 26 ft bgs, the excavation is not expected to reach the groundwater table. The sub-cellar will contain 45 parking spots. The cellar will contain 25 parking sports. Groundwater was not encountered, refusal was reached at 27 ft bgs. The proposed remedial action will consist of: community air monitoring, excavation and removal of soil for the majority of the site to a depth of 22 feet below grade except for two recessed area to the northwest and northeast, which will be excavated to 2 feet bgs. A small portion will be excavated to 27 ft bgs. Removal of all USTs that are encountered during soil removal actions and registrations of all found tanks. Performance of remedial actions for the open spill case on property which include installation and monitoring of off site groundwater wells as required and approved by NYSDEC, and may include the removal of LNAPL present beneath the site, treatment of groundwater plume via injections of biorem and chem ox if required by NYSDEC, excavation and removal of petroleum impacted soil, where feasible to 2 feet below groundwater and the implementation of a groundwater monitoring program. A separate RAWP Addendum may be required by NYSDEC. Construction of an engineered composite cover of a min of 6 inch thick reinforced concrete building slab. Installation of a vapor barrier system consisting of vapor barrier beneath the building slab and outside of sub-grade foundation sidewalls. Vapor barrier will be 20 mill in thickness. Installation of passive SSDS. Property is also E-designated. 9/7/2016: Rashad Spoke to DEC Vought and sent report review letter approving RAWP to NYCOER pending proposed monitoring well locations. 10/5/2016: Rashad Shaminder submitted addendum to myself and John Durnin, John is DEC project manager for hazardous waste remediation project on this site. Sent email to John seeking if I should administratively close this spill and refer it to his hazardous waste project. 10/6/2016: Rashad Review of

MOTOR AND IRON WORKS (Continued) **S118705940**

the addendum is as follows;
they are proposing installation of two down gradient groundwater monitoring wells along the western
boundary of the site. Also five additional soil vapor samples have been proposed along the northern
and southern boundaries of the site. Discussions with John continue on possible case transfer
(Remediation ID number 241191). 10/13/2016: Rashad On 10/12 DEC Durnin sent comments to Shaminder
for the RAWP Addendum which include: Revised RAWP Addendum (see figure below) Site investigation
decisions for this P site are based on the entire property being excavated to the depth of at least
22 feet. The north corner of the site along 32nd Street (recessed area) and the east corner of the
site along 33rd Street (recessed area) both are only going to be excavated to a depth of 2 feet.
Should the developer not implement this excavation plan, the soil investigation would require
additional sampling from 2 feet to 22 feet across to entire property. Soil Vapor According to the
June 22, 2016 draft RIR (page 20), nine soil vapor samples (SV-1 through SV-9) were collected but
only 7 are documented (SV-1 to SV-7). This should be corrected in the final RIR. Relocate proposed
SV-11 away from the former basement area to ensure the soil vapor sample (6 -7 probe depth) is
representative of the soil conditions without any influence of the former basement. Add soil vapor
sample points SV-13 and SV-14 at each end of the site near 32nd Street and 33rd Street to evaluate
the potential for off-site migration. Soil There is only one soil sample, SB-9 (21 -23) below the
two foot depth. All the other soil samples are from the 0 to 2 depth. The off-site soil borings
for MW-1 and MW-2 must be logged continuously and screened with a PID. Any visual evidence of
contamination or elevated PID readings will require soil sample collection and laboratory analysis
for VOCs, SVOCs and Metals. Groundwater Based on groundwater data from other OER Brownfield Sites
in the area, the groundwater flow direction is most likely in the westerly direction and
approximately 20 feet deep. Indicate the diameter of the proposed wells and the type of well
drilling rig to be used. Since refusal was encountered at 27 feet during a previous attempt, a
larger drill rig is needed to install the four proposed monitoring wells. Provide well construction
details for all new wells. MW-1 and MW-2 must be greater than 20 feet apart to be representative of
a broader area of groundwater, to not influence one another and to enhance the verification of the
groundwater flow direction. MW-2 needs to be far enough along 32nd Street to reasonably be
downgradient of the site. MW-3 should be located near SB-9 where elevated levels of

MOTOR AND IRON WORKS (Continued) **S118705940**

Trimethylbenzenes, Ethyl Benzene, n-Propylbenzene and total Xylenes were encountered in the soil at
21 to 23 feet. MW-4 will show if there is off-site groundwater impacting the site (assuming a
westerly groundwater flow). As per DEC Vought, no further comments are needed for petroleum
remediation as DEC Durnin has taken the lead and addressed the Departments comments/concerns.
10/31/2016: Rashad On 10/28 DEC Durnin asked for update to revised addendum. Alysha from OER sent
revised addendum report. It has been uploaded to D2. 11/9/2016: Rashad John Durnin sent email:
There has been a question raised regarding the revision of the RAWP Addendum for 37-21 32nd Street,
Spill #16-03003. The consultant, Advanced Cleanup Technologies, Inc. (ACT) prepared the revised
addendum to the Remedial Action Work Plan (RAWP) and RAWPs required a P.E. to do the work. However,
the work I ve been reviewing and commented on involves investigative work necessary to evaluate if
this project (NYSDEC P Site) will be in the NYCOER BF program or the NYSDEC BF program, typically
investigative work not requiring a P.E. Is it possible that this is actually an addendum to an
existing RIWP prepared by ACT in early 2016? Alysha replied: The addendum is for the existing RIWP
and will be also included as an appendix in the Stipulation List.
1/5/2017: Rashad Emailed DEC
Durnin about possible case transfer due to my resignation at DEC, received no response. 1/6/2017:
Rashad After meeting with RSE Austin spill will be assigned to DEC Durnin. There is a DEC approved
RI Work Plan addendum for additional wells and SVI sampling. Waiting for this to be done. DEC sent
a sidewalk opening permit request letter on February 23, 2017. (3/31/2017) The additional well
samples and SVI sampling were completed in May 2017. Site remediation/construction began in January
2018. Daily reports are available on the NYCOER EPIC website (16TMP0372M). Once the site
remediation is completed, DEC will evaluate the open spill and determine if it can be closed. The
DEC Project Manager, John Durnin, will retire in April 2018. The new Project Manager will be Kyle
Forster. (3/29/2018), Remedial Action Report acceptable to DEC. A memo has been filed documenting
the remedial actions taken and summarizes remaining contamination. Both filed in D2 (4/1/2021). -
K. Forster"

Remarks: ""

All Materials:

Site ID:	529439
Operable Unit ID:	1278269
Operable Unit:	01
Material ID:	2283151
Material Code:	0066A
Material Name:	unknown petroleum

MOTOR AND IRON WORKS (Continued) **S118705940**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

BL383 **32-10 37TH AV** **NY LTANKS** **S105995592**
ESE **32-10 37TH AVE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.480 mi.
2537 ft. **Site 2 of 4 in cluster BL**

Relative:
Higher

Actual:
38 ft.

LTANKS:

Name:	32-10 37TH AV
Address:	32-10 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0200301 / 2005-06-16
Facility ID:	0200301
Site ID:	147177
Spill Date:	2002-04-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	GWHEITZM
Referred To:	Not reported
Reported to Dept:	2002-04-09
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-09
Spill Record Last Update:	2005-06-16
Spiller Name:	TED LEVY
Spiller Company:	Not reported
Spiller Address:	32-10 37TH AV
Spiller County:	001
Spiller Contact:	TED LEVY
Spiller Phone:	(516) 984-3307
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	125302
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SANGESLAND 4/29/2002 - Sangesland spoke to property owner (Mr. Ron Levy). Mr. Levy did not feel comfortable with ProTest and requested information on how to close out this spill. Isolate and retest just the tank and just the piping. Once the spill is closed out, owner will abandon the tank and switch to gas. 6/10/2002 Man hole on top of tank was left open. Gasket was replaced and the tank passed the retest. 7/3/2002 Mr. Levy called. He will send a copy of the tank

32-10 37TH AV (Continued) **S105995592**

test which shows that the tank passed the second test. He also said that he will be pulling the tank out and wanted to know the proper procedures. Sangesland provided Mr. Levy with a contact at PBS. 6/16/05 Heitzman: See PBS 2-607788. Tank was removed July 2002. Closed."

Remarks: ""

All TTF:

Facility ID:	0200301
Spill Number:	0200301
Spill Tank Test:	1527020
Site ID:	147177
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147177
Operable Unit ID:	853728
Operable Unit:	01
Material ID:	525303
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BL384 **32-15 37TH AVE** **NY LTANKS** **S100494742**
ESE **32-15 37TH AVE** **N/A**
1/4-1/2 **LONG ISLAND CITY, NY**
0.480 mi.
2537 ft. **Site 3 of 4 in cluster BL**

Relative:
Higher

Actual:
39 ft.

LTANKS:

Name:	32-15 37TH AVE
Address:	32-15 37TH AVE
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9212707 / 1993-03-10
Facility ID:	9212707
Site ID:	220254
Spill Date:	1993-02-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial

32-15 37TH AVE (Continued) **S100494742**

Spill Class:	C3
Cleanup Ceased:	1993-03-10
SWIS:	4101
Investigator:	SULLIVAN
Referred To:	Not reported
Reported to Dept:	1993-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-02-11
Spill Record Last Update:	1993-03-17
Spiller Name:	Not reported
Spiller Company:	APT BLDG
Spiller Address:	32-15 37TH AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	182178
DEC Memo:	""
Remarks:	"OIL ON FLOOR IN TANK ROOM. CONTAINED. VAC TRUCK, SPEEDI-DRI BEING USED TO CLEAN SPILL. CALLER SPILL TEAM ON SITE."

All Materials:

Site ID:	220254
Operable Unit ID:	979708
Operable Unit:	01
Material ID:	402543
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1000.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

BK385 **FALIDAS ASSCOCIATES** **RCRA-VSQG** **1007264881**
South **25-01 QUEENS PLAZA N** **NY LTANKS** **NYR000123547**
1/4-1/2 **LONG ISLAND CITY, NY 11101** **NY MANIFEST**
0.480 mi. **NJ MANIFEST**
2537 ft. **Site 2 of 2 in cluster BK**

Relative: **Higher**
Actual: **26 ft.**

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Falidas Asscociates
Handler Address:	25-01 QUEENS PLAZA N
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYR000123547
Contact Name:	GEORGE V FALIDAS

FALIDAS ASSCOCIATES (Continued) **1007264881**

Contact Address:	QUEENS PLAZA N
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-392-0514
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	QUEENS PLAZA N
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	George Falidas
Owner Type:	Private
Operator Name:	Falidas Associates
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

FALIDAS ASSCOCIATES (Continued) **1007264881**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	No

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name: GEORGE FALIDAS	
Legal Status:	Private
Date Became Current:	19840404
Date Ended Current:	Not reported
Owner/Operator Address:	25-01 QUEENS PLAZA N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-392-0514
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name: GEORGE FALIDAS	
Legal Status:	Private
Date Became Current:	19840404
Date Ended Current:	Not reported
Owner/Operator Address:	25-01 QUEENS PLAZA N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-392-0514
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: FALIDAS ASSOCIATES	
Legal Status:	Private
Date Became Current:	19840404
Date Ended Current:	Not reported
Owner/Operator Address:	25-15 QUEENS PLAZA N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-392-0514
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name: FALIDAS ASSOCIATES	
Legal Status:	Private
Date Became Current:	19840404
Date Ended Current:	Not reported
Owner/Operator Address:	25-15 QUEENS PLAZA N
Owner/Operator City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner/Operator Telephone:	718-392-0514
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

FALIDAS ASSCOCIATES (Continued) **1007264881**

Receive Date: 20060101
Handler Name: FALIDAS ASSCOCIATES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: FALIDAS ASSCOCIATES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20040330
Handler Name: FALIDAS ASSCOCIATES
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 56291
NAICS Description: REMEDIATION SERVICES

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

LTANKS:
Name: FALIDAS ASSOCIATES
Address: 25-15 QUEENS PLAZA NORTH
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 0305348 / 2007-05-21

FALIDAS ASSCOCIATES (Continued) **1007264881**

Facility ID:	0305348
Site ID:	66252
Spill Date:	2003-08-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	rvketani
Referred To:	Not reported
Reported to Dept:	2003-08-20
CID:	216
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-08-20
Spill Record Last Update:	2007-05-21
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	GEORGE FALIDAS
Spiller Phone:	(718) 392-0514
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	63466
DEC Memo:	"On 7/14/05, J Peck called RIR Com. Cynthia Roby doesn't work there now. Left mesasage to return call concerning spill. Could not determine owner of property from Property Shark or Acris. Called George Falidas on 7/14/05, left message to call back. On 1/19/05, reattempted to determine owner of property. No success. 3/30/07 - Austin - Trasferred to Ketani for further review - end 5/21/07 - Raphael Ketani. I reactiviated the case today. There was very little in the case file. Some printed pages for spill #0305345 (which doesn't pertain to the case, except the memo from Mr. Sigona to Mr. Hassan), an 11/7/05 letter from Joseph Peck of DEC to George Failda regarding the spill, printouts from Google Earth and Property Shark, and a printout of the spill report for this case. I did a search of ACRIS, the NYC Property Tax database, and Property Shark and determined that 25-15 Queens Plaza North is just one part of the range of properties (25-01 to 25-27 Queens Plaza North) owned by Falidas Associates. It is also known by Bridge Plaza North. The block and lot are: 00415 and 0004. I called up George Falidas (718) 392-0514 of Falidas Associates and was connected to his brother, John Falidas. I made a field visit and met John Falidas. He showed me the basement of one of the properties owned by Falidas Associates and which is near to where the tank failed 2 buildings away. We entered a work room rented by a garment making company. The floor and walls and bathroom were clean. There were no signs of oil and no oil odors. Mr. Falidas said that he had paid lots of money to get the oil cleaned up years ago and the responsible party never paid anything to him. Mr. Falidas had a package of documents from the EPA and the DEC and showed them to me. These were the RCRA Subtitle C Site Identification

FALIDAS ASSCOCIATES (Continued) **1007264881**

Form, letters from South Mall Analytical Labs to PTC, and a DEC Spill Report. He gave me copies of these documents. I was particularly interested in the old DEC spill report form as this document wasn't in the case file. Next, I visited the 2 story building between Mr. Falidas' building and the site of origin of the spill. I met Sandro Cestaro of Atlantic Precious Metal Casting, Inc. (718) 937-7100. He showed me his basement. There were some signs of a thin film of mud in one corner of the basement, but no signs or odors of oil, even though this was the building where the oil first entered. Lastly, I went to the site of the oil spill. The auto parts service place had burned completely, according to the old spill report case notes. This site was 41-22 to 41-30 27 Street. The site was sold to developers who later built an apartment building that was finished in early 2007. This building is listed as 41-28 27 Street. I met the super., Leonardo Colon. He took me to the lowest point in the building. This was a parking garage. There were no signs of oil nor any odors. He said he was new here and didn't know much about the building. The building management company is Golden Management and the contact person is Brandon Wechsler (718) 230-2600, ext 111. I took 3 pictures of the apartment building and the neighboring properties. I remember seeing the dig out for the foundation for the building when I passed by the site many months back. They went down below the bottom of the foundation for the neighboring building which contains Atlantic Precious. This is a depth of about 15 feet or so. Based upon my site visits and the fact that the old auto parts area has been dug out, and the lack of evidence of a spill, I am closing the spill case. "

Remarks: "SPILL AT A COMMERCIAL BLD CALLER IS A TENANT AND REQ A CALL FROM DEC SPILL HAS NOT BEEN CLEANED UP BEEN SMELLING THIS FOR ABOUT 3 WEEKS "

All Materials:

Site ID:	66252
Operable Unit ID:	871982
Operable Unit:	01
Material ID:	502602
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	FALIDAS ASSOCIATES
Address:	25-15 QUEENS PLAZA
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8905133 / 1992-11-19
Facility ID:	8905133
Site ID:	237933
Spill Date:	1989-08-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1992-11-19
SWIS:	4101
Investigator:	BATTISTA

FALIDAS ASSCOCIATES (Continued) **1007264881**

Referred To:	Not reported
Reported to Dept:	1989-08-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-09-06
Spill Record Last Update:	2004-01-07
Spiller Name:	Not reported
Spiller Company:	FALIDAS ASSOCIATES
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	195968
DEC Memo:	""
Remarks:	"5K TANK FAILED HORNER EZY CHECK, STOPPED TEST, MANHOLE LEAKING, WILL REPLACE GASKET & RETEST."

All TTF:

Facility ID:	8905133
Spill Number:	8905133
Spill Tank Test:	1535902
Site ID:	237933
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	237933
Operable Unit ID:	930454
Operable Unit:	01
Material ID:	445573
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater

FALIDAS ASSCOCIATES (Continued) **1007264881**

Oxygenate: Not reported

NY MANIFEST:
Name: FALIDAS ASSOCIATES
Address: 25-01 QUEENS PLAZA N
City,State,Zip: LONG ISLAND CITY, NY 11101
Country: USA
EPA ID: NYR000123547
Facility Status: Not reported
Location Address 1: 25-15 QUEENS BLVD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: LONG ISLAND CITY
Location State: NY
Location Zip: 11101
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000123547
Mailing Name: FALIDAS ASSOCIATES
Mailing Contact: N/S
Mailing Address 1: 25-15 QUEENS BLVD
Mailing Address 2: Not reported
Mailing City: LONG ISLAND CITY
Mailing State: NY
Mailing Zip: 11101
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 7183920514

NJ MANIFEST:
EPA Id: NYR000123547
Mail Address: 25-15 QUEENS BLVD
Mail City/State/Zip: LONG ISLAND 11101
Facility Phone: 7183920514
Emergency Phone: Not reported
Contact: Not reported
Comments: Not reported
SIC Code: Not reported
County: 00
Municipal: 00
Previous EPA Id: Not reported
Gen Flag: X
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: NJA5082592
EPA ID: NYR000123547
Date Shipped: 12/03/2004
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYR000080549

FALIDAS ASSCOCIATES (Continued) **1007264881**

Transporter 2 EPA ID:	NJD986607380
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/03/2004
Date Trans2 Transported Waste:	02/07/2005
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/07/2005
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	03150595
Was Load Rejected:	LONG ISLAND 11101
Reason Load Was Rejected:	Not reported

386
NE
1/4-1/2
0.486 mi.
2568 ft.

HALKIDIKI AUTO CENTER INC.
33-21 21ST STREET
ASTORIA, NY 11106

NY LTANKS **U000411272**
NY UST **N/A**

Relative:
Higher

Actual:
18 ft.

LTANKS:

Name:	33-21 21ST ST/GAS STOP
Address:	33-21 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8809261 / 2003-07-29
Facility ID:	8809261
Site ID:	296241
Spill Date:	1989-02-28
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	A1
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	SIGONA

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Referred To:	Not reported
Reported to Dept:	1989-02-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-04-04
Spill Record Last Update:	2004-12-16
Spiller Name:	Not reported
Spiller Company:	GAS STOP
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	239720
DEC Memo:	"Spill number closed by A. Sigona. See file for additional information. Rommel"
Remarks:	"EXPLOSIVE LEVEL IN SEWER SUSTAINEDFOR AN UNKNOWN TIME PERIOD TILL INVESTIGATED ON 3/1/89, (2) PEOPLE TAKEN TO HOSPITAL, SIGNIFICANT GROUNDWATER CONTAMINATION."

All TTF:

Facility ID:	8809261
Spill Number:	8809261
Spill Tank Test:	1535208
Site ID:	296241
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	296241
Operable Unit ID:	925178
Operable Unit:	01
Material ID:	454016
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Recovered: .00
Resource Affected: Sewer
Oxygenate: Not reported

UST:
Name: HALKIDIKI AUTO CENTER INC.
Address: 33-21 21ST STREET
City,State,Zip: ASTORIA, NY 11106
Id/Status: 2-480428 / Active
Program Type: PBS
Region: STATE
DEC Region: 2
Expiration Date: 10/07/2015
UTM X: 590091.85726
UTM Y: 4513130.44686
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:
Site Id: 21435
Affiliation Type: Facility Operator
Company Name: HALKIDIKI AUTO CENTER INC.
Contact Type: Not reported
Contact Name: COSTAS STEFADOUROS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 932-7171
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-10-07

Site Id: 21435
Affiliation Type: Emergency Contact
Company Name: HALKIDIKI AUTO CENTER
Contact Type: Not reported
Contact Name: COSTAS STEFADOUROS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (347) 987-0606
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2010-10-07

Site Id: 21435
Affiliation Type: Facility Owner
Company Name: HALKIDIKI AUTO CENTER
Contact Type: Not reported

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Contact Name:	Not reported
Address1:	33-21 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 932-7171
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-10-07

Site Id:	21435
Affiliation Type:	Mail Contact
Company Name:	HALKIDIKI AUTO CENTER
Contact Type:	Not reported
Contact Name:	COSTAS STEFADOUROS
Address1:	33-21 21ST STREET
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11106
Country Code:	001
Phone:	(718) 932-7171
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2010-10-07

Tank Info:

Tank Number:	001
Tank ID:	39015
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well

Tank Number: 002
Tank ID: 39016
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well

Tank Number: 003
Tank ID: 39017
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Equipment Records:
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	004
Tank ID:	39018
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H04 - Tank Leak Detection - Groundwater Well
B00 - Tank External Protection - None
J01 - Dispenser - Pressurized Dispenser
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number:	005
Tank ID:	39019
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0009
Common Name of Substance:	Gasoline

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 006
Tank ID: 39020
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None

Tank Number: 007
Tank ID: 39021
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number: 008
Tank ID: 39022
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
J01 - Dispenser - Pressurized Dispenser
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
H04 - Tank Leak Detection - Groundwater Well

Tank Number: 009

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Tank ID: 48516
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1949
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 9999
Common Name of Substance: Other

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number: 010
Tank ID: 48517
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

B00 - Tank External Protection - None

Tank Number: 011
Tank ID: 48518
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
B00 - Tank External Protection - None

Tank Number: 012
Tank ID: 48519
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: Not reported
Date Tank Closed: 07/01/1994
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0000
Common Name of Substance: Empty

Tightness Test Method: 00
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: MJGRIFFI
Last Modified: 05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
F00 - Pipe External Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping

Tank Number:	013
Tank ID:	48520
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

Equipment Records:

D00 - Pipe Type - No Piping
I00 - Overfill - None
H00 - Tank Leak Detection - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Number:	014
Tank ID:	48521
Tank Status:	Closed - Removed
Material Name:	Closed - Removed
Capacity Gallons:	550
Install Date:	Not reported
Date Tank Closed:	07/01/1994
Registered:	True
Tank Location:	Underground
Tank Type:	Steel/carbon steel
Material Code:	0000
Common Name of Substance:	Empty
Tightness Test Method:	00
Date Test:	Not reported
Next Test Date:	Not reported
Pipe Model:	Not reported
Modified By:	MJGRIFFI
Last Modified:	05/09/2022

HALKIDIKI AUTO CENTER INC. (Continued) **U000411272**

Equipment Records:

D00 - Pipe Type - No Piping
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

BL387 **CLOSED-LACKOF RECENT INFO** **NY LTANKS** **S100145575**
SE **37-14 33RD STREET** **N/A**
1/4-1/2 **NEW YORK CITY, NY**
0.499 mi.
2634 ft. **Site 4 of 4 in cluster BL**

Relative:
Higher

Actual:
34 ft.

LTANKS:

Name:	CLOSED-LACKOF RECENT INFO
Address:	37-14 33RD STREET
City,State,Zip:	NEW YORK CITY, NY
Spill Number/Closed Date:	8905637 / 2003-03-06
Facility ID:	8905637
Site ID:	221353
Spill Date:	1989-09-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	4101
Investigator:	ADMIN. CLOSED
Referred To:	Not reported
Reported to Dept:	1989-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-09-11
Spill Record Last Update:	2003-10-24
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	37-14 33RD STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	183072
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was ADMIN.CLOSED 03/06/2003- Closed Due To The Nature / Extent Of The Spill Report"
Remarks:	"1.5K TANK FAILED PETRO TITE WITH A LEAK RATE OF -.643GPH, TANK TESTER RECOMMENDED THAT THE OWNER TAKE THE TANK OUT OF SERVICE, CLEAN & FILL WITH CEMENT, TO PUT 550 GALLON TANK IN BASEMENT.CLOSED DUE TO

CLOSED-LACKOF RECENT INFO (Continued) **S100145575**

LACK OF ANY RECENT INFO- DOES NOT MEET ANY CLEAN UP REQUIREMENTS."

All TTF:

Facility ID:	8905637
Spill Number:	8905637
Spill Tank Test:	1535986
Site ID:	221353
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	221353
Operable Unit ID:	933277
Operable Unit:	01
Material ID:	446052
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

388
East
1/2-1
0.531 mi.
2804 ft.

34-14 31ST STREET
34-14 31ST STREET
ASTORIA, NY 11106

NY SHWS **S118256210**
N/A

Relative:
Higher

Actual:
50 ft.

SHWS:

Name:	34-14 31ST STREET
Address:	34-14 31ST STREET
City,State,Zip:	ASTORIA, NY 11106
Program:	HW
Site Code:	514253
Classification:	P
Region:	2
Acres:	0.092
HW Code:	241179
Record Add:	09/28/2015
Record Upd:	12/29/2017
Updated By:	JHOCONNE
Site Description:	"Location: The 4,000 square feet site is located at 34-14 31st Street in the Borough of Queens, Queens County, NY in an urban area. Site

34-14 31ST STREET (Continued) **S118256210**

Features: The Site currently consists of a 2-story commercial building which has been utilized as an auto repair shop since around 1936. Current Zoning and Land Use: The site is currently zoned as R5 (lower density residential districts) and is adjacent to an elevated subway track along 31st Street. The site is bounded to the north by a residential building, to the east by 31st Street, to the south by a commercial building, and to the west by residential buildings along 30th Street. Past Use of the Site: The Site is currently occupied by a 2-story structure which operates as an auto repair shop. A Phase I conducted in May 2015 identified the site s current and past use as an auto repair shop as well as the presence of 2 above-ground storage tanks as recognized environmental conditions. Site Geology and Hydrogeology: Boring logs were not provided with the Phase II ESA and a description of site-specific geology and hydrogeology was not included as part of the report."

Env Problem: "Nature and Extent of Contamination: Prior to Completion of Remediation Based on preliminary investigations, the primary contaminants of concern were volatile organic compounds (VOCs). Soil The chlorinated solvent tetrachloroethylene (PCE) was identified in one of four soil samples above the Unrestricted Use SCOs (UUSCOs) in parenthesis. PCE was detected at a concentration of 4.8 ppm (1.3 ppm). Several metals were detected above UUSCOs and included lead up to 193 ppm (63 ppm), mercury up to 0.47 ppm (0.18 ppm), and nickel up to 39.6 ppm (30 ppm). No SVOCs, PCBs, or pesticides were detected above the UUSCOs. Groundwater Several attempts were made to collect groundwater samples, but groundwater was not encountered to the maximum depth investigated. Soil Vapor PCE and trichloroethene (TCE) were found in the indoor sub-slab air sample at 918 ug/m3 and 54.6 ug/m3 respectively. A corresponding indoor air sample found PCE at 0.215 ug/m3. Post-Remediation Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were PCE in soil and PCE and TCE in soil vapor. Remedial actions have successfully achieved soil cleanup objectives for unrestricted use and applicable guidance values for soil vapor and indoor air samples. "

Health Problem: "Remedial actions are complete and have eliminated the potential for contact with site-related contaminants."

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 4
Sub Type: E
Owner Name: Adrian Goldenberg
Owner Company: Coo-Kee, Inc.
Owner Address: 34-14 31st Street
Owner Addr2: Not reported
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America

34-14 31ST STREET (Continued) **S118256210**

HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

389
ESE
1/2-1
0.557 mi.
2943 ft.

FORMER LUFT CO. INC. COSMETICS MANUFACTURER
34-12 36TH AVENUE
LONG ISLAND CITY, NY 11106

NY SHWS **U001831683**
NY Spills **N/A**

Relative:
Higher

Actual:
40 ft.

SHWS:

Name:	FORMER LUFT CO. INC. COSMETICS MANUFACTURER
Address:	34-12 36TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11106
Program:	HW
Site Code:	460318
Classification:	N
Region:	2
Acres:	0.920
HW Code:	241139
Record Add:	01/25/2012
Record Upd:	07/23/2019
Updated By:	JHOCONNE

Site Description: "Location: The Site is located at 34-12 36th Avenue, Long Island City, NY in an urban area. It consists of a four-story public school building with a partial basement and a total floor area of approximately 40,000 square feet. The school occupies the first 3 floors and the owner occupies the top floor. Site Features: The Site is bounded by 36th Avenue to the north followed by two four-story residential buildings, 35th Street to the east followed by two-story commercial buildings, two-story commercial and residential properties to the south, and three- and four-story residential with first floor commercial spaces to the west. Current Zoning/Use(s): The site is zoned as M1-1, and is surrounded by industrial, commercial and residential uses. Historic Use(s): The Site was a commercial building occupied by various manufacturing and warehousing entities including a cosmetic manufacturing firm from at least 1934 to approximately 1967. The Site was renovated for use as a public school in 2002. Site Topography, Geology and Hydrogeology: The Site is generally level and the surrounding area slopes downward from north to south. The geology of Queens County consists of unconsolidated glacial deposits overlying crystalline bedrock at about 80 feet below ground surface (bgs). Soil cores collected during prior investigations generally consisted of fill material containing brown sandy silt with some gravel, to a depth of 8 feet bgs. The Site is located 1.1 miles east of the East River and approximately 1.5 miles northeast of Newtown Creek. Groundwater is at 18 to 21 feet bgs. The hydraulic gradient direction is towards the southwest. The site did not qualify for addition to the Registry of Inactive Hazardous Waste Disposal Sites. The source of the contamination noted on-site was determined to be from an upgradient property. See site no. C241149 for further

FORMER LUFT CO. INC. COSMETICS MANUFACTURER (Continued) **U001831683**

updates."

Env Problem: "Nature and Extent of Contamination: The Supplemental Site Investigation (SSI) dated April 2012 indicated that the presence of tetra-chloroethylene (PCE) and its breakdown products at elevated concentrations in the underlying groundwater. The subsequent Addendum to the SSI performed in June 2012 revealed the presence of these chlorinated volatile organic compounds (CVOCs) at even higher concentrations in nearby upgradient locations. Soil - There were no volatile organic compounds detected in soil samples at concentrations at or above the Unrestricted Use Soil Cleanup Objectives (UUSCOs). Twelve of sixty-five semi-volatile organic compounds (SVOCs) were detected in one or more soil samples. However, none were detected above the UUSCOs. Seven of the eight metals analyzed for were detected, but only lead and silver were detected at concentrations exceeding the UUSCOs. These were attributed to the characteristics of the fill material. PCBs were not detected in any of the soil samples. Groundwater - On-site: Three VOCs, namely PCE (450 ppb), tri-chloroethylene (TCE-15 ppb), and cis-1,2-dichloroethylene (DCE-24 ppb)were detected in groundwater samples at levels exceeding groundwater standards. Off-site: PCE and one or more of its breakdown products were detected above Class GA Standards in all of the groundwater samples save one. The highest concentrations of these CVOCs were detected in samples from monitoring wells located directly in front of the dry cleaning concern at 35-45 35th Street (13,600 ppb) and at the intersection of 35th Street and 36th Avenue (5,500 ppb -50 feet southwest of the dry cleaning concern) northeast of and directly upgradient of the Site. Sub-slab soil vapor - Sixteen petroleum and chlorinated solvent related VOCs were detected in one or more of the four sub-slab soil vapor samples. Concentrations of 1,1-Dichloroethane (DCA), 1,2,4-Trimethylbenzene (TMB), 1,3,5-Trimethylbenzene, cis-1,2-Dichloroethene (DCE), PCE and TCE were detected at concentrations greater than the range of published background concentrations. PCE and TCE were detected at concentrations exceeding the NYSDOH Air Guideline Values (AGVs) in all four samples. Indoor Air - Fifteen petroleum and chlorinated solvent related VOCs were detected in at least one of the two indoor air samples. The concentrations of 1,2,4-TMB, 1,3,5-TMB and PCE exceeded the range of corresponding background indoor air concentrations. However, the concentration of PCE was below the corresponding NYSDOH AGV. A subsequent indoor air sampling event confirmed these findings. Outdoor Air - PCE was detected in the outdoor air sample at a concentration well below the concentrations found in indoor air and TCE was not detected in the outdoor air sample, indicating that the presence of these compounds in indoor air did not originate from ambient conditions. Significant Threat: The results of the SSI groundwater analysis revealed that PCE, TCE and cis-1,2-DCE were detected at concentrations above the NYSDEC groundwater standard on-site. The presence of these VOCs in groundwater did not appear to be attributable to an on-site source as there was no corresponding detections at high concentrations in soil samples. However, as the Addendum to the SSI revealed there are greater levels of CVOC contamination in nearby off-site upgradient locations and this is most likely the source of on-site CVOC contamination. CVOCs detected at elevated concentrations in sub-slab soil vapor and indoor air are attributable to the the contamination in groundwater. Comparisons of the sub-slab soil vapor concentrations of PCE and TCE to indoor air concentrations indicate that the vapor

FORMER LUFT CO. INC. COSMETICS MANUFACTURER (Continued) **U001831683**

intrusion pathway is complete and, as per the NYSDOH decision matrices, mitigation is the recommended action. Therefore, a Sub-Slab Depressurization System was installed and is operating to prevent soil vapor migration into the building."

Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	4
Sub Type:	NNN
Owner Name:	Lee Guterman
Owner Company:	NYSCA
Owner Address:	30-30 Thomson Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Sharif El Fouly
Owner Company:	Sharif Designs Ltd.
Owner Address:	34-12 36th Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11106
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	SOIL
Address:	34-12 36TH ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1010245 / 2010-12-31
Facility ID:	1010245
Facility Type:	ER
DER Facility ID:	398753
Site ID:	443842
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	4101

FORMER LUFT CO. INC. COSMETICS MANUFACTURER (Continued) **U001831683**

Spill Date:	2010-12-31
Investigator:	HRAHMED
Referred To:	Not reported
Reported to Dept:	2010-12-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-12-31
Spill Record Last Update:	2010-12-31
Spiller Name:	Not reported
Spiller Company:	METRO FUEL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	RENEE LEWIS
DEC Memo:	"12/31/10-HRAHMED-Spoke to Rene Lewis (917 420 8330) of Alliance Mechanical. As per him, 5-7 gal of #6 oil spill from the vent line due to overfill. Noticed oil stain on the wall and side walk. PTC powewashed the wall and the sidewalk. There was no spill in the tankroom. Uploaded closure report and some picture in eDocs. This case is closed. "
Remarks:	"Caller advised overfill of tank. Clean up is in process."

All Materials:

Site ID:	443842
Operable Unit ID:	1194289
Operable Unit:	01
Material ID:	2190050
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

390
SE
1/2-1
0.560 mi.
2957 ft.

AMTRAK SUNNYSIDE YARD
39-29 HONEYWELL STREET
LONG ISLAND CITY, NY 11101

NY SHWS **S103575644**
NY LTANKS **N/A**
NY TANKS
NY Spills

Relative:
Higher

Actual:
19 ft.

SHWS:

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW
Site Code:	57794

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 133.000
HW Code: 241006
Record Add: 11/18/1999
Record Upd: 08/01/2022
Updated By: JHOCONNE
Site Description: "Location: Sunnyside Yard (the Site) is located at 39-29 Honeywell Street, Long Island City, Queens County, New York. Site Features: The Site is a railroad maintenance and storage facility that currently encompasses approximately 133 acres. The Site is bordered by commercial/residential properties, with Northern Boulevard located to the north, 42nd Place located to the east, Thompson Avenue to the west, and Skillman Avenue located to the south. Newtown Creek, which defines the border between Queens and Kings Counties, is located less than 0.5 mile south of the western portion of the Site. Current Zoning/Use: The Site is located in Manufacturing Zone (M1-1) and used as a railroad maintenance and storage facility Historic Use: The Yard was originally constructed in the early 1900s by the Pennsylvania Tunnel and Terminal Company, a subsidiary of Pennsylvania Railroad (later known as the Penn Central Transportation Company). On April 1, 1976, the Consolidated Rail Corporation (Conrail) acquired the Site, and the same day conveyed it to Amtrak, which has continued to operate it as a storage and maintenance facility for railroad rolling stock. Prior to September 29, 1961, a portion of the yard was owned by Long Island Rail Road (LIRR). Today, the LIRR maintains a right-of-way through the Yard. LIRR is constructing tunnels through the Yard as part of its East Side Access (ESA) project. Operable Units: The site is divided into six operable units. An operable unit represents a portion of a remedial program for a site that for technical or administrative reasons can be addressed separately to investigate, eliminate or mitigate a release, threat of release or exposure pathway resulting from the site contamination. The operable units for this site are: Operable unit 1 (OU1) is the soil above the water table within the footprint of the High Speed Trainset Facility Service and Inspection (HSTF S & I) Building. Operable unit 2 (OU2) is the soil above the water table within the footprint of the HSTF S & I Building ancillary structures. Operable unit 3 (OU3) is the soil and separate phase petroleum hydrocarbon accumulation above the water table and soil below the water table within 8 acres in the north central portion of the Site. Operable unit 4 (OU4) is the soil above the water table (unsaturated zone) at the Site, excluding OU-1, OU-2, and OU-3. Operable unit 5 (OU5) is the sewer system beneath the Site. Operable unit 6 (OU6) is the groundwater and saturated soil beneath the Site. Site Geology and Hydrology: Historic fill on the Site is predominantly comprised of reworked glacial deposits (unstratified sand, silt, clay and gravel) and railroad ballast, with lesser amounts of ash, cinders and construction debris. With the exception of paved areas, land occupied by buildings, and vegetated areas, the railroad ballast is ubiquitous at the land surface throughout the Site. Groundwater beneath the Site occurs in fill deposits or native deposits. The saturated native deposits comprise the Upper Glacial aquifer. The depth to groundwater across the Site varies from one to fifteen feet below ground surface. Groundwater within the shallow deposits flows predominantly west across the Site. However, groundwater between Queens Boulevard and Honeywell Street flows

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

northerly and northwesterly toward the buried flow path of the former Dutch Kills Creek. In the deeper deposits, groundwater predominantly flows west across the Site. "

Env Problem: "Nature and Extent of Contamination: Prior to Remediation: Remedial investigations have been conducted in multiple phases under NYSDEC oversight pursuant to the consent order. Seventeen specific areas of concern (AOCs) were identified. Operable Unit 1: Polychlorinated biphenyls (PCBs) were detected in 16 of 19 soil samples; all but one were less than 1 parts per million (ppm). The maximum concentration was 2 ppm. Six semi-volatile organic compounds (SVOCs), specifically polycyclic aromatic hydrocarbons (PAHs), were detected above Technical and Administrative Guidance Memo (TAGM) 4046 Recommended Soil Cleanup Objectives (RSCOs) at depths up to three feet below ground surface (bgs). However, there was only one exceedance of the site specific soil cleanup level (SSSCL) of 10 ppm. Operable Unit 2: The soil above groundwater was sampled at depths up to three feet bgs. PCBs were detected in 15 of the 20 samples at a maximum concentration of 4.5 ppm. The other compounds of concern, lead and total PAHs, were also detected at levels below the SSSCLs of 1000 ppm and 25 ppm respectively. Therefore, No Action was selected in the Record of Decision (ROD) for OU2. Operable Unit 3: Surface Soil - The SSSCLs were exceeded for PCBs (2 out of 102 samples); lead (3 out of 3) and cPAHs (2 out of 27). The maximum concentration for PCBs was 73 ppm; for lead it was 1,080 ppm and cPAHs 108 ppm. Additionally, half an acre of visible petroleum contaminated surface soil was delineated at an average depth of one foot bgs. Subsurface Soil - There were no exceedances of the SSSCLs for the contaminants of concern. Waste Materials - The waste material onsite consists of PCB contaminated petroleum present in: (1) surface soils as mentioned above; (2) a potentially mobile separate phase hydrocarbon (SPH) plume floating over the groundwater surface; (3) a residual SPH trapped in soil pores below the water table; and (4) residues in underground structures. Sixty-five samples of SPH were collected and analyzed for PCBs. The maximum concentration was 360 ppm. SPH and sludge samples taken from underground structures contained PCB concentrations of 512 and 517 ppm respectively. Operable Unit 4: Surface Soil - There were exceedances of the SSSCLs for PCBs, lead and PAHs. The maximum PCB concentration was 25,000 ppm; PAH was 113 ppm and lead was 7,020 ppm. Subsurface Soil - There were exceedances in soil samples for the SSSCLs for PCBs, lead and PAHs. The maximum PCB concentration was 3500 ppm; lead was 2600 ppm and PAH was 119 ppm. Operable Unit 5: Sewer Sediment - PCBs were detected in sediment from the sewers at concentrations ranging from 0.053 ppm to 120 ppm, which exceeds the SSSCL of 25 ppm. MH-6 was remediated as an IRM in October 2011. Sewer Water - Discrete water samples (filtered and unfiltered) were collected from 12 manhole locations and analyzed for PCBs during performance of the OU-5 RI. PCBs were detected in 17 of 39 unfiltered samples with concentrations ranging from 0.14 parts per billion (ppb) to 83 ppb. Five of the unfiltered samples also exceeded the 1 ppb waste water effluent limit. The waste water effluent limit is appropriate since the sewer discharges to a Waste Water Treatment Plant. Only one of the 39 filtered samples contained PCBs at a concentration (1.8 ppb) slightly exceeding the 1 ppb waste water effluent limit. Operable Unit 6: Saturated Subsurface Soil - A total of 159 samples of soil were collected from 29 boring locations. There were no exceedances of the SSSCLs for the contaminants of concern. Groundwater - Three plumes of chlorinated volatile organic compounds

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

(CVOCs) were defined at the site. However, none of these were attributable to site operations, but are attributable to off-site sources. No site related groundwater contamination of concern was identified. Post Remediation: Remediation has been completed in OU-1 where 472 tons of contaminated soil, fill and debris were excavated and disposed of along with 280 cubic yards of concrete and asphalt and 2,450 gallons of liquid. A No Action ROD was issued for OU-2. Remediation has been initiated at OU-3 and OU-4. The OU-5 ROD for cleaning the sewers was issued on March 27, 2011, and the OU-6 ROD (No Action) was issued on March 30, 2010. "

Health Problem:	"Groundwater in the area of the site is not used as a source of potable water. Access to the site is controlled, preventing trespassers from coming in contact with contaminated soils."
Dump:	True
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	1910
Disp Term:	unknown
Lat/Long:	40:45:03:0 / 73:56:01:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	2013-09-19 14:35:00
Updated By:	kbdilige
Own Op:	4
Sub Type:	E
Owner Name:	JOSEPH P. DEVITO
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	39-29 HONEYWELL ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Not reported
Owner Company:	PENNSYLVANIA RAILROAD - AMTRAK
Owner Address:	400 N. CAPITOL ST. NW
Owner Addr2:	Not reported
Owner City,St,Zip:	WASHINGTON, DC 20001
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	National Rail Passenger Corporation
Owner Address:	400 North Capitol Street NW
Owner Addr2:	Not reported
Owner City,St,Zip:	Washington, DC 20001
Owner Country:	United States of America

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Public Library
Owner Address:	Sunnyside Branch
Owner Addr2:	43-06 Greenpoint Avenue
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Amtrak - Sunnyside Yard
Owner Address:	39-29 Honeywell Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	01
Owner Name:	Not reported
Owner Company:	Amtrak and New Jersey Transit Corp
Owner Address:	39-29 Honeywell Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Sunnyside, NY 11101
Owner Country:	United States of America
HW Code:	241006
Waste Type:	BENZO(A)ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	XYLENE (MIXED)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	1,2,4-TRICHLOROBENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	POLYCHLORINATED BIPHENYLS (PCB)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	FLUORANTHENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	ANTHRACENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241006
Waste Type:	BENZO(B)FLUORANTHENE

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241006
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241006
Waste Type: BENZO[K]FLUORANTHENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241006
Waste Type: indeno(1,2,3-cd)pyrene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241006
Waste Type: BENZ(A)ANTHRACENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241006
Waste Type: Chrysene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 0310802
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2020-02-11 11:22:00
Record Updated: 2020-02-11 11:22:00
Updated By: JHOCONNE
Crossref ID: 9300199
Cross Ref Type Code: 01
Cross Ref Type: Spill No.
Record Added Date: 2013-06-11 10:57:00
Record Updated: 2013-06-11 10:57:00
Updated By: HRAHMED
Crossref ID: P-79652
Cross Ref Type Code: 11
Cross Ref Type: ICS ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2005-02-24 15:54:00
Updated By: INITIAL

LTANKS:
Name: CLOSED-LACKOF RECENT INFO
Address: 39-29 HONEYWELL STREET
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9013163 / 2003-03-14
Facility ID: 9013163
Site ID: 97453
Spill Date: 1991-03-23
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: ADMIN. CLOSED
Referred To: Not reported
Reported to Dept: 1991-03-26

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-04
Spill Record Last Update:	2004-03-30
Spiller Name:	Not reported
Spiller Company:	AMTRAK
Spiller Address:	39-29 HONEYWELL STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	86808
DEC Memo:	""
Remarks:	"20K TANK FAILED,CONTRACTOR WILL PUMP TANK,PRESENTLY ROUX ASSOCIATES PERFORMING SITE ASSESSMENT,SITE IS PART OF RIFF PROJECT,JAMES QUINN, DEC REMEDIAL ACTION (518-457-3395). CLOSED DUE TO LACK OF ANY RECENT INFO - DOES NOT MEET ANY CLEANUP REQUIREMENTS. "

All TTF:

Facility ID:	9013163
Spill Number:	9013163
Spill Tank Test:	1538365
Site ID:	97453
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	97453
Operable Unit ID:	950385
Operable Unit:	01
Material ID:	426055
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Groundwater

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Oxygenate: Not reported

Name: AMTRAK SUNNYSIDE YARD
Address: 39-29 HONEYWELL STREET
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9207333 / 2003-11-24
Facility ID: 9207333
Site ID: 97456
Spill Date: 1991-01-01
Spill Cause: Tank Failure
Spill Source: Non Major Facility > 1,100 gal
Spill Class: A3
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1992-09-24
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1992-09-28
Spill Record Last Update: 2003-11-24
Spiller Name: ENVIRONMENTAL DEPT
Spiller Company: NATIONAL RAILROAD PASS
Spiller Address: 400 WEST 31ST STREET, 4TH
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 86808
DEC Memo: ""
Remarks: "ALL 14 TANKS CLEANED AND FILLED W/CONCRETE 4 TEST BORINES DONE 2/10/92, 4 EA MONITORING WELLS 3/3/92 INDICATES CONTAMINATED SOIL AND G/W CLOSED SITE 1960"

All Materials:
Site ID: 97456
Operable Unit ID: 970974
Operable Unit: 01
Material ID: 407971
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Resource Affected: Groundwater
Oxygenate: Not reported

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

TANKS:

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Facility Id:	2-323497
Region:	STATE
DEC Region:	2
Site Status:	Active
Program Type:	PBS
Expiration Date:	08/23/2023
UTM X:	590181.07499
UTM Y:	4511737.51069

SPILLS:

Name:	AMTRAK
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0401755 / 2007-11-20
Facility ID:	0401755
Facility Type:	ER
DER Facility ID:	86808
Site ID:	311577
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	4101
Spill Date:	2004-05-14
Investigator:	kkchanda
Referred To:	Not reported
Reported to Dept:	2004-05-18
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-05-18
Spill Record Last Update:	2008-10-06
Spiller Name:	HARRY SUEBERT
Spiller Company:	AMTRACK
Spiller Address:	3929 HONEYWELL STREET
Spiller Company:	001
Contact Name:	HARRY SUEBERT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 7/9/07: Reassigned to Kartik Chanda (Chanda) 9/10/07: Kartik Chanda of DEC has reviewed this spill case and sent a letter to National Railroad Passenger, 400 West 31st St., 4th Floor, NY, NY 10001, Attn: Emma Cattafi requiring that the following information be submitted to DEC for review by 10/25/07: 1. An explanation of the cause of the tank/equipment failure; 2. Either a

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

description of the work
performed to restore the integrity of the tank system (including retesting results), or a
description of the work performed to close (decommission) the tank; 3. Information regarding
petroleum contamination found at the site and cleanup activities (if any) associated with a release
from this tank system; 4. Any available documentation (i.e., invoices, bills, sampling analysis
reports, etc.) pertaining to the work performed at this site
associated with this violation.
10/17/07: Chanda received a letter from Emma Cattafi, Senior Environmental Coordinator, Amtrak with
enclosed: 1. Invoices from Eadtmond describing work performed. 2.Invoices and scope of work from
CHES. 3. Soil sample analysis report. 4.Tightness test tesults. 5.Shipping paper for soil disposal.
11/19/07: Chanda reviewed soil sample analytical results and UST tightness test results for this
spill and has the following comments: 1. On May 14, 2004, the oil was found during the soil
excavation phase of a project to upgrade/ retrofit an existing 20,000-gallon UST. 2. Amtrak
estimated a release of approximately 10 gallon of #2 fuel oil. 3. Clean Harbors Environmental
Services(CHES) excavated the contaminated soil surrounding the tank. VOCs and SVOCs were not
detected in soil analytical results. Kartik Chanda discussed with Joe Sun (NYSDEC) regarding the
findings of the soil analytical results and based on the information presented to the Department,
DEC closed this spill, dated 11/20/07. 11/21/07: Chanda sent an NFA letter to Ms.Emma Cattafi,
Senior Environmental Coordinator, AMTRAK, by regular mail. "

Remarks: "LEAKING BAD FILL PIPE: IN PROCESS OF CLEANING UP: "

All Materials:

Site ID:	311577
Operable Unit ID:	883594
Operable Unit:	01
Material ID:	492947
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	10.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK
Address:	39-29 HONEYWELL ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1412278 / 2015-04-03
Facility ID:	1412278
Facility Type:	ER

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

DER Facility ID:	415437
Site ID:	506094
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2015-03-31
Investigator:	SXMAHAT
Referred To:	Not reported
Reported to Dept:	2015-03-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-03-31
Spill Record Last Update:	2015-10-28
Spiller Name:	CHRIS BENSON
Spiller Company:	AMTRAK
Spiller Address:	39-29 HONEYWELL ST
Spiller Company:	999
Contact Name:	CHRIS BENSON
DEC Memo:	"3/31/15: Mahat t/c: DEC Mahat contancted Mr. Benson ans asked him to send some picture and closure report as clean up is done by retained contractor. DEC is waiting for a closure report. 4/3/15: Mahat E/C: DEC Mahat received an narrative clean up report from Mr. Benson. Absorbents were applied to the effected concrete to. Affected soils were excavated to a depth of 9 , and concrete was scrubbed with a degreasing agent to remove any remaining product. The area was returned to service, 2x drums of oily solids were generated. V/R, Chris Benson Senior Environmental & Safety Analyst New York - Operations AMTRAK 39-29 Honeywell St. Long Island City, NY, 11101 Cell 917-538-2982 ATS 521-6084 Office 212-630-6084 christian.benson@amtrak.com Based on the report and the facility and initial picture. The Department does not warranr any further investigation. Spill case will be closed in DEC Spill Database. "
Remarks:	"rain caused buckets to lose fluid to soil, c/u pending by Phillip Service"

All Materials:

Site ID:	506094
Operable Unit ID:	1255405
Operable Unit:	01
Material ID:	2258141
Material Code:	0811A
Material Name:	compressor oil
Case No.:	Not reported
Material FA:	Petroleum

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK
Address:	39-29 HONEYWELL ST
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	1112990 / 2012-02-14
Facility ID:	1112990
Facility Type:	ER
DER Facility ID:	415437
Site ID:	460959
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	4101
Spill Date:	2012-02-13
Investigator:	vszhune
Referred To:	Not reported
Reported to Dept:	2012-02-14
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-02-14
Spill Record Last Update:	2012-02-14
Spiller Name:	CHRIS BENSON
Spiller Company:	AMTRAK
Spiller Address:	39-29 HONEYWELL ST
Spiller Company:	999
Contact Name:	CHRIS BENSON
DEC Memo:	"02/14/12- Christian Benson from Amtrack sent the following email: Around appx 1500hrs, 13FEB12, while replacing fuel in a portable heating unit, an Amtrak employee noticed fuel leaking from the underside of the fuel tank. The employee notified their supervisor, who instructed them to bring it to the motor pool area, away from the track area. The employee tilted the unit upwards to move product away from the hole. Upon reaching the motor pool, the employee had to tilt the unit back down, allowing product to begin leaking again. It is now estimated that only 1.2 gallons were released as employees were able to remove remaining product from the tank and place into a separate drum. The spilled material was contained with absorbent boom, pads, and sand. Clean-up was completed the morning of 14FEB12, and all wastes were placed into a

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

drum for disposal. S-200
product will be used to further ensure full remediation of the area.
Product was only released on
impermeable surface, no waterways or soil was affected. Spill Closed.
"

Remarks: "Caller reporting a spill of 5 gallons of #1 fuel oil (kerosene) to concrete. Clean up is in progress."

All Materials:

Site ID:	460959
Operable Unit ID:	1211057
Operable Unit:	01
Material ID:	2208758
Material Code:	0012A
Material Name:	kerosene
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Resource Affected:	Not reported
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9113048 / 1992-03-25
Facility ID:	9113048
Facility Type:	ER
DER Facility ID:	86808
Site ID:	97455
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1992-03-25
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1992-03-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Railroad Car
Spill Notifier:	Federal Government
Cleanup Ceased:	1992-03-25
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-03-31
Spill Record Last Update:	2003-11-24
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Remarks: "LOCOMOTIVE # 621; TRANSFORMER OVERHEATED. OIL ON SOIL. SORBENT APPLIED. CLEANUP CONFIRMED."

All Materials:

Site ID:	97455
Operable Unit ID:	966658
Operable Unit:	01
Material ID:	414583
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0103793 / 2003-06-26
Facility ID:	0103793
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219136
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	2001-07-10
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2001-07-10
CID:	382
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-10
Spill Record Last Update:	2004-03-30
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"A leak from either pipe or tank of a low ph car wash fluid - leak found while repairing tank. most contained to inside area but some seepage into ground. clean up in progress by clean harbors and amtrack"

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

All Materials:

Site ID:	219136
Operable Unit ID:	840419
Operable Unit:	01
Material ID:	535869
Material Code:	0045A
Material Name:	cleaning chemicals/products
Case No.:	Not reported
Material FA:	Other
Quantity:	50.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0109691 / 2003-11-24
Facility ID:	0109691
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219137
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	2002-01-05
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2002-01-05
CID:	398
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-01-05
Spill Record Last Update:	2003-11-24
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	RICHARD MOHLENHOFF
DEC Memo:	""
Remarks:	"Caller was unsure if leak from there equipment or contractors. No call back requested."

All Materials:

Site ID:	219137
Operable Unit ID:	848051
Operable Unit:	01

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Material ID:	527340
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0200853 / 2003-10-17
Facility ID:	0200853
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219138
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	2002-04-20
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2002-04-23
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-23
Spill Record Last Update:	2004-03-30
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"Broken hose on loader. cleanup completed."

All Materials:

Site ID:	219138
Operable Unit ID:	851686
Operable Unit:	01
Material ID:	522282
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	35.00

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	0303007 / 2003-08-29
Facility ID:	0303007
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219139
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	2003-06-21
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	2003-06-21
CID:	390
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-21
Spill Record Last Update:	2003-11-24
Spiller Name:	HARRY SEUBERT
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	JOHN PIELLI
DEC Memo:	""
Remarks:	"Hose on a crane failed - spilling material - clean harbors in enroute for clean up"

All Materials:

Site ID:	219139
Operable Unit ID:	869827
Operable Unit:	01
Material ID:	507450
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9804210 / 1998-08-27
Facility ID:	9804210
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219140
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	4101
Spill Date:	1998-07-02
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-07-03
CID:	365
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-03
Spill Record Last Update:	2003-11-24
Spiller Name:	ENVIRONMENTAL DEPT
Spiller Company:	NATIONAL RAILROAD PASSENG
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	RICHARD MOHLENHOFF
DEC Memo:	""
Remarks:	"Small railroad tie fire occurred last night - drum near by spilled - clean up in progress"

All Materials:

Site ID:	219140
Operable Unit ID:	1065071
Operable Unit:	01
Material ID:	318926
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9811804 / 2003-11-24
Facility ID:	9811804

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Facility Type:	ER
DER Facility ID:	86808
Site ID:	219141
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	4101
Spill Date:	1998-12-18
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1998-12-18
CID:	257
Water Affected:	Not reported
Spill Source:	Non Major Facility > 1,100 gal
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-18
Spill Record Last Update:	2004-04-02
Spiller Name:	RICHARD MOHLENHOFF
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	RICHARD MOHLANHOFF
DEC Memo:	""
Remarks:	"During tank removal caller found contaminated soil next to the fill lines"

All Materials:

Site ID:	219141
Operable Unit ID:	1069067
Operable Unit:	01
Material ID:	312087
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Groundwater
Oxygenate:	Not reported

Name:	AMTRAK SUNNYSIDE YARD
Address:	39-29 HONEYWELL STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9814658 / 2003-11-24
Facility ID:	9814658
Facility Type:	ER
DER Facility ID:	86808
Site ID:	219142
DEC Region:	2
Spill Cause:	Equipment Failure

AMTRAK SUNNYSIDE YARD (Continued) **S103575644**

Spill Class:	B3
SWIS:	4101
Spill Date:	1999-03-09
Investigator:	SIGONA
Referred To:	Not reported
Reported to Dept:	1999-03-09
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-09
Spill Record Last Update:	2003-11-24
Spiller Name:	RICHARD MOHLENHOFF
Spiller Company:	NATIONAL RAILROAD PASS
Spiller Address:	400 WEST 31ST STREET, 4TH
Spiller Company:	001
Contact Name:	RICHARD MOHLENHOFF
DEC Memo:	""
Remarks:	"FAULTY SEAL ON EQUIPMENT AT ABOVE LOCATION. MATERIAL IDENTIFIED AS CONTAINING PCB'S. CLEAN UP TO FOLLOW REPAIRS. NO BACK REQUESTED."

All Materials:

Site ID:	219142
Operable Unit ID:	1072250
Operable Unit:	01
Material ID:	311338
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access
13 additional NY SPILL: record(s) in the EDR Site Report.

391
SW
1/2-1
0.619 mi.
3269 ft.

THE WILLS BUILDING
43-01 21ST STREET
LONG ISLAND CITY, NY 11101

NY SHWS **S113916801**
NY INST CONTROL **N/A**
NY BROWNFIELDS

Relative:
Higher

Actual:
19 ft.

SHWS:

Name:	THE WILLS BUILDING
Address:	43-01 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW
Site Code:	477031

THE WILLS BUILDING (Continued) **S113916801**

Classification: N
Region: 2
Acres: 1.100
HW Code: 241143
Record Add: 12/21/2012
Record Upd: 02/21/2018
Updated By: JXGRECO
Site Description: "Location: The site is located at 43-01 21st Street in Long Island City, Queens, NY. Site transitioned to Brownfield Cleanup Program as Site #C241143. Please refer to that site number for accurate information."
Env Problem: "Site transitioned to Brownfield Cleanup Program as Site #C241143. Please refer to that site number for accurate information."
Health Problem: "As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: E
Owner Name: Not reported
Owner Company: Wills Group Family Limited Partnership
Owner Address: 254 E 68th St; Apt 26E
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10065-6017
Owner Country: United States of America
Own Op: 1
Sub Type: E
Owner Name: Not reported
Owner Company: Wills Group Family LP
Owner Address: 43-01 21st St.
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101-5023
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

INST CONTROL:
Name: THE WILLS BUILDING

THE WILLS BUILDING (Continued) **S113916801**

Address:	43-01 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Site Code:	490427
Control Name:	Landuse Restriction
HW Code:	C241143
Control Code:	25
Control Type:	INST
Dt record added:	09/14/2015
Dt rec updated:	06/02/2021
Updated By:	JXPEREZM
Site Code:	490427
Site Description:	"Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False

THE WILLS BUILDING (Continued) **S113916801**

Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)

THE WILLS BUILDING (Continued) **S113916801**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: IC/EC Plan
HW Code: C241143
Control Code: 34
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM
Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs).

THE WILLS BUILDING (Continued) **S113916801**

Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America

THE WILLS BUILDING (Continued) **S113916801**

HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: Ground Water Use Restriction
HW Code: C241143

THE WILLS BUILDING (Continued) **S113916801**

Control Code:	08
Control Type:	INST
Dt record added:	09/14/2015
Dt rec updated:	06/02/2021
Updated By:	JXPEREZM
Site Code:	490427
Site Description:	"Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-01-03 15:39:00

THE WILLS BUILDING (Continued) **S113916801**

Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN

THE WILLS BUILDING (Continued) **S113916801**

Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: Soil Management Plan
HW Code: C241143
Control Code: 14
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM
Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a

THE WILLS BUILDING (Continued) **S113916801**

lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143

THE WILLS BUILDING (Continued) **S113916801**

Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: Monitoring Plan
HW Code: C241143
Control Code: 31
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM

THE WILLS BUILDING (Continued) **S113916801**

Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith

THE WILLS BUILDING (Continued) **S113916801**

Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00

THE WILLS BUILDING (Continued) **S113916801**

Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: Site Management Plan
HW Code: C241143
Control Code: 32
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM
Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

THE WILLS BUILDING (Continued) **S113916801**

Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-01-03 15:39:00
Record Upd:	2015-12-03 08:29:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Public Library - Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Patricia Dunphy
Owner Company:	43-01 21st Street L.L.C.
Owner Address:	15 East 26th St., 7th Fl
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Patricia Dunphey
Owner Company:	43-01 21st Street L.L.C.
Owner Address:	15 East 26th St.
Owner Addr2:	7th Floor
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
HW Code:	C241143
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	BENZO(A)PYRENE

THE WILLS BUILDING (Continued) **S113916801**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: O&M Plan
HW Code: C241143
Control Code: 33
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM
Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete

THE WILLS BUILDING (Continued) **S113916801**

3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "

Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America

THE WILLS BUILDING (Continued) **S113916801**

Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier

THE WILLS BUILDING (Continued) **S113916801**

Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

Name: THE WILLS BUILDING
Address: 43-01 21ST STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Site Code: 490427
Control Name: Environmental Easement
HW Code: C241143
Control Code: J
Control Type: INST
Dt record added: 09/14/2015
Dt rec updated: 06/02/2021
Updated By: JXPEREZM
Site Code: 490427
Site Description: "Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem: "Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air

THE WILLS BUILDING (Continued) **S113916801**

quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2014-01-03 15:39:00
Record Upd: 2015-12-03 08:29:00
Updated By: JXGRECO
Own Op: Document Repository
Sub Type: NNN
Owner Name: Tienya Smith
Owner Company: Queens Public Library - Long Island City Branch
Owner Address: 37-44 21st Street
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11101
Owner Country: United States of America
Own Op: 6
Sub Type: P03
Owner Name: Patricia Dunphy
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St., 7th Fl
Owner Addr2: Not reported
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
Own Op: 1
Sub Type: P03
Owner Name: Patricia Dunphey
Owner Company: 43-01 21st Street L.L.C.
Owner Address: 15 East 26th St.
Owner Addr2: 7th Floor
Owner City,St,Zip: New York, NY 10010
Owner Country: United States of America
HW Code: C241143
Waste Type: tetrachloroethene (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: cis-1,2-Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: BENZO(A)PYRENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: trichloroethene (TCE)
Waste Quantity: UNKNOWN

THE WILLS BUILDING (Continued) **S113916801**

Waste Code: Not reported
HW Code: C241143
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1,2-TRICHLORETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: TETRACHLOROETHYLENE (PCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: C241143
Waste Type: 1,1 Dichloroethene
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: C241143-04-14
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-09-23 11:36:00
Record Updated: 2015-09-23 11:49:00
Updated By: JXGRECO
Crossref ID: Place Holder
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-09-23 11:52:00
Updated By: JXGRECO
Crossref ID: 2015000374359
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2015-09-23 10:31:00
Record Updated: 2015-10-27 13:21:00
Updated By: JXGRECO

BROWNFIELDS:

Name:	THE WILLS BUILDING
Address:	43-01 21ST STREET
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	BCP
Site Code:	490427
Acres:	1.110
HW Code:	C241143
SWIS:	4101
Town:	New York City
Record Added Date:	01/03/2014
Record Updated Date:	11/16/2021
Update By:	GWBURKE
Site Description:	"Location: The site is located in an urban area in the Long Island City neighborhood of Queens County at the corner of 43rd Avenue and 21st Street. Site Features: The site is a 1.11-acre parcel and is currently developed with a brick and steel-reinforced concrete 3-story building with a partial basement. Current Zoning and Land Use: The site is zoned M1-4, allowing for manufacturing. The building is currently fully occupied by numerous small businesses with activities ranging from warehousing to light manufacturing work. The

THE WILLS BUILDING (Continued) **S113916801**

	surrounding area consists mostly of commercial and industrial buildings, and the nearest residential buildings appear to be over 500 feet from the site. Past Use(s) of the Site: Past land uses include x-ray equipment manufacturing, cosmetic manufacturing, clothing manufacturing and uniform service companies. Site Geology and Hydrogeology: The property is relatively flat, with an approximate ground elevation of 19 feet above mean sea level. General topography in the area of the site slopes slightly to the west. The East River is located approximately 1/2 mile west of the site. Overburden materials are comprised of brown sands, silty sands, and trace amounts of fine gravel. Bedrock beneath the site has been encountered at approximately 20 feet below ground surface (bgs). Groundwater has been encountered in the overburden at approximately 12 feet bgs, and its flow is to the south. Bedrock groundwater appears to flow towards the west. "
Env Problem:	"Remediation at the site is complete. Prior to remediation, the primary contaminants of concern were tetrachloroethene and to a lesser extent, trichloroethene, in groundwater and soil vapor. The remedial action is successful in minimizing human contact with remaining contamination. Residual contamination in the soil, groundwater, and soil vapor is being managed under a Site Management Plan."
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system has been installed in the on-site building to address soil vapor intrusion. Additional sampling is needed to determine if soil vapor intrusion is a concern for off-site buildings."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2014-01-03 15:39:00
Record Upd:	2015-12-03 08:29:00
Updated By:	JXGRECO
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tienya Smith
Owner Company:	Queens Public Library - Long Island City Branch
Owner Address:	37-44 21st Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Patricia Dunphy
Owner Company:	43-01 21st Street L.L.C.

THE WILLS BUILDING (Continued) **S113916801**

Owner Address:	15 East 26th St., 7th Fl
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	Patricia Dunphey
Owner Company:	43-01 21st Street L.L.C.
Owner Address:	15 East 26th St.
Owner Addr2:	7th Floor
Owner City,St,Zip:	New York, NY 10010
Owner Country:	United States of America
HW Code:	C241143
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	cis-1,2-Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	1,1,2-TRICHLORETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241143
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C241143-04-14
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-09-23 11:36:00
Record Updated:	2015-09-23 11:49:00
Updated By:	JXGRECO
Crossref ID:	Place Holder
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-09-23 10:31:00
Record Updated:	2015-09-23 11:52:00
Updated By:	JXGRECO
Crossref ID:	2015000374359

THE WILLS BUILDING (Continued) **S113916801**

Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-09-23 10:31:00
Record Updated:	2015-10-27 13:21:00
Updated By:	JXGRECO

392
ESE
1/2-1
0.638 mi.
3367 ft.

Relative:
Higher

Actual:
37 ft.

TEITELBAUM DRY CLEANER
35-45 35TH ST
LONG ISLAND CITY, NY 11106

NY SHWS **1000400106**
NY BROWNFIELDS **NYD981132459**
RCRA NonGen / NLR
ICIS
US AIRS
FINDS
NY AIRS
NY MANIFEST
RI MANIFEST

SHWS:

Name:	TEITELBAUM DRY CLEANING INC
Address:	35-45 35TH STREET
City,State,Zip:	ASTORIA, NY 11106
Program:	HW
Site Code:	481508
Classification:	N
Region:	2
Acres:	0.260
HW Code:	241149
Record Add:	05/03/2013
Record Upd:	01/31/2014
Updated By:	JHOCONNE
Site Description:	"Location: The 11,200 square foot (0.26 acre) site is located at 3545 35th Street, Long Island City, NY in an urban area. The site is bordered by 35th Street and residential buildings to the west, by a 2 story commercial/industrial building to the north, by a parking lot to the east, by an Islamic center to the southeast, and by a 2 story commercial/industrial building to the south. Site Features: The site is occupied by a 1 to 2 story commercial dry cleaner. Current Zoning/Use(s): The site is zoned as M1-5, and is surrounded by industrial, commercial and residential uses. Historical Use(s): The Site is an industrial building conducting dry cleaning operations since 1975. The site is a RCRA large quantity generator (EPA ID # NYD981132459) of spent solvent, waste code F002. Site Topography, Geology and Hydrogeology: The Site is generally level and the surrounding area slopes downward from north to south. The geology of Queens County consists of unconsolidated glacial deposits overlying crystalline bedrock at about 80 feet below ground surface (bgs). Soil cores collected during investigation on a nearby site (site no. 241139) generally consisted of fill material containing brown sandy silt with some gravel, to a depth of 8 feet bgs. The Site is located 1.1 miles east of the East River and approximately 1.5 miles northeast of Newtown Creek. Groundwater in the vicinity of the site was encountered at approximately 17 to 20 feet bgs and flows towards the southwest."
Env Problem:	"Nature and Extent of Contamination: Information is based on the results of a site characterization investigation performed at the nearby Former Luft Co. Inc. Cosmetics Manufacturer site (241139). That investigation was triggered by the discovery of elevated levels of cVOCs in the indoor air and sub-slab vapor of the school building on that site. The subsequent Supplemental Site Investigation (SSI)

TEITELBAUM DRY CLEANER (Continued) **1000400106**

indicated that elevated concentrations of cVOCs (namely PCE) existed along the adjacent sidewalk on the western side of 35th Street and the south-eastern section of the school building. The addendum to the SSI ascertained that the Former Luft Cosmetics site was not a source of the contamination. Seven groundwater wells were installed upgradient and cross gradient of the school and samples taken at the groundwater interface. One well was installed adjacent to and another just downgradient of the Teitelbaum site. Groundwater Several cVOCs associated with chlorinated solvents, namely, tetra-chloroethylene (PCE) and its breakdown products tri-chloroethylene (TCE) and cis-1,2-dichloroethylene (cis-DCE), were detected at elevated levels from groundwater samples taken at the groundwater interface at locations along the adjacent sidewalk and downgradient of the Site. PCE, cis-DCE and TCE concentrations were at orders of magnitude of the TOGS SCG of 5 g/l; trans-DCE and 1,1-DCE were also detected at levels above the SCG. Concentrations of cVOCs decreased in the downgradient direction consistent with the inferred contaminant plume. The groundwater flow direction was identified as southwesterly by the Addendum to the Supplemental Site Investigation Report (ASSIR) of the nearby Former Luft Co. Inc. Cosmetics Manufacturer site. Significant Threat: Evaluation of significant threat will be made following completion of the Site Characterization. This Site has entered the Brownfield Cleanup Program (BCP). Executed Brownfiled Cleanup Agreement signed on 01/09/2014. See site no. C224149 for further updates."

Health Problem:	"As information for this site becomes available, it will be reviewed by the NYSDOH to determine if site contamination presents public health exposure concerns."
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	E
Owner Name:	Andrea Pampillonio
Owner Company:	S & C Properties, LLC
Owner Address:	2 Bay Club Drive Apt. 10G
Owner Addr2:	Not reported
Owner City,St,Zip:	Bayside, NY 11360
Owner Country:	United States of America
Own Op:	4
Sub Type:	03
Owner Name:	Robert Ratafia
Owner Company:	Teitelbaum Dry Cleaning Inc./F. Gusenberger & Sons Inc.
Owner Address:	35-45 35th St.
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11106
Owner Country:	United States of America
HW Code:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BROWNFIELDS:

Name:	TEITELBAUM DRY CLEANING INC.
Address:	35-45 35TH STREET
City,State,Zip:	ASTORIA, NY 11106
Program:	BCP
Site Code:	487391
Acres:	0.230
HW Code:	C241149
SWIS:	4101
Town:	New York City
Record Added Date:	09/27/2013
Record Updated Date:	07/23/2020
Update By:	JHOCONNE
Site Description:	"Location: The site is located in an urban area in the Astoria section of Queens, NY specifically at 35-45 35th street. The site is bordered by 35th Street and residential buildings to the west, by a 2-story commercial/industrial building to the north, by a parking lot to the east, by a religious center to the southeast, and by a 2-story commercial/industrial building to the south. Site Features: The site is currently improved with a commercial/manufacturing building that covers the entire site footprint with an area of 10, 000 square feet (0.23 acres). The ground floor is currently utilized for dry cleaning operations and a portion of the building contains a second floor for office space and storage. There is a small sub-grade boiler room (measuring approximately 3 ft x 5 ft) located in the northernmost corner of the property containing a fuel oil fired steam boiler, condensate tank, and sump. Current Zoning and Land Use: The site is zoned M1-5 (manufacturing and light industrial) and is surrounded by industrial, commercial and residential uses. Past Use of the Site: The site has been a commercial dry cleaner operating under various names and ownership since at least 1965 and possibly as far back as 1952. Site Geology/Hydrogeology: The site is generally level and the surrounding area slopes downward from north to south. The geology of Queens County consists of unconsolidated glacial deposits overlying crystalline bedrock at about 80 feet below ground surface (ft-bgs). The site is covered by two to five feet of surface fill material containing brown sandy silt with some gravel, underlain by fine to medium-grained sand with some silt. There is a minor clayey sand lens present within the first six feet in the southern portion of the property. Bedrock was not encountered during the remedial investigation. Groundwater was encountered at approximately 17 ft-bgs to 23 ft-bgs and generally flows to the south towards Newtown Creek. "
	Not reported
Env Problem:	"Nature and Extent of Contamination: As part of the Remedial Investigation (RI) soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Groundwater

TEITELBAUM DRY CLEANER (Continued) **1000400106**

was also analyzed for emerging contaminants (ECs). Soil vapor, sub-slab soil vapor and indoor air were analyzed for VOCs. Based upon the results of the RI, the primary contaminants of concern for the site include tetrachloroethene (PCE) and its breakdown products. Soil - Highly elevated concentrations of chlorinated VOCs (CVOCs) compared to applicable Protection of Groundwater Soil Cleanup Objectives (PGSCO) or the Unrestricted Use SCO (UUSCO) were found in soils collected from the northwestern portion of the site in proximity to an abandoned underground storage tank (UST). Concentrations of CVOCs ranged from 360 to 1100 part per million (ppm) with PCE ranging from 2 to 1,100 ppm (PGSCO is 1.3 ppm), TCE concentrations ranging from 2.4 to 21 ppm (PGSCO is 0.47 ppm), Cis-1,2-DCE concentrations ranging from 0.46 to 6.4 ppm (PGSCO is 0.25 ppm) There were also minor petroleum-related impacts in this area, which were likely the results of minor spills associated with typical UST operations, including naphthalene at 26 ppm (UUSCO is 12 ppm), xylenes ranging from 1.3 to 2.1 ppm (UUSCO is 0.26 ppm), toluene ranging from 0.78 to 0.85 ppm (UUSCO is 0.07 ppm), 1,2,4 trimethylbenzene (TMB) at 3.8 to 11 ppm (UUSCO is 3.6 ppm) and 1,3,5 TMB at 9.6 ppm (UUSCO is 8.4 ppm). The UST grave likely created a depression in the subsurface resulting in a preferential pathway for CVOCs contamination to collect. This area is considered to be the source of CVOCs contamination in groundwater and soil vapor on- and off-site. CVOC impacts in this area extend vertically from approximately 5 to 20 ft-bgs and are limited to a radius of approximately 15 to 20 feet. CVOC concentrations drastically decrease in soil outside of this radius and are generally not detected above UUSCOs outside of a 30-foot radius. Data doesn't indicate any off-site impacts in soil related to this site.
Groundwater - Groundwater results from the RI indicate that elevated concentrations of CVOCs compared to ambient water quality standards (AWQS) are present throughout the site and are migrating off-site. The most recent sampling results revealed that the on-site concentrations which exceeded AWQS for PCE ranged from 6.9 ppb to a maximum to 120 parts per billion (ppb) (AWQS is 5 ppb) in the source area mentioned above. The corresponding TCE (AWQS of 5 ppb) concentrations revealed one exceedance at 14 ppb, and cis-1,2-DCE (AWQS of 5 ppb) concentrations also revealed one exceedance of 70 ppb. CVOC contamination is consistent with current and former site operations. Off-site concentrations within the proposed plume of contamination revealed the aforementioned CVOCs at maximum concentrations of 130 ppb, 62 ppb and 860 ppb for PCE, TCE and cis-1,2-DCE respectively. PCE concentrations which exceeded AWQS ranged from 8.6 ppb to 130 ppb, TCE had one exceedance at 62 ppb and cis-1,2-DCE exceedances ranged from 8 ppb to 860 ppb. Levels of perfluorooctanesulfonic acid (PFOS) and/or perfluorooctanoic acid (PFOA) were detected at concentrations above the NYSDEC screening level of 10 ppt in all three EC groundwater samples with PFOS at a maximum concentration of 41.5 parts per trillion (ppt) and PFOA at 55.4 ppt. 1,4-dioxane was not detected in any sample. Data does not indicate that the site is a possible source of PFOS or PFOA contamination. Soil Vapor, Sub-Slab Soil Vapor and Indoor Air - The results of the RI showed PCE and TCE to be present in all eleven sub-slab vapor samples collected beneath the on-site building, as well as all indoor air samples. PCE ranged from 50.4 g/m3 to 328,000 g/m3 in sub-slab soil vapor and ranged from 10.3 g/m3 to 425 g/m3 in the indoor air samples. TCE ranged from 5.86 g/m3 to 14,500 g/m3 in sub-slab soil vapor and ranged from 2.1 g/m3 to 105 g/m3 in the

TEITELBAUM DRY CLEANER (Continued) **1000400106**

	indoor air samples. The soil vapor contamination extends off-site to the west, north and south where soil vapor sampling was done at seven location in surrounding sidewalks along 35th Street and 36th Avenue. PCE concentrations ranged from 274 g/m3 to 2,860 g/m3 and TCE concentrations ranged from 19.1 g/m3 to 47.2 g/m3. The NYSDEC and NYSDOH have determined that the Site poses a significant threat to human health. "
Health Problem:	"People who dig below the ground surface may come into contact with contaminants in subsurface soil and groundwater. Contaminated groundwater at the site is not used for drinking or other purposes and the site is served by a public water supply that obtains water from a different source not affected by this contamination. Volatile organic compounds in soil vapor (air spaces within the soil) may move into buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The potential exists for the inhalation of site contaminants in both on-site and off-site structures."
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-10-02 10:32:00
Record Upd:	2020-05-18 12:39:00
Updated By:	SNBOLLER
Own Op:	1
Sub Type:	E
Owner Name:	Andrea Pampillonio
Owner Company:	S & C Properties, LLC
Owner Address:	2 Bay Club Drive
Owner Addr2:	Apt. 10G
Owner City,St,Zip:	Bayside, NY 11360
Owner Country:	United States of America
Own Op:	6
Sub Type:	P02
Owner Name:	Andrea Pampillonio
Owner Company:	S & C Properties, LLC
Owner Address:	2 Bay Club Drive Apt. 10G
Owner Addr2:	Not reported
Owner City,St,Zip:	Bayside, NY 11360
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Robert Ratafia
Owner Company:	Red Cap Valet (lessee), d/b/a Teitelbaum Dry Cleaning Inc.
Owner Address:	35-45 35th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11106
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Logan Ragsdale

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Owner Company:	Queens Library - Broadway Branch
Owner Address:	4020 Broadway
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11103
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Florence Koulouris
Owner Company:	Queens Community Board 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	Not reported
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	C241149
Waste Type:	DICHLOROETHYLENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	1,2,4-TMB
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C241149
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

HW Code:	C241149
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C241149-12-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2020-02-10 08:25:00
Record Updated:	2020-02-10 08:25:00
Updated By:	SNBOLLER

RCRA Listings:

Date Form Received by Agency:	20180828
Handler Name:	Teitelbaum Dry Cleaner
Handler Address:	35-45 35TH ST
Handler City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA ID:	NYD981132459
Contact Name:	ANDREA PAMKPILLONIO
Contact Address:	BAY CLUB DR APT 10G
Contact City,State,Zip:	BAYSIDE, NY 11360
Contact Telephone:	917-543-8513
Contact Fax:	Not reported
Contact Email:	APAPAP13@YAHOO.COM
Contact Title:	SOLE MEMBER
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	BAY CLUB DR APT 10G
Mailing City,State,Zip:	BAYSIDE, NY 11360
Owner Name:	S & C Properties C/O Andrea Pampillonio
Owner Type:	Private
Operator Name:	Red Cap Valet - Lessee, Dba Teitelbaum Dry Cleaning Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline

TEITELBAUM DRY CLEANER (Continued) **1000400106**

2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20180828
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	S & C PROPERTIES C/O ANDREA PAMPILLONIO
Legal Status:	Private
Date Became Current:	20121217
Date Ended Current:	Not reported
Owner/Operator Address:	2 BAY CLUB DR APT 10G
Owner/Operator City,State,Zip:	BAYSIDE, NY 11360

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Owner/Operator Telephone: 917-543-8513
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: APAPAP13@YAHOO.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: S & C PROPERTIES C/O ANDREA PAMPILLONIO
Legal Status: Private
Date Became Current: 20121217
Date Ended Current: Not reported
Owner/Operator Address: 2 BAY CLUB DR APT 10G
Owner/Operator City,State,Zip: BAYSIDE, NY 11360
Owner/Operator Telephone: 917-543-8513
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: APAPAP13@YAHOO.COM

Owner/Operator Indicator: Owner
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RED CAP VALET - LESSEE, DBA TEITELBAUM DRY CLEANING INC
Legal Status: Private
Date Became Current: 20020101
Date Ended Current: Not reported
Owner/Operator Address: 1868 NIAGARA FALLS BLVD STE 205
Owner/Operator City,State,Zip: TONAWANDA, NY 14150
Owner/Operator Telephone: 718-482-7555
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: RED CAP VALET - LESSEE, DBA TEITELBAUM DRY CLEANING INC
Legal Status: Private
Date Became Current: 20020101
Date Ended Current: Not reported
Owner/Operator Address: 1868 NIAGARA FALLS BLVD STE 205
Owner/Operator City,State,Zip: TONAWANDA, NY 14150
Owner/Operator Telephone: 718-482-7555
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: OWNERNAME
Legal Status: Private
Date Became Current: Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 19990714
Handler Name: TEITELBAUM CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20060101
Handler Name: TEITELBAUM CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: TEITELBAUM CLEANERS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180828
Handler Name: TEITELBAUM DRY CLEANER
Federal Waste Generator Description: Not a generator, verified
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

Receive Date: 19850904
Handler Name: TEITELBAUM CLEANERS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20180123
Handler Name: TEITELBAUM DRY CLEANER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Code: 812320
NAICS Description: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED)

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20180523
Actual Return to Compliance Date: 20180706
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20180618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180906
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - Pre-transport
Date Violation was Determined: 20180523
Actual Return to Compliance Date: 20180706
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20180618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180906
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Violation Short Description:	TSD IS-Container Use and Management
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYSR
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 20180523
Actual Return to Compliance Date: 20180706
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20180618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180906
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Violation Short Description:	TSD IS-Preparedness and Prevention
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYSR
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19980623
Actual Return to Compliance Date: 19980910
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19980824
Enforcement Identifier: 000
Date of Enforcement Action: 19980721
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2CFP
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYSR
Enforcement Responsible Sub-Organization:	R2
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	State Statute or Regulation
Date Violation was Determined:	20180523
Actual Return to Compliance Date:	20180706
Return to Compliance Qualifier:	Documented
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20180618
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	20180906
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: TSD IS-Preparedness and Prevention
Date Violation was Determined: 20180523
Actual Return to Compliance Date: 20180706
Return to Compliance Qualifier: Documented
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 20180618
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 20180906
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYSR
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 20180523

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	19980623
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2CFP
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19980910
Scheduled Compliance Date:	19980824
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Former Citation:	Not reported
Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	20180523
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYSR
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	20180706
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

ICIS:

Enforcement Action ID:	NY000A0000263040039700308
FRS ID:	110001594310
Action Name:	TEITELBAUM CLEANERS 360811000100308
Facility Name:	TEITELBAUM CLEANERS
Facility Address:	35-45 35TH ST LONG ISLAND CITY, NY 111061608
Enforcement Action Type:	Notice of Violation
Facility County:	QUEENS
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	7216
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	40.755728
Longitude in Decimal Degrees:	-73.92572
Permit Type Desc:	Not reported
Program System Acronym:	NY0000002630400397
Facility NAICS Code:	812320
Tribal Land Code:	Not reported

US AIRS MINOR:

Envid:	1000400106
Region Code:	02
Programmatic ID:	AIR NY0000002630400397
Facility Registry ID:	110001594310

TEITELBAUM DRY CLEANER (Continued) **1000400106**

D and B Number: Not reported
Primary SIC Code: 7216
NAICS Code: 812320
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:
Region Code: 02
Programmatic ID: AIR NY0000002630400397
Facility Registry ID: 110001594310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-03-26 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400397
Facility Registry ID: 110001594310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1998-11-10 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400397
Facility Registry ID: 110001594310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 1999-02-16 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02
Programmatic ID: AIR NY0000002630400397
Facility Registry ID: 110001594310
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: MACT Standards (40 CFR Part 63)
Activity Date: 2013-04-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 02

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Programmatic ID:	AIR NY0000002630400397
Facility Registry ID:	110001594310
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	MACT Standards (40 CFR Part 63)
Activity Date:	2005-07-28 00:00:00
Activity Status Date:	2005-07-28 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	02
Programmatic ID:	AIR NY0000002630400397
Facility Registry ID:	110001594310
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2013-04-18 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

FINDS:
Registry ID: 110001594310

Click Here for FRS Facility Detail Report:

Environmental Interest/Information System:
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.
AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AIRS:
Name: TEITELBAUM CLEANERS
Address: 35-45 35TH ST

TEITELBAUM DRY CLEANER (Continued) **1000400106**

City,State,Zip:	LONG ISLAND CITY, NY 11106
DECID:	2630400397
Process ID:	Not reported
Latitude:	Not reported
Longitude:	Not reported
FIPS Code:	Not reported
Auth Type Code:	AFR
Permit Status:	Issued
Auth Status Code:	2
Emissions:	Not reported
Issue date:	03/21/2002
Expired Date:	Not reported
Emission Unit date:	Not reported
Contamination:	Not reported
EPA Control Code:	Not reported
Control Eff:	Not reported
Unit:	Not reported

NY MANIFEST:

Name:	TEITELBAUM CLEANERS
Address:	35-45 35TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
Country:	USA
EPA ID:	NYD981132459
Facility Status:	Not reported
Location Address 1:	35-45 35TH STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	11106
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981132459
Mailing Name:	TEITELBAUM CLEANERS
Mailing Contact:	MINDY PETERS
Mailing Address 1:	35-45 35TH STREET
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11106
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183929522

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	12/28/2011
Trans1 Recv Date:	12/28/2011

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Trans2 Recv Date:	01/04/2012
TSD Site Recv Date:	01/05/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981132459
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID084802842
TSDF ID 2:	Not reported
Manifest Tracking Number:	002592497SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	440
Units:	P - Pounds
Number of Containers:	4
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	F002
Waste Code 1_2:	D007
Waste Code 1_3:	D029
Waste Code 1_4:	D039
Waste Code 1_5:	D040
Waste Code 1_6:	Not reported

RI MANIFEST:

Name:	TEITELBAUM CLEANERS INC
Address:	35-45 35TH ST
City,State,Zip:	LONG ISLAND CITY, NY 11106
EPA Id:	NYD981132459
GEN Cert Date:	2/18/2011
Manifest Document Number:	003785194FLE
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
TSDF Id:	RID084802842
TSDF Name:	SAFETY KLEEN
Qty:	240
WT/Vol Units:	P
TSDF Date:	2/24/2011
Transporter 2 Id:	NJD071629976
Item Number:	2
Transporter 2 Name:	2/24/2011

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Transporter Name 2:	SAFETY KLEEN
Transporter EPAID:	TXR000050930
Transporter Receipt Date:	2/18/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Fee Exempt Code:	Not reported
Comment:	Not reported
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
Quarter:	Not reported
Transporter Contact Name:	Not reported
Transporter Contact Email:	Not reported
Filing Date:	Not reported
Total Fee:	Not reported
Billing Name:	Not reported
Paid Date:	Not reported
Paid Time:	Not reported
Facility Receipt Date:	Not reported
Fee:	Not reported
Manifest Created Date:	Not reported
Manifest Updated Date:	Not reported

RI MANIFEST:

Transporter Receipt Date:	4/16/2012
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003207007SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	440
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/16/2012
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	4/19/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/19/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/18/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003785194FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	440
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/18/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	2/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/18/2011
Number Of Containers:	4
Container Type:	DF

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003785194FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	240
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/18/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	2/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/28/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	002592497SKS
Quarter:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	400
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/28/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/4/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/4/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/18/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003785194FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	240
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/18/2011
Facility Receipt Date:	Not reported
Fee:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Transporter 2 Receipt Date:	2/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	4/21/2011
Number Of Containers:	5
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	002593829SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	550
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/21/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	4/29/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/29/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	2/18/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003785194FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	440
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	2/18/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	2/24/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	2/24/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	4/21/2011
Number Of Containers:	5
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	002593829SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	550
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	4/21/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	4/29/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	4/29/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/28/2011
Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	002592497SKS
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	440
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/28/2011
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/4/2012
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/4/2012
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/21/2010

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Number Of Containers:	4
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459
Manifest Docket Number:	003785074FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	200
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	2
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/21/2010
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/13/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/13/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported
Transporter Receipt Date:	12/21/2010
Number Of Containers:	3
Container Type:	DF
Waste Code1:	D007
Waste Code2:	D029
Waste Code3:	D039
Waste Code4:	Not reported
Waste Code5:	Not reported
Waste Code6:	Not reported
Comment:	Not reported
Fee Exempt Code:	Not reported
TSDF Name:	SAFETY KLEEN
TSDF Id:	RID084802842
Transporter Name 2:	SJ TRANSPORTATION CO INC
Company Permit Number:	Not reported
Year:	Not reported
EPA ID:	NYD981132459

TEITELBAUM DRY CLEANER (Continued) **1000400106**

Manifest Docket Number:	003785074FLE
Quarter:	Not reported
Waste Description:	TOXIC LIQUIDS ORGANIC NOS
Transporter Contact Name:	Not reported
Quantity:	300
Transporter Contact Email:	Not reported
WT/Vol Units:	P
Filing Date:	Not reported
Total Fee:	Not reported
Item Number:	1
Transporter Name:	SAFETY KLEEN
Billing Name:	Not reported
Transporter EPA ID:	TXR000050930
Date Paid:	Not reported
Time Paid:	Not reported
GEN Cert Date:	12/21/2010
Facility Receipt Date:	Not reported
Fee:	Not reported
Transporter 2 Receipt Date:	1/13/2011
Manifest Created Date:	Not reported
TSDF Receipt Date:	1/13/2011
Transporter 2 ID:	NJD071629976
Manifest Updated Date:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional RI_MANIFEST: record(s) in the EDR Site Report.

393
SW
1/2-1
0.686 mi.
3623 ft.

WILSON HANLEY, INC.
21-11 44TH AVENUE
LONG ISLAND CITY, NY 11101

NY SHWS **1001362336**
NY AST **N/A**

Relative:
Higher

Actual:
19 ft.

SHWS:

Name:	THOMAS C. WILSON-BETTER TOOLS FOR BETTER WORK
Address:	21-11 44TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program:	HW
Site Code:	384281
Classification:	N
Region:	2
Acres:	0.037
HW Code:	241110
Record Add:	07/13/2007
Record Upd:	06/11/2008
Updated By:	MOBARRIE
Site Description:	"Site will be investigated as part of the off-site to adjacent site 241107. "
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported

WILSON HANLEY, INC. (Continued) **1001362336**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	THOMAS C. WILSON, INC.
Owner Company:	THOMAS C. WILSON, INC.
Owner Address:	21-11 44TH AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AST:

Name:	WILSON HANLEY, INC.
Address:	21-11 44TH AVENUE
City,State,Zip:	LONG ISLAND CITY, NY 11101
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-017663
Program Type:	PBS
UTM X:	588940.91729
UTM Y:	4511500.89836
Expiration Date:	10/23/2027
Site Type:	Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id:	153
Affiliation Type:	Facility Operator
Company Name:	WILSON HANLEY, INC.
Contact Type:	Not reported
Contact Name:	STEPHEN HANLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-07-18

Site Id: 153

WILSON HANLEY, INC. (Continued) **1001362336**

Affiliation Type:	Emergency Contact
Company Name:	WILSON HANLEY, INC.
Contact Type:	Not reported
Contact Name:	STEPHEN HANLEY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 729-3360
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-07-18

Site Id:	153
Affiliation Type:	Facility Owner
Company Name:	WILSON HANLEY, INC.
Contact Type:	PRESIDENT
Contact Name:	STEPHEN HANLEY
Address1:	21-11 44TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-3360
EMail:	TCWILSON@TCWILSON.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-07-18

Site Id:	153
Affiliation Type:	Mail Contact
Company Name:	WILSON HANLEY, INC.
Contact Type:	PRESIDENT
Contact Name:	STEPHEN HANLEY
Address1:	21-11 44TH AVENUE
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 729-3360
EMail:	TCWILSON@TCWILSON.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-07-18

Tank Info:

Tank Number:	001
Tank Id:	27076
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

WILSON HANLEY, INC. (Continued) **1001362336**

Equipment Records:
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	10/09/1944
Capacity Gallons:	3000
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	#2 fuel oil (on-site consumption)
Tank Number:	002
Tank Id:	27077
Material Code:	9999
Common Name of Substance:	Other

Equipment Records:
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron
K00 - Spill Prevention - None
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
I00 - Overfill - None
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	08/01/1981
Capacity Gallons:	600
Tightness Test Method:	-
Date Test:	Not reported
Next Test Date:	Not reported

WILSON HANLEY, INC. (Continued) **1001362336**

Date Tank Closed:	Not reported
Register:	True
Modified By:	MJGRIFFI
Last Modified:	05/09/2022
Material Name:	other

---

394 **ARMY PICTURIAL CEN** **FUDS** **1024899218**
East **N/A**
1/2-1 **LONG ISLAND CITY, NY**
0.705 mi.
3724 ft.

Relative:
Higher

Actual:
38 ft.

FUDS:

EPA Region:	02
Installation ID:	NY29799F112500
Congressional District Number:	7
Name:	ARMY PICTURIAL CEN
FUDS Number:	C02NY0583
City:	LONG ISLAND CITY
State:	NY
County:	QUEENS
Object ID:	8985
USACE Division:	NAD
USACE District:	New England District (NAE)
Status:	Properties without projects
Current Owner:	LOCAL: CITY CITY OF NEW YORK; PRIVATE OWNER ; PRIV: PRIVATE CITY OF NEW YORK; PRIVATE OWNER
EMS Map Link:	https://fudsportal.usace.army.mil/ems/inventory/map?id=58291
Eligibility:	Eligible
Has Projects:	No
NPL Status:	Not reported
Project Required:	No
Feature Description:	The site was used by the Army Signal Corps as a photographic center and movie studio.
Latitude:	40.75638889
Longitude:	-73.92444444

---

395 **STANDARD MOTOR PRODUCTS INC** **RCRA-SQG** **1000310304**
SE **37-18 NORTHERN BLVD SITE 1** **NY SHWS** **NYD001315266**
1/2-1 **LONG ISLAND CITY, NY 11101** **NY LTANKS**
0.734 mi. **NY CBS**
3878 ft. **NY VCP**
NY Spills

Relative:
Higher

NY MANIFEST
PA MANIFEST

Actual:
23 ft.

RCRA Listings:

Date Form Received by Agency:	20070101
Handler Name:	Standard Motor Products Inc
Handler Address:	37-18 NORTHERN BLVD SITE 1
Handler City,State,Zip:	LONG ISLAND CITY, NY 11101
EPA ID:	NYD001315266
Contact Name:	MURRAY ROSE
Contact Address:	NORTHERN BLVD
Contact City,State,Zip:	LONG ISLAND CITY, NY 11101
Contact Telephone:	718-392-0200

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Ny
State District:	NYSDEC R2
Mailing Address:	NORTHERN BLVD
Mailing City,State,Zip:	LONG ISLAND CITY, NY 11101
Owner Name:	Standard Motor Products
Owner Type:	Municipal
Operator Name:	Standard Motor Products
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20150414
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D000
Waste Description: Not Defined

Waste Code: D001
Waste Description: Ignitable Waste

Waste Code: D002
Waste Description: Corrosive Waste

Waste Code: F001
Waste Description: The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichlorethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F002
Waste Description: The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F003
Waste Description: The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: F005
Waste Description: The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Nonhalogenated Solvents Or Those Solvents Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code: U002
Waste Description: 2-Propanone (I) (Or) Acetone (I)

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Waste Code: U080
Waste Description: Methane, Dichloro- (Or) Methylene Chloride

Waste Code: U154
Waste Description: Methanol (I) (Or) Methyl Alcohol (I)

Waste Code: U220
Waste Description: Benzene, Methyl- (Or) Toluene

Waste Code: U226
Waste Description: Ethane, 1,1,1-Trichloro- (Or) Methyl Chloroform

Waste Code: U239
Waste Description: Benzene, Dimethyl- (I,T) (Or) Xylene (I)

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: STANDARD MOTOR PRODUCTS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: STANDARD MOTOR PRODUCTS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: STANDARD MOTOR PRODUCTS
Legal Status: Municipal
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 20060101
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Small Quantity Generator

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 20070101
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19840712
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19900301
Handler Name: STANDARD MOTOR PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19920206
Handler Name: STANDARD MOTOR PRODUCTS
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19940223
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19960319
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 19980330
Handler Name: STANDARD MOTOR PRODUCTS INC
Federal Waste Generator Description: Large Quantity Generator
State District Owner: Ny
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 336322
NAICS Description: OTHER MOTOR VEHICLE ELECTRICAL AND ELECTRONIC EQUIPMENT MANUFACTURING

Has the Facility Received Notices of Violations:
Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Generators - General
Date Violation was Determined: 19880926
Actual Return to Compliance Date: 19881223
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Scheduled Compliance Date:	19881120
Enforcement Identifier:	001
Date of Enforcement Action:	19881020
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYDEC
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19870127
Actual Return to Compliance Date:	19881228
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Generators - General
Date Violation was Determined:	19940413
Actual Return to Compliance Date:	19940601
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Scheduled Compliance Date: 19940513
Enforcement Identifier: 000
Date of Enforcement Action: 19940413
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: NY
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYADS
Enforcement Responsible Sub-Organization: R2
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: EPA
Violation Short Description: Generators - General
Date Violation was Determined: 19990514
Actual Return to Compliance Date: 19990528
Return to Compliance Qualifier: Observed
Violation Responsible Agency: EPA
Scheduled Compliance Date: 19990614
Enforcement Identifier: 000
Date of Enforcement Action: 19990514
Enforcement Responsible Agency: EPA
Enforcement Docket Number: Not reported
Enforcement Attorney: R2
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number:Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: R2AHJ
Enforcement Responsible Sub-Organization: RCB
SEP Sequence Number: Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	Yes
Agency Which Determined Violation:	EPA
Violation Short Description:	Generators - Pre-transport
Date Violation was Determined:	20070406
Actual Return to Compliance Date:	20080630
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	EPA
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	20070412
Enforcement Responsible Agency:	EPA
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	VERBAL INFORMAL
Enforcement Responsible Person:	R2OSK
Enforcement Responsible Sub-Organization:	RCB
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: No
Agency Which Determined Violation: Not reported
Violation Short Description: Not reported
Date Violation was Determined: Not reported
Actual Return to Compliance Date: Not reported
Return to Compliance Qualifier: Not reported
Violation Responsible Agency: Not reported
Scheduled Compliance Date: Not reported
Enforcement Identifier: Not reported
Date of Enforcement Action: Not reported
Enforcement Responsible Agency: Not reported
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

Evaluation Action Summary:

Evaluation Date:	19880926
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19881223
Scheduled Compliance Date:	19881120
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19870127
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	NON-FINANCIAL RECORD REVIEW
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	19881228
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19990819
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19940228
Evaluation Responsible Agency:	State
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYADS

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	19940601
Scheduled Compliance Date:	19940513
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19990406
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2AHJ
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	19990528
Scheduled Compliance Date:	19990614
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20070406
Evaluation Responsible Agency:	EPA
Found Violation:	Yes
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2OSK
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	20080630
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	19951016
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYHHN
Evaluation Responsible Sub-Organization:	R2
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

Evaluation Date:	20130320
Evaluation Responsible Agency:	EPA
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	R2OSK
Evaluation Responsible Sub-Organization:	RCB
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Request Agency: Not reported
Former Citation: Not reported

SHWS:
Name: STANDARD MOTOR PRODUCTS, INC.
Address: 37-18 NORTHERN BOULEVARD
City,State,Zip: LONG ISLAND CITY, NY 11101
Program: HW
Site Code: 58682
Classification: Significant threat to the public health or environment - action required.
Region: 2
Acres: 1.100
HW Code: 241016
Record Add: 11/18/1999
Record Upd: 08/01/2022
Updated By: JHOCONNE
Site Description: "Site Location: The site is located at 37-18 Northern Boulevard, Long Island City, Queens County, New York in the northwestern section of the county. Bordering the Site is Northern Boulevard to the north; Amtrak s Sunnyside Railroad Yard (Sunnyside Yard) to the south; 39th Street, an automobile dealership, and a Hess (formerly Merit) gasoline station to the east; and commercial and industrial properties to the west. Site Features: The Site is approximately rectangular in shape and occupies approximately one acre of land. The Site contains a six-story industrial building with approximately 42,000 square feet per floor. A narrow strip of land on the south side of the property contains a loading dock and a dirt access path for vehicles. This strip of land is owned by the Metropolitan Transportation Authority (MTA) and was part of a long-term lease to Standard Motor Products. Current Zoning/Use(s): The site is being used for commercial office space. There is a commercial vegetable farm occupying part of the building s roof. Past Uses of the Site: The Site has historically been involved in industrial and manufacturing activities since 1919. A small plating line for chrome plating of small machine parts operated from approximately 1975 to 1984. The site was previously used for painting automobile parts prior to distribution. In 1984, aqueous based paints replaced the previously used solvent-based paints. All painting operations were gradually eliminated between 1990 and 1991. The site also housed several other processes and included die-casting operations that ceased in the 1970s; rubber production that was eliminated around 1985; and degreasing which utilized chlorinated solvents that ended in 1990. Until March 2008, automobile parts and components at the site were manufactured in the basement. The manufacturing operations included metal fabrication and machining, plastic injection molding, and assembly. A small photography laboratory for production of newsletters, brochures also operated. Hazardous or toxic materials involved in plant operations are lubricating oils for machinery, caustics for degreasing, phenolics used in molding processes, epoxies for coil production, and water-based inks involved in their small-scale printing. All wastes were temporarily stored on-site in secure containers prior to off-site disposal at a licensed treatment, storage, and disposal (TSD) facility. Site Geology and Hydrogeology: The Site is underlain by the following units (in order by increasing depth): urban fill, Upper Pleistocene glacial deposits (including

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

both till and channel deposits), and bedrock. The fill is predominantly comprised of reworked glacial deposits (sand, silt, clay, and gravel) and railroad ballast with minor amounts of construction debris and other materials. The Upper Pleistocene glacial deposits consist mainly of ground moraine deposits (unstratified, poorly sorted mixture of sand, silt, clay, and gravel). Bedrock was encountered at a depth of 74 feet below land surface (i.e. 53 feet below mean sea level). The groundwater beneath the Site occurs under water table (unconfined) conditions. The depth to groundwater in the vicinity of the Site is approximately 5 feet below ground surface (bgs). The water table occurs in either fill or glacial deposits. Groundwater elevation data show that flow is primarily from east to west beneath the Site. Due to the proximity to the East River, the hydraulic gradients are gentle which is consistent with the regional groundwater contour map and the groundwater contours present on the adjacent Sunnyside Yard property. The groundwater flow rate was estimated to be 0.78 feet/day. "

Env Problem: "Nature and Extent of Contamination: Soil - At one location, arsenic was detected at 19 parts per million (ppm), which is above the applicable soil cleanup objective (SCO) of 16 ppm. Groundwater - Tetrachloroethylene (PCE) has been found at concentrations of up to 17 parts per billion (ppb). Trichloroethylene (TCE) has been found at concentrations of up to 78 ppb. Cis-1,2-Dichloroethene (cis-1,2-DCE) has been found at concentrations of up to 93 ppb. Vinyl chloride (VC) has been found at concentrations of up to 31 ppb. 1,1,1-Trichloroethane 1,1,1-TCA) has been found at concentrations of up to 180 ppb. An air sparge and soil vapor extraction system was installed to remediate site groundwater and has been operating since September 2013. Soil Vapor- The highest concentrations of chlorinated VOCs were detected at SB-05. Sub-slab samples contained PCE at concentration of up to 620 ug/m3. TCE and cis-1,2-DCE have been found at concentrations of up to 2,800 ug/m3 and up to 52 ug/m3 respectively. Chlorinated ethanes were found and included 1,1,1-TCA and 1,1-DCA at concentrations up to 5,200 ug/m3 and up to 450 ug/m3 respectively. An Interim Remedial Measure (IRM) consisting of a sub-slab depressurization system (SSDS) has been installed in the building and is currently in operation. "

Health Problem: "The on-site structure will have an active sub-slab depressurization system which will prevent contamination from entering the building via soil vapor intrusion. A air sparge/soil vapor extraction system will address contaminants present in the groundwater. Exposure to site-related contaminants in drinking water are not expected because public water serves the area. "

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: unknown
Lat/Long: 40:45:07:0 / 73:55:31:0
Dell: False
Record Add: 1999-11-18 12:00:00
Record Upd: 2013-09-19 15:14:00
Updated By: kbdilige
Own Op: Document Repository
Sub Type: NNN

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Owner Name:	Roz Rubinstein
Owner Company:	Queens Public Library Broadway Branch
Owner Address:	40-20 Broadway
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11103
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Gordon Johnson
Owner Company:	Metropolitan Transporation Auth.
Owner Address:	347 Madion Aeve.
Owner Addr2:	9th Floor
Owner City,St,Zip:	New York, NY 10017
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	C/O RXR REALTY LLC
Owner Company:	RXR SMP OWNER LLC
Owner Address:	625 RXR PLAZA
Owner Addr2:	Not reported
Owner City,St,Zip:	UNIONDALE, NY 11566
Owner Country:	United States of America
HW Code:	241016
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1 Dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1,1-Trichloroethane(TCA)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	1,1-DICHLOROETHANE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	METHYL-TERT-BUTYL ETHER (MTBE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	241016
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Waste Code: Not reported
HW Code: 241016
Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241016
Waste Type: ETHYLBENZENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241016
Waste Type: VINYL CHLORIDE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 241016
Waste Type: DICHLOROETHYLENE
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 2-477869
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2007-01-04 15:05:00
Record Updated: 2007-01-04 15:05:00
Updated By: SMMARTIN
Crossref ID: r2-0637-04-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2016-12-12 16:18:00
Record Updated: 2016-12-12 16:18:00
Updated By: SMMARTIN
Crossref ID: 04/13/2010
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2016-12-12 16:19:00
Record Updated: 2016-12-12 16:19:00
Updated By: SMMARTIN
Crossref ID: NYD001315266
Cross Ref Type Code: 05
Cross Ref Type: EPA Site ID
Record Added Date: 1999-11-18 12:00:00
Record Updated: 2001-05-10 16:31:00
Updated By: REGTRANS

LTANKS:
Name: STANDARD MOTOR PROD INC
Address: 37-18 NORTHERN BLVD
City,State,Zip: LONG ISLAND CITY, NY
Spill Number/Closed Date: 9509528 / 2004-03-23
Facility ID: 9509528
Site ID: 153383
Spill Date: 1995-11-01
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 4101
Investigator: SMMARTIN
Referred To: Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Reported to Dept:	1995-11-01
CID:	357
Water Affected:	Not reported
Spill Notifier:	DEC
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-01
Spill Record Last Update:	2004-03-23
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	AVIS REDMAN
Spiller Phone:	(718) 392-0200
Spiller Extention:	Not reported
DEC Region:	2
DER Facility ID:	130150
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MARTINKAT 02/18/04: Reassigned from KRIMGOLD to Martinkat. "
Remarks:	"OIL IN TANK ROOM "

All Materials:

Site ID:	153383
Operable Unit ID:	1020065
Operable Unit:	01
Material ID:	360474
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

CBS:

Name:	STANDARD MOTOR PRODUCTS, INC.
Address:	37-18 NORTHERN BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
CBS Number:	2-000153
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	2
UTMX:	590670.88539
UTMY:	4511788.22315

VCP:

Name:	STANDARD MOTOR PRODUCTS BUILDING
Address:	37-18 NORTHERN BOULEVARD
City,State,Zip:	LONG ISLAND CITY, NY 11101
Program Type:	VCP

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Site Code:	58683
HW Code:	V00257
Site Class:	N
SWIS:	4101
Region:	2
Town:	New York City
Acres:	Not reported
Date Record Added:	11/30/2000
Date Record Updated:	10/19/2001
Updated By:	REEVANS
Site Description:	"See Registry Site # 241016"
Env Problem:	""
Health Problem:	""
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	6
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	Standard Motor Products
Owner Address:	37-18 NORTHERN BLVD.
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	Not reported
Owner Company:	NEW YORK CITY INDUSTRIAL DEVELOPMENT
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	37-18 NORTHERN BLVD/QUNS
Address:	37-18 NORTHERN BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9006846 / 1990-10-15

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Facility ID:	9006846
Facility Type:	ER
DER Facility ID:	130150
Site ID:	153382
DEC Region:	2
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	4101
Spill Date:	1990-09-21
Investigator:	FINGER
Referred To:	Not reported
Reported to Dept:	1990-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-09-25
Spill Record Last Update:	2004-09-02
Spiller Name:	Not reported
Spiller Company:	STANDARD MOTOR PRO
Spiller Address:	37-18 NORTHERN BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DRUMS FELL OFF TRUCK, SPILLED ONTO SOIL AREA, SPEEDY DRY WAS APPLIED, WILL PICK UP & REMOVE CONTAMINATED SOIL."

All Materials:

Site ID:	153382
Operable Unit ID:	947356
Operable Unit:	01
Material ID:	434292
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	-1.00
Units:	L
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

Name:	SPILL NUMBER 9900754
Address:	37-18 NORTHERN BLVD
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	9900754 / 2002-06-11
Facility ID:	9900754
Facility Type:	ER
DER Facility ID:	130150
Site ID:	153384
DEC Region:	2

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Spill Cause:	Unknown
Spill Class:	C4
SWIS:	4101
Spill Date:	1999-04-20
Investigator:	JHOCONNE
Referred To:	Not reported
Reported to Dept:	1999-04-20
CID:	366
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-20
Spill Record Last Update:	2004-09-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL CON ED E2MIS NOTES 7-08-99 4-20-99 1100hrs. An undiaperable sheen found on 500 gals of water in Vault #unknown, no secondary or primary cables in structure, contained, no sewers or waterways affected. Sample to be taken. Lab Seq#99-04008 <1ppm 4-20-99 2000hrs. 5-01-99 18:00hrs. CLeanup completed & Env. Tag #24760 removed. UPDATE - 5/4/99 - NO LEAKING COMPANY EQUIPMENT. INCIDENT IS CLOSED."
Remarks:	"PRODUCT FOUND IN VAULT AND IS CONTAINED ON WATER. SAMPLES TO BE TAKEN AND CLEAN UP TO BEGIN. CON ED #124344."

All Materials:

Site ID:	153384
Operable Unit ID:	1079518
Operable Unit:	01
Material ID:	307875
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Resource Affected:	Soil
Oxygenate:	Not reported

NY MANIFEST:

Name:	STANDARD MOTOR PRODUCTS
Address:	37-18 NORTHERN BLVD
City,State,Zip:	LONG ISLAND CITY, NY 11101-1616

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Country:	USA
EPA ID:	NYD001315266
Facility Status:	Not reported
Location Address 1:	37-18 NORTHERN BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	LONG ISLAND CITY
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD001315266
Mailing Name:	STANDARD MOTOR PRODUCTS
Mailing Contact:	STANDARD MOTOR PRODUCTS
Mailing Address 1:	37-18 NORTHERN BLVD
Mailing Address 2:	Not reported
Mailing City:	LONG ISLAND CITY
Mailing State:	NY
Mailing Zip:	11101
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7183920200

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	TXR000081205
Trans2 State ID:	Not reported
Generator Ship Date:	12/10/2015
Trans1 Recv Date:	12/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/10/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001315266
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	005172577SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	14
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Manifest Details:

Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	80
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	000895431GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2010
Manifest Number:	000895431GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U151
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	10
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	D002
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2010
Manifest Number:	000895430GBF
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	04/07/2010
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	200
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2008
Manifest Number:	000141753SKS
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	06/30/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD987367216
TSD Date:	Not reported
TSD Facility Name:	AERC COM INC ADVANCED ENVIRONMENTAL RECYCLING
TSD Facility Address:	2591 MITCHELL AVENUE
TSD Facility City:	ALLENTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D008
Container Number:	3
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2008
Manifest Number:	000141753SKS
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	06/30/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	718-316-4332
TSD EPA Id:	PAD987367216
TSD Date:	Not reported
TSD Facility Name:	AERC COM INC ADVANCED ENVIRONMENTAL RECYCLING
TSD Facility Address:	2591 MITCHELL AVENUE
TSD Facility City:	ALLENTOWN
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D002
Container Number:	3

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Container Type:	Metal drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2006
Manifest Number:	PAH043327
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	30
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported
Year:	2006
Manifest Number:	PAH043327
Manifest Type:	TSD Copy
Generator EPA Id:	NYD001315266
Generator Date:	03/20/2006
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	718-316-4332
Page Number:	1
Line Number:	4
Waste Number:	D008
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	5
Unit:	Gallons (liquids only)

STANDARD MOTOR PRODUCTS INC (Continued) **1000310304**

Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Click this hyperlink while viewing on your computer to access
2 additional PA_MANIFEST: record(s) in the EDR Site Report.

396
East
1/2-1
0.751 mi.
3964 ft.

LEVCO METALS
34-11 36TH STREET
ASTORIA, NY 11106

NY SHWS **U003391190**
NY AST **N/A**
NY INST CONTROL
NY VCP
NY Spills

Relative:
Higher

Actual:
39 ft.

SHWS:
Name: LEVCO METALS PROPERTY
Address: 34-11 36TH STREET
City,State,Zip: LONG ISLAND CITY, NY 11101
Program: HW
Site Code: 58675
Classification: C
Region: 2
Acres: 0.500
HW Code: 241009
Record Add: 11/18/1999
Record Upd: 05/16/2012
Updated By: JHOCONNE
Site Description: "See also Site no. V00600 Location: The Levco Metals Finishers property is located in an urban area of New York City in an industrial part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The entire site is occupied by a one story building which covers approximately 21,900 sq.ft. Historical Use: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. In March 1996, the Record of Decision (ROD) was executed, which recommended delisting of the site from the Registry. The site has been delisted from the Registry in May 1996. The ROD also recommended additional groundwater monitoring on a semi-annual basis. "
Env Problem: "Nature and Extent of Contamination: Interim Remedial Measures (IRMs) consisting of excavation and off-site disposal of soil achieved the main remedial goals of the removal of hazardous waste in the former sump area and the cleanup of on-site soil to levels protective of the public health and the environment. Additional remedial action commenced in 2005 under the Voluntary Cleanup Program (see site no. V00600) which is intended to address residual contaminants in the groundwater. An off-site vapor investigation was completed in 2010 which concluded that there were no off-site vapor issues. Soil: Prior to IRM: elevated concentrations of volatile organic compounds (e.g., 2 ppm trichloroethane; 3.5 ppm trichloroethene) and metals (e.g. 21.2 ppm cadmium; 12 ppm chromium) were detected in the soil beneath the sump area. Contaminated soil from this area was excavated and disposed off site in October 1994. Groundwater : On-Site groundwater is contaminated as a result of disposal activities. Predominant contaminants above Class GA groundwater standards are trichloroethene, 1,1,1-trichloroethane, and cis-1,2-dichloroethene. The ROD recommended additional groundwater monitoring on a semi-annual basis. From 1996 to 2001, several rounds of groundwater monitoring have been conducted and showed that the contaminant levels

LEVCO METALS (Continued) **U003391190**

	in the groundwater beneath the site have not declined to acceptable levels. Further remediation of groundwater is being addressed under site no. V00600. Soil gas: An off-site vapor investigation was completed in 2010 which concluded that there were no off-site vapor issues. "
Health Problem:	"Soil and groundwater are contaminated with volatile organic compounds (VOCs). Exposure to contaminated groundwater is not expected since the area is served by public water. Contaminated soil is subsurface, therefore exposure is unlikely. A soil vapor extraction system is in place on-site to remediate VOCs in soil and soil vapor. Therefore, inhalation exposure via soil vapor exposure has been minimized. Additional data is needed to evaluate the potential for off-site exposure due to soil vapor intrusion."
Dump:	False
Structure:	True
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	unknown
Disp Term:	1990
Lat/Long:	40:45:32:0 / 73:55:20:0
Dell:	False
Record Add:	1999-11-18 12:00:00
Record Upd:	1999-11-18 12:00:00
Updated By:	INITIAL
Own Op:	3
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	KAUFMAN ASTORIA STUDIOS
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	ZZ
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	GEORGE S. KAUFMAN
Owner Company:	KAUFMAN ASTORIA STUDIOS
Owner Address:	34-12 36TH ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11101
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Kaufman Astoria Studios
Owner Address:	34-12 36th Street
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11101
Owner Country:	United States of America
HW Code:	241009
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported

LEVCO METALS (Continued) **U003391190**

Record Updated: Not reported
Updated By: Not reported

AST:
Name: 34-11 36TH AVENUE
Address: 34-11 36TH AVENUE
City,State,Zip: ASTORIA, NY 11106
Region: STATE
DEC Region: 2
Site Status: Active
Facility Id: 2-334979
Program Type: PBS
UTM X: 590556.62142
UTM Y: 4512165.84474
Expiration Date: 03/22/2028
Site Type: Apartment Building/Office Building

Affiliation Records:
Site Id: 15954
Affiliation Type: Facility Owner
Company Name: 3411 REALTY LLC
Contact Type: MANAGING AGENT
Contact Name: ANNIE ASSOULINE
Address1: 415 EAST 75TH STREET
Address2: Not reported
City: NEW YORK
State: NY
Zip Code: 10021
Country Code: 001
Phone: (212) 249-1400
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-09-30

Site Id: 15954
Affiliation Type: Facility Operator
Company Name: 34-11 36TH AVENUE
Contact Type: Not reported
Contact Name: DIMITRIOS TSAKANAS
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (212) 249-1400
EMail: Not reported
Fax Number: Not reported
Modified By: JSMACRI
Date Last Modified: 2022-09-30

Site Id: 15954
Affiliation Type: Mail Contact
Company Name: DIMITRIOS TSAKONAS
Contact Type: Not reported
Contact Name: ANNIE ASSOULINE

LEVCO METALS (Continued) **U003391190**

Address1:	415 EAST 75TH STREET, APT 1FW
Address2:	Not reported
City:	NEW YORK
State:	NY
Zip Code:	10021
Country Code:	001
Phone:	(212) 249-1400
EMail:	ANNIEASSOULINE@AOL.COM
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-30

Site Id:	15954
Affiliation Type:	Emergency Contact
Company Name:	3411 REALTY LLC
Contact Type:	Not reported
Contact Name:	DIMITRIOS TSAKANAS
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(917) 807-9084
EMail:	Not reported
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2022-09-30

Tank Info:

Tank Number:	001
Tank Id:	20924
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None
L09 - Piping Leak Detection - Exempt Suction Piping
J02 - Dispenser - Suction Dispenser
G00 - Tank Secondary Containment - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
F00 - Pipe External Protection - None
I04 - Overfill - Product Level Gauge (A/G)
A00 - Tank Internal Protection - None
D01 - Pipe Type - Steel/Carbon Steel/Iron

Tank Location:	Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/1940
Capacity Gallons:	3000
Tightness Test Method:	NN
Date Test:	Not reported

LEVCO METALS (Continued) **U003391190**

Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	JSMACRI
Last Modified:	09/30/2022
Material Name:	#2 fuel oil (on-site consumption)

INST CONTROL:

Name:	LEVCO METALS
Address:	34-11 36TH STREET
City,State,Zip:	ASTORIA, NY 11106
Site Code:	57131
Control Name:	IC/EC Plan
HW Code:	V00600
Control Code:	34
Control Type:	INST
Dt record added:	11/21/2017
Dt rec updated:	07/05/2018
Updated By:	LSZINOMA
Site Code:	57131
Site Description:	"See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."
Env Problem:	"Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-19 15:01:00
Record Upd:	2018-01-18 09:36:00
Updated By:	JHOCONNE

LEVCO METALS (Continued) **U003391190**

Own Op: 1
Sub Type: P03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36th Street
Owner Addr2: Executive Offices, 2nd floor
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Queens Library at Broadway
Owner Address: 4020 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36TH STREET
Owner Addr2: 2nd Floor Executive Offices
Owner City,St,Zip: ASTORIA, NY 11106
Owner Country: United States of America
Own Op: 6
Sub Type: 01
Owner Name: Tracy Capune
Owner Company: LEVCO WOODWORK JOINT VENTURE
Owner Address: C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10123
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Community Board No. 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: LL Suite 1025
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600

LEVCO METALS (Continued) **U003391190**

Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 241009
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2002-07-23 08:57:00
Record Updated: 2002-08-19 14:01:00
Updated By: brhumphr
Crossref ID: 2-090360
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-11-21 16:39:00
Record Updated: 2017-11-21 16:39:00
Updated By: SMMARTIN
Crossref ID: W2-0939-02-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-11-21 16:37:00
Record Updated: 2017-11-21 16:37:00
Updated By: SMMARTIN
Crossref ID: 2017000395873
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-21 16:23:00
Record Updated: 2017-11-21 16:23:00
Updated By: SMMARTIN
Crossref ID: 12/16/2002
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2017-11-21 16:38:00
Record Updated: 2017-11-21 16:38:00
Updated By: SMMARTIN

Name: LEVCO METALS
Address: 34-11 36TH STREET
City,State,Zip: ASTORIA, NY 11106
Site Code: 57131
Control Name: Deed Restriction
HW Code: V00600
Control Code: A
Control Type: INST
Dt record added: 11/21/2017
Dt rec updated: 07/05/2018
Updated By: LSZINOMA
Site Code: 57131
Site Description: "See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping,

LEVCO METALS (Continued) **U003391190**

etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."

Env Problem: "Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-09-19 15:01:00
Record Upd: 2018-01-18 09:36:00
Updated By: JHOCONNE
Own Op: 1
Sub Type: P03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36th Street
Owner Addr2: Executive Offices, 2nd floor
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Queens Library at Broadway
Owner Address: 4020 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36TH STREET
Owner Addr2: 2nd Floor Executive Offices
Owner City,St,Zip: ASTORIA, NY 11106
Owner Country: United States of America
Own Op: 6
Sub Type: 01
Owner Name: Tracy Capune

LEVCO METALS (Continued) **U003391190**

Owner Company: LEVCO WOODWORK JOINT VENTURE
Owner Address: C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10123
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Community Board No. 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: LL Suite 1025
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 241009
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2002-07-23 08:57:00
Record Updated: 2002-08-19 14:01:00
Updated By: brhumphr
Crossref ID: 2-090360
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-11-21 16:39:00
Record Updated: 2017-11-21 16:39:00
Updated By: SMMARTIN
Crossref ID: W2-0939-02-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-11-21 16:37:00
Record Updated: 2017-11-21 16:37:00
Updated By: SMMARTIN
Crossref ID: 2017000395873
Cross Ref Type Code: 25

LEVCO METALS (Continued) **U003391190**

Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-21 16:23:00
Record Updated: 2017-11-21 16:23:00
Updated By: SMMARTIN
Crossref ID: 12/16/2002
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2017-11-21 16:38:00
Record Updated: 2017-11-21 16:38:00
Updated By: SMMARTIN

Name: LEVCO METALS
Address: 34-11 36TH STREET
City,State,Zip: ASTORIA, NY 11106
Site Code: 57131
Control Name: Site Management Plan
HW Code: V00600
Control Code: 32
Control Type: INST
Dt record added: 11/21/2017
Dt rec updated: 07/05/2018
Updated By: LSZINOMA
Site Code: 57131
Site Description: "See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."
Env Problem: "Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

LEVCO METALS (Continued) **U003391190**

Record Add: 2013-09-19 15:01:00
Record Upd: 2018-01-18 09:36:00
Updated By: JHOCONNE
Own Op: 1
Sub Type: P03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36th Street
Owner Addr2: Executive Offices, 2nd floor
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Queens Library at Broadway
Owner Address: 4020 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36TH STREET
Owner Addr2: 2nd Floor Executive Offices
Owner City,St,Zip: ASTORIA, NY 11106
Owner Country: United States of America
Own Op: 6
Sub Type: 01
Owner Name: Tracy Capune
Owner Company: LEVCO WOODWORK JOINT VENTURE
Owner Address: C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10123
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Community Board No. 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: LL Suite 1025
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)

LEVCO METALS (Continued) **U003391190**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 241009
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2002-07-23 08:57:00
Record Updated: 2002-08-19 14:01:00
Updated By: brhumphr
Crossref ID: 2-090360
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-11-21 16:39:00
Record Updated: 2017-11-21 16:39:00
Updated By: SMMARTIN
Crossref ID: W2-0939-02-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-11-21 16:37:00
Record Updated: 2017-11-21 16:37:00
Updated By: SMMARTIN
Crossref ID: 2017000395873
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-21 16:23:00
Record Updated: 2017-11-21 16:23:00
Updated By: SMMARTIN
Crossref ID: 12/16/2002
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2017-11-21 16:38:00
Record Updated: 2017-11-21 16:38:00
Updated By: SMMARTIN

Name: LEVCO METALS
Address: 34-11 36TH STREET
City,State,Zip: ASTORIA, NY 11106
Site Code: 57131
Control Name: Monitoring Plan
HW Code: V00600
Control Code: 31
Control Type: INST
Dt record added: 11/21/2017
Dt rec updated: 07/05/2018
Updated By: LSZINOMA
Site Code: 57131
Site Description: "See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing

LEVCO METALS (Continued) **U003391190**

development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."

Env Problem: "Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "

Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "

Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-09-19 15:01:00
Record Upd: 2018-01-18 09:36:00
Updated By: JHOCONNE
Own Op: 1
Sub Type: P03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36th Street
Owner Addr2: Executive Offices, 2nd floor
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Queens Library at Broadway
Owner Address: 4020 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36TH STREET
Owner Addr2: 2nd Floor Executive Offices
Owner City,St,Zip: ASTORIA, NY 11106
Owner Country: United States of America

LEVCO METALS (Continued) **U003391190**

Own Op: 6
Sub Type: 01
Owner Name: Tracy Capune
Owner Company: LEVCO WOODWORK JOINT VENTURE
Owner Address: C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10123
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Community Board No. 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: LL Suite 1025
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 241009
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2002-07-23 08:57:00
Record Updated: 2002-08-19 14:01:00
Updated By: brhumphr
Crossref ID: 2-090360
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-11-21 16:39:00
Record Updated: 2017-11-21 16:39:00
Updated By: SMMARTIN
Crossref ID: W2-0939-02-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-11-21 16:37:00
Record Updated: 2017-11-21 16:37:00

LEVCO METALS (Continued) **U003391190**

Updated By: SMMARTIN
Crossref ID: 2017000395873
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-21 16:23:00
Record Updated: 2017-11-21 16:23:00
Updated By: SMMARTIN
Crossref ID: 12/16/2002
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2017-11-21 16:38:00
Record Updated: 2017-11-21 16:38:00
Updated By: SMMARTIN

Name: LEVCO METALS
Address: 34-11 36TH STREET
City,State,Zip: ASTORIA, NY 11106
Site Code: 57131
Control Name: Ground Water Use Restriction
HW Code: V00600
Control Code: 08
Control Type: INST
Dt record added: 11/21/2017
Dt rec updated: 07/05/2018
Updated By: LSZINOMA
Site Code: 57131
Site Description: "See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."
Env Problem: "Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "
Health Problem: "Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported

LEVCO METALS (Continued) **U003391190**

Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2013-09-19 15:01:00
Record Upd: 2018-01-18 09:36:00
Updated By: JHOCONNE
Own Op: 1
Sub Type: P03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36th Street
Owner Addr2: Executive Offices, 2nd floor
Owner City,St,Zip: Astoria, NY 11106
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Queens Library at Broadway
Owner Address: 4020 Broadway
Owner Addr2: Not reported
Owner City,St,Zip: Long Island City, NY 11103
Owner Country: United States of America
Own Op: 4
Sub Type: 03
Owner Name: Tracy Capune
Owner Company: Kaufman Astoria Studios
Owner Address: 34-12 36TH STREET
Owner Addr2: 2nd Floor Executive Offices
Owner City,St,Zip: ASTORIA, NY 11106
Owner Country: United States of America
Own Op: 6
Sub Type: 01
Owner Name: Tracy Capune
Owner Company: LEVCO WOODWORK JOINT VENTURE
Owner Address: C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10123
Owner Country: United States of America
Own Op: Document Repository
Sub Type: NNN
Owner Name: Not reported
Owner Company: Community Board No. 1
Owner Address: 45-02 Ditmars Boulevard
Owner Addr2: LL Suite 1025
Owner City,St,Zip: Astoria, NY 11105
Owner Country: United States of America
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1 TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN

LEVCO METALS (Continued) **U003391190**

Waste Code: Not reported
HW Code: V00600
Waste Type: TRICHLOROETHENE (TCE)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00600
Waste Type: 1,1,1-TCA
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: 241009
Cross Ref Type Code: 02
Cross Ref Type: HW Site ID
Record Added Date: 2002-07-23 08:57:00
Record Updated: 2002-08-19 14:01:00
Updated By: brhumphr
Crossref ID: 2-090360
Cross Ref Type Code: 18
Cross Ref Type: PBS No.
Record Added Date: 2017-11-21 16:39:00
Record Updated: 2017-11-21 16:39:00
Updated By: SMMARTIN
Crossref ID: W2-0939-02-10
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2017-11-21 16:37:00
Record Updated: 2017-11-21 16:37:00
Updated By: SMMARTIN
Crossref ID: 2017000395873
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-11-21 16:23:00
Record Updated: 2017-11-21 16:23:00
Updated By: SMMARTIN
Crossref ID: 12/16/2002
Cross Ref Type Code: 26
Cross Ref Type: Agreement/Consent Order Date
Record Added Date: 2017-11-21 16:38:00
Record Updated: 2017-11-21 16:38:00
Updated By: SMMARTIN

VCP:
Name: LEVCO METALS
Address: 34-11 36TH STREET
City,State,Zip: ASTORIA, NY 11106
Program Type: VCP
Site Code: 57131
HW Code: V00600
Site Class: C
SWIS: 4101
Region: 2
Town: New York City
Acres: 0.500
Date Record Added: 07/23/2002

LEVCO METALS (Continued) **U003391190**

Date Record Updated:	08/07/2018
Updated By:	JHOCONNE
Site Description:	"See also Site no. 241009 Location: The Levco Metals Finishers property is located in an urban area in New York City in an industrial/residential part of Long Island City, Queens County. The address is 34-11 36th Street. Site Features: The site is undergoing development. Current Zoning and Land Use: The site is under construction. The zoning is commercial. Past Use of the Site: Levco was a metal finishing facility which conducted metal stripping, etching, and plating processes for over 30 years. Industrial operations ceased in November 1990. The entire site was occupied by a one story building which covered approximately 21,900 sq.ft and was demolished in 2000. The site was used as a parking lot until 2017. Site Geology and Hydrogeology: Site soils removed from the sump area were described as silty, clayey sands and clay in the upper part of the aquifer with coarser sand and gravel deposits to a till layer above the bedrock. The groundwater table is at 15 feet below grade and the bedrock is 30 feet below that. Groundwater flows to the west, and the East River lies 1.5 miles west of the site."
Env Problem:	"Nature and Extent of Contamination: The remediation of the site is complete. The contaminant of concern in soil and groundwater had been trichloroethene (TCE). Remedial actions have successfully achieved soil cleanup objectives for commercial use. Residual contamination is being managed under a Site Management Plan. "
Health Problem:	"Remedial actions are complete and measures are in place to control the potential for coming in contact with residual contamination remaining at the site. "
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-09-19 15:01:00
Record Upd:	2018-01-18 09:36:00
Updated By:	JHOCONNE
Own Op:	1
Sub Type:	P03
Owner Name:	Tracy Capune
Owner Company:	Kaufman Astoria Studios
Owner Address:	34-12 36th Street
Owner Addr2:	Executive Offices, 2nd floor
Owner City,St,Zip:	Astoria, NY 11106
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Queens Library at Broadway
Owner Address:	4020 Broadway
Owner Addr2:	Not reported
Owner City,St,Zip:	Long Island City, NY 11103
Owner Country:	United States of America
Own Op:	4
Sub Type:	03

LEVCO METALS (Continued) **U003391190**

Owner Name:	Tracy Capune
Owner Company:	Kaufman Astoria Studios
Owner Address:	34-12 36TH STREET
Owner Addr2:	2nd Floor Executive Offices
Owner City,St,Zip:	ASTORIA, NY 11106
Owner Country:	United States of America
Own Op:	6
Sub Type:	01
Owner Name:	Tracy Capune
Owner Company:	LEVCO WOODWORK JOINT VENTURE
Owner Address:	C/O KAUFMAN REALTY, 450 SEVENTH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10123
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	Community Board No. 1
Owner Address:	45-02 Ditmars Boulevard
Owner Addr2:	LL Suite 1025
Owner City,St,Zip:	Astoria, NY 11105
Owner Country:	United States of America
HW Code:	V00600
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00600
Waste Type:	1,1,1 TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00600
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00600
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00600
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00600
Waste Type:	1,1,1-TCA
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	241009
Cross Ref Type Code:	02
Cross Ref Type:	HW Site ID
Record Added Date:	2002-07-23 08:57:00
Record Updated:	2002-08-19 14:01:00
Updated By:	brhumphr
Crossref ID:	2-090360
Cross Ref Type Code:	18
Cross Ref Type:	PBS No.
Record Added Date:	2017-11-21 16:39:00
Record Updated:	2017-11-21 16:39:00

LEVCO METALS (Continued) **U003391190**

Updated By:	SMMARTIN
Crossref ID:	W2-0939-02-10
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2017-11-21 16:37:00
Record Updated:	2017-11-21 16:37:00
Updated By:	SMMARTIN
Crossref ID:	2017000395873
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-11-21 16:23:00
Record Updated:	2017-11-21 16:23:00
Updated By:	SMMARTIN
Crossref ID:	12/16/2002
Cross Ref Type Code:	26
Cross Ref Type:	Agreement/Consent Order Date
Record Added Date:	2017-11-21 16:38:00
Record Updated:	2017-11-21 16:38:00
Updated By:	SMMARTIN

SPILLS:

Name:	34-11 36TH STREET / QUEEN
Address:	34-11 36TH STREET
City,State,Zip:	LONG ISLAND CITY, NY
Spill Number/Closed Date:	8607571 / 1987-03-30
Facility ID:	8607571
Facility Type:	ER
DER Facility ID:	143329
Site ID:	170332
DEC Region:	2
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	4101
Spill Date:	1987-02-28
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-03-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1987-03-30
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-03-13
Spill Record Last Update:	2004-02-18
Spiller Name:	Not reported
Spiller Company:	LEVCO
Spiller Address:	34-11 36 ST.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : PAUL DECKER (CERT. ENG. TEST. CO.) WILL SEND LAB RESULTS TO AUSTIN; MEETING WILL BE ARRANGED

LEVCO METALS (Continued) **U003391190**

TO DEVELOP FURTHER STRAGETY. /
/ : PAUL DECKER (CERT. ENG. TEST. CO.) WILL SEND LAB RESULTS TO AUSTIN; MEETING WILL BE ARRANGED TO
DEVELOP FURTHER STRATEGY. 10/10/95: This is additional information about material spilled from the
translation of the old spill file: TRICHLORETHYLENE."

Remarks: "NOTIFIED OF CONTAMINATION BY CONSULTANT FOR PROPERTY OWNER."

Count: 16 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
ASTORIA	S128782024	2701 CLEANERS	27-01 24TH AVE	11102	NY DRYCLEANERS
ASTORIA	S103479788	CON ED ASTORIA	31ST AVE		NY LTANKS
ASTORIA	S128782060	UNITED CLEANERS	30-07 36TH AVE	11106	NY DRYCLEANERS
LONG ISLAND CITY	1014201525	FLEMM LEAD CO.	52-01(-05) 31ST PLACE	11101	SEMS-ARCHIVE, LEAD SMELTERS
LONG ISLAND CITY	S121988458	CLOSED-LACKOF RECENT INFO	52020 37TH STREET		NY LTANKS
LONG ISLAND CITY	S116555661	APARTMENT BUILDING	43-14 40TH STREET		NY LTANKS
LONG ISLAND CITY	S128782081	WORLD CLASS GARMENT CARE	27-09A 40TH AVE	11101	NY DRYCLEANERS
LONG ISLAND CITY	S128906042	QUEENS MEDALLION LEASING	21-03 44TH AVENUE	11101	NY SHWS
LONG ISLAND CITY	S128906041	21-03 44TH AVENUE	21-03 44TH AVENUE	11101	NY SHWS
LONG ISLAND CITY	S113916711	44TH ROAD EAST OF 21ST STREET PLUM	44TH ROAD EAST OF 21ST STREET	11120	NY SHWS
LONG ISLAND CITY	S125896294	27-09 40TH AVENUE	27-03 AND 27-09/27-11 40TH AVE	11101	NY SHWS, NY BROWNFIELDS
LONG ISLAND CITY	S121933832	PURVES STREET GROUNDWATER	PURVES STREET BTW THOMPSON AVE	11101	NY SHWS
NEW YORK	S113916734	1ST AVE. AND E. 76TH STREET GW	1ST AVE. AND E. 76TH STREET IN	10021	NY SHWS
NEW YORK	S121933884	CE - YORK AVE STATION	YORK AVE. BETWEEN 61ST & 63RD	10021	NY SHWS
QUEENS COUNTY	S113917043	QUEENS WEST - SOUTH	CENTER BLVD, 47TH RD, 48TH AVE	11101	NY SHWS
QUEENS COUNTY	S113916834	OUTLET CITY	QUEENS BLVD & JACKSON AVE	11101	NY SHWS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: N/A
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 03/26/2023
Date Data Arrived at EDR: 03/28/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 06/23/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 02/08/2023
Date Data Arrived at EDR: 02/09/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/20/2023
Date Data Arrived at EDR: 02/21/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/20/2023
Date Data Arrived at EDR: 02/21/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Annually

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Lists of state and tribal leaking storage tanks

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 05/08/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 03/08/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 82

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/19/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/25/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/20/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2023
Date Data Arrived at EDR: 05/09/2023
Date Made Active in Reports: 07/14/2023
Number of Days to Update: 66

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 05/09/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 09/27/2022
Date Data Arrived at EDR: 12/12/2022
Date Made Active in Reports: 03/06/2023
Number of Days to Update: 84
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 06/14/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 09/27/2022
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 06/02/2023
Number of Days to Update: 73
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

Lists of state and tribal voluntary cleanup sites

VCP: Voluntary Cleanup Agreements
New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing
A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng
A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 07/08/2021
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/08/2023
Date Made Active in Reports: 05/25/2023
Number of Days to Update: 78

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 06/06/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Site List
A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing
In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 04/06/2023
Date Data Arrived at EDR: 04/13/2023
Date Made Active in Reports: 04/19/2023
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 06/08/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/21/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 06/05/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 04/19/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 07/11/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/24/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 05/22/2023
Date Data Arrived at EDR: 05/23/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 48

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Quarterly

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 02/01/2023
Date Data Arrived at EDR: 02/02/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 82
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/19/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 02/09/2023
Number of Days to Update: 2
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database
This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 05/08/2023
Date Data Arrived at EDR: 05/16/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 55

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 05/16/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021
Date Data Arrived at EDR: 07/13/2021
Date Made Active in Reports: 03/09/2022
Number of Days to Update: 239

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 07/10/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021
Date Data Arrived at EDR: 02/03/2023
Date Made Active in Reports: 02/10/2023
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/13/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/01/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 06/16/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 75

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/19/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 04/17/2023
Date Data Arrived at EDR: 04/18/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 83

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/18/2023
Next Scheduled EDR Contact: 07/31/2023
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 04/27/2022
Date Data Arrived at EDR: 05/04/2022
Date Made Active in Reports: 05/10/2022
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 06/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/20/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 07/07/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25
Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/15/2023
Date Data Arrived at EDR: 03/21/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 70
Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 04/14/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 87
Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251
Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 04/25/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 03/31/2023
Date Data Arrived at EDR: 04/20/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 81

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2021
Date Data Arrived at EDR: 03/09/2023
Date Made Active in Reports: 03/20/2023
Number of Days to Update: 11

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/20/2023
Next Scheduled EDR Contact: 10/02/2023
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 04/26/2023
Date Data Arrived at EDR: 05/02/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 15

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data
Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 04/03/2023
Date Data Arrived at EDR: 04/04/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

US MINES: Mines Master Index File
Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/02/2023
Date Data Arrived at EDR: 02/22/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 84

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/24/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing
This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 01/07/2022
Date Data Arrived at EDR: 02/24/2023
Date Made Active in Reports: 05/17/2023
Number of Days to Update: 82

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing
Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines
An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/17/2023
Date Data Arrived at EDR: 03/17/2023
Date Made Active in Reports: 05/30/2023
Number of Days to Update: 74

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/02/2023
Date Data Arrived at EDR: 02/28/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 24

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/25/2023
Date Data Arrived at EDR: 03/31/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/29/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021
Date Data Arrived at EDR: 05/21/2021
Date Made Active in Reports: 08/11/2021
Number of Days to Update: 82

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 11/09/2021
Date Data Arrived at EDR: 10/20/2022
Date Made Active in Reports: 01/10/2023
Number of Days to Update: 82

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 05/15/2023
Date Data Arrived at EDR: 05/17/2023
Date Made Active in Reports: 07/10/2023
Number of Days to Update: 54

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/17/2023
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 06/24/2020
Date Data Arrived at EDR: 03/17/2021
Date Made Active in Reports: 11/08/2022
Number of Days to Update: 601

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 33

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/07/2023
Number of Days to Update: 8

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS ECHO FIRE TRAINING: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facilitys name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS PART 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration?s document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 03/30/2023
Date Data Arrived at EDR: 03/30/2023
Date Made Active in Reports: 04/03/2023
Number of Days to Update: 4

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 04/27/2023
Date Data Arrived at EDR: 04/27/2023
Date Made Active in Reports: 05/02/2023
Number of Days to Update: 5

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

PFAS 2: New York State Inactive Landfill Initiative

A list of landfills that were investigated and the analytical results for PFOA and PFOS for those landfills. These data represent the landfills from the ILI database that were investigated.

Date of Government Version: 11/14/2022
Date Data Arrived at EDR: 01/12/2023
Date Made Active in Reports: 01/23/2023
Number of Days to Update: 11

Source: Department of Environmental Conservation
Telephone: 518-402-9662
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

PFAS 3: PFAS Environmental Site Remediation List

Per- and Polyfluoroalkyl Substances (PFAS) are a group of chemicals used to make fluoropolymer coatings and products that resist heat, oil, stains, grease, and water. Fluoropolymer coatings are blends of resins and lubricants used in products such as water-repellent clothing, furniture, adhesives, paint and varnish, food packaging, heat-resistant non-stick cooking surfaces and insulation of electrical wires. Chemicals in this group include perfluorooctanoic acid (PFOA) and perfluorooctane sulfonic acid (PFOS).

Date of Government Version: 02/06/2023
Date Data Arrived at EDR: 02/07/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 77

Source: Department of Environmental Conservation
Telephone: 518-402-9759
Last EDR Contact: 05/05/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 02/14/2023
Date Data Arrived at EDR: 02/15/2023
Date Made Active in Reports: 05/09/2023
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing

A listing of coal ash disposal site locations.

Date of Government Version: 03/22/2023
Date Data Arrived at EDR: 03/24/2023
Date Made Active in Reports: 06/07/2023
Number of Days to Update: 75

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 03/06/2023
Date Data Arrived at EDR: 03/08/2023
Date Made Active in Reports: 05/25/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 05/31/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 10/27/2022
Date Data Arrived at EDR: 12/12/2022
Date Made Active in Reports: 03/07/2023
Number of Days to Update: 85

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 06/13/2023
Next Scheduled EDR Contact: 09/25/2023
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 03/27/2023
Date Data Arrived at EDR: 03/29/2023
Date Made Active in Reports: 06/13/2023
Number of Days to Update: 76

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 06/22/2023
Next Scheduled EDR Contact: 10/09/2023
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 07/31/2021
Date Data Arrived at EDR: 01/05/2023
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 05/31/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 12/31/2022
Date Data Arrived at EDR: 02/01/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 83

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 05/04/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 01/30/2023
Date Data Arrived at EDR: 02/01/2023
Date Made Active in Reports: 04/25/2023
Number of Days to Update: 83

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 05/03/2023
Next Scheduled EDR Contact: 08/14/2023
Data Release Frequency: Varies

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 10/29/2021
Date Made Active in Reports: 01/19/2022
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 04/27/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 10/20/2022
Date Data Arrived at EDR: 11/09/2022
Date Made Active in Reports: 01/30/2023
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/30/2023
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2022
Date Data Arrived at EDR: 02/08/2022
Date Made Active in Reports: 05/06/2022
Number of Days to Update: 87

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: Varies

UIC: Underground Injection Control Wells
A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 02/26/2023
Date Data Arrived at EDR: 03/01/2023
Date Made Active in Reports: 05/19/2023
Number of Days to Update: 79

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 05/30/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers
This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 04/04/2023
Date Data Arrived at EDR: 04/12/2023
Date Made Active in Reports: 06/28/2023
Number of Days to Update: 77

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 07/12/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Varies

PCS: Permit Compliance System
PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: No Update Planned

PCS ENF: Enforcement data
No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System
Mineral Resources Data System

Date of Government Version: 08/23/2022
Date Data Arrived at EDR: 11/22/2022
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 98

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 05/25/2023
Next Scheduled EDR Contact: 09/04/2023
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI
Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/07/2023
Date Data Arrived at EDR: 06/08/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 1

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 07/05/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 05/23/2023
Next Scheduled EDR Contact: 09/11/2023
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 04/20/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 02/09/2023
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 12

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 02/09/2023
Date Data Arrived at EDR: 02/16/2023
Date Made Active in Reports: 02/28/2023
Number of Days to Update: 12

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 04/26/2023
Next Scheduled EDR Contact: 08/07/2023
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 11/16/2022
Date Data Arrived at EDR: 11/16/2022
Date Made Active in Reports: 02/06/2023
Number of Days to Update: 82

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/11/2023
Next Scheduled EDR Contact: 08/21/2023
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/27/2023
Next Scheduled EDR Contact: 10/16/2023
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 11/30/2021
Date Made Active in Reports: 02/18/2022
Number of Days to Update: 80

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 05/10/2022
Next Scheduled EDR Contact: 08/28/2023
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 07/06/2023
Next Scheduled EDR Contact: 10/23/2023
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/01/2023
Next Scheduled EDR Contact: 09/18/2023
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

23-0454
3705 21ST STREET
LONG ISLAND CITY, NY 11101

TARGET PROPERTY COORDINATES

Latitude (North):	40.758182 - 40° 45' 29.46''
Longitude (West):	73.938068 - 73° 56' 17.04''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	589638.9
UTM Y (Meters):	4512244.5
Elevation:	17 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	14115942 CENTRAL PARK, NY
Version Date:	2019
South Map:	14115940 BROOKLYN, NY
Version Date:	2019

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General NW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 17 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
3604970089F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
3604970093F	FEMA FIRM Flood data
3604970202F	FEMA FIRM Flood data
3604970206F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
CENTRAL PARK	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era:	Paleozoic
System:	Ordovician
Series:	Ordovician
Code:	Oe *(decoded above as Era, System & Series)*

GEOLOGIC AGE IDENTIFICATION

Category: Eugeosynclinal Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: URBAN LAND

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 10 inches

Depth to Bedrock Max: > 10 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification			
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: silt loam
loamy sand
sandy loam
fine sandy loam

Surficial Soil Types: silt loam
loamy sand
sandy loam
fine sandy loam

Shallow Soil Types: sandy loam

Deeper Soil Types: unweathered bedrock
very gravelly - loamy sand
stratified
sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000831755	0 - 1/8 Mile ESE
2	USGS40000831691	1/8 - 1/4 Mile SSW
3	USGS40000831882	1/8 - 1/4 Mile NW
5	USGS40000831744	1/4 - 1/2 Mile WSW
8	USGS40000831605	1/4 - 1/2 Mile SE
9	USGS40000831669	1/4 - 1/2 Mile ESE
10	USGS40000831512	1/4 - 1/2 Mile SSE
11	USGS40000831487	1/4 - 1/2 Mile South
12	USGS40000831796	1/4 - 1/2 Mile West
13	USGS40000831511	1/2 - 1 Mile SE
14	USGS40000831481	1/2 - 1 Mile SW
16	USGS40000832054	1/2 - 1 Mile NNE
B17	USGS40000831480	1/2 - 1 Mile SE
18	USGS40000831434	1/2 - 1 Mile SSE
19	USGS40000832005	1/2 - 1 Mile NE
21	USGS40000832167	1/2 - 1 Mile North
22	USGS40000831496	1/2 - 1 Mile ESE
23	USGS40000831273	1/2 - 1 Mile SSW
24	USGS40000831640	1/2 - 1 Mile ESE
25	USGS40000831488	1/2 - 1 Mile WSW
26	USGS40000831198	1/2 - 1 Mile South
27	USGS40000831211	1/2 - 1 Mile SSE
28	USGS40000831585	1/2 - 1 Mile ESE
29	USGS40000831272	1/2 - 1 Mile SSE
30	USGS40000831282	1/2 - 1 Mile SSW
C31	USGS40000831350	1/2 - 1 Mile SE
32	USGS40000831795	1/2 - 1 Mile East
C33	USGS40000831319	1/2 - 1 Mile SE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
4	NYREG1000009531	1/8 - 1/4 Mile South
A6	NYREG1000009366	1/4 - 1/2 Mile NNE
A7	NYREG1000009367	1/4 - 1/2 Mile NNE
B15	NYREG1000009204	1/2 - 1 Mile SE
20	NYREG1000009657	1/2 - 1 Mile ESE

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG10000040279	1/4 - 1/2 Mile ENE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	NYOG10000040124	1/2 - 1 Mile NNW
A3	NYOG10000040117	1/2 - 1 Mile NNW

PHYSICAL SETTING SOURCE MAP - 7390563.2s


E 79th St
E 71st St
E 63rd St
E 62nd St
E 61st St
Astoria Park S
Astoria Blvd
Amtrak Rail
Subway
36th Ave
Queensboro Br
Queensboro Br W
Amtrak Railroad
Long Island Railroad
NY-25A
Borden Ave
43rd Ave
47th Ave
49th Ave
50th Ave
39th St
43rd St
11th St
21st St
Penn Dr
Koch Hwy
Hunters Point Ave
Hunters Point Ave Railroad
Penn Railroad
Amtrak Railroad
Long Island Railroad
Amtrak Railroad
Amtrak Railroad
Amtrak

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
ESE **FED USGS** **USGS40000831755**
0 - 1/8 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 95. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	92	Well Hole Depth Units:	ft

2
SSW **FED USGS** **USGS40000831691**
1/8 - 1/4 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1221. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	178	Well Hole Depth Units:	ft

3
NW **FED USGS** **USGS40000831882**
1/8 - 1/4 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 954. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	301	Well Hole Depth Units:	ft

4
South **NY WELLS** **NYREG1000009531**
1/8 - 1/4 Mile
Higher

Well Number:	Q003931	Owner:	Jcc Construction Incorporated
Well Depth:	50	Diameter:	4
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

5
WSW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000831744**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1272. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	195	Well Hole Depth Units:	ft

A6
NNE
1/4 - 1/2 Mile
Higher

NY WELLS **NYREG1000009366**

Well Number:	Q003765	Owner:	Nyc Sanitation Dept.
Well Depth:	143	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

A7
NNE
1/4 - 1/2 Mile
Higher

NY WELLS **NYREG1000009367**

Well Number:	Q003765	Owner:	Nyc Sanitation Dept.
Well Depth:	143	Diameter:	6
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

8
SE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000831605**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1912. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	400	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

9
ESE **FED USGS** **USGS40000831669**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1246. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	220	Well Hole Depth Units:	ft

10
SSE **FED USGS** **USGS40000831512**
1/4 - 1/2 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 3122. 2	Type:	Well
Description:	LAT/LONG UPDATES FROM SIM 3066		
HUC:	02030201	Drainage Area:	Not Reported
Drainage Area Units:	Not Reported	Contrib Drainage Area:	Not Reported
Contrib Drainage Area Unts:	Not Reported		
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Unconfined single aquifer
Construction Date:	20000614	Well Depth:	55
Well Depth Units:	ft	Well Hole Depth:	55
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	54	Level reading date:	2005-02-23
Feet below surface:	Not Reported	Feet to sea level:	14.42
Note:	Not Reported		

Level reading date:	2004-12-17	Feet below surface:	Not Reported
Feet to sea level:	14.55	Note:	Not Reported
Level reading date:	2004-11-17	Feet below surface:	Not Reported
Feet to sea level:	14.54	Note:	Not Reported
Level reading date:	2004-10-26	Feet below surface:	Not Reported
Feet to sea level:	14.52	Note:	Not Reported
Level reading date:	2004-09-22	Feet below surface:	Not Reported
Feet to sea level:	14.49	Note:	Not Reported
Level reading date:	2004-08-24	Feet below surface:	Not Reported
Feet to sea level:	14.35	Note:	Not Reported
Level reading date:	2004-07-22	Feet below surface:	Not Reported
Feet to sea level:	14.13	Note:	Not Reported
Level reading date:	2004-06-23	Feet below surface:	Not Reported
Feet to sea level:	14.03	Note:	Not Reported

Level reading date:	2004-05-25	Feet below surface:	Not Reported
Feet to sea level:	14.13	Note:	Not Reported
Level reading date:	2004-04-29	Feet below surface:	Not Reported
Feet to sea level:	14.10	Note:	Not Reported
Level reading date:	2004-03-17	Feet below surface:	Not Reported
Feet to sea level:	14.12	Note:	Not Reported
Level reading date:	2004-02-25	Feet below surface:	Not Reported
Feet to sea level:	14.21	Note:	Not Reported
Level reading date:	2003-12-29	Feet below surface:	Not Reported
Feet to sea level:	14.24	Note:	Not Reported
Level reading date:	2003-11-26	Feet below surface:	Not Reported
Feet to sea level:	14.13	Note:	Not Reported
Level reading date:	2003-10-30	Feet below surface:	Not Reported
Feet to sea level:	14.14	Note:	Not Reported
Level reading date:	2003-09-26	Feet below surface:	Not Reported
Feet to sea level:	14.23	Note:	Not Reported
Level reading date:	2003-08-28	Feet below surface:	Not Reported
Feet to sea level:	14.26	Note:	Not Reported
Level reading date:	2003-07-30	Feet below surface:	Not Reported
Feet to sea level:	14.13	Note:	Not Reported
Level reading date:	2003-06-26	Feet below surface:	Not Reported
Feet to sea level:	14.16	Note:	Not Reported
Level reading date:	2003-05-28	Feet below surface:	Not Reported
Feet to sea level:	13.85	Note:	Not Reported
Level reading date:	2003-04-24	Feet below surface:	Not Reported
Feet to sea level:	13.78	Note:	Not Reported
Level reading date:	2003-03-19	Feet below surface:	Not Reported
Feet to sea level:	13.57	Note:	Not Reported
Level reading date:	2003-02-26	Feet below surface:	Not Reported
Feet to sea level:	13.54	Note:	Not Reported
Level reading date:	2003-01-30	Feet below surface:	Not Reported
Feet to sea level:	13.38	Note:	Not Reported
Level reading date:	2002-12-23	Feet below surface:	Not Reported
Feet to sea level:	13.35	Note:	Not Reported
Level reading date:	2002-11-22	Feet below surface:	Not Reported
Feet to sea level:	13.32	Note:	Not Reported
Level reading date:	2002-10-23	Feet below surface:	Not Reported
Feet to sea level:	13.10	Note:	Not Reported
Level reading date:	2002-09-24	Feet below surface:	Not Reported
Feet to sea level:	12.84	Note:	Not Reported
Level reading date:	2002-08-28	Feet below surface:	Not Reported
Feet to sea level:	12.70	Note:	Not Reported

Level reading date:	2002-07-18	Feet below surface:	Not Reported
Feet to sea level:	12.76	Note:	Not Reported
Level reading date:	2002-06-26	Feet below surface:	Not Reported
Feet to sea level:	12.80	Note:	Not Reported
Level reading date:	2002-05-30	Feet below surface:	Not Reported
Feet to sea level:	12.78	Note:	Not Reported
Level reading date:	2002-04-26	Feet below surface:	Not Reported
Feet to sea level:	12.72	Note:	Not Reported
Level reading date:	2002-03-19	Feet below surface:	Not Reported
Feet to sea level:	12.90	Note:	Not Reported
Level reading date:	2002-02-26	Feet below surface:	Not Reported
Feet to sea level:	13.05	Note:	Not Reported
Level reading date:	2002-01-29	Feet below surface:	Not Reported
Feet to sea level:	13.20	Note:	Not Reported
Level reading date:	2001-12-27	Feet below surface:	Not Reported
Feet to sea level:	13.45	Note:	Not Reported
Level reading date:	2001-11-20	Feet below surface:	Not Reported
Feet to sea level:	13.83	Note:	Not Reported
Level reading date:	2001-10-23	Feet below surface:	Not Reported
Feet to sea level:	14.58	Note:	Not Reported
Level reading date:	2001-09-25	Feet below surface:	Not Reported
Feet to sea level:	15.36	Note:	Not Reported
Level reading date:	2001-08-22	Feet below surface:	Not Reported
Feet to sea level:	15.17	Note:	Not Reported
Level reading date:	2001-07-25	Feet below surface:	Not Reported
Feet to sea level:	15.02	Note:	Not Reported
Level reading date:	2001-06-27	Feet below surface:	Not Reported
Feet to sea level:	15.06	Note:	Not Reported
Level reading date:	2001-05-23	Feet below surface:	Not Reported
Feet to sea level:	14.75	Note:	Not Reported
Level reading date:	2001-04-24	Feet below surface:	Not Reported
Feet to sea level:	14.44	Note:	Not Reported
Level reading date:	2001-03-19	Feet below surface:	Not Reported
Feet to sea level:	14.03	Note:	Not Reported
Level reading date:	2001-02-26	Feet below surface:	Not Reported
Feet to sea level:	13.78	Note:	Not Reported
Level reading date:	2001-01-31	Feet below surface:	Not Reported
Feet to sea level:	13.48	Note:	Not Reported
Level reading date:	2000-12-20	Feet below surface:	Not Reported
Feet to sea level:	12.91	Note:	Not Reported
Level reading date:	2000-11-29	Feet below surface:	Not Reported
Feet to sea level:	12.89	Note:	Not Reported

Level reading date:	2000-10-24	Feet below surface:	Not Reported
Feet to sea level:	13.00	Note:	Not Reported
Level reading date:	2000-09-27	Feet below surface:	Not Reported
Feet to sea level:	12.86	Note:	Not Reported
Level reading date:	2000-08-28	Feet below surface:	Not Reported
Feet to sea level:	12.82	Note:	Not Reported
Level reading date:	2000-07-24	Feet below surface:	Not Reported
Feet to sea level:	12.56	Note:	Not Reported

11
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000831487**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 2721. 1	Type:	Well
Description:	Not Reported	HUC:	02030101
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	300	Well Hole Depth Units:	ft

12
West
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000831796**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 165. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	205	Well Hole Depth Units:	ft

13
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831511**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1635. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	40	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

14
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000831481**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 962. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	195	Well Hole Depth Units:	ft

B15
SE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000009204**

Well Number:	Q003586	Owner:	Amtrak
Well Depth:	60	Diameter:	5
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

16
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000832054**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1619. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	43	Well Hole Depth Units:	ft

B17
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831480**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 13. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	89	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

18
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831434**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 2445. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	110	Well Hole Depth Units:	ft

19
NE
1/2 - 1 Mile
Higher

FED USGS **USGS40000832005**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1257. 1	Type:	Well
Description:	4201	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	150	Well Hole Depth Units:	ft

20
ESE
1/2 - 1 Mile
Higher

NY WELLS **NYREG1000009657**

Well Number:	Q004047D	Owner:	Ralph Zirinsky Realty Company
Well Depth:	54	Diameter:	8
Casing Length:	0	Screen Diameter:	0
Screen Length:	0		

21
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000832167**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 408. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	57	Well Hole Depth Units:	ft

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

22
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831496**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 389. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	84	Well Hole Depth Units:	ft

23
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831273**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1738. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	146	Well Hole Depth Units:	ft

24
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831640**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 376. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	122	Well Hole Depth Units:	ft

25
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831488**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 161. 1	Type:	Well
Description:	1101	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	228	Well Hole Depth Units:	ft

26
South
1/2 - 1 Mile
Higher

FED USGS **USGS40000831198**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 171. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	500	Well Hole Depth Units:	ft

27
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831211**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 2333. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	37	Well Hole Depth Units:	ft

28
ESE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831585**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1813. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Northern Atlantic Coastal Plain aquifer system		
Formation Type:	Glacial Aquifer, Upper	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	58
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

29
SSE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831272**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 1258. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	63	Well Hole Depth Units:	ft

30
SSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000831282**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 399. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	68	Well Hole Depth Units:	ft

C31
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831350**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 602. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	159	Well Hole Depth Units:	ft

32
East
1/2 - 1 Mile
Higher

FED USGS **USGS40000831795**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 379. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	147	Well Hole Depth Units:	ft

C33
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000831319**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	Q 386. 1	Type:	Well
Description:	Not Reported	HUC:	02030201
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Not Reported
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	222	Well Hole Depth Units:	ft

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
ENE **OIL_GAS** **NYOG10000040279**
1/4 - 1/2 Mile

API #:	31061237500000	Well Name:	Crescent - B
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Status:	Plugged and Abandoned
Well Type:	Stratigraphic	Permit Date:	Not Reported
Drill Date:	Not Reported	Completion Date:	12-FEB-99
Plug Date:	Not Reported	Field Name:	Not Applicable
Formation:	Fordham Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	0
True Depth:	826	Measured Length:	826

A2
NNW **OIL_GAS** **NYOG10000040124**
1/2 - 1 Mile

API #:	31061210460000	Well Name:	TG-2
Owner:	Octagon Development LLC	Operator:	2130
Well Status:	Plugged and Abandoned	Well Type:	Dry Hole
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	28-AUG-03	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Fordham Gneiss
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

A3
NNW **OIL_GAS** **NYOG10000040117**
1/2 - 1 Mile

API #:	31061210350000	Well Name:	TG-1
Owner:	Octagon Development LLC	Operator:	2130
Well Status:	Plugged and Abandoned	Well Type:	Dry Hole
Permit Date:	Not Reported	Drill Date:	Not Reported
Completion Date:	15-NOV-02	Plug Date:	Not Reported
Field Name:	Not Applicable	Formation:	Fordham Gneiss
Borehole Slant:	Vertical	State Owned Lease:	NA
Proposed Depth:	1500	True Depth:	1500
Measured Length:	1500		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

Federal EPA Radon Zone for QUEENS County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for QUEENS COUNTY, NY

Number of sites tested: 81

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.620 pCi/L	97%	0%	3%
Basement	0.970 pCi/L	93%	6%	1%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

12.6 Historical Research Documentation
(Fire Insurance Maps, City Directory Information, Aerial Photographs, etc.)

23-0454
3705 21st Street
Long Island City, NY 11101

Inquiry Number: 7390563.5
July 17, 2023

The EDR-City Directory Abstract

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at approximately five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1922 through current. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 660 feet of the target property.

Summary information obtained is provided in the text of this report.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Year	*Source*	*TP*	*Adjoining*	*Text Abstract*	*Source Image*
2020	EDR Digital Archive	X	X	X	-
2017	Cole Information	-	X	X	-
	Cole Information	X	X	X	-
2014	Cole Information	-	X	X	-
	Cole Information	X	X	X	-
2010	Cole Information	X	X	X	-
2005	Cole Information	X	X	X	-
	Hill-Donnelly Information Services	X	X	X	-
2000	Cole Information	X	X	X	-
1996	NYNEX	-	X	X	-
1995	Cole Information	X	X	X	-
1992	Cole Information	X	X	X	-
1991	NYNEX Information Resource Company	X	X	X	-
1983	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1976	New York Telephone	-	X	X	-

EXECUTIVE SUMMARY

Year	Source	TP	Adjoining	Text Abstract	Source Image
1976	New York Telephone	X	X	X	-
1970	New York Telephone	X	X	X	-
1967	New York Telephone	X	X	X	-
1962	New York Telephone Directory	X	X	X	-
1950	New York Telephone	-	-	X	-
	New York Telephone	-	X	X	-
1945	New York Telephone	-	X	X	-
	New York Telephone	X	X	X	-
1939	New York Telephone Company	X	X	X	-
1934	R. L. Polk & Co.	X	X	X	-
1922	H.C. Morris	-	-	-	-

EXECUTIVE SUMMARY

SELECTED ADDRESSES

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

Address	*Type*	*Findings*
3707 21st street	Client Entered	
3727 21st street	Client Entered	
3712 21st street	Client Entered	
3725 21st street	Client Entered	
3701 21st street	Client Entered	
3735 21st street	Client Entered	
3720 22nd street	Client Entered	
3724 22nd street	Client Entered	
2115 38th Avenue	Client Entered	

FINDINGS

TARGET PROPERTY INFORMATION

ADDRESS

3705 21st Street
Long Island City, NY 11101

FINDINGS DETAIL

Target Property research detail.

21st

3712 21st

Year	*Uses*	*Source*
2005	H Caruso Agostino	Hill-Donnelly Information Services
	h Lobaido Gaspare +A	Hill-Donnelly Information Services
	No Current Listing	Hill-Donnelly Information Services
	Wade Mark v	Hill-Donnelly Information Services
2000	Agostino Caruso	Cole Information Services
	Gaspare Lobaido	Cole Information Services
	Steven Maheu	Cole Information Services
	Toshihiro Komatsu	Cole Information Services
1970	Marini Nicholas J	New York Telephone
1967	Marini Nicholas J	New York Telephone
	Pallotta Michl	New York Telephone
1962	Marini Nicholas J	New York Telephone Directory
	Pallotta Michl	New York Telephone Directory
	Vigilante Sam	New York Telephone Directory
1939	Schultz J	New York Telephone Company
1934	Tashman Archie pkr	R. L. Polk & Co.
	Tashman Hyman Ida formn	R. L. Polk & Co.
	Tashman Irving student	R. L. Polk & Co.

FINDINGS

21ST AVE

3712 21ST AVE

Year	Uses	Source
1939	Schultz J	New York Telephone Company
1934	Tashman Archie pkr	R. L. Polk & Co.
	Tashman Hyman Ida formn	R. L. Polk & Co.
	Tashman Irving student	R. L. Polk & Co.

21ST ST

3705 21ST ST

Year	Uses	Source
2020	REPAIR GUYS INC	EDR Digital Archive
2010	NEW LONDON AUTO TYRE SHOP	Cole Information
2005	LONDON AUTO ELECTRIC INC	Cole Information
	VISTA AUTO CENTER INC	Cole Information
1995	KYENG JIK LEE	Cole Information
1992	KYENG JIK LEE	Cole Information
1991	Highway Auto Svce Center	NYNEX Information Resource Company
1970	LIC Auto Parts Inc	New York Telephone

3707 21ST ST

Year	Uses	Source
2020	PRIMETIME CARS INC	EDR Digital Archive
	SHIMULAUTO REPAIR GLASS & TIRE	EDR Digital Archive
2017	REPAIR GUYS INC	Cole Information
2005	J K AUTO GLASS	Cole Information
	OCCUPANT UNKNOWN	Cole Information
1995	J K AUTO GLASS	Cole Information
1992	EDDIE'S AUTO BODY & FENDER WORKS INC	Cole Information
1991	Eddies Auto Body & Fender Works Inc	NYNEX Information Resource Company
1983	Eddies Auto Body & Fender Works Inc	New York Telephone
1976	Bell Body & Fender Inc	New York Telephone
	Eddies Auto Body & Fender Wk	New York Telephone

FINDINGS

Year	Uses	Source
1970	Eddies Auto Body & Fender Wk	New York Telephone
1967	Eddies Auto Body & Fender Wk	New York Telephone
1962	Bartlett Raymond C auto reprs	New York Telephone Directory
	Eddies Body & Fender	New York Telephone Directory
1939	Barts Auto Wrecking L	New York Telephone Company
1934	Burkerts Welding & Auto Repairs Frank Burkert Arnold Olsen	R. L. Polk & Co.
	Olsen Arnold mech Burkerts Welding & Auto Repairs	R. L. Polk & Co.

3725 21ST ST

Year	Uses	Source
2020	MOLLA AUTO SALES	EDR Digital Archive
2017	AZUAY AUTO REPAIR CO	Cole Information
	QAZI & SONS USED PARTS INC	Cole Information
2014	ALL IN ONE AUTOMOBILE REPAIR	Cole Information
	NEW APNA AUTOMOBILE REPAIR INCORPORA	Cole Information
2010	M & N	Cole Information
	MAG TAXI MANAGEMENT	Cole Information
	QAZI WORLD AUTO PARTS INC	Cole Information
	RICKY AUTO ALARM ELECT INC	Cole Information
	SONALI AUTO REPAIR INC	Cole Information
	TIME COLLISION AUTO SHOP	Cole Information
2005	LONG ISLAND CITY USED AUTO PARTS	Cole Information
	NEW TJ MOTOR INC	Cole Information
	OCCUPANT UNKNOWN	Cole Information
	PAK LAND AUTO REPAIR & BODY SHOP INC	Cole Information
2000	CITY USED AUTO PARTS INCORPORATED	Cole Information
	CITY USED TIRES SHOP	Cole Information
1983	GE TS E L E L Automotive Co Inc	New York Telephone

3727 21ST ST

Year	Uses	Source
2020	QAZI & SON S INC	EDR Digital Archive
2017	21ST ST AUTO REPAIR INC	Cole Information

FINDINGS

Year	Uses	Source
2017	QAZI & SON S INC	Cole Information
2014	21ST STREET AUTOMOBILE REPAIR INCORP	Cole Information
	NEW TAREK AUTOMOBILE REPAIR	Cole Information
	RANA AUTOMOBILE REPAIR	Cole Information
2010	H A TRANSPORTATION INC	Cole Information
	RANA AUTO REPAIR	Cole Information
1995	J P AUTO SALVAGE LTD	Cole Information
1992	G E-T S E L E L AUTOMOTIVE CO INC	Cole Information
1991	G E T S E L E L AUTOMOTIVE CO INC	NYNEX Information Resource Company
1970	GENL AUTO PARTS	New York Telephone
	Genl Auto Wreckrs	New York Telephone
1967	BENL AUTO PARTS	New York Telephone
	Genl Auto Wreckers	New York Telephone
	Genl Auto Wreckrs	New York Telephone
1962	GENL AUTO PARTS	New York Telephone Directory
	Genl Auto Wreckers	New York Telephone Directory
	Genl Auto Wreckrs	New York Telephone Directory
1945	Chalson Bros Inc used cars parts	New York Telephone
1939	Chalson Bros used cars parts	New York Telephone Company
	Charlson Bros Inc	New York Telephone Company

21st street

3707 21st street

Year	Uses	Source

3712 21st street

Year	Uses	Source

3725 21st street

Year	Uses	Source

FINDINGS

3727 21st street

Year	*Uses*	*Source*

23RD RD

3725 23RD RD

Year	*Uses*	*Source*
1934	Gray Lyman Gertrude lab	R. L. Polk & Co.
	How es Elizabeth	R. L. Polk & Co.
	Weinman Wm prod w kr	R. L. Polk & Co.

FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

12 LIC

3720 12 LIC

Year	Uses	Source
1991	AAAA York Inc	NYNEX Information Resource Company
	AAAA York Inc	NYNEX Information Resource Company

12ND ST

3712 12ND ST

Year	Uses	Source
1962	Alert Truckg Co	New York Telephone Directory

3714 12ND ST

Year	Uses	Source
1962	Amoia C	New York Telephone Directory
	Ruggiero Jos	New York Telephone Directory

3715 12ND ST

Year	Uses	Source
1962	Lanni Viola	New York Telephone Directory

3716 12ND ST

Year	Uses	Source
1962	Russo Vincenzo	New York Telephone Directory

3717 12ND ST

Year	Uses	Source
1962	Graham Richd	New York Telephone Directory

3718 12ND ST

Year	Uses	Source
1962	Hudson Maintnce Corp	New York Telephone Directory
	Kimball Warren M & Co	New York Telephone Directory

FINDINGS

3719 12ND ST

Year	Uses	Source
1962	Vidal Madeline	New York Telephone Directory
	Vidal Victor A	New York Telephone Directory

3720 12ND ST

Year	Uses	Source
1962	Buettner J G b	New York Telephone Directory
	Buettner J G scafldg	New York Telephone Directory

12TH ST

3625 12TH ST

Year	Uses	Source
2020	43-34 53RD ST LLC	EDR Digital Archive

3702 12TH ST

Year	Uses	Source
2010	FIELD VISION SVC INC	Cole Information
2005	Fieldvision Services	Hill-Donnelly Information Services

3713 12TH ST

Year	Uses	Source
2020	STANLEY MACH	EDR Digital Archive
2014	STAN MACH	Cole Information
2005	No Current Listing	Hill-Donnelly Information Services
	MACH JOSEPHINA	Cole Information
1976	Mach Frank	New York Telephone
1970	Mach Frank	New York Telephone
1967	Mach Frank	New York Telephone
1945	Mach Frank	New York Telephone
1939	Mach May Mrs	New York Telephone Company
1934	Bon Avita Nicholas rear	R. L. Polk & Co.
	Mach Stanley May asst formn	R. L. Polk & Co.
	Vincinere Peter Ann chauf	R. L. Polk & Co.

FINDINGS

3715 12TH ST

Year	Uses	Source
2020	SAEED ANJUM	EDR Digital Archive
2017	SAEED ANJUM	Cole Information
2014	PREMIERE CONSTRUCTION INCORPORATED	Cole Information
	HOWARD CONSTRUCTION	Cole Information
	L VECCHARELLI	Cole Information
2010	PREMIERE WATERPROOFING ROOF	Cole Information
	SAEED ANJUM	Cole Information
2005	h Vecchiarelli Lenny AV	Hill-Donnelly Information Services
	LENNY VECCHIARELLI	Cole Information
2000	Lenny Vecchiarelli	Cole Information
	LENNY VECCHIARELLI	Cole Information
1992	VECCHIARELLI, LENNY	Cole Information
1991	Vecchiarelli Lenny	NYNEX Information Resource Company
1983	Lanni Viola	New York Telephone
1976	Lanni Viola	New York Telephone
1970	Lanni Viola	New York Telephone
1967	Lanni Viola	New York Telephone
1934	Lenni Michl Susie lab	R. L. Polk & Co.
	Masotti Anthony Antoinette macaroni mkr	R. L. Polk & Co.

3717 12TH ST

Year	Uses	Source
2020	YEPEZ ATANASIO	EDR Digital Archive
2017	YEPEZ ATANASIO	Cole Information
2014	MIGUEL CHAPULIN	Cole Information
	YEPEZ ATANASIO	Cole Information
2010	YEPEZ ANANACIO	Cole Information
	FLORENCIO CASTILLO	Cole Information
2005	Priego Magdalena yv	Hill-Donnelly Information Services
	h Yepez Atanacio v	Hill-Donnelly Information Services
	MIGUEL CHAPULIN	Cole Information
	YEPEZ ANANACIO	Cole Information

FINDINGS

Year	Uses	Source
2005	FLORENCIO CASTILLO	Cole Information
2000	Amanda Melendez	Cole Information
	MONICA GOMEZ	Cole Information
1992	SALINAS, CARLOS	Cole Information
	LITKE, VLADIMIR	Cole Information
1970	Graichen Richd	New York Telephone
1967	Graichen Richd	New York Telephone
1945	Graichen Richd	New York Telephone
1934	Destefano Margt drsmkr	R. L. Polk & Co.
	Destefano Vincent lab	R. L. Polk & Co.
	Destefano Vito Louise lab	R. L. Polk & Co.

3718 12TH ST

Year	Uses	Source
1970	Kuzma Anna	New York Telephone

3719 12TH ST

Year	Uses	Source
1945	Wenson H W	New York Telephone
1934	Resta Angelo Fonda gargage mn	R. L. Polk & Co.
	Wenson Clara B sten	R. L. Polk & Co.
	Wenson Henry W Anna M meatctr	R. L. Polk & Co.
	Wenson Harry W jr clk	R. L. Polk & Co.

3721 12TH ST

Year	Uses	Source
2017	CABINET SHAPES INC	Cole Information
2014	CABINET SHAPES INCORPORATED	Cole Information
2010	CABINET SHAPES INC	Cole Information
2005	Cabinet Shapes Inc 200 718 784 6255 o	Hill-Donnelly Information Services
	CABINET SHAPES CORP	Cole Information
2000	Air Elctrncs Corp	Cole Information
	Aircom Elctrncs	Cole Information
	Cllr Ftr Cmmnctns	Cole Information

FINDINGS

Year	Uses	Source
2000	AIRCOM COMMUNICATIONS AND ELECTRONICS CORPORATION	Cole Information
	AIR COM COMMUNICATIONS & ELECTRONICS CORPORATION	Cole Information
	CELLULAR FUTURE COMMUNICATIONS INCORPORATED	Cole Information
1995	CELLULAR FUTURE COMMUNICATIONS INC	Cole Information
	AIRCOM COMMUNICATIONS AND ELECTRONICS CORP	Cole Information
	AIR COM COMMUNICATIONS & ELECTRONICS CORP	Cole Information
1992	CELLULAR FUTURE COMMUNICATIONS INC	Cole Information
	AIRCOM COMMUNICATIONS & ELECTRONICS CORP	Cole Information
	AIRCOM COMMUNICATIONS AND ELECTRONICS CORP	Cole Information
1991	Aircom Communications & Electronics Corp	NYNEX Information Resource Company
	Aircom Communications And Electronics Corp	NYNEX Information Resource Company
	Cellular Future Communications Inc	NYNEX Information Resource Company
1983	Cirex International Inc	New York Telephone
1976	BASIC LEASING CORP	New York Telephone
	Basic Svces	New York Telephone
	CONTRACT ICE	New York Telephone
	Labelson Ralph Co Inc A Div Of Basic Leasing Corp	New York Telephone
1970	Basic Leasing Corp	New York Telephone
	Ice Leasing Corp	New York Telephone
	Labelson Ralph Colnc A Div of Basic Leasing Corp	New York Telephone
1934	Cheselbrough R	R. L. Polk & Co.
	Ennrmoarto Frank Isabelle lab	R. L. Polk & Co.

13 LIC

3620 13 LIC

Year	Uses	Source
1991	Inspeco Inc	NYNEX Information Resource Company

FINDINGS

13RD ST

3603 13RD ST

Year	Uses	Source
1962	Ferzola Sal b	New York Telephone Directory
	Ferzola Truckg Co	New York Telephone Directory

3605 13RD ST

Year	Uses	Source
1962	Tortora John	New York Telephone Directory

3609 13RD ST

Year	Uses	Source
1962	Aaron Jos	New York Telephone Directory
	Aaron Thos S	New York Telephone Directory

3611 13RD ST

Year	Uses	Source
1962	Aaron Geo	New York Telephone Directory

3617 13RD ST

Year	Uses	Source
1962	Christiano Frank J	New York Telephone Directory

3624 13RD ST

Year	Uses	Source
1962	Tufano Filomena	New York Telephone Directory

3633 13RD ST

Year	Uses	Source
1962	Friendship Bapt Chrch	New York Telephone Directory
	Price Edw	New York Telephone Directory
	Simmons Rosetta V	New York Telephone Directory

3712 13RD ST

Year	Uses	Source
1962	Antonucci Rose C	New York Telephone Directory

FINDINGS

3714 13RD ST

Year	Uses	Source
1962	Libramento Grant D	New York Telephone Directory

3728 13RD ST

Year	Uses	Source
1962	Atomic Concrete Breakers	New York Telephone Directory
	Consolidatd Concrete Cutting Corp	New York Telephone Directory

13TH RD

3741 13TH RD

Year	Uses	Source
1939	George Jack R Lf	New York Telephone Company

13TH ST

3541 13TH ST

Year	Uses	Source
2000	QUEENSBORO FARM PRODS INCORPORATED	Cole Information

3549 13TH ST

Year	Uses	Source
1934	Adamo Angelo lab	R. L. Polk & Co.
	Basilice Anthony chauf	R. L. Polk & Co.
	Bonanno Chas Mary ship clk	R. L. Polk & Co.
	Guadazo Thos	R. L. Polk & Co.
	Jessino John Amelia lab	R. L. Polk & Co.
	Jessino Jos Mary lab	R. L. Polk & Co.
	Pizolla Salvatore	R. L. Polk & Co.

3550 13TH ST

Year	Uses	Source
1945	Gasso Anthony	New York Telephone
1934	Gasso Anthony slsmn	R. L. Polk & Co.
	Gasso Vencenzo	R. L. Polk & Co.
	Martonorte Thos Rose lab	R. L. Polk & Co.

FINDINGS

3552 13TH ST

Year	Uses	Source
1945	Serigano J	New York Telephone
1934	Serigano Guiseppi Jelsonaina concrete	R. L. Polk & Co.

3557 13TH ST

Year	Uses	Source
2014	SHERIEF KAMEL	Cole Information
2005	Kamel Sherief v	Hill-Donnelly Information Services
	SHERIEF KAMEL	Cole Information

3558 13TH ST

Year	Uses	Source
1934	Demartine Catherine M pkr	R. L. Polk & Co.
	Demartine Mary T pkr	R. L. Polk & Co.
	Demartine Peter Josephine lab	R. L. Polk & Co.
	Glorigo Salvatore Andriena lab	R. L. Polk & Co.

3564 13TH ST

Year	Uses	Source
1945	Maddox Carpet Dyeing Co	New York Telephone

3602 13TH ST

Year	Uses	Source
2020	CNS IMPORTS	EDR Digital Archive
2014	DRAPEMASTERS OF AMERICAN	Cole Information
	DRAPE MASTERS OF AMERICA	Cole Information
2010	DRAPEMASTERS OF AMERICA	Cole Information
2005	LUMINATOR SERVICE	Cole Information

3603 13TH ST

Year	Uses	Source
2020	LUIS VALENTIN	EDR Digital Archive
	LUCY CORNEJO-CABRERA	EDR Digital Archive
	TERESA ALAM	EDR Digital Archive
2017	STEVEN SHIMABUKU	Cole Information

FINDINGS

Year	Uses	Source
2014	AIDA CABRERA	Cole Information
	LUIS VALENTINE	Cole Information
	STEVEN SHIMABUKU	Cole Information
2010	NYC PET STORE	Cole Information
	PET CHAUFFEUR CORP	Cole Information
2005	K V Power Electric Inc	Hill-Donnelly Information Services
	Nyc Pet Food R	Hill-Donnelly Information Services
	Nyc Pet Store	Hill-Donnelly Information Services
	Pet Chauffeur	Hill-Donnelly Information Services
	NYC PET STORE	Cole Information
2000	Rhonda Dickerson	Cole Information
	RHONDA DICKERSON	Cole Information
1976	Ayala Antonio	New York Telephone
1970	Figueroa Ramon	New York Telephone
1967	Haber Henry	New York Telephone
1934	Mano Fred chauf	R. L. Polk & Co.

3605 13TH ST

Year	Uses	Source
2020	DAVID BRAVO	EDR Digital Archive
	LIBERTAD HERAS	EDR Digital Archive
	RICHARD DRAGOSITZ	EDR Digital Archive
2017	DAVID BRAVO	Cole Information
	LIBERTAD HERAS	Cole Information
2014	ALI AHMED	Cole Information
	DAVID BRAVO	Cole Information
	RICHARD DRAGOSITZ	Cole Information
2010	SHAWN FROMM	Cole Information
	RICHARD DRAGOSITZ	Cole Information
2005	3609 N	Hill-Donnelly Information Services
	CIRKUS FROM HELL	Cole Information
	JOHN FROMM	Cole Information
	RICHARD DRAGOSITZ	Cole Information

FINDINGS

Year	Uses	Source
2000	Shawn Fromm	Cole Information
	SHAWN FROMM	Cole Information
	DAWN CONOVER	Cole Information
1992	GOLINO, PERRY	Cole Information
	TORTORA, JOHN	Cole Information
	TORRES, C	Cole Information
1991	Ficeto Michel	NYNEX Information Resource Company
	Tortora John	NYNEX Information Resource Company
1983	Ficeto Michel	New York Telephone
	Tortora John	New York Telephone
1970	Tortora John	New York Telephone
1967	Tortora John	New York Telephone
1945	Tortora John	New York Telephone
1934	Tortora Anthony meat ctr	R. L. Polk & Co.
	Tortora John Theresa lab	R. L. Polk & Co.

3609 13TH ST

Year	Uses	Source
2017	ROBYN JONES	Cole Information
2014	ROBYN JONES	Cole Information
2010	JOSEPHINE MULLIGAN	Cole Information
	JESSE CERDA	Cole Information
2005	JOSEPHINE MULLIGAN	Cole Information
	TOM AARON	Cole Information
2000	LUIS ZAMUDIO	Cole Information
1992	WILLIAMS, PAMELA	Cole Information
1991	Williams Parnela	NYNEX Information Resource Company
1976	Alves E	New York Telephone
1970	Price Edw	New York Telephone
1967	Evans Edw	New York Telephone
1934	Hatfield John P Grace lab	R. L. Polk & Co.

FINDINGS

3610 13TH ST

Year	Uses	Source
2017	MANAGEMENT AFFILIATES LLC	Cole Information
	NY ONE LIMOUSINE INC	Cole Information
2014	NY ONE LIMOUSINE INCORPORATED	Cole Information
	MANAGEMENT AFFILIATES LLC	Cole Information
2005	Casa Custom Woodw orking	Hill-Donnelly Information Services
	CASA CUSTOM WOODWORKING	Cole Information
2000	Casa Cstm Woodw kg	Cole Information
	CASA CUSTOM WOODWORKING	Cole Information
1995	ULTIMATE MEDICAL SUPLS INC	Cole Information
	HANDY AMBULETTE CORP	Cole Information
	ULTIMATE AMBULETTE	Cole Information
1992	HANDY AMBULETTE CORP	Cole Information
	ULTIMATE MEDICAL SUPLS INC	Cole Information
	ULTIMATE AMBULETTE	Cole Information
1991	Handy Ambulette Corp	NYNEX Information Resource Company
	Ultimate Medical Supls Inc	NYNEX Information Resource Company
1983	Sapala Enterprises Inc	New York Telephone

3611 13TH ST

Year	Uses	Source
2005	OCCUPANT UNKNOWN	Cole Information
2000	Thomas Aaron	Cole Information
	THOMAS AARON	Cole Information
1992	AARON, GEO	Cole Information
1991	Aaron Geo	NYNEX Information Resource Company
1983	Aaron Geo	New York Telephone
1976	Aaron Geo	New York Telephone
1970	Aaron Geo	New York Telephone
1967	Aaron Geo	New York Telephone
1934	Aarons Geo Nancy H Indryw kr	R. L. Polk & Co.

FINDINGS

3614 13TH ST

Year	Uses	Source
2017	ENERGY CAPITAL COMPNAY LLC	Cole Information
2014	ENERGY CAPITAL COMPNAY LLC	Cole Information

3615 13TH ST

Year	Uses	Source
2014	PEGASUS ELECTRIC	Cole Information
	TRI RAIL INTERNATIONAL IN	Cole Information
2010	TAXITRONIC INC	Cole Information
	METRO METER SHOPSTAXITRONICS	Cole Information
2005	Taxitronic Inc 25s 718 752 1656 o	Hill-Donnelly Information Services
	TAXITRONIC INC	Cole Information
2000	Metrometer Inc	Cole Information
	METROMETER INCORPORATED	Cole Information
1995	METROMETER INC	Cole Information
1992	METROMETER INC	Cole Information
1991	Metrometer Inc	NYNEX Information Resource Company
1934	Diressi Jerome Carmila lab	R. L. Polk & Co.
	Diressi Louise lab	R. L. Polk & Co.
	Monganel Rose Wid Louis	R. L. Polk & Co.

3616 13TH ST

Year	Uses	Source
2020	NJS ELECTRICAL SVC CORP	EDR Digital Archive
2017	N J S ELECTRICAL SVCS CORP	Cole Information
2014	N J S ELECTRICAL SVCS CORPORATION	Cole Information
2010	NJS ELECTRICAL SVC CORP	Cole Information
2005	NJS Electrical Svc Corp	Hill-Donnelly Information Services

3617 13TH ST

Year	Uses	Source
1939	Lo Magilo Carmine	New York Telephone Company
1934	Santamaria Dominick Grace lab	R. L. Polk & Co.
	Santamaria Theresa	R. L. Polk & Co.

FINDINGS

3618 13TH ST

Year	Uses	Source
2000	Champion Ambl Inc	Cole Information
	CHAMPION AMBULANCE INCORPORATED	Cole Information
1983	Cornell Irorf Wks Inc rollingdoors	New York Telephone
1976	Cornell Iron Wks Inc rolling doors	New York Telephone
1970	Cornell Iron Wks Inc rolling doors	New York Telephone

3620 13TH ST

Year	Uses	Source
2020	CASTLESTONE CONSTRUCTION CORP	EDR Digital Archive
2017	CASTLE STONE CONSTRUCTION	Cole Information
2014	CASTLE STONE CONSTRUCTION	Cole Information
2010	CASTLE STONE CONSTRUCTION	Cole Information
	METROMETER INC	Cole Information
2005	Castle Stone Construction	Hill-Donnelly Information Services
	Henry Paul Electric Inc	Hill-Donnelly Information Services
	Metrometer Inc	Hill-Donnelly Information Services
	METROMETER INC	Cole Information
	HENRY PAUL ELECTRIC INC	Cole Information
2000	Henry Pl Eec Inc	Cole Information
	HENRY PAUL ELECTRIC INCORPORATED	Cole Information
	OCCUPANT UNKNOWN	Cole Information
1995	NEW CENTURY CONSTRUCTION CORP	Cole Information
1992	T L I CHARTERS	Cole Information
	TESTWELL CRAIG LABS INC	Cole Information
1991	T L I Charters	NYNEX Information Resource Company
	Testw ell Craig Labs Inc	NYNEX Information Resource Company
1983	TLI Charters	New York Telephone
	TESTWELL LABS INC	New York Telephone
1970	Testw ell Labs Inc	New York Telephone
1934	CORNELL IRON WORKS INC NY cap $1 36 000 Milton L Cornel Pres Treas John B Cornell V Pres Sec Rolling Steel and Overhead Action Deeevs Approved by Underw riters Laboratory	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	CORNELL MILTON L Pres and Treas Corneil Iron Works	R. L. Polk & Co.

3624 13TH ST

Year	Uses	Source
2020	MICHAEL WINKLER	EDR Digital Archive
	ALEXANDER RUPP	EDR Digital Archive
	TERRY MAHABIR	EDR Digital Archive
	DAVID SPANO	EDR Digital Archive
	MALIKA MACCHI	EDR Digital Archive
	JOHN CROWDER	EDR Digital Archive
	BEBE MAHABIR	EDR Digital Archive
2017	HANME INDUSTRIES INC	Cole Information
	JESUS MONTALVO	Cole Information
	SELENA GREEN	Cole Information
2014	HANME INDUSTRIES INCORPORATED	Cole Information
	JESUS MONTALVO	Cole Information
	RAFAEL CASTELLANOS	Cole Information
	BEBE MAHABIR	Cole Information
2010	SUPER EAGLE CONTRACTING INC	Cole Information
	ORORIO RIBAS	Cole Information
	YIP KIN	Cole Information
	AHMED ABDEL	Cole Information
	JESUS MONTALVO	Cole Information
	ABM HAIDER	Cole Information
	SHICHAO LIANG	Cole Information
2005	h Jensen Leonore Az	Hill-Donnelly Information Services
	h Uang Shichao 0 718 482 7383 oi	Hill-Donnelly Information Services
	No Current Listing	Hill-Donnelly Information Services
	CHEUNG KEE CONTRACTOR	Cole Information
	SIUFON CASTELLANOS	Cole Information
	YIP KIN	Cole Information
	F WU	Cole Information
	XU HUANG	Cole Information

FINDINGS

Year	Uses	Source
2005	KWOK TSE	Cole Information
	MING ONG	Cole Information
	ANNE KATZ	Cole Information
	LEONORE JENSEN	Cole Information
	SHICHAO LIANG	Cole Information
2000	Leonore Jensen	Cole Information
	Kin Y Ng	Cole Information
	Ngok Y Ng	Cole Information
	Kwok C Tse	Cole Information
	KWOK TSE	Cole Information
	KIN NG	Cole Information
	LEONORE JENSEN	Cole Information
1995	APOLO INTERNATIONAL ENT INC	Cole Information
1992	THOMAS ACCESSORIES CO INC	Cole Information
	HO, HUYNH	Cole Information
	TRAN, TIN	Cole Information
	XUE, GEORGE	Cole Information
1991	Bartley Wm	NYNEX Information Resource Company
	Lee Kinh Sui	NYNEX Information Resource Company
	Thomas Accessories Co Inc	NYNEX Information Resource Company
	Tran Loc V	NYNEX Information Resource Company
	Tran Tin	NYNEX Information Resource Company
1983	Bartley Wm	New York Telephone
	Bodek Hillel	New York Telephone
	Tufano Filomena	New York Telephone
1976	Bodek Hillel	New York Telephone
1970	Davila Bartolo	New York Telephone
	Popp Margaret	New York Telephone
	Tufano Filomena	New York Telephone
1967	Popp Margaret	New York Telephone
	Laszlo Sandor	New York Telephone
	Tufano Filomena	New York Telephone

FINDINGS

Year	Uses	Source
1934	Tufano Anthony lab	R. L. Polk & Co.
	Tufano Carmini Mary	R. L. Polk & Co.
	Tufano Frank Virginia truckmn	R. L. Polk & Co.
	Tufano Jos Florence beverages	R. L. Polk & Co.
	Tufano Maimie fctyw kr	R. L. Polk & Co.
	Tufano Ralph Frances trucking	R. L. Polk & Co.

3630 13TH ST

Year	Uses	Source
2014	TASK TRANSPORTATION INCORPORATED	Cole Information
2000	Sr T Fitzgerald	Cole Information
1983	New s Shipping Co Inc	New York Telephone
	Trunks And Stuff Co	New York Telephone
1945	Rieper Co billiard cues	New York Telephone
1939	Rieper Co billiard cues	New York Telephone Company
1934	Kieper John J Raymond J Kieper Co	R. L. Polk & Co.

3631 13TH ST

Year	Uses	Source
1991	Papoutsells Efstratos K	NYNEX Information Resource Company

3633 13TH ST

Year	Uses	Source
1967	Friendship Bapt Chrch	New York Telephone
	Hilton Elvera Mrs	New York Telephone
	Price Edw	New York Telephone
1934	Cimitile Jos F Cath J prod	R. L. Polk & Co.
	Franzese Alex meat ctr	R. L. Polk & Co.
	Franzese Alf candy mkr	R. L. Polk & Co.
	Franzese Frank meat ctr	R. L. Polk & Co.
	Franzese Ralph Concetta lab	R. L. Polk & Co.
	Mangini Michl Carmela lab	R. L. Polk & Co.
	Sundie Angelina candymkr	R. L. Polk & Co.

FINDINGS

3637 13TH ST

Year	Uses	Source
1934	Trotto Louis paper box mkr	R. L. Polk & Co.

3644 13TH ST

Year	Uses	Source
2010	CRESCENT STREET CONSTRUCTION	Cole Information
2005	Crescent Street Construction	Hill-Donnelly Information Services
	CRESCENT STREET CONSTRUCTION	Cole Information

3666 13TH ST

Year	Uses	Source
1934	Giancola John	R. L. Polk & Co.

3687 13TH ST

Year	Uses	Source
1934	Trotto Michl Mary lab	R. L. Polk & Co.

3702 13TH ST

Year	Uses	Source
1967	AEG TOOL DIV OF FERROSTAAL OVERSEAS CORP	New York Telephone
	AEG Tool Div	New York Telephone
	Holes Co Div of Trimount Corp	New York Telephone

3710 13TH ST

Year	Uses	Source
2005	Caballero Sergio v	Hill-Donnelly Information Services

3711 13TH ST

Year	Uses	Source
1945	Home Industries	New York Telephone
1939	Queens Laundry Svce	New York Telephone Company
	Queens Wet Wash Co	New York Telephone Company
	Rosemar Laundry Svce	New York Telephone Company
1934	Back Number Budd TN Robt Budd dlr in old new spapers	R. L. Polk & Co.
	Budd Robt Back Number Budd	R. L. Polk & Co.

FINDINGS

3712 13TH ST

Year	Uses	Source
2020	PG HEATING & COOLING	EDR Digital Archive
2014	PG HEATING & COOLING	Cole Information
2010	P G HEATING & COOLING	Cole Information
	AGRAM ELECTRIC	Cole Information
2005	Megaris Electrical o	Hill-Donnelly Information Services
1970	Soltan Joan	New York Telephone
1967	Desharnais Ernest	New York Telephone
1945	Antonucci Innocent Rose	New York Telephone
1934	Antonucci Paul Rose lab	R. L. Polk & Co.
	Carcione Saml lab	R. L. Polk & Co.

3713 13TH ST

Year	Uses	Source
1934	Bon Avita Louis Theresa h rear	R. L. Polk & Co.
	Pagano Jas Anna cigarmkr	R. L. Polk & Co.
	Pagano Jas jr tailor	R. L. Polk & Co.
	Pagano Julia candy dipper	R. L. Polk & Co.
	Spaterelli Domonick Antoinette	R. L. Polk & Co.

3714 13TH ST

Year	Uses	Source
2020	DYNAMIC FIRE INC	EDR Digital Archive
2017	DYNAMIC FIRE INC	Cole Information
2014	DYNAMIC FIRE INCORPORATED	Cole Information
2010	DYNAMIC FIRE INC	Cole Information
2005	DYNAMIC FIRE INC	Cole Information
2000	Dynamic Fire Inc	Cole Information
	DYNAMIC FIRE INCORPORATED	Cole Information
1992	S D R CONSTR CO	Cole Information
1991	S D R Constr Co	NYNEX Information Resource Company
1970	Haber Henry	New York Telephone
1967	Libramento Grant D	New York Telephone
1934	Parente Anthony lab	R. L. Polk & Co.

FINDINGS

3715 13TH ST

Year	Uses	Source
2020	84Q304 VOICE CHARTER SCH OF NY	EDR Digital Archive
	GERACI MEGHAN	EDR Digital Archive
	GOMEZ-LANE STEFANY	EDR Digital Archive
	JACOB BLACKWELL PUBLIC SCHOOL	EDR Digital Archive
2017	84Q304 VOICE CHARTER SCHOOL OF NY	Cole Information
	CITY OF NEW YORK	Cole Information
	VOICE CHARTER SCHOOL OF NY	Cole Information
2014	CITY OF NEW YORK	Cole Information
	VOICE CHARTER SCHOOL OF NY	Cole Information
	84Q304 VOICE CHARTER SCHOOL OF NEWYO	Cole Information
2010	GOODWILL	Cole Information
	PUBLIC SCHOOL 111	Cole Information
	84 Q 304 VOICE CHARTER SCHLNY	Cole Information
	BROOKLYN PUBLIC LIBRARY	Cole Information
	VOICE CHARTER SCHOOL OF NY	Cole Information
2005	+ Goodw ill Industries	Hill-Donnelly Information Services
	Public School 111 3 718 786 2073 a	Hill-Donnelly Information Services
	Queens Child Guidance Ctr	Hill-Donnelly Information Services
	GOODWILL INDUSTRIES	Cole Information
	PUBLIC SCHOOL 111	Cole Information
	NEW YORK CITY BOARD EDUCATION	Cole Information
2000	New York City of PS	Cole Information
	Bilek Jeffrey J	Cole Information
	Local 891 Wifr Fnd	Cole Information
	Queens Child Gdnc	Cole Information
	QUEENS CHILD GUIDNC CENTER INCORPORATED CAPS PROGRAM AT PS 1	Cole Information
	LOCAL 891 WELFARE FUND	Cole Information
	N Y CITY OF EDUCATION	Cole Information
	BILEK JEFFREY J	Cole Information
1995	NYC EDUCATION COMMUNITY SCHOOL BOARDS SCHOOLS-ELEMENTARY PS 1111	Cole Information

Year	Uses	Source
1995	BILEK, JEFFREY J	Cole Information
	NEW YORK CITY TEACHER CENTERS CONSORTIUM	Cole Information
	QUEENS CHILD GUIDANCE CENTER INC-CAPS PROGRAM AT PS 111	Cole Information
1992	FIGLUIZZI, MICHAEL	Cole Information
	QUEENS CHILD GUIDANCE CENTER INC-CAPS PROGRAM AT PS 111	Cole Information
	NYC EDUCATION-COMMUNITY SCHOOL BOARDS-SCHOOLS-ELEMENTARY-PS 111	Cole Information
1991	Fanneron John P custodian	NYNEX Information Resource Company
1983	Fanneron John P custodian	New York Telephone
1976	Bulanow ski Walter b	New York Telephone
1970	Fernandez Antonio b	New York Telephone

3716 13TH ST

Year	Uses	Source
2020	CHARLIE'S AUTO REPAIR	EDR Digital Archive
2017	APPLE AUTO BODY & TOWING SERVICE COR	Cole Information
2014	CHARLIES AUTOMOBILE COLLISION	Cole Information
2010	CHARLIES AUTO COLLISION INC	Cole Information
2000	Unique Mrbl & Grnt	Cole Information
	UNIQUE MARBLE & GRANITE WORKS INCORPORATED	Cole Information
1995	UNIQUE MARBLE & GRANITE WORKS INC	Cole Information
1991	Allied Waterproofing Inc	NYNEX Information Resource Company
1983	Hercules Flooring Co Inc	New York Telephone
	SDR Constr Co	New York Telephone
	Wearever Floors Inc	New York Telephone
1976	Hercules Flooring Co	New York Telephone
1970	Queen Transptn Co	New York Telephone
	Stover Frank trucker	New York Telephone
1967	Queen Transptn Co	New York Telephone
1934	Rutter Jas E Helen carp	R. L. Polk & Co.

FINDINGS

3717 13TH ST

Year	Uses	Source
1934	Cimitile Anthony Agnes lab	R. L. Polk & Co.
	Marrone Santo Antolinette lab	R. L. Polk & Co.

3722 13TH ST

Year	Uses	Source
2020	VICTOR TODARO	EDR Digital Archive
2017	BLEECKER PASTRY TARTUFO	Cole Information
2014	BLEECKER PASTRY TARTUFO	Cole Information
2010	BLEECKER PASTRY TARTUFO	Cole Information
2005	Bleecker Pastry Tartufo	Hill-Donnelly Information Services
	BLEECKER PASTRY TARTUFO INC	Cole Information
2000	Blckr Pastry Trtf	Cole Information
	BLEECKER PASTRY TARTUFO	Cole Information
1995	BLEECKER PASTRY TARTUFO	Cole Information
1992	BLEECKER PASTRY TARTUFO	Cole Information
1991	Bleecker Pastry Tartufo	NYNEX Information Resource Company
1976	Ferrostaal Metabo Tool Corp	New York Telephone
1970	AEG TOOL DIV OF FERROSTAAL OVERSEAS CORP	New York Telephone
	FERROSTAAL OVERSEAS CORP imptrs exptrs AEG Tool Div	New York Telephone

3723 13TH ST

Year	Uses	Source
1934	Mirando Luigi Mary lab	R. L. Polk & Co.
	Santino Frances w id Alfonso	R. L. Polk & Co.

3724 13TH ST

Year	Uses	Source
2020	U-HAUL NEIGHBORHOOD DEALER	EDR Digital Archive
2010	BIG CITY AUTO BODY & TOWING CO	Cole Information
2005	Big City Auto Body & Tow ing Co	Hill-Donnelly Information Services
	BIG CITY AUTO BODY & TOWING SERVICE	Cole Information
2000	Big At Bdy & Tow New York	Cole Information

FINDINGS

Year	Uses	Source
2000	SUNRAY MOTORS LIMITED	Cole Information
	BIG CITY AUTO BODY & TOWING SVCE CORPORATION OF NY	Cole Information
1995	BIG CITY AUTO BODY & TOWING SVCE CORP OF NY	Cole Information
	SUNRAY MOTORS LTD	Cole Information
1992	BIG CITY AUTO BODY & TOWING SVCE CORP OF NY	Cole Information
	SUNRAY MOTORS LTD	Cole Information
1991	Sunray Motors Ltd	NYNEX Information Resource Company
1983	BIG CITY AUTO BODY & TOWING SVCE CORP	New York Telephone

3726 13TH ST

Year	Uses	Source
2020	BIG CITY AUTO BODY-TOWING SVCE	EDR Digital Archive
2017	BIG CITY AUTO BODY & TOWING SVCE CO	Cole Information
	BIG CITY AUTO BODY & TOWING SERVICE	Cole Information
2014	APPLE AUTO BODY & TOWING SVC CORP	Cole Information
	BIG CITY AUTO BODY & TOWING SVC CORP	Cole Information
	BIG CITY AUTO BODY & TOWING SVCE CO	Cole Information
2010	APPLE AUTO BODY & TOWING SVC	Cole Information
2005	Apple Auto Body &Towing Svc	Hill-Donnelly Information Services
	APPLE AUTO BODY & TOWING SERVICE COR	Cole Information
	SUNRAY MOTORS LTD	Cole Information
	BIG CITY AUTO BODY & TOWING SERVICE	Cole Information
2000	Apple Bdy & Tow Crp	Cole Information
	Big At Bdy & Tow Co	Cole Information
	BIG CITY AUTO BODY & TOWING SVCE COMPANY	Cole Information
	APPLE AUTO BODY & TOWING SVCE CORPORATION	Cole Information
1995	BIG CITY AUTO BODY & TOWING SVCE CO	Cole Information
	APPLE AUTO BODY & TOWING SVCE CORP	Cole Information

FINDINGS

Year	Uses	Source
1992	BIG CITY AUTO BODY & TOWING SVCE CO	Cole Information
	APPLE AUTO BODY & TOWING SVCE CORP	Cole Information
1991	Apple Auto Body & Towing Svce Corp	NYNEX Information Resource Company
	Apple Auto Body & Towing Svce Corp	NYNEX Information Resource Company
1976	Core Boring Corp	New York Telephone
1970	Core Boring Corp	New York Telephone
1967	Consolidatd Concrete Cutng Corp	New York Telephone
	Core Boring Corp	New York Telephone
	Feiden Demolition Co Inc	New York Telephone

3728 13TH ST

Year	Uses	Source
1970	Atomic Concrete Breakers	New York Telephone
	High Grade Auto Coach Inc	New York Telephone
1967	Atomic Concrete Breakers	New York Telephone
1939	Standifer Petersen & Sorensen Co contrs	New York Telephone Company
1934	Petersen Contracting Co Inc NY Peter N Petersen pres treas	R. L. Polk & Co.

3738 13TH ST

Year	Uses	Source
2020	MEZCO TOYZ LLC	EDR Digital Archive
	INTEGRATED INDUSTRIAL SYSTS	EDR Digital Archive
2017	KALYNN CONSTRUCTION & DESIGN	Cole Information
2014	KALYNN CONSTRUCTION & DESIGN	Cole Information
	NORTHERN BAY CONTRACTORS	Cole Information
	INTEGRATED INDUSTRIAL SYSTEMS INC	Cole Information
2010	BIG GAME CONSTRUCTION CORP	Cole Information
	NORTHERN BAY CONTRACTORS	Cole Information
2005	Integrated Industrial Syst Inc	Hill-Donnelly Information Services
	Northern Bay Contractors	Hill-Donnelly Information Services
	NORTHERN BAY CONTRACTORS INC	Cole Information
2000	INTEGRATED INDUSTRIAL SYSTEMS INCORPORATED	Cole Information

FINDINGS

Year	Uses	Source
2000	TOLEDO SCALE DIVISION OF RELIANCE ELECTRIC COMPANY	Cole Information
	W T WINTER ASSOCIATES INCORPORATED	Cole Information
	W T WINTER ASSOCIATES INCORPORATED	Cole Information
	INTEGRATED INDUSTRIAL SYSTEMS INCORPORATED	Cole Information
1995	TOLEDO SCALE AUTHORIZED DISTRIBUTOR	Cole Information
	W T WINTER ASSOCS INC	Cole Information
	W T WINTER ASSOCIATES INC	Cole Information
	INTEGRATED INDUSTRIAL SYSTEMS INC	Cole Information
1992	TOLEDO SCALE AUTHORIZED DISTRIBUTOR	Cole Information
	W T WINTER ASSOCS INC	Cole Information
	W T WINTER ASSOCIATES INC	Cole Information
1991	Toledo Scale Div Of Reliance Electric Co	NYNEX Information Resource Company
	W T Winter Associates Inc	NYNEX Information Resource Company
	W T Winter Assocs Inc	NYNEX Information Resource Company
	W T Winter Associates Inc	NYNEX Information Resource Company

3741 13TH ST

Year	Uses	Source
1934	Augustus Chas N Mathilda ship clk	R. L. Polk & Co.

3745 13TH ST

Year	Uses	Source
1934	Collins Edw Julia mason	R. L. Polk & Co.
	Fletcher Sol lab	R. L. Polk & Co.
	Oliver Rose M nurse	R. L. Polk & Co.
	Redman Griffln lab	R. L. Polk & Co.
	Wilson Albert chauf	R. L. Polk & Co.

3783 13TH ST

Year	Uses	Source
2000	Toledo Scl Athrzd	Cole Information
	38TH AV INTS FROM	Cole Information

Year	Uses	Source
2000	TOLEDO SCALE AUTHORIZED DISTRIBUTER	Cole Information

3801 13TH ST

Year	Uses	Source
1945	Terinnl	New York Telephone

14 LIC

3602 14 LIC

Year	Uses	Source
1991	Adath Israel Cntr	NYNEX Information Resource Company

14TH AVE

3508 14TH AVE

Year	Uses	Source
1970	Von Mery Claire	New York Telephone

3510 14TH AVE

Year	Uses	Source
1983	Carranza J Mrs	New York Telephone

3611 14TH AVE

Year	Uses	Source
1970	Superior Table Novelties Corp	New York Telephone

14TH ST

3505 14TH ST

Year	Uses	Source
1962	Lacher Anna Mis	New York Telephone Directory

3510 14TH ST

Year	Uses	Source
1939	Hedmen Ivar	New York Telephone Company

3516 14TH ST

Year	Uses	Source
1939	Schoenberg Chas	New York Telephone Company

FINDINGS

3528 14TH ST

Year	Uses	Source
1945	Atlas Contractors Equip Storage Yard	New York Telephone
	Valorosa Nicholas auto w reckng	New York Telephone

3531 14TH ST

Year	Uses	Source
1967	Sorrenti Ralph	New York Telephone

3535 14TH ST

Year	Uses	Source
1934	Sherriff Robt stone contr	R. L. Polk & Co.

3545 14TH ST

Year	Uses	Source
1939	Queens Boxing Corp	New York Telephone Company
1934	Kleery Holding Co Inc NY Jos J Kleinhenz pres Wm Middleton sec Jos P Perry treas real est	R. L. Polk & Co.
	Queens Boxing Corp Queens Hauiage Corp trucking	R. L. Polk & Co.
	Queens Haulage Corp NY Jos J Kleinhenz pres Wm Middleton sec Jos P Perry treas	R. L. Polk & Co.

3546 14TH ST

Year	Uses	Source
1945	Melrose Salvage Corp	New York Telephone
1934	Basilice Pacifico Maculata junk dlr	R. L. Polk & Co.

3548 14TH ST

Year	Uses	Source
1934	Metropolitan Carting Co	R. L. Polk & Co.

3550 14TH ST

Year	Uses	Source
1945	Baselice Pacifico	New York Telephone
1934	Parial Fannie silk w kr	R. L. Polk & Co.

FINDINGS

3555 14TH ST

Year	Uses	Source
1962	Knapp Sheldon H	New York Telephone Directory

3602 14TH ST

Year	Uses	Source
2020	LEDGARD NADA RUTH	EDR Digital Archive
	NEIMAN CASEY	EDR Digital Archive
	APPELBAUM ALEXIS H	EDR Digital Archive
	DE LEON ELSA	EDR Digital Archive
	BIPATH SARAH	EDR Digital Archive
	JACKSON DEVELOPMENT CTR	EDR Digital Archive
	EMRALINO LILIANE F	EDR Digital Archive
2017	JACKSON DEVELOPMET CENTER	Cole Information
2014	JACKSON DEVELOPMENT CENTER	Cole Information
2010	JACKSON DEVELOPMENT CTR	Cole Information
2005	Adath Israel Ctr o	Hill-Donnelly Information Services
	Jackson Development Ctr	Hill-Donnelly Information Services
2000	Adath Israel Cntr	Cole Information
	ADATH ISRAEL CNTR	Cole Information
1995	ADATH ISRAEL CNTR	Cole Information
1992	ADATH ISRAEL CNTR	Cole Information
1983	Adath Israel Cntr	New York Telephone
1962	Adath Israel Cntr	New York Telephone Directory

3605 14TH ST

Year	Uses	Source
2000	SS Pizzer	Cole Information

3610 14TH ST

Year	Uses	Source
1934	Riker Chas Mary	R. L. Polk & Co.

3620 14TH ST

Year	Uses	Source
1970	Great Eastern Brass Wks Inc	New York Telephone

FINDINGS

Year	Uses	Source
1970	GREAT EASTERN DISCOUNT CNTR Hmpstd Tpk @Elmont@	New York Telephone
	Great Eastern Discount Cntr Hmpstd Tpk @Elmont@	New York Telephone

3622 14TH ST

Year	Uses	Source
2020	ATM	EDR Digital Archive
	MIDTOWN OPERATING CORP	EDR Digital Archive
2017	ECKHOFF TRUCK BODIES	Cole Information
2014	ECKHOFF TRUCK BODIES	Cole Information
2010	ECKHOFF TRUCK BODIES	Cole Information
2005	Eckhoff Truck Bodies	Hill-Donnelly Information Services
	EAGLE WING REALITY LLC	Cole Information
2000	Eckhoff Truck Bds	Cole Information
	ECKHOFF TRUCK BODIES	Cole Information
1995	ECKHOFF TRUCK BODIES	Cole Information
1992	ECKHOFF TRUCK BODIES	Cole Information
1991	Eckhoff Christian Truck Bodies	NYNEX Information Resource Company
1983	Eckhoff Christian Truck Bodies	New York Telephone
1976	Eckhoff Christian Truck Bodies	New York Telephone
1970	ECKHOFF CHRISTIAN TRUCK BODIES	New York Telephone

3628 14TH ST

Year	Uses	Source
2014	PYRGOS USED AUTOMOBILE PARTS INCORPO	Cole Information
2010	PYRGOS USED AUTO PARTS INC	Cole Information
2005	Ferrara Brothers	Hill-Donnelly Information Services
	Sonic Construction Inc	Hill-Donnelly Information Services
2000	Andrew Tselos	Cole Information
	Eddies Body & Fndr	Cole Information
	Ts EL Inc	Cole Information
	Tsil Auto Inc	Cole Information
	37TH AV INTS FROM	Cole Information

FINDINGS

Year	Uses	Source
2000	21ST ST INTS FROM	Cole Information
	G E TS E L E L AUTOMOTIVE COMPANY INCORPORATED	Cole Information
	EDDIES AUTO BODY & FENDER WORKS INCORPORATED	Cole Information
	G E TSELEL AUTOMOTIVE INCORPORATED	Cole Information
	ANDREW TSELOS	Cole Information
1995	EDDIE'S AUTO BODY & FENDER WORKS INC	Cole Information
	G E TSELEL AUTOMOTIVE INC	Cole Information
	G E-T'S E L E L AUTOMOTIVE CO INC	Cole Information
1992	A A A POLLUTION CONTROL	Cole Information
	AAA OIL POLLUTION SPECIALISTS INC	Cole Information
	AAA RETUBING & INSTALLATION CORP	Cole Information
	A A A RETUBING & INSTALLATION CORP	Cole Information
1991	A A A Pollution Control	NYNEX Information Resource Company
	A A A POLLUTION CONTROL	NYNEX Information Resource Company
	A A A RETUBING & INSTALLATION CORP Expert Boler Repair And Retubing	NYNEX Information Resource Company
	A A A Retubing & Installation Corp	NYNEX Information Resource Company
	AAA RETUBINUG & INSTALLATION CORP	NYNEX Information Resource Company

3630 14TH ST

Year	Uses	Source
1983	J W J Auto Repr	New York Telephone
1962	Prescott Auto Wreckrs of NY	New York Telephone Directory
1945	Prescott Auto Wreckrs of NY	New York Telephone
1939	Prescott Auto Wreckrs of NY	New York Telephone Company
1934	Prescott Auto Wreckers of NY RTN : Michl Floria Pasquale Piccinni	R. L. Polk & Co.

3731 14TH ST

Year	Uses	Source
1983	Culbert Ethel M	New York Telephone

FINDINGS

3734 14TH ST

Year	Uses	Source
1976	LI Seneca Social Club	New York Telephone

21st

3701 21st

Year	Uses	Source
1950	SWITCHGEAR ASSEMBLY	New York Telephone
	QUEENSBORO ASSEMBLY DIV	New York Telephone
	SWITCHGEAR ASSEMBLY	New York Telephone
	QUEENSBORO ASSEMBLY DIV	New York Telephone

21ST AVE

3702 21ST AVE

Year	Uses	Source
1934	Harder Alice student	R. L. Polk & Co.
	Harder Emil slsmn	R. L. Polk & Co.
	Harder Ida clk	R. L. Polk & Co.
	Sutton Edna	R. L. Polk & Co.
	Sutton Geo Benicia clk	R. L. Polk & Co.
	Sutton Minnie student	R. L. Polk & Co.
	Sutton Robt garagew kr	R. L. Polk & Co.
	Sutton Sophie clk	R. L. Polk & Co.
	Sutton Susanna sten	R. L. Polk & Co.

3704 21ST AVE

Year	Uses	Source
1962	Lotocki Robt W	New York Telephone Directory
1939	OBrien Jos	New York Telephone Company
1934	Adler Betty Mrs City Bargain Store	R. L. Polk & Co.
	Kelley Christopher A Eillen clk	R. L. Polk & Co.
	Mack Mary w id Fred	R. L. Polk & Co.
	Zimler Jacob Rose clk	R. L. Polk & Co.
	Zimitz Sarah clk	R. L. Polk & Co.

FINDINGS

3708 21ST AVE

Year	Uses	Source
1970	Caronia Albert	New York Telephone
	Caronia M	New York Telephone
1967	Caronia Albert	New York Telephone
	Caronia M	New York Telephone
1962	Caronia Albert	New York Telephone Directory
	Caronia M	New York Telephone Directory
1945	Caronia M	New York Telephone
1939	Caronia M	New York Telephone Company
1934	Caronia Lawrence Theresa florist	R. L. Polk & Co.
	Caronia M florist	R. L. Polk & Co.
	Schoenecker Henry Lena meat ctr	R. L. Polk & Co.

3710 21ST AVE

Year	Uses	Source
1945	Gittleson Rose	New York Telephone
1939	Gittleson Rose	New York Telephone Company
	Natl Beer Pipe Cleaning Co	New York Telephone Company
	Natl Svce Co	New York Telephone Company
1934	Gittleson Jacob Bessie	R. L. Polk & Co.
	Gittleson Louis Norma ins broker	R. L. Polk & Co.
	Gittleson Rose	R. L. Polk & Co.

3714 21ST AVE

Year	Uses	Source
1945	Franco Alexndr MD	New York Telephone
1939	France Alexndr MD	New York Telephone Company
1934	Ruck Anna beautician	R. L. Polk & Co.
	Ruck Harry clk	R. L. Polk & Co.
	Ruck Nicholas Susan barber	R. L. Polk & Co.

3718 21ST AVE

Year	Uses	Source
1934	Hall Chas Flora uphol	R. L. Polk & Co.

FINDINGS

3720 21ST AVE

Year	Uses	Source
1967	Rizzuti Vincent DDS ofc	New York Telephone
1962	Rizzutti Vincent DD S ofc	New York Telephone Directory
1945	Rizzuti Benny	New York Telephone
1939	Rizzuti Benny	New York Telephone Company
1934	Lange Otto Clara asst mgr	R. L. Polk & Co.
	Rizzuti Vincent student	R. L. Polk & Co.

3792 21ST AVE

Year	Uses	Source
1939	Harder Emil	New York Telephone Company

3804 21ST AVE

Year	Uses	Source
1992	TESTA, ANGELO	Cole Information
	MCLAUGHLIN, RODD	Cole Information
1970	Kelly F M	New York Telephone
1967	Kelly F M	New York Telephone
1945	De Lisi Marcantonio	New York Telephone
	Kelly Jos V	New York Telephone
1939	Kelly Jos V	New York Telephone Company
1934	Basile Jas Margt tinsmith	R. L. Polk & Co.
	Brennand Mark Anna elev opr	R. L. Polk & Co.
	Matson Chas lab	R. L. Polk & Co.
	Mc Conley Wm Florence lab	R. L. Polk & Co.
	Murphy Wm Cath guard Mhn	R. L. Polk & Co.

3807 21ST AVE

Year	Uses	Source
1970	Camilleri Jos	New York Telephone
	Chollat Namy Germaine	New York Telephone
	Fortune Mabel H Mrs	New York Telephone
	Gittleson M	New York Telephone
	Killoran Cornelius M	New York Telephone

FINDINGS

Year	Uses	Source
1970	Vojtech Chas J	New York Telephone
1967	Camilleri Jos	New York Telephone
	Chollat Namy Germalne	New York Telephone
	Fortune Mabel H Mrs	New York Telephone
	Gittleson M	New York Telephone
	Killoran Cornelius M	New York Telephone
	Robine Frank J	New York Telephone
	Vojtech Chas J	New York Telephone
1962	Camilleri Jos	New York Telephone Directory
	Chollat Namy Germaine	New York Telephone Directory
	Fortune Mabel H Mrs	New York Telephone Directory
	Killoran Cornelius M	New York Telephone Directory
	Vojtech Chas J	New York Telephone Directory
1945	Chollat Namy Germaine	New York Telephone
	Fortune Mabel H Mrs	New York Telephone
	Gittleson Louis	New York Telephone
1934	Bacola Esther w id Louis supt	R. L. Polk & Co.
	Egbert Chas Cath Master Sign Co	R. L. Polk & Co.
	Fortune Mabel Mrs	R. L. Polk & Co.
	Gilliam Cornillus Eva mach opr	R. L. Polk & Co.
	Hackett Julia w id John	R. L. Polk & Co.
	Hela Fred C Anna inspr	R. L. Polk & Co.
	Keiller John Margt	R. L. Polk & Co.
	Naw roth Eritz Gertrude elec w kr	R. L. Polk & Co.
	Parker Dorothy w id Harry clk	R. L. Polk & Co.
	Rose Court apts	R. L. Polk & Co.
	Sutera Chas Helen plmbr	R. L. Polk & Co.
	Willensky Sol Gussie drsmkr	R. L. Polk & Co.

3817 21ST AVE

Year	Uses	Source
1945	De Franco Chas	New York Telephone

FINDINGS

3819 21ST AVE

Year	Uses	Source
1934	Tierl Otto F real est slsmn	R. L. Polk & Co.

21ST ST

3588 21ST ST

Year	Uses	Source
1962	Haris How ard W	New York Telephone Directory

3602 21ST ST

Year	Uses	Source
2020	NYC INTERBORO MANAGEMENT	EDR Digital Archive
	TJ AUTO REPAIRS	EDR Digital Archive
2017	TJ AUTO REPAIRS	Cole Information
2014	TJ AUTO REPAIRS	Cole Information
	TJ AUTOMOBILE REPAIRS	Cole Information
2010	T J AUTO REPAIRS & SVC STATION	Cole Information
	STA AUTO CTR	Cole Information
2005	Shere Punjab Tow ing Inc	Hill-Donnelly Information Services
	TJ Auto Repairs & Svc Station	Hill-Donnelly Information Services
	TJ AUTO REPAIRS & SERVICE STATION IN	Cole Information
	ASTORIA USED AUTO PARTS INC	Cole Information
1995	SIFNOS SERVICE STATION INC	Cole Information
1992	TSIOKRIS FOTIOS	Cole Information
1991	Tsiokris Fotios	NYNEX Information Resource Company
1970	Ravensw ood Svce Sta	New York Telephone
1967	Ravenw ood Svce Sta	New York Telephone
1962	Ravensw ood Sunoco Svce Sta	New York Telephone Directory
1945	Esposito Neil svce sta	New York Telephone
1939	Balboy Svce	New York Telephone Company

3603 21ST ST

Year	Uses	Source
1983	Furlani Jos	New York Telephone

FINDINGS

3605 21ST ST

Year	Uses	Source
1970	Hobbs Raymond E	New York Telephone

3606 21ST ST

Year	Uses	Source
1934	Kenny Katherine tel opr	R. L. Polk & Co.

3607 21ST ST

Year	Uses	Source
2020	DREAM AWNING DESIGN	EDR Digital Archive
	GBI INDUSTRY	EDR Digital Archive
2017	DREAM & SIGNS AWNING	Cole Information
	WANDA ROMERO	Cole Information
2014	DREAM AWNING & DESIGN	Cole Information
	WANDA ROMERO	Cole Information
2010	B & I SIGNS & AWNINGS	Cole Information
	DREAM AWNINGS	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2005	And Signs Dream Awning	Hill-Donnelly Information Services
	B & I Signs & Aw	Hill-Donnelly Information Services
	Dream Awning & Design	Hill-Donnelly Information Services
	VISION TEXTILE OF NY CORP	Cole Information
	DREAM SIGNS & AWNINGS	Cole Information
1995	PINTO ENTERPRISES INC	Cole Information
	JACKSON HEWITT TAX SVC	Cole Information
	TIP TOP TIRES	Cole Information
1992	GRANT ELECTRICAL SUPL CO INC	Cole Information
	GRANT ELECTRICAL SUPPLY	Cole Information
1991	Grant Electrical Supply	NYNEX Information Resource Company
	Grant Electrical Supl Co Inc	NYNEX Information Resource Company
1983	New Foxes Den	New York Telephone
1967	Chez Joey	New York Telephone
1934	Connors Cornelius V personnel clk Dept of Hosp	R. L. Polk & Co.

FINDINGS

3608 21ST ST

Year	Uses	Source
1970	Wolff Sophie Mrs	New York Telephone

3609 21ST ST

Year	Uses	Source
2005	OCCUPANT UNKNOWN	Cole Information
1995	T C B ALARMS	Cole Information

3611 21ST ST

Year	Uses	Source
2020	SEPULVEDA-ALEM HECTOR E MD	EDR Digital Archive
	WEILL CORNELL MEDICINE	EDR Digital Archive
	NAZ ANEELA	EDR Digital Archive
	AMDUR MADELEINE	EDR Digital Archive
	WOMEN & CHILDREN'S HEALTH	EDR Digital Archive
	POLO LORENA MD	EDR Digital Archive
	BENJAMIN BENSY	EDR Digital Archive
	NEHAL UMBEREEN S MD	EDR Digital Archive
	ASGARY RAMIN MD	EDR Digital Archive
	DALAL RISHIKESH P MD	EDR Digital Archive
	NEVES STEPHANIE	EDR Digital Archive
	LONG ISLAND CITY HEALTH	EDR Digital Archive
	CARD ANDREA D MD	EDR Digital Archive
	LEE NANCY JADE MD	EDR Digital Archive
	COMMUNITY HEALTHCARE NETWORK	EDR Digital Archive
2014	COMMUNITY HEALTHCARE NETWORK	Cole Information
	LONG ISLAND CITY HEALTH CENTER	Cole Information
2010	LONG ISLAND CITY HEALTH CTR	Cole Information
	GROVER JILLIAN F	Cole Information
	COMMUNITY HEALTHCARE	Cole Information
	WOMEN & CHILDRENS HEALTH CTR	Cole Information
2005	Long Island City Comm Practice	Hill-Donnelly Information Services
	New York Presbyterian Hospital	Hill-Donnelly Information Services
	Women & Childrens Health Ctr	Hill-Donnelly Information Services

Year	Uses	Source
2005	u Charles Raw lins Julitte 0718 482 7772 oi	Hill-Donnelly Information Services
	NEW YORK PRESBYTERIAN HOSPITAL	Cole Information
	LONG ISLAND CITY COMMUNITY PRAC	Cole Information
2000	NEW YORK HOSPITAL CORNELL MEDICAL CENTER THE	Cole Information
	WOMEN & CHILDRENS HEALTH CENTER	Cole Information
1995	WOMEN & CHILDREN'S HEALTH CENTER	Cole Information
1991	Tel Ko Electronics	NYNEX Information Resource Company
1983	Inter Soccer Sports Enterprises Inc	New York Telephone
	Sav On Petroleum Inc	New York Telephone
1976	Svce Dept	New York Telephone
1970	Parts Dept	New York Telephone
	Svce Dept	New York Telephone
1967	Parts Dept	New York Telephone
	Svce Dept	New York Telephone
1962	Flag Lines Inc	New York Telephone Directory

3616 21ST ST

Year	Uses	Source
1962	Kesten Laurence b	New York Telephone Directory

3617 21ST ST

Year	Uses	Source
1970	LaPadella Ristorante Inc	New York Telephone
1967	Tw in Donuts Inc	New York Telephone
1962	Goldberg Sam Auto Wrecking	New York Telephone Directory
	Goldberg Yeata	New York Telephone Directory
	Zabatta Sal	New York Telephone Directory
1945	Goldberg Sam auto w ieckg	New York Telephone
1939	Goldberg Sam auto w reckg	New York Telephone Company

3618 21ST ST

Year	Uses	Source
2017	AMALGAMATED BANK	Cole Information
2014	AMALGAMATED BANK	Cole Information

FINDINGS

Year	Uses	Source
2010	AMALGAMATED BANK	Cole Information
2005	KFC NATIONAL MANAGEMENT	Cole Information
	KFC	Cole Information
2000	KENTUCKY FRIED CHICKEN USA INCORPORATED	Cole Information
1995	KFC	Cole Information
	KENTUCKY FRIED CHICKEN USA INC	Cole Information
1992	KENTUCKY FRIED CHICKEN NATIONAL MANAGEMENT CO	Cole Information

3619 21ST ST

Year	Uses	Source
2014	KALLIOKUS BALLYS	Cole Information
2005	Ballys Kallokus v	Hill-Donnelly Information Services

3620 21ST ST

Year	Uses	Source
1945	Genl Auto Wreckrs	New York Telephone
1939	Genl Auto Wrecking Co	New York Telephone Company

3621 21ST ST

Year	Uses	Source
2020	MICHAEL'S CAR WASH	EDR Digital Archive
2017	MICHAELS CAR WASH	Cole Information
2014	MICHAELS CAR WASH	Cole Information
2010	AUTO CARE LUBES LTD	Cole Information
	MICHAELS CAR WASH	Cole Information
2005	Michaels Car Wash 2s	Hill-Donnelly Information Services
	h Lage John	Hill-Donnelly Information Services
	MICHAELS CAR WASH	Cole Information
1995	LAGE, JOHN	Cole Information
1992	LAGE, JOHN	Cole Information

3622 21ST ST

Year	Uses	Source
1962	Twin Lane Auto Lndry	New York Telephone Directory

FINDINGS

3624 21ST ST

Year	Uses	Source
2020	SHAH JEE MOTORS	EDR Digital Archive
	T & A TOP MOTORS	EDR Digital Archive
2017	T & A TOP MOTORS	Cole Information
	SHAH JEE MOTORS	Cole Information
	HILLSTAR MOTOR INCORPORATED	Cole Information
2014	T & A TOP MOTORS	Cole Information
	SHAH JEE MOTORS	Cole Information
2010	BEST AUTO MARKET INC	Cole Information
	T & A TOP MOTORS	Cole Information
2005	T& A Top Motors	Hill-Donnelly Information Services
	Worldwide Best Buy Cars Inc	Hill-Donnelly Information Services
	WORLDWIDE BEST BUY CARS INC	Cole Information
	BEST AUTO MARKET INC	Cole Information
1962	Peggys Diner	New York Telephone Directory

3626 21ST ST

Year	Uses	Source
1945	Nats Auto Wreckrs Inc	New York Telephone

3632 21ST ST

Year	Uses	Source
2017	GENERAL AUTO REPAIRS INC	Cole Information
2014	GENERAL AUTO REPAIRS INC	Cole Information
	GENERAL AUTOMOBILE REPAIRS INCORPORA	Cole Information
2010	GENERAL AUTO REPAIRS INC	Cole Information
2005	General Auto Repairs Inc	Hill-Donnelly Information Services
	GENERAL AUTO REPRS INC	Cole Information
2000	GENERAL AUTO REPRS INCORPORATED	Cole Information
	H & H CAR BUYERS	Cole Information
1995	GENERAL AUTO SALES	Cole Information
	GENERAL AUTO REPRS INC	Cole Information
1992	GENERAL AUTO REPRS INC	Cole Information

FINDINGS

3633 21ST ST

Year	Uses	Source
2017	JOHN L CAR WASH	Cole Information
2014	JOHN L CAR WASH	Cole Information
2010	JOHN L CAR WASH	Cole Information
2005	JOHN L CAR WASH	Cole Information
2000	JOHN L CAR WASH	Cole Information
1995	JOHN L CAR WASH	Cole Information
1992	SILVEIRA & GONCALVES CAR WASH INC	Cole Information
1991	Silveira & Goncalves Car Wash Inc	NYNEX Information Resource Company
1983	Silveira & Goncalives Car Wash Inc	New York Telephone
1970	Leifer Bros Steel Co Inc	New York Telephone
1967	Leifer Bros Steel Co Inc	New York Telephone
1962	Leifer Bros Steel Co Inc	New York Telephone Directory
1945	Amer Coml Steel Co	New York Telephone
1939	Amer Coml Steel Co	New York Telephone Company

3637 21ST ST

Year	Uses	Source
2020	ULTIMATE AUTO CARE	EDR Digital Archive
2017	9 DOLLAR LOCKSMITH	Cole Information
	ULTIMATE AUTO CARE	Cole Information
2014	ULTIMATE AUTOMOBILE CARE	Cole Information
2010	ULTIMATE AUTO CARE	Cole Information
2005	Ultimate Auto Care Is	Hill-Donnelly Information Services
	ULTIMATE AUTO CARE OF 21ST	Cole Information
2000	T & V AUTO SVCE CENTER INCORPORATED	Cole Information
1995	T & V AUTO SVCE CENTER INC	Cole Information
1992	T & V AUTO SVCE CENTER INC	Cole Information
1991	T & V Auto Svce Center Inc	NYNEX Information Resource Company
1983	T & V Auto Svce Sta	New York Telephone
1970	Your Own Svce Sta	New York Telephone
1967	Your Own Svce Sta	New York Telephone
1962	Your Own Svce Sta	New York Telephone Directory

FINDINGS

Year	Uses	Source
1945	Your Own Svc Sta Inc	New York Telephone
1939	Relay Motor Truck Svce	New York Telephone Company

3638 21ST ST

Year	Uses	Source
1970	SKR Car Wash & Machinery Co Inc	New York Telephone
	Talk of The Town Car Wash	New York Telephone

3640 21ST ST

Year	Uses	Source
1970	Twee Twee Syce Sta	New York Telephone
1967	Twee Twee svce sta	New York Telephone
1962	Twee Twee svce sta	New York Telephone Directory
1945	C & F Svce Sta	New York Telephone
1939	De Rosa Jos gas sta	New York Telephone Company

3642 21ST ST

Year	Uses	Source
2020	H M SVC STATION	EDR Digital Archive
2017	H M SVCE STA	Cole Information
2014	H M SERVICE STATION	Cole Information
2010	H M SVC STATION	Cole Information
2005	H M Svc Station 1 R	Hill-Donnelly Information Services
	H M SERVICE STA	Cole Information
1995	H M SVCE STA	Cole Information
1992	H M SVCE STA	Cole Information
1991	H M Svce Sta	NYNEX Information Resource Company

3650 21ST ST

Year	Uses	Source
2014	DAVID WALKER	Cole Information
2010	DAVID WALKER	Cole Information

3702 21ST ST

Year	Uses	Source
2010	SILIA CHRISTOFI	Cole Information

FINDINGS

3703 21ST ST

Year	Uses	Source
2020	METROMETER SHOP INC	EDR Digital Archive
2017	A A TOWING ILLEGALLY PARKED REMOVED	Cole Information
2014	A A TOWING ILLEGALLY PARKED REMOVED	Cole Information
2000	NINA FOOTWEAR CORPORATION	Cole Information
1995	NINA FOOTWEAR INC	Cole Information
1992	NINA FOOTWEAR INC	Cole Information
1991	Nina Footwear Inc	NYNEX Information Resource Company
1983	Amer Sanitary Partition Corp	New York Telephone
1976	Amer Sanitary Partitions Corp	New York Telephone
1970	Amer Samitary Partition Corp	New York Telephone
1967	Amer Sanitary Partitiore Corp	New York Telephone
1962	Amer Sanitary Partition Corp	New York Telephone Directory

3704 21ST ST

Year	Uses	Source
2010	BLANCA MONSALVE	Cole Information

3708 21ST ST

Year	Uses	Source
2005	LILY COURTLAND	Cole Information

3711 21ST ST

Year	Uses	Source
2014	ANTHONY ALDORASI	Cole Information
2010	ANTHONY ALDORASI	Cole Information
2000	N Y CITY BD OF EDUCATION	Cole Information
	N Y CITY OF EDUCATION	Cole Information

3714 21ST ST

Year	Uses	Source
2010	PEDRO KOURTESIS	Cole Information
2005	PEDRO KOURTESIS	Cole Information
1934	Ruck Nicholas tel installer	R. L. Polk & Co.

FINDINGS

3717 21ST ST

Year	Uses	Source
1945	Reliable Auto Wreckrs	New York Telephone
1939	C & S Auto Wrecking Co	New York Telephone Company
	Reliable Auto Wrecking Co	New York Telephone Company

3718 21ST ST

Year	Uses	Source
2010	DIANE CAMPBELL	Cole Information

3720 21ST ST

Year	Uses	Source
2010	ANTHONY BARTOLOTTA	Cole Information

3734 21ST ST

Year	Uses	Source
2014	EHSEN ALI	Cole Information
2010	EHSEN ALI	Cole Information

3735 21ST ST

Year	Uses	Source
2020	COMFORT INN	EDR Digital Archive
2010	ERRA METALS INC	Cole Information
2005	ERRA METALS INC	Cole Information
	ERRA ROCCO	Cole Information
2000	A A ERRA METALS INCORPORATED	Cole Information
	ERRA ROCCO SCRP MTLS	Cole Information
1995	A A ERRA METALS INC	Cole Information
	ERRA METALS INC	Cole Information
	ERRA ROCCO, SCRP MTLS	Cole Information
1992	ERRA ROCCO, SCRP MTLS	Cole Information
1939	Erra Rocco & Son scrap metl	New York Telephone Company
	Rocco Erra scrap metl	New York Telephone Company

FINDINGS

3744 21ST ST

Year	Uses	Source
2020	QUEENSBORO PUBLIC LIBRARY-LONG	EDR Digital Archive
2017	QUEENSBORO PUBLIC LIBRARYLONG ISLAN	Cole Information
2014	QUEENSBORO PUBLIC LIBRARYLONG ISLAN	Cole Information
2010	LONG ISLAND CITY PUBLIC LIBR	Cole Information

3745 21ST ST

Year	Uses	Source
2020	NICOSLA SERVICE CTR	EDR Digital Archive
2017	MS FUEL INC	Cole Information
2014	MS FUEL INCORPORATED	Cole Information
	A NICOSIA SERVICE CENTER	Cole Information
2010	NICOSIA SERVICE CTR	Cole Information
2005	ROYAL CROWN AUTO CENTER INC	Cole Information
	NICOSIA SERVICESTATION INC	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2000	A NICOSIA SERVICES CNTR	Cole Information
	GUSS TEXACO	Cole Information
1995	GUS'S TEXACO	Cole Information
	NICOSIA SVCE CENTER	Cole Information
1992	GUS'S TEXACO	Cole Information
	NICOSIA SVCE CENTER	Cole Information
1991	Guss Texaco	NYNEX Information Resource Company
	Nicosia Svce Center	NYNEX Information Resource Company
1983	CONSTANTINES SVCE STA	New York Telephone
	Guss Shell Svce Sta	New York Telephone
1976	Guss Shell Svce Sta	New York Telephone
1970	Authentic Auto Svce Inc	New York Telephone
1967	Van Alst Svce Sta	New York Telephone
1962	VanAlst Service Station	New York Telephone Directory
1945	Van Alst Service Sta	New York Telephone
1939	Plaza Auto Repairg	New York Telephone Company

FINDINGS

Year	Uses	Source
1934	Van Alst Service Station RTN Peter Vartabedian	R. L. Polk & Co.

3801 21ST ST

Year	Uses	Source
2020	KING OF QUEENS AUTOMOTIVE	EDR Digital Archive
1970	Burger Stop Inc	New York Telephone
1967	Burger Stop Inc	New York Telephone

3802 21ST ST

Year	Uses	Source
2020	SHELL GAS STATION	EDR Digital Archive
	HERMIN EMPIRE	EDR Digital Archive
2017	SHELL	Cole Information
	T & H MANAGEMENT INC	Cole Information
	HERMIN EMPIRE	Cole Information
	HERMIN EMPIRES INC	Cole Information
2014	HERMIN EMPIRE	Cole Information
	HERMIN EMPIRES INCORPORATED	Cole Information
2010	T & H MANAGEMENT INC	Cole Information
2005	T & H Management Inc	Hill-Donnelly Information Services
1995	SAVEWAY ASTORIA INC	Cole Information
1992	SAVEWAY ASTORIA INC	Cole Information
1970	Economy Svce	New York Telephone
1967	Economy Svce	New York Telephone
1962	Economy Svce	New York Telephone Directory
1945	World Oil Corp	New York Telephone

3803 21ST ST

Year	Uses	Source
2020	BROTHERS 786 INC	EDR Digital Archive
2017	SFEIR CAB CORP	Cole Information
	KING OF QUEEN AUTOMOTIVE LLC	Cole Information
	KING OF QUEENS AUTOMOTIVE	Cole Information
2010	NEW USA AUTO REPAIR SVC	Cole Information

FINDINGS

Year	Uses	Source
2010	UHAUL CO	Cole Information
	U S AUTO REPAIR SHOP	Cole Information
2005	Queens Auto Repair & Body SHP	Hill-Donnelly Information Services
	QUEENS AUTO REPAIR & BODY SHOP INC	Cole Information
1995	NY-QUEENS ILLEGAL PARKING INC	Cole Information
1991	Berry Jose	NYNEX Information Resource Company
1983	K & B Auto Svce	New York Telephone

3804 21ST ST

Year	Uses	Source
2010	MARIA CIERNO	Cole Information
	MAY WANHAMID	Cole Information

3807 21ST ST

Year	Uses	Source
2014	HAYDEE RAMOS	Cole Information
	JAMES DOOLEY	Cole Information
2010	RABIA AKTER	Cole Information
	IVAN ANASTASSOV	Cole Information
	MARLA KUSNET	Cole Information
	DUMITRIU CAMELIA	Cole Information
	SAFET AVDIC	Cole Information
	HAYDEE RAMOS	Cole Information
	KALLIOPI STEFATOS	Cole Information
	ILEANA BOBES	Cole Information
	JOHN YASKO	Cole Information
	JAMES DOOLEY	Cole Information
	BERDJUHI ANTEKELYAN	Cole Information

3810 21ST ST

Year	Uses	Source
1962	Velotta Sue Mrs	New York Telephone Directory
1939	Acme Gas Sta	New York Telephone Company

FINDINGS

3811 21ST ST

Year	Uses	Source
1967	Chiarella Donato	New York Telephone
1962	Miale Domenick M	New York Telephone Directory
1934	Chiarella John Theresa	R. L. Polk & Co.
	Chiarella John Dorothy chauf	R. L. Polk & Co.
	Chiarella Lillian	R. L. Polk & Co.
	Chiarella Lora pkr	R. L. Polk & Co.
	Chiarella Marie	R. L. Polk & Co.

3815 21ST ST

Year	Uses	Source
1995	GRAND AUTO SALES	Cole Information
1992	GRAND AUTO SALES	Cole Information
1970	Hertz Truck Leasing & Rentl	New York Telephone
1967	Rent A Truck	New York Telephone
1962	HERTZ TRUCK LEASING & RENTL SVCE	New York Telephone Directory
1934	Quinn Ellen w id Jas	R. L. Polk & Co.
	Quinn Rita	R. L. Polk & Co.

3817 21ST ST

Year	Uses	Source
1983	De Lalla Louise	New York Telephone
1962	Metropolitn Truck Rentl	New York Telephone Directory
1934	Daly Elizabeth w id Wm	R. L. Polk & Co.
	Daly Margt sten	R. L. Polk & Co.

3819 21ST ST

Year	Uses	Source
2017	PEP BOYS	Cole Information
	STRICTLY LOCKSMITH	Cole Information
2014	PEP BOYS	Cole Information
2010	STAPLES	Cole Information
2005	Staples The Office Superstore	Hill-Donnelly Information Services
	STAPLES THE OFFICE SUPERSTORE	Cole Information

FINDINGS

Year	Uses	Source
2000	STAPLES THE OFFICE SUPERSTORE	Cole Information
	STAPLES THE OFFICE SUPERSTORE	Cole Information
1995	STAPLES THE OFFICE SUPERSTORE	Cole Information
1992	STAPLES THE OFFICE SUPERSTORE	Cole Information

3820 21ST ST

Year	Uses	Source
2000	PEP BOYS AUTOMOTIVE	Cole Information

3821 21ST ST

Year	Uses	Source
1934	Campbell Jas Alice clk PO	R. L. Polk & Co.
	Hill Patk Mary	R. L. Polk & Co.

3823 21ST ST

Year	Uses	Source
1934	Teofrio Peter Theresa porter	R. L. Polk & Co.

3825 21ST ST

Year	Uses	Source
2017	COMPLETE AUTO SERVICE	Cole Information
2014	HITECH AUTO REPR & BODY SHOP	Cole Information
2010	COMPLETE AUTO SVC	Cole Information
2005	Complete Auto Svc is	Hill-Donnelly Information Services
	NEW HI TECH AUTO REPAIR & BODY SHOP	Cole Information
2000	COMPLETE AUTO SERVICE	Cole Information
1995	HI-TECH AUTO REPR & BODY SHOP	Cole Information
1992	M & W BODY SHOP	Cole Information
	PUNJAV AUTO REPR	Cole Information
1991	Lupoli Svce Sta	NYNEX Information Resource Company
1983	Lupoli Svce Sta	New York Telephone
1976	Cioffi Svce Sta	New York Telephone
1970	Cioffi Svce Sta	New York Telephone
1967	Cioffi Svce Sta	New York Telephone
1962	Cioffi Svce Sta	New York Telephone Directory

Year	Uses	Source
1934	Flynn Robt May chauf	R. L. Polk & Co.

3826 21ST ST

Year	Uses	Source
2017	WAVE CAR WASH	Cole Information
2014	WAVE CAR WASH	Cole Information
2010	WAVE CAR WASH	Cole Information
2005	Niagra Car Washunderdog	Hill-Donnelly Information Services
	Wave Car Wash s	Hill-Donnelly Information Services
	WAVE CAR WASH	Cole Information
2000	WAVE CAR WASH	Cole Information

3837 21ST ST

Year	Uses	Source
1939	Lupoli Nick	New York Telephone Company
1934	Lupoli Jennie clk Tisdale Lumber Co	R. L. Polk & Co.
	Lupoli Nicholas Virginia pdlr	R. L. Polk & Co.
	Lupoli Peter pdlr	R. L. Polk & Co.
	Lupoli Raffaele police	R. L. Polk & Co.

22 ABBREV ASTORIA

3611 22 ABBREV ASTORIA

Year	Uses	Source
1991	Targa Auto Body Repr	NYNEX Information Resource Company
	Targa Auto Body Repr	NYNEX Information Resource Company

22 LIC

3802 22 LIC

Year	Uses	Source
1991	A G A Deli Restrnt	NYNEX Information Resource Company

FINDINGS

22IBAY SD 95242

3611 22IBAY SD 95242

Year	Uses	Source
1945	McCann Jos S	New York Telephone

22ND

3802 22ND

Year	Uses	Source
1962	Nappi Richd H b	New York Telephone Directory

22ND AVE

3714 22ND AVE

Year	Uses	Source
1962	Krouse John F	New York Telephone Directory

22ND ST

3505 22ND ST

Year	Uses	Source
1962	Soltan Eileen P	New York Telephone Directory

3506 22ND ST

Year	Uses	Source
1970	Miglin Stella E	New York Telephone

3537 22ND ST

Year	Uses	Source
1970	Sims Hilda	New York Telephone

3609 22ND ST

Year	Uses	Source
1967	J B Waste Oil Co	New York Telephone

3611 22ND ST

Year	Uses	Source
2020	DELPHI INTERIORS CABINETS LTD	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	EDISON ELECTRICAL CORP	EDR Digital Archive
2017	DELPHI CUSTOM FURNITURE LTD	Cole Information
	DRILL REALTY INC	Cole Information
	DELPHI INTERIORS CABINETS LTD	Cole Information
	EDISON ELECTRICAL CORP	Cole Information
2014	DRILL REALTY INCORPORATED	Cole Information
	EDISON ELECTRICAL CORPORATION	Cole Information
	DELPHI CUSTOM FURNITURE LIMITED	Cole Information
	DELPHI INTERIORS CABINETS LIMITED	Cole Information
2010	DRILL REALTY INC	Cole Information
2005	Delphi Interiors Cabinets LTD	Hill-Donnelly Information Services
	Drill Realty Inc I F	Hill-Donnelly Information Services
	DELPHI INTERIORS CABINETS LTD	Cole Information
	DRILL REALTY INC	Cole Information
2000	Stavros Tsagouris	Cole Information
	STAVROS TSAGOURIS	Cole Information
1995	SPEEDY EDDY AUTOMOTIVE	Cole Information
1992	SPEEDY EDDY AUTOMOTIVE	Cole Information
1983	Leo Stern Inc	New York Telephone
1970	Lilie Hoffmann Steel Towens Inc	New York Telephone
	Pauls Auto Reprs	New York Telephone
1967	Lilie Hoffmann Steel Towers Inc	New York Telephone
	Pauls Auto Repr	New York Telephone
1962	Ely Sunswick Corp	New York Telephone Directory
	Equipment Erecting Corp	New York Telephone Directory
	Equipment Installation Co Inc	New York Telephone Directory
	Lilie Hoffmann Steel Towers Inc	New York Telephone Directory
	Pollack Selig contr	New York Telephone Directory
1939	Pollack Selig b	New York Telephone Company
1934	Pollack Selig Inc cap $1 000 Selig Pollack pres treas riggers ship	R. L. Polk & Co.

FINDINGS

3613 22ND ST

Year	Uses	Source
2020	JAVELIN ELECTRIC	EDR Digital Archive
2005	Utos Athanasios	Hill-Donnelly Information Services
	ATHANASIOS LITOS	Cole Information
1995	ULTRACOOL	Cole Information
1992	SHELLO MOTORS	Cole Information
	L & L SVCE STA INC	Cole Information
1991	L & L Svce Sta Inc	NYNEX Information Resource Company
1983	Paramedical Specialties Inc	New York Telephone

3614 22ND ST

Year	Uses	Source
1991	GOMEZS AUTO BODY	NYNEX Information Resource Company

3615 22ND ST

Year	Uses	Source
1945	Queens Mach & Tool Co	New York Telephone

3617 22ND ST

Year	Uses	Source
2005	JOHN MOUKAS	Cole Information
1995	UNITED CUSTOM MADE FURNITURE INC	Cole Information
	CUSTOM MADE FURNITURE BY UNITED	Cole Information
1992	UNITED CUSTOM MADE FURNITURE INC	Cole Information
1991	UNITED CUSTOM MADE FURNITURE INC	NYNEX Information Resource Company
1983	Bridge Oil Co Inc	New York Telephone
1976	OIL SVCE CORP	New York Telephone
1970	JB OIL SVCE CORP	New York Telephone
1967	J B OIL SVCE CORP	New York Telephone
1962	WELLS BROS IRON WKS	New York Telephone Directory
1945	Wells Bros Iron & Plate Wks	New York Telephone

3618 22ND ST

Year	Uses	Source
1983	LIC Junk Yard Inc	New York Telephone

FINDINGS

3621 22ND ST

Year	Uses	Source
2020	K B F INC	EDR Digital Archive
2017	KBF INC	Cole Information
2014	SOUTHERN FOOD USA INCORPORATED	Cole Information
2000	W Chiang	Cole Information
	W CHIANG	Cole Information
1995	W CHIANG	Cole Information
1992	W CHIANG	Cole Information
1991	W Chiang	NYNEX Information Resource Company
1983	Shine Electronics Co Inc	New York Telephone
	Tel Star TV Co	New York Telephone

3625 22ND ST

Year	Uses	Source
1983	Mauro H & Son	New York Telephone
1945	Service & warehouse	New York Telephone
	Nicholas Pile Co	New York Telephone
	Ryan Crane & Shovel Svce Inc	New York Telephone
1939	Owen Bucket Co The	New York Telephone Company
	Rapp John F b	New York Telephone Company
	Ryan Crane & Shovel Svce Inc	New York Telephone Company
1934	Owen Bucket Co Ohio Frank W S Elmes mgr machy mfrs	R. L. Polk & Co.

3631 22ND ST

Year	Uses	Source
2020	M A A P I S INC	EDR Digital Archive
2017	C 2 PLUMBING CORP	Cole Information
	CASE CONSTRUCTION CO INC	Cole Information
2014	C TWO PLUMBING CORPORATION	Cole Information
	CASE CONSTRUCTION CO INC	Cole Information
2010	CASE CONSTRUCTION CO INC	Cole Information
	C 2 PLUMBING CORP	Cole Information
2005	C 2 Plumbing Corp	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	Case Construction Co Inc	Hill-Donnelly Information Services
	JOHN LAGE CAR WASHING	Cole Information
	CASE PLUMBING LLC	Cole Information
2000	AKRO GENERAL CONTRACTING INCORPORATED	Cole Information

3633 22ND ST

Year	Uses	Source
2017	START MANAGEMENT LLC	Cole Information
2010	SOUTHERN FOOD USA INC	Cole Information
	ADELPHI RESTORATION CORP	Cole Information
2005	Delphi Restoration	Hill-Donnelly Information Services
	Southern Food USA Inc	Hill-Donnelly Information Services
	DELPHI RESTORATION CORP	Cole Information
	ADELPHI RESTORATION CORP	Cole Information
	P & A INTERNATIONAL INC	Cole Information
	SOUTHERN FOOD USA INC	Cole Information
2000	EMCO TECHNOLOGY CONSTRUCTION CORPORATION	Cole Information
1992	REVERE ARMORED INC	Cole Information

3635 22ND ST

Year	Uses	Source
2017	21ST CENTURY AUTO REPAIR BODY SHOP	Cole Information
2005	Color Guide Of New York	Hill-Donnelly Information Services
	COLOR GUIDE OF NEW YORK	Cole Information
1995	A & H AUTO REPAIR	Cole Information
	W T WINTER ASSOCS INC	Cole Information
	AMERICAN COMPUTER MACHINES ENTERPRISE INC	Cole Information
	THE SOUND BEYOND ELECTRICAL CORP	Cole Information
	H S CONSTRUCTION	Cole Information
	A & H AUTO REPR	Cole Information
1992	W T WINTER ASSOCS INC	Cole Information
1991	Food & Juice Inc	NYNEX Information Resource Company

FINDINGS

Year	Uses	Source
1991	Mail Flight Ltd	NYNEX Information Resource Company
1983	Flexco Prods Inc	New York Telephone
	Regal Prods Co zippers	New York Telephone
1976	Flexco Prods Inc	New York Telephone
1970	Flexco Prods Inc	New York Telephone
	JB Waste Oil Co	New York Telephone
1967	Flexco Prods Inc	New York Telephone
1962	Flexco Prods Inc	New York Telephone Directory
1945	Burmann Bros w d turning	New York Telephone
1939	Burmann Bros Inc w d turng	New York Telephone Company
1934	Burmann Bros Philip Fredk and Carl Burmann w ood turners	R. L. Polk & Co.
	Burmann Carl Elizabeth Burmann Bros	R. L. Polk & Co.
	Burmann Fredk Martha Burmann Bros	R. L. Polk & Co.
	Burmann Philip Cath Burmann Bros	R. L. Polk & Co.

3638 22ND ST

Year	Uses	Source
1970	DelGrosso Yolanda	New York Telephone

3639 22ND ST

Year	Uses	Source
2010	BMI AUTO & BODY CTR	Cole Information
2005	Bmi Auto &Body Ctr ls 718 482 681801 o	Hill-Donnelly Information Services
	B M I AUTO & BODY CENTER	Cole Information
2000	Licoln Auto & Body	Cole Information
	LINCOLN AUTO & BODY CENTER	Cole Information
1995	GOLDEN TOUCH COLLISION	Cole Information
1991	MATSULO INTERIOR ASSOCS	NYNEX Information Resource Company

3640 22ND ST

Year	Uses	Source
2020	GLADSTONE GALLERY	EDR Digital Archive
2017	GLADSTONE GALLERY	Cole Information
2014	GLADSTONE GALLERY	Cole Information

FINDINGS

3701 22ND ST

Year	Uses	Source
2000	BAC Klim Assc Inc	Cole Information
	37TH AV INTS FROM	Cole Information

3709 22ND ST

Year	Uses	Source
2020	JALAL MOTOR LLC	EDR Digital Archive
2014	TJ AUTOMOBILE BODY INCORPORATED	Cole Information
2010	T J AUTOBODY INC	Cole Information
2005	T 3 Autobody Shop Is	Hill-Donnelly Information Services
	T J AUTOBODY INC	Cole Information
	NEW T J MOTOR INC	Cole Information
2000	Patiala Auto Rpr	Cole Information
	RAFIQ MOHAMMED	Cole Information

3710 22ND ST

Year	Uses	Source
2010	SHOW MEDIA	Cole Information

3711 22ND ST

Year	Uses	Source
2020	NEW PRESTIGE AUTOMTV CARE INC	EDR Digital Archive
2017	LLC CUSTOM AUTO & BODY SHOP INC	Cole Information
	NEW PRESTIGE AUTOMOTIVE CARE INC	Cole Information
2014	LIC CUSTOM AUTO & BODY SHOP INC	Cole Information
	NEW PRESTIGE AUTOMOTIVE CARE INCORPO	Cole Information
2010	LIC CUSTOM AUTO & BODY SHOP	Cole Information
	NEW PRESTIGE AUTOMOTIVE	Cole Information
2005	Lic Custom Auto & Body Shop	Hill-Donnelly Information Services
	Prestige Auto Care Ctr Inc	Hill-Donnelly Information Services
	LIC CUSTOM AUTO & BODY SHOP INC	Cole Information
2000	LIC Auto & Body Inc	Cole Information
1991	Apple Gate & Security Co Inc	NYNEX Information Resource Company
	Apple Gate & Security Co Inc	NYNEX Information Resource Company

FINDINGS

Year	Uses	Source
1983	Will Do Messenger & Trucking Svce	New York Telephone
1970	VOLUNTEERS OF AMER clthg etc pick up svce	New York Telephone
1967	VOLUNTEERS OF AMERICA clothing etc pick up svce	New York Telephone
1962	VOLUNTEERS OF AMERICA clothing etc pick up svce	New York Telephone Directory
1945	Harlem Chemcl Co	New York Telephone
	Hecht Saml chemcls	New York Telephone
	Hecht Saml chemcls	New York Telephone
	Melrah Pharmaceuticals Co	New York Telephone
1939	Amer Fibre Mills	New York Telephone Company
1934	Harpoon Paint Products Co Inc NY Philip C Samuels pres Edw Brandt v pres sec treas paint mfrs	R. L. Polk & Co.

3713 22ND ST

Year	Uses	Source
2020	HYEWAY AUTO REPAIR INC	EDR Digital Archive
2010	HYEWAY AUTO REPAIR INC	Cole Information
2005	Hyew ay Auto Repair Inc	Hill-Donnelly Information Services
	OCCUPANT UNKNOWN	Cole Information
2000	Hyew ay At Rpr Inc	Cole Information
	HYEWAY AUTO REPAIR INCORPORATED	Cole Information
1992	BRUNO LIMOUSINE, USED CARS	Cole Information
1991	Bruno Limousine used cars	NYNEX Information Resource Company
1983	Andys Truck Repr	New York Telephone

3715 22ND ST

Year	Uses	Source
1934	Willette Edw Helen mgr Kernerator Co	R. L. Polk & Co.

3716 22ND ST

Year	Uses	Source
2020	R & N COLLISION LTD	EDR Digital Archive
2017	R & N COLLISION LTD	Cole Information

FINDINGS

Year	Uses	Source
2014	R & N COLLISION LTD	Cole Information
	COLLISION SERVICES INCORPORATED	Cole Information
2010	QUEENS COUNTY COLLISION INC	Cole Information
	CRO RAD REALTY	Cole Information
	R & N COLLISION LTD	Cole Information
2005	R & N Collision LTD is	Hill-Donnelly Information Services
	R & N COLLISION LTD	Cole Information
2000	R & N Collsion Ltd	Cole Information
	R & N COLLISION LIMITED	Cole Information
1995	R & N COLLISION LTD	Cole Information
1992	R & N COLLISION LTD	Cole Information
1991	R & N Collision Ltd	NYNEX Information Resource Company
1945	Amer Sanitary Partition Co	New York Telephone
	Capitol Sup & Mfg Co	New York Telephone
	Katz J M bathroom fixts	New York Telephone
1939	Amer Sanitary Partition Co	New York Telephone Company

3717 22ND ST

Year	Uses	Source
1945	Alpha Sheet Metal Works	New York Telephone
1939	Alpha Sheet Metal Works	New York Telephone Company

3718 22ND ST

Year	Uses	Source
1934	Sands Lubricant Co TN Michl Sand	R. L. Polk & Co.

3720 22ND ST

Year	Uses	Source
2017	ELEMENTAL FOOD DESIGN INCORPOR	Cole Information
	22ND ST EMERGENCY PLUMBING SERVICES	Cole Information
	LONG IS CITY AMERICAN	Cole Information
2014	22ND STREET EMERGENCY PLUMBING SERVI	Cole Information
	OTARIAN INCORPORATED	Cole Information

FINDINGS

Year	Uses	Source
2014	LONG IS CITY AMERICAN	Cole Information
	ELEMENTAL FOOD DESIGN INCORPORATED	Cole Information
2010	SUSHI HOUSE	Cole Information
2005	Sushi House 2 R	Hill-Donnelly Information Services
	ISABI CORP	Cole Information
2000	Susbi House	Cole Information
	SUSHI HOUSE	Cole Information
1995	COLLISION AUTO REPAIR SVC	Cole Information
1992	QUALI-T CREATIONS INC	Cole Information
1991	Quali T Creations Inc	NYNEX Information Resource Company
1962	Bens Coml Truck Painting	New York Telephone Directory
	YORK SCAFFOLD & LADDER RENTL CORP	New York Telephone Directory

3723 22ND ST

Year	Uses	Source
1991	Saniuk Lidia	NYNEX Information Resource Company

3724 22ND ST

Year	Uses	Source
2017	T & H VENDING SUPPLY INC	Cole Information
2014	PRINCEKA DISTRIBUTION INCORPORATED	Cole Information
2000	American Empire	Cole Information
	38TH AV INTS FROM	Cole Information
1995	FIRST AIR SERVICE INC	Cole Information
1945	Bruno Patents Inc	New York Telephone
1939	LI Tank Co	New York Telephone Company
	Stimmel Leanard w inches	New York Telephone Company
	Stimmel Saml w inches	New York Telephone Company
	Stimmel Winch Co	New York Telephone Company
1934	Curtis Edw F pres treas Curtis Trucking Co Inc	R. L. Polk & Co.
	Curtis Truking Co Inc NY Edw F Curtis pres treas Jos Zinque sec	R. L. Polk & Co.
	Zinque Jos sec Curtis Trucking Co Inc	R. L. Polk & Co.

FINDINGS

3732 22ND ST

Year	Uses	Source
1976	CONSOLIDATD CARPET TRADE WORKROOM INC	New York Telephone
1970	CONSOLIDATO CARPET TRADE WORKROOM INC	New York Telephone
1967	CONSOLIDATD CARPET TRADE WORKROOM INC	New York Telephone
1934	Gudeman Leo Lillian v pres Golden Bear Cookie Co Inc	R. L. Polk & Co.

3740 22ND ST

Year	Uses	Source
1939	Golden Bear Cookie Co Inc	New York Telephone Company

3742 22ND ST

Year	Uses	Source
1992	TARA MECHANICAL CO INC	Cole Information
1991	Tara Mechanical Co Inc	NYNEX Information Resource Company
	Tara P I	NYNEX Information Resource Company
	Trishul Mechanical Corp	NYNEX Information Resource Company
1983	Allied Sheet Metal Wks Inc	New York Telephone
1962	Torque Transmission of Queens Inc	New York Telephone Directory
1945	Brinberg Body Bldrs	New York Telephone
1939	Brinberg Body Bldrs Inc	New York Telephone Company

3782 22ND ST

Year	Uses	Source
1934	Golden Bear Cookie Co Inc cap $100000 Jos Hirsch pres Leo Gudeman v pres Lee Hirsch sec treas	R. L. Polk & Co.

3802 22ND ST

Year	Uses	Source
2020	UNITED AUTO REPAIR INC	EDR Digital Archive
2017	UNITED MOTOR SERVICE	Cole Information
2010	UNITED MOTOR SERVILCE	Cole Information
2005	Super Auto Transmissions	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	United Auto Repair Inc 15s	Hill-Donnelly Information Services
2000	Bnglmtr Rpr & Body	Cole Information
	Super Auto Trans	Cole Information
	BNGLAMOTOR REPAIR & BODY SHOP	Cole Information
	SUPER AUTO TRANSMISSIONS	Cole Information
1992	NATO AUTO BODY REPAIR	Cole Information
	TEDDY'S RESTAURANT CORP	Cole Information
	K & S AUTO REPR	Cole Information
	AGA DATA SVCECO INC	Cole Information
1991	All World Import Export Corp	NYNEX Information Resource Company
	K & S Auto Repr	NYNEX Information Resource Company
1983	AGA Data Svce Co Inc	New York Telephone
	GODIVA CHOCOLATIER INC	New York Telephone
	Notos Auto Body Repr	New York Telephone
1970	Industrl Finishing Co	New York Telephone
	Nappi Richd H b	New York Telephone
1967	Industrl Finislhing Co	New York Telephone
	Nappi Richd H b	New York Telephone
1962	Industri Finishing Co	New York Telephone Directory
	Industri Filter Prods Inc	New York Telephone Directory
1945	Industri Finishing Co	New York Telephone
	Magnus Mach Tool Co Ltd	New York Telephone
	Nappi Richd H b	New York Telephone
1939	Industrl Finishing Corp	New York Telephone Company
	Murphy & Co auto paintng	New York Telephone Company
	Nappi Richd H b	New York Telephone Company
1934	P & D Mfg Co Inc NY cap $50 000 Peter Piffath pres Bert Danziger sec treas auto parts	R. L. Polk & Co.
	P & D Mfg Co of Canada Ltd Ont Can: cap $20 000 Peter Piffah pers Bert Danziger sec treas auto parts	R. L. Polk & Co.

FINDINGS

23RD

3716 23RD

Year	Uses	Source
1934	Adler SIMON SEC TREAS STEUBEN KITCHEN INC	R. L. Polk & Co.

23RD AVE

3706 23RD AVE

Year	Uses	Source
1934	Astoria Auto Laundry TN Jos Bruno	R. L. Polk & Co.

3707 23RD AVE

Year	Uses	Source
1934	Perrichio Steph Pauline	R. L. Polk & Co.
	Tymowicz Geo Anna lab	R. L. Polk & Co.

3708 23RD AVE

Year	Uses	Source
1991	Barnes Albert H	NYNEX Information Resource Company

3709 23RD AVE

Year	Uses	Source
1976	La Bate Vincent	New York Telephone
1970	Labate Vincent	New York Telephone
1967	Labate Vincent	New York Telephone
1962	LaBate Vincent	New York Telephone Directory
1934	Gilbert Frank Ella stock clk	R. L. Polk & Co.
	Kohsiek Wm Selma	R. L. Polk & Co.
	Loues Spaghetti House Mary A Gesner restr	R. L. Polk & Co.
	Lynch Peter F Mary slsmn	R. L. Polk & Co.

3710 23RD AVE

Year	Uses	Source
1991	Diakovasilis Aristotelis	NYNEX Information Resource Company
1976	De Soucey William	New York Telephone

FINDINGS

Year	Uses	Source
1970	DeSoucey William	New York Telephone
1967	DeSoucey Mary E	New York Telephone
1962	De Soucey Mary E	New York Telephone Directory
1945	De Soucey Mary E	New York Telephone
1934	De Soucey Marie tel oopr	R. L. Polk & Co.
	De Soucey Wm Anna RR mail clk	R. L. Polk & Co.

3711 23RD AVE

Year	Uses	Source
1967	Callahan Donald J	New York Telephone
1939	Patrowicz Frank paintr	New York Telephone Company
1934	Brasen Axel Irene ironwkr	R. L. Polk & Co.
	Brasen Wilfred	R. L. Polk & Co.
	Coppini Peter Carrie walter	R. L. Polk & Co.
	Fegan Harold R Lillian car washer	R. L. Polk & Co.
	Orzechowski Augusta wid Walter	R. L. Polk & Co.

3712 23RD AVE

Year	Uses	Source
1991	Simonetti Kathryn	NYNEX Information Resource Company
	Simonetti L	NYNEX Information Resource Company
1945	Maier Wm	New York Telephone
1939	Maier Eliz	New York Telephone Company
1934	Maier Wm Elizabeth Maier Electric Co	R. L. Polk & Co.
	Maier Wm Elizabeth elec contr	R. L. Polk & Co.
	Maier Wm Anna meat ctr	R. L. Polk & Co.

3714 23RD AVE

Year	Uses	Source
1934	Bartsch Robt Martha br mgr Kesbec Inc	R. L. Polk & Co.
	Nawroth Albert Bertha cigar mkr	R. L. Polk & Co.
	Nawroth Herman clk	R. L. Polk & Co.

FINDINGS

3715 23RD AVE

Year	Uses	Source
1976	Bruno Louis A	New York Telephone
1970	Astoria Auto Svce	New York Telephone
1967	Astoria Auto Svce	New York Telephone
1962	Astoria Auto Svce	New York Telephone Directory
1945	Astoria Auto Svce	New York Telephone
1939	Astoria Auto Svce	New York Telephone Company
1934	Friess Carl tailor	R. L. Polk & Co.
	Roche Wm A Jennette lndry	R. L. Polk & Co.
	Zenith Hand Laundry Wm a Roche	R. L. Polk & Co.

3717 23RD AVE

Year	Uses	Source
1934	Szarnyassy Geo Rose gro	R. L. Polk & Co.

3718 23RD AVE

Year	Uses	Source
1991	Komodromos G	NYNEX Information Resource Company
1934	Bauer Christian Kath piano mkr	R. L. Polk & Co.
	Bauerschmitt Geo porter	R. L. Polk & Co.
	Hanft Carl Martha tmstr	R. L. Polk & Co.
	Heinhold Herbert Bertha baker	R. L. Polk & Co.

3719 23RD AVE

Year	Uses	Source
1962	COC Mfg Corp	New York Telephone Directory
	Camera Optics Mfg Corp	New York Telephone Directory
1945	Virginia Meat Mkt	New York Telephone
1939	LI Water Meter Repr Co Inc	New York Telephone Company

3720 23RD AVE

Year	Uses	Source
1934	Cooke John w alter	R. L. Polk & Co.
	Cooke Thos restr	R. L. Polk & Co.

FINDINGS

3731 23RD AVE

Year	*Uses*	*Source*
1970	Callahan Donald J	New York Telephone

23RD RD

3710 23RD RD

Year	*Uses*	*Source*
1934	De Soucey Jas V asst formn Pres Boro Q	R. L. Polk & Co.

3711 23RD RD

Year	*Uses*	*Source*
1934	Rebele Chas J Josephine checker	R. L. Polk & Co.

3712 23RD RD

Year	*Uses*	*Source*
1934	Maier Electric Co TN: Wm Maler elec contr	R. L. Polk & Co.

3716 23RD RD

Year	*Uses*	*Source*
1934	Stark Jacob pres Steuben Kitchen Inc	R. L. Polk & Co.
	Steuben Kitchen Inc NY Jacob Stark pres Simon Adier sec treas condiment mfrs	R. L. Polk & Co.

3719 23RD RD

Year	*Uses*	*Source*
1934	American Motion Picture Machinery Works Edmund Wisneski Herman Janssen	R. L. Polk & Co.

3721 23RD RD

Year	*Uses*	*Source*
1934	Trondle Geo Wilhelmina stg eng	R. L. Polk & Co.
	Trondle Marie clk	R. L. Polk & Co.

23RD ST

3612 23RD ST

Year	*Uses*	*Source*
2014	G & FAST ELECTRIC INC	Cole Information

FINDINGS

Year	Uses	Source
2010	G & FAST ELECTRIC	Cole Information
2005	G & Fast Electric	Hill-Donnelly Information Services
	G & FAST ELECTRIC INC	Cole Information
2000	G & Fast Elec Corp	Cole Information
	G & FAST ELECTRIC CORPORATION	Cole Information
1995	G & FAST ELECTRIC CORP	Cole Information
1992	G & FAST ELECTRIC CORP	Cole Information
1991	G & Fast Electric Corp	NYNEX Information Resource Company
1970	Balikoff Katherine	New York Telephone

3613 23RD ST

Year	Uses	Source
1945	Traynor & Hanson Corp trukmn & riggers	New York Telephone

3615 23RD ST

Year	Uses	Source
1991	Del Legno Inc	NYNEX Information Resource Company
1983	A & D Treues Inc	New York Telephone
	Rubber & Plastics Compound Co Inc oaes	New York Telephone
1970	Nab Const Corp	New York Telephone
	Recreational Facilities Inc	New York Telephone
	Simpson Iron Wks Inc	New York Telephone
	SIMPSON ROOFING & VENTLATO CO INC	New York Telephone
1967	NAB Const Corp	New York Telephone
	Simpson Iron Wks Inc	New York Telephone
	Simpson Roofing & Ventlatg Co Inc	New York Telephone
1962	N A B Const Corp	New York Telephone Directory
	Simpson Iron Wks Inc	New York Telephone Directory
	Simpson Roofing & Ventlatg Co Inc	New York Telephone Directory

3616 23RD ST

Year	Uses	Source
2017	BANNER EXPRESS & TRUCKING CORP	Cole Information
	DOUBLE R FOODS	Cole Information

FINDINGS

Year	Uses	Source
2014	DOUBLE R FOODS	Cole Information
2010	DOUBLE R FOOD DISTRIBUTORS	Cole Information
2005	Double R Foods s	Hill-Donnelly Information Services
2000	Banner Trucking	Cole Information
	BANNER EXPRESS & TRUCKING CORPORATION	Cole Information
	BANNER EXPRESS & TRUCKING	Cole Information
1995	BANNER EXPRESS & TRUCKING CORP	Cole Information
1992	BANNER EXPRESS & TRUCKING CORP	Cole Information
1991	Banner Express & Trucking Corp	NYNEX Information Resource Company

3620 23RD ST

Year	Uses	Source
2020	DIAMOND AUTO REPAIR	EDR Digital Archive
2017	DIAMOND AUTO REPAIR	Cole Information
2014	DIAMOND AUTO REPAIR	Cole Information
2005	Diamond Auto Repair is	Hill-Donnelly Information Services
	DIAMOND AUTO REPAIR	Cole Information
2000	Diamond Auto Rpr	Cole Information
	DIAMOND AUTO REPAIR	Cole Information
1995	PAPIS, JOHN	Cole Information
1992	PAPIS, JOHN	Cole Information
1991	PAPIS JOHN	NYNEX Information Resource Company

3623 23RD ST

Year	Uses	Source
2017	MELVA CONSTRUCTION CORP	Cole Information
	CENTRAL CRANKSHAFT	Cole Information
2014	MELVA CONSTRUCTION CORPORATION	Cole Information
	ENGINE HOUSE	Cole Information
	CENTRAL CRANKSHAFT	Cole Information
2010	MELVA CONSTRUCTION CORP	Cole Information
	ENGINE HOUSE	Cole Information
	CENTRAL CRANKSHAFT	Cole Information

Year	Uses	Source
2005	Melva Construction Corp	Hill-Donnelly Information Services
	MELVA CONSTRUCTION CORP	Cole Information
2000	Argento	Cole Information
	Centrel Crankshaft	Cole Information
	Engine House	Cole Information
	Melva Const Corp	Cole Information
1995	CENTRAL CRANKSHAFT	Cole Information
1945	Dragone Jack	New York Telephone
1939	Dragone Jack	New York Telephone Company

3624 23RD ST

Year	Uses	Source
2020	RITEWAY TOWING	EDR Digital Archive
2017	RITEWAY TOWING	Cole Information
2014	A & Z AUTO	Cole Information
2010	NEW DELHI AUTO REPAIR CORP	Cole Information
2005	New Delhi Auto Repair Corp	Hill-Donnelly Information Services
	NEW DELI AUTO REPAIR CORP	Cole Information
2000	New Di At Rpr Crp	Cole Information
1995	PAPIS BROKERAGE	Cole Information
1983	Arrow Paper Co Inc	New York Telephone
1976	ARROW PAPER CO INC	New York Telephone
1970	COHEN HENRY B DRUG CO INC	New York Telephone
1967	Cohen Henry B Drug Co Inc	New York Telephone
1962	COHEN HENRY B DRUG CO INC	New York Telephone Directory

3625 23RD ST

Year	Uses	Source
2010	GRAND AUTO SVC	Cole Information

3628 23RD ST

Year	Uses	Source
2017	A2Z MECHANICAL INC	Cole Information
2014	A2Z MECHANICAL INCORPORATED	Cole Information

FINDINGS

Year	Uses	Source
2010	O T & T INE	Cole Information
	LONG ISLAND CITY ENGINE	Cole Information
2005	Central Crankshaft 1s	Hill-Donnelly Information Services
	Long Island City Engine	Hill-Donnelly Information Services
	OT&T s 718937 1181 00oo	Hill-Donnelly Information Services
	LONG ISLAND ENGINE CENTRAL	Cole Information
	O T AND T INC	Cole Information
2000	Central Crankshaft	Cole Information
	Long Isle Cty Eng	Cole Information
	LONG ISLAND CITY ENGINE CENTRAL	Cole Information
1995	CENTRAL CRANKSHAFT	Cole Information
1992	CENTRAL CRANKSHAFT	Cole Information

3629 23RD ST

Year	Uses	Source
2005	JACKSON CO INC WILLIAM H	Cole Information

3632 23RD ST

Year	Uses	Source
2020	K V POWER ELECTRIC INC	EDR Digital Archive
	EXPERT MACHINE SVC INC	EDR Digital Archive
	J R GRECH CONSTR CORP	EDR Digital Archive
	RAYMOND GRECH	EDR Digital Archive
	SILVANO GRECH	EDR Digital Archive
2017	JR GRECH CONSTRUCTION CORP	Cole Information
	NEW KC ELECTRIC INC	Cole Information
2014	NEW KC ELECTRIC INCORPORATED	Cole Information
	JR GRECH CONSTRUCTION CORPORATION	Cole Information
	JR	Cole Information
2010	J R GRECH CONSTRUCTION CORP	Cole Information
	NEW KC ELECTRIC INC	Cole Information
2005	LAGIO SIGNS INC	Cole Information
	JR GRECH CONSTRUCTION CORP	Cole Information
2000	Jr Grech Const Crp	Cole Information

FINDINGS

Year	Uses	Source
2000	JR GRECH CONSTRUCTION CORPORATION	Cole Information
1995	JR GRECH CONSTR CORP	Cole Information
1992	JR GRECH CONSTR CORP	Cole Information
1991	JR GRECH CONSTR CORP	NYNEX Information Resource Company

3633 23RD ST

Year	Uses	Source
2005	High Tech Electrical Svc Corp	Hill-Donnelly Information Services
	HIGH TECH ELECTRICAL SERVICES	Cole Information
2000	High Tech Electrl	Cole Information
	HIGH TECHNOLOGY ELECTRICAL SERVICE CORPORATION	Cole Information
1995	PILOT GAS & HEAT SVCE CORP	Cole Information
1992	PILOT GAS & HEAT SVCE CORP	Cole Information
	PILOT ENERGY CORP	Cole Information
1991	Pilot Energy Corp	NYNEX Information Resource Company
	Pilot Gas & Heat Svce Corp	NYNEX Information Resource Company
1983	Pilot Energy Corp	New York Telephone
	Pilot Gas & Heat Svce Corp	New York Telephone
1976	Elian Frank & Co ash hoists	New York Telephone
	GENL CONVEYOR CO INC	New York Telephone
	Hoisweil Ash Lift Mfrs	New York Telephone
1970	Elian Frank & Co ash hoists	New York Telephone
	Genl Conveyor Co Inc	New York Telephone
	Hoistwell Ash Lift Mfrs	New York Telephone
1967	Elian Frank & Co ash hoists	New York Telephone
	Genl Conveyor Co Inc	New York Telephone
	Hoistwell Ash Lift Mfrs	New York Telephone
1962	Elian Frank & Co ash hoists	New York Telephone Directory
	Genl Conveyor Co Inc	New York Telephone Directory
	Hoistwell Ash Lift Mfrs	New York Telephone Directory
1945	Elian Frank & Co ash hoists	New York Telephone
1939	Elian Frank & Co ash hoists	New York Telephone Company

FINDINGS

3636 23RD ST

Year	Uses	Source
2020	RIGHT CONNECTION PLBG & HTG	EDR Digital Archive
2017	THE RIGHT CONNECTION PLUMBING & HEAT	Cole Information
2014	THE RIGHT CONNECTION PLUMBING & HEAT	Cole Information
	ALPHA GENERAL CONTRACTORS	Cole Information
2010	RIGHT CONNECTION PLBG & HTG	Cole Information
	ALPHA GENERAL CONTR OF NY	Cole Information
2005	Right Connection Plbg & Htg	Hill-Donnelly Information Services
	Perritt P	Hill-Donnelly Information Services
	THE RIGHT CONNECTION PLUMBING	Cole Information
	TOP RENOVATION CORP	Cole Information
2000	The Plbg & Htg Inc	Cole Information
1995	THE RIGHT CONNECTION PLUMBING & HEATING INC	Cole Information
1992	CONNECTION GENERAL CONSTRUCTION CORP	Cole Information
	THE RIGHT CONNECTION PLUMBING & HEATING INC	Cole Information

3651 23RD ST

Year	Uses	Source
1945	Koenig Leo	New York Telephone

3652 23RD ST

Year	Uses	Source
2000	Apartments Robert Barzso	Cole Information
	Zoila Cordero	Cole Information
	Hassan Hashem	Cole Information
	L Francisco Och	Cole Information
	Luke Ryan	Cole Information

3704 23RD ST

Year	Uses	Source
2010	ARIAN SADEGHI	Cole Information

FINDINGS

3706 23RD ST

Year	Uses	Source
2010	B TRAN	Cole Information

3708 23RD ST

Year	Uses	Source
2010	RONALD SIMONS	Cole Information
2000	3712 NP	Cole Information

3709 23RD ST

Year	Uses	Source
2005	CLARE MASTRELLI	Cole Information

3710 23RD ST

Year	Uses	Source
2005	ARISTOTELI DIAKOVASILIS	Cole Information

3711 23RD ST

Year	Uses	Source
2005	ASTORIA PEDIATRIC ASSOCS PC	Cole Information
	JAMES MITCHELL	Cole Information
2000	JAMES MITCHELL	Cole Information
1991	Cohen Sol & Co trucking	NYNEX Information Resource Company
	Neptune Sales Co	NYNEX Information Resource Company
1962	Gans Tooler Co	New York Telephone Directory
1939	Clover Shop Inc womns wear	New York Telephone Company

3712 23RD ST

Year	Uses	Source
2014	JANA ZALAHOVA	Cole Information
2010	JANA ZALAHOVA	Cole Information
2005	SPIROS KATSIFIS	Cole Information
1970	Lokken John	New York Telephone

3714 23RD ST

Year	Uses	Source
2005	PETER BOUREKAS	Cole Information

FINDINGS

3715 23RD ST

Year	Uses	Source
2010	PAUL COVIELLO	Cole Information

3716 23RD ST

Year	Uses	Source
2020	KSW INC	EDR Digital Archive
	ORION TECHINCAL SVC A KSW CO	EDR Digital Archive
	PRECISION SOLAR RENEWABLES LLC	EDR Digital Archive
	KSW MECHANICAL SVC INC	EDR Digital Archive
2017	K S W MECHANICAL SVCS INC	Cole Information
2014	K S W MECHANICAL SVCS INCORPORATED	Cole Information
2010	KSW INC	Cole Information
	KSW MECHANICAL SVC INC	Cole Information
2005	+3 WP Mechanical Svc	Hill-Donnelly Information Services
	KSW Inc o 718 361 6500 os	Hill-Donnelly Information Services
	KSW Mechanical Svc Inc	Hill-Donnelly Information Services
	h Wachtel Duklauer & Fein 718361 6500oo	Hill-Donnelly Information Services
	K S W MECHANICAL SERVICES INC	Cole Information
	KSW INC	Cole Information
2000	P Mechl Serv	Cole Information
	P Mechl Serv	Cole Information
	W Mechl Svcs	Cole Information
	Mechl Svcs Inc	Cole Information
	Wachtel Dklr & Fein	Cole Information
	WACHTEL DUKLAUER & FEIN	Cole Information
	K S W MECHANICAL SERVICES INCORPORATED	Cole Information
	J W P MECHANICAL SERVICES	Cole Information
1995	WACHTEL, DUKLAUER & FEIN	Cole Information
	J W P MECHANICAL SERVICES	Cole Information
	K S W MECHANICAL SVCS INC	Cole Information
1992	KERBY SAUNDERS-WARKOL INC	Cole Information
	KERBY SAUNDERS WARKOL INC	Cole Information

Year	Uses	Source
1991	Kerby Saunders Warkol Inc	NYNEX Information Resource Company
	Kerby Saunders Warkol Inc	NYNEX Information Resource Company
1970	American Polystrat Corp	New York Telephone
1967	B & B Hanger Co Inc	New York Telephone

3719 23RD ST

Year	Uses	Source
2017	PUNJAB MOTORS CORP	Cole Information
2014	MARTY S AUTOBODY & REPAIR SHOP INC	Cole Information
2005	Scalamandreo	Hill-Donnelly Information Services
1983	Roman Truck Tank Repr Svce	New York Telephone
	Roman Truck Tank Repr Svce	New York Telephone
1970	Roman Truck Tank Repr Svce	New York Telephone
	Roman Truck Tank Repr Svce	New York Telephone
1967	Roman Truck Tank Repr Svce	New York Telephone
	Roman Truck Tank Repr Svce	New York Telephone
1962	Roman Truck Tank Repr Svce	New York Telephone Directory
	Roman Truck Tank Repr Svce	New York Telephone Directory
1945	Adensite Co Inc	New York Telephone
1939	Adensite Co Inc	New York Telephone Company

3721 23RD ST

Year	Uses	Source
1934	Trondle Wm Newtown Battery & Ignition Service	R. L. Polk & Co.

3722 23RD ST

Year	Uses	Source
2020	BEVERLY HILLS LIMOUSINE SVC	EDR Digital Archive
	SPECTACULAR LIMOUSINE SVC	EDR Digital Archive
	MEIR AMIR	EDR Digital Archive
2017	HTP INC	Cole Information
	SPECTACULAR LIMOUSINE SERVICES	Cole Information
2014	SPECTACULAR LIMOUSINE SERVICES	Cole Information
	HTP INCORPORATED	Cole Information

Year	Uses	Source
2010	SPECTACULAR LIMOUSINE SVC INC	Cole Information
	SIX STARS OF NEW YORK	Cole Information
	SPECTACULAR LIMOUSINE SVC	Cole Information
	HIGH TECH LIMO MNTNC & REPAIR	Cole Information
2005	PERDIDO PRODUCTIONS	Cole Information

3752 23RD ST

Year	Uses	Source
2010	ANTHONY BERNACET	Cole Information
2005	ANTHONY BERNACET	Cole Information

2ND AVE

3501 2ND AVE

Year	Uses	Source
1991	Abbbas Ashraf	NYNEX Information Resource Company
	Alihodzic Biserka	NYNEX Information Resource Company
	Cunniff John J Sr	NYNEX Information Resource Company
	Dondero M A	NYNEX Information Resource Company
	Gilmore Robt W Mrs	NYNEX Information Resource Company
	Mc Donald F	NYNEX Information Resource Company
	Mc Dougall Bernadette V	NYNEX Information Resource Company
	Solenski B	NYNEX Information Resource Company
1983	Alexander A V	New York Telephone
	Baglivio Stephen	New York Telephone
	Cunniff John J Sr	New York Telephone
	Cunningham B	New York Telephone
	Dondero M A	New York Telephone
	Gilmore Robt W Mrs	New York Telephone
	Lorentz Raymond T	New York Telephone
	Mc Donald F	New York Telephone
	Murphy Agnes M	New York Telephone
	Nieman Theo	New York Telephone
	Solenski B	New York Telephone

FINDINGS

Year	Uses	Source
1983	Spada J T	New York Telephone
	Sundquist S	New York Telephone
1976	Alexander A V	New York Telephone
	Cunniff John J Sr	New York Telephone
	Cunningham B	New York Telephone
	Dondero M A	New York Telephone
	Gilmore Robt W Mrs	New York Telephone
	Given E	New York Telephone
	Hopper V R	New York Telephone
	Leu Fred	New York Telephone
	Lo Cicero John Mrs	New York Telephone

3502 2ND AVE

Year	Uses	Source
1991	Dimilta Provisions Dist Corp	NYNEX Information Resource Company
	Dimina D	NYNEX Information Resource Company
1983	Boylan Thomas J	New York Telephone
	Dimilta Provisions Dist Corp	New York Telephone
1976	Boylan Margaret M Mrs	New York Telephone
	Hodermarsky Jos	New York Telephone

3504 2ND AVE

Year	Uses	Source
1991	Giannakidis K	NYNEX Information Resource Company

3507 2ND AVE

Year	Uses	Source
1991	Sala A	NYNEX Information Resource Company
1983	Furnari Giacomo	New York Telephone
	Sala A	New York Telephone

3508 2ND AVE

Year	Uses	Source
1991	Deudon Robt	NYNEX Information Resource Company
1983	Deudon Robt	New York Telephone

Year	Uses	Source
1976	Deudon Robt	New York Telephone
	Kincle Irene	New York Telephone

3509 2ND AVE

Year	Uses	Source
1991	Papa Rocco	NYNEX Information Resource Company
	Trentacosti Michl	NYNEX Information Resource Company
1983	Papa Rocco	New York Telephone
	Trentacosti Michl	New York Telephone
	Trentacosti S	New York Telephone

3511 2ND AVE

Year	Uses	Source
1991	Kalfa E U	NYNEX Information Resource Company
	Orphanides Gao	NYNEX Information Resource Company
1983	Kalfa E U	New York Telephone
	Orphanides Geo	New York Telephone
	Orphanides James	New York Telephone

3512 2ND AVE

Year	Uses	Source
1991	La Regina J	NYNEX Information Resource Company
1983	La Regina M	New York Telephone
1976	La Regina M	New York Telephone

3513 2ND AVE

Year	Uses	Source
1991	Miccoli Anthony	NYNEX Information Resource Company
	Pisella Bart	NYNEX Information Resource Company
	Pisella Joseph	NYNEX Information Resource Company
1983	Pisella Joseph	New York Telephone

3514 2ND AVE

Year	Uses	Source
1983	Wemple B J	New York Telephone

FINDINGS

3517 2ND AVE

Year	Uses	Source
1983	Psares George	New York Telephone

3518 2ND AVE

Year	Uses	Source
1991	Kaplan Gilbert	NYNEX Information Resource Company
	Sajjasophon Prasan	NYNEX Information Resource Company
1983	Kaplan Gilbert	New York Telephone

3519 2ND AVE

Year	Uses	Source
1991	Leone S	NYNEX Information Resource Company
1983	Leone S	New York Telephone

3520 2ND AVE

Year	Uses	Source
1991	Davey P J	NYNEX Information Resource Company
	Hart Ilona	NYNEX Information Resource Company
	Hart W N C	NYNEX Information Resource Company
1983	Davey P J	New York Telephone
1976	Davey P J	New York Telephone

3601 2ND AVE

Year	Uses	Source
1991	Belletti Lorenzo	NYNEX Information Resource Company
	Ghillani Mario	NYNEX Information Resource Company
1983	Belletti Lorenzo	New York Telephone
	Ghillani Mario	New York Telephone
1976	Belletti Loretizo	New York Telephone
	Ghillani Mario	New York Telephone

3602 2ND AVE

Year	Uses	Source
1991	Syperreck George	NYNEX Information Resource Company
1983	Kreatsoulas J	New York Telephone

FINDINGS

3604 2ND AVE

Year	Uses	Source
1991	La Motta L	NYNEX Information Resource Company
1983	La Motta John	New York Telephone
1976	La Motta John	New York Telephone

3607 2ND AVE

Year	Uses	Source
1991	Martinez Sahyly	NYNEX Information Resource Company

3609 2ND AVE

Year	Uses	Source
1991	Barry John	NYNEX Information Resource Company
	Doyle Andrew	NYNEX Information Resource Company
1983	Barry John	New York Telephone
	Lombardo Tom	New York Telephone
1976	Lombardo Tom	New York Telephone

3610 2ND AVE

Year	Uses	Source
1991	Tenaglia Salvatore	NYNEX Information Resource Company
1983	Tenaglia Salvatore	New York Telephone

3611 2ND AVE

Year	Uses	Source
1991	Delgado B	NYNEX Information Resource Company
1983	Tripoli Ignazio	New York Telephone
1976	La Micela Salvatrice	New York Telephone

3613 2ND AVE

Year	Uses	Source
1991	Koncz Ruth Mrs	NYNEX Information Resource Company
1983	Carluccio Vito	New York Telephone
	Koncz Ruth Mrs	New York Telephone

FINDINGS

3614 2ND AVE

Year	Uses	Source
1991	Tsouros Demetrios	NYNEX Information Resource Company
1983	Tsouros Demetrios	New York Telephone
1976	Cassano Ronald V	New York Telephone

3617 2ND AVE

Year	Uses	Source
1991	Tuthill Laura	NYNEX Information Resource Company
1983	Tuthill Laura	New York Telephone
1976	Gavriel Moshe	New York Telephone
1934	Dinino Edw sec treas Majestic Marble Crafts Inc	R. L. Polk & Co.

3618 2ND AVE

Year	Uses	Source
1991	Atlas Susan	NYNEX Information Resource Company
	Pollack V	NYNEX Information Resource Company
1983	Atlas Susan	New York Telephone
	Pollack V	New York Telephone
1976	Atlas Jas	New York Telephone

3619 2ND AVE

Year	Uses	Source
1991	Daru Jacqueline	NYNEX Information Resource Company
	Krikorian Gary	NYNEX Information Resource Company
1983	Krikorian Gary	New York Telephone
1976	Alexander Chas A	New York Telephone

3620 2ND AVE

Year	Uses	Source
1991	Amaya Giselle	NYNEX Information Resource Company
	Saccoccia Magret	NYNEX Information Resource Company
1983	Metzler S	New York Telephone
	Mosher Michael D	New York Telephone
	Shone George	New York Telephone

Year	Uses	Source
1983	Tria M	New York Telephone
1976	Allen Paul M	New York Telephone
	Hampl Mildred	New York Telephone
	Kral Emil	New York Telephone

3708 2ND AVE

Year	Uses	Source
1991	Urgo Nick	NYNEX Information Resource Company
1976	Caronia Albert	New York Telephone
	Caronia M	New York Telephone

3804 2ND AVE

Year	Uses	Source
1976	Kelly F M	New York Telephone

2ND ST

3527 2ND ST

Year	Uses	Source
1970	Panuccio Nicholas	New York Telephone

3712 2ND ST

Year	Uses	Source
1934	Vyhnlek Louis baker	R. L. Polk & Co.

36TH AV ABBREV L IC

1401 36TH AV ABBREV L IC

Year	Uses	Source
1991	Beloritsky Izrail	NYNEX Information Resource Company

36TH AV ABBREV LI C

1401 36TH AV ABBREV LI C

Year	Uses	Source
1983	Leslie Enid G	New York Telephone

FINDINGS

36TH AVE

1401 36TH AVE

Year	*Uses*	*Source*
2020	PRICE CONSTRUCTION INC	EDR Digital Archive
	I HAVE A DREAM PROGRAM	EDR Digital Archive
	JULISSA FERNANDEZ	EDR Digital Archive
	CATHERINE REID	EDR Digital Archive
	SLIM BENAMOR	EDR Digital Archive
	KRZYSZTOF GILAROWSKI	EDR Digital Archive
	JOSE MEDINA	EDR Digital Archive
	PERVIS NESMITH	EDR Digital Archive
	LUKASZ KROLAK	EDR Digital Archive
	JENNIFER GERVACIO	EDR Digital Archive
	WESLEY BRYANT	EDR Digital Archive
	KATRINA MCBRIDE	EDR Digital Archive
	SALINA PRICE	EDR Digital Archive
	JAHAIRA SANCHEZ	EDR Digital Archive
	MATILDA BECKLES	EDR Digital Archive
	MIGDALIA JIMENEZ	EDR Digital Archive
	CARLOS NARVAEZ	EDR Digital Archive
	THERESA HALLMAN	EDR Digital Archive
	TANIA TAVAREZ	EDR Digital Archive
	DOROTHY CAESAR	EDR Digital Archive
	CATHERINE SOLOMON	EDR Digital Archive
	KENDALL REID	EDR Digital Archive
	GAIL DOUGBEY	EDR Digital Archive
	CALVIN BOLEN	EDR Digital Archive
	TERESA KROLAK	EDR Digital Archive
	TYRONE HAYNES	EDR Digital Archive
	STUART MINGO	EDR Digital Archive
	SARAH HAYNES	EDR Digital Archive
	HAZEL DOUGBEY	EDR Digital Archive
	GLORIA LADD	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	ROXANNE VALDEZ	EDR Digital Archive
	ROBERT CHAVIS	EDR Digital Archive
	BARBARA ZAMBRANA	EDR Digital Archive
	PASCALL DOUGBEY	EDR Digital Archive
	CARMEN ROSARIO	EDR Digital Archive
	PAOLA RIVERA	EDR Digital Archive
	KRYSTAL MCNEILL	EDR Digital Archive
	DAVON OWENS	EDR Digital Archive
	MONSERRATE FIGUEROA	EDR Digital Archive
	SYED RAHMAN	EDR Digital Archive
	KATRINA DAVIS	EDR Digital Archive
	KASHA CEASER	EDR Digital Archive
	MAJENDA REID	EDR Digital Archive
	SHAUNDRE SHERROD	EDR Digital Archive
	SHELTON SOLOMON	EDR Digital Archive
	KARLICK PRICE	EDR Digital Archive
	AURORA CASTILLO	EDR Digital Archive
	TAMIKO ROBINSON	EDR Digital Archive
	RAHKIAH LEE	EDR Digital Archive
	NARGIS RAHMAN	EDR Digital Archive
	ALVARO JARAMILLO	EDR Digital Archive
	DANIEL HARRIGAN	EDR Digital Archive
	RAMOS COLEMAN	EDR Digital Archive
	KASHA CAESAR	EDR Digital Archive
	MARGITE MEDINA	EDR Digital Archive
	JACQUELINE REID	EDR Digital Archive
	ELVIS SANTANA	EDR Digital Archive
	MELISSA VEGA	EDR Digital Archive
	BETTY GOMEZ	EDR Digital Archive
	BENJAMIN CHAVIS	EDR Digital Archive
	AURORA NAZARIO	EDR Digital Archive
	DIVI PAEZ	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	DAVID RADEMAKER	EDR Digital Archive
	VITALIA FERNANDEZ	EDR Digital Archive
	MAKEDA PRICE	EDR Digital Archive
	JESSICA WALLROLON	EDR Digital Archive
	JOYCE CHAVIS	EDR Digital Archive
	MARY BRYANT	EDR Digital Archive
	SANDRA PERRY	EDR Digital Archive
	KEVIN BECKLES	EDR Digital Archive
2017	BEN AMOR SLIM GLORIA LADD	Cole Information
	MANNY CORDERO	Cole Information
	JENNIFER GERVACIO	Cole Information
	KRZYSZTOF GILAROWSKI	Cole Information
	NICOLAS JIMENEZ	Cole Information
	SALINA PRICE	Cole Information
	BETSY RODRIGUEZ	Cole Information
	TERRY SMITH	Cole Information
	ISAIAS CASTILLO	Cole Information
	STAR HARLEY	Cole Information
	BARRY NEWBY	Cole Information
	AYOKU BARRINGER	Cole Information
	CALVIN BOLEN	Cole Information
	T HALL	Cole Information
	EUGENE KROLAK	Cole Information
	KENDALL REID	Cole Information
	ROBERT CHAVIS	Cole Information
	MONSERRATE FIGUEROA	Cole Information
	BARBARA ZAMBRANA	Cole Information
	MARY BATISTA	Cole Information
	EDWIN LOPEZ	Cole Information
	BRIANNA MELENDEZ	Cole Information
	SHAUNDRE SHERROD	Cole Information
	S BENAMOR	Cole Information

FINDINGS

Year	Uses	Source
2017	RAHKIAH LEE	Cole Information
	PATRICK PINKARD	Cole Information
	WILLY VALDEZ	Cole Information
	RAMOS COLEMAN	Cole Information
	ALVARO JARAMILLO	Cole Information
	ANTHONY MCNEILL	Cole Information
	MARGITE MEDINA	Cole Information
	NELSON NAZARIO	Cole Information
	REYNALDO RIZAS	Cole Information
	MATTHEW DOUGBEY	Cole Information
	JOSEPH MCFADDEN	Cole Information
	JUANA MUNOZ	Cole Information
	JOEY NEGRON	Cole Information
	DIVI PAEZ	Cole Information
	DAVID RADEMAKER	Cole Information
2014	MAURICE EADDY	Cole Information
	JENNIFER GERVACIO	Cole Information
	KATRINA MCBRIDE	Cole Information
	NEDRA BRYANT	Cole Information
	ISAIAS CASTILLO	Cole Information
	ERIC DONDOH	Cole Information
	MIGDALIA JIMENEZ	Cole Information
	CALVIN BOLEN	Cole Information
	ANTONIA FIOL	Cole Information
	EUGENE KROLAK	Cole Information
	GLORIA LADD	Cole Information
	STUART MINGO	Cole Information
	AZIZUN NESSA	Cole Information
	AMOR BEN	Cole Information
	ROBERT CHAVIS	Cole Information
	MONSERRATE FIGUEROA	Cole Information
	CARMEN ROSARIO	Cole Information

FINDINGS

Year	Uses	Source
2014	SHARITA BRASWELL	Cole Information
	BRENDA HAYNES	Cole Information
	DIANA MERCED	Cole Information
	MAJENDA REID	Cole Information
	JANNIE SOLOMON	Cole Information
	WILLY VALDEZ	Cole Information
	DINA MENJIVAR	Cole Information
	PATRICK PINKARD	Cole Information
	TAMIKO ROBINSON	Cole Information
	BETTY TAYLOR	Cole Information
	YAHAIRA BORDGOS	Cole Information
	RAMOS COLEMAN	Cole Information
	BETTY GOMEZ	Cole Information
	ALVARO JARAMILLO	Cole Information
	ANTHONY MCNEILL	Cole Information
	MARGITE MEDINA	Cole Information
	NELSON NAZARIO	Cole Information
	BRENDA NEWSOME	Cole Information
	XAVIER SAEZ	Cole Information
	ELVIS SANTANA	Cole Information
	MATTHEW DOUGBEY	Cole Information
2010	PRICE CONSTRUCTION INC	Cole Information
	KRZYSZTOF GILAROWSKI	Cole Information
	LUZ RODRIGUEZ	Cole Information
	JENNIE COLEMAN	Cole Information
	MATILDA BECKLES	Cole Information
	ROXANA VALDEZ	Cole Information
	RUPERT SANCHARA	Cole Information
	HAZEL DOUGBEY	Cole Information
	SARAH HAYNES	Cole Information
	ANTONIA FIOL	Cole Information
	CALVIN BOLEN	Cole Information

FINDINGS

Year	Uses	Source
2010	KENDALL REID	Cole Information
	MAURICE MILLIAM	Cole Information
	BARBARA MARXUACH	Cole Information
	LILLIANA MUNOZ	Cole Information
	GLORIA LADD	Cole Information
	TRINA DAVIS	Cole Information
	CARMEN ROSARIO	Cole Information
	MONSERRATE FIGUEROA	Cole Information
	BRIAN PETERSON	Cole Information
	SHARITA BRASWELL	Cole Information
	DIANA MERCED	Cole Information
	DENISE MCNEILL	Cole Information
	SHAUNDRE SHERROD	Cole Information
	LASHEEN HARRIS	Cole Information
	MELODY IRIZARRY	Cole Information
	BETTY TAYLOR	Cole Information
	PATRICK PINKARD	Cole Information
	OLGA PAGAN	Cole Information
	TAMIKO ROBINSON	Cole Information
	DINA MENJIVAR	Cole Information
	BRENDA NEWSOME	Cole Information
	DANIEL CACERES	Cole Information
	BENJAMIN CHAVIS	Cole Information
	ALVARO JARAMILLO	Cole Information
	LESLIE SALAS	Cole Information
	DIVI PAEZ	Cole Information
	ANTHONY PALACIO	Cole Information
	MARY BRYANT	Cole Information
2005	Multi Unit Address	Hill-Donnelly Information Services
	Communications Deliveries	Hill-Donnelly Information Services
	Encamacion C	Hill-Donnelly Information Services
	Harris B	Hill-Donnelly Information Services

FINDINGS

Year	*Uses*	*Source*
2005	Numbr 3 A I Have A Dream Program	Hill-Donnelly Information Services
	Kayla Management Inc 1 P	Hill-Donnelly Information Services
	Numbr 2 G h Mingo Mildred & Henry A	Hill-Donnelly Information Services
	Perry Maurice	Hill-Donnelly Information Services
	Reid Stephanie	Hill-Donnelly Information Services
	Robinson Jamel v	Hill-Donnelly Information Services
	Numbr 6 E h Sanchez M p	Hill-Donnelly Information Services
	Numbr 4 E h Simms L A	Hill-Donnelly Information Services
	Mult Unit Address	Hill-Donnelly Information Services
	Numbr 6 C h Be Wkles M A	Hill-Donnelly Information Services
	Numbr 4 C Bolen Calvin A	Hill-Donnelly Information Services
	Numbr 6 F h Bryant Mary V	Hill-Donnelly Information Services
	Numbr 3 F h Figueroa Monserrate	Hill-Donnelly Information Services
	Numbr 3 A Flol A A	Hill-Donnelly Information Services
	Numbr 6D h Haynes Sarah Ao	Hill-Donnelly Information Services
	Jimenez Migdalia v	Hill-Donnelly Information Services
	Numbr 4 F h Krolak Teresa	Hill-Donnelly Information Services
	Numbr 5 Ah Macon Patricia A	Hill-Donnelly Information Services
	Numbr 3 H h Mcneill D	Hill-Donnelly Information Services
	Numbr 3 C Navedo Joseph P vo	Hill-Donnelly Information Services
	Numbr 3 G Paez Divi	Hill-Donnelly Information Services
	Numbr 6 A Pagan Olga A	Hill-Donnelly Information Services
	Pages Elvin Ricarda Av	Hill-Donnelly Information Services
	Numbr 2 F Pinkard Patrick A	Hill-Donnelly Information Services
	Numbr 5 E 8h Re Id 3 A718	Hill-Donnelly Information Services
	Numbr 2D h Rodriguez L N Ao	Hill-Donnelly Information Services
	Sanchara Rupert Av	Hill-Donnelly Information Services
	Numbr 4 A h Solomon A 0 718 786 6856 8 S	Hill-Donnelly Information Services
	Taylor Horace Ao	Hill-Donnelly Information Services
	I HAVE A DREAM PROGRAM	Cole Information
	SOFIA DESTEFANO	Cole Information
	MARIA SANCHEZ	Cole Information

FINDINGS

Year	*Uses*	*Source*
2005	ROBERT DAVIS	Cole Information
	MATILDA BECKLES	Cole Information
	C ENCARNACION	Cole Information
	SONIA RODRIGUEZ	Cole Information
	ISAIAS CASTILLO	Cole Information
	LOUIS LAMBERTY	Cole Information
	MIGDALIA JIMENEZ	Cole Information
	CARLTON SMITH	Cole Information
	SARAH HAYNES	Cole Information
	HAZEL DOUGBEY	Cole Information
	ANTONIA FIOL	Cole Information
	SUE PURSLEY	Cole Information
	CALVIN BOLEN	Cole Information
	JOE ALLEN	Cole Information
	STUART MINGO	Cole Information
	MONSERRATE FIGUEROA	Cole Information
	MEGAN MELENDEZ	Cole Information
	ALEX HAMILTON	Cole Information
	YAHAERA BURGOS	Cole Information
	DENISE MCNEILL	Cole Information
	MELODY IRIZARRY	Cole Information
	OLGA PAGAN	Cole Information
	ELVIN PAGES	Cole Information
	PATRICK PINKARD	Cole Information
	J REID	Cole Information
	TAMIKO ROBINSON	Cole Information
	SHELTON SOLOMON	Cole Information
	RAFIQUE KROLAK	Cole Information
	BENJAMIN CHAVIS	Cole Information
	ALVARO JARAMILLO	Cole Information
	NATHAN HALL	Cole Information
	SHAMONDA GRAHAM	Cole Information

FINDINGS

Year	Uses	Source
2005	DIVI PAEZ	Cole Information
	MARY BRYANT	Cole Information
	JUANA MUNOZ	Cole Information
	SOOHEE CHUNG	Cole Information
2000	M Backles	Cole Information
	Riva Beloritsky	Cole Information
	Ronald Braye	Cole Information
	Mary Bryant	Cole Information
	Nefratia Coleman	Cole Information
	4D Sofia Destefano	Cole Information
	A Fiol	Cole Information
	I HAVE A DREAM PROGRAM	Cole Information
	MERCED DIANA	Cole Information
	SOFIA DESTEFANO	Cole Information
	P MACON	Cole Information
	LARRY HAYNES	Cole Information
	S TATUM	Cole Information
	LUZ RODRIGUEZ	Cole Information
	DENISE MCNEIL	Cole Information
	RONALD BRAYE	Cole Information
	LOUIS LAMBERTY	Cole Information
	JAHAIRA SANCHEZ	Cole Information
	CARLTON SMITH	Cole Information
	GAIL DOUGBEY	Cole Information
	TERESA KROLAK	Cole Information
	HARRY HAIRSTON	Cole Information
	PETER GILAROWSKI	Cole Information
	ANTONIA FIOL	Cole Information
	CALVIN BOLEN	Cole Information
	HENRY MINGO	Cole Information
	M BECKLES	Cole Information
	RIVA BELORITSKY	Cole Information

FINDINGS

Year	Uses	Source
2000	SUI LAU	Cole Information
	DIANA MERCED	Cole Information
	OLGA PAGAN	Cole Information
	TIMEKA PIDGEN	Cole Information
	PATRICK PINKARD	Cole Information
	SHIRLEY WILLIAMS	Cole Information
	MARY BRYANT	Cole Information
1996	FIOL A	NYNEX
	FLANNERY Louise	NYNEX
1995	I HAVE A DREAM PROGRAM	Cole Information
1992	MULVEY, JOS R	Cole Information
	CRUMP, JOHN	Cole Information
	TAKESKY, ANNA	Cole Information
	LAU, SUI-HEI	Cole Information
	QUIDONE, SALVATORE	Cole Information
	SOKOLOVA, SIMA	Cole Information
	SOLOMON, CATHERINE	Cole Information
	JAFFE, EDWARD	Cole Information
	IRBY, BEN	Cole Information
	RODRIGUEZ, L N	Cole Information
	CASTRO, MARIE	Cole Information
	BERRY, TILLMAN	Cole Information
	DESTEFANO, SOFIA C	Cole Information
	BELORITSKY, IZRAIL	Cole Information
	BONAPARTE, ROBERT	Cole Information
	DUNLAP, SARAH	Cole Information
	MATTHEWS, CLARENCE	Cole Information
	BELLINGER, SPIGINER	Cole Information
	LAMBERTY, LOUIS	Cole Information
	MINGO, HENRY & MILDRED	Cole Information
	PINKARD, PATRICK	Cole Information
	SOJOS, PATRICIA	Cole Information

FINDINGS

Year	Uses	Source
1992	FIOL, A	Cole Information
	SANCHEZ, FRANK	Cole Information
	LEE, BIU	Cole Information
1991	Rodriguez L N	NYNEX Information Resource Company
	Sojos Kelly	NYNEX Information Resource Company
	Solomon Catherine	NYNEX Information Resource Company
	Bellinger Spiginer	NYNEX Information Resource Company
	Bonaparte Robert	NYNEX Information Resource Company
	Bryant Mary	NYNEX Information Resource Company
	Crump John	NYNEX Information Resource Company
	De Stefano Sofia C	NYNEX Information Resource Company
	Dunlap Sarah	NYNEX Information Resource Company
	Fiol A	NYNEX Information Resource Company
	Jaffe Edward	NYNEX Information Resource Company
	Lamberty Louis	NYNEX Information Resource Company
	Lau Sui Hei	NYNEX Information Resource Company
	Matthews Clarence	NYNEX Information Resource Company
	Mingo Henry & Mildred	NYNEX Information Resource Company
	Mulvey Jos R	NYNEX Information Resource Company
	Pinkard Patrick	NYNEX Information Resource Company
	Quidone Salvatore	NYNEX Information Resource Company
	Quiello M	NYNEX Information Resource Company
	Takesky Anna	NYNEX Information Resource Company
	Williams Jas A	NYNEX Information Resource Company
	Lee Biu	NYNEX Information Resource Company
1983	Amengual John	New York Telephone
	Bellinger Spiginer	New York Telephone
	Beloritsky Izrail	New York Telephone
	Berry Tillman	New York Telephone
	Bonaparte Robert	New York Telephone
	Boutros Antoine	New York Telephone
	Coletti Frank	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	Crump John	New York Telephone
	Crump L Q	New York Telephone
	Dema Mary	New York Telephone
	Doshinsky Jos	New York Telephone
	Fiol A	New York Telephone
	Garcia Angel	New York Telephone
	Gilgoff Mollie	New York Telephone
	Goldberg E H	New York Telephone
	Matthew s Clarence	New York Telephone
	Mingo Henry	New York Telephone
	Morra Richd	New York Telephone
	Mulvey Jos R	New York Telephone
	Pinkard Patrick	New York Telephone
	Quidone Salvatore	New York Telephone
	Slominsky Abraham	New York Telephone
	Sojos Kelly	New York Telephone
	Takesky Anna	New York Telephone
	Vazquez J	New York Telephone
	Williams Jas A	New York Telephone
	Danna Silvia	New York Telephone
	Klein Herbert	New York Telephone
	Lee Biu	New York Telephone
	Sanchez Frank	New York Telephone
1976	Acerno Jos A	New York Telephone
	Banks Dorothy M Mrs	New York Telephone
	Bellinger Spiglner	New York Telephone
	Berry Tillman	New York Telephone
	Boutros Antoine	New York Telephone
	Carlson Sverre	New York Telephone
	Coletti Frank	New York Telephone
	Dema Carmine W	New York Telephone
	Gilgoff Mollie	New York Telephone

FINDINGS

Year	Uses	Source
1976	Goldberg E H	New York Telephone
	Hengler Leo G	New York Telephone
	Keenan John J	New York Telephone
	Bonaparte Dolores	New York Telephone
	Danna Jos	New York Telephone
	Klein Herbert	New York Telephone
	Lerner Yetta	New York Telephone
1970	Acerno Jos A	New York Telephone
	Allen A C	New York Telephone
	Bellinger Spiginer	New York Telephone
	Berry Tillman	New York Telephone
	Bionda Louis	New York Telephone
	Birn Max	New York Telephone
	Borden Mary Mrs Sr	New York Telephone
	Carlson Sverre	New York Telephone
	Chiarella Donato	New York Telephone
	Crump John H	New York Telephone
	Cvirko Wm V	New York Telephone
	Dema Carmine W	New York Telephone
	Freeman Ruth	New York Telephone
	Freeman Warren	New York Telephone
	Goldberg E H	New York Telephone
	Hengler Leo G	New York Telephone
	Keenan John J	New York Telephone
	Lampert Julius	New York Telephone
	Manganiello Ralph	New York Telephone
	Matthews Clarence	New York Telephone
	Mingo Henry	New York Telephone
	Morra Richd	New York Telephone
	Rodfield Harry	New York Telephone
	Rosen Clifton S	New York Telephone
	Schultzman Celia	New York Telephone

FINDINGS

Year	Uses	Source
1970	Slominsky Abraham	New York Telephone
	Smith Herman J	New York Telephone
	Stiefel Douglas M	New York Telephone
	Takesky Anna	New York Telephone
	Williams Jas A	New York Telephone
	Cuccia Nicholas J	New York Telephone
	Danna Jos	New York Telephone
	Klein Herbert	New York Telephone
	Kriegh Monty	New York Telephone
	Lasner Hyman	New York Telephone
	Mauro Michael A	New York Telephone
	Savitsky Carl	New York Telephone
1967	Acerno Jos A	New York Telephone
	Bassette Geo W	New York Telephone
	Bellinger Spiginer	New York Telephone
	Berry Tillman	New York Telephone
	Bionda Louis	New York Telephone
	Birn Max	New York Telephone
	Borden Mary Mrs Sr	New York Telephone
	Carlson Sverre	New York Telephone
	Crump John H	New York Telephone
	Cvirko Wm V	New York Telephone
	Dema Carmine W	New York Telephone
	Freeman Ruth	New York Telephone
	Freeman Warren	New York Telephone
	Hengler Leo G	New York Telephone
	Keenan John J	New York Telephone
	Lampert Julius	New York Telephone
	Manganiello Ralph	New York Telephone
	Mingo Henry	New York Telephone
	Morra Richd	New York Telephone
	Rodfield Harry	New York Telephone

FINDINGS

Year	Uses	Source
1967	Rosen Clifton S	New York Telephone
	Slominsky Abraham	New York Telephone
	Smith Herman J	New York Telephone
	Stiefel Douglas P	New York Telephone
	Switzen Nathan	New York Telephone
	Takesky Anna	New York Telephone
	Wittemann Walter	New York Telephone
	Cuccia Nicholas J	New York Telephone
	Danna Jos	New York Telephone
	Klein Herbert	New York Telephone
	Kriegh Monty	New York Telephone
	Lasner Hyman	New York Telephone
	Medina Wilfred	New York Telephone
	Savitsky Carl	New York Telephone
1962	King Christine L	New York Telephone Directory
	Allegro Chas	New York Telephone Directory
	Bassette Geo W	New York Telephone Directory
	Becton Jas	New York Telephone Directory
	Bellinger Spiginer	New York Telephone Directory
	Benedikt Ben	New York Telephone Directory
	Berry Tillman	New York Telephone Directory
	Bionda Louis	New York Telephone Directory
	Birn Max	New York Telephone Directory
	Boorshtein Morris	New York Telephone Directory
	Borden Mary Mrs Sr	New York Telephone Directory
	Burke Annette Mrs	New York Telephone Directory
	Carlson Sverre	New York Telephone Directory
	Carpenter Josephine Mrs	New York Telephone Directory
	Cohen Morris	New York Telephone Directory
	Coppa Frank J	New York Telephone Directory
	Corpening Walter L	New York Telephone Directory
	Cvirko Wm V	New York Telephone Directory

FINDINGS

Year	Uses	Source
1962	Epstein Martin O	New York Telephone Directory
	Ferrer Max	New York Telephone Directory
	Fiorello Eugene	New York Telephone Directory
	Freeman Ruth	New York Telephone Directory
	Freeman Warren	New York Telephone Directory
	Halper Benj	New York Telephone Directory
	Hengler Leo G	New York Telephone Directory
	Keyes Bernard S	New York Telephone Directory
	Lampert Julius	New York Telephone Directory
	Mulvey Jos R	New York Telephone Directory
	Pugh N	New York Telephone Directory
	Rosen Clifton S	New York Telephone Directory
	Rotunno Anthony	New York Telephone Directory
	Rubenstein Oscar	New York Telephone Directory
	Stiefel Douglas M	New York Telephone Directory
	Strongin Harry	New York Telephone Directory
	Switzen Nathan	New York Telephone Directory
	Takesky Anna	New York Telephone Directory
	Di Cicco Michl F	New York Telephone Directory
	Lasner Hyman	New York Telephone Directory
	Lenahan Jerome J	New York Telephone Directory
	Zide Larry	New York Telephone Directory

1403 36TH AVE

Year	Uses	Source
1991	Berry Tillman	NYNEX Information Resource Company

1411 36TH AVE

Year	Uses	Source
2000	ANNA TAKESKY	Cole Information

1412 36TH AVE

Year	Uses	Source
1934	Balboy Service TN Edw J Balbian Caspar Boyajian gas sta	R. L. Polk & Co.

FINDINGS

1423 36TH AVE

Year	Uses	Source
1934	Mecca Jos Mary lab	R. L. Polk & Co.

1435 36TH AVE

Year	Uses	Source
1934	Donatlli Candida fcty w kr	R. L. Polk & Co.

2001 36TH AVE

Year	Uses	Source
2000	OLYMPIA MOUKAS	Cole Information

2005 36TH AVE

Year	Uses	Source
1939	Catanzaro Alfred	New York Telephone Company

2009 36TH AVE

Year	Uses	Source
2005	CONCHA SANCHEZ	Cole Information

2011 36TH AVE

Year	Uses	Source
2005	JOSEPH LYNAM	Cole Information

2012 36TH AVE

Year	Uses	Source
2005	LENOX STONEHILL	Cole Information

2015 36TH AVE

Year	Uses	Source
1962	Hurd Walter J	New York Telephone Directory

2025 36TH AVE

Year	Uses	Source
2005	BERNARD LIEBHABER	Cole Information

2026 36TH AVE

Year	Uses	Source
2010	PATRICIA CREMIN	Cole Information

FINDINGS

Year	Uses	Source
2005	Cremin Pat	Hill-Donnelly Information Services
	PATRICIA CREMIN	Cole Information

2027 36TH AVE

Year	Uses	Source
2005	ANTONIOS POLITIS	Cole Information

2054 36TH AVE

Year	Uses	Source
2000	Christos Sourlis	Cole Information

2059 36TH AVE

Year	Uses	Source
2005	MICHAEL WILDES	Cole Information
2000	Padraig Beahn	Cole Information

2065 36TH AVE

Year	Uses	Source
2000	Michael Matsumoto	Cole Information

2066 36TH AVE

Year	Uses	Source
2000	Alfred Hertrich	Cole Information

2068 36TH AVE

Year	Uses	Source
2005	JOHN PRY	Cole Information
2000	Kris Gilly	Cole Information
	Evan Harrington	Cole Information
	21ST ST INTS FROM	Cole Information

2101 36TH AVE

Year	Uses	Source
1991	Garrido June	NYNEX Information Resource Company

FINDINGS

2102 36TH AVE

Year	Uses	Source
2020	K & F FOOD CORP	EDR Digital Archive
	PALACE CHICKEN & GRILL	EDR Digital Archive
2017	PALACE CHICKEN & GRILL	Cole Information
	DOWN THE ROAD LOCKSMITH	Cole Information
	PALACE FRIED CHICKEN	Cole Information
2014	RP PALACE 11106 COMPANY	Cole Information
2010	SEABREEZE DELI	Cole Information
2005	Palace Fried Chicken I R	Hill-Donnelly Information Services
	PALACE FRIED CHICKEN	Cole Information
2000	Palace Fried Chick	Cole Information
	PALACE FRIED CHICKEN	Cole Information
1992	KATHY'S FRIED CHICKEN	Cole Information
1991	KATHYS FRIED CHICKEN	NYNEX Information Resource Company
1983	KATHYS FRIED CHICKEN	New York Telephone
1976	Kansas Fried Chicken	New York Telephone
1970	Tri Boro Lunchnet	New York Telephone
	Triborn Lunchnet	New York Telephone
1967	Tri Boro Lunchnet	New York Telephone
	Triboro Lunchnet	New York Telephone
1962	Triboro Lunchnet	New York Telephone Directory
	Triboro Lunchnet	New York Telephone Directory

2104 36TH AVE

Year	Uses	Source
2020	CIFER SENSE	EDR Digital Archive
	QUEENS FINEST BARBER	EDR Digital Archive
	BRUCE PAYNE	EDR Digital Archive
2017	A TOWING BUSINESS	Cole Information
	I & S SHOE REPAIR	Cole Information
	SAMS BARBER SHOP	Cole Information
2014	A TOWING BUSINESS	Cole Information
	I & S SHOE REPAIR	Cole Information

FINDINGS

Year	Uses	Source
2014	SAMS BARBER SHOP	Cole Information
2010	VINNYS PIZZERIA II	Cole Information
	I & S SHOE REPAIR	Cole Information
	SAMS BARBER SHOP	Cole Information
2005	A 1 Locksmith Svc 1s	Hill-Donnelly Information Services
	Asap Locksmiths 24 HRS	Hill-Donnelly Information Services
	Sams Barber Shop I s	Hill-Donnelly Information Services
	SAMS BARBER SHOP	Cole Information
2000	I & S Shoe Repair	Cole Information
	Viays Pizzer	Cole Information
	I & S SHOE REPAIR	Cole Information
1995	VINNY'S PIZZERIA II	Cole Information
1992	VINNY'S PIZZERIA II	Cole Information
1991	Vinnys Pizzeria II	NYNEX Information Resource Company
1983	GNC Check Cashing Inc	New York Telephone

2105 36TH AVE

Year	Uses	Source
1939	Baldw in Beverages Inc	New York Telephone Company
	Sw ance Club Beverages Inc	New York Telephone Company
1934	Baldw in Beverages Inc Y Andrew Mars pres Geo Mars sec Michl Marina treas	R. L. Polk & Co.
	Maffia Fred bottler Baldw in Beverages Inc	R. L. Polk & Co.
	Sw anee Club Beverages RTN Baldw in Beverages Inc	R. L. Polk & Co.

2106 36TH AVE

Year	Uses	Source
2020	DELI INC J & M COFFEE	EDR Digital Archive
2017	DELI INC J & M COFFEE	Cole Information
	ALCANTARA CERRAJERO BARATO	Cole Information
2010	B S COFFEE SHOP	Cole Information
2005	B S Coffee Shop IR	Hill-Donnelly Information Services
	B S COFFEE SHOP	Cole Information
2000	Kims Donut Shp Inc	Cole Information

Year	Uses	Source
2000	KIMS DONUT SHOP INCORPORATED	Cole Information
1995	KIM'S DONUT SHOP INC	Cole Information
1992	KIM'S DONUT SHOP INC	Cole Information
1991	Kims Donut Shop Inc	NYNEX Information Resource Company
1983	Joe Grasse Cards	New York Telephone
1976	Jo Anns Pizzerla & Delcatesn	New York Telephone
1970	Jo Anns Pizzeria & Delcatesn	New York Telephone
1967	Jo Anns Pizzeria & Delcatesn	New York Telephone
1962	Jo Ann Pizzeria & Delcatesn	New York Telephone Directory

2108 36TH AVE

Year	Uses	Source
2017	ZHENG LI TONG	Cole Information
2014	ZHENG LI TONG	Cole Information
2010	ZHEN LI TONG RESTAURANT	Cole Information
2005	Sam Lee Kitchen f	Hill-Donnelly Information Services
	SAM LEE KITCHEN	Cole Information
	SHANLEE	Cole Information
2000	Shun Lee Kitchen	Cole Information
	SHANLEE	Cole Information
1995	SHANLEE	Cole Information
1992	SHANLEE	Cole Information
1991	Shanlee	NYNEX Information Resource Company
1983	Wow Liquors Inc	New York Telephone
1976	Brow ns Liquor Inc	New York Telephone
1970	Flynns Liquors liqrs	New York Telephone
1967	Flynns Liquors ligrs	New York Telephone
1962	Flynn Liquors liqrs	New York Telephone Directory

2110 36TH AVE

Year	Uses	Source
2005	Vinnys Pizzeria II	Hill-Donnelly Information Services

FINDINGS

2111 36TH AVE

Year	Uses	Source
2005	LUISE PEDROSO	Cole Information

2112 36TH AVE

Year	Uses	Source
2020	METROCARE PHARMACY	EDR Digital Archive
	EXQUISITO RESTAURANT	EDR Digital Archive
	PHARMACY METROCARE	EDR Digital Archive
2017	PHARMACY METROCARE	Cole Information
	FRIENDLY PIZZA RESTAURANT	Cole Information
2014	PHARMACY METROCARE	Cole Information
	CLEARCHOICE	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2010	PHARMACY METROCARE	Cole Information
	METROCARE PHARMACY	Cole Information
	CLEAR CHOICE	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2005	Clear Choice	Hill-Donnelly Information Services
	Get More Wireless	Hill-Donnelly Information Services
	GET MORE WIRELESS	Cole Information
	CLEAR CHOICE	Cole Information
	FRESCO TRADING INC	Cole Information
2000	Clear Choice	Cole Information
	CLEAR CHOICE	Cole Information
1995	JOEMO SALES INC	Cole Information
1992	ALUMINUM FACADES	Cole Information
1991	Dynamic Crafting Corp	NYNEX Information Resource Company
1983	Industrial Packaging & Maintenance Co	New York Telephone
	SIGMA FOODS INC	New York Telephone
1976	Key Food Stores	New York Telephone
1970	Key Food Stores	New York Telephone
1967	Key Food Stores	New York Telephone
1962	Key Food Stores	New York Telephone Directory

Year	Uses	Source
1962	Regal Meat Mkt	New York Telephone Directory

2113 36TH AVE

Year	Uses	Source
1962	Frankel Jacob	New York Telephone Directory

2116 36TH AVE

Year	Uses	Source
2020	36 AVENUE WINE & LIQUOR CORP	EDR Digital Archive
	NB NET SOLUTIONS INC	EDR Digital Archive
	NICK SAKELOS	EDR Digital Archive
2017	NB NET SOLUTIONS INC	Cole Information
2014	CHRIS TV	Cole Information
2010	CHRIS TV	Cole Information
2005	Chris TV Svc ls	Hill-Donnelly Information Services
	Sakelos Nick	Hill-Donnelly Information Services
	CHRIS TV SERVICE	Cole Information
2000	Chrris TV Svce	Cole Information
	CHRIS TV SVCE	Cole Information
1995	CHRIS TV SVCE	Cole Information
1992	CHRIS TV SVCE	Cole Information
1991	Chris TV Svce	NYNEX Information Resource Company
1983	Chris TV Svce	New York Telephone
1976	Chris TV Svce	New York Telephone

2118 36TH AVE

Year	Uses	Source
2010	LUU TUYEN MICHELLE	Cole Information
2005	Luutuyen Michelle s	Hill-Donnelly Information Services
	Luu Tuyen Michelle v	Hill-Donnelly Information Services
	ASTORIA SUPER CLEAN LAUNDROMAT INC	Cole Information
	LUU TUYEN MICHELLE	Cole Information
2000	John Alkay	Cole Information
1992	G & S LAUNDROMAT	Cole Information

Year	Uses	Source
1991	G & S Laundromat	NYNEX Information Resource Company
1970	Two Way Laundromat Co	New York Telephone
1967	Two Way Laundromat Co	New York Telephone
1962	Two Way Laundromat Co	New York Telephone Directory

2120 36TH AVE

Year	Uses	Source
2020	LUCKY CLEANERS	EDR Digital Archive
2014	YOON YOUNG	Cole Information
2010	LUCKY CLEANERS	Cole Information
2005	Lucky Cleaners 1s 718 482 8842 as	Hill-Donnelly Information Services
	Yoon Young v	Hill-Donnelly Information Services
	LUCKY CLEANERS	Cole Information
2000	Lucky Cleaners	Cole Information
	LUCKY CLEANERS	Cole Information
1995	LUCKY CLEANERS	Cole Information
1992	LUCKY CLEANERS	Cole Information
1991	Lucky Cleaners	NYNEX Information Resource Company
1983	Litts Variety Store Inc	New York Telephone
1970	Litts Variety Store Inc	New York Telephone
1967	Litts Variety Store Inc	New York Telephone
1962	Litts Variety Store Inc	New York Telephone Directory

2122 36TH AVE

Year	Uses	Source
2020	CHIEN CHIEN DELI GROCERY CORD	EDR Digital Archive
2017	A J FRIENDLY GROCERY CORP	Cole Information
2014	HABIIE DELI GROCERY CORPORATION	Cole Information
2010	A J FRIENDLY GROCERY CORP	Cole Information
2005	Friendly Grocery Store	Hill-Donnelly Information Services
	FRIENDLY GROCERY STORE	Cole Information
2000	Joseph Conti	Cole Information
	Friendly Groc Str	Cole Information
	FRIENDLY GROCERY STORE	Cole Information

Year	Uses	Source
1995	FRIENDLY GROCERY STORE	Cole Information
1992	FRIENDLY GROCERY STORE	Cole Information
1991	M & C Variety	NYNEX Information Resource Company

2124 36TH AVE

Year	Uses	Source
1983	Maysanna Beauty Salon	New York Telephone

2126 36TH AVE

Year	Uses	Source
2020	AMERICAN CUSTOM	EDR Digital Archive
2010	AMERICAN CUSTOM	Cole Information
2005	American Custom R	Hill-Donnelly Information Services
2000	American Custom	Cole Information
	AMERICAN CUSTOM	Cole Information
1995	AMERICAN CUSTOM	Cole Information
1992	AMERICAN CUSTOM	Cole Information
1983	GARTNER FLOOR COVERING CO linolm	New York Telephone
1976	GARTNER FLOOR COVERING CO linolm	New York Telephone
1970	SARTNER FLOOR COVERING CO linoim	New York Telephone
1967	GARTNER FLOOR COVERING CO linoim	New York Telephone
1962	GARTNER FLOOR COVERING CO linolm	New York Telephone Directory

2129 36TH AVE

Year	Uses	Source
2000	M Flayter	Cole Information
	Dan Smith	Cole Information

2130 36TH AVE

Year	Uses	Source
1962	Anastasio Jos Jr	New York Telephone Directory

2133 36TH AVE

Year	Uses	Source
1970	Mishler Julius L	New York Telephone
1967	Mishler Julius L	New York Telephone

Year	Uses	Source
1962	Mishier Julius L	New York Telephone Directory

2136 36TH AVE

Year	Uses	Source
2014	LANE WHITLOW	Cole Information
2010	LANE WHITLOW	Cole Information
2000	Matthew Roth	Cole Information

2137 36TH AVE

Year	Uses	Source
2000	Dan T Bobes	Cole Information

2140 36TH AVE

Year	Uses	Source
2000	Joseph F ONeill	Cole Information

2142 36TH AVE

Year	Uses	Source
2005	G STOJANOVIC	Cole Information
2000	Astoria MBL Lock	Cole Information

2148 36TH AVE

Year	Uses	Source
2005	LAURA BRAY	Cole Information

2157 36TH AVE

Year	Uses	Source
2000	Robson Cerqueir	Cole Information

2159 36TH AVE

Year	Uses	Source
1945	Klimpl A	New York Telephone

2160 36TH AVE

Year	Uses	Source
2005	JUNICHI OTA	Cole Information

FINDINGS

2162 36TH AVE

Year	Uses	Source
1962	Pinces Michl	New York Telephone Directory

2169 36TH AVE

Year	Uses	Source
2005	DOMINICK MEZZATESTA	Cole Information

2170 36TH AVE

Year	Uses	Source
2000	Eliza Samacki	Cole Information

2171 36TH AVE

Year	Uses	Source
2005	HYAN IM	Cole Information
1970	Cesario John	New York Telephone
1962	Cesario John	New York Telephone Directory

2175 36TH AVE

Year	Uses	Source
2005	Maros Fashion Co	Hill-Donnelly Information Services
2000	MAROS FASHION COMPANY	Cole Information

2176 36TH AVE

Year	Uses	Source
2000	GIANNAKOPOULOS & GIANNAKOPOULOS	Cole Information

2177 36TH AVE

Year	Uses	Source
2000	Laurinda Tavoni	Cole Information

2195 36TH AVE

Year	Uses	Source
1934	Marina Michl treas Baldw in Beverage Inc	R. L. Polk & Co.

2201 36TH AVE

Year	Uses	Source
1996	FRYE Kathleen	NYNEX

FINDINGS

Year	*Uses*	*Source*
1991	Camilleri Peter	NYNEX Information Resource Company
	Chan Wai Fong	NYNEX Information Resource Company
	Dimaiuta Susan P	NYNEX Information Resource Company
	Dorsey Grace Mrs	NYNEX Information Resource Company
	Frye Kathleen	NYNEX Information Resource Company
	Garcia Gumercinda	NYNEX Information Resource Company
	Hauptman David M	NYNEX Information Resource Company
	Hauptman Mollie Mrs	NYNEX Information Resource Company
	Hines E K	NYNEX Information Resource Company
	Maiorella Frank	NYNEX Information Resource Company
	Maiorella Frank	NYNEX Information Resource Company
	Martell D	NYNEX Information Resource Company
	Mednikov A G	NYNEX Information Resource Company
	Ornstein A	NYNEX Information Resource Company
	Polevoy Savely	NYNEX Information Resource Company
	Ravner Murray	NYNEX Information Resource Company
	Roberts L L	NYNEX Information Resource Company
	Rocos Helen	NYNEX Information Resource Company
	Sauber E	NYNEX Information Resource Company
	Shoikhet I	NYNEX Information Resource Company
	Torres A	NYNEX Information Resource Company
	Totle Wm	NYNEX Information Resource Company
	Touanen Barbara	NYNEX Information Resource Company
1983	Camilleri Peter	New York Telephone
	Dimaiuta Susan P	New York Telephone
	Dorsey Grace Mrs	New York Telephone
	Dryer Maurice	New York Telephone
	Garcia Gumercinda	New York Telephone
	Hauptman David M	New York Telephone
	Hauptman Mollie Mrs	New York Telephone
	Maiorella Frank	New York Telephone
	Maiorella Frank	New York Telephone

FINDINGS

Year	*Uses*	*Source*
1983	Mednikov A G	New York Telephone
	Munoz Jaime	New York Telephone
	Ornstein A	New York Telephone
	Polevoy Savely	New York Telephone
	Rokosz M	New York Telephone
	Sauber Charles F	New York Telephone
	Serebnitsky Galina	New York Telephone
	Shoikhet I	New York Telephone
	Suszko Harry E	New York Telephone
	Totle Wm	New York Telephone
1976	Becker Louis P	New York Telephone
	Berenback Chas	New York Telephone
	Camilleri Peter	New York Telephone
	Carpenter Josephine	New York Telephone
	Casamassina Martin	New York Telephone
	Dimaiuta Susan P	New York Telephone
	Dorsey Grace Mrs	New York Telephone
	Dryer Maurice	New York Telephone
	Ficke Jos R	New York Telephone
	Geis Michl	New York Telephone
	Hauptman David M	New York Telephone
	Hauptman Mollie Mrs	New York Telephone
	Lopez Antonio	New York Telephone
	Maiorella Frank	New York Telephone
	Maiorella Frank	New York Telephone
1970	Becker Louis P	New York Telephone
	Berenback Chas	New York Telephone
	Carpenter Josephine	New York Telephone
	Casamassina Martin	New York Telephone
	Chorow ski Paul	New York Telephone
	Cillo C A	New York Telephone
	Comparetto Jos B	New York Telephone

FINDINGS

Year	Uses	Source
1970	Dorsey Grace Mrs	New York Telephone
	Dryer Maurice	New York Telephone
	Essig Martin	New York Telephone
	Ferber Rebecca	New York Telephone
	Ficke Jos R	New York Telephone
	Finkelstein May	New York Telephone
	Finkelstein Meyer L	New York Telephone
	Geis Michl	New York Telephone
	Haimow itz Oscar	New York Telephone
	Jumanow itz Morris	New York Telephone
	Jumanow itz Morris	New York Telephone
	Mangan Robt F	New York Telephone
	Margolin Jack	New York Telephone
	Moskw a N	New York Telephone
	Mulvey Joseph Jr	New York Telephone
	Odw ak Harry	New York Telephone
	Penn I	New York Telephone
	Rokosz Teddy	New York Telephone
	Scopp Saml M	New York Telephone
	Vallejo Francisco A	New York Telephone
	Wexler Sam	New York Telephone
1967	Becker Louis P	New York Telephone
	Berenback Chas	New York Telephone
	Carpenter Josephine	New York Telephone
	Casamassina Martin	New York Telephone
	Chorow ski Paul	New York Telephone
	Cilio C A	New York Telephone
	Comparetto Jos B	New York Telephone
	Costello Mary Mrs	New York Telephone
	Dorsey Grace Mrs	New York Telephone
	Dryer Maurice	New York Telephone
	Essig Martin	New York Telephone

FINDINGS

Year	Uses	Source
1967	Ferber Rebecca	New York Telephone
	Ficke Jos R	New York Telephone
	Geis Michl	New York Telephone
	Gioeli Thos	New York Telephone
	Haimow ita Oscar	New York Telephone
	Jumanow itz Morris	New York Telephone
	Mangan Robt F	New York Telephone
	Margolin Jack	New York Telephone
	Moskw a N	New York Telephone
	Odw ak Harry	New York Telephone
	Penn I	New York Telephone
	Scopp Saml N	New York Telephone
	Straker Claudine Mrs	New York Telephone
	Wexler Sam	New York Telephone
1962	Askinazi Edw	New York Telephone Directory
	Becker Louis P	New York Telephone Directory
	Been J A	New York Telephone Directory
	Bellanti Jos	New York Telephone Directory
	Bennett H	New York Telephone Directory
	Carr Albert	New York Telephone Directory
	Casamassina Martin	New York Telephone Directory
	Chorow ski Paul	New York Telephone Directory
	Comparetto Jos B	New York Telephone Directory
	Costello Mary Mrs	New York Telephone Directory
	Cox Gerald	New York Telephone Directory
	Dorsey Grace Mrs	New York Telephone Directory
	Essig Martin	New York Telephone Directory
	Ferber Rebecca	New York Telephone Directory
	Ficke Jos R	New York Telephone Directory
	Friedson Richd M	New York Telephone Directory
	Geis Michl	New York Telephone Directory
	Gioeli Thos	New York Telephone Directory

Year	Uses	Source
1962	Haimowitz Oscar	New York Telephone Directory
	Healy Jas E	New York Telephone Directory
	Jumanowitz Morris	New York Telephone Directory
	Lifschitz Esthpr	New York Telephone Directory
	Mangan Robt F	New York Telephone Directory
	Odwak Harry	New York Telephone Directory
	Penn I	New York Telephone Directory
	Poggi Emil	New York Telephone Directory
	Schoor Oscar	New York Telephone Directory
	Schwartz Anne P	New York Telephone Directory
	Scopp Saml M	New York Telephone Directory
	Sorkin Al	New York Telephone Directory
	Suszko Harry E	New York Telephone Directory
	Vando Ulises	New York Telephone Directory
	Wexler Sam	New York Telephone Directory
	Zilbert Leah Mrs	New York Telephone Directory

2212 36TH AVE

Year	Uses	Source
1962	Johns Mkt Italian Amer grocrs	New York Telephone Directory

2220 36TH AVE

Year	Uses	Source
1991	Key Food Stores	NYNEX Information Resource Company
1983	Key Food Stores	New York Telephone

36TH ST

1412 36TH ST

Year	Uses	Source
1991	Troy Gloria	NYNEX Information Resource Company

1500 36TH ST

Year	Uses	Source
1939	Forman Harry lumbr	New York Telephone Company

FINDINGS

1759 36TH ST

Year	Uses	Source
1967	Res	New York Telephone

37TH AV LIC

1301 37TH AV LIC

Year	Uses	Source
1967	Two Way Enterprises	New York Telephone

37TH AVE

1201 37TH AVE

Year	Uses	Source
2020	REED DRIVE CONSTRUCTION CORP	EDR Digital Archive
2017	REED DRIVE CONSTRUCTION CORP	Cole Information
2014	REED DRIVE CONSTRUCTION CORPORATION	Cole Information
1945	Donady Eliz Mrs	New York Telephone
1939	Donady F M Miss	New York Telephone Company
1934	Donadl Wm formn Pres BQ	R. L. Polk & Co.
	Donady Dorothy clk	R. L. Polk & Co.

1202 37TH AVE

Year	Uses	Source
2020	HOTEL NIRVANA	EDR Digital Archive
	CP & SONS LLC	EDR Digital Archive

1204 37TH AVE

Year	Uses	Source
2005	Aurax Corp	Hill-Donnelly Information Services
2000	Audax Const Corp	Cole Information
	Nu Del Constr Co	Cole Information
	NU DEL CONSTRUCTION COMPANY	Cole Information
	AUDAX CONSTRUCTION CORPORATION	Cole Information
	RPO	Cole Information
1995	NU-DEL CONSTR CO	Cole Information

FINDINGS

Year	Uses	Source
1995	AUDAX CONSTRUCTION CORP	Cole Information
	RPO	Cole Information
1992	NU-DEL CONSTR CO	Cole Information
	AUDAX CONSTRUCTION CORP	Cole Information
	RPO	Cole Information
	NU-DEL CORP	Cole Information
1991	Nu Del Corp	NYNEX Information Resource Company
	Nu Del Constr Co	NYNEX Information Resource Company
	RPO	NYNEX Information Resource Company
1983	Bryan Robert L	New York Telephone
1970	Rivera Carmen Mrs	New York Telephone
1967	Rivera Carmen Mrs	New York Telephone
1962	Boccuzzi Michl P	New York Telephone Directory
1934	Beacucito Michl Sophie meter reader	R. L. Polk & Co.
	Dornicik Aug marble plshr	R. L. Polk & Co.
	Dornicik Frank marble plshr	R. L. Polk & Co.
	Dornicik Jos Josephine	R. L. Polk & Co.
	Dornicik Steph lamp shade mkr	R. L. Polk & Co.

1206 37TH AVE

Year	Uses	Source
2000	Big N Eqp Rnt Crp	Cole Information
	BIG N EQUIP RENTAL CORPORATION	Cole Information
1995	BIG N EQUIP RENTAL CORP	Cole Information
1992	BIG N EQUIP RENTAL CORP	Cole Information
1983	Audax Constr Co Inc	New York Telephone
	Big N Equip Rental Corp	New York Telephone

1207 37TH AVE

Year	Uses	Source
2020	RICHARD FASANELLA	EDR Digital Archive
	EVELYN FASANELLA	EDR Digital Archive
2017	RICHARD FASANELLA	Cole Information
2014	LAURA ZELENAK	Cole Information

FINDINGS

Year	Uses	Source
2014	RICHARD FASANELLA	Cole Information
2010	EVELYN FASANELLA	Cole Information
2005	h Fasanella Evelyn A 0 718 609 1244 o	Hill-Donnelly Information Services
	ANTHONY FASANELLA	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information
1992	AHMED, AHMED	Cole Information
	HO, HELEN	Cole Information
1991	Frak David A	NYNEX Information Resource Company
	Lei Wai Nong	NYNEX Information Resource Company
	Squires Donald A	NYNEX Information Resource Company
	Vasile Florentina Michelle	NYNEX Information Resource Company
1983	Gangi Theresa	New York Telephone
	Chan Thomas	New York Telephone
1976	Gallagher Michl	New York Telephone
	Digilio Nicholas J	New York Telephone
	Gallagher J	New York Telephone
1970	Gallagher Michl	New York Telephone
	Digilio Nicholas J	New York Telephone
1967	Bruno Jas	New York Telephone
	Digilio Nicholas J	New York Telephone
	Recupero Theo	New York Telephone
1962	Barhold Catherine L	New York Telephone Directory
	Fasanella Giacomo	New York Telephone Directory
	Recupero Theo	New York Telephone Directory
	Seripiero Giusepne	New York Telephone Directory
1945	Stoppa Jos	New York Telephone
1939	Stoppa Jos	New York Telephone Company
1934	Fasanella Michl Katie fish pdlr	R. L. Polk & Co.
	Settane Dominick Lucy lab	R. L. Polk & Co.
	Stoppa J & Co TN Jos Stoppa gro	R. L. Polk & Co.
	Stoppa Jos Antoinette J Stoppa & Co	R. L. Polk & Co.
	Vecchiarella Nicholas Concetta carp	R. L. Polk & Co.

FINDINGS

1208 37TH AVE

Year	Uses	Source
2010	RPO	Cole Information
	REED DRIVE CONSTRUCTION CORP	Cole Information
	CYNTHIA TOMBROS	Cole Information
2005	Audax Construction Corp	Hill-Donnelly Information Services
2000	Audax Constr Corp	Cole Information
	RPO	Cole Information
	RPO	Cole Information
	AUDAX CONSTRUCTION CORPORATION	Cole Information
1995	RPO	Cole Information
	AUDAX CONSTR CORP	Cole Information
1992	RPO	Cole Information
	AUDAX CONSTR CORP	Cole Information
1991	Audax Constr Corp	NYNEX Information Resource Company
	Therma plex Corp	NYNEX Information Resource Company
1983	Plasticon Chemcls Inc	New York Telephone
	Therma Plex Corp	New York Telephone
1970	Flama Record Corp	New York Telephone
1967	Flama Record Corp	New York Telephone
1934	Cervone Saml Josephine lab	R. L. Polk & Co.

1209 37TH AVE

Year	Uses	Source
2020	MICHAL ZELENAK	EDR Digital Archive
	ELISABETH ZELENAK	EDR Digital Archive
	ELVIRA ZELENAK	EDR Digital Archive
	RACHEL ZELENAK	EDR Digital Archive
2017	MICHAL ZELENAK	Cole Information
2014	MICHAL ZELENAK	Cole Information
2010	MICHAL ZELENAK	Cole Information
2005	h Zelenak Michal A	Hill-Donnelly Information Services
	MICHAL ZELENAL	Cole Information
2000	Michal Zelenal	Cole Information

FINDINGS

Year	Uses	Source
2000	MICHAL ZELENAL	Cole Information
1995	SARRAS, DEMETRIOS	Cole Information
1992	SARRAS, DEMETRIOS	Cole Information
1991	Sarras Demetrios	NYNEX Information Resource Company
1976	JC Sheet Metal & Roofing Corp	New York Telephone
1970	Canaialosi Jas sheet mtl & rfg	New York Telephone
	JC Sheet Metal & Roofing Co	New York Telephone
	Zaino George P	New York Telephone
1962	Barbieri Steve Jr	New York Telephone Directory
1945	Camera Jos bar grill	New York Telephone
1934	Micuci Nicholas Lena clothes prsr	R. L. Polk & Co.

1211 37TH AVE

Year	Uses	Source
2020	J C SHEET METAL & ROOFING CORP	EDR Digital Archive
	JAMES CANGIALOSI	EDR Digital Archive
	NICOLE ALONGE	EDR Digital Archive
2017	J C SHEET METAL & ROOFING CORP	Cole Information
	JORGE CAICEDO	Cole Information
2014	J C SHEET METAL & ROOFING CORP	Cole Information
	KATRINA SHIRER	Cole Information
	JAMES CANGIALOSI	Cole Information
2010	J C SHEET METAL & ROOFING CORP	Cole Information
	DARYLL ROBINSON	Cole Information
	JAMARL GILMOIE	Cole Information
2005	H Cangialosi James	Hill-Donnelly Information Services
	I C Sheet Metal & Roofing Corp	Hill-Donnelly Information Services
	Robinson Daryll	Hill-Donnelly Information Services
	J C SHEET METAL & ROOFING CORP	Cole Information
	DARYLL ROBINSON	Cole Information
	REBECCA MURRAY	Cole Information
	JAMES CANGIALOSI	Cole Information
2000	James Cangialosi	Cole Information

FINDINGS

Year	Uses	Source
2000	Kevin Lyons	Cole Information
	JC Metal & Roof Crp	Cole Information
	JC SHEET METAL & ROOFING CORPORATION	Cole Information
	KEVIN LYONS	Cole Information
	JAMES CANGIALOSI	Cole Information
1995	JC SHEET METAL & ROOFING CORP	Cole Information
1992	JC SHEET METAL & ROOFING CORP	Cole Information
	CANGIALOSI, JAMES	Cole Information
1991	J C Sheet Metal & Roofing Corp	NYNEX Information Resource Company
1983	JC Sheet Metal & Roofing Corp	New York Telephone
1970	Camera Jos	New York Telephone
1967	Camera Jos	New York Telephone
1962	BLAIKIE MILLER & HiNES INC	New York Telephone Directory
	Camera Jos	New York Telephone Directory
1939	Cervone N staty	New York Telephone Company
1934	Cervone Anna candymkr	R. L. Polk & Co.
	Cervone Lucy candymkr	R. L. Polk & Co.
	Cervone Nicholas Cath confr	R. L. Polk & Co.
	Cervone Raefella w id Jos	R. L. Polk & Co.
	Cervone Rita candymkr	R. L. Polk & Co.

1212 37TH AVE

Year	Uses	Source
2020	VELLA INTERIORS INC	EDR Digital Archive
	HOLLY NICOLOIS	EDR Digital Archive
	MICHAEL VELLA	EDR Digital Archive
2017	VELLA INTERIORS INC	Cole Information
2014	VELLA INTERIORS INCORPORATED	Cole Information
2010	VELLA INTERIORS INC	Cole Information
2005	Vella Interiors Inc	Hill-Donnelly Information Services
	VELLA INTERIORS INC	Cole Information
2000	Velia Intrrs Inc	Cole Information
	VELLA INTERIORS INCORPORATED	Cole Information

FINDINGS

Year	Uses	Source
1995	TRI-STAR OFFSET CORP	Cole Information
	EASTERN PRINTING	Cole Information
	LA CARTA PUBLICATIONS INC	Cole Information
1992	TRI-STAR OFFSET CORP	Cole Information
	EASTERN PRINTING	Cole Information
	LA CARTA PUBLICATIONS INC	Cole Information
1991	La Carta Publications Inc	NYNEX Information Resource Company
	MGN Paper Sales	NYNEX Information Resource Company
	M G N Paper Svce	NYNEX Information Resource Company
	Tri Star Offset Corp	NYNEX Information Resource Company
1983	Futbol Publications Inc	New York Telephone
	TRI STAR OFFSET CORP	New York Telephone
1976	ABC De las americas	New York Telephone
1970	Sleepable Sofas Inc	New York Telephone
	SLEEPWELL SHOPS LTD	New York Telephone
1967	Dudley Sports Co	New York Telephone
1962	CONTINENTL MOTORS AUTHRIZD DISTRIBTRS	New York Telephone Directory
	McCulloch Corp	New York Telephone Directory
	Reiner John & Co Inc gas & dresl engs	New York Telephone Directory
	Wisconsin Engines & Parts	New York Telephone Directory
	Wisconsin Motor Distribtrs	New York Telephone Directory
1945	Reiner John & Co gas & diesel engs	New York Telephone
	Wisconsin Motor Sales Co of NY	New York Telephone
1939	Chrome Furn Inc	New York Telephone Company

1215 37TH AVE

Year	Uses	Source
2020	MAJOR PLUMBING LLC	EDR Digital Archive
	CGERAKARIS HEATING	EDR Digital Archive
2017	WILLIAM CGERAKARIS HEATING	Cole Information
2014	WILLIAM CGERAKARIS HEATING	Cole Information
2010	GENESIS PLUMBING & HEATING	Cole Information
	TESTERMAN MECHANICAL INC	Cole Information

FINDINGS

Year	Uses	Source
2010	WILLIAM GERAKARIS PLBG & HTG	Cole Information
2005	Testerman Mechanical Inc	Hill-Donnelly Information Services
	William Gerakaris Plbg & Htg	Hill-Donnelly Information Services
	WILLIAM C GERAKARIS PLUMBING CORP	Cole Information
	TESTERMAN MECHANICAL INC	Cole Information
2000	A & A Plbg & Htg Crp	Cole Information
	Grkrs Plbg & Htg	Cole Information
	BAY RESTORATION CORPORATION	Cole Information
1995	NITA'S KITCHEN INC	Cole Information
1992	NITA'S KITCHEN INC	Cole Information
1991	Nitas Kitchen Inc	NYNEX Information Resource Company
1976	Dickwisch R W Inc cabnt mkrs	New York Telephone
	Efkarpides Kyriacos	New York Telephone
1970	Dickwisch R W Inc cabnt mkrs	New York Telephone
	Doran Wm F	New York Telephone
1967	Doran Wm F	New York Telephone
	Helix Spring Corp	New York Telephone
1962	Air Lite Window Shield Corp	New York Telephone Directory
	Doran Wm F	New York Telephone Directory
1939	Duffy Arnold Grease Co	New York Telephone Company
	Duffy Jas F greases	New York Telephone Company
1934	Anderson John Mary pntr	R. L. Polk & Co.

1217 37TH AVE

Year	Uses	Source
2014	CHRYSOULA KRITKIMOS	Cole Information
2010	CHRYSOULA KRITHIMOS	Cole Information
2005	h Krithimos Chrysoula	Hill-Donnelly Information Services
	CHRYSOULA KRITHIMOS	Cole Information
2000	C Krithimos	Cole Information
	ZOES DINETTE INCORPORATED	Cole Information
	C KRITHIMOS	Cole Information
1992	GEORGATOS, CHRISTOS	Cole Information

Year	Uses	Source
1992	KRITHIMOS, CHRYSOULA	Cole Information
1991	Georgatos C	NYNEX Information Resource Company
	Krithimos Chrysoula	NYNEX Information Resource Company
1983	Moms Kitchen	New York Telephone
1976	Lunch Hse	New York Telephone
1970	Lunch Hse	New York Telephone
1967	Lunch Hse restrnt	New York Telephone
1962	Lunch Hse restrnt	New York Telephone Directory
	Montes Julie	New York Telephone Directory

1218 37TH AVE

Year	Uses	Source
2020	MICHAEL VELLA	EDR Digital Archive
	KEENAN KENNEDY	EDR Digital Archive
2014	KEENAN KENNEDY	Cole Information
	JOHN BELEVANAKIF	Cole Information
2010	LUIS RODRIGUEZ	Cole Information
	PETER MINAR	Cole Information
	JOHN BELEVANAKIF	Cole Information
2005	No Current Listing	Hill-Donnelly Information Services
	PETER MINAR	Cole Information
	JOSE CASTILLO	Cole Information
1992	CADENA, LUCILA	Cole Information
1991	Cadena Myriam	NYNEX Information Resource Company
1983	Munoz Ignacio	New York Telephone
1976	Bransfield Beatrice	New York Telephone
1970	Bransfield Beatrice	New York Telephone
	Pinas Jose V	New York Telephone
1967	Bransfield Beatrice	New York Telephone
1962	Bransfield Beatrice	New York Telephone Directory
	Maloney Emily A	New York Telephone Directory
1945	Maloney Wm	New York Telephone
1939	Maloney Wm	New York Telephone Company

FINDINGS

Year	Uses	Source
1934	Bransfield Edw J Margt elev opr	R. L. Polk & Co.
	Bransfield Michl J Beatrice truck driver	R. L. Polk & Co.

1219 37TH AVE

Year	Uses	Source
2020	CRESCENT ST CONSTRUCTION CORP	EDR Digital Archive
2017	CRESCENT ST CONSTRUCTION CORP	Cole Information
2014	CRESCENT STREET CONSTRUCTION CORPORA	Cole Information
2010	CRESCENT ST CONSTRUCTION CORP	Cole Information
2005	Crescent Street Construction	Hill-Donnelly Information Services
2000	Crscut St Const	Cole Information
	CRESCENT ST CONSTRUCTION CORPORATION	Cole Information
1995	S T STEVENS MACH CORP-FAX NUMBER	Cole Information
	S T STEVENS MACH CORP	Cole Information
1992	ST STEVENS MACH CORP	Cole Information
	ST STEVENS MACH CORP FAX LINE	Cole Information
1991	ST Stevens Mach Corp	NYNEX Information Resource Company
	St Stevens Mach Corp Fax Line	NYNEX Information Resource Company
1983	ST Stevens Mach Corp	New York Telephone
1970	ST Stevens Mach Corp	New York Telephone
1967	ST Stevens Mach Corp	New York Telephone

1220 37TH AVE

Year	Uses	Source
2020	BCNY RESTORATION CORP	EDR Digital Archive
	BAYSIDE CONTRACTING	EDR Digital Archive
	SIRAK CONSTRUCTION	EDR Digital Archive
2017	BAYSIDE CONTRACTING	Cole Information
	RODEL RODEL ELECTRICAL CONTRACTORS	Cole Information
	TYCOON CONSTRUCTION CORP	Cole Information
2014	BAYSIDE CONTRACTING	Cole Information

FINDINGS

Year	Uses	Source
2014	RODEL RODEL ELECTRICAL CONTRACTORS	Cole Information
	TYCOON CONSTRUCTION CORPORATION	Cole Information
2010	RODEL ELECTRICAL CONTRACTORS	Cole Information
	BAYSIDE WAREHOUSE LLC	Cole Information
	MILLENNIUM CENTURY CONSTR	Cole Information
	TYCOON CONSTRUCTION CORP	Cole Information
2005	Panzella Jillian	Hill-Donnelly Information Services
	Papadopoulos Tommy	Hill-Donnelly Information Services
	SYLVIO SAVIDIS	Cole Information
2000	Sylvio Savidis	Cole Information
	13TH ST INTS FROM	Cole Information
	SYLVIO SAVIDIS	Cole Information
1995	FINESSE RENTAL LTD	Cole Information
1992	FINESSE RENTAL LTD	Cole Information
1991	Finesse Rental Ltd	NYNEX Information Resource Company
1983	JOCO CONSTR CORP	New York Telephone
1976	Albi Knitting Machine Inc	New York Telephone
	Harry Hirsch Machinery Corp	New York Telephone
	Harry Hirsch Machinery Corp	New York Telephone
1970	Albi Knitting Machine Inc	New York Telephone
	Harry Hirsch Machinery Corp	New York Telephone
1967	Manshul Const Corp	New York Telephone
1945	Queens Laundry Svce	New York Telephone
	Queens Wet Wash Co	New York Telephone
	Rosemar Laundry Svce	New York Telephone
1934	Weiss Albert pres Rosemar Laundry Corp	R. L. Polk & Co.

1266 37TH AVE

Year	Uses	Source
1996	Baskin Robbins Ice Cream Store	NYNEX

FINDINGS

1272 37TH AVE

Year	Uses	Source
1939	Nolan Frank A	New York Telephone Company

1287 37TH AVE

Year	Uses	Source
1934	Profeta Robt Mary lab	R. L. Polk & Co.

1301 37TH AVE

Year	Uses	Source
2010	INTERIOR DESIGN CARPENTRY ART	Cole Information
2005	No Current Listing	Hill-Donnelly Information Services
	INTERIOR DESIGN CARPENTRY ART	Cole Information
1992	EFFICIENT COMMUNICATIONS INC	Cole Information
	IMPERIAL SVCNG CO INC	Cole Information
1991	Imperial Svcng Co Inc	NYNEX Information Resource Company
1983	Imperial Svcng Co Inc	New York Telephone
1976	Equitable Washing Mach Co	New York Telephone
	Gomet Corp	New York Telephone
	Gottlieb Philip R b	New York Telephone
1970	Equitable Washing Mach Co	New York Telephone
	Gomet Const Corp	New York Telephone
	Gomet Design Corp	New York Telephone
	Gottlieb Philip R b	New York Telephone
	Meter Mac Ltd	New York Telephone
	Metgot Inc	New York Telephone
	Metliz Danl Assocs engnrs & archts	New York Telephone
	Nu Lava Corp	New York Telephone
	Phildan Machs Inc	New York Telephone
	Two Way Enterprises	New York Telephone
1967	Equitable Washing Mach Co	New York Telephone
	Gomet Const Corp	New York Telephone
	Gottlieb Philip R b	New York Telephone
	Meter Mac Ltd	New York Telephone
	Metgot Inc	New York Telephone

FINDINGS

Year	Uses	Source
1967	Metliz Danl Assocs engnrs & archts	New York Telephone
	Nu Lava Corp	New York Telephone
	Phildan Machs Inc	New York Telephone
1945	Teofilo John	New York Telephone
	Tognieri Dora	New York Telephone
1934	Indiveri John Lena piano stringer	R. L. Polk & Co.
	Teofelio Jos Mary gro	R. L. Polk & Co.
	Teofelio Lena	R. L. Polk & Co.

1307 37TH AVE

Year	Uses	Source
2020	FALCON FIRE & SECURITY	EDR Digital Archive
	ELIT GREEN BUILDERS CORP	EDR Digital Archive
	HOUR CHILDREN INC	EDR Digital Archive
2017	CEMA CONSTRUCTION CORP	Cole Information
	ELIT GREEN BUILDERS CORP	Cole Information
	FALCON FIRE & SECURITY	Cole Information
	HOUR CHILDREN INC	Cole Information
	HOUR CHILDREN	Cole Information
2014	PROMO PRO LIMITED	Cole Information
	ALMA CONSTRUCTION	Cole Information
	FALCON FIRE & SECURITY	Cole Information
	ELIT GREEN BUILDERS CORPORATION	Cole Information
	HOUR CHILDREN INCORPORATED	Cole Information
	CEMA CONSTRUCTION CORPORATION	Cole Information
2010	ELIT GREEN BUILDERS CORP	Cole Information
	PROMOPRO LTD	Cole Information
	COPPER CREATIONS INC	Cole Information
2005	HMP Constru	Hill-Donnelly Information Services
	Network Funding Inc IF	Hill-Donnelly Information Services
	Promo Pro LTD 20 o	Hill-Donnelly Information Services
	Superior Drywall & Acoustical	Hill-Donnelly Information Services
	TOLT CONSTRUCTION CORP	Cole Information

FINDINGS

Year	Uses	Source
2005	US ELECTRIC CORP	Cole Information
	NETWORK FUNDING CORP	Cole Information
	PROMO PRO LTD	Cole Information
2000	Alma Constuction	Cole Information
	Etny Environ Inc	Cole Information
	Joanides John CP	Cole Information
	Promao Pro Ltd	Cole Information
	Pnmpr Ltd Snlght	Cole Information
	Vim Paint & Restor	Cole Information
	PROMO PRO LIMITED	Cole Information
	PROMO-PRO LIMITED SUNLIGHT RESTORATION	Cole Information
	ALMA CONSTRUCTION	Cole Information
	ARIS RESTORATION CORPORATION	Cole Information
	SINGER ROOFING	Cole Information
	VIM PAINTING & RESTORATION CORPORATION	Cole Information
	JOANIDES JOHN CPA	Cole Information
1995	SUMMIT WATERPROOFING & RESTORATION CORP	Cole Information
	VIM PAINTING & RESTORATION CORP	Cole Information
	FALCON CONSTRUCTION INC	Cole Information
	TOP COVE	Cole Information
	ANTHOS CONTRACTING CORP	Cole Information
1992	VIM PAINTING & RESTORATION CORP	Cole Information
1991	Vim Painting & Restoration Corp	NYNEX Information Resource Company
1983	Gem Capitol	New York Telephone
	SUMMIT WATRPRFNG & RE STORATON	New York Telephone
	Vim Painting	New York Telephone
1976	Greek Broadcasting System	New York Telephone
1970	Field Richd	New York Telephone
	Tufano Frank	New York Telephone
1967	Field Richd	New York Telephone
	Tufano Frank	New York Telephone

Year	Uses	Source
1962	Tufano Carmine	New York Telephone Directory
	Tufano Carol	New York Telephone Directory
	Tufano Frank	New York Telephone Directory
1934	Daddieco Nicholas Margt lab	R. L. Polk & Co.
	Montanaro Jos Blanche lab	R. L. Polk & Co.
	Trocco I Dominick lab	R. L. Polk & Co.
	Trocco Frank Antoinette lab	R. L. Polk & Co.

1310 37TH AVE

Year	Uses	Source
1934	Teofelio Cresanzo	R. L. Polk & Co.

1315 37TH AVE

Year	Uses	Source
2020	SUMMIT WATERPROOFING	EDR Digital Archive
2017	SUMMIT WATERPROOFING & RESTORATION C	Cole Information
	INFO DATA NETWORK INC	Cole Information
2014	PRESTIGE ELEVATOR	Cole Information
	SUMMIT WATERPROOFING & RESTORATION C	Cole Information
	ECONO TELEPHONE	Cole Information
	INFO DATA NETWORK INCORPORATED	Cole Information
2010	SUMMIT WATERPROOFING	Cole Information
	GREENLIGHT INITIATIVE	Cole Information
	AMERICAN SCAFFOLDING CORP	Cole Information
	OUR FELLOWSHIP LTD	Cole Information
	SOLID STATE CITY	Cole Information
2005	Accent Contracting Corp	Hill-Donnelly Information Services
	Econo Tel 1 P	Hill-Donnelly Information Services
	Info Data Network Inc 2 P	Hill-Donnelly Information Services
	Sommiet Enterprises Inc	Hill-Donnelly Information Services
	Summit Waterproofing	Hill-Donnelly Information Services
	INFO DATA NETWORK INC	Cole Information
	GUSMAR REALTY CORP	Cole Information

FINDINGS

Year	Uses	Source
2005	SUMMIT WATERPROOFING & RESTORATION C	Cole Information
	NEW MILLENIUM REALTY	Cole Information
	ECONO TEL	Cole Information
	CONFLUENCE 1 CORP	Cole Information
	ATLAS CONSTRUCTION OF NEW YORK INC	Cole Information
2000	Afghan Blue Sky	Cole Information
	Bravo Contrng Corp	Cole Information
	Gls Financial Serv	Cole Information
	New York Russnc Const	Cole Information
	New Est & Dev Corp	Cole Information
	Summit Rester Crp	Cole Information
	AFGHAN BLUE SKY COMPANY	Cole Information
	SUMMIT WATERPROOFING & RESTORATION CORPORATION	Cole Information
	SAVOYA CONSTRUCTION COMPANY	Cole Information
	BRAVO CONTRACTING CORPORATION	Cole Information
	UNITED PAINTING & CONTRACTING INCORPORATED	Cole Information
	JOSEPH SAMMARTANO	Cole Information
1992	SUMMIT WATERPROOFING & RESTORATION CORP	Cole Information
	SUMMIT RENOVATION CORP	Cole Information
	BRAVO CONTRACTING CORP	Cole Information
	FALCON WATERPROOFING	Cole Information
1991	SUMMIT WATERPROOFING & RESTORATION CORP	NYNEX Information Resource Company
1939	Miet Robt ornmtl Iron w ks	New York Telephone Company
1934	Matcovich Philip Cath iron w kr	R. L. Polk & Co.

1319 37TH AVE

Year	Uses	Source
2000	14TH ST INTS FROM	Cole Information
1991	Boland A	NYNEX Information Resource Company
	Lam Son Loc	NYNEX Information Resource Company

FINDINGS

Year	Uses	Source
1983	Georgakis George	New York Telephone
	Georgakis Painters Corp	New York Telephone
	Gonzalez Carmen	New York Telephone
1970	Manganiello Jas	New York Telephone
	Manganiello Jas Jr	New York Telephone
1967	Manganiello Jas	New York Telephone
	Manganiello Jas Jr	New York Telephone
1962	Manganiello Jas	New York Telephone Directory
1945	Manganiello Jas	New York Telephone
1934	Abbene Salvatore Stella auto mech	R. L. Polk & Co.
	Ede Frank Elizabeth chauf	R. L. Polk & Co.
	Greyhound automotive Engineers TN auto w reckers	R. L. Polk & Co.

1333 37TH AVE

Year	Uses	Source
1996	Y Z M Lighting Inc	NYNEX

1401 37TH AVE

Year	Uses	Source
2005	CHANJEET SINGH	Cole Information

1442 37TH AVE

Year	Uses	Source
1991	Pappas Spiros	NYNEX Information Resource Company

1450 37TH AVE

Year	Uses	Source
1939	Blue Ribn Toy & Novlty Co	New York Telephone Company

1801 37TH AVE

Year	Uses	Source
1970	Jupiter Washers Inc	New York Telephone

1806 37TH AVE

Year	Uses	Source
1934	Gibbons Chas A Louisa	R. L. Polk & Co.

FINDINGS

1919 37TH AVE

Year	Uses	Source
2000	Essie Csmtcs Ltd	Cole Information
	Essie Csmtcs Ltd	Cole Information
	LJM GENERAL CONSTRUCTION INCORPORATED	Cole Information
	NITTSU NIPPON EXPRESS U S A INCORPORATED	Cole Information

1931 37TH AVE

Year	Uses	Source
2000	Vincent Mktg Inc	Cole Information

1940 37TH AVE

Year	Uses	Source
2005	KENCO RETAIL SHOP	Cole Information

1944 37TH AVE

Year	Uses	Source
2000	ASTORIA LIQUOR STORE	Cole Information

1946 37TH AVE

Year	Uses	Source
2005	LA CATINELLA FOOD INC	Cole Information

1948 37TH AVE

Year	Uses	Source
2000	VERY BEST LAUNDRY	Cole Information

1951 37TH AVE

Year	Uses	Source
2000	TERRAFERMA CONSTRUCTION CORPORATION	Cole Information

2001 37TH AVE

Year	Uses	Source
2010	AYMAN HADHOUD	Cole Information

FINDINGS

2002 37TH AVE

Year	Uses	Source
2005	RASVAN IONESCU	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2003 37TH AVE

Year	Uses	Source
2005	Goumas Sidtiros	Hill-Donnelly Information Services
2000	E Xanthoudakis	Cole Information
	STEVE XANTHOUDAKIS	Cole Information

2004 37TH AVE

Year	Uses	Source
2005	JOHN BRANDEIS	Cole Information
2000	K OBrien	Cole Information
	JOHN BRANDEIS	Cole Information
	K OBRIEN	Cole Information

2006 37TH AVE

Year	Uses	Source
2000	Hilary Wamner	Cole Information
	HILARY WARNER	Cole Information
	LEONARD BACICH	Cole Information

2007 37TH AVE

Year	Uses	Source
2005	LEONIDAS BOURITSAS	Cole Information

2008 37TH AVE

Year	Uses	Source
2005	MAUREEN VARVI	Cole Information
2000	Maureen Varvi	Cole Information
	MAUREEN VARVI	Cole Information

2009 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

FINDINGS

2010 37TH AVE

Year	Uses	Source
2005	MARTIN MCCARTHY	Cole Information
2000	Martin Mc Carthy	Cole Information
	MARTIN MCCARTHY	Cole Information

2011 37TH AVE

Year	Uses	Source
2005	Drew s Alfred M	Hill-Donnelly Information Services
2000	OCCUPANT UNKNOWN	Cole Information

2012 37TH AVE

Year	Uses	Source
2005	EPHRAIM PIAMA	Cole Information
2000	SIMON PIANA	Cole Information

2013 37TH AVE

Year	Uses	Source
2005	CHRIS MARNEZOS	Cole Information
2000	D RAMIERZ	Cole Information

2014 37TH AVE

Year	Uses	Source
2005	Ralbovsky Josip	Hill-Donnelly Information Services
	JOSIP RALBOVSKY	Cole Information
2000	ROBERT SALERNI	Cole Information
1970	DeStefano Louise Mrs	New York Telephone

2015 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2016 37TH AVE

Year	Uses	Source
2005	YOU SU	Cole Information
2000	You H Su	Cole Information
	Ming M Zhou	Cole Information

FINDINGS

Year	Uses	Source
2000	TSE LIU	Cole Information
	YOU SU	Cole Information
	MING ZHOU	Cole Information

2017 37TH AVE

Year	Uses	Source
2005	Flossos Spiro	Hill-Donnelly Information Services
	SPIRO FLOSSOS	Cole Information
2000	MARY HUDSON	Cole Information

2018 37TH AVE

Year	Uses	Source
2000	George OShe	Cole Information
	GEORGE OSHEA	Cole Information

2019 37TH AVE

Year	Uses	Source
2010	BORIS SORIANO	Cole Information
2005	Soria Irma 7a	Hill-Donnelly Information Services
	H Soriano Boris	Hill-Donnelly Information Services
	Sverdlova Elina	Hill-Donnelly Information Services
	BORIS SORIANO	Cole Information
2000	Marco Tonelli	Cole Information
	Renato Tonelli	Cole Information
	MARCO TONELLI	Cole Information

2020 37TH AVE

Year	Uses	Source
2000	James Kieman	Cole Information
	Theresa Simone	Cole Information
	JAMES KIERNAN	Cole Information
	THERESA SIMONE	Cole Information

2021 37TH AVE

Year	Uses	Source
2005	MELISSA CARROLL	Cole Information

FINDINGS

Year	Uses	Source
2000	Linan Dong	Cole Information
	Wilfred Tenaillon	Cole Information
	WILFRED TENAILLON	Cole Information

2023 37TH AVE

Year	Uses	Source
2005	AMBER HANCOCK	Cole Information
2000	SUSAN GREENE	Cole Information

2025 37TH AVE

Year	Uses	Source
2005	H Rosete Roland	Hill-Donnelly Information Services
	ROLAND ROSETE	Cole Information
2000	ROLAND ROSETE	Cole Information

2026 37TH AVE

Year	Uses	Source
2005	NICHOLAS ZOTALIS	Cole Information
2000	Jose Lebron	Cole Information
	JOSE LEBRON	Cole Information

2028 37TH AVE

Year	Uses	Source
1939	Schmuck Andreas	New York Telephone Company

2032 37TH AVE

Year	Uses	Source
2005	DUMITRU POPESCU	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2034 37TH AVE

Year	Uses	Source
2005	LAURA GILDEA	Cole Information
2000	Stalla Delrosario	Cole Information
	W Gin	Cole Information
	NIKKI AW	Cole Information

FINDINGS

Year	Uses	Source
2000	STELLA DELROSARIO	Cole Information
	A NG	Cole Information
	W GIN	Cole Information

2037 37TH AVE

Year	Uses	Source
2010	GEORGE HATZINIKOLAOU	Cole Information
2000	Bryan Kelly	Cole Information
	BRYAN KELLY	Cole Information

2039 37TH AVE

Year	Uses	Source
2005	h Sanchez Diego s	Hill-Donnelly Information Services
2000	OCCUPANT UNKNOWN	Cole Information

2044 37TH AVE

Year	Uses	Source
2005	KATHRYN OBRIEN	Cole Information

2056 37TH AVE

Year	Uses	Source
2005	PATRICIO MUNOZ	Cole Information
2000	A GRENETZ	Cole Information

2058 37TH AVE

Year	Uses	Source
2005	LUCIA DANGELO	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2060 37TH AVE

Year	Uses	Source
2005	CHUCK NG	Cole Information

2062 37TH AVE

Year	Uses	Source
2005	ALFONSO CARLINO	Cole Information

FINDINGS

2066 37TH AVE

Year	Uses	Source
2005	Tormna Stefanie	Hill-Donnelly Information Services
	BOB BRADER	Cole Information
2000	Daniel Domingo	Cole Information
	DANIEL DOMINGO	Cole Information

2068 37TH AVE

Year	Uses	Source
2005	SUSIE CASTRO	Cole Information
2000	A Antonio	Cole Information
	Susie Castro	Cole Information
	SUSIE CASTRO	Cole Information
	HUGO DIAZ	Cole Information
	A ANTONIO	Cole Information

2070 37TH AVE

Year	Uses	Source
2000	A ODonnell	Cole Information
	21ST ST INTS FROM	Cole Information
	A ODONNELL	Cole Information

2103 37TH AVE

Year	Uses	Source
2000	Desiree Lopez	Cole Information
	DESIREE LOPEZ	Cole Information
1945	Belinsky Larry auto wreckng	New York Telephone
	United Auto Wrecking Co	New York Telephone

2111 37TH AVE

Year	Uses	Source
2010	EMMANUEL DIAKOGEORGIOS	Cole Information
2005	Diakogeorgios Irene	Hill-Donnelly Information Services
	EMMANU DIAKOGEORGIOS	Cole Information
2000	I Diakogeorgios	Cole Information
	Wilson	Cole Information

Year	Uses	Source
2000	IRENE DIAKOGEORGIOS	Cole Information
	R WILSON	Cole Information

2112 37TH AVE

Year	Uses	Source
2005	MARINO KALLINDERIS	Cole Information
2000	MARINO KALLINDERIS	Cole Information

2113 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2114 37TH AVE

Year	Uses	Source
2005	AJIT SAHA	Cole Information
2000	Saian Mulmi	Cole Information
	OCCUPANT UNKNOWN	Cole Information

2115 37TH AVE

Year	Uses	Source
2005	Chen Rui Man	Hill-Donnelly Information Services
	DAN LAI	Cole Information
2000	Dan H Lai	Cole Information
	DAN LAI	Cole Information

2116 37TH AVE

Year	Uses	Source
2005	ILIAS PAPAZACHARIOU	Cole Information
2000	A Xaramopoaiou	Cole Information
	A XARAMOPOULOU	Cole Information

2117 37TH AVE

Year	Uses	Source
2017	PARTS AUTHORITY STORE 14	Cole Information
	PARTS AUTHORITY	Cole Information
	EJ ELECTRIC	Cole Information

FINDINGS

Year	Uses	Source
2014	EJ ELECTRIC	Cole Information
2010	ENDO FREIGHT FORWARDERS NY	Cole Information
2005	CCS Freight Corp 10i	Hill-Donnelly Information Services
	Endo Freight Forw arders Ny	Hill-Donnelly Information Services
	Ishikaw a Gumi LTD	Hill-Donnelly Information Services
	C C S FREIGHT CORP	Cole Information
	ENDO FREIGHT FORWARDERS	Cole Information
2000	S Freight Corp	Cole Information
	Endo Frght Frw rdrs	Cole Information
	Ishikaw a Guni Ltd	Cole Information
	ISHIKAWA GUMI LIMITED	Cole Information
	ENDO FREIGHT FORWARDERS N Y INCORPORATED	Cole Information
	C C S FREIGHT CORPORATION	Cole Information
	OCCUPANT UNKNOWN	Cole Information
1995	C C S FREIGHT CORP	Cole Information
	ISHIKAWA-GUMI LTD	Cole Information
	ENDO FREIGHT FORWARDERS N Y INC	Cole Information
1992	C C S FREIGHT CORP	Cole Information
	ISHIKAWA-GUMI LTD	Cole Information
	ENDO FREIGHT FORWARDERS NY INC	Cole Information
1991	C C S Freight Corp	NYNEX Information Resource Company
	ENDO FREIGHT FORWARDERS NY INC	NYNEX Information Resource Company
	Ishikaw a Gumi Ltd	NYNEX Information Resource Company
1983	C C S Freight Corp	New York Telephone
	Endo Corp endo corp	New York Telephone
	ENDO FREIGHT FORWARDERS NY INC	New York Telephone
	Ishikaw a Gumi Ltd	New York Telephone
1976	A Greene Co Inc	New York Telephone
	Green Co A Inc	New York Telephone
1970	A Greene Co Inc	New York Telephone
	World Housew recking CO Inc	New York Telephone
	Greene A Co Inc hse w reckrs	New York Telephone

2118 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2119 37TH AVE

Year	Uses	Source
2005	Bournias Mike	Hill-Donnelly Information Services
	Panteloukas Kostas	Hill-Donnelly Information Services
	KONSTANTINOS PANTELOUKAS	Cole Information
2000	LESLYE ANDERSON	Cole Information

2120 37TH AVE

Year	Uses	Source
2005	MICHAEL GATANAS	Cole Information
2000	MICHAEL GATANAS	Cole Information

2121 37TH AVE

Year	Uses	Source
2005	Sikder Shahida Abdul Hai & Ab	Hill-Donnelly Information Services
	HABIBUR RAHMAN	Cole Information
2000	Golam K Chow dhury	Cole Information
	Habibur Rahman	Cole Information
	Kanm Rez	Cole Information
	KARIM REZA	Cole Information

2122 37TH AVE

Year	Uses	Source
2005	KINIKI STIRLING	Cole Information
2000	Vicente Aleksinko	Cole Information
	VICENTE ALEKSINKO	Cole Information
1962	Berger Henry	New York Telephone Directory

2123 37TH AVE

Year	Uses	Source
2005	SachInvala Zarine	Hill-Donnelly Information Services
2000	Amer Bagel	Cole Information

FINDINGS

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2124 37TH AVE

Year	Uses	Source
2005	CLAUDIO OLIVERA	Cole Information
2000	Zak Belkebir	Cole Information
	Mohamed Kraim	Cole Information
	MOHAMED KRAIMA	Cole Information
	ZAK BELKEBIR	Cole Information

2125 37TH AVE

Year	Uses	Source
2005	JAMES CASSAR	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2126 37TH AVE

Year	Uses	Source
2005	TIMOLEON KOKKINOS	Cole Information
2000	Timoleon Kokkinos	Cole Information

2127 37TH AVE

Year	Uses	Source
2010	NATALIA SEREDINSKAYA	Cole Information
2005	Seredinskaya Natalia	Hill-Donnelly Information Services
	Shevchuk Ostap Yo	Hill-Donnelly Information Services
	NATALIA SEREDINSKAYA	Cole Information
2000	C CONNOLLY	Cole Information

2129 37TH AVE

Year	Uses	Source
2005	MIKE PSCORAS	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2130 37TH AVE

Year	Uses	Source
2000	Jesuina Santos	Cole Information

FINDINGS

2131 37TH AVE

Year	Uses	Source
2010	MIGUEL ARMENTEROS	Cole Information
2005	Armenteros M	Hill-Donnelly Information Services

2132 37TH AVE

Year	Uses	Source
2000	Harry Likourentzos	Cole Information
	Harry Likourentzos	Cole Information
	HARRY LIKOURENTZOS	Cole Information

2133 37TH AVE

Year	Uses	Source
2010	ADAMANDI TRIANTAFILIDIS	Cole Information
2005	Papaloukas Georgios	Hill-Donnelly Information Services
	Triantafilldes Evangelos	Hill-Donnelly Information Services
2000	Mannos Baris	Cole Information
	MARINOS BARIS	Cole Information

2134 37TH AVE

Year	Uses	Source
2005	THOMAS SPERAZZA	Cole Information
2000	Thomas Speraz	Cole Information
	THOMAS SPERAZZA	Cole Information

2135 37TH AVE

Year	Uses	Source
2005	Pantelias A	Hill-Donnelly Information Services
	ATHANASIOS PANTELIAS	Cole Information
2000	Vasilike Padelias	Cole Information
	A Pantelias	Cole Information
	V PADELIAS	Cole Information
	A PANTELIAS	Cole Information

FINDINGS

2136 37TH AVE

Year	Uses	Source
2005	JOVITA ORTEGA	Cole Information
2000	Kinuyo Kawamoto	Cole Information
	L Orteg	Cole Information
	Maritza Orteg	Cole Information
	Raquel Orteg	Cole Information
	LUCIA ORTEGA	Cole Information

2137 37TH AVE

Year	Uses	Source
2005	Hoffman A	Hill-Donnelly Information Services
2000	F Ferreir	Cole Information
	F FERREIRA	Cole Information

2138 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information
1962	McDonnell Kathryn P	New York Telephone Directory

2139 37TH AVE

Year	Uses	Source
2005	Dechkounlan R	Hill-Donnelly Information Services
	MARAL SERCE	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2140 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2141 37TH AVE

Year	Uses	Source
2005	DelidimItropoulos Theodore	Hill-Donnelly Information Services
	THEODORE DELIDIMITROPOULOS	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

FINDINGS

2142 37TH AVE

Year	Uses	Source
2000	Y Benchakroun	Cole Information
	Tony Saint	Cole Information
	TONY SAINT	Cole Information

2143 37TH AVE

Year	Uses	Source
2005	Delidlmitropulu Vaia	Hill-Donnelly Information Services
	VAIA DELIDIMITROPULU	Cole Information

2144 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2145 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2146 37TH AVE

Year	Uses	Source
2005	SCOTT MCCORD	Cole Information
2000	Yishun Lai	Cole Information
	Scott Mc Cord	Cole Information
	SCOTT MCCORD	Cole Information

2147 37TH AVE

Year	Uses	Source
2014	SALVATORE CONIGLAIRO	Cole Information
2010	SALVATORE CONIGLAIRO	Cole Information
2005	Coniglairo Salvatore	Hill-Donnelly Information Services
	Pannizzo Domenico	Hill-Donnelly Information Services
	DOMENICO PANNIZZO	Cole Information
2000	S Coniglairo	Cole Information
	D PANNIZZO	Cole Information
	S CONIGLAIRO	Cole Information

FINDINGS

2148 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2149 37TH AVE

Year	Uses	Source
2010	ELENI MITRI	Cole Information
2005	h Mitri Eleni	Hill-Donnelly Information Services
	ELENI MITRI	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2150 37TH AVE

Year	Uses	Source
2005	KATHERINE ZIOGAS	Cole Information
2000	Alice Spelios	Cole Information
	TOM SPELIOS	Cole Information

2151 37TH AVE

Year	Uses	Source
2005	KAZUKO MINAMOTO	Cole Information
2000	Viktor Bensh	Cole Information
	VIKTOR BERISHA	Cole Information

2153 37TH AVE

Year	Uses	Source
2010	GEORGE KIRIAKES	Cole Information
2005	Kiriakes George	Hill-Donnelly Information Services
2000	Piro Qirjaqi	Cole Information
	GEORGE KIRIAKES	Cole Information

2154 37TH AVE

Year	Uses	Source
2000	XUONG CHONG	Cole Information

2155 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

FINDINGS

2156 37TH AVE

Year	Uses	Source
2005	WILLIAM BICKNELL	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2157 37TH AVE

Year	Uses	Source
2000	GERARD MURTHA	Cole Information

2158 37TH AVE

Year	Uses	Source
2000	Pinder Paul	Cole Information
	K Weeks	Cole Information
	K WEEKS	Cole Information

2159 37TH AVE

Year	Uses	Source
2005	ANTHONY MARINO	Cole Information
2000	M Percival	Cole Information
	M PERCIVAL	Cole Information

2160 37TH AVE

Year	Uses	Source
2000	Rnastasia Knezis	Cole Information

2161 37TH AVE

Year	Uses	Source
2010	PETER GRUDZIEN	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2162 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2163 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

FINDINGS

2164 37TH AVE

Year	Uses	Source
2005	VINCENT LOMANTO	Cole Information
2000	Diego Lomanto	Cole Information
	Redouane Ziouti	Cole Information
	DIEGO LOMANTO	Cole Information

2166 37TH AVE

Year	Uses	Source
2005	STELIS MAVROGIORGIS	Cole Information
2000	R Okazaki	Cole Information
	R OKAZAKI	Cole Information

2167 37TH AVE

Year	Uses	Source
2005	SIDIROPOULOU KYRIAKI	Cole Information
2000	Wiliam Neilson	Cole Information
	WILLIAM NEILSON	Cole Information

2168 37TH AVE

Year	Uses	Source
2005	JOHN DOTSIKAS	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2170 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2171 37TH AVE

Year	Uses	Source
2005	Caglar Elif v	Hill-Donnelly Information Services
	GEORGE MORELLI	Cole Information
2000	DIEGO RIVAS	Cole Information

2172 37TH AVE

Year	Uses	Source
2005	JONATHAN ROSE	Cole Information

Year	Uses	Source
2000	Nikolaos Antonion	Cole Information
	N ANTONIOU	Cole Information

2174 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2176 37TH AVE

Year	Uses	Source
2005	SHIRLEY FREIRE	Cole Information

2201 37TH AVE

Year	Uses	Source
2020	JK LIMO SVC	EDR Digital Archive
	SHAIDA PARVEEN	EDR Digital Archive
2017	JK LIMO SERVICE	Cole Information
2014	JK LIMO SERVICE	Cole Information
2010	GILL AUTO BODY & REPAIR INC	Cole Information
2005	Parveen Shalda v	Hill-Donnelly Information Services
	NEW CHENOB AUTOBODY	Cole Information
2000	New Ctinb Atbdy Shp	Cole Information
	SONI & MONI INCORPORATED	Cole Information
	NEW CHENAB AUTOBODY SHOP	Cole Information
1995	EJAZ ALI	Cole Information
	EJAZ, ALI	Cole Information
1992	EMPIRE LIMOUSINE SVCE	Cole Information
	ALPINE LIMOUSINE INC	Cole Information
1991	Empire Limousine Svce	NYNEX Information Resource Company
1976	Fyne Instrmnt Co	New York Telephone
	Fyr Fyter Co US Hwy No 1 @Newark@ NJ NYC Tel No WO 21997	New York Telephone
1970	Schulster Dr J Co	New York Telephone
	Schulsterizing Corp of America	New York Telephone
1967	Schulster Dr J Co	New York Telephone
1939	Alliance Auto Painting & Body Co	New York Telephone Company

FINDINGS

Year	Uses	Source
1934	Alliance Auto Painting Co RTN Patk Nicholas	R. L. Polk & Co.
	Nicholas Path Margt Alliance Auto Painting Co	R. L. Polk & Co.

2202 37TH AVE

Year	Uses	Source
2020	GEORGE KIRIAKOPOULOS	EDR Digital Archive
2017	TGM AUTO REPAIR CORP	Cole Information
2014	TGM AUTOMOBILE REPAIR CORPORATION	Cole Information
2010	TGM AUTO REPAIR CORP	Cole Information
2005	TGM Auto Repair Corp Is	Hill-Donnelly Information Services
2000	Auto Rpr Corp	Cole Information
	M Ante Repairs	Cole Information
	T G M AUTO REPAIRS	Cole Information
	T G M AUTO REPAIR CORPORATION	Cole Information
1995	T G M AUTO REPAIR CORP	Cole Information
	T G M AUTO REPAIRS	Cole Information
1992	ZIKOS, DEMETRA	Cole Information
1991	Manolas A	NYNEX Information Resource Company
1945	Victory Prods Corp	New York Telephone

2205 37TH AVE

Year	Uses	Source
2005	Multi Unit Address	Hill-Donnelly Information Services
	Choechen Ngaw ang Y	Hill-Donnelly Information Services
	Kinlay Gem	Hill-Donnelly Information Services
	Samaras A	Hill-Donnelly Information Services
	Sannfillppo Peter	Hill-Donnelly Information Services
	Scherlch Nathan	Hill-Donnelly Information Services
	Singh Mohan	Hill-Donnelly Information Services
	Stelgerw ald Deborah	Hill-Donnelly Information Services
	Tellez Ricarda	Hill-Donnelly Information Services
	Theodore Marie 0718 726 6178 g	Hill-Donnelly Information Services
	Valencerina C F	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	MARIE THEODORE	Cole Information
	VASILIOS CHRISTOU	Cole Information
	ATHANASIA SAMARAS	Cole Information
2000	E Barbos	Cole Information
	Nazma Begum	Cole Information
	Kate Hebinck	Cole Information
	Sharon Hwang	Cole Information
	Jawed Iqbal	Cole Information
	Mayte Negrete	Cole Information
	Jose L Rodriguez	Cole Information
	Sadtwant Singh	Cole Information
	Agustin Solano	Cole Information
	Valencenin	Cole Information
	K Vandoolaeghe	Cole Information
	Wm Van Tichelt	Cole Information
	MAYTE NEGRETE	Cole Information
	SHARON HWANG	Cole Information
	C VALENCERINA	Cole Information
	K VANDOOLAEGHE	Cole Information
	KATE HEBINCK	Cole Information
	JOSE RODRIGUEZ	Cole Information
	FLOR GONZALEZ	Cole Information
	E BARBOSA	Cole Information
	MALI	Cole Information
	AGUSTIN SOLANO	Cole Information
	WIM VANTICHELT	Cole Information
	JAWED IQBAL	Cole Information
1934	DAvison Fred W solr	R. L. Polk & Co.

2207 37TH AVE

Year	Uses	Source
2020	A1 COLLISION	EDR Digital Archive
	CHAUDHARY KARIM	EDR Digital Archive

FINDINGS

Year	Uses	Source
2017	A1 COLLISION	Cole Information
2014	E&Z ELECTRICAL MAINTENANCE INC	Cole Information
	A1 COLLISION	Cole Information
2010	E & Z ELECTRICAL MAIN INC	Cole Information
2005	Astro Hi Lifts Corp	Hill-Donnelly Information Services
	Awami Auto Body & Repair Shop	Hill-Donnelly Information Services
	E & Z Electrical Main Inc	Hill-Donnelly Information Services
	Karim Chaudhary F	Hill-Donnelly Information Services
	AWAMI AUTO BODY & REPAIR SHOP INC	Cole Information
	XTRA CARE AMBULETTE SERVICES INC	Cole Information
2000	Awami Bdy & Rpr Inc	Cole Information
	E & Z Maint Inc	Cole Information
	E & Z ELECTRICAL MAINTENANCE INCORPORATED	Cole Information
	AWAMI AUTO BODY & REPAIR SHOP INCORPORATED	Cole Information
	OCCUPANT UNKNOWN	Cole Information
1995	AWAMI AUTO BODY & REPAIR SHOP INC	Cole Information
1992	SAME DAY SVCES UNLIMITED INC	Cole Information
1991	Complete Delivery Systems Inc	NYNEX Information Resource Company
1983	Astro Hi Lifts Corp	New York Telephone
	Astro Jet Room restrnts JFK Intrnatl Airpt ABBREV Idlwld	New York Telephone
1976	Astro Hi Lifts Corp	New York Telephone
	Astro Hi Lifts Corp	New York Telephone
1970	The Hallen Constr Co Inc	New York Telephone
1967	ECKHOFF CHRISTIAN truk bodies	New York Telephone
1962	ECKHOFF CHRISTIAN trunk bodies	New York Telephone Directory
1939	Holland Catherine	New York Telephone Company

2208 37TH AVE

Year	Uses	Source
2020	QUALITY CAR TECH	EDR Digital Archive
2017	J & G AUTO REPAIR & BODY SHOP	Cole Information

FINDINGS

Year	Uses	Source
2010	THIRTYSEVENTH AVE AUTO REPAIR	Cole Information
2005	h Megaris Maria	Hill-Donnelly Information Services
	Thirty Seventh Ave Auto Repair	Hill-Donnelly Information Services
	RMR TRANSMISSION CORP	Cole Information
	PAL AUTO REPAIR & BODY SHOP INC	Cole Information
2000	Maria Meganis	Cole Information
	Thirty At Rpr & Bdy	Cole Information
	37 AVE AUTO REPAIR AND BODY SHOP	Cole Information
	THIRTY-SEVENTH AVE AUTO REPAIR & BODY SHOP	Cole Information
	MARIA MEGARIS	Cole Information
1995	BALLY'S AUTO COLLISION	Cole Information
	BELLO LONG ISLAND CITY AUTO REPAIR INC	Cole Information
	BELLO INSURANCE BROKERAGE LTD	Cole Information
1992	BELLO LONG ISLAND CITY AUTO REPAIR INC	Cole Information
1991	Black & Yellow Auto Tec Inc	NYNEX Information Resource Company
1945	Volpit Chew ing Candy Inc	New York Telephone
1934	Byron Baking Co RTN Michel Ethlujmiatos & Momelaos Sourgiauis	R. L. Polk & Co.

2211 37TH AVE

Year	Uses	Source
2000	Michael Krysiak	Cole Information
	MICHAEL KRYSIAK	Cole Information
	KESLEY COIMBRA	Cole Information

2212 37TH AVE

Year	Uses	Source
2014	BRANDON CHATKIN	Cole Information
2010	DIMITRIOS IAKOVOU	Cole Information
2000	Bullet Trucking	Cole Information
	OCCUPANT UNKNOWN	Cole Information

FINDINGS

2213 37TH AVE

Year	Uses	Source
2005	Schulz Allen	Hill-Donnelly Information Services
	SHADLA GROOMS	Cole Information
2000	A SCHULZ	Cole Information
	S GROOMS	Cole Information
1945	Olsen Engine & Motor Wks	New York Telephone
1939	Olsen Engine & Motor Wks	New York Telephone Company

2214 37TH AVE

Year	Uses	Source
2005	Glovanelli Steven	Hill-Donnelly Information Services
2000	Steven Giovaneli	Cole Information
	Tina Peppas	Cole Information
	TINA PEPPAS	Cole Information
	STEVEN GIOVANELLI	Cole Information
1970	Miller Max Truckg & Forw dg Co	New York Telephone
1967	Hughes Cibbon Indstries Corp	New York Telephone
	Miller Max Truckg & Forw dg Co	New York Telephone
1962	UDDEHOLM CO OF AMERICA INC w arehese	New York Telephone Directory
1939	Cole Chemcl Corp	New York Telephone Company
	Cole Chester David Dalny Rd Jam RE pubic 90169	New York Telephone Company
1934	Harry Silverstein formn	R. L. Polk & Co.

2215 37TH AVE

Year	Uses	Source
2020	AAD AUTO REPAIR & BODY SHOP	EDR Digital Archive
2014	BENGUL TOWING & LIMOSUINE SERVICE	Cole Information
2010	SHERWOOD SILVER BAY LIMO CORP	Cole Information
	DESHI MOTORS INC	Cole Information
2005	NT Corp 1 s	Hill-Donnelly Information Services
	Sherw ood Justice & Barton Limo	Hill-Donnelly Information Services
2000	G & C Auto	Cole Information

FINDINGS

Year	Uses	Source
2000	SHERWOOD SILVER BAY LIMOUSINE CORPORATION	Cole Information
	G & C AUTO REPAIRS OF 37TH AVE	Cole Information
1995	SHERWOOD SILVER BAY LIMOUSINE CORP	Cole Information
	SHERWOOD JUSTICE & BARTON LIMOUSINE CORP	Cole Information
	G & C AUTO REPAIRS OF 37TH AVE	Cole Information
1992	SHERWOOD JUSTICE & BARTON LIMOUSINE CORP	Cole Information
	SHAW LIMOUSINE CORP	Cole Information
1991	Shaw Limousine Corp	NYNEX Information Resource Company
	Sherwood Justice & Barton Limousine Corp	NYNEX Information Resource Company
1983	Shleppers Moving & Delivery Svce Inc	New York Telephone
1976	Andys Truck Repr	New York Telephone
	Banner Exprss & Truckg Co	New York Telephone
1970	Banner Exprs & Truckg Co	New York Telephone
1967	Banner Exprss & Truckg Co	New York Telephone
1962	Banner Exprss & Truckg Co	New York Telephone Directory

2216 37TH AVE

Year	Uses	Source
1934	Kirsch Mamie H tchr	R. L. Polk & Co.

2217 37TH AVE

Year	Uses	Source
2010	SILVIO RICCARDELLO	Cole Information
2005	Riccardello Slvio T 0718 626 41519 C	Hill-Donnelly Information Services
	Slvestri Erica 0718 726 72070 a	Hill-Donnelly Information Services
	SILVIO RICCARDELLO	Cole Information
2000	SILVIO RICCARDELLO	Cole Information

2218 37TH AVE

Year	Uses	Source
2005	Chung Hyun	Hill-Donnelly Information Services
	Ciaccio Anthony o	Hill-Donnelly Information Services
	Ciaccido Anthony	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	Ciacdo Anthony o	Hill-Donnelly Information Services
	Gallagher Aileen	Hill-Donnelly Information Services
	AILEEN GALLAGHER	Cole Information
2000	Jennifer Mac Avinta	Cole Information
	Leslie Northcutt	Cole Information
	E HATZIOANNOU	Cole Information
	J MACAVINTA	Cole Information
	LESLIE NORTHCUTT	Cole Information

2219 37TH AVE

Year	Uses	Source
2020	TWINS COLLISION INC	EDR Digital Archive
2014	M & B TWINS COLLISION	Cole Information
2010	TWINS COLLISION INC	Cole Information
2005	Twins Collision Inc I s	Hill-Donnelly Information Services
	TWINS COLLISION INC	Cole Information
2000	M & B Bdy & Fndr Inc	Cole Information
	M & B AUTO BODY & FENDER INCORPORATED	Cole Information
1995	M & B AUTO BODY & FENDER INC	Cole Information
1992	M & B AUTO BODY & FENDER INC	Cole Information
1991	Hechler Bros Stayrite Inc	NYNEX Information Resource Company
	Stayrite Inc hearing aids	NYNEX Information Resource Company
1983	Hechler Bros Stayrite Inc	New York Telephone
	Stayrite Inc hearing aids	New York Telephone
1976	Hechler Bros Inc hearing aids	New York Telephone
1970	Hechler Bros Inc hearing aids	New York Telephone
	Stayrite Inc	New York Telephone
1967	Hechler Bros Inc hearing aids	New York Telephone
	Stayrite Inc	New York Telephone
1962	Hechler Bros Inc hearing aids	New York Telephone Directory
1939	Milco Bronze Co	New York Telephone Company

FINDINGS

2220 37TH AVE

Year	Uses	Source
1970	Pickw ick Moving Co Inc	New York Telephone

2221 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2222 37TH AVE

Year	Uses	Source
2005	MENELAOS PISSOURIOS	Cole Information
2000	Alexis Chaconis	Cole Information
	A CHACONIS	Cole Information

2223 37TH AVE

Year	Uses	Source
2005	Fishback D	Hill-Donnelly Information Services
	h Legas Chris	Hill-Donnelly Information Services
2000	CHRIS LEGAS	Cole Information

2224 37TH AVE

Year	Uses	Source
2014	NONIE MICHEALS	Cole Information
2010	NONIE MICHEALS	Cole Information
2005	h Micheals Nonie	Hill-Donnelly Information Services
	Stergio Afroditi v	Hill-Donnelly Information Services
	NONIE MICHEALS	Cole Information
2000	N MULLER	Cole Information
	NORA ALEMAN	Cole Information

2227 37TH AVE

Year	Uses	Source
2005	Arf Mohammad	Hill-Donnelly Information Services
	Ortiz Juan	Hill-Donnelly Information Services
	MOHAMMAD ARIF	Cole Information
2000	J Magure	Cole Information

Year	Uses	Source
2000	Yan Tang	Cole Information
	YAN TANG	Cole Information
	J MAGUIRE	Cole Information

2228 37TH AVE

Year	Uses	Source
2010	SEAN HOLLAND	Cole Information
2005	SEAN HOLLAND	Cole Information
2000	Alan Rafterman	Cole Information
	ALAN RAFTERMAN	Cole Information

2229 37TH AVE

Year	Uses	Source
2005	Katsigeorgis John	Hill-Donnelly Information Services
	JOHN KATSIGEORGIS	Cole Information
2000	Wingchau Chong	Cole Information

2230 37TH AVE

Year	Uses	Source
2005	Bleyer M v	Hill-Donnelly Information Services
	Velez Nestor	Hill-Donnelly Information Services
	ANNA BAKERTCY	Cole Information
2000	Anna Albani	Cole Information
	ANNA ALBANI	Cole Information
	J BAKERTCY	Cole Information

2231 37TH AVE

Year	Uses	Source
2005	Manning Calogero	Hill-Donnelly Information Services
	TOMMASO GAMBINO	Cole Information
2000	Enza Gambino	Cole Information
	ENZA GAMBINO	Cole Information

2234 37TH AVE

Year	Uses	Source
2014	ILHAM BOUKHARI	Cole Information

Year	Uses	Source
2010	YOUNG SONG	Cole Information
2005	YOUNG SONG	Cole Information
2000	C TSOURISTAKIS	Cole Information

2236 37TH AVE

Year	Uses	Source
2010	THOMAS KILLEEN	Cole Information
2005	Killeen Thomas A	Hill-Donnelly Information Services
2000	OCCUPANT UNKNOWN	Cole Information

2237 37TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2238 37TH AVE

Year	Uses	Source
2005	Smergilio Amelia	Hill-Donnelly Information Services
	AMELIA SMERGILIO	Cole Information
2000	MARY OKOLOTKIEWICZ	Cole Information

2239 37TH AVE

Year	Uses	Source
2000	Miroslava Wachtl	Cole Information
	M WACHTL	Cole Information

2240 37TH AVE

Year	Uses	Source
2005	Bauer R	Hill-Donnelly Information Services
	Bauer Robert 0718 606 8965 o	Hill-Donnelly Information Services
	Shen Meng I v	Hill-Donnelly Information Services
	CHIA WANG	Cole Information
2000	Robert Bauer	Cole Information
	Xin Chen	Cole Information
	Paula Traugott	Cole Information
	XIN CHEN	Cole Information
	ROBERT BAUER	Cole Information

FINDINGS

Year	Uses	Source
2000	PAULA TRAUGOTT	Cole Information

2241 37TH AVE

Year	Uses	Source
2005	Conlon James	Hill-Donnelly Information Services
	JAMES CONLON	Cole Information
2000	David Bobick	Cole Information
	Souad Daanouri	Cole Information
	Jason Levinson	Cole Information
	Yael Mendels	Cole Information
	SALAS LEE	Cole Information
	DAVID BOBICK	Cole Information
	SOUAD DAANOUNI	Cole Information
	YAEL MENDELS	Cole Information
	JASON LEVINSON	Cole Information

2242 37TH AVE

Year	Uses	Source
2005	h Yoshlmura Jenny v 7 718 726 0261 oo	Hill-Donnelly Information Services
	JENNY YOSHIMURA	Cole Information
2000	Anthony Cirjak	Cole Information
	Jenny Yoshmur	Cole Information
	ANTHONY CIRJAK	Cole Information
	SCOTT SCHINDER	Cole Information
	JENNY YOSHIMURA	Cole Information

2244 37TH AVE

Year	Uses	Source
2005	Breuer Anthony	Hill-Donnelly Information Services
	Breuer C	Hill-Donnelly Information Services
	Hillen D	Hill-Donnelly Information Services
	D HILLEN	Cole Information
2000	Fernando Allen	Cole Information
	Nao Nagamori	Cole Information

Year	Uses	Source
2000	Erik Sentell	Cole Information
	D HILLEN	Cole Information
	NAO NAGAMORI	Cole Information
	F ALLEN	Cole Information
	ERIK SENTELL	Cole Information

2247 37TH AVE

Year	Uses	Source
2010	JULIAN PANOVSKI	Cole Information
2005	Baker Raymond	Hill-Donnelly Information Services
	Gran David	Hill-Donnelly Information Services
	DAVID GRAN	Cole Information
2000	David Gran	Cole Information
	Dan Wernette	Cole Information
	RAYMOND BAKER	Cole Information
	DAVID GRAN	Cole Information
	DAN WERNETTE	Cole Information

2248 37TH AVE

Year	Uses	Source
2005	Kimmel D	Hill-Donnelly Information Services
2000	Kurt Nelson	Cole Information
	Michele Sequin	Cole Information
	KURT NELSON	Cole Information
	M SEQUIN	Cole Information
	R EVANGELISTA	Cole Information

2249 37TH AVE

Year	Uses	Source
2005	CATHERINE MILIOS	Cole Information
2000	PAMELA COTTER	Cole Information

2250 37TH AVE

Year	Uses	Source
2005	Lannigan Peter	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	PETER LANNIGAN	Cole Information
2000	Jan Kostk	Cole Information
	JAN KOSTKA	Cole Information

2251 37TH AVE

Year	Uses	Source
2005	EDUARDO LEON	Cole Information
2000	Eduardo Leon	Cole Information
	EDUARDO LEON	Cole Information

2253 37TH AVE

Year	Uses	Source
2005	Dmytryszyn Nic	Hill-Donnelly Information Services
	NICHOLAS DMYTRYSZYN	Cole Information
2000	N DMYTRYSZYN	Cole Information

2254 37TH AVE

Year	Uses	Source
2005	Markou D	Hill-Donnelly Information Services
	Serrano Carlos	Hill-Donnelly Information Services
	CARLOS SERRANO	Cole Information
2000	Marco Alvarez	Cole Information
	D Markou	Cole Information
	D MARKOU	Cole Information
	MARCO ALVAREZ	Cole Information
	J JUGUILON	Cole Information

2256 37TH AVE

Year	Uses	Source
2000	Marina Boiadjian	Cole Information
	MARINA BOIADJIAN	Cole Information

2257 37TH AVE

Year	Uses	Source
2005	Morrissetle Melissa	Hill-Donnelly Information Services

FINDINGS

2258 37TH AVE

Year	Uses	Source
2005	Dimitropoulou Kath	Hill-Donnelly Information Services
	Sophodeous Lenia	Hill-Donnelly Information Services
	Versace Gary & Heather	Hill-Donnelly Information Services
	KATHERINE DIMITROPOULOU	Cole Information
2000	C Tsoutsanis	Cole Information
	C TSOUTSANIS	Cole Information

2259 37TH AVE

Year	Uses	Source
2005	Trudeau Kimb	Hill-Donnelly Information Services
2000	Danielle Ryan	Cole Information
	Dongho Song	Cole Information
	D RYAN	Cole Information

2260 37TH AVE

Year	Uses	Source
2005	Balducci An	Hill-Donnelly Information Services
	Balducd Michael	Hill-Donnelly Information Services
	Weeks K	Hill-Donnelly Information Services
	FRANK BALDUCCI	Cole Information
2000	Jennie Balducci	Cole Information
	A FILIPOWSKI	Cole Information
	JENNIE BALDUCCI	Cole Information

2261 37TH AVE

Year	Uses	Source
2014	KOSTA MOUSTOGIANNI	Cole Information
2005	Moustogiannis K	Hill-Donnelly Information Services
	KOSTAS MOUSTOGIANNI	Cole Information
2000	K Moustogiannis	Cole Information
	KOSTAS MOUSTOGIANNIS	Cole Information

FINDINGS

2263 37TH AVE

Year	Uses	Source
2014	CHRIS HROILJAC	Cole Information
2010	CHRIS HROILJAC	Cole Information
2005	Milohnic Ana	Hill-Donnelly Information Services
	ANA MILOHNIC	Cole Information
2000	RIDHA FELLAH	Cole Information
	C AVERKIOU	Cole Information
	ANA MILOHNIC	Cole Information

2264 37TH AVE

Year	Uses	Source
2010	REMIGIO RUCCONDICH	Cole Information
2005	Neves Nelson	Hill-Donnelly Information Services

2265 37TH AVE

Year	Uses	Source
2005	Kalandranis L	Hill-Donnelly Information Services
	Kalandranis L	Hill-Donnelly Information Services
	Mancuso Joseph	Hill-Donnelly Information Services
	LEO MANCUSO	Cole Information
2000	JOSEPH MANCUSO	Cole Information

2266 37TH AVE

Year	Uses	Source
2005	Clattei T	Hill-Donnelly Information Services
2000	OCCUPANT UNKNOWN	Cole Information

2272 37TH AVE

Year	Uses	Source
2005	Akhazzan Said	Hill-Donnelly Information Services
	BRIAN FOLEY	Cole Information
2000	Olga Alexandrovn	Cole Information
	OLGA ALEXANDROVNA	Cole Information

FINDINGS

2281 37TH AVE

Year	*Uses*	*Source*
2014	MARNIE ZIGELMAN	Cole Information
2010	WILLIAM LEE	Cole Information
	KEVIN COHEN	Cole Information
2005	Dillon John	Hill-Donnelly Information Services
	Fields David	Hill-Donnelly Information Services
	Garcia Juan	Hill-Donnelly Information Services
	h Looks Claudia o	Hill-Donnelly Information Services
	Radakovic Zarko	Hill-Donnelly Information Services
	Ryan Abbieo	Hill-Donnelly Information Services
	JUAN GARCIA	Cole Information
	JOHN DILLON	Cole Information
	ZARKO RADAKOVIC	Cole Information
	KEVIN COHEN	Cole Information
	JOHN MCCORMICK	Cole Information
	DAVID FIELDS	Cole Information
2000	Joel Beaver	Cole Information
	Kevin Cohen	Cole Information
	Michelle Collett	Cole Information
	Trent Porter	Cole Information
	Zarko Radakovic	Cole Information
	Teresa Roberts	Cole Information
	Shanice Wong	Cole Information
	23RD ST INTS FROM	Cole Information
	JEROME BASMA	Cole Information
	JUAN GARCIA	Cole Information
	JOEL BEAVER	Cole Information
	SHANICE WONG	Cole Information
	ZARKO RADAKOVIC	Cole Information
	TERESA ROBERTS	Cole Information
	KEVIN COHEN	Cole Information
	M COLLETTA	Cole Information

FINDINGS

Year	Uses	Source
2000	TRENT PORTER	Cole Information

2301 37TH AVE

Year	Uses	Source
2005	h Jaime Moscoso	Hill-Donnelly Information Services
	Livio Auto Svc 1i	Hill-Donnelly Information Services
	Sergios Auto Repair 1 s	Hill-Donnelly Information Services
	JAIME MOSCOSO	Cole Information
	LIVIO AUTO SERVICE	Cole Information
	SERGIOS	Cole Information
2000	Jaimo Moscoso	Cole Information
	Laube Balvin	Cole Information
	LAUBE BALVINA	Cole Information
	JAIME MOSCOSO	Cole Information
1995	JOHN'S AUTO CENTER	Cole Information
1992	G & A AUTO REPAIR	Cole Information
1991	M & B Auto Body & Fender Inc	NYNEX Information Resource Company
1983	M & B Auto Body & Fender Inc	New York Telephone
1976	MV Auto Body	New York Telephone
1970	Clements Bros	New York Telephone
	Fidelity Adistmt Bur Inc	New York Telephone
	FIDELITY & CASUALTY CO OF NY THE	New York Telephone

2302 37TH AVE

Year	Uses	Source
2017	TWINS COLLISION INC	Cole Information
	37 AVE LOCKSMITHAND FLAT FIX 24 HRS	Cole Information
2014	SAFDAR SHAH	Cole Information
2010	SHAH JEE MOTORS	Cole Information
	SYED IQBAL	Cole Information
2005	Shah Jee Motors 11 R	Hill-Donnelly Information Services
	Syed Motor Inc 1 R	Hill-Donnelly Information Services
	SHAH JEE MOTORS	Cole Information
	SYED MOTOR INC	Cole Information

FINDINGS

Year	Uses	Source
2005	SYED IQBAL	Cole Information
2000	Hi Tech At Dgnstc	Cole Information
	Shah Jee Motors	Cole Information
	Syed Motor Inc	Cole Information
	SHAH JEE MOTORS	Cole Information
	HI TECHNOLOGY AUTO DIAGNOSTIC CENTER CORPORATION	Cole Information
1995	HI TECH AUTO DIAGNOSTIC CENTER CORP	Cole Information
1992	ANDREAS AUTO REPR SHOP INC	Cole Information
1983	DATSIKAS SAPANAS INC	New York Telephone
1976	Harrys Motor repair	New York Telephone
1970	San ANITON SYGE STA CORP	New York Telephone
1967	San Anton Svce Sta Corp	New York Telephone
1962	Elkay Svce Sta	New York Telephone Directory
1945	Bisoco Oil Co	New York Telephone
1939	Pauls Service Sta	New York Telephone Company

2303 37TH AVE

Year	Uses	Source
2005	H Lohr EJAO	Hill-Donnelly Information Services
	EUGENE LOHR	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information
1967	Wysocki Mary Mrs	New York Telephone
1945	Bailey John W	New York Telephone
1939	Bailey John W	New York Telephone Company
1934	Bailey John Wm Mao R brklyr	R. L. Polk & Co.

2307 37TH AVE

Year	Uses	Source
2020	PETER LANZILOTTA	EDR Digital Archive
	ANNE LANZILOTTA	EDR Digital Archive
2017	PETER LANZILOTTA	Cole Information
2014	MUHAMMED SHAHEEN	Cole Information
	PETER LANZILOTTA	Cole Information

FINDINGS

Year	Uses	Source
2010	MUHAMMED SHAHEEN	Cole Information
	PETER LANZILOTTA	Cole Information
2005	H Lanzilotta A P A	Hill-Donnelly Information Services
	HShaheen M 0 as	Hill-Donnelly Information Services
	EDWARD NUNEZ	Cole Information
	ANNE LANZILOTTA	Cole Information
	CHRISTIAN GARAY	Cole Information
2000	Christian M Garay	Cole Information
	Gladys M Nunez	Cole Information
	C GARAY	Cole Information
	GLADYS NUNEZ	Cole Information
1992	LANZILOTTA, PETER	Cole Information
1991	Jones Leslie	NYNEX Information Resource Company
	Lanzilotta Peter	NYNEX Information Resource Company
1983	Lanziloota Pete	New York Telephone
1976	Donohue Matthew J	New York Telephone
	Lanzilotta Pete	New York Telephone
1970	Donohue Matthew J	New York Telephone
	Lanzilotta Pete	New York Telephone
1967	Donohue Matthew J	New York Telephone
	Lanzilotta Pete	New York Telephone
1962	Donohue Matthew J	New York Telephone Directory
	Lanzilotta Pete	New York Telephone Directory
1945	Donohue Matthew J	New York Telephone
1934	Gademan Albert Margt Gademan Service Station	R. L. Polk & Co.
	Mann John C Janet gas atndt	R. L. Polk & Co.

2309 37TH AVE

Year	Uses	Source
2020	MALLIK DURBAR	EDR Digital Archive
	SAMRAT MAJIMDER	EDR Digital Archive
	KHANDAKER MORSHED	EDR Digital Archive
	NOMAN BHUYAN	EDR Digital Archive

FINDINGS

Year	Uses	Source
2020	MOHAMMAD ALAM	EDR Digital Archive
	ABDULLAH MAMUN	EDR Digital Archive
	MOHAMMED SHAMSUDDIN	EDR Digital Archive
2017	ABDULLAH MAMUN	Cole Information
	NOMAN BHUYAN	Cole Information
2014	MARISOL CARRETO	Cole Information
	NOMAN BHUYAN	Cole Information
	M HOSSAIN	Cole Information
	SECELIA FRANCOUER	Cole Information
2010	ROBERT BROWNE	Cole Information
	MARISOL CARRETO	Cole Information
	LETICIA CAMACHO	Cole Information
	HERBERTO NAVA	Cole Information
	SECELIA FRANCOUER	Cole Information
2005	Camacho Letida	Hill-Donnelly Information Services
	Carreto Marisol	Hill-Donnelly Information Services
	h Francouer Secelia	Hill-Donnelly Information Services
	Souza Jose R	Hill-Donnelly Information Services
	ROBERT BROWNE	Cole Information
	MARTIN FERNANDEZ	Cole Information
	MARISOL CARRETO	Cole Information
	BROWNE ROBERT	Cole Information
	JOSE SOUZA	Cole Information
	HERBERTO NAVA	Cole Information
	JORGE RAMIREZ	Cole Information
	K TENESACA	Cole Information
	NAHUN HERNANDEZ	Cole Information
	SECELIA FRANCOUER	Cole Information
	FELIX PEREZ	Cole Information
2000	Robert Brow ne	Cole Information
	Robert J Brow ne	Cole Information
	Eddie Cerda	Cole Information

FINDINGS

Year	Uses	Source
2000	Martin Fernandez	Cole Information
	Secelia Francouer	Cole Information
	Felix Perez	Cole Information
	Jose R Souz	Cole Information
	MARTIN FERNANDEZ	Cole Information
	ROBERT BROWNE	Cole Information
	EDDIE CERDA	Cole Information
	JOSE SOUZA	Cole Information
	SECELIA FRANCOUER	Cole Information
	FELIX PEREZ	Cole Information
1996	FRANCOUER Secelia	NYNEX
1992	TARCIZIO, ROCHA	Cole Information
	REVELO, CARLOS	Cole Information
	FRANCOUER, SECELIA	Cole Information
	TORRES, ADRIAN	Cole Information
1991	Francouer Secella	NYNEX Information Resource Company
	Tarcizio Rocha	NYNEX Information Resource Company
1976	Lodovici Lodovico	New York Telephone
1962	Lanzilotta Ann M	New York Telephone Directory
1934	Lanzilotta Peter Rose lab	R. L. Polk & Co.
	Sullivan Danl Kath	R. L. Polk & Co.
	Sullivan Philip longshoremn	R. L. Polk & Co.

2311 37TH AVE

Year	Uses	Source
2010	MANUEL NAULA	Cole Information
1976	Beta Maintnce Co Corp industrl paintrs	New York Telephone

2313 37TH AVE

Year	Uses	Source
1991	Engco Imports Inc	NYNEX Information Resource Company
1976	Algene Mfg Corp	New York Telephone
1970	Algene Mfs Corp	New York Telephone
1967	Algene Mfg Corp	New York Telephone

FINDINGS

Year	Uses	Source
1962	Algene Mfg Corp	New York Telephone Directory
	Carter Milchman Exprt Corp	New York Telephone Directory
1945	Uddeholm Co of America Inc w arehse	New York Telephone
1939	Filtermass Mfg Co Inc F	New York Telephone Company

2315 37TH AVE

Year	Uses	Source
2014	PROFESSIONAL SERVICE CENTERS	Cole Information
2010	PROFESSIONAL SERVICES CTR	Cole Information
2005	Professional Services Ctr	Hill-Donnelly Information Services
2000	Prfssnl Svc Cntrs	Cole Information
	PROFESSIONAL SVCE CENTERS	Cole Information

2317 37TH AVE

Year	Uses	Source
1995	RAMA AUTO REPR INC	Cole Information
1991	George Zik Corp	NYNEX Information Resource Company
1967	Stonier Baking Co	New York Telephone
1962	Stonier Baking Co	New York Telephone Directory
1945	Golden Flake Butter Gem Shop	New York Telephone
	Stonier D H bkry	New York Telephone
1939	Skual Baking Co Inc	New York Telephone Company
	Sw edish Baking Co	New York Telephone Company
1934	Skoal Baking Co Inc NY Lincoln Walsh mgr	R. L. Polk & Co.
	United Sw edish Baking Co RTN Dillion Walsh	R. L. Polk & Co.

2319 37TH AVE

Year	Uses	Source
2005	International Geotechnical Lab	Hill-Donnelly Information Services
2000	Phikmi Jhnsn US	Cole Information
	Phikmi Jhnsn US	Cole Information
	PHILKERAM JOHNSON USA	Cole Information
	PHILKERAM JOHNSON USA	Cole Information

FINDINGS

2322 37TH AVE

Year	Uses	Source
2000	Anthony D Katsaras	Cole Information
	E Polimeris	Cole Information
	Infprxs Consltng	Cole Information
	INFOPRAXIS CONSULTING	Cole Information
	ANTHONY KATSARAS	Cole Information
	E POLIMERIS	Cole Information

2324 37TH AVE

Year	Uses	Source
2010	LEON GUERRA	Cole Information
2005	Guerra Leon	Hill-Donnelly Information Services
2000	Amy Kelly	Cole Information
	Noreen Molloy	Cole Information
	NOREEN MOLLOY	Cole Information
	AMY KELLY	Cole Information

2325 37TH AVE

Year	Uses	Source
2005	Tellas John	Hill-Donnelly Information Services
	Tellas John	Hill-Donnelly Information Services
	JOHN TELLAS	Cole Information
2000	John Tellas	Cole Information
	John Tellas	Cole Information
	Panagiotis Zenetos	Cole Information
	Panagiotis Zenetos	Cole Information
	P ZENETOS	Cole Information
	JOHN TELLAS	Cole Information

2328 37TH AVE

Year	Uses	Source
2010	RAFFI JAMGOCIAN	Cole Information
2005	h Johnson Jeff & Cath	Hill-Donnelly Information Services
	Sgantzos Konstantinos	Hill-Donnelly Information Services

Year	Uses	Source
2000	M Chan	Cole Information
	K SGANTZOS	Cole Information
	M CHAN	Cole Information

2329 37TH AVE

Year	Uses	Source
2010	EVANGELIA KOTSIAS-PALMER	Cole Information
2005	Fotiadis G	Hill-Donnelly Information Services
	GEORGIA FOTIADIS	Cole Information
2000	Chris Athanassiou	Cole Information
	G Fotiadis	Cole Information
	CHRIS ATHANASSIOU	Cole Information
	G FOTIADIS	Cole Information

2330 37TH AVE

Year	Uses	Source
2005	Uu Chun Chi	Hill-Donnelly Information Services
	Vassiliou Christos v	Hill-Donnelly Information Services
	EFSTRATIOS MARKAKIS	Cole Information
2000	Metaxia Rorakou	Cole Information
	METAXIA FLORAKOU	Cole Information

2331 37TH AVE

Year	Uses	Source
2010	OSCAR ALMEIDA	Cole Information
2000	Mahamed A Ismais	Cole Information
	Liliane Santos	Cole Information
	LILIANE SANTOS	Cole Information
	SALAH HAMOUDA	Cole Information
	MOHAMED ISMAIS	Cole Information

2332 37TH AVE

Year	Uses	Source
2010	MARIA GUILAS	Cole Information
2005	MARIA GUILAS	Cole Information

FINDINGS

Year	Uses	Source
2000	Eliz A Principe	Cole Information
	JACK ROMAN	Cole Information
	E PRINCIPE	Cole Information

2333 37TH AVE

Year	Uses	Source
2005	ALAN PLEAKIS	Cole Information
2000	Mark Roemer	Cole Information
	D PLEAKIS	Cole Information
	MARK ROEMER	Cole Information

2334 37TH AVE

Year	Uses	Source
2010	EVA RODRIGUEZ	Cole Information
2005	Tadych S	Hill-Donnelly Information Services
	EVA RODRIGUEZ	Cole Information
2000	E Rodriguec	Cole Information
	E RODRIGUEZ	Cole Information

2336 37TH AVE

Year	Uses	Source
2005	Maroulletis C	Hill-Donnelly Information Services
	COSTAS MAROULLETIS	Cole Information
2000	Javier G Lopez	Cole Information
	JAVIER LOPEZ	Cole Information
	ANDREAS VASSILIOU	Cole Information

2337 37TH AVE

Year	Uses	Source
2005	Kesselman Igal	Hill-Donnelly Information Services
2000	A Hartenbach	Cole Information
	A HARTENBACH	Cole Information
	C SAITTA	Cole Information

FINDINGS

2338 37TH AVE

Year	Uses	Source
2005	EBlades Costas D v	Hill-Donnelly Information Services
	DAVID KUTCHER	Cole Information
2000	Jaime Levine	Cole Information
	JAIME LEVINE	Cole Information
	COSTAS ELIADES	Cole Information

2339 37TH AVE

Year	Uses	Source
2005	Mazouz Lahsen	Hill-Donnelly Information Services
2000	ROBERT OSWALD	Cole Information

2341 37TH AVE

Year	Uses	Source
2005	Konnaris An	Hill-Donnelly Information Services
	ANDREAS KONNARIS	Cole Information
2000	ANDREAS KONNARIS	Cole Information
	D KALAMARIS	Cole Information

2342 37TH AVE

Year	Uses	Source
2005	MUSARRAT ZAIDI	Cole Information
2000	Abdul Rashid	Cole Information
	C Vallianos	Cole Information
	ABDUL RASHID	Cole Information
	C VALLIANOS	Cole Information

2343 37TH AVE

Year	Uses	Source
2005	Medvedska Maria v	Hill-Donnelly Information Services
	JOHN KOZUCH	Cole Information
2000	Cheryl Vlahos	Cole Information
	Yovko Voutov	Cole Information
	Sarah Walker	Cole Information
	SARAH WALKER	Cole Information

FINDINGS

Year	Uses	Source
2000	CHERYL VLAHOS	Cole Information

2344 37TH AVE

Year	Uses	Source
2000	K ANTONYSZYN	Cole Information

2347 37TH AVE

Year	Uses	Source
2005	Santagata An	Hill-Donnelly Information Services
2000	Hossam Elbanan	Cole Information
	C Olivan	Cole Information
	C OLIVARI	Cole Information
	HOSSAM ELBANAN	Cole Information

2349 37TH AVE

Year	Uses	Source
2005	Villanueva Robert & Harriet	Hill-Donnelly Information Services
	718728	Hill-Donnelly Information Services
	ROBERT VILLANUEVA	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2350 37TH AVE

Year	Uses	Source
2005	h Khan Pankaj	Hill-Donnelly Information Services
	h Zeaur Rahman	Hill-Donnelly Information Services
	RAHMAN ZEAUR	Cole Information
2000	Pankaj Khan	Cole Information
	RAHMAN ZEAUR	Cole Information
	PANKAJ KHAN	Cole Information

2351 37TH AVE

Year	Uses	Source
2000	Mariana Misetic	Cole Information
	MARIANA MISETIC	Cole Information

FINDINGS

37TH AVE FL 1

1218 37TH AVE FL 1

Year	Uses	Source
2020	RIGOBERTO AVILES	EDR Digital Archive
	TIA POOLER	EDR Digital Archive

37TH AVE FL 2

1218 37TH AVE FL 2

Year	Uses	Source
2020	JOHN BELIVANASKIS	EDR Digital Archive

37TH COLLEGE PT

1333 37TH COLLEGE PT

Year	Uses	Source
1934	Hannigan Richd J carpentry inspr pres BQ	R. L. Polk & Co.

37TH ST

1212 37TH ST

Year	Uses	Source
1934	Borgia Bros Co Inc NY cap $15000 Vincent Carnevale pres treas Rudolph Haas v pres Wm F Sprosser sec	R. L. Polk & Co.

1229 37TH ST

Year	Uses	Source
1934	Homer Mrs Homer Dancing School	R. L. Polk & Co.

1314 37TH ST

Year	Uses	Source
1934	Doonan Lawrence F	R. L. Polk & Co.

1816 37TH ST

Year	Uses	Source
1939	Forlenza Antonio	New York Telephone Company

FINDINGS

1833 37TH ST

Year	Uses	Source
1939	Luhrs John C	New York Telephone Company

1919 37TH ST

Year	Uses	Source
1991	Nittsu New York Inc Household Goods Div	NYNEX Information Resource Company
1983	NIPPON EXPRESS USA INC	New York Telephone
	NITTSU IPPON EXPRESS U S A INC Household Goods Division	New York Telephone

1935 37TH ST

Year	Uses	Source
1970	Cohen Bros trucking	New York Telephone
	Cohen Sol & Co trucking	New York Telephone
	Cohen Sol & Co trucking	New York Telephone
1967	Cohen Bros trukmn	New York Telephone
	Cohen Sol trukmn & warehousemen	New York Telephone
1962	Cohen Bros trukmn	New York Telephone Directory
	Cohen Sol trukmn & warehousemen	New York Telephone Directory

1946 37TH ST

Year	Uses	Source
1991	Joes & Anthonys Pizzeria	NYNEX Information Resource Company

1948 37TH ST

Year	Uses	Source
1991	Shohebs Laundromat	NYNEX Information Resource Company
1976	Courtesy Drugs Inc	New York Telephone

2001 37TH ST

Year	Uses	Source
1945	Batel Alfred b	New York Telephone
	LI Floor Craft Co	New York Telephone
1939	Batel Alfred b	New York Telephone Company
	LI Floor Craft Co	New York Telephone Company

FINDINGS

2002 37TH ST

Year	Uses	Source
1976	Krishnan R G	New York Telephone
1970	Barra Lajos	New York Telephone
1967	Barra Lajos	New York Telephone
1962	Barra Lajos	New York Telephone Directory
1945	Dagress Jas P Jr	New York Telephone

2003 37TH ST

Year	Uses	Source
1939	Mammano Pater	New York Telephone Company

2004 37TH ST

Year	Uses	Source
1991	Brandeis John Jr	NYNEX Information Resource Company
1945	Friedel Chas Jr	New York Telephone

2006 37TH ST

Year	Uses	Source
1991	Bacich Leonard	NYNEX Information Resource Company
1945	Ferris Jas	New York Telephone

2007 37TH ST

Year	Uses	Source
1983	Ralph Robt E	New York Telephone
1970	Ralph Robt E	New York Telephone
1967	Ralph Robt E	New York Telephone
1945	Ralph Robt	New York Telephone

2009 37TH ST

Year	Uses	Source
1970	Simone Anthony	New York Telephone
	Vafa Said	New York Telephone
1967	Simone Anthony	New York Telephone
	Thistleton Frank	New York Telephone
1962	Chrysanthou Chas	New York Telephone Directory

FINDINGS

Year	Uses	Source
1962	Simone Anthonuy	New York Telephone Directory

2010 37TH ST

Year	Uses	Source
1945	Venel Chas	New York Telephone

2011 37TH ST

Year	Uses	Source
1945	Rosen Isidore	New York Telephone
1939	Rosen Isidore	New York Telephone Company

2012 37TH ST

Year	Uses	Source
1991	Wiegelmann W	NYNEX Information Resource Company
1983	Wiegelmann W	New York Telephone
1970	Walter H A	New York Telephone

2014 37TH ST

Year	Uses	Source
1996	FREITAS Andrew	NYNEX

2016 37TH ST

Year	Uses	Source
1945	Feltovic Jos A	New York Telephone

2017 37TH ST

Year	Uses	Source
1939	Maynard Isabel C Mrs	New York Telephone Company

2018 37TH ST

Year	Uses	Source
1970	Payne Thos H	New York Telephone
1945	Fay Jessie M Mrs	New York Telephone
	Scudi John V	New York Telephone
1939	Fay Jessie M Mrs	New York Telephone Company
	Scudi John V	New York Telephone Company

FINDINGS

2020 37TH ST

Year	Uses	Source
1996	FINKELSTEIN Robert	NYNEX
1991	Doogan Francis	NYNEX Information Resource Company
	OKely Aileen Mary	NYNEX Information Resource Company

2021 37TH ST

Year	Uses	Source
1939	Silber Fred	New York Telephone Company

2025 37TH ST

Year	Uses	Source
1945	Weiss Mildred G Mrs	New York Telephone

2026 37TH ST

Year	Uses	Source
1967	Cremin Richd	New York Telephone

2028 37TH ST

Year	Uses	Source
1991	Castellano Anthony	NYNEX Information Resource Company

2030 37TH ST

Year	Uses	Source
1996	FRONIMOS Alexander	NYNEX
1991	Schatz Alfred J	NYNEX Information Resource Company
1976	Goldner Marie C Mrs	New York Telephone
1970	Goldner Marie C Mrs	New York Telephone

2056 37TH ST

Year	Uses	Source
1934	Gleason Jas Annie doormn	R. L. Polk & Co.
	Gleason Lillian sten	R. L. Polk & Co.
	Kreps Oscar Johanna Kreps Shoe Repairing	R. L. Polk & Co.
	Siegler Rose cook	R. L. Polk & Co.

FINDINGS

2058 37TH ST

Year	Uses	Source
1991	Sanchez Edgardo J	NYNEX Information Resource Company
1945	Cervantes Consuelo	New York Telephone
1934	Ward Jas P Euphenia bkpr	R. L. Polk & Co.

2060 37TH ST

Year	Uses	Source
1934	Handy Edw in G cigar mkr	R. L. Polk & Co.
	Handy Edw in R Alice C ferdral govt agt	R. L. Polk & Co.
	New some Robt Helen chauf	R. L. Polk & Co.

2062 37TH ST

Year	Uses	Source
1945	Ianni Rose Mrs	New York Telephone
1934	Leslie Frank Mary radio eng	R. L. Polk & Co.
	Zamello Ralph Louise sta firemn	R. L. Polk & Co.

2066 37TH ST

Year	Uses	Source
1934	Mahoney Wm Marie plstr	R. L. Polk & Co.

2068 37TH ST

Year	Uses	Source
1991	Spilman W J	NYNEX Information Resource Company
1962	Spilman Wm J	New York Telephone Directory
1934	Zacharis Nicholas Mary chef	R. L. Polk & Co.

2070 37TH ST

Year	Uses	Source
1983	Hamaratos George	New York Telephone
1934	Grossman Abr mlnry mfr	R. L. Polk & Co.
	Grossman Louis mlnry mfr	R. L. Polk & Co.
	Karp Philip Rose dress opr	R. L. Polk & Co.
	Saltzman Morris Fanny mlnr	R. L. Polk & Co.

FINDINGS

2110 37TH ST

Year	Uses	Source
1934	Bohn Conrad Gertrude truck dr	R. L. Polk & Co.
	Rohdo Jos Julia w tchmn	R. L. Polk & Co.
	Rohdo Louis Mrs lndry w kr	R. L. Polk & Co.

2112 37TH ST

Year	Uses	Source
1945	Carlucci John	New York Telephone
1934	Laregina Anne clk	R. L. Polk & Co.
	Laregina Anthony Jennie printer	R. L. Polk & Co.
	Laregina Matio	R. L. Polk & Co.

2113 37TH ST

Year	Uses	Source
1934	Bezlrjlan Harry Bessie tailor	R. L. Polk & Co.
	Poehlman Max Gertrude clk	R. L. Polk & Co.

2114 37TH ST

Year	Uses	Source
1945	Koblchuk Frank	New York Telephone
1934	Puglisi Alderice student	R. L. Polk & Co.
	Puglisi Concetto Antoinette real est	R. L. Polk & Co.
	Puglisi Danl student	R. L. Polk & Co.

2115 37TH ST

Year	Uses	Source
1934	Mollayan Geo taxi driver	R. L. Polk & Co.
	Mollayan Harry	R. L. Polk & Co.
	Mollayan Richd slsmn	R. L. Polk & Co.

2116 37TH ST

Year	Uses	Source
1970	Blockow itch John	New York Telephone
1967	Blockow itch John	New York Telephone
1962	Blockow itch John	New York Telephone Directory

FINDINGS

Year	Uses	Source
1934	Koch Marguerita Wid Jacob A embdr	R. L. Polk & Co.

2117 37TH ST

Year	Uses	Source
1934	Comiskey Richd lab DS	R. L. Polk & Co.
	Loughlin Helen investigator	R. L. Polk & Co.
	Loughlin John Nellie prisonkpr	R. L. Polk & Co.

2118 37TH ST

Year	Uses	Source
1945	Masterson Delia Mrs	New York Telephone
1939	Masterson Patk	New York Telephone Company
1934	Masterson Patk F Dehlia police	R. L. Polk & Co.

2119 37TH ST

Year	Uses	Source
1991	Job Alyson	NYNEX Information Resource Company
1934	Franzone Jos Petrina real est	R. L. Polk & Co.

2120 37TH ST

Year	Uses	Source
1991	Gatanas Michael	NYNEX Information Resource Company
1934	Piesback Georglana tel opr	R. L. Polk & Co.
	Piesback John D Elizabeth plmbr	R. L. Polk & Co.

2121 37TH ST

Year	Uses	Source
1962	Jowise Peter F	New York Telephone Directory
1945	Meehan Thos J	New York Telephone
1939	Meehan Thos J	New York Telephone Company
1934	Meehan Thos J Irene truckmn	R. L. Polk & Co.

2122 37TH ST

Year	Uses	Source
1970	Berger Henry	New York Telephone
1967	Berger Henry	New York Telephone

FINDINGS

Year	Uses	Source
1934	Berger Henry Kath restr	R. L. Polk & Co.

2123 37TH ST

Year	Uses	Source
1934	Olivieri Jos Mary oystermn	R. L. Polk & Co.

2124 37TH ST

Year	Uses	Source
1970	Hastings Anna Mrs	New York Telephone
1967	Hastings Anna Mrs	New York Telephone
1962	Hastings Anna Mrs	New York Telephone Directory
1945	Hastings Edw F	New York Telephone
1939	Hastings Edw F	New York Telephone Company
1934	Hastings Edw F Anna electn	R. L. Polk & Co.
	Hastings Mary w id John	R. L. Polk & Co.

2125 37TH ST

Year	Uses	Source
1945	Lempit M	New York Telephone
1939	Lempit M	New York Telephone Company

2126 37TH ST

Year	Uses	Source
1983	Cunningham Wm J	New York Telephone
1976	Cunningham Wm J	New York Telephone
1970	Cunningham Wm J	New York Telephone
1967	Cunningham Wm J	New York Telephone
1934	Hatounian Harry engr	R. L. Polk & Co.
	Hatounian Jack slsmn	R. L. Polk & Co.

2127 37TH ST

Year	Uses	Source
1991	Connolly C C	NYNEX Information Resource Company
1983	Connolly C C	New York Telephone
1976	Connolly C C	New York Telephone
1970	Connolly C C	New York Telephone

FINDINGS

Year	Uses	Source
1967	Connolly C C	New York Telephone
1945	Connolly Cecelia C	New York Telephone
1939	Connolly Cecelia C	New York Telephone Company
1934	Connelly Francis Ana Wtchmn	R. L. Polk & Co.
	Connelly Jas chauf	R. L. Polk & Co.
	Connelly Jos chauf	R. L. Polk & Co.
	Connelly Julia clk	R. L. Polk & Co.

2128 37TH ST

Year	Uses	Source
1934	Carey Anne M tchr	R. L. Polk & Co.
	Carey Wm A Anna v pres Alex Taylor	R. L. Polk & Co.
	Olivieri Paul Rose w aiter	R. L. Polk & Co.

2129 37TH ST

Year	Uses	Source
1939	Homer I Mrs	New York Telephone Company
1934	Welsh Chas Isabella F actor	R. L. Polk & Co.
	Welsh Maude dancing tchr	R. L. Polk & Co.
	Welsh May dancing tchr	R. L. Polk & Co.

2130 37TH ST

Year	Uses	Source
1991	Martins Antonio	NYNEX Information Resource Company
1983	Pavlouvakis Nick	New York Telephone
1967	Moegel H K	New York Telephone
1934	Mc Garry Wm J clk	R. L. Polk & Co.
	Mc Garry Wm P Lillian brklyr	R. L. Polk & Co.
	Ryan Jas printers hlpr	R. L. Polk & Co.

2131 37TH ST

Year	Uses	Source
1934	Carlson Carl Gerda pianomkr	R. L. Polk & Co.

FINDINGS

2132 37TH ST

Year	Uses	Source
1991	Sharma Raj K	NYNEX Information Resource Company
1934	Dampfhofer Alex Gessalla chauf	R. L. Polk & Co.

2133 37TH ST

Year	Uses	Source
1934	Gordon Jas D Frances carp	R. L. Polk & Co.

2134 37TH ST

Year	Uses	Source
1934	Beranek Anna w id Vincent	R. L. Polk & Co.
	Beranek Marie bkpr	R. L. Polk & Co.
	Ulreich Emil Helen w aiter	R. L. Polk & Co.

2135 37TH ST

Year	Uses	Source
1991	Mc Grath Tim	NYNEX Information Resource Company
1983	Shepherd J H	New York Telephone
1970	Rose Robt O	New York Telephone
1945	Rose Robt O	New York Telephone
1939	Rose Robt O	New York Telephone Company
1934	Rose Jas tile str	R. L. Polk & Co.
	Rose Robt Isabelle compositor	R. L. Polk & Co.

2136 37TH ST

Year	Uses	Source
1934	Enderley Frank Kath w aiter	R. L. Polk & Co.
	Enderley Violet student	R. L. Polk & Co.
	Scanlon Ned hotel w kr	R. L. Polk & Co.

2137 37TH ST

Year	Uses	Source
1976	Dalheimer Wm A	New York Telephone
1939	Murphy Margaret M	New York Telephone Company
1934	Murphy John mech	R. L. Polk & Co.

Year	Uses	Source
1934	Murphy John J Mary chauf	R. L. Polk & Co.
	Murphy Margt M tel opr	R. L. Polk & Co.

2138 37TH ST

Year	Uses	Source
1934	Mc Donnell Edw clk	R. L. Polk & Co.
	Mc Donnell Jas Kath	R. L. Polk & Co.
	Mc Donnell Jas clk	R. L. Polk & Co.
	Mc Donnell John student	R. L. Polk & Co.
	Mc Donnell Kath P clk	R. L. Polk & Co.
	Mc Donnell Richd	R. L. Polk & Co.
	Mc Donnell Thos ship clk	R. L. Polk & Co.

2139 37TH ST

Year	Uses	Source
1934	Conroy Michl Mabel stmftr	R. L. Polk & Co.

2140 37TH ST

Year	Uses	Source
1962	Albert Emma T	New York Telephone Directory
1945	Albert Emma T	New York Telephone
1934	Albert Adam F Emma slsmn	R. L. Polk & Co.

2141 37TH ST

Year	Uses	Source
1934	Vaupel Reinbart Lena mach	R. L. Polk & Co.

2142 37TH ST

Year	Uses	Source
1991	Verivakis Nick	NYNEX Information Resource Company
1934	Lynch Bridget drsmkr	R. L. Polk & Co.
	Morrison Grace	R. L. Polk & Co.
	Morrisson Sarah maid	R. L. Polk & Co.

FINDINGS

2143 37TH ST

Year	Uses	Source
1991	Delidimitropulu Vaia	NYNEX Information Resource Company
	DelidImitropulu Vaia	NYNEX Information Resource Company
1983	Middelkoop M F	New York Telephone
1970	Forlano E J	New York Telephone
1967	Forlano E J	New York Telephone
1962	Forlano E J	New York Telephone Directory
1945	Forlano E	New York Telephone
1939	Forlano Louis	New York Telephone Company
1934	Forlano Geo student	R. L. Polk & Co.
	Forlano Louis Nicolina barger	R. L. Polk & Co.
	Forlano Mary sten	R. L. Polk & Co.

2144 37TH ST

Year	Uses	Source
1991	Antoniou Ioannis G	NYNEX Information Resource Company
1934	Mc Carthy Danl Elizabeth paper ctr	R. L. Polk & Co.

2145 37TH ST

Year	Uses	Source
1945	Conlon John W	New York Telephone
1939	Conlon John W	New York Telephone Company
	Conlon Jos G Woodhaven Ri chml 25433	New York Telephone Company
1934	Kluger Harold student	R. L. Polk & Co.
	Kluger Jacob Gussie ins agt	R. L. Polk & Co.
	Kluger Ruth bkpr	R. L. Polk & Co.

2146 37TH ST

Year	Uses	Source
1934	Ulreich Albin clk	R. L. Polk & Co.
	Ulreich Eug clk	R. L. Polk & Co.

2147 37TH ST

Year	Uses	Source
1991	Mcguire A	NYNEX Information Resource Company

FINDINGS

Year	Uses	Source
1934	Urtnowski Jos Josephine mldr	R. L. Polk & Co.

2148 37TH ST

Year	Uses	Source
1934	Petro Anna clk Mhn	R. L. Polk & Co.
	Petro Chas trunk hlpr	R. L. Polk & Co.
	Petro Jas mech	R. L. Polk & Co.
	Petro John J colln clk	R. L. Polk & Co.
	Petro Nicholas slsmn	R. L. Polk & Co.

2149 37TH ST

Year	Uses	Source
1991	Antonioli Paul	NYNEX Information Resource Company
1983	Antonioli Paul	New York Telephone
1976	Antonioli Paul	New York Telephone
1970	Antonioli Paul	New York Telephone
1967	Antonioll Paul	New York Telephone
1962	Antonioli Paul	New York Telephone Directory
1945	Poggio Frank	New York Telephone
1939	Taylor Robt	New York Telephone Company
1934	Taylor John Student	R. L. Polk & Co.
	Taylor Robt Florence caterer	R. L. Polk & Co.

2150 37TH ST

Year	Uses	Source
1962	Fina Michl	New York Telephone Directory
1939	Enersen Wm	New York Telephone Company
1934	Black Alex Jean checker	R. L. Polk & Co.

2151 37TH ST

Year	Uses	Source
1945	Lynam Jas	New York Telephone
1934	Mc Donough Mary	R. L. Polk & Co.
	Mc Donough Patk	R. L. Polk & Co.

FINDINGS

2152 37TH ST

Year	Uses	Source
1934	Christie Jas Margt Indrymn	R. L. Polk & Co.

2153 37TH ST

Year	Uses	Source
1934	Kubec Frank Anna tailor	R. L. Polk & Co.
	Spirek Bdhumil Marie ormn	R. L. Polk & Co.
	Spirek Gerald bkpr	R. L. Polk & Co.

2154 37TH ST

Year	Uses	Source
1967	Garry A	New York Telephone
1962	Garry A	New York Telephone Directory
1945	Garry A	New York Telephone
1939	Garry A	New York Telephone Company
1934	Garry Gertrude clk	R. L. Polk & Co.
	Garry Grace clk	R. L. Polk & Co.
	Garry Lillian tchr	R. L. Polk & Co.
	Garry Louis F clk	R. L. Polk & Co.

2155 37TH ST

Year	Uses	Source
1934	Schmitt Adam Louise slsmn	R. L. Polk & Co.

2156 37TH ST

Year	Uses	Source
1945	Olivet Loretta	New York Telephone
1934	Irving Wm C Dora clk	R. L. Polk & Co.

2157 37TH ST

Year	Uses	Source
1991	Murtha Gerard	NYNEX Information Resource Company
1983	Murtha Gerard	New York Telephone
1934	Cody Robt F Caroline police	R. L. Polk & Co.
	Cook Jos Madeline fctyw kr	R. L. Polk & Co.

FINDINGS

2158 37TH ST

Year	Uses	Source
1983	Kalpakis Milton G	New York Telephone
1934	Wall Micaela vocal tchr	R. L. Polk & Co.
	Wall Robt Mildred w atch repr	R. L. Polk & Co.

2159 37TH ST

Year	Uses	Source
1962	McCarthy Jos J	New York Telephone Directory
1939	Mc Carthy Jos J	New York Telephone Company
1934	Mc Carthy Jos Eva	R. L. Polk & Co.

2160 37TH ST

Year	Uses	Source
1934	Varnay Z	R. L. Polk & Co.
	Varney Alex student	R. L. Polk & Co.
	Varney Lothan Jennie carp	R. L. Polk & Co.
	Varney Wesley student	R. L. Polk & Co.

2161 37TH ST

Year	Uses	Source
1934	Mc Mahon Cornelius pipemn	R. L. Polk & Co.
	Mc Mahon Theresa w id Jas	R. L. Polk & Co.
	Usuriello Zaira: James & Son	R. L. Polk & Co.
	Usuriello Ida bkpr	R. L. Polk & Co.
	Usuriello Vincent Zira barber	R. L. Polk & Co.

2162 37TH ST

Year	Uses	Source
1934	Casey Clarence clk	R. L. Polk & Co.
	Kelly Edw A firemn indprt Dept of Educ	R. L. Polk & Co.
	Kelly Rita student	R. L. Polk & Co.
	Kelly sally clk	R. L. Polk & Co.

FINDINGS

2163 37TH ST

Year	Uses	Source
1945	Tuohy Veronica H	New York Telephone
1934	Casey Jas mech	R. L. Polk & Co.

2164 37TH ST

Year	Uses	Source
1945	Profera Louis	New York Telephone
1939	Profera Louis	New York Telephone Company
1934	Prefere Frank slsmn	R. L. Polk & Co.
	Prefere Louis Louise w tchmn	R. L. Polk & Co.
	Prefere Salvatore garage w kr	R. L. Polk & Co.
	Prefere SAville bkpr	R. L. Polk & Co.
	Profera Louis Louise piano plshr	R. L. Polk & Co.
	Profera SAvio bkpr	R. L. Polk & Co.

2165 37TH ST

Year	Uses	Source
1976	Banner Andrew	New York Telephone
1970	Banner Andrew	New York Telephone
1967	Banner Andrew	New York Telephone
1962	Banner Andrew	New York Telephone Directory
1945	Banner Andrew	New York Telephone
1939	Banner Andrew	New York Telephone Company
1934	Banner Andrew Ethel M mgr Tisdale Cola Co Inc	R. L. Polk & Co.

2166 37TH ST

Year	Uses	Source
1934	Guiffrida Eug berber	R. L. Polk & Co.
	Guiffrida Pater musician	R. L. Polk & Co.
	Guiffrida Vincenza w id Sylvester	R. L. Polk & Co.

2167 37TH ST

Year	Uses	Source
1934	Brejcha Wm Mary	R. L. Polk & Co.

FINDINGS

2168 37TH ST

Year	Uses	Source
1945	Burke Jas	New York Telephone
1934	Burke Jas Josephine chauf	R. L. Polk & Co.
	Casey Helen tel opr	R. L. Polk & Co.
	Cragan Kath w id Jas	R. L. Polk & Co.

2169 37TH ST

Year	Uses	Source
1934	Zeppel Kurt Louise uphol	R. L. Polk & Co.

2170 37TH ST

Year	Uses	Source
1934	Walsh Jas clk	R. L. Polk & Co.
	Walsh John clk	R. L. Polk & Co.
	Walsh Wm file clk	R. L. Polk & Co.
	Walsh Wm Mary lab	R. L. Polk & Co.

2171 37TH ST

Year	Uses	Source
1962	Antonievich Anthony	New York Telephone Directory
1934	Antonievich Anthony baker	R. L. Polk & Co.
	Antonievich Frank chef	R. L. Polk & Co.
	Antonievich Katie M w id Mateo	R. L. Polk & Co.
	Antonievich Zora bkpr	R. L. Polk & Co.

2172 37TH ST

Year	Uses	Source
1934	Manning Mary	R. L. Polk & Co.
	Philbin Marion sten	R. L. Polk & Co.
	Philbin Patk Josephine chauf	R. L. Polk & Co.
	Walsh Anna Mrs	R. L. Polk & Co.

2175 37TH ST

Year	Uses	Source
1934	Heyson Foster Anna stationer	R. L. Polk & Co.

FINDINGS

2176 37TH ST

Year	Uses	Source
1991	Zafiromitsos Alexandros	NYNEX Information Resource Company
1934	Hatounian Yanoff Anna oriental rugs	R. L. Polk & Co.

2178 37TH ST

Year	Uses	Source
1934	Neighborhood Tailor Shop RTN DAvid Gatow	R. L. Polk & Co.

2179 37TH ST

Year	Uses	Source
1934	Scala Ciro Raphaelo fruits and vegetables	R. L. Polk & Co.

2183 37TH ST

Year	Uses	Source
1934	Gordon Elsie	R. L. Polk & Co.

2201 37TH ST

Year	Uses	Source
1962	Schulster Dr J Co	New York Telephone Directory

2205 37TH ST

Year	Uses	Source
1991	Demopoulos Michael	NYNEX Information Resource Company
	Dotsikas A	NYNEX Information Resource Company
	Mousakheel Abdul	NYNEX Information Resource Company
	Singh Dalbara	NYNEX Information Resource Company
	Villalba Elliott	NYNEX Information Resource Company
1983	Conway Stephen	New York Telephone
	Demopoulos Michael	New York Telephone
	Dotsikas A	New York Telephone
	Sarkissian Pedros	New York Telephone
	Toumpouras Constantine	New York Telephone
1976	Conway Stephen	New York Telephone
	Dotsikas Kostas	New York Telephone
	Facatselis John	New York Telephone

FINDINGS

Year	Uses	Source
1970	Boone P Mrs	New York Telephone
	Conway Stephen	New York Telephone
	Ray Felicia Mrs	New York Telephone
1967	Boone P Mrs	New York Telephone
	Conway Stephen	New York Telephone
	Ray Felicia Mrs	New York Telephone
1962	Boone P Mrs	New York Telephone Directory
	Conway Stephen	New York Telephone Directory
	Ray Felicia Mrs	New York Telephone Directory
	Ryan Danl	New York Telephone Directory
1945	Burkart Margaret J Mis	New York Telephone
	Conway Catherine Mrs	New York Telephone
	Ray Edwn	New York Telephone
	Ryan Danl	New York Telephone
1939	Baden Frances Mrs	New York Telephone Company
	Bowers Florence Mrs	New York Telephone Company
	Ray Edwin	New York Telephone Company
	Souran Christ	New York Telephone Company
1934	Allen Raphael C Helen acct	R. L. Polk & Co.
	Bailey Sylvia opr	R. L. Polk & Co.
	Barnwell John Josephine plmbr	R. L. Polk & Co.
	Biederman Edw Gertrude teller	R. L. Polk & Co.
	Bingham Paul	R. L. Polk & Co.
	Dillmuth Wm leather belt mkr	R. L. Polk & Co.
	Ferber Jacob Fannie mattresemkr	R. L. Polk & Co.
	Fitzgerald Cath Mrs	R. L. Polk & Co.
	Gatow DAvid Bessie Neighborhood Tailor Shop	R. L. Polk & Co.
	Gonzales Albilene Theresa cabtmkr	R. L. Polk & Co.
	Gretchel Adolph real est	R. L. Polk & Co.
	Kaffen Irving Anna Hy Grade Meat & Polutry Mkt	R. L. Polk & Co.
	La Testa Vito	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Lindsay Chas V Charlotte blr clnr Bx	R. L. Polk & Co.
	Lopez Domingo Franceas pntr	R. L. Polk & Co.
	Mackey Saml Emily lab	R. L. Polk & Co.
	Marzano Dominick Anna mgr Mhn	R. L. Polk & Co.
	Marzano Jos L student	R. L. Polk & Co.
	Masters Annie w id Jas	R. L. Polk & Co.
	Masters Edw H V exmnr	R. L. Polk & Co.
	Modesti Bruno clk	R. L. Polk & Co.
	Modesti Tito Mary cigar mkr	R. L. Polk & Co.
	Murphy Thos Margt formn	R. L. Polk & Co.
	Samuels Eli Alice photog	R. L. Polk & Co.
	SAvina Court apt bldg	R. L. Polk & Co.
	Schlaefer Waiter J Mildred clk Mhn	R. L. Polk & Co.
	Schuneman Otto Blanche: Boulevard Pet Shop	R. L. Polk & Co.
	Slafer Waller J Mildred C clk	R. L. Polk & Co.
	Tarre Emil Flora barber	R. L. Polk & Co.
	Telvin Francis X Cath policemn	R. L. Polk & Co.
	Ward Wm L Carrie carp	R. L. Polk & Co.

2207 37TH ST

Year	Uses	Source
1934	Lindberg Emma	R. L. Polk & Co.

2208 37TH ST

Year	Uses	Source
1991	Winer Arthur	NYNEX Information Resource Company
1970	Malvarosa C	New York Telephone
1967	Malvarosa C	New York Telephone
1962	Malvarosa C	New York Telephone Directory
1945	Rother Jos	New York Telephone
1934	Bloom Benj Rose dry gds	R. L. Polk & Co.
	Bloom Julia E ston	R. L. Polk & Co.
	Lentz Geo chauf	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Lentz Henry	R. L. Polk & Co.
	Lentz Marie slsw n	R. L. Polk & Co.
	Lentz Steph	R. L. Polk & Co.

2211 37TH ST

Year	Uses	Source
1991	Haeno Yoko	NYNEX Information Resource Company
	Mcdonnell Mark	NYNEX Information Resource Company
1939	Bartha N Paul MD	New York Telephone Company
1934	Bartha Edna designer	R. L. Polk & Co.
	Bartha Francis slsmn Mhn	R. L. Polk & Co.
	Bartha Helen w id Alex	R. L. Polk & Co.
	Bartha Julia designer	R. L. Polk & Co.
	Bartha Margt beader Mhn	R. L. Polk & Co.
	Bartha Steph buyer	R. L. Polk & Co.

2212 37TH ST

Year	Uses	Source
1934	Beyer Geo Edna M com art	R. L. Polk & Co.
	Fischer Geo Mathilda expmn	R. L. Polk & Co.
	Weick Fredk Isabel mach	R. L. Polk & Co.

2213 37TH ST

Year	Uses	Source
1991	Miranda Sandra	NYNEX Information Resource Company
1945	Genovese Anthony	New York Telephone
1934	Portenza Benj	R. L. Polk & Co.
	Portenza Dominick Mary boothlack	R. L. Polk & Co.
	Portenza John	R. L. Polk & Co.
	Weiss Adolph Bella clothing	R. L. Polk & Co.
	Weiss Eleanor student	R. L. Polk & Co.
	Weiss Jesse slsmn	R. L. Polk & Co.

FINDINGS

2214 37TH ST

Year	Uses	Source
1970	Facciponti Joan	New York Telephone
	Facciponti Lena I	New York Telephone
1967	Facciponti Lelia I	New York Telephone
	Manis Gus	New York Telephone
1945	Williams Katherine H Mrs	New York Telephone
1934	Reed Jas E Mary guard	R. L. Polk & Co.
	Williams Vernard E Kath prsmn	R. L. Polk & Co.

2215 37TH ST

Year	Uses	Source
1934	Dubak Julius Fannie	R. L. Polk & Co.

2217 37TH ST

Year	Uses	Source
1934	Blaustein Dorothy bkpr	R. L. Polk & Co.
	Blaustein Esther nurse	R. L. Polk & Co.
	Blaustein Louis Anna harness mkr	R. L. Polk & Co.
	Blaustein Sarah tchr	R. L. Polk & Co.

2218 37TH ST

Year	Uses	Source
1991	Dechkounian Roupen	NYNEX Information Resource Company
1945	Smith Geo R	New York Telephone
1939	Smith Geo R	New York Telephone Company
1934	Carlson Oscar Alma chauf	R. L. Polk & Co.
	Swenson Christine wid Gus	R. L. Polk & Co.
	Swenson Dagne clk	R. L. Polk & Co.
	Tuttle Lester Elsie	R. L. Polk & Co.

2219 37TH ST

Year	Uses	Source
1991	Belli Vincent	NYNEX Information Resource Company
1983	Belli Vincent	New York Telephone
1976	Belli Vincent	New York Telephone

FINDINGS

Year	Uses	Source
1970	Belli Vincent	New York Telephone
1967	Belli Vincent	New York Telephone
1962	Belli Vincent	New York Telephone Directory
1945	Belli Vincent	New York Telephone
1939	Belli V excavtr	New York Telephone Company
	Grand Constn Corpn	New York Telephone Company
1934	Belli Angelina sten	R. L. Polk & Co.
	Belli Theresa	R. L. Polk & Co.
	Belli Vincent Elizabetha	R. L. Polk & Co.
	Belli Vincent Grand Construction Co	R. L. Polk & Co.
	Belli Wm G eng asst Bd W S	R. L. Polk & Co.
	Grand Construction Co Vincent Belli exc Avating	R. L. Polk & Co.
	Sullivan Harry P Anna mtrmn	R. L. Polk & Co.

2220 37TH ST

Year	Uses	Source
1939	Dorman Morris	New York Telephone Company
1934	DAvis Henry Annie	R. L. Polk & Co.
	Dorman Morris Rose Dorman Bros	R. L. Polk & Co.
	Fried Max slsmn	R. L. Polk & Co.
	Hirsch Casper Bessie slsmn	R. L. Polk & Co.

2221 37TH ST

Year	Uses	Source
1983	Pirrone Vito	New York Telephone
1945	Langer Geo	New York Telephone
1939	Langer Geo	New York Telephone Company
	Smith Catherine F	New York Telephone Company
	Steinberger E	New York Telephone Company
1934	Kampmann Fredk Antonette carp	R. L. Polk & Co.
	Langer Geo Nellie projectionist	R. L. Polk & Co.
	Langstaff Edw clk Mhn	R. L. Polk & Co.
	Lipare Dominick paper box mkr	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Lipare Lena mkr	R. L. Polk & Co.
	Mallozzi Chas musician	R. L. Polk & Co.
	Smith Cath J tel opr	R. L. Polk & Co.

2222 37TH ST

Year	Uses	Source
1934	Lee Cristopher J Sheila clk Mhn	R. L. Polk & Co.
	Lee Maureen ins agt	R. L. Polk & Co.
	Lee Sheila clk	R. L. Polk & Co.
	Vaupel Ernest Julia slsmn	R. L. Polk & Co.

2223 37TH ST

Year	Uses	Source
1991	Legas Chris	NYNEX Information Resource Company
1983	Legas Chris	New York Telephone
1976	Legas Chris	New York Telephone
1970	Legas Chris	New York Telephone
	Legas Geo	New York Telephone
1967	Legas Chris	New York Telephone
	Legas Geo	New York Telephone
1962	Legas Chris	New York Telephone Directory
1939	Staciva Stanley M D	New York Telephone Company
1934	Basta Frank auto mech	R. L. Polk & Co.
	Koster Wm F Harriet asst supt	R. L. Polk & Co.
	Pisan Anthony Elsie brklyrh	R. L. Polk & Co.
	Van Cura Edw	R. L. Polk & Co.

2224 37TH ST

Year	Uses	Source
1991	Gould Andrew	NYNEX Information Resource Company
	Orenstein May atty	NYNEX Information Resource Company
	Orenstein N	NYNEX Information Resource Company
1962	Lang Saml	New York Telephone Directory
1945	Fredericks Solon	New York Telephone

FINDINGS

Year	Uses	Source
1939	Fredericks S	New York Telephone Company
1934	Fredericks Solon Emma furrier	R. L. Polk & Co.
	Rothschild Anna Wid Nathan	R. L. Polk & Co.
	Stein Aaron dish washer	R. L. Polk & Co.
	Stein Henrietta clk	R. L. Polk & Co.

2227 37TH ST

Year	Uses	Source
1934	Gottlieb Edw	R. L. Polk & Co.
	Gottlieb Florence	R. L. Polk & Co.
	Gottlieb Max Esther	R. L. Polk & Co.
	Gottlieb Max Esther neckwear	R. L. Polk & Co.
	Weiss Louis Diana clnr	R. L. Polk & Co.

2228 37TH ST

Year	Uses	Source
1934	De Guire Emma	R. L. Polk & Co.
	De Guira Emma	R. L. Polk & Co.
	Gray Chas A	R. L. Polk & Co.
	Moquin Alf Margt music arranger	R. L. Polk & Co.
	Strenk John Krestina	R. L. Polk & Co.
	Strenk Krestina midwife	R. L. Polk & Co.
	Strenk Tessie wid Anthony	R. L. Polk & Co.

2229 37TH ST

Year	Uses	Source
1976	Geta Chas	New York Telephone
1970	Gafa Chas	New York Telephone
1967	Gafa Chas	New York Telephone
1962	Gafa Chas	New York Telephone Directory
1945	Cronin John C	New York Telephone
1939	Rescigno Jos	New York Telephone Company
1934	Genaro Jos Bertha garage	R. L. Polk & Co.
	Spatny Chas Rose carp	R. L. Polk & Co.

FINDINGS

2230 37TH ST

Year	Uses	Source
1970	Quoma Mary	New York Telephone
1967	Quoma Mary	New York Telephone
1962	Quoma Mary	New York Telephone Directory
1934	Friedborg Anna Mrs tailor	R. L. Polk & Co.
	Friedborg Herman clk	R. L. Polk & Co.
	Friedborg Milton Anna checker	R. L. Polk & Co.
	Gross Eannie w id Louis	R. L. Polk & Co.
	Tew el Ruht slsw n	R. L. Polk & Co.

2231 37TH ST

Year	Uses	Source
1991	Gambino Thomas	NYNEX Information Resource Company
1976	Collins Edw Jos	New York Telephone
1970	Collins Edw Jos	New York Telephone
	Russell Anna	New York Telephone
1967	Collins Edw Jos	New York Telephone
	Gagel Edw R	New York Telephone
1962	Gagel Edw R	New York Telephone Directory
1945	Collins Edw Jos	New York Telephone
1939	Collins Edw Jos	New York Telephone Company
1934	Collins Edw J Elizabeth clk	R. L. Polk & Co.
	Lipare Jos clk	R. L. Polk & Co.
	Lyman John	R. L. Polk & Co.
	Lyman Margt w id John	R. L. Polk & Co.

2233 37TH ST

Year	Uses	Source
1934	Dorsey Elizabeth clk	R. L. Polk & Co.
	Dorsey John	R. L. Polk & Co.
	Dorsey Jos	R. L. Polk & Co.
	Giannone Antoinette	R. L. Polk & Co.
	Giannone Cath	R. L. Polk & Co.
	Giannone Michl printer	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Giannone Rocco G Marion A barber	R. L. Polk & Co.

2234 37TH ST

Year	Uses	Source
1939	Buchhart Prosper Wm	New York Telephone Company
1934	Hoyle Herbert Madeline elec eng	R. L. Polk & Co.
	Smith Helen F w id Frank tel opr	R. L. Polk & Co.

2236 37TH ST

Year	Uses	Source
1939	Geduldig Benj	New York Telephone Company
1934	Featherstone Ethel sten	R. L. Polk & Co.
	Featherstone Geo F Mary	R. L. Polk & Co.
	Featherstone How ard servicemn	R. L. Polk & Co.
	Hosmer Dorothy Mrs	R. L. Polk & Co.
	Wolf Wm W Clara slsmn	R. L. Polk & Co.
	Wolfe Wm W Myrtle slsmn	R. L. Polk & Co.
	Young Louis C Florence slsmn	R. L. Polk & Co.

2237 37TH ST

Year	Uses	Source
1983	Linarello Alexndr Sr	New York Telephone
1970	Lamb Thos A	New York Telephone
1967	Lamb Thos A	New York Telephone
	Olsen Lauritz	New York Telephone
1962	Lamb Wm J	New York Telephone Directory
	Olsen Lauritz	New York Telephone Directory
1945	Comerford Thos F	New York Telephone
	Residence	New York Telephone
1939	Comerford Thos F	New York Telephone Company
1934	Flynn Wm J Irene supt	R. L. Polk & Co.
	Lamb Thos A Bridle	R. L. Polk & Co.

FINDINGS

2238 37TH ST

Year	Uses	Source
1970	Fischer Julius	New York Telephone
	Sussman Irving	New York Telephone
1967	Fischer Julius	New York Telephone
	Sussman Irving	New York Telephone
1962	Fischer Julius	New York Telephone Directory
	Sussman Irving	New York Telephone Directory
1945	Fischer Julius	New York Telephone
	May Jerrolde L	New York Telephone
	May Leo	New York Telephone
1939	May Jerrolde L	New York Telephone Company
	May Leo	New York Telephone Company
	May Lewis H Co rl est & ins Sta Plaza FA r Rock 70060	New York Telephone Company
	May Lewis H Co rl est ins Sta Plaza FA r Rock 78682	New York Telephone Company
1934	Baylere Augustin Clara clk	R. L. Polk & Co.
	Fischer Wm student	R. L. Polk & Co.

2239 37TH ST

Year	Uses	Source
1934	Constantinides Nicholas Despina printer Mhn	R. L. Polk & Co.
	Kacamburas Chas Cath fruits	R. L. Polk & Co.

2240 37TH ST

Year	Uses	Source
1934	Freiwirth Bertha wid Max	R. L. Polk & Co.
	Freiwirth Pual Dorothy plmbr	R. L. Polk & Co.

2241 37TH ST

Year	Uses	Source
1991	Harrell L D	NYNEX Information Resource Company
1983	Fanola Gabi	New York Telephone
1962	Auer Wm	New York Telephone Directory
1945	Auer Wm	New York Telephone

FINDINGS

Year	Uses	Source
1939	Auer Wm	New York Telephone Company
	Haas John	New York Telephone Company
1934	Auer Mary sten	R. L. Polk & Co.
	Auer Wm Mary meat ctr	R. L. Polk & Co.
	Auer Wm jr meat ctr	R. L. Polk & Co.

2242 37TH ST

Year	Uses	Source
1976	Giachetti John	New York Telephone
1945	Bauerschmidt Wm	New York Telephone
1939	Lentz Geo	New York Telephone Company
	Lentz Paul	New York Telephone Company

2243 37TH ST

Year	Uses	Source
1945	OConnor Danl F	New York Telephone
1934	Goodman Robt E probation ofcr Courts	R. L. Polk & Co.
	Huneke Karl Erna br mgr H C Bohack Co Inc	R. L. Polk & Co.
	Klaus Walter Dora tinsmith	R. L. Polk & Co.

2244 37TH ST

Year	Uses	Source
1991	Hillen D	NYNEX Information Resource Company
	Jacobson Linda	NYNEX Information Resource Company
	Levengood Edward C	NYNEX Information Resource Company
	Spasc Petar	NYNEX Information Resource Company
1967	Bickmann Edw	New York Telephone
1962	Bickmann Edw	New York Telephone Directory
1945	Bickmann Edw	New York Telephone
	Ess Anton	New York Telephone
1939	Bickmann Edw	New York Telephone Company
	Ess Anton	New York Telephone Company
1934	Ess Adelaide designer Mhn	R. L. Polk & Co.
	Ess Anton Loretta probation officer Courts	R. L. Polk & Co.

FINDINGS

2247 37TH ST

Year	Uses	Source
1983	Hoffmann Gottfried C	New York Telephone
1976	Hoffmann Gottfried C	New York Telephone
1970	Hoffmann Gottfried C	New York Telephone
1967	Hoffmann Gottfried C	New York Telephone
1962	Hoffmann Gottfried C	New York Telephone Directory
1945	Hoffmann Gottfried C	New York Telephone
1939	Guckenberger Aug F	New York Telephone Company
	Hoffmann Gottfried C	New York Telephone Company
1934	Hoffman Amelia bkpr Mhn	R. L. Polk & Co.
	Hoffman Gottfreid C lda slsmn	R. L. Polk & Co.

2248 37TH ST

Year	Uses	Source
1991	Gatzotias Zisis	NYNEX Information Resource Company
	Sherman Glenn	NYNEX Information Resource Company
1970	Rudolph Andrew J Jr	New York Telephone
1967	Rudolph A J	New York Telephone
	Rudolph Andrew J Jr	New York Telephone
1962	Rudolph Andrew J Jr	New York Telephone Directory
1939	Rudolph A J	New York Telephone Company
	Tie Jos	New York Telephone Company
1934	Rudolph Andrew J Susan N slsmn	R. L. Polk & Co.
	Rudolph Andrew J jr clk	R. L. Polk & Co.
	Schoke Franz w aiter	R. L. Polk & Co.
	Wylie Anna w id Saml	R. L. Polk & Co.
	Wylie Helen	R. L. Polk & Co.
	Wylie Minnie supvr	R. L. Polk & Co.

2249 37TH ST

Year	Uses	Source
1945	Rudolph A J	New York Telephone
1934	Hubner Jos Emma slsmn	R. L. Polk & Co.
	Lombard Thos Janet contr	R. L. Polk & Co.

FINDINGS

2250 37TH ST

Year	Uses	Source
1934	Barretta Jos Mary embr Mhn	R. L. Polk & Co.
	Nespole Louise	R. L. Polk & Co.
	Nespole Michl Theresa slsmn	R. L. Polk & Co.
	Van Dugteren Arnold Anna	R. L. Polk & Co.
	Van Tella Chas Theresa meat dept mgr H C Bohack Co Inc	R. L. Polk & Co.

2251 37TH ST

Year	Uses	Source
1962	Kalench John	New York Telephone Directory
1945	Kalench John	New York Telephone
	Smith Lillian Mrs	New York Telephone
1934	Dubak Nicholas J L clk	R. L. Polk & Co.
	La Rosa Anthony	R. L. Polk & Co.

2253 37TH ST

Year	Uses	Source
1962	OShea Timothy J	New York Telephone Directory
	Schnuerle Johanna	New York Telephone Directory
1945	OShea Timiothy J	New York Telephone
	Schnuerle August	New York Telephone
1939	Schnuerle August	New York Telephone Company
1934	Bruce Agnes tel opr	R. L. Polk & Co.
	Comunale Nicholas Adeline asst mgr Met Life	R. L. Polk & Co.
	Pulis Allan	R. L. Polk & Co.
	Richards Arth Cath hlpr	R. L. Polk & Co.

2254 37TH ST

Year	Uses	Source
1967	Cautela Mary Mrs	New York Telephone
1962	Gunst Robt	New York Telephone Directory
1945	Cautela Felix	New York Telephone
1939	Cautela Fellx	New York Telephone Company

Year	Uses	Source
1934	Carch Michl tailor	R. L. Polk & Co.

2256 37TH ST

Year	Uses	Source
1983	Kelly Robt P	New York Telephone
1976	Kelly Robt P	New York Telephone
1970	Kelly Robt P	New York Telephone
	Roesch Edw A Jr	New York Telephone
1967	Kelly Robt P	New York Telephone
	Roesch Edw A Jr	New York Telephone
1962	Kelly Angelina E Mrs	New York Telephone Directory
	Roesch Edw A Jr	New York Telephone Directory
1945	Roesch Edw A	New York Telephone
1934	Doty Lew is Marie mgr	R. L. Polk & Co.

2257 37TH ST

Year	Uses	Source
1970	Macropoulos Gust T	New York Telephone
1934	Marchelos Chas Matilda dish w ahser	R. L. Polk & Co.

2258 37TH ST

Year	Uses	Source
1976	Cohen Jerry	New York Telephone
1934	Kunte Anna w id John	R. L. Polk & Co.
	Kutman Terry Helen elec eng	R. L. Polk & Co.
	Serrio Leonardo Lena brklyr	R. L. Polk & Co.

2259 37TH ST

Year	Uses	Source
1991	Balducci Frank	NYNEX Information Resource Company
	Schupan Rose E	NYNEX Information Resource Company
1983	Schupan Rose E	New York Telephone
1970	Schupak Rose E	New York Telephone
1967	Schupan Rose E	New York Telephone
1962	Schupan Rose E	New York Telephone Directory

FINDINGS

Year	Uses	Source
1945	Shimmerlik Geo	New York Telephone
	Shimmerlik L Miss M D	New York Telephone
1939	Shimmerlik L Miss MD	New York Telephone Company
	Simak Geo	New York Telephone Company
1934	Di Fruscio Marco uphol	R. L. Polk & Co.

2260 37TH ST

Year	Uses	Source
1991	Tangari Rose	NYNEX Information Resource Company
1983	Tangari Mike	New York Telephone
1970	Tangari Mike	New York Telephone
1967	Tangari Mike	New York Telephone
1962	Tangari Mike	New York Telephone Directory
1939	Karcasinas Stephen	New York Telephone Company
1934	Irving J Florence clk	R. L. Polk & Co.
	Riggie Cop Anna genl contr	R. L. Polk & Co.

2261 37TH ST

Year	Uses	Source
1991	Lissauer J M	NYNEX Information Resource Company
1934	Di Frucio Tulic Mary barber	R. L. Polk & Co.
	Schoor Alex student	R. L. Polk & Co.
	Schoor Jean clk	R. L. Polk & Co.
	Schoor Oscar slsmn	R. L. Polk & Co.
	Schoor Saml Augusta	R. L. Polk & Co.
	Schoor Sarah	R. L. Polk & Co.
	Vitaglione Mary slsw n F W Woolw orth Co	R. L. Polk & Co.
	Vitale Jas Concetta	R. L. Polk & Co.

2263 37TH ST

Year	Uses	Source
1945	Rebbo Frank	New York Telephone
1939	Rebbo Frank	New York Telephone Company
1934	Kalench John Elsie slsmn	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Rebbo Anna slsw n	R. L. Polk & Co.
	Rebbo Frank Pauline elev opr	R. L. Polk & Co.

2264 37TH ST

Year	Uses	Source
1934	Destefano Michl Helen music tchr	R. L. Polk & Co.

2265 37TH ST

Year	Uses	Source
1991	Mancuso Jos	NYNEX Information Resource Company
1983	Mancuso Jos	New York Telephone
1970	Mancuso Jos	New York Telephone
1967	Mancuso Jos	New York Telephone
1962	Mancuso Jos	New York Telephone Directory
1934	Cannite Frank Rose mach	R. L. Polk & Co.
	Mirabella Aug Camella barber	R. L. Polk & Co.

2266 37TH ST

Year	Uses	Source
1945	Stone Jas	New York Telephone
1934	Demo Emanuel Bessie chef Mhn	R. L. Polk & Co.
	Demo Jas	R. L. Polk & Co.
	Honig Herman slsmn	R. L. Polk & Co.
	Honig Louis slsmn	R. L. Polk & Co.
	Honig Max Rae dry gds	R. L. Polk & Co.
	Honig Saml E Edith real est	R. L. Polk & Co.

2267 37TH ST

Year	Uses	Source
1945	Blumenblatt Thelma	New York Telephone
	Shapiro Gertrude A	New York Telephone
	Shapiro Jacob	New York Telephone
1939	Shapiro Jacob	New York Telephone Company
1934	Kaplan Helen	R. L. Polk & Co.
	Shapiro Harry Student	R. L. Polk & Co.

FINDINGS

2270 37TH ST

Year	Uses	Source
1945	Connors Cornelius V	New York Telephone
	Connors John J	New York Telephone
	Frank B Miss	New York Telephone
1939	Connors Cornelius V	New York Telephone Company
	Connors John J	New York Telephone Company
	Frank B Miss	New York Telephone Company
1934	Frank Belle bead w kr	R. L. Polk & Co.
	Leone Michl Mary chauf	R. L. Polk & Co.
	Pottor Chas Helen taxi drive	R. L. Polk & Co.
	Profera Jasper Mary hlpr	R. L. Polk & Co.

2272 37TH ST

Year	Uses	Source
1976	Festo Jos	New York Telephone
1967	Festo Jos	New York Telephone
1962	Festo Jos	New York Telephone Directory
1934	Festo Michl Laura lab	R. L. Polk & Co.
	Valentine Achfiles Frances lab	R. L. Polk & Co.

2281 37TH ST

Year	Uses	Source
1991	Garcia Juan	NYNEX Information Resource Company
	Scotto Michl	NYNEX Information Resource Company
1983	Scotto Michl	New York Telephone
1970	Scotto Michl	New York Telephone
1967	Horvath Isabelle H	New York Telephone
	McKenna Virginia C	New York Telephone
1962	Horvath Isabelle H	New York Telephone Directory
1939	Kranker Jos	New York Telephone Company
1934	Farrell Jos T Anna taxi	R. L. Polk & Co.
	Farrell Jos T jr clk	R. L. Polk & Co.
	Ford Jas J Irene city police	R. L. Polk & Co.
	Hageman Geo F Elsie caterer	R. L. Polk & Co.

Year	Uses	Source
1934	Paradise How ard G Martha acct	R. L. Polk & Co.
	Sartorio Louis Susanne supt	R. L. Polk & Co.
	Vago Oscar Claire slsmn	R. L. Polk & Co.
	Weissmann Chas Hani tinsmith	R. L. Polk & Co.
	Weissmann Josephine beautician	R. L. Polk & Co.
	Young Arth Anna meat ctr	R. L. Polk & Co.

2295 37TH ST

Year	Uses	Source
1934	Mausler Chas H Gertrude carrier PO	R. L. Polk & Co.

2303 37TH ST

Year	Uses	Source
1970	Wysocki Mary Mrs	New York Telephone

2313 37TH ST

Year	Uses	Source
1962	Koutsouras Stavros	New York Telephone Directory

2318 37TH ST

Year	Uses	Source
1934	Luhrs Luhrs Cath sten	R. L. Polk & Co.

2322 37TH ST

Year	Uses	Source
1934	Indof Edw fcty w kr	R. L. Polk & Co.
	Indof Mary w id Valentine	R. L. Polk & Co.
	Jackman Harry Lena brklyr	R. L. Polk & Co.
	Kiely Jack Mary	R. L. Polk & Co.

2324 37TH ST

Year	Uses	Source
1976	Czurylow ski Julius	New York Telephone
1934	Burke Jas Sarah bellmn	R. L. Polk & Co.

FINDINGS

2325 37TH ST

Year	Uses	Source
1976	Fischetti M	New York Telephone

2327 37TH ST

Year	Uses	Source
1962	Maguire Jas J	New York Telephone Directory
1945	Barberich Jos F	New York Telephone

2328 37TH ST

Year	Uses	Source
1991	Bouras Nickolaos	NYNEX Information Resource Company
	Sgantzos Konstantinos	NYNEX Information Resource Company
1934	Caldrona Sadie w id Jos	R. L. Polk & Co.
	Caruso Jacob Anna lab	R. L. Polk & Co.
	Tow ens Wm Anna M chauf	R. L. Polk & Co.

2329 37TH ST

Year	Uses	Source
1976	Kotsias Vasilios	New York Telephone
1967	Kotsias Vasilios	New York Telephone

2330 37TH ST

Year	Uses	Source
1991	Papastamatiou Nick	NYNEX Information Resource Company
	Rouvas Vasiliki Vivian	NYNEX Information Resource Company
1970	Bello Max	New York Telephone
	Xuereb Anthony	New York Telephone
1967	Xuereb Anthony	New York Telephone
1962	Xuereb Anthony	New York Telephone Directory
1945	Reynolds Rose Mrs	New York Telephone
1939	Reynolds Mary Mrs	New York Telephone Company
1934	Brandalick Martin Mary clk	R. L. Polk & Co.
	Reynolds Mary w id Thos A	R. L. Polk & Co.

FINDINGS

2331 37TH ST

Year	Uses	Source
1983	Iannece Vincent	New York Telephone
	Verde Antimo	New York Telephone
1970	Guinto E	New York Telephone
1945	Rozemberk Wm	New York Telephone
1934	Hilken Nellie w id John	R. L. Polk & Co.
	Novak Chas electn	R. L. Polk & Co.
	Novak Mary Mrs hsew kr	R. L. Polk & Co.
	Pospisil chas stone ctr	R. L. Polk & Co.
	Pospisil Jacob Carolyn stone ctr	R. L. Polk & Co.
	Schmidt Wm Della clk	R. L. Polk & Co.
	Wajsocher Jos Anna tailor	R. L. Polk & Co.

2332 37TH ST

Year	Uses	Source
1991	Khani Alireza	NYNEX Information Resource Company
1970	Walker Geo A	New York Telephone
1967	Walker Geo A	New York Telephone
1962	Walker Geo A	New York Telephone Directory
1934	Walker Ethel clk	R. L. Polk & Co.
	Walker Geo clk	R. L. Polk & Co.
	Walker John Mary	R. L. Polk & Co.
	Walker John jr clk	R. L. Polk & Co.

2333 37TH ST

Year	Uses	Source
1991	Pleakis Dominick	NYNEX Information Resource Company
1983	Benedetto Felice	New York Telephone
	Pleakis Dominick	New York Telephone
1970	Pleakis Dominick	New York Telephone
1967	Pleakis Dominick	New York Telephone
1962	Pleakis Dominick	New York Telephone Directory
1934	Messier Arth L Julia gasoline	R. L. Polk & Co.
	Pleakis Domenick Madeline lab	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Valencuich Alex Susan w aiter	R. L. Polk & Co.

2334 37TH ST

Year	Uses	Source
1967	Albanides Anagnostin	New York Telephone
1934	Cook Geo clk	R. L. Polk & Co.
	Cook John	R. L. Polk & Co.
	Cook Mary	R. L. Polk & Co.
	Cook Wm	R. L. Polk & Co.

2336 37TH ST

Year	Uses	Source
1991	Maroulletis Florentia	NYNEX Information Resource Company
	Schuck Maria Mrs	NYNEX Information Resource Company

2337 37TH ST

Year	Uses	Source
1991	Saitta C	NYNEX Information Resource Company
1983	Saitta Alfonso Jr	New York Telephone

2339 37TH ST

Year	Uses	Source
1970	Cruz Carlos	New York Telephone

2340 37TH ST

Year	Uses	Source
1962	West Horace K	New York Telephone Directory
1934	Bakley John student	R. L. Polk & Co.
	Sheehan Jos Tillie lab	R. L. Polk & Co.

2341 37TH ST

Year	Uses	Source
1945	Sinnott Richd	New York Telephone
1939	Sinnott Richd	New York Telephone Company
1934	Coyne John restrw kr	R. L. Polk & Co.
	Gaynor Rose w id Jas	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Stanker Henrietta	R. L. Polk & Co.

2343 37TH ST

Year	Uses	Source
1976	Giorgos Panagiotes	New York Telephone
1939	Piazza Jas	New York Telephone Company
1934	Bonanno John J Kath boat bldr	R. L. Polk & Co.
	Flynn Jos Helen custom insnr	R. L. Polk & Co.
	Weber Harry Rose ins agt	R. L. Polk & Co.

2344 37TH ST

Year	Uses	Source
1991	Antonyszyn Kataryna	NYNEX Information Resource Company
	Brown Linda C	NYNEX Information Resource Company
1983	Antonysxyn Kataryna	New York Telephone
1976	Antonyszyn Kataryna	New York Telephone
1934	Elian Wm Anna porter	R. L. Polk & Co.

2347 37TH ST

Year	Uses	Source
1996	FIGUEROA Nelson	NYNEX
1991	Olivari C	NYNEX Information Resource Company
1983	Olivari A M	New York Telephone
	Santogade F	New York Telephone
1967	Santogade F	New York Telephone
1962	Santogade F	New York Telephone Directory
1934	Bonanno Jos plstr	R. L. Polk & Co.
	Bonanno Leo	R. L. Polk & Co.
	Peter Robt Mary chandeliermkr	R. L. Polk & Co.

2348 37TH ST

Year	Uses	Source
1991	Mastandrea Domenico	NYNEX Information Resource Company
1983	Ringston Raymond Jr	New York Telephone
1976	Devine C	New York Telephone

FINDINGS

Year	Uses	Source
1970	Devine C	New York Telephone
1934	Eggers Aug Minnie porter	R. L. Polk & Co.
	Eggers Fredk mach	R. L. Polk & Co.
	Eggers Roso clk	R. L. Polk & Co.
	Hische Geo Window clnr	R. L. Polk & Co.
	Hische w id Henry	R. L. Polk & Co.

2349 37TH ST

Year	Uses	Source
1934	Kutak Frank Helen musiclan	R. L. Polk & Co.
	Kutak Mary w id Frank	R. L. Polk & Co.
	Novack Louis plstr	R. L. Polk & Co.

2350 37TH ST

Year	Uses	Source
1991	Mc Dermott John	NYNEX Information Resource Company
1934	Holcher Henry Marie L carp	R. L. Polk & Co.
	Schmidt Helen bkpr	R. L. Polk & Co.

2351 37TH ST

Year	Uses	Source
1967	Benka L	New York Telephone
1962	Benka L	New York Telephone Directory
1945	Benka L	New York Telephone
1939	Benka L	New York Telephone Company
1934	Benka John Theresa cabt mkr	R. L. Polk & Co.
	Benka Louis Anna musician	R. L. Polk & Co.
	Toal Elizabeth	R. L. Polk & Co.
	Toal John	R. L. Polk & Co.
	Walsh Ella inspr	R. L. Polk & Co.

FINDINGS

38 AV

1454 38 AV

Year	Uses	Source
2000	ARLETE HONORATO	Cole Information

38D

2044 38D

Year	Uses	Source
1934	Devore Peter W Suzanne H restr	R. L. Polk & Co.

2167 38D

Year	Uses	Source
1934	Reilly Jennie L clk	R. L. Polk & Co.
	OBrien Bartholomew J clk	R. L. Polk & Co.

38TH

1805 38TH

Year	Uses	Source
2000	ATLAS SANITATION CORPORATION	Cole Information

1807 38TH

Year	Uses	Source
2000	ENVIRO SCOPE CONSULTING CORPORATION	Cole Information
	SANDHU ENTERPRISES INCORPORATED	Cole Information

2181 38TH

Year	Uses	Source
1934	Aaron Irving Fay fruits	R. L. Polk & Co.

38TH AVE

1211 38TH AVE

Year	Uses	Source
2017	B H B TRADING INC	Cole Information
	AMERICORE DRILLING	Cole Information

FINDINGS

Year	Uses	Source
2017	AMERICORE	Cole Information
	AFRICA AMERICA COFFEE TRADING COMPAN	Cole Information
2014	B H B TRADING INCORPORATED	Cole Information
	AFRICA AMERICA COFFEE TRADING COMPAN	Cole Information
2010	AMERICORE DRILLING	Cole Information
	BHB TRADING INC	Cole Information
	TASK TRANSPORTATION INC	Cole Information
2005	h Ramsingh Zammana v	Hill-Donnelly Information Services
	OBJECT DESIGN	Cole Information
	OCCUPANT UNKNOWN	Cole Information
2000	Object Designs Inc	Cole Information
	Ramsingh Zamman	Cole Information
	Urban Apparel Grp	Cole Information
	RAMSINGH ZAMMANA	Cole Information
	OBJECT DESIGNS INCORPORATED	Cole Information
	URBAN APPAREL GROUP INCORPORATED	Cole Information
	PATRICK TALTY	Cole Information
1995	MAIL FLIGHT INC	Cole Information
	TAURUS DELIVERY SVCE	Cole Information
1992	MAIL FLIGHT LTD	Cole Information
	ROYALE INTERNATIONAL COURIERS INC	Cole Information
	MIDNITE EXPRESS INC	Cole Information
	TAURUS DELIVERY SVCE	Cole Information
1991	Midnite Express Inc	NYNEX Information Resource Company
	Royale International Couriers Inc	NYNEX Information Resource Company
	Taurus Delivery Svce	NYNEX Information Resource Company

1214 38TH AVE

Year	Uses	Source
2017	AMADEUS MARBLE & GRANITE CORP	Cole Information
2014	AMADEUS MARBLE & GRANITE CORP	Cole Information
2010	AMADEUS MARBLE & GRANITE	Cole Information

FINDINGS

Year	Uses	Source
2005	Amadeus Marble & Granite	Hill-Donnelly Information Services
	AMADEUS MARBLE & GRANITE CORP	Cole Information

1217 38TH AVE

Year	Uses	Source
2020	SETS MACHINE INC	EDR Digital Archive
2017	NATIONAL ENVIRONMENTAL SAFETY COMPAN	Cole Information
	NATIONAL ENVIRONMENTAL SAFETY	Cole Information
2014	DELLAVECCHIA MICHAEL	Cole Information
	NATIONAL ENVIRONMENTAL SAFETY	Cole Information
2010	NATIONAL ENVIRONMENTAL SAFETY	Cole Information
2005	Vertical Elevator 1 P	Hill-Donnelly Information Services
	REALTY LLC	Cole Information
	CENTURY ELEVATOR MAINTENANCE CORP	Cole Information
	CAPM REALTY LLC	Cole Information
2000	Park Plus	Cole Information
	13TH ST INTS FROM	Cole Information
	PARK PLUS	Cole Information
1995	UNALITE	Cole Information
	LUMINEX	Cole Information
	UNALITE ELECTRIC & LIGHTING CORP	Cole Information
1992	UNALITE	Cole Information
	LUMINEX	Cole Information
	UNALITE ELECTRIC & LIGHTING CORP	Cole Information
1991	IVERSEN METAL SVCE CO	NYNEX Information Resource Company
	Luminex	NYNEX Information Resource Company
	Unalite	NYNEX Information Resource Company
	Unalite Electric & Lighting Corp	NYNEX Information Resource Company

1221 38TH AVE

Year	Uses	Source
2014	AKIVA WEINGARTEN	Cole Information
2010	AKIVA WEINGARTEN	Cole Information

FINDINGS

1245 38TH AVE

Year	Uses	Source
2014	ZACHARY EINSTEIN	Cole Information

1306 38TH AVE

Year	Uses	Source
2020	PART'S AUTHORITY	EDR Digital Archive
	Q P B C INC	EDR Digital Archive
2017	Q P B C INC	Cole Information
2010	SAFE ART TRANSPORT	Cole Information
2005	Safe Art Transport I R	Hill-Donnelly Information Services
2000	Safe Art Transport	Cole Information
	21ST ST INTS FROM	Cole Information
	SAFE ART TRANSPORT	Cole Information
1995	FORGE INDUSTRIES	Cole Information
1962	Bedik Corp	New York Telephone Directory
	Murachanian Exprt Co Inc	New York Telephone Directory
	United Overseas Corp	New York Telephone Directory

1438 38TH AVE

Year	Uses	Source
1934	Donato Cath	R. L. Polk & Co.

1455 38TH AVE

Year	Uses	Source
1991	Lukach M	NYNEX Information Resource Company

2103 38TH AVE

Year	Uses	Source
2014	VEDAT KIYICI	Cole Information
2010	VEDAT KIYICI	Cole Information
2005	VEDAT KIYICI	Cole Information

2104 38TH AVE

Year	Uses	Source
2010	MOZE BERGSON	Cole Information

FINDINGS

Year	Uses	Source
2005	MOZE BERGSON	Cole Information

2105 38TH AVE

Year	Uses	Source
2005	Mahmood K	Hill-Donnelly Information Services
	Mc Garry	Hill-Donnelly Information Services
	Perez Mlguel	Hill-Donnelly Information Services
	h Vazquez Leonardo	Hill-Donnelly Information Services
2000	Shamin Ahmed	Cole Information
	Tomoko Hayakaw	Cole Information
	Tariq Mehmood	Cole Information
	Frank Shaw n	Cole Information
	KAUR PARMJIT	Cole Information
	FRANK SHAWN	Cole Information
	TOMOKO HAYAKAWA	Cole Information
	TARIQ MEHMOOD	Cole Information
	SHAMIN AHMED	Cole Information
1967	Chris Auto Svce	New York Telephone
1945	Lambs Auto Wrecking	New York Telephone

2107 38TH AVE

Year	Uses	Source
2010	GERARD PALADZOLO	Cole Information
2005	Uncy Andre	Hill-Donnelly Information Services
	GERARD PALADZOLO	Cole Information
2000	Rebecca Smithmeyer	Cole Information
	Peggy Sw isher	Cole Information
	ARA GEMDZIAN	Cole Information
	PEGGY SWISHER	Cole Information
	REBECCA SMITHMEYER	Cole Information

2109 38TH AVE

Year	Uses	Source
2010	ELIZABETH GANDOLFO	Cole Information

Year	Uses	Source
2010	ERIC BRASURE	Cole Information
2005	Gandol Fo Elizabeth 7v	Hill-Donnelly Information Services
	ELIZABETH GANDOLFO	Cole Information
	JESSE WILLMON	Cole Information
	JOHN COSTANZA	Cole Information
2000	Law rence Palermo	Cole Information
	J LAPERTOSA	Cole Information
	L PALERMO	Cole Information
	RON LENT	Cole Information

2110 38TH AVE

Year	Uses	Source
2020	FIAZ KHAN	EDR Digital Archive
2017	SAHIL KHAN AUTO REPAIR	Cole Information
	S K AUTO	Cole Information
2014	NEW YORK AUTOMOBILE REPAIR CORPORATI	Cole Information
2010	NEW YORK AUTO REPAIR CORP	Cole Information
2005	New York Auto Repair Corp	Hill-Donnelly Information Services
	NEW YORK AUTO REPAIR CORP	Cole Information
	AUTO REPAIR	Cole Information
	LIMOUSINE AUTO REPAIR INC	Cole Information
2000	New York Auto Rpr Corp	Cole Information
	NEW YORK AUTO REPAIR CORPORATION	Cole Information
1995	NEW YORK AUTO REPAIR CORP	Cole Information
1992	SALAMIS SVCE STA INC	Cole Information

2111 38TH AVE

Year	Uses	Source
2010	CARRIE BARNES	Cole Information
2005	No Current Listing	Hill-Donnelly Information Services
	CARRIE BARNES	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information
1983	Rudow ski Shirley Y	New York Telephone

FINDINGS

2112 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information
1991	Lynch John J	NYNEX Information Resource Company

2113 38TH AVE

Year	Uses	Source
2000	M Charalambous	Cole Information
	M CHARALAMBOUS	Cole Information

2114 38TH AVE

Year	Uses	Source
2010	ALEKSANDER MEHILLI	Cole Information
2005	Esp Inosa Mercedes	Hill-Donnelly Information Services
	Mehilll Aleksander	Hill-Donnelly Information Services
	ALEKSANDER MEHILLI	Cole Information
2000	A MEHILLI	Cole Information

2115 38TH AVE

Year	Uses	Source
2020	BROTHER'S AUTO REPAIR	EDR Digital Archive
2017	SALAMIS SVCE STA INC	Cole Information
	BROTHERS AUTO REPAIR	Cole Information
2014	BROTHERS REPAIR SHOP INCORPORATED	Cole Information
2010	SALAMIS SERVICE STATION	Cole Information
	CVS CLUB	Cole Information
2005	Salamis Service Station Inc	Hill-Donnelly Information Services
	Tonys Towing Svc 1s	Hill-Donnelly Information Services
	BETTER QUALITY MECHANICAL INC	Cole Information
2000	Lance Posner	Cole Information
	Cmmrcl Vehic Svcs	Cole Information
	Salamis Svce St	Cole Information
	Tonys Towing Svc	Cole Information
	SALAMIS SVCE STATION INCORPORATED	Cole Information
	TONYS TOWING SERVICE	Cole Information

FINDINGS

Year	Uses	Source
2000	COMMERCIAL VEHICLE SVCES	Cole Information
	RADIO ACTIVE	Cole Information
	LANCE POSNER	Cole Information
1995	SALAMIS SVCE STA INC	Cole Information
	RADIO ACTIVE	Cole Information
	COMMERCIAL VEHICLE SVCES	Cole Information
	TONY'S TOWING SERVICE	Cole Information
1992	TOPAZ ELECTRIC CONSTR CO INC	Cole Information
1991	Topaz Electric Constr Co Inc	NYNEX Information Resource Company

2116 38TH AVE

Year	Uses	Source
2005	A ELANA	Cole Information
2000	Iris Fitilis	Cole Information
	IRIS FITILIS	Cole Information

2117 38TH AVE

Year	Uses	Source
2005	PAULINE LABBATE	Cole Information

2119 38TH AVE

Year	Uses	Source
2005	Murphy P	Hill-Donnelly Information Services
	PAMELA MURPHY	Cole Information
2000	P ALEXANDER	Cole Information

2120 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2121 38TH AVE

Year	Uses	Source
2014	SEAN MAYO	Cole Information
2010	SEAN MAYO	Cole Information
2005	MAIKO MEGURO	Cole Information
2000	ADRIAN SANTOS	Cole Information

FINDINGS

2122 38TH AVE

Year	Uses	Source
2010	JOHN HEINIS	Cole Information
2005	Smith Usa	Hill-Donnelly Information Services
	JOHN HEINIS	Cole Information
2000	OCCUPANT UNKNOWN	Cole Information

2123 38TH AVE

Year	Uses	Source
2000	NATALIE SPINOS	Cole Information

2125 38TH AVE

Year	Uses	Source
1970	Young Wanetta	New York Telephone
	Young Warren A	New York Telephone

2126 38TH AVE

Year	Uses	Source
2000	John Zabniak	Cole Information
	JOHN ZABNIAK	Cole Information

2127 38TH AVE

Year	Uses	Source
2005	Pillos Elias	Hill-Donnelly Information Services
	ELIAS PILIOS	Cole Information
2000	Khalil Chiadmi	Cole Information
	KHALIL CHIADMI	Cole Information

2128 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2129 38TH AVE

Year	Uses	Source
2005	h Sobral Nelida	Hill-Donnelly Information Services
2000	NELIDA SOBRAL	Cole Information

FINDINGS

2130 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2131 38TH AVE

Year	Uses	Source
1939	Jewell Andrew	New York Telephone Company

2132 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2134 38TH AVE

Year	Uses	Source
2014	LUIZ MACHADO	Cole Information
2010	LUIZ MACHADO	Cole Information
2005	LUIZ MACHADO	Cole Information
2000	A Macabu	Cole Information
	A MACABU	Cole Information

2135 38TH AVE

Year	Uses	Source
2005	Flossos John & Spiro	Hill-Donnelly Information Services
	NIKI FLOSSOS	Cole Information
2000	Niki Flossos	Cole Information
	Efrem Goldman	Cole Information
	EFREM GOLDMAN	Cole Information
	JOHN FLOSSOS	Cole Information

2136 38TH AVE

Year	Uses	Source
2005	Souravlls Hrisoval	Hill-Donnelly Information Services
	HRISOVALANPIS SOURAVLIS	Cole Information
2000	A PAPAZOGLOU	Cole Information

FINDINGS

2138 38TH AVE

Year	Uses	Source
2005	KrushInski William	Hill-Donnelly Information Services
	WILLIAM KRUSHINSKI	Cole Information
2000	William Krushinski	Cole Information
	WILLIAM KRUSHINSKI	Cole Information

2139 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2140 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2143 38TH AVE

Year	Uses	Source
2005	Giotis George	Hill-Donnelly Information Services
	Gutierrez Ruben	Hill-Donnelly Information Services
	RUBEN GUTIERREZ	Cole Information
2000	George Giotis	Cole Information
	Matthew B Hayw orth	Cole Information
	GEORGE GIOTIS	Cole Information
	MATTHEW HAYWORTH	Cole Information

2145 38TH AVE

Year	Uses	Source
2005	ALICIA CHRISTOFI	Cole Information
2000	Teresa Brosnan	Cole Information
	Eileen Reilly	Cole Information
	Natalya Romanko	Cole Information
	TERESA BROSNAN	Cole Information
	EILEEN REILLY	Cole Information
	NATALYA ROMANKO	Cole Information

FINDINGS

2147 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2148 38TH AVE

Year	Uses	Source
2000	Deidre Mc Kenn	Cole Information
	Derdre Mc Kenn	Cole Information
	Peader Rice	Cole Information
	DEIDRE MCKENNA	Cole Information

2149 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2150 38TH AVE

Year	Uses	Source
2005	Scavetta Paul V	Hill-Donnelly Information Services
	PAUL SCAVETTA	Cole Information

2152 38TH AVE

Year	Uses	Source
2000	Dominick Grimaldi	Cole Information
	D GRIMALDI	Cole Information

2153 38TH AVE

Year	Uses	Source
1967	Cinaglia Angelo	New York Telephone

2154 38TH AVE

Year	Uses	Source
2005	AL GIMENEZ	Cole Information
2000	A Gimenez	Cole Information
	A GIMENEZ	Cole Information

2155 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

FINDINGS

Year	Uses	Source
1939	Katzenstein M rl est	New York Telephone Company

2156 38TH AVE

Year	Uses	Source
2014	IBRAHIM ATA	Cole Information
2010	IBRAHIM ATA	Cole Information
2005	Lampier Penelope	Hill-Donnelly Information Services
	Mohamed Abrahim	Hill-Donnelly Information Services
2000	ABRAHIM MOHAMED	Cole Information
	EDGAR TELLO	Cole Information

2157 38TH AVE

Year	Uses	Source
2000	JOSEPH MAHONEY	Cole Information
1962	Friedrich Jos M	New York Telephone Directory

2158 38TH AVE

Year	Uses	Source
2005	Magliano R v	Hill-Donnelly Information Services
	ROSE MAGLIANO	Cole Information
2000	R MAGLIANO	Cole Information
1970	Cinaglia Angelo	New York Telephone
1962	Cinaglia Angelo	New York Telephone Directory

2159 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2160 38TH AVE

Year	Uses	Source
2005	Mir	Hill-Donnelly Information Services

2161 38TH AVE

Year	Uses	Source
2000	James Kushner	Cole Information
	JAMES KUSHNER	Cole Information

Year	Uses	Source
1991	Contovoros Paul	NYNEX Information Resource Company

2163 38TH AVE

Year	Uses	Source
2000	OCCUPANT UNKNOWN	Cole Information

2164 38TH AVE

Year	Uses	Source
2010	DEMTRIOS MARKOUIZOS	Cole Information
2005	Markouizos Demtrios	Hill-Donnelly Information Services
	Walker ammie v	Hill-Donnelly Information Services
	DEMTRIOS MARKOUIZOS	Cole Information
2000	Basil Bbeshbeshy	Cole Information
	BASIL ELBESHBESHY	Cole Information

2165 38TH AVE

Year	Uses	Source
2005	Chun Suzanne v	Hill-Donnelly Information Services
	SUZANNE CHUN	Cole Information
2000	Yoon Cho	Cole Information
	Anb Fashion Inc	Cole Information
	YOON CHO	Cole Information

2166 38TH AVE

Year	Uses	Source
2010	CHARLES GABRIELLINI	Cole Information
2005	Gabriellini A v	Hill-Donnelly Information Services
	Gabriellini Jacqueline	Hill-Donnelly Information Services
2000	A GABRIELLINI	Cole Information

2167 38TH AVE

Year	Uses	Source
2005	h Cruz Maria Elena	Hill-Donnelly Information Services
	Delgado Dimas	Hill-Donnelly Information Services
	Ferreira Alcides & A	Hill-Donnelly Information Services
	MARIA CRUZ	Cole Information

Year	Uses	Source
2000	Manuela Blasini	Cole Information
	Ricardo Delgado	Cole Information
	Alcides Ferreir	Cole Information
	Alex E Pasmay	Cole Information
	MANUELA BLASINI	Cole Information
	ALEX PASMAY	Cole Information
	ALCIDES FERREIRA	Cole Information
	RICARDO DELGADO	Cole Information

2169 38TH AVE

Year	Uses	Source
2005	Tourtoulis Adam W v 718 278 2231 as	Hill-Donnelly Information Services
	ELEFTHERIA TOURTOULIS	Cole Information
2000	ADAM TOURTOULIS	Cole Information

2170 38TH AVE

Year	Uses	Source
2010	JOSEPHINE SCOTTI	Cole Information

2171 38TH AVE

Year	Uses	Source
2005	Danae Fonseca v V	Hill-Donnelly Information Services
	EMMANUEL SPANTIDAKIS	Cole Information
2000	THALIA HADJIGAVREIL	Cole Information

2172 38TH AVE

Year	Uses	Source
2005	Boumias Maria v	Hill-Donnelly Information Services
2000	D BOURNIAS	Cole Information

2173 38TH AVE

Year	Uses	Source
2005	Dibiase Rocco & Cateria V	Hill-Donnelly Information Services
2000	Paul West	Cole Information
	ROCCO DIBIASE	Cole Information
	PAUL WEST	Cole Information

FINDINGS

2180 38TH AVE

Year	*Uses*	*Source*
2010	JAMES RUBIN	Cole Information
	ILZA PEREIRA	Cole Information
	SERSERAY BASARIR	Cole Information
	D VELENZAS	Cole Information
	VINCENT MANIACI	Cole Information
2005	Multi Unit Address	Hill-Donnelly Information Services
	Colon Edaw in v	Hill-Donnelly Information Services
	Numbr C 3h Colon L A	Hill-Donnelly Information Services
	Espinosa Rosa	Hill-Donnelly Information Services
	Hinders Kathleen V	Hill-Donnelly Information Services
	Jackson Devon V	Hill-Donnelly Information Services
	Landolfi J	Hill-Donnelly Information Services
	Lattner Maryann H 0718 728 7211 00oo	Hill-Donnelly Information Services
	Lew is Mike V	Hill-Donnelly Information Services
	Maniaci Vincent	Hill-Donnelly Information Services
	Pereira Iza V	Hill-Donnelly Information Services
	Rubin Jim	Hill-Donnelly Information Services
	Speeney Mark V	Hill-Donnelly Information Services
	Tung Geoffrey	Hill-Donnelly Information Services
	Voeller Joseph	Hill-Donnelly Information Services
	JIM RUBIN	Cole Information
2000	Charles Caron	Cole Information
	William Douglas	Cole Information
	Brian Garten	Cole Information
	James J Jackson	Cole Information
	Brian Kaplan	Cole Information
	Iiza Pereir	Cole Information
	Dan Sherman	Cole Information
	David M Tang	Cole Information
	Tim True	Cole Information
	Geoffrey Tung	Cole Information

FINDINGS

Year	Uses	Source
2000	Paul E Weiz	Cole Information
	Solaris C	Cole Information
	SOLARIS N Y C	Cole Information
	M RAHMAN	Cole Information
	L COLON	Cole Information
	DAN SHERMAN	Cole Information
	BRIAN GARTEN	Cole Information
	PAUL WEIZ	Cole Information
	TIM TRUE	Cole Information
	MARK SPEENEY	Cole Information
	BRIAN KAPLAN	Cole Information
	G TUNG	Cole Information
	E COLON	Cole Information
	JAMES JACKSON	Cole Information
	WILLIAM DOUGLAS	Cole Information
	CHARLES CARONIA	Cole Information
	D SALVATI	Cole Information
	ILZA PEREIRA	Cole Information
	F BARRISH	Cole Information
	JIM RUBIN	Cole Information
	DAVID TANG	Cole Information
1991	Juoa George	NYNEX Information Resource Company
1962	Schussler John	New York Telephone Directory

2181 38TH AVE

Year	Uses	Source
2014	STEVEN SANNUTO	Cole Information
2005	Multi Unit Address	Hill-Donnelly Information Services
	Ahmed Munsur V	Hill-Donnelly Information Services
	Bogert Ronald V	Hill-Donnelly Information Services
	Coea Alexander	Hill-Donnelly Information Services
	Davaakhuu Tumurkhuu v	Hill-Donnelly Information Services
	h Dennis Josh	Hill-Donnelly Information Services

FINDINGS

Year	Uses	Source
2005	Hadjahmed Nabila	Hill-Donnelly Information Services
	h Hbabou Rachid	Hill-Donnelly Information Services
	Kape Michael 8 V	Hill-Donnelly Information Services
	Kardoulias John	Hill-Donnelly Information Services
	Moskovitz Pzahi o	Hill-Donnelly Information Services
	Oliveri Mary v	Hill-Donnelly Information Services
	Sabovic Muho v	Hill-Donnelly Information Services
	Schoenhaar Gary v	Hill-Donnelly Information Services
	GIASUDDIN AHMED	Cole Information
	MICHELLINE COONROD	Cole Information
	RACHID HBABOU	Cole Information
	MICHAEL KAPE	Cole Information
	ALEXANDER COLEA	Cole Information
	SALVATORE RIZZO	Cole Information
2000	Christine Caponi	Cole Information
	Jason Chan	Cole Information
	Fat K Chow	Cole Information
	Michelline Coonrod	Cole Information
	Theresa Ranigan	Cole Information
	Rachid Hbabou	Cole Information
	J Ingram	Cole Information
	Bev Jafek	Cole Information
	Michael B Kape	Cole Information
	Wane Mac Gregor	Cole Information
	Pzahi Moskovitz	Cole Information
	David J Rodkin	Cole Information
	Gary Schoenhaar	Cole Information
	Harun Seker	Cole Information
	Harun Seker	Cole Information
	C Cnsltnts Ltd	Cole Information
	HARUN SEKER	Cole Information
	DAVID RODKIN	Cole Information

Year	Uses	Source
2000	C CAPONI	Cole Information
	BEV JAFEK	Cole Information
	A COLEA	Cole Information
	BILL MIHAS	Cole Information
	WANE MACGREGOR	Cole Information
	JASON CHAN	Cole Information
	RACHID HBABOU	Cole Information
	THERESA FLANIGAN	Cole Information
	MICHAEL KAPE	Cole Information
	GARY SCHOENHAAR	Cole Information
	J INGRAM	Cole Information

2211 38TH AVE

Year	Uses	Source
2020	HOLIDAY IMAGE INC	EDR Digital Archive

2212 38TH AVE

Year	Uses	Source
1983	Modena Domenick F	New York Telephone

2222 38TH AVE

Year	Uses	Source
1945	Gaborc Albert	New York Telephone

2223 38TH AVE

Year	Uses	Source
1970	McGivney Margaret Miss RN	New York Telephone
1962	McGivney Margaret Miss RN	New York Telephone Directory

38TH RD

2110 38TH RD

Year	Uses	Source
1962	Henick Wm	New York Telephone Directory

FINDINGS

38TH ST

1729 38TH ST

Year	Uses	Source
1934	Yakemchek Peter Stella lab	R. L. Polk & Co.

1801 38TH ST

Year	Uses	Source
1934	Fritz Jos Caroline restr	R. L. Polk & Co.
	Sander Valentine w aiter	R. L. Polk & Co.

1807 38TH ST

Year	Uses	Source
1995	N A N C O CONSTRUCTION CORP	Cole Information
	SANDHU ENTERPRISES INC	Cole Information
	ENVIRO-SCOPE CONSULTING CORP	Cole Information

1811 38TH ST

Year	Uses	Source
1991	AAAAA Tow ing	NYNEX Information Resource Company
	Brandys Automotive Inc	NYNEX Information Resource Company

1813 38TH ST

Year	Uses	Source
1934	Muff Frank J Emma auto repr	R. L. Polk & Co.

1815 38TH ST

Year	Uses	Source
1970	Accurate Concrete Breaking Co	New York Telephone
	Pegno Angelo rok drilg & blastg	New York Telephone
1967	Accurate Concrete Breaking Co	New York Telephone
	L&J CONCRETE CORP	New York Telephone
	Pegno Angelo rok drilg & blastg	New York Telephone
1962	Accurate Concrete Breaking Co	New York Telephone Directory
	L & J CONCRETE CORP	New York Telephone Directory
	Pegno Angelo rok drilg & blastg	New York Telephone Directory
1934	Muff Wm H Olga	R. L. Polk & Co.

FINDINGS

1820 38TH ST

Year	Uses	Source
1945	Tri Boro Boat Basin	New York Telephone
	Fenmore Magnus	New York Telephone
	Goenner Eugene marine contrs	New York Telephone
1939	Astoria Boatyard	New York Telephone Company
	Queens Rubber Cement Corp	New York Telephone Company

1835 38TH ST

Year	Uses	Source
1995	WHITE COFFEE CORP	Cole Information
	PARKER HOUSE COFFEE CO	Cole Information
1992	WHITE COFFEE CORP	Cole Information
	PARKER HOUSE COFFEE CO	Cole Information
1991	Parker House Coffee Co	NYNEX Information Resource Company
	WHITE COFFEE CORP	NYNEX Information Resource Company
1983	Commercial Fasteners Corp	New York Telephone
1970	Exhibit Craft Inc	New York Telephone
1967	Exhibit Craft Inc	New York Telephone
1962	Exhibit Craft Inc	New York Telephone Directory

1850 38TH ST

Year	Uses	Source
1970	Bienstock Florence	New York Telephone

1902 38TH ST

Year	Uses	Source
1991	DEBORAH CAR SVCE INC	NYNEX Information Resource Company
1983	A & M S Carting Co Inc	New York Telephone
1970	TRAYNOR & HANSEN CORP trukmn	New York Telephone
1967	TRAYNOR & HANSEN CORP trukmn	New York Telephone
1962	TRAYNOR & HAN SEN CORP trukmn	New York Telephone Directory

1936 38TH ST

Year	Uses	Source
1970	SECS INC	New York Telephone

FINDINGS

Year	Uses	Source
1970	SUPEERiR ELECTROMECHANICAL COMPONENTS SVCE INC	New York Telephone
1967	SECS INC	New York Telephone
	Superior Electromechanical Components Svce Inc	New York Telephone

1954 38TH ST

Year	Uses	Source
1991	Bayside Constr Co Inc	NYNEX Information Resource Company
1983	Bayside Roofing Co Inc	New York Telephone
1976	Bayside Roofing Co Inc	New York Telephone
1970	Bayside Roofing Co Inc	New York Telephone
1967	BAYSIDE ROOFING CO INC	New York Telephone

2022 38TH ST

Year	Uses	Source
1934	Allmon Geo Anna linemn	R. L. Polk & Co.
	Anderson Gust Av Thyra lab	R. L. Polk & Co.
	Franke Bertha	R. L. Polk & Co.
	Franke Karl Julia piano mkr	R. L. Polk & Co.

2028 38TH ST

Year	Uses	Source
1934	Aetna Marble Co Inc NY Frank Kral pres Wm Prosek v pres Chas Cacha sec Alois Kral treas	R. L. Polk & Co.

2029 38TH ST

Year	Uses	Source
1976	Aetna Marble Co fcty	New York Telephone
	Aetna Prods Co Nw Stn Rd @Holtsville@ NYC Te l No J 60415	New York Telephone
1970	Aetna Marble Co fcty	New York Telephone
1967	Aetna Marble Co fcty	New York Telephone
1962	Aetna Marble Co fcty	New York Telephone Directory
1945	Aetna Marble Co foty	New York Telephone
1939	Aetna Marble Co fcty	New York Telephone Company

FINDINGS

Year	Uses	Source
1939	If no answ er call HA vemyr 62141	New York Telephone Company
	Aetna Paint & Varnish Co Dumnt Av Wdhvn Ml chgn 21022	New York Telephone Company

2033 38TH ST

Year	Uses	Source
1991	Dessillas Spiridon	NYNEX Information Resource Company
1983	Papadopoulos G	New York Telephone

2035 38TH ST

Year	Uses	Source
1976	Gullo Vincent P	New York Telephone
1934	Graser Aug Lena pdlr	R. L. Polk & Co.
	Maguire Jas Augusta truck driver	R. L. Polk & Co.
	Martin Jas charlotte mach opr	R. L. Polk & Co.

2062 38TH ST

Year	Uses	Source
1996	FUCHS Matthew S	NYNEX

2067 38TH ST

Year	Uses	Source
1991	Barnes Douglas Y	NYNEX Information Resource Company
	Kanelakis Artemios	NYNEX Information Resource Company
	Martin A	NYNEX Information Resource Company
	Schott Stephen J	NYNEX Information Resource Company
	Wanke H	NYNEX Information Resource Company
1983	Arty Painting Co	New York Telephone
	Fernandez H	New York Telephone
1976	Basile Jerome J	New York Telephone
1970	Scully Geo E Mrs	New York Telephone
1934	Bigelow DAvid Reba slsmn	R. L. Polk & Co.
	Dow nie Gerald Annie chef	R. L. Polk & Co.
	Fosar Court apt bldg	R. L. Polk & Co.
	Galbraith Alf clk	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Galbraith John M	R. L. Polk & Co.
	Gilman Lillian cook Mhn	R. L. Polk & Co.
	Heimann Ernest Hylda w aiter	R. L. Polk & Co.
	Hippner Reinhold	R. L. Polk & Co.
	Hogan Patk Margt driver	R. L. Polk & Co.
	Kallio Eino clk	R. L. Polk & Co.
	Kallio Irene garagemn	R. L. Polk & Co.
	Lynch Anna M	R. L. Polk & Co.
	Linch Jas J auto mech	R. L. Polk & Co.
	Moller Jos Marion electn	R. L. Polk & Co.
	Netsett w alter Rosa w aiter	R. L. Polk & Co.
	Schuette Hans Olga truck driver	R. L. Polk & Co.
	Stew art John Anna bkpr	R. L. Polk & Co.

2075 38TH ST

Year	Uses	Source
1996	FUCHSMAN Phyllis	NYNEX
1991	Bacello Nelson	NYNEX Information Resource Company
	Kalamboukis Theodoros	NYNEX Information Resource Company
	Mendez Nancy	NYNEX Information Resource Company
	Min Byung Kw on	NYNEX Information Resource Company
	Rosekrans Geo	NYNEX Information Resource Company
1983	Caffrey M E	New York Telephone
	Pigot John C	New York Telephone
	Rosekrans Geo	New York Telephone
1970	Pigot John C	New York Telephone
	Pigot Martha R Mrs	New York Telephone
	Rosekrans Geo	New York Telephone
1967	Pigot John C	New York Telephone
	Rosekrans Geo	New York Telephone
1962	Kalman Sam	New York Telephone Directory
	Pigot John C	New York Telephone Directory
	Strauss Meyer	New York Telephone Directory

FINDINGS

Year	Uses	Source
1945	Kalman Lynn	New York Telephone
1939	Szadvary G	New York Telephone Company
1934	Callahan Michl Alice lab	R. L. Polk & Co.
	Carney Helen M clk	R. L. Polk & Co.
	Carney Rose adjuster	R. L. Polk & Co.
	Carney Rose w id Thos	R. L. Polk & Co.
	Carney Theo lab	R. L. Polk & Co.
	Carney Thos lab	R. L. Polk & Co.
	Hasse Otto Virginia slsmn	R. L. Polk & Co.
	Isabel Court apt bldg	R. L. Polk & Co.
	Judge Jas steam eng	R. L. Polk & Co.
	Mac Gregor John Annie supt	R. L. Polk & Co.
	Mc Intyre John Bridget slsmn	R. L. Polk & Co.
	Myers Wm I Rose stmfitr	R. L. Polk & Co.
	Reimers Walter Margt caulker	R. L. Polk & Co.
	Riha Rose w id Rudolph	R. L. Polk & Co.
	Szadvary Grifielin Helen clk	R. L. Polk & Co.
	Tw erdy Oscar Elia civil eng	R. L. Polk & Co.

2103 38TH ST

Year	Uses	Source
1991	Kozo Imre	NYNEX Information Resource Company
1983	Kozo Imre	New York Telephone
	Sileo Dominick	New York Telephone
1976	Kozo Imre	New York Telephone
1970	Kozo Imre	New York Telephone
	Sileo Dominlck	New York Telephone
1967	Kozo Imre	New York Telephone
	Sileo Dominick	New York Telephone
1962	Sileo Dominick	New York Telephone Directory
1945	Sileo Dominick	New York Telephone
1934	Calligy Patk plmbr	R. L. Polk & Co.
	De Lisi Anthony Antoinette mach opr	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	De Lisi Anthony Antoinette mach opr	R. L. Polk & Co.
	Jirinec John Mae electn	R. L. Polk & Co.
	Oppizzi Dominick Mary lab	R. L. Polk & Co.
	Sileo Dominick Stella printer	R. L. Polk & Co.

2105 38TH ST

Year	Uses	Source
1983	Mc Adam M	New York Telephone
1976	Cully M	New York Telephone
	Magnifico Miriam Mrs	New York Telephone
1970	Magnifico Miriam Mrs	New York Telephone
	McAdam Mildred	New York Telephone
1967	Magnifico Miriam Mrs	New York Telephone
1962	Gance Katherine Mrs	New York Telephone Directory
	Magnifico Miriaee Mrs	New York Telephone Directory
1945	Gance Katherine Mrs	New York Telephone
	Magnifico Miriam Mrs	New York Telephone
1934	Fellini Dante Mildred cook	R. L. Polk & Co.
	Romerio Atilio Ricetta cook	R. L. Polk & Co.
	Vanderpoppe Geo Adelaide clk	R. L. Polk & Co.

2107 38TH ST

Year	Uses	Source
1991	Yetemian Alice	NYNEX Information Resource Company
1983	Gianquinto F	New York Telephone
1939	Curtin Denis	New York Telephone Company
1934	Ditty Jas C Cath slsmm	R. L. Polk & Co.
	Fisher Irving Annie llab	R. L. Polk & Co.
	Gance Anthony Cath clk	R. L. Polk & Co.
	Madden Edw Ella mach	R. L. Polk & Co.
	Stump Edw Dorothy survevor	R. L. Polk & Co.

FINDINGS

2109 38TH ST

Year	Uses	Source
1983	Costa Dominick	New York Telephone
1962	Smith Rosa V	New York Telephone Directory
1945	Smith Rosa Miss	New York Telephone
1939	Ditty Jas C	New York Telephone Company
	Smith Rosa Miss	New York Telephone Company
1934	Auchter Chas stmftr	R. L. Polk & Co.
	Modesti Vito Mary clk	R. L. Polk & Co.
	Moyka Chas Marie meatchr	R. L. Polk & Co.
	Schrag Theresa w id Wm	R. L. Polk & Co.

2111 38TH ST

Year	Uses	Source
1970	Merring Harry L	New York Telephone
1967	Merrino Harry L	New York Telephone
1962	Merring Harry L	New York Telephone Directory
1945	Merring Harry E	New York Telephone
1939	Merring Harry E	New York Telephone Company

2112 38TH ST

Year	Uses	Source
1934	Bearese John Mary slsmn	R. L. Polk & Co.

2113 38TH ST

Year	Uses	Source
1934	Gomi Elizabeth mach opr	R. L. Polk & Co.
	Gomi Loretta mach opr	R. L. Polk & Co.

2114 38TH ST

Year	Uses	Source
1934	Baldo Sando Sadle	R. L. Polk & Co.
	Strignano Salvatore Mary gelatine printer	R. L. Polk & Co.

FINDINGS

2115 38TH ST

Year	Uses	Source
1991	Herbst Jill	NYNEX Information Resource Company
1939	Haines Chas	New York Telephone Company
1934	Abbott Victoria	R. L. Polk & Co.
	Haines Chas Alice butler	R. L. Polk & Co.

2116 38TH ST

Year	Uses	Source
1934	Lanzetta Frank Mary lab	R. L. Polk & Co.

2117 38TH ST

Year	Uses	Source
1970	Hunter William	New York Telephone
1967	Neely Thos M C	New York Telephone
1939	Labbate Matteo	New York Telephone Company
1934	LAbbats Matteo Rose elev opr	R. L. Polk & Co.

2118 38TH ST

Year	Uses	Source
1939	Law rence John	New York Telephone Company
1934	Law rence Bernhardt Marie iron w kr	R. L. Polk & Co.
	Law rence John fctyw kr	R. L. Polk & Co.

2119 38TH ST

Year	Uses	Source
1934	Finger Wm Mary plmbr	R. L. Polk & Co.

2120 38TH ST

Year	Uses	Source
1934	Farley John Florence clk	R. L. Polk & Co.
	Farrelly John Florence clk	R. L. Polk & Co.
	ONeil Anna w id Jas	R. L. Polk & Co.
	ONeil Evelyn M tel opr	R. L. Polk & Co.
	Schoening Margt w id Herbert	R. L. Polk & Co.

FINDINGS

2121 38TH ST

Year	Uses	Source
1934	Anderer Arth clk	R. L. Polk & Co.
	Anderer Jos Mary uphol	R. L. Polk & Co.

2122 38TH ST

Year	Uses	Source
1962	Klauser Frank	New York Telephone Directory
1939	Klauser Frank	New York Telephone Company
1934	Klauser Frank Rose uphol	R. L. Polk & Co.

2123 38TH ST

Year	Uses	Source
1962	Back Geo	New York Telephone Directory
1945	Astarita Benj A	New York Telephone
	Astarita Lillian R	New York Telephone
1939	Astarita Benj A	New York Telephone Company
1934	Astarita Benj A Janet capt Fire Dept	R. L. Polk & Co.

2124 38TH ST

Year	Uses	Source
1967	Petersen Florence M	New York Telephone
1962	Petersen Florence M	New York Telephone Directory
1945	Mundle Arthur	New York Telephone
1939	Mundle Arthur	New York Telephone Company
1934	Mundle Arth O Lena chauf	R. L. Polk & Co.
	Mundle Lillian clk	R. L. Polk & Co.

2126 38TH ST

Year	Uses	Source
1939	Schmidt E Miss	New York Telephone Company
1934	Schmidt Edna clk	R. L. Polk & Co.
	Schmidt Geo clk	R. L. Polk & Co.
	Schmidt Geo Elizabeth slsmn	R. L. Polk & Co.

FINDINGS

2127 38TH ST

Year	Uses	Source
1991	Pilios Ilias	NYNEX Information Resource Company
1983	Pilios Elias	New York Telephone
1934	Amatulli Onofrio mach	R. L. Polk & Co.
	Amatulli Pasquale news dlr Mhn	R. L. Polk & Co.
	Di Felice Angela Antoinette mach opr	R. L. Polk & Co.

2128 38TH ST

Year	Uses	Source
1983	Cassar Joseph	New York Telephone
1934	Buttafoco Vincent Felicis lab	R. L. Polk & Co.

2129 38TH ST

Year	Uses	Source
1934	Dunne Cath sten	R. L. Polk & Co.
	Dunne John F Mary formn	R. L. Polk & Co.
	Dunne Margt sten	R. L. Polk & Co.
	Dunne Timothy J clk	R. L. Polk & Co.

2130 38TH ST

Year	Uses	Source
1934	Sapianza Anna drsmkr	R. L. Polk & Co.
	Sapianza John clk	R. L. Polk & Co.
	Sapianza Michl Nunzia barber	R. L. Polk & Co.
	Sapianza Paul chauf	R. L. Polk & Co.

2131 38TH ST

Year	Uses	Source
1934	Fuhrig Paul Mary elev opr	R. L. Polk & Co.

2132 38TH ST

Year	Uses	Source
1945	Brown Carl	New York Telephone
1939	Brown Carl flr scraping	New York Telephone Company
1934	Brown Carl Long Island Flooring Co	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Longren Aaron Greta pkr	R. L. Polk & Co.

2134 38TH ST

Year	Uses	Source
1934	Amato Paul Josephine indry prsr	R. L. Polk & Co.

2135 38TH ST

Year	Uses	Source
1996	FLOSSOS John	NYNEX
1939	Dailey E M	New York Telephone Company
1934	Dailey Eug M Mary printer	R. L. Polk & Co.
	Dailey Rose Mary sten	R. L. Polk & Co.

2136 38TH ST

Year	Uses	Source
1934	Cohen Evelyn sten	R. L. Polk & Co.
	Cohen Fanny w id Barnet	R. L. Polk & Co.
	Cohen Pearl sten	R. L. Polk & Co.
	Cohen Philip elev opr	R. L. Polk & Co.
	Cohen Sol slsmn	R. L. Polk & Co.

2137 38TH ST

Year	Uses	Source
1967	Carr Josephine	New York Telephone
1934	Born Arth D P Margt clk	R. L. Polk & Co.
	Born Law rence bkpr	R. L. Polk & Co.

2138 38TH ST

Year	Uses	Source
1934	Contagian Armenek Nazek	R. L. Polk & Co.
	Donnelly Marion clk	R. L. Polk & Co.
	Greco Thos Rose cigarmkr	R. L. Polk & Co.
	Grego frances	R. L. Polk & Co.
	Grego Thos Rose cigarmkr	R. L. Polk & Co.

FINDINGS

2139 38TH ST

Year	Uses	Source
1934	Lanno Jos Cammella brklyr	R. L. Polk & Co.

2140 38TH ST

Year	Uses	Source
1934	Kerbacher Anton Julia carp	R. L. Polk & Co.
	Kerbacher Anton lab	R. L. Polk & Co.
	Kerbacher Fanny clk	R. L. Polk & Co.
	Kerbacher Frank ship clk	R. L. Polk & Co.
	Kerbacher John clk	R. L. Polk & Co.

2143 38TH ST

Year	Uses	Source
1991	Grisafi Peter	NYNEX Information Resource Company
1962	Conese Eleanor	New York Telephone Directory
1945	Conese Thos	New York Telephone
1939	Domonkos Jos	New York Telephone Company
1934	Conese Frank lab	R. L. Polk & Co.
	Conese Mary mach opr	R. L. Polk & Co.
	Conese Thos Mary carp	R. L. Polk & Co.
	Lutz Barbara mach opr	R. L. Polk & Co.

2144 38TH ST

Year	Uses	Source
1967	Kantarian Kachig	New York Telephone
1962	Kantarian Harry	New York Telephone Directory
1945	Kantrian Larain Harry	New York Telephone
1939	Kantarian Harry	New York Telephone Company
1934	Staibl John H Mary G engr	R. L. Polk & Co.

2145 38TH ST

Year	Uses	Source
1991	Kerbacher Geo	NYNEX Information Resource Company
1983	Kerbacher Geo	New York Telephone
1976	Kerbacher Geo	New York Telephone

Year	Uses	Source
1970	Kerbacher Geo	New York Telephone
1967	Kerbacher Geo	New York Telephone
1962	Kerbacher Geo	New York Telephone Directory
1934	Broomfield Geo news dlr	R. L. Polk & Co.
	Broomfield John	R. L. Polk & Co.
	Broomfield Lillian nurse	R. L. Polk & Co.
	Pound Edw Anna chauf	R. L. Polk & Co.

2146 38TH ST

Year	Uses	Source
1934	Mahoney Danl J Hannah stone ctr	R. L. Polk & Co.
	Mahoney Frances clk	R. L. Polk & Co.
	Mahoney Josephine bkpr	R. L. Polk & Co.
	Mc Carthy Timothy stock clk	R. L. Polk & Co.

2147 38TH ST

Year	Uses	Source
1934	Pomposello Anthony lab	R. L. Polk & Co.
	Pomposello Louis Carmella plstr	R. L. Polk & Co.
	Pomposello Peter Antoinette	R. L. Polk & Co.
	Pomposello Roger lab	R. L. Polk & Co.

2148 38TH ST

Year	Uses	Source
1991	Bournias Kiriakos	NYNEX Information Resource Company
1983	Domonkos Jos	New York Telephone
1976	Domonkos Jos	New York Telephone
1970	Domonkos Jos	New York Telephone
1967	Domonkos Jos	New York Telephone
1962	Domonkos Jos	New York Telephone Directory
1945	Russell Renee	New York Telephone
1934	Conese Fannie clk	R. L. Polk & Co.
	Domonkos Jos Mary slsmn	R. L. Polk & Co.
	Hager Julius Helen photog	R. L. Polk & Co.

FINDINGS

2149 38TH ST

Year	Uses	Source
1934	ORourke Mary w id Wm	R. L. Polk & Co.

2150 38TH ST

Year	Uses	Source
1945	Koritzer R C	New York Telephone
1939	Koritzer R C	New York Telephone Company
1934	Lang Chas hotel clk	R. L. Polk & Co.
	PAvlick Agnes student	R. L. Polk & Co.
	PAvlick Andrew Mary furrier	R. L. Polk & Co.
	PAvlick Anna sten	R. L. Polk & Co.
	PAvlick Elsie designers model	R. L. Polk & Co.
	PAvlick Emily clk	R. L. Polk & Co.
	PAvlick Lillian bkpr	R. L. Polk & Co.
	PAvlick Mary furrier	R. L. Polk & Co.

2151 38TH ST

Year	Uses	Source
1934	Gueriskie Geo	R. L. Polk & Co.
	Gueriskie Louis Mary Chauf	R. L. Polk & Co.

2152 38TH ST

Year	Uses	Source
1934	Dempsey Christopher A Mary clk	R. L. Polk & Co.

2153 38TH ST

Year	Uses	Source
1939	Serrett Wm	New York Telephone Company
1934	Serrett Wm Henrietia sta eng	R. L. Polk & Co.

2154 38TH ST

Year	Uses	Source
1934	Blessing Albetrt Elizabeth lithog	R. L. Polk & Co.

FINDINGS

2155 38TH ST

Year	Uses	Source
1934	Nagle Johanna tel opr	R. L. Polk & Co.
	Nagle Patk Bridget clk PO	R. L. Polk & Co.

2156 38TH ST

Year	Uses	Source
1991	Chanrion Eric	NYNEX Information Resource Company
1970	Fenyes Rose Mrs	New York Telephone
1967	Fenyes Rose Mrs	New York Telephone
1962	Fenyes Rose Mrs	New York Telephone Directory
1945	Fenyes Rose Mrs	New York Telephone
1939	Seligson Louis	New York Telephone Company
1934	Seligson Jos uphol	R. L. Polk & Co.
	Seligson Louis Sarah uphol	R. L. Polk & Co.
	Seligson Morris pharm	R. L. Polk & Co.

2157 38TH ST

Year	Uses	Source
1991	Mahoney Joseph D Mrs	NYNEX Information Resource Company
1983	Mahoney Joseph D Mrs	New York Telephone
1976	Mahoney Jos D Mrs	New York Telephone
1970	Mahoney Jos D Mrs	New York Telephone
1967	Mahoney Jos D Mrs	New York Telephone
1934	Benes Marie C clk	R. L. Polk & Co.
	Cremin Mary w id Michl slsw n	R. L. Polk & Co.

2158 38TH ST

Year	Uses	Source
1991	Magliano A	NYNEX Information Resource Company
1983	Magliano A	New York Telephone
1976	Magliano Alice	New York Telephone
1934	Cinaglia Alice sten	R. L. Polk & Co.
	Cinaglia Angelo Mary barber	R. L. Polk & Co.
	Cinaglia Jos sstudent	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Cox Frank E clk	R. L. Polk & Co.
	Serrett Wm J lab	R. L. Polk & Co.

2160 38TH ST

Year	Uses	Source
1934	Lang Louis Dora interier decorater	R. L. Polk & Co.
	Lang Saml interior decorater	R. L. Polk & Co.

2161 38TH ST

Year	Uses	Source
1934	Kline Frances w aitress	R. L. Polk & Co.
	Kline Frank Regins	R. L. Polk & Co.
	Kline Jos truck driver	R. L. Polk & Co.

2162 38TH ST

Year	Uses	Source
1945	Simone Rose Mrs	New York Telephone
1934	Schrag Albert F Rose supt	R. L. Polk & Co.
	Schrag Albert F jr lab	R. L. Polk & Co.

2163 38TH ST

Year	Uses	Source
1939	Del Monte Ernesto	New York Telephone Company
1934	Hogan Bridget w id Jas	R. L. Polk & Co.
	Hogan Danl porter	R. L. Polk & Co.
	Hogan Edw lab	R. L. Polk & Co.
	Hogan Frank porter	R. L. Polk & Co.
	Hogan Jas C clk	R. L. Polk & Co.

2164 38TH ST

Year	Uses	Source
1991	Universal Diagnostic Laboratories	NYNEX Information Resource Company
1934	Buccola Anna R tel opr	R. L. Polk & Co.
	Buccola Nicholas Rose barber	R. L. Polk & Co.

FINDINGS

2165 38TH ST

Year	Uses	Source
1991	Batra Sachin	NYNEX Information Resource Company
1945	Romerio Benj	New York Telephone
1934	Sammon Anna sten	R. L. Polk & Co.
	Sammon Elizabeth clk	R. L. Polk & Co.
	Sammon John Bella clk Mhn	R. L. Polk & Co.

2166 38TH ST

Year	Uses	Source
1991	Gabrielini Jacqueline	NYNEX Information Resource Company
1983	Mangialardi Angelo	New York Telephone
1970	Mangialardi Angelo	New York Telephone
	Nolan Jos P	New York Telephone
1967	Mangialardi Angelo	New York Telephone
	Nolan Jos P	New York Telephone
1962	Mangialardi Jacquline	New York Telephone Directory
1945	Mangialardi Angelo	New York Telephone

2167 38TH ST

Year	Uses	Source
1934	OSullivan Michl Julia po clk	R. L. Polk & Co.

2168 38TH ST

Year	Uses	Source
1976	Boyce Thos F	New York Telephone
1970	Boyce Thos F	New York Telephone
1967	Boyce Thos F	New York Telephone
1962	Boyce Thos F	New York Telephone Directory
1934	Boyce Thos Emilia marble plshr	R. L. Polk & Co.

2169 38TH ST

Year	Uses	Source
1991	Tourtoulis Adam W	NYNEX Information Resource Company
1934	Shair Bessie bkpr	R. L. Polk & Co.
	Shair Chas clk	R. L. Polk & Co.

Year	Uses	Source
1934	Shair Jane	R. L. Polk & Co.
	Shair Nathan clk	R. L. Polk & Co.
	Shair Saml clk	R. L. Polk & Co.

2170 38TH ST

Year	Uses	Source
1962	Akerlind Mary E	New York Telephone Directory
1934	Zimmerman Mary E wid Morris	R. L. Polk & Co.

2171 38TH ST

Year	Uses	Source
1991	Hadjigavreil Thalia	NYNEX Information Resource Company
1962	McGeough Etta Mrs	New York Telephone Directory
1934	Mc Geough Etta w id Jas	R. L. Polk & Co.
	Mc Geough Jas clk	R. L. Polk & Co.
	Ryan Wm prsmn	R. L. Polk & Co.

2172 38TH ST

Year	Uses	Source
1983	New man Fredericka	New York Telephone
1970	New man Fredericka	New York Telephone
1967	New man Fredericka	New York Telephone
1962	New man Fredericka	New York Telephone Directory
1945	Akerlind Jack	New York Telephone
1934	Ackerlind Jack lab	R. L. Polk & Co.
	Akerlind Edw lab	R. L. Polk & Co.
	Akerlind Rubin Ruth pianomkr	R. L. Polk & Co.

2173 38TH ST

Year	Uses	Source
1991	Dibiase Rocco & Caterina	NYNEX Information Resource Company
1962	Kirw an John	New York Telephone Directory
1945	Danielson Gustave	New York Telephone
1939	Danielson Gustave	New York Telephone Company
1934	Danielson Gust Ave Alma const formn	R. L. Polk & Co.

Year	Uses	Source
1934	Danielson Ivy clk Mhn	R. L. Polk & Co.
	Johanns Lars lab	R. L. Polk & Co.

2174 38TH ST

Year	Uses	Source
1962	Viggiani Matilda	New York Telephone Directory
1945	Viggiani Matilda	New York Telephone
1934	Viggiani Alf Mathilde Ditmars Printing	R. L. Polk & Co.
	Viggiani Antoinette sten	R. L. Polk & Co.
	Viggiani Aug printer	R. L. Polk & Co.
	Viggiani Helen student	R. L. Polk & Co.
	Viggiani Venere drsmkr	R. L. Polk & Co.

2180 38TH ST

Year	Uses	Source
1991	Alaimo Calogero	NYNEX Information Resource Company
	Cocheo Gildo	NYNEX Information Resource Company
	Salvati D	NYNEX Information Resource Company
1983	Abadjian Grigori	New York Telephone
	Alaimo Calogero	New York Telephone
	Barrish F	New York Telephone
	Barrish L	New York Telephone
	Cocheo Gildo	New York Telephone
	Lowy Danl	New York Telephone
	Salvati D	New York Telephone
1976	Alaimo Calogero	New York Telephone
	Barrish Frances Mrs	New York Telephone
	Cocheo Gildo	New York Telephone
	Lowy Danl	New York Telephone
1970	Alaimo Calogero	New York Telephone
	Barrish Frances Mrs	New York Telephone
	Carrozza Albert Jr	New York Telephone
	Cocheo Gildo	New York Telephone
	DeLaPlata Henry M	New York Telephone

FINDINGS

Year	Uses	Source
1970	Lowy Danl	New York Telephone
1967	Alaimo Calogero	New York Telephone
	Barrish Frances Mrs	New York Telephone
	Chiominto Emilio	New York Telephone
	Cocheo Gildo	New York Telephone
	DeLaPlata Henry M	New York Telephone
	Lowy Danl	New York Telephone
	Regazzi Anne Marie Mrs	New York Telephone
1962	Alaimo Calogero	New York Telephone Directory
	Barrish Saml	New York Telephone Directory
	Cocheo Gildo	New York Telephone Directory
	LOWY DANL paintr paperhanger	New York Telephone Directory
1945	Berger Julius	New York Telephone
	Gold Morris	New York Telephone
	Nicham Franz	New York Telephone
	Shea Jas	New York Telephone
1939	Berger Julius	New York Telephone Company
	Berkowitz Howard	New York Telephone Company
	Bingham Frank	New York Telephone Company
	Gold Morris	New York Telephone Company
	Haas Siegfried	New York Telephone Company
	Shea Jas	New York Telephone Company
	Stein Aaron	New York Telephone Company
1934	Baumoehl Herman Regina slsmn	R. L. Polk & Co.
	Baumoehl Leo printer	R. L. Polk & Co.
	Baumoehl Sam	R. L. Polk & Co.
	Beaulieu Ernest Antoinette barber	R. L. Polk & Co.
	Beltrone Gene Mrs dencer	R. L. Polk & Co.
	Berkowitz Andrew student	R. L. Polk & Co.
	Bila Paul R Elizabeth claim agt	R. L. Polk & Co.
	Bingham Frank Sally porter	R. L. Polk & Co.
	Broeder Arth O acet	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Broeder Raymond L acct	R. L. Polk & Co.
	Burns Norma Mrs dancer	R. L. Polk & Co.
	Carr Harold Ella linemn	R. L. Polk & Co.
	Ditmars Court apt bldgs	R. L. Polk & Co.
	Friedland Max Lilian D sign pntr	R. L. Polk & Co.
	Frischmann Jos	R. L. Polk & Co.
	Harnett Edw Helen truck driver	R. L. Polk & Co.
	Hayward Anna mach opr	R. L. Polk & Co.
	Hayward Annie wid Harry	R. L. Polk & Co.
	Long Chas J elec eng	R. L. Polk & Co.
	Long Howard A	R. L. Polk & Co.
	Mc Brien Robt Laura slsmn	R. L. Polk & Co.
	Mc Cusker Thos W Margueriete clk	R. L. Polk & Co.
	Mirovsky Jos Carmela carp	R. L. Polk & Co.
	Mirovsky Ruth	R. L. Polk & Co.
	Nass Milderd	R. L. Polk & Co.
	Peters Fredk Mary chauf	R. L. Polk & Co.
	Reiss Anna wid Saml	R. L. Polk & Co.
	Rosenberg Jack clk	R. L. Polk & Co.
	Schons Nicholas Marguerite blgg supt	R. L. Polk & Co.
	Schussler John Emma barber	R. L. Polk & Co.
	Skydanek Bernard Augusta pharm	R. L. Polk & Co.
	Skydanek Bernard jr clk	R. L. Polk & Co.
	Skydanek Blasta	R. L. Polk & Co.
	Wrona Morris Sophie tailor	R. L. Polk & Co.
	Wrona Sarah clk	R. L. Polk & Co.

2181 38TH ST

Year	Uses	Source
1991	Busch C	NYNEX Information Resource Company
	Conway Michl J	NYNEX Information Resource Company
	Mobasser Mojgan	NYNEX Information Resource Company
	Prien Madia	NYNEX Information Resource Company

FINDINGS

Year	Uses	Source
1991	Sharkey Molly	NYNEX Information Resource Company
	Silvers Victor	NYNEX Information Resource Company
	Spininger Philip	NYNEX Information Resource Company
1983	Astrinidis Stavros	New York Telephone
	Busch C	New York Telephone
	Conway Michl J	New York Telephone
	Finkenthal L	New York Telephone
	Sharkey Molly	New York Telephone
1976	Busch C	New York Telephone
	Conway Michl J	New York Telephone
	Finkenthal L	New York Telephone
1970	Busch C	New York Telephone
	Cabinos Martha	New York Telephone
	Conway Michl J	New York Telephone
	Finkenthal L	New York Telephone
	Katz Solomon	New York Telephone
1967	Busch Charlotte	New York Telephone
	Conway Michi J	New York Telephone
	Finkenthal Minnie	New York Telephone
	Fischer Alex S	New York Telephone
	Marzano Dominick	New York Telephone
	Ryan Cornelius	New York Telephone
1962	Barrlaux Lucien J	New York Telephone Directory
	Callahan T	New York Telephone Directory
	Conway Michl J	New York Telephone Directory
	Fischer Alex S	New York Telephone Directory
	Katz Jerry	New York Telephone Directory
	Katz Solomon	New York Telephone Directory
	Marzano Dominick	New York Telephone Directory
	Wood Mary S	New York Telephone Directory
1945	Birnbaum Max	New York Telephone
	Busch Charlotte	New York Telephone

FINDINGS

Year	Uses	Source
1945	Conway Michl J	New York Telephone
	Marzano Dominick	New York Telephone
	Ratnoff Philip	New York Telephone
1939	Finnegan Jas Mrs	New York Telephone Company
	Gerking Helene	New York Telephone Company
	Ginsberg Alfred	New York Telephone Company
	Sternberg Siegbert	New York Telephone Company
1934	Ambarin Herounch Wid Artian	R. L. Polk & Co.
	Ambarin Jack Nevart lab	R. L. Polk & Co.
	Bondi Peter Maria stone ctr	R. L. Polk & Co.
	Calnan John Mae police	R. L. Polk & Co.
	DAndrea Maurice Ruby meat ctr	R. L. Polk & Co.
	Finkenthal Louis Minnie prntr	R. L. Polk & Co.
	Fisher Andrew W Bertha photo inshr	R. L. Polk & Co.
	Fuchs Chas Gezella Broadway Moving & Storage	R. L. Polk & Co.
	Hannon Anna tel opr	R. L. Polk & Co.
	Hannon Mary clk	R. L. Polk & Co.
	Hannon Michl Mary carp	R. L. Polk & Co.
	Hannon Rita clk	R. L. Polk & Co.
	Hoffman DAvid Eva slsmn	R. L. Polk & Co.
	Kiernan Helen	R. L. Polk & Co.
	Kiernan Thos Mary lab	R. L. Polk & Co.
	Kissman Robt Mary mach opr	R. L. Polk & Co.
	Lebenguth Eug Margt drftsmn	R. L. Polk & Co.
	Le Marier Albert Janet printer	R. L. Polk & Co.
	Litman Sol Jennie fish dlr	R. L. Polk & Co.
	Lorrin Camillo Madeline brklyr	R. L. Polk & Co.
	Lortie Jos Belida brklyr	R. L. Polk & Co.
	Markowitz Aaron Rebeca cooper	R. L. Polk & Co.
	Markowitz Abr musician	R. L. Polk & Co.
	Mc Coniff Michl Marion	R. L. Polk & Co.
	Mc Namara Loretta clk	R. L. Polk & Co.

FINDINGS

Year	Uses	Source
1934	Mc Namara Margt clk	R. L. Polk & Co.
	Mc Namara Mary w id Morris	R. L. Polk & Co.
	Olding Dorothy J editorial asst	R. L. Polk & Co.
	Olding Seraphine Mrs clk	R. L. Polk & Co.
	Olman John Erna auto mech	R. L. Polk & Co.
	Ratnoff Mortimer clk Mhn	R. L. Polk & Co.
	Russo Saml Helen clk	R. L. Polk & Co.
	Ryan Danl Irene lab	R. L. Polk & Co.
	Saracel Court Apartments	R. L. Polk & Co.
	Schoenfeld Abr Dora slsmn	R. L. Polk & Co.
	Seydel Felix Ida pntr	R. L. Polk & Co.
	Snyder Geo Caroline clk	R. L. Polk & Co.
	Stechler Mildred bkpr	R. L. Polk & Co.
	Steckler Jos F Bessie	R. L. Polk & Co.
	Steckler Sylvia sten	R. L. Polk & Co.
	Sullivan Jas L Anna M police	R. L. Polk & Co.
	Thornton John Lillian brklyr	R. L. Polk & Co.
	Volz Eug lab	R. L. Polk & Co.
	Wall Sidney Bertha uphol	R. L. Polk & Co.

2183 38TH ST

Year	Uses	Source
1939	Bain Mary	New York Telephone Company

FINDINGS

ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1201 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1201 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1201 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1202 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1204 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1206 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1206 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1206 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1206 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1208 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1209 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1211 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1212 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1214 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1214 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1214 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1214 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1215 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1217 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1217 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1218 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1218 37TH AVE FL 1	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1218 37TH AVE FL 2	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1221 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1221 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1245 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1266 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1272 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1287 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1301 37TH AV LIC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1306 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1306 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1307 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1310 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1314 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1315 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1319 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1333 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1333 37TH COLLEGE PT	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1401 36TH AV ABBREV L IC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AV ABBREV LI C	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1401 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1401 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1403 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1411 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1412 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1412 36TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1423 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1435 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1438 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1442 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1450 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1454 38 AV	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1455 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1500 36TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1729 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1759 36TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1801 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1801 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1805 38TH	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1806 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1807 38TH	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1807 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1811 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1813 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1815 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
1815 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1815 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1815 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1816 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1820 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1820 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
1833 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1835 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1850 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1902 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1902 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1902 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1902 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1902 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1919 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1919 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1919 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1931 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1935 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1935 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1935 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
1936 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1936 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1940 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1944 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1946 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1946 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1948 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1948 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1948 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1951 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1954 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1954 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
1954 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
1954 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
1954 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2001 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2001 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2001 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2001 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2002 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2002 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2002 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2002 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2002 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2002 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2002 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2003 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2003 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2003 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2004 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2004 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2004 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2004 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2005 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2006 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2006 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2006 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2007 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2007 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2007 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2007 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2007 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2008 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2008 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2009 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2009 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2009 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2009 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2009 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2010 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2010 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2010 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2011 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2011 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2011 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2011 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2011 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2012 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2012 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2012 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2012 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2012 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2012 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2013 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2013 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3633 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3633 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3633 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3635 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3636 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3636 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3637 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3637 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3638 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3638 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3639 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3639 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3639 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3639 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3639 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3640 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3640 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3640 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3640 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3640 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3640 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3640 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3640 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3642 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3642 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3644 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3644 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3650 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3650 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3651 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3652 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3666 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3687 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3701 21st	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1945, 1939, 1934, 1922
3701 21st street	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3701 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3702 12TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3702 12TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3702 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3702 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3702 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3703 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3704 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3704 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3704 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3704 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3704 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3706 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3706 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3707 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3708 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3708 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3709 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3709 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3709 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3709 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3710 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3710 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3710 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3710 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3710 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3710 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3711 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3711 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3711 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3711 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3711 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3711 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3711 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3711 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3711 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3711 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3711 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3711 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3712 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3712 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3712 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3712 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3712 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3712 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3712 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3712 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3712 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3712 2ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3713 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3713 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3713 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3713 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3714 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3714 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3714 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3714 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3714 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3714 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3714 22ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3714 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3714 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3715 12TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 12TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3715 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3715 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3716 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3716 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3716 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3716 23RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3716 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3716 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3717 12TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 12TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3717 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3717 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3717 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3717 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3717 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3717 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3718 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3718 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3718 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3718 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3718 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3718 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3718 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3719 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3719 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3719 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3719 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3719 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3719 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3719 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3719 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 12 LIC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 12ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3720 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3720 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2014 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2014 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2014 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2014 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2015 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2015 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2016 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2016 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2016 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2017 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2017 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2017 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2018 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2018 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2018 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2018 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2019 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2019 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2019 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2020 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2020 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2020 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2021 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2021 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2021 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2022 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2023 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2023 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2025 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2025 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2025 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2025 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2026 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2026 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2026 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2026 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2026 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2027 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2028 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2028 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2028 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2029 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2030 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2030 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2030 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2030 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2032 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2032 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2033 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2033 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2034 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2034 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2035 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2035 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2037 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2037 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2039 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2039 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2044 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2044 38D	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2054 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2056 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2056 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2056 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2058 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2058 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2058 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2058 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2058 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2059 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2059 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2060 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2060 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2062 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2062 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2062 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2062 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2065 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2066 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2066 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2066 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2066 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2067 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2067 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2067 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2067 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2067 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2068 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2068 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2068 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2068 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2068 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2068 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2068 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2070 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2070 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2070 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2075 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2101 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2102 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2103 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2103 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2104 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2105 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2105 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2105 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2105 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2105 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2106 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2107 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2107 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2107 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2107 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2107 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2107 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2107 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2108 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2109 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2109 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2109 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2109 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2109 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2109 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2109 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2109 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2110 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2110 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2110 38TH RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2111 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2111 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2111 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2111 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2111 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2112 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2112 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2112 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2112 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2113 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2113 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2113 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2113 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2113 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2114 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2114 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2114 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2114 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2114 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2114 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2114 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2114 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2115 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2115 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2115 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38th Avenue	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2115 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2115 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2116 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2116 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2116 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2116 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2116 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2117 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2117 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2117 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2117 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2118 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2118 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2118 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2118 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2118 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2119 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2119 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2119 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2119 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2119 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2119 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2119 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2120 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2120 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2120 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2120 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2121 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2121 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2121 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2121 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2121 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2121 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2122 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2122 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2122 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2122 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2122 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2122 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2122 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2123 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2123 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2123 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2123 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2123 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2123 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2123 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2123 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2124 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2124 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2124 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2124 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2124 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2124 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2124 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2124 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2124 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2125 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2125 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2125 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2125 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2125 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2126 36TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2126 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2126 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2126 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2126 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2127 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2127 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2127 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2128 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2128 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2128 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2128 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2129 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2129 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2129 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2129 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2129 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2129 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2129 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2129 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2130 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2130 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2130 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2130 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2130 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2130 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2130 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2130 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2131 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2131 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2131 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2131 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2131 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2132 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2132 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2132 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2132 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2132 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2132 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2132 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2133 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2133 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2133 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2133 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2133 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2133 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2133 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2134 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2134 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2134 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2135 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2135 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2135 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2136 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2136 36TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 36TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2136 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2136 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2137 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2137 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2137 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2137 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2137 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2137 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2137 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2137 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2138 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2138 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2138 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2138 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2138 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2138 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2139 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2139 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2139 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2139 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2139 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2140 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2140 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2140 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2140 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2140 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2140 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2140 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2141 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2141 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2141 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2142 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2142 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2142 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2142 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2142 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2143 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2143 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2143 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2143 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2143 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2143 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2144 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2144 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2144 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2144 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2144 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2144 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2144 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2144 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2145 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2145 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2145 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2145 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2145 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2146 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2146 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2146 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2146 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2147 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2147 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2147 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2148 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2148 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2148 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2149 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2149 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2149 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2149 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2150 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2150 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2150 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2150 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2150 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2150 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2150 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2150 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2150 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2151 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2151 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2151 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2151 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2151 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2152 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2152 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2152 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2153 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2153 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2153 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2153 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2153 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2153 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2153 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2154 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2154 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2154 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2154 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2154 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2154 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2154 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2154 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2154 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2155 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2155 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2155 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2155 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2155 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2156 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2156 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2156 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2156 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2157 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2157 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2157 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2157 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2158 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2158 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2158 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2158 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2159 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2159 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2159 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2159 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2159 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2159 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2159 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2160 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2160 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2160 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2160 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2160 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2161 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2161 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2161 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2161 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2161 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2161 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2162 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2162 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2162 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2162 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2162 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2163 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2163 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2163 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2163 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2163 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2163 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2164 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2164 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2164 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2164 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2164 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2165 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2165 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2165 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2165 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2165 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2165 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2166 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2166 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2166 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2167 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2167 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2167 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2167 38D	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2167 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2167 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2167 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2168 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2168 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2168 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2168 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2168 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2168 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2168 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2168 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2168 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2169 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2169 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2169 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2169 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2169 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2169 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2170 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2170 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2170 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2170 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2170 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2170 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2171 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2171 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2171 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2171 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2171 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2171 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2172 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2172 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2172 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2173 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2173 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2173 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2173 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2173 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2173 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2173 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2174 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2174 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2174 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2174 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2175 36TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2175 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2175 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2176 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2176 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2176 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2176 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2177 36TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2178 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2179 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2180 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2180 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2180 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2181 38TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2181 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2183 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2183 38TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2195 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2201 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2201 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2202 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2205 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2207 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2207 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2208 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2211 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2211 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2211 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2211 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2211 38TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2212 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2212 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2212 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2212 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2212 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2212 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2213 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2213 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2213 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2213 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2213 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2213 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2213 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2214 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2214 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2214 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2214 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2215 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2216 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2217 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2217 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2217 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2217 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2218 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2218 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2218 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2218 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2218 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2218 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2219 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2220 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2220 36TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2220 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2220 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2220 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2221 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2221 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2221 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2221 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2221 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2222 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2222 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2222 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2222 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2223 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2223 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2223 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2223 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2223 38TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2224 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2224 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2224 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2224 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2224 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2224 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2224 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2224 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2224 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2227 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2227 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2227 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2228 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2228 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2228 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2228 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2229 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2229 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2229 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2230 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2230 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2230 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2230 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2230 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2230 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2231 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2231 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2231 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2233 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2234 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2234 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2234 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2234 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2234 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2234 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2236 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2236 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2236 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2236 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2236 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2237 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2237 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2238 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2238 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2238 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2239 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2239 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2240 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2240 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2240 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2241 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2241 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2241 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2242 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2242 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2242 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2242 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2242 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2243 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2243 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2244 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2244 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2244 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2247 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2248 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2248 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2248 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2249 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2249 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2249 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2249 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2250 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2250 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2250 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2251 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2251 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2251 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2251 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2251 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2253 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2253 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2253 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2253 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2253 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2253 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2254 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2254 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2254 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2254 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2254 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2254 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2254 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2256 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2256 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2257 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2257 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2257 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2258 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2258 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2258 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2258 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2259 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2259 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2259 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2260 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2260 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2261 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2261 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2261 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2261 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2261 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2263 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2263 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2263 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2263 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2263 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2263 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2263 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2264 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2264 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2264 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2265 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2265 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2265 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2266 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2266 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2266 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2266 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2267 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2267 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2267 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2270 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2270 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2270 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2272 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2272 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2272 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2272 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2272 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2272 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2281 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2295 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2301 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2302 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2303 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2303 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2303 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2303 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2303 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2303 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2307 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2309 37TH AVE	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2309 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2311 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2311 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2313 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2313 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2315 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2315 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2315 37TH AVE	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2315 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2317 37TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2318 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2319 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2319 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2322 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2322 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2324 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2324 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2324 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2324 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2324 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2325 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2325 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2325 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2327 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2327 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2328 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2328 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2328 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2328 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2328 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2329 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2329 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2329 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2329 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2329 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2330 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2331 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2331 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2331 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2331 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2331 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2331 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2332 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2332 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2333 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2333 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2333 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2334 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2334 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2334 37TH AVE	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2334 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2334 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2336 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2336 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2336 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2337 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2337 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2337 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2337 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2338 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2338 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2339 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2339 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2339 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2340 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2340 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2341 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2341 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2341 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
2341 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2341 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2342 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2342 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2343 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2343 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2343 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2343 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2343 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2344 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2344 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2344 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2344 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2344 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2347 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2347 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2347 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2348 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2348 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2348 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2348 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2348 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
2349 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2349 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2349 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2350 37TH AVE	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2350 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2350 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2350 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2351 37TH AVE	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
2351 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
2351 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
2351 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
2351 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
2351 37TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3501 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3501 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3501 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3502 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3502 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3502 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3504 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3505 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3505 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3506 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3507 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3507 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3508 14TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3508 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3508 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3508 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3509 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3509 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3510 14TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3510 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3511 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3511 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3512 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3512 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3512 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3513 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3513 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3514 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3516 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3517 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3518 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3518 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3519 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3519 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3520 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3520 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3520 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3527 2ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3528 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3531 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3535 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3537 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3541 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3545 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3545 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3546 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3546 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3548 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3549 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3550 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3550 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3550 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3550 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3552 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3552 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3555 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3557 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3557 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3558 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3564 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3588 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3601 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3601 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3601 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14 LIC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3602 14TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3602 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3603 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3603 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3603 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3604 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3604 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3604 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3605 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 14TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3605 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3606 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3607 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3608 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3609 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3609 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3610 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3610 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3610 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 14TH AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3611 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22 ABBREV ASTORIA	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22IBAY SD 95242	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3611 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3611 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3612 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3613 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3613 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3614 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3614 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3614 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3614 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3614 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3614 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3615 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3615 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3615 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3615 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3616 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3616 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3617 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3617 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3617 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3617 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3617 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3617 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3617 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3617 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3618 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3618 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3618 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3619 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3619 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3619 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3619 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3619 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13 LIC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3620 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3620 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3620 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3621 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3621 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 14TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3622 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3623 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3623 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3623 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3624 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3624 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3625 12TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3625 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3625 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3625 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3625 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3625 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3626 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3628 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3629 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3630 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3630 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3630 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3630 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3630 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3630 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3630 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3630 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3630 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3630 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3630 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3631 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3631 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3632 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3720 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3720 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3720 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3720 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3720 22nd street	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3720 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3721 12TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 12TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3721 23RD RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3721 23RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 23RD ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 23RD ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 23RD ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3722 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3723 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3723 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3724 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3724 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3724 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 22ND ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3724 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3724 22nd street	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3726 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3728 13RD ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3728 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3728 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3728 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3728 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3731 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3731 23RD AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3732 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3732 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3732 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3732 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3734 14TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3734 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3734 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3735 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3735 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3735 21st street	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3738 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3740 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3741 13TH RD	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3741 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3742 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3744 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3744 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3744 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3744 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3745 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3752 23RD ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3752 23RD ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3782 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3783 13TH ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3792 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3801 13TH ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3801 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3801 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3801 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3802 22 LIC	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3802 22ND ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3803 21ST ST	2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3803 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3804 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3804 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3804 2ND AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3807 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3807 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3807 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3807 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3807 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3807 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3807 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3810 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3810 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3811 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3811 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3811 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3815 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3817 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1939, 1934, 1922
3817 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3817 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3817 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3819 21ST AVE	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3819 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3819 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3820 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3821 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3823 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922

FINDINGS

Address Researched	Address Not Identified in Research Source
3825 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3825 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1962, 1950, 1945, 1939, 1934, 1922
3826 21ST ST	2020, 2017, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3826 21ST ST	2020, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3826 21ST ST	2020, 2017, 2014, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3826 21ST ST	2020, 2017, 2014, 2010, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3826 21ST ST	2020, 2017, 2014, 2010, 2005, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1934, 1922
3837 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1934, 1922
3837 21ST ST	2020, 2017, 2014, 2010, 2005, 2000, 1996, 1995, 1992, 1991, 1983, 1976, 1970, 1967, 1962, 1950, 1945, 1939, 1922

TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

Address Researched	Address Not Identified in Research Source
3705 21st Street	1996, 1922

23-0454

3705 21st Street

Long Island City, NY 11101

Inquiry Number: 7390563.3

July 17, 2023

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

07/17/23

Site Name:

23-0454
3705 21st Street
Long Island City, NY 11101
EDR Inquiry # 7390563.3

Client Name:

Middleton Environmental Inc.
50 Park Avenue
Babylon, NY 11702
Contact: Sarah Heyne

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Middleton Environmental Inc. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 099A-4278-BB05

PO # 23-0454

Project 23-0454

Maps Provided:

2006	1994	1985	1915
2005	1993	1980	1898
2004	1992	1979	
2003	1991	1977	
2002	1990	1970	
2001	1989	1950	
1996	1988	1947	
1995	1986	1936	

Sanborn® Library search results

Certification #: 099A-4278-BB05

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Middleton Environmental Inc. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #	099A-4278-BB05
Copyright	2006

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 77
Volume 1, Sheet 76
Volume 1, Sheet 80

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #	099A-4278-BB05
Copyright	1996

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 76
Volume 1, Sheet 77

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #	099A-4278-BB05
Copyright	1986

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 77
Volume 1, Sheet 76
Volume 1, Sheet 80

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #:	099A-4278-BB05
Copyright	1977

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 76
Volume 1, Sheet 80
Volume 1, Sheet 77

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #	099A-4278-BB05
Copyright	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 77
Volume 1, Sheet 80

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #:	099A-4278-BB05
Copyright	1947

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 77
Volume 1, Sheet 80

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #:	099A-4278-BB05
Copyright	1936

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600





Volume 1, Sheet 80
Volume 1, Sheet 77

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #099A-4278-BB05

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #:	099A-4278-BB05
Copyright	1915

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 77

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	23-0454
Address:	3705 21st Street
City, ST, ZIP:	Long Island City, NY 11101
Client:	Middleton Environmental Inc.
EDR Inquiry:	7390563.3
Order Date:	07/17/2023
Certification #:	099A-4278-BB05
Copyright	1898

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 77
Volume 1, Sheet 80

N

12.7 Prior Environmental Reports

ASTEM LABORATORIES, INC.

ENVIROMENTAL ENGINEERING CONSULTANTS
AIR , WATER, SOIL, RADON, ASBESTOS, LEAD TESTING

223-14 114 Rd
Cambria Heights
Queens, NY 11411
Tel. (917) 497-0190

11712 S.W. 128th Pl.
Miami, Fl. 33186
Fax (305) 348-6007

October 20, 2003

Mr. Steven Sangesland,
Environmental Engineer I
Environmental Remediation Division
NYCDEC
47-40 21st Street
Long Island City, N.Y. 11101-5407

Re: Spill No. 0230068– LIC Used Auto Parts 37-25 21st Street, Long Island City, NY

Dear Mr. Sangesland:

Please be informed that ASTEM Laboratories, Inc. conducted an Environmental Site Assessment at the aforementioned property on June 16, 2003. Enclosed, please find the results of this investigation.

A copy of this report has also been sent to Ms. Virginia Lupoli of Yardly Associates LLC, P.O. Box 237, Cold Spring Harbor, New York 11724.

Please do not hesitate to contact me at (917) 497-0190 should you have any questions.

Sincerely,
ASTEM Laboratories, Inc.

Norman D.H. Munroe, Eng.Sc.D.
Technical Director

ANALYTICAL SYSTEMS & TECHNOLOGIES FOR ENVIROMENTAL MANAGEMENT

ENVIRONMENTAL SITE ASSESSMENT

FOR

LIC USED AUTO PARTS
SPILL NO. 0230068
37-25 21ST STREET
LONG ISLAND CITY, NEW YORK 11101

PREPARED BY

ASTEM LABORATORIES, INC.
11712 S.W. 128TH PLACE
MIAMI, FLORIDA 33186

ASTEM LABORATORIES, INC.

ASTEM LABORATORIES, INC.

ENVIROMENTAL ENGINEERING CONSULTANTS
AIR , WATER, SOIL, RADON, ASBESTOS, LEAD TESTING

223-14 114 Rd
Cambria Heights
Queens, NY 11411
Tel. (917) 497-0190

11712 S.W. 128th Pl
Miami, Fl 33186
Fax: (305) 348-6007

ENVIRONMENTAL SITE ASSESSMENT
LIC USED AUTO PARTS
SPILL NO. 0230068
37-25 21ST STREET
LONG ISLAND CITY, NEW YORK 11101

ASTEM PROJECT NUMBER: 2003-1

Technical Director

Dr. Norman D.H. Munroe
(917)-497-0190

September, 2003

Date:

TABLE OF CONTENTS

SECTION			PAGE
	EXECUTIVE SUMMARY		4
1.0	INTRODUCTION		6
2.0	SITE HISTORY		6
3.0	METHODS		7
	3.1	Soil Sampling	7
	3.2	Screening Tests for Volatile Hydrocarbons, (VOCs)	7
	3.3	Ground Water Sampling	8
4.0	RESULTS		8
	4.1	Ground Water Monitoring	8
	4.2	Soil Monitoring	9
5.0	CONCLUSION		10

LIST OF TABLES

TABLE		PAGE
1.	SUMMARY OF GROUNDWATER ANALYTICAL RESULTS	11
2.	SUMMARY OF SOIL ANALYTICAL RESULTS	12
3.	SUMMARY OF SOIL VAPOR PID RESULTS	13
4.	SUMMARY OF SOIL INORGANIC RESULTS-HEAVY METALS	14

APPENDICES

APPENDIX	PAGE
A. Sample Location Map - UST Area	
B. Water Analytical Reports	
C. Soil Analytical Reports	

EXECUTIVE SUMMARY

ASTEM Laboratories, Inc. was retained in June of 2003 to conduct an environmental site assessment at the premises located at 37-25 21st Street, Long Island City, New York. The purpose of the investigation was to determine whether any subsurface contamination occurred as a result of a reported spill, which occurred on March 11, 2003.

The aforementioned site has been an active "Auto Parts" facility for several years. The property is approximately 30,000 square feet and its entire surface is covered with concrete. In this investigation, a total of twelve soil samples were collected at various levels and sent to Chemtech Laboratory of 284 Sheffield Street, Mountainside, New Jersey for laboratory analyses. These samples were analyzed in the laboratory for aromatic volatile organics (BTEX petroleum hydrocarbon constituents) by EPA Method 8260, for semi-volatile hydrocarbons by EPA Method 8270 B/N and for heavy metals.

The results of the laboratory analysis on the soil samples indicate that each petroleum hydrocarbon constituent level was less than 0.7 parts per billion (ug/kg) except for some BTEX constituents (ethylbenzene and xylene) in soil taken from BH-2, BH-4 and BH-9. Nevertheless, the concentrations of BTEX in soil samples were generally below the regulatory limit.

The concentrations of volatile organics (BTEX) in water samples were also generally below the regulatory limit or undetected. An elevated concentration of benzene was found only in one water sample taken from the soil/water interface in BH-4. The water and soil analytical data are summarized in Tables 1 and 2. The only location where elevated levels of benzene, and MTBE were detected in the soil and water sample was obtained from BH-4.

Semi-volatile hydrocarbons in the soil and water samples were well below the regulatory limit. Most SVOCs constituents were undetected in most of the samples (see results in the appendix).

Heavy metal concentration in soil samples exceeded the regulatory limit, especially in the cases of lead, arsenic and cadmium and to a lesser extent chromium and copper.

The depth to groundwater at the subject site was estimated to occur at approximately 12 to 13 feet below grade. However, in the vicinity of BH-4, the depth to water was 6 feet. This appeared to be a small layer of perched water on the property. Based on the results of this environmental site assessment, there appears to be a small plume of perched water located at the rear of the property (using benzene concentration as the delineating parameter). Since this low level of contamination (2.7 ppb benzene) was located near to the surface at BH-4,

where there is a perched water layer, it appears to be an isolated location where surface water may have accumulated. No perched water was encountered at any other location on the property.

Although the depth of the concrete varied in thickness from between 8 inches to 2 feet, it appeared that ground coverage was complete and impervious to surface spills.

In the light of the results obtained in this investigation, it is recommended that no remediation is required at this time. Furthermore, based upon the fact that this type of activity has been conducted at the aforementioned site for approximately 60 years, the low level of contamination detected in the vicinity of BH-4 can be expected to degrade over time by microbially induced degradation.

1.0 INTRODUCTION

In June of 2003, ASTEM Laboratories, Inc. (ASTEM) was retained to conduct an Environmental Site Assessment at LIC Used Auto Parts, which is located at 37-25 21st Street, Long Island City, New York. The specific objectives of this site investigation were to determine the presence of any subsurface contamination and to delineate the extent of any contaminated groundwater.

On June 16, 2003, ASTEM requested the services of Clearwater Drilling of Patchogue, New York who utilized a Geo-Probe drilling rig to acquire soil and water samples from the subject site. Additional soil and water samples were also acquired by Summit Drilling of New Jersey on August 5, 2003.

2.0 SITE HISTORY

The aforementioned site has been an active "Auto Parts" facility for approximately 60 years and is owner by Yardly Associates, Inc. P.O. Box 237, Cold Spring Harbor, NY 11743. The property is approximately 30,000 square feet and its entire surface is covered with concrete. It consists of three parcels of land. The central area of the property appears to be the car dismantling area and happens to be the area where the spill occurred. The perimeter of the yard is lined primarily with automobile racks (3 cars high). A large number of engines, transmissions, various engine parts and multiple automobile batteries are usually on the premises.

A spill **(SPILL NO. 0230068)** was reported to the DEC on March 11, 2003. At the time of the ESA, the central area where the spilled auto fluids (oil, transmission fluids etc.) occurred was thoroughly cleaned. The concrete is this area was very thick. In fact in several locations, refusal occurred at the 2 foot level (see schematic diagram in the appendix). Although the depth of the concrete varied in thickness from between 8 inches to 2 feet, it appeared that ground coverage was complete and impervious to surface spills.

On August 5, 2003 and June 16, 2003, subsurface soil investigations were conducted by ASTEM. The following is a summary of the findings and subsequent field investigations by ASTEM:

1. A spill Investigation No. 0230068 was assigned on March 11, 2003 by the Department of Environmental Conservation.

2. On June 16, 2003, soil and samples were collected by Clearwater Drilling, Inc. from the property at various depths and analyzed for benzene, toluene, ethyl-benzene, xylenes, and MTBE. The analytical results indicated that no significant amount of petroleum constituents were present in the soil and water.

3. Additional Geo-probe sampling was conducted on August 5, 2003 by Summit Drilling, Inc. The analytical data of the water and soil are summarized in Tables 1 and 2, and the analytical reports are included in the Appendix.

4. Soil vapors emanating from the soil during the acquisition of soil samples from 5 foot levels within each borehole were analyzed for volatile organic compounds. The VOCs were measured with a Photo Ionization Detection (PID) unit. Only samples with the highest reading were sent to Chemtech Laboratory under strict chain-of-custody for analysis. The soil vapor PID results are summarized in Table 3.

3.0 METHODS

3.1 Soil Sampling

Soil samples were first taken at five foot intervals from each borehole. Samples were inspected for texture, moisture, color and evidence of contamination (see schematic diagram for locations in the Appendix). These samples were stored in coolers at or below 4°C and sent to the laboratory under strict chain-of-custody. These samples were tested for volatile organics by EPA method 8260 + Methyl Tertiary Butyl Ether (MTBE), EPA Method 8270 B/N and for heavy metals. The results of the soil analysis are presented in the Appendix.

3.2 Screening Tests for Total Volatile Hydrocarbons, (VOCS)

The total volatile organic compounds were measured using an HNU Photoionization Analyzer Model PI-101. The instrument was affixed with a 10.2 eV bulb, which is capable of detecting VOCs with an ionization potential of less than 10.2 eV. The Instrument was first calibrated by zeroing the meter while on standby mode. Once zeroed, the sensitivity switch is set to the 0 to 200 scale and the reading is calibrated against the contents of a compressed gas cylinder containing Span Gas supplied by HNU Systems, Inc. The calibration is periodically checked in order to insure that no significant drift had occurred.

Soil samples were placed into glass jars or zip-lock plastic bags with special care to prevent any escape of VOCs from the sample, and to maintain adequate headspace. The jars were labeled with the location number, depth of sample, and date of collection. In addition, the characteristics (color, odor, moisture, texture, density, consistency, layering) were logged in a notebook.

3.3 Groundwater Sampling

Groundwater samples were collected, by employing a pump, which was attached to the Geo-probe subsurface sampler. Samples were discharged into 40ml vials, which were tightly sealed with the omission of any bubbles or headspace.

4.0 RESULTS

4.1 GROUNDWATER MONITORING

The depth to groundwater at the subject site was estimated to occur at approximately 13 to 15 feet below grade. Groundwater movement appears to be in a westerly direction and follows the local topography. The concentrations of volatile organics (BTEX) in water samples were also generally below the regulatory limit or undetected. An elevated concentration of benezene was found only in one water sample taken from the soil/water interface in BH-4. The water and soil analytical data are summarized in Tables 1 and 2. The only location where elevated levels of benzene, and MTBE were detected in the soil and water sample was obtained from BH-4.

Semi-volatile hydrocarbons in the water were well below the regulatory limit. Most SVOCs constituents were undetected in BH-4, BH-5, BH-6, BH-7, BH-8 and BH-9 (see results in the appendix).

The analytical water data are summarized in Table 1 and the analytical results are included in Appendix B.

Based on the results of this site assessment, a plume (using benzene concentration as the delineating parameter) of an approximate radius of 20 feet exists at the subject site to the rear of the property.

4.2 SOIL MONITORING

The results of the laboratory analysis on the soil samples indicate that each petroleum hydrocarbon constituent level was less than 0.7 parts per billion (ug/kg) except for some BTEX constituents (ethylbenzene and xylene) in soil taken from BH-2, BH-4 and BH-9. Nevertheless, the concentrations of BTEX found in the soil samples were generally below the regulatory limit.

Semi-volatile hydrocarbons in the soil were well below the regulatory limit. Most SVOCs constituents were undetected in BH-4, BH-5, BH-6, BH-7, BH-8 and BH-9 (see results in the appendix).

Heavy metal concentration in soil samples exceeded the regulatory limit, especially in the cases of lead, arsenic and cadmium and to a lesser extent chromium and copper.

5.0 CONCLUSION

The following are conclusions made as a result of this environmental site assessment:

- The water analytical results revealed that BTEX constituents, as well as MTBE and naphthalene were generally below the regulatory limit except for BH-4.
- The soil analytical results revealed that BTEX constituents, as well as MTBE and naphthalene were generally below the regulatory limit except for BH-4.
- Static water level was estimated to range from 13 feet to 16 feet below grade except for a perched water layer in the vicinity of BH-4.
- The spilled auto fluids (oil, transmission fluids etc.) in the central area of the property were thoroughly cleaned.
- Based on the results of this site assessment, a plume (using benzene concentration as the delineating parameter) of an approximate radius of 20 feet exists perched at a depth of 6 feet from the surface to the rear of the subject site.
- Heavy metal concentration in soil samples exceed the regulatory limit, especially in the cases of lead, arsenic and cadmium.
- Although the depth of the concrete varied in thickness from between 8 inches to 2 feet, it appeared that ground coverage was complete and impervious to surface spills.
- In the light of the results obtained in this investigation, and based upon the fact that this type of activity has been conducted at the aforementioned site for approximately 60 years, the low level of contamination detected in the vicinity of BH-4 can be expected to degrade over time by microbially induced degradation.

TABLE 1

SUMMARY OF GROUNDWATER ANALYTICAL RESULTS
Premises located at
37-25 21st street
Long Island City, New York

All Concentrations in parts per billion (ppb)
(unless otherwise noted)

Borehole ID	Sample Date	Benzene	Toluene	Ethyl-benzene	Total Xylene	MTBE	Napth
BH-1	06/16/03	U	U	U	U	8.9	U
BH-2	06/16/03	U	U	U	U	6.1	U
BH-4	06/16/03	2.7	2.2	2.3	10.1	120	2.7
BH-5	06/16/03	U	U	U	U	U	U
BH-6	08/05/03	U	U	U	<2.2	13	35
BH-8	08/05/03	U	U	U	<2.2	9.4	U
BH-9	08/05/03	U	U	U	<7.8	18	4.5
BH-10	08/05/03	U	U	U	<7.8	19	8.0
NYSDEC		**0.7**	**5.0**	**5.0**	**15.0**	~~50~~ 10	**10**

MTBE = Methyl tertiary-butyl ether

TABLE 2

SUMMARY OF SOIL ANALYTICAL RESULTS
Premises located at
37-25 21st street
Long Island City, New York

All Concentrations in parts per billion (ppb)
(unless otherwise noted)

Borehole ID	Sample Date	Benzene	Toluene	Ethyl-benzene	Xylene	MTBE	Napth
BH-1	06/16/03	U	U	U	U	U	U
BH-2	06/16/03	U	U	4.7	6.2	U	U
BH-4	06/16/03	U	U	170	264	200	53
BH-5A	06/16/03	U	U	U	U	U	U
BH-9	08/05/03	<1.1	4.7	<1.1	7.0	U	15
NYSDEC		**14**	**100**	**100**	**100**	**1000**	**200**

MTBE = Methyl tertiary-butyl ether

TABLE 3

SUMMARY OF SOIL VAPOR PID RESULTS
37-25 21st street
Long Island City, New York

VOA Concentrations in Meter Readings
(unless otherwise noted)

Depth (feet)	BH-1	BH-2	BH-4	BH-5
5	U	U	U	U
10	U	U5	U	5
15	U	U	U	U

VOA = Volatile Organic Aromatics

TABLE 4

SUMMARY OF INORGANIC ANALYSIS - METAL RESULTS
37-25 21st street
Long Island City, New York
Concentration expresses as mg/kg, (ppm)

Borehole	Sb	As	Be	Cd	Cr	Cu	Pb	Hg	Ni	Se	Ag	Th	Zn
BH-6	1.9	2.7	0.15	0.13	5.2	23.6	1720	0.06	6.4	0.44	0.29	0.33	347
BH-7	127	16.8	0.16	24.8	32.9	3470	2190	0.66	161	0.44	2.3	0.33	6940
BH-9	1.6	17.7	0.23	0.12	14.8	64.4	480	0.24	12.8	0.43	0.28	0.32	227
RCRA Limit		5.0		1.0	5.0		5.0	0.2		1.0	5.0		

APPENDIX A

Sample Location Map



New York 917-497-0190
Florida (305) 388-1317 Fax (305) 348 6007

CLIENT: 37-25 21st street
Long Island City, NY

PROJECT TITLE: ~~LSD UNDERGROUND TANKS~~

DRAWING TITLE: Plan Layout

PROJECT MANAGER	DRAWN BY
Dr. Norman Munroe	M.CROSS

DATE	SCALE	PROJECT NO.	DRAWING NO.
10-20-03	1" = 20 '		

APPENDIX B

Water Analytical Reports

CHEMTECH

CHAIN OF CUSTODY RECORD

284 Sheffield Street, Mountainside, NJ 07092
(908) 789-8900 Fax (908) 789-8922
www.chemtech.net

CHEMTECH JOB NO.: K2982
CHEMTECH QUOTE NO.:

CLIENT INFORMATION

REPORT TO BE SENT TO:

COMPANY: 4 STEM LABORATORIES
ADDRESS: 11712 S.W. 128 PL.
CITY: MIAMI STATE: FL. ZIP: 33186
ATTENTION: DR. NORMAN MUNROE
PHONE: (305) 348-3556 FAX: 305-348-6007

PROJECT INFORMATION

PROJECT NAME: JUNK YARD.
37-25 21st St. L.I.C
PROJECT NO.: LOCATION: N.Y.
PROJECT MANAGER:
E-MAIL:
PHONE: FAX:

BILLING INFORMATION

BILL TO: PO #:
ADDRESS: SAME
CITY: STATE: ZIP:
ATTENTION: PHONE:

DATA TURNAROUND INFORMATION

FAX: 7 DAYS *
HARD COPY: DAYS *
EDD: DAYS *
* TO BE APPROVED BY CHEMTECH
** NORMAL TURNAROUND TIME - 14 DAYS

DATA DELIVERABLE INFORMATION

☒ RESULTS ONLY ☐ USEPA CLP
☐ RESULTS + QC ☐ NYS ASP "B"
☐ NJ REDUCED ☐ NYS ASP "A"
☐ NJ CLP ☐ EDD
☐ EDD FORMAT:

ANALYSIS

	1	2	3	4	5	6	7	8	9
	8021+MTBE	8021 TMTBE	8021+MTBE	8021+MTBE	8270/BN	8270/BN	8021+MTBE	8021 TMTBE	

PRESERVATIVES

COMMENTS

← Specify Preservatives
A – HCl B – HNO_3
C – H_2SO_4 D – NaOH
E – ICE F – Other

CHEMTECH SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE COMP	SAMPLE TYPE GRAB	SAMPLE COLLECTION DATE	SAMPLE COLLECTION TIME	# OF BOTTLES	1	2	3	4	5	6	7	8	9
1. BH-1		L			6/16	10:00	2	X								
2. BH-2		L			"	10:30	2		X	X						
3. BH-4		L			"	11:00	2			X						
4. BH-5		L			"	11:30	2				X					
5. BH-4		L			"	1:00	1					X				
6. BH-5		L			"	1:30	1						X			
7. BH-[illegible]		S			"	[illegible]	1							X		
8. BH-3		S			"	[illegible]	1								X	

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY

RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:
1. N. MUNROE	6/19/2003 5:30	1.
RELINQUISHED BY:	DATE/TIME:	RECEIVED BY:
2.		2.
RELINQUISHED BY:	DATE/TIME: 6/19/03 1730	RECEIVED FOR LAB BY:
3.		3. Sunny Patel

Conditions of bottles or coolers at receipt: ☒ Compliant ☐ Non-Compliant ☐ Temp. of Cooler 3
MeOH extractions requires an additional 4oz. jar for percent solid.
Comments:

Page ____ of ____

Shipped Via: Client ☐ Hand Delivered ☐ Overnight
Chemtech ☐ Picked Up ☐ Overnight

Shipment Complete ☐ Yes ☐ No

Ver. 9/2002

WHITE – CHEMTECH COPY FOR RETURN TO CLIENT YELLOW – CHEMTECH COPY PINK – SAMPLER COPY

34863

CHEMTECH

284 Sheffield Street Mountainside NJ 07092
Tel. 908-789-8900 Fax: 908-789-8922

DATA REPORTING QUALIFIERS- ORGANIC

For reporting results, the following " Results Qualifiers" are used:

Value	If the result is a value greater than or equal to the detection limit, report the value
U	Indicates the compound was analyzed for but was not detected. Report the minimum detection limit for the sample with the U, i.e. "10 U". This is not necessarily the instrument detection limit attainable for this particular sample based on any concentration or dilution that may have been required.
J	Indicates an estimated value. This flag is used: (1) When estimating a concentration for a tentatively identified compound (library search hits, where a 1:1 response is assumed.) (2) When the mass spectral data indicated the identification, however the result was less than the specified detection limit greater than zero. If the detection limit was 10ug/L and a concentration of 3 ug/L was calculated report as 3 J. This is flag is used when similar situation arise on any organic parameter i.e. Pest, PCB and others.
B	Indicates the analyte was found in the blank as well as the sample report as "12 B".
E	Indicates the analyte 's concentration exceeds the calibrated range of the instrument for that specific analysis.
D	This flag identifies all compounds identified in an analysis at a secondary dilution factor.
P	This flag is used for Pesticide/PCB target analyte when there is >25% difference for detected concentrations between the two GC columns. The lower of the two values is reported on Form 1 and flagged with a "P".
N	This flag indicates presumptive evidence of a compound. This is only used for tentatively identified compounds (TICs), where the identification is based on a mass spectral library search. It applies to all TIC results. For generic characterization of a TIC, such as chlorinated hydrocarbon, the flag is not used.
A	This flag indicates that a Tentatively Identified Compound is a suspected aldol-condensation product.

QA REVIEW GENERAL DOCUMENTATION

Project #: R2982

	Completed
For thorough review, the report must have the following:	
GENERAL:	
Are all original paperwork present (chain of custody, record of communication, airbill, sample management lab chronicle, login page)	✓
Check chain-of-custody for proper relinquish/return of samples	✓
Is the chain of custody signed and complete	✓
Check internal chain-of-custody for proper relinquish/return of samples /sample extracts	✓
Collect information for each project id from server. Were all requirements followed	✓
COVER PAGE:	
Do numbers of samples correspond to the number of samples in the Chain of Custody and on login page	✓
Do lab numbers and client Ids on cover page agree with the Chain of Custody	✓
CHAIN OF CUSTODY:	
Do requested analyses on Chain of Custody agree with form I results	✓
Do requested analyses on Chain of Custody agree with the log-in page	✓
Were the correct method log-in for analysis according to the Analytical Request and Chain of Custody	✓
Were the samples received within hold time	✓
Were any problems found with the samples at arrival recorded in the Sample Management Laboratory Chronicle	✓

Non – Conformance /Comments:

1st Level QA Review Signature: Babal Sellers Date: 7/1/03

2nd Level QA Review Signature: [illegible] Date: 7/1/03

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-1
LAB ID: R2982-01
FILENAME: F:\DATA1\U062605.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIERS	MDL (ug/L)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.0
74-87-3	CHLOROMETHANE	U		1.0
75-01-4	VINYL CHLORIDE	U		1.0
74-97-5	BROMOMETHANE	U		1.0
75-00-3	CHLOROETHANE	U		1.0
75-69-4	TRICHLOROFLOUROMETHANE	U		1.0
75-35-4	1,1 DICHLOROETHENE	U		1.0
75-09-2	METHYLENE CHLORIDE	U		1.0
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.0
75-34-3	1,1 DICHLOROETHANE	U		1.0
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.0
67-66-3	CHLOROFORM	U		1.0
74-97-5	BROMOCHLOROMETHANE	U		1.0
71-55-6	1,1,1 TRICHLOROETHANE	U		1.0
563-58-6	1,1 DICHLOROPROPENE	U		1.0
56-23-5	CARBON TETRACHLORIDE	U		1.0
107-06-2	1,2 DICHLOROETHANE	U		1.0
79-01-6	TRICHLOROETHENE	U		1.0
78-87-5	1,2 DICHLOROPROPANE	U		1.0
75-27-4	BROMODICHLOROMETHANE	U		1.0
74-95-3	DIBROMOMETHANE	U		1.0
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.0
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.0
630-20-6	1,1,2-TRICHLOROETHANE	U		1.0
142-28-9	1,3 DICHLOROPROPANE	U		1.0
127-18-4	TETRACHLOROETHENE	U		1.0
75-27-4	DIBROMOCHLOROMETHANE	U		1.0
106-93-4	1,2 DIBROMOETHANE	U		1.0
108-90-7	CHLOROBENZENE	U		1.0
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.0
75-25-2	BROMOFORM	U		1.0
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.0
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.0
108-86-1	BROMOBENZENE	U		1.0
95-49-8	2, CHLOROTOLUENE	U		1.0
106-34-4	4, CHLOROTOLUENE	U		1.0
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-1
LAB ID: R2982-01
FILENAME: F:\DATA1\V062605.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIER	MDL (ug/L)
75-35-4	1,1 DICHLOROETHENE	U		1.0
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	8.9		1.0
71-43-2	BENZENE	U		1.0
108-88-3	TOLUENE	U		1.0
100-41-4	ETHYLBENZENE	U		1.0
136777-61-2	M&P XYLENES	U		2.0
95-47-6	O-XYLENE	U		1.0
100-42-5	STYRENE	U		1.0
98-82-8	ISOPROPYLBENZENE	U		1.0
103-65-1	n-PROPYLBENZENE	U		1.0
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.0
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.0
98-06-6	TERT-BUTYLBENZENE	U		1.0
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.0
135-98-8	SEC-BUTYLBENZENE	U		1.0
541-73-1	1,3 DICHLOROBENZENE	U		1.0
99-87-6	ISOPROPYLTOLUENE	U		1.0
106-46-7	1,4 DICHLOROBENZENE	U		1.0
104-51-8	n-BUTYLBENZENE	U		1.0
95-50-1	1,2 DICHLOROBENZENE	U		1.0
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
91-20-3	NAPHTHALENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-2
LAB ID: R2982-02
FILENAME: F:\DATA1\U062606.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIERS	MDL (ug/L)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.0
74-87-3	CHLOROMETHANE	U		1.0
75-01-4	VINYL CHLORIDE	U		1.0
74-97-5	BROMOMETHANE	U		1.0
75-00-3	CHLOROETHANE	U		1.0
75-69-4	TRICHLOROFLOUROMETHANE	U		1.0
75-35-4	1,1 DICHLOROETHENE	U		1.0
75-09-2	METHYLENE CHLORIDE	U		1.0
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.0
75-34-3	1,1 DICHLOROETHANE	U		1.0
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.0
67-66-3	CHLOROFORM	U		1.0
74-97-5	BROMOCHLOROMETHANE	U		1.0
71-55-6	1,1,1 TRICHLOROETHANE	U		1.0
563-58-6	1,1 DICHLOROPROPENE	U		1.0
56-23-5	CARBON TETRACHLORIDE	U		1.0
107-06-2	1,2 DICHLOROETHANE	U		1.0
79-01-6	TRICHLOROETHENE	U		1.0
78-87-5	1,2 DICHLOROPROPANE	U		1.0
75-27-4	BROMODICHLOROMETHANE	U		1.0
74-95-3	DIBROMOMETHANE	U		1.0
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.0
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.0
630-20-6	1,1,2-TRICHLOROETHANE	U		1.0
142-28-9	1,3 DICHLOROPROPANE	U		1.0
127-18-4	TETRACHLOROETHENE	U		1.0
75-27-4	DIBROMOCHLOROMETHANE	U		1.0
106-93-4	1,2 DIBROMOETHANE	U		1.0
108-90-7	CHLOROBENZENE	U		1.0
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.0
75-25-2	BROMOFORM	U		1.0
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.0
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.0
108-86-1	BROMOBENZENE	U		1.0
95-49-8	2, CHLOROTOLUENE	U		1.0
106-34-4	4, CHLOROTOLUENE	U		1.0
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-2
LAB ID: R2982-02
FILENAME: F:\DATA1\V062606.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIER	MDL (ug/L)
75-35-4	1,1 DICHLOROETHENE	U		1.0
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	6.1		1.0
71-43-2	BENZENE	U		1.0
108-88-3	TOLUENE	U		1.0
100-41-4	ETHYLBENZENE	U		1.0
136777-61-2	M&P XYLENES	U		2.0
95-47-6	O-XYLENE	U		1.0
100-42-5	STYRENE	U		1.0
98-82-8	ISOPROPYLBENZENE	U		1.0
103-65-1	n-PROPYLBENZENE	U		1.0
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.0
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.0
98-06-6	TERT-BUTYLBENZENE	U		1.0
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.0
135-98-8	SEC-BUTYLBENZENE	U		1.0
541-73-1	1,3 DICHLOROBENZENE	U		1.0
99-87-6	ISOPROPYLTOLUENE	U		1.0
106-46-7	1,4 DICHLOROBENZENE	U		1.0
104-51-8	n-BUTYLBENZENE	U		1.0
95-50-1	1,2 DICHLOROBENZENE	U		1.0
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
91-20-3	NAPHTHALENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-4
LAB ID: R2982-03
FILENAME: F:\DATA1\U062607.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIERS	MDL (ug/L)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.0
74-87-3	CHLOROMETHANE	U		1.0
75-01-4	VINYL CHLORIDE	U		1.0
74-97-5	BROMOMETHANE	U		1.0
75-00-3	CHLOROETHANE	U		1.0
75-69-4	TRICHLOROFLOUROMETHANE	U		1.0
75-35-4	1,1 DICHLOROETHENE	U		1.0
75-09-2	METHYLENE CHLORIDE	U		1.0
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.0
75-34-3	1,1 DICHLOROETHANE	U		1.0
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.0
67-66-3	CHLOROFORM	U		1.0
74-97-5	BROMOCHLOROMETHANE	U		1.0
71-55-6	1,1,1 TRICHLOROETHANE	U		1.0
563-58-6	1,1 DICHLOROPROPENE	U		1.0
56-23-5	CARBON TETRACHLORIDE	U		1.0
107-06-2	1,2 DICHLOROETHANE	U		1.0
79-01-6	TRICHLOROETHENE	U		1.0
78-87-5	1,2 DICHLOROPROPANE	U		1.0
75-27-4	BROMODICHLOROMETHANE	U		1.0
74-95-3	DIBROMOMETHANE	U		1.0
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.0
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.0
630-20-6	1,1,2-TRICHLOROETHANE	U		1.0
142-28-9	1,3 DICHLOROPROPANE	U		1.0
127-18-4	TETRACHLOROETHENE	U		1.0
75-27-4	DIBROMOCHLOROMETHANE	U		1.0
106-93-4	1,2 DIBROMOETHANE	U		1.0
108-90-7	CHLOROBENZENE	70		1.0
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.0
75-25-2	BROMOFORM	U		1.0
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.0
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.0
108-86-1	BROMOBENZENE	U		1.0
95-49-8	2, CHLOROTOLUENE	U		1.0
106-34-4	4, CHLOROTOLUENE	U		1.0
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-4
LAB ID: R2982-03
FILENAME: F:\DATA1\V062607.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIER	MDL (ug/L)
75-35-4	1,1 DICHLOROETHENE	U		1.0
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	120		1.0
71-43-2	BENZENE	2.7		1.0
108-88-3	TOLUENE	2.2		1.0
100-41-4	ETHYLBENZENE	2.3		1.0
136777-61-2	M&P XYLENES	4.3		2.0
95-47-6	O-XYLENE	5.8		1.0
100-42-5	STYRENE	U		1.0
98-82-8	ISOPROPYLBENZENE	U		1.0
103-65-1	n-PROPYLBENZENE	U		1.0
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.0
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	3.5		2.0
98-06-6	TERT-BUTYLBENZENE	U		1.0
95-63-6	1,2,4-TRIMETHYLBENZENE	2.4		1.0
135-98-8	SEC-BUTYLBENZENE	1.9		1.0
541-73-1	1,3 DICHLOROBENZENE	U		1.0
99-87-6	ISOPROPYLTOLUENE	U		1.0
106-46-7	1,4 DICHLOROBENZENE	U		1.0
104-51-8	n-BUTYLBENZENE	1.5		1.0
95-50-1	1,2 DICHLOROBENZENE	10		1.0
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
91-20-3	NAPHTHALENE	2.7		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5
LAB ID: R2982-04
FILENAME: F:\DATA1\U062608.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIERS	MDL (ug/L)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.0
74-87-3	CHLOROMETHANE	U		1.0
75-01-4	VINYL CHLORIDE	U		1.0
74-97-5	BROMOMETHANE	U		1.0
75-00-3	CHLOROETHANE	U		1.0
75-69-4	TRICHLOROFLOUROMETHANE	U		1.0
75-35-4	1,1 DICHLOROETHENE	U		1.0
75-09-2	METHYLENE CHLORIDE	U		1.0
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.0
75-34-3	1,1 DICHLOROETHANE	U		1.0
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.0
67-66-3	CHLOROFORM	U		1.0
74-97-5	BROMOCHLOROMETHANE	U		1.0
71-55-6	1,1,1 TRICHLOROETHANE	U		1.0
563-58-6	1,1 DICHLOROPROPENE	U		1.0
56-23-5	CARBON TETRACHLORIDE	U		1.0
107-06-2	1,2 DICHLOROETHANE	U		1.0
79-01-6	TRICHLOROETHENE	U		1.0
78-87-5	1,2 DICHLOROPROPANE	U		1.0
75-27-4	BROMODICHLOROMETHANE	U		1.0
74-95-3	DIBROMOMETHANE	U		1.0
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.0
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.0
630-20-6	1,1,2-TRICHLOROETHANE	U		1.0
142-28-9	1,3 DICHLOROPROPANE	U		1.0
127-18-4	TETRACHLOROETHENE	U		1.0
75-27-4	DIBROMOCHLOROMETHANE	U		1.0
106-93-4	1,2 DIBROMOETHANE	U		1.0
108-90-7	CHLOROBENZENE	U		1.0
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.0
75-25-2	BROMOFORM	U		1.0
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.0
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.0
108-86-1	BROMOBENZENE	U		1.0
95-49-8	2, CHLOROTOLUENE	U		1.0
106-34-4	4, CHLOROTOLUENE	U		1.0
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5
LAB ID: R2982-04
FILENAME: F:\DATA1\V062608.RAW
BATCH: LB22363

MATRIX: AQUEOUS
DATE ANALYZED: 6/26/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/L)	QUALIFIER	MDL (ug/L)
75-35-4	1,1 DICHLOROETHENE	U		1.0
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	U		1.0
71-43-2	BENZENE	U		1.0
108-88-3	TOLUENE	U		1.0
100-41-4	ETHYLBENZENE	U		1.0
136777-61-2	M&P XYLENES	U		2.0
95-47-6	O-XYLENE	U		1.0
100-42-5	STYRENE	U		1.0
98-82-8	ISOPROPYLBENZENE	U		1.0
103-65-1	n-PROPYLBENZENE	U		1.0
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.0
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.0
98-06-6	TERT-BUTYLBENZENE	U		1.0
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.0
135-98-8	SEC-BUTYLBENZENE	U		1.0
541-73-1	1,3 DICHLOROBENZENE	U		1.0
99-87-6	ISOPROPYLTOLUENE	U		1.0
106-46-7	1,4 DICHLOROBENZENE	U		1.0
104-51-8	n-BUTYLBENZENE	U		1.0
95-50-1	1,2 DICHLOROBENZENE	U		1.0
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.0
87-68-3	HEXACHLOROBUTADIENE	U		1.0
91-20-3	NAPHTHALENE	U		1.0

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID: R2982-05 Client ID: BH-4

Date Collected: 6/16/03 Date Received: 6/19/03
Date Analyzed: 6/24/03 Matrix: WATER
Date Extracted: 6/24/03 File ID: BC006559.D
Dilution: 1 Instrument ID: BNAC
Analytical Method: 8270 Analytical Run ID: BC060303
Sample Wt/Vol: 960.0 Extract Vol: 1000
Injection Vol: 2 % Moisture: 100
Associated Blank: PB062503-13B

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
is(2-Chloroethyl)ether	111-44-4	< 1.2	U	10	1.2	ug/L
2-Dichlorobenzene	95-50-1	< 1.0	U	10	1.0	ug/L
,3-Dichlorobenzene	541-73-1	< 1.2	U	10	1.2	ug/L
4-Dichlorobenzene	106-46-7	< 1.0	U	10	1.0	ug/L
2-oxybis(1-Chloropropane)	108-60-1	< 1.0	U	10	1.0	ug/L
N-Nitroso-di-n-propylamine	621-64-7	< 1.0	U	10	1.0	ug/L
exachloroethane	67-72-1	< 1.1	U	10	1.1	ug/L
itrobenzene	98-95-3	< 1.0	U	10	1.0	ug/L
sophorone	78-59-1	< 1.0	U	10	1.0	ug/L
s(2-Chloroethoxy)methane	111-91-1	< 1.0	U	10	1.0	ug/L
,2,4-Trichlorobenzene	120-82-1	< 1.2	U	10	1.2	ug/L
laphthalene	91-20-3	3.1	J	10	1.2	ug/L
Chloroaniline	106-47-8	< 1.2	U	10	1.2	ug/L
exachlorobutadiene	87-68-3	< 1.6	U	10	1.6	ug/L
-Methylnaphthalene	91-57-6	< 1.2	U	10	1.2	ug/L
xachlorocyclopentadiene	77-47-4	< 4.0	U	10	4.0	ug/L
-Chloronaphthalene	91-58-7	< 1.2	U	10	1.2	ug/L
Nitroaniline	88-74-4	< 1.0	U	10	1.0	ug/L
methylphthalate	131-11-3	< 1.0	U	10	1.0	ug/L
cenaphthylene	208-96-8	< 1.2	U	10	1.2	ug/L
-Dinitrotoluene	606-20-2	< 1.0	U	10	1.0	ug/L
itroaniline	99-09-2	< 1.2	U	10	1.2	ug/L
cenaphthene	83-32-9	1.2	J	10	1.0	ug/L
enzofuran	132-64-9	< 1.0	U	10	1.0	ug/L
Dinitrotoluene	121-14-2	< 1.1	U	10	1.1	ug/L
iethylphthalate	84-66-2	< 1.0	U	10	1.0	ug/L
hlorophenyl-phenylether	7005-72-3	< 1.2	U	10	1.2	ug/L
orene	86-73-7	< 1.1	U	10	1.1	ug/L
-Nitroaniline	100-01-6	< 2.5	U	10	2.5	ug/L
itrosodiphenylamine	86-30-6	< 2.1	U	10	2.1	ug/L
obenzene	122-66-7	< 0.340	U	10	0.340	ug/L

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID:	R2982-05	Client ID:	BH-4
Date Collected:	6/16/03	Date Received:	6/19/03
Date Analyzed:	6/24/03	Matrix:	WATER
Date Extracted:	6/24/03	File ID:	BC006559.D
Dilution:	1	Instrument ID:	BNAC
Analytical Method:	8270	Analytical Run ID:	BC060303
Sample Wt/Vol:	960.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB062503-13B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
Bromophenyl-phenylether	101-55-3	< 1.4	U	10	1.4	ug/L
Hexachlorobenzene	118-74-1	< 1.1	U	10	1.1	ug/L
Phenanthrene	85-01-8	2.7	J	10	1.0	ug/L
Anthracene	120-12-7	< 1.4	U	10	1.4	ug/L
Di-n-butylphthalate	84-74-2	1.9	JB	10	1.2	ug/L
Fluoranthene	206-44-0	1.5	J	10	1.0	ug/L
Pyrene	129-00-0	1.4	J	10	1.0	ug/L
Butylbenzylphthalate	85-68-7	< 1.0	U	10	1.0	ug/L
3,3-Dichlorobenzidine	91-94-1	< 1.0	U	21	1.0	ug/L
Benzo(a)anthracene	56-55-3	< 1.0	U	10	1.0	ug/L
Chrysene	218-01-9	< 1.7	U	10	1.7	ug/L
bis(2-Ethylhexyl)phthalate	117-81-7	2.2	JB	10	1.0	ug/L
Di-n-octyl phthalate	117-84-0	< 1.6	U	10	1.6	ug/L
Benzo(b)fluoranthene	205-99-2	< 1.0	U	10	1.0	ug/L
Benzo(k)fluoranthene	207-08-9	< 2.7	U	10	2.7	ug/L
Benzo(a)pyrene	50-32-8	< 1.6	U	10	1.6	ug/L
Indeno(1,2,3-cd)pyrene	193-39-5	< 1.7	U	10	1.7	ug/L
Dibenz(a,h)anthracene	53-70-3	< 1.6	U	10	1.6	ug/L
Benzo(g,h,i)perylene	191-24-2	< 1.4	U	10	1.4	ug/L
SURROGATES						
Nitrobenzene-d5	4165-60-0	160.86	80 %	35 - 114		SPK: 200
2-Fluorobiphenyl	321-60-8	150.42	75 %	43 - 116		SPK: 200
Terphenyl-d14	1718-51-0	116.89	58 %	33 - 141		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	123636	4.84			
Naphthalene-d8	1146-65-2	422123	6.87			
Acenaphthene-d10	15067-26-2	210158	9.96			
Phenanthrene-d10	1517-22-2	312887	12.65			
Chrysene-d12	1719-03-5	309980	17.50			
Perylene-d12	1520-96-3	317597	19.98			

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID:	R2982-06	Client ID:	BH-5
Date Collected:	6/16/03	Date Received:	6/19/03
Date Analyzed:	6/24/03	Matrix:	WATER
Date Extracted:	6/24/03	File ID:	BC006560.D
Dilution:	1	Instrument ID:	BNAC
Analytical Method:	8270	Analytical Run ID:	BC060303
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB062503-13B		

rameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
(2-Chloroethyl)ether	111-44-4	< 1.2	U	10	1.2	ug/L
-Dichlorobenzene	95-50-1	< 1.0	U	10	1.0	ug/L
3-Dichlorobenzene	541-73-1	< 1.2	U	10	1.2	ug/L
-Dichlorobenzene	106-46-7	< 1.0	U	10	1.0	ug/L
-oxybis(1-Chloropropane)	108-60-1	< 1.0	U	10	1.0	ug/L
-Nitroso-di-n-propylamine	621-64-7	< 1.0	U	10	1.0	ug/L
xachloroethane	67-72-1	< 1.1	U	10	1.1	ug/L
robenzene	98-95-3	< 1.0	U	10	1.0	ug/L
ophorone	78-59-1	< 1.0	U	10	1.0	ug/L
(2-Chloroethoxy)methane	111-91-1	< 1.0	U	10	1.0	ug/L
2,4-Trichlorobenzene	120-82-1	< 1.2	U	10	1.2	ug/L
aphthalene	91-20-3	< 1.2	U	10	1.2	ug/L
hloroaniline	106-47-8	< 1.2	U	10	1.2	ug/L
exachlorobutadiene	87-68-3	< 1.5	U	10	1.5	ug/L
Methylnaphthalene	91-57-6	< 1.2	U	10	1.2	ug/L
achlorocyclopentadiene	77-47-4	< 3.9	U	10	3.9	ug/L
Chloronaphthalene	91-58-7	< 1.2	U	10	1.2	ug/L
itroaniline	88-74-4	< 1.0	U	10	1.0	ug/L
ethylphthalate	131-11-3	< 1.0	U	10	1.0	ug/L
cenaphthylene	208-96-8	< 1.2	U	10	1.2	ug/L
Dinitrotoluene	606-20-2	< 1.0	U	10	1.0	ug/L
itroaniline	99-09-2	< 1.2	U	10	1.2	ug/L
cenaphthene	83-32-9	8.2	J	10	1.0	ug/L
enzofuran	132-64-9	< 1.0	U	10	1.0	ug/L
Dinitrotoluene	121-14-2	< 1.1	U	10	1.1	ug/L
ethylphthalate	84-66-2	1.2	J	10	1.0	ug/L
hlorophenyl-phenylether	7005-72-3	< 1.2	U	10	1.2	ug/L
orene	86-73-7	3.1	J	10	1.1	ug/L
Nitroaniline	100-01-6	< 2.4	U	10	2.4	ug/L
itrosodiphenylamine	86-30-6	< 2.0	U	10	2.0	ug/L
obenzene	122-66-7	< 0.330	U	10	0.330	ug/L

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID:	R2982-06	Client ID:	BH-5
Date Collected:	6/16/03	Date Received:	6/19/03
Date Analyzed:	6/24/03	Matrix:	WATER
Date Extracted:	6/24/03	File ID:	BC006560.D
Dilution:	1	Instrument ID:	BNAC
Analytical Method:	8270	Analytical Run ID:	BC060303
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB062503-13B		

ameter	CAS Number	Concentration	C	RDL	MDL	Units
RGETS						
Bromophenyl-phenylether	101-55-3	< 1.3	U	10	1.3	ug/L
achlorobenzene	118-74-1	< 1.1	U	10	1.1	ug/L
enanthrene	85-01-8	3.2	J	10	1.0	ug/L
hracene	120-12-7	1.8	J	10	1.3	ug/L
n-butylphthalate	84-74-2	1.4	JB	10	1.2	ug/L
oranthene	206-44-0	4.2	J	10	1.0	ug/L
ene	129-00-0	3.5	J	10	1.0	ug/L
ylbenzylphthalate	85-68-7	< 1.0	U	10	1.0	ug/L
3-Dichlorobenzidine	91-94-1	< 1.0	U	20	1.0	ug/L
zo(a)anthracene	56-55-3	1.3	J	10	1.0	ug/L
ysene	218-01-9	< 1.6	U	10	1.6	ug/L
(2-Ethylhexyl)phthalate	117-81-7	3.8	J	10	1.0	ug/L
n-octyl phthalate	117-84-0	< 1.5	U	10	1.5	ug/L
nzo(b)fluoranthene	205-99-2	< 1.0	U	10	1.0	ug/L
nzo(k)fluoranthene	207-08-9	< 2.7	U	10	2.7	ug/L
zo(a)pyrene	50-32-8	< 1.5	U	10	1.5	ug/L
eno(1,2,3-cd)pyrene	193-39-5	< 1.6	U	10	1.6	ug/L
benz(a,h)anthracene	53-70-3	< 1.5	U	10	1.5	ug/L
zo(g,h,i)perylene	191-24-2	< 1.3	U	10	1.3	ug/L
RROGATES						
benzene-d5	4165-60-0	156.5	78 %	35 - 114		SPK: 200
luorobiphenyl	321-60-8	146.71	73 %	43 - 116		SPK: 200
phenyl-d14	1718-51-0	113.78	57 %	33 - 141		SPK: 200
ERNAL STANDARDS						
-Dichlorobenzene-d4	3855-82-1	125705	4.84			
thalene-d8	1146-65-2	399120	6.88			
naphthene-d10	15067-26-2	197004	9.98			
enanthrene-d10	1517-22-2	334699	12.65			
sene-d12	1719-03-5	326351	17.50			
rylene-d12	1520-96-3	308932	19.98			

Hit Summary Report

SDG No.: R2982 Order ID: R2982

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: SVOC-Chemtech Full BN

mple ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
ient ID:	BH-4S							
982-09	BH-4S	SOIL	Naphthalene	180	J	410	49	ug/Kg
2982-09	BH-4S	SOIL	2-Methylnaphthalene	190	J	410	49	ug/Kg
982-09	BH-4S	SOIL	Acenaphthylene	100	J	410	49	ug/Kg
982-09	BH-4S	SOIL	Acenaphthene	510		410	49	ug/Kg
2982-09	BH-4S	SOIL	Dibenzofuran	260	J	410	41	ug/Kg
982-09	BH-4S	SOIL	Fluorene	590		410	45	ug/Kg
982-09	BH-4S	SOIL	Phenanthrene	3300		410	41	ug/Kg
2982-09	BH-4S	SOIL	Anthracene	1100		410	54	ug/Kg
982-09	BH-4S	SOIL	Di-n-butylphthalate	120	J	410	49	ug/Kg
982-09	BH-4S	SOIL	Fluoranthene	2900		410	41	ug/Kg
2982-09	BH-4S	SOIL	Pyrene	2800		410	41	ug/Kg
982-09	BH-4S	SOIL	Butylbenzylphthalate	400	J	410	41	ug/Kg
2982-09	BH-4S	SOIL	Benzo(a)anthracene	1600		410	41	ug/Kg
2982-09	BH-4S	SOIL	Chrysene	1600		410	66	ug/Kg
982-09	BH-4S	SOIL	bis(2-Ethylhexyl)phthalate	380	J	410	41	ug/Kg
2982-09	BH-4S	SOIL	Benzo(b)fluoranthene	1300		410	41	ug/Kg
2982-09	BH-4S	SOIL	Benzo(k)fluoranthene	1200		410	110	ug/Kg
982-09	BH-4S	SOIL	Benzo(a)pyrene	1400		410	62	ug/Kg
2982-09	BH-4S	SOIL	Indeno(1,2,3-cd)pyrene	370	J	410	66	ug/Kg
982-09	BH-4S	SOIL	Dibenz(a,h)anthracene	120	J	410	62	ug/Kg
982-09	BH-4S	SOIL	Benzo(g,h,i)perylene	470		410	54	ug/Kg
			Total SVOC's:	20890.00				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	20890.00				
ient ID:	BH-4W							
982-05	BH-4W	WATER	Naphthalene	3.1	J	10	1.2	ug/L
2982-05	BH-4W	WATER	Acenaphthene	1.2	J	10	1.0	ug/L
982-05	BH-4W	WATER	Phenanthrene	2.7	J	10	1.0	ug/L
982-05	BH-4W	WATER	Di-n-butylphthalate	1.9	JB	10	1.2	ug/L
2982-05	BH-4W	WATER	Fluoranthene	1.5	J	10	1.0	ug/L
982-05	BH-4W	WATER	Pyrene	1.4	J	10	1.0	ug/L
982-05	BH-4W	WATER	bis(2-Ethylhexyl)phthalate	2.2	J	10	1.0	ug/L
			Total SVOC's:	14.00				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	14.00				

e: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Hit Summary Report

SDG No.: R2982 Order ID: R2982

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: SVOC-Chemtech Full BN

mple ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
lient ID:	BH-5							
982-06	BH-5	WATER	Acenaphthene	8.2	J	10	1.0	ug/L
2982-06	BH-5	WATER	Diethylphthalate	1.2	J	10	1.0	ug/L
2982-06	BH-5	WATER	Fluorene	3.1	J	10	1.1	ug/L
982-06	BH-5	WATER	Phenanthrene	3.2	J	10	1.0	ug/L
2982-06	BH-5	WATER	Anthracene	1.8	J	10	1.3	ug/L
982-06	BH-5	WATER	Di-n-butylphthalate	1.4	JB	10	1.2	ug/L
982-06	BH-5	WATER	Fluoranthene	4.2	J	10	1.0	ug/L
2982-06	BH-5	WATER	Pyrene	3.5	J	10	1.0	ug/L
982-06	BH-5	WATER	Benzo(a)anthracene	1.3	J	10	1.0	ug/L
982-06	BH-5	WATER	bis(2-Ethylhexyl)phthalate	3.8	J	10	1.0	ug/L
			Total SVOC's:	31.70				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	31.70				
ient ID:	BH-5B							
982-11	BH-5B	SOIL	Phenanthrene	52	J	400	40	ug/Kg
2982-11	BH-5B	SOIL	Anthracene	69	J	400	52	ug/Kg
982-11	BH-5B	SOIL	Fluoranthene	400		400	40	ug/Kg
982-11	BH-5B	SOIL	Pyrene	310	J	400	40	ug/Kg
2982-11	BH-5B	SOIL	Benzo(a)anthracene	200	J	400	40	ug/Kg
982-11	BH-5B	SOIL	Chrysene	180	J	400	63	ug/Kg
982-11	BH-5B	SOIL	Benzo(b)fluoranthene	190	J	400	40	ug/Kg
2982-11	BH-5B	SOIL	Benzo(k)fluoranthene	190	J	400	100	ug/Kg
982-11	BH-5B	SOIL	Benzo(a)pyrene	230	J	400	59	ug/Kg
2982-11	BH-5B	SOIL	Indeno(1,2,3-cd)pyrene	88	J	400	63	ug/Kg
2982-11	BH-5B	SOIL	Benzo(g,h,i)perylene	100	J	400	52	ug/Kg
			Total SVOC's:	2009.00				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	2009.00				

te: The asterisk "*" flag next to a parameter signifies a TIC parameter.

CHEMTECH
284 Sheffield Street Mountainside NJ 07092
Tel. 908-789-8900

END OF ANALYTICAL RESULTS

CHEMTECH 284 Sheffield Street • Mountainside, NJ 07092 Phone: 908.789.8900 Fax: 908.789.8922

August 18, 2003

Dear Customer:

Due to the recent power blackout in the northeast, we lost a great amount of processed data. Although we are re-processing the data and recovering quickly, we were unable to meet the agreed turnaround. We apologize for the inconvenience this delay may have caused.

Please do not hesitate to contact us if you require any further information at 908-789-8900, ext. 204.

Sincerely,

Krupa Dubey
QC Officer

A FULL SERVICE ENVIRONMENTAL LABORATORY
EXPRESS

CHEMTECH

284 Sheffield Street, Mountainside NJ 07092
Tel: 908-789-8900 Fax 908-789-8922

COVER PAGE

ProjectID: Junk Yard

Order R3695

CustomerName ASTEM Laboratory, Inc.

LAB SAMPLE NO.	CLIENT SAMPLE NO
R3695-01	BH-6
R3695-02	BH-6
R3695-03	BH-6
R3695-04	BH-7
R3695-05	BH-8
R3695-06	BH-9
R3695-07	BH-9
R3695-08	BH-10

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. Release of the data contained in this hard copy data package has been authorized by the laboratory manager or his designee, as verified by the following signature.

Signature: _____ Name: Kunpa Pubey

Date: 8/20/03 Title: QA/QC

NYDOH CERTIFICATION NO.11376

NJDEP CERTIFICATION NO. 20012

CHEMTECH

284 Sheffield Street Mountainside NJ 07092
Tel. 908-789-8900 Fax: 908-789-8922

DATA REPORTING QUALIFIERS- ORGANIC

For reporting results, the following " Results Qualifiers" are used:

Value	If the result is a value greater than or equal to the detection limit, report the value
U	Indicates the compound was analyzed for but was not detected. Report the minimum detection limit for the sample with the U, i.e. "10 U". This is not necessarily the instrument detection limit attainable for this particular sample based on any concentration or dilution that may have been required.
J	Indicates an estimated value. This flag is used: (1) When estimating a concentration for a tentatively identified compound (library search hits, where a 1:1 response is assumed.) (2) When the mass spectral data indicated the identification, however the result was less than the specified detection limit greater than zero. If the detection limit was 10ug/L and a concentration of 3 ug/L was calculated report as 3 J. This is flag is used when similar situation arise on any organic parameter i.e. Pest, PCB and others.
B	Indicates the analyte was found in the blank as well as the sample report as "12 B".
E	Indicates the analyte 's concentration exceeds the calibrated range of the instrument for that specific analysis.
D	This flag identifies all compounds identified in an analysis at a secondary dilution factor.
P	This flag is used for Pesticide/PCB target analyte when there is >25% difference for detected concentrations between the two GC columns. The lower of the two values is reported on Form 1 and flagged with a "P".
N	This flag indicates presumptive evidence of a compound. This is only used for tentatively identified compounds (TICs), where the identification is based on a mass spectral library search. It applies to all TIC results. For generic characterization of a TIC, such as chlorinated hydrocarbon, the flag is not used.
A	This flag indicates that a Tentatively Identified Compound is a suspected aldol-condensation product.

CHEMTECH

284 Sheffield Street Mountainside NJ 07092
Tel. 908-789-8900 Fax: 908-789-8922

DATA REPORTING QUALIFIERS- INORGANIC

For reporting results, the following " Results Qualifiers" are used:

J	If the reported value was obtained from a reading that was less than the Contract Required Detection Limit (CRDL), but greater than or equal to the Instrument Detection Limit (IDL).
U	If the analyte was analyzed for, but not detected.
E	The reported value is estimated because of the presence of interference
M	Duplicate injection precision not met.
N	Spiked sample recovery not within control limits.
S	The reported value was determined by the Method of Standard Addition (MSA).
W	Post-digestion spike for Furnace AA analysis is out of control limits (85-115%), while absorbance is less that 50% of spike absorbance.
*	Duplicate analysis not within control limits.
+	Correlation coefficient for the MSA is less than 0.995.
***	Entering "S", "W " or " +" is mutually exclusive. NO combination of these qualifiers can appear in the same field for an analyte.

M	Method qualifiers "P" for ICP instrument "A" for Flame AA "PM" for ICP when Microwave Digestion is used "AM" for flame AA when Microwave Digestion is used "FM" for furnace AA when Microwave Digestion is used "CV" for Manual Cold Vapor AA "AV" for automated Cold Vapor AA "CA" for MIDI-Distillation Spectrophotometric "AS" for Semi -Automated Spectrophotometric "C" for Manual Spectrophotometric "T" for Titrimetric "NR" for analyte not required to be analyzed

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-01	Client ID:	BH-6
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/9/03	Matrix:	WATER
File ID:	VD080907.D	Analytical Run ID:	VD080903
Dilution:	1	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBD0808W2
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 0.71	U	5.0	0.71	ug/L
hloromethane	74-87-3	< 0.51	U	5.0	0.51	ug/L
nyl chloride	75-01-4	< 0.79	U	5.0	0.79	ug/L
romomethane	74-83-9	< 0.38	U	5.0	0.38	ug/L
loroethane	75-00-3	< 2.4	U	5.0	2.4	ug/L
chlorofluoromethane	75-69-4	< 0.73	U	5.0	0.73	ug/L
ert butyl alcohol	75-65-0	< 4.0	U	25	4.0	ug/L
-Dichloroethene	75-35-4	< 0.69	U	5.0	0.69	ug/L
rolein	107-02-8	< 4.9	U	25	4.9	ug/L
crylonitrile	107-13-1	< 3.5	U	25	3.5	ug/L
tone	67-64-1	< 3.5	U	5.0	3.5	ug/L
rbon disulfide	75-15-0	< 0.72	U	5.0	0.72	ug/L
ethyl tert-butyl Ether	1634-04-4	13		5.0	1.0	ug/L
thylene Chloride	75-09-2	< 1.8	U	5.0	1.8	ug/L
ns-1,2-Dichloroethene	156-60-5	< 0.81	U	5.0	0.81	ug/L
inyl Acetate	108-05-4	< 2.6	U	25	2.6	ug/L
-Dichloroethane	75-34-3	< 0.66	U	5.0	0.66	ug/L
-Butanone	78-93-3	< 2.3	U	5.0	2.3	ug/L
rbon Tetrachloride	56-23-5	< 0.47	U	5.0	0.47	ug/L
-Dichloropropane	594-20-7	< 0.63	U	5.0	0.63	ug/L
s-1,2-Dichloroethene	156-59-2	< 0.62	U	5.0	0.62	ug/L
mochloromethane	74-97-5	< 0.91	U	5.0	0.91	ug/L
roform	67-66-3	< 0.61	U	5.0	0.61	ug/L
1,1-Trichloroethane	71-55-6	< 0.75	U	5.0	0.75	ug/L
-Dichloropropene	563-43-2	< 3.0	U	5.0	3.0	ug/L
nzene	71-43-2	< 0.71	U	5.0	0.71	ug/L
2-Dichloroethane	107-06-2	< 0.56	U	5.0	0.56	ug/L
hloroethene	79-01-6	< 0.72	U	5.0	0.72	ug/L
-Dichloropropane	78-87-5	< 0.73	U	5.0	0.73	ug/L
bromomethane	74-95-3	< 0.61	U	5.0	0.61	ug/L
modichloromethane	75-27-4	< 0.73	U	5.0	0.73	ug/L
Methyl-2-Pentanone	108-10-1	< 0.81	U	5.0	0.81	ug/L
luene	108-88-3	< 0.71	U	5.0	0.71	ug/L
-Dichloropropene	10061-02-6	< 0.66	U	5.0	0.66	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-01 Client ID: BH-6

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/9/03 Matrix: WATER
File ID: VD080907.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Wol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
[redacted]-1,3-Dichloropropene	10061-01-5	< 0.66	U	5.0	0.66	ug/L
1,1,2-Trichloroethane	79-00-5	< 0.62	U	5.0	0.62	ug/L
[redacted]-Dichloropropane	142-28-9	< 0.57	U	5.0	0.57	ug/L
[redacted]Chloroethyl vinyl ether	110-75-8	< 2.2	U	5.0	2.2	ug/L
2-Hexanone	591-78-6	< 0.60	U	5.0	0.60	ug/L
[redacted]bromochloromethane	124-48-1	< 0.66	U	5.0	0.66	ug/L
[redacted]-Dibromoethane	106-93-4	< 0.63	U	5.0	0.63	ug/L
Tetrachloroethene	127-18-4	< 0.70	U	5.0	0.70	ug/L
[redacted]lorobenzene	108-90-7	< 0.78	U	5.0	0.78	ug/L
[redacted],1,2-Tetrachloroethane	630-20-6	< 0.64	U	5.0	0.64	ug/L
Ethyl Benzene	100-41-4	< 0.76	U	5.0	0.76	ug/L
[redacted]o-Xylenes	136777-61-2	< 1.5	U	5.0	1.5	ug/L
[redacted]-Xylene	95-47-6	< 0.72	U	5.0	0.72	ug/L
Styrene	100-42-5	< 0.92	U	5.0	0.92	ug/L
[redacted]omoform	75-25-2	< 0.49	U	5.0	0.49	ug/L
Isopropylbenzene	98-82-8	< 0.75	U	5.0	0.75	ug/L
[redacted]1,2,2-Tetrachloroethane	79-34-5	< 0.70	U	5.0	0.70	ug/L
[redacted],3-Trichloropropane	96-18-4	< 1.0	U	5.0	1.0	ug/L
Bromobenzene	108-86-1	< 0.60	U	5.0	0.60	ug/L
[redacted]propylbenzene	103-61-5	< 0.80	U	5.0	0.80	ug/L
[redacted]Chlorotoluene	95-49-8	< 0.85	U	5.0	0.85	ug/L
1,3,5-Trimethylbenzene	108-67-8	< 0.97	U	5.0	0.97	ug/L
[redacted]Chlorotoluene	106-43-4	< 1.0	U	5.0	1.0	ug/L
[redacted]-Butylbenzene	98-06-6	< 0.94	U	5.0	0.94	ug/L
1,2,4-Trimethylbenzene	95-63-6	< 0.83	U	5.0	0.83	ug/L
[redacted]-butylbenzene	135-98-8	< 0.96	U	5.0	0.96	ug/L
[redacted]-Isopropyltoluene	99-87-6	< 1.1	U	5.0	1.1	ug/L
1,3-Dichlorobenzene	541-73-1	< 0.74	U	5.0	0.74	ug/L
[redacted]-Dichlorobenzene	106-46-7	< 0.93	U	5.0	0.93	ug/L
[redacted]-Butylbenzene	104-51-8	< 1.2	U	5.0	1.2	ug/L
[redacted]2-Dichlorobenzene	95-50-1	< 0.88	U	5.0	0.88	ug/L
[redacted]-Dibromo-3-Chloropropane	96-12-8	< 0.91	U	5.0	0.91	ug/L
[redacted],2,4-Trichlorobenzene	120-82-1	< 1.3	U	5.0	1.3	ug/L
[redacted]xachlorobutadiene	87-68-3	< 0.94	U	5.0	0.94	ug/L
[redacted]phthalene	91-20-3	35		5.0	0.91	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-01 Client ID: BH-6

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/9/03 Matrix: WATER
File ID: VD080907.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Vol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 1.0	U	5.0	1.0	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	52.83	106 %	68 - 135		SPK: 50
Dibromofluoromethane	1868-53-7	48.17	96 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	50.2	100 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	48.86	98 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	708897	12.99			
1,4-Difluorobenzene	540-36-3	1184250	15.24			
Chlorobenzene-d5	3114-55-4	1143736	22.59			
1,4-Dichlorobenzene-d4	3855-82-1	606972	28.99			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-05	Client ID:	BH-8
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
File ID:	VD080908.D	Analytical Run ID:	VD080903
Dilution:	1	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBD0808W2
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 0.71	U	5.0	0.71	ug/L
Chloromethane	74-87-3	< 0.51	U	5.0	0.51	ug/L
nyl chloride	75-01-4	< 0.79	U	5.0	0.79	ug/L
Bromomethane	74-83-9	< 0.38	U	5.0	0.38	ug/L
hloroethane	75-00-3	< 2.4	U	5.0	2.4	ug/L
chlorofluoromethane	75-69-4	< 0.73	U	5.0	0.73	ug/L
Tert butyl alcohol	75-65-0	< 4.0	U	25	4.0	ug/L
-Dichloroethene	75-35-4	< 0.69	U	5.0	0.69	ug/L
rolein	107-02-8	< 4.9	U	25	4.9	ug/L
Acrylonitrile	107-13-1	< 3.5	U	25	3.5	ug/L
etone	67-64-1	< 3.5	U	5.0	3.5	ug/L
rbon disulfide	75-15-0	< 0.72	U	5.0	0.72	ug/L
Methyl tert-butyl Ether	1634-04-4	9.4		5.0	1.0	ug/L
thylene Chloride	75-09-2	< 1.8	U	5.0	1.8	ug/L
ans-1,2-Dichloroethene	156-60-5	< 0.81	U	5.0	0.81	ug/L
Vinyl Acetate	108-05-4	< 2.6	U	25	2.6	ug/L
-Dichloroethane	75-34-3	< 0.66	U	5.0	0.66	ug/L
-Butanone	78-93-3	< 2.3	U	5.0	2.3	ug/L
arbon Tetrachloride	56-23-5	< 0.47	U	5.0	0.47	ug/L
-Dichloropropane	594-20-7	< 0.63	U	5.0	0.63	ug/L
is-1,2-Dichloroethene	156-59-2	< 0.62	U	5.0	0.62	ug/L
mochloromethane	74-97-5	< 0.91	U	5.0	0.91	ug/L
oroform	67-66-3	< 0.61	U	5.0	0.61	ug/L
,1,1-Trichloroethane	71-55-6	< 0.75	U	5.0	0.75	ug/L
-Dichloropropene	563-43-2	< 3.0	U	5.0	3.0	ug/L
nzene	71-43-2	< 0.71	U	5.0	0.71	ug/L
,2-Dichloroethane	107-06-2	< 0.56	U	5.0	0.56	ug/L
hloroethene	79-01-6	< 0.72	U	5.0	0.72	ug/L
-Dichloropropane	78-87-5	< 0.73	U	5.0	0.73	ug/L
ibromomethane	74-95-3	< 0.61	U	5.0	0.61	ug/L
modichloromethane	75-27-4	< 0.73	U	5.0	0.73	ug/L
-Methyl-2-Pentanone	108-10-1	< 0.81	U	5.0	0.81	ug/L
oluene	108-88-3	< 0.71	U	5.0	0.71	ug/L
-Dichloropropene	10061-02-6	< 0.66	U	5.0	0.66	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-05 Client ID: BH-8

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/10/03 Matrix: WATER
File ID: VD080908.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Vol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
-1,3-Dichloropropene	10061-01-5	< 0.66	U	5.0	0.66	ug/L
1,1,2-Trichloroethane	79-00-5	< 0.62	U	5.0	0.62	ug/L
3-Dichloropropane	142-28-9	< 0.57	U	5.0	0.57	ug/L
Chloroethyl vinyl ether	110-75-8	< 2.2	U	5.0	2.2	ug/L
2-Hexanone	591-78-6	< 0.60	U	5.0	0.60	ug/L
bromochloromethane	124-48-1	< 0.66	U	5.0	0.66	ug/L
-Dibromoethane	106-93-4	< 0.63	U	5.0	0.63	ug/L
Tetrachloroethene	127-18-4	< 0.70	U	5.0	0.70	ug/L
lorobenzene	108-90-7	< 0.78	U	5.0	0.78	ug/L
,1,2-Tetrachloroethane	630-20-6	< 0.64	U	5.0	0.64	ug/L
Ethyl Benzene	100-41-4	< 0.76	U	5.0	0.76	ug/L
p-Xylenes	136777-61-2	< 1.5	U	5.0	1.5	ug/L
Xylene	95-47-6	< 0.72	U	5.0	0.72	ug/L
Styrene	100-42-5	< 0.92	U	5.0	0.92	ug/L
omoform	75-25-2	< 0.49	U	5.0	0.49	ug/L
opropylbenzene	98-82-8	< 0.75	U	5.0	0.75	ug/L
1,2,2-Tetrachloroethane	79-34-5	< 0.70	U	5.0	0.70	ug/L
,3-Trichloropropane	96-18-4	< 1.0	U	5.0	1.0	ug/L
Bromobenzene	108-86-1	< 0.60	U	5.0	0.60	ug/L
propylbenzene	103-61-5	< 0.80	U	5.0	0.80	ug/L
Chlorotoluene	95-49-8	< 0.85	U	5.0	0.85	ug/L
,3,5-Trimethylbenzene	108-67-8	< 0.97	U	5.0	0.97	ug/L
Chlorotoluene	106-43-4	< 1.0	U	5.0	1.0	ug/L
-Butylbenzene	98-06-6	< 0.94	U	5.0	0.94	ug/L
,2,4-Trimethylbenzene	95-63-6	< 0.83	U	5.0	0.83	ug/L
-butylbenzene	135-98-8	< 0.96	U	5.0	0.96	ug/L
sopropyltoluene	99-87-6	< 1.1	U	5.0	1.1	ug/L
,3-Dichlorobenzene	541-73-1	< 0.74	U	5.0	0.74	ug/L
-Dichlorobenzene	106-46-7	< 0.93	U	5.0	0.93	ug/L
-Butylbenzene	104-51-8	< 1.2	U	5.0	1.2	ug/L
,2-Dichlorobenzene	95-50-1	< 0.88	U	5.0	0.88	ug/L
-Dibromo-3-Chloropropane	96-12-8	< 0.91	U	5.0	0.91	ug/L
,2,4-Trichlorobenzene	120-82-1	< 1.3	U	5.0	1.3	ug/L
exachlorobutadiene	87-68-3	< 0.94	U	5.0	0.94	ug/L
phthalene	91-20-3	< 0.91	U	5.0	0.91	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-05	Client ID:	BH-8
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
File ID:	VD080908.D	Analytical Run ID:	VD080903
Dilution:	1	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBD0808W2
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 1.0	U	5.0	1.0	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	51.37	103 %	68 - 135		SPK: 50
Dibromofluoromethane	1868-53-7	48.92	98 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	50.14	100 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	50.08	100 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	705797	12.98			
1,4-Difluorobenzene	540-36-3	1153937	15.23			
Chlorobenzene-d5	3114-55-4	1039997	22.59			
1,4-Dichlorobenzene-d4	3855-82-1	542932	28.99			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-06 Client ID: BH-9W

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/10/03 Matrix: WATER
File ID: VD080909.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Vol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
Dichlorodifluoromethane	75-71-8	< 0.71	U	5.0	0.71	ug/L
Chloromethane	74-87-3	< 0.51	U	5.0	0.51	ug/L
Vinyl chloride	75-01-4	< 0.79	U	5.0	0.79	ug/L
Bromomethane	74-83-9	< 0.38	U	5.0	0.38	ug/L
Chloroethane	75-00-3	< 2.4	U	5.0	2.4	ug/L
Trichlorofluoromethane	75-69-4	< 0.73	U	5.0	0.73	ug/L
Tert butyl alcohol	75-65-0	< 4.0	U	25	4.0	ug/L
1,1-Dichloroethene	75-35-4	< 0.69	U	5.0	0.69	ug/L
Acrolein	107-02-8	< 4.9	U	25	4.9	ug/L
Acrylonitrile	107-13-1	< 3.5	U	25	3.5	ug/L
Acetone	67-64-1	< 3.5	U	5.0	3.5	ug/L
Carbon disulfide	75-15-0	< 0.72	U	5.0	0.72	ug/L
Methyl tert-butyl Ether	1634-04-4	18		5.0	1.0	ug/L
Methylene Chloride	75-09-2	< 1.8	U	5.0	1.8	ug/L
trans-1,2-Dichloroethene	156-60-5	< 0.81	U	5.0	0.81	ug/L
Vinyl Acetate	108-05-4	< 2.6	U	25	2.6	ug/L
1,1-Dichloroethane	75-34-3	< 0.66	U	5.0	0.66	ug/L
2-Butanone	78-93-3	< 2.3	U	5.0	2.3	ug/L
Carbon Tetrachloride	56-23-5	< 0.47	U	5.0	0.47	ug/L
1,2-Dichloropropane	594-20-7	< 0.63	U	5.0	0.63	ug/L
cis-1,2-Dichloroethene	156-59-2	2.0	J	5.0	0.62	ug/L
Bromochloromethane	74-97-5	< 0.91	U	5.0	0.91	ug/L
Chloroform	67-66-3	< 0.61	U	5.0	0.61	ug/L
1,1,1-Trichloroethane	71-55-6	< 0.75	U	5.0	0.75	ug/L
cis-1,3-Dichloropropene	563-43-2	< 3.0	U	5.0	3.0	ug/L
Benzene	71-43-2	< 0.71	U	5.0	0.71	ug/L
1,2-Dichloroethane	107-06-2	< 0.56	U	5.0	0.56	ug/L
Trichloroethene	79-01-6	1.8	J	5.0	0.72	ug/L
1,2-Dichloropropane	78-87-5	2.2	J	5.0	0.73	ug/L
Dibromomethane	74-95-3	< 0.61	U	5.0	0.61	ug/L
Bromodichloromethane	75-27-4	< 0.73	U	5.0	0.73	ug/L
4-Methyl-2-Pentanone	108-10-1	< 0.81	U	5.0	0.81	ug/L
Toluene	108-88-3	< 0.71	U	5.0	0.71	ug/L
trans-1,3-Dichloropropene	10061-02-6	< 0.66	U	5.0	0.66	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-06 Client ID: BH-9W

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/10/03 Matrix: WATER
File ID: VD080909.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Vol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
-1,3-Dichloropropene	10061-01-5	< 0.66	U	5.0	0.66	ug/L
,1,2-Trichloroethane	79-00-5	< 0.62	U	5.0	0.62	ug/L
,3-Dichloropropane	142-28-9	< 0.57	U	5.0	0.57	ug/L
Chloroethyl vinyl ether	110-75-8	< 2.2	U	5.0	2.2	ug/L
-Hexanone	591-78-6	< 0.60	U	5.0	0.60	ug/L
Dibromochloromethane	124-48-1	< 0.66	U	5.0	0.66	ug/L
-Dibromoethane	106-93-4	< 0.63	U	5.0	0.63	ug/L
Tetrachloroethene	127-18-4	< 0.70	U	5.0	0.70	ug/L
hlorobenzene	108-90-7	12		5.0	0.78	ug/L
,1,2-Tetrachloroethane	630-20-6	< 0.64	U	5.0	0.64	ug/L
Ethyl Benzene	100-41-4	< 0.76	U	5.0	0.76	ug/L
p-Xylenes	136777-61-2	< 1.5	U	5.0	1.5	ug/L
Xylene	95-47-6	6.3		5.0	0.72	ug/L
Styrene	100-42-5	< 0.92	U	5.0	0.92	ug/L
omoform	75-25-2	< 0.49	U	5.0	0.49	ug/L
opropylbenzene	98-82-8	< 0.75	U	5.0	0.75	ug/L
,1,2,2-Tetrachloroethane	79-34-5	< 0.70	U	5.0	0.70	ug/L
,3-Trichloropropane	96-18-4	< 1.0	U	5.0	1.0	ug/L
romobenzene	108-86-1	< 0.60	U	5.0	0.60	ug/L
-propylbenzene	103-61-5	< 0.80	U	5.0	0.80	ug/L
Chlorotoluene	95-49-8	< 0.85	U	5.0	0.85	ug/L
,3,5-Trimethylbenzene	108-67-8	8.0		5.0	0.97	ug/L
Chlorotoluene	106-43-4	< 1.0	U	5.0	1.0	ug/L
-Butylbenzene	98-06-6	< 0.94	U	5.0	0.94	ug/L
,2,4-Trimethylbenzene	95-63-6	19		5.0	0.83	ug/L
-butylbenzene	135-98-8	< 0.96	U	5.0	0.96	ug/L
sopropyltoluene	99-87-6	< 1.1	U	5.0	1.1	ug/L
,3-Dichlorobenzene	541-73-1	22		5.0	0.74	ug/L
-Dichlorobenzene	106-46-7	72		5.0	0.93	ug/L
Butylbenzene	104-51-8	< 1.2	U	5.0	1.2	ug/L
,2-Dichlorobenzene	95-50-1	730	E	5.0	0.88	ug/L
-Dibromo-3-Chloropropane	96-12-8	< 0.91	U	5.0	0.91	ug/L
,2,4-Trichlorobenzene	120-82-1	4.2	J	5.0	1.3	ug/L
exachlorobutadiene	87-68-3	< 0.94	U	5.0	0.94	ug/L
phthalene	91-20-3	4.5	J	5.0	0.91	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06	Client ID:	BH-9W
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
File ID:	VD080909.D	Analytical Run ID:	VD080903
Dilution:	1	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBD0808W2
Sample Wt/Wol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 1.0	U	5.0	1.0	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	49.76	100 %	68 - 135		SPK: 50
Dibromofluoromethane	1868-53-7	45.17	90 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	47.96	96 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	48.37	97 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	691150	12.98			
1,4-Difluorobenzene	540-36-3	1160170	15.24			
Chlorobenzene-d5	3114-55-4	1104283	22.58			
1,4-Dichlorobenzene-d4	3855-82-1	653986	28.96			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-06DL | Client ID: BH-9WDL

Date Collected: 8/5/03 | Date Received: 8/6/03
Date Analyzed: 8/14/03 | Matrix: WATER
File ID: VG081243.D | Analytical Run ID: VG081303
Dilution: 5 | Instrument ID: MSVOAD
Analytical Method: 8260 | Associated Blank: VBG0813W3
Sample Wt/Wol: 5.0 Units: mL | Soil Extract Vol:
Soil Aliquot Vol: | % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 3.6	UD	25	3.6	ug/L
Chloromethane	74-87-3	< 2.6	UD	25	2.6	ug/L
nyl chloride	75-01-4	< 4.0	UD	25	4.0	ug/L
Bromomethane	74-83-9	< 1.9	UD	25	1.9	ug/L
loroethane	75-00-3	< 12	UD	25	12	ug/L
ichlorofluoromethane	75-69-4	< 3.6	UD	25	3.6	ug/L
Tert butyl alcohol	75-65-0	< 20	UD	120	20	ug/L
-Dichloroethene	75-35-4	< 3.4	UD	25	3.4	ug/L
rolein	107-02-8	< 24	UD	120	24	ug/L
Acrylonitrile	107-13-1	< 18	UD	120	18	ug/L
etone	67-64-1	< 18	UD	25	18	ug/L
arbon disulfide	75-15-0	< 3.6	UD	25	3.6	ug/L
Methyl tert-butyl Ether	1634-04-4	17	JD	25	5.2	ug/L
thylene Chloride	75-09-2	< 8.8	UD	25	8.8	ug/L
ans-1,2-Dichloroethene	156-60-5	< 4:0	UD	25	4.0	ug/L
Vinyl Acetate	108-05-4	< 13	UD	120	13	ug/L
-Dichloroethane	75-34-3	< 3.3	UD	25	3.3	ug/L
2-Butanone	78-93-3	< 12	UD	25	12	ug/L
arbon Tetrachloride	56-23-5	< 2.4	UD	25	2.4	ug/L
-Dichloropropane	594-20-7	< 3.2	UD	25	3.2	ug/L
is-1,2-Dichloroethene	156-59-2	< 3.1	UD	25	3.1	ug/L
omochloromethane	74-97-5	< 4.6	UD	25	4.6	ug/L
loroform	67-66-3	< 3.0	UD	25	3.0	ug/L
,1,1-Trichloroethane	71-55-6	< 3.8	UD	25	3.8	ug/L
-Dichloropropene	563-43-2	< 15	UD	25	15	ug/L
nzene	71-43-2	< 3.6	UD	25	3.6	ug/L
,2-Dichloroethane	107-06-2	< 2.8	UD	25	2.8	ug/L
chloroethene	79-01-6	< 3.6	UD	25	3.6	ug/L
,2-Dichloropropane	78-87-5	< 3.6	UD	25	3.6	ug/L
ibromomethane	74-95-3	< 3.0	UD	25	3.0	ug/L
omodichloromethane	75-27-4	< 3.6	UD	25	3.6	ug/L
-Methyl-2-Pentanone	108-10-1	6.5	JD	25	4.0	ug/L
oluene	108-88-3	< 3.6	UD	25	3.6	ug/L
3-Dichloropropene	10061-02-6	< 3.3	UD	25	3.3	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06DL	Client ID:	BH-9WDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/14/03	Matrix:	WATER
File ID:	VG081243.D	Analytical Run ID:	VG081303
Dilution:	5	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBG0813W3
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
s-1,3-Dichloropropene	10061-01-5	< 3.3	UD	25	3.3	ug/L
1,1,2-Trichloroethane	79-00-5	< 3.1	UD	25	3.1	ug/L
1,3-Dichloropropane	142-28-9	< 2.8	UD	25	2.8	ug/L
Chloroethyl vinyl ether	110-75-8	< 11	UD	25	11	ug/L
2-Hexanone	591-78-6	< 3.0	UD	25	3.0	ug/L
bromochloromethane	124-48-1	< 3.3	UD	25	3.3	ug/L
2-Dibromoethane	106-93-4	< 3.2	UD	25	3.2	ug/L
Tetrachloroethene	127-18-4	< 3.5	UD	25	3.5	ug/L
hlorobenzene	108-90-7	6.3	JD	25	3.9	ug/L
,1,2-Tetrachloroethane	630-20-6	< 3.2	UD	25	3.2	ug/L
Ethyl Benzene	100-41-4	< 3.8	UD	25	3.8	ug/L
p-Xylenes	136777-61-2	< 7.6	UD	25	7.6	ug/L
Xylene	95-47-6	< 3.6	UD	25	3.6	ug/L
Styrene	100-42-5	< 4.6	UD	25	4.6	ug/L
omoform	75-25-2	< 2.4	UD	25	2.4	ug/L
sopropylbenzene	98-82-8	< 3.8	UD	25	3.8	ug/L
1,2,2-Tetrachloroethane	79-34-5	< 3.5	UD	25	3.5	ug/L
2,3-Trichloropropane	96-18-4	< 5.2	UD	25	5.2	ug/L
Bromobenzene	108-86-1	< 3.0	UD	25	3.0	ug/L
propylbenzene	103-61-5	< 4.0	UD	25	4.0	ug/L
Chlorotoluene	95-49-8	< 4.2	UD	25	4.2	ug/L
,3,5-Trimethylbenzene	108-67-8	5.6	JD	25	4.8	ug/L
Chlorotoluene	106-43-4	< 5.1	UD	25	5.1	ug/L
t-Butylbenzene	98-06-6	< 4.7	UD	25	4.7	ug/L
,2,4-Trimethylbenzene	95-63-6	12	JD	25	4.2	ug/L
c-butylbenzene	135-98-8	< 4.8	UD	25	4.8	ug/L
sopropyltoluene	99-87-6	< 5.4	UD	25	5.4	ug/L
,3-Dichlorobenzene	541-73-1	13	JD	25	3.7	ug/L
-Dichlorobenzene	106-46-7	53	D	25	4.6	ug/L
-Butylbenzene	104-51-8	< 6.2	UD	25	6.2	ug/L
2-Dichlorobenzene	95-50-1	720	D	25	4.4	ug/L
-Dibromo-3-Chloropropane	96-12-8	< 4.6	UD	25	4.6	ug/L
,2,4-Trichlorobenzene	120-82-1	< 6.4	UD	25	6.4	ug/L
xachlorobutadiene	87-68-3	< 4.7	UD	25	4.7	ug/L
phthalene	91-20-3	11	JD	25	4.6	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06DL	Client ID:	BH-9WDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/14/03	Matrix:	WATER
File ID:	VG081243.D	Analytical Run ID:	VG081303
Dilution:	5	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBG0813W3
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 5.2	UD	25	5.2	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	51.59	103 %	68 - 135		SPK: 50
Bromofluoromethane	1868-53-7	50.94	102 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	51.14	102 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	54.35	109 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	1080978	8.26			
1,4-Difluorobenzene	540-36-3	2082187	9.80			
Chlorobenzene-d5	3114-55-4	1630619	16.12			
1,4-Dichlorobenzene-d4	3855-82-1	586371	21.33			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-08 Client ID: BH-10

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/10/03 Matrix: WATER
File ID: VD080910.D Analytical Run ID: VD080903
Dilution: 1 Instrument ID: MSVOAD
Analytical Method: 8260 Associated Blank: VBD0808W2
Sample Wt/Vol: 5.0 Units: mL Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 0.71	U	5.0	0.71	ug/L
hloromethane	74-87-3	< 0.51	U	5.0	0.51	ug/L
inyl chloride	75-01-4	< 0.79	U	5.0	0.79	ug/L
Bromomethane	74-83-9	< 0.38	U	5.0	0.38	ug/L
hloroethane	75-00-3	< 2.4	U	5.0	2.4	ug/L
richlorofluoromethane	75-69-4	< 0.73	U	5.0	0.73	ug/L
Tert butyl alcohol	75-65-0	< 4.0	U	25	4.0	ug/L
1-Dichloroethene	75-35-4	< 0.69	U	5.0	0.69	ug/L
crolein	107-02-8	< 4.9	U	25	4.9	ug/L
Acrylonitrile	107-13-1	< 3.5	U	25	3.5	ug/L
cetone	67-64-1	< 3.5	U	5.0	3.5	ug/L
arbon disulfide	75-15-0	< 0.72	U	5.0	0.72	ug/L
Methyl tert-butyl Ether	1634-04-4	19		5.0	1.0	ug/L
ethylene Chloride	75-09-2	< 1.8	U	5.0	1.8	ug/L
trans-1,2-Dichloroethene	156-60-5	< 0.81	U	5.0	0.81	ug/L
inyl Acetate	108-05-4	< 2.6	U	25	2.6	ug/L
1-Dichloroethane	75-34-3	< 0.66	U	5.0	0.66	ug/L
2-Butanone	78-93-3	< 2.3	U	5.0	2.3	ug/L
arbon Tetrachloride	56-23-5	< 0.47	U	5.0	0.47	ug/L
2-Dichloropropane	594-20-7	< 0.63	U	5.0	0.63	ug/L
is-1,2-Dichloroethene	156-59-2	2.2	J	5.0	0.62	ug/L
romochloromethane	74-97-5	< 0.91	U	5.0	0.91	ug/L
hloroform	67-66-3	< 0.61	U	5.0	0.61	ug/L
1,1,1-Trichloroethane	71-55-6	< 0.75	U	5.0	0.75	ug/L
1-Dichloropropene	563-43-2	< 3.0	U	5.0	3.0	ug/L
enzene	71-43-2	< 0.71	U	5.0	0.71	ug/L
2-Dichloroethane	107-06-2	< 0.56	U	5.0	0.56	ug/L
ichloroethene	79-01-6	1.4	J	5.0	0.72	ug/L
2-Dichloropropane	78-87-5	2.9	J	5.0	0.73	ug/L
ibromomethane	74-95-3	< 0.61	U	5.0	0.61	ug/L
romodichloromethane	75-27-4	< 0.73	U	5.0	0.73	ug/L
-Methyl-2-Pentanone	108-10-1	< 0.81	U	5.0	0.81	ug/L
oluene	108-88-3	< 0.71	U	5.0	0.71	ug/L
,3-Dichloropropene	10061-02-6	< 0.66	U	5.0	0.66	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-08 | Client ID: BH-10

Date Collected: 8/5/03 | Date Received: 8/6/03
Date Analyzed: 8/10/03 | Matrix: WATER
File ID: VD080910.D | Analytical Run ID: VD080903
Dilution: 1 | Instrument ID: MSVOAD
Analytical Method: 8260 | Associated Blank: VBD0808W2
Sample Wt/Wol: 5.0 Units: mL | Soil Extract Vol:
Soil Aliquot Vol: | % Moisture: 100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
cis-1,3-Dichloropropene	10061-01-5	< 0.66	U	5.0	0.66	ug/L
1,1,2-Trichloroethane	79-00-5	< 0.62	U	5.0	0.62	ug/L
1,3-Dichloropropane	142-28-9	< 0.57	U	5.0	0.57	ug/L
2-Chloroethyl vinyl ether	110-75-8	< 2.2	U	5.0	2.2	ug/L
2-Hexanone	591-78-6	< 0.60	U	5.0	0.60	ug/L
Dibromochloromethane	124-48-1	< 0.66	U	5.0	0.66	ug/L
1,2-Dibromoethane	106-93-4	< 0.63	U	5.0	0.63	ug/L
Tetrachloroethene	127-18-4	< 0.70	U	5.0	0.70	ug/L
Chlorobenzene	108-90-7	12		5.0	0.78	ug/L
1,1,1,2-Tetrachloroethane	630-20-6	< 0.64	U	5.0	0.64	ug/L
Ethyl Benzene	100-41-4	< 0.76	U	5.0	0.76	ug/L
m/p-Xylenes	136777-61-2	< 1.5	U	5.0	1.5	ug/L
o-Xylene	95-47-6	6.8		5.0	0.72	ug/L
Styrene	100-42-5	< 0.92	U	5.0	0.92	ug/L
Bromoform	75-25-2	< 0.49	U	5.0	0.49	ug/L
Isopropylbenzene	98-82-8	< 0.75	U	5.0	0.75	ug/L
1,1,2,2-Tetrachloroethane	79-34-5	< 0.70	U	5.0	0.70	ug/L
1,2,3-Trichloropropane	96-18-4	< 1.0	U	5.0	1.0	ug/L
Bromobenzene	108-86-1	< 0.60	U	5.0	0.60	ug/L
N-propylbenzene	103-61-5	< 0.80	U	5.0	0.80	ug/L
2-Chlorotoluene	95-49-8	< 0.85	U	5.0	0.85	ug/L
1,3,5-Trimethylbenzene	108-67-8	13		5.0	0.97	ug/L
4-Chlorotoluene	106-43-4	< 1.0	U	5.0	1.0	ug/L
tert-Butylbenzene	98-06-6	< 0.94	U	5.0	0.94	ug/L
1,2,4-Trimethylbenzene	95-63-6	22		5.0	0.83	ug/L
sec-butylbenzene	135-98-8	< 0.96	U	5.0	0.96	ug/L
4-Isopropyltoluene	99-87-6	< 1.1	U	5.0	1.1	ug/L
1,3-Dichlorobenzene	541-73-1	25		5.0	0.74	ug/L
1,4-Dichlorobenzene	106-46-7	86		5.0	0.93	ug/L
n-Butylbenzene	104-51-8	< 1.2	U	5.0	1.2	ug/L
1,2-Dichlorobenzene	95-50-1	810	E	5.0	0.88	ug/L
1,2-Dibromo-3-Chloropropane	96-12-8	< 0.91	U	5.0	0.91	ug/L
1,2,4-Trichlorobenzene	120-82-1	5.5		5.0	1.3	ug/L
Hexachlorobutadiene	87-68-3	< 0.94	U	5.0	0.94	ug/L
Naphthalene	91-20-3	8.0		5.0	0.91	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-08	Client ID:	BH-10
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
File ID:	VD080910.D	Analytical Run ID:	VD080903
Dilution:	1	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBD0808W2
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 1.0	U	5.0	1.0	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	53.04	106 %	68 - 135		SPK: 50
Dibromofluoromethane	1868-53-7	49.16	98 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	51.13	102 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	51.19	102 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	652931	12.98			
1,4-Difluorobenzene	540-36-3	1115254	15.24			
Chlorobenzene-d5	3114-55-4	1102557	22.59			
1,4-Dichlorobenzene-d4	3855-82-1	630611	28.95			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-08DL	Client ID:	BH-10DL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/14/03	Matrix:	WATER
File ID:	VG081244.D	Analytical Run ID:	VG081303
Dilution:	5	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBG0813W3
Sample Wt/Wol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 3.6	UD	25	3.6	ug/L
hloromethane	74-87-3	< 2.6	UD	25	2.6	ug/L
inyl chloride	75-01-4	< 4.0	UD	25	4.0	ug/L
Bromomethane	74-83-9	< 1.9	UD	25	1.9	ug/L
hloroethane	75-00-3	< 12	UD	25	12	ug/L
richlorofluoromethane	75-69-4	< 3.6	UD	25	3.6	ug/L
Tert butyl alcohol	75-65-0	< 20	UD	120	20	ug/L
1-Dichloroethene	75-35-4	< 3.4	UD	25	3.4	ug/L
crolein	107-02-8	< 24	UD	120	24	ug/L
Acrylonitrile	107-13-1	< 18	UD	120	18	ug/L
cetone	67-64-1	< 18	UD	25	18	ug/L
arbon disulfide	75-15-0	< 3.6	UD	25	3.6	ug/L
Methyl tert-butyl Ether	1634-04-4	16	JD	25	5.2	ug/L
ethylene Chloride	75-09-2	< 8.8	UD	25	8.8	ug/L
rans-1,2-Dichloroethene	156-60-5	< 4.0	UD	25	4.0	ug/L
inyl Acetate	108-05-4	< 13	UD	120	13	ug/L
1-Dichloroethane	75-34-3	< 3.3	UD	25	3.3	ug/L
-Butanone	78-93-3	< 12	UD	25	12	ug/L
arbon Tetrachloride	56-23-5	< 2.4	UD	25	2.4	ug/L
2-Dichloropropane	594-20-7	< 3.2	UD	25	3.2	ug/L
is-1,2-Dichloroethene	156-59-2	< 3.1	UD	25	3.1	ug/L
omochloromethane	74-97-5	< 4.6	UD	25	4.6	ug/L
hloroform	67-66-3	< 3.0	UD	25	3.0	ug/L
,1,1-Trichloroethane	71-55-6	< 3.8	UD	25	3.8	ug/L
1-Dichloropropene	563-43-2	< 15	UD	25	15	ug/L
enzene	71-43-2	< 3.6	UD	25	3.6	ug/L
2-Dichloroethane	107-06-2	< 2.8	UD	25	2.8	ug/L
ichloroethene	79-01-6	< 3.6	UD	25	3.6	ug/L
,2-Dichloropropane	78-87-5	< 3.6	UD	25	3.6	ug/L
ibromomethane	74-95-3	< 3.0	UD	25	3.0	ug/L
omodichloromethane	75-27-4	< 3.6	UD	25	3.6	ug/L
-Methyl-2-Pentanone	108-10-1	< 4.0	UD	25	4.0	ug/L
luene	108-88-3	< 3.6	UD	25	3.6	ug/L
,3-Dichloropropene	10061-02-6	< 3.3	UD	25	3.3	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-08DL	Client ID:	BH-10DL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/14/03	Matrix:	WATER
File ID:	VG081244.D	Analytical Run ID:	VG081303
Dilution:	5	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBG0813W3
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
s-1,3-Dichloropropene	10061-01-5	< 3.3	UD	25	3.3	ug/L
1,1,2-Trichloroethane	79-00-5	< 3.1	UD	25	3.1	ug/L
3-Dichloropropane	142-28-9	< 2.8	UD	25	2.8	ug/L
-Chloroethyl vinyl ether	110-75-8	< 11	UD	25	11	ug/L
2-Hexanone	591-78-6	< 3.0	UD	25	3.0	ug/L
ibromochloromethane	124-48-1	< 3.3	UD	25	3.3	ug/L
2-Dibromoethane	106-93-4	< 3.2	UD	25	3.2	ug/L
Tetrachloroethene	127-18-4	< 3.5	UD	25	3.5	ug/L
hlorobenzene	108-90-7	5.8	JD	25	3.9	ug/L
1,1,2-Tetrachloroethane	630-20-6	< 3.2	UD	25	3.2	ug/L
Ethyl Benzene	100-41-4	< 3.8	UD	25	3.8	ug/L
/p-Xylenes	136777-61-2	< 7.6	UD	25	7.6	ug/L
-Xylene	95-47-6	< 3.6	UD	25	3.6	ug/L
Styrene	100-42-5	< 4.6	UD	25	4.6	ug/L
romoform	75-25-2	< 2.4	UD	25	2.4	ug/L
Isopropylbenzene	98-82-8	< 3.8	UD	25	3.8	ug/L
1,2,2-Tetrachloroethane	79-34-5	< 3.5	UD	25	3.5	ug/L
2,3-Trichloropropane	96-18-4	< 5.2	UD	25	5.2	ug/L
Bromobenzene	108-86-1	< 3.0	UD	25	3.0	ug/L
-propylbenzene	103-61-5	< 4.0	UD	25	4.0	ug/L
Chlorotoluene	95-49-8	< 4.2	UD	25	4.2	ug/L
1,3,5-Trimethylbenzene	108-67-8	6.3	JD	25	4.8	ug/L
Chlorotoluene	106-43-4	< 5.1	UD	25	5.1	ug/L
rt-Butylbenzene	98-06-6	< 4.7	UD	25	4.7	ug/L
1,2,4-Trimethylbenzene	95-63-6	13	JD	25	4.2	ug/L
ec-butylbenzene	135-98-8	< 4.8	UD	25	4.8	ug/L
Isopropyltoluene	99-87-6	< 5.4	UD	25	5.4	ug/L
1,3-Dichlorobenzene	541-73-1	14	JD	25	3.7	ug/L
4-Dichlorobenzene	106-46-7	60	D	25	4.6	ug/L
-Butylbenzene	104-51-8	< 6.2	UD	25	6.2	ug/L
2-Dichlorobenzene	95-50-1	760	D	25	4.4	ug/L
2-Dibromo-3-Chloropropane	96-12-8	< 4.6	UD	25	4.6	ug/L
1,2,4-Trichlorobenzene	120-82-1	< 6.4	UD	25	6.4	ug/L
exachlorobutadiene	87-68-3	< 4.7	UD	25	4.7	ug/L
aphthalene	91-20-3	7.6	JD	25	4.6	ug/L

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-08DL	Client ID:	BH-10DL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/14/03	Matrix:	WATER
File ID:	VG081244.D	Analytical Run ID:	VG081303
Dilution:	5	Instrument ID:	MSVOAD
Analytical Method:	8260	Associated Blank:	VBG0813W3
Sample Wt/Vol:	5.0 Units: mL	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	100

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 5.2	UD	25	5.2	ug/L
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	52.11	104 %	68 - 135		SPK: 50
Dibromofluoromethane	1868-53-7	51.3	103 %	70 - 125		SPK: 50
Toluene-d8	2037-26-5	50.35	101 %	70 - 125		SPK: 50
4-Bromofluorobenzene	460-00-4	54.78	110 %	70 - 125		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	1069733	8.26			
1,4-Difluorobenzene	540-36-3	2096791	9.80			
Chlorobenzene-d5	3114-55-4	1660263	16.12			
1,4-Dichlorobenzene-d4	3855-82-1	609311	21.33			

Hit Summary Report

SDG No.: R3695 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: VOC- Chemtech Full

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
Client ID:	BH-10							
3695-08	BH-10	WATER	Methyl tert-butyl Ether	19		5.0	1.0	ug/L
R3695-08	BH-10	WATER	cis-1,2-Dichloroethene	2.2	J	5.0	0.62	ug/L
3695-08	BH-10	WATER	Trichloroethene	1.4	J	5.0	0.72	ug/L
3695-08	BH-10	WATER	1,2-Dichloropropane	2.9	J	5.0	0.73	ug/L
R3695-08	BH-10	WATER	Chlorobenzene	12		5.0	0.78	ug/L
3695-08	BH-10	WATER	o-Xylene	6.8		5.0	0.72	ug/L
3695-08	BH-10	WATER	1,3,5-Trimethylbenzene	13		5.0	0.97	ug/L
R3695-08	BH-10	WATER	1,2,4-Trimethylbenzene	22		5.0	0.83	ug/L
3695-08	BH-10	WATER	1,3-Dichlorobenzene	25		5.0	0.74	ug/L
3695-08	BH-10	WATER	1,4-Dichlorobenzene	86		5.0	0.93	ug/L
R3695-08	BH-10	WATER	1,2,4-Trichlorobenzene	5.5		5.0	1.3	ug/L
3695-08	BH-10	WATER	Naphthalene	8.0		5.0	0.91	ug/L
			Total VOC's:	203.80				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	203.80				
Client ID:	BH-10DL							
3695-08DL	BH-10DL	WATER	Methyl tert-butyl Ether	16	JD	25	5.2	ug/L
3695-08DL	BH-10DL	WATER	Chlorobenzene	5.8	JD	25	3.9	ug/L
3695-08DL	BH-10DL	WATER	1,3,5-Trimethylbenzene	6.3	JD	25	4.8	ug/L
3695-08DL	BH-10DL	WATER	1,2,4-Trimethylbenzene	13	JD	25	4.2	ug/L
3695-08DL	BH-10DL	WATER	1,3-Dichlorobenzene	14	JD	25	3.7	ug/L
3695-08DL	BH-10DL	WATER	1,4-Dichlorobenzene	60	D	25	4.6	ug/L
3695-08DL	BH-10DL	WATER	1,2-Dichlorobenzene	760	D	25	4.4	ug/L
3695-08DL	BH-10DL	WATER	Naphthalene	7.6	JD	25	4.6	ug/L
			Total VOC's:	882.70				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	882.70				
nt ID:	BH-6							
3695-01	BH-6	WATER	Methyl tert-butyl Ether	13		5.0	1.0	ug/L
3695-01	BH-6	WATER	Naphthalene	35		5.0	0.91	ug/L
			Total VOC's:	48.00				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	48.00				
lient ID:	BH-8							
3695-05	BH-8	WATER	Methyl tert-butyl Ether	9.4		5.0	1.0	ug/L
			Total VOC's:	9.40				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	9.40				

e: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Hit Summary Report

SDG No.: R3695 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: VOC- Chemtech Full

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
ient ID:	BH-9S							
695-07	BH-9S	SOIL	Methylene Chloride	10	B	5.3	1.4	ug/Kg
3695-07	BH-9S	SOIL	cis-1,2-Dichloroethene	15		5.3	0.95	ug/Kg
695-07	BH-9S	SOIL	Trichloroethene	21		5.3	1.1	ug/Kg
695-07	BH-9S	SOIL	Toluene	4.7	J	5.3	1.2	ug/Kg
3695-07	BH-9S	SOIL	Tetrachloroethene	8.4		5.3	1.3	ug/Kg
695-07	BH-9S	SOIL	Chlorobenzene	7.5		5.3	1.2	ug/Kg
695-07	BH-9S	SOIL	m/p-Xylenes	5.8		5.3	2.9	ug/Kg
3695-07	BH-9S	SOIL	o-Xylene	1.2	J	5.3	1.2	ug/Kg
695-07	BH-9S	SOIL	1,2,4-Trimethylbenzene	2.7	J	5.3	1.5	ug/Kg
3695-07	BH-9S	SOIL	1,3-Dichlorobenzene	5.1	J	5.3	1.1	ug/Kg
3695-07	BH-9S	SOIL	1,4-Dichlorobenzene	14		5.3	0.84	ug/Kg
695-07	BH-9S	SOIL	1,2-Dichlorobenzene	140		5.3	0.95	ug/Kg
3695-07	BH-9S	SOIL	Naphthalene	1.5	J	5.3	1.3	ug/Kg
			Total VOC's:	236.90				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	236.90				
ent ID:	BH-9SDL							
3695-07DL	BH-9SDL	SOIL	Methylene Chloride	7.4	D	5.3	1.4	ug/Kg
695-07DL	BH-9SDL	SOIL	cis-1,2-Dichloroethene	13	D	5.3	0.95	ug/Kg
695-07DL	BH-9SDL	SOIL	Trichloroethene	20	D	5.3	1.1	ug/Kg
3695-07DL	BH-9SDL	SOIL	Toluene	4.2	JD	5.3	1.2	ug/Kg
695-07DL	BH-9SDL	SOIL	Tetrachloroethene	7.2	D	5.3	1.3	ug/Kg
695-07DL	BH-9SDL	SOIL	Chlorobenzene	6.6	D	5.3	1.2	ug/Kg
3695-07DL	BH-9SDL	SOIL	m/p-Xylenes	4.9	JD	5.3	2.9	ug/Kg
695-07DL	BH-9SDL	SOIL	1,2,4-Trimethylbenzene	2.6	JD	5.3	1.5	ug/Kg
695-07DL	BH-9SDL	SOIL	1,3-Dichlorobenzene	4.6	JD	5.3	1.1	ug/Kg
3695-07DL	BH-9SDL	SOIL	1,4-Dichlorobenzene	12	D	5.3	0.84	ug/Kg
695-07DL	BH-9SDL	SOIL	1,2-Dichlorobenzene	130	D	5.3	0.95	ug/Kg
			Total VOC's:	212.50				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	212.50				

ote: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Hit Summary Report

SDG No.: R3695 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: VOC- Chemtech Full

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
Client ID:	BH-9W							
3695-06	BH-9W	WATER	Methyl tert-butyl Ether	18		5.0	1.0	ug/L
R3695-06	BH-9W	WATER	cis-1,2-Dichloroethene	2.0	J	5.0	0.62	ug/L
3695-06	BH-9W	WATER	Trichloroethene	1.8	J	5.0	0.72	ug/L
3695-06	BH-9W	WATER	1,2-Dichloropropane	2.2	J	5.0	0.73	ug/L
R3695-06	BH-9W	WATER	Chlorobenzene	12		5.0	0.78	ug/L
3695-06	BH-9W	WATER	o-Xylene	6.3		5.0	0.72	ug/L
3695-06	BH-9W	WATER	1,3,5-Trimethylbenzene	8.0		5.0	0.97	ug/L
R3695-06	BH-9W	WATER	1,2,4-Trimethylbenzene	19		5.0	0.83	ug/L
3695-06	BH-9W	WATER	1,3-Dichlorobenzene	22		5.0	0.74	ug/L
R3695-06	BH-9W	WATER	1,4-Dichlorobenzene	72		5.0	0.93	ug/L
R3695-06	BH-9W	WATER	1,2,4-Trichlorobenzene	4.2	J	5.0	1.3	ug/L
3695-06	BH-9W	WATER	Naphthalene	4.5	J	5.0	0.91	ug/L
			Total VOC's:	172.00				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	172.00				
Client ID:	BH-9WDL							
3695-06DL	BH-9WDL	WATER	Methyl tert-butyl Ether	17	JD	25	5.2	ug/L
R3695-06DL	BH-9WDL	WATER	4-Methyl-2-Pentanone	6.5	JD	25	4.0	ug/L
R3695-06DL	BH-9WDL	WATER	Chlorobenzene	6.3	JD	25	3.9	ug/L
3695-06DL	BH-9WDL	WATER	1,3,5-Trimethylbenzene	5.6	JD	25	4.8	ug/L
R3695-06DL	BH-9WDL	WATER	1,2,4-Trimethylbenzene	12	JD	25	4.2	ug/L
3695-06DL	BH-9WDL	WATER	1,3-Dichlorobenzene	13	JD	25	3.7	ug/L
3695-06DL	BH-9WDL	WATER	1,4-Dichlorobenzene	53	D	25	4.6	ug/L
R3695-06DL	BH-9WDL	WATER	1,2-Dichlorobenzene	720	D	25	4.4	ug/L
3695-06DL	BH-9WDL	WATER	Naphthalene	11	JD	25	4.6	ug/L
			Total VOC's:	844.40				
			Total TIC's:	0.00				
			Total VOC's and TIC's:	844.40				

Note: The asterisk "*" flag next to a parameter signifies a TIC parameter.

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-02	Client ID:	BH-6
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011469.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
bis(2-Chloroethyl)ether	111-44-4	< 1.2	U	10	1.2	ug/L
1,2-Dichlorobenzene	95-50-1	< 1.0	U	10	1.0	ug/L
1,3-Dichlorobenzene	541-73-1	< 1.2	U	10	1.2	ug/L
1,4-Dichlorobenzene	106-46-7	< 1.0	U	10	1.0	ug/L
2,2-oxybis(1-Chloropropane)	108-60-1	< 1.0	U	10	1.0	ug/L
N-Nitroso-di-n-propylamine	621-64-7	< 1.0	U	10	1.0	ug/L
Hexachloroethane	67-72-1	< 1.1	U	10	1.1	ug/L
Nitrobenzene	98-95-3	< 1.0	U	10	1.0	ug/L
Isophorone	78-59-1	< 1.0	U	10	1.0	ug/L
bis(2-Chloroethoxy)methane	111-91-1	< 1.0	U	10	1.0	ug/L
1,2,4-Trichlorobenzene	120-82-1	< 1.2	U	10	1.2	ug/L
Naphthalene	91-20-3	21		10	1.2	ug/L
4-Chloroaniline	106-47-8	< 1.2	U	10	1.2	ug/L
Hexachlorobutadiene	87-68-3	< 1.5	U	10	1.5	ug/L
2-Methylnaphthalene	91-57-6	3.4	J	10	1.2	ug/L
Hexachlorocyclopentadiene	77-47-4	< 3.9	U	10	3.9	ug/L
2-Chloronaphthalene	91-58-7	< 1.2	U	10	1.2	ug/L
2-Nitroaniline	88-74-4	< 1.0	U	10	1.0	ug/L
Dimethylphthalate	131-11-3	< 1.0	U	10	1.0	ug/L
Acenaphthylene	208-96-8	1.3	J	10	1.2	ug/L
2,6-Dinitrotoluene	606-20-2	< 1.0	U	10	1.0	ug/L
3-Nitroaniline	99-09-2	< 1.2	U	10	1.2	ug/L
Acenaphthene	83-32-9	7.2	J	10	1.0	ug/L
Dibenzofuran	132-64-9	5.3	J	10	1.0	ug/L
2,4-Dinitrotoluene	121-14-2	< 1.1	U	10	1.1	ug/L
Diethylphthalate	84-66-2	< 1.0	U	10	1.0	ug/L
4-Chlorophenyl-phenylether	7005-72-3	< 1.2	U	10	1.2	ug/L
Fluorene	86-73-7	8.5	J	10	1.1	ug/L
4-Nitroaniline	100-01-6	< 2.4	U	10	2.4	ug/L
N-Nitrosodiphenylamine	86-30-6	< 2.0	U	10	2.0	ug/L
Azobenzene	122-66-7	< 0.330	U	10	0.330	ug/L

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-02	Client ID:	BH-6
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011469.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
4-Bromophenyl-phenylether	101-55-3	< 1.3	U	10	1.3	ug/L
Hexachlorobenzene	118-74-1	< 1.1	U	10	1.1	ug/L
Phenanthrene	85-01-8	36		10	1.0	ug/L
Anthracene	120-12-7	8.6	J	10	1.3	ug/L
Di-n-butylphthalate	84-74-2	< 1.2	U	10	1.2	ug/L
Fluoranthene	206-44-0	27		10	1.0	ug/L
Pyrene	129-00-0	22		10	1.0	ug/L
Butylbenzylphthalate	85-68-7	< 1.0	U	10	1.0	ug/L
3,3-Dichlorobenzidine	91-94-1	< 1.0	U	20	1.0	ug/L
Benzo(a)anthracene	56-55-3	11		10	1.0	ug/L
Chrysene	218-01-9	11		10	1.6	ug/L
bis(2-Ethylhexyl)phthalate	117-81-7	3.1	JB	10	1.0	ug/L
Di-n-octyl phthalate	117-84-0	< 1.5	U	10	1.5	ug/L
Benzo(b)fluoranthene	205-99-2	10	J	10	1.0	ug/L
Benzo(k)fluoranthene	207-08-9	10	J	10	2.7	ug/L
Benzo(a)pyrene	50-32-8	12		10	1.5	ug/L
Indeno(1,2,3-cd)pyrene	193-39-5	5.3	J	10	1.6	ug/L
Dibenz(a,h)anthracene	53-70-3	4.2	J	10	1.5	ug/L
Benzo(g,h,i)perylene	191-24-2	7.0	J	10	1.3	ug/L
SURROGATES						
Nitrobenzene-d5	4165-60-0	129.45	65 %	35 - 114		SPK: 200
2-Fluorobiphenyl	321-60-8	130.28	65 %	43 - 116		SPK: 200
Terphenyl-d14	1718-51-0	100.45	50 %	33 - 141		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	171580	4.83			
Naphthalene-d8	1146-65-2	638536	6.98			
Acenaphthene-d10	15067-26-2	459049	10.32			
Phenanthrene-d10	1517-22-2	700211	13.20			
Chrysene-d12	1719-03-5	708530	18.45			
Perylene-d12	1520-96-3	665309	21.14			

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-05	Client ID:	BH-8
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011461.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
bis(2-Chloroethyl)ether	111-44-4	< 1.2	U	10	1.2	ug/L
1,2-Dichlorobenzene	95-50-1	< 1.0	U	10	1.0	ug/L
1,3-Dichlorobenzene	541-73-1	< 1.2	U	10	1.2	ug/L
1,4-Dichlorobenzene	106-46-7	< 1.0	U	10	1.0	ug/L
2,2-oxybis(1-Chloropropane)	108-60-1	< 1.0	U	10	1.0	ug/L
N-Nitroso-di-n-propylamine	621-64-7	< 1.0	U	10	1.0	ug/L
Hexachloroethane	67-72-1	< 1.1	U	10	1.1	ug/L
Nitrobenzene	98-95-3	< 1.0	U	10	1.0	ug/L
Isophorone	78-59-1	< 1.0	U	10	1.0	ug/L
bis(2-Chloroethoxy)methane	111-91-1	< 1.0	U	10	1.0	ug/L
1,2,4-Trichlorobenzene	120-82-1	< 1.2	U	10	1.2	ug/L
Naphthalene	91-20-3	< 1.2	U	10	1.2	ug/L
4-Chloroaniline	106-47-8	< 1.2	U	10	1.2	ug/L
Hexachlorobutadiene	87-68-3	< 1.5	U	10	1.5	ug/L
2-Methylnaphthalene	91-57-6	< 1.2	U	10	1.2	ug/L
Hexachlorocyclopentadiene	77-47-4	< 3.9	U	10	3.9	ug/L
2-Chloronaphthalene	91-58-7	< 1.2	U	10	1.2	ug/L
2-Nitroaniline	88-74-4	< 1.0	U	10	1.0	ug/L
Dimethylphthalate	131-11-3	< 1.0	U	10	1.0	ug/L
Acenaphthylene	208-96-8	< 1.2	U	10	1.2	ug/L
2,6-Dinitrotoluene	606-20-2	< 1.0	U	10	1.0	ug/L
3-Nitroaniline	99-09-2	< 1.2	U	10	1.2	ug/L
Acenaphthene	83-32-9	< 1.0	U	10	1.0	ug/L
Dibenzofuran	132-64-9	< 1.0	U	10	1.0	ug/L
2,4-Dinitrotoluene	121-14-2	< 1.1	U	10	1.1	ug/L
Diethylphthalate	84-66-2	< 1.0	U	10	1.0	ug/L
4-Chlorophenyl-phenylether	7005-72-3	< 1.2	U	10	1.2	ug/L
Fluorene	86-73-7	< 1.1	U	10	1.1	ug/L
4-Nitroaniline	100-01-6	< 2.4	U	10	2.4	ug/L
N-Nitrosodiphenylamine	86-30-6	< 2.0	U	10	2.0	ug/L
Azobenzene	122-66-7	< 0.330	U	10	0.330	ug/L

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-05	Client ID:	BH-8
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011461.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
4-Bromophenyl-phenylether	101-55-3	< 1.3	U	10	1.3	ug/L
Hexachlorobenzene	118-74-1	< 1.1	U	10	1.1	ug/L
Phenanthrene	85-01-8	< 1.0	U	10	1.0	ug/L
Anthracene	120-12-7	< 1.3	U	10	1.3	ug/L
Di-n-butylphthalate	84-74-2	1.2	J	10	1.2	ug/L
Fluoranthene	206-44-0	< 1.0	U	10	1.0	ug/L
Pyrene	129-00-0	< 1.0	U	10	1.0	ug/L
Butylbenzylphthalate	85-68-7	< 1.0	U	10	1.0	ug/L
3,3-Dichlorobenzidine	91-94-1	< 1.0	U	20	1.0	ug/L
Benzo(a)anthracene	56-55-3	< 1.0	U	10	1.0	ug/L
Chrysene	218-01-9	< 1.6	U	10	1.6	ug/L
bis(2-Ethylhexyl)phthalate	117-81-7	6.3	JB	10	1.0	ug/L
Di-n-octyl phthalate	117-84-0	< 1.5	U	10	1.5	ug/L
Benzo(b)fluoranthene	205-99-2	< 1.0	U	10	1.0	ug/L
Benzo(k)fluoranthene	207-08-9	< 2.7	U	10	2.7	ug/L
Benzo(a)pyrene	50-32-8	< 1.5	U	10	1.5	ug/L
Indeno(1,2,3-cd)pyrene	193-39-5	< 1.6	U	10	1.6	ug/L
Dibenz(a,h)anthracene	53-70-3	< 1.5	U	10	1.5	ug/L
Benzo(g,h,i)perylene	191-24-2	< 1.3	U	10	1.3	ug/L
SURROGATES						
Nitrobenzene-d5	4165-60-0	102.56	51 %	35 - 114		SPK: 200
2-Fluorobiphenyl	321-60-8	124	62 %	43 - 116		SPK: 200
Terphenyl-d14	1718-51-0	100.79	50 %	33 - 141		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	165690	4.82			
Naphthalene-d8	1146-65-2	636490	6.99			
Acenaphthene-d10	15067-26-2	446386	10.33			
Phenanthrene-d10	1517-22-2	675842	13.20			
Chrysene-d12	1719-03-5	698466	18.43			
Perylene-d12	1520-96-3	652893	21.11			

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06	Client ID:	BH-9-W
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011468.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	960.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
bis(2-Chloroethyl)ether	111-44-4	< 1.2	U	10	1.2	ug/L
1,2-Dichlorobenzene	95-50-1	390	E	10	1.0	ug/L
1,3-Dichlorobenzene	541-73-1	23		10	1.2	ug/L
1,4-Dichlorobenzene	106-46-7	76		10	1.0	ug/L
2,2-oxybis(1-Chloropropane)	108-60-1	< 1.0	U	10	1.0	ug/L
N-Nitroso-di-n-propylamine	621-64-7	< 1.0	U	10	1.0	ug/L
Hexachloroethane	67-72-1	< 1.1	U	10	1.1	ug/L
Nitrobenzene	98-95-3	< 1.0	U	10	1.0	ug/L
Isophorone	78-59-1	< 1.0	U	10	1.0	ug/L
bis(2-Chloroethoxy)methane	111-91-1	< 1.0	U	10	1.0	ug/L
1,2,4-Trichlorobenzene	120-82-1	5.9	J	10	1.2	ug/L
Naphthalene	91-20-3	10	J	10	1.2	ug/L
4-Chloroaniline	106-47-8	< 1.2	U	10	1.2	ug/L
Hexachlorobutadiene	87-68-3	< 1.6	U	10	1.6	ug/L
2-Methylnaphthalene	91-57-6	2.8	J	10	1.2	ug/L
Hexachlorocyclopentadiene	77-47-4	< 4.0	U	10	4.0	ug/L
2-Chloronaphthalene	91-58-7	< 1.2	U	10	1.2	ug/L
2-Nitroaniline	88-74-4	< 1.0	U	10	1.0	ug/L
Dimethylphthalate	131-11-3	< 1.0	U	10	1.0	ug/L
Acenaphthylene	208-96-8	< 1.2	U	10	1.2	ug/L
2,6-Dinitrotoluene	606-20-2	< 1.0	U	10	1.0	ug/L
3-Nitroaniline	99-09-2	< 1.2	U	10	1.2	ug/L
Acenaphthene	83-32-9	< 1.0	U	10	1.0	ug/L
Dibenzofuran	132-64-9	< 1.0	U	10	1.0	ug/L
2,4-Dinitrotoluene	121-14-2	< 1.1	U	10	1.1	ug/L
Diethylphthalate	84-66-2	< 1.0	U	10	1.0	ug/L
4-Chlorophenyl-phenylether	7005-72-3	< 1.2	U	10	1.2	ug/L
Fluorene	86-73-7	< 1.1	U	10	1.1	ug/L
4-Nitroaniline	100-01-6	< 2.5	U	10	2.5	ug/L
N-Nitrosodiphenylamine	86-30-6	< 2.1	U	10	2.1	ug/L
Azobenzene	122-66-7	< 0.340	U	10	0.340	ug/L

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06	Client ID:	BH-9-W
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	WATER
Date Extracted:	8/9/03	File ID:	BB011468.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	960.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
4-Bromophenyl-phenylether	101-55-3	< 1.4	U	10	1.4	ug/L
Hexachlorobenzene	118-74-1	< 1.1	U	10	1.1	ug/L
Phenanthrene	85-01-8	< 1.0	U	10	1.0	ug/L
Anthracene	120-12-7	< 1.4	U	10	1.4	ug/L
Di-n-butylphthalate	84-74-2	1.7	J	10	1.2	ug/L
Fluoranthene	206-44-0	1.3	J	10	1.0	ug/L
Pyrene	129-00-0	2.7	J	10	1.0	ug/L
Butylbenzylphthalate	85-68-7	< 1.0	U	10	1.0	ug/L
3,3-Dichlorobenzidine	91-94-1	< 1.0	U	21	1.0	ug/L
Benzo(a)anthracene	56-55-3	1.1	J	10	1.0	ug/L
Chrysene	218-01-9	< 1.7	U	10	1.7	ug/L
bis(2-Ethylhexyl)phthalate	117-81-7	3.0	JB	10	1.0	ug/L
Di-n-octyl phthalate	117-84-0	< 1.6	U	10	1.6	ug/L
Benzo(b)fluoranthene	205-99-2	1.1	J	10	1.0	ug/L
Benzo(k)fluoranthene	207-08-9	< 2.7	U	10	2.7	ug/L
Benzo(a)pyrene	50-32-8	1.9	J	10	1.6	ug/L
Indeno(1,2,3-cd)pyrene	193-39-5	< 1.7	U	10	1.7	ug/L
Dibenz(a,h)anthracene	53-70-3	< 1.6	U	10	1.6	ug/L
Benzo(g,h,i)perylene	191-24-2	1.4	J	10	1.4	ug/L
SURROGATES						
Nitrobenzene-d5	4165-60-0	136.69	68 %	35 - 114		SPK: 200
2-Fluorobiphenyl	321-60-8	153.81	77 %	43 - 116		SPK: 200
Terphenyl-d14	1718-51-0	120.95	60 %	33 - 141		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	147822	4.83			
Naphthalene-d8	1146-65-2	571173	6.99			
Acenaphthene-d10	15067-26-2	409103	10.32			
Phenanthrene-d10	1517-22-2	677596	13.21			
Chrysene-d12	1719-03-5	647818	18.45			
Perylene-d12	1520-96-3	585689	21.13			

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-06DL | Client ID: BH-9WDL

Date Collected: 8/5/03 | Date Received: 8/6/03
Date Analyzed: 8/13/03 | Matrix: WATER
Date Extracted: 8/9/03 8/8/03 | File ID: BB011546.D
Dilution: 10 | Instrument ID: BNAB
Analytical Method: 8270 | Analytical Run ID: BB072803
Sample Wt/Vol: 980.0 | Extract Vol: 1000
Injection Vol: 2 | % Moisture: 100
Associated Blank: PB080903-07B

rameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
s(2-Chloroethyl)ether	111-44-4	< 12	UD	100	12	ug/L
2-Dichlorobenzene	95-50-1	900	ED	100	10	ug/L
1,3-Dichlorobenzene	541-73-1	24	JD	100	12	ug/L
4-Dichlorobenzene	106-46-7	96	JD	100	10	ug/L
2-oxybis(1-Chloropropane)	108-60-1	< 10	UD	100	10	ug/L
N-Nitroso-di-n-propylamine	621-64-7	< 10	UD	100	10	ug/L
exachloroethane	67-72-1	< 11	UD	100	11	ug/L
itrobenzene	98-95-3	< 10	UD	100	10	ug/L
sophorone	78-59-1	< 10	UD	100	10	ug/L
(2-Chloroethoxy)methane	111-91-1	< 10	UD	100	10	ug/L
2,4-Trichlorobenzene	120-82-1	< 12	UD	100	12	ug/L
aphthalene	91-20-3	< 12	UD	100	12	ug/L
Chloroaniline	106-47-8	< 12	UD	100	12	ug/L
exachlorobutadiene	87-68-3	< 15	UD	100	15	ug/L
Methylnaphthalene	91-57-6	< 12	UD	100	12	ug/L
xachlorocyclopentadiene	77-47-4	< 39	UD	100	39	ug/L
-Chloronaphthalene	91-58-7	< 12	UD	100	12	ug/L
Nitroaniline	88-74-4	< 10	UD	100	10	ug/L
methylphthalate	131-11-3	< 10	UD	100	10	ug/L
cenaphthylene	208-96-8	< 12	UD	100	12	ug/L
-Dinitrotoluene	606-20-2	< 10	UD	100	10	ug/L
Nitroaniline	99-09-2	< 12	UD	100	12	ug/L
cenaphthene	83-32-9	< 10	UD	100	10	ug/L
enzofuran	132-64-9	< 10	UD	100	10	ug/L
4-Dinitrotoluene	121-14-2	< 11	UD	100	11	ug/L
ethylphthalate	84-66-2	< 10	UD	100	10	ug/L
Chlorophenyl-phenylether	7005-72-3	< 12	UD	100	12	ug/L
luorene	86-73-7	< 11	UD	100	11	ug/L
Nitroaniline	100-01-6	< 24	UD	100	24	ug/L
Nitrosodiphenylamine	86-30-6	< 20	UD	100	20	ug/L
-Bromophenyl-phenylether	101-55-3	< 13	UD	100	13	ug/L

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-06DL	Client ID:	BH-9WDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/13/03	Matrix:	WATER
Date Extracted:	8/9/03 8/8/03	File ID:	BB011546.D
Dilution:	10	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	980.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	100
Associated Blank:	PB080903-07B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
Hexachlorobenzene	118-74-1	< 11	UD	100	11	ug/L
Phenanthrene	85-01-8	< 10	UD	100	10	ug/L
Anthracene	120-12-7	< 13	UD	100	13	ug/L
Carbazole	86-74-8	< 4.2	UD	100	4.2	ug/L
Di-n-butylphthalate	84-74-2	< 12	UD	100	12	ug/L
Fluoranthene	206-44-0	< 10	UD	100	10	ug/L
Pyrene	129-00-0	< 10	UD	100	10	ug/L
Butylbenzylphthalate	85-68-7	< 10	UD	100	10	ug/L
3,3-Dichlorobenzidine	91-94-1	< 10	UD	200	10	ug/L
Benzo(a)anthracene	56-55-3	< 10	UD	100	10	ug/L
Chrysene	218-01-9	< 16	UD	100	16	ug/L
bis(2-Ethylhexyl)phthalate	117-81-7	< 10	UD	100	10	ug/L
Di-n-octyl phthalate	117-84-0	< 15	UD	100	15	ug/L
Benzo(b)fluoranthene	205-99-2	< 10	UD	100	10	ug/L
Benzo(k)fluoranthene	207-08-9	< 27	UD	100	27	ug/L
Benzo(a)pyrene	50-32-8	< 15	UD	100	15	ug/L
Indeno(1,2,3-cd)pyrene	193-39-5	< 16	UD	100	16	ug/L
Dibenz(a,h)anthracene	53-70-3	< 15	UD	100	15	ug/L
Benzo(g,h,i)perylene	191-24-2	< 13	UD	100	13	ug/L
SURROGATES						
Nitrobenzene-d5	4165-60-0	151.2	76 %	35 - 114		SPK: 200
2-Fluorobiphenyl	321-60-8	192.2	96 %	43 - 116		SPK: 200
Terphenyl-d14	1718-51-0	183.1	92 %	33 - 141		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	155932	4.79			
Naphthalene-d8	1146-65-2	625128	6.96			
Acenaphthene-d10	15067-26-2	437647	10.29			
Phenanthrene-d10	1517-22-2	666605	13.16			
Chrysene-d12	1719-03-5	573518	18.41			
Perylene-d12	1520-96-3	260489	21.08			

Hit Summary Report

SDG No.: R3695-01 **Order ID:** R3695

Client: ASTEM Laboratory, Inc. **Project ID:**

Test: SVOC-Chemtech Full BN

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
ient ID:	BH-9W							
695-06	BH-9W	WATER	1,3-Dichlorobenzene	23		10	1.2	ug/L
R3695-06	BH-9W	WATER	1,4-Dichlorobenzene	76		10	1.0	ug/L
695-06	BH-9W	WATER	1,2,4-Trichlorobenzene	5.9	J	10	1.2	ug/L
695-06	BH-9W	WATER	Naphthalene	10	J	10	1.2	ug/L
R3695-06	BH-9W	WATER	2-Methylnaphthalene	2.8	J	10	1.2	ug/L
695-06	BH-9W	WATER	Di-n-butylphthalate	1.7	J	10	1.2	ug/L
3695-06	BH-9W	WATER	Fluoranthene	1.3	J	10	1.0	ug/L
R3695-06	BH-9W	WATER	Pyrene	2.7	J	10	1.0	ug/L
695-06	BH-9W	WATER	Benzo(a)anthracene	1.1	J	10	1.0	ug/L
3695-06	BH-9W	WATER	bis(2-Ethylhexyl)phthalate	3.0	JB	10	1.0	ug/L
695-06	BH-9W	WATER	Benzo(b)fluoranthene	1.1	J	10	1.0	ug/L
695-06	BH-9W	WATER	Benzo(a)pyrene	1.9	J	10	1.6	ug/L
3695-06	BH-9W	WATER	Benzo(g,h,i)perylene	1.4	J	10	1.4	ug/L
			Total SVOC's:	131.90				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	131.90				
ent ID:	BH-9WDL							
3695-06DL	BH-9WDL	WATER	1,3-Dichlorobenzene	24	JD	100	12	ug/L
695-06DL	BH-9WDL	WATER	1,4-Dichlorobenzene	96	JD	100	10	ug/L
			Total SVOC's:	120.00				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	120.00				

ote: The asterisk "*" flag next to a parameter signifies a TIC parameter.

APPENDIX C

Soil Analytical Reports

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-1
LAB ID: R2982-07
FILENAME: F:\DATA1\U062315.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.3
74-87-3	CHLOROMETHANE	U		1.3
75-01-4	VINYL CHLORIDE	U		1.3
74-97-5	BROMOMETHANE	U		1.3
75-00-3	CHLOROETHANE	U		1.3
75-69-4	TRICHLOROFLOUROMETHANE	U		1.3
75-35-4	1,1 DICHLOROETHENE	U		1.3
75-09-2	METHYLENE CHLORIDE	3.1	B	1.3
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.3
75-34-3	1,1 DICHLOROETHANE	U		1.3
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.5
67-66-3	CHLOROFORM	U		1.3
74-97-5	BROMOCHLOROMETHANE	U		1.3
71-55-6	1,1,1 TRICHLOROETHANE	U		1.3
563-58-6	1,1 DICHLOROPROPENE	U		1.3
56-23-5	CARBON TETRACHLORIDE	U		1.3
107-06-2	1,2 DICHLOROETHANE	U		1.3
79-01-6	TRICHLOROETHENE	U		1.3
78-87-5	1,2 DICHLOROPROPANE	U		1.3
75-27-4	BROMODICHLOROMETHANE	U		1.3
74-95-3	DIBROMOMETHANE	U		1.3
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.3
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.3
630-20-6	1,1,2-TRICHLOROETHANE	U		1.3
142-28-9	1,3 DICHLOROPROPANE	U		1.3
127-18-4	TETRACHLOROETHENE	U		1.3
75-27-4	DIBROMOCHLOROMETHANE	U		1.3
106-93-4	1,2 DIBROMOETHANE	U		1.3
108-90-7	CHLOROBENZENE	U		1.3
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.3
75-25-2	BROMOFORM	U		1.3
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.3
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.3
108-86-1	BROMOBENZENE	U		1.3
95-49-8	2, CHLOROTOLUENE	U		1.3
106-34-4	4, CHLOROTOLUENE	U		1.3
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.3
87-68-3	HEXACHLOROBUTADIENE	U		1.3
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.3

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

% SOLIDS 79%

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-1
LAB ID: R2982-07
FILENAME: F:\DATA1\V062315.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		1.3
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	U		1.3
71-43-2	BENZENE	U		1.3
108-88-3	TOLUENE	U		1.3
100-41-4	ETHYLBENZENE	U		1.3
136777-61-2	M&P XYLENES	U		2.5
95-47-6	O-XYLENE	U		1.3
100-42-5	STYRENE	U		1.3
98-82-8	ISOPROPYLBENZENE	U		1.3
103-65-1	n-PROPYLBENZENE	U		1.3
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.5
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.5
98-06-6	TERT-BUTYLBENZENE	U		1.3
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.3
135-98-8	SEC-BUTYLBENZENE	U		1.3
541-73-1	1,3 DICHLOROBENZENE	U		1.3
99-87-6	ISOPROPYLTOLUENE	U		1.3
106-46-7	1,4 DICHLOROBENZENE	U		1.3
104-51-8	n-BUTYLBENZENE	U		1.3
95-50-1	1,2 DICHLOROBENZENE	U		1.3
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.3
87-68-3	HEXACHLOROBUTADIENE	U		1.3
91-20-3	NAPHTHALENE	U		1.3

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

% SOLIDS 79%

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-2
LAB ID: R2982-08
FILENAME: F:\DATA1\U062406.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.3
74-87-3	CHLOROMETHANE	U		1.3
75-01-4	VINYL CHLORIDE	U		1.3
74-97-5	BROMOMETHANE	U		1.3
75-00-3	CHLOROETHANE	U		1.3
75-69-4	TRICHLOROFLOUROMETHANE	U		1.3
75-35-4	1,1 DICHLOROETHENE	U		1.3
75-09-2	METHYLENE CHLORIDE	U		1.3
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.3
75-34-3	1,1 DICHLOROETHANE	U		1.3
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.6
67-66-3	CHLOROFORM	U		1.3
74-97-5	BROMOCHLOROMETHANE	U		1.3
71-55-6	1,1,1 TRICHLOROETHANE	U		1.3
563-58-6	1,1 DICHLOROPROPENE	U		1.3
56-23-5	CARBON TETRACHLORIDE	U		1.3
107-06-2	1,2 DICHLOROETHANE	U		1.3
79-01-6	TRICHLOROETHENE	U		1.3
78-87-5	1,2 DICHLOROPROPANE	U		1.3
75-27-4	BROMODICHLOROMETHANE	U		1.3
74-95-3	DIBROMOMETHANE	U		1.3
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.3
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.3
630-20-6	1,1,2-TRICHLOROETHANE	U		1.3
142-28-9	1,3 DICHLOROPROPANE	U		1.3
127-18-4	TETRACHLOROETHENE	U		1.3
75-27-4	DIBROMOCHLOROMETHANE	U		1.3
106-93-4	1,2 DIBROMOETHANE	U		1.3
108-90-7	CHLOROBENZENE	U		1.3
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.3
75-25-2	BROMOFORM	U		1.3
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.3
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.3
108-86-1	BROMOBENZENE	U		1.3
95-49-8	2, CHLOROTOLUENE	U		1.3
106-34-4	4, CHLOROTOLUENE	U		1.3
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.3
87-68-3	HEXACHLOROBUTADIENE	U		1.3
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.3

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

% SOLIDS 78%

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-2
LAB ID: R2982-08
FILENAME: F:\DATA1\V062406.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		1.3
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	U		1.3
71-43-2	BENZENE	U		1.3
108-88-3	TOLUENE	U		1.3
100-41-4	ETHYLBENZENE	4.7		1.3
136777-61-2	M&P XYLENES	U		2.6
95-47-6	O-XYLENE	6.2		1.3
100-42-5	STYRENE	U		1.3
98-82-8	ISOPROPYLBENZENE	U		1.3
103-65-1	n-PROPYLBENZENE	1.3		1.3
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.6
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	12		2.6
98-06-6	TERT-BUTYLBENZENE	U		1.3
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.3
135-98-8	SEC-BUTYLBENZENE	11		1.3
541-73-1	1,3 DICHLOROBENZENE	U		1.3
99-87-6	ISOPROPYLTOLUENE	U		1.3
106-46-7	1,4 DICHLOROBENZENE	U		1.3
104-51-8	n-BUTYLBENZENE	22		1.3
95-50-1	1,2 DICHLOROBENZENE	8.7		1.3
120-82-1	1,2,4 TRICHLOROBENZENE	3.6		1.3
87-68-3	HEXACHLOROBUTADIENE	1.7		1.3
91-20-3	NAPHTHALENE	U		1.3

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

% SOLIDS 78%

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-4
LAB ID: R2982-09 5X
FILENAME: F:\DATA1\U062317.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 5
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		6.4
74-87-3	CHLOROMETHANE	U		6.4
75-01-4	VINYL CHLORIDE	U		6.4
74-97-5	BROMOMETHANE	U		6.4
75-00-3	CHLOROETHANE	U		6.4
75-69-4	TRICHLOROFLOUROMETHANE	U		6.4
75-35-4	1,1 DICHLOROETHENE	U		6.4
75-09-2	METHYLENE CHLORIDE	9.1	B	6.4
156-60-5	TRANS-1,2-DICHLOROETHENE	U		6.4
75-34-3	1,1 DICHLOROETHANE	U		6.4
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		13
67-66-3	CHLOROFORM	U		6.4
74-97-5	BROMOCHLOROMETHANE	U		6.4
71-55-6	1,1,1 TRICHLOROETHANE	U		6.4
563-58-6	1,1 DICHLOROPROPENE	U		6.4
56-23-5	CARBON TETRACHLORIDE	U		6.4
107-06-2	1,2 DICHLOROETHANE	U		6.4
79-01-6	TRICHLOROETHENE	U		6.4
78-87-5	1,2 DICHLOROPROPANE	U		6.4
75-27-4	BROMODICHLOROMETHANE	U		6.4
74-95-3	DIBROMOMETHANE	U		6.4
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		6.4
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		6.4
630-20-6	1,1,2-TRICHLOROETHANE	U		6.4
142-28-9	1,3 DICHLOROPROPANE	U		6.4
127-18-4	TETRACHLOROETHENE	U		6.4
75-27-4	DIBROMOCHLOROMETHANE	U		6.4
106-93-4	1,2 DIBROMOETHANE	U		6.4
108-90-7	CHLOROBENZENE	19		6.4
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		6.4
75-25-2	BROMOFORM	U		6.4
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		6.4
96-18-4	1,2,3 TRICHLOROPROPANE	U		6.4
108-86-1	BROMOBENZENE	U		6.4
95-49-8	2, CHLOROTOLUENE	U		6.4
106-34-4	4, CHLOROTOLUENE	U		6.4
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		6.4
87-68-3	HEXACHLOROBUTADIENE	U		6.4
87-61-6	1,2,3 TRICHLOROBENZENE	U		6.4

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

% SOLIDS 79%

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-4
LAB ID: R2982-09 5X
FILENAME: F:\DATA1\V062317.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 5
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		6.4
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	200		6.4
71-43-2	BENZENE	U		6.4
108-88-3	TOLUENE	U		6.4
100-41-4	ETHYLBENZENE	170		6.4
136777-61-2	M&P XYLENES	14		13
95-47-6	O-XYLENE	250		6.4
100-42-5	STYRENE	U		6.4
98-82-8	ISOPROPYLBENZENE	54		6.4
103-65-1	n-PROPYLBENZENE	45		6.4
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		13
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	300		13
98-06-6	TERT-BUTYLBENZENE	U		6.4
95-63-6	1,2,4-TRIMETHYLBENZENE	26		6.4
135-98-8	SEC-BUTYLBENZENE	290		6.4
541-73-1	1,3 DICHLOROBENZENE	U		6.4
99-87-6	ISOPROPYLTOLUENE	21		6.4
106-46-7	1,4 DICHLOROBENZENE	U		6.4
104-51-8	n-BUTYLBENZENE	350		6.4
95-50-1	1,2 DICHLOROBENZENE	230		6.4
120-82-1	1,2,4 TRICHLOROBENZENE	86		6.4
87-68-3	HEXACHLOROBUTADIENE	66		6.4
91-20-3	NAPHTHALENE	53		6.4

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

% SOLIDS 79%

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5A
LAB ID: R2982-10
FILENAME: F:\DATA1\U062318.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.1
74-87-3	CHLOROMETHANE	U		1.1
75-01-4	VINYL CHLORIDE	U		1.1
74-97-5	BROMOMETHANE	U		1.1
75-00-3	CHLOROETHANE	U		1.1
75-69-4	TRICHLOROFLOUROMETHANE	U		1.1
75-35-4	1,1 DICHLOROETHENE	U		1.1
75-09-2	METHYLENE CHLORIDE	1.7	B	1.1
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.1
75-34-3	1,1 DICHLOROETHANE	U		1.1
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.1
67-66-3	CHLOROFORM	U		1.1
74-97-5	BROMOCHLOROMETHANE	U		1.1
71-55-6	1,1,1 TRICHLOROETHANE	U		1.1
563-58-6	1,1 DICHLOROPROPENE	U		1.1
56-23-5	CARBON TETRACHLORIDE	U		1.1
107-06-2	1,2 DICHLOROETHANE	U		1.1
79-01-6	TRICHLOROETHENE	U		1.1
78-87-5	1,2 DICHLOROPROPANE	U		1.1
75-27-4	BROMODICHLOROMETHANE	U		1.1
74-95-3	DIBROMOMETHANE	U		1.1
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.1
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.1
630-20-6	1,1,2-TRICHLOROETHANE	U		1.1
142-28-9	1,3 DICHLOROPROPANE	U		1.1
127-18-4	TETRACHLOROETHENE	U		1.1
75-27-4	DIBROMOCHLOROMETHANE	U		1.1
106-93-4	1,2 DIBROMOETHANE	U		1.1
108-90-7	CHLOROBENZENE	U		1.1
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.1
75-25-2	BROMOFORM	U		1.1
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.1
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.1
108-86-1	BROMOBENZENE	U		1.1
95-49-8	2, CHLOROTOLUENE	U		1.1
106-34-4	4, CHLOROTOLUENE	U		1.1
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.1
87-68-3	HEXACHLOROBUTADIENE	U		1.1
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.1

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

% SOLIDS 93%

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5A
LAB ID: R2982-10
FILENAME: F:\DATA1\V062318.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		1.1
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	U		1.1
71-43-2	BENZENE	U		1.1
108-88-3	TOLUENE	U		1.1
100-41-4	ETHYLBENZENE	U		1.1
136777-61-2	M&P XYLENES	U		2.1
95-47-6	O-XYLENE	U		1.1
100-42-5	STYRENE	U		1.1
98-82-8	ISOPROPYLBENZENE	U		1.1
103-65-1	n-PROPYLBENZENE	U		1.1
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.1
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.1
98-06-6	TERT-BUTYLBENZENE	U		1.1
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.1
135-98-8	SEC-BUTYLBENZENE	U		1.1
541-73-1	1,3 DICHLOROBENZENE	U		1.1
99-87-6	ISOPROPYLTOLUENE	U		1.1
106-46-7	1,4 DICHLOROBENZENE	U		1.1
104-51-8	n-BUTYLBENZENE	U		1.1
95-50-1	1,2 DICHLOROBENZENE	U		1.1
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.1
87-68-3	HEXACHLOROBUTADIENE	U		1.1
91-20-3	NAPHTHALENE	U		1.1

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

% SOLIDS 93%

Chemtech

GC Volatiles
DETECTOR: HALL

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5B
LAB ID: R2982-11
FILENAME: F:\DATA1\U062319.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIERS	MDL (ug/Kg)
75-71-8	DICHLORODIFLUOROMETHANE	U		1.2
74-87-3	CHLOROMETHANE	U		1.2
75-01-4	VINYL CHLORIDE	U		1.2
74-97-5	BROMOMETHANE	U		1.2
75-00-3	CHLOROETHANE	U		1.2
75-69-4	TRICHLOROFLOUROMETHANE	U		1.2
75-35-4	1,1 DICHLOROETHENE	U		1.2
75-09-2	METHYLENE CHLORIDE	3.2	B	1.2
156-60-5	TRANS-1,2-DICHLOROETHENE	U		1.2
75-34-3	1,1 DICHLOROETHANE	U		1.2
	2,2-DCPRPA+CIS-1,2DICHLOROETHENE	U		2.4
67-66-3	CHLOROFORM	U		1.2
74-97-5	BROMOCHLOROMETHANE	U		1.2
71-55-6	1,1,1 TRICHLOROETHANE	U		1.2
563-58-6	1,1 DICHLOROPROPENE	U		1.2
56-23-5	CARBON TETRACHLORIDE	U		1.2
107-06-2	1,2 DICHLOROETHANE	U		1.2
79-01-6	TRICHLOROETHENE	U		1.2
78-87-5	1,2 DICHLOROPROPANE	U		1.2
75-27-4	BROMODICHLOROMETHANE	U		1.2
74-95-3	DIBROMOMETHANE	U		1.2
10061-02-6	CIS 1,3 DICHLOROPROPENE	U		1.2
10061-02-6	TRANS 1,3 DICHLOROPROPENE	U		1.2
630-20-6	1,1,2-TRICHLOROETHANE	U		1.2
142-28-9	1,3 DICHLOROPROPANE	U		1.2
127-18-4	TETRACHLOROETHENE	U		1.2
75-27-4	DIBROMOCHLOROMETHANE	U		1.2
106-93-4	1,2 DIBROMOETHANE	U		1.2
108-90-7	CHLOROBENZENE	U		1.2
630-20-6	1,1,1,2 TETRACHLOROETHANE	U		1.2
75-25-2	BROMOFORM	U		1.2
79-34-5	1,1,2,2 TETRACHLOROETHANE	U		1.2
96-18-4	1,2,3 TRICHLOROPROPANE	U		1.2
108-86-1	BROMOBENZENE	U		1.2
95-49-8	2, CHLOROTOLUENE	U		1.2
106-34-4	4, CHLOROTOLUENE	U		1.2
96-12-8	1,2-DIBROMO-3-CHLOROPROPANE	U		1.2
87-68-3	HEXACHLOROBUTADIENE	U		1.2
87-61-6	1,2,3 TRICHLOROBENZENE	U		1.2

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
D = DILUTION
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW

% SOLIDS 83%

Chemtech

GC Volatiles
DETECTOR: PID

Tabulated Analytical Report
Method 8021

CLIENT: ASTEM LABORATORY, INC.
PROJECT: JUNK YARD
SAMPLE ID: BH-5B
LAB ID: R2982-11
FILENAME: F:\DATA1\V062319.RAW
BATCH: LB22363

MATRIX: SOIL
DATE ANALYZED: 6/24/03
ANALYST: PHM
DILUTION: 1
PROJECT#: R2982

CAS #	COMPOUNDS	RESULTS (ug/Kg)	QUALIFIER	MDL (ug/Kg)
75-35-4	1,1 DICHLOROETHENE	U		1.2
1634-04-4	METHYL TERT BUTYL ETHER (MTBE)	U		1.2
71-43-2	BENZENE	U		1.2
108-88-3	TOLUENE	U		1.2
100-41-4	ETHYLBENZENE	U		1.2
136777-61-2	M&P XYLENES	U		2.4
95-47-6	O-XYLENE	U		1.2
100-42-5	STYRENE	U		1.2
98-82-8	ISOPROPYLBENZENE	U		1.2
103-65-1	n-PROPYLBENZENE	U		1.2
	2-CHLORTOLUENE+P-ETHYLTOLUENE	U		2.4
	4-CHLOROTOLUENE+1,3,5-TRIMETHYLBENZENE	U		2.4
98-06-6	TERT-BUTYLBENZENE	U		1.2
95-63-6	1,2,4-TRIMETHYLBENZENE	U		1.2
135-98-8	SEC-BUTYLBENZENE	U		1.2
541-73-1	1,3 DICHLOROBENZENE	U		1.2
99-87-6	ISOPROPYLTOLUENE	U		1.2
106-46-7	1,4 DICHLOROBENZENE	U		1.2
104-51-8	n-BUTYLBENZENE	U		1.2
95-50-1	1,2 DICHLOROBENZENE	U		1.2
120-82-1	1,2,4 TRICHLOROBENZENE	U		1.2
87-68-3	HEXACHLOROBUTADIENE	U		1.2
91-20-3	NAPHTHALENE	U		1.2

MDL = METHOD DETECTION LIMIT
U =UNDETECTED BELOW MDL
B = PRESENT IN THE ASSOCIATED BLANK
E = EXCEEDED CALIBRATION RANGE, DILUTION TO FOLLOW
D = DILUTION

% SOLIDS 83%

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID: R2982-09 Client ID: BH-4

Date Collected: 6/16/03 Date Received: 6/19/03
Date Analyzed: 6/24/03 Matrix: SOIL
Date Extracted: 6/24/03 File ID: BB010245.D
Dilution: 1 Instrument ID: BNAB
Analytical Method: 8270 Analytical Run ID: BB061703
Sample Wt/Vol: 30.3 Extract Vol: 1000
Injection Vol: 2 % Moisture: 21
Associated Blank: PB062403-12B

rameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
(2-Chloroethyl)ether	111-44-4	< 49	U	410	49	ug/Kg
-Dichlorobenzene	95-50-1	< 41	U	410	41	ug/Kg
,3-Dichlorobenzene	541-73-1	< 49	U	410	49	ug/Kg
-Dichlorobenzene	106-46-7	< 41	U	410	41	ug/Kg
-oxybis(1-Chloropropane)	108-60-1	< 41	U	410	41	ug/Kg
-Nitroso-di-n-propylamine	621-64-7	< 41	U	410	41	ug/Kg
xachloroethane	67-72-1	< 45	U	410	45	ug/Kg
trobenzene	98-95-3	< 41	U	410	41	ug/Kg
ophorone	78-59-1	< 41	U	410	41	ug/Kg
(2-Chloroethoxy)methane	111-91-1	< 41	U	410	41	ug/Kg
2,4-Trichlorobenzene	120-82-1	< 49	U	410	49	ug/Kg
aphthalene	91-20-3	180	J	410	49	ug/Kg
hloroaniline	106-47-8	< 49	U	410	49	ug/Kg
exachlorobutadiene	87-68-3	< 62	U	410	62	ug/Kg
Methylnaphthalene	91-57-6	190	J	410	49	ug/Kg
xachlorocyclopentadiene	77-47-4	< 160	U	410	160	ug/Kg
Chloronaphthalene	91-58-7	< 49	U	410	49	ug/Kg
itroaniline	88-74-4	< 41	U	1000	41	ug/Kg
ethylphthalate	131-11-3	< 41	U	410	41	ug/Kg
enaphthylene	208-96-8	100	J	410	49	ug/Kg
Dinitrotoluene	606-20-2	< 41	U	410	41	ug/Kg
Nitroaniline	99-09-2	< 49	U	1000	49	ug/Kg
enaphthene	83-32-9	510		410	49	ug/Kg
enzofuran	132-64-9	260	J	410	41	ug/Kg
-Dinitrotoluene	121-14-2	< 45	U	410	45	ug/Kg
ethylphthalate	84-66-2	< 41	U	410	41	ug/Kg
hlorophenyl-phenylether	7005-72-3	< 49	U	410	49	ug/Kg
orene	86-73-7	590		410	45	ug/Kg
Nitroaniline	100-01-6	< 99	U	1000	99	ug/Kg
itrosodiphenylamine	86-30-6	< 83	U	410	83	ug/Kg
obenzene	122-66-7	< 45	U	410	45	ug/Kg

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID: R2982-09 Client ID: BH-4

Date Collected: 6/16/03 Date Received: 6/19/03
Date Analyzed: 6/24/03 Matrix: SOIL
Date Extracted: 6/24/03 File ID: BB010245.D
Dilution: 1 Instrument ID: BNAB
Analytical Method: 8270 Analytical Run ID: BB061703
Sample Wt/Vol: 30.3 Extract Vol: 1000
Injection Vol: 2 % Moisture: 21
Associated Blank: PB062403-12B

rameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
Bromophenyl-phenylether	101-55-3	< 54	U	410	54	ug/Kg
xachlorobenzene	118-74-1	< 45	U	410	45	ug/Kg
henanthrene	85-01-8	3300		410	41	ug/Kg
thracene	120-12-7	1100		410	54	ug/Kg
n-butylphthalate	84-74-2	120	JB	410	49	ug/Kg
luoranthene	206-44-0	2900		410	41	ug/Kg
rene	129-00-0	2800		410	41	ug/Kg
utylbenzylphthalate	85-68-7	400	J	410	41	ug/Kg
3-Dichlorobenzidine	91-94-1	< 41	U	410	41	ug/Kg
nzo(a)anthracene	56-55-3	1600		410	41	ug/Kg
hrysene	218-01-9	1600		410	66	ug/Kg
is(2-Ethylhexyl)phthalate	117-81-7	380	JB	410	41	ug/Kg
n-octyl phthalate	117-84-0	< 62	U	410	62	ug/Kg
enzo(b)fluoranthene	205-99-2	1300		410	41	ug/Kg
nzo(k)fluoranthene	207-08-9	1200		410	110	ug/Kg
nzo(a)pyrene	50-32-8	1400		410	62	ug/Kg
ndeno(1,2,3-cd)pyrene	193-39-5	370	J	410	66	ug/Kg
enz(a,h)anthracene	53-70-3	120	J	410	62	ug/Kg
nzo(g,h,i)perylene	191-24-2	470		410	54	ug/Kg
URROGATES						
robenzene-d5	4165-60-0	143.67	72 %	23 - 120		SPK: 200
-Fluorobiphenyl	321-60-8	140.43	70 %	30 - 116		SPK: 200
phenyl-d14	1718-51-0	167.8	84 %	18 - 137		SPK: 200
NTERNAL STANDARDS						
4-Dichlorobenzene-d4	3855-82-1	149761	5.37			
phthalene-d8	1146-65-2	587928	7.60			
cenaphthene-d10	15067-26-2	395633	10.98			
enanthrene-d10	1517-22-2	608240	13.91			
rysene-d12	1719-03-5	440721	19.23			
erylene-d12	1520-96-3	414707	21.97			

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID: R2982-11 Client ID: BH-5B

Date Collected:	6/16/03	Date Received:	6/19/03
Date Analyzed:	6/24/03	Matrix:	SOIL
Date Extracted:	6/24/03	File ID:	BB010244.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB061703
Sample Wt/Vol:	30.1	Extract Vol:	1000
Injection Vol:	2	% Moisture:	17
Associated Blank:	PB062403-12B		

rameter	CAS Number	Concentration	C	RDL	MDL	Units
RGETS						
(2-Chloroethyl)ether	111-44-4	< 47	U	400	47	ug/Kg
-Dichlorobenzene	95-50-1	< 40	U	400	40	ug/Kg
3-Dichlorobenzene	541-73-1	< 47	U	400	47	ug/Kg
-Dichlorobenzene	106-46-7	< 40	U	400	40	ug/Kg
oxybis(1-Chloropropane)	108-60-1	< 40	U	400	40	ug/Kg
Nitroso-di-n-propylamine	621-64-7	< 40	U	400	40	ug/Kg
achloroethane	67-72-1	< 44	U	400	44	ug/Kg
obenzene	98-95-3	< 40	U	400	40	ug/Kg
phorone	78-59-1	< 40	U	400	40	ug/Kg
2-Chloroethoxy)methane	111-91-1	< 40	U	400	40	ug/Kg
4-Trichlorobenzene	120-82-1	< 47	U	400	47	ug/Kg
phthalene	91-20-3	< 47	U	400	47	ug/Kg
hloroaniline	106-47-8	< 47	U	400	47	ug/Kg
achlorobutadiene	87-68-3	< 59	U	400	59	ug/Kg
Methylnaphthalene	91-57-6	< 47	U	400	47	ug/Kg
achlorocyclopentadiene	77-47-4	< 150	U	400	150	ug/Kg
Chloronaphthalene	91-58-7	< 47	U	400	47	ug/Kg
itroaniline	88-74-4	< 40	U	1000	40	ug/Kg
ethylphthalate	131-11-3	< 40	U	400	40	ug/Kg
enaphthylene	208-96-8	< 47	U	400	47	ug/Kg
Dinitrotoluene	606-20-2	< 40	U	400	40	ug/Kg
troaniline	99-09-2	< 47	U	1000	47	ug/Kg
enaphthene	83-32-9	< 47	U	400	47	ug/Kg
nzofuran	132-64-9	< 40	U	400	40	ug/Kg
Dinitrotoluene	121-14-2	< 44	U	400	44	ug/Kg
ethylphthalate	84-66-2	< 40	U	400	40	ug/Kg
lorophenyl-phenylether	7005-72-3	< 47	U	400	47	ug/Kg
orene	86-73-7	< 44	U	400	44	ug/Kg
Nitroaniline	100-01-6	< 95	U	1000	95	ug/Kg
trosodiphenylamine	86-30-6	< 79	U	400	79	ug/Kg
obenzene	122-66-7	< 43	U	400	43	ug/Kg

SVOC

SDG No.: R2982

Client: ASTEM Laboratory, Inc.

Sample ID:	R2982-11	Client ID:	BH-5B
Date Collected:	6/16/03	Date Received:	6/19/03
Date Analyzed:	6/24/03	Matrix:	SOIL
Date Extracted:	6/24/03	File ID:	BB010244.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB061703
Sample Wt/Vol:	30.1	Extract Vol:	1000
Injection Vol:	2	% Moisture:	17
Associated Blank:	PB062403-12B		

ameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
romophenyl-phenylether	101-55-3	< 52	U	400	52	ug/Kg
achlorobenzene	118-74-1	< 44	U	400	44	ug/Kg
enanthrene	85-01-8	52	J	400	40	ug/Kg
hracene	120-12-7	69	J	400	52	ug/Kg
n-butylphthalate	84-74-2	< 47	U	400	47	ug/Kg
uoranthene	206-44-0	400		400	40	ug/Kg
ene	129-00-0	310	J	400	40	ug/Kg
ylbenzylphthalate	85-68-7	< 40	U	400	40	ug/Kg
3-Dichlorobenzidine	91-94-1	< 40	U	400	40	ug/Kg
zo(a)anthracene	56-55-3	200	J	400	40	ug/Kg
rysene	218-01-9	180	J	400	63	ug/Kg
s(2-Ethylhexyl)phthalate	117-81-7	< 40	U	400	40	ug/Kg
n-octyl phthalate	117-84-0	< 59	U	400	59	ug/Kg
enzo(b)fluoranthene	205-99-2	190	J	400	40	ug/Kg
enzo(k)fluoranthene	207-08-9	190	J	400	100	ug/Kg
zo(a)pyrene	50-32-8	230	J	400	59	ug/Kg
deno(1,2,3-cd)pyrene	193-39-5	88	J	400	63	ug/Kg
enz(a,h)anthracene	53-70-3	< 60	U	400	60	ug/Kg
zo(g,h,i)perylene-	191-24-2	100	J	400	52	ug/Kg
URROGATES						
obenzene-d5	4165-60-0	129.77	65 %	23 - 120		SPK: 200
Fluorobiphenyl	321-60-8	141.32	71 %	30 - 116		SPK: 200
phenyl-d14	1718-51-0	137.55	69 %	18 - 137		SPK: 200
TERNAL STANDARDS						
4-Dichlorobenzene-d4	3855-82-1	140816	5.38			
hthalene-d8	1146-65-2	540642	7.58			
cenaphthene-d10	15067-26-2	381208	10.97			
enanthrene-d10	1517-22-2	615338	13.88			
ysene-d12	1719-03-5	666577	19.16			
rylene-d12	1520-96-3	712350	21.90			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-07 Client ID: BH-9S

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/12/03 Matrix: SOIL
File ID: VJ081277.D Analytical Run ID: VJ081203
Dilution: 1 Instrument ID: MSVOAJ
Analytical Method: 8260 Associated Blank: VBJ0812S2
Sample Wt/Wol: 5.0 Units: g Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 0.95	U	5.3	0.95	ug/Kg
hloromethane	74-87-3	< 1.8	U	5.3	1.8	ug/Kg
inyl chloride	75-01-4	< 1.1	U	5.3	1.1	ug/Kg
Bromomethane	74-83-9	< 1.1	U	5.3	1.1	ug/Kg
hloroethane	75-00-3	< 1.4	U	5.3	1.4	ug/Kg
ichlorofluoromethane	75-69-4	< 1.4	U	5.3	1.4	ug/Kg
Tert butyl alcohol	75-65-0	< 4.4	U	26	4.4	ug/Kg
l-Dichloroethene	75-35-4	< 1.2	U	5.3	1.2	ug/Kg
crolein	107-02-8	< 7.1	U	26	7.1	ug/Kg
Acrylonitrile	107-13-1	< 8.0	U	26	8.0	ug/Kg
cetone	67-64-1	< 3.7	U	5.3	3.7	ug/Kg
arbon disulfide	75-15-0	< 1.4	U	5.3	1.4	ug/Kg
Methyl tert-butyl Ether	1634-04-4	< 0.95	U	5.3	0.95	ug/Kg
ethylene Chloride	75-09-2	10	B	5.3	1.4	ug/Kg
rans-1,2-Dichloroethene	156-60-5	< 1.2	U	5.3	1.2	ug/Kg
inyl Acetate	108-05-4	< 4.8	U	26	4.8	ug/Kg
-Dichloroethane	75-34-3	< 0.95	U	5.3	0.95	ug/Kg
-Butanone	78-93-3	< 5.3	U	5.3	5.3	ug/Kg
rbon Tetrachloride	56-23-5	< 2.2	U	5.3	2.2	ug/Kg
-Dichloropropane	594-20-7	< 0.84	U	5.3	0.84	ug/Kg
is-1,2-Dichloroethene	156-59-2	15		5.3	0.95	ug/Kg
omochloromethane	74-97-5	< 1.2	U	5.3	1.2	ug/Kg
loroform	67-66-3	< 1.1	U	5.3	1.1	ug/Kg
,1,1-Trichloroethane	71-55-6	< 1.1	U	5.3	1.1	ug/Kg
-Dichloropropene	563-43-2	< 1.4	U	5.3	1.4	ug/Kg
enzene	71-43-2	< 1.1	U	5.3	1.1	ug/Kg
,2-Dichloroethane	107-06-2	< 1.2	U	5.3	1.2	ug/Kg
chloroethene	79-01-6	21		5.3	1.1	ug/Kg
,2-Dichloropropane	78-87-5	< 0.84	U	5.3	0.84	ug/Kg
ibromomethane	74-95-3	< 1.1	U	5.3	1.1	ug/Kg
omodichloromethane	75-27-4	< 0.84	U	5.3	0.84	ug/Kg
-Methyl-2-Pentanone	108-10-1	< 4.2	U	5.3	4.2	ug/Kg
luene	108-88-3	4.7	J	5.3	1.2	ug/Kg
3-Dichloropropene	10061-02-6	< 1.1	U	5.3	1.1	ug/Kg

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID: R3695-07 Client ID: BH-9S

Date Collected: 8/5/03 Date Received: 8/6/03
Date Analyzed: 8/12/03 Matrix: SOIL
File ID: VJ081277.D Analytical Run ID: VJ081203
Dilution: 1 Instrument ID: MSVOAJ
Analytical Method: 8260 Associated Blank: VBJ0812S2
Sample Wt/Vol: 5.0 Units: g Soil Extract Vol:
Soil Aliquot Vol: % Moisture: 5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
s-1,3-Dichloropropene	10061-01-5	< 0.95	U	5.3	0.95	ug/Kg
1,1,2-Trichloroethane	79-00-5	< 1.2	U	5.3	1.2	ug/Kg
1,3-Dichloropropane	142-28-9	< 1.1	U	5.3	1.1	ug/Kg
Chloroethyl vinyl ether	110-75-8	< 1.5	U	5.3	1.5	ug/Kg
2-Hexanone	591-78-6	< 5.3	U	5.3	5.3	ug/Kg
Dibromochloromethane	124-48-1	< 0.95	U	5.3	0.95	ug/Kg
2-Dibromoethane	106-93-4	< 1.1	U	5.3	1.1	ug/Kg
Tetrachloroethene	127-18-4	8.4		5.3	1.3	ug/Kg
hlorobenzene	108-90-7	7.5		5.3	1.2	ug/Kg
1,1,2,2-Tetrachloroethane	630-20-6	< 1.2	U	5.3	1.2	ug/Kg
Ethyl Benzene	100-41-4	< 1.1	U	5.3	1.1	ug/Kg
p-Xylenes	136777-61-2	5.8		5.3	2.9	ug/Kg
Xylene	95-47-6	1.2	J	5.3	1.2	ug/Kg
Styrene	100-42-5	< 1.5	U	5.3	1.5	ug/Kg
omoform	75-25-2	< 1.2	U	5.3	1.2	ug/Kg
sopropylbenzene	98-82-8	< 1.2	U	5.3	1.2	ug/Kg
1,1,2,2-Tetrachloroethane	79-34-5	< 1.1	U	5.3	1.1	ug/Kg
2,3-Trichloropropane	96-18-4	< 1.6	U	5.3	1.6	ug/Kg
Bromobenzene	108-86-1	< 0.95	U	5.3	0.95	ug/Kg
N-propylbenzene	103-61-5	< 1.4	U	5.3	1.4	ug/Kg
Chlorotoluene	95-49-8	< 1.8	U	5.3	1.8	ug/Kg
1,3,5-Trimethylbenzene	108-67-8	< 1.4	U	5.3	1.4	ug/Kg
Chlorotoluene	106-43-4	< 1.5	U	5.3	1.5	ug/Kg
t-Butylbenzene	98-06-6	< 1.8	U	5.3	1.8	ug/Kg
1,2,4-Trimethylbenzene	95-63-6	2.7	J	5.3	1.5	ug/Kg
c-butylbenzene	135-98-8	< 1.9	U	5.3	1.9	ug/Kg
sopropyltoluene	99-87-6	< 1.9	U	5.3	1.9	ug/Kg
1,3-Dichlorobenzene	541-73-1	5.1	J	5.3	1.1	ug/Kg
-Dichlorobenzene	106-46-7	14		5.3	0.84	ug/Kg
-Butylbenzene	104-51-8	< 2.5	U	5.3	2.5	ug/Kg
1,2-Dichlorobenzene	95-50-1	140	E	5.3	0.95	ug/Kg
-Dibromo-3-Chloropropane	96-12-8	< 1.1	U	5.3	1.1	ug/Kg
1,2,4-Trichlorobenzene	120-82-1	< 1.6	U	5.3	1.6	ug/Kg
Hexachlorobutadiene	87-68-3	< 2.6	U	5.3	2.6	ug/Kg
phthalene	91-20-3	1.5	J	5.3	1.3	ug/Kg

8/12/03

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07	Client ID:	BH-9S
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/12/03	Matrix:	SOIL
File ID:	VJ081277.D	Analytical Run ID:	VJ081203
Dilution:	1	Instrument ID:	MSVOAJ
Analytical Method:	8260	Associated Blank:	VBJ0812S2
Sample Wt/Vol:	5.0 Units: g	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 2.0	U	5.3	2.0	ug/Kg
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	62.94	126 %	70 - 121		SPK: 50
Dibromofluoromethane	1868-53-7	64.35	129 %	80 - 120		SPK: 50
Toluene-d8	2037-26-5	41.71	83 %	81 - 117		SPK: 50
4-Bromofluorobenzene	460-00-4	30.59	61 %	74 - 121		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	60816	4.47			
1,4-Difluorobenzene	540-36-3	121533	5.11			
Chlorobenzene-d5	3114-55-4	84498	7.54			
1,4-Dichlorobenzene-d4	3855-82-1	21753	8.95			

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07DL	Client ID:	BH-9SDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/13/03	Matrix:	SOIL
File ID:	VJ081289.D	Analytical Run ID:	VJ081203
Dilution:	1	Instrument ID:	MSVOAJ
Analytical Method:	8260	Associated Blank:	VBJ0812S4
Sample Wt/Vol:	5.0 Units: g	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
ARGETS						
Dichlorodifluoromethane	75-71-8	< 0.95	UD	5.3	0.95	ug/Kg
hloromethane	74-87-3	< 1.8	UD	5.3	1.8	ug/Kg
inyl chloride	75-01-4	< 1.1	UD	5.3	1.1	ug/Kg
Bromomethane	74-83-9	< 1.1	UD	5.3	1.1	ug/Kg
hloroethane	75-00-3	< 1.4	UD	5.3	1.4	ug/Kg
richlorofluoromethane	75-69-4	< 1.4	UD	5.3	1.4	ug/Kg
Tert butyl alcohol	75-65-0	< 4.4	UD	26	4.4	ug/Kg
1-Dichloroethene	75-35-4	< 1.2	UD	5.3	1.2	ug/Kg
crolein	107-02-8	< 7.1	UD	26	7.1	ug/Kg
Acrylonitrile	107-13-1	< 8.0	UD	26	8.0	ug/Kg
cetone	67-64-1	< 3.7	UD	5.3	3.7	ug/Kg
Carbon disulfide	75-15-0	< 1.4	UD	5.3	1.4	ug/Kg
Methyl tert-butyl Ether	1634-04-4	< 0.95	UD	5.3	0.95	ug/Kg
ethylene Chloride	75-09-2	7.4	D	5.3	1.4	ug/Kg
rans-1,2-Dichloroethene	156-60-5	< 1.2	UD	5.3	1.2	ug/Kg
Vinyl Acetate	108-05-4	< 4.8	UD	26	4.8	ug/Kg
1-Dichloroethane	75-34-3	< 0.95	UD	5.3	0.95	ug/Kg
-Butanone	78-93-3	< 5.3	UD	5.3	5.3	ug/Kg
arbon Tetrachloride	56-23-5	< 2.2	UD	5.3	2.2	ug/Kg
2-Dichloropropane	594-20-7	< 0.84	UD	5.3	0.84	ug/Kg
is-1,2-Dichloroethene	156-59-2	13	D	5.3	0.95	ug/Kg
romochloromethane	74-97-5	< 1.2	UD	5.3	1.2	ug/Kg
hloroform	67-66-3	< 1.1	UD	5.3	1.1	ug/Kg
,1,1-Trichloroethane	71-55-6	< 1.1	UD	5.3	1.1	ug/Kg
-Dichloropropene	563-43-2	< 1.4	UD	5.3	1.4	ug/Kg
enzene	71-43-2	< 1.1	UD	5.3	1.1	ug/Kg
,2-Dichloroethane	107-06-2	< 1.2	UD	5.3	1.2	ug/Kg
ichloroethene	79-01-6	20	D	5.3	1.1	ug/Kg
,2-Dichloropropane	78-87-5	< 0.84	UD	5.3	0.84	ug/Kg
ibromomethane	74-95-3	< 1.1	UD	5.3	1.1	ug/Kg
omodichloromethane	75-27-4	< 0.84	UD	5.3	0.84	ug/Kg
-Methyl-2-Pentanone	108-10-1	< 4.2	UD	5.3	4.2	ug/Kg
oluene	108-88-3	4.2	JD	5.3	1.2	ug/Kg
,3-Dichloropropene	10061-02-6	< 1.1	UD	5.3	1.1	ug/Kg

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07DL	Client ID:	BH-9SDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/13/03	Matrix:	SOIL
File ID:	VJ081289.D	Analytical Run ID:	VJ081203
Dilution:	1	Instrument ID:	MSVOAJ
Analytical Method:	8260	Associated Blank:	VBJ0812S4
Sample Wt/Vol:	5.0 Units: g	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
s-1,3-Dichloropropene	10061-01-5	< 0.95	UD	5.3	0.95	ug/Kg
1,1,2-Trichloroethane	79-00-5	< 1.2	UD	5.3	1.2	ug/Kg
1,3-Dichloropropane	142-28-9	< 1.1	UD	5.3	1.1	ug/Kg
Chloroethyl vinyl ether	110-75-8	< 1.5	UD	5.3	1.5	ug/Kg
2-Hexanone	591-78-6	< 5.3	UD	5.3	5.3	ug/Kg
Dibromochloromethane	124-48-1	< 0.95	UD	5.3	0.95	ug/Kg
2-Dibromoethane	106-93-4	< 1.1	UD	5.3	1.1	ug/Kg
Tetrachloroethene	127-18-4	7.2	D	5.3	1.3	ug/Kg
hlorobenzene	108-90-7	6.6	D	5.3	1.2	ug/Kg
1,1,2-Tetrachloroethane	630-20-6	< 1.2	UD	5.3	1.2	ug/Kg
Ethyl Benzene	100-41-4	< 1.1	UD	5.3	1.1	ug/Kg
p-Xylenes	136777-61-2	4.9	JD	5.3	2.9	ug/Kg
Xylene	95-47-6	< 1.2	UD	5.3	1.2	ug/Kg
Styrene	100-42-5	< 1.5	UD	5.3	1.5	ug/Kg
romoform	75-25-2	< 1.2	UD	5.3	1.2	ug/Kg
sopropylbenzene	98-82-8	< 1.2	UD	5.3	1.2	ug/Kg
1,1,2,2-Tetrachloroethane	79-34-5	< 1.1	UD	5.3	1.1	ug/Kg
2,3-Trichloropropane	96-18-4	< 1.6	UD	5.3	1.6	ug/Kg
Bromobenzene	108-86-1	< 0.95	UD	5.3	0.95	ug/Kg
N-propylbenzene	103-61-5	< 1.4	UD	5.3	1.4	ug/Kg
Chlorotoluene	95-49-8	< 1.8	UD	5.3	1.8	ug/Kg
1,3,5-Trimethylbenzene	108-67-8	< 1.4	UD	5.3	1.4	ug/Kg
Chlorotoluene	106-43-4	< 1.5	UD	5.3	1.5	ug/Kg
t-Butylbenzene	98-06-6	< 1.8	UD	5.3	1.8	ug/Kg
1,2,4-Trimethylbenzene	95-63-6	2.6	JD	5.3	1.5	ug/Kg
c-butylbenzene	135-98-8	< 1.9	UD	5.3	1.9	ug/Kg
sopropyltoluene	99-87-6	< 1.9	UD	5.3	1.9	ug/Kg
1,3-Dichlorobenzene	541-73-1	4.6	JD	5.3	1.1	ug/Kg
-Dichlorobenzene	106-46-7	12	D	5.3	0.84	ug/Kg
Butylbenzene	104-51-8	< 2.5	UD	5.3	2.5	ug/Kg
2-Dichlorobenzene	95-50-1	130	D	5.3	0.95	ug/Kg
-Dibromo-3-Chloropropane	96-12-8	< 1.1	UD	5.3	1.1	ug/Kg
2,4-Trichlorobenzene	120-82-1	< 1.6	UD	5.3	1.6	ug/Kg
exachlorobutadiene	87-68-3	< 2.6	UD	5.3	2.6	ug/Kg
phthalene	91-20-3	< 1.3	UD	5.3	1.3	ug/Kg

Volatiles

SDG No.: R3695

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07DL	Client ID:	BH-9SDL
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/13/03	Matrix:	SOIL
File ID:	VJ081289.D	Analytical Run ID:	VJ081203
Dilution:	1	Instrument ID:	MSVOAJ
Analytical Method:	8260	Associated Blank:	VBJ0812S4
Sample Wt/Wol:	5.0 Units: g	Soil Extract Vol:	
Soil Aliquot Vol:		% Moisture:	5

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
1,2,3-Trichlorobenzene	87-61-6	< 2.0	UD	5.3	2.0	ug/Kg
SURROGATES						
1,2-Dichloroethane-d4	17060-07-0	52.86	106 %	70 - 121		SPK: 50
Dibromofluoromethane	1868-53-7	58.96	118 %	80 - 120		SPK: 50
Toluene-d8	2037-26-5	42.05	84 %	81 - 117		SPK: 50
4-Bromofluorobenzene	460-00-4	30.02	60 %	74 - 121		SPK: 50
INTERNAL STANDARDS						
Pentafluorobenzene	363-72-4	106533	4.47			
1,4-Difluorobenzene	540-36-3	209769	5.11			
Chlorobenzene-d5	3114-55-4	146839	7.54			
1,4-Dichlorobenzene-d4	3855-82-1	36104	8.97			

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-04	Client ID:	BH-7
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	SOIL
Date Extracted:	8/7/03	File ID:	BB011473.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	30.4	Extract Vol:	1000
Injection Vol:	2	% Moisture:	7
Associated Blank:	PB080803-22B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
bis(2-Chloroethyl)ether	111-44-4	< 41	U	350	41	ug/Kg
1,2-Dichlorobenzene	95-50-1	< 35	U	350	35	ug/Kg
1,3-Dichlorobenzene	541-73-1	< 41	U	350	41	ug/Kg
1,4-Dichlorobenzene	106-46-7	< 35	U	350	35	ug/Kg
2,2-oxybis(1-Chloropropane)	108-60-1	< 35	U	350	35	ug/Kg
N-Nitroso-di-n-propylamine	621-64-7	< 35	U	350	35	ug/Kg
Hexachloroethane	67-72-1	< 39	U	350	39	ug/Kg
Nitrobenzene	98-95-3	< 35	U	350	35	ug/Kg
Isophorone	78-59-1	< 35	U	350	35	ug/Kg
bis(2-Chloroethoxy)methane	111-91-1	< 35	U	350	35	ug/Kg
1,2,4-Trichlorobenzene	120-82-1	< 41	U	350	41	ug/Kg
Naphthalene	91-20-3	< 41	U	350	41	ug/Kg
4-Chloroaniline	106-47-8	< 41	U	350	41	ug/Kg
Hexachlorobutadiene	87-68-3	< 53	U	350	53	ug/Kg
2-Methylnaphthalene	91-57-6	< 41	U	350	41	ug/Kg
Hexachlorocyclopentadiene	77-47-4	< 130	U	350	130	ug/Kg
2-Chloronaphthalene	91-58-7	< 41	U	350	41	ug/Kg
2-Nitroaniline	88-74-4	< 35	U	880	35	ug/Kg
Dimethylphthalate	131-11-3	< 35	U	350	35	ug/Kg
Acenaphthylene	208-96-8	230	J	350	41	ug/Kg
2,6-Dinitrotoluene	606-20-2	< 35	U	350	35	ug/Kg
3-Nitroaniline	99-09-2	< 41	U	880	41	ug/Kg
Acenaphthene	83-32-9	48	J	350	41	ug/Kg
Dibenzofuran	132-64-9	75	J	350	35	ug/Kg
2,4-Dinitrotoluene	121-14-2	< 39	U	350	39	ug/Kg
Diethylphthalate	84-66-2	< 35	U	350	35	ug/Kg
4-Chlorophenyl-phenylether	7005-72-3	< 41	U	350	41	ug/Kg
Fluorene	86-73-7	170	J	350	39	ug/Kg
4-Nitroaniline	100-01-6	< 84	U	880	84	ug/Kg
N-Nitrosodiphenylamine	86-30-6	< 70	U	350	70	ug/Kg
Azobenzene	122-66-7	< 38	U	350	38	ug/Kg

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-04	Client ID:	BH-7
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	SOIL
Date Extracted:	8/7/03	File ID:	BB011473.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Wol:	30.4	Extract Vol:	1000
Injection Vol:	2	% Moisture:	7
Associated Blank:	PB080803-22B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
4-Bromophenyl-phenylether	101-55-3	< 46	U	350	46	ug/Kg
Hexachlorobenzene	118-74-1	< 39	U	350	39	ug/Kg
Phenanthrene	85-01-8	1400		350	35	ug/Kg
Anthracene	120-12-7	320	J	350	46	ug/Kg
Di-n-butylphthalate	84-74-2	43	J	350	41	ug/Kg
Fluoranthene	206-44-0	1600		350	35	ug/Kg
Pyrene	129-00-0	1400		350	35	ug/Kg
Butylbenzylphthalate	85-68-7	< 35	U	350	35	ug/Kg
3,3-Dichlorobenzidine	91-94-1	< 35	U	350	35	ug/Kg
Benzo(a)anthracene	56-55-3	1100		350	35	ug/Kg
Chrysene	218-01-9	1000		350	56	ug/Kg
bis(2-Ethylhexyl)phthalate	117-81-7	390	B	350	35	ug/Kg
Di-n-octyl phthalate	117-84-0	< 53	U	350	53	ug/Kg
Benzo(b)fluoranthene	205-99-2	1000		350	35	ug/Kg
Benzo(k)fluoranthene	207-08-9	1200		350	91	ug/Kg
Benzo(a)pyrene	50-32-8	1400		350	53	ug/Kg
Indeno(1,2,3-cd)pyrene	193-39-5	330	J	350	56	ug/Kg
Dibenz(a,h)anthracene	53-70-3	400		350	53	ug/Kg
Benzo(g,h,i)perylene	191-24-2	580		350	46	ug/Kg
SURROGATES						
Nitrobenzene-d5	4165-60-0	147.44	74 %	23 - 120		SPK: 200
2-Fluorobiphenyl	321-60-8	164.85	82 %	30 - 116		SPK: 200
Terphenyl-d14	1718-51-0	200.8	100 %	18 - 137		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	163446	4.83			
Naphthalene-d8	1146-65-2	602038	6.98			
Acenaphthene-d10	15067-26-2	421015	10.32			
Phenanthrene-d10	1517-22-2	624346	13.21			
Chrysene-d12	1719-03-5	568879	18.48			
Perylene-d12	1520-96-3	395816	21.17			

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07	Client ID:	BH-9-S
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	SOIL
Date Extracted:	8/7/03	File ID:	BB011474.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Wol:	30.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	5
Associated Blank:	PB080803-22B		

rameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
s(2-Chloroethyl)ether	111-44-4	< 41	U	350	41	ug/Kg
,2-Dichlorobenzene	95-50-1	2400		350	35	ug/Kg
1,3-Dichlorobenzene	541-73-1	270	J	350	41	ug/Kg
-Dichlorobenzene	106-46-7	500		350	35	ug/Kg
2,2-oxybis(1-Chloropropane)	108-60-1	< 35	U	350	35	ug/Kg
N-Nitroso-di-n-propylamine	621-64-7	< 35	U	350	35	ug/Kg
exachloroethane	67-72-1	< 38	U	350	38	ug/Kg
Nitrobenzene	98-95-3	< 35	U	350	35	ug/Kg
sophorone	78-59-1	< 35	U	350	35	ug/Kg
s(2-Chloroethoxy)methane	111-91-1	< 35	U	350	35	ug/Kg
1,2,4-Trichlorobenzene	120-82-1	460		350	41	ug/Kg
aphthalene	91-20-3	180	J	350	41	ug/Kg
Chloroaniline	106-47-8	< 41	U	350	41	ug/Kg
Hexachlorobutadiene	87-68-3	< 52	U	350	52	ug/Kg
Methylnaphthalene	91-57-6	120	J	350	41	ug/Kg
exachlorocyclopentadiene	77-47-4	< 130	U	350	130	ug/Kg
2-Chloronaphthalene	91-58-7	< 41	U	350	41	ug/Kg
Nitroaniline	88-74-4	< 35	U	870	35	ug/Kg
imethylphthalate	131-11-3	< 35	U	350	35	ug/Kg
cenaphthylene	208-96-8	47	J	350	41	ug/Kg
-Dinitrotoluene	606-20-2	< 35	U	350	35	ug/Kg
3-Nitroaniline	99-09-2	< 41	U	870	41	ug/Kg
enaphthene	83-32-9	< 41	U	350	41	ug/Kg
enzofuran	132-64-9	< 35	U	350	35	ug/Kg
2,4-Dinitrotoluene	121-14-2	< 38	U	350	38	ug/Kg
thylphthalate	84-66-2	76	J	350	35	ug/Kg
Chlorophenyl-phenylether	7005-72-3	< 41	U	350	41	ug/Kg
luorene	86-73-7	< 38	U	350	38	ug/Kg
Nitroaniline	100-01-6	< 83	U	870	83	ug/Kg
Nitrosodiphenylamine	86-30-6	< 69	U	350	69	ug/Kg
zobenzene	122-66-7	< 38	U	350	38	ug/Kg

SVOC

SDG No.: R3695-01

Client: ASTEM Laboratory, Inc.

Sample ID:	R3695-07	Client ID:	BH-9-S
Date Collected:	8/5/03	Date Received:	8/6/03
Date Analyzed:	8/10/03	Matrix:	SOIL
Date Extracted:	8/7/03	File ID:	BB011474.D
Dilution:	1	Instrument ID:	BNAB
Analytical Method:	8270	Analytical Run ID:	BB072803
Sample Wt/Vol:	30.0	Extract Vol:	1000
Injection Vol:	2	% Moisture:	5
Associated Blank:	PB080803-22B		

Parameter	CAS Number	Concentration	C	RDL	MDL	Units
TARGETS						
4-Bromophenyl-phenylether	101-55-3	< 45	U	350	45	ug/Kg
Hexachlorobenzene	118-74-1	810		350	38	ug/Kg
Phenanthrene	85-01-8	65	J	350	35	ug/Kg
Anthracene	120-12-7	64	J	350	45	ug/Kg
Di-n-butylphthalate	84-74-2	120	J	350	41	ug/Kg
Fluoranthene	206-44-0	46	J	350	35	ug/Kg
Pyrene	129-00-0	100	J	350	35	ug/Kg
Butylbenzylphthalate	85-68-7	< 35	U	350	35	ug/Kg
3,3-Dichlorobenzidine	91-94-1	< 35	U	350	35	ug/Kg
Benzo(a)anthracene	56-55-3	56	J	350	35	ug/Kg
Chrysene	218-01-9	66	J	350	56	ug/Kg
bis(2-Ethylhexyl)phthalate	117-81-7	400	B	350	35	ug/Kg
Di-n-octyl phthalate	117-84-0	< 52	U	350	52	ug/Kg
Benzo(b)fluoranthene	205-99-2	86	J	350	35	ug/Kg
Benzo(k)fluoranthene	207-08-9	< 90	U	350	90	ug/Kg
Benzo(a)pyrene	50-32-8	67	J	350	52	ug/Kg
Indeno(1,2,3-cd)pyrene	193-39-5	88	J	350	56	ug/Kg
Dibenz(a,h)anthracene	53-70-3	< 52	U	350	52	ug/Kg
Benzo(g,h,i)perylene	191-24-2	430		350	45	ug/Kg
SURROGATES						
Nitrobenzene-d5	4165-60-0	134.19	67 %	23 - 120		SPK: 200
2-Fluorobiphenyl	321-60-8	154.69	77 %	30 - 116		SPK: 200
Terphenyl-d14	1718-51-0	281.38	141 %	18 - 137		SPK: 200
INTERNAL STANDARDS						
1,4-Dichlorobenzene-d4	3855-82-1	178486	4.82			
Naphthalene-d8	1146-65-2	629469	6.99			
Acenaphthene-d10	15067-26-2	411418	10.34			
Phenanthrene-d10	1517-22-2	591703	13.22			
Chrysene-d12	1719-03-5	241501	18.52			
Perylene-d12	1520-96-3	113667	21.24			

Hit Summary Report

SDG No.: R3695-01 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID:

Test: SVOC-Chemtech Full BN

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
Client ID:	BH-6							
R3695-02	BH-6	WATER	Naphthalene	21		10	1.2	ug/L
R3695-02	BH-6	WATER	2-Methylnaphthalene	3.4	J	10	1.2	ug/L
R3695-02	BH-6	WATER	Acenaphthylene	1.3	J	10	1.2	ug/L
R3695-02	BH-6	WATER	Acenaphthene	7.2	J	10	1.0	ug/L
R3695-02	BH-6	WATER	Dibenzofuran	5.3	J	10	1.0	ug/L
R3695-02	BH-6	WATER	Fluorene	8.5	J	10	1.1	ug/L
R3695-02	BH-6	WATER	Phenanthrene	36		10	1.0	ug/L
R3695-02	BH-6	WATER	Anthracene	8.6	J	10	1.3	ug/L
R3695-02	BH-6	WATER	Carbazole	5.6	J	10	0.420	ug/L
R3695-02	BH-6	WATER	Fluoranthene	27		10	1.0	ug/L
R3695-02	BH-6	WATER	Pyrene	22		10	1.0	ug/L
R3695-02	BH-6	WATER	Benzo(a)anthracene	11		10	1.0	ug/L
R3695-02	BH-6	WATER	Chrysene	11		10	1.6	ug/L
R3695-02	BH-6	WATER	bis(2-Ethylhexyl)phthalate	3.1	JB	10	1.0	ug/L
R3695-02	BH-6	WATER	Benzo(b)fluoranthene	10	J	10	1.0	ug/L
R3695-02	BH-6	WATER	Benzo(k)fluoranthene	10	J	10	2.7	ug/L
R3695-02	BH-6	WATER	Benzo(a)pyrene	12		10	1.5	ug/L
R3695-02	BH-6	WATER	Indeno(1,2,3-cd)pyrene	5.3	J	10	1.6	ug/L
R3695-02	BH-6	WATER	Dibenz(a,h)anthracene	4.2	J	10	1.5	ug/L
R3695-02	BH-6	WATER	Benzo(g,h,i)perylene	7.0	J	10	1.3	ug/L
			Total SVOC's:	219.50				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	219.50				

Note: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Hit Summary Report

SDG No.: R3695-01 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Test: SVOC-Chemtech Full BN

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
Client ID:	BH-7							
3695-04	BH-7	SOIL	Acenaphthylene	230	J	350	42	ug/Kg
R3695-04	BH-7	SOIL	Acenaphthene	49	J	350	42	ug/Kg
3695-04	BH-7	SOIL	Dibenzofuran	76	J	350	35	ug/Kg
3695-04	BH-7	SOIL	Fluorene	170	J	350	39	ug/Kg
R3695-04	BH-7	SOIL	Phenanthrene	1400		350	35	ug/Kg
3695-04	BH-7	SOIL	Anthracene	330	J	350	46	ug/Kg
3695-04	BH-7	SOIL	Carbazole	150	J	350	15	ug/Kg
R3695-04	BH-7	SOIL	Di-n-butylphthalate	43	J	350	42	ug/Kg
3695-04	BH-7	SOIL	Fluoranthene	1600		350	35	ug/Kg
3695-04	BH-7	SOIL	Pyrene	1500		350	35	ug/Kg
R3695-04	BH-7	SOIL	Benzo(a)anthracene	1100		350	35	ug/Kg
3695-04	BH-7	SOIL	Chrysene	1000		350	57	ug/Kg
R3695-04	BH-7	SOIL	bis(2-Ethylhexyl)phthalate	400	B	350	35	ug/Kg
R3695-04	BH-7	SOIL	Benzo(b)fluoranthene	1100		350	35	ug/Kg
3695-04	BH-7	SOIL	Benzo(k)fluoranthene	1300		350	92	ug/Kg
R3695-04	BH-7	SOIL	Benzo(a)pyrene	1400		350	53	ug/Kg
R3695-04	BH-7	SOIL	Indeno(1,2,3-cd)pyrene	330	J	350	57	ug/Kg
3695-04	BH-7	SOIL	Dibenz(a,h)anthracene	400		350	54	ug/Kg
R3695-04	BH-7	SOIL	Benzo(g,h,i)perylene	590		350	46	ug/Kg
			Total SVOC's:	13168.00				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	13168.00				
ent ID:	BH-8							
R3695-05	BH-8	WATER	bis(2-Ethylhexyl)phthalate	6.3	JB	10	1.0	ug/L
			Total SVOC's:	6.30				
			Total TIC's:	0.00				
			Total SVOC's and TIC's:	6.30				

Note: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Hit Summary Report

SDG No.: R3695-01 **Order ID:** R3695

Client: ASTEM Laboratory, Inc. **Project ID:** Junk Yard

Test: SVOC-Chemtech Full BN

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
ient ID:	BH-9S							
695-07	BH-9S	SOIL	1,2-Dichlorobenzene	2400		350	35	ug/Kg
3695-07	BH-9S	SOIL	1,3-Dichlorobenzene	270	J	350	41	ug/Kg
695-07	BH-9S	SOIL	1,4-Dichlorobenzene	500		350	35	ug/Kg
695-07	BH-9S	SOIL	1,2,4-Trichlorobenzene	460		350	41	ug/Kg
3695-07	BH-9S	SOIL	Naphthalene	180	J	350	41	ug/Kg
695-07	BH-9S	SOIL	2-Methylnaphthalene	120	J	350	41	ug/Kg
695-07	BH-9S	SOIL	Acenaphthylene	47	J	350	41	ug/Kg
3695-07	BH-9S	SOIL	Diethylphthalate	76	J	350	35	ug/Kg
695-07	BH-9S	SOIL	Hexachlorobenzene	810		350	38	ug/Kg
3695-07	BH-9S	SOIL	Phenanthrene	65	J	350	35	ug/Kg
3695-07	BH-9S	SOIL	Anthracene	64	J	350	45	ug/Kg
695-07	BH-9S	SOIL	Di-n-butylphthalate	120	J	350	41	ug/Kg
3695-07	BH-9S	SOIL	Fluoranthene	46	J	350	35	ug/Kg
3695-07	BH-9S	SOIL	Pyrene	100	J	350	35	ug/Kg
695-07	BH-9S	SOIL	Benzo(a)anthracene	56	J	350	35	ug/Kg
3695-07	BH-9S	SOIL	Chrysene	66	J	350	56	ug/Kg
695-07	BH-9S	SOIL	bis(2-Ethylhexyl)phthalate	400	B	350	35	ug/Kg
695-07	BH-9S	SOIL	Benzo(b)fluoranthene	86	J	350	35	ug/Kg
3695-07	BH-9S	SOIL	Benzo(a)pyrene	67	J	350	52	ug/Kg
695-07	BH-9S	SOIL	Indeno(1,2,3-cd)pyrene	88	J	350	56	ug/Kg
695-07	BH-9S	SOIL	Benzo(g,h,i)perylene	430		350	45	ug/Kg

Total SVOC's:	6451.00
Total TIC's:	0.00
Total SVOC's and TIC's:	6451.00

ote: The asterisk "*" flag next to a parameter signifies a TIC parameter.

Metals

- 1 -

INORGANIC ANALYSIS DATA PACKAGE

Client: ASTEM Laboratory, Inc. **SDG No.:** R3695 **Method Type:** SW846

Sample ID: R3695-03 **Client ID:** BH-6

Contract: ASTEM Laboratory, Inc. **Lab Code:** CHEMED **Case No.:** **SAS No.:** R3695

Matrix: SOIL **Date Received:** 8/6/03 **Level:** LOW

% Solids: 95 **Sample Wt/Vol:** 1.0 **Final Vol:** 100.0

Analyte	CAS No.	Concentration	Units	C	Qual	M	DL	Instrument ID	Analytical Run
Antimony	7440-36-0	1.9	mg/Kg	J		P	0.21	P2	P208113
Arsenic	7440-38-2	2.7	mg/Kg			P	0.22	P2	P208113
Beryllium	7440-41-7	0.15	mg/Kg	J		P	0.14	P2	P208113
Cadmium	7440-43-9	0.13	mg/Kg	U		P	0.13	P2	P208113
Chromium	7440-47-3	5.2	mg/Kg			P	0.20	P2	P208113
Copper	7440-50-8	23.6	mg/Kg			P	0.27	P2	P208113
Lead	7439-92-1	1720	mg/Kg			P	0.25	P2	P208113
Mercury	7439-97-6	0.06	mg/Kg			CV	0.01	CV2	081103B
Nickel	7440-02-0	6.4	mg/Kg			P	0.80	P2	P208113
Selenium	7782-49-2	0.44	mg/Kg	U		P	0.44	P2	P208113
Silver	7440-22-4	0.29	mg/Kg	U		P	0.29	P2	P208113
Thallium	7440-28-0	0.33	mg/Kg	U		P	0.33	P2	P208113
Zinc	7440-66-6	347	mg/Kg			P	0.68	P2	P208113

Color Before: BROWN **Clarity Before:** **Texture:** MEDIUM

Color After: YELLOW **Clarity After:** **Artifacts:**

Comments:

Metals

- 1 -

INORGANIC ANALYSIS DATA PACKAGE

Client: ASTEM Laboratory, Inc. **SDG No.:** R3695 **Method Type:** SW846

Sample ID: R3695-04 **Client ID:** BH-7

Contract: ASTEM Laboratory, Inc. **Lab Code:** CHEMED **Case No.:** **SAS No.:** R3695

Matrix: SOIL **Date Received:** 8/6/03 **Level:** LOW

% Solids: 93 **Sample Wt/Vol:** 1.0 **Final Vol:** 100.0

Analyte	CAS No.	Concentration	Units	C	Qual	M	DL	Instrument ID	Analytical Run
Antimony	7440-36-0	127	mg/Kg			P	0.21	P2	P208113
Arsenic	7440-38-2	16.8	mg/Kg			P	0.22	P2	P208113
Beryllium	7440-41-7	0.16	mg/Kg	J		P	0.14	P2	P208113
Cadmium	7440-43-9	24.8	mg/Kg			P	0.13	P2	P208113
Chromium	7440-47-3	32.9	mg/Kg			P	0.20	P2	P208113
Copper	7440-50-8	3470	mg/Kg			P	0.27	P2	P208113
Lead	7439-92-1	2190	mg/Kg			P	0.25	P2	P208113
Mercury	7439-97-6	0.66	mg/Kg			CV	0.05	CV2	081103B
Nickel	7440-02-0	161	mg/Kg			P	0.80	P2	P208113
Selenium	7782-49-2	0.44	mg/Kg	U		P	0.44	P2	P208113
Silver	7440-22-4	2.3	mg/Kg			P	0.28	P2	P208113
Thallium	7440-28-0	0.33	mg/Kg	U		P	0.33	P2	P208113
Zinc	7440-66-6	6940	mg/Kg			P	0.67	P2	P208113

Color Before: BROWN **Clarity Before:** **Texture:** MEDIUM

Color After: YELLOW **Clarity After:** **Artifacts:**

Comments:

Metals

- 1 -

INORGANIC ANALYSIS DATA PACKAGE

Client: ASTEM Laboratory, Inc. SDG No.: R3695 Method Type: SW846

Sample ID: R3695-07 Client ID: BH-9

Contract: ASTEM Laboratory, Inc. Lab Code: CHEMED Case No.: SAS No.: R3695

Matrix: SOIL Date Received: 8/6/03 Level: LOW

% Solids: 95 Sample Wt/Vol: 1.0 Final Vol: 100.0

Analyte	CAS No.	Concentration	Units	C	Qual	M	DL	Instrument ID	Analytical Run
Antimony	7440-36-0	1.6	mg/Kg	J		P	0.21	P2	P208113
Arsenic	7440-38-2	17.7	mg/Kg			P	0.22	P2	P208113
Beryllium	7440-41-7	0.23	mg/Kg	J		P	0.13	P2	P208113
Cadmium	7440-43-9	0.12	mg/Kg	U		P	0.12	P2	P208113
Chromium	7440-47-3	14.8	mg/Kg			P	0.20	P2	P208113
Copper	7440-50-8	64.4	mg/Kg			P	0.27	P2	P208113
Lead	7439-92-1	480	mg/Kg			P	0.25	P2	P208113
Mercury	7439-97-6	0.24	mg/Kg			CV	0.01	CV2	081103B
Nickel	7440-02-0	12.8	mg/Kg			P	0.79	P2	P208113
Selenium	7782-49-2	0.43	mg/Kg	U		P	0.43	P2	P208113
Silver	7440-22-4	0.28	mg/Kg	U		P	0.28	P2	P208113
Thallium	7440-28-0	0.32	mg/Kg	U		P	0.32	P2	P208113
Zinc	7440-66-6	227	mg/Kg			P	0.66	P2	P208113

Color Before: BROWN Clarity Before: Texture: MEDIUM

Color After: YELLOW Clarity After: Artifacts:

Comments:

Hit Summary Sheet
SW-846

SDG No.: R3695 Order ID: R3695

Client: ASTEM Laboratory, Inc. Project ID: Junk Yard

Sample ID	Client ID	Matrix	Parameter	Concentration	C	RDL	MDL	Units
Client ID:	BH-6							
695-03	BH-6	SOIL	Antimony	1.9	J	6.3	0.21	mg/Kg
R3695-03	BH-6	SOIL	Arsenic	2.7		1.1	0.22	mg/Kg
695-03	BH-6	SOIL	Beryllium	0.15	J	0.53	0.14	mg/Kg
695-03	BH-6	SOIL	Chromium	5.2		1.1	0.20	mg/Kg
R3695-03	BH-6	SOIL	Copper	23.6		2.6	0.27	mg/Kg
695-03	BH-6	SOIL	Lead	1720		0.32	0.25	mg/Kg
695-03	BH-6	SOIL	Mercury	0.06		0.01	0.01	mg/Kg
R3695-03	BH-6	SOIL	Nickel	6.4		4.2	0.80	mg/Kg
595-03	BH-6	SOIL	Zinc	347		2.1	0.68	mg/Kg
Client ID:	BH-7							
595-04	BH-7	SOIL	Antimony	127		6.3	0.21	mg/Kg
595-04	BH-7	SOIL	Arsenic	16.8		1.0	0.22	mg/Kg
R3695-04	BH-7	SOIL	Beryllium	0.16	J	0.52	0.14	mg/Kg
595-04	BH-7	SOIL	Cadmium	24.8		0.52	0.13	mg/Kg
695-04	BH-7	SOIL	Chromium	32.9		1.0	0.20	mg/Kg
R3695-04	BH-7	SOIL	Copper	3470		2.6	0.27	mg/Kg
595-04	BH-7	SOIL	Lead	2190		0.31	0.25	mg/Kg
3695-04	BH-7	SOIL	Mercury	0.66		0.05	0.05	mg/Kg
R3695-04	BH-7	SOIL	Nickel	161		4.2	0.80	mg/Kg
595-04	BH-7	SOIL	Silver	2.3		1.0	0.28	mg/Kg
3695-04	BH-7	SOIL	Zinc	6940		2.1	0.67	mg/Kg
nt ID:	BH-9							
3695-07	BH-9	SOIL	Antimony	1.6	J	6.2	0.21	mg/Kg
3695-07	BH-9	SOIL	Arsenic	17.7		1.0	0.22	mg/Kg
695-07	BH-9	SOIL	Beryllium	0.23	J	0.52	0.13	mg/Kg
3695-07	BH-9	SOIL	Chromium	14.8		1.0	0.20	mg/Kg
695-07	BH-9	SOIL	Copper	64.4		2.6	0.27	mg/Kg
695-07	BH-9	SOIL	Lead	480		0.31	0.25	mg/Kg
3695-07	BH-9	SOIL	Mercury	0.24		0.01	0.01	mg/Kg
695-07	BH-9	SOIL	Nickel	12.8		4.1	0.79	mg/Kg
695-07	BH-9	SOIL	Zinc	227		2.1	0.66	mg/Kg

New York State Department of Environmental Conservation
Division of Environmental Remediation
Bureau of Spills Management
47-40 21ST Street, Long Island City, NY 11101
Phone: (718) 482-6753
Fax: (718) 482-4098

Erin M. Crotty
Commissioner

Virginia Lupoli
Yardley Associates LLC
P.O. Box 237
Cold Spring Harbor, NY 11724

May 9, 2003

RE: LIC Used Auto Parts 37-25 21st Street, Long Island City, NY

Spill # 0230068

Dear Ms. Lupoli:

The Department of Environmental Conservation (DEC) has inspected the subject property owned by Yardley Associates LLC. Several spill violations were identified during this inspection and the above referenced Spill Number was registered with the DEC.

At this time the DEC requires the following work to be performed at the site:

1) Within 60 days of this letter, a Delineation Plan must be submitted to the DEC which outlines a schedule and procedure for:
   a) Surface cleaning the site to determine condition of cap blacktop or cement.
   b) Conducting a "Geo-Probe" subsurface soil investigation to delineate contamination
   c) Obtaining four (4) groundwater samples from various locations on the site.

2) Within 60 days of DEC approval of the Delineation Plan, the work outlined in the Plan will be completed and a Delineation Report outlining the results will be submitted to the DEC.

3) Depending upon the results of the Delineation Report, a Remediation Plan will be required to be submitted along with the Delineation Report in Step 2 above. This Plan will outline a proposed plan to remediate the site to bring it within DEC standards.

As per your request, attached is a listing of environmental contractors who are on the State Remediation Contractors List. It should be noted that you are free to hire any contractor either on or off this list to complete the work outlined above. The DEC would strongly suggest that an initial meeting be held with the DEC and the chosen contractor to outline the work to be done at the site.

Under the Navigation Law, any person or entity failing to investigate and remediate a petroleum spill can be fined upwards of $25,000 per day. Additionally, the State may investigate and remediate this spill if you are unwilling or unable. In this case, you will be held accountable for the actual costs of clean up, and any fines which will be solicited by the New York State Attorney General's Office.

If you have any questions concerning this letter, or would like to discuss the work needed, feel free to call my office at (718) 482-6753.

Sincerely,

Steven Sangesland
Environmental Engineer I
Environmental Remediation Division
Region 2 - New York State

Spill Response/Remediation Contractors List - Region 2 New York City

Surface Spill Response

1) Milro Associates - Freeport, LI 516-379-1500
2) Trade-Winds Envir. - Bay Shore, LI 631-435-8900
3) Fenley & Nichol Envir. - Deer Park, LI 631-586-4900

Subsurface Remediation

4) Miller Envir. Group - Calverton, LI 631-369-4900
5) EnviroTrac Ltd. - Ronkonkoma, LI 631-471-1500
6) Winston Contractors - Commack, LI / Queens 718-445-4232

NYSDEC SPILL REPORT FORM

DEC REGION# 2 (Long Island City) **SPILL NUMBER** 0230068
SPILL NAME: LIC USED AUTO PARTS **DEC LEAD:** SANGESLAND
CALLER'S NAME: STEVEN SANGESLAND **NOTIFIER'S NAME:**
CALLER'S AGENCY: REG 2 DEC **NOTIFIER'S AGENCY:**
CALLER'S PHONE: (718) 482-6753 **EXT.** **NOTIFIER'S PHONE:** **EXT.**

SPILL DATE: 03/11/2003 **TIME:** 12:00
CALL RECEIVED DATE: 03/11/2003 **TIME:** 12:00 **RECEIVED BY CID #:**

Material Spilled	Mat. Class	Am't Spilled	Units	Am't Recovered
1) MOTOR OIL	(Pet)-Haz-Other-Unk.	50	(Gal) Lbs	0
2) ANTIFREEZE	Pet-Haz-(Other)-Unk.	50	(Gal) Lbs	0
3) BATTERY ACID	Pet-Haz-(Other)-Unk.	1	(Gal) Lbs	0
4) TRANSMISSION FLUID	(Pet)-Haz-Other-Unk.	50	(Gal) Lbs	0

SPILL LOCATION

PLACE: LIC USED AUTO PARTS
STREET: 37-25 21ST STREET
T/C/V: LONG ISLAND CITY **CO:** QUEENS
CONTACT:
PHONE: **EXT.**

POTENTIAL SPILLER

NAME: LIC USED AUTO PARTS
STREET: 37-25 21ST STREET
CITY: LONG ISLAND CITY
STATE: NY **ZIP:** 11101-
CONTACT:
PHONE: **EXT.**

SPILL CAUSE

Human Error	Tank Test Failure*	Tank Failure
Traffic Accident	Housekeeping	Tank Overfill
Equipment Failure	(Deliberate)	Other
Vandalism	Abandoned Drums	Unknown

SPILL SOURCE

Gas Station	Private Dwelling	Non-Maj Facility
Passenger Vehicle	Vessel	(Comm/Indust)
Comm. Vehicle	Railroad Car	Non-Comm/Instit
Tank Truck	Major Facility	Unknown

RESOURCE AFFECTED

(On Land)	Groundwater	Air
In Sewer	Surface Water**	

**WATERBODY:

SPILL REPORTED BY

Responsible Party	Tank Tester	Local Agency
Affected Persons	(DEC)	Federal Gov't
Police Department	Citizen	Other
Fire Department	Health Dept.	

CALLER REMARKS: DEC SPILLS GROUP CALLED TO SITE OF POLICE ACTION AT A JUNK YARD. SITE HAD SPILLS OF AUTO RELATED LIQUIDS OVER ENTIRE YARD AREA.

*PBS Number	Tank Number	Tank Size	Test Method	Leak Rate

PRIMARY CONTACT CALLED DATE: **TIME:** hrs. **REACHED DATE:** **TIME:** hrs.
SECONDARY CONT. CALLED DATE: **TIME:** hrs. **FAXED BY CID#:**

PIN #	T & A	Cost Center	ISR to Central Office
Cleanup Ceased	Meets St'ds NO	Last Inspection	Penalty NO
RP-CUI	ENF-INIT	INVES-COM	CAP
UST Trust Eligible NO	Site: A (B) C D E	Resp. Party 1 (2) 3 4 5 6	Reg Close Date

Created on 03/11/2003 **Last Updated on** 05/07/2003 **Is Updated?** YES **EDO** **DATA INPUT** [ ]
Date Printed: 05/07/2003

PrintFor 3/30/1999

Spill Number: 0230068 **Spill Name:** LIC USED AUTO PARTS **Printed on:** 05/07/2003

Material Spilled	Material Class	Amount Spilled	Units	Amount Recovered
5)AUTO WASTE FLUIDS	PETRO	0	Gallons	
6)GASOLINE	PETRO	0	Gallons	

DEC REMARKS

3/11/2003 Sangesland responded to the site of an ECO/Police action at a junk yard.

Site has been an active "Auto Parts" facility for approx 2 years.
Site is an irregular T shaped lot (approx 120' x 200')
Cement/asphalt appears to cover majority of the lot, unknown if this ground cover is complete and impervious to surface spills. No obvious floor drains could be seen. Unknown if rainwater, auto fluids run into the ground or directly off site.

Central area of the yard appears to be the car dismantling area and contains the majority of the spilled auto fluids (oil, transmission fluid, etc.) There is no controled spill containment area (no curbing, collection tank etc).

Perimeter of yard was lined primarily with automobile racks (3 cars high). Ground staining appeared weathered and less severe than in the central area.

Along with automotive liquids, the yard contained a large number of engines, transmissions, various engine parts and multiple automobile batteries (several appeared damaged and overturned).

DEC Requirements:

1) Surface of the yard must be cleaned down to the cement/asphalt level. An integrity inspection will be made to determine if there are any floor drains or open cracks directly to the ground below.
2) A "Site Delineation" will be required at the property. A series of soil borings will be taken in a grid pattern over the area of the yard and soil/water samples tested to EPA Method 8260, 8770 & heavy metals.
3) Based on the results of the "Site Delineation", a "Site Remediation Plan" will need to be prepared which will identify the procedure to clean up the contamination identified in the delineation.

4/11/2003 - The owner of the property is believed to be "Virginia" 516-383-9358. She is somehow associated with "Yardley Associates". A call was made to this number in an attempt to get a mailing address, but no response was recieved.
Lease holder to the site is: Jussain Zulfiqar and/or Anwar Javed.

5/7/2003 Sangesland spoke with Virginia Lupoli (owner) She inherited the property from her father. Yardley Associates LLC is the corporate name for the owner.
Sangesland outlined the work which will be required on this site. 1) Power wash the lot to determine the condition of the black top or cement pavement
2) Geo Probe of site to determine the subsurface condition of the site.
3) A 60 day limit will be put in the letter.
4) A list of state contractors will be forwarded with the letter

DEC REMARKS (Continued)

Contact info:
Yardley Associates LLC
Attn: Virginia Lupoli
P.O. Box 237
Cold Spring Harbor, NY 11724
Fax # 631-385-4477

~~Federal Express~~

Do work

Dear Ms. Lupoli:

Prepare a "Delineation Plan" which outlines a schedule for:

~~Divide the site in sections and~~

1) Clean the site down to cement or asphalt surface
2) Conduct a "Geo probe" boring investigation of the site
3) Prepare a "Delineation Report" showing results of the full investigation.
4) ~~Based~~ on the results of this report, a "Remediation Plan" may be required to outline the plan to clean up the site.

Sandra

LIC used Auto Parts

0230068 37-25 21st ST.

ADA Sue Middleton 718-286-7076

FAX 718-286-6658

NYPD-P.O. Joe Wedge - 718-217-8515

ASTEM LABORATORIES, INC.

ENVIROMENTAL ENGINEERING CONSULTANTS
AIR , WATER, SOIL, RADON, ASBESTOS, LEAD TESTING

223-14 114 Rd
Cambria Heights
Queens, NY 11411
Tel: (917) 497-0190

11712 S.W. 128th Pl
Miami, Fl. 33186
Fax (305) 348-6007

November 10, 2003

Mr. Steven Sangesland,
Environmental Engineer I
Environmental Remediation Division
NYCDEC
47-40 21st Street
Long Island City, N.Y. 11101-5407

Re: Spill No. 0230068– LIC Used Auto Parts 37-25 21st Street, Long Island City, NY

Dear Mr. Sangesland:

Further to our conversation following the submission of the Environmental Site Assessment, please be informed that ASTEM Laboratories, Inc. will evaluate the direction of flow of surface water at the aforementioned facility and submit recommendations regarding containment around the property.

Please do not hesitate to contact me at (917) 497-0190 should you have any questions.

Sincerely,
ASTEM Laboratories, Inc.

[redacted]

NYSDEC SPILL REPORT FORM

DEC REGION: 2 **SPILL NUMBER:** 0230068

SPILL NAME: LIC USED AUTO PARTS **DEC LEAD:** SMSANGES

CALLER NAME: STEVEN SANGESLAND **NOTIFIER'S NAME:**

CLR'S AGENCY: REG 2 DEC **NOTIFIER'S AGENCY:**

CALLER'S PHONE: (718) 482-6753 **NOTIFIER'S PHONE:**

SPILL DATE: 03/11/2003 **SPILL TIME:** 12:00 pm **DISPATCHER:**

CALL RECEIVED DATE: 03/11/2003 **RECEIVED TIME:** 12:00 pm

SPILL LOCATION

PLACE: LIC USED AUTO PARTS **COUNTY:** Queens

STREET: 37-25 21ST STREET **TOWN/CITY:** New York City

COMMUNITY: LONG ISLAND CITY

CONTACT: **CONTACT PHONE:**

CONT. FACTOR: Deliberate **SPILL REPORTED BY:** DEC

FACILITY TYPE: Commercial/Industrial **WATERBODY:**

CALLER REMARKS:

DEC SPILLS GROUP CALLED TO SITE OF POLICE ACTION AT A JUNK YARD. SITE HAD SPILLS OF AUTO RELATED LIQUIDS OVER ENTIRE YARD AREA.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
auto waste fluids	Petroleum	0.00 G	0.00 G	Soil,
gasoline	Petroleum	0.00 G	0.00 G	Soil,
motor oil	Petroleum	50.00 G	0.00 G	Soil,
transmission fluid	Petroleum	50.00 G	0.00 G	Soil,
antifreeze	Other	50.00 G	0.00 G	Soil,
battery acid	Other	1.00 G	0.00 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
LIC USED AUTO PARTS	37-25 21ST STREET LONG ISLAND CITY NY 11101	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "SANGESLAND"
3/11/2003 Sangesland responded to the site of an ECO/Police action at a junk yard.

Site has been an active "Auto Parts" facility for approx 2 years.

NYSDEC SPILL REPORT FORM

DEC REGION:	2	**SPILL NUMBER:**	0230068
SPILL NAME:	LIC USED AUTO PARTS	**DEC LEAD:**	SMSANGES

Site is an irregular T shaped lot (approx 120' x 200')

Cement/asphalt appears to cover majority of the lot, unknown if this ground cover is complete and impervious to surface spills. No obvious floor drains could be seen. Unknown if rainwater, auto fluids run into the ground or directly off site.

Central area of the yard appears to be the car dismantling area and contains the majority of the spilled auto fluids (oil, transmission fluid, etc.) There is no controled spill containment area (no curbing, collection tank etc).

Perimeter of yard was lined primarily with automobile racks (3 cars high). Ground staining appeared weathered and less severe than in the central area.

Along with automotive liquids, the yard contained a large number of engines, transmissions, various engine parts and multiple automobile batteries (several appeared damaged and overturned).

DEC Requirements:
1) Surface of the yard must be cleaned down to the cement/asphalt level. An integrity inspection will be made to determine if there are any floor drains or open cracks directly to the ground below.
2) A "Site Delineation" will be required at the property. A series of soil borings will be taken in a grid pattern over the area of the yard and soil/water samples tested to EPA Method 8260, 8770 & heavy metals.
3) Based on the results of the "Site Delineation", a "Site Remediation Plan" will need to be prepared which will identify the procedure to clean up the contamination identified in the delineation.

4/11/2003 - The owner of the property is believed to be "Virginia" 516-383-9358. She is somehow associated with "Yardley Associates". A call was made to this number in an attempt to get a mailing address, but no response was recieved.

Lease holder to the site is: Jussain Zulfiqar and/or Anwar Javed.

5/7/2003 Sangesland spoke with Virginia Lupoli (owner) She inherited the property from her father. Yardley Associates LLC is the corporate name for the owner.
Sangesland outlined the work which will be required on this site.
1) Power wash the lot to determine the condition of the black top or cement pavement
2) Geo Probe of site to determine the subsurface condition of the site.
3) A 60 day limit will be put in the letter.
4) A list of state contractors will be forwarded with the letter

Contact info:
Yardley Associates LLC
Attn: Virginia Lupoli
P.O. Box 237
Cold Spring Harbor, NY 11724
Fax # 631-385-4477

11/4/2003 Sangesland reviewed an Environmental Site Assessment for this site prepared by Dr. Norman Munroe (917-497-0190) of Astem Labs Inc. Report states that the entire site is capped with a cement pad between 8" and 24" thick. There did not appear to be any open preferential pathways directly to the soil. The report did not outline the path for rain water runoff or recharge.

Report outlines soil boring work done on the site along with some ground water sampling.

NYSDEC SPILL REPORT FORM

DEC REGION: 2 **SPILL NUMBER:** 0230068

SPILL NAME: LIC USED AUTO PARTS **DEC LEAD:** SMSANGES

Some minor soil VOC hits (BTEX) in BH-2, BH-4 and BH-9
One minor groundwater hit for Benzene & MTBE in BH-4
SVOC's for soil and water were below regulatory limits
Heavy metal concentrations in soil samples exceeded regulatory limits for several metals including: lead arsenic, cadmium, chromium and copper.

Based on this information, the case is closed with no further action required.

PIN **T & A** **COST CENTER**

CLASS: B2 **CLOSE DATE:** 01/29/2007 **MEETS STANDARDS:** False