PHASE I ENVIRONMENTAL SITE ASSESSMENT
OF

MACY'S WHITE PLAINS GALLERIA
100 MAIN STREET
WHITE PLAINS, NEW YORK 10601

ATC PROJECT NO. Z214DCWP01

APRIL 12, 2019

Prepared by:

ATC Group Services LLC
104 East 25th ST,, 8th Floor
New York, New York 10010
Phone: 2123538280

Prepared for:

Mr. Jonathon Rood
WP Galleria Realty, LP
100 N. Sepulveda Blvd., Suite 1925
El Segundo, California 90245

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY....1
1.1 General Information....1
1.2 Findings and Conclusions Summary....2
1.3 Significant Data Gap Summary....3
1.4 Recommendations....4

2.0 INTRODUCTION....5
2.1 Purpose....5
2.2 Scope....5
2.3 Significant Assumptions....6
2.4 Limitations and Exceptions....6
2.5 Special Terms and Conditions (User Reliance)....8

3.0 SITE DESCRIPTION....9
3.1 Location and Legal Description....9
3.2 Surrounding Area General Characteristics....9
3.3 Current Use of the Property....9
3.4 Description of Property Improvements....9
3.5 Current Uses of Adjoining Properties....10

4.0 USER PROVIDED INFORMATION....11
4.1 Title Records....11
4.2 Environmental Liens or Activity and Use Limitations (AULs)....11
4.3 Specialized Knowledge or Experience of the User....11
4.4 Significant Valuation Reduction for Environmental Issues....11
4.5 Owner, Property Manager, and Occupant Information....11
4.6 Reason For Performing Phase I ESA....11
4.7 Other User Provided Documents....11

5.0 RECORDS REVIEW....12
5.1 Standard Environmental Records....12
5.1.1 Federal Database Findings....13
5.1.2 State and Tribal Database Findings....15
5.1.3 Local Environmental Record Sources....19
5.2 Physical Setting Sources....20
5.2.1 Topography....20
5.2.2 Geology....20
5.2.3 Soils....20
5.2.4 Hydrology....20
5.2.5 Other Physical Setting Sources....20
5.3 Historical Records Sources....21
5.3.1 Aerial Photographs....21
5.3.2 Fire Insurance Maps....22
5.3.3 Property Tax Files....24
5.3.4 Recorded Land Title Records....25
5.3.5 Historical USGS Topographic Maps....25
5.3.6 City Directories....25
5.3.7 Building Department Records....25
5.3.8 Zoning/Land Use Records....25

TABLE OF CONTENTS

5.3.9 Prior Reports..... 26
5.3.10 Other Historical Sources..... 26

6.0 SITE RECONNAISSANCE..... 27
6.1 Methodology and Limiting Conditions..... 27
6.2 Hazardous Substance Use, Storage, and Disposal..... 27
6.3 Underground Storage Tanks..... 27
6.4 Aboveground Storage Tanks..... 27
6.5 Other Petroleum Products..... 28
6.6 Polychlorinated Biphenyls (PCBs)..... 28
6.7 Unidentified Substance Containers..... 28
6.8 Nonhazardous Solid Waste..... 28
6.9 Wastewater..... 28
6.10 Waste Pits, Ponds and Lagoons..... 29
6.11 Drains and Sumps..... 29
6.12 Septic Systems..... 29
6.13 Stormwater Management System..... 29
6.14 Wells..... 29

7.0 SUBSURFACE VAPOR MIGRATION..... 30

8.0 INTERVIEWS..... 31

9.0 OTHER ENVIRONMENTAL CONDITIONS..... 32
9.1 Asbestos-Containing Material (ACM)..... 32
9.2 Radon..... 32
9.3 Lead in Drinking Water..... 32
9.4 Lead-Based Paint (LBP)..... 32
9.5 Mold Screening..... 32
9.6 Additional User Requested Services..... 33

10.0 REFERENCES..... 34

11.0 TERMINOLOGY..... 35

Appendix A Site Vicinity Map
Appendix B Site Plan
Appendix C Site Photographs
Appendix E Regulatory Database Report
Appendix F Aerial Photographs
Appendix G Historical Research Documentation
Appendix H Prior Reports
Appendix I Resumes
Appendix J Records of Communication
Appendix L Other Supporting Documentation

1.0 EXECUTIVE SUMMARY

1.1 General Information

Project Information:
Macy's White Plains Galleria
Z214DCWP01

Consultant Information:
ATC Group Services LLC
104 East 25th ST,, 8th Floor
New York, New York 10010
Phone: 2123538280
Fax: 212-979-8447
Inspection Date: 04/02/2019
Report Date: 04/12/2019

Site Information:
Macy's White Plains Galleria
100 Main Street
White Plains, New York 10601
County: Westchester
Latitude, Longitude: 41.031696, -73.768216
Site Access Contact: Mr. Tom Miles

Client Information:
WP Galleria Realty, LP
Mr. Jonathon Rood
100 N. Sepulveda Blvd., Suite 1925
El Segundo, California 90245

Site Assessor

Denise Cosenza
Project Manager
On Behalf Of Chelsea Helm - Project Manager

Senior Reviewer

Denise Cosenza
Project Manager

Environmental Professional Statement:

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in Section 312.10 part of 40 CFR 312. We have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Denise Cosenza - Project Manager

1.2 Findings and Conclusions Summary

ATC Group Services LLC (ATC) has performed a Phase I Environmental Site Assessment (ESA) of the property in conformance with the scope and limitations of ASTM Standard Practice E1527-13. Any exceptions to, or deletions from, this practice are described in Section 2.0 of this report. This assessment has revealed no evidence of *recognized environmental conditions* in connection with the property. The table below provides a summary of report findings and conclusions.

Report Section		Further Action?	De minimis Condition	REC and/or CREC	Historical REC	ASTM Non - Scope Condition	Description
4.0	**User Provided Information**	No					
5.1.1	**Federal Database Findings**	No					
5.1.2	**State and Tribal Database Findings**	No					See Note 1.
5.1.3	**Local Environmental Record Sources**	No					
5.3	**Historical Records Sources**	No					
6.2	**Hazardous Substance Use, Storage, and Disposal**	No					
6.3	**Underground Storage Tanks**	No					See Note 2.
6.4	**Aboveground Storage Tanks**	No	X				See Note3.
6.5	**Other Petroleum Products**	No	X				See Note 4.
6.6	**Polychlorinated Biphenyls (PCBs)**	No					
6.7	**Unidentified Substance Containers**	No					
6.8	**Nonhazardous Solid Waste**	No					
6.9	**Wastewater**	No					
6.10	**Waste Pits, Ponds and Lagoons**	No					
6.11	**Drains and Sumps**	No					
6.12	**Septic Systems**	No					
6.13	**Stormwater Management System**	No					
6.14	**Wells**	No					
7.0	**Subsurface Vapor Migration**	No					
8.0	**Interviews**	No					
9.1	**Asbestos-Containing Material (ACM)**	No					
9.2	**Radon**	No					
9.3	**Lead in Drinking Water**	No					
9.4	**Lead-Based Paint (LBP)**	No					
9.5	**Mold Screening**	No					See Note 5.
9.6	**Additional User Requested Services**	No					

Note 1: Former Property retail occupant, A&S, was identified on the New York State Department of Environmental Conservation (NYSDEC) Leaking Tanks (NY LTANKS) database with spill cases 8805571 and 8803673 in 1988 that both appear to be related to tank test failures associated with a 10,000-gallon tank(s). The tank had reportedly been re-lined and put back in service. No additional details were reported. The spill cases achieved regulatory closure with the NYSDEC. Since it appears that there was no actual

release, and no further action such as remediation was recommended, these LTANKS cases are not considered to be a *recognized environmental condition*.

Note 2: During the Site reconnaissance ATC observed two fuel oil fill ports within the sidewalk along Main Street, directly in front of the loading dock area and two fill ports within the loading dock area. According to a Fuel Oil Tank Upgrade Project Report, prepared by Clayton Environmental Services, Inc., and dated April 25, 1997, two 10,000-gallon underground storage tanks (USTs) were installed in 1979 on a concrete pad below the loading dock area and were "closed-in-place" in January 1997. The USTs were reportedly in good condition at the time of closure and no further sampling was required. Based on review of the Tank Closure report, the four (4) fill ports are likely associated with the two "closed-in place" USTs. Based on the reviewed documentation and the reported condition of the USTs during their removal, they are not considered to be a *recognized environmental condition.*

Note 3: ATC observed one 1,000-gallon diesel fuel aboveground storage tank (AST) within the east portion of the loading dock area that was reportedly installed in 1997. The 1,000-gallon diesel AST transfers fuel to a 100-gallon day tank AST and emergency generator located within the penthouse generator room of the property building. ATC observed oil staining on the concrete pad below the emergency generator engine. No unusually strong odors or signs of corrosion were noted.Based on its location, minor quantity and lack of pathway to the subsurface, this minor staining is considered to be a *de minimis condition.*

Note 4: ATC observed one passenger elevator and one freight elevator that service the property building. The elevators are property-owned, cable/gear traction type, manufactured by Otis Elevator Co., and maintained by Shindler Elevator Corporation on a regular basis. The elevator machine rooms are located on the penthouse level. ATC observed minor oil staining in the immediate vicinity of the passenger elevator equipment on the concrete floor In addition, ATC also observed a slight petroleum-like sheen on standing water within the loading dock area of the property building. The sheen is likely associated with the typical operations of vehicles both driving and parking in this concrete-paved loading area. ATC considers the oil staining in the elevator equipment room and the observed sheen in the loading area to represent *de minimis conditions.*

Note 5: ATC conducted a screening survey for readily observable mold and conditions conducive to mold on the property. The screening consisted of limited interview, document review (if any) and physical observation. ATC observed various areas of water stained ceiling tiles throughout the penthouse, including the elevator lobby, back storage rooms, the sales floor, and employee lounge within the third floor of the property building. ATC observed approximately eight square feet of suspect visible mold growth (SVMG) within the Back of House (BOH) storage room, located in the out of service sales area on the third floor. According to the Chief Engineer, roof leaks have affected these areas and are currently being addressed.

1.3 Significant Data Gap Summary

Data gaps may have been encountered during the performance of this Phase I ESA and are discussed within the section of the report where they were encountered. However, according to ASTM Standard Practice E1527-13, data gaps are only significant if "other information and/or professional experience raises reasonable concerns involving the data gap." The following table is a summary of significant data gaps identified in this report.

SIGNIFICANT DATA GAP SUMMARY	
Report Section	**Description**
3.5 Current Uses of Adjoining Properties	No significant data gaps identified
4.2 Environmental Liens or Activity and Use Limitations (AULs)	No significant data gaps identified
5.1 Standard Environmental Records	No significant data gaps identified
5.2 Physical Setting Sources	No significant data gaps identified
5.3 Historical Records Sources	No significant data gaps identified
6.1 Methodology and Limiting Conditions	No significant data gaps identifiedv
7.0 Subsurface Vapor Migration	No significant data gaps identified
8.0 Interviews	No significant data gaps identified

1.4 Recommendations

Based on information collected from the Phase I ESA, ATC offers no recommendations for further action at this time.

2.0 INTRODUCTION

2.1 Purpose

The purpose of this Phase I ESA was to identify *recognized environmental conditions* in connection with the property at the time of the site reconnaissance. The scope of work for this Phase I ESA may also include certain potential environmental conditions beyond the scope of ASTM Standard Practice E1527-13 as listed below. This report documents the findings, opinions and conclusions of the Phase I ESA.

2.2 Scope

This Phase I ESA was conducted in general accordance with the ASTM Standard Practice E1527-13, consistent with a level of care and skill ordinarily practiced by the environmental consulting profession currently providing similar services under similar circumstances. Significant additions, deletions or exceptions to ASTM Standard Practice E1527-13 are noted below or in the corresponding sections of this report. The scope of this assessment included an evaluation of the following:

- Physical setting characteristics of the property through a review of referenced sources such as topographic maps and geologic, soils and hydrologic reports.

- Usage of the property, adjoining properties and surrounding area through a review of referenced historical sources such as land title records, fire insurance maps, city directories, aerial photographs, prior reports and interviews.

- Observations and interviews regarding current property usage and condition including: the use, treatment, storage, disposal or generation of hazardous substances, petroleum products, hazardous wastes, nonhazardous solid wastes and wastewater.

- Usage of adjoining and surrounding area properties and the likely impact of known or suspected releases of hazardous substances or petroleum products from those properties in, on, or at the property.

- Information in referenced environmental agency databases and local environmental records, within the specified approximate minimum search distance from the property.

- Potential for subsurface vapor migration in, on or at the property as described in Section 7.0.

The scope of the assessment also included consideration of the following potential environmental issues or conditions that are beyond the scope of ASTM Standard Practice E1527-13:

- The scope of work for the Mold Screening was intended to be consistent with ASTM E 2418-06: Standard Guide for Readily Observable Mold and Conditions Conducive to Mold in Commercial Buildings: Baseline Survey Process. The scope of work, including potential deviations from the Standard Guide, is described as follows. The interview was limited to at least one knowledgeable person from property management or engineering staff. The document review was limited to only those relevant documents made readily available to ATC in a timely manner. The physical observations were limited to certain Heating, Ventilation and Air Conditioning (HVAC) system areas and other readily accessible building areas likely to become subject to water damage, plumbing leaks, and flooding. Unless noted otherwise herein, ATC observed the HVAC equipment room(s) and accessible mechanical rooms and, in buildings with package units in the ceiling, at least one unit per floor. Also, unless noted otherwise, ATC observed accessible areas of the basement (or lowest level), the top floor, the roof (including any penthouse areas) and at least one mid-level floor (if applicable). For multi-story buildings, the total number of floors observed (inclusive of those already mentioned) was intended to be up to 10% of the total number of floors (if readily accessible). For hotel and multi-family buildings, ATC targeted the lowest and highest levels and roof as described above and up to 10% of units, including one per floor if readily accessible. The Mold Screening did not include destructive methods of observation. No sampling or laboratory analyses were conducted. The Mold Screening service as described herein was limited in scope and by the time and cost considerations typically associated with performing a Phase I ESA. No method can guarantee that a hazard will be

discovered if evidence of the hazard is not encountered within the performance of the Mold Screening as authorized and that opinions and conclusions must, out of necessity, be extrapolated from limited information and discrete, non-continuous data points. Unidentified mold or other microbial conditions may exist on the property.

- Visual observation of suspect asbestos-containing materials (ACM), consisting of providing an opinion on the condition of suspect ACM on the property based upon visual observation during the site reconnaissance. No sampling of suspect ACM was conducted.

- Radon document review, consisting of the review of published radon data with regard to the potential for elevated levels of radon gas in the surrounding area of the property. No radon sampling was conducted.

- Lead in drinking water data review, consisting of contacting the water supplier for information regarding whether or not the potable water provided to the property meets the drinking water standards for lead.

- Visual observation of suspect lead-based paint (LBP), consisting of providing an opinion on the potential for LBP based on the construction date of buildings on the property and visual observation of the condition of suspect LBP.

- Wetlands document review, consisting of a review of a current National Wetlands Inventory map of the surrounding area to note if the property is identified on the map as having a wetland.

- Flood plain document review, consisting of a review of a reasonably ascertainable flood plain map of the surrounding area to note if the property is identified on the map as being located within a flood plain.

- Regulatory Agency File and Records Review, consisting of conducting a file review (i.e., via Freedom of Information Act (FOIA) request or alternative method/source) for the property and/or one adjoining property at one regulatory agency, as warranted by the findings of the ESA. If ATC determines that additional Regulatory Agency File and Records Reviews are warranted, ATC will advise Client and seek written authorization for the additional services and fees.

2.3 Significant Assumptions

The assumptions in this report were not considered as having a significant impact on the determination of *recognized environmental conditions* associated with the property.

2.4 Limitations and Exceptions

ATC has prepared this Phase I ESA report using reasonable efforts to identify *recognized environmental conditions* associated with hazardous substances or petroleum products in, on, or at the property. Findings contained within this report are based on information collected from observations made on the day(s) of the site reconnaissance and from reasonably ascertainable information obtained from certain public agencies and other referenced sources.

The ASTM Standard Practice E 1527-13 recognizes inherent limitations for Phase I ESAs, including, but not limited to:

- *Uncertainty Not Eliminated:* a Phase I ESA cannot wholly eliminate uncertainty regarding the potential for *recognized environmental conditions* in connection with a property.

- *Not Exhaustive:* a Phase I ESA is not an exhaustive assessment of the environmental conditions on a property.

- *Past Uses of the Property:* a Phase I ESA does not require review of standard historical sources at less than five year intervals. Therefore, past uses of the property may not be discovered.

Users of this report may refer to ASTM Standard Practice E 1527-13 for further information regarding these and other limitations. This report is not definitive and should not be assumed to be a complete and/or specific definition of all conditions above or below grade. Current subsurface conditions may differ from the conditions determined by surface observations, interviews and reviews of historical sources. The most reliable method of evaluating subsurface conditions is through intrusive techniques, which are beyond the scope of this report. Information in this report is not intended to be used as a construction document and should not be used for demolition, renovation, or other property construction purposes. Any use of this report by any party, beyond the scope and intent of the original parties, shall be at the sole risk and expense of such user.

ATC makes no representation or warranty that the past or current operations at the property are, or have been, in compliance with all applicable federal, state and local laws, regulations and codes. This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not investigated. Regardless of the findings stated in this report, ATC is not responsible for consequences or conditions arising from facts not fully disclosed to ATC during the assessment.

An independent data research company provided the government agency databases referenced in this report. Information on surrounding area properties was requested for approximate minimum search distances and is assumed to be correct and complete unless obviously contradicted by ATC's observations or other credible referenced sources reviewed during the assessment. ATC shall not be liable for the database firm's failure to make relevant files or documents properly available, to properly index files, or otherwise to fail to maintain to produce accurate or complete records.

ATC makes no warranty, guarantee or certification regarding the quality, accuracy or reliability of any prior report provided to ATC and discussed in this Phase I ESA report. ATC expressly disclaims any and all liability for any errors or omissions contained in any prior reports provided to ATC and discussed in this Phase I ESA report.

ATC used reasonable efforts to identify evidence of aboveground and underground storage tanks and ancillary equipment on the property during the assessment. "Reasonable efforts" were limited to observation of accessible areas, review of referenced public records and interviews. These reasonable efforts may not identify subsurface equipment or evidence hidden from view by things including, but not limited to, snow cover, paving, construction activities, stored materials and landscaping.

Any estimates of costs or quantities in this report are approximations for commercial real estate transaction due diligence purposes and are based on the findings, opinions and conclusions of this assessment which are limited by the scope of the assessment, schedule demands, cost constraints, accessibility limitations and other factors associated with performing the Phase I ESA. Subsequent determinations of costs or quantities may vary from the estimates in this report. The estimated costs or quantities in this report are not intended to be used for financial disclosure related to FASB Statement No. 143, FASB Interpretation No. 47, Sarbanes/Oxley Act or any United States Securities and Exchange Commission reporting obligations, and may not be used for such purposes in any form without the express written permission of ATC.

ATC is not a professional title insurance or land surveyor firm and makes no guarantee, express or implied, that any land title records acquired or reviewed in this report, or any physical descriptions or depictions of the property in this report, represent a comprehensive definition or precise delineation of property ownership or boundaries.

The Environmental Professional Statement in Section 1.1 of this report does not "certify" the findings contained in this report and is not a legal opinion of such *Environmental Professional*. The statement is meant to document ATC's opinion that an individual meeting the qualifications of an *Environmental Professional* was involved in the performance of the assessment and that the activities performed by, or under the supervision of, the *Environmental Professional* were performed in conformance with the standards and practices set forth in 40 CFR Part 312 per the methodology in ASTM Standard Practice E 1527-13 and the scope of work for this assessment.

Per ASTM Standard Practice E 1527-13, Section 6, User Responsibilities, the User of this assessment has specific obligations for performing tasks during this assessment that will help identify the possibility of

recognized environmental conditions in connection with the property. Failure by the User to fully comply with the requirements may impact their ability to use this report to help qualify for *Landowner Liability Protections* (LLPs) under CERCLA. ATC makes no representations or warranties regarding a User's qualification for liability protection under any federal, state or local laws or regulations.

In accordance with the ASTM Standard Practice E 1527-13, this report is presumed to be valid for a six month period. If the report is older than six months, the following information must be updated in order for the report to be valid: (1) regulatory review, (2) site visit, (3) interviews, (4) specialized knowledge, and (5) environmental liens. Reports older than one year may not meet ASTM Standard Practice E 1527-13 and therefore, the report must be updated to reflect current conditions and property-specific information.

Other limitations and exceptions that are specific to the scope of this report may be found in corresponding sections.

2.5 Special Terms and Conditions (User Reliance)

This report is for the use and benefit of , and may be relied upon by, WP Galleria Realty LP, and any of its affiliates and their respective successors and assigns, in connection with a commercial real estate transaction involving the property. No third party is authorized to use this report for any purpose. Any use by or distribution of this report to third parties, without the express written consent of ATC, is at the sole risk and expense of such third party.

3.0 SITE DESCRIPTION

3.1 Location and Legal Description

The property address is 100 Main Street, White Plains, Westchester County, New York 10601. The Site Vicinity Map is located in Appendix A. The Site Plan is located in Appendix B. Site Photographs are provided in Appendix C. According to information obtained from the Westchester County GIS system, the property is identified as Tax ID 125.75-4-4.

3.2 Surrounding Area General Characteristics

The property is located within the City of White Plains in Westchester County in an area characterized primarily by commercial offices, government offices, municipal courts, retail stores, restaurants, and residential buildings. Surface topography across the property and in the surrounding area is sloped towards the west-northwest. Specific adjacent and abutting properties are summarized in Section 3.5.

3.3 Current Use of the Property

The property consists of approximately 2.25 acres and is developed with a three-story building with a rooftop penthouse constructed between 1979 and 1980. The building encompasses approximately 315,200 s quare feet and is currently occupied by Macy's. The first, second, and third floors consist of retail sales floors, stock/storage rooms, and offices. A portion of the third floor is currently unused and consists of various storage rooms and an employee lounge. The rooftop penthouse consists of a HVAC/boiler equipment room. Two loading docks are located at street level along Main Street. The property building is surrounded by concrete pavement and sidewalks.

3.4 Description of Property Improvements

The following table provides general descriptions of property improvements.

PROPERTY IMPROVEMENTS	
Size of Property (approximate)	2.25 acres
General Topography of Property	Sloped towards the west-northwest.
Adjoining and/or Access/Egress Roads	Main Street to the north, Court Street to the east and Martine Avenue to the south.
Paved or Concrete Areas (including parking)	Concrete loading and bay areas. Concrete sidewalks to the north, east, and south
Unimproved Areas	None
Landscaped Areas	Tree planers located along the surrounding street.
Surface Water	None
Potable Water Source	City of White Plains Department of Public Works
Sanitary Sewer Utility	City of White Plains Department of Public Works
Storm Sewer Utility	City of White Plains Department of Public Works
Electrical Utility	Consolidated Edison (Con Ed)
Natural Gas Utility	Con Ed
Current Occupancy Status	100%
Unoccupied Buildings/Spaces/Structures	Portion of the third floor is not used
Number of Occupied Buildings	One
Building Name or General Building Description	Macy's
Number of Floors	Three with rooftop penthouse
Total Square Feet of Space (approximate)	315,200 square feet.
Construction Completion Date (year)	1979-1980
Construction Type	Concrete and steel frame
Interior Finishes Description	Gypsum, acoustic ceiling tiles, carpet, wood flooring, vinyl floor tiles, bare concrete
Exterior Finishes Description	Masonry
Cooling System Type	Rooftop cooling tower
Heating System Type	Two gas-fired boilers

Emergency Power	One diesel-fired generator

3.5 Current Uses of Adjoining Properties

Current uses of the adjoining properties were observed to be as described in the following table.

Refer to Section 5.1.2 and Section 5.3 for specific details pertaining to regulatory agency database listings and historical uses of the adjoining properties.

CURRENT USES OF ADJOINING PROPERTIES				
Direction From Property	**Address**	**Occupant(s) Name**	**Current Use**	**Potential Environmental Conditions**
North	123-199 Main Street	Multi-family buildings with various commercial storefronts (Travel services, restaurants, and a vacant store)	Mixed Use	See Section 5.1 and Section 5.3
East	200-202 Main Street	Starbucks, paved courtyard	Commercial	None
East	19-37 Court Street	Restaurant and vacant commercial stores	Commercial	See Section 5.1.1 and Section 5.1.2
East	167-183 Martine Avenue	7-Eleven	Commercial	None
Southeast	168 Martine Avenue	Metro PCS	Commercial	None
South	110-111 Dr. Martin Luther King / 148 Martine Avenue	Westchester County Offices	Office	See Section 5.1.1 and Section 5.1.2
West	100 Main Street	Galleria Mall and Parking Garage	Retail	See Section 5.1.1 and Section 5.1.2

4.0 USER PROVIDED INFORMATION

The following section summarizes information (if any) provided by WP Galleria Realty LP (User) with regard to the Phase I ESA. Documentation may be found in Appendix D or where referenced in this report.

4.1 Title Records

User provided no title records information.

4.2 Environmental Liens or Activity and Use Limitations (AULs)

The User provided no information regarding property environmental liens or activity and use limitations (AULs). ATC contracted Environmental Data Resources, Inc. (EDR) to perform an environmental lien search for the property. According to EDR, no environmental liens or AULs (such as engineering controls, land use restrictions or institutional controls) were identified for the property. A copy of the report is included in Appendix L. The review of the environmental lien and AUL search did not identify past uses indicating *recognized environmental conditions* in connection with the property.

4.3 Specialized Knowledge or Experience of the User

The User provided no specialized knowledge or experience regarding *recognized environmental conditions* associated with the property.

4.4 Significant Valuation Reduction for Environmental Issues

The User provided no information regarding a significant valuation reduction for environmental issues associated with the property.

4.5 Owner, Property Manager, and Occupant Information

Mr. Tom Miles and Mr. Josh McCord of Galleria White Plains, were identified by the User as the property contacts. Mr. John DiMicelli of Macy's Inc. was the site escort.

4.6 Reason For Performing Phase I ESA

According to information provided by the User, this Phase I ESA will be used in connection with a commercial real estate transaction to identify *recognized environmental conditions* associated with the property.

4.7 Other User Provided Documents

Per the ASTM Standard Practice E 1527-13, ATC obtained the documents listed below from the User. Further discussion may be found in Section 5.3.9 and other relevant sections of this report.

OTHER USER PROVIDED DOCUMENTS		
Title	**Date (if known)**	**Author and/or Source (if known)**
Fuel Oil Tank Upgrade Project Report	April 25, 1997	Clayton Environmental Consultants, Inc.

5.0 RECORDS REVIEW

5.1 Standard Environmental Records

The regulatory agency database report discussed in this section, provided by EDR of Shelton, Connecticut, was reviewed for information regarding reported use or release of hazardous substances and petroleum products on or near the property. Unless otherwise noted, the information provided by the regulatory agency database report and other sources referenced in this report, were considered sufficient for *recognized environmental condition (REC)*, *controlled recognized environmental condition (CREC)*, *historical recognized environmental condition (HREC)* or *de minimis condition* determinations without conducting supplemental agency file reviews. ATC also reviewed the "unmappable" (also referred to as "orphan") listings within the database report, cross-referencing available address information and facility names. Unmappable sites are listings that could not be plotted with confidence, but are potentially in the general area of the property, based on the partial street address, city, or zip code. Any unmappable site that was identified by ATC as being within the approximate minimum search distance from the property, based on the site reconnaissance and/or cross-referencing to mapped listings, is included in the discussion within this section. The complete regulatory agency database report may be found in Appendix E.

SUMMARY OF FEDERAL, STATE AND TRIBAL DATABASE FINDINGS								
Regulatory Database	**Target Property**	**Search Distance (Miles)**	**< 1/8**	**1/8 - 1/4**	**1/4 - 1/2**	**1/2 - 1**	**> 1**	**Total Plotted**
National Priority List (NPL)		1	0	0	0	0	NR	0
Proposed National Priority List Sites (Proposed NPL)		1	0	0	0	0	NR	0
RCRA - Large Quantity Generators (RCRA-LQG)		0.25	2	3	NR	NR	NR	5
RCRA - Small Quantity Generators (RCRA-SQG)	X	0.25	0	4	NR	NR	NR	6
RCRA - Conditionally Exempt Small Quantity Generators (RCRA-CESQG)		0.25	4	4	NR	NR	NR	8
Engineering Controls Sites List (US ENG CONTROLS)		0.5	0	0	0	NR	NR	0
Sites with Institutional Controls (US INST CONTROL)		0.5	0	0	0	NR	NR	0
A Listing of Brownfields Sites (US BROWNFIELDS)		0.5	0	0	0	NR	NR	0
Toxic Chemical Release Inventory System (TRIS)		TP	NR	NR	NR	NR	NR	0
Toxic Substances Control Act (TSCA)		TP	NR	NR	NR	NR	NR	0
Integrated Compliance Information System (ICIS)		TP	NR	NR	NR	NR	NR	0
Facility Index System/Facility Registry System (FINDS)	X	TP	NR	NR	NR	NR	NR	7
EDR Exclusive Historical Auto Stations (EDR Hist Auto)		0.125	3	NR	NR	NR	NR	3
EDR Exclusive Historical Cleaners (EDR Hist Cleaner)		0.125	0	NR	NR	NR	NR	0
RCRA - Non Generators / No Longer Regulated (RCRA NonGen / NLR)	X	0.25	35	56	NR	NR	NR	94
EDR Exclusive Historical Cleaners (EDR Hist Cleaner)		0.125	3	NR	NR	NR	NR	3
EDR Exclusive Historical Auto Stations (EDR Hist Auto)		0.125	0	NR	NR	NR	NR	0
Enforcement & Compliance History Information (ECHO)	X	TP	NR	NR	NR	NR	NR	6

Regulatory Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Facility and Manifest Data (NY NY MANIFEST)	X	0.25	43	73	NR	NR	NR	120
Registered Drycleaners (NY DRYCLEANERS)		0.25	0	0	NR	NR	NR	0
Chemical Bulk Storage Database (NY CBS AST)		0.25	0	0	NR	NR	NR	0
Spills Information Database (NY LTANKS)		0.5	20	44	97	NR	NR	162
Spills Information Database (NY SPILLS)		0.125	49	NR	NR	NR	NR	50
Major Oil Storage Facility Site Listing (NY MOSF)		0.5	0	0	0	NR	NR	0
Recovered Government Archive Solid Waste Facilities List (NY RGA LF)		TP	NR	NR	NR	NR	NR	0
Chemical Bulk Storage Database (NY CBS UST)		0.25	0	0	NR	NR	NR	0
Voluntary Cleanup Agreements (NY VCP)		0.5	0	1	0	NR	NR	1
Storage Tank Facility Listing (NY TANKS)		0.25	0	0	NR	NR	NR	0
Manifest Information (NJ NJ MANIFEST)		0.25	17	21	NR	NR	NR	38
Facility Register (NY SWF/LF)		0.5	1	0	0	NR	NR	1
Hazardous Substance Waste Disposal Site Inventory (NY HSWDS)		0.5	0	0	0	NR	NR	0
Petroleum Bulk Storage (NY AST)		0.25	14	13	NR	NR	NR	27
Petroleum Bulk Storage (PBS) Database (NY UST)		0.25	13	34	NR	NR	NR	48
E DESIGNATION SITE LISTING (NY E DESIGNATION)		0.125	0	NR	NR	NR	NR	0
Brownfields Site List (NY BROWNFIELDS)		0.5	2	0	1	NR	NR	3
Inactive Hazardous Waste Disposal Sites in New York State (NY SHWS)		1	0	0	0	2	NR	2
Chemical Bulk Storage Site Listing (NY CBS)		0.25	0	0	NR	NR	NR	0
Voluntary Cleanup Program Listing NYC (NY VCP NYC)		0.5	0	0	0	NR	NR	0
Registry of Engineering Controls (NY ENG CONTROLS)		0.5	0	1	0	NR	NR	1
Registered Cooling Towers (NY COOLING TOWERS)	X	TP	NR	NR	NR	NR	NR	4

5.1.1 Federal Database Findings

The property was identified in the following federal agency databases reviewed:

Macy's White Plains Cogeneration / Macy's - White Plains
100 Main Street
White Plains, NY 10601

Databases: Resource Conservation and Recovery Act (RCRA) - Small Quantity Generator (SQG), Facility Index System (FINDS), Enforcement and Compliance History Online (ECHO), NY Manifest
Approximate Distance from the Property: Not Applicable (NA); Target Property (TP)
Assumed Groundwater Gradient: NA; TP
Regulatory Data Summary: The property is listed as a RCRA SQG of ignitable hazardous wastes (EPA waste code D001) as of 2007. The property was also listed as a RCRA SQG as of 2003. A compliance evaluation was performed on-site in 2011. A date of compliance is not reported. No other violations were reported. The FINDS and ECHO listings are administrative in nature and generally points to other database listings. Additionally, the property is also listed on the NY Manifest database and is likely associated with the property's RCRA listing discussed above. According to the Manifest listing, wastes were transported from the property in 2018
Discussion: Based on the administrative nature of these listings, ATC does not consider the federal agency listings to represent a *recognized environmental condition* at this time.

The following listing(s) with a known or significant potential for release and impact in, on, or at the property were identified in the federal agency databases researched:

The Picture People
100 Main Street, Space 329
White Plains, NY 10603
Databases: RCRA-SQG, FINDS, ECHO
Approximate Distance from the Property: Adjacent to the west
Assumed Groundwater Gradient: Down-gradient
Regulatory Data Summary: This facility was listed as a RCRA SQG of hazardous wastes between 2000 and 2007. The 2000 listing notes silver hazardous wastes (EPA waste code: D011). A written informal notice was received which achieved compliance in 2001. The FINDS and ECHO listings are administrative in nature and generally points to other database listings.
Discussion: Based on the compliance with the historical violation, ATC does not consider the federal agency listings to represent a *recognized environmental condition* to the property at this time.

Expressly Portraits
100 Main St. Galleria Mall
White Plains, NY 10603
Databases: RCRA Non Generator (NonGen) / No Longer Regulated (NLR), FINDS, ECHO
Approximate Distance from the Property: Adjacent to the west
Assumed Groundwater Gradient: Down-gradient
Regulatory Data Summary: This facility was listed as a non-generator of hazardous waste in 2006 and 2007. Historically, this facility was listed as a RCRA SQG of silver hazardous wastes in 1994. A written informal notice was received which achieved compliance in 1997. The FINDS and ECHO listings are administrative in nature and generally points to other database listings.
Discussion: Based on the compliance with the historical violation, ATC does not consider the federal agency listings to represent a *recognized environmental condition* to the property at this time.

C P I Photo Finish
100 Main Street, Suite 301
White Plains, NY 10603
Databases: RCRA-NonGen / NLR, FINDS, ECHO
Approximate Distance from the Property: Adjacent to the west
Assumed Groundwater Gradient: Down-gradient
Regulatory Data Summary: This facility was listed as a non-generator of hazardous waste in 1999. Historically, this facility was listed as a RCRA SQG of silver hazardous wastes in 1997. No violations were reported. The FINDS and ECHO listings are administrative in nature and generally points to other database listings.
Discussion: Based on the absence of reported violations, ATC does not consider the federal agency listings to represent a *recognized environmental condition* to the property at this time.

J C Penny Co. Inc.
100 Main Street
White Plains, NY 10603

Databases: RCRA-NonGen/NLR
Approximate Distance from the Property: Adjacent to the west
Assumed Groundwater Gradient: Down-gradient
Regulatory Data Summary: This facility was listed as listed as a non-generator of hazardous wastes as of 2006. Historically, the facility was listed as a RCRA SQG of corrosive hazardous wastes (EPA waste code: D001) in 1994. No violations were reported.
Discussion: Based on the absence of reported violations, ATC does not consider the federal agency listings to represent a *recognized environmental condition* to the property at this time.

Westchester County Office Bldg
148 Martine Avenue
White Plains, NY 10603
Databases: RCRA Conditionally Exempt Small Quantity Generator (CESQG)
Approximate Distance from the Property: Adjacent to the south, beyond Martine Avenue
Assumed Groundwater Gradient: Cross-gradient
Regulatory Data Summary: This facility was listed as a RCRA CESQG of hazardous wastes in 2007. Historically, the site was listed as a RCRA SQG of ignitable hazardous wastes in 1989, and was verified as a non-generator in 1991 and 2006. Notices of violations were issued in 1989 and 1999 for a non-financial record evaluation and two compliance inspections. One of the compliance violations achieved compliance and the other two are not reported. Refer to Section 5.1.2 below for additional state agency database listings associated with this site.
Discussion: Based on the description of the reported violation and the inferred groundwater gradient relative to the property, ATC does not consider the federal agency listing to represent a *recognized environmental condition* to the property at this time.

Various adjacent site address listings or listings in adjacent roadways were identified in the RCRA databases associated with Con Edison manholes, service boxes, below-ground vaults, or surface roadways. Based on the limited nature of these listings and the absence of reported violations and spills cases, ATC concludes that the adjacent site listings or listings in adjacent roadways in the RCRA databases do not represent r*ecognized environmental conditions* to the property.

Based on distance, topography, assumed groundwater gradient, current regulatory status, and/or the absence of reported releases, none of the other sites listed in the federal agency databases searched are considered to represent a likely past, present or material threat of release in, on, or at the property. Given the physical setting characteristics of the property and surrounding area, supplemental agency file reviews were not warranted to verify the database report information.

5.1.2 State and Tribal Database Findings

The property was identified on the state and/or tribal databases reviewed:

A&S
100 Main Street
White Plains, NY
Databases: Leaking Tanks (LTANKS)
Approximate Distance for the Property: Not Applicable (NA)
Assumed Groundwater Gradient: NA
Regulatory Data Summary: A&S, a former retail tenant of the property was identified on the LTANKS database with Spill No. 8803673 that was opened on July 27, 1988 when a 10,000-gallon failed a tank tightness test. A No Further Action (NFA) determination was issued by the NYSDEC and the spill case was closed on August 9, 1988. Additionally, Spill No. 8805571 was opened on September 29, 1088 when a 10,000-gallon tank identified as Petroleum Bulk Storage (PBS) No. is 173665 failed a tank tightness test. The tank was relined and put back into service. This LTANKS case was closed on March 7, 1989.
Discussion: Based on the database description revealing no evidence of an actual release, coupled with ATC's review of the Underground Storage Tank (UST) closure report indicating the above mentioned tanks were properly closed in accordance with all applicable regulations, ATC does consider these historical LTANKS listings to represent a *recognized environmental condition.* Refer to Section 5.3.9 for pertinent details associated with the on-site USTs.

The following listing(s) with a known or significant potential for release and impact in, on, or at the property were identified in the state and tribal databases researched:

Wyassup-Laurel Glen Corp / Office Bldg / Drain - Cooking Grease
175 Main Street
White Plains, NY 10603
Databases: NY Aboveground Storage Tank (AST), NY Spills
Approximate Distance from the Property: Adjacent to the north, beyond Main Street approximately 43 feet
Assumed Groundwater Gradient: Cross-gradient
Regulatory Data Summary: This facility is listed on the AST database with one 5,000-gallon "in-service" AST containing No. 6 fuel oil that was installed in March 2000. Spill Case No. 9910497 was generated on December 2, 1992 due to a report of an oil-like substance observed on the ground. The site was inspected and no spill was observed. The spill case achieved regulatory closure the same day. Spill No. 1511825 was generated on March 12, 2016 due to the dumping of cooking grease into storm drains. The case was forwarded to the county Health Department and the case was closed on April 11, 2016.
Discussion: Based on the description and regulatory closure of the spill cases by the NYSDEC and the inferred groundwater gradient, ATC does not consider these state agency listings to represent a *recognized environmental condition* to the property at this time.

Last Call NY Inc/DBA - Vintage Bar / Vintage Restaurant
171-173 Main Street
White Plains, NY 10603
Databases: NY UST, NY Spills, NY (LTANKS), NY Manifest
Approximate Distance from the Property: Adjacent to the north, beyond Main Street, approximately 43 feet
Assumed Groundwater Gradient: Cross-gradient
Regulatory Data Summary: This facility is listed on the UST database with one 1,500-gallon UST "closed-removed" in 2006. The former restaurant is also listed on the LTANKS database under Spill No. 0602861 due to a tank test failure of the 1,500-gallon UST, reported to the department on June 14, 2006. According to the listing, the tank had been emptied, cleaned, and removed and corrosion and numerous holes were observed. Two monitoring wells were installed and a subsequent investigation in March, 2007 did not identify free product. 2.64 tons of contaminated soil were reportedly removed from the site and the spill case achieved regulatory closure in September, 2008.
Discussion: Based on the database descriptions, inferred groundwater gradient, and regulatory closure of the spill case by the NYSDEC, ATC does not consider these state agency listings to represent a *recognized environmental condition* to the property.

Court & Martine 2009 LLC.
39-55 Court St. / 167-183 Martine Ave.
White Plains, NY 10603
Databases: NY AST
Approximate Distance from the Property: Adjacent to the north, beyond Main Street, Approximately 55 feet
Assumed Groundwater Gradient: Cross-gradient
Regulatory Data Summary: This facility is listed on the AST database with one 2,000-gallon "in-service" AST containing No. 2 fuel oil and installed in 1991. No releases have been reported.
Discussion: Based on the absence of reported releases, ATC does not consider this state agency listing to represent a *recognized environmental condition* to the property.

J.C. Penney Co. Inc.
100 Main Street
White Plains, NY 10603
Databases: NY Underground Storage Tank (UST), NY Spills, NY LTANKS, NY Manifest
Approximate Distance from the Property: Adjacent to the west, approximately 211 feet
Assumed Groundwater Gradient: Down-gradient
Regulatory Data Summary: J.C. Penny is listed on the UST database with one 8,000-gallon UST "closed-in-place" in 1999, one 100-gallon "Tank converted to Non-Regulated use" UST in 1979, and one 1,000-gallon "Tank converted to Non-Regulated use" UST in 1996. The facility is listed on the LTANKS

database due to a spill of 20 gallons of fuel oil on June 10, 1991 resulting from the overfill of a tank. According to the listing, the release was contained on the sidewalk and the case was closed on June 13, 1991. The NY Spills database lists Spill No. 9204133 due to oil that was discovered in a basement sump of the J.C. Penney Department Store during a repair of the sump pump, reported on July 10, 1992. The sump was reportedly vacuumed and the material disposed of by Luzon. This spill case achieved regulatory closure on August 4, 1992. Spill No. 0302779 was generated due to a spill of 20 gallons of hydraulic oil resulting from a subject stuck in an area, reported on June 16, 2003. The Fire Department was on scene and the case was closed the same day. Spill No. 0211359 was generated on February 13, 2003 and reportedly involved approximately 40 gallons of petroleum due to a surface spill from a vehicle. This case achieved regulatory closure on February 27, 2005. Spill No. 0703055 was generated when a person dumped less than one gallon of gas into a storm drain, reported on June 13, 2007. This spill achieved regulatory closure on June 14, 2007. According to the manifest listing, hazardous wastes were transported from the site in 1994,
Discussion: Based on the regulatory closure of the spill cases by the NYSDEC, ATC does not consider these state agency listings to represent a *recognized environmental condition* to the property.

I/F/O The Melting Pot
35 Court Street
White Plains, NY 10603
Databases: NY Spills
Approximate Distance from the Property: Adjacent to the east, beyond Court Street, approximately 215 feet
Assumed Groundwater Gradient: Up-gradient
Regulatory Data Summary: This facility is listed on the NY Spills database under Spill Case No. 1000201 due to cooking grease spilling onto the street and into storm drains, reported on April 6, 2010. According to the listing, the case was forwarded to the county Health Department, and No Further Action (NFA) was determined due to the nature of the spill (i.e. non-petroleum). The spill case achieved regulatory closure the same day.
Discussion: Based on the regulatory closure and nature/description of the spill, ATC does not consider this state agency listing to represent a *recognized environmental condition* to the property.

Minskoff Management
39-47 Court Street
White Plains, NY 10603
Databases: NY Spills
Approximate Distance from the Property: Adjacent to the east, beyond Court Street,
approximately 216 feet
Assumed Groundwater Gradient: Up-gradient
Regulatory Data Summary: This facility is listed on the NY Spills database under Spill Case No. 9110040 due to an odor and No. 2 fuel oil observed on the concrete floor, reported on December 20, 1991. According to the listing, cleanup ceased in January, 1992 and the spill case achieved regulatory closure on March 10, 1992.
Discussion: Based on the regulatory closure of the spill by the NYSDEC, ATC does not consider this state agency listing to represent a *recognized environmental condition* to the property.

Michael E Land Office Bldg / Westchester County Office Bldg / Railroad One LF
148 Martine Avenue
White Plains, NY 10603
Databases: NY AST, NY UST, NY Spills, NY LTANKS, NY Manifest, NY Solid Waste Facilities/Landfill Sites (SWF/LF), NY Financial Assurance, NY Spills
Approximate Distance from the Property: Adjacent to the south, beyond Martine Avenue, approximately 55 feet
Assumed Groundwater Gradient: Cross-gradient
Regulatory Data Summary: This office building is identified on the NY AST database with one 25-gallon "in-service" AST containing diesel fuel and installed in 1998, one 2,000-gallon "in-service" AST containing diesel fuel and installed in 2005, one 300-gallon "in-service" AST containing diesel fuel and installed in 2001, and one 338-gallon "in-service" AST containing diesel fuel and installed in 2008. This facility is also identified on the NY UST database with one 1,500-gallon UST that was installed in 1972 and "closed-in-place" in 2002. The product stored is not reported. Additionally, one 30,000-gallon UST was installed in 2003 and

administratively closed in 2004. The product stored is not reported. One 3,000-gallon "in-service" diesel UST was installed in 1998, one 5,000-gallon diesel UST was "administratively closed" in 2004, one 10,000-gallon and one 6,000-gallon UST were "administratively closed" in 2004 and 2005 (products stored were not reported), and two 3,000-gallon "in-service" gasoline USTs installed in 1991.

The office building is listed on the NY Spills database under Spill Spill No. 8900947, which was generated due to approximately 15 gallons of gasoline that had spilled to concrete during a delivery on May 1, 1989. According to the listing, the spill was cleaned and the case was closed on July 25, 1989. Spill No. 9103040 was generated due to contamination that was found during the removal of tanks and was reported to the Westchester County Department of Health (WCDOH) on June 12, 1991. According to the listing, the contaminated soils did not meet NYSDEC requirements and soils should be stockpiled on plastic and removed. No additional details were reported and the spill case achieved regulatory closure on June 18, 1991. Spill No. 9202919 was generated due to a gasoline spill reported to the department on June 10, 1992. According to the listing, the spill was contained on the sidewalk, cleaned with speedi-dry, and the spill case was closed on July 13, 1992. Spill No. 0109874 was generated on January 11, 2002 due to a tank test failure with material that had leaked within a containment. The spill case was closed on January 14, 2002. Additionally, the facility was listed on the LTANKS database under Spill No. 0301426 was generated due to a tank overfill on May 8, 2003. According to the listing, the spill was cleaned and the case was closed the same day. Additional NY Spills listings include Spill No. 0412020 that was generated on February 10, 2005 due to equipment failure and cleanup conducted in a paved parking lot. According to the listing, tank testing was required. No additional details were reported and the spill case was closed on December 18, 2008. Lastly, Spill No. 0503295 was generated on June 17, 2005 due to a tank overfill. According to the listing, no further remediation was required and the case was closed on September 26, 2005. According to the manifest listing, wastes were transported from the site in 2010.

Railroad One LF is listed on the NY SWF/LF database as an "inactive" solid waste facility under the owner name Westchester County DPW. The NY Financial Assurance database ensures that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.
Discussion: Based on the database descriptions, inferred groundwater gradient, and regulatory closures of the spill cases, ATC does not consider these state agency listings to represent a *recognized environmental condition* to the property at this time.

DPW Vehicle / The Michicallian Office
Martine Avenue and Court Street
White Plains, NY 10603
Databases: NY Spills, NY LTANKS
Approximate Distance from the Property: Adjoining intersection to the southeast
Assumed Groundwater Gradient: Cross-gradient/Up-gradient
Regulatory Data Summary: The adjoining intersection to the southeast is listed on the NY LTANKS database under Spill No. 8905963 due to a tank overfill on September 18, 1989. According to the listing, the Fire Department was on scene and the spill case was closed on November 29, 1989. Spill No. 9310783 was generated due to oil discovered during a tank pull, reported to the department on November 16, 1993. According to the listing, 77.98 ton of soil was removed in 1993. The spill case was subsequently closed on November 18, 1993. The adjoining intersection to the southeast is also listed on the NY Spills database under Spill No. 1305831 due to a spill of hydraulic oil in the roadway reported to the department on September 3, 2013. According to the listing, cleanup was completed and no drains were impacted. The spill case achieved regulatory closure on October 7, 2013.
Discussion: Based on the database descriptions and regulatory closures of the spill cases by the NYSDEC, ATC does not consider these state agency listings to represent a *recognized environmental condition* to the property.

Residence
185-187 Main Street
White Plains, NY 10603
Databases: NY LTANKS
Approximate Distance from the Property: Adjacent to the north, beyond Main Street, approximately 107 feet
Assumed Groundwater Gradient: Cross-gradient

Regulatory Data Summary: The adjacent residence to the north is listed on the NY LTANKS database under Spill No. 9708138 due to contaminated soil discovered during a tank removal beneath the sidewalk that was reported to the department on October 9, 1997. According to the listing, all contaminated material was removed and the spill case was closed on November 10, 1997.
Discussion: Based on the regulatory closure of the spill case, ATC does not consider this state agency listing to represent a *recognized environmental condition* to the property.

Based on distance, topography, assumed groundwater gradient, current regulatory status, and/or the absence of reported releases, none of the other sites listed in the state and tribal databases searched are considered to represent a likely past, present or material threat of release in, on, or at the property. Given the physical setting characteristics of the property and surrounding area, supplemental agency file reviews were not warranted to verify the database report information.

5.1.3 Local Environmental Record Sources

New York State Department of Environmental Conservation (NYSDEC)

The NYSDEC maintains files of incidents involving environmentally regulated materials. The records maintained by the NYSDEC include reports of spills of hazardous chemicals and citizen complaints on environmental issues. NYSDEC information concerning the property was requested under the Freedom of Information Law (FOIL). ATC has not received a response from the NYSDEC at the time this report was issued. ATC will issue an addendum to this report if additional information received warrants modifications to the conclusions included herein.

Westchester County Department of Health (WCDOH)

ATC submitted an online FOIL request to the Westchester County Department of Health on March 22, 2019 in an effort to obtain records pertaining to the property. ATC has not received a response from the Westchester County Department of Health at the time this report was issued. ATC will issue an addendum to this report if additional information received warrants modifications to the conclusions included herein.

City of White Plains Clerk's Office

ATC submitted an online request to the Clerk's Office to obtain information concerning the property and surrounding areas. A response dated, March 9, 2019 indicated no responsive records were found.

City of White Plains Building Department

ATC submitted an online request to the Commissioner of Buildings to obtain information concerning the property. A response dated, March 9, 2019 indicated no responsive records were found.

Electrical and Natural Gas Utility Company

According to the property engineer, Con Ed provides the electric and natural gas services to the property.

Water Utility

The City of White Plains Department of Public Works provides the potable water utilities to the property. According to the City of White Plains Department of Public Works Annual Drinking Water Quality Report for 2017, one hundred percent of the water delivered by the City of White Plains is purchased from The New York City Department of Environmental Protection (NYCDEP) through Westchester County Water District No. 1. The raw water purchased from New York City is drawn from the Kensico Reservoir, which is an unfiltered surface water source. Review of the analytical data provided in the report confirmed that the municipally supplied water meets all drinking water standards established by the EPA Safe Drinking Water Act, including those for lead.

Sewer Utility

The City of White Plains Department of Public Works operates and maintains a separate wastewater system for the City of White Plains. According to the Westchester Geographic Information Systems (GIS) map, the property is located within the Bronx Valley sewer district, where sewage is pumped and treated at the Yonkers Joint Treatment Plant.

Other Local Environmental Records Sources

No additional local environmental records sources were reviewed.

5.2 Physical Setting Sources

5.2.1 Topography

Based on the United States Geological Survey (USGS) 7.5-Minute Series Topographic Map, White Plains Quadrangle, dated 2013, the property is located between 200 and 220 feet above mean sea level (MSL). The property is slightly sloped toward the west-northwest. A copy of the topographic map is included in Appendix A.

5.2.2 Geology

According to the USDA *Soil Survey of Westchester County,* the City of White Plains lies within the New England uplands physiographic province. The New England uplands area is geologically complex and exhibits moderate relief. Westchester County is largely underlain by a heavily metamorphosed complex of Precambrian and Paleozoic sedimentary and igneous rocks subjected to a high degree of metamorphism.

5.2.3 Soils

According to USDA Natural Resource Conservation Services Web Soil Survey, the soils beneath the Property are classified as Urban land. Urban land refers to soils that have been altered by urban development such as buildings and streets, where at least 85 percent of the surface is covered with asphalt, concrete or other impervious building material. Typically, these soils have been mixed with other materials, such as brick and concrete, and characteristics can only be determined by on-site investigation.

5.2.4 Hydrology

No past groundwater investigations have been identified for the property; thus, no site-specific groundwater information was available. However, regional groundwater flow direction is generally influenced by major hydrogeologic features such as a river or lake. Surface and/or bedrock topography may also influence regional groundwater flow direction. Based on a review of the *White Plains, NY* USGS topographic map, the presumed local groundwater flow direction is to the west-northwest. Therefore, in assessing potential external environmental impact, properties located east-southeast (presumed up-gradient) of the property are of primary concern. It should be noted that local geologic features may cause local groundwater flow direction to differ from the regional flow direction. A complete hydrogeologic investigation would be necessary to determine groundwater flow direction.

Estimated groundwater levels and/or flow direction(s) may vary due to seasonal fluctuations in precipitation, local usage demands, geology, underground structures, or de-watering operations.

5.2.5 Other Physical Setting Sources

Wetlands

ATC reviewed the United States Department of Interior, Fish and Wildlife Service (USFWS) National Wetlands Inventory (NWI) Wetlands Mapper, for information regarding wetlands on the property. According to the NWI map, no wetlands or portions of wetlands are located on the property. A copy of the National Wetlands Inventory map is included in Appendix L.

Floodplains

ATC reviewed the National Flood Insurance Program, Flood Insurance Rate Map (FIRM), to determine if the property is located within a floodplain. According to the FIRM, Community Panel Number 36119C0267F, the property is not located within the 100-year or the 500-year flood zones. Refer to Appendix L for a copy of the FIRM.

5.3 Historical Records Sources

The table presented below summarizes the findings of the research pertaining to historical property and surrounding area uses.

The property was developed with a court house and jail, first seen in the 1885 Sanborn map. According to this map, the court house underwent several additions, including court rooms and record halls that were built between 1893 and 1928. The Westchester County courthouse facility consisting of multiple buildings occupied the property until at least 1962. The existing retail mall was developed between 1979 and 1980. Area usage was primarily developed with various office buildings, stores, hotels, and residential buildings between 1885 and 1930. Beginning in at least 1950, the surrounding areas are increasingly developed with commercial, office, and retail uses. Of note, several journal and photo printing shops were located adjacent to the west, north, and east from at least 1885 to 2010.

Intervals (greater than five years) were encountered during the research of historical use information for the property and surrounding area. However, based on the review of reasonably ascertainable historical sources, these intervals did not have an impact on the *recognized environmental condition* determinations of this assessment and are not significant data gaps.

HISTORICAL USE SUMMARY				
Period	**Property Historical Uses**	**Surrounding Area Historical Uses**	**Source(s)**	**Intervals/Comments**
Prior to 1940	Westchester County Court House	Mixed-use	Fire Insurance Maps Topographic Maps	Data gaps identified: 1905-1911 and 1911-1930
1940 - 1960	Westchester County Court House	Mixed-use	Fire Insurance Maps Topographic Maps Aerial Photographs	No data gaps identified
1961 - 1980	Galleria Mall (1979-1980)	Mixed-use	Fire Insurance Maps Topographic Maps Aerial Photographs City Directories	Data gaps identified: 1979-1985
1981 - 2000	Galleria Mall	Mixed-use	Fire Insurance Maps Topographic Maps Aerial Photographs City Directories Zoning Department Tax Files	No data gaps identified
2001 - present	Galleria Mall	Mixed-use	Fire Insurance Maps Topographic Maps Aerial Photographs City Directories	No data gaps identified

5.3.1 Aerial Photographs

ATC reviewed available aerial photographs of the property and surrounding area obtained from EDR. Available aerial photographs ranged from 1941 to 2017. The following table includes descriptions and interpretations from the aerial photograph review. Copies of reproducible aerial photographs are included in Appendix F.

The property appears developed with a multi-story commercial-type building on the north portion, and six low-rise commercial-type structures on the south portion in the 1941 and 1953 photographs. Beginning in the 1958 photograph, and until 1974, one of the central low-rise buildings is no longer depicted and the area

now appears to be utilized as a parking lot. The existing property building within the Galleria Mall is first seen developed in the 1985 photograph, and appears unchanged until the 2017 photograph.

The surrounding areas in all directions are depicted with dense urban development. In the the 1971 photograph, widespread demolition activities appear to be depicted to the west of the property. In 1974, this area is depicted with what appears to be several paved and unpaved parking lots with parked cars. One multi-story commercial-type structure is depicted to the west-southwest. Areas further west of the property appear to be cleared for redevelopment. Low-rise commercial-type structures are depicted to the east, and several high-rise mixed-use buildings are depicted to the north and south. The existing Galleria Mall is first seen developed in the 1985 photograph. The surrounding areas to the north, east, and south are depicted with high- and low-rise commercial-type structures in the 1985 through 2017 photographs.

The review of aerial photographs did not identify past uses indicating *recognized environmental conditions* in, on, or at the property or surrounding area.

5.3.2 Fire Insurance Maps

A search for fire insurance maps for the property and surrounding area was conducted by EDR. The following are descriptions and interpretations from the fire insurance map reviews. Documentation is included in Appendix G.

FIRE INSURANCE MAP SUMMARY		
Year	**Property Comments**	**Surrounding Area Comments**
1885	The property is depicted with the Westchester County Court House on the central portion and a jail on the southern portion. Grand Street is depicted along the west portion of the property boundary. An artesian well and a shed are depicted on the southeast portion of the property. The northern-most portion is undeveloped.	The surrounding area to the north is depicted with Railroad Ave, beyond which are various two-story commercial and residential buildings including a hotel, low offices, and a candy store. The area to the east is depicted with Court St., beyond which is a bank, dwellings, a school, and an associated engine house. Martine Ave. is depicted to the south, beyond which appears to be not printed. The adjoining areas to the south are depicted with two-story various dwellings, law offices, and a journal printing shop.
1889	The property appears relatively unchanged from the 1885 map with the exception two gas-fired boilers are depicted within the Court House and the artesian well is no longer present.	The surrounding area to the north is depicted with several offices, a "repairing shop" and a hotel. The area to the east, beyond Court St. is depicted with a bank, a hotel, a restaurant, a dwelling, and a school. The surrounding areas to the south appear relatively undeveloped with the exception of one dwelling beyond Martine Ave. The adjacent area to the east is unchanged from the 1885 map.
1894	The property appears relatively unchanged from the 1889 map with the exception of an addition to the court house built in 1893, utilized as a Hall of Records.	The surrounding areas appear relatively unchanged from the 1889 map. Additional dwellings are depicted to the south, beyond Martine Ave. The adjacent bank to the east is also labeled with laundry offices.

Year	Property Comments	Surrounding Area Comments
1900	The property appears unchanged from the 1894 map.	The surrounding areas appear relatively unchanged from the 1894 map. The area to the north is depicted with various offices, a barber, a dwelling, a hotel, and a furniture store. The area to the east is depicted with a bank, a hotel, an office building, a dwelling, a carpenter house, and a school. The area to the west is now depicted with various office buildings, a cafe, the journal printing shop, and various dwellings.
1905	The property appears relatively unchanged from the 1894 map. The south portion of the jail is labeled as a bake shop.	The surrounding areas appear relatively unchanged from the 1900 map. The area to the north is depicted with a paints store and other various stores, as well as a hotel. The area to the east is now depicted with the bank, hotel, construction house, a library, and a school. The area to the west is now depicted with a Westchester & Bronx Title & Mortgage Guaranty Co., the Gutherland Building, the Westchester County Republican Committee building, an alley, a cafe, Union H&L Co. Village Rooms, the police headquarters, and four dwellings.
1911	The court house is now depicted with additions on the east and west ends of the property The additions are labeled the new hall of records and the supreme court building.	The surrounding areas appear relatively unchanged from the 1905 map with the exception the adjacent are to the north is increasingly developed with multi-story stores and offices including the Eastern State Journal building, the Realty Building, and a store with laundry services on the basement level. The Court Square Theater is depicted to the northeast, beyond Main Street. The adjacent area to the east appears relatively unchanged with the exception one of the office buildings is now labeled Barnum Offices Printing. The adjacent area to the southeast, beyond the intersection of Court Street and Martine Avenue, redeveloped with various two-story stores labeled the White Plains Club. The adjacent area to the south consists of two vacant, undeveloped lots. The adjacent area to the west appears relatively unchanged with the exception a Fire Department and bowling alley are now depicted.

Year	Property Comments	Surrounding Area Comments
1930 1942	The property is depicted with another addition on the north portion of the property, built in 1916. Another addition to the court house was built in 1928 and is located on the southwest corner of the property. The court house now consists of various court rooms, clerk buildings, records building, the jail. and a bakery. A boiler room with three steam boilers is located in the central portion of the property.	The adjacent area to the north is now depicted as court buildings and various stores. The adjacent area to the east is depicted with a drug store, an office building, a vacant undeveloped lot, a store, a hotel, and the bureau of motor vehicles. The adjacent area to the southeast is now labeled as stores and bowling. The adjacent area to the south is now developed with various two-story stores and offices, including automotive sales and the Westchester County Republican Committee, beyond which is an automotive repair shop. The adjacent area to the west appears unchanged.
1950	The property appears unchanged from the 1942 map.	The surrounding areas are depicted with commercial stores, restaurants, and office buildings. Three dwellings remain depicted to the west.
1987 1989 1990 1992 1993 1994 1995 2002 2003 2004	The property is now depicted with the existing Galleria Mall, built between 1979 and 1980. The property is depicted as a three- and four-story building with basement. One elevator is depicted.	The adjacent area to the north is depicted with an office building, a beauty school, a court building, a vacant building, and a two-tenant store. The bank to the east now depicted as an undeveloped park, with a small commercial building built in 2004. Remaining areas to the east are depicted with single-story commercial stores. The adjacent area to the south is redeveloped with a three-story office building and parking. The adjoining area to the west is depicted with the Galleria Mall and open deck parking garage.

The property is depicted as the Westchester County Court House with a jail in the 1885 Sanborn map. Various additions, including court rooms and record halls, were built between 1893 and 1928. The court house and associated buildings were demolished sometime between 1950 and 1979, when the property was redeveloped with the existing retail Mall structure in 1979 and 1980.

The surrounding areas were primarily depicted with residences, stores, hotels, schools, banks, and office buildings between 1885 and and 2004. Increased urban developed is depicted in the 1911 and 1930 maps. The historical uses of the adjacent areas to the south with an automotive sales and repair shop in 1930, to the west with a printing shop between at least 1885 and 1911, and to the east with a printing shop in 1911 are not considered an environmental concern give the surrounding areas were redeveloped with large commercial buildings beginning in the 1942 map.

The review of fire insurance maps did not identify past uses indicating *recognized environmental conditions* in, on, or at the property or surrounding area.

5.3.3 Property Tax Files

According to the 2018 and 2019 Final Assessment Rolls for the City of White Plains, the current owner of the property is identified as A & S Galleria R.E. Inc. ATC was able to review a historical deed at the Office of the Westchester County Clerk, Westchester Records Online. The previous owner was identified as Federated Department Stores Inc. prior to 1989. No other historical tax file information was readily available for review.

The review of tax files did not identify past uses indicating *recognized environmental conditions* in, on, or at the property or surrounding area.

5.3.4 Recorded Land Title Records

The acquisition of recorded land title records was not required by the scope of work for the Phase I ESA.

5.3.5 Historical USGS Topographic Maps

ATC reviewed reasonably ascertainable historical USGS Topographic Maps for information regarding past uses of the property obtained from EDR. The topographic maps were dated 1892, 1893, 1899, 1902, 1932, 1938, 1944, 1947, 1957, 1960, 1967, 1971, 1979, 1994, 2012, and 2013. The 1892 through 1902 topographic maps depict the property as developed, however specific property improvements could not be determined. The 1932 through 2013 topographic maps reviewed identify the property and the surrounding area as densely developed urban land. The review of historical USGS Topographic Maps did not identify past uses indicating *recognized environmental conditions* at the property or surrounding area. Documentation is included in Appendix G.

5.3.6 City Directories

Research regarding the availability of historical city directories was obtained from EDR. The following are descriptions and interpretations from the historical city directory review. Documentation is included in Appendix G.

The primary property address, 100 Main Street, was listed with various Galleria Mall tenants in the 1972 though 2014 city directories. The review of historical Sanborn maps identifies the former property address as 166 Main Street from at least 1930 until the property was redeveloped with the existing Galleria Mall in 1979 and 1980. The Westchester County Court House, a private listing, and passport info are listed under this address in the 1972 and 1977 city directories. Beginning in the 1982 city directory, Abraham & Straus is listed under 100 Main Street, and Macy's is listed in 2000 and 2014.

The cross streets to the east, south, and west (Court Street and Martine Avenue) are not listed in any of the city directories reviewed. The adjacent areas to the north, beyond Main Street, include 125-199 Main Street, and are listed with various commercial stores and offices including a furniture store, a beauty store/institution, various law/attorney offices, a taxi service, municipal court buildings, an airlines office, and photo, typewriting, and reporting companies between 1972 and 2014. A computer factory is listed under 169 Main Street in the 1987 city directory, and in 1992 a travel service is listed. A photo shop is listed under 175 Main Street in the 1972 through 2010 city directories. Between 1992 and 2014, the surrounding areas to the north are generally listed with restaurants, law offices, and banks.

The review of city directories did not identify past uses indicating *recognized environmental conditions* in, on, or at the property surrounding areas.

5.3.7 Building Department Records

ATC contacted the White Plains Building Department for reasonably ascertainable historical building department records. As of the date this report was prepared, ATC has not received a response. ATC will notify the client if additional information received warrants modifications to the conclusions included herein. ATC also attempted to obtain building department records from EDR; however, no records were identified. Documentation is included in Appendix G.

5.3.8 Zoning/Land Use Records

According to the City of White Plains Maps, Plans & Zoning website, the property is located in zone B-6, designated as "Enclosed Mall." The property as been zoning B-6 since at least 1981, according to a City of White Plains Zoning Map, dated June 1981, last amended in August 2015, and revised in February 2016. According to the Westchester County GIS map, the property's land use is Commercial and Retail. Documentation is included in Appendix G.

The review of historical zoning/land use records did not identify past uses indicating *recognized environmental conditions* in, on, or at the property or surrounding area..

5.3.9 Prior Reports

The following provides a summary of information gleaned from prior reports made available to or obtained by ATC for review.

"Fuel Oil Tank Upgrade Project Report, Tank Closure and Installation at Macy's Department Store Galleria Mall, 100 Main Street White Plains, New York" prepared by Clayton Environmental Consultants, Inc., and dated April 25, 1997.

The following is a summary of activities that occurred during the removal of two USTs and installation of an AST that occurred in 1997 on the property:

- Two 10,000-gallon USTs were installed in 1979 on a concrete pad below the loading dock area, were constructed of steel, and were closed-in-place in January 1997. The USTs were reportedly in good condition with no evidence of past or present petroleum leaks noted during field activities. The tanks were cleaned out and filled with a concrete slurry to grade level. Vent lines and other openings were also filled with concrete;
- Clayton contracted subcontractors to install one 1,000-gallon AST and associated piping. The AST is of steel construction and equipped with an alarm and a 1,100-gallon secondary containment dike;
- In addition to the two 10,000-gallon USTs, tank registration permits also identified one 100-gallon AST containing heating oil and installed in 1979. The property's PBS No. is 3-173665. This AST is likely the existing 100-gallon diesel day tank associated with the generator.

Clayton Environmental indicated that final permits from NYSDEC and White Plains Building Department were obtained following the completion of work. Clayton Environmental reported that no further action was required regarding the tank system at the property.

The review of prior reports did not identify past uses indicating *recognized environmental conditions* in, on or at the property or surrounding area. Documentation is included in Appendix H.

ATC makes no warranty, guarantee or certification regarding the quality, accuracy or reliability of any prior report provided to ATC and discussed in this Phase I ESA report. ATC expressly disclaims any and all liability for any errors or omissions contained in any prior reports provided to ATC and discussed in this Phase I ESA report.

5.3.10 Other Historical Sources

No other historical sources were reviewed.

6.0 SITE RECONNAISSANCE

The following is a summary of visual and/or physical observations of the property on the day of the site visit. Photographs can be found in Appendix C.

6.1 Methodology and Limiting Conditions

Ms. Chelsea Helm of ATC conducted the site reconnaissance on April 2, 2019 and was escorted by Mr. John Dimicelli, Facilities Director with Macy's, Inc. The site reconnaissance consisted of visual and/or physical observations of: the property and improvements; adjoining sites as viewed from the property; and, the surrounding area based on visual observations made during the trip to and from the property. Unimproved portions of the property (if any) were observed along the perimeter and in a general grid pattern in safely accessible areas, if accessible and possible. Building exteriors (if any) were observed along the perimeter from the ground, unless described otherwise. Building interiors (if any) were observed as they were made safely accessible, unless described otherwise. Weather at the time of the site reconnaissance was sunny and approximately 38 degrees Fahrenheit.

6.2 Hazardous Substance Use, Storage, and Disposal

ATC observed various 55-gallon drums throughout the penthouse mechanical room of the property building. Two 55-gallon steel drums containing waste oil are reportedly picked up and disposed of by US Ecology on an as-needed basis. The waste oil is reportedly generated from machines and/or engines with vacuum pumps within the mechanical room. Additionally, two 55-gallon plastic drums containing boiler treatment chemicals were observed. All drums appeared to be in good condition with no evidence of leaks and/or staining noted.

ATC also observed various cabinets (i.e. flammables cabinets) containing paints, adhesives, aerosols, and other general commercial cleaning products. All containers were retail in size and appeared to be in good condition. Various 5-gallon buckets containing paint primers, adhesives, and other routine maintenance products were also observed. One 5-gallon bucket containing diesel engine oil was observed within the penthouse generator room. No evidence of leaks and/or staining was observed.

The presence of the listed hazardous substances does not represent a *recognized environmental condition* based on the observed conditions.

6.3 Underground Storage Tanks

During the Site reconnaissance ATC observed two fuel oil fill ports within the sidewalk along Main Street, directly in front of the loading dock area and two fill ports within the loading dock area. According to a Fuel Oil Tank Upgrade Project Report, prepared by Clayton Environmental Services, Inc., and dated April 25, 1997, two 10,000-gallon USTs were installed in 1979 on a concrete pad below the loading dock area and were "closed-in-place" in January 1997. The USTs were reportedly in good condition at the time of closure and no further sampling was required. Based on review of the provided report, the four (4) fill ports are likely associated with the two "closed-in place" USTs. Based on the reviewed documentation and the reported condition of the USTs during their removal, they are not considered to be a *recognized environmental condition.*

6.4 Aboveground Storage Tanks

ATC observed one 1,000-gallon diesel fuel AST within the east portion of the loading dock area that was reportedly installed in 1997. The 1,000-gallon diesel AST transfers fuel to a 100-gallon day tank AST and emergency generator located within the penthouse generator room of the property building. ATC observed oil staining on the concrete pad below the emergency generator engine. No unusually strong odors or signs of corrosion were noted.Based on its location, minor quantity and lack of pathway to the subsurface, this minor staining is considered to be a *de minimis condition.*

6.5 Other Petroleum Products

ATC observed one passenger elevator and one freight elevator that service the property building. The elevators are property-owned, cable/gear traction type, manufactured by Otis Elevator Co., and maintained by Shindler Elevator Corporation on a regular basis. The elevator machine rooms are located on the penthouse level. ATC observed minor oil staining in the immediate vicinity of the passenger elevator equipment on the concrete floor and considers this to represent a *de minimis condition.*

ATC also observed a slight petroleum-like sheen on standing water within the loading dock area of the property building. The sheen is likely associated with the typical operations of vehicles both driving and parking in this concrete-paved loading area. The observed sheen is considered to represent a *de minimis condition.*

ATC observed one hydraulic cardboard baler and one hydraulic trash compactor, located in loading bay area of the property building. The hydraulic equipment appeared to be in good condition with no evidence of spills, leaks, or staining noted. The cardboard baler and trash compactor do not represent a *recognized environmental condition* based on the observed conditions.

ATC observed various electric transformers throughout mechanical rooms on the penthouse level of the property building. No reports of issues and/or leaks were disclosed and the the transformers are reportedly replaced when needed. The transformers are property-owned and appeared to be "dry-type." The observed electrical transformers do not represent a *recognized environmental condition*.

6.6 Polychlorinated Biphenyls (PCBs)

ATC did not observe evidence of the use, storage or disposal of PCB-containing equipment in, on or at the property.

Fluorescent light ballasts were identified throughout the building. No evidence of leaking or staining around the outside of the light fixtures was observed by ATC. Fluorescent light ballasts manufactured prior to 1979 may contain PCBs. Based on the construction date of the property (1979-1980), it possible that on-site fluorescent light ballasts contain PCBs. Individual ballasts should be inspected in-house for PCB-content labeling during routine servicing and replacement, and ballasts that are either labeled as PCB-containing or units that are unlabeled should be disposed of properly in accordance with applicable regulations if no longer needed.

6.7 Unidentified Substance Containers

ATC observed one approximate 50-gallon plastic drum with a "corrosive" label in the mechanical penthouse. No additional information was available. No evidence of leaks and/or staining was observed. The unidentified drum does not represent a *recognized environmental condition* based on the observed condition.

6.8 Nonhazardous Solid Waste

ATC observed evidence of the generation, storage, and disposal of nonhazardous solid waste on the property in the form of routine garbage, stored and disposed of in a hydraulic baler and compactor, detailed in Section 6.6 above. Garbage removal is performed by County Waste Management on a regular basis. No evidence of spills, release, or mismanagement of materials was observed.operates a separate wastewater sewer system for the City of White Plains. Both of these Bureau's operate under the supervision of the direction of the Commissioner of Public Works and the Bureau’s Superintendent.

6.9 Wastewater

ATC observed evidence of wastewater generated, treated or discharged (including sanitary sewage) in, on or at the property or to adjoining properties as summarized below.

WASTEWATER SUMMARY TABLE			
Type of Wastewater	**Generation Process**	**Treatment System?**	**Discharged To?**
Commercial Sanitary Sewage	Routine operations	No	Sanitary Sewer
Stormwater	Rain events	No	Storm Sewer

6.10 Waste Pits, Ponds and Lagoons

ATC did not observe evidence of waste pits, ponds or lagoons in, on or at the property.

6.11 Drains and Sumps

ATC observed various floor drains in the mechanical room and restrooms within the property building. A trench drain was also observed at the loading dock entrance, along the sidewalk of Main Street. All drains connect to the sanitary sewer. No unusually strong odors, staining or signs of corrosion were noted in the area of the drains. No sumps were observed at the property.

The identified drains and/or sumps do not represent a *recognized environmental condition* based on the observed conditions.

6.12 Septic Systems

ATC did not observe evidence of a septic system on the property.

6.13 Stormwater Management System

Stormwater runoff on the property sidewalks drains to catch basins located along Main Street, Court Street, and Martine Avenue, which discharge to the stormwater sewer system. Stormwater from the rooftop of the building is directed to the stormwater sewer system via roof drains.

6.14 Wells

ATC did not observe evidence of wells in, on or at the property.

7.0 SUBSURFACE VAPOR MIGRATION

ATC conducted a limited screening for potential vapor encroachment conditions (VECs) that may affect the property. The VEC screening focused on the current and historical usage of the property and also utilized the aforementioned regulatory agency database report provided by EDR to evaluate identified Chemicals of Concern (COCs), including petroleum hydrocarbons. To identify the area of concern (AOC) for contaminated sites with non-petroleum hydrocarbon COCs, ATC utilized the approximate minimum search distance defined by ASTM E 2600-15 of 1,760 feet (1/3 mile) from the property boundary for COC-contaminated sites. For sites contaminated with petroleum hydrocarbon COCs, ATC utilized the AOC approximate minimum search distance of 528 feet (1/10 mile). The AOC was adjusted accordingly based on review of physical setting characteristics, known release information, property and land features, groundwater flow direction, and soil type, et al.

ASTM's Vapor Encroachment guidance indicates that when groundwater flow direction can be estimated or determined, the cross-gradient or downgradient radius distances can be significantly reduced. Reduced AOC distances can be calculated when considering groundwater flow direction by utilizing the following default distances, which were determined using the Buonicore Methodology: (non-petroleum hydrocarbon COCs) 1,760 feet in the upgradient direction; 365 feet in the cross-gradient direction; and 100 feet in the downgradient direction and (petroleum hydrocarbon COCs) 528 feet in the upgradient direction; 165 feet in the cross-gradient direction if Light, Non-Aqueous Phase Liquid, (LNAPL i.e. floating product) is suspected; 95 feet in the cross-gradient direction if no LNAPL is suspected; 100 feet in the downgradient direction (LNAPL suspected); and 30 feet in the downgradient position (LNAPL not suspected).

ATC reviewed potential sources of COCs from the sites reported on the EDR database report. No VECs were identified in connection with the property.

8.0 INTERVIEWS

The persons identified in the table below were interviewed to obtain information regarding *recognized environmental conditions* in connection with the property. Pertinent information from the interviews is discussed in applicable sections of this report with details documented (including failed attempts to interview) on Record of Communication forms in Appendix J.

INTERVIEW SUMMARY				
Role	**Name**	**Title/Company**	**Years Assoc. With Property**	**Interview Type**
Site Contact	Tom Miles	VP of Portfolio Management/Galleria at White Plains	Unknown	In Person
Site Contact	Josh McCord	Retail Manager/Galleria at White Plains	Unknown	In Person
Site Escort	John DiMiceli	Facilities Director/Macy's, Inc.	Approximately four years	In Person
Site Escort	Robert Logiudice	Chief Engineer/Macy's, Inc.	Approximately one month	In Person
State Government Agency	Representative	New York State Department of Environmental Conservation (NYSDEC)	Unknown	Email
Local Government Agency	Representative	Westchester County Department of Health (WCDOH)	Unknown	Email
Local Government Agency	Representative	City of White Plains Clerk's Office	Unknown	Email
Local Government Agency	Representative	City of White plains Building Department	Unknown	Email

9.0 OTHER ENVIRONMENTAL CONDITIONS

9.1 Asbestos-Containing Material (ACM)

Based on the scope of work for this ESA, sampling and analysis for ACM was not conducted. All suspect ACM should be properly assessed prior to disturbance from construction or maintenance activities. Most observed building materials and finishes were noted to be in good to fair condition at the time of the site visit. The following building materials and finishes were noted to be in fair or poor condition at the time of the site visit: acoustic ceiling tiles in the penthouse elevator lobby, and third floor back of house (BOH) sales floor and storage rooms. Suspect materials observed during the course of the assessment included gypsum board walls, acoustic ceiling tiles, pipe insulation, carpet mastic, cove base, and vinyl floor tiles and associated mastic. According to the Macy's Facilities Director, annual ACM surveys are performed at the property and materials are properly tested and abated as needed. An asbestos Operations & Maintenance (O&M) Plan, completed by a third party, is reportedly in place and is updated for the property.

9.2 Radon

Radon is a naturally occurring colorless, odorless gas that is a by-product of the decay of radioactive materials potentially present in bedrock and soil. The EPA guidance action level for annual residential exposure to radon is 4.0 picoCuries per liter of air (pCi/L). The guidance action level is not a regulatory requirement for private owners of commercial real estate, but is commonly used for comparison purposes to suggest whether further action at a building may be prudent.

ATC's review of published radon data indicates that the property is located in EPA Radon Zone 3 (Low Potential) where the average indoor concentration of radon is less than 2 pCi/L, which is less than the EPA Action Level of 4.0 pCi/L. Additionally, the NYSDOH maintains a database of radon test results on a local and county level. According to the NYSDOH, a total of 145 radon tests have been conducted in basements of the City of White Plains. The average radon level was found to be 2.89 pCi/L which is below the US EPA action level of 4.0 pCi/L. Based on the regional statistics and commercial nature of the property, radon is not considered a significant environmental concern to the property.

9.3 Lead in Drinking Water

As previously discussed in Section 5.1.3, and based on the Annual Drinking Water Quality Report for 2017 of the City of White Plains, the public water supply meets federal and state guidelines for tested parameters, including those established for lead. The 2017 source water assessment findings did not report any violations. Lead-in-drinking water screening was not part of the scope of work for this assessment.

9.4 Lead-Based Paint (LBP)

Based on the commercial use of the property, consideration of LBP on painted surfaces was not included in the scope of work for this ESA. Given the construction date of the property (1979-1980), LBP is not likely to be present at the property. All suspect LBP should be properly assessed prior to disturbance from construction or maintenance activities. Most observed painted surfaces were noted to be in fair condition at the time of the site visit.

9.5 Mold Screening

According to Section 931 of the New York State Labor Law Article 32, New York State requires that mold assessments be conducted by an individual who holds a valid mold assessment license with the New York State Department of Labor. It should be noted that the property inspection was completed for due diligence purposes and was not conducted with the intent to be a mold assessment. Our assessment services included a limited visual review of readily observable conditions in the areas made accessible by property representatives, and the accounts presented by Client/property representatives. If we observed a condition that may be associated with water damage or apparent microbial impact, we have noted such observations;however, our assessment is not intended to be, and should not be construed as, a Mold Assessment, as defined under Article 32. A formal mold assessment can only be performed by a New York State Department of Labor licensed Mold Assessor. ATC may provide this service, if desired, at the request of the Client.

ATC conducted a screening survey for readily observable mold and conditions conducive to mold on the property. The screening consisted of limited interview, document review (if any) and physical observation. ATC interviewed Mr. John DiMiceli, Facilities Director with Macy's, Inc. regarding potential mold conditions at the property. ATC observed various areas of water stained ceiling tiles throughout the penthouse, and back storage rooms, the sales floor, and employee lounge within the third floor of the property building. ATC observed approximately eight square feet of suspect visible mold growth (SVMG) within the Back of House (BOH) storage room, located in the unusded sales area on the third floor of the property building. According to the Chief Engineer, roof leaks have affected these areas and are currently being addressed.

9.6 Additional User Requested Services

No additional User requested services were included in the scope of work for this ESA.

10.0 REFERENCES

ASTM International, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process,* ASTM Designation E1527-13, November 2013.

ASTM International. *Standard Guide for Readily Observable Mold and Conditions Conducive to Mold in Commercial Buildings: Baseline Survey Process*, ASTM Designation E 2418-06. March 2006.

ASTM International. *Standard Guide for Visual Asbestos Screens of Buildings*, ASTM Designation E2308-05. August 2005.

ASTM International, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*, ASTM Designation E 2600-15, December 2015.

City of White Plains City Departments, Department of Public Works, Water Quality Report for 2017 (https://www.cityofwhiteplains.com/704/2017-Water-Quality-Report).

Environmental Data Resources, Inc. (EDR), Radius Map with Geocheck, Report, Inquiry Number 5604205.2S, dated March 28, 2019.

EDR, Aerial Photo Decade Package, Inquiry Number 5604205.11S, dated March 28, 2019.

EDR, Building Permit Report, "No Coverage" Inquiry Number 5604205.8, dated March 28, 2019.

EDR, City Directory Abstract, Inquiry Number 5604205.5S, dated March 29, 2019.

EDR, Sanborn Map Report, Inquiry Number 5604205.3S, dated March 28, 2019.

EDR, Property Tax Map Report, "No Coverage" Inquiry Number 5604205.6, dated March 28, 2019.

EDR, Historical Topographic Map Report, Inquiry Number 5604205.4S, dated March 28, 2019.

Federal Emergency Management Agency (FEMA), Flood Insurance Rate Map (FIRM).

"Fuel Oil Tank Upgrade Project Report, Tank Closure and Installation at Macy's Department Store Galleria Mall, 100 Main Street White Plains, New York" prepared by Clayton Environmental Consultants, Inc., and dated April 25, 1997.

New York State Department of Health Radon Level Maps and Statistics (NYSDOH)
(https://www.health.ny.gov/environmental/radiological/radon/maps_statistics.htm)

United States Fish and Wildlife Service, National Wetland Inventory Mapper (http://www.fws.gov/nwi/).

United States Geological Survey (USGS) Topographic Map, White Plains Quadrangle Map, 7.5 Minute Series, dated 2013.

Westchester County GIS (https://giswww.westchestergov.com/gismap/)

11.0 TERMINOLOGY

The following provides definitions and descriptions of certain key terms that may be used in this report. Italics indicate terms that are defined by ASTM Standard Practice E 1527-13. The Standard Practice should be referenced for further detail (such as the precise wording), related definitions or additional explanation regarding the meaning of these or other terms.

recognized environmental condition(s) (REC) - the presence or likely presence of any *hazardous substances* or *petroleum products* in, on, or at a *property*: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a *material threat* of a future release to the environment.

material threat - a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional (EP), is threatening and might result in impact to public health or the environment. An example might include an aboveground storage tank system that contains a hazardous substance and which shows evidence of damage such that it may cause or contribute to tank integrity failure with a release of contents to the environment.

de minimis condition - is a condition that generally does not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of the appropriate governmental agencies. An example might include a release of *hazardous substances* or *petroleum products* that could reasonably and foreseeably result in a concentration exceeding the applicable regulatory agency risk-based residential standards or substantial damage to natural resources. The risk of that exposure or damage would represent a threat to human health or the environment. If an enforcement action would be less likely than not, then the condition is considered to be generally not likely the subject of an enforcement action. A condition determined to be *de minimis* is not a *REC* or *controlled recognized environmental condition (CREC).*

historical recognized environmental condition (HREC) - a past release of any *hazardous substances* or *petroleum products* that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls (for example, property use restrictions, activity and use limitations, institutional controls, or engineering controls). Before calling the past release a *HREC*, the environmental professional (EP) must determine whether the past release is a *REC* at the time the assessment is conducted (for example, if there has been a change in the regulatory criteria). If the EP considers the past release to be a *REC* at the time the Phase I ESA is conducted, the condition will be reported in Section 1.2 the Findings and Conclusions Summary table as a *REC*.


controlled recognized environmental condition (CREC) - a *recognized environmental condition* resulting from a past release of *hazardous substances* or *petroleum products* that has been addressed to the satisfaction of the applicable regulatory authority (for example, as evidenced by the issuance of a no further action letter or equivalent, or meeting risk-based criteria established by regulatory authority), with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, property use restrictions, activity and use limitation, institutional controls, or engineering controls). Per E1527-13, a *CREC* will be reported in the Section 1.2 Findings and Conclusions Summary table as a *CREC* and a *REC*.

migrate/migration - refers to the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface.

business environmental risk (BER) - refers to a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated per the ASTM standard.

Appendix A

Site Vicinity Map



104 East 25th St.
New York, New York 10010
Phone: (212) 353-8280
Fax: (212) 979-8447

APPENDIX A: SITE VICINITY MAP


Macy's White Plains Galleria
100 Main Street
White Plains, NY 10601

SOURCE:

U.S. Geologic Survey Topographic Map 7.5 Minute Series, White Plains Quadrangle, 2013

Appendix B

Site Plan



Legend:

Approximate limits of property boundary

Approximate location of closed-in-place 10,000-gallon USTs

ATC

104 East 25th St.
New York, New York 10010
Phone: (212) 353-8280
Fax: (212) 979-8447

Source:
US Fish and Wildlife
NWI Wetlands Mapper

APPENDIX B: SITE PLAN

Macy's White Plains Galleria
100 Main Street
White Plains, NY 10601

ATC PROJECT NUMBER
Z214DCWP01

Appendix C

Site Photographs



Photograph 1: View of the Macy's loading dock area from Main Street.



Photograph 2: View of two exterior remote fill ports likely used for the closed-in-place 10,000-gallon USTs at the property.



Photograph 3: View of interior fuel oil fill ports located within the loading dock area of the property building.




Photograph 4: View of 1,000-gallon AST within the loading dock area of the property.



Photograph 5: "Dry Type" electric transformers located at the property.



Photograph 6: DeMinimis oil staining beneath the property's emergency generator.



Photograph 7: Container of diesel oil stored within the generator room of the property building.



Photograph 8: View of general building storage at the property.



Photograph 9: Elevator equipment at the property.



Photograph 10: View of two 55-gallon steel drums containing waste oil.



Photograph 11: Paint storage cabinet located within the penthouse mechanical room of the property building.



Photograph 12: Approximatel50-gallon plastic drum containing an unknown corrosive substance, stored in the penthouse mechanical room of the property.



Photograph 13: Gas-fired boilers within the penthouse mechanical room of the property building.



Photograph 14: Boiler treatment chemicals stored at the property.



Photograph 15: Rooftop cooling towers at the property building.



Photograph 16: Representative view of the rooftop with roof drains.



Photograph 17: Flammables materials cabinet within the property building.



Photograph 18: Suspect visible mold growth within the back storage room on the third floor of the property building.



Photograph 19: Stained ceiling tiles on the third floor of the property building.




Photograph 20: Hydraulic cardboard baler on the first floor of the property building.



Photograph 21: Hydraulic trash compactor on the first floor of the property building.



Photograph 22: Representative view of the loading docks within the property building.



Photograph 23: Standing water with slight petroleum sheen observed within the loading dock area of the property building.



Photograph 24: View of adjacent area to the north, beyond Main Street.



Photograph 25: View of adjacent area to the northeast, beyond Main Street.



Photograph 26: View of adjoining Galleria parking garage to the west.



Photograph 27: View of adjacent area to the east, beyond Court Street.



Photograph 28: View of adjacent area to the south, beyond Martine Avenue.

Appendix E

Regulatory Database Report

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.2s
March 28, 2019

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	933
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-8
Physical Setting Source Map Findings	A-10
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

100 MAIN STREET
WHITE PLAINS, NY 10601

COORDINATES

Latitude (North):	41.0316960 - 41° 1' 54.10''
Longitude (West):	73.7682160 - 73° 46' 5.57''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	603549.2
UTM Y (Meters):	4542794.5
Elevation:	211 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5939761 WHITE PLAINS, NY
Version Date:	2013
Northeast Map:	5641951 GLENVILLE, CT
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522, 20150624
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	J.C. PENNEY	100 MAIN ST	NY UST		TP
A2	EXPRESSLY PORTRAITS	100 MAIN ST - GALLER	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST		TP
A3	MACYS WHITE PLAINS C	100 MAIN ST	FINDS, ECHO		TP
A4	MACY'S EAST #55	100 MAIN ST	NY MANIFEST		TP
A5	MACYS - WHITE PLAINS	100 MAIN ST	FINDS, ECHO		TP
A6	PICTURE PEOPLE THE	100 MAIN ST SPACE 32	RCRA-SQG, FINDS, ECHO, NY MANIFEST		TP
A7		100 E. MAIN ST	NY COOLING TOWERS		TP
A8	MACYS - WHITE PLAINS	100 MAIN ST	RCRA-SQG, FINDS, ECHO		TP
A9		100 MAIN STREET	NY COOLING TOWERS		TP
A10		100 E. MAIN ST	NY COOLING TOWERS		TP
A11	GALLERIA OF WHITE PL	100 MAIN STREET	FINDS		TP
A12		100 MAIN STREET	NY COOLING TOWERS		TP
A13	J C PENNEY CO INC	100 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...		TP
A14	C P I PHOTO FINISH	100 MAIN ST STE 301	RCRA NonGen / NLR, FINDS, ECHO		TP
B15	CON EDISON	WILLIAMS ST & MAIN S	RCRA NonGen / NLR	Lower	34, 0.006, NW
B16	CON EDISON	WILLIAMS ST & MAIN S	RCRA NonGen / NLR, NJ MANIFEST	Lower	34, 0.006, NW
B17	CON EDISON MANHOLE:	MAIN ST & WILLIAMS S	RCRA NonGen / NLR, NY MANIFEST	Lower	34, 0.006, NW
B18	CONSOLIDATED EDISON	WILLIAM ST & MAIN ST	NY MANIFEST	Lower	34, 0.006, NW
B19	CON ED- TM462	WILLIAMS & MAIN ST	NY MANIFEST	Lower	34, 0.006, NW
B20	CON EDISON	WILLIAMS ST & MAIN S	NY MANIFEST	Lower	34, 0.006, NW
A21	LAST CALL NY INC/DBA	171-173 MAIN STREET	NY UST	Lower	43, 0.008, North
A22	VINTAGE RESTAURANT	171-173 MAIN STREET	NY LTANKS	Lower	43, 0.008, North
A23	WYASSUP-LAUREL GLEN	175 MAIN STREET	NY AST	Lower	43, 0.008, North
A24	OFFICE BLDG	175 MAIN ST	NY Spills	Lower	43, 0.008, North
A25	DRAIN - COOKING GREA	175 MAIN STREET	NY Spills	Lower	43, 0.008, North
A26	CON EDISON SERVICE B	19 COURT ST	RCRA NonGen / NLR, NY MANIFEST	Higher	53, 0.010, ENE
A27	CON EDISON SERVICE B	19 COURT ST	NJ MANIFEST	Higher	53, 0.010, ENE
C28	CON EDISON MANHOLE 5	COURT ST & MAIN ST	RCRA NonGen / NLR	Lower	54, 0.010, NNE
C29	CON EDISON MANHOLE 1	MAIN ST & COURT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	54, 0.010, NNE
C30	CON EDISON MANHOLE:	MAIN ST & COURT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	54, 0.010, NNE
C31	CON EDISON	COURT ST & MAIN ST	NY MANIFEST	Lower	54, 0.010, NNE
C32	ROADWAY	MAIN ST & COURT ST	NY Spills	Lower	54, 0.010, NNE
C33	CON EDISON	COURT ST & MAIN ST	RCRA NonGen / NLR	Lower	54, 0.010, NNE
C34	CON EDISON MANHOLE 1	COURT ST & MAIN ST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	54, 0.010, NNE
C35	CON EDISON	MAIN ST & COURT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	54, 0.010, NNE
C36	CON EDISON MANHOLE:	MAIN ST & COURT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	54, 0.010, NNE
C37	CON EDISON	COURT ST & MAIN ST	NJ MANIFEST	Lower	54, 0.010, NNE
C38	CON EDISON SERVICE B	MAIN ST & COURT ST	RCRA NonGen / NLR, NY MANIFEST	Lower	54, 0.010, NNE
C39	CON EDISON	COURT ST & MAIN ST	NY MANIFEST	Lower	54, 0.010, NNE

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
C40	CON EDISON	COURT ST & MAIN ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	54, 0.010, NNE
A41	I/F/O THE MELTING PO	35 COURT ST	NY Spills	Higher	54, 0.010, East
A42	MINSKOFF MANAGEMENT	39-47 COURT STREET	NY Spills	Higher	55, 0.010, East
A43	COURT & MARTINE 2009	39-55 COURT ST / 167	NY AST	Higher	55, 0.010, East
D44	MICHAEL E LAND OFFIC	148 MARTINE AVE	NY LTANKS, NY Spills	Higher	55, 0.010, SSE
D45	WESTCHESTER COUNTY O	148 MARTINE AVENUE	NY AST	Higher	55, 0.010, SSE
D46	CON EDISON	148 MARTINE AVE	NJ MANIFEST	Higher	55, 0.010, SSE
D47	WESTCHESTER COUNTY O	148 MARTINE AVENUE	NY UST	Higher	55, 0.010, SSE
D48	CON EDISON	148 MARTINE AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	55, 0.010, SSE
D49	WESTCHESTER COUNTY O	148 MARTINE AVE	RCRA-CESQG, NY MANIFEST	Higher	55, 0.010, SSE
D50	CON ED	148 MARTINE AVE	NY MANIFEST	Higher	55, 0.010, SSE
D51	DPW VEHICLE	COURT ST AND MARTINE	NY Spills	Higher	67, 0.013, SE
D52	CON EDISON	COURT ST & MARTINE A	NY MANIFEST	Higher	67, 0.013, SE
D53	CON EDISON MANHOLE 9	MARTINE AVE & COURT	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	67, 0.013, SE
D54	CON EDISON	COURT ST & MARTINE A	RCRA NonGen / NLR, FINDS, ECHO	Higher	67, 0.013, SE
D55	CON EDISON	COURT ST & MARTINE A	NJ MANIFEST	Higher	67, 0.013, SE
D56	CON EDISON	MARTINE AVE & COURT	NY MANIFEST	Higher	67, 0.013, SE
D57	CON EDISON	MARTINE AVE & COURT	NY MANIFEST	Higher	67, 0.013, SE
D58	THE MICHICALLIAN OFF	MARTINE AVE & COURT	NY LTANKS	Higher	67, 0.013, SE
D59	CON EDISON	MARTINE & COURT ST	NY MANIFEST	Higher	67, 0.013, SE
D60	CON EDISON TRANSFORM	MARTINE AVE & COURT	RCRA NonGen / NLR, NY MANIFEST	Higher	67, 0.013, SE
D61	INTERSECTION OF COUR	COURT ST. & MARITINE	NY LTANKS	Higher	67, 0.013, SE
D62	RAILROAD ONE LF	148 MARTINE AVENUE	NY SWF/LF, NY Financial Assurance	Higher	69, 0.013, SE
D63	SPILL NUMBER 8900947	148 MARTEEN AVENUE	NY Spills	Higher	98, 0.019, SSE
C64	RESIDENCE	185- 187 MAIN ST	NY LTANKS	Lower	107, 0.020, NE
B65	NY POWER AUTH	123 MAIN ST	RCRA NonGen / NLR	Lower	124, 0.023, WNW
B66	NEW YORK POWER AUTHO	123 MAIN STREET	NY UST, NY AST	Lower	124, 0.023, WNW
B67	NEW YORK POWER AUTH	123 MAIN ST	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	124, 0.023, WNW
B68	ODDESY CORP MAINT DE	123 MAIN STREET	NY LTANKS, NY Spills	Lower	124, 0.023, WNW
C69	CONSOLIDATED EDISON	189 MAIN ST	NJ MANIFEST	Lower	124, 0.023, North
C70	MANHOLE # 10236	189 MAIN STREET	NY Spills	Lower	124, 0.023, North
C71	199 MAIN STREET REAL	199 MAIN STREET	NY UST, NY AST	Lower	131, 0.025, NE
B72	MARTIN LUTHER KING &	MAIN STREET	NY Spills	Lower	134, 0.025, WNW
D73	TM 5706	MARTINE AVE/ COURT S	NY Spills	Higher	143, 0.027, SE
D74	SPILL NUMBER 0108867	412 MARTIN AND COURT	NY Spills	Higher	145, 0.027, SE
D75	LITTLE HOUSE RESTAUR	169 MARTINE AVE	NY Spills	Higher	156, 0.030, ESE
C76	SOIL	3 RENAISSANCE SQUARE	NY Spills	Lower	199, 0.038, NNE
B77	A&S STORE	GALLERIA PLAZA	NY LTANKS	Lower	217, 0.041, WNW
B78	A & S STORE	GALLERIA PLAZA	NY LTANKS	Lower	217, 0.041, WNW

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
D79	MINSKOFF CORP.	179 MARTINE AVE	NY LTANKS	Higher	224, 0.042, ESE
D80	WEST HEALTH DEPT	148 MARTINE AVE	NY LTANKS	Higher	237, 0.045, SSE
E81	CON EDISON	MARTINE & GROVE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	246, 0.047, SW
E82	CON EDISON	MARTINE & GROVE ST	NY MANIFEST	Lower	246, 0.047, SW
E83	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	247, 0.047, SW
E84	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	247, 0.047, SW
E85	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	247, 0.047, SW
C86	SPILL NUMBER 0206130	203 MAIN ST	NY LTANKS	Higher	253, 0.048, NE
C87	BRIAN HOLDING COMPAN	203 MAIN STREET	NY UST	Higher	253, 0.048, NE
B88	VAULT #0070	MAIN ST & GROVE ST	NY Spills	Lower	260, 0.049, WNW
B89	WHITE PLAINS GARAGE	MAIN ST & GROVE ST	NY Spills	Lower	260, 0.049, WNW
B90	CON EDISON MANHOLE 9	MAIN ST & MARTIN LUT	RCRA NonGen / NLR	Lower	260, 0.049, WNW
F91	CAMERA STORE	44 MAMARONECK AVE	NY Spills	Higher	278, 0.053, East
F92	WOOLWORTH STORE BASE	24-34 MAMARONECK AVE	NY Spills	Higher	278, 0.053, East
F93	CVS PHARMACY #4745	26-32 MAMARONECK AVE	RCRA-LQG, NY MANIFEST	Higher	278, 0.053, East
F94	24-46 MAMARONECK ASS	34 MAMARONECK AVE	NY Spills	Higher	278, 0.053, East
F95	QUICK PICK SHOES	40 MAMARONECK	NY Spills	Higher	278, 0.053, East
F96	IN DITCH	IN FRONT OF 187 MART	NY Spills	Higher	288, 0.055, ESE
C97	213 MAIN STREET	213 MAIN ATREET	NY Spills	Higher	304, 0.058, NE
F98	CALANO & CALANO REAL	14 MAMARONECK AVENUE	NY UST	Higher	304, 0.058, ENE
F99	OFFICE BUILDING	14 MAMARONECK AVE	NY LTANKS	Higher	304, 0.058, ENE
D100	COUNTY OF WESTCHESTE	85 COURT STREET	NY AST	Higher	306, 0.058, SE
F101	CVS PHARMACY #4745	24 MAMARONECK AVE	PA MANIFEST	Higher	324, 0.061, ENE
G102	WHITE PLAINS TOWN CE	MAMARONECK AVE & MAI	RCRA NonGen / NLR	Higher	330, 0.062, NE
G103	CON EDISON MANHOLE:	MAMARONECK AVE & MAI	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	343, 0.065, NE
G104	CON EDISON MANHOLE:	221 MAIN ST	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Higher	352, 0.067, NE
G105	CON EDISON - MANHOLE	221 MAIN STREET	NJ MANIFEST	Higher	352, 0.067, NE
G106	CAPELLI CONSTRUCTION	MAIN ST & MAMARONECK	NY Spills	Higher	352, 0.067, NE
G107	MAMARANECK AV	MAIN ST	NY Spills	Higher	352, 0.067, NE
F108	196-200 MARTINE AVEN	196-200 MARTINE AVEN	NY AST	Higher	361, 0.068, ESE
F109	EMPLOYMENT BUILDING?	48 MAMARONECK AVE.	NY Spills	Higher	366, 0.069, ESE
F110	48 MAMARONECK AVENUE	48 MAMARONECK AVENUE	NY AST	Higher	366, 0.069, ESE
G111	TARGET CONSTRUCTION	7 MAMARONECK AVE	NY Spills	Higher	372, 0.070, ENE
F112	SHARP IMAGE CLEANER	198 MARTINE AVE	EDR Hist Cleaner	Higher	374, 0.071, ESE
F113	WHITE PLAINS CITY CE	MAMARONECK/MARTINE A	NY Spills	Higher	377, 0.071, ESE
F114	CON EDISON	240 MARTINE AVE & MA	RCRA NonGen / NLR, FINDS, ECHO, NJ MANIFEST	Higher	392, 0.074, ESE
F115	ROADWAY	MAMARONECK AVE AND M	NY Spills	Higher	392, 0.074, ESE
F116	1-HOUR PHOTO FINISH	60B MAMARONECK AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	400, 0.076, ESE
F117	SPILL NUMBER 0103591	MAMARONECK AVE/MARTI	NY Spills	Higher	412, 0.078, ESE

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H118	IN FRONT OF GALERIA	MAIN ST	NY Spills	Lower	427, 0.081, West
F119	UNOCCUPIED COMMERCIA	31 MAMARONECK AVE	NY Spills	Higher	428, 0.081, East
G120	221 MAIN STREET	221 MAIN ST	NY BROWNFIELDS, NY Spills	Higher	437, 0.083, NE
I121	INNS OF COURT	99 COURT ST	NY LTANKS	Higher	453, 0.086, SSE
I122	THE INNS OF COURT PR	99 COURT ST.	NY UST	Higher	453, 0.086, SSE
J123	76 MAMARONECK AVENUE	76 MAMARONECK AVENUE	NY UST	Higher	456, 0.086, ESE
G124	CON EDISON	MAIN ST & CHURCH ST	RCRA NonGen / NLR, NY MANIFEST	Higher	460, 0.087, NE
G125	CON EDISON	MAIN ST & CHURCH ST	NJ MANIFEST	Higher	460, 0.087, NE
J126	47 MAMARONECK AVENUE	47 MAMARONECK AVENUE	NY UST	Higher	477, 0.090, ESE
J127	47 MAMARONECK AVENUE	47 MAMARONECK AVENUE	NY Spills	Higher	477, 0.090, ESE
K128	IN STREET	55 CHURCH STREET	NY Spills	Higher	498, 0.094, NNE
L129	CON EDISON	HAMILTON & MARTIN LU	NY MANIFEST	Lower	507, 0.096, NW
L130	MANHOLE #4021	HAMILTON AVE & GROVE	NY Spills	Lower	507, 0.096, NW
M131	CAPELLI CONSTRUCTION	HAMILTON AVE/COTTAGE	NY Spills	Lower	509, 0.096, North
M132	CONSTRUCTION SITE	HAMILTON AVE/COTTAGE	NY Spills	Lower	509, 0.096, North
M133	MAN HOLE	HAMILTON AVE AND COT	NY Spills	Lower	509, 0.096, North
M134	CON EDISON	HAMILTON AVE & RENNA	NY MANIFEST	Lower	513, 0.097, North
I135	CIGARETTE WORLD	10-12 QUARROPAS ST	NY Spills	Higher	525, 0.099, SE
N136	WESTCHESTER COUNTY C	110 DR MARTIN LUTHER	RCRA-CESQG	Lower	529, 0.100, SSW
K137	WHITE PLAINS POLICE	279 HAMILTON AVENUE	NY LTANKS, NY MANIFEST	Lower	540, 0.102, North
K138	WHITE PLAINS POLICE	279 HAMILTON AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	540, 0.102, North
K139	FORMER WPPD	279 HAMITON AVE	NY LTANKS	Lower	540, 0.102, North
N140	NYSDEC	GRAND & QUARRAPUS	NY MANIFEST	Higher	542, 0.103, South
N141	CON EDISON	111 MARTIN LUTHER KI	NJ MANIFEST	Lower	546, 0.103, SSW
N142	WESTCHESTER COUNTY C	111 GROVE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	546, 0.103, SSW
N143	CON EDISON	111 MARTIN LUTHER KI	RCRA NonGen / NLR	Lower	546, 0.103, SSW
N144	WESTCHESTER COUNTY C	111 MARTIN LUTHER KI	NY UST, NY AST	Lower	546, 0.103, SSW
J145	204 MARTINE ASSOCIAT	204 MARTINE AVE	NY AST	Higher	549, 0.104, East
H146	NYNEX	111 MAIN ST	NY LTANKS, NY Spills	Lower	551, 0.104, WNW
H147	NYNEX MATERIEL ENTER	111 MAIN ST	RCRA NonGen / NLR, NY MANIFEST	Lower	551, 0.104, WNW
M148	CON EDISON - VAULT 9	200 HAMILTON AVE & C	NY BROWNFIELDS, NY Spills, NY MANIFEST	Lower	556, 0.105, NNW
M149	WHITE PLAINS MALL CL	200 HAMILTON AVE	EDR Hist Cleaner	Lower	556, 0.105, NNW
K150	RENAISSANCE CORPORAT	235 MAIN STREET	NY AST	Higher	562, 0.106, NE
K151	9TH STREET H J LLC	55 CHURCH ST	EDR Hist Auto	Higher	562, 0.106, NNE
K152	55 CHURCH WP LLC	55 CHURCH STREET	NY AST	Higher	562, 0.106, NNE
K153	CENTURYLINK COMMUNIC	55 CHURCH STREET, FI	MA AST	Higher	562, 0.106, NNE
J154	CON ED VAULT TM572	MAMARONECK AVE AT MI	NY Spills	Higher	562, 0.106, SE
J155	CON EDISON TRANSFORM	MITCHELL PL & MAMARO	RCRA NonGen / NLR, NY MANIFEST	Higher	570, 0.108, ESE
K156	HAMILTON TEXACO SERV	303 HAMILTON AVE	EDR Hist Auto	Higher	585, 0.111, North

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J157	KIMCO REALTY CORP	100 MAMARONECK AVENU	NY UST	Higher	589, 0.112, SE
158	VAULT 9104	MARTINE AVE	NY Spills	Lower	596, 0.113, SW
I159	POST OFFICE SQUARE	QUARROPAS ST	NY Spills	Higher	596, 0.113, SSE
K160	HAMILTON MAIN PARKIN	HAMILTON AVE & MAIN	NY LTANKS	Higher	603, 0.114, NNE
M161	C.F	274 HAMILTON ABVE	NY Spills	Lower	617, 0.117, North
M162	CON EDISON	274 HAMILTON AVE	NY MANIFEST	Lower	617, 0.117, North
M163	CODI BROTHERS INC	274 HAMILTON AVENUE	EDR Hist Auto	Lower	617, 0.117, North
O164	131 GRANT AVE	131 GRANT AVE	NY LTANKS	Higher	617, 0.117, South
K165	LIGHTHOUSE FOR THE B	44 CHURCH STREET	NY Spills	Higher	629, 0.119, NNE
H166	BISCARDI FRANK	102 MAIN ST	EDR Hist Cleaner	Lower	637, 0.121, West
N167	CON EDISON	QUARROPAS ST & MLK B	RCRA NonGen / NLR	Lower	645, 0.122, South
N168	CON EDISON	QUARROPAS ST & MLK B	NY MANIFEST	Lower	645, 0.122, South
N169	CON EDISON	QUARROPAS ST & MARTI	NY MANIFEST	Lower	645, 0.122, South
N170	WESTCHESTER COURTHOU	GROVE ST AND QUARROP	NY Spills	Lower	645, 0.122, South
N171	CON EDISON	GROVE ST & QUARROPAS	RCRA NonGen / NLR, NJ MANIFEST	Lower	645, 0.122, South
N172	CON EDISON	QUARROPAS ST & MLK B	NJ MANIFEST	Lower	645, 0.122, South
J173	MITCHELL PLACE ASSOC	10 MITCHELL PLACE	NY LTANKS	Higher	649, 0.123, ESE
M174	EXXON DIV OF CFI #70	274 HAMILTON AVE & C	RCRA-CESQG, FINDS, ECHO, NY MANIFEST	Lower	650, 0.123, North
M175	EXXON SERVICE STATIO	274 HAMILTON AVE	NY LTANKS, NY Spills	Lower	650, 0.123, North
M176	AAMA AUTO SERVICE, I	274 HAMILTON AVENUE	NY UST, NY AST	Lower	650, 0.123, North
M177	AMCOTT ASSOCIATES	300 HAMILTON AVENUE	NY UST	Higher	659, 0.125, North
M178	AMCOTT ASSOCIATES	300 HAMILTON AVENUE	NY AST	Higher	659, 0.125, North
J179	GAS STATION	9 MITCHELL PL	NY LTANKS, NY Spills	Higher	673, 0.127, ESE
J180	DEVON PLAZA REALTY	9 MITCHELL PLACE	NY UST	Higher	673, 0.127, ESE
P181	GHP HAMILTON AVENUE	170 HAMILTON AVENUE	NY UST	Lower	689, 0.130, WNW
P182	CONSOLIDATED EDISON	170 HAMILTON AVE	NY Spills, NY MANIFEST	Lower	689, 0.130, WNW
N183	RECKSON ASSOCIATES	140 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	705, 0.134, South
O184	CON EDISON - VAULT 4	161 GRAND ST	NY MANIFEST	Higher	717, 0.136, South
Q185	WHITE PLAINS DEPT OF	255 MAIN ST	RCRA NonGen / NLR	Higher	723, 0.137, NE
Q186	WHITE PLAINS DEPT OF	255 MAIN STREET	NY LTANKS, NY MANIFEST, NY SPDES	Higher	723, 0.137, NE
Q187	MUNICIPAL BUILDING	255 MAIN ST	NY UST	Higher	723, 0.137, NE
O188	COMMERCIAL BUSINESS	158 GRAND STREET	NY LTANKS	Higher	730, 0.138, South
R189	NICKY'S RESTAURANT	107 MAMARONECK AVE	NY LTANKS	Higher	730, 0.138, SE
S190	210 MARTINE AVENUE	210 MARTINE AVENUE	NY UST	Higher	733, 0.139, East
Q191	CON EDISON	218 MAIN ST	NY MANIFEST	Higher	744, 0.141, ENE
R192	DEVON PLAZA REALITY	109 MAMARONECK AVE	NY LTANKS	Higher	744, 0.141, SE
R193	110-122 MAMARONECK A	110 MAMARONECK AVENU	NY UST	Higher	754, 0.143, SE
R194	SILVERMAN REALITY	110 MAMARONECK AVE	NY LTANKS	Higher	754, 0.143, SE
Q195	T S T WHITE PLAINS L	220 MAIN ST	NY Spills, RCRA NonGen / NLR, NY MANIFEST	Higher	755, 0.143, ENE

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
Q196	CIRCUIT CITY STORE #	220 MAIN ST	RCRA-CESQG, FINDS, ECHO	Higher	755, 0.143, ENE
O197	177 GRAND STREET ASS	177 GRAND STREET	NY UST	Higher	772, 0.146, South
O198	177 GRAND STREET ASS	177 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	772, 0.146, South
O199	150 GRAND STREET OFF	150 GRAND STREET	NY UST	Higher	793, 0.150, South
O200	OFFICE BLDG BASEMENT	150 GRAND STREET	NY LTANKS	Higher	793, 0.150, South
T201	SPILL NUMBER 8809894	23 MITCHELL PLACE	NY LTANKS	Higher	813, 0.154, ESE
T202	SEA MANAGEMENT	23 MITCHELL PLACE	NY UST	Higher	813, 0.154, ESE
R203	PER-BAR	124 MAMARONECK AVE	NY LTANKS	Higher	814, 0.154, SE
Q204	TARGET STORE T1358	9 CITY PL	RCRA-LQG, FINDS, ECHO, NY MANIFEST	Higher	830, 0.157, ENE
T205	SPILL NUMBER 9905959	25 MITCHELL PLACE	NY LTANKS	Higher	836, 0.158, ESE
R206	CON EDISON	134 MAMARONECK AVE	RCRA NonGen / NLR	Higher	836, 0.158, SE
R207	CON EDISON	134 MAMARONECK AVE	NY Spills, NY MANIFEST	Higher	836, 0.158, SE
R208	CON EDISON	134 MAMARANECK AVE	NY MANIFEST	Higher	836, 0.158, SE
R209	CON EDISON	134 MAMARANECK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	836, 0.158, SE
R210	M AND T BANK	134 MAMARONECK AVENU	NY AST	Higher	836, 0.158, SE
U211	CON EDISON	81 MAIN ST FRONT OF	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	840, 0.159, West
S212	28 MITCHELL PLACE IN	28 MITCHELL PLACE	NY UST	Higher	846, 0.160, ESE
S213	28 MITCHELL PLACE	28 MITCHELL PLACE	NY LTANKS	Higher	846, 0.160, ESE
Q214	CON EDISON	MAIN ST & CITY PL	NY MANIFEST	Higher	850, 0.161, ENE
Q215	CON EDISON MANHOLE	MAIN ST & CITY PL	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	850, 0.161, ENE
Q216	CON EDISON	MAIN ST & CITY PL	NJ MANIFEST	Higher	850, 0.161, ENE
Q217	CON EDISON SERVICE B	MAIN ST & CITY PL	RCRA NonGen / NLR, NY MANIFEST	Higher	850, 0.161, ENE
Q218	CON EDISON	MAIN ST & CITY PL	RCRA NonGen / NLR, FINDS, ECHO	Higher	850, 0.161, ENE
R219	CON EDISON	128 MAMARONECK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	853, 0.162, SE
R220	CON EDISON	128 MAMARONECK AVE	NY MANIFEST	Higher	853, 0.162, SE
R221	CON EDISON	128 MAMARONECK AVE	NJ MANIFEST	Higher	853, 0.162, SE
222	MCI DBA VERIZON BUSI	95 CHURCH STREET	NY UST	Higher	871, 0.165, North
S223	SPILL NUMBER 0108164	32 MITCHELL PL	NY LTANKS	Higher	893, 0.169, ESE
R224	CON EDISON	134 MAMARANECK AVE	NJ MANIFEST	Higher	905, 0.171, SE
R225	CON EDISON	134 MAMARONECK AVE	NJ MANIFEST	Higher	905, 0.171, SE
V226	SLATER NEIGHBORHOOD	2 FISHER COURT	NY UST	Lower	907, 0.172, South
V227	SLADER NEIGHBORHOOD	2 FISHER CT	NY LTANKS	Lower	907, 0.172, South
R228	CON EDISON SERVICE B	133 MAMARONECK AVE I	RCRA NonGen / NLR, NY MANIFEST	Higher	922, 0.175, SE
V229	CON EDISON	GROVE ST & FISCHER C	RCRA NonGen / NLR, FINDS, ECHO	Lower	922, 0.175, South
V230	CONSOLIDATED EDISON	GROVE & FISHER	NY MANIFEST	Lower	922, 0.175, South
V231	CON EDISON SERVICE B	GROVE ST & FISCHER A	RCRA NonGen / NLR, NY MANIFEST	Lower	922, 0.175, South
V232	CON EDISON	GROVE ST & FISCHER C	NJ MANIFEST	Lower	922, 0.175, South
T233	BARGAM HOME	36-38 MITCHELL PLACE	NY LTANKS	Higher	940, 0.178, East
W234	RECKSON METRO CENTER	360 HAMILTON AVE	NY AST, US AIRS	Higher	943, 0.179, NNE

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
W235	RECKSON ASSOCIATES	360 HAMILTON AVE - M	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Higher	943, 0.179, NNE
W236	A T & T	360 HAMILTON AVE	RCRA-SQG, NY MANIFEST	Higher	943, 0.179, NNE
T237	APARTMENT BLDG	37-43 MITCHELL PL	NY LTANKS	Higher	970, 0.184, ESE
U238	CON EDISON MANHOLE:	LEXINGTON AVE & E MA	RCRA-LQG, FINDS, ECHO	Lower	981, 0.186, West
U239	CON EDISON	S LEXINGTON AV & MAI	NY MANIFEST	Lower	984, 0.186, West
U240	CON EDISON VAULT: 70	MAIN ST & LEXINGTON	RCRA NonGen / NLR, NY MANIFEST	Lower	984, 0.186, West
U241	CON EDISON	S. LEXINGTON AVE &AM	NY MANIFEST	Lower	984, 0.186, West
U242	CON EDISON MANHOLE:	LEXINGTON AVE & MAIN	RCRA NonGen / NLR, NY MANIFEST	Lower	984, 0.186, West
T243	APT. BUILDING	40 MITCHELL PLACE	NY UST	Higher	988, 0.187, East
T244	APARTMENT BUILDING	40 MITCHELL PL	NY LTANKS	Higher	988, 0.187, East
X245	CON EDISON	148 MAMARONECK AVE	NJ MANIFEST	Higher	1007, 0.191, SE
X246	CON EDISON	148 MAMARONECK AVE F	RCRA NonGen / NLR, NY MANIFEST	Higher	1007, 0.191, SE
X247	CON EDISON	148 MAMARONECK AVE	RCRA NonGen / NLR	Higher	1007, 0.191, SE
Y248	MARRIOT INN	5 BARKER AVE	NY LTANKS	Lower	1009, 0.191, NNW
Y249	RESIDENCE INN - TTF	5 BARKER AVE	NY LTANKS	Lower	1009, 0.191, NNW
X250	CON EDISON	MAMARONECK AVE & E P	NY MANIFEST	Higher	1010, 0.191, SE
X251	CON EDISON	E POST RD & MAMMARON	NJ MANIFEST	Higher	1010, 0.191, SE
X252	CON EDISON	E POST RD & MAMMARON	NY MANIFEST	Higher	1010, 0.191, SE
X253	CON EDISON MANHOLE 3	MAMARONECK AVE & E P	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1010, 0.191, SE
X254	CON EDISON MANHOLE 3	MAMARONECK AVE & E P	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1010, 0.191, SE
X255	CON EDISON	E POST RD & MAMMARON	RCRA NonGen / NLR, FINDS, ECHO	Higher	1010, 0.191, SE
Z256	CON EDISON	N LEXINGTON AVE & MA	RCRA NonGen / NLR	Lower	1012, 0.192, WSW
Z257	CON EDISON - MANHOLE	MARTINE AVE & LE	RCRA-LQG	Lower	1012, 0.192, WSW
Z258	CON EDISON SERVICE B	S LEXINGTON AVE & MA	RCRA NonGen / NLR, NY MANIFEST	Lower	1012, 0.192, WSW
Z259	CON EDISON MANHOLE:	MARTINE AVE & S LEXI	RCRA NonGen / NLR, NY MANIFEST	Lower	1012, 0.192, WSW
Z260	CON EDISON	N LEXINGTON AVE & MA	NJ MANIFEST	Lower	1012, 0.192, WSW
Z261	CON EDISON	MARTINE AVE & LEXING	NY MANIFEST	Lower	1012, 0.192, WSW
Z262	CON EDISON SERVICE B	S LEXINGTON AVE & MA	RCRA NonGen / NLR, NY MANIFEST	Lower	1012, 0.192, WSW
Z263	CON EDISON	N LEXINGTON AVE & MA	NY MANIFEST	Lower	1012, 0.192, WSW
Z264	CON EDISON	S. LEXINGTON AV &AMP	NY MANIFEST	Lower	1012, 0.192, WSW
Z265	GALLERIA WEST GARAGE	MARTINE AVE & SO LEX	NY UST, NY AST	Lower	1012, 0.192, WSW
X266	HALPERN ENTERPRISES	170 EAST POST ROAD	NY LTANKS	Higher	1019, 0.193, SE
X267	DEVON PLAZA REALTY	170 EAST POST ROAD	NY UST	Higher	1019, 0.193, SE
Y268	CON EDISON	COTTAGE PL & BARKER	NY MANIFEST	Lower	1022, 0.194, NNW
Y269	CON EDISON MANHOLE:	BARKER ST & COTTAGE	RCRA NonGen / NLR, NY MANIFEST	Lower	1022, 0.194, NNW
Y270	CON EDISON VAULT: 52	COTTAGE PL & BARKER	RCRA NonGen / NLR, FINDS	Lower	1022, 0.194, NNW
AA271	EDGAR	1 BARKER AVE	NY LTANKS	Lower	1025, 0.194, NW
Z272	77 SOUTH LEXINGTON A	77 SOUTH LEXINGTON A	NY LTANKS	Lower	1026, 0.194, WSW
Z273	PUBLIC SAFETY BUILDI	77 SOUTH LEXINGTON A	NY UST, NY AST	Lower	1026, 0.194, WSW

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AB274	COMMERCIAL	130-144 EAST POST RD	NY LTANKS	Higher	1029, 0.195, SSE
X275	151 EAST POST ROAD C	151 EAST POST ROAD	NY UST	Higher	1032, 0.195, SE
X276	COMMERCIAL PROERTY	151 EAST POST ROAD	NY LTANKS	Higher	1032, 0.195, SE
X277	OFFICE BLDG	171 EAST POST RD	NY LTANKS	Higher	1041, 0.197, SE
AC278	170 GRAND STREET ASS	170 GRAND STREET	NY UST, NY AST	Higher	1042, 0.197, South
AC279	170 GRAND STREET	170 GRAND STREET	NY LTANKS, NY Spills	Higher	1042, 0.197, South
AD280	CON EDISON	LEXINGTON & HAMILTON	RCRA NonGen / NLR, FINDS, ECHO, NJ MANIFEST, NY...	Lower	1045, 0.198, WNW
AD281	CON EDISON	HAMILTON & N LEXINGT	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1045, 0.198, WNW
AD282	CON EDISON MANHOLE:	HAMILTON AVE & LEXIN	RCRA NonGen / NLR, NY MANIFEST	Lower	1045, 0.198, WNW
X283	CON EDISON MANHOLE:	149 MAMARONECK AVE F	RCRA NonGen / NLR, NY MANIFEST	Higher	1053, 0.199, SE
AE284	MGH CO., LLC	45 MITCHELL PLACE	NY UST	Higher	1061, 0.201, East
AE285	MGH CO	45 MITCHELL PLACE	NY LTANKS	Higher	1061, 0.201, East
AE286	APT BUILDING	45 MITCHELL PLACE	NY LTANKS	Higher	1061, 0.201, East
AB287	WESTCHESTER COUNTY O	112 EAST POST ROAD	NY UST, NY AST	Higher	1064, 0.202, SSE
AB288	WESTCHESTER OFFICE B	112 EAST POST ROAD	NY LTANKS	Higher	1064, 0.202, SSE
AB289	WESTCHESTER COUNTY -	112 E POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1064, 0.202, SSE
AF290	CON EDISON SERVICE B	FISHER CT & QUARROPA	RCRA NonGen / NLR, FINDS	Lower	1069, 0.202, SSW
AF291	CON EDISON	QUARROPAS ST & FISHE	NY MANIFEST	Lower	1069, 0.202, SSW
AF292	CON EDISON MANHOLE:	QUARROPAS ST & FISCH	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1069, 0.202, SSW
AF293	CON EDISON	FISHER CT & QUARROPA	NY MANIFEST	Lower	1069, 0.202, SSW
AF294	CHARLES L. BRIEANT U	300 QUARROPAS STREET	NY UST, NY AST	Lower	1070, 0.203, SSW
AB295	COACHMAN HOTEL	123 EAST POST ROAD	NY LTANKS	Higher	1079, 0.204, SSE
AB296	WESTHAB COACHMAN FAM	123 EAST POST ROAD	NY UST	Higher	1079, 0.204, SSE
AB297	COACHMAN HOTEL	123 E POST RD	RCRA-CESQG	Higher	1079, 0.204, SSE
AA298	CON EDISON MANHOLE 4	BARKER AVE & GROVE S	RCRA NonGen / NLR, NY MANIFEST	Lower	1088, 0.206, NW
AG299	CON EDISON MANHOLE	WALLER AVE & E POST	RCRA NonGen / NLR, NY MANIFEST	Higher	1091, 0.207, ESE
AG300	CONSOLIDATED EDISON	WALLER AVE & EAST PO	NY MANIFEST	Higher	1091, 0.207, ESE
AG301	CON EDISON	POST RD & WALLER AVE	NY MANIFEST	Higher	1091, 0.207, ESE
AH302	STATION PLAZA	76 SOUTH LEXINGTON A	NY UST, NY AST	Lower	1102, 0.209, SW
AI303	SAFE FLIGHT INSTRUME	20 NEW KING ST	NY UST, RCRA NonGen / NLR, FINDS, ECHO, NY...	Lower	1105, 0.209, WNW
AG304	PIP PRINTING	190 E POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1118, 0.212, ESE
AG305	PUCKHINKONNUCK CORP.	190 EAST POST ROAD	NY UST, NY AST	Higher	1118, 0.212, ESE
AI306	COMMERICAL BUILDING	10 NEW KING STREET	NY LTANKS	Lower	1139, 0.216, WNW
AC307	WESTCHESTER HOBBIES	104 E POST RD	RCRA NonGen / NLR, FINDS, ECHO	Higher	1140, 0.216, SSE
308	WHITE PLAINS CITY OF	MARTINE AVE PUBLIC L	RCRA NonGen / NLR	Higher	1142, 0.216, East
AD309	WHITE PLAINS GENL AU	76 HAMILTON AVE	RCRA NonGen / NLR, FINDS, ECHO	Lower	1142, 0.216, WNW
AD310	CON EDISON MANHOLE 5	LEXINGTON AVE & NEW	RCRA NonGen / NLR	Lower	1148, 0.217, WNW
AD311	CONSOLIKDATED EDISON	NEW ST & LEXINGTON A	NY MANIFEST	Lower	1148, 0.217, WNW
W312	VAULT 6174	400 HAMILTON AVENUE	NY LTANKS, NY Spills	Higher	1149, 0.218, NNE

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
W313	WHITE PLAINS LL CENT	400 HAMILTON AVE	RCRA NonGen / NLR	Higher	1149, 0.218, NNE
W314	AT&T	400 HAMILTON AVE	RCRA-SQG, NY MANIFEST	Higher	1149, 0.218, NNE
W315	CON EDISON	400 HAMILTON AVE & E	NJ MANIFEST	Higher	1149, 0.218, NNE
W316	WHITE PLAINS LL CENT	400 HAMILTON AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1149, 0.218, NNE
W317	CON EDISON - VAULT 5	400 HAMILTON AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1149, 0.218, NNE
W318	CON EDISON	400 HAMILTON AVE & E	NY MANIFEST	Higher	1149, 0.218, NNE
AJ319	CON EDISON MANHOLE:	BARKER AVE & CHURCH	RCRA NonGen / NLR, NY MANIFEST	Higher	1152, 0.218, North
AJ320	CON EDISON SERVICE B	BARKER AVE & CHURCH	RCRA NonGen / NLR, NY MANIFEST	Higher	1152, 0.218, North
AA321	PEPE CADILLAC	15 WATER STREET	NY AST	Lower	1158, 0.219, NW
AA322	PEPE CADILLAC	15 WATER STREET	NY UST	Lower	1158, 0.219, NW
AI323	OFFICE BLDG	4 NEW KING ST	NY LTANKS	Lower	1160, 0.220, WNW
AI324	WHITE PLAINS MGP SIT	9 NEW STREET AND 12	EDR MGP	Lower	1160, 0.220, WNW
AI325	CONSOLIDATED EDISON	9 NEW STREET	NY MANIFEST	Lower	1160, 0.220, WNW
AI326	CON EDISON - WHITE P	9 NEW STREET	RCRA-SQG	Lower	1160, 0.220, WNW
AG327	SPILL NUMBER 9900622	179 EAST COAST RD	NY LTANKS	Higher	1165, 0.221, SE
AI328	CE - WHITE PLAINS MG	9 NEW STREET AND 12	NY ENG CONTROLS, NY INST CONTROL, NY VCP	Lower	1166, 0.221, NW
AI329	CONSOLIDATED EDISON	12 WATER ST - MH 561	NY MANIFEST	Lower	1166, 0.221, NW
AI330	NUCLEAR DEVELOPMENT	5 NEW STREET	FUSRAP	Lower	1173, 0.222, WNW
AI331	SPILL NUMBER 0000953	1 NEW KING STREET	NY LTANKS	Lower	1186, 0.225, WNW
AH332	OUR LADY OF MT CARME	92 SOUTH LEXINGTON A	NY UST	Lower	1190, 0.225, SW
AH333	OUR LADY OF MOUNT CA	92 SOUTH LEXINGTON A	NY LTANKS	Lower	1190, 0.225, SW
AK334	WINDBROOK HOUSING	223 DR MARTIN LUTHER	NY LTANKS	Higher	1193, 0.226, South
AK335	WINBROOK HOUSING DEV	223 DR. MARTIN LUTHE	NY UST	Higher	1193, 0.226, South
AC336	CON EDISON	100 POST RD	RCRA NonGen / NLR	Higher	1195, 0.226, South
AC337	CON EDISON	100 POST RD	NJ MANIFEST	Higher	1195, 0.226, South
AC338	CON EDISON	100 POST RD	NY MANIFEST	Higher	1195, 0.226, South
AG339	193-197 EAST POST RO	193-197 EAST POST RO	NY UST, NY AST	Higher	1199, 0.227, ESE
AG340	APARTMENT BUILDING	193 EAST POST ROAD	NY LTANKS	Higher	1199, 0.227, ESE
AK341	WHITE PLAIN HOUSING	225 GROVE ST	NY LTANKS	Higher	1200, 0.227, South
AL342	REAL ESTATE - TTF	6 CHESTER AVE	NY LTANKS	Higher	1215, 0.230, SSE
AC343	CON ED	E NEW YORK POST RD &	NY MANIFEST	Higher	1215, 0.230, South
AC344	CON EDISON	E POST RD & GRAND ST	NJ MANIFEST	Higher	1215, 0.230, South
AC345	CON EDISON	E POST RD & GRAND ST	RCRA NonGen / NLR	Higher	1215, 0.230, South
AC346	CON ED	E POST RD & GRAND ST	NY MANIFEST	Higher	1215, 0.230, South
AC347	CON EDISON	E NEW YORK POST RD &	NJ MANIFEST	Higher	1215, 0.230, South
AC348	CON EDISON	E POST RD & GRAND ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	1215, 0.230, South
X349	STEWARD	165 MAMARONECK AVENU	NY LTANKS	Higher	1228, 0.233, SE
AC350	CONSOLIDATED EDISON	E NY POST RD & CROMW	NY MANIFEST	Higher	1236, 0.234, South
AC351	CON EDISON	CROMWELL PL & E POST	RCRA NonGen / NLR	Higher	1236, 0.234, South

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AC352	CON ED	CROMWELL PL & E POST	NY MANIFEST	Higher	1236, 0.234, South
AC353	CON EDISON	CROMWELL PL & E. NY	NY MANIFEST	Higher	1236, 0.234, South
AC354	CON EDISON	CROMWELL PL & E POST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1236, 0.234, South
AE355	URBAN LEAGUE OF WEST	61 MITCHELL PLACE	NY UST	Higher	1251, 0.237, East
AJ356	BIRCHWOOD ASSOCIATES	35 BARKER AVENUE	NY UST	Higher	1253, 0.237, North
AM357	COLIN SERVICE SYSTEM	1 BROCKWAY PLACE	NY UST	Higher	1253, 0.237, ENE
AL358	RESIDENTS	8 CHESTER AVE	NY LTANKS	Higher	1254, 0.237, SSE
AN359	GATEWAY BLDG	1 N LEXINGTON AVE 13	NY MANIFEST	Lower	1257, 0.238, West
AN360	GATEWAY CENTER ONE	1 NORTH LEXINGTON AV	NY AST	Lower	1257, 0.238, West
AN361	CUSHMAN & WAKEFIELD	1 N LEXINGTON AVE	PA MANIFEST	Lower	1257, 0.238, West
AN362	CUSHMAN & WAKEFIELD	ONE N LEXINGTON AVE	PA MANIFEST	Lower	1257, 0.238, West
AN363	GATEWAY PLAZA	1 NORTH LEXINGTON AV	NY UST	Lower	1257, 0.238, West
AN364	GATEWAY BUILDING	1 N LEXINGTON AVE 1	RCRA-CESQG, FINDS, NJ MANIFEST	Lower	1257, 0.238, West
AN365	GATEWAY BLDG	1 NORTH LEXINGTON AV	NY LTANKS, NY Spills	Lower	1257, 0.238, West
AO366	KEMPLER RESIDENCE	169 MAMARONECK AVE	NY LTANKS	Higher	1279, 0.242, SE
AM367	SEARS ROEBUCK & CO 1	MAIN ST	RCRA-CESQG	Higher	1283, 0.243, ENE
AM368	WALMART #3441	275 MAIN ST	RCRA-SQG, NY MANIFEST	Higher	1283, 0.243, ENE
AM369	SEARS	MAIN ST	NY Spills, NY MANIFEST	Higher	1283, 0.243, ENE
AL370	CHESTER MAPLE PARKIN	9 CHESTER AVE	NY MANIFEST	Higher	1288, 0.244, SSE
AL371	CHESTER MAPLE PARKIN	9 CHESTER AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1288, 0.244, SSE
AJ372	BARKER AVENUE OWNERS	33 BARKER AVENUE	NY UST, NY AST	Higher	1290, 0.244, North
AO373	JOHN DALE, INC.	176-180 MAMRONECK AV	NY UST	Higher	1297, 0.246, SE
AO374	JOHN DALE INC	178 MAMORENECK AVE	NY LTANKS	Higher	1297, 0.246, SE
AO375	CON EDISON	184 MAMARONECK AVE &	RCRA NonGen / NLR, NY MANIFEST	Higher	1297, 0.246, SE
AP376	CON EDISON	445 HAMILTON AVE	NY MANIFEST	Higher	1311, 0.248, NE
AP377	CON EDISON	445 HAMILTON AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1311, 0.248, NE
AP378	CON EDISON	445 HAMILTON AVE	NJ MANIFEST	Higher	1311, 0.248, NE
AQ379	APARTMENT BLDG	40 BARKER AVE	NY LTANKS	Higher	1334, 0.253, NNE
380	240 EAST POST RD	240 EAST POST RD	NY LTANKS	Lower	1372, 0.260, ESE
AM381	LASALLE PARTNERS	1 NORTH BROADWAY	NY LTANKS	Higher	1382, 0.262, ENE
AQ382	COMMERCIAL	41 BARKER AVE	NY LTANKS, NY Spills	Higher	1384, 0.262, NNE
AM383	ES GORDON	7-11 SOUTH BROADWAY	NY LTANKS	Higher	1394, 0.264, ENE
AR384	BART GOLDBERG APT. B	277 MARTINE AVE	NY LTANKS	Higher	1402, 0.266, East
385	VILLANOVA - TTF	144 CHURCH ST	NY LTANKS	Higher	1446, 0.274, North
AP386	OFFICE BUILDING	15 NORTH BROADWAY	NY LTANKS, NY Spills	Higher	1480, 0.280, NE
AR387	CEMMEL HOUSE BUILDIN	300 MARTINE AVE	NY LTANKS, NY Spills	Lower	1504, 0.285, East
AS388	OFFICE BLDG	203 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	1514, 0.287, SE
AT389	WIND BROOK APTS.	33 FISHER AVE	NY LTANKS, NY Spills	Lower	1548, 0.293, SW
390	@	44 NORTH BROADWAY	NY LTANKS, NY Spills	Lower	1562, 0.296, East

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AU391	GARDEN APARTMENTS	101 N. BROADWAY	NY LTANKS	Higher	1571, 0.298, NE
AT392	HYDRAULIC FLUID TO S	134 SOUTH LEXINGTON	NY LTANKS, NY Spills	Lower	1577, 0.299, SSW
AR393	COUNTY OFFICE BLD	MARTINE AVE	NY LTANKS, NY Spills	Lower	1600, 0.303, East
394	PARK ROSE	12 WESTCHESTER AVE	NY LTANKS, NY Spills	Lower	1607, 0.304, ENE
AU395	BUILDING	20 NORTH BROADWAY	NY LTANKS, NY Spills	Higher	1614, 0.306, NE
396	PIRRO, MONSELL REALT	40 WALLER AVE	NY LTANKS	Higher	1621, 0.307, SE
AS397	WHITE PLAINS DPW	MAPLE & MAMARONECK A	NY LTANKS	Higher	1636, 0.310, SE
AS398	WHITE PLAINS-FIRE HO	MAMARONECK & MAPLE A	NY LTANKS	Higher	1636, 0.310, SE
AV399	GREENRIDGE ESTATES	1-13 GREENRIDGE AVE	NY LTANKS	Higher	1640, 0.311, SSE
AV400	CITY PARKING GARAGE	CHESTER AVE MARBLE A	NY LTANKS	Higher	1641, 0.311, SSE
AU401	APT BUILDING	16 NORTH BROADWAY	NY LTANKS, NY Spills	Higher	1681, 0.318, NE
AT402	CHURCH	65 FISHER AVE	NY LTANKS, NY Spills	Lower	1688, 0.320, SW
AU403	CON ED	10 NORTH BROADWAY	NY LTANKS, NY Spills, NY MANIFEST	Higher	1702, 0.322, NE
AW404	PATRIOT MANAGEMENT	2 WESTCHESTER AVE	NY LTANKS, NY Spills	Higher	1717, 0.325, ENE
405	PRESBYTERIAN CHURCH	39 NORTH BROADWAY	NY LTANKS	Higher	1739, 0.329, NNE
406	APARTMENT	8 LONGVIEW AVE	NY LTANKS, NY Spills	Higher	1764, 0.334, South
AX407	WHITE PLAINS HOSPITA	41 E POST RD	NY LTANKS, NY Spills, NY MANIFEST	Higher	1768, 0.335, South
AX408	WHITE PLAINS HOSPITA	41 EAST POST ROAD	NY LTANKS	Higher	1768, 0.335, South
AV409	JOHN L WHITE RESIDEN	9 GREENRIDGE AVE	NY LTANKS	Higher	1800, 0.341, SSE
AY410	YOUNG COAL & LUMBER	55 BANK STREET	NY BROWNFIELDS, NY MANIFEST	Lower	1801, 0.341, WSW
AZ411	COMMERCIAL PROPERTY	235 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	1805, 0.342, SSE
AY412	PEPE MOTORS INC	50 BANK ST	RCRA-CESQG, NY LTANKS, FINDS, ECHO, NY MANIFEST	Lower	1823, 0.345, WSW
AW413	CON ED	300 MAIN ST	NY LTANKS, NY MANIFEST	Higher	1851, 0.351, ENE
414	CROWN PLAZA HOTEL	66 HALE AVE	NY LTANKS	Lower	1873, 0.355, ESE
AX415	WHITE PLAINS HOSPITA	DAVIS AVE	NY LTANKS, NY Spills	Higher	1881, 0.356, South
AX416	HOSPITAL (UNK NAME)	41 EAST COAST ROAD	NY LTANKS	Higher	1881, 0.356, South
AX417	WHITE PLAINS HOSPITA	MAPLE AVE	NY LTANKS	Higher	1881, 0.356, South
BA418	BUSINESS	7 LAKE STREET	NY LTANKS, NY Spills	Higher	1914, 0.363, NE
AZ419	WHITE PLAINS YMCA	250 MAMARONECK AVE	NY LTANKS	Higher	1930, 0.366, SSE
AX420	WHITE PLAINS HOSPITA	EAST NEW YORK POST R	NY LTANKS	Lower	1954, 0.370, SSW
BB421	APT. BUILDING	50 NORTH BROADWAY	NY LTANKS, NY Spills	Higher	1964, 0.372, NNE
BC422	PRIVATE ENTERPRISE	20 FERRIS AVE	NY LTANKS, NY Spills	Lower	1966, 0.372, NW
BD423	PDUZZI - TTF	188 CHURCH ST	NY LTANKS	Higher	1985, 0.376, North
BC424	FIRE STATION 2		NY LTANKS	Lower	1998, 0.378, NW
AZ425	YMCA	260 MAMARONECK AVE	NY LTANKS	Higher	2008, 0.380, SSE
426	RESIDENCE	325 MAIN ST	NY LTANKS	Higher	2024, 0.383, ENE
BE427	SPILL NUMBER 0103645	12 EAST POST RD	NY LTANKS	Lower	2035, 0.385, SSW
BF428	35 PARK AVENUE	35 PARK AVENUE	NY LTANKS	Higher	2049, 0.388, NNW
BE429	GETTY SERVICE STATIO	11 EAST POST ROAD	NY LTANKS	Lower	2064, 0.391, SSW

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BE430	SPILL NUMBER 8600048	11 EAST POST ROAD	NY LTANKS	Lower	2064, 0.391, SSW
431	WESTCHESTER SHOPPING	WEST AVE & PAWLING S	NY LTANKS	Lower	2068, 0.392, East
BB432	SPILL NUMBER 8807217	52 NORTH BROADWAY	NY LTANKS	Higher	2076, 0.393, NNE
BE433	GETTY S/S	11 EAST POND ROAD	NY LTANKS	Higher	2095, 0.397, SSW
434	APT. HOUSE	82 BANK STREET	NY LTANKS, NY Spills	Higher	2109, 0.399, SW
435	RESIDENCE	25 LONGVIEW AVE	NY LTANKS	Higher	2109, 0.399, South
436	PRIVATE HOME	11 PARK AVE	NY LTANKS	Higher	2115, 0.401, North
BA437	APT BUILDING	16 LAKE STREET	NY LTANKS	Higher	2119, 0.401, NE
438	FRANKLIN APTS	25 FRANKLIN AVE	NY LTANKS, NY Spills	Lower	2131, 0.404, ENE
BG439	WHITE PLAINS HONDA	31 WESTMPORELAND AVE	NY LTANKS	Lower	2146, 0.406, WSW
BH440	PRIVATE HOME	18 DEKALB AVE	NY LTANKS, NY Spills	Lower	2150, 0.407, SE
BH441	TORELLI	21 DEKALB AVE	NY LTANKS	Higher	2164, 0.410, SE
BE442	SPILL NUMBER 0013009	1 EAST POST RD	NY LTANKS	Lower	2192, 0.415, SSW
BD443	SPILL NUMBER 0209590	25 PARK AVE	NY LTANKS	Higher	2194, 0.416, North
444	ROADWAY	285 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	2206, 0.418, SSE
BG445	MUNICIPAL GARAGE	111	NY LTANKS	Lower	2214, 0.419, WSW
BE446	BISCARDI CLEANERS	201 SO. LEXINGTON AV	NY LTANKS, NY Spills, NY DRYCLEANERS	Lower	2223, 0.421, SSW
447	LAZZARO	47 PARK AVE	NY LTANKS	Higher	2231, 0.423, NNW
BG448	CIVIC CENTER MOTORS	31 WESTMORELAND AVE	NY LTANKS, NY Spills	Lower	2233, 0.423, WSW
449	WHITE PLAINS MED CEN	170 MAPLE AVE	NY LTANKS	Higher	2235, 0.423, South
450	APARTMENT BLDG	21 GREENRIDGE AVE	NY LTANKS, NY Spills	Higher	2258, 0.428, SSE
451	YWCA	69 NORTH BROADWAY	NY LTANKS	Higher	2259, 0.428, NNE
BF452	SPILL NUMBER 9909558	7 PARK CIRCLE	NY LTANKS	Higher	2278, 0.431, NNW
BG453	COMMERCIAL PROPERTY	39 WESTMORELAND AVE	NY LTANKS, NY Spills	Lower	2283, 0.432, WSW
BG454	IRVINGTON	IRVINGTON	NY LTANKS	Lower	2302, 0.436, SW
455	JSD MANAGEMENT	15 LAKE ST	NY LTANKS	Higher	2315, 0.438, NE
456	KEY FORD OF WHITE PL	80 WESTCHESTER AVE	RCRA-CESQG, NY LTANKS, FINDS, ECHO, NY MANIFEST	Lower	2343, 0.444, East
457	SUBODH DESHMUKH RESI	39 PARKVIEW CT	NY LTANKS	Higher	2348, 0.445, North
BI458	AVIS	20 WEST POST RD	NY LTANKS	Lower	2379, 0.451, SSW
459	SPILL NUMBER 0011055	2 AMHERST PL	NY LTANKS	Lower	2415, 0.457, NE
460	STEWART PLACE CONDOS	10 STEWART PLACE	NY LTANKS, NY Spills	Higher	2449, 0.464, NNE
461	GABERIAL	7 FAIRVIEW AVE	NY LTANKS	Higher	2453, 0.465, NW
462	BERTE HOME	3 CHURCH COURT	NY LTANKS	Higher	2469, 0.468, NNW
BJ463	10 SCHOOL STREET	10 SCHOOL STREET	NY LTANKS	Higher	2481, 0.470, West
464	MILLER CENTER FOR NU	37 DEKALD AVE	NY LTANKS	Higher	2493, 0.472, SE
BJ465	12 HARMON STREET	12 HARMON STREET	NY LTANKS	Higher	2502, 0.474, West
BI466	WHITE PLAINS LINC/ME	25 WEST COAST RD	NY LTANKS	Higher	2524, 0.478, SSW
BK467	FIRE HOUSE # 4	MAPLE AVE & S LEXING	NY LTANKS	Higher	2536, 0.480, SSW
468	SPILL NUMBER 0310118	79 NORTH BROADWAY	NY LTANKS, NY Spills	Higher	2537, 0.480, North

MAPPED SITES SUMMARY

Target Property Address:
100 MAIN STREET
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BL469	PRIVATE HOME	43 LONGVIEW AVE	NY LTANKS	Higher	2566, 0.486, South
BK470	GREAT GRANT MANOR PR	235 SOUTH LEXINGTON	NY LTANKS	Higher	2584, 0.489, SSW
471	FELIX DAVILA	36 DAVIS RD	NY LTANKS	Higher	2588, 0.490, South
472	REALTY TRANSACTION	52 PARK CIRCLE	NY LTANKS	Higher	2597, 0.492, NNW
473	RESIDENCE	23 OAKWOOD RD	NY LTANKS	Higher	2623, 0.497, South
BL474	RESIDENTS	44 LONGVIEW AVE	NY LTANKS	Higher	2627, 0.498, South
475	NEW YORK PRESBYTERIA	21 BLOOMINGDALE ROAD	RCRA-LQG, NY LTANKS, NY CBS, NY CBS AST, NY...	Lower	2629, 0.498, ESE
476	BILTMORE TOWERS APTS	30 LAKE STREET	NY LTANKS, NY Spills	Lower	2630, 0.498, NE
477	AUTOMOBILE CLUB OF N	101 WESTMORELAND AVE	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY...	Lower	2670, 0.506, WSW
478	MAMARONECK AVENUE DR	359-369 MAMARONECK A	NY SHWS, NY Spills	Higher	2847, 0.539, SSE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
J.C. PENNEY 100 MAIN ST WHITE PLAINS, NY 10601	NY UST Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019 Status: 5. Tank converted to Non-Regulated use Status: 4. Closed - in place Id/Status:: 3-173665 Id/Status:: 3-600104 Site Status: Unregulated: <1101 gal. PBS	N/A
EXPRESSLY PORTRAITS 100 MAIN ST - GALLER WHITE PLAINS, NY 10603	RCRA NonGen / NLR EPA ID:: NY0000969121 FINDS Registry ID:: 110004322849 ECHO Registry ID: 110004322849 NY MANIFEST EPA ID: NY0000969121	NY0000969121
MACYS WHITE PLAINS C 100 MAIN ST WHITE PLAINS, NY 10601	FINDS Registry ID:: 110054890347 ECHO Registry ID: 110054890347	N/A
MACY'S EAST #55 100 MAIN ST WHITE PLAINS, NY 10601	NY MANIFEST EPA ID: NYR000120329	N/A
MACYS - WHITE PLAINS 100 MAIN ST WHITE PLAINS, NY 10601	FINDS Registry ID:: 110016725748 ECHO Registry ID: 110016725748	N/A
PICTURE PEOPLE THE 100 MAIN ST SPACE 32 WHITE PLAINS, NY 10603	RCRA-SQG EPA ID:: NYR000084806 FINDS Registry ID:: 110004561402 ECHO Registry ID: 110004561402 NY MANIFEST	NYR000084806

EPA ID: NYR000084806

100 E. MAIN ST
100 E. MAIN ST
WHITE PLAINS, NY 10601

NY COOLING TOWERS — N/A

MACYS - WHITE PLAINS
100 MAIN ST
WHITE PLAINS, NY 10601

RCRA-SQG — NYR000120329
EPA ID:: NYR000120329

FINDS
Registry ID:: 110009462553

ECHO
Registry ID: 110009462553

100 MAIN STREET
100 MAIN STREET
WHITE PLAINS, NY 10601

NY COOLING TOWERS — N/A

100 E. MAIN ST
100 E. MAIN ST
WHITE PLAINS, NY 10601

NY COOLING TOWERS — N/A

GALLERIA OF WHITE PL
100 MAIN STREET
WHITE PLAINS, NY 10601

FINDS — N/A
Registry ID:: 110019206599

100 MAIN STREET
100 MAIN STREET
WHITE PLAINS, NY 10601

NY COOLING TOWERS — N/A

J C PENNEY CO INC
100 MAIN ST
WHITE PLAINS, NY 10601

NY LTANKS — NY0000806901
Site ID: 137993
Spill Number/Closed Date: 9102767 / 1991-06-13

NY Spills
Site ID: 137992
Site ID: 137995
Site ID: 382912
Site ID: 104864
Spill Number/Closed Date: 0302779 / 2003-06-16
Spill Number/Closed Date: 9204133 / 1992-08-04
Spill Number/Closed Date: 0703055 / 2007-06-14
Spill Number/Closed Date: 0211359 / 2005-02-27

RCRA NonGen / NLR
EPA ID:: NY0000806901

NY MANIFEST
EPA ID: NY0000806901

C P I PHOTO FINISH
100 MAIN ST STE 301
WHITE PLAINS, NY 10601

RCRA NonGen / NLR — NYR000034082

EXECUTIVE SUMMARY

EPA ID:: NYR000034082

FINDS
Registry ID:: 110004531374

ECHO
Registry ID: 110004531374

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROL ---------- Sites with Institutional Controls

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal leaking storage tank lists

INDIAN LUST - Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS - Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST - Underground Storage Tank Listing
NY CBS UST - Chemical Bulk Storage Database
NY MOSF UST - Major Oil Storage Facilities Database
NY MOSF - Major Oil Storage Facility Site Listing
NY MOSF AST - Major Oil Storage Facilities Database
INDIAN UST - Underground Storage Tanks on Indian Land
NY TANKS - Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL - Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP - Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP - Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS - A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWTIRE - Registered Waste Tire Storage & Facility List
NY SWRCY - Registered Recycling Facility List
INDIAN ODI - Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9 - Torres Martinez Reservation Illegal Dump Site Locations
ODI - Open Dump Inventory
IHS OPEN DUMPS - Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL - Delisted National Clandestine Laboratory Register
NY DEL SHWS - Delisted Registry Sites
US CDL - National Clandestine Laboratory Register
NY PFAS - PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST - Historical Petroleum Bulk Storage Database
NY HIST AST - Historical Petroleum Bulk Storage Database

EXECUTIVE SUMMARY

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data
COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List

EXECUTIVE SUMMARY

NY RGA LF..... Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 5 RCRA-LQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #4745 EPA ID:: NYR000194852	***26-32 MAMARONECK AVE***	***E 0 - 1/8 (0.053 mi.)***	***F93***	***169***
CON EDISON MANHOLE: EPA ID:: NYP004308268	***221 MAIN ST***	***NE 0 - 1/8 (0.067 mi.)***	***G104***	***194***
TARGET STORE T1358 EPA ID:: NYR000134106	***9 CITY PL***	***ENE 1/8 - 1/4 (0.157 mi.)***	***Q204***	***349***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID:: NYP004303764	***LEXINGTON AVE & E MA***	***W 1/8 - 1/4 (0.186 mi.)***	***U238***	***420***
CON EDISON - MANHOLE EPA ID:: NYP004303145	MARTINE AVE & LE	WSW 1/8 - 1/4 (0.192 mi.)	Z257	453

EXECUTIVE SUMMARY

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
A T & T EPA ID:: NYD986998060	***360 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.179 mi.)***	***W236***	***415***
AT&T EPA ID:: NYD070955828	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W314***	***555***
WALMART #3441 EPA ID:: NYR000134999	***275 MAIN ST***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AM368***	***660***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - WHITE P EPA ID:: NYR000023275	9 NEW STREET	WNW 1/8 - 1/4 (0.220 mi.)	AI326	580

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 03/01/2018 has revealed that there are 8 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WESTCHESTER COUNTY O EPA ID:: NYD072705213	***148 MARTINE AVE***	***SSE 0 - 1/8 (0.010 mi.)***	***D49***	***91***
CIRCUIT CITY STORE # EPA ID:: NYN008016099	***220 MAIN ST***	***ENE 1/8 - 1/4 (0.143 mi.)***	***Q196***	***338***
COACHMAN HOTEL EPA ID:: NY0000895086	123 E POST RD	SSE 1/8 - 1/4 (0.204 mi.)	AB297	519
SEARS ROEBUCK & CO 1 EPA ID:: NY0000923193	MAIN ST	ENE 1/8 - 1/4 (0.243 mi.)	AM367	657

Lower Elevation	Address	Direction / Distance	Map ID	Page
NEW YORK POWER AUTH EPA ID:: NYD986982999	***123 MAIN ST***	***WNW 0 - 1/8 (0.023 mi.)***	***B67***	***125***
WESTCHESTER COUNTY C EPA ID:: NYR000124206	110 DR MARTIN LUTHER	SSW 0 - 1/8 (0.100 mi.)	N136	240
EXXON DIV OF CFI #70 EPA ID:: NYD013387436	***274 HAMILTON AVE & C***	***N 0 - 1/8 (0.123 mi.)***	***M174***	***292***
GATEWAY BUILDING	***1 N LEXINGTON AVE 1***	***W 1/8 - 1/4 (0.238 mi.)***	***AN364***	***644***

EPA ID:: NYD986984698

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 11/12/2018 has revealed that there are 2 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MAMARONECK AVENUE DR Site Code: 387008	***359-369 MAMARONECK A***	***SSE 1/2 - 1 (0.539 mi.)***	***478***	***930***

Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTOMOBILE CLUB OF N Site Code: 374633	***101 WESTMORELAND AVE***	***WSW 1/2 - 1 (0.506 mi.)***	***477***	***906***

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the list.

A review of the NY SWF/LF list, as provided by EDR, and dated 12/31/2018 has revealed that there is 1 NY SWF/LF site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
RAILROAD ONE LF	***148 MARTINE AVENUE***	***SE 0 - 1/8 (0.013 mi.)***	***D62***	***113***

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 11/12/2018 has revealed that there are 161 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MICHAEL E LAND OFFIC Site ID: 214706	***148 MARTINE AVE***	***SSE 0 - 1/8 (0.010 mi.)***	***D44***	***77***

Site ID: 347878 Site ID: 126439 Spill Number/Closed Date: 0301426 / 2003-05-08 Spill Number/Closed Date: 0503295 / 2005-09-26 Spill Number/Closed Date: 0109874 / 2002-01-14				
THE MICHICALLIAN OFF Site ID: 276042 Spill Number/Closed Date: 9310783 / 1993-11-18	MARTINE AVE & COURT	SE 0 - 1/8 (0.013 mi.)	D58	108
INTERSECTION OF COUR Site ID: 187446 Spill Number/Closed Date: 8905963 / 1989-11-29	COURT ST. & MARITINE	SE 0 - 1/8 (0.013 mi.)	D61	112
MINSKOFF CORP. Site ID: 217944 Spill Number/Closed Date: 9201879 / 1992-05-15	179 MARTINE AVE	ESE 0 - 1/8 (0.042 mi.)	D79	147
WEST HEALTH DEPT Site ID: 126440 Spill Number/Closed Date: 8701223 / 2004-11-06	148 MARTINE AVE	SSE 0 - 1/8 (0.045 mi.)	D80	148
SPILL NUMBER 0206130 Site ID: 176565 Spill Number/Closed Date: 0206130 / 2003-09-03	203 MAIN ST	NE 0 - 1/8 (0.048 mi.)	C86	162
OFFICE BUILDING Site ID: 284245 Site ID: 229197 Spill Number/Closed Date: 9613653 / 1997-03-05 Spill Number/Closed Date: 0313324 / 2004-04-22	14 MAMARONECK AVE	ENE 0 - 1/8 (0.058 mi.)	F99	180
INNS OF COURT Site ID: 204590 Spill Number/Closed Date: 9606465 / 2006-02-28	99 COURT ST	SSE 0 - 1/8 (0.086 mi.)	I121	221
HAMILTON MAIN PARKIN Site ID: 286661 Spill Number/Closed Date: 8707260 / 1989-11-29	HAMILTON AVE & MAIN	NNE 0 - 1/8 (0.114 mi.)	K160	276
131 GRANT AVE Site ID: 385277 Spill Number/Closed Date: 0705016 / 2013-01-30	131 GRANT AVE	S 0 - 1/8 (0.117 mi.)	O164	281
MITCHELL PLACE ASSOC Site ID: 76057 Spill Number/Closed Date: 8902485 / 1989-10-02	10 MITCHELL PLACE	ESE 0 - 1/8 (0.123 mi.)	J173	291
GAS STATION Site ID: 199404 Spill Number/Closed Date: 9710474 / 1998-10-27	***9 MITCHELL PL***	***ESE 1/8 - 1/4 (0.127 mi.)***	***J179***	***308***
WHITE PLAINS DEPT OF Site ID: 294455 Spill Number/Closed Date: 8707220 / 1988-03-14	***255 MAIN STREET***	***NE 1/8 - 1/4 (0.137 mi.)***	***Q186***	***320***
COMMERCIAL BUSINESS Site ID: 338963 Site ID: 351900 Spill Number/Closed Date: 0413115 / 2005-09-07 Spill Number/Closed Date: 0506649 / 2006-02-03	158 GRAND STREET	S 1/8 - 1/4 (0.138 mi.)	O188	325
NICKY'S RESTAURANT Site ID: 239748	107 MAMARONECK AVE	SE 1/8 - 1/4 (0.138 mi.)	R189	327

Spill Number/Closed Date: 8900599 / 1989-05-03				
DEVON PLAZA REALITY Site ID: 254450 Spill Number/Closed Date: 9512203 / 1995-12-29	109 MAMARONECK AVE	SE 1/8 - 1/4 (0.141 mi.)	R192	330
SILVERMAN REALITY Site ID: 308222 Spill Number/Closed Date: 0011270 / 2003-01-22	110 MAMARONECK AVE	SE 1/8 - 1/4 (0.143 mi.)	R194	332
OFFICE BLDG BASEMENT Site ID: 307349 Spill Number/Closed Date: 8908740 / 1990-02-07	150 GRAND STREET	S 1/8 - 1/4 (0.150 mi.)	O200	345
SPILL NUMBER 8809894 Site ID: 286069 Spill Number/Closed Date: 8809894 / 1991-12-20	23 MITCHELL PLACE	ESE 1/8 - 1/4 (0.154 mi.)	T201	346
PER-BAR Site ID: 116904 Spill Number/Closed Date: 8802839 / 1989-01-18	124 MAMARONECK AVE	SE 1/8 - 1/4 (0.154 mi.)	R203	348
SPILL NUMBER 9905959 Site ID: 111332 Spill Number/Closed Date: 9905959 / 1999-10-08	25 MITCHELL PLACE	ESE 1/8 - 1/4 (0.158 mi.)	T205	360
28 MITCHELL PLACE Site ID: 206822 Site ID: 206823 Spill Number/Closed Date: 9901259 / 1999-05-13 Spill Number/Closed Date: 9903630 / 2001-11-14	28 MITCHELL PLACE	ESE 1/8 - 1/4 (0.160 mi.)	S213	373
SPILL NUMBER 0108164 Site ID: 255456 Site ID: 255457 Site ID: 255458 Spill Number/Closed Date: 0108164 / 2002-07-22 Spill Number/Closed Date: 9611678 / 1996-12-24 Spill Number/Closed Date: 9611679 / 1997-11-10	32 MITCHELL PL	ESE 1/8 - 1/4 (0.169 mi.)	S223	390
BARGAM HOME Site ID: 350305 Spill Number/Closed Date: 0505320 / 2005-12-18	36-38 MITCHELL PLACE	E 1/8 - 1/4 (0.178 mi.)	T233	405
APARTMENT BLDG Site ID: 248365 Spill Number/Closed Date: 0208214 / 2003-04-07	37-43 MITCHELL PL	ESE 1/8 - 1/4 (0.184 mi.)	T237	418
APARTMENT BUILDING Site ID: 151265 Spill Number/Closed Date: 0304394 / 2003-10-31	40 MITCHELL PL	E 1/8 - 1/4 (0.187 mi.)	T244	430
HALPERN ENTERPRISES Site ID: 154885 Spill Number/Closed Date: 8804996 / 2005-04-30	170 EAST POST ROAD	SE 1/8 - 1/4 (0.193 mi.)	X266	469
COMMERCIAL Site ID: 159846 Spill Number/Closed Date: 0002215 / 2011-02-28	130-144 EAST POST RD	SSE 1/8 - 1/4 (0.195 mi.)	AB274	480
COMMERCIAL PROERTY Site ID: 363155 Spill Number/Closed Date: 0601015 / 2006-11-03	151 EAST POST ROAD	SE 1/8 - 1/4 (0.195 mi.)	X276	482
OFFICE BLDG	171 EAST POST RD	SE 1/8 - 1/4 (0.197 mi.)	X277	484

Site ID: 293961 Spill Number/Closed Date: 9811157 / 2004-03-30				
170 GRAND STREET	***170 GRAND STREET***	***S 1/8 - 1/4 (0.197 mi.)***	***AC279***	***486***
Site ID: 332894 Spill Number/Closed Date: 0408227 / 2007-11-28				
MGH CO	45 MITCHELL PLACE	E 1/8 - 1/4 (0.201 mi.)	AE285	501
Site ID: 78194 Site ID: 143584 Spill Number/Closed Date: 9904849 / 2000-01-11 Spill Number/Closed Date: 9510979 / 1995-12-12				
APT BUILDING	45 MITCHELL PLACE	E 1/8 - 1/4 (0.201 mi.)	AE286	503
Site ID: 475842 Spill Number/Closed Date: 1212688 / Not Reported				
WESTCHESTER OFFICE B	112 EAST POST ROAD	SSE 1/8 - 1/4 (0.202 mi.)	AB288	505
Site ID: 243138 Spill Number/Closed Date: 9009334 / 1990-12-11				
COACHMAN HOTEL	123 EAST POST ROAD	SSE 1/8 - 1/4 (0.204 mi.)	AB295	517
Site ID: 211948 Spill Number/Closed Date: 9306655 / 1993-09-24				
VAULT 6174	***400 HAMILTON AVENUE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W312***	***547***
Site ID: 72317 Spill Number/Closed Date: 9604857 / 1996-07-22				
SPILL NUMBER 9900622	179 EAST COAST RD	SE 1/8 - 1/4 (0.221 mi.)	AG327	583
Site ID: 260731 Spill Number/Closed Date: 9900622 / 2000-03-24				
WINDBROOK HOUSING	223 DR MARTIN LUTHER	S 1/8 - 1/4 (0.226 mi.)	AK334	605
Site ID: 243532 Spill Number/Closed Date: 0207150 / 2002-11-25				
APARTMENT BUILDING	193 EAST POST ROAD	ESE 1/8 - 1/4 (0.227 mi.)	AG340	612
Site ID: 158568 Spill Number/Closed Date: 0310631 / 2005-10-11				
WHITE PLAIN HOUSING	225 GROVE ST	S 1/8 - 1/4 (0.227 mi.)	AK341	613
Site ID: 293104 Spill Number/Closed Date: 8904683 / 1992-07-30				
REAL ESTATE - TTF	6 CHESTER AVE	SSE 1/8 - 1/4 (0.230 mi.)	AL342	615
Site ID: 514142 Spill Number/Closed Date: 1506711 / Not Reported				
STEWARD	165 MAMARONECK AVENU	SE 1/8 - 1/4 (0.233 mi.)	X349	623
Site ID: 118993 Site ID: 180689 Spill Number/Closed Date: 9701601 / 2005-02-12 Spill Number/Closed Date: 0303361 / 2007-06-22				
RESIDENTS	8 CHESTER AVE	SSE 1/8 - 1/4 (0.237 mi.)	AL358	636
Site ID: 71801 Spill Number/Closed Date: 9610881 / 2012-04-16				
KEMPLER RESIDENCE	169 MAMARONECK AVE	SE 1/8 - 1/4 (0.242 mi.)	AO366	656
Site ID: 160482 Spill Number/Closed Date: 0301465 / 2003-08-25				
JOHN DALE INC	178 MAMORENECK AVE	SE 1/8 - 1/4 (0.246 mi.)	AO374	682

Site ID: 325049
Spill Number/Closed Date: 9810809 / 1998-12-01

APARTMENT BLDG | 40 BARKER AVE | NNE 1/4 - 1/2 (0.253 mi.) | AQ379 | 689
Site ID: 271212
Spill Number/Closed Date: 9713796 / 2001-01-31

LASALLE PARTNERS | 1 NORTH BROADWAY | ENE 1/4 - 1/2 (0.262 mi.) | AM381 | 691
Site ID: 245085
Spill Number/Closed Date: 8807326 / 1989-03-08

COMMERCIAL | 41 BARKER AVE | NNE 1/4 - 1/2 (0.262 mi.) | AQ382 | 692
Site ID: 422220
Spill Number/Closed Date: 0909513 / 2010-03-04

ES GORDON | 7-11 SOUTH BROADWAY | ENE 1/4 - 1/2 (0.264 mi.) | AM383 | 695
Site ID: 86174
Spill Number/Closed Date: 9303840 / 1994-05-04

BART GOLDBERG APT. B | 277 MARTINE AVE | E 1/4 - 1/2 (0.266 mi.) | AR384 | 696
Site ID: 255929
Spill Number/Closed Date: 9008032 / 1990-11-08

VILLANOVA - TTF | 144 CHURCH ST | N 1/4 - 1/2 (0.274 mi.) | 385 | 698
Site ID: 529884
Spill Number/Closed Date: 1603426 / 2016-09-06

OFFICE BUILDING | 15 NORTH BROADWAY | NE 1/4 - 1/2 (0.280 mi.) | AP386 | 699
Site ID: 125976
Spill Number/Closed Date: 9207265 / 1996-02-01

OFFICE BLDG | 203 MAMARONECK AVE | SE 1/4 - 1/2 (0.287 mi.) | AS388 | 703
Site ID: 329412
Spill Number/Closed Date: 9710787 / Not Reported

GARDEN APARTMENTS | 101 N. BROADWAY | NE 1/4 - 1/2 (0.298 mi.) | AU391 | 716
Site ID: 77672
Spill Number/Closed Date: 8904418 / 1992-07-30

BUILDING | 20 NORTH BROADWAY | NE 1/4 - 1/2 (0.306 mi.) | AU395 | 724
Site ID: 84678
Site ID: 396726
Spill Number/Closed Date: 0111039 / 2002-03-11
Spill Number/Closed Date: 0800897 / 2008-06-08

PIRRO, MONSELL REALT | 40 WALLER AVE | SE 1/4 - 1/2 (0.307 mi.) | 396 | 728
Site ID: 162080
Spill Number/Closed Date: 8709325 / 1988-02-02

WHITE PLAINS DPW | MAPLE & MAMARONECK A | SE 1/4 - 1/2 (0.310 mi.) | AS397 | 729
Site ID: 90852
Spill Number/Closed Date: 9111846 / 1992-03-10

WHITE PLAINS-FIRE HO | MAMARONECK & MAPLE A | SE 1/4 - 1/2 (0.310 mi.) | AS398 | 730
Site ID: 311048
Spill Number/Closed Date: 8707149 / 1989-01-05

GREENRIDGE ESTATES | 1-13 GREENRIDGE AVE | SSE 1/4 - 1/2 (0.311 mi.) | AV399 | 732
Site ID: 425068
Spill Number/Closed Date: 0912193 / 2011-12-22

CITY PARKING GARAGE | CHESTER AVE MARBLE A | SSE 1/4 - 1/2 (0.311 mi.) | AV400 | 733
Site ID: 158538
Spill Number/Closed Date: 9109520 / 1992-03-25

APT BUILDING | 16 NORTH BROADWAY | NE 1/4 - 1/2 (0.318 mi.) | AU401 | 734

Site ID: 337751
Site ID: 381144
Spill Number/Closed Date: 0412306 / 2005-08-27
Spill Number/Closed Date: 0701599 / 2007-12-12

CON ED	***10 NORTH BROADWAY***	***NE 1/4 - 1/2 (0.322 mi.)***	***AU403***	***740***
Site ID: 302706				
Spill Number/Closed Date: 0301652 / 2003-12-12				
PATRIOT MANAGEMENT	***2 WESTCHESTER AVE***	***ENE 1/4 - 1/2 (0.325 mi.)***	***AW404***	***744***
Site ID: 322460				
Spill Number/Closed Date: 8800351 / 2004-05-06				
PRESBYTERIAN CHURCH	39 NORTH BROADWAY	NNE 1/4 - 1/2 (0.329 mi.)	405	746
Site ID: 424343				
Site ID: 120033				
Spill Number/Closed Date: 0911530 / 2017-05-11				
Spill Number/Closed Date: 8705816 / 1988-03-04				
APARTMENT	***8 LONGVIEW AVE***	***S 1/4 - 1/2 (0.334 mi.)***	***406***	***748***
Site ID: 420361				
Site ID: 441326				
Site ID: 440652				
Spill Number/Closed Date: 0907812 / 2009-11-04				
Spill Number/Closed Date: 1007877 / 2011-07-05				
Spill Number/Closed Date: 1007255 / 2017-12-12				
WHITE PLAINS HOSPITA	***41 E POST RD***	***S 1/4 - 1/2 (0.335 mi.)***	***AX407***	***752***
Site ID: 455090				
Spill Number/Closed Date: 1107393 / 2011-10-31				
WHITE PLAINS HOSPITA	41 EAST POST ROAD	S 1/4 - 1/2 (0.335 mi.)	AX408	759
Site ID: 68377				
Spill Number/Closed Date: 9414693 / 1995-02-13				
JOHN L WHITE RESIDEN	9 GREENRIDGE AVE	SSE 1/4 - 1/2 (0.341 mi.)	AV409	760
Site ID: 424347				
Spill Number/Closed Date: 0911533 / 2011-10-28				
COMMERCIAL PROPERTY	***235 MAMARONECK AVE***	***SSE 1/4 - 1/2 (0.342 mi.)***	***AZ411***	***766***
Site ID: 460824				
Site ID: 128036				
Spill Number/Closed Date: 1112859 / 2012-03-30				
Spill Number/Closed Date: 0404588 / 2005-01-10				
CON ED	***300 MAIN ST***	***ENE 1/4 - 1/2 (0.351 mi.)***	***AW413***	***775***
Site ID: 76155				
Site ID: 76156				
Site ID: 153296				
Spill Number/Closed Date: 8708398 / 1988-02-17				
Spill Number/Closed Date: 9810968 / 2000-02-09				
Spill Number/Closed Date: 9209346 / 1993-07-19				
WHITE PLAINS HOSPITA	***DAVIS AVE***	***S 1/4 - 1/2 (0.356 mi.)***	***AX415***	***781***
Site ID: 66799				
Spill Number/Closed Date: 9303501 / 1996-06-18				
HOSPITAL (UNK NAME)	41 EAST COAST ROAD	S 1/4 - 1/2 (0.356 mi.)	AX416	783
Site ID: 191235				
Spill Number/Closed Date: 9806058 / 1998-08-17				
WHITE PLAINS HOSPITA	MAPLE AVE	S 1/4 - 1/2 (0.356 mi.)	AX417	784
Site ID: 290020				

Spill Number/Closed Date: 9304740 / 1994-01-06

BUSINESS	***7 LAKE STREET***	***NE 1/4 - 1/2 (0.363 mi.)***	***BA418***	***785***
Site ID: 494900				
Site ID: 368064				
Site ID: 386923				
Site ID: 380826				
Spill Number/Closed Date: 1401610 / 2015-07-17				
Spill Number/Closed Date: 0604972 / 2006-11-17				
Spill Number/Closed Date: 0706405 / 2008-07-31				
Spill Number/Closed Date: 0701292 / 2007-09-28				
WHITE PLAINS YMCA	250 MAMARONECK AVE	SSE 1/4 - 1/2 (0.366 mi.)	AZ419	790
Site ID: 503665				
Spill Number/Closed Date: 1410006 / 2015-12-08				
APT. BUILDING	***50 NORTH BROADWAY***	***NNE 1/4 - 1/2 (0.372 mi.)***	***BB421***	***793***
Site ID: 219739				
Spill Number/Closed Date: 9212081 / 1994-06-29				
PDUZZI - TTF	188 CHURCH ST	N 1/4 - 1/2 (0.376 mi.)	BD423	799
Site ID: 108306				
Spill Number/Closed Date: 9905239 / 2009-12-16				
YMCA	260 MAMARONECK AVE	SSE 1/4 - 1/2 (0.380 mi.)	AZ425	802
Site ID: 263885				
Spill Number/Closed Date: 9013259 / 2002-03-23				
RESIDENCE	325 MAIN ST	ENE 1/4 - 1/2 (0.383 mi.)	426	803
Site ID: 230651				
Spill Number/Closed Date: 9710553 / 1998-01-09				
35 PARK AVENUE	35 PARK AVENUE	NNW 1/4 - 1/2 (0.388 mi.)	BF428	805
Site ID: 272501				
Spill Number/Closed Date: 0303364 / 2010-06-29				
SPILL NUMBER 8807217	52 NORTH BROADWAY	NNE 1/4 - 1/2 (0.393 mi.)	BB432	810
Site ID: 354798				
Site ID: 181366				
Spill Number/Closed Date: 0509076 / 2006-03-21				
Spill Number/Closed Date: 8807217 / 1988-12-02				
GETTY S/S	11 EAST POND ROAD	SSW 1/4 - 1/2 (0.397 mi.)	BE433	813
Site ID: 319803				
Spill Number/Closed Date: 9210753 / 1992-12-31				
APT. HOUSE	***82 BANK STREET***	***SW 1/4 - 1/2 (0.399 mi.)***	***434***	***814***
Site ID: 301757				
Spill Number/Closed Date: 0312286 / 2005-03-27				
RESIDENCE	25 LONGVIEW AVE	S 1/4 - 1/2 (0.399 mi.)	435	816
Site ID: 339072				
Spill Number/Closed Date: 0413208 / 2005-05-08				
PRIVATE HOME	11 PARK AVE	N 1/4 - 1/2 (0.401 mi.)	436	817
Site ID: 364664				
Spill Number/Closed Date: 0602237 / 2006-10-22				
APT BUILDING	16 LAKE STREET	NE 1/4 - 1/2 (0.401 mi.)	BA437	818
Site ID: 425742				
Spill Number/Closed Date: 0912833 / 2010-06-23				
TORELLI	21 DEKALB AVE	SE 1/4 - 1/2 (0.410 mi.)	BH441	825
Site ID: 253456				

Spill Number/Closed Date: 0206319 / 2005-02-02				
SPILL NUMBER 0209590 Site ID: 206038 Spill Number/Closed Date: 0209590 / 2002-12-18	25 PARK AVE	N 1/4 - 1/2 (0.416 mi.)	BD443	827
ROADWAY Site ID: 85909 Spill Number/Closed Date: 9712450 / Not Reported	***285 MAMARONECK AVE***	***SSE 1/4 - 1/2 (0.418 mi.)***	***444***	***828***
LAZZARO Site ID: 238028 Spill Number/Closed Date: 9815351 / 2004-12-07	47 PARK AVE	NNW 1/4 - 1/2 (0.423 mi.)	447	833
WHITE PLAINS MED CEN Site ID: 204425 Spill Number/Closed Date: 0004388 / 2001-06-22	170 MAPLE AVE	S 1/4 - 1/2 (0.423 mi.)	449	840
APARTMENT BLDG Site ID: 335499 Spill Number/Closed Date: 0410525 / 2005-02-24	***21 GREENRIDGE AVE***	***SSE 1/4 - 1/2 (0.428 mi.)***	***450***	***841***
YWCA Site ID: 63852 Spill Number/Closed Date: 0207697 / 2003-05-09	69 NORTH BROADWAY	NNE 1/4 - 1/2 (0.428 mi.)	451	843
SPILL NUMBER 9909558 Site ID: 222795 Spill Number/Closed Date: 9909558 / 2000-01-12	7 PARK CIRCLE	NNW 1/4 - 1/2 (0.431 mi.)	BF452	844
JSD MANAGEMENT Site ID: 213796 Spill Number/Closed Date: 8902337 / 1992-07-30	15 LAKE ST	NE 1/4 - 1/2 (0.438 mi.)	455	850
SUBODH DESHMUKH RESI Site ID: 434804 Spill Number/Closed Date: 1001726 / 2010-08-03	39 PARKVIEW CT	N 1/4 - 1/2 (0.445 mi.)	457	856
STEWART PLACE CONDOS Site ID: 469308 Spill Number/Closed Date: 1206313 / 2013-05-16	***10 STEWART PLACE***	***NNE 1/4 - 1/2 (0.464 mi.)***	***460***	***860***
GABERIAL Site ID: 65789 Spill Number/Closed Date: 0000372 / 2000-10-13	7 FAIRVIEW AVE	NW 1/4 - 1/2 (0.465 mi.)	461	862
BERTE HOME Site ID: 344494 Spill Number/Closed Date: 0501302 / 2005-06-19	3 CHURCH COURT	NNW 1/4 - 1/2 (0.468 mi.)	462	864
10 SCHOOL STREET Site ID: 392081 Spill Number/Closed Date: 0710736 / 2008-05-01	10 SCHOOL STREET	W 1/4 - 1/2 (0.470 mi.)	BJ463	865
MILLER CENTER FOR NU Site ID: 211184 Spill Number/Closed Date: 8802117 / 1988-08-30	37 DEKALD AVE	SE 1/4 - 1/2 (0.472 mi.)	464	866
12 HARMON STREET Site ID: 352081 Spill Number/Closed Date: 0506799 / 2012-08-15	12 HARMON STREET	W 1/4 - 1/2 (0.474 mi.)	BJ465	867
WHITE PLAINS LINC/ME Site ID: 226425 Spill Number/Closed Date: 0005954 / 2001-04-24	25 WEST COAST RD	SSW 1/4 - 1/2 (0.478 mi.)	BI466	869
FIRE HOUSE # 4	MAPLE AVE & S LEXING	SSW 1/4 - 1/2 (0.480 mi.)	BK467	870

Site ID: 178231
Spill Number/Closed Date: 8707150 / 1989-01-05

SPILL NUMBER 0310118	***79 NORTH BROADWAY***	***N 1/4 - 1/2 (0.480 mi.)***	***468***	***871***
Site ID: 319975				
Spill Number/Closed Date: 8708679 / 1989-01-06				
PRIVATE HOME	43 LONGVIEW AVE	S 1/4 - 1/2 (0.486 mi.)	BL469	873
Site ID: 352870				
Site ID: 354077				
Spill Number/Closed Date: 0507448 / 2006-03-15				
Spill Number/Closed Date: 0508523 / 2006-07-11				
GREAT GRANT MANOR PR	235 SOUTH LEXINGTON	SSW 1/4 - 1/2 (0.489 mi.)	BK470	875
Site ID: 147077				
Site ID: 147078				
Site ID: 147079				
Site ID: 147080				
Spill Number/Closed Date: 0204243 / 2002-11-06				
Spill Number/Closed Date: 0304500 / 2003-10-31				
Spill Number/Closed Date: 9313731 / 1995-01-05				
Spill Number/Closed Date: 9706472 / 1998-02-27				
FELIX DAVILA	36 DAVIS RD	S 1/4 - 1/2 (0.490 mi.)	471	880
Site ID: 187946				
Spill Number/Closed Date: 0304516 / 2003-10-23				
REALTY TRANSACTION	52 PARK CIRCLE	NNW 1/4 - 1/2 (0.492 mi.)	472	881
Site ID: 347156				
Spill Number/Closed Date: 0502737 / 2005-07-25				
RESIDENCE	23 OAKWOOD RD	S 1/4 - 1/2 (0.497 mi.)	473	882
Site ID: 246760				
Spill Number/Closed Date: 9906780 / 2000-01-28				
RESIDENTS	44 LONGVIEW AVE	S 1/4 - 1/2 (0.498 mi.)	BL474	884
Site ID: 166538				
Spill Number/Closed Date: 9614364 / 1997-03-11				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
VINTAGE RESTAURANT	171-173 MAIN STREET	N 0 - 1/8 (0.008 mi.)	A22	44
Site ID: 365437				
Spill Number/Closed Date: 0602861 / 2008-09-26				
RESIDENCE	185- 187 MAIN ST	NE 0 - 1/8 (0.020 mi.)	C64	115
Site ID: 81930				
Spill Number/Closed Date: 9708138 / 1997-11-10				
ODDESY CORP MAINT DE	***123 MAIN STREET***	***WNW 0 - 1/8 (0.023 mi.)***	***B68***	***130***
Site ID: 160999				
Site ID: 161000				
Site ID: 74955				
Spill Number/Closed Date: 8906607 / 1991-06-12				
Spill Number/Closed Date: 9910168 / 1999-11-22				
Spill Number/Closed Date: 8907663 / 1991-06-12				
A&S STORE	GALLERIA PLAZA	WNW 0 - 1/8 (0.041 mi.)	B77	144
Site ID: 187319				
Spill Number/Closed Date: 8805571 / 1989-03-07				
A & S STORE	GALLERIA PLAZA	WNW 0 - 1/8 (0.041 mi.)	B78	146

Site ID: 187318 Spill Number/Closed Date: 8803673 / 1988-08-09				
WHITE PLAINS POLICE	***279 HAMILTON AVENUE***	***N 0 - 1/8 (0.102 mi.)***	***K137***	***241***
Site ID: 92789 Spill Number/Closed Date: 8606771 / 1989-11-29				
FORMER WPPD	279 HAMITON AVE	N 0 - 1/8 (0.102 mi.)	K139	246
Site ID: 306552 Spill Number/Closed Date: 0405806 / 2007-07-06				
NYNEX	***111 MAIN ST***	***WNW 0 - 1/8 (0.104 mi.)***	***H146***	***257***
Site ID: 239422 Site ID: 145113 Spill Number/Closed Date: 9609101 / 1999-11-26 Spill Number/Closed Date: 9314933 / 1995-03-01				
EXXON SERVICE STATIO	***274 HAMILTON AVE***	***N 0 - 1/8 (0.123 mi.)***	***M175***	***296***
Site ID: 190041 Spill Number/Closed Date: 8707486 / 1987-12-18				
SLADER NEIGHBORHOOD	2 FISHER CT	S 1/8 - 1/4 (0.172 mi.)	V227	395
Site ID: 214463 Spill Number/Closed Date: 9810451 / 2003-12-05				
MARRIOT INN	5 BARKER AVE	NNW 1/8 - 1/4 (0.191 mi.)	Y248	436
Site ID: 348566 Site ID: 483619 Spill Number/Closed Date: 0503865 / 2005-10-28 Spill Number/Closed Date: 1303150 / 2014-02-28				
RESIDENCE INN - TTF	5 BARKER AVE	NNW 1/8 - 1/4 (0.191 mi.)	Y249	439
Site ID: 507776 Spill Number/Closed Date: 1501552 / 2015-07-20				
EDGAR	1 BARKER AVE	NW 1/8 - 1/4 (0.194 mi.)	AA271	476
Site ID: 330854 Spill Number/Closed Date: 9807932 / 1999-11-19				
77 SOUTH LEXINGTON A	77 SOUTH LEXINGTON A	WSW 1/8 - 1/4 (0.194 mi.)	Z272	477
Site ID: 106697 Spill Number/Closed Date: 0304231 / 2003-07-22				
COMMERICAL BUILDING	10 NEW KING STREET	WNW 1/8 - 1/4 (0.216 mi.)	AI306	538
Site ID: 439407 Spill Number/Closed Date: 1006070 / 2010-10-28				
OFFICE BLDG	4 NEW KING ST	WNW 1/8 - 1/4 (0.220 mi.)	AI323	575
Site ID: 170684 Spill Number/Closed Date: 9809692 / 2003-12-05				
SPILL NUMBER 0000953	1 NEW KING STREET	WNW 1/8 - 1/4 (0.225 mi.)	AI331	600
Site ID: 272947 Spill Number/Closed Date: 0000953 / 2001-02-07				
OUR LADY OF MOUNT CA	92 SOUTH LEXINGTON A	SW 1/8 - 1/4 (0.225 mi.)	AH333	601
Site ID: 219315 Site ID: 448286 Site ID: 239739 Spill Number/Closed Date: 8704169 / 1987-10-21 Spill Number/Closed Date: 1100855 / 2012-01-23 Spill Number/Closed Date: 8703713 / 1987-10-21				
GATEWAY BLDG	***1 NORTH LEXINGTON AV***	***W 1/8 - 1/4 (0.238 mi.)***	***AN365***	***650***

Site ID: 276348
Site ID: 131721
Site ID: 255792
Spill Number/Closed Date: 8908197 / 1990-01-29
Spill Number/Closed Date: 9000726 / 1991-12-06
Spill Number/Closed Date: 9108659 / 1991-11-13

240 EAST POST RD	240 EAST POST RD	ESE 1/4 - 1/2 (0.260 mi.)	380	690
Site ID: 135983				
Spill Number/Closed Date: 9903233 / 1999-12-15				
CEMMEL HOUSE BUILDIN	***300 MARTINE AVE***	***E 1/4 - 1/2 (0.285 mi.)***	***AR387***	***701***
Site ID: 293177				
Spill Number/Closed Date: 0206553 / 2002-12-13				
WIND BROOK APTS.	***33 FISHER AVE***	***SW 1/4 - 1/2 (0.293 mi.)***	***AT389***	***706***
Site ID: 441310				
Spill Number/Closed Date: 1007861 / 2011-07-05				
@	***44 NORTH BROADWAY***	***E 1/4 - 1/2 (0.296 mi.)***	***390***	***709***
Site ID: 328668				
Spill Number/Closed Date: 0302230 / 2009-11-05				
HYDRAULIC FLUID TO S	***134 SOUTH LEXINGTON***	***SSW 1/4 - 1/2 (0.299 mi.)***	***AT392***	***717***
Site ID: 218519				
Spill Number/Closed Date: 0008525 / 2001-03-12				
COUNTY OFFICE BLD	***MARTINE AVE***	***E 1/4 - 1/2 (0.303 mi.)***	***AR393***	***719***
Site ID: 172819				
Spill Number/Closed Date: 8806957 / 1989-02-06				
PARK ROSE	***12 WESTCHESTER AVE***	***ENE 1/4 - 1/2 (0.304 mi.)***	***394***	***721***
Site ID: 411931				
Spill Number/Closed Date: 0900020 / 2015-06-05				
CHURCH	***65 FISHER AVE***	***SW 1/4 - 1/2 (0.320 mi.)***	***AT402***	***738***
Site ID: 355853				
Spill Number/Closed Date: 0509976 / 2006-12-20				
PEPE MOTORS INC	***50 BANK ST***	***WSW 1/4 - 1/2 (0.345 mi.)***	***AY412***	***769***
Site ID: 284462				
Spill Number/Closed Date: 9607100 / 1999-04-29				
CROWN PLAZA HOTEL	66 HALE AVE	ESE 1/4 - 1/2 (0.355 mi.)	414	780
Site ID: 453595				
Spill Number/Closed Date: 1105926 / Not Reported				
WHITE PLAINS HOSPITA	EAST NEW YORK POST R	SSW 1/4 - 1/2 (0.370 mi.)	AX420	791
Site ID: 240948				
Spill Number/Closed Date: 9506062 / 2005-01-02				
PRIVATE ENTERPRISE	***20 FERRIS AVE***	***NW 1/4 - 1/2 (0.372 mi.)***	***BC422***	***795***
Site ID: 166779				
Site ID: 166780				
Site ID: 166781				
Spill Number/Closed Date: 0402326 / 2004-06-02				
Spill Number/Closed Date: 8800487 / 1989-01-11				
Spill Number/Closed Date: 8800670 / 1989-01-11				
FIRE STATION 2		NW 1/4 - 1/2 (0.378 mi.)	BC424	800
Site ID: 297873				
Spill Number/Closed Date: 8801791 / 1989-01-24				
SPILL NUMBER 0103645	12 EAST POST RD	SSW 1/4 - 1/2 (0.385 mi.)	BE427	804

Site ID: 129951
Spill Number/Closed Date: 0103645 / 2003-12-09

GETTY SERVICE STATIO	11 EAST POST ROAD	SSW 1/4 - 1/2 (0.391 mi.)	BE429	806
Site ID: 261414 Site ID: 261415 Spill Number/Closed Date: 0407127 / 2004-09-27 Spill Number/Closed Date: 9710611 / 1998-05-08				
SPILL NUMBER 8600048	11 EAST POST ROAD	SSW 1/4 - 1/2 (0.391 mi.)	BE430	808
Site ID: 200602 Spill Number/Closed Date: 8600048 / 1987-02-24				
WESTCHESTER SHOPPING	WEST AVE & PAWLING S	E 1/4 - 1/2 (0.392 mi.)	431	809
Site ID: 213450 Spill Number/Closed Date: 9310531 / 1995-01-20				
FRANKLIN APTS	***25 FRANKLIN AVE***	***ENE 1/4 - 1/2 (0.404 mi.)***	***438***	***820***
Site ID: 154120 Spill Number/Closed Date: 8801525 / 1988-08-19				
WHITE PLAINS HONDA	31 WESTMPORELAND AVE	WSW 1/4 - 1/2 (0.406 mi.)	BG439	822
Site ID: 224484 Spill Number/Closed Date: 9514655 / 1996-02-15				
PRIVATE HOME	***18 DEKALB AVE***	***SE 1/4 - 1/2 (0.407 mi.)***	***BH440***	***823***
Site ID: 195806 Spill Number/Closed Date: 0406991 / 2004-10-04				
SPILL NUMBER 0013009	1 EAST POST RD	SSW 1/4 - 1/2 (0.415 mi.)	BE442	826
Site ID: 156648 Spill Number/Closed Date: 0013009 / 2001-03-12				
MUNICIPAL GARAGE	111	WSW 1/4 - 1/2 (0.419 mi.)	BG445	830
Site ID: 129523 Spill Number/Closed Date: 8808829 / 1991-08-07				
BISCARDI CLEANERS	***201 SO. LEXINGTON AV***	***SSW 1/4 - 1/2 (0.421 mi.)***	***BE446***	***831***
Site ID: 322267 Spill Number/Closed Date: 0100630 / 2006-05-01				
CIVIC CENTER MOTORS	***31 WESTMORELAND AVE***	***WSW 1/4 - 1/2 (0.423 mi.)***	***BG448***	***835***
Site ID: 110892 Site ID: 110893 Site ID: 68432 Spill Number/Closed Date: 0108090 / 2001-11-08 Spill Number/Closed Date: 0206674 / 2003-02-26 Spill Number/Closed Date: 0010522 / 2001-07-10				
COMMERCIAL PROPERTY	***39 WESTMORELAND AVE***	***WSW 1/4 - 1/2 (0.432 mi.)***	***BG453***	***845***
Site ID: 221603 Site ID: 404560 Spill Number/Closed Date: 9411173 / 1995-09-22 Spill Number/Closed Date: 0807224 / 2009-01-07				
IRVINGTON	IRVINGTON	SW 1/4 - 1/2 (0.436 mi.)	BG454	848
Site ID: 309074 Spill Number/Closed Date: 8708811 / 1988-03-03				
KEY FORD OF WHITE PL	***80 WESTCHESTER AVE***	***E 1/4 - 1/2 (0.444 mi.)***	***456***	***851***
Site ID: 320738 Spill Number/Closed Date: 8606267 / 1987-01-08				
AVIS	20 WEST POST RD	SSW 1/4 - 1/2 (0.451 mi.)	BI458	858

Site ID: 159466
Spill Number/Closed Date: 8706892 / 1988-07-27

SPILL NUMBER 0011055 — 2 AMHERST PL — NE 1/4 - 1/2 (0.457 mi.) — 459 — 859
Site ID: 196605
Spill Number/Closed Date: 0011055 / 2001-09-18

NEW YORK PRESBYTERIA — 21 BLOOMINGDALE ROAD — ESE 1/4 - 1/2 (0.498 mi.) — 475 — 885
Site ID: 267816
Site ID: 267817
Spill Number/Closed Date: 0404544 / 2009-06-24
Spill Number/Closed Date: 9813782 / 1999-06-02

BILTMORE TOWERS APTS — 30 LAKE STREET — NE 1/4 - 1/2 (0.498 mi.) — 476 — 898
Site ID: 443959
Site ID: 337240
Site ID: 243796
Site ID: 149672
Site ID: 408703
Spill Number/Closed Date: 1010357 / 2011-03-30
Spill Number/Closed Date: 0411926 / 2005-03-27
Spill Number/Closed Date: 8706628 / 1988-07-27
Spill Number/Closed Date: 9905417 / 2003-12-05
Spill Number/Closed Date: 0811148 / 2009-04-14

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 47 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WESTCHESTER COUNTY O	148 MARTINE AVENUE	SSE 0 - 1/8 (0.010 mi.)	D47	86
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019 Status: 1. In-Service Status: 0. Administratively closed Status: 4. Closed - in place Id/Status:: 3-168777 Site Status: Active				
BRIAN HOLDING COMPAN	203 MAIN STREET	NE 0 - 1/8 (0.048 mi.)	C87	164
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019 Status: 4. Closed - in place Id/Status:: 3-049999 Site Status: Unregulated: <1101 gal. PBS				
CALANO & CALANO REAL	14 MAMARONECK AVENUE	ENE 0 - 1/8 (0.058 mi.)	F98	180
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019 Status: 1. In-Service Id/Status:: 3-801152 Site Status: Active				
THE INNS OF COURT PR	99 COURT ST.	SSE 0 - 1/8 (0.086 mi.)	I122	223
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019				

Status: 3. Closed - Removed
Id/Status:: 3-601002
Site Status: Unregulated: <1101 gal. PBS

76 MAMARONECK AVENUE	76 MAMARONECK AVENUE	ESE 0 - 1/8 (0.086 mi.)	J123	223

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Status: 3. Closed - Removed
Id/Status:: 3-074659
Site Status: Unregulated

47 MAMARONECK AVENUE	47 MAMARONECK AVENUE	ESE 0 - 1/8 (0.090 mi.)	J126	229

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-030929
Site Status: Unregulated

KIMCO REALTY CORP	100 MAMARONECK AVENU	SE 0 - 1/8 (0.112 mi.)	J157	274

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-801328
Site Status: Unregulated: <1101 gal. PBS

AMCOTT ASSOCIATES	300 HAMILTON AVENUE	N 0 - 1/8 (0.125 mi.)	M177	306

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Status: 0. Administratively closed
Status: 1. In-Service
Id/Status:: 3-259241
Id/Status:: 3-801122
Site Status: Active
Site Status: Unregulated

DEVON PLAZA REALTY	9 MITCHELL PLACE	ESE 1/8 - 1/4 (0.127 mi.)	J180	310

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Status: 1. In-Service
Status: 4. Closed - in place
Id/Status:: 3-412384
Site Status: Unregulated

MUNICIPAL BUILDING	255 MAIN ST	NE 1/8 - 1/4 (0.137 mi.)	Q187	324

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3a. Closed - Prior to 04/1991
Status: 4. Closed - in place
Id/Status:: 3-169552
Site Status: Unregulated: <1101 gal. PBS

210 MARTINE AVENUE	210 MARTINE AVENUE	E 1/8 - 1/4 (0.139 mi.)	S190	328

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-801056
Site Status: Unregulated

110-122 MAMARONECK A	110 MAMARONECK AVENU	SE 1/8 - 1/4 (0.143 mi.)	R193	331

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-074640
Site Status: Unregulated: <1101 gal. PBS

177 GRAND STREET ASS	177 GRAND STREET	S 1/8 - 1/4 (0.146 mi.)	O197	339

Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019

Status: 1. In-Service
Id/Status:: 3-049816
Site Status: Active

150 GRAND STREET OFF | 150 GRAND STREET | S 1/8 - 1/4 (0.150 mi.) | O199 | 344
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Status: 0. Administratively closed
Id/Status:: 3-800119
Id/Status:: 3-176885
Site Status: Unregulated
Site Status: Administratively Closed

SEA MANAGEMENT | 23 MITCHELL PLACE | ESE 1/8 - 1/4 (0.154 mi.) | T202 | 347
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-600172
Site Status: Unregulated: <1101 gal. PBS

28 MITCHELL PLACE IN | 28 MITCHELL PLACE | ESE 1/8 - 1/4 (0.160 mi.) | S212 | 372
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-600900
Site Status: Unregulated: <1101 gal. PBS

MCI DBA VERIZON BUSI | 95 CHURCH STREET | N 1/8 - 1/4 (0.165 mi.) | 222 | 388
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Status: 0. Administratively closed
Id/Status:: 3-259233
Site Status: Unregulated

APT. BUILDING | 40 MITCHELL PLACE | E 1/8 - 1/4 (0.187 mi.) | T243 | 429
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-600486
Site Status: Unregulated: <1101 gal. PBS

DEVON PLAZA REALTY | 170 EAST POST ROAD | SE 1/8 - 1/4 (0.193 mi.) | X267 | 470
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-050067
Site Status: Unregulated

151 EAST POST ROAD C | 151 EAST POST ROAD | SE 1/8 - 1/4 (0.195 mi.) | X275 | 481
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-030910
Site Status: Active

170 GRAND STREET ASS | 170 GRAND STREET | S 1/8 - 1/4 (0.197 mi.) | AC278 | 485
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-800392
Site Status: Active

MGH CO., LLC | 45 MITCHELL PLACE | E 1/8 - 1/4 (0.201 mi.) | AE284 | 500
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-800409
Site Status: Active

WESTCHESTER COUNTY O | 112 EAST POST ROAD | SSE 1/8 - 1/4 (0.202 mi.) | AB287 | 504
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019

Status: 1. In-Service
Id/Status:: 3-801218
Site Status: Active

WESTHAB COACHMAN FAM — 123 EAST POST ROAD — SSE 1/8 - 1/4 (0.204 mi.) — AB296 — 518
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-801262
Site Status: Unregulated

PUCKHINKONNUCK CORP. — ***190 EAST POST ROAD*** — ***ESE 1/8 - 1/4 (0.212 mi.)*** — ***AG305*** — ***537***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-032476
Site Status: Active

WINBROOK HOUSING DEV — 223 DR. MARTIN LUTHE — S 1/8 - 1/4 (0.226 mi.) — AK335 — 606
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-493597
Site Status: Active

193-197 EAST POST RO — ***193-197 EAST POST RO*** — ***ESE 1/8 - 1/4 (0.227 mi.)*** — ***AG339*** — ***611***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-178683
Site Status: Active

URBAN LEAGUE OF WEST — 61 MITCHELL PLACE — E 1/8 - 1/4 (0.237 mi.) — AE355 — 633
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-802108
Site Status: Unregulated

BIRCHWOOD ASSOCIATES — 35 BARKER AVENUE — N 1/8 - 1/4 (0.237 mi.) — AJ356 — 634
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 0. Administratively closed
Status: 1. In-Service
Id/Status:: 3-496502
Site Status: Active

COLIN SERVICE SYSTEM — 1 BROCKWAY PLACE — ENE 1/8 - 1/4 (0.237 mi.) — AM357 — 635
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-411310
Site Status: Unregulated: <1101 gal. PBS

BARKER AVENUE OWNERS — ***33 BARKER AVENUE*** — ***N 1/8 - 1/4 (0.244 mi.)*** — ***AJ372*** — ***680***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-169668
Site Status: Active

JOHN DALE, INC. — 176-180 MAMRONECK AV — SE 1/8 - 1/4 (0.246 mi.) — AO373 — 681
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Status: 0. Administratively closed
Id/Status:: 3-800038
Site Status: Unregulated: <1101 gal. PBS

Lower Elevation	Address	Direction / Distance	Map ID	Page

LAST CALL NY INC/DBA — 171-173 MAIN STREET — N 0 - 1/8 (0.008 mi.) — A21 — 43
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019

Status: 3. Closed - Removed
Id/Status:: 3-800096
Site Status: Unregulated: <1101 gal. PBS

NEW YORK POWER AUTHO ***123 MAIN STREET*** ***WNW 0 - 1/8 (0.023 mi.)*** ***B66*** ***118***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Database: UST, Date of Government Version: 02/11/2019
Status: 1. In-Service
Id/Status:: 3-496812
Site Status: Administratively Closed

199 MAIN STREET REAL ***199 MAIN STREET*** ***NE 0 - 1/8 (0.025 mi.)*** ***C71*** ***138***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 4. Closed - in place
Id/Status:: 3-049824
Site Status: Active

WESTCHESTER COUNTY C ***111 MARTIN LUTHER KI*** ***SSW 0 - 1/8 (0.103 mi.)*** ***N144*** ***254***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-801217
Site Status: Active

AAMA AUTO SERVICE, I ***274 HAMILTON AVENUE*** ***N 0 - 1/8 (0.123 mi.)*** ***M176*** ***300***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Status: 3. Closed - Removed
Status: 0. Administratively closed
Id/Status:: 3-164135
Site Status: Active

GHP HAMILTON AVENUE 170 HAMILTON AVENUE WNW 1/8 - 1/4 (0.130 mi.) P181 312
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-466034
Site Status: Active

SLATER NEIGHBORHOOD 2 FISHER COURT S 1/8 - 1/4 (0.172 mi.) V226 395
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-169560
Site Status: Unregulated: <1101 gal. PBS

GALLERIA WEST GARAGE ***MARTINE AVE & SO LEX*** ***WSW 1/8 - 1/4 (0.192 mi.)*** ***Z265*** ***467***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-169579
Site Status: Unregulated: <1101 gal. PBS

PUBLIC SAFETY BUILDI ***77 SOUTH LEXINGTON A*** ***WSW 1/8 - 1/4 (0.194 mi.)*** ***Z273*** ***478***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-601115
Site Status: Active

CHARLES L. BRIEANT U ***300 QUARROPAS STREET*** ***SSW 1/8 - 1/4 (0.203 mi.)*** ***AF294*** ***515***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-801467
Site Status: Active

STATION PLAZA ***76 SOUTH LEXINGTON A*** ***SW 1/8 - 1/4 (0.209 mi.)*** ***AH302*** ***527***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019

Status: 4. Closed - in place
Id/Status:: 3-139637
Site Status: Administratively Closed

SAFE FLIGHT INSTRUME ***20 NEW KING ST*** ***WNW 1/8 - 1/4 (0.209 mi.)*** ***AI303*** ***529***
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3a. Closed - Prior to 04/1991
Status: 3. Closed - Removed
Id/Status:: 3-005754
Site Status: Unregulated: <1101 gal. PBS

PEPE CADILLAC 15 WATER STREET NW 1/8 - 1/4 (0.219 mi.) AA322 574
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Id/Status:: 3-801848
Site Status: Active

OUR LADY OF MT CARME 92 SOUTH LEXINGTON A SW 1/8 - 1/4 (0.225 mi.) AH332 601
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Id/Status:: 3-074462
Site Status: Unregulated

GATEWAY PLAZA 1 NORTH LEXINGTON AV W 1/8 - 1/4 (0.238 mi.) AN363 642
Database: WESTCHESTER CO. UST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
Status: 4. Closed - in place
Status: 1. In-Service
Status: 0. Administratively closed
Id/Status:: 3-496871
Id/Status:: 3-800106
Site Status: Active
Site Status: Unregulated: <1101 gal. PBS

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 27 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COURT & MARTINE 2009	39-55 COURT ST / 167	E 0 - 1/8 (0.010 mi.)	A43	76
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019 Status: 1. In-Service PBS Number: 3-177903				
WESTCHESTER COUNTY O	148 MARTINE AVENUE	SSE 0 - 1/8 (0.010 mi.)	D45	83
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019 Status: 1. In-Service PBS Number: 3-168777				
COUNTY OF WESTCHESTE	85 COURT STREET	SE 0 - 1/8 (0.058 mi.)	D100	182
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019 Status: 1. In-Service PBS Number: 3-801525				
196-200 MARTINE AVEN	196-200 MARTINE AVEN	ESE 0 - 1/8 (0.068 mi.)	F108	200
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019				

Status: 2. Temporarily out of service
PBS Number: 3-802125

48 MAMARONECK AVENUE | 48 MAMARONECK AVENUE | ESE 0 - 1/8 (0.069 mi.) | F110 | 202
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
PBS Number: 3-074632

204 MARTINE ASSOCIAT | 204 MARTINE AVE | E 0 - 1/8 (0.104 mi.) | J145 | 256
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
PBS Number: 3-173398

RENAISSANCE CORPORAT | 235 MAIN STREET | NE 0 - 1/8 (0.106 mi.) | K150 | 268
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-049980

55 CHURCH WP LLC | 55 CHURCH STREET | NNE 0 - 1/8 (0.106 mi.) | K152 | 269
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-800862
PBS Number: 3-800303

AMCOTT ASSOCIATES | 300 HAMILTON AVENUE | N 0 - 1/8 (0.125 mi.) | M178 | 307
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-259241

M AND T BANK | 134 MAMARONECK AVENU | SE 1/8 - 1/4 (0.158 mi.) | R210 | 368
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 3. Closed - Removed
PBS Number: 3-601013

RECKSON METRO CENTER | 360 HAMILTON AVE | NNE 1/8 - 1/4 (0.179 mi.) | W234 | 406
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-177342

170 GRAND STREET ASS | 170 GRAND STREET | S 1/8 - 1/4 (0.197 mi.) | AC278 | 485
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-800392

WESTCHESTER COUNTY O | 112 EAST POST ROAD | SSE 1/8 - 1/4 (0.202 mi.) | AB287 | 504
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-801218

PUCKHINKONNUCK CORP. | 190 EAST POST ROAD | ESE 1/8 - 1/4 (0.212 mi.) | AG305 | 537
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-032476

193-197 EAST POST RO | 193-197 EAST POST RO | ESE 1/8 - 1/4 (0.227 mi.) | AG339 | 611
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-178683

BARKER AVENUE OWNERS | 33 BARKER AVENUE | N 1/8 - 1/4 (0.244 mi.) | AJ372 | 680
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-169668

Lower Elevation	Address	Direction / Distance	Map ID	Page

WYASSUP-LAUREL GLEN | 175 MAIN STREET | N 0 - 1/8 (0.008 mi.) | A23 | 47
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019

Status: 1. In-Service
PBS Number: 3-032433

NEW YORK POWER AUTHO ***123 MAIN STREET*** ***WNW 0 - 1/8 (0.023 mi.)*** ***B66*** ***118***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Database: AST, Date of Government Version: 02/11/2019
Status: 1. In-Service
PBS Number: 3-496812
Facility Id: 3-602326

199 MAIN STREET REAL ***199 MAIN STREET*** ***NE 0 - 1/8 (0.025 mi.)*** ***C71*** ***138***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-049824

WESTCHESTER COUNTY C ***111 MARTIN LUTHER KI*** ***SSW 0 - 1/8 (0.103 mi.)*** ***N144*** ***254***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-801217

AAMA AUTO SERVICE, I ***274 HAMILTON AVENUE*** ***N 0 - 1/8 (0.123 mi.)*** ***M176*** ***300***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
Status: 3. Closed - Removed
Status: 3a. Closed - Prior to 04/1991
Status: 0. Administratively closed
PBS Number: 3-164135

GALLERIA WEST GARAGE ***MARTINE AVE & SO LEX*** ***WSW 1/8 - 1/4 (0.192 mi.)*** ***Z265*** ***467***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 0. Administratively closed
PBS Number: 3-169579

PUBLIC SAFETY BUILDI ***77 SOUTH LEXINGTON A*** ***WSW 1/8 - 1/4 (0.194 mi.)*** ***Z273*** ***478***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-601115

CHARLES L. BRIEANT U ***300 QUARROPAS STREET*** ***SSW 1/8 - 1/4 (0.203 mi.)*** ***AF294*** ***515***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-801467

STATION PLAZA ***76 SOUTH LEXINGTON A*** ***SW 1/8 - 1/4 (0.209 mi.)*** ***AH302*** ***527***
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 0. Administratively closed
Status: 3. Closed - Removed
PBS Number: 3-139637

PEPE CADILLAC 15 WATER STREET NW 1/8 - 1/4 (0.219 mi.) AA321 573
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-801848

GATEWAY CENTER ONE 1 NORTH LEXINGTON AV W 1/8 - 1/4 (0.238 mi.) AN360 638
Database: WESTCHESTER CO. AST, Date of Government Version: 01/02/2019
Status: 1. In-Service
PBS Number: 3-496871

MA AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Protection's Summary Listing of all the Tanks Registered in the State of Massachusetts.

A review of the MA AST list, as provided by EDR, has revealed that there is 1 MA AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CENTURYLINK COMMUNIC	55 CHURCH STREET, FI	NNE 0 - 1/8 (0.106 mi.)	K153	270
Database: AST 2, Date of Government Version: 01/15/2019				

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 11/12/2018 has revealed that there is 1 NY ENG CONTROLS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NW 1/8 - 1/4 (0.221 mi.)***	***AI328***	***584***
Site Code: 58617				

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 11/12/2018 has revealed that there is 1 NY INST CONTROL site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NW 1/8 - 1/4 (0.221 mi.)***	***AI328***	***584***
Site Code: 58617				

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there is 1 NY VCP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NW 1/8 - 1/4 (0.221 mi.)***	***AI328***	***584***
Database: VCP, Date of Government Version: 11/12/2018				
Site Code: 58617				

EXECUTIVE SUMMARY

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 11/12/2018 has revealed that there are 3 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
221 MAIN STREET Site Code: 58997	***221 MAIN ST***	***NE 0 - 1/8 (0.083 mi.)***	***G120***	***215***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON - VAULT 9 Site Code: 570663	***200 HAMILTON AVE & C***	***NNW 0 - 1/8 (0.105 mi.)***	***M148***	***263***
YOUNG COAL & LUMBER Site Code: 481411	***55 BANK STREET***	***WSW 1/4 - 1/2 (0.341 mi.)***	***AY410***	***761***

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 11/12/2018 has revealed that there are 49 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
I/F/O THE MELTING PO Site ID: 431359 Spill Number/Closed Date: 1000201 / 2010-04-06	35 COURT ST	E 0 - 1/8 (0.010 mi.)	A41	74
MINSKOFF MANAGEMENT Site ID: 239414 Spill Number/Closed Date: 9110040 / 1992-03-10	39-47 COURT STREET	E 0 - 1/8 (0.010 mi.)	A42	75
MICHAEL E LAND OFFIC Site ID: 183296 Site ID: 126441 Site ID: 337374 Spill Number/Closed Date: 9202919 / 1992-07-13 Spill Number/Closed Date: 9103040 / 1991-06-18 Spill Number/Closed Date: 0412020 / 2008-12-18	***148 MARTINE AVE***	***SSE 0 - 1/8 (0.010 mi.)***	***D44***	***77***
DPW VEHICLE Site ID: 486412 Spill Number/Closed Date: 1305831 / 2013-10-07	COURT ST AND MARTINE	SE 0 - 1/8 (0.013 mi.)	D51	96
SPILL NUMBER 8900947 Site ID: 253231	148 MARTEEN AVENUE	SSE 0 - 1/8 (0.019 mi.)	D63	114

Spill Number/Closed Date: 8900947 / 1989-07-25				
TM 5706	MARTINE AVE/ COURT S	SE 0 - 1/8 (0.027 mi.)	D73	140
Site ID: 131740				
Spill Number/Closed Date: 0302648 / 2003-06-18				
SPILL NUMBER 0108867	412 MARTIN AND COURT	SE 0 - 1/8 (0.027 mi.)	D74	141
Site ID: 78764				
Spill Number/Closed Date: 0108867 / 2001-12-05				
LITTLE HOUSE RESTAUR	169 MARTINE AVE	ESE 0 - 1/8 (0.030 mi.)	D75	142
Site ID: 91914				
Spill Number/Closed Date: 8802366 / 1988-06-23				
CAMERA STORE	44 MAMARONECK AVE	E 0 - 1/8 (0.053 mi.)	F91	167
Site ID: 117103				
Spill Number/Closed Date: 9211618 / 1994-09-13				
WOOLWORTH STORE BASE	24-34 MAMARONECK AVE	E 0 - 1/8 (0.053 mi.)	F92	168
Site ID: 94110				
Spill Number/Closed Date: 9408182 / 1995-10-06				
24-46 MAMARONECK ASS	34 MAMARONECK AVE	E 0 - 1/8 (0.053 mi.)	F94	175
Site ID: 397212				
Spill Number/Closed Date: 0801310 / 2008-07-24				
QUICK PICK SHOES	40 MAMARONECK	E 0 - 1/8 (0.053 mi.)	F95	177
Site ID: 72336				
Spill Number/Closed Date: 9407242 / 1995-10-12				
IN DITCH	IN FRONT OF 187 MART	ESE 0 - 1/8 (0.055 mi.)	F96	178
Site ID: 440646				
Spill Number/Closed Date: 1007249 / 2014-04-29				
213 MAIN STREET	213 MAIN ATREET	NE 0 - 1/8 (0.058 mi.)	C97	179
Site ID: 106609				
Spill Number/Closed Date: 9107596 / 1991-10-24				
CAPELLI CONSTRUCTION	MAIN ST & MAMARONECK	NE 0 - 1/8 (0.067 mi.)	G106	198
Site ID: 119716				
Spill Number/Closed Date: 0203876 / 2002-07-12				
MAMARANECK AV	MAIN ST	NE 0 - 1/8 (0.067 mi.)	G107	199
Site ID: 253715				
Spill Number/Closed Date: 0111231 / 2002-02-26				
EMPLOYMENT BUILDING?	48 MAMARONECK AVE.	ESE 0 - 1/8 (0.069 mi.)	F109	201
Site ID: 391767				
Spill Number/Closed Date: 0710471 / 2008-01-08				
TARGET CONSTRUCTION	7 MAMARONECK AVE	ENE 0 - 1/8 (0.070 mi.)	G111	203
Site ID: 231571				
Spill Number/Closed Date: 0306496 / 2003-09-23				
WHITE PLAINS CITY CE	MAMARONECK/MARTINE A	ESE 0 - 1/8 (0.071 mi.)	F113	204
Site ID: 168279				
Spill Number/Closed Date: 0111561 / 2004-03-10				
ROADWAY	MAMARONECK AVE AND M	ESE 0 - 1/8 (0.074 mi.)	F115	208
Site ID: 464312				
Spill Number/Closed Date: 1201594 / 2012-05-21				
SPILL NUMBER 0103591	MAMARONECK AVE/MARTI	ESE 0 - 1/8 (0.078 mi.)	F117	211
Site ID: 254230				
Spill Number/Closed Date: 0103591 / 2001-08-09				
UNOCCUPIED COMMERCIA	31 MAMARONECK AVE	E 0 - 1/8 (0.081 mi.)	F119	213

Site ID: 263395
Spill Number/Closed Date: 9704158 / 2004-09-08

221 MAIN STREET	***221 MAIN ST***	***NE 0 - 1/8 (0.083 mi.)***	***G120***	***215***
Site ID: 349725 Site ID: 387315 Site ID: 343904 Site ID: 342486 Spill Number/Closed Date: 0504810 / 2008-06-17 Spill Number/Closed Date: 0706741 / 2008-07-31 Spill Number/Closed Date: 0500820 / 2008-06-17 Spill Number/Closed Date: 0413395 / 2005-05-12				
47 MAMARONECK AVENUE	47 MAMARONECK AVENUE	ESE 0 - 1/8 (0.090 mi.)	J127	229
Site ID: 423210 Spill Number/Closed Date: 0910450 / 2013-05-07				
IN STREET	55 CHURCH STREET	NNE 0 - 1/8 (0.094 mi.)	K128	231
Site ID: 126397 Spill Number/Closed Date: 9307797 / 1993-09-29				
CIGARETTE WORLD	10-12 QUARROPAS ST	SE 0 - 1/8 (0.099 mi.)	I135	239
Site ID: 363053 Spill Number/Closed Date: 0600936 / 2006-04-26				
CON ED VAULT TM572	MAMARONECK AVE AT MI	SE 0 - 1/8 (0.106 mi.)	J154	270
Site ID: 258368 Spill Number/Closed Date: 0403577 / 2004-07-08				
POST OFFICE SQUARE	QUARROPAS ST	SSE 0 - 1/8 (0.113 mi.)	I159	275
Site ID: 106758 Spill Number/Closed Date: 8807856 / 1989-07-05				
LIGHTHOUSE FOR THE B	44 CHURCH STREET	NNE 0 - 1/8 (0.119 mi.)	K165	282
Site ID: 112766 Spill Number/Closed Date: 9314430 / 1997-11-12				

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
OFFICE BLDG	175 MAIN ST	N 0 - 1/8 (0.008 mi.)	A24	48
Site ID: 83742 Spill Number/Closed Date: 9910497 / 1999-12-02				
DRAIN - COOKING GREA	175 MAIN STREET	N 0 - 1/8 (0.008 mi.)	A25	49
Site ID: 524609 Spill Number/Closed Date: 1511825 / 2016-04-11				
ROADWAY	MAIN ST & COURT ST	NNE 0 - 1/8 (0.010 mi.)	C32	59
Site ID: 410519 Spill Number/Closed Date: 0812871 / 2009-02-27				
ODDESY CORP MAINT DE	***123 MAIN STREET***	***WNW 0 - 1/8 (0.023 mi.)***	***B68***	***130***
Site ID: 160998 Spill Number/Closed Date: 8606381 / 1987-03-16				
MANHOLE # 10236	189 MAIN STREET	N 0 - 1/8 (0.023 mi.)	C70	136
Site ID: 354925 Site ID: 364045 Spill Number/Closed Date: 0509190 / 2005-11-01 Spill Number/Closed Date: 0601744 / 2008-06-11				
MARTIN LUTHER KING &	MAIN STREET	WNW 0 - 1/8 (0.025 mi.)	B72	139

Site ID: 326507
Spill Number/Closed Date: 0101975 / 2001-05-21

SOIL	3 RENAISSANCE SQUARE	NNE 0 - 1/8 (0.038 mi.)	C76	143
Site ID: 445639				
Spill Number/Closed Date: 1011749 / 2011-03-31				
VAULT #0070	MAIN ST & GROVE ST	WNW 0 - 1/8 (0.049 mi.)	B88	164
Site ID: 179454				
Spill Number/Closed Date: 9908279 / 1999-10-07				
WHITE PLAINS GARAGE	MAIN ST & GROVE ST	WNW 0 - 1/8 (0.049 mi.)	B89	165
Site ID: 179453				
Spill Number/Closed Date: 9110939 / 1992-01-24				
IN FRONT OF GALERIA	MAIN ST	W 0 - 1/8 (0.081 mi.)	H118	212
Site ID: 253722				
Spill Number/Closed Date: 9809244 / 1998-10-23				
MANHOLE #4021	HAMILTON AVE & GROVE	NW 0 - 1/8 (0.096 mi.)	L130	233
Site ID: 69649				
Spill Number/Closed Date: 0205032 / 2002-08-13				
CAPELLI CONSTRUCTION	HAMILTON AVE/COTTAGE	N 0 - 1/8 (0.096 mi.)	M131	234
Site ID: 365413				
Spill Number/Closed Date: 0602844 / 2006-06-16				
CONSTRUCTION SITE	HAMILTON AVE/COTTAGE	N 0 - 1/8 (0.096 mi.)	M132	235
Site ID: 360291				
Spill Number/Closed Date: 0513756 / 2006-03-01				
MAN HOLE	HAMILTON AVE AND COT	N 0 - 1/8 (0.096 mi.)	M133	236
Site ID: 418169				
Spill Number/Closed Date: 0905876 / 2009-08-20				
NYNEX	***111 MAIN ST***	***WNW 0 - 1/8 (0.104 mi.)***	***H146***	***257***
Site ID: 239423				
Spill Number/Closed Date: 9808850 / 1998-10-16				
CON EDISON - VAULT 9	***200 HAMILTON AVE & C***	***NNW 0 - 1/8 (0.105 mi.)***	***M148***	***263***
Site ID: 560605				
Spill Number/Closed Date: 1706297 / Not Reported				
VAULT 9104	MARTINE AVE	SW 0 - 1/8 (0.113 mi.)	158	274
Site ID: 312169				
Spill Number/Closed Date: 0009470 / 2000-11-20				
C.F	274 HAMILTON ABVE	N 0 - 1/8 (0.117 mi.)	M161	278
Site ID: 397930				
Spill Number/Closed Date: 0801891 / 2008-05-19				
WESTCHESTER COURTHOU	GROVE ST AND QUARROP	S 0 - 1/8 (0.122 mi.)	N170	287
Site ID: 167279				
Spill Number/Closed Date: 0010532 / 2002-10-02				
EXXON SERVICE STATIO	***274 HAMILTON AVE***	***N 0 - 1/8 (0.123 mi.)***	***M175***	***296***
Site ID: 105471				
Site ID: 404037				
Spill Number/Closed Date: 9707887 / Not Reported				
Spill Number/Closed Date: 0806742 / 2009-02-24				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/01/2018 has revealed that there are 91 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA ID:: NYP004432662	***19 COURT ST***	***ENE 0 - 1/8 (0.010 mi.)***	***A26***	***50***
CON EDISON EPA ID:: NYP004785739	***148 MARTINE AVE***	***SSE 0 - 1/8 (0.010 mi.)***	***D48***	***90***
CON EDISON MANHOLE 9 EPA ID:: NYP004224176	***MARTINE AVE & COURT***	***SE 0 - 1/8 (0.013 mi.)***	***D53***	***99***
CON EDISON EPA ID:: NYP004784880	***COURT ST & MARTINE A***	***SE 0 - 1/8 (0.013 mi.)***	***D54***	***102***
CON EDISON TRANSFORM EPA ID:: NYP004321162	***MARTINE AVE & COURT***	***SE 0 - 1/8 (0.013 mi.)***	***D60***	***110***
WHITE PLAINS TOWN CE EPA ID:: NYR000062356	MAMARONECK AVE & MAI	NE 0 - 1/8 (0.062 mi.)	G102	188
CON EDISON MANHOLE: EPA ID:: NYP004312302	***MAMARONECK AVE & MAI***	***NE 0 - 1/8 (0.065 mi.)***	***G103***	***189***
CON EDISON EPA ID:: NYP004213484	***240 MARTINE AVE & MA***	***ESE 0 - 1/8 (0.074 mi.)***	***F114***	***205***
1-HOUR PHOTO FINISH EPA ID:: NYR000035253	***60B MAMARONECK AVE***	***ESE 0 - 1/8 (0.076 mi.)***	***F116***	***209***
CON EDISON EPA ID:: NYP004161261	***MAIN ST & CHURCH ST***	***NE 0 - 1/8 (0.087 mi.)***	***G124***	***224***
CON EDISON TRANSFORM EPA ID:: NYP004475315	***MITCHELL PL & MAMARO***	***ESE 0 - 1/8 (0.108 mi.)***	***J155***	***271***
RECKSON ASSOCIATES EPA ID:: NYR000096263	***140 GRAND ST***	***S 1/8 - 1/4 (0.134 mi.)***	***N183***	***315***
WHITE PLAINS DEPT OF EPA ID:: NYN008015984	255 MAIN ST	NE 1/8 - 1/4 (0.137 mi.)	Q185	319
T S T WHITE PLAINS L EPA ID:: NYR000054361	***220 MAIN ST***	***ENE 1/8 - 1/4 (0.143 mi.)***	***Q195***	***333***
177 GRAND STREET ASS EPA ID:: NYR000063727	***177 GRAND ST***	***S 1/8 - 1/4 (0.146 mi.)***	***O198***	***340***
CON EDISON EPA ID:: NYP004806469	134 MAMARONECK AVE	SE 1/8 - 1/4 (0.158 mi.)	R206	361
CON EDISON EPA ID:: NYP004805065	***134 MAMARANECK AVE***	***SE 1/8 - 1/4 (0.158 mi.)***	***R209***	***367***
CON EDISON MANHOLE EPA ID:: NYP004211173	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q215***	***376***
CON EDISON SERVICE B	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q217***	***381***

EPA ID:: NYP004462990				
CON EDISON	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q218***	***383***
EPA ID:: NYP004757043				
CON EDISON	***128 MAMARONECK AVE***	***SE 1/8 - 1/4 (0.162 mi.)***	***R219***	***384***
EPA ID:: NYP004846877				
CON EDISON SERVICE B	***133 MAMARONECK AVE I***	***SE 1/8 - 1/4 (0.175 mi.)***	***R228***	***397***
EPA ID:: NYP004368668				
RECKSON ASSOCIATES	***360 HAMILTON AVE - M***	***NNE 1/8 - 1/4 (0.179 mi.)***	***W235***	***410***
EPA ID:: NYR000071779				
CON EDISON	***148 MAMARONECK AVE F***	***SE 1/8 - 1/4 (0.191 mi.)***	***X246***	***432***
EPA ID:: NYP004192761				
CON EDISON	148 MAMARONECK AVE	SE 1/8 - 1/4 (0.191 mi.)	X247	435
EPA ID:: NYP004799854				
CON EDISON MANHOLE 3	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X253***	***444***
EPA ID:: NYP004225892				
CON EDISON MANHOLE 3	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X254***	***448***
EPA ID:: NYP004225900				
CON EDISON	***E POST RD & MAMMARON***	***SE 1/8 - 1/4 (0.191 mi.)***	***X255***	***451***
EPA ID:: NYP004801361				
CON EDISON MANHOLE:	***149 MAMARONECK AVE F***	***SE 1/8 - 1/4 (0.199 mi.)***	***X283***	***498***
EPA ID:: NYP004366654				
WESTCHESTER COUNTY -	***112 E POST RD***	***SSE 1/8 - 1/4 (0.202 mi.)***	***AB289***	***506***
EPA ID:: NYD986951978				
CON EDISON MANHOLE	***WALLER AVE & E POST***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AG299***	***522***
EPA ID:: NYP004208852				
PIP PRINTING	***190 E POST RD***	***ESE 1/8 - 1/4 (0.212 mi.)***	***AG304***	***534***
EPA ID:: NY0000298893				
WESTCHESTER HOBBIES	***104 E POST RD***	***SSE 1/8 - 1/4 (0.216 mi.)***	***AC307***	***539***
EPA ID:: NYR000050658				
WHITE PLAINS CITY OF	MARTINE AVE PUBLIC L	E 1/8 - 1/4 (0.216 mi.)	308	541
EPA ID:: NYD986951986				
WHITE PLAINS LL CENT	400 HAMILTON AVE	NNE 1/8 - 1/4 (0.218 mi.)	W313	554
EPA ID:: NYD980529192				
WHITE PLAINS LL CENT	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W316***	***561***
EPA ID:: NYD980525919				
CON EDISON - VAULT 5	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W317***	***564***
EPA ID:: NYP004135695				
CON EDISON MANHOLE:	***BARKER AVE & CHURCH***	***N 1/8 - 1/4 (0.218 mi.)***	***AJ319***	***568***
EPA ID:: NYP004365813				
CON EDISON SERVICE B	***BARKER AVE & CHURCH***	***N 1/8 - 1/4 (0.218 mi.)***	***AJ320***	***571***
EPA ID:: NYP004450730				
CON EDISON	100 POST RD	S 1/8 - 1/4 (0.226 mi.)	AC336	607
EPA ID:: NYP004761797				
CON EDISON	E POST RD & GRAND ST	S 1/8 - 1/4 (0.230 mi.)	AC345	618
EPA ID:: NYP004772521				
CON EDISON	***E POST RD & GRAND ST***	***S 1/8 - 1/4 (0.230 mi.)***	***AC348***	***622***

EPA ID:: NYP004772455				
CON EDISON EPA ID:: NYP004772372	CROMWELL PL & E POST	S 1/8 - 1/4 (0.234 mi.)	AC351	627
CON EDISON EPA ID:: NYP004210779	***CROMWELL PL & E POST***	***S 1/8 - 1/4 (0.234 mi.)***	***AC354***	***630***
CHESTER MAPLE PARKIN EPA ID:: NYD986984714	***9 CHESTER AVE***	***SSE 1/8 - 1/4 (0.244 mi.)***	***AL371***	***678***
CON EDISON EPA ID:: NYP004193967	***184 MAMARONECK AVE &***	***SE 1/8 - 1/4 (0.246 mi.)***	***AO375***	***683***
CON EDISON EPA ID:: NYP004804688	***445 HAMILTON AVE***	***NE 1/8 - 1/4 (0.248 mi.)***	***AP377***	***686***

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA ID:: NYP004846109	WILLIAMS ST & MAIN S	NW 0 - 1/8 (0.006 mi.)	B15	33
CON EDISON EPA ID:: NYP004214599	***WILLIAMS ST & MAIN S***	***NW 0 - 1/8 (0.006 mi.)***	***B16***	***34***
CON EDISON MANHOLE: EPA ID:: NYP004328050	***MAIN ST & WILLIAMS S***	***NW 0 - 1/8 (0.006 mi.)***	***B17***	***37***
CON EDISON MANHOLE 5 EPA ID:: NYP004137717	COURT ST & MAIN ST	NNE 0 - 1/8 (0.010 mi.)	C28	53
CON EDISON MANHOLE 1 EPA ID:: NYP004146551	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C29***	***54***
CON EDISON MANHOLE: EPA ID:: NYP004432753	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C30***	***56***
CON EDISON EPA ID:: NYP004784807	COURT ST & MAIN ST	NNE 0 - 1/8 (0.010 mi.)	C33	60
CON EDISON MANHOLE 1 EPA ID:: NYP004224754	***COURT ST & MAIN ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C34***	***61***
CON EDISON EPA ID:: NYP004146833	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C35***	***65***
CON EDISON MANHOLE: EPA ID:: NYP004327854	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C36***	***66***
CON EDISON SERVICE B EPA ID:: NYP004450573	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C38***	***69***
CON EDISON EPA ID:: NYP004350450	***COURT ST & MAIN ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C40***	***73***
NY POWER AUTH EPA ID:: NYD986983468	123 MAIN ST	WNW 0 - 1/8 (0.023 mi.)	B65	116
CON EDISON EPA ID:: NYP004398962	***MARTINE & GROVE ST***	***SW 0 - 1/8 (0.047 mi.)***	***E81***	***149***
CON EDISON MANHOLE 9 EPA ID:: NYP004224465	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E83***	***152***
CON EDISON MANHOLE 9 EPA ID:: NYP004224101	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E84***	***156***
CON EDISON MANHOLE 9	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E85***	***159***

EPA ID:: NYP004224192				
CON EDISON MANHOLE 9 EPA ID:: NYP004232856	MAIN ST & MARTIN LUT	WNW 0 - 1/8 (0.049 mi.)	B90	166
WHITE PLAINS POLICE EPA ID:: NYD986876019	***279 HAMILTON AVE***	***N 0 - 1/8 (0.102 mi.)***	***K138***	***244***
WESTCHESTER COUNTY C EPA ID:: NYR000028902	***111 GROVE ST***	***SSW 0 - 1/8 (0.103 mi.)***	***N142***	***250***
CON EDISON EPA ID:: NYP004885055	111 MARTIN LUTHER KI	SSW 0 - 1/8 (0.103 mi.)	N143	253
NYNEX MATERIEL ENTER EPA ID:: NYD980582480	***111 MAIN ST***	***WNW 0 - 1/8 (0.104 mi.)***	***H147***	***260***
CON EDISON EPA ID:: NYP004805560	QUARROPAS ST & MLK B	S 0 - 1/8 (0.122 mi.)	N167	284
CON EDISON EPA ID:: NYP004213476	***GROVE ST & QUARROPAS***	***S 0 - 1/8 (0.122 mi.)***	***N171***	***288***
CON EDISON EPA ID:: NYP004212403	***81 MAIN ST FRONT OF***	***W 1/8 - 1/4 (0.159 mi.)***	***U211***	***369***
CON EDISON EPA ID:: NYP004825978	***GROVE ST & FISCHER C***	***S 1/8 - 1/4 (0.175 mi.)***	***V229***	***399***
CON EDISON SERVICE B EPA ID:: NYP004428926	***GROVE ST & FISCHER A***	***S 1/8 - 1/4 (0.175 mi.)***	***V231***	***402***
CON EDISON VAULT: 70 EPA ID:: NYP004371571	***MAIN ST & LEXINGTON***	***W 1/8 - 1/4 (0.186 mi.)***	***U240***	***423***
CON EDISON MANHOLE: EPA ID:: NYP004307484	***LEXINGTON AVE & MAIN***	***W 1/8 - 1/4 (0.186 mi.)***	***U242***	***427***
CON EDISON EPA ID:: NYP004786067	N LEXINGTON AVE & MA	WSW 1/8 - 1/4 (0.192 mi.)	Z256	452
CON EDISON SERVICE B EPA ID:: NYP004408274	***S LEXINGTON AVE & MA***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z258***	***455***
CON EDISON MANHOLE: EPA ID:: NYP004318374	***MARTINE AVE & S LEXI***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z259***	***457***
CON EDISON SERVICE B EPA ID:: NYP004408282	***S LEXINGTON AVE & MA***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z262***	***462***
CON EDISON MANHOLE: EPA ID:: NYP004420485	***BARKER ST & COTTAGE***	***NNW 1/8 - 1/4 (0.194 mi.)***	***Y269***	***472***
CON EDISON VAULT: 52 EPA ID:: NYP004485504	***COTTAGE PL & BARKER***	***NNW 1/8 - 1/4 (0.194 mi.)***	***Y270***	***474***
CON EDISON EPA ID:: NYP004210985	***LEXINGTON & HAMILTON***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD280***	***488***
CON EDISON EPA ID:: NYP004210852	***HAMILTON & N LEXINGT***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD281***	***492***
CON EDISON MANHOLE: EPA ID:: NYP004398830	***HAMILTON AVE & LEXIN***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD282***	***495***
CON EDISON SERVICE B EPA ID:: NYP004514436	***FISHER CT & QUARROPA***	***SSW 1/8 - 1/4 (0.202 mi.)***	***AF290***	***509***
CON EDISON MANHOLE:	***QUARROPAS ST & FISCH***	***SSW 1/8 - 1/4 (0.202 mi.)***	***AF292***	***512***

EPA ID:: NYP004314233				
CON EDISON MANHOLE 4	***BARKER AVE & GROVE S***	***NW 1/8 - 1/4 (0.206 mi.)***	***AA298***	***521***
EPA ID:: NYP004146783				
SAFE FLIGHT INSTRUME	***20 NEW KING ST***	***WNW 1/8 - 1/4 (0.209 mi.)***	***AI303***	***529***
EPA ID:: NYD001221530				
WHITE PLAINS GENL AU	***76 HAMILTON AVE***	***WNW 1/8 - 1/4 (0.216 mi.)***	***AD309***	***543***
EPA ID:: NYD013395397				
CON EDISON MANHOLE 5	LEXINGTON AVE & NEW	WNW 1/8 - 1/4 (0.217 mi.)	AD310	545
EPA ID:: NYP004140646				

FUSRAP: DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

A review of the FUSRAP list, as provided by EDR, and dated 08/08/2017 has revealed that there is 1 FUSRAP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NUCLEAR DEVELOPMENT	5 NEW STREET	WNW 1/8 - 1/4 (0.222 mi.)	AI330	599
Site Status: Eliminated from consideration under FUSRAP				
Site ID: NY.32				

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 116 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B	***19 COURT ST***	***ENE 0 - 1/8 (0.010 mi.)***	***A26***	***50***
EPA ID: NYP004432662				
WESTCHESTER COUNTY O	***148 MARTINE AVE***	***SSE 0 - 1/8 (0.010 mi.)***	***D49***	***91***
EPA ID: NYD072705213				
CON ED	148 MARTINE AVE	SSE 0 - 1/8 (0.010 mi.)	D50	95
EPA ID: NYP004785739				
CON EDISON	COURT ST & MARTINE A	SE 0 - 1/8 (0.013 mi.)	D52	97
EPA ID: NYP004784880				
CON EDISON MANHOLE 9	***MARTINE AVE & COURT***	***SE 0 - 1/8 (0.013 mi.)***	***D53***	***99***
EPA ID: NYP004224176				
CON EDISON	MARTINE AVE & COURT	SE 0 - 1/8 (0.013 mi.)	D56	105
EPA ID: NYP004714374				
CON EDISON	MARTINE AVE & COURT	SE 0 - 1/8 (0.013 mi.)	D57	106
EPA ID: NYP004714358				
CON EDISON	MARTINE & COURT ST	SE 0 - 1/8 (0.013 mi.)	D59	109
EPA ID: NYP004850869				
CON EDISON TRANSFORM	***MARTINE AVE & COURT***	***SE 0 - 1/8 (0.013 mi.)***	***D60***	***110***

EPA ID: NYP004321162				
CVS PHARMACY #4745	***26-32 MAMARONECK AVE***	***E 0 - 1/8 (0.053 mi.)***	***F93***	***169***
EPA ID: NYR000194852				
CON EDISON MANHOLE:	***MAMARONECK AVE & MAI***	***NE 0 - 1/8 (0.065 mi.)***	***G103***	***189***
EPA ID: NYP004789996				
EPA ID: NYP004312302				
CON EDISON MANHOLE:	***221 MAIN ST***	***NE 0 - 1/8 (0.067 mi.)***	***G104***	***194***
EPA ID: NYP004308268				
1-HOUR PHOTO FINISH	***60B MAMARONECK AVE***	***ESE 0 - 1/8 (0.076 mi.)***	***F116***	***209***
EPA ID: NYR000035253				
CON EDISON	***MAIN ST & CHURCH ST***	***NE 0 - 1/8 (0.087 mi.)***	***G124***	***224***
EPA ID: NYP004161261				
NYSDEC	GRAND & QUARRAPUS	S 0 - 1/8 (0.103 mi.)	N140	247
EPA ID: NYP003600954				
CON EDISON TRANSFORM	***MITCHELL PL & MAMARO***	***ESE 0 - 1/8 (0.108 mi.)***	***J155***	***271***
EPA ID: NYP004475315				
RECKSON ASSOCIATES	***140 GRAND ST***	***S 1/8 - 1/4 (0.134 mi.)***	***N183***	***315***
EPA ID: NYR000096263				
CON EDISON - VAULT 4	161 GRAND ST	S 1/8 - 1/4 (0.136 mi.)	O184	318
EPA ID: NYP004983803				
WHITE PLAINS DEPT OF	***255 MAIN STREET***	***NE 1/8 - 1/4 (0.137 mi.)***	***Q186***	***320***
EPA ID: NYD000877423				
CON EDISON	218 MAIN ST	ENE 1/8 - 1/4 (0.141 mi.)	Q191	329
EPA ID: NYP004586020				
T S T WHITE PLAINS L	***220 MAIN ST***	***ENE 1/8 - 1/4 (0.143 mi.)***	***Q195***	***333***
EPA ID: NYR000054361				
177 GRAND STREET ASS	***177 GRAND ST***	***S 1/8 - 1/4 (0.146 mi.)***	***O198***	***340***
EPA ID: NYR000063727				
TARGET STORE T1358	***9 CITY PL***	***ENE 1/8 - 1/4 (0.157 mi.)***	***Q204***	***349***
EPA ID: NYR000134106				
CON EDISON	***134 MAMARONECK AVE***	***SE 1/8 - 1/4 (0.158 mi.)***	***R207***	***362***
EPA ID: NYP004806469				
CON EDISON	134 MAMARANECK AVE	SE 1/8 - 1/4 (0.158 mi.)	R208	365
EPA ID: NYP004805065				
CON EDISON	MAIN ST & CITY PL	ENE 1/8 - 1/4 (0.161 mi.)	Q214	375
EPA ID: NYP004757043				
CON EDISON MANHOLE	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q215***	***376***
EPA ID: NYP004211173				
CON EDISON SERVICE B	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q217***	***381***
EPA ID: NYP004462990				
CON EDISON	128 MAMARONECK AVE	SE 1/8 - 1/4 (0.162 mi.)	R220	386
EPA ID: NYP004846877				
CON EDISON SERVICE B	***133 MAMARONECK AVE I***	***SE 1/8 - 1/4 (0.175 mi.)***	***R228***	***397***
EPA ID: NYP004368668				
RECKSON ASSOCIATES	***360 HAMILTON AVE - M***	***NNE 1/8 - 1/4 (0.179 mi.)***	***W235***	***410***
EPA ID: NYR000071779				
A T & T	***360 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.179 mi.)***	***W236***	***415***

EPA ID: NYP005001854 EPA ID: NYD986998060				
CON EDISON EPA ID: NYP004192761 EPA ID: NYP004799854	***148 MAMARONECK AVE F***	***SE 1/8 - 1/4 (0.191 mi.)***	***X246***	***432***
CON EDISON EPA ID: NYP004688784	MAMARONECK AVE & E P	SE 1/8 - 1/4 (0.191 mi.)	X250	440
CON EDISON EPA ID: NYP004801361	E POST RD & MAMMARON	SE 1/8 - 1/4 (0.191 mi.)	X252	443
CON EDISON MANHOLE 3 EPA ID: NYP004225892	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X253***	***444***
CON EDISON MANHOLE 3 EPA ID: NYP004225900	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X254***	***448***
CON EDISON MANHOLE: EPA ID: NYP004366654	***149 MAMARONECK AVE F***	***SE 1/8 - 1/4 (0.199 mi.)***	***X283***	***498***
WESTCHESTER COUNTY - EPA ID: NYD986951978	***112 E POST RD***	***SSE 1/8 - 1/4 (0.202 mi.)***	***AB289***	***506***
CON EDISON MANHOLE EPA ID: NYP004208852	***WALLER AVE & E POST***	***ESE 1/8 - 1/4 (0.207 mi.)***	***AG299***	***522***
CONSOLIDATED EDISON EPA ID: NYP004229793	WALLER AVE & EAST PO	ESE 1/8 - 1/4 (0.207 mi.)	AG300	524
CON EDISON EPA ID: NYP004852394	POST RD & WALLER AVE	ESE 1/8 - 1/4 (0.207 mi.)	AG301	526
PIP PRINTING EPA ID: NY0000298893	***190 E POST RD***	***ESE 1/8 - 1/4 (0.212 mi.)***	***AG304***	***534***
AT&T EPA ID: NYD070955828	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W314***	***555***
WHITE PLAINS LL CENT EPA ID: NYD980525919	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W316***	***561***
CON EDISON - VAULT 5 EPA ID: NYP004135695	***400 HAMILTON AVE***	***NNE 1/8 - 1/4 (0.218 mi.)***	***W317***	***564***
CON EDISON EPA ID: NYP004763926	400 HAMILTON AVE & E	NNE 1/8 - 1/4 (0.218 mi.)	W318	567
CON EDISON MANHOLE: EPA ID: NYP004365813	***BARKER AVE & CHURCH***	***N 1/8 - 1/4 (0.218 mi.)***	***AJ319***	***568***
CON EDISON SERVICE B EPA ID: NYP004450730	***BARKER AVE & CHURCH***	***N 1/8 - 1/4 (0.218 mi.)***	***AJ320***	***571***
CON EDISON EPA ID: NYP004761797	100 POST RD	S 1/8 - 1/4 (0.226 mi.)	AC338	609
CON ED EPA ID: NYP004772455	E NEW YORK POST RD &	S 1/8 - 1/4 (0.230 mi.)	AC343	616
CON ED EPA ID: NYP004772521	E POST RD & GRAND ST	S 1/8 - 1/4 (0.230 mi.)	AC346	619
CONSOLIDATED EDISON EPA ID: NYP004230025	E NY POST RD & CROMW	S 1/8 - 1/4 (0.234 mi.)	AC350	625
CON ED EPA ID: NYP004772372	CROMWELL PL & E POST	S 1/8 - 1/4 (0.234 mi.)	AC352	627
CON EDISON	CROMWELL PL & E. NY	S 1/8 - 1/4 (0.234 mi.)	AC353	628

EPA ID: NYP004772370				
CON EDISON EPA ID: NYP004210779	***CROMWELL PL & E POST***	***S 1/8 - 1/4 (0.234 mi.)***	***AC354***	***630***
WALMART #3441 EPA ID: NYR000134999	***275 MAIN ST***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AM368***	***660***
SEARS EPA ID: NY0000923193	***MAIN ST***	***ENE 1/8 - 1/4 (0.243 mi.)***	***AM369***	***673***
CHESTER MAPLE PARKIN EPA ID: NYD986984714	9 CHESTER AVE	SSE 1/8 - 1/4 (0.244 mi.)	AL370	677
CON EDISON EPA ID: NYP004193967	***184 MAMARONECK AVE &***	***SE 1/8 - 1/4 (0.246 mi.)***	***AO375***	***683***
CON EDISON EPA ID: NYP004804688	445 HAMILTON AVE	NE 1/8 - 1/4 (0.248 mi.)	AP376	686

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON MANHOLE: EPA ID: NYP004328050	***MAIN ST & WILLIAMS S***	***NW 0 - 1/8 (0.006 mi.)***	***B17***	***37***
CONSOLIDATED EDISON EPA ID: NYP004227389	WILLIAM ST & MAIN ST	NW 0 - 1/8 (0.006 mi.)	B18	39
CON ED- TM462 EPA ID: NYZ004019766	WILLIAMS & MAIN ST	NW 0 - 1/8 (0.006 mi.)	B19	41
CON EDISON EPA ID: NYP004846109	WILLIAMS ST & MAIN S	NW 0 - 1/8 (0.006 mi.)	B20	42
CON EDISON MANHOLE 1 EPA ID: NYP004146551	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C29***	***54***
CON EDISON MANHOLE: EPA ID: NYP004432753	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C30***	***56***
CON EDISON EPA ID: NYP004784807	COURT ST & MAIN ST	NNE 0 - 1/8 (0.010 mi.)	C31	58
CON EDISON MANHOLE 1 EPA ID: NYP004224754	***COURT ST & MAIN ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C34***	***61***
CON EDISON EPA ID: NYP004146833	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C35***	***65***
CON EDISON MANHOLE: EPA ID: NYP004327854	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C36***	***66***
CON EDISON SERVICE B EPA ID: NYP004450573	***MAIN ST & COURT ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C38***	***69***
CON EDISON EPA ID: NYP004384657	COURT ST & MAIN ST	NNE 0 - 1/8 (0.010 mi.)	C39	72
NEW YORK POWER AUTH EPA ID: NYD986982999	***123 MAIN ST***	***WNW 0 - 1/8 (0.023 mi.)***	***B67***	***125***
CON EDISON EPA ID: NYP004398962	MARTINE & GROVE ST	SW 0 - 1/8 (0.047 mi.)	E82	151
CON EDISON MANHOLE 9 EPA ID: NYP004224465	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E83***	***152***
CON EDISON MANHOLE 9	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E84***	***156***

EPA ID: NYP004224101				
CON EDISON MANHOLE 9 EPA ID: NYP004224192	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E85***	***159***
CON EDISON EPA ID: NYP004855397	HAMILTON & MARTIN LU	NW 0 - 1/8 (0.096 mi.)	L129	232
CON EDISON EPA ID: NYP004713814	HAMILTON AVE & RENNA	N 0 - 1/8 (0.097 mi.)	M134	237
WHITE PLAINS POLICE EPA ID: NYP000877423	***279 HAMILTON AVENUE***	***N 0 - 1/8 (0.102 mi.)***	***K137***	***241***
WESTCHESTER COUNTY C EPA ID: NYR000028902	***111 GROVE ST***	***SSW 0 - 1/8 (0.103 mi.)***	***N142***	***250***
NYNEX MATERIEL ENTER EPA ID: NYD980582480	***111 MAIN ST***	***WNW 0 - 1/8 (0.104 mi.)***	***H147***	***260***
CON EDISON - VAULT 9 EPA ID: NYP004937316	***200 HAMILTON AVE & C***	***NNW 0 - 1/8 (0.105 mi.)***	***M148***	***263***
CON EDISON EPA ID: NYP004717195	274 HAMILTON AVE	N 0 - 1/8 (0.117 mi.)	M162	279
CON EDISON EPA ID: NYP004805560	QUARROPAS ST & MLK B	S 0 - 1/8 (0.122 mi.)	N168	284
CON EDISON EPA ID: NYP004733887	QUARROPAS ST & MARTI	S 0 - 1/8 (0.122 mi.)	N169	285
EXXON DIV OF CFI #70 EPA ID: NYD013387436	***274 HAMILTON AVE & C***	***N 0 - 1/8 (0.123 mi.)***	***M174***	***292***
CONSOLIDATED EDISON EPA ID: NYP004108221	***170 HAMILTON AVE***	***WNW 1/8 - 1/4 (0.130 mi.)***	***P182***	***313***
CON EDISON EPA ID: NYP004212403	***81 MAIN ST FRONT OF***	***W 1/8 - 1/4 (0.159 mi.)***	***U211***	***369***
CONSOLIDATED EDISON EPA ID: NYP004228116	GROVE & FISHER	S 1/8 - 1/4 (0.175 mi.)	V230	400
CON EDISON SERVICE B EPA ID: NYP004428926	***GROVE ST & FISCHER A***	***S 1/8 - 1/4 (0.175 mi.)***	***V231***	***402***
CON EDISON EPA ID: NYP004707600	S LEXINGTON AV & MAI	W 1/8 - 1/4 (0.186 mi.)	U239	422
CON EDISON VAULT: 70 EPA ID: NYP004371571	***MAIN ST & LEXINGTON***	***W 1/8 - 1/4 (0.186 mi.)***	***U240***	***423***
CON EDISON EPA ID: NYP004303764	S. LEXINGTON AVE &AM	W 1/8 - 1/4 (0.186 mi.)	U241	425
CON EDISON MANHOLE: EPA ID: NYP004307484	***LEXINGTON AVE & MAIN***	***W 1/8 - 1/4 (0.186 mi.)***	***U242***	***427***
CON EDISON SERVICE B EPA ID: NYP004408274	***S LEXINGTON AVE & MA***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z258***	***455***
CON EDISON MANHOLE: EPA ID: NYP004318374	***MARTINE AVE & S LEXI***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z259***	***457***
CON EDISON EPA ID: NYP004303145	MARTINE AVE & LEXING	WSW 1/8 - 1/4 (0.192 mi.)	Z261	460
CON EDISON SERVICE B	***S LEXINGTON AVE & MA***	***WSW 1/8 - 1/4 (0.192 mi.)***	***Z262***	***462***

EPA ID: NYP004408282				
CON EDISON EPA ID: NYP004786067	N LEXINGTON AVE & MA	WSW 1/8 - 1/4 (0.192 mi.)	Z263	464
CON EDISON EPA ID: NYP004688545	S. LEXINGTON AV &AMP	WSW 1/8 - 1/4 (0.192 mi.)	Z264	466
CON EDISON EPA ID: NYP004485504	COTTAGE PL & BARKER	NNW 1/8 - 1/4 (0.194 mi.)	Y268	471
CON EDISON MANHOLE: EPA ID: NYP004420485	***BARKER ST & COTTAGE***	***NNW 1/8 - 1/4 (0.194 mi.)***	***Y269***	***472***
CON EDISON EPA ID: NYP004210985	***LEXINGTON & HAMILTON***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD280***	***488***
CON EDISON EPA ID: NYP004210852	***HAMILTON & N LEXINGT***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD281***	***492***
CON EDISON MANHOLE: EPA ID: NYP004398830	***HAMILTON AVE & LEXIN***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD282***	***495***
CON EDISON EPA ID: NYP004314833	QUARROPAS ST & FISHE	SSW 1/8 - 1/4 (0.202 mi.)	AF291	511
CON EDISON MANHOLE: EPA ID: NYP004314233	***QUARROPAS ST & FISCH***	***SSW 1/8 - 1/4 (0.202 mi.)***	***AF292***	***512***
CON EDISON EPA ID: NYP004514436	FISHER CT & QUARROPA	SSW 1/8 - 1/4 (0.202 mi.)	AF293	514
CON EDISON MANHOLE 4 EPA ID: NYP004146783	***BARKER AVE & GROVE S***	***NW 1/8 - 1/4 (0.206 mi.)***	***AA298***	***521***
SAFE FLIGHT INSTRUME EPA ID: NYD001221530	***20 NEW KING ST***	***WNW 1/8 - 1/4 (0.209 mi.)***	***AI303***	***529***
CONSOLIKDATED EDISON EPA ID: NYP004139705	NEW ST & LEXINGTON A	WNW 1/8 - 1/4 (0.217 mi.)	AD311	546
CONSOLIDATED EDISON EPA ID: NYP004700894 EPA ID: NYR000023275	9 NEW STREET	WNW 1/8 - 1/4 (0.220 mi.)	AI325	577
CONSOLIDATED EDISON EPA ID: NYP004237859	12 WATER ST - MH 561	NW 1/8 - 1/4 (0.221 mi.)	AI329	598
GATEWAY BLDG EPA ID: NYD986984698	1 N LEXINGTON AVE 13	W 1/8 - 1/4 (0.238 mi.)	AN359	637

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 3 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CVS PHARMACY #4745 Generator EPA Id: NYR000194852	24 MAMARONECK AVE	ENE 0 - 1/8 (0.061 mi.)	F101	183

Lower Elevation	Address	Direction / Distance	Map ID	Page
CUSHMAN & WAKEFIELD	1 N LEXINGTON AVE	W 1/8 - 1/4 (0.238 mi.)	AN361	639

Generator EPA Id: NYD986984698				
CUSHMAN & WAKEFIELD Generator EPA Id: NYD986984698	ONE N LEXINGTON AVE	W 1/8 - 1/4 (0.238 mi.)	AN362	641

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2017 has revealed that there are 38 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON SERVICE B EPA Id: NYP004432662	19 COURT ST	ENE 0 - 1/8 (0.010 mi.)	A27	52
CON EDISON EPA Id: NYP004785739	148 MARTINE AVE	SSE 0 - 1/8 (0.010 mi.)	D46	85
CON EDISON MANHOLE 9 EPA Id: NYP004224176	***MARTINE AVE & COURT***	***SE 0 - 1/8 (0.013 mi.)***	***D53***	***99***
CON EDISON EPA Id: NYP004784880	COURT ST & MARTINE A	SE 0 - 1/8 (0.013 mi.)	D55	103
CON EDISON - MANHOLE EPA Id: NYP004308268	221 MAIN STREET	NE 0 - 1/8 (0.067 mi.)	G105	197
CON EDISON EPA Id: NYP004213484	***240 MARTINE AVE & MA***	***ESE 0 - 1/8 (0.074 mi.)***	***F114***	***205***
CON EDISON EPA Id: NYP004161261	MAIN ST & CHURCH ST	NE 0 - 1/8 (0.087 mi.)	G125	227
CON EDISON MANHOLE EPA Id: NYP004211173	***MAIN ST & CITY PL***	***ENE 1/8 - 1/4 (0.161 mi.)***	***Q215***	***376***
CON EDISON EPA Id: NYP004757043	MAIN ST & CITY PL	ENE 1/8 - 1/4 (0.161 mi.)	Q216	380
CON EDISON EPA Id: NYP004846877	128 MAMARONECK AVE	SE 1/8 - 1/4 (0.162 mi.)	R221	387
CON EDISON EPA Id: NYP004805065	134 MAMARANECK AVE	SE 1/8 - 1/4 (0.171 mi.)	R224	392
CON EDISON EPA Id: NYP004806469	134 MAMARONECK AVE	SE 1/8 - 1/4 (0.171 mi.)	R225	394
CON EDISON EPA Id: NYP004799854	148 MAMARONECK AVE	SE 1/8 - 1/4 (0.191 mi.)	X245	431
CON EDISON EPA Id: NYP004801361	E POST RD & MAMMARON	SE 1/8 - 1/4 (0.191 mi.)	X251	442
CON EDISON MANHOLE 3 EPA Id: NYP004225892	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X253***	***444***
CON EDISON MANHOLE 3 EPA Id: NYP004225900	***MAMARONECK AVE & E P***	***SE 1/8 - 1/4 (0.191 mi.)***	***X254***	***448***
CON EDISON EPA Id: NYD070955828 EPA Id: NYP004763926	400 HAMILTON AVE & E	NNE 1/8 - 1/4 (0.218 mi.)	W315	559
CON EDISON	100 POST RD	S 1/8 - 1/4 (0.226 mi.)	AC337	608

EPA Id: NYP004761797				
CON EDISON EPA Id: NYP004772521	E POST RD & GRAND ST	S 1/8 - 1/4 (0.230 mi.)	AC344	617
CON EDISON EPA Id: NYP004772455	E NEW YORK POST RD &	S 1/8 - 1/4 (0.230 mi.)	AC347	621
CON EDISON EPA Id: NYP004210779	***CROMWELL PL & E POST***	***S 1/8 - 1/4 (0.234 mi.)***	***AC354***	***630***
CON EDISON EPA Id: NYP004804688	445 HAMILTON AVE	NE 1/8 - 1/4 (0.248 mi.)	AP378	687

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON EDISON EPA Id: NYP004846109 EPA Id: NYP004214599	***WILLIAMS ST & MAIN S***	***NW 0 - 1/8 (0.006 mi.)***	***B16***	***34***
CON EDISON MANHOLE 1 EPA Id: NYP004224754	***COURT ST & MAIN ST***	***NNE 0 - 1/8 (0.010 mi.)***	***C34***	***61***
CON EDISON EPA Id: NYP004784807	COURT ST & MAIN ST	NNE 0 - 1/8 (0.010 mi.)	C37	68
CONSOLIDATED EDISON EPA Id: NYP004144358	189 MAIN ST	N 0 - 1/8 (0.023 mi.)	C69	135
CON EDISON MANHOLE 9 EPA Id: NYP004224465	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E83***	***152***
CON EDISON MANHOLE 9 EPA Id: NYP004224101	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E84***	***156***
CON EDISON MANHOLE 9 EPA Id: NYP004224192	***MARTINE AVE & GROVE***	***SW 0 - 1/8 (0.047 mi.)***	***E85***	***159***
CON EDISON EPA Id: NYP004885055	111 MARTIN LUTHER KI	SSW 0 - 1/8 (0.103 mi.)	N141	249
CON EDISON EPA Id: NYP004213476	***GROVE ST & QUARROPAS***	***S 0 - 1/8 (0.122 mi.)***	***N171***	***288***
CON EDISON EPA Id: NYP004805560	QUARROPAS ST & MLK B	S 0 - 1/8 (0.122 mi.)	N172	290
CON EDISON EPA Id: NYP004212403	***81 MAIN ST FRONT OF***	***W 1/8 - 1/4 (0.159 mi.)***	***U211***	***369***
CON EDISON EPA Id: NYP004825978	GROVE ST & FISCHER C	S 1/8 - 1/4 (0.175 mi.)	V232	404
CON EDISON EPA Id: NYP004786067	N LEXINGTON AVE & MA	WSW 1/8 - 1/4 (0.192 mi.)	Z260	459
CON EDISON EPA Id: NYP004210985	***LEXINGTON & HAMILTON***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD280***	***488***
CON EDISON EPA Id: NYP004210852	***HAMILTON & N LEXINGT***	***WNW 1/8 - 1/4 (0.198 mi.)***	***AD281***	***492***
GATEWAY BUILDING EPA Id: NYD986984698	***1 N LEXINGTON AVE 1***	***W 1/8 - 1/4 (0.238 mi.)***	***AN364***	***644***

EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS MGP SIT	9 NEW STREET AND 12	WNW 1/8 - 1/4 (0.220 mi.)	AI324	577

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 3 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
9TH STREET H J LLC	55 CHURCH ST	NNE 0 - 1/8 (0.106 mi.)	K151	268
HAMILTON TEXACO SERV	303 HAMILTON AVE	N 0 - 1/8 (0.111 mi.)	K156	273

Lower Elevation	Address	Direction / Distance	Map ID	Page
CODI BROTHERS INC	274 HAMILTON AVENUE	N 0 - 1/8 (0.117 mi.)	M163	280

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 3 EDR Hist

EXECUTIVE SUMMARY

Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SHARP IMAGE CLEANER	198 MARTINE AVE	ESE 0 - 1/8 (0.071 mi.)	F112	204


Lower Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS MALL CL	200 HAMILTON AVE	NNW 0 - 1/8 (0.105 mi.)	M149	267
BISCARDI FRANK	102 MAIN ST	W 0 - 1/8 (0.121 mi.)	H166	283

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 5 records.

Site Name	Database(s)
COMMERCIAL PROPERTY	NY LTANKS
FORECLOSED - TTF	NY LTANKS
HART RESIDENCE	NY LTANKS
FORMER DPW STAGING AREA	NY VCP
FORMER HANGAR B SEPTIC FIELD	NY VCP

OVERVIEW MAP - 5604205.2S




- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Pipelines
- 100-year flood zone
- 500-year flood zone
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Macys White Plains Galleria ADDRESS: 100 Main Street White Plains NY 10601 LAT/LONG: 41.031696 / 73.768216	CLIENT: ATC Group Services LLC CONTACT: Chelsea Helm INQUIRY #: 5604205.2s DATE: March 28, 2019 2:40 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 5604205.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	Macys White Plains Galleria	CLIENT:	ATC Group Services LLC
ADDRESS:	100 Main Street White Plains NY 10601	CONTACT:	Chelsea Helm
		INQUIRY #:	5604205.2s
LAT/LONG:	41.031696 / 73.768216	DATE:	March 28, 2019 2:42 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		2	3	NR	NR	NR	5
RCRA-SQG	0.250	2	0	4	NR	NR	NR	6
RCRA-CESQG	0.250		4	4	NR	NR	NR	8
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROL	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	0	2	NR	2
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		1	0	0	NR	NR	1
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500	1	20	44	97	NR	NR	162
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250	1	13	34	NR	NR	NR	48
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY MOSF	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	0	NR	NR	NR	0
NY AST	0.250		14	13	NR	NR	NR	27
MA AST	0.250		1	0	NR	NR	NR	1
NY CBS AST	0.250		0	0	NR	NR	NR	0
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	1	0	NR	NR	1
NY INST CONTROL	0.500		0	1	0	NR	NR	1
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	1	0	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		2	0	1	NR	NR	3
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWTIRE	0.500		0	0	0	NR	NR	0
NY SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	1	49	NR	NR	NR	NR	50
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250	3	35	56	NR	NR	NR	94
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	1	0	0	NR	1
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP	7	NR	NR	NR	NR	NR	7
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
ECHO	TP	6	NR	NR	NR	NR	NR	6
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		0	0	NR	NR	NR	0
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250	4	43	73	NR	NR	NR	120
PA MANIFEST	0.250		1	2	NR	NR	NR	3
NJ MANIFEST	0.250		17	21	NR	NR	NR	38
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP	4	NR	NR	NR	NR	NR	4
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	1	0	0	NR	1
EDR Hist Auto	0.125		3	NR	NR	NR	NR	3
EDR Hist Cleaner	0.125		3	NR	NR	NR	NR	3
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		29	208	259	98	2	0	596

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1 **J.C. PENNEY** **NY UST** **U003884533**
Target **100 MAIN ST** **N/A**
Property **WHITE PLAINS, NY 10601**

Site 1 of 24 in cluster A

Actual:
211 ft.

WESTCHESTER CO. UST:

Id/Status:	3-600104 / Unregulated: <1101 gal. PBS
Operator Name:	Keith Layman
Owner Name:	Jc Penney
Owner Street:	P.o. Box 659000
Owner Address2:	Not reported
Owner City:	Dallas
Owner State:	TX
Owner Zipcode:	75265-9000
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	8000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	08/25/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	3
Status:	5. Tank converted to Non-Regulated use
Capacity:	100
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	08/01/1996
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

J.C. PENNEY (Continued) **U003884533**

Tank Number:	4
Status:	5. Tank converted to Non-Regulated use
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1997
Date Perm Closure:	08/01/1996
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

A2 Target Property **EXPRESSLY PORTRAITS**
100 MAIN ST - GALLERIA MALL
WHITE PLAINS, NY 10603

RCRA NonGen / NLR **1000981336**
FINDS **NY0000969121**
ECHO
NY MANIFEST

Site 2 of 24 in cluster A

Actual: 211 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	EXPRESSLY PORTRAITS
Facility address:	100 MAIN ST - GALLERIA MALL SPACE 378 WHITE PLAINS, NY 10603
EPA ID:	NY0000969121
Mailing address:	TRITON DR - SUITE C FOSTER CITY, NY 94404
Contact:	ROGER BLAKE
Contact address:	TRITON DR - SUITE C FOSTER CITY, NY 94404
Contact country:	US
Contact telephone:	415-578-9291
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EXPRESSLY PORTRAITS CORP
Owner/operator address:	1151 TRITON DR - SUITE C FOSTER CITY, CA 94404
Owner/operator country:	US
Owner/operator telephone:	415-578-9291
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

EXPRESSLY PORTRAITS (Continued) **1000981336**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EXPRESSLY PORTRAITS CORP
Owner/operator address: 1151 TRITON DR - SUITE C
FOSTER CITY, CA 94404
Owner/operator country: US
Owner/operator telephone: 415-578-9291
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: EXPRESSLY PORTRAITS
Classification: Not a generator, verified

Date form received by agency: 12/08/1994
Site name: EXPRESSLY PORTRAITS
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Records/Reporting
Date violation determined: 08/26/1997
Date achieved compliance: 10/22/1997
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 08/26/1997
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

EXPRESSLY PORTRAITS (Continued) **1000981336**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/01/1997
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Records/Reporting
Date achieved compliance: 10/22/1997
Evaluation lead agency: State

FINDS:

Registry ID: 110004322849

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000981336
Registry ID: 110004322849
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004322849

NY MANIFEST:
Country: USA
EPA ID: NY0000969121
Facility Status: Not reported
Location Address 1: 100 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10603
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000969121
Mailing Name: EXPRESSLY PORTRAITS
Mailing Contact: FRANK GORHAM
Mailing Address 1: 100 MAIN ST
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10603
Mailing Zip 4: Not reported
Mailing Country: USA

EXPRESSLY PORTRAITS (Continued) **1000981336**

Mailing Phone: 0000000000

NY MANIFEST:

Document ID:	MAM3497030
Manifest Status:	Not reported
seq:	01
Year:	2000
Trans1 State ID:	NYDW9495
Trans2 State ID:	T422NXNJ
Generator Ship Date:	04/07/2000
Trans1 Recv Date:	04/07/2000
Trans2 Recv Date:	04/10/2000
TSD Site Recv Date:	04/12/2000
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000969121
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCR000074591
TSDF ID 1:	MAD982755639
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00500
Units:	P - Pounds
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A3 **MACYS WHITE PLAINS COGENERATION** **FINDS** **1016008457**
Target **100 MAIN ST** **ECHO** **N/A**
Property **WHITE PLAINS, NY 10601**

Site 3 of 24 in cluster A

Actual:
211 ft.

FINDS:

Registry ID: 110054890347

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016008457
Registry ID:	110054890347
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110054890347

A4 **MACY'S EAST #55** **NY MANIFEST** **S117564976**
Target **100 MAIN ST** **N/A**
Property **WHITE PLAINS, NY 10601**

Site 4 of 24 in cluster A

Actual:
211 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYR000120329
Facility Status:	Not reported
Location Address 1:	700 LEE BLVD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	YORKTOWN HEIGHTS
Location State:	NY
Location Zip:	10598
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000120329
Mailing Name:	MACY'S EAST #55

MACY'S EAST #55 (Continued) **S117564976**

Mailing Contact:	MAYBELLE VALENTIN
Mailing Address 1:	700 LEE BLVD
Mailing Address 2:	Not reported
Mailing City:	YORKTOWN HEIGHTS
Mailing State:	NY
Mailing Zip:	10598
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142433302

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD084814136
Trans2 State ID:	Not reported
Generator Ship Date:	06/18/2018
Trans1 Recv Date:	06/18/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/27/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000120329
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MID980991566
TSDF ID 2:	Not reported
Manifest Tracking Number:	018352509JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8025
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D005
Waste Code 1_3:	D035
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported

MACY'S EAST #55 (Continued) **S117564976**

Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY MANIFEST: record(s) in the EDR Site Report.

A5 **MACYS - WHITE PLAINS #30** **FINDS** **1007217088**
Target **100 MAIN ST** **ECHO** **N/A**
Property **WHITE PLAINS, NY 10601**

Site 5 of 24 in cluster A

Actual: **211 ft.**

FINDS:

Registry ID: 110016725748

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access
additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007217088
Registry ID: 110016725748
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110016725748

A6 **PICTURE PEOPLE THE** **RCRA-SQG** **1001961666**
Target **100 MAIN ST SPACE 329** **FINDS** **NYR000084806**
Property **WHITE PLAINS, NY 10603** **ECHO**
NY MANIFEST

Site 6 of 24 in cluster A

Actual: **211 ft.**

RCRA-SQG:

Date form received by agency: 01/01/2007
Facility name: PICTURE PEOPLE THE
Facility address: 100 MAIN ST SPACE 329
GALLERIA MALL
WHITE PLAINS, NY 10603
EPA ID: NYR000084806
Mailing address: MAIN ST SPACE 329
GALLERIA MALL
WHITE PLAINS, NY 10603
Contact: SANTA MITCHELL
Contact address: MAIN ST SPACE 329 GALLERIA MALL
WHITE PLAINS, NY 10603
Contact country: US
Contact telephone: 914-428-2811
Contact email: Not reported
EPA Region: 02

PICTURE PEOPLE THE (Continued) **1001961666**

Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name: THE PICTURE PEOPLE
Owner/operator address: 1157 TRITON DR STE B
FOSTER CITY, CA 94404
Owner/operator country: US
Owner/operator telephone: 800-998-3686
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: THE PICTURE PEOPLE
Owner/operator address: 1157 TRITON DR STE B
FOSTER CITY, CA 94404
Owner/operator country: Not reported
Owner/operator telephone: 800-998-3686
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: THE PICTURE PEOPLE
Owner/operator address: 1157 TRITON DR STE B
FOSTER CITY, CA 94404
Owner/operator country: US
Owner/operator telephone: 800-998-3686
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No

PICTURE PEOPLE THE (Continued) **1001961666**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PICTURE PEOPLE THE
Classification: Small Quantity Generator

Date form received by agency: 11/16/2000
Site name: PICTURE PEOPLE THE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 02/16/2000
Site name: PICTURE PEOPLE THE
Classification: Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - 372.2(b)(2)/(c)/373-3.3(g)
Area of violation: Generators - General
Date violation determined: 12/08/2000
Date achieved compliance: 07/11/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 06/21/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 372.2(b)(2)/(c)/373-3.3(g)
Area of violation: Generators - General
Date violation determined: 12/08/2000
Date achieved compliance: 07/11/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 04/10/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

PICTURE PEOPLE THE (Continued) **1001961666**

Evaluation Action Summary:
Evaluation date: 12/08/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 07/11/2001
Evaluation lead agency: State

FINDS:

Registry ID: 110004561402

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001961666
Registry ID: 110004561402
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004561402

NY MANIFEST:
Country: USA
EPA ID: NYR000084806
Facility Status: Not reported
Location Address 1: 100 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10603
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000084806
Mailing Name: PICTURE PLACE-389 GALLERIA MALL
Mailing Contact: VERNESSA VASQUEZ
Mailing Address 1: 100 MAIN ST
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10603
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9144282811

NY MANIFEST:
Document ID: Not reported

PICTURE PEOPLE THE (Continued) **1001961666**

Manifest Status:	Not reported
seq:	Not reported
Year:	2007
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	02/26/2007
Trans1 Recv Date:	02/26/2007
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2007
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000084806
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	MAD982755639
TSDF ID 2:	Not reported
Manifest Tracking Number:	000369677SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H010
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	690
Units:	P - Pounds
Number of Containers:	2
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D011
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A7 **NY COOLING TOWERS** **S121996073**
Target Property **100 E. MAIN ST** **N/A**
WHITE PLAINS, NY 10601

Site 7 of 24 in cluster A

Actual: 211 ft.

COOLING TOWERS:

Equipment Unique ID:	6530
Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	Marley
Model:	NC1211GM
Cooling Capacity:	180
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/07/2007
Inspection Date:	09/01/2015
Date of Bacteriological Collection:	08/27/2015
Date of Legionella Collection:	08/27/2015
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	41.032
Longitude:	-73.7718

A8 **MACYS - WHITE PLAINS #30** **RCRA-SQG** **1007112716**
Target Property **100 MAIN ST** **FINDS** **NYR000120329**
WHITE PLAINS, NY 10601 **ECHO**

Site 8 of 24 in cluster A

Actual: 211 ft.

RCRA-SQG:

Date form received by agency:	02/27/2007
Facility name:	MACYS - WHITE PLAINS #30
Facility address:	100 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYR000120329
Mailing address:	MAIN ST WHITE PLAINS, NY 10601
Contact:	ELIZABETH M KONKLE
Contact address:	RTE 18 SOUTH & RUES LANE MACYS EAST BRUNSWICK #088 EAST BRUNSWICK, NJ 08816
Contact country:	US
Contact telephone:	732-631-5593
Contact email:	ELIZABETH.KONKLE@MACYS.COM
EPA Region:	02
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MACYS EAST
Owner/operator address:	W 7TH ST CINCINNATI, OH 45202
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

MACYS - WHITE PLAINS #30 (Continued) **1007112716**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 02/01/2006
Owner/Op end date: Not reported

Owner/operator name: MACYS EAST
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 02/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Historical Generators:
Date form received by agency: 02/26/2007
Site name: MACYS - WHITE PLAINS #30
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/26/2007
Site name: MACYS - WHITE PLAINS #30
Classification: Small Quantity Generator

Date form received by agency: 11/17/2003
Site name: MACYS STORE #30

MACYS - WHITE PLAINS #30 (Continued) **1007112716**

Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 01/06/2011
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110009462553

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1007112716
Registry ID: 110009462553
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009462553

A9 **NY COOLING TOWERS** **S121996546**
Target Property **100 MAIN STREET** **N/A**
WHITE PLAINS, NY 10601

Site 9 of 24 in cluster A

Actual: 211 ft.

COOLING TOWERS:
Equipment Unique ID: 7028
Equipment Borough: Not reported
Intended Use: Air Conditioning
Manufacturer: MARLEY
Model: NC-8307K2bb
Cooling Capacity: 700
Cooling Capacity Unit: Tonnage
Commissioned Date: 08/05/2008
Inspection Date: 09/26/2018

(Continued) **S121996546**

Date of Bacteriological Collection:	09/26/2018
Date of Legionella Collection:	09/26/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	41.032
Longitude:	-73.7718

A10 **NY COOLING TOWERS** **S121996121**
Target Property **100 E. MAIN ST** **N/A**
WHITE PLAINS, NY 10601

Site 10 of 24 in cluster A

Actual: 211 ft.

COOLING TOWERS:

Equipment Unique ID:	6579
Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	Marley
Model:	7-Feb
Cooling Capacity:	468
Cooling Capacity Unit:	Tonnage
Commissioned Date:	05/07/2007
Inspection Date:	Not reported
Date of Bacteriological Collection:	Not reported
Date of Legionella Collection:	08/27/2015
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	41.032
Longitude:	-73.7718

A11 **GALLERIA OF WHITE PLAINS** **FINDS** **1007758249**
Target Property **100 MAIN STREET** **N/A**
WHITE PLAINS, NY 10601

Site 11 of 24 in cluster A

Actual: 211 ft.

FINDS:

Registry ID: 110019206599

Environmental Interest/Information System
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

A12 **NY COOLING TOWERS** **S121991640**
Target Property **100 MAIN STREET** **N/A**
WHITE PLAINS, NY 10601

Site 12 of 24 in cluster A

Actual: 211 ft.

COOLING TOWERS:

Equipment Unique ID:	1916
Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	Baltimore Air Coil
Model:	3935-2W
Cooling Capacity:	1860
Cooling Capacity Unit:	Tonnage
Commissioned Date:	03/25/1996
Inspection Date:	05/08/2018
Date of Bacteriological Collection:	07/12/2018
Date of Legionella Collection:	07/16/2018
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	41.032
Longitude:	-73.7718

A13 **J C PENNEY CO INC** **NY LTANKS** **1000912475**
Target Property **100 MAIN ST** **NY Spills** **NY0000806901**
WHITE PLAINS, NY 10601 **RCRA NonGen / NLR**
NY MANIFEST

Site 13 of 24 in cluster A

Actual: 211 ft.

LTANKS:

Spill Number/Closed Date:	9102767 / 1991-06-13
Facility ID:	9102767
Site ID:	137993
Spill Date:	1991-06-10
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-06-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-06-13
Spill Record Last Update:	1991-07-10
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	118002

J C PENNEY CO INC (Continued) **1000912475**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "CONTAINED ON SIDEWALK CASTLE OIL TO CLEAN UP"

All Materials:
Site ID: 137993
Operable Unit ID: 956636
Operable Unit: 01
Material ID: 425258
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0302779 / 2003-06-16
Facility ID: 0302779
Facility Type: ER
DER Facility ID: 118002
Site ID: 137992
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6017
Spill Date: 2003-06-16
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2003-06-16
CID: 204
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Police Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-06-16
Spill Record Last Update: 2003-06-18
Spiller Name: Not reported
Spiller Company: GALLERIA MALL
Spiller Address: 100 MAIN STREET
Spiller Company: 001
Contact Name: PATRICK MURPHY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks: "SUBJECT STUCK IN ELEVATOR - FIRE DEPARTMENT ON SCENE "

All Materials:
Site ID: 137992
Operable Unit ID: 870528
Operable Unit: 01

J C PENNEY CO INC (Continued) **1000912475**

Material ID:	507231
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9204133 / 1992-08-04
Facility ID:	9204133
Facility Type:	ER
DER Facility ID:	118002
Site ID:	137995
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1992-07-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-07-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1992-08-04
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-13
Spill Record Last Update:	1995-05-19
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"OIL DISCOVERED IN BASEMENT SUMP; SUMP PUMP WAS BROKEN AND TO BE REPAIRED WHEN OIL WAS DISCOVERED LUZON TO VAC SUMP PICK UP AND DISPOSE TODD GHIOSAY NOTIFIED"

All Materials:

Site ID:	137995
Operable Unit ID:	967942
Operable Unit:	01
Material ID:	411881
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G

J C PENNEY CO INC (Continued) **1000912475**

Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0703055 / 2007-06-14
Facility ID: 0703055
Facility Type: ER
DER Facility ID: 118002
Site ID: 382912
DEC Region: 3
Spill Cause: Human Error
Spill Class: C4
SWIS: 6017
Spill Date: 2007-06-13
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2007-06-14
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Health Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-06-14
Spill Record Last Update: 2007-06-14
Spiller Name: DENISE
Spiller Company: GALLERIA MALL
Spiller Address: 100 MAIN STREET
Spiller Company: 001
Contact Name: DENISE
DEC Memo: "7/14/07 WPPD reported that the WPFD recovered the gas. NFA TG"
Remarks: "a person dumped out his gas into storm drain when he could not return it: less then 1 gallon"

All Materials:
Site ID: 382912
Operable Unit ID: 1140291
Operable Unit: 01
Material ID: 2130355
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0211359 / 2005-02-27
Facility ID: 0211359
Facility Type: ER
DER Facility ID: 118002
Site ID: 104864

J C PENNEY CO INC (Continued) **1000912475**

DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2003-02-13
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-02-13
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-13
Spill Record Last Update:	2005-02-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	D.C. CIOCCA - WPFD
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 2/27/05 surface spill from vehicle--close "
Remarks:	"WHITE PLAINS FD ON SCENE AND THEY NEED A RESPONSE FROM DEC"

All Materials:

Site ID:	104864
Operable Unit ID:	864691
Operable Unit:	01
Material ID:	565743
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	J C PENNEY CO INC
Facility address:	100 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NY0000806901
Mailing address:	PO BOX 250 WAYNE, NY 07470
Contact:	Not reported
Contact address:	PO BOX 250 WAYNE, NY 07470
Contact country:	US
Contact telephone:	Not reported

J C PENNEY CO INC (Continued) **1000912475**

Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: J C PENNEY CO INC
Owner/operator address: PO BOX 1001
DALLAS, TX 75301
Owner/operator country: US
Owner/operator telephone: 214-591-1000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: J C PENNEY CO INC
Owner/operator address: PO BOX 1001
DALLAS, TX 75301
Owner/operator country: US
Owner/operator telephone: 214-591-1000
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: J C PENNEY CO INC
Classification: Not a generator, verified

Date form received by agency: 01/24/1995
Site name: J C PENNEY CO INC

J C PENNEY CO INC (Continued) **1000912475**

Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 09/20/1994
Site name: J C PENNEY CO INC
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NY0000806901
Facility Status: Not reported
Location Address 1: 100 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NY0000806901
Mailing Name: J C PENNEYS
Mailing Contact: ROY LANGBRIDGE
Mailing Address 1: P O BOX 250 RT 46
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2017851881

NY MANIFEST:
Document ID: NYB4480794
Manifest Status: K
seq: Not reported
Year: 1994
Trans1 State ID: TW56975PA
Trans2 State ID: Not reported
Generator Ship Date: 10/26/1994
Trans1 Recv Date: 10/26/1994
Trans2 Recv Date: / /
TSD Site Recv Date: 11/01/1994
Part A Recv Date: 11/30/1994

J C PENNEY CO INC (Continued) **1000912475**

Part B Recv Date:	11/18/1994
Generator EPA ID:	NY0000806901
Trans1 EPA ID:	PAD064035819
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00075
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A14 **C P I PHOTO FINISH** **RCRA NonGen / NLR** **1001125005**
Target **100 MAIN ST STE 301** **FINDS** **NYR000034082**
Property **WHITE PLAINS, NY 10601** **ECHO**

Site 14 of 24 in cluster A

Actual:
211 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	C P I PHOTO FINISH
Facility address:	100 MAIN ST STE 301 GALLERIA MALL WHITE PLAINS, NY 10601-2604

C P I PHOTO FINISH (Continued) **1001125005**

EPA ID: NYR000034082
Mailing address: WASHINGTON AVE
ST LOUIS, NY 63103
Contact: Not reported
Contact address: WASHINGTON AVE
ST LOUIS, NY 63103
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: FOX PHOTO INC
Owner/operator address: 1706 WASHINGTON AVE
ST LOUIS, MO 63103
Owner/operator country: US
Owner/operator telephone: 313-231-1575
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FOX PHOTO INC
Owner/operator address: 1706 WASHINGTON AVE
ST LOUIS, MO 63103
Owner/operator country: US
Owner/operator telephone: 313-231-1575
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

C P I PHOTO FINISH (Continued) **1001125005**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: C P I PHOTO FINISH
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: C P I PHOTO FINISH
Classification: Not a generator, verified

Date form received by agency: 01/08/1997
Site name: C P I PHOTO FINISH
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004531374

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001125005
Registry ID: 110004531374
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004531374

B15 **CON EDISON** **RCRA NonGen / NLR** **1019908455**
NW **WILLIAMS ST & MAIN ST** **NYP004846109**
< 1/8 **WHITE PLAINS, NY 10601**
0.006 mi.
34 ft. **Site 1 of 16 in cluster B**

Relative:
Lower

Actual:
199 ft.

RCRA NonGen / NLR:
Date form received by agency: 09/30/2015
Facility name: CON EDISON
Facility address: WILLIAMS ST & MAIN ST
WHITE PLAINS, NY 10601
EPA ID: NYP004846109
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING

CON EDISON (Continued) **1019908455**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/30/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

B16 **CON EDISON** **RCRA NonGen / NLR** **1014399082**
NW **WILLIAMS ST & MAIN ST** **NJ MANIFEST** **NYP004214599**
< 1/8 **WHITE PLAINS, NY 10601**
0.006 mi.
34 ft. **Site 2 of 16 in cluster B**

Relative:
Lower

Actual:
199 ft.

RCRA NonGen / NLR:
Date form received by agency: 08/31/2010
Facility name: CON EDISON
Facility address: WILLIAMS ST & MAIN ST
WHITE PLAINS, NY 10601
EPA ID: NYP004214599
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: DOMINIC BIZZARO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

CON EDISON (Continued) **1014399082**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
- EPA Id: NYP004846109
- Mail Address: IRVING PL 15TH FL NE
- Mail City/State/Zip: NEW YORK, NY 10003
- Facility Phone: Not reported
- Emergency Phone: Not reported
- Contact: THOMAS TEELING
- Comments: Not reported
- SIC Code: Not reported
- County: NY119
- Municipal: Not reported
- Previous EPA Id: Not reported
- Gen Flag: Not reported
- Trans Flag: Not reported
- TSDF Flag: Not reported
- Name Change: Not reported
- Date Change: Not reported

Manifest:
- Manifest Number: 014460337JJK
- EPA ID: NYP004846109
- Date Shipped: 9/30/2015
- TSDF EPA ID: NJD002200046
- Transporter EPA ID: NYD006982359
- Transporter 2 EPA ID: Not reported
- Transporter 3 EPA ID: Not reported
- Transporter 4 EPA ID: Not reported
- Transporter 5 EPA ID: Not reported
- Transporter 6 EPA ID: Not reported
- Transporter 7 EPA ID: Not reported
- Transporter 8 EPA ID: Not reported
- Transporter 9 EPA ID: Not reported
- Transporter 10 EPA ID: Not reported
- Date Trans1 Transported Waste: Not reported
- Date Trans2 Transported Waste: Not reported
- Date Trans3 Transported Waste: Not reported
- Date Trans4 Transported Waste: Not reported
- Date Trans5 Transported Waste: Not reported
- Date Trans6 Transported Waste: Not reported

CON EDISON (Continued) **1014399082**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

EPA Id:	NYP004214599
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001086109GBF
EPA ID:	NYP004214599
Date Shipped:	08/31/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/31/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

CON EDISON (Continued) **1014399082**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	09/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

B17 **CON EDISON MANHOLE: 10233** **RCRA NonGen / NLR** **1016960696**
NW **MAIN ST & WILLIAMS ST** **NY MANIFEST** **NYP004328050**
< 1/8 **WHITE PLAINS, NY 10607**
0.006 mi.
34 ft. **Site 3 of 16 in cluster B**

Relative: **Lower**
Actual: **199 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/11/2013
Facility name:	CON EDISON MANHOLE: 10233
Facility address:	MAIN ST & WILLIAMS ST WHITE PLAINS, NY 10607
EPA ID:	NYP004328050
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE: 10233 (Continued) **1016960696**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/11/2013
Site name: CON EDISON MANHOLE: 10233
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004328050
Facility Status: Not reported
Location Address 1: MAIN ST & WILLIAMS ST
Code: BP
Location Address 2: MH # 10233
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10607
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004328050
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CON EDISON MANHOLE: 10233 (Continued) **1016960696**

Generator Ship Date:	07/11/2013
Trans1 Recv Date:	07/11/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004328050
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695885JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B18 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823807**
NW **WILLIAM ST & MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.006 mi.
34 ft. **Site 4 of 16 in cluster B**

Relative: NY MANIFEST:
Lower

Country:	USA
EPA ID:	NYP004227389
Facility Status:	Not reported
Location Address 1:	WILLIAM ST & MAIN ST
Code:	BP

Actual:
199 ft.

CONSOLIDATED EDISON (Continued) **S110823807**

Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004227389
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/09/2011
Trans1 Recv Date: 02/09/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/10/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004227389
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007655507JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 400.0

CONSOLIDATED EDISON (Continued) **S110823807**

Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B19 **CON ED- TM462** **NY MANIFEST** **S109064656**
NW **WILLIAMS & MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.006 mi.
34 ft. **Site 5 of 16 in cluster B**

Relative:
Lower

Actual:
199 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYZ004019766
Facility Status:	Not reported
Location Address 1:	WILLIAMS & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	0000

NY MANIFEST:

EPAID:	NYZ004019766
Mailing Name:	CON ED- TM462
Mailing Contact:	Not reported
Mailing Address 1:	Not reported
Mailing Address 2:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	Not reported
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

B20
NW
< 1/8
0.006 mi.
34 ft.

CON EDISON
WILLIAMS ST & MAIN ST
WHITE PLAINS, NY 10601

Site 6 of 16 in cluster B

NY MANIFEST **S118463067**
N/A

Relative:
Lower

Actual:
199 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004846109
Facility Status:	Not reported
Location Address 1:	WILLIAMS ST & MAIN ST
Code:	BP
Location Address 2:	TM 5567
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004846109
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/30/2015
Trans1 Recv Date:	09/30/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004846109
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460337JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118463067**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A21 **LAST CALL NY INC/DBA - VINTAGE BAR** **NY UST** **U004176795**
North **171-173 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10543**
0.008 mi.
43 ft. **Site 15 of 24 in cluster A**

Relative: **Lower**
Actual: **205 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-800096 / Unregulated: <1101 gal. PBS
Operator Name:	Decklin Farrell
Owner Name:	The Singer Trust c/o George A Bowman Inc.
Owner Street:	36 West 44th Street
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10036
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/12/2006
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	99. Other
Piping Location:	1. Aboveground
Piping Type:	10. Copper

LAST CALL NY INC/DBA - VINTAGE BAR (Continued) **U004176795**

Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

A22 **VINTAGE RESTAURANT** **NY LTANKS** **S108059295**
North **171-173 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.008 mi.
43 ft. **Site 16 of 24 in cluster A**

Relative: LTANKS:
Lower

Actual:
205 ft.

Spill Number/Closed Date:	0602861 / 2008-09-26
Facility ID:	0602861
Site ID:	365437
Spill Date:	2006-06-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-06-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-14
Spill Record Last Update:	2008-09-26
Spiller Name:	FREDERICK SASSE
Spiller Company:	SINGER TRUST C/O GEORGE A BOWNMAN INC
Spiller Address:	36 W 44TH ST. SUIT 810
Spiller County:	001
Spiller Contact:	MIKE
Spiller Phone:	(516) 924-3824
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	315576
DEC Memo:	"6/14/06 Pro Test on site to test the 1500 gallon tank as ordered by the DEC. Tester couldn't get vacuum on the tank. Andre from ProTest said the cement on top of the tank needs to be removed to expose all of the bungs and piping. Once that is performed, then the tank can be isolated and tested. Visual observation revealed that the steel on the top of the tank was very heavily corroded. TG 06/29/06 AM - ProTest back on site retesting the lines and the tank. Andre reported that the vent line and the remote fill line both failed the test. The tank failed to hold a vacuum therefore, it also failed. Andre recommending unearthing the manway and checking that for a definitive answer on the tank failure. However this can't be accomplished until a refrigeration compressor is moved which will require a refrigeration mechanic. TG 06/29/06 John Leddy from ProTest officially reported that the tank failed and that the tank has lost

VINTAGE RESTAURANT (Continued) **S108059295**

two inches of oil since the 14th and the tank is not being used. Recommending emptying the tank to their client. TG 07/05/06 Joe Ostrosky from Petroleum Tank Cleaners (PTC) reported that PTC was hired to remove the oil from the tank. The tank has been emptied, cut open and cleaned. TG 11/15/06 New England Tank Services has completed the removal of the tank, allowing for an inspection. Substantial corrosion and numerous holes were observed. A letter was sent to the management company requiring the installation of two monitoring wells. 03/12/07 Monitoring well installation report submitted by JM Associates who were subcontracted by Fleet Environmental. No free product was detected in the wells. TG 07/30/07 New England Tank Services reported that they removed the tank along with 2.64 tons of petroleum contaminated soil. TG "

Remarks: ""

All TTF:

Facility ID:	0602861
Spill Number:	0602861
Spill Tank Test:	1550055
Site ID:	365437
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	365437
Operable Unit ID:	1123455
Operable Unit:	01
Material ID:	2112912
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0602861 / 2008-09-26
Facility ID:	0602861
Site ID:	365437
Spill Date:	2006-06-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported

VINTAGE RESTAURANT (Continued) **S108059295**

SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-06-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-14
Spill Record Last Update:	2008-09-26
Spiller Name:	JOHN HAMILTON
Spiller Company:	SINGER TRUSTEE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MIKE
Spiller Phone:	(516) 924-3824
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	315576
DEC Memo:	"6/14/06 Pro Test on site to test the 1500 gallon tank as ordered by the DEC. Tester couldn't get vacuum on the tank. Andre from ProTest said the cement on top of the tank needs to be removed to expose all of the bungs and piping. Once that is performed, then the tank can be isolated and tested. Visual observation revealed that the steel on the top of the tank was very heavily corroded. TG 06/29/06 AM - ProTest back on site retesting the lines and the tank. Andre reported that the vent line and the remote fill line both failed the test. The tank failed to hold a vacuum therefore, it also failed. Andre recommending unearthing the manway and checking that for a definitive answer on the tank failure. However this can't be accomplished until a refrigeration compressor is moved which will require a refrigeration mechanic. TG 06/29/06 John Leddy from ProTest officially reported that the tank failed and that the tank has lost two inches of oil since the 14th and the tank is not being used. Recommending emptying the tank to their client. TG 07/05/06 Joe Ostrosky from Petroleum Tank Cleaners (PTC) reported that PTC was hired to remove the oil from the tank. The tank has been emptied, cut open and cleaned. TG 11/15/06 New England Tank Services has completed the removal of the tank, allowing for an inspection. Substantial corrosion and numerous holes were observed. A letter was sent to the management company requiring the installation of two monitoring wells. 03/12/07 Monitoring well installation report submitted by JM Associates who were subcontracted by Fleet Environmental. No free product was detected in the wells. TG 07/30/07 New England Tank Services reported that they removed the tank along with 2.64 tons of petroleum contaminated soil. TG "
Remarks:	""

All TTF:

Facility ID:	0602861
Spill Number:	0602861
Spill Tank Test:	1550055
Site ID:	365437
Tank Number:	1

VINTAGE RESTAURANT (Continued) **S108059295**

Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	365437
Operable Unit ID:	1123455
Operable Unit:	01
Material ID:	2112912
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A23 **WYASSUP-LAUREL GLEN CORP.** **NY AST** **U004177669**
North **175 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.008 mi.
43 ft. **Site 17 of 24 in cluster A**

Relative: **Lower**

Actual: **206 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-032433
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Perez
Owner Name:	Wyassup-Laurel Glen Corp.
Owner Street:	855 Lexington Avenue
Owner Address2:	3rd Floor
Owner City/State/Zip:	New York, NY 10065
Tank Number:	002
Status:	1. In-Service
Date Installation:	03/01/2000
Capacity:	5000
Product Stored:	0003. #6 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	5. Synthetic Liner

WYASSUP-LAUREL GLEN CORP. (Continued) **U004177669**

Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

A24 **OFFICE BLDG** **NY Spills** **S104508595**
North **175 MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.008 mi.
43 ft. **Site 18 of 24 in cluster A**

Relative: **Lower**
Actual: **206 ft.**

SPILLS:

Spill Number/Closed Date:	9910497 / 1999-12-02
Facility ID:	9910497
Facility Type:	ER
DER Facility ID:	77041
Site ID:	83742
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-12-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-12-02
CID:	371
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-02
Spill Record Last Update:	2000-01-26
Spiller Name:	Not reported
Spiller Company:	CONSTRUCTION CREW
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/02/99 CALLED TELEPHONE NUMBER ON SHEET-NO JOHN VEGA. SITE INSPECTED BY T. GHIOSAY-NO SPILL. NFA"
Remarks:	"WORKS AGROSS THE STREET FROM THE BLDG, SAW PEOPLE WALKING AROUND BLDG AND THERE IS AN OIL-TYPE PRODUCT ALL OVER THE GROUND."

All Materials:

Site ID:	83742
Operable Unit ID:	1089187
Operable Unit:	01
Material ID:	295979
Material Code:	0066A

OFFICE BLDG (Continued) **S104508595**

Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A25 **DRAIN - COOKING GREASE** **NY Spills** **S118636741**
North **175 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.008 mi.
43 ft. **Site 19 of 24 in cluster A**

Relative: **Lower**

Actual: **206 ft.**

SPILLS:

Spill Number/Closed Date:	1511825 / 2016-04-11
Facility ID:	1511825
Facility Type:	ER
DER Facility ID:	478849
Site ID:	524609
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	6017
Spill Date:	2016-03-12
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2016-03-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-03-12
Spill Record Last Update:	2016-04-11
Spiller Name:	PAUL
Spiller Company:	SOFRITO
Spiller Address:	175 MAIN STREET
Spiller Company:	999
Contact Name:	PAUL
DEC Memo:	"3-12-16 Spoke with Paul. He says that he witnessed a deliberate dumping down the storm sewer of several oversize buckets. These buckets contained what appeared to be some sort of grease. Location is behind the Galleria Mall on William Street which is off of Main St. This is a municipal lot. He sent 2 pictures which will be decdoc'd. jm 3/22/16: Photos taken by the Caller were sent to DEC and entered into DecDocs. jod 4/11/16: Forwarded to County Health department. No other action taken. jod"
Remarks:	"business dumping what looks like grease down the drain looking for call back Has pictures"

All Materials:

DRAIN - COOKING GREASE (Continued) **S118636741**

Site ID:	524609
Operable Unit ID:	1273571
Operable Unit:	01
Material ID:	2278007
Material Code:	9999
Material Name:	other - grease
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A26 **CON EDISON SERVICE BOX: 464** **RCRA NonGen / NLR** **1016969593**
ENE **19 COURT ST** **NY MANIFEST** **NYP004432662**
< 1/8 **WHITE PLAINS, NY 10602**
0.010 mi.
53 ft. **Site 20 of 24 in cluster A**

Relative:
Higher

Actual:
211 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/03/2014
Facility name:	CON EDISON SERVICE BOX: 464
Facility address:	19 COURT ST WHITE PLAINS, NY 10602
EPA ID:	NYP004432662
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/03/2014

CON EDISON SERVICE BOX: 464 (Continued) **1016969593**

Site name: CON EDISON SERVICE BOX: 464
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004432662
Facility Status: Not reported
Location Address 1: S/O 19 COURT ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004432662
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/03/2014
Trans1 Recv Date: 02/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/04/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004432662
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692715JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

CON EDISON SERVICE BOX: 464 (Continued) **1016969593**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

A27 **CON EDISON SERVICE BOX: 464** **NJ MANIFEST** **S120666081**
ENE **19 COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.010 mi.
53 ft. **Site 21 of 24 in cluster A**

Relative:
Higher

Actual:
211 ft.

NJ MANIFEST:

EPA Id:	NYP004432662
Mail Address:	VING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015319726JJK
EPA ID:	NYP004432662
Date Shipped:	2/29/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON SERVICE BOX: 464 (Continued) **S120666081**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C28 **CON EDISON MANHOLE 5622** **RCRA NonGen / NLR** **1009218109**
NNE **COURT ST & MAIN ST** **NYP004137717**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
54 ft. **Site 1 of 21 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

RCRA NonGen / NLR:

Date form received by agency:	11/25/2005
Facility name:	CON EDISON MANHOLE 5622
Facility address:	COURT ST & MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYP004137717
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTONIO DELGADO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	718-204-4201
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE 5622 (Continued) **1009218109**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/24/2005
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 11/23/2005
Site name: CON EDISON
Classification: Unverified

Violation Status: No violations found

C29 **CON EDISON MANHOLE 10236** **RCRA NonGen / NLR** **1010327416**
NNE **MAIN ST & COURT ST** **NY MANIFEST** **NYP004146551**
< 1/8 **WHITE PLAINS, NY 10606**
0.010 mi.
54 ft. **Site 2 of 21 in cluster C**

Relative:
Lower

Actual:
208 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/11/2007
Facility name: CON EDISON MANHOLE 10236
Facility address: MAIN ST & COURT ST
WHITE PLAINS, NY 10606
EPA ID: NYP004146551
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: STEVEN MARTIS
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON MANHOLE 10236 (Continued) **1010327416**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2007
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	01/09/2007
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004146551
Facility Status:	Not reported
Location Address 1:	MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004146551
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NC
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C30 **CON EDISON MANHOLE: 5622** **RCRA NonGen / NLR** **1016969602**
NNE **MAIN ST & COURT ST** **NY MANIFEST** **NYP004432753**
< 1/8 **WHITE PLAINS, NY 10602**
0.010 mi.
54 ft. **Site 3 of 21 in cluster C**

Relative:
Lower

Actual:
208 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/03/2014
Facility name:	CON EDISON MANHOLE: 5622
Facility address:	MAIN ST & COURT ST WHITE PLAINS, NY 10602
EPA ID:	NYP004432753
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/03/2014
Site name:	CON EDISON MANHOLE: 5622
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004432753
Facility Status:	Not reported
Location Address 1:	COURT ST & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602

CON EDISON MANHOLE: 5622 (Continued) **1016969602**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004432753
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/03/2014
Trans1 Recv Date: 02/03/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/04/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004432753
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692714JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 300
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON MANHOLE: 5622 (Continued) **1016969602**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C31 **CON EDISON** **NY MANIFEST** **S118090838**
NNE **COURT ST & MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
54 ft. **Site 4 of 21 in cluster C**

Relative:
Lower

Actual:
208 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004784807
Facility Status:	Not reported
Location Address 1:	COURT ST & MAIN ST
Code:	BP
Location Address 2:	MH 5622
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004784807
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/20/2015
Trans1 Recv Date:	05/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004784807
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S118090838**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467522JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	835
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	B002
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C32 **ROADWAY** **NY Spills** **S109415778**
NNE **MAIN ST & COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
54 ft. **Site 5 of 21 in cluster C**

Relative: SPILLS:
Lower

Actual:
208 ft.

Spill Number/Closed Date:	0812871 / 2009-02-27
Facility ID:	0812871
Facility Type:	ER
DER Facility ID:	359765
Site ID:	410519
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6017
Spill Date:	2009-02-27
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2009-02-27

ROADWAY (Continued) **S109415778**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-02-27
Spill Record Last Update:	2009-04-04
Spiller Name:	SEAMUS ROCHE
Spiller Company:	LIBERT LINES TRANSIT BUS # 457
Spiller Address:	MAIN ST & COURT ST
Spiller Company:	999
Contact Name:	SEAMUS ROCHE
DEC Memo:	"SPILLER HIRED 3D ENV. FOR CLEANUP OF ROADWAY. CONFIRMED WITH 3D ENV. NFA DT"
Remarks:	"Caller states a tranmission failure caised oil to spill onto blacktop. Cleanup is ongoing."

All Materials:

Site ID:	410519
Operable Unit ID:	1167002
Operable Unit:	01
Material ID:	2158524
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C33 **CON EDISON** **RCRA NonGen / NLR** **1019903377**
NNE **COURT ST & MAIN ST** **NYP004784807**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
54 ft. **Site 6 of 21 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

RCRA NonGen / NLR:

Date form received by agency:	05/20/2015
Facility name:	CON EDISON
Facility address:	COURT ST & MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYP004784807
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02

CON EDISON (Continued) **1019903377**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/20/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

C34 **CON EDISON MANHOLE 10236** **RCRA NonGen / NLR** **1014918856**
NNE **COURT ST & MAIN ST** **NJ MANIFEST** **NYP004224754**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.010 mi.
54 ft. **Site 7 of 21 in cluster C**

Relative: Lower
Actual: 208 ft.

RCRA NonGen / NLR:
Date form received by agency: 02/18/2011
Facility name: CON EDISON MANHOLE 10236
Facility address: COURT ST & MAIN ST
WHITE PLAINS, NY 10601
EPA ID: NYP004224754
Mailing address: IRVING PL RM 828
NEW YORK, NY 10003
Contact: DOMINIC BIZZARO
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No

CON EDISON MANHOLE 10236 (Continued) **1014918856**

Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/19/2011
Site name: CON EDISON MANHOLE 10236
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004224754
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DOMINIC BIZZARO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655841JJK
EPA ID: NYP004224754
Date Shipped: 1/19/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported

CON EDISON MANHOLE 10236 (Continued) **1014918856**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004224754
Facility Status:	Not reported
Location Address 1:	COURT ST
Code:	BP
Location Address 2:	MAIN ST
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224754
Mailing Name:	CONED - MH10236
Mailing Contact:	CONED - MH10236
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported

CON EDISON MANHOLE 10236 (Continued) **1014918856**

Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/19/2011
Trans1 Recv Date:	01/19/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/20/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224754
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655841JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C35 **CON EDISON** **RCRA NonGen / NLR** **1010327472**
NNE **MAIN ST & COURT ST** **NY MANIFEST** **NYP004146833**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
54 ft. **Site 8 of 21 in cluster C**

Relative:
Lower

Actual:
208 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/11/2007
Facility name:	CON EDISON
Facility address:	MAIN ST & COURT ST WHITE PLAINS, NY 10601
EPA ID:	NYP004146833
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	ANTONIO DELGADO
Contact address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact country:	US
Contact telephone:	718-204-4201
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/10/2007
Site name:	CON EDISON
Classification:	Not a generator, verified

Date form received by agency:	01/09/2007
Site name:	CON EDISON
Classification:	Unverified

Violation Status: No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004146833
Facility Status:	Not reported
Location Address 1:	MAIN STREET & COURT STREET
Code:	BP
Location Address 2:	Not reported

CON EDISON (Continued) **1010327472**

Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004146833
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C36 **CON EDISON MANHOLE: 10235** **RCRA NonGen / NLR** **1016960682**
NNE **MAIN ST & COURT ST** **NY MANIFEST** **NYP004327854**
< 1/8 **WHITE PLAINS, NY 10610**
0.010 mi.
54 ft. **Site 9 of 21 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/11/2013
Facility name:	CON EDISON MANHOLE: 10235
Facility address:	MAIN ST & COURT ST WHITE PLAINS, NY 10610
EPA ID:	NYP004327854
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON MANHOLE: 10235 (Continued) **1016960682**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/11/2013
Site name: CON EDISON MANHOLE: 10235
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004327854
Facility Status: Not reported
Location Address 1: MAIN ST & COURT ST
Code: BP
Location Address 2: MH #10235
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004327854
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/11/2013
Trans1 Recv Date: 07/11/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/17/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004327854
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported

CON EDISON MANHOLE: 10235 (Continued) **1016960682**

Manifest Tracking Number:	011695970JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C37 **CON EDISON** **NJ MANIFEST** **S120671973**
NNE **COURT ST & MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
54 ft. **Site 10 of 21 in cluster C**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYP004784807
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Actual:
208 ft.

CON EDISON (Continued) **S120671973**

Manifest:

Manifest Number:	014467522JJK
EPA ID:	NYP004784807
Date Shipped:	5/20/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

C38 **CON EDISON SERVICE BOX: 12498** **RCRA NonGen / NLR** **1016971319**
NNE **MAIN ST & COURT ST** **NY MANIFEST** **NYP004450573**
< 1/8 **WHITE PLAINS, NY 10607**
0.010 mi.
54 ft. **Site 11 of 21 in cluster C**

Relative:
Lower

Actual:
208 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/24/2014
Facility name:	CON EDISON SERVICE BOX: 12498
Facility address:	MAIN ST & COURT ST WHITE PLAINS, NY 10607
EPA ID:	NYP004450573
Mailing address:	IRVING PL, 15TH FL NE

CON EDISON SERVICE BOX: 12498 (Continued) **1016971319**

NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/24/2014
Site name: CON EDISON SERVICE BOX: 12498
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004450573
Facility Status: Not reported
Location Address 1: MAIN ST & LOVET ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004450573
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003

CON EDISON SERVICE BOX: 12498 (Continued) **1016971319**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/24/2014
Trans1 Recv Date:	02/24/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004450573
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772727JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C39
NNE
< 1/8
0.010 mi.
54 ft.

CON EDISON
COURT ST & MAIN ST
WHITE PLAINS, NY 10701

Site 12 of 21 in cluster C

NY MANIFEST **S116042143**
N/A

Relative:
Lower

Actual:
208 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004384657
Facility Status:	Not reported
Location Address 1:	COURT ST & MAIN ST
Code:	BP
Location Address 2:	TM3256
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10701
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004384657
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2013
Trans1 Recv Date:	11/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/06/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004384657
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695080JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116042143**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C40 **CON EDISON** **RCRA NonGen / NLR** **1016962067**
NNE **COURT ST & MAIN ST** **FINDS** **NYP004350450**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.010 mi.
54 ft. **Site 13 of 21 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

RCRA NonGen / NLR:

Date form received by agency:	09/23/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 3256
Facility address:	COURT ST & MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYP004350450
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON (Continued) **1016962067**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 08/23/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 3256
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069657829

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016962067
Registry ID: 110069657829
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069657829

A41 **I/F/O THE MELTING POT** **NY Spills** **S110307755**
East **35 COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
54 ft. **Site 22 of 24 in cluster A**

Relative:
Higher

Actual:
215 ft.

SPILLS:
Spill Number/Closed Date: 1000201 / 2010-04-06
Facility ID: 1000201
Facility Type: ER
DER Facility ID: 380329
Site ID: 431359
DEC Region: 3
Spill Cause: Deliberate
Spill Class: E5
SWIS: 6017
Spill Date: 2010-04-06
Investigator: kabrowne
Referred To: Not reported

I/F/O THE MELTING POT (Continued) **S110307755**

Reported to Dept:	2010-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-04-06
Spill Record Last Update:	2010-04-06
Spiller Name:	DENIS HEINZGER
Spiller Company:	THE MELTING POT
Spiller Address:	35 COURT ST
Spiller Company:	999
Contact Name:	DENIS HEINZGER
DEC Memo:	"4/6/10 - A juvenile caused the spil. Nonpetroleum spill. Spill being overseen by Westchester County DOH. No spill. NFA. KAB"
Remarks:	"DUE TO CONTAINERS FALLING OVER ON THE CURB ABOUT 50 GALLONS SPILLED TO THE STREET AND A STORM DRAIN. CLEAN UP PENDING."

All Materials:

Site ID:	431359
Operable Unit ID:	1182813
Operable Unit:	01
Material ID:	2177016
Material Code:	0046A
Material Name:	cooking grease
Case No.:	Not reported
Material FA:	Other
Quantity:	50.00
Units:	G
Recovered:	50.00
Oxygenate:	Not reported

A42 **MINSKOFF MANAGEMENT** **NY Spills** **S102151723**
East **39-47 COURT STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
55 ft. **Site 23 of 24 in cluster A**

Relative:
Higher

Actual:
216 ft.

SPILLS:

Spill Number/Closed Date:	9110040 / 1992-03-10
Facility ID:	9110040
Facility Type:	ER
DER Facility ID:	196905
Site ID:	239414
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1991-12-20
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-12-20

MINSKOFF MANAGEMENT (Continued) **S102151723**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	1992-01-08
Cleanup Meets Std:	True
Last Inspection:	1992-01-08
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-07
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"APPRX. 1 OF PRODUCT IN BASEMENT CONCRETE FLOOR FIRE DEPT. RESPONDED TO COMPLAINT OF ODORS CARLOS WCHD WILL TRY TO GET SOMEONE FROM WCHD TO INSPECT APPEARS TO BE VERY LARGE OVERFILL"

All Materials:

Site ID:	239414
Operable Unit ID:	960055
Operable Unit:	01
Material ID:	418614
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

A43 **COURT & MARTINE 2009 LLC** **NY AST** **A100412049**
East **39-55 COURT ST / 167-183 MARTINE AVE.** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 24 of 24 in cluster A**

Relative:
Higher

Actual:
216 ft.

WESTCHESTER CO. AST:

PBS Number:	3-177903
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Kevin Calcagni
Owner Name:	Court & Martine 2009 LLC
Owner Street:	39-55 Court St / 167-183 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	003
Status:	1. In-Service
Date Installation:	03/01/1991
Capacity:	2000

COURT & MARTINE 2009 LLC (Continued) **A100412049**

Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	06/01/1994
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

D44 **MICHAEL E LAND OFFICE BLD** **NY LTANKS S102151229**
SSE **148 MARTINE AVE** **NY Spills N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
55 ft. **Site 1 of 26 in cluster D**

Relative: **Higher**
Actual: **221 ft.**

LTANKS:

Spill Number/Closed Date:	0301426 / 2003-05-08
Facility ID:	0301426
Site ID:	214706
Spill Date:	2003-05-08
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	VPMCCABE
Referred To:	Not reported
Reported to Dept:	2003-05-08
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-08
Spill Record Last Update:	2003-05-12
Spiller Name:	CALLER
Spiller Company:	KENN ORICCHIO
Spiller Address:	500 KINGSLAND
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 995-3905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	153551
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MCCABE "

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Remarks: "DRIVER OVERFILLED TANK. ALL CLEANED UP"

All Materials:
Site ID: 214706
Operable Unit ID: 867817
Operable Unit: 01
Material ID: 505918
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: 5.00
Oxygenate: Not reported

Spill Number/Closed Date: 0503295 / 2005-09-26
Facility ID: 0503295
Site ID: 347878
Spill Date: 2005-06-17
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: JBODee
Referred To: WCDOH
Reported to Dept: 2005-06-17
CID: 407
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-06-17
Spill Record Last Update: 2005-09-26
Spiller Name: LOU MASTRO
Spiller Company: MICHAEL E LAND OFFICE BLD
Spiller Address: 148 MARTINE AVE
Spiller County: 001
Spiller Contact: LOU MASTRO
Spiller Phone: (845) 565-9600
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 153551
DEC Memo: "09/26/05: Letter to J. Varmon, County of Westchester DPW, from C. Lalak, WCDOH, dated 13Sep2005. Spill closure report, reporting requirement and as-built plans received. Department still needs a copy of the passing tightness test. Submit results asap. No further remdiation required regarding this spill number."
Remarks: "Located on the court st side of the building."

All Materials:
Site ID: 347878
Operable Unit ID: 1105557

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Operable Unit:	01
Material ID:	1521369
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0109874 / 2002-01-14
Facility ID:	0109874
Site ID:	126439
Spill Date:	2002-01-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6018
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-01-12
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-01-12
Spill Record Last Update:	2003-09-02
Spiller Name:	SAME
Spiller Company:	WESTCHESTER CO DPW
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	MIKE CIRCOSTA
Spiller Phone:	(914) 995-3905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	304255
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"LINE TEST FAILURE AT ABOVE LOCATION. SOME MATERIAL DID LEAK AND WAS RECOVERED IN CONTAINMENT AREA. LINE TO BE REPLACED."

All TTF:

Facility ID:	0109874
Spill Number:	0109874
Spill Tank Test:	1526811
Site ID:	126439
Tank Number:	5
Tank Size:	3000
Material:	0009
EPA UST:	Not reported
UST:	Not reported

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.10
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	126439
Operable Unit ID:	848218
Operable Unit:	01
Material ID:	552679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9202919 / 1992-07-13
Facility ID:	9202919
Facility Type:	ER
DER Facility ID:	153551
Site ID:	183296
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6017
Spill Date:	1992-06-10
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1992-06-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-07-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-11
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	IS. TRANSPORTATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Remarks: "SPILL CONTAINED ON PAVEMENT MOST EVAPORATED SPEEDI-DRI WAS APPLIED AND F.D. WASHED AREA MARINE POLLUTION CONTROL ON WAY TO VAC OUT STORM DRAIN VICKI WCHD ON SCENE"

All Materials:

Site ID:	183296
Operable Unit ID:	970249
Operable Unit:	01
Material ID:	554262
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	23.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9103040 / 1991-06-18
Facility ID:	9103040
Facility Type:	ER
DER Facility ID:	304255
Site ID:	126441
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	D3
SWIS:	6018
Spill Date:	1991-06-12
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-06-18
Spill Record Last Update:	2003-09-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FOUND CONTAMINATION WHILE REMOVING TANKS ARBEN CORP. IS PULLING THE TANKS STOCKPILE OF SOIL IS NOT TO DEC REQUIREMENTS LAURI TAYLOR INSTRUCTED THEM TO STOCKPILE ON PLASTIC SOIL STOCKPILE TO BE REMOVED"

All TTF:

Facility ID:	9103040
Spill Number:	9103040

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Spill Tank Test:	1538674
Site ID:	126441
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	126441
Operable Unit ID:	957062
Operable Unit:	01
Material ID:	425507
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0412020 / 2008-12-18
Facility ID:	0412020
Facility Type:	ER
DER Facility ID:	153551
Site ID:	337374
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-02-10
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2005-02-10
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-10
Spill Record Last Update:	2008-12-18
Spiller Name:	UNKNOWN

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Spiller Company:	MODEL PERTROLEUM
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	EDDIE
DEC Memo:	"2/17/05: Letter to John Varmon, Westchester DPW from Karen Magnuson, WCDOH dated 11Feb2005. Details work required. First report due 15Mar2005. 2/17/05: Letter to Al Cirino, Model Transportation, Inc from Karen Magnuson, WCDOH dated 11Feb2005. Tanks must be tightness tested by 18Feb2005. Details work required. First report due 15Mar2005."
Remarks:	"CLEAN UP IS IN PROCESS AND MANAGEMENT ON THE WAY TO LOOK AT LOCATION. LOCATED IN A PAVED PARKING LOT."

All Materials:

Site ID:	337374
Operable Unit ID:	1099339
Operable Unit:	01
Material ID:	579677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D45 **WESTCHESTER COUNTY OFFICE BUILDING** **NY AST** **A100276662**
SSE **148 MARTINE AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 2 of 26 in cluster D**

Relative: **Higher**
Actual: **221 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-168777
Site Status:	Active
GDS Number:	3550000034
Operator Name:	Westchester County DPW Operations
Owner Name:	Westchester County DPW
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	001
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	room acts as secondary containment
Piping Location:	1. Aboveground

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **A100276662**

Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	010
Status:	1. In-Service
Date Installation:	03/01/2005
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only),10. Impervious Underlayment (AST Only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	10
Status:	1. In-Service
Date Installation:	07/01/2001
Capacity:	300
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	99. Other
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	11
Status:	1. In-Service

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **A100276662**

Date Installation:	07/01/2008
Capacity:	336
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,LOCATION: 85 COURT ST
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	GENERATOR BELLY TANK
Piping Location:	0. No Piping
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	Not reported

D46 **CON EDISON** **NJ MANIFEST** **S120672054**
SSE **148 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 3 of 26 in cluster D**

Relative:
Higher

Actual:
221 ft.

NJ MANIFEST:

EPA Id:	NYP004785739
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454293JJK
EPA ID:	NYP004785739
Date Shipped:	5/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON (Continued) **S120672054**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D47 **WESTCHESTER COUNTY OFFICE BUILDING** **NY UST** **U003994465**
SSE **148 MARTINE AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 4 of 26 in cluster D**

Relative:
Higher

Actual:
221 ft.

WESTCHESTER CO. UST:

Id/Status:	3-168777 / Active
Operator Name:	Westchester County DPW Operations
Owner Name:	Westchester County DPW
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	3550000034
Tank Number:	008
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	9999. Other
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1972
Date Perm Closure:	12/10/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	Not reported
Tank Internal Protection:	1. Epoxy liner

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **U003994465**

Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	009
Status:	0. Administratively closed
Capacity:	30000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	10/01/2003
Date Perm Closure:	11/01/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	Not reported
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1998
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	8. Equivalent Technology
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	0. Administratively closed

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **U003994465**

Capacity:	5000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1998
Date Perm Closure:	11/01/2004
Tank Location:	Not reported
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	4
Status:	0. Administratively closed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1998
Date Perm Closure:	11/01/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	99. Other
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5
Status:	1. In-Service
Capacity:	3000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	04/01/1991
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	99. Other

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **U003994465**

Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	6
Status:	1. In-Service
Capacity:	3000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	04/01/1991
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	99. Other
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	7
Status:	0. Administratively closed
Capacity:	6000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	09/01/1993
Date Perm Closure:	05/12/2005
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	Not reported
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

D48 **CON EDISON** **RCRA NonGen / NLR** **1019903452**
SSE **148 MARTINE AVE** **FINDS** **NYP004785739**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.010 mi.
55 ft. **Site 5 of 26 in cluster D**

Relative:
Higher

Actual:
221 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/22/2015
Facility name:	CON EDISON
Facility address:	148 MARTINE AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004785739
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/22/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069663126

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019903452**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019903452
Registry ID: 110069663126
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069663126

D49 **WESTCHESTER COUNTY OFFICE BLDG** **RCRA-CESQG** **1000396564**
SSE **148 MARTINE AVE** **NY MANIFEST** **NYD072705213**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 6 of 26 in cluster D**

Relative: Higher
Actual: 221 ft.

RCRA-CESQG:
Date form received by agency: 01/01/2007
Facility name: WESTCHESTER COUNTY OFFICE BLDG
Facility address: 148 MARTINE AVE
WHITE PLAINS, NY 10601
EPA ID: NYD072705213
Mailing address: MARTINE AVE
WHITE PLAINS, NY 10601
Contact: Not reported
Contact address: MARTINE AVE
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Facility is not located on Indian land. Additional information is not known.
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: WESTCHESTER COUNTY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private

WESTCHESTER COUNTY OFFICE BLDG (Continued) **1000396564**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: WESTCHESTER COUNTY
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WESTCHESTER COUNTY OFFICE BLDG
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WESTCHESTER COUNTY OFFICE BLDG
Classification: Not a generator, verified

Date form received by agency: 03/14/1989
Site name: WESTCHESTER COUNTY OFFICE BLDG
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

WESTCHESTER COUNTY OFFICE BLDG (Continued) **1000396564**

Facility Has Received Notices of Violations:
- Regulation violated: Not reported
- Area of violation: Generators - General
- Date violation determined: 03/31/1989
- Date achieved compliance: 10/18/1990
- Violation lead agency: State
  - Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
  - Enforcement action date: 10/18/1990
  - Enf. disposition status: Not reported
  - Enf. disp. status date: Not reported
  - Enforcement lead agency: State
  - Proposed penalty amount: Not reported
  - Final penalty amount: 25000
  - Paid penalty amount: 25000

Evaluation Action Summary:
- Evaluation date: 08/09/1999
- Evaluation: NON-FINANCIAL RECORD REVIEW
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA

- Evaluation date: 08/05/1999
- Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
- Area of violation: Not reported
- Date achieved compliance: Not reported
- Evaluation lead agency: EPA

- Evaluation date: 03/31/1989
- Evaluation: FOCUSED COMPLIANCE INSPECTION
- Area of violation: Generators - General
- Date achieved compliance: 10/18/1990
- Evaluation lead agency: State

NY MANIFEST:
- Country: USA
- EPA ID: NYD072705213
- Facility Status: Not reported
- Location Address 1: 148 MARTINE AVE
- Code: BP
- Location Address 2: Not reported
- Total Tanks: Not reported
- Location City: WHITE PLAINS
- Location State: NY
- Location Zip: 10601
- Location Zip 4: Not reported

NY MANIFEST:
- EPAID: NYD072705213
- Mailing Name: WESTCHESTER CITY OFFICE BLDG
- Mailing Contact: WESTCHESTER CITY OFFICE BLDG
- Mailing Address 1: 19 BRODHURST AVE
- Mailing Address 2: Not reported
- Mailing City: HAWTHORNE
- Mailing State: NY
- Mailing Zip: 10532
- Mailing Zip 4: Not reported

WESTCHESTER COUNTY OFFICE BLDG (Continued) **1000396564**

Mailing Country:	USA
Mailing Phone:	9145932305

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJR000003749
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/2010
Trans1 Recv Date:	03/08/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/08/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD072705213
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD991291105
TSDF ID 2:	Not reported
Manifest Tracking Number:	005972801JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D50 **CON ED** **NY MANIFEST** **S118090928**
SSE **148 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
55 ft. **Site 7 of 26 in cluster D**

Relative:
Higher

Actual:
221 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004785739
Facility Status:	Not reported
Location Address 1:	148 MARTINE AVE
Code:	BP
Location Address 2:	MH 5823
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004785739
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/22/2015
Trans1 Recv Date:	05/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004785739
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454293JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON ED (Continued) **S118090928**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D51 **DPW VEHICLE** **NY Spills** **S113915643**
SE **COURT ST AND MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.013 mi.
67 ft. **Site 8 of 26 in cluster D**

Relative: **Higher**
Actual: **220 ft.**

SPILLS:

Spill Number/Closed Date:	1305831 / 2013-10-07
Facility ID:	1305831
Facility Type:	ER
DER Facility ID:	441527
Site ID:	486412
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2013-09-03
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2013-09-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2013-09-03
Spill Record Last Update:	2013-10-07

DPW VEHICLE (Continued) **S113915643**

Spiller Name:	BILL MCMAHON
Spiller Company:	WHITE PLAINS DPW
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BILL MCMAHON
DEC Memo:	"9-3-13: J.O'Dee call to V.Mc./Dspt.: John in contact with BILL MCMAHON/DPW. DPW responding and may be hairing Tri.St. J.O'Dee handling. 9/04/13: Bill McMahon from DPW called me directly when the spill occured yesterday. At first he stated fluid had entered a catch basin and they were calling Tri-State. He also stated that there was a multi-vehicle traffic accident as a result of this spill, a car reportedly slid through a traffic light. Bill called back later and stated that no material had entered the catch basin and DPW was completing the clean up themselves. I called back this morning and left a message asking him for an update. jod 10/07/13: Tri-State was contacted but never hired to perform any work. White Plains DPW reports the clean up was completed and no drains were impacted. No disposal documentation was provided. jod"
Remarks:	"spill to roadway and catch basin/clean up underway"

All Materials:

Site ID:	486412
Operable Unit ID:	1236058
Operable Unit:	01
Material ID:	2235359
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

D52 **CON EDISON** **NY MANIFEST** **S119075420**
SE **COURT ST & MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.013 mi.
67 ft. **Site 9 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004784880
Facility Status:	Not reported
Location Address 1:	E SIDE COURT ST & MARTINE
Code:	BP
Location Address 2:	MH 12496
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004784880
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL

CON EDISON (Continued) **S119075420**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/20/2015
Trans1 Recv Date:	05/20/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004784880
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014467523JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1834
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **S119075420**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D53 **CON EDISON MANHOLE 932** **RCRA NonGen / NLR** **1014918798**
SE **MARTINE AVE & COURT ST** **NJ MANIFEST** **NYP004224176**
< 1/8 **WHITE PLAINS, NY 10605** **NY MANIFEST**
0.013 mi.
67 ft. **Site 10 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/15/2011
Facility name:	CON EDISON MANHOLE 932
Facility address:	MARTINE AVE & COURT ST WHITE PLAINS, NY 10605
EPA ID:	NYP004224176
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/16/2011
Site name:	CON EDISON MANHOLE 932
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004224176
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

CON EDISON MANHOLE 932 (Continued) **1014918798**

Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655566JJK
EPA ID:	NYP004224176
Date Shipped:	1/16/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111

CON EDISON MANHOLE 932 (Continued) **1014918798**

Quantity: 100.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004224176
Facility Status:	Not reported
Location Address 1:	MAINTIME & COURT ST
Code:	BP
Location Address 2:	MH 9132
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224176
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/16/2011
Trans1 Recv Date:	01/16/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/18/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224176
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655566JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N

CON EDISON MANHOLE 932 (Continued) **1014918798**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D54 **CON EDISON** **RCRA NonGen / NLR** **1019903384**
SE **COURT ST & MARTINE AVE** **FINDS** **NYP004784880**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.013 mi.
67 ft. **Site 11 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

RCRA NonGen / NLR:

Date form received by agency:	05/20/2015
Facility name:	CON EDISON
Facility address:	COURT ST & MARTINE AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004784880
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No

CON EDISON (Continued) **1019903384**

Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	05/20/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110069657892

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019903384
Registry ID:	110069657892
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069657892

D55 **CON EDISON** **NJ MANIFEST** **S120671981**
SE **COURT ST & MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.013 mi.
67 ft. **Site 12 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

NJ MANIFEST:

EPA Id:	NYP004784880
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported

CON EDISON (Continued) **S120671981**

Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014467523JJK
EPA ID:	NYP004784880
Date Shipped:	5/20/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

D56
SE
< 1/8
0.013 mi.
67 ft.

CON EDISON
MARTINE AVE & COURT ST
WHITE PLAINS, NY 10801

Site 13 of 26 in cluster D

NY MANIFEST **S117738399**
N/A

Relative:
Higher

Actual:
220 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004714374
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & COURT ST
Code:	BP
Location Address 2:	MH7098
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004714374
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/13/2015
Trans1 Recv Date:	01/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004714374
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774706JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117738399**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D57 **CON EDISON** **NY MANIFEST** **S117738397**
SE **MARTINE AVE & COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10801**
0.013 mi.
67 ft. **Site 14 of 26 in cluster D**

Relative: **Higher**

Actual: **220 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004714358
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & COURT ST
Code:	BP
Location Address 2:	VS4250
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004714358
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

CON EDISON (Continued) **S117738397**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/13/2015
Trans1 Recv Date:	01/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004714358
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012774710JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D58 **THE MICHICALLIAN OFFICE** **NY LTANKS** **S100782193**
SE **MARTINE AVE & COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.013 mi.
67 ft. **Site 15 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Spill Number/Closed Date:	9310783 / 1993-11-18
Facility ID:	9310783
Site ID:	276042
Spill Date:	1993-11-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1993-11-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-03
Spill Record Last Update:	1997-07-29
Spiller Name:	Not reported
Spiller Company:	W.C. DPW
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	224426
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/16/93 DEC ON SITE TO DETERMINE CONTAMINATION; 11/18/93 REMOVAL OF 77.98 TONS OF SOIL; "
Remarks:	"DISCOVERED OIL IN TANK PULL FAXED TO TODD GHIOSAY"

All Materials:

Site ID:	276042
Operable Unit ID:	989528
Operable Unit:	01
Material ID:	389858
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

D59 **CON EDISON** **NY MANIFEST** **S118463400**
SE **MARTINE & COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.013 mi.
67 ft. **Site 16 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004850869
Facility Status:	Not reported
Location Address 1:	MARTINE & COURT ST
Code:	BP
Location Address 2:	TM 5706
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004850869
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/09/2015
Trans1 Recv Date:	10/09/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004850869
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245137JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118463400**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D60 **CON EDISON TRANSFORMER MANHOLE: 5706** **RCRA NonGen / NLR** **1016960251**
SE **MARTINE AVE & COURT** **NY MANIFEST** **NYP004321162**
< 1/8 **WHITE PLAINS, NY 10601**
0.013 mi.
67 ft. **Site 17 of 26 in cluster D**

Relative: **Higher**

Actual: **220 ft.**

RCRA NonGen / NLR:

Date form received by agency:	07/17/2013
Facility name:	CON EDISON TRANSFORMER MANHOLE: 5706
Facility address:	MARTINE AVE & COURT WHITE PLAINS, NY 10601
EPA ID:	NYP004321162
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON TRANSFORMER MANHOLE: 5706 (Continued) **1016960251**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/17/2013
Site name: CON EDISON TRANSFORMER MANHOLE: 5706
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004321162
Facility Status: Not reported
Location Address 1: MARTINE AVE & SO COURT ST
Code: BP
Location Address 2: MH 2706
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004321162
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: NYD006982359
Generator Ship Date: 06/17/2013
Trans1 Recv Date: 06/17/2013
Trans2 Recv Date: 06/18/2013
TSD Site Recv Date: 06/18/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004321162

CON EDISON TRANSFORMER MANHOLE: 5706 (Continued) **1016960251**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693084JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

D61 **INTERSECTION OF COURT ST.** **NY LTANKS** **S102674960**
SE **COURT ST. & MARITINE AVE.** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.013 mi.
67 ft. **Site 18 of 26 in cluster D**

Relative: LTANKS:
Higher

Actual: Spill Number/Closed Date:	8905963 / 1989-11-29
220 ft. Facility ID:	8905963
Site ID:	187446
Spill Date:	1989-09-18
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1989-11-29
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-18

INTERSECTION OF COURT ST. (Continued) **S102674960**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	1989-11-29
Spiller Name:	Not reported
Spiller Company:	RAD OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	156611
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"TANK TRUCK WAS OVERFILLED. WHITE PLAINS P.D. & F.D. ON SCENE."

All Materials:

Site ID:	187446
Operable Unit ID:	931170
Operable Unit:	01
Material ID:	446358
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D62 **RAILROAD ONE LF** **NY SWF/LF** **S106615651**
SE **148 MARTINE AVENUE** **NY Financial Assurance** **N/A**
< 1/8 **CROTON-ON-HUDSON, NY unkno**
0.013 mi.
69 ft. **Site 19 of 26 in cluster D**

Relative:
Higher

Actual:
220 ft.

SWF/LF:

Flag:	INACTIVE
Region Code:	3
Phone Number:	Not reported
Owner Name:	WESTCHESTER COUNTY DPW
Owner Type:	County
Owner Address:	148 MARTINE AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10601
Owner Email:	Not reported
Owner Phone:	Not reported
Contact Name:	Not reported
Contact Address:	Not reported
Contact Addr2:	Not reported

RAILROAD ONE LF (Continued) **S106615651**

Contact City,St,Zip: Not reported
Contact Email: Not reported
Contact Phone: Not reported
Activity Desc: Landfill - MSW - permit
Activity Number: [60S01]
Active: No
East Coordinate: 593076
North Coordinate: 4559802
Accuracy Code: Not reported
Regulatory Status: None
Waste Type: Not reported
Authorization #: 702
Authorization Date: Not reported
Expiration Date: 12/31/1986
Operator Name: WESTCHESTER COUNTY DPW
Operator Type: Not reported
Laste Date: Not reported

NY Financial Assurance 1:
Owner Name: WESTCHESTER COUNTY DPW
Region: 3
Estimate Type: Post-closure Estimate
Estimate Amount: 12141652
Estimate Date: 10/01/2013
Mechanism: Local government financial test
Mechanism Amount: 11160338
Issue Date: 10/01/2015
Expiration Date: 09/30/2016
Activity Number: 60S01
Activity Description: Landfill - MSW - permit

D63 **SPILL NUMBER 8900947** **NY Spills** **S104644427**
SSE **148 MARTEEN AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.019 mi.
98 ft. **Site 20 of 26 in cluster D**

Relative:
Higher

Actual:
222 ft.

SPILLS:
Spill Number/Closed Date: 8900947 / 1989-07-25
Facility ID: 8900947
Facility Type: ER
DER Facility ID: 207447
Site ID: 253231
DEC Region: 3
Spill Cause: Unknown
Spill Class: Not reported
SWIS: 6017
Spill Date: 1989-05-01
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1989-05-01
CID: Not reported
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Responsible Party
Cleanup Ceased: 1989-07-25
Cleanup Meets Std: True

SPILL NUMBER 8900947 (Continued) **S104644427**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-05-05
Spill Record Last Update:	1989-07-26
Spiller Name:	Not reported
Spiller Company:	RAD OIL COMPANY
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY / / : SPILL CLEANED UP BY SPILLER N.F.A. / / : SPILL CLEANED UP BY SPILLER N.F.A. 11/29/95: This is additional information about material spilled from the translation of the old spill file: NO LEAD."
Remarks:	"DISCOVERED AFTER FUEL OIL DELIVERY. SOME ON CONCRETE AND SOME INTO CATCH BASIN. BOARD OF HEALTH ON SCENE. RAD OIL CONTRACTED WITH TYREE CO. CLEANUP TO BE DONE BY TYREE"

All Materials:

Site ID:	253231
Operable Unit ID:	927505
Operable Unit:	01
Material ID:	452264
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C64 **RESIDENCE** **NY LTANKS** **S102660217**
NE **185- 187 MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.020 mi.
107 ft. **Site 14 of 21 in cluster C**

Relative: LTANKS:
Lower

Actual: Spill Number/Closed Date:	9708138 / 1997-11-10
209 ft. Facility ID:	9708138
Site ID:	81930
Spill Date:	1997-10-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	369
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

RESIDENCE (Continued) **S102660217**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1998-01-29
Spiller Name:	STANLEY DRUCKER
Spiller Company:	Not reported
Spiller Address:	185- 187 MAIN ST
Spiller County:	001
Spiller Contact:	STANLEY DRUCKER
Spiller Phone:	(914) 937-7307
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75659
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/10/97 SOIL TO BE STOCKPILED & DISPOSED; 10/13/97 LUZON TANK REMOVAL IN DOWNTOWN WHITE PLAINS; TANK LOCATED IN BUCK U/G VAULTED, UNDER THE SIDEWALK; ALL CONTAMINATION MATERIAL REMOVED; "
Remarks:	"contaminated soil uncovered during tank removal. tanks in u/g vault filled with dirt-about 4 yards worth. "

All Materials:

Site ID:	81930
Operable Unit ID:	1051362
Operable Unit:	01
Material ID:	330125
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B65 **NY POWER AUTH** **RCRA NonGen / NLR** **1000555801**
WNW **123 MAIN ST** **NYD986983468**
< 1/8 **WHITE PLAINS, NY 10601**
0.023 mi.
124 ft. **Site 7 of 16 in cluster B**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	01/01/2007
Facility name:	NY POWER AUTH
Facility address:	123 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYD986983468
Mailing address:	MAIN ST WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	MAIN ST WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02

Actual:
195 ft.

NY POWER AUTH (Continued) **1000555801**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: NY POWER AUTH
Owner/operator address: 123 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-681-6200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NY POWER AUTH
Owner/operator address: 123 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-681-6200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NY POWER AUTH
Classification: Not a generator, verified

Date form received by agency: 03/02/1992
Site name: NY POWER AUTH
Classification: Conditionally Exempt Small Quantity Generator

NY POWER AUTH (Continued) **1000555801**

. Waste code: NONE
. Waste name: None

Date form received by agency: 10/22/1991
Site name: NY POWER AUTH
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

B66 **NEW YORK POWER AUTHORITY** **NY UST 1004902218**
WNW **123 MAIN STREET** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.023 mi.
124 ft. **Site 8 of 16 in cluster B**

Relative: **Lower**
Actual: **195 ft.**

UST:
Id/Status: 3-602326 / Active
Program Type: PBS
Region: STATE
DEC Region: 3
Expiration Date: 01/08/2022
UTM X: 603463.16253
UTM Y: 4543064.62683
Site Type: Other

Affiliation Records:
Site Id: 488037
Affiliation Type: Facility Owner
Company Name: NEW YORK POWER AUTHORITY
Contact Type: VICE PRESIDENT, ENVIRONMENT, HEALTH & SAFETY
Contact Name: JOHN KAHABKA
Address1: 123 MAIN STREET
Address2: Not reported
City: WHITE PLAINS
State: NY

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Zip Code:	10601
Country Code:	001
Phone:	(914) 287-3797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2016-10-13

Site Id:	488037
Affiliation Type:	Mail Contact
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	123 MAIN STREET
Address2:	Not reported
City:	WHITE PLAINS
State:	NY
Zip Code:	10601
Country Code:	001
Phone:	(914) 287-3797
EMail:	JOHN.NOLAN@NYPA.GOV
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2016-10-13

Site Id:	488037
Affiliation Type:	Facility Operator
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 287-3797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2017-01-20

Site Id:	488037
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 260-5193
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Date Last Modified: 2016-10-13

Tank Info:

Tank Number: 1
Tank ID: 249946
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 2086
Install Date: 12/01/1981
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: BHYUKOWE
Last Modified: 04/14/2017

Equipment Records:

E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
B04 - Tank External Protection - Fiberglass
D08 - Pipe Type - Equivalent Technology
I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
A00 - Tank Internal Protection - None
F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)

Tank Number: 2
Tank ID: 249947
Tank Status: In Service
Material Name: In Service
Capacity Gallons: 9410
Install Date: 12/01/1981
Date Tank Closed: Not reported
Registered: True
Tank Location: Underground
Tank Type: Equivalent technology
Tightness Test Method: -
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: RXBRAUKS
Last Modified: 02/01/2018

Equipment Records:

B04 - Tank External Protection - Fiberglass
D08 - Pipe Type - Equivalent Technology

NEW YORK POWER AUTHORITY (Continued) **1004902218**

I02 - Overfill - High Level Alarm
K01 - Spill Prevention - Catch Basin
L09 - Piping Leak Detection - Exempt Suction Piping
E04 - Piping Secondary Containment - Double walled UG
C03 - Pipe Location - Aboveground/Underground Combination
F04 - Pipe External Protection - Fiberglass
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser
L01 - Piping Leak Detection - Interstitial - Electronic Monitoring
A00 - Tank Internal Protection - None
F99 - Pipe External Protection - Other
H05 - Tank Leak Detection - In-Tank System (ATG)

WESTCHESTER CO. UST:

Id/Status:	3-496812 / Administratively Closed
Operator Name:	NEW YORK POWER AUTHORITY
Owner Name:	New York Power Authority
Owner Street:	123 Main Street
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	2086
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	12/01/1981
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	2
Status:	1. In-Service
Capacity:	9410
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	12/01/1981
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AST:

Region:	STATE
DEC Region:	3
Site Status:	Active
Facility Id:	3-602326
Program Type:	PBS
UTM X:	603463.16253
UTM Y:	4543064.62683
Expiration Date:	01/08/2022
Site Type:	Other

Affiliation Records:

Site Id:	488037
Affiliation Type:	Facility Owner
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	VICE PRESIDENT, ENVIRONMENT, HEALTH & SAFETY
Contact Name:	JOHN KAHABKA
Address1:	123 MAIN STREET
Address2:	Not reported
City:	WHITE PLAINS
State:	NY
Zip Code:	10601
Country Code:	001
Phone:	(914) 287-3797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2016-10-13

Site Id:	488037
Affiliation Type:	Mail Contact
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	123 MAIN STREET
Address2:	Not reported
City:	WHITE PLAINS
State:	NY
Zip Code:	10601
Country Code:	001
Phone:	(914) 287-3797
EMail:	JOHN.NOLAN@NYPA.GOV
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2016-10-13

Site Id:	488037

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Affiliation Type:	Facility Operator
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(914) 287-3797
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2017-01-20

Site Id:	488037
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK POWER AUTHORITY
Contact Type:	Not reported
Contact Name:	JOHN NOLAN
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(914) 260-5193
EMail:	Not reported
Fax Number:	Not reported
Modified By:	BHYUKOWE
Date Last Modified:	2016-10-13

Tank Info:

Tank Number:	3
Tank Id:	249948

Equipment Records:

E00 - Piping Secondary Containment - None
J03 - Dispenser - Gravity
G01 - Tank Secondary Containment - Diking (Aboveground)
H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
F01 - Pipe External Protection - Painted/Asphalt Coating
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	30
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BHYUKOWE
Last Modified:	04/14/2017
Material Name:	diesel

Tank Number:	4
Tank Id:	249949

Equipment Records:

E00 - Piping Secondary Containment - None
J03 - Dispenser - Gravity
I04 - Overfill - Product Level Gauge (A/G)
C01 - Pipe Location - Aboveground
K00 - Spill Prevention - None
L99 - Piping Leak Detection - Other
D01 - Pipe Type - Steel/Carbon Steel/Iron
F01 - Pipe External Protection - Painted/Asphalt Coating
G09 - Tank Secondary Containment - Modified Double-Walled (Aboveground)
I03 - Overfill - Automatic Shut-Off
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
H99 - Tank Leak Detection - Other

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	01/01/2000
Capacity Gallons:	100
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	BHYUKOWE
Last Modified:	04/14/2017
Material Name:	diesel

WESTCHESTER CO. AST:

PBS Number:	3-496812
Site Status:	Administratively Closed
GDS Number:	Not reported
Operator Name:	NEW YORK POWER AUTHORITY
Owner Name:	New York Power Authority
Owner Street:	123 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601

NEW YORK POWER AUTHORITY (Continued) **1004902218**

Tank Number:	3
Status:	1. In-Service
Date Installation:	12/01/1981
Capacity:	30
Product Stored:	0008. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	other
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	4
Status:	1. In-Service
Date Installation:	01/01/2000
Capacity:	100
Product Stored:	0008. Diesel
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	other
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

B67 **NEW YORK POWER AUTH** **RCRA-CESQG** **1004758118**
WNW **123 MAIN ST** **FINDS** **NYD986982999**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.023 mi. **NY MANIFEST**
124 ft. **Site 9 of 16 in cluster B**

Relative: **Lower**
Actual: **195 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	NEW YORK POWER AUTH
Facility address:	123 MAIN ST WHITE PLAINS HEADQUARTERS WHITE PLAINS, NY 10601
EPA ID:	NYD986982999

NEW YORK POWER AUTH (Continued) **1004758118**

Mailing address: MAIN ST
WHITE PLAINS HEADQUARTERS
WHITE PLAINS, NY 10601
Contact: JOHN BLAKE
Contact address: MAIN ST WHITE PLAINS HEADQUARTERS
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: 914-681-6384
Contact email: Not reported
EPA Region: 02
Land type: State
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: NEW YORK POWER AUTH
Owner/operator address: 123 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-681-6200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: NEW YORK POWER AUTH
Owner/operator address: 123 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-681-6200
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: State
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

NEW YORK POWER AUTH (Continued) **1004758118**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NEW YORK POWER AUTH
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/27/1992
Site name: NEW YORK POWER AUTHORITY
Classification: Large Quantity Generator

Date form received by agency: 12/12/1991
Site name: NEW YORK POWER AUTH
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 10/05/2015

NEW YORK POWER AUTH (Continued) **1004758118**

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009481220

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR SYNTHETIC MINOR

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Registry ID: 110022533775

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

TSCA SUBMITTER

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region

NEW YORK POWER AUTH (Continued) **1004758118**

that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004758118
Registry ID:	110009481220
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009481220

NY MANIFEST:

Country:	USA
EPA ID:	NYD986982999
Facility Status:	Not reported
Location Address 1:	123 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986982999
Mailing Name:	NEW YORK POWER AUTHORITY
Mailing Contact:	EDWARD ALKIEWICZ
Mailing Address 1:	123 MAIN STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142873247

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2018
Trans1 Recv Date:	04/30/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/20/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986982999
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	ARD069748192
TSDF ID 2:	Not reported

NEW YORK POWER AUTH (Continued) **1004758118**

Manifest Tracking Number:	011799958FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H040
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D018
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional NY MANIFEST: record(s) in the EDR Site Report.

B68 **ODDESY CORP MAINT DEPT** **NY LTANKS S104278796**
WNW **123 MAIN STREET** **NY Spills N/A**
< 1/8 **WHITE PLAINS, NY**
0.023 mi.
124 ft. **Site 10 of 16 in cluster B**

Relative: LTANKS:
Lower

Actual: Spill Number/Closed Date:	8906607 / 1991-06-12
195 ft. Facility ID:	8906607
Site ID:	160999
Spill Date:	1989-10-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-10-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

ODDESY CORP MAINT DEPT (Continued) **S104278796**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-10-16
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ODDESY CORP MAINT DEPT
Spiller Address:	123 MAIN ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PETRO TITE, 10K, -.483 GPH, SYSTEM FAILED W/PLUMBING INCLUDED. WILL E.I.R. NEXT WEEK THEY PLAN TO ISOLATE TANK TO RETEST. PASSED RETEST"

All TTF:

Facility ID:	8906607
Spill Number:	8906607
Spill Tank Test:	1536167
Site ID:	160999
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	160999
Operable Unit ID:	931611
Operable Unit:	01
Material ID:	447023
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9910168 / 1999-11-22
Facility ID:	9910168
Site ID:	161000

ODDESY CORP MAINT DEPT (Continued) **S104278796**

Spill Date:	1999-11-19
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	PJDECICC
Referred To:	Not reported
Reported to Dept:	1999-11-22
CID:	323
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-22
Spill Record Last Update:	2000-01-26
Spiller Name:	JOHN MORABIDO
Spiller Company:	COMFORCE (CONTRACTOR)
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	JOSEPH DOSSO
Spiller Phone:	(914) 287-3144
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO 11/22/99 OVERFOLD VALVE LET GO WHEN TESTING GENERATOR; CONTAINED IN CONCRETE CONTAINMENT. NFA"
Remarks:	"ON A Y2K GENERATOR ON THE 17TH FLOOR. SPILL WAS CLEANED UP. "

All Materials:

Site ID:	161000
Operable Unit ID:	1084933
Operable Unit:	01
Material ID:	555904
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	42.00
Units:	G
Recovered:	42.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8907663 / 1991-06-12
Facility ID:	8907663
Site ID:	74955
Spill Date:	1989-11-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	wxwadswo

ODDESY CORP MAINT DEPT (Continued) **S104278796**

Referred To:	Not reported
Reported to Dept:	1989-11-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-09
Spill Record Last Update:	1993-12-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH "
Remarks:	"HIRED CASTLE OIL CO. TO PUMP OUT WILL RETEST SPILL # 8906607 IS THE ORIGINAL # GIVEN TO THIS SITE REFER TO 8906607 FOR MORE INFORMATION PASSED RETEST"

All TTF:

Facility ID:	8907663
Spill Number:	8907663
Spill Tank Test:	1536349
Site ID:	74955
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	74955
Operable Unit ID:	935283
Operable Unit:	01
Material ID:	444449
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

ODDESY CORP MAINT DEPT (Continued) **S104278796**

Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	8606381 / 1987-03-16
Facility ID:	8606381
Facility Type:	ER
DER Facility ID:	70243
Site ID:	160998
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1987-01-13
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	1987-03-16
Cleanup Meets Std:	True
Last Inspection:	1987-03-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-09
Spill Record Last Update:	1988-02-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	160998
Operable Unit ID:	903964
Operable Unit:	01
Material ID:	475507
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

C69 **CONSOLIDATED EDISON CO OF NY** **NJ MANIFEST** **S108170363**
North **189 MAIN ST** **N/A**
< 1/8 **WHITEPLAINS, NY 10601**
0.023 mi.
124 ft. **Site 15 of 21 in cluster C**

Relative:
Lower

Actual:
209 ft.

NJ MANIFEST:

EPA Id:	NYP004144358
Mail Address:	31-01 20TH AVE
Mail City/State/Zip:	ASTORIA 11105
Facility Phone:	7182044151
Emergency Phone:	Not reported
Contact:	DONNA COVENTRY
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	NJA5239251
EPA ID:	NYP004144358
Date Shipped:	08/06/2006
TSDF EPA ID:	NJD991291105
Transporter EPA ID:	NJD003812047
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/06/2006
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/09/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CONSOLIDATED EDISON CO OF NY (Continued) **S108170363**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	09200621
Was Load Rejected:	ASTORIA 11105
Reason Load Was Rejected:	Not reported

C70 **MANHOLE # 10236** **NY Spills** **S107416552**
North **189 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.023 mi.
124 ft. **Site 16 of 21 in cluster C**

Relative:
Lower

Actual:
209 ft.

SPILLS:

Spill Number/Closed Date:	0509190 / 2005-11-01
Facility ID:	0509190
Facility Type:	ER
DER Facility ID:	314244
Site ID:	354925
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2005-11-01
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2005-11-01
CID:	27
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-01
Spill Record Last Update:	2005-11-14
Spiller Name:	FRANK FERRARO
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"No storm drains impacted. Cleaned up. NFA."
Remarks:	"Caller reports a leak from their delivery truck. There was a hole in the hose. White Plains FD is on the scene. Callers company will be sending a cleanup crew. Spill is on the street in front of the business."

All Materials:

Site ID:	354925
Operable Unit ID:	1112311
Operable Unit:	01
Material ID:	2102353
Material Code:	0001A
Material Name:	#2 fuel oil

MANHOLE # 10236 (Continued) **S107416552**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Spill Number/Closed Date:	0601744 / 2008-06-11
Facility ID:	0601744
Facility Type:	ER
DER Facility ID:	314244
Site ID:	364045
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-05-17
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-05-17
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-05-17
Spill Record Last Update:	2008-06-11
Spiller Name:	JOHN MANFREDI
Spiller Company:	CAPELLI ENTERPRISES
Spiller Address:	189 MAIN STREET
Spiller Company:	999
Contact Name:	ERT DESK’
DEC Memo:	"05/17/06 Met with Con ED rep Tim Riley who explained that the impacted manhole conatined about and inch of fuel oil floating on several hundred gallons of water. A sample was taken and results rec’d later indicate that material was similar to a light fuel oil. A curbside fill line for 189 Main Street is one possible source. Requested that when the manhole is safe for entry that Con Ed personnel attempt to determine where the furl is entering the structure. TG 07/21/06 JM Associates coordinated the testing of the remote fill and vent lines servicing 189 Main Street and both of those lines failed. The remote fill was excavated and petroleum impacted soil was present beneath the line. Local WP building Dept work permit prohibited complete removal of the line, so remediation will continue when the building is demolished. TG 06/10/08 Closure report submitted by JM Associates. 13.32 tons of PCS removed. No post excavation sample results were taken. TG"
Remarks:	"UNKNOWN DOING LAB RESULTS: CONED # 200085"

All Materials:

Site ID:	364045
Operable Unit ID:	1122096

MANHOLE # 10236 (Continued) **S107416552**

Operable Unit:	01
Material ID:	2111583
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C71 **199 MAIN STREET REALTY CORP.** **NY UST U004175928**
NE **199 MAIN STREET** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.025 mi.
131 ft. **Site 17 of 21 in cluster C**

Relative: **Lower**
Actual: **209 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-049824 / Active
Operator Name:	Pat Agovino
Owner Name:	199 Main Street Realty Corp.
Owner Street:	P.O. Box 8197
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	199
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/01/1994
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	201
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported

199 MAIN STREET REALTY CORP. (Continued) **U004175928**

Date Perm Closure:	08/01/1994
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-049824
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Pat Agovino
Owner Name:	199 Main Street Realty Corp.
Owner Street:	P.O. Box 8197
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601

Tank Number:	202
Status:	1. In-Service
Date Installation:	11/01/1994
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access),10. Impervious Underlayment (AST Only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

B72 **MARTIN LUTHER KING &** **NY Spills** **S105057532**
WNW **MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.025 mi.
134 ft. **Site 11 of 16 in cluster B**

Relative: SPILLS:
Lower

Actual: Spill Number/Closed Date:	0101975 / 2001-05-21
195 ft. Facility ID:	0101975
Facility Type:	ER
DER Facility ID:	278182

MARTIN LUTHER KING & (Continued) **S105057532**

Site ID:	326507
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6000
Spill Date:	2001-05-21
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	2001-05-21
CID:	205
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-05-21
Spill Record Last Update:	2001-06-13
Spiller Name:	TONY DEOLIVIERA
Spiller Company:	LIBERTY LINES TRANSIT
Spiller Address:	475 SAWMILL RIVER RD
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"HOSE LEAKED. CLEANUP COMPLETED, EXCEPT APPROX 1QT TO STORM DRAIN."

All Materials:

Site ID:	326507
Operable Unit ID:	840783
Operable Unit:	01
Material ID:	537667
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D73 **TM 5706** **NY Spills** **S106014973**
SE **MARTINE AVE/ COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.027 mi.
143 ft. **Site 21 of 26 in cluster D**

Relative: **Higher**

Actual: **219 ft.**

SPILLS:

Spill Number/Closed Date:	0302648 / 2003-06-18
Facility ID:	0302648
Facility Type:	ER
DER Facility ID:	113504
Site ID:	131740
DEC Region:	3

TM 5706 (Continued) **S106014973**

Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2003-06-12
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-06-12
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-12
Spill Record Last Update:	2003-06-19
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MARK SCHLAGEL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 6-17-03 DAMAGED TRANSFORMER REMOVED. 663 GALLONS OF FLUID REMOVED FROM THE STRUCTURE AND 200 GALLONS OF OIL REMOVED FROM TRANFORMER. THE STUCTURE WAS DOUBLE WASHED. NFA TG"
Remarks:	"1800 gal of water alonge with the 90 gal of unk type of oil clean up pending - con ed spill 148701"

All Materials:

Site ID:	131740
Operable Unit ID:	869482
Operable Unit:	01
Material ID:	507113
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	90.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D74 **SPILL NUMBER 0108867** **NY Spills** **S105234981**
SE **412 MARTIN AND COURT** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.027 mi.
145 ft. **Site 22 of 26 in cluster D**

Relative: SPILLS:
Higher

Spill Number/Closed Date:	0108867 / 2001-12-05
Facility ID:	0108867
Facility Type:	ER
DER Facility ID:	73265
Site ID:	78764

Actual:
219 ft.

SPILL NUMBER 0108867 (Continued) **S105234981**

DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2001-12-05
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2001-12-05
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-12-05
Spill Record Last Update:	2002-01-15
Spiller Name:	NESTOR MARTINEZ
Spiller Company:	LIBERTY LINES TRANSIT
Spiller Address:	101 GRASSLAND RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BROWNE 12/5/2001 TRI STATE IS CURRENTLY CLEANING THE SPILL. APPROX. 5 GALLONS SPILLED. NO FURTHER ACTION."
Remarks:	"hydro line on a bus broke spill was to roadway no sewers or waterways affected tri state enviromental was called in and did the clean up "

All Materials:

Site ID:	78764
Operable Unit ID:	847179
Operable Unit:	01
Material ID:	530078
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D75 **LITTLE HOUSE RESTAURANT** **NY Spills** **S102153141**
ESE **169 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.030 mi.
156 ft. **Site 23 of 26 in cluster D**

Relative:
Higher

Actual:
218 ft.

SPILLS:

Spill Number/Closed Date:	8802366 / 1988-06-23
Facility ID:	8802366
Facility Type:	ER
DER Facility ID:	82564

LITTLE HOUSE RESTAURANT (Continued) **S102153141**

Site ID:	91914
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1988-06-15
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-06-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1988-06-23
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DPW RESPONDED, WILL SAND DOWN SPILL."

All Materials:

Site ID:	91914
Operable Unit ID:	919631
Operable Unit:	01
Material ID:	457937
Material Code:	0820A
Material Name:	cooking oil
Case No.:	Not reported
Material FA:	Other
Quantity:	55.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C76 **SOIL** **NY Spills** **S110768383**
NNE **3 RENAISSANCE SQUARE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.038 mi.
199 ft. **Site 18 of 21 in cluster C**

Relative: **Lower**
Actual: **210 ft.**

SPILLS:

Spill Number/Closed Date:	1011749 / 2011-03-31
Facility ID:	1011749
Facility Type:	ER
DER Facility ID:	400485
Site ID:	445639
DEC Region:	3

SOIL (Continued) **S110768383**

Spill Cause:	Human Error
Spill Class:	B1
SWIS:	6017
Spill Date:	2011-02-24
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2011-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-02-24
Spill Record Last Update:	2011-03-31
Spiller Name:	Not reported
Spiller Company:	RITZ CARLTON
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	PATRICK BECCARIA
DEC Memo:	"2/24/11 - Left a message with Caller to return phone call. C. Lalak & C. Torres, Westchester County DOH, will conduct an inspection and report back to DEC. KAB 3/31/11 AS per WCDOH spill CLeanup finished NFA JO'M"
Remarks:	"Caller advised approximately 80 gallons of diesel spilled. Clean up is in process."

All Materials:

Site ID:	445639
Operable Unit ID:	1196021
Operable Unit:	01
Material ID:	2192206
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

B77 **A&S STORE** **NY LTANKS** **S100137114**
WNW **GALLERIA PLAZA** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.041 mi.
217 ft. **Site 12 of 16 in cluster B**

Relative: LTANKS:
Lower

Actual: Spill Number/Closed Date:	8805571 / 1989-03-07
193 ft. Facility ID:	8805571
Site ID:	187319
Spill Date:	1988-09-29
Spill Cause:	Tank Test Failure

A&S STORE (Continued) **S100137114**

Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-03-07
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-09-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-10-19
Spill Record Last Update:	1989-03-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	156504
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/07/89: TANK WAS RELINED AND PUT BACK INTO SERVIVE. 03/07/89: TANK WAS RELINED AND PUT BACK INTO SERVIVE. "
Remarks:	"-.068 GPH; NO COMMENTS (RETEST). 10K TANK. PBS #173665"

All TTF:

Facility ID:	8805571
Spill Number:	8805571
Spill Tank Test:	1534700
Site ID:	187319
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	187319
Operable Unit ID:	920745
Operable Unit:	01
Material ID:	457473
Material Code:	0001A
Material Name:	#2 fuel oil

A&S STORE (Continued) **S100137114**

Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

B78 **A & S STORE** **NY LTANKS** **S100136963**
WNW **GALLERIA PLAZA** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.041 mi.
217 ft. **Site 13 of 16 in cluster B**

Relative: **Lower**
Actual: **193 ft.**

LTANKS:
Spill Number/Closed Date: 8803673 / 1988-08-09
Facility ID: 8803673
Site ID: 187318
Spill Date: 1988-07-27
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-08-09
SWIS: 6017
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-07-27
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2003-12-02
Spiller Name: Not reported
Spiller Company: DENNIS MURPHY
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 156504
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was J OKESSON "
Remarks: "10K -.155 PBS TO FOLLOW UP. NFA"

All TTF:
Facility ID: 8803673
Spill Number: 8803673
Spill Tank Test: 1534356
Site ID: 187318
Tank Number: Not reported
Tank Size: 0
Material: 0001

A & S STORE (Continued) **S100136963**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	187318
Operable Unit ID:	918836
Operable Unit:	01
Material ID:	459213
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D79 **MINSKOFF CORP.** **NY LTANKS** **S102673852**
ESE **179 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.042 mi.
224 ft. **Site 24 of 26 in cluster D**

Relative: **Higher**
Actual: **217 ft.**

LTANKS:

Spill Number/Closed Date:	9201879 / 1992-05-15
Facility ID:	9201879
Site ID:	217944
Spill Date:	1992-05-15
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1992-05-15
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-05-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	ORIG. CONSUMERS

MINSKOFF CORP. (Continued) **S102673852**

Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	180303
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAINED ON CONCRETE FLOOR IN CELLAR SPILLER DOING CLEAN UP"

All Materials:

Site ID:	217944
Operable Unit ID:	969292
Operable Unit:	01
Material ID:	413166
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D80 **WEST HEALTH DEPT** **NY LTANKS** **S106703105**
SSE **148 MARTINE AVE** **N/A**
< 1/8 **YONKERS, NY**
0.045 mi.
237 ft. **Site 25 of 26 in cluster D**

Relative: Higher
Actual: 225 ft.

LTANKS:

Spill Number/Closed Date:	8701223 / 2004-11-06
Facility ID:	8701223
Site ID:	126440
Spill Date:	1987-05-13
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C5
Cleanup Ceased:	Not reported
SWIS:	6018
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1987-05-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-25
Spill Record Last Update:	2004-11-05
Spiller Name:	Not reported
Spiller Company:	TOM ZIMINSKY
Spiller Address:	Not reported

WEST HEALTH DEPT (Continued) **S106703105**

Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	109305
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"TANK TESTED. WILL HAVE TO PLACE MONTORING WELLS."

All TTF:

Facility ID:	8701223
Spill Number:	8701223
Spill Tank Test:	1530809
Site ID:	126440
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	126440
Operable Unit ID:	907699
Operable Unit:	01
Material ID:	471174
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

E81 **CON EDISON** **RCRA NonGen / NLR** **1018277456**
SW **MARTINE & GROVE ST** **FINDS** **NYP004398962**
< 1/8 **WHITE PLAINS, NY 10610** **ECHO**
0.047 mi.
246 ft. **Site 1 of 5 in cluster E**

Relative: **Lower**
Actual: **198 ft.**

RCRA NonGen / NLR:

Date form received by agency:	12/03/2013
Facility name:	CON EDISON
Facility address:	MARTINE & GROVE ST WHITE PLAINS, NY 10610
EPA ID:	NYP004398962
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003

CON EDISON (Continued) **1018277456**

Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/03/2013
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110067680290

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018277456
Registry ID: 110067680290
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067680290

E82
SW
< 1/8
0.047 mi.
246 ft.

CON EDISON
MARTINE & GROVE ST
WHITE PLAINS, NY 10610

Site 2 of 5 in cluster E

NY MANIFEST **S116043535**
N/A

Relative:
Lower

Actual:
198 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004398962
Facility Status:	Not reported
Location Address 1:	NS MARTIN AVE 85 FT NO GROVE ST
Code:	BP
Location Address 2:	MH 9130
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004398962
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2013
Trans1 Recv Date:	12/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004398962
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695018JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S116043535**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E83 **CON EDISON MANHOLE 9772** **RCRA NonGen / NLR** **1014918827**
SW **MARTINE AVE & GROVE ST SE COR** **NJ MANIFEST** **NYP004224465**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.047 mi.
247 ft. **Site 3 of 5 in cluster E**

Relative: **Lower**

Actual: **198 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/17/2011
Facility name:	CON EDISON MANHOLE 9772
Facility address:	MARTINE AVE & GROVE ST SE COR WHITE PLAINS, NY 10601
EPA ID:	NYP004224465
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DOMINIC BIZZARO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON MANHOLE 9772 (Continued) **1014918827**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/18/2011
Site name: CON EDISON MANHOLE 9772
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004224465
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DOMINIC BIZZARO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655782JJK
EPA ID: NYP004224465
Date Shipped: 1/18/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported

CON EDISON MANHOLE 9772 (Continued) **1014918827**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004224465
Facility Status:	Not reported
Location Address 1:	MARTINE AVE
Code:	BP
Location Address 2:	GROVE AVE
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224465
Mailing Name:	CONED - MH9772
Mailing Contact:	CONED - MH9772
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON MANHOLE 9772 (Continued) **1014918827**

seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2011
Trans1 Recv Date:	01/18/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224465
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655782JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E84 **CON EDISON MANHOLE 9128** **RCRA NonGen / NLR** **1014918791**
SW **MARTINE AVE & GROVE ST MH 9128** **NJ MANIFEST** **NYP004224101**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.047 mi.
247 ft. **Site 4 of 5 in cluster E**

Relative:
Lower

Actual:
198 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/14/2011
Facility name:	CON EDISON MANHOLE 9128
Facility address:	MARTINE AVE & GROVE ST MH 9128 WHITE PLAINS, NY 10601
EPA ID:	NYP004224101
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/15/2011
Site name:	CON EDISON MANHOLE 9128
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004224101
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GINO FRABASILE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655565JJK
EPA ID:	NYP004224101
Date Shipped:	1/15/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

CON EDISON MANHOLE 9128 (Continued) **1014918791**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004224101
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & GRANE ST
Code:	BP
Location Address 2:	MH 9128
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224101
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/15/2011
Trans1 Recv Date:	01/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/18/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224101
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655565JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

E85 **CON EDISON MANHOLE 9130** **RCRA NonGen / NLR** **1014918800**
SW **MARTINE AVE & GROVE ST MH 9130** **NJ MANIFEST** **NYP004224192**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.047 mi.
247 ft. **Site 5 of 5 in cluster E**

Relative: **Lower**

Actual: **198 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/15/2011
Facility name:	CON EDISON MANHOLE 9130
Facility address:	MARTINE AVE & GROVE ST MH 9130 WHITE PLAINS, NY 10601
EPA ID:	NYP004224192
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	GINO FRABASILE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON MANHOLE 9130 (Continued) **1014918800**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/16/2011
Site name: CON EDISON MANHOLE 9130
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004224192
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: GINO FRABASILE
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655817JJK
EPA ID: NYP004224192
Date Shipped: 1/16/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: Not reported
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: Not reported
TSDF EPA Facility Name: Not reported

CON EDISON MANHOLE 9130 (Continued) **1014918800**

QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004224192
Facility Status:	Not reported
Location Address 1:	MARTINE AVE BET. GROVE ST & COURT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224192
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported

CON EDISON MANHOLE 9130 (Continued) **1014918800**

Generator Ship Date:	01/16/2011
Trans1 Recv Date:	01/16/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224192
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655817JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C86 **SPILL NUMBER 0206130** **NY LTANKS** **S105996744**
NE **203 MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
253 ft. **Site 19 of 21 in cluster C**

Relative: LTANKS:
Higher

Spill Number/Closed Date:	0206130 / 2003-09-03
Facility ID:	0206130
Site ID:	176565
Spill Date:	2002-09-12
Spill Cause:	Tank Test Failure

Actual:
211 ft.

SPILL NUMBER 0206130 (Continued) **S105996744**

Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-13
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-13
Spill Record Last Update:	2003-09-08
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN JANUS
Spiller Phone:	(914) 760-0257
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148388
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 09/03/03 TANK CLOSED IN PLACE, VAULT CLEAN."
Remarks:	"while doing an inspection of the tank oil was observed leaking back into the empty tank."

All TTF:

Facility ID:	0206130
Spill Number:	0206130
Spill Tank Test:	1527446
Site ID:	176565
Tank Number:	1
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	176565
Operable Unit ID:	857669
Operable Unit:	01
Material ID:	516742
Material Code:	0001A
Material Name:	#2 fuel oil

SPILL NUMBER 0206130 (Continued) **S105996744**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C87 **BRIAN HOLDING COMPANY** **NY UST** **U003994385**
NE **203 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.048 mi.
253 ft. **Site 20 of 21 in cluster C**

Relative: **Higher**
Actual: **211 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-049999 / Unregulated: <1101 gal. PBS
Operator Name:	John Janis
Owner Name:	Brian Holding Company c/o Stillman Management
Owner Street:	141 Halstead Avenue
Owner Address2:	Not reported
Owner City:	Mamaroneck
Owner State:	NY
Owner Zipcode:	10543
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	12/10/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

B88 **VAULT #0070** **NY Spills** **S104282831**
WNW **MAIN ST & GROVE ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.049 mi.
260 ft. **Site 14 of 16 in cluster B**

Relative: **Lower**
Actual: **191 ft.**

SPILLS:

Spill Number/Closed Date:	9908279 / 1999-10-07
Facility ID:	9908279
Facility Type:	ER

VAULT #0070 (Continued) **S104282831**

DER Facility ID:	150615
Site ID:	179454
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-10-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-10-07
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-07
Spill Record Last Update:	2004-03-17
Spiller Name:	JOE DEVOTI
Spiller Company:	CON ED VAULT #0070
Spiller Address:	MAIN ST & GROVE ST
Spiller Company:	001
Contact Name:	JOE DEVOTI
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"WILL FOLLOW UP TOMORROW. CON E D#128310"

All Materials:

Site ID:	179454
Operable Unit ID:	1086946
Operable Unit:	01
Material ID:	300955
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B89 **WHITE PLAINS GARAGE** **NY Spills** **S102151755**
WNW **MAIN ST & GROVE ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.049 mi.
260 ft. **Site 15 of 16 in cluster B**

Relative: SPILLS:
Lower

Actual: Spill Number/Closed Date:	9110939 / 1992-01-24
191 ft. Facility ID:	9110939
Facility Type:	ER
DER Facility ID:	150615
Site ID:	179453

WHITE PLAINS GARAGE (Continued) **S102151755**

DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1992-01-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-01-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-01-24
Spill Record Last Update:	1993-12-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PLUGGED VENT TANK OVERFLOWED TO PAVED AREA DRIVER APPLIED SPEEDI-DRY AND WILL DISPOSE"

All Materials:

Site ID:	179453
Operable Unit ID:	964739
Operable Unit:	01
Material ID:	416013
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B90 **CON EDISON MANHOLE 9763** **RCRA NonGen / NLR** **1014919130**
WNW **MAIN ST & MARTIN LUTHER KING** **NYP004232856**
< 1/8 **WHITE PLAINS, NY 10601**
0.049 mi.
260 ft. **Site 16 of 16 in cluster B**

Relative: **Lower**

Actual: **191 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/28/2011
Facility name:	CON EDISON MANHOLE 9763
Facility address:	MAIN ST & MARTIN LUTHER KING BLVD WHITE PLAINS, NY 10601
EPA ID:	NYP004232856

CON EDISON MANHOLE 9763 (Continued) **1014919130**

Mailing address: IRVING PLAZA RM 828
NEW YORK, NY 10003
Contact: GINO FRABASILE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/29/2011
Site name: CON EDISON MANHOLE 9763
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

F91 **CAMERA STORE** **NY Spills** **S102152262**
East **44 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.053 mi.
278 ft. **Site 1 of 19 in cluster F**

Relative: SPILLS:
Higher
Spill Number/Closed Date: 9211618 / 1994-09-13
Actual: Facility ID: 9211618
214 ft. Facility Type: ER
DER Facility ID: 101879
Site ID: 117103
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6017
Spill Date: 1993-01-08
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1993-01-08
CID: Not reported
Water Affected: Not reported

CAMERA STORE (Continued) **S102152262**

Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	1994-09-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-11
Spill Record Last Update:	1994-09-13
Spiller Name:	Not reported
Spiller Company:	KEMPNER CORP.
Spiller Address:	257 MAMARONECK AVE.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"F.D. ON SCENE WOULD LIKE CALL BACK POSSIBLE OVERFILL TANK LEAK"

All Materials:

Site ID:	117103
Operable Unit ID:	976059
Operable Unit:	01
Material ID:	405007
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

F92 **WOOLWORTH STORE BASEMENT** **NY Spills** **S102155171**
East **24-34 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.053 mi.
278 ft. **Site 2 of 19 in cluster F**

Relative: **Higher**
Actual: **214 ft.**

SPILLS:

Spill Number/Closed Date:	9408182 / 1995-10-06
Facility ID:	9408182
Facility Type:	ER
DER Facility ID:	84283
Site ID:	94110
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1994-09-19
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-09-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other

WOOLWORTH STORE BASEMENT (Continued) **S102155171**

Cleanup Ceased:	1995-10-06
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-09-26
Spill Record Last Update:	1995-10-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER WORKING AT WOOLWORTH'S ON DIFFERENT SPILL DISCOVERED NEW RELEASE POSS. FROM 3K TANK IN BASEMENT WILL DO TANK TEST TOMORROW CLEAN UP ONGOING"

All Materials:

Site ID:	94110
Operable Unit ID:	1005808
Operable Unit:	01
Material ID:	377622
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

F93 **CVS PHARMACY #4745** **RCRA-LQG** **1014958239**
East **26-32 MAMARONECK AVE** **NY MANIFEST** **NYR000194852**
< 1/8 **WHITE PLAINS, NY 10601**
0.053 mi.
278 ft. **Site 3 of 19 in cluster F**

Relative: **Higher**
Actual: **214 ft.**

RCRA-LQG:

Date form received by agency:	03/17/2016
Facility name:	CVS PHARMACY #4745
Facility address:	26-32 MAMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYR000194852
Mailing address:	CVS DR MAIL DROP 23062A WOONSOCKET, RI 02895
Contact:	NICOLE WILKINSON
Contact address:	CVS DR MAIL CODE 2340 WOONSOCKET, RI 02895
Contact country:	US
Contact telephone:	401-770-7132
Contact email:	NICOLE.WILKINSON@CVSHEALTH.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any

CVS PHARMACY #4745 (Continued) **1014958239**

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	24-26 MAMARONECK AVENUE, LLC
Owner/operator address:	MAMARONECK AVENUE WHITE PLAINS, NY 10605
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	07/26/2007
Owner/Op end date:	Not reported

Owner/operator name:	CVS ALBANY, L.L.C.
Owner/operator address:	CVS DR WOONSOCKET, RI 02895
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	11/04/2007
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CVS PHARMACY #4745 (Continued) **1014958239**

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U165
. Waste name: NAPHTHALENE

Historical Generators:
Date form received by agency: 03/17/2014
Site name: CVS PHARMACY #4745
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE

CVS PHARMACY #4745 (Continued) **1014958239**

MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

Date form received by agency: 03/05/2012
Site name: CVS PHARMACY #4745
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D011
. Waste name: SILVER

CVS PHARMACY #4745 (Continued) **1014958239**

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code: D001
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs): 112

Waste code: D002
Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs): 48

Waste code: D007
Waste name: CHROMIUM
Amount (Lbs): 13

Waste code: D009
Waste name: MERCURY
Amount (Lbs): 6

Waste code: D010
Waste name: SELENIUM
Amount (Lbs): 13

Waste code: D011
Waste name: SILVER
Amount (Lbs): 749

Waste code: D024
Waste name: M-CRESOL
Amount (Lbs): 4

CVS PHARMACY #4745 (Continued) **1014958239**

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs): 13

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 10

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 25

Waste code: U165
Waste name: NAPHTHALENE
Amount (Lbs): 1

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000194852
Facility Status: Not reported
Location Address 1: 26-32 MAMARONECK ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000194852
Mailing Name: CVS PHARMACY #4745
Mailing Contact: CVS PHARMACY #4745
Mailing Address 1: 26-32 MAMARONECK AVE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9149490961

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: PAD982661381
Trans2 State ID: NJD071629976
Generator Ship Date: 04/16/2018
Trans1 Recv Date: 04/16/2018
Trans2 Recv Date: 04/23/2018
TSD Site Recv Date: 04/23/2018
Part A Recv Date: Not reported

CVS PHARMACY #4745 (Continued) **1014958239**

Part B Recv Date:	Not reported
Generator EPA ID:	NYR000194852
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	010767503FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	9
Units:	P - Pounds
Number of Containers:	1
Container Type:	BA - Burlap, plastic, paper bags
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D001
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
38 additional NY MANIFEST: record(s) in the EDR Site Report.

F94 **24-46 MAMARONECK ASSOC** **NY Spills** **S109062465**
East **34 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.053 mi.
278 ft. **Site 4 of 19 in cluster F**

Relative: SPILLS:
Higher

Actual: Spill Number/Closed Date:	0801310 / 2008-07-24
214 ft. Facility ID:	0801310
Facility Type:	ER
DER Facility ID:	346652
Site ID:	397212
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-05-02

24-46 MAMARONECK ASSOC (Continued) **S109062465**

Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-05-02
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-02
Spill Record Last Update:	2008-07-24
Spiller Name:	JOE
Spiller Company:	24-46 MAMARONECK ASSOC
Spiller Address:	34 MAMARONECK AVE
Spiller Company:	999
Contact Name:	JOE
DEC Memo:	"06/02/08 Northeast Environmental reported that 15.41 tons of contaminated soil surrounding a vaulted 1,000 gallon tank was disposed. Nfa. TG "
Remarks:	"ABOVE GROUND AND ALL THE DIRT AROUND TANK IS CONTAMINATED"

All TTF:

Facility ID:	0801310
Spill Number:	0801310
Spill Tank Test:	2453639
Site ID:	397212
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	False
Cause:	03
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	397212
Operable Unit ID:	1154171
Operable Unit:	01
Material ID:	2144961
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F95 **QUICK PICK SHOES** **NY Spills** **S102155134**
East **40 MAMARONECK** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.053 mi.
278 ft. **Site 5 of 19 in cluster F**

Relative:
Higher

Actual:
214 ft.

SPILLS:

Spill Number/Closed Date:	9407242 / 1995-10-12
Facility ID:	9407242
Facility Type:	ER
DER Facility ID:	68294
Site ID:	72336
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1994-08-29
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-08-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1995-10-12
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-09-07
Spill Record Last Update:	1995-12-04
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"OIL COMING INTO BUILDING THROUGH FLOOR (CONCRETE) AND FLOOR DRAINS WILL NOTIFY W.C.H.D."

All Materials:

Site ID:	72336
Operable Unit ID:	1004668
Operable Unit:	01
Material ID:	380255
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

F96 **IN DITCH** **NY Spills** **S110539942**
ESE **IN FRONT OF 187 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.055 mi.
288 ft. **Site 6 of 19 in cluster F**

Relative:
Higher

Actual:
216 ft.

SPILLS:

Spill Number/Closed Date:	1007249 / 2014-04-29
Facility ID:	1007249
Facility Type:	ER
DER Facility ID:	395658
Site ID:	440646
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2010-10-06
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-06
Spill Record Last Update:	2014-04-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BRIAN MURPHY
DEC Memo:	"10-6-10 Spoke with Brian Murphy. Todd G has already been on site and directed caller on procedures to take. jm"
Remarks:	"soil contamination found during excavation. Clean up pending. Todd Giosay was on scene"

All Materials:

Site ID:	440646
Operable Unit ID:	1191254
Operable Unit:	01
Material ID:	2186376
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C97 **213 MAIN STREET** **NY Spills** **S102151385**
NE **213 MAIN ATREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.058 mi.
304 ft. **Site 21 of 21 in cluster C**

Relative:
Higher

Actual:
212 ft.

SPILLS:

Spill Number/Closed Date:	9107596 / 1991-10-24
Facility ID:	9107596
Facility Type:	ER
DER Facility ID:	93839
Site ID:	106609
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1991-10-16
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-10-16
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"GOT INTO FIRE SPRINKLER SYSTEM MOST OF IT ON GROUND USED SPEEDI-DRY TO CLEAN UP"

All Materials:

Site ID:	106609
Operable Unit ID:	958041
Operable Unit:	01
Material ID:	419796
Material Code:	0043A
Material Name:	antifreeze
Case No.:	Not reported
Material FA:	Other
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F98 **CALANO & CALANO REALTY CORP.** **NY UST** **U004176164**
ENE **14 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.058 mi.
304 ft. **Site 7 of 19 in cluster F**

Relative:
Higher

Actual:
213 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801152 / Active
Operator Name:	Michael Calano
Owner Name:	Calano & Calano Realty Corp
Owner Street:	14 Mamaroneck Avenue
Owner Address2:	3rd floor
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1960
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

F99 **OFFICE BUILDING** **NY LTANKS** **S106385494**
ENE **14 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.058 mi.
304 ft. **Site 8 of 19 in cluster F**

Relative:
Higher

Actual:
213 ft.

LTANKS:

Spill Number/Closed Date:	9613653 / 1997-03-05
Facility ID:	9613653
Site ID:	284245
Spill Date:	1997-02-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-20
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester

OFFICE BUILDING (Continued) **S106385494**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-20
Spill Record Last Update:	2005-11-08
Spiller Name:	KEMPNER CORP
Spiller Company:	OFFICE BUILDING
Spiller Address:	14 NANARONNECK AV
Spiller County:	001
Spiller Contact:	KEMPNER CORP
Spiller Phone:	(914) 946-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188973
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/05/1995 TANK PASSED A RETEST ON THIS DATE. NFA"
Remarks:	""

All Materials:

Site ID:	284245
Operable Unit ID:	1041238
Operable Unit:	01
Material ID:	338758
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0313324 / 2004-04-22
Facility ID:	0313324
Site ID:	229197
Spill Date:	2004-03-04
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-03-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-04
Spill Record Last Update:	2004-04-22
Spiller Name:	Not reported

OFFICE BUILDING (Continued) **S106385494**

Spiller Company:	CELESTILA GROUP
Spiller Address:	14 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(646) 935-1200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188973
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 04/22/04 TANK PASSED A RETEST ON 3-29-04. jbo"
Remarks:	"RECOMEND: EXCAVATE, AND RETEST "

All TTF:

Facility ID:	0313324
Spill Number:	0313324
Spill Tank Test:	1529019
Site ID:	229197
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	229197
Operable Unit ID:	880498
Operable Unit:	01
Material ID:	498477
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D100 **COUNTY OF WESTCHESTER** **NY AST** **A100465792**
SE **85 COURT STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.058 mi.
306 ft. **Site 26 of 26 in cluster D**

Relative: **Higher**
Actual: **226 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-801525
Site Status:	Administratively Closed
GDS Number:	Not reported
Operator Name:	John Varmon
Owner Name:	County of Westchester

COUNTY OF WESTCHESTER (Continued) **A100465792**

Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	11
Status:	1. In-Service
Date Installation:	07/01/2008
Capacity:	336
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge),GEN BELLY TANK
Tank Secondary Containment:	GEN BELLY TANK
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

F101 **CVS PHARMACY #4745** **PA MANIFEST** **S118068905**
ENE **24 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.061 mi.
324 ft. **Site 9 of 19 in cluster F**

Relative:
Higher

Actual:
213 ft.

Manifest Details:

Year:	2015
Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	U165
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

CVS PHARMACY #4745 (Continued) **S118068905**

Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	9
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015
Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2015

CVS PHARMACY #4745 (Continued) **S118068905**

Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	D009
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	U002
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2015
Manifest Number:	006247110FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852

CVS PHARMACY #4745 (Continued) **S118068905**

Generator Date:	01/13/2015
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D001
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	007274278FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	11/11/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	U002
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	6
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	007274278FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	11/11/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

CVS PHARMACY #4745 (Continued) **S118068905**

Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	4
Waste Number:	D001
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	66
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	007274278FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	11/11/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	D002
Container Number:	1
Container Type:	Fiber or plastic boxes, cartons, cases
Waste Quantity:	3
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	007274278FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000194852
Generator Date:	11/11/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	401-765-1500
TSD EPA Id:	Not reported

CVS PHARMACY #4745 (Continued) **S118068905**

TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D001
Container Number:	1
Container Type:	Burlap, cloth, paper or plastic bags
Waste Quantity:	6
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
1 additional PA_MANIFEST: record(s) in the EDR Site Report.

G102 **WHITE PLAINS TOWN CENTER** **RCRA NonGen / NLR** **1001233124**
NE **MAMARONECK AVE & MAIN ST** **NYR000062356**
< 1/8 **WHITE PLAINS, NY 10601**
0.062 mi.
330 ft. **Site 1 of 10 in cluster G**

Relative:
Higher

Actual:
213 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WHITE PLAINS TOWN CENTER
Facility address:	MAMARONECK AVE & MAIN ST MARTINE AVE WHITE PLAINS, NY 10601
EPA ID:	NYR000062356
Contact:	CHARLES REID
Contact address:	MAMARONECK AVE & MAIN ST MARTINE AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	212-715-0371
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	TST WHITE PLAINS LLC
Owner/operator address:	520 MADISON AVE NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	212-715-0371
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

WHITE PLAINS TOWN CENTER (Continued) **1001233124**

Owner/operator name: TST WHITE PLAINS LLC
Owner/operator address: 520 MADISON AVE
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: 212-715-0371
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS TOWN CENTER
Classification: Not a generator, verified

Date form received by agency: 10/20/1998
Site name: WHITE PLAINS TOWN CENTER
Classification: Small Quantity Generator

Violation Status: No violations found

G103 **CON EDISON MANHOLE: 1790** **RCRA NonGen / NLR** **1016677588**
NE **MAMARONECK AVE & MAIN ST** **FINDS** **NYP004312302**
< 1/8 **WHITE PLAINS, NY 10610** **ECHO**
0.065 mi. **NY MANIFEST**
343 ft. **Site 2 of 10 in cluster G**

Relative:
Higher

Actual:
213 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/14/2013
Facility name: CON EDISON MANHOLE: 1790
Facility address: MAMARONECK AVE & MAIN ST
WHITE PLAINS, NY 10610
EPA ID: NYP004312302
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: DENNIS ROHRER
Contact address: Not reported
Not reported

CON EDISON MANHOLE: 1790 (Continued) **1016677588**

Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/14/2013
Site name: CON EDISON MANHOLE: 1790
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069677674

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110058876453

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

CON EDISON MANHOLE: 1790 (Continued) **1016677588**

ECHO:
Envid: 1016677588
Registry ID: 110058876453
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058876453

Envid: 1016677588
Registry ID: 110069677674
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069677674

NY MANIFEST:
Country: USA
EPA ID: NYP004789996
Facility Status: Not reported
Location Address 1: MAIN ST & MAMARONECK AVE
Code: BP
Location Address 2: MH 1791
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004789996
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 06/04/2015
Trans1 Recv Date: 06/04/2015
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/04/2015
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004789996
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 014467537JJK
Import Indicator: N
Export Indicator: N

CON EDISON MANHOLE: 1790 (Continued) **1016677588**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Country:	USA
EPA ID:	NYP004312302
Facility Status:	Not reported
Location Address 1:	FO 9 MAMARONECK AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004312302
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON MANHOLE: 1790 (Continued) **1016677588**

seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/14/2013
Trans1 Recv Date:	05/14/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/14/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004312302
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658315JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G104 **CON EDISON MANHOLE: 467** **RCRA-LQG** **1016677263**
NE **221 MAIN ST** **FINDS** **NYP004308268**
< 1/8 **WHITE PLAINS, NY 10602** **ECHO**
0.067 mi. **NY MANIFEST**
352 ft. **Site 3 of 10 in cluster G**

Relative:
Higher

Actual:
213 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 467
Facility address:	221 MAIN STREET WHITE PLAINS, NY 10602
EPA ID:	NYP004308268
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	05/07/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

CON EDISON MANHOLE: 467 (Continued) **1016677263**

Owner/Op start date: 05/07/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 06/07/2013
Site name: CON EDISON MANHOLE: 467
Classification: Not a generator, verified

Date form received by agency: 05/07/2013
Site name: CON EDISON MANHOLE: 467
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058879094

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677263
Registry ID: 110058879094
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058879094

CON EDISON MANHOLE: 467 (Continued) **1016677263**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004308268
Facility Status:	Not reported
Location Address 1:	221 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004308268
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/2013
Trans1 Recv Date:	05/07/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004308268
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842714JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON MANHOLE: 467 (Continued) **1016677263**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	3000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G105 **CON EDISON - MANHOLE 467** **NJ MANIFEST** **S120665951**
NE **221 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.067 mi.
352 ft. **Site 4 of 10 in cluster G**

Relative:
Higher

Actual:
213 ft.

NJ MANIFEST:

EPA Id:	NYP004308268
Mail Address:	IRVING PLACE, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS HUACON
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014470867JJK
EPA ID:	NYP004308268
Date Shipped:	2/8/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported

CON EDISON - MANHOLE 467 (Continued) **S120665951**

Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

G106 **CAPELLI CONSTRUCTION** **NY Spills** **S106005554**
NE **MAIN ST & MAMARONECK AV** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.067 mi.
352 ft. **Site 5 of 10 in cluster G**

Relative: **Higher**
Actual: **213 ft.**

SPILLS:

Spill Number/Closed Date:	0203876 / 2002-07-12
Facility ID:	0203876
Facility Type:	ER
DER Facility ID:	103989
Site ID:	119716
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2002-07-12
Investigator:	rdbendel
Referred To:	Not reported
Reported to Dept:	2002-07-12
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

CAPELLI CONSTRUCTION (Continued) **S106005554**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-12
Spill Record Last Update:	2002-07-22
Spiller Name:	Not reported
Spiller Company:	CAPELLI CONSTUCTION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was BENDELL "
Remarks:	"BROKEN HYDRAULIC LINE ON A STREET CLEANER. APPROXIMATELY 10 GALLONS SPILLED OVER A ONE BLOCK AREA. POLICE AND FIRE DEPARTMENTS ON SCENE. SPILLER HIRING 3B ENVIRONMENTAL FOR CLEAN UP."

All Materials:

Site ID:	119716
Operable Unit ID:	856667
Operable Unit:	01
Material ID:	521683
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G107 **MAMARANECK AV** **NY Spills** **S106468401**
NE **MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.067 mi.
352 ft. **Site 6 of 10 in cluster G**

Relative:
Higher

Actual:
213 ft.

SPILLS:

Spill Number/Closed Date:	0111231 / 2002-02-26
Facility ID:	0111231
Facility Type:	ER
DER Facility ID:	277118
Site ID:	253715
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6000
Spill Date:	2002-02-26
Investigator:	rxamato
Referred To:	Not reported
Reported to Dept:	2002-02-26
CID:	211
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

MAMARANECK AV (Continued) **S106468401**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-02-26
Spill Record Last Update:	2002-03-04
Spiller Name:	SAME
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	SEAN MCKEEVER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was SMITH "
Remarks:	"CONTRACTOR REMOVING DEBRIS FROM MANHOLE AND DISTURBED ASBESTOS WHICH LANDED IN PILE BEING REMOVED - NO CLEAN UP - CON ED 141525"

All Materials:

Site ID:	253715
Operable Unit ID:	849762
Operable Unit:	01
Material ID:	528821
Material Code:	0026A
Material Name:	asbestos
Case No.:	01332214
Material FA:	Hazardous Material
Quantity:	1.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

F108 **196-200 MARTINE AVENUE** **NY AST** **A100433532**
ESE **196-200 MARTINE AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.068 mi.
361 ft. **Site 10 of 19 in cluster F**

Relative: Higher
Actual: 216 ft.

WESTCHESTER CO. AST:

PBS Number:	3-802125
Site Status:	Active
GDS Number:	Not reported
Operator Name:	125th 33 Mamaroneck, LLC
Owner Name:	125th 33 Mamaroneck, LLC
Owner Street:	42 Oak Avenue, 3rd Floor
Owner Address2:	Not reported
Owner City/State/Zip:	Tuckahoe, NY 10707
Tank Number:	1
Status:	2. Temporarily out of service
Date Installation:	01/01/1970
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

196-200 MARTINE AVENUE (Continued) **A100433532**

Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

F109 **EMPLOYMENT BUILDING?** **NY Spills** **S108981735**
ESE **48 MAMARONECK AVE.** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.069 mi.
366 ft. **Site 11 of 19 in cluster F**

Relative: **Higher**
Actual: **216 ft.**

SPILLS:

Spill Number/Closed Date:	0710471 / 2008-01-08
Facility ID:	0710471
Facility Type:	ER
DER Facility ID:	341366
Site ID:	391767
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2008-01-03
Investigator:	WCHD
Referred To:	SCHNEIDER/HEINZINGER
Reported to Dept:	2008-01-03
CID:	406
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-03
Spill Record Last Update:	2008-01-22
Spiller Name:	WILLIAM SILSDORF
Spiller Company:	EMPLOYMENT BUILDING?
Spiller Address:	48 MAMARONECK AVE.
Spiller Company:	001
Contact Name:	WILLIAM SILSDORF
DEC Memo:	"PBS #3-074632 - WCHD & WP Building Dept. on scene. 5000. gal. vaulted AST. Filled on 12/29/07 3200 gal. left in tank. Uses 175 gal/day x 6 days=1050 gal. Loss of potentially 1800 -100= 800 gal. Elite on site with vac truck and smaller pump. Tank in very poor condition. Todd Ghiosay contaced and will follow up."
Remarks:	"Caller says the tank failed releasing the material into the basement of the building. Caller is unsure if the cause was corrosion of the tank or physical damage. Elite Environmental will be doing the clean up and the Westchester Dept. of Health is on scene."

EMPLOYMENT BUILDING? (Continued) **S108981735**

All TTF:

Facility ID:	0710471
Spill Number:	0710471
Spill Tank Test:	2384409
Site ID:	391767
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	False
Cause:	00
Source:	01
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	391767
Operable Unit ID:	1148803
Operable Unit:	01
Material ID:	2139295
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F110 **48 MAMARONECK AVENUE, LLC** **NY AST** **A100252294**
ESE **48 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.069 mi.
366 ft. **Site 12 of 19 in cluster F**

Relative: WESTCHESTER CO. AST:
Higher

PBS Number:	3-074632
Site Status:	Unregulated: <1101 gal. PBS
GDS Number:	Not reported
Operator Name:	Ramon Lemus
Owner Name:	48 Mamaroneck Avenue, LLC c/o Silverman Realty
Owner Street:	237 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605

Actual:
216 ft.

Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	12/01/1951
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	02/29/2008

48 MAMARONECK AVENUE, LLC (Continued) **A100252294**

Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	Not reported
Dispenser:	2. Suction

G111 **TARGET CONSTRUCTION SITE** **NY Spills** **S106018272**
ENE **7 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.070 mi.
372 ft. **Site 7 of 10 in cluster G**

Relative: **Higher**
Actual: **214 ft.**

SPILLS:

Spill Number/Closed Date:	0306496 / 2003-09-23
Facility ID:	0306496
Facility Type:	ER
DER Facility ID:	190862
Site ID:	231571
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2003-09-19
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-09-19
CID:	365
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-09-19
Spill Record Last Update:	2004-03-10
Spiller Name:	JOHN MANFREDI
Spiller Company:	Not reported
Spiller Address:	357 MARTINE AVE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 09/23/03 ACTUAL LOCATION OF SPILL IS 357 MARTINE AVE IN WHITE PLAINS. 25 TO 50 GALLONS OF #2 FUEL OIL TO CONCRETE FLOOR IN GENERATOR ROOM. CLEAN UP COMPLETED AS PER STEFAN GOREAU OF WCHD. Cleanup information contained in a report submitted by JM Associates Inc. for spill no 01-11561. TG"

TARGET CONSTRUCTION SITE (Continued) **S106018272**

Remarks: "fire dept on scene trying to clean up - 25 gal in the loading dock area the rest is outside - notification only at this time - clean up contractor on site - wchd on site"

All Materials:

Site ID:	231571
Operable Unit ID:	872981
Operable Unit:	01
Material ID:	503715
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F112 **SHARP IMAGE CLEANER** **EDR Hist Cleaner** **1018689814**
ESE **198 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.071 mi.
374 ft. **Site 13 of 19 in cluster F**

Relative: EDR Hist Cleaner
Higher

Actual: **216 ft.**

Year:	Name:	Type:
1997	SHARP IMAGE CLEANERS	Garment Pressing And Cleaners' Agents
1998	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
1999	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2000	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2001	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2002	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2003	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2004	SHARP IMAGE CLEANER	Garment Pressing And Cleaners' Agents
2005	BISCARDI CLEANERS INC	Drycleaning Plants, Except Rugs
2006	BISCARDI CLEANERS INC	Drycleaning Plants, Except Rugs
2007	BISCARDI CLEANERS INC	Drycleaning Plants, Except Rugs
2008	BISCARDI CLEANERS INC	Drycleaning Plants, Except Rugs

F113 **WHITE PLAINS CITY CENTER** **NY Spills** **S106001664**
ESE **MAMARONECK/MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.071 mi.
377 ft. **Site 14 of 19 in cluster F**

Relative: SPILLS:
Higher

Actual: **215 ft.**

Spill Number/Closed Date:	0111561 / 2004-03-10
Facility ID:	0111561
Facility Type:	ER
DER Facility ID:	141765
Site ID:	168279
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A3
SWIS:	6017

WHITE PLAINS CITY CENTER (Continued) **S106001664**

Spill Date:	2002-03-05
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-03-07
CID:	282
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	2002-05-14
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-07
Spill Record Last Update:	2004-03-19
Spiller Name:	Not reported
Spiller Company:	FULLER DEVELOPMENT CORP
Spiller Address:	14 MAMARONECK AVE
Spiller Company:	001
Contact Name:	JOHN MANFREDI
DEC Memo:	""
Remarks:	"they were digging on the property and found contaminated soil. call complaint ."

All Materials:

Site ID:	168279
Operable Unit ID:	848541
Operable Unit:	01
Material ID:	525580
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F114 **CON EDISON** **RCRA NonGen / NLR** **1014398973**
ESE **240 MARTINE AVE & MAMARONECK AVE** **FINDS** **NYP004213484**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.074 mi. **NJ MANIFEST**
392 ft. **Site 15 of 19 in cluster F**

Relative: **Higher**
Actual: **215 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/13/2010
Facility name:	CON EDISON
Facility address:	240 MARTINE AVE & MAMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004213484
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported

CON EDISON (Continued) **1014398973**

Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110064269786

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1014398973
Registry ID: 110064269786
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110064269786

NJ MANIFEST:
EPA Id: NYP004213484
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DONALD SENNO
Comments: Not reported
SIC Code: Not reported
County: NY119

CON EDISON (Continued) **1014398973**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001086128GBF
EPA ID:	NYP004213484
Date Shipped:	08/13/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/13/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	400 P

F115
ESE
< 1/8
0.074 mi.
392 ft.

ROADWAY
MAMARONECK AVE AND MARTINE AVE
WHITE PLAINS, NY

Site 16 of 19 in cluster F

NY Spills **S111836349**
N/A

Relative:
Higher

Actual:
215 ft.

SPILLS:

Spill Number/Closed Date:	1201594 / 2012-05-21
Facility ID:	1201594
Facility Type:	ER
DER Facility ID:	418708
Site ID:	464312
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2012-05-18
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-05-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-05-18
Spill Record Last Update:	2012-05-21
Spiller Name:	Not reported
Spiller Company:	LIBERTY LINES BUS CO
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	TONY DEOLIZEIRA
DEC Memo:	"5/18/12: Motor oil spill from a Bus, contained to pavement with speedi-dry. Tri-State Environmental contacted, en route with clean up crew and street sweeper. Lisa Hauer will update DEC. jod 5/21/12: Tri-State completed clean up. jod"
Remarks:	"clean up underway"

All Materials:

Site ID:	464312
Operable Unit ID:	1214369
Operable Unit:	01
Material ID:	2212409
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

F116 **1-HOUR PHOTO FINISH** **RCRA NonGen / NLR** **1001127917**
ESE **60B MAMARONECK AVE** **NY MANIFEST** **NYR000035253**
< 1/8 **WHITE PLAINS, NY 10601**
0.076 mi.
400 ft. **Site 17 of 19 in cluster F**

Relative:
Higher

Actual:
216 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	1-HOUR PHOTO FINISH
Facility address:	60B MAMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYR000035253
Mailing address:	MAMARONECK AVE WHITE PLAINS, NY 10601
Contact:	KURT OLSEN
Contact address:	MAMARONECK AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-761-5205
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	KURT OLSEN
Owner/operator address:	127 GARTH ST 4G SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	914-725-0653
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KURT OLSEN
Owner/operator address:	127 GARTH ST 4G SCARSDALE, NY 10583
Owner/operator country:	US
Owner/operator telephone:	914-725-0653
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

1-HOUR PHOTO FINISH (Continued) **1001127917**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: 1-HOUR PHOTO FINISH
Classification: Not a generator, verified

Date form received by agency: 05/06/1997
Site name: 1-HOUR PHOTO FINISH
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000035253
Facility Status: Not reported
Location Address 1: 60-B MANARONECK AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000035253
Mailing Name: 1-HOUR PHOTO FINISH
Mailing Contact: KURT OLSEN
Mailing Address 1: 60-B MAMARONECK AVE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: 4223
Mailing Country: USA
Mailing Phone: 9147615205

NY MANIFEST:
Document ID: MAJ0830070
Manifest Status: Not reported
seq: 01

1-HOUR PHOTO FINISH (Continued) **1001127917**

Year:	1998
Trans1 State ID:	NYCR2436
Trans2 State ID:	FY22NXNJ
Generator Ship Date:	11/12/1998
Trans1 Recv Date:	11/12/1998
Trans2 Recv Date:	11/16/1998
TSD Site Recv Date:	12/01/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000035253
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	MAD982755639
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D011 - SILVER 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00250
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

F117 **SPILL NUMBER 0103591** **NY Spills** **S105056083**
ESE **MAMARONECK AVE/MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.078 mi.
412 ft. **Site 18 of 19 in cluster F**

Relative: SPILLS:
Higher

Actual: Spill Number/Closed Date:	0103591 / 2001-08-09
216 ft. Facility ID:	0103591
Facility Type:	ER
DER Facility ID:	208233
Site ID:	254230
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4

SPILL NUMBER 0103591 (Continued) **S105056083**

SWIS:	6017
Spill Date:	2001-07-02
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-07-03
CID:	396
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-03
Spill Record Last Update:	2002-04-29
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	NICK DIFIORE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 08/09/2001 LETTER SENT TO SILVERMAN REALTY BY S. GOREAU (WCDOH); BASED ON REVIEW OF CLOSURE REPORT SUBMITTED, WCDOH REQUIRES NO FURTHER ACTION."
Remarks:	"caller states that a contracter smelled oil while doing work..nfd..they did call the county heath dept...req call back."

All Materials:

Site ID:	254230
Operable Unit ID:	842126
Operable Unit:	01
Material ID:	535668
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

H118 **IN FRONT OF GALERIA MALL** **NY Spills** **S103573377**
West **MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.081 mi.
427 ft. **Site 1 of 4 in cluster H**

Relative: SPILLS:
Lower

Actual: Spill Number/Closed Date:	9809244 / 1998-10-23
191 ft. Facility ID:	9809244
Facility Type:	ER
DER Facility ID:	277118
Site ID:	253722
DEC Region:	3
Spill Cause:	Equipment Failure

IN FRONT OF GALERIA MALL (Continued) **S103573377**

Spill Class:	C4
SWIS:	6000
Spill Date:	1998-10-23
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1998-10-23
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-23
Spill Record Last Update:	2002-07-17
Spiller Name:	RAY PEREIRA
Spiller Company:	LIBERTY LINES TRANSIT
Spiller Address:	475 SAWMILL RIVER RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"fuel line ruptured on truck - spill cleaned up"

All Materials:

Site ID:	253722
Operable Unit ID:	1066518
Operable Unit:	01
Material ID:	316701
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

F119 **UNOCCUPIED COMMERCIAL** **NY Spills** **S102664436**
East **31 MAMARONECK AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.081 mi.
428 ft. **Site 19 of 19 in cluster F**

Relative:
Higher

Actual:
215 ft.

SPILLS:

Spill Number/Closed Date:	9704158 / 2004-09-08
Facility ID:	9704158
Facility Type:	ER
DER Facility ID:	214720
Site ID:	263395
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017

UNOCCUPIED COMMERCIAL (Continued) **S102664436**

Spill Date:	1997-07-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-07-08
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-07-08
Spill Record Last Update:	2004-09-21
Spiller Name:	JTF MANAGEMENT
Spiller Company:	UNOCCUPIED COMMERCIAL
Spiller Address:	31 MAMARONECK AV
Spiller Company:	001
Contact Name:	JTF MANAGEMENT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/08/97 SPOKE WITH JIM DERIVAN; 5K VAULTED TANK IN BASEMENT; TANK APPEARS TO BE OK BUT PIPING FROM REMOTE FILL APPEARS TO BE LEAKING; CALLER WILL EXCAVATE ONCE ALL LOCAL PERMITS ARE OBTAINED; HE WILL SUBMIT REPORT TO TARRYTOWN OFFICE; March 2004 Tank is in a vault surrounded with sand, so it needs to be tested. WCHD (Vinny) has told the owner to remove the tank or test it. He thinks the tank is going to be removed. 9/21/04: Letter to Westchester Arts Council dated 8Sep2004. Spill closed by Danielle Jackson, WCDOH. NFA required at this time."
Remarks:	"A FUEL OIL LEAK WAS NOTED COMING THROUGH THE BASEMENT WALL OF THE ABOVE BUILDING - AN INVESTIGATION HAS FOUND THAT THE FILL PIPE WAS LEAKING AND FURTHER CONTAMINATION IS TILL BEING INVESTIGATED"

All Materials:

Site ID:	263395
Operable Unit ID:	1050028
Operable Unit:	01
Material ID:	333417
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G120 **221 MAIN STREET** **NY BROWNFIELDS** **S106704121**
NE **221 MAIN ST** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.083 mi.
437 ft. **Site 8 of 10 in cluster G**

Relative:
Higher

Actual:
215 ft.

BROWNFIELDS:

Program:	BCP
Site Code:	58997
Acres:	2.6
HW Code:	C360073
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	07/26/2004
Record Updated Date:	12/20/2007
Update By:	MJRYAN
Site Description:	Location Description: The site is located in an urban portion of Westchester County, occupying several city tax parcels, including 221 Main Street, in the City of White Plains. Current Use: The site is currently being redeveloped. The newly constructed complex will contain approximately 125 hotel rooms, 400 condominiums and approximately 10,000 square feet of street levels stores. Surrounding Uses: The site is surrounded by commercial properties with a mix of retail and office space. Historical Source(s)of contamination: The historical source of contamination at this site included multiple leaking underground storage tanks (USTs). Investigations revealed the presence of ten USTs. Investigations/Actions Performed to date: Previous environmental investigations include a Phase I Investigation in 2002 and a Petroleum Contamination Site Investigation completed in June of 1993. Under the Brownfield Cleanup Program, a Remedial Investigation was conducted in 2005-2006. Based on RI findings, an Interim Remedial Measure (IRM) was planned and implemented which included the removal of all USTs, and contaminated soil. Current Action: A Final Engineering Report which documents the remedial activities completed has been approved. On December 19, 2006 a Certificate of Completion was issued declaring remedial activities complete, and that a Track 1 cleanup (i.e., unrestricted use) has been achieved.
Env Problem:	Contaminant of concern: Petroleum-related compounds including volatile organic compounds (VOCs) and polycyclic aromatic hydrocarbons. Impacted Media: Soil and groundwater. Known SCGs exceedences: Investigation revealed benzene, toluene, ethyl-benzene and xylenes, however, as part of a site-wide remedial program (2005-2006) all contaminated media has been removed and properly disposed.
Health Problem:	The site is located in downtown White Plains, public water serves the area. Through the implementation of an IRM the site has been remediated and nearly all the soil has been removed to bedrock eliminating potential exposure to contaminated soil. Proposed redevelopment of the site will include a ventilated below-grade parking garage with foundation drainage which will effectively eliminate the potential for soil vapor intrusion to occur.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported

221 MAIN STREET (Continued) **S106704121**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Owner
Sub Type:	06
Owner Name:	C/O CAPPELLI ENTERPRISES, INC.
Owner Company:	LC MAIN, LLC
Owner Address:	115 STEVENS AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	RENAISSANCE HOTEL PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	E
Owner Name:	Steven Elghanayan
Owner Company:	EPIC Renaissance LLC
Owner Address:	15 Watts Street, 5th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	RENAISSANCE OFFICE PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	RENAISSANCE PARKING PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	RENAISSANCE RENTAL PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	RENAISSANCE CONDOMINIUM PARTNERS

221 MAIN STREET (Continued) **S106704121**

Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	06
Owner Name:	C/O CAPPELLI ENTERPRISES, INC.
Owner Company:	LC MAIN, LLC
Owner Address:	115 STEVENS AVE.
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	09
Owner Name:	Not reported
Owner Company:	EPIC Renaissance LLC
Owner Address:	15 Watts Street, 5th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Spill Number/Closed Date:	0504810 / 2008-06-17
Facility ID:	0504810
Facility Type:	ER
DER Facility ID:	292111
Site ID:	349725
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	2005-07-21
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2008-06-17

221 MAIN STREET (Continued) **S106704121**

Spiller Name:	JOHN MANFERI
Spiller Company:	COMMECRCIAL BUISNESS
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	JOHN MANFERI
DEC Memo:	"06/17/08 Spill addressed by the Brownfield Cleanup Program remedial action, as documented in the Final Engineering Report for site no. C3-60-073. JPC "
Remarks:	"2 1000 GALLON TANKS: FOUND CONTAMINATION:"

All Materials:

Site ID:	349725
Operable Unit ID:	1107313
Operable Unit:	01
Material ID:	2097204
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0706741 / 2008-07-31
Facility ID:	0706741
Facility Type:	ER
DER Facility ID:	292111
Site ID:	387315
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	6017
Spill Date:	2007-09-18
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-09-18
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2007-09-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-18
Spill Record Last Update:	2008-07-31
Spiller Name:	VENESSA
Spiller Company:	COMMERCIAL SITE
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	VENESSA
DEC Memo:	"7/31/08: Spill closure report from JM Associates submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"

221 MAIN STREET (Continued) **S106704121**

Remarks: "OVERFILLED THE TANK AND IS SURFACE SPILL AND IS BEING CLEANED UP' CALLED ENVIRO WASTE TO PUMP"

All Materials:

Site ID:	387315
Operable Unit ID:	1144524
Operable Unit:	01
Material ID:	2134831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0500820 / 2008-06-17
Facility ID:	0500820
Facility Type:	ER
DER Facility ID:	292111
Site ID:	343904
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2005-04-20
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2008-06-17
Spiller Name:	JOHN MANFREDIE
Spiller Company:	CONSTRUCTION PROJECT
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	JOHN MANFREDIE
DEC Memo:	"3/20/05 John Manfredi reported that this spill was reported based on the results of a test pit dug in the vicinity of this tank which has already been removed. Gross contamination was found at the water table. Site is under active construction, so remediation will occur as the project progresses. Estimated time frame is a few months. TG 06/17/08 Spill addressed by the Brownfield Cleanup Program remedial action, as documented in the Final Engineering Report for site no. C3-60-073. JPC "
Remarks:	"5000 GALLON TANK, FOUYND WHILE EXCAVATING: HOLES IN TANK ALSO:"

221 MAIN STREET (Continued) **S106704121**

All Materials:

Site ID:	343904
Operable Unit ID:	1102569
Operable Unit:	01
Material ID:	582786
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0413395 / 2005-05-12
Facility ID:	0413395
Facility Type:	ER
DER Facility ID:	292111
Site ID:	342486
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-03-24
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-24
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-24
Spill Record Last Update:	2005-05-12
Spiller Name:	JOHN MANFREDI
Spiller Company:	NORTHEAST CORNER
Spiller Address:	BAR BUILDING ANNEX
Spiller Company:	001
Contact Name:	JOHN MANFREDI
DEC Memo:	"4/20/05 UST removal report rec'd from JM Associates. Based on the info contained in that report, NFA required. TG"
Remarks:	"after excavating found a 4000 gallon tank about 70 years old contact cell phone JOHN MANFREDI 9144475634 unknown if tank is intact or if any material has gotten out into soil it is possible caller states in process of removing cleaning and testing area now"

All TTF:

Facility ID:	0413395
Spill Number:	0413395
Spill Tank Test:	1548723
Site ID:	342486

221 MAIN STREET (Continued) **S106704121**

Tank Number:	Not reported
Tank Size:	4000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	342486
Operable Unit ID:	1101213
Operable Unit:	01
Material ID:	581340
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I121 **INNS OF COURT** **NY LTANKS** **S102399524**
SSE **99 COURT ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.086 mi.
453 ft. **Site 1 of 4 in cluster I**

Relative:
Higher

Actual:
229 ft.

LTANKS:

Spill Number/Closed Date:	9606465 / 2006-02-28
Facility ID:	9606465
Site ID:	204590
Spill Date:	1996-08-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-08-20
CID:	349
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-20

INNS OF COURT (Continued) **S102399524**

Spill Record Last Update:	2006-02-28
Spiller Name:	SUSAN HARVEY
Spiller Company:	INNS OF COURT
Spiller Address:	99 COURT ST
Spiller County:	001
Spiller Contact:	SUSAN HARVEY
Spiller Phone:	(914) 947-8400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170073
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/28/06 Tank passed an isolation retest but lines failed in Aug of 1996. Tank was scheduled to be abandoned in place and lines removed by NES Oct 1996. WCHD PBS databse lists site as Unregulated as of June 1997. NFA jod"
Remarks:	""

All TTF:

Facility ID:	9606465
Spill Number:	9606465
Spill Tank Test:	1544695
Site ID:	204590
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	204590
Operable Unit ID:	1034262
Operable Unit:	01
Material ID:	561159
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I122 **THE INNS OF COURT PROPERTIES** **NY UST** **U003994986**
SSE **99 COURT ST.** **N/A**
< 1/8 **, NY 10601**
0.086 mi.
453 ft. **Site 2 of 4 in cluster I**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-601002 / Unregulated: <1101 gal. PBS
Operator Name:	None
Owner Name:	Henry J. Miller
Owner Street:	85 Birchall Drive
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1997
Date Perm Closure:	01/01/1997
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Actual:
229 ft.

J123 **76 MAMARONECK AVENUE, LLC** **NY UST** **U003994298**
ESE **76 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.086 mi.
456 ft. **Site 1 of 10 in cluster J**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-074659 / Unregulated
Operator Name:	Jim Schneider
Owner Name:	76 Mamaroneck Avenue, LLC
Owner Street:	237 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported

Actual:
217 ft.

76 MAMARONECK AVENUE, LLC (Continued) **U003994298**

Tank Leak Detection:	0. None
Date Installation:	12/01/1956
Date Perm Closure:	07/01/1990
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1990
Date Perm Closure:	01/15/2013
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	2. Original sacrificial anode
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

G124 **CON EDISON** **RCRA NonGen / NLR** **1012185322**
NE **MAIN ST & CHURCH ST** **NY MANIFEST** **NYP004161261**
< 1/8 **WHITE PLAINS, NY 10601**
0.087 mi.
460 ft. **Site 9 of 10 in cluster G**

Relative: **Higher**
Actual: **216 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	MAIN ST & CHURCH ST WHITE PLAINS, NY 10601
EPA ID:	NYP004161261
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	917-559-8971
Contact email:	Not reported

CON EDISON (Continued) **1012185322**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/18/2008
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004161261
Facility Status: Not reported
Location Address 1: MAIN ST & CHURCH
Code: BP
Location Address 2: MH1422
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004161261
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CON EDISON (Continued) **1012185322**

seq:	Not reported
Year:	2008
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/20/2008
Trans1 Recv Date:	09/20/2008
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/22/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004161261
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001432820FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	B007
Waste Code 1_2:	B002
Waste Code 1_3:	D008
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

G125 **CON EDISON** **NJ MANIFEST** **S120665658**
NE **MAIN ST & CHURCH ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.087 mi.
460 ft. **Site 10 of 10 in cluster G**

Relative:
Higher

Actual:
216 ft.

NJ MANIFEST:

EPA Id:	NYP004161261
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015323139JJK
EPA ID:	NYP004161261
Date Shipped:	2/3/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120665658**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported
Manifest Number:	015319674JJK
EPA ID:	NYP004161261
Date Shipped:	2/17/2016
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J126 **47 MAMARONECK AVENUE CORP.** **NY UST** **U003994282**
ESE **47 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.090 mi.
477 ft. **Site 2 of 10 in cluster J**

Relative:
Higher

Actual:
216 ft.

WESTCHESTER CO. UST:

Id/Status:	3-030929 / Unregulated
Operator Name:	Not reported
Owner Name:	47 Mamaroneck Avenue Corp.
Owner Street:	47 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1977
Date Perm Closure:	08/23/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

J127 **47 MAMARONECK AVENUE CORP** **NY Spills** **S110139099**
ESE **47 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.090 mi.
477 ft. **Site 3 of 10 in cluster J**

Relative:
Higher

Actual:
216 ft.

SPILLS:

Spill Number/Closed Date:	0910450 / 2013-05-07
Facility ID:	0910450
Facility Type:	ER
DER Facility ID:	372112
Site ID:	423210
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2009-12-22
Investigator:	jbodee
Referred To:	REFER TO WCDOH
Reported to Dept:	2009-12-22
CID:	Not reported
Water Affected:	Not reported

47 MAMARONECK AVENUE CORP (Continued) **S110139099**

Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-22
Spill Record Last Update:	2013-05-07
Spiller Name:	Not reported
Spiller Company:	UNK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	SAME AS ABOVE
DEC Memo:	"12/22/09 - Caller did not leave phone number or correct address. Refer to Westchester County DOH. KAB 5/07/13: Tank closure report submitted to WCDoH PBS. Stefan Goreau reports: 0910450 47 Mamaronenck Avenue, White Plains. Tank removed, contaminated soil removed, end point samples below CP-51. NFA letter from WCDoH PBS enter into EDocs. DEC requires no further action at this time. jod "
Remarks:	"Water has entered 2000 gallon underground storage tank. They have pumped the tank dry and will be meeting the owner today."

All TTF:

Facility ID:	0910450
Spill Number:	0910450
Spill Tank Test:	2488273
Site ID:	423210
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	False
UST:	True
Cause:	01
Source:	99
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	jbodee
Last Modified Date:	Not reported

All Materials:

Site ID:	423210
Operable Unit ID:	1179022
Operable Unit:	01
Material ID:	2172563
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

K128 **IN STREET** **NY Spills** **S102154640**
NNE **55 CHURCH STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.094 mi.
498 ft. **Site 1 of 11 in cluster K**

Relative:
Higher

Actual:
216 ft.

SPILLS:

Spill Number/Closed Date:	9307797 / 1993-09-29
Facility ID:	9307797
Facility Type:	ER
DER Facility ID:	109268
Site ID:	126397
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1993-09-27
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-09-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-09-29
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	PETRO TANK CLEANERS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"UNKNOWN EQUIPMENT FAILURE TO CAUSE OIL TO LEAK FROM TRUCK VENT TO PAVED AREA DRIVER APPLIED SPEEDI-DRI WHITE PLAINS F.D. ON SITE VAC TRUCK ON SITE TO CLEAN UP"

All Materials:

Site ID:	126397
Operable Unit ID:	986303
Operable Unit:	01
Material ID:	394052
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L129 **CON EDISON** **NY MANIFEST** **S118463677**
NW **HAMILTON & MARTIN LUTHER KING** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.096 mi.
507 ft. **Site 1 of 2 in cluster L**

Relative:
Lower

Actual:
187 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004855397
Facility Status:	Not reported
Location Address 1:	HAMILTON & MARTIN LUTHER KING
Code:	BP
Location Address 2:	SB 8320
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004855397
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/19/2015
Trans1 Recv Date:	10/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004855397
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245105JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S118463677**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

L130 **MANHOLE #4021** **NY Spills** **S106006516**
NW **HAMILTON AVE & GROVE ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.096 mi.
507 ft. **Site 2 of 2 in cluster L**

Relative: **Lower**
Actual: **187 ft.**

SPILLS:

Spill Number/Closed Date:	0205032 / 2002-08-13
Facility ID:	0205032
Facility Type:	ER
DER Facility ID:	66203
Site ID:	69649
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2002-08-12
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-08-13
CID:	201
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-13
Spill Record Last Update:	2002-10-30

MANHOLE #4021 (Continued) **S106006516**

Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"4 OZ OF PRODUCT @ 30014 PARTS/MIL. CLEAN UP WILL BEGIN THE MORNING. CON ED #144499."

All Materials:

Site ID:	69649
Operable Unit ID:	857795
Operable Unit:	01
Material ID:	552589
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M131 **CAPELLI CONSTRUCTION SITE** **NY Spills** **S108057431**
North **HAMILTON AVE/COTTAGE PLACE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.096 mi.
509 ft. **Site 1 of 14 in cluster M**

Relative: **Lower**

Actual: **207 ft.**

SPILLS:

Spill Number/Closed Date:	0602844 / 2006-06-16
Facility ID:	0602844
Facility Type:	ER
DER Facility ID:	315552
Site ID:	365413
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-06-14
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-06-14
CID:	444
Water Affected:	STORM DRAIN
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-14
Spill Record Last Update:	2006-08-09
Spiller Name:	DISPPATCHER NICHOLSON

CAPELLI CONSTRUCTION SITE (Continued) **S108057431**

Spiller Company:	CONSTRUCTION SITE
Spiller Address:	HAMILTON AVE/COTTAGE PLAC
Spiller Company:	001
Contact Name:	DISPPATCHER NICHOLSON
DEC Memo:	"06/14/06: OFFICER NICHOLSON SAYS THAT A 55 GAL DRUM WAS TIPPED OVER. CAPPELLI CONSTRUCTION IS THE CONTRACTOR. WCHD SAYS THAT TODD G. IS HANDLING AND WILL RESPOND. 06/14/06 JM Associates Chris Slagel on site. He contacted EnviroWaste who sent a crew to sweep up speedi dry which was spread on the spilled form oil. Very little oil reached the storm drain. NFA. TG"
Remarks:	"LEAKAGE OF ABOUT 10-15 GALLONS OF FUEL INTO A STORM DRAIN"

All Materials:

Site ID:	365413
Operable Unit ID:	1123433
Operable Unit:	01
Material ID:	2112894
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M132 **CONSTRUCTION SITE** **NY Spills** **S107657258**
North **HAMILTON AVE/COTTAGE PLACE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.096 mi.
509 ft. **Site 2 of 14 in cluster M**

Relative: **Lower**

Actual: **207 ft.**

SPILLS:

Spill Number/Closed Date:	0513756 / 2006-03-01
Facility ID:	0513756
Facility Type:	ER
DER Facility ID:	315552
Site ID:	360291
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-03-01
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-03-01
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-03-01

CONSTRUCTION SITE (Continued) **S107657258**

Spill Record Last Update: 2006-03-07
Spiller Name: OFFICER ALLOW
Spiller Company: CONSTRUCTION SITE
Spiller Address: HAMILITON/COTTAGE PLACE
Spiller Company: 001
Contact Name: OFFICER ALLOW
DEC Memo: ""
Remarks: "on cement truck, fire dept on scene and was contained"

All Materials:
Site ID: 360291
Operable Unit ID: 1117467
Operable Unit: 01
Material ID: 2107979
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

M133 **MAN HOLE** **NY Spills** **S109828875**
North **HAMILTON AVE AND COTTAGE PLACE** **N/A**
< 1/8 **WHITEPLAINS, NY**
0.096 mi.
509 ft. **Site 3 of 14 in cluster M**

Relative: **Lower**
Actual: **207 ft.**

SPILLS:
Spill Number/Closed Date: 0905876 / 2009-08-20
Facility ID: 0905876
Facility Type: ER
DER Facility ID: 367286
Site ID: 418169
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6017
Spill Date: 2009-08-19
Investigator: mbmastro
Referred To: Not reported
Reported to Dept: 2009-08-19
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2009-08-19
Spill Record Last Update: 2009-08-20
Spiller Name: Not reported
Spiller Company: CON ED

MAN HOLE (Continued) **S109828875**

Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"8/20/09 RP will be doing clean up and sending report to WP, nfa..mm"
Remarks:	"spill contained to man hole/clean up pending"

All Materials:

Site ID:	418169
Operable Unit ID:	1174357
Operable Unit:	01
Material ID:	2166689
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

M134 **CON EDISON** **NY MANIFEST** **S117738350**
North **HAMILTON AVE & RENNAISANCE** **N/A**
< 1/8 **WHITE PLAINS, NY 10801**
0.097 mi.
513 ft. **Site 4 of 14 in cluster M**

Relative:
Lower

Actual:
207 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004713814
Facility Status:	Not reported
Location Address 1:	HAMILTON AVE & RENNAISANCE
Code:	BP
Location Address 2:	MH8323
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004713814
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015

CON EDISON (Continued) **S117738350**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/11/2015
Trans1 Recv Date:	01/11/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004713814
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013244426JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

I135 **CIGARETTE WORLD** **NY Spills** **S107787635**
SE **10-12 QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.099 mi.
525 ft. **Site 3 of 4 in cluster I**

Relative:
Higher

Actual:
227 ft.

SPILLS:

Spill Number/Closed Date:	0600936 / 2006-04-26
Facility ID:	0600936
Facility Type:	ER
DER Facility ID:	313250
Site ID:	363053
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6017
Spill Date:	2006-04-24
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-04-24
CID:	409
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-24
Spill Record Last Update:	2006-04-26
Spiller Name:	SCOTT GERBER
Spiller Company:	KIMCO
Spiller Address:	3333 NEW HYDE PARK RD
Spiller Company:	001
Contact Name:	TRACY WALL
DEC Memo:	"04/26/06 DEC REVIEWED EXIT SAMPLE RESULTS, CONTAMINATION MINIMAL. NO REMEDIATION IS NECCESSARY - NO ACTION REQUIRED. jod"
Remarks:	"CLEAN UP IS NOT IN PROGRESS. TRACY HAD TALKED TO ROB AMATO AND NO CALL BACK REQUIRED. EDITED AT 04/24//2006 @ 15:54"

All Materials:

Site ID:	363053
Operable Unit ID:	1121120
Operable Unit:	01
Material ID:	2110606
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N136
SSW
< 1/8
0.100 mi.
529 ft.

WESTCHESTER COUNTY COURT HOUSE
110 DR MARTIN LUTHER KING JR BLVD
WHITE PLAINS, NY 10601

Site 1 of 13 in cluster N

RCRA-CESQG | **1007371355** | **NYR000124206**

Relative:
Lower

Actual:
203 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	WESTCHESTER COUNTY COURT HOUSE
Facility address:	110 DR MARTIN LUTHER KING JR BLVD WHITE PLAINS, NY 10601
EPA ID:	NYR000124206
Mailing address:	DR MARTIN LUTHER KING JR BLVD WHITE PLAINS, NY 10601
Contact:	DAVID W LOMASNEY
Contact address:	DR MARTIN LUTHER KING JR BLVD WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-946-9681
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	County
Owner/Operator Type:	Operator
Owner/Op start date:	04/21/2004
Owner/Op end date:	Not reported

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

WESTCHESTER COUNTY COURT HOUSE (Continued) **1007371355**

Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: 04/21/2004
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WESTCHESTER COUNTY COURT HOUSE
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/30/2004
Site name: WESTCHESTER COUNTY COURT HOUSE
Classification: Large Quantity Generator

. Waste code: D007
. Waste name: CHROMIUM

Violation Status: No violations found

K137 **WHITE PLAINS POLICE DEPT** **NY LTANKS** **S100139018**
North **279 HAMILTON AVENUE** **NY MANIFEST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
540 ft. **Site 2 of 11 in cluster K**

Relative:
Lower

Actual:
210 ft.

LTANKS:
Spill Number/Closed Date: 8606771 / 1989-11-29
Facility ID: 8606771
Site ID: 92789
Spill Date: 1987-02-04
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1989-11-29
SWIS: 6017
Investigator: PATEL
Referred To: Not reported
Reported to Dept: 1987-02-04
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester

WHITE PLAINS POLICE DEPT (Continued) **S100139018**

Last Inspection:	1987-02-17
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-09
Spill Record Last Update:	2007-10-25
Spiller Name:	Not reported
Spiller Company:	WPPD
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83302
DEC Memo:	"There is a 2007 Region 3 signed stipulation agreement for this site which can be found at: http://internal/home/rgenf/donepages/consent_orders/ mt10/25/07"
Remarks:	"TTTF"

All TTF:

Facility ID:	8606771
Spill Number:	8606771
Spill Tank Test:	1530547
Site ID:	92789
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	92789
Operable Unit ID:	903611
Operable Unit:	01
Material ID:	472333
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA

WHITE PLAINS POLICE DEPT (Continued) **S100139018**

EPA ID:	NYP000877423
Facility Status:	Not reported
Location Address 1:	279 HAMILTON AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP000877423
Mailing Name:	WHITE PLAINS POLICE DEPT
Mailing Contact:	WHITE PLAINS POLICE DEPT
Mailing Address 1:	279 HAMILTON AVENUE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146824210

NY MANIFEST:

Document ID:	PAB5062794
Manifest Status:	K
seq:	Not reported
Year:	1988
Trans1 State ID:	PA-AH0287
Trans2 State ID:	PA-AH
Generator Ship Date:	10/13/1988
Trans1 Recv Date:	10/13/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/13/1988
Part A Recv Date:	12/05/1988
Part B Recv Date:	12/20/1988
Generator EPA ID:	NYP000877423
Trans1 EPA ID:	NJD000603563
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported

WHITE PLAINS POLICE DEPT (Continued) **S100139018**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04800
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K138 **WHITE PLAINS POLICE DEPT** **RCRA NonGen / NLR** **1000397528**
North **279 HAMILTON AVE** **FINDS** **NYD986876019**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.102 mi.
540 ft. **Site 3 of 11 in cluster K**

Relative: **Lower**

Actual: **210 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WHITE PLAINS POLICE DEPT
Facility address:	279 HAMILTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYD986876019
Mailing address:	HAMILTON AVE WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	HAMILTON AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THE CITY OF WHITE PLAINS
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	THE CITY OF WHITE PLAINS
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212

WHITE PLAINS POLICE DEPT (Continued) **1000397528**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS POLICE DEPT
Classification: Not a generator, verified

Date form received by agency: 04/13/1995
Site name: WHITE PLAINS POLICE DEPT
Classification: Unverified

. Waste code: NONE
. Waste name: None

Date form received by agency: 10/05/1988
Site name: WHITE PLAINS POLICE DEPT
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004438207

Environmental Interest/Information System

WHITE PLAINS POLICE DEPT (Continued) **1000397528**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000397528
Registry ID:	110004438207
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004438207

K139 **FORMER WPPD** **NY LTANKS** **S106702646**
North **279 HAMITON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.102 mi.
540 ft. **Site 4 of 11 in cluster K**

Relative: **Lower**

Actual: **210 ft.**

LTANKS:

Spill Number/Closed Date:	0405806 / 2007-07-06
Facility ID:	0405806
Site ID:	306552
Spill Date:	1987-01-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2004-08-27
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2004-08-27
Spill Record Last Update:	2007-07-06
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS POLICE DEPT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247580
DEC Memo:	"7/6/07 Tipple met with Kahabka and conducted a final inspection of all remaining work as indicated in the STIP. Stip obligations for the installation of engineering controls have been met, continued

FORMER WPPD (Continued) **S106702646**

inspections of those engineering controls to be conducted regularly by the NYPA as per the STIP."
Remarks: "Area is going to be cleaned up."

All Materials:
Site ID: 306552
Operable Unit ID: 889358
Operable Unit: 01
Material ID: 486659
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 306552
Operable Unit ID: 889358
Operable Unit: 01
Material ID: 486658
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

N140 **NYSDEC** **NY MANIFEST** **1009235252**
South **GRAND & QUARRAPUS** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.103 mi.
542 ft. **Site 2 of 13 in cluster N**

Relative:
Higher

Actual:
229 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP003600954
Facility Status: Not reported
Location Address 1: GRAND & QUARRAPUS
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP003600954
Mailing Name: NYSDEC
Mailing Contact: ROBERT SMITH
Mailing Address 1: 21 S PUTT CORNERS RD
Mailing Address 2: Not reported
Mailing City: NEW PALTZ
Mailing State: NY

NYSDEC (Continued) **1009235252**

Mailing Zip:	12561
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9142555453

NY MANIFEST:

Document ID:	NYB2077632
Manifest Status:	C
seq:	Not reported
Year:	1991
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/1991
Trans1 Recv Date:	03/19/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/02/1991
Part A Recv Date:	04/12/1991
Part B Recv Date:	04/12/1991
Generator EPA ID:	NYP003600954
Trans1 EPA ID:	NYD986908085
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD082785429
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N141
SSW
< 1/8
0.103 mi.
546 ft.

CON EDISON
111 MARTIN LUTHER KING JR BLVD
WHITE PLAINS, NY 10601

Site 3 of 13 in cluster N

NJ MANIFEST **S120678603**
N/A

Relative:
Lower

Actual:
199 ft.

NJ MANIFEST:

EPA Id:	NYP004885055
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015323084JJK
EPA ID:	NYP004885055
Date Shipped:	12/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120678603**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

N142 **WESTCHESTER COUNTY COURTHOUSE** **RCRA NonGen / NLR** **1001119601**
SSW **111 GROVE ST** **FINDS** **NYR000028902**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.103 mi. **NY MANIFEST**
546 ft. **Site 4 of 13 in cluster N**

Relative:
Lower

Actual:
199 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WESTCHESTER COUNTY COURTHOUSE
Facility address:	111 GROVE ST WHITE PLAINS, NY 10601
EPA ID:	NYR000028902
Mailing address:	GROVE ST WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	GROVE ST WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	WESTCHESTER COUNTY
Owner/operator address:	148 MARTINE AVE WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-285-2559
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	County
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	WESTCHESTER COUNTY
Owner/operator address:	148 MARTINE AVE WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-285-2559
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	County
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WESTCHESTER COUNTY COURTHOUSE
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WESTCHESTER COUNTY COURTHOUSE
Classification: Not a generator, verified

Date form received by agency: 09/06/1996
Site name: WESTCHESTER COUNTY COURTHOUSE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

FINDS:

Registry ID: 110004528182

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001119601
Registry ID:	110004528182
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004528182

NY MANIFEST:

Country:	USA
EPA ID:	NYR000028902
Facility Status:	Not reported
Location Address 1:	111 GROVE STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000028902
Mailing Name:	WESTCHESTER COUNTY COURTHOUSE
Mailing Contact:	JOHN BLAKE/RANDI SMITH
Mailing Address 1:	123 MAIN STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146816384

NY MANIFEST:

Document ID:	NYB8450235
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	MA102
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/1997
Trans1 Recv Date:	05/07/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/12/1997
Part A Recv Date:	05/20/1997
Part B Recv Date:	06/10/1997
Generator EPA ID:	NYR000028902
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID 1:	AZ0000337360
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00855
Units:	P - Pounds
Number of Containers:	011
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00170
Units:	P - Pounds
Number of Containers:	015
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N143 **CON EDISON** **RCRA NonGen / NLR** **1019909457**
SSW **111 MARTIN LUTHER KING JR BLVD** **NYP004885055**
< 1/8 **WHITE PLAINS, NY 10601**
0.103 mi.
546 ft. **Site 5 of 13 in cluster N**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	12/30/2015
Facility name:	CON EDISON
Facility address:	111 MARTIN LUTHER KING JR BLVD WHITE PLAINS, NY 10601
EPA ID:	NYP004885055
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02

Actual:
199 ft.

CON EDISON (Continued) **1019909457**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/30/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

N144 **WESTCHESTER COUNTY COURTHOUSE** **NY UST U003988573**
SSW **111 MARTIN LUTHER KING JR. BLVD.** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.103 mi.
546 ft. **Site 6 of 13 in cluster N**

Relative: **Lower**

Actual: **199 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-801217 / Active
Operator Name: David Fazio
Owner Name: Westchester County DPW
Owner Street: 148 Martine Avenue
Owner Address2: Not reported
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10601
GDS Number: Not reported

Tank Number: 009
Status: 1. In-Service
Capacity: 30000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 10/01/2003
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection: 3. Fiberglass liner (FRP)
Tank External Protection: 4. Fiberglass
Tank Secondary Containment: 4. Double-Walled (underground only)
Piping Location: 3. Aboveground/Underground Combination

WESTCHESTER COUNTY COURTHOUSE (Continued) **U003988573**

Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	5. Jacketed
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

WESTCHESTER CO. AST:

PBS Number:	3-801217
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Fazio
Owner Name:	Westchester County DPW
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601

Tank Number:	003
Status:	1. In-Service
Date Installation:	01/01/2006
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	1. Diking (aboveground only),12. Double-Walled (AST only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	DAY TANK
Dispenser:	2. Suction

Tank Number:	12
Status:	1. In-Service
Date Installation:	06/02/2002
Capacity:	60
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only),10. Impervious Underlayment (AST Only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **U003988573**

Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	DAY TANK
Dispenser:	2. Suction

Tank Number:	3
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	12. Double-Walled (AST only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin,LOCATED IN SIDEWALK STREET LEVEL
Dispenser:	2. Suction

J145 **204 MARTINE ASSOCIATES / ICG** **NY AST** **A100082594**
East **204 MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.104 mi.
549 ft. **Site 4 of 10 in cluster J**

Relative:
Higher

Actual:
216 ft.

WESTCHESTER CO. AST:

PBS Number:	3-173398
Site Status:	Unregulated: <1101 gal. PBS
GDS Number:	Not reported
Operator Name:	204 Martine Associates
Owner Name:	204 Martine Associates / Icg
Owner Street:	One Summit Ave
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10606

Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	Not reported
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	09/01/1993
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	3. Aboveground/underground combination

204 MARTINE ASSOCIATES / ICG (Continued) **A100082594**

Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

H146 **NYNEX** **NY LTANKS** **S101102877**
WNW **111 MAIN ST** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.104 mi.
551 ft. **Site 2 of 4 in cluster H**

Relative: **Lower**
Actual: **192 ft.**

LTANKS:

Spill Number/Closed Date:	9609101 / 1999-11-26
Facility ID:	9609101
Site ID:	239422
Spill Date:	1996-10-21
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-21
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-10-21
Spill Record Last Update:	1999-12-06
Spiller Name:	Not reported
Spiller Company:	NYNEX
Spiller Address:	111 MAIN ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(914) 793-5200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196913
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/26/99 FEBRUARY 1998 TANK CLOSURE REPORT PREPARED BY S&W SERVICES DOCUMENTING TWO 20K DIESEL TANK REMOVALS. HAS BEEN REVIEWED. 524.7 TONS OF CONTAMINATED SOIL REMOVED. NFA"
Remarks:	"DURING REMOVAL OF TWO TANKS THEY FOUND CONTAMINATED SOIL UNDER THE SECOND TANK"

All Materials:

Site ID:	239422
Operable Unit ID:	1040314
Operable Unit:	01
Material ID:	344831

NYNEX (Continued) **S101102877**

Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9314933 / 1995-03-01
Facility ID:	9314933
Site ID:	145113
Spill Date:	1994-03-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-01
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1994-03-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-03-22
Spill Record Last Update:	1995-03-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	123666
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E I R UST 2000"

All TTF:

Facility ID:	9314933
Spill Number:	9314933
Spill Tank Test:	1542517
Site ID:	145113
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

NYNEX (Continued) **S101102877**

Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	145113
Operable Unit ID:	993211
Operable Unit:	01
Material ID:	386709
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9808850 / 1998-10-16
Facility ID:	9808850
Facility Type:	ER
DER Facility ID:	196913
Site ID:	239423
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	1998-10-15
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-10-16
CID:	384
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-10-16
Spill Record Last Update:	1998-10-21
Spiller Name:	TOM OBRIEN
Spiller Company:	BELL ATLANTIC
Spiller Address:	111 MAIN ST
Spiller Company:	001
Contact Name:	TOM OBRIEN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"RUPTURE IN THE LINE CAUSED SPILL ON THE 5TH FLOOR OF BLDG. UNSURE IF

NYNEX (Continued) **S101102877**

IT GOT INTO STORM DRAIN."

All Materials:

Site ID:	239423
Operable Unit ID:	1066233
Operable Unit:	01
Material ID:	566481
Material Code:	0028A
Material Name:	ethylene glycol
Case No.:	00107211
Material FA:	Hazardous Material
Quantity:	700.00
Units:	G
Recovered:	700.00
Oxygenate:	Not reported

H147 **NYNEX MATERIEL ENTERPRISES CO** **RCRA NonGen / NLR** **1000225769**
WNW **111 MAIN ST** **NY MANIFEST** **NYD980582480**
< 1/8 **WHITE PLAINS, NY 10601**
0.104 mi.
551 ft. **Site 3 of 4 in cluster H**

Relative: **Lower**

Actual: **192 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	NYNEX MATERIEL ENTERPRISES CO
Facility address:	111 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYD980582480
Mailing address:	NINTH AVE NEW YORK, NY 10001
Contact:	Not reported
Contact address:	NINTH AVE NEW YORK, NY 10001
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEW YORK TELEPHONE CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK TELEPHONE CO
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999

NYNEX MATERIEL ENTERPRISES CO (Continued) **1000225769**

Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: NYNEX MATERIEL ENTERPRISES CO
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: NYNEX MATERIEL ENTERPRISES CO
Classification: Not a generator, verified

Date form received by agency: 03/25/1981
Site name: NYNEX MATERIEL ENTERPRISES CO
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF

NYNEX MATERIEL ENTERPRISES CO (Continued) **1000225769**

DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD980582480
Facility Status: Not reported
Location Address 1: 111 MAIN STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD980582480
Mailing Name: NEW YORK TELEPHONE COMPANY
Mailing Contact: NEW YORK TELEPHONE COMPANY
Mailing Address 1: 111 MAIN STREET
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2008
Trans1 State ID: NJD003812047
Trans2 State ID: Not reported
Generator Ship Date: 10/08/2008
Trans1 Recv Date: 10/08/2008
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/09/2008
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYD980582480
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 000405185GBF
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported

NYNEX MATERIEL ENTERPRISES CO (Continued) **1000225769**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

M148 **CON EDISON - VAULT 9075** **NY BROWNFIELDS S120958439**
NNW **200 HAMILTON AVE & COTTAGE PL** **NY Spills N/A**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.105 mi.
556 ft. **Site 5 of 14 in cluster M**

Relative: **Lower**

Actual: **201 ft.**

BROWNFIELDS:

Program:	BCP
Site Code:	570663
Acres:	3.74
HW Code:	C360177
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	05/22/2018
Record Updated Date:	06/25/2018
Update By:	LSZINOMA
Site Description:	Location The Site is located at 200 Hamilton Avenue in the City of White Plains, Westchester County, New York and is legally defined as Tax Map ID Section 125.67, Block 5, Lot 1 on the City of White Plains tax map. The 3.74-acre Site is bounded by Barker Avenue to the north followed by offices, a hotel, and commercial development; Cottage Place to the east followed by a gasoline station and commercial buildings; Hamilton Avenue to the south followed by commercial and government buildings; and Dr. Martin Luther King Jr. Boulevard to the west followed by commercial development. The surrounding area consists primarily of commercial and governmental uses, with residences further north of the Site. Site Features The Site is developed with a rectangular-shaped two-story shopping mall and an east-adjacent asphalt-paved parking lot, with additional parking on the building roof, accessed by a ramp on the northern side of the building. The topography surrounding the Site slopes downward to the west from approximately 200 feet along Cottage Place to approximately

CON EDISON - VAULT 9075 (Continued) **S120958439**

190 feet along Martin Luther King Jr. Boulevard. Current Zoning and Land Use The Site is currently zoned as a Neighborhood Business (B-2) District, and was established and mapped to this location as a specific land use component of the City of White Plains Central Renewal Project (No. NY R-13), which was approved in 1964 and involved the redevelopment of 120 acres of downtown White Plains. The B-2 District, and resulting White Plains Mall construction in 1972, was intended to provide a relocation opportunity for retail and service businesses displaced by the Central Renewal Project. However, since that time the character of downtown White Plains has shifted. A component of the proposed Site development includes a change in the current zoning to a new Transit Development 1 (TD-1) District. This proposed new zoning district would allow for the construction of the mixed-use transit oriented community development consistent with the City of White Plains Strategic Plan to enable innovative development adjacent to the City of White Plains' transit hub, thus encouraging a more walkable and less vehicle dependent community. The current land use is commercial and the surrounding area consists primarily of commercial and governmental uses, with residences further north of the Site. Past Use of the Site A review of historic Sanborn fire insurance maps indicated that the Site was historically bisected by a public street (William Street) and contained several private residential dwellings, a candy manufacturer, and two gasoline stations. The gasoline stations included a facility with three gasoline tanks at 230 Hamilton Avenue (southeastern portion of the Site) on the 1930 through 1950 maps, and a facility with greasing operations and four gasoline tanks at 250 Hamilton Avenue (southern portion of the Site) on the 1950 map. The former on-site structures were likely present until construction of the current two-story shopping mall and east-adjacent asphalt-paved parking lot. Based on historic records and interviews, the shopping mall was constructed in 1972 and has operated as the White Plains Mall with a variety of tenants since its construction, including potential dry cleaners listed in historic City Directories. Surrounding uses included a brush factory west-adjacent to the Site that later became a carpet cleaning business and a laundry facility, a manufactured gas plant northwest of the Site that later became a substation, and a gasoline station east-adjacent of the Site. Site Geology and Hydrogeology The topography surrounding the Site slopes downward to the west from approximately 200 feet along Cottage Place to approximately 190 feet along Martin Luther King Jr. Boulevard. Subsurface soils encountered at the Site during previous environmental and geotechnical investigations indicated that the Site is underlain by a layer of fill extending from ground surface to depths ranging from 5 to 12 feet bgs. This fill layer included sand, silt, gravel, organics (wood/grass), brick, asphalt, and rubber. Apparent native soils composed of varying amounts of sand, silt, and gravel were identified underlying the fill layer. During a recent geotechnical investigation of the Site, bedrock was reported at depths ranging from approximately 13 feet below existing grade in the northeastern portion of the parking lot to approximately 37 feet below existing grade in the central portion of the parking lot, corresponding to approximate elevations of 183 and 165 feet, respectively. The water table was measured in the nine on-site groundwater monitoring wells at depths ranging from 9.58 to 23.90 feet bgs, at elevations ranging from 178.70 to 181.89 feet. The deeper groundwater depths were noted at higher elevations in the eastern portion of the Site (along

CON EDISON - VAULT 9075 (Continued) **S120958439**

	Cottage Place) and at shallower depths in lower elevations in the southern and western portions of the Site (along Hamilton Avenue and Martin Luther King Boulevard). Contour maps indicate that groundwater generally flows in a southwesterly direction across the Site.
Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Kenneth D. Narva
Owner Company:	S-WD/WP LLC
Owner Address:	S-WD/WP LLC
Owner Addr2:	168-A Irving Avenue, Suite 200K
Owner City,St,Zip:	Port Chester, NY 10573
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Brian Kenney
Owner Company:	White Plains Public Library
Owner Address:	100 Martine Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	W.P. Mall Realty, LLC
Owner Address:	35 West Street, Suite 202
Owner Addr2:	Not reported
Owner City,St,Zip:	Spring Valley, NY 10977
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	NYS Department of Environmental Conservation
Owner Address:	21 South Putt Corners Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561-1696
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported

CON EDISON - VAULT 9075 (Continued) **S120958439**

Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Spill Number/Closed Date:	1706297 / Not Reported
Facility ID:	1706297
Facility Type:	ER
DER Facility ID:	514102
Site ID:	560605
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	6017
Spill Date:	2017-09-22
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-09-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2017-09-28
Spill Record Last Update:	2017-12-26
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BECKY
DEC Memo:	"9/28/17 AKRF was performing Phase II, noticed some sites where soil seemed odiferous and possibly contaminated. Took soil and gw samples, soil samples came back below CP-51. GW samples came back high in MTBE, benzene, and toluene in 3 areas. Site used to be old shopping mall. AKRF states that there was a gas station at site in 1970's, and there is currently a gas station across the road from the site. Will send in copy of soil and gw analysis. ga 10/05/17 Becky called and said the report will be completed soon and she expects to submit it in a week or two. TG 12/21/17 AKRF submitted a Phase II Investigation Report (See report in DecDocs.) TG"
Remarks:	"historic spill, found last week after samples were taken, just ground water impacted, clean up is pending"

All Materials:

Site ID:	560605
Operable Unit ID:	1308600
Operable Unit:	01
Material ID:	2315602

CON EDISON - VAULT 9075 (Continued) **S120958439**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004937316
Facility Status:	Not reported
Location Address 1:	200 HAMILTON AVE & COTTAGE PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004937316
Mailing Name:	CON EDISON - VAULT 9075
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

M149 **WHITE PLAINS MALL CLEANERS** **EDR Hist Cleaner** **1020120254**
NNW **200 HAMILTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.105 mi.
556 ft. **Site 6 of 14 in cluster M**

Relative: EDR Hist Cleaner
Lower

Actual: **201 ft.**

Year:	Name:	Type:
1996	WHTIE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
1997	WHTIE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
1998	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
1999	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
2000	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
2001	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
2002	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs
2003	WHITE PLAINS MALL CLEANERS	Drycleaning Plants, Except Rugs

K150 **RENAISSANCE CORPORATE CENTER** **NY AST** **A100355605**
NE **235 MAIN STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.106 mi.
562 ft. **Site 5 of 11 in cluster K**

Relative: **Higher**

Actual: **218 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-049980
Site Status:	Active
GDS Number:	Not reported
Operator Name:	William Dixon (superintendent)
Owner Name:	235-245 Delaware Realty Associates LLC
Owner Street:	120 Bloomingdale Road Suite 105
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1974
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	3. Gravity

K151 **9TH STREET H J LLC** **EDR Hist Auto** **1021475536**
NNE **55 CHURCH ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.106 mi.
562 ft. **Site 6 of 11 in cluster K**

Relative: **Higher**

Actual: **217 ft.**

EDR Hist Auto

Year:	Name:	Type:
2011	9TH STREET H J LLC	Gasoline Service Stations
2012	9TH STREET H J LLC	Gasoline Service Stations
2013	9TH STREET H J LLC	Gasoline Service Stations
2014	9TH STREET H J LLC	Gasoline Service Stations

K152 **55 CHURCH WP LLC** **NY AST** **A100204409**
NNE **55 CHURCH STREET** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.106 mi.
562 ft. **Site 7 of 11 in cluster K**

Relative:
Higher

Actual:
217 ft.

WESTCHESTER CO. AST:

PBS Number:	3-800862
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Tony Sapp Century Link Communications
Owner Name:	55 Church Street WP LLC
Owner Street:	55 Church Street
Owner Address2:	1st Floor
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	001
Status:	1. In-Service
Date Installation:	01/01/2000
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	001
Status:	1. In-Service
Date Installation:	01/01/1956
Capacity:	15000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None

55 CHURCH WP LLC (Continued) **A100204409**

Dispenser:	2. Suction
Tank Number:	002
Status:	1. In-Service
Date Installation:	01/01/2000
Capacity:	275
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	0. None
Dispenser:	2. Suction

K153 **CENTURYLINK COMMUNICATIONS, LLC** **MA AST** **A100457181**
NNE **55 CHURCH STREET, FIRST FLOOR** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.106 mi.
562 ft. **Site 8 of 11 in cluster K**

Relative:
Higher

Actual:
217 ft.

J154 **CON ED VAULT TM572** **NY Spills** **S106720539**
SE **MAMARONECK AVE AT MITCHELL PLACE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.106 mi.
562 ft. **Site 5 of 10 in cluster J**

Relative:
Higher

Actual:
218 ft.

SPILLS:

Spill Number/Closed Date:	0403577 / 2004-07-08
Facility ID:	0403577
Facility Type:	ER
DER Facility ID:	211462
Site ID:	258368
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2004-07-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2004-07-02
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

CON ED VAULT TM572 (Continued) **S106720539**

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-02
Spill Record Last Update:	2004-10-08
Spiller Name:	ERT DESK
Spiller Company:	CON ED
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY see e2mis # 154165. TG"
Remarks:	"FAULTY 500 KVA TRANSFORMER - CAPACITY IS 335 GALLONS - PRIVATE PROPERTY AFFECTED - CLEAN HARBOR WILL BE CLEANING UP - HISTORICAL 16 PPM OF PCB'S FROM 1995. UPDATE: ONE GALLON OF OIL ENTERED THE SEWER."

All Materials:

Site ID:	258368
Operable Unit ID:	885818
Operable Unit:	01
Material ID:	491151
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	335.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

J155 **CON EDISON TRANSFORMER MANHOLE: 572** **RCRA NonGen / NLR** **1016973726**
ESE **MITCHELL PL & MAMARONECK AVE** **NY MANIFEST** **NYP004475315**
< 1/8 **WHITE PLAINS, NY 10606**
0.108 mi.
570 ft. **Site 6 of 10 in cluster J**

Relative:
Higher

Actual:
218 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/22/2014
Facility name:	CON EDISON TRANSFORMER MANHOLE: 572
Facility address:	MITCHELL PL & MAMARONECK AVE WHITE PLAINS, NY 10606
EPA ID:	NYP004475315
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON TRANSFORMER MANHOLE: 572 (Continued) **1016973726**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/22/2014
Site name: CON EDISON TRANSFORMER MANHOLE: 572
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004475315
Facility Status: Not reported
Location Address 1: MITCHELL RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004475315
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING ST
Mailing Address 2: 15TH ST
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CON EDISON TRANSFORMER MANHOLE: 572 (Continued) **1016973726**

Generator Ship Date:	03/22/2014
Trans1 Recv Date:	03/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/27/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004475315
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772704JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

K156 **HAMILTON TEXACO SERVICE** **EDR Hist Auto** **1020148230**
North **303 HAMILTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.111 mi.
585 ft. **Site 9 of 11 in cluster K**

Relative: EDR Hist Auto
Higher

Actual:
213 ft.

Year:	Name:	Type:
1970	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1971	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1972	HAMILTON TEXACO SERVICE	Gasoline Service Stations

HAMILTON TEXACO SERVICE (Continued) **1020148230**

1973	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1974	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1975	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1976	HAMILTON TEXACO SERVICE	Gasoline Service Stations
1977	HAMILTON TEXACO SERVICE	Gasoline Service Stations

J157 **KIMCO REALTY CORP** **NY UST** **U004176745**
SE **100 MAMARONECK AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.112 mi.
589 ft. **Site 7 of 10 in cluster J**

Relative: **Higher**
Actual: **219 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-801328 / Unregulated: <1101 gal. PBS
Operator Name:	Not reported
Owner Name:	Kimco Realty Corp
Owner Street:	3333 New Hyde Park
Owner Address2:	Not reported
Owner City:	New Hyde Park
Owner State:	NY
Owner Zipcode:	11040
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	01/25/2006
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

---

158 **VAULT 9104** **NY Spills** **S104880531**
SW **MARTINE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.113 mi.
596 ft.

Relative: **Lower**
Actual: **198 ft.**

SPILLS:

Spill Number/Closed Date:	0009470 / 2000-11-20
Facility ID:	0009470
Facility Type:	ER
DER Facility ID:	145441
Site ID:	312169

VAULT 9104 (Continued) **S104880531**

DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2000-11-17
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-17
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-17
Spill Record Last Update:	2000-11-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/20/2000 CLOSURE REPORT SENT TO TARRYTOWN OFFICE. NFA"
Remarks:	"IN FRONT OF THE WHITE PLAINS LIBRARY - CONTAINED - CASE #134424"

All Materials:

Site ID:	312169
Operable Unit ID:	830411
Operable Unit:	01
Material ID:	543412
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I159 **POST OFFICE SQUARE** **NY Spills** **S103568736**
SSE **QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.113 mi.
596 ft. **Site 4 of 4 in cluster I**

Relative:
Higher

Actual:
235 ft.

SPILLS:

Spill Number/Closed Date:	8807856 / 1989-07-05
Facility ID:	8807856
Facility Type:	ER
DER Facility ID:	93976
Site ID:	106758
DEC Region:	3
Spill Cause:	Other

POST OFFICE SQUARE (Continued) **S103568736**

Spill Class:	C4
SWIS:	6017
Spill Date:	1988-08-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-12-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	DEC
Cleanup Ceased:	1989-06-28
Cleanup Meets Std:	True
Last Inspection:	1989-06-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-01-05
Spill Record Last Update:	1997-10-07
Spiller Name:	Not reported
Spiller Company:	POLERA BUILDING CORP
Spiller Address:	180 BROOK ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/05/89: SITE OWNER HIRED EES TO REMOVE CONTAMINATED SOIL. CLEAN UP SATIFACTORY. NFA. "
Remarks:	"TANK RIPPED OPEN DURING SITE EXCAVATION PROPER TANK CLOSURE & SOIL CLEAN UP NEEDED."

All Materials:

Site ID:	106758
Operable Unit ID:	923332
Operable Unit:	01
Material ID:	452630
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K160 **HAMILTON MAIN PARKING STR** **NY LTANKS** **S100139680**
NNE **HAMILTON AVE & MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.114 mi.
603 ft. **Site 10 of 11 in cluster K**

Relative: **Higher**
Actual: **219 ft.**

LTANKS:

Spill Number/Closed Date:	8707260 / 1989-11-29
Facility ID:	8707260
Site ID:	286661
Spill Date:	1987-11-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported

HAMILTON MAIN PARKING STR (Continued) **S100139680**

Cleanup Ceased:	1989-11-29
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-27
Spill Record Last Update:	1989-11-29
Spiller Name:	RED BROCCHI
Spiller Company:	C/WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	232336
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks:	"2K TANK SYSTEM -.5257 GPH, TO E, I & R"

All TTF:

Facility ID:	8707260
Spill Number:	8707260
Spill Tank Test:	1532412
Site ID:	286661
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286661
Operable Unit ID:	911136
Operable Unit:	01
Material ID:	466224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported

HAMILTON MAIN PARKING STR (Continued) **S100139680**

Recovered: .00
Oxygenate: Not reported

M161 **C.F** **NY Spills** **S109062966**
North **274 HAMILTON ABVE** **N/A**
< 1/8 **WHITE PLAIINS, NY**
0.117 mi.
617 ft. **Site 7 of 14 in cluster M**

Relative: **Lower**

Actual: **210 ft.**

SPILLS:

Spill Number/Closed Date:	0801891 / 2008-05-19
Facility ID:	0801891
Facility Type:	ER
DER Facility ID:	347316
Site ID:	397930
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	6017
Spill Date:	2008-05-19
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	2008-05-19
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-19
Spill Record Last Update:	2008-05-27
Spiller Name:	MELISSA GLIDEN
Spiller Company:	C.F
Spiller Address:	274 HAMILTON ABVE
Spiller Company:	001
Contact Name:	MELISSA GLIDEN
DEC Memo:	"Spoke to Amanda. Water in tank top sumps. Tyree scheduled to pump out. NFA."
Remarks:	"tyree to pump"

All Materials:

Site ID:	397930
Operable Unit ID:	1154848
Operable Unit:	01
Material ID:	2145675
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

M162 **CON EDISON** **NY MANIFEST** **S117738650**
North **274 HAMILTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.117 mi.
617 ft. **Site 8 of 14 in cluster M**

Relative:
Lower

Actual:
210 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004717195
Facility Status:	Not reported
Location Address 1:	274 HAMILTON AVE
Code:	BP
Location Address 2:	TM 4691
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004717195
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/21/2015
Trans1 Recv Date:	01/21/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004717195
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014161949JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117738650**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	350
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

M163 **CODI BROTHERS INC** **EDR Hist Auto** **1020580145**
North **274 HAMILTON AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.117 mi.
617 ft. **Site 9 of 14 in cluster M**

Relative: EDR Hist Auto
Lower

Actual:
210 ft.

Year:	Name:	Type:
1969	CODI BROS INC	Gasoline Service Stations
1970	CODI BROS INC	Gasoline Service Stations
1971	CODI BROS INC	Gasoline Service Stations
1972	CODI BROS INC	Gasoline Service Stations
1973	CODI BROS INC	Gasoline Service Stations
1974	CODI BROTHERS INC	Gasoline Service Stations
1975	CODI BROTHERS INC	Gasoline Service Stations
1976	CODI BROTHERS INC	Gasoline Service Stations
1977	CODI BROTHERS INC	Gasoline Service Stations
1978	CODI BROTHERS INC	Gasoline Service Stations
1979	CODI BROTHERS INC	Gasoline Service Stations
1980	CODI BROTHERS INC	Gasoline Service Stations
1982	CODI BROTHERS INC	Gasoline Service Stations
1983	CODI BROTHERS INC	Gasoline Service Stations
1985	CODI BROTHERS INC	Gasoline Service Stations
1986	CODI BROTHERS INC	Gasoline Service Stations
1987	CODI BROTHERS INC	Gasoline Service Stations
1988	CODI BROTHERS INC	Gasoline Service Stations
1989	CODI BROTHERS INC	Gasoline Service Stations
1990	CODI BROTHERS INC	Gasoline Service Stations
1991	CODI BROTHERS INC	Gasoline Service Stations
1992	CODI BROTHERS INC	Gasoline Service Stations
1993	CODI BROTHERS INC	Gasoline Service Stations

CODI BROTHERS INC (Continued) **1020580145**

1994	CODI BROTHERS INC	Gasoline Service Stations
1995	CODI BROTHERS INC	Gasoline Service Stations
1996	CODI BROTHERS INC	Gasoline Service Stations
1997	CODI BROTHERS INC	Gasoline Service Stations
1998	CODI BROTHERS INC	Gasoline Service Stations
1999	CODI BROTHERS INC	Gasoline Service Stations
2000	CODI BROTHERS INC	Gasoline Service Stations
2001	CODI BROTHERS INC	Gasoline Service Stations
2002	CODI BROTHERS INC	Gasoline Service Stations
2003	CODI BROTHERS INC	Gasoline Service Stations
2004	CODI BROTHERS INC	Gasoline Service Stations
2005	CODI BROTHERS INC	Gasoline Service Stations
2006	CODI BROTHERS INC	Gasoline Service Stations
2007	CODI BROTHERS INC	Gasoline Service Stations
2008	CODI BROTHERS INC	Gasoline Service Stations
2009	CODI BROTHERS INC	Gasoline Service Stations
2010	CODI BROTHERS INC	Gasoline Service Stations
2011	CODI BROTHERS INC	Gasoline Service Stations
2012	CODI BROTHERS INC	Gasoline Service Stations
2012	AAMA AUTO SERVICE INC	General Automotive Repair Shops
2013	AAMA AUTO SERVICE INC	General Automotive Repair Shops
2013	CODI BROTHERS INC	Gasoline Service Stations
2014	AAMA AUTO SERVICE INC	General Automotive Repair Shops
2014	CODI BROTHERS INC	Gasoline Service Stations

O164 **131 GRANT AVE** **NY LTANKS** **S108765471**
South **131 GRANT AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.117 mi.
617 ft. **Site 1 of 7 in cluster O**

Relative: **Higher**
Actual: **232 ft.**

LTANKS:

Spill Number/Closed Date:	0705016 / 2013-01-30
Facility ID:	0705016
Site ID:	385277
Spill Date:	2007-08-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2007-08-02
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-08-02
Spill Record Last Update:	2013-01-30
Spiller Name:	JIM ROOD
Spiller Company:	Not reported
Spiller Address:	131 GRANT AVE
Spiller County:	001

131 GRANT AVE (Continued) **S108765471**

Spiller Contact:	JIM ROOD
Spiller Phone:	(845) 228-0076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	334663
DEC Memo:	"WILL RETEST 1/30/2013 With Albany Approval all Homeowner TTF failures greater then 5 years old can be closed NFA JO'M"
Remarks:	"ISOLATION"

All TTF:

Facility ID:	0705016
Spill Number:	0705016
Spill Tank Test:	1551050
Site ID:	385277
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	385277
Operable Unit ID:	1142547
Operable Unit:	01
Material ID:	2132784
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K165 **LIGHTHOUSE FOR THE BLIND** **NY Spills** **S102154862**
NNE **44 CHURCH STREET** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.119 mi.
629 ft. **Site 11 of 11 in cluster K**

Relative:
Higher

Actual:
219 ft.

SPILLS:

Spill Number/Closed Date:	9314430 / 1997-11-12
Facility ID:	9314430
Facility Type:	ER
DER Facility ID:	98478
Site ID:	112766
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3

LIGHTHOUSE FOR THE BLIND (Continued) **S102154862**

SWIS:	6017
Spill Date:	1994-03-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-03-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-14
Spill Record Last Update:	1997-12-04
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/15/97 TANK ABANDONED IN PLACE; NO REMOVAL OF CONTAMINATED SOIL WAS PERFORMED; STANDARDS MET = NO; "
Remarks:	"TANK IS LEAKING INTO BUILDING FIRE ALARM CREW DISCOVERED LARGE SPILL THINK AN UST IS PRESENT OWNER IS BRINGING IN CONTRACTOR OIL IS ENTERING BASEMENT THROUGH UNDERGROUND EXTERIOR PIPE"

All Materials:

Site ID:	112766
Operable Unit ID:	996362
Operable Unit:	01
Material ID:	386225
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

H166 **BISCARDI FRANK** **EDR Hist Cleaner** **1019940041**
West **102 MAIN ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.121 mi.
637 ft. **Site 4 of 4 in cluster H**

Relative: EDR Hist Cleaner
Lower

Actual: **198 ft.**

Year:	Name:	Type:
1971	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1972	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1973	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1974	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1975	BISCARDI FRANK	Drycleaning Plants, Except Rugs

N167
South
< 1/8
0.122 mi.
645 ft.

CON EDISON
QUARROPAS ST & MLK BLVD
WHITE PLAINS, NY 10601

Site 7 of 13 in cluster N

RCRA NonGen / NLR | **1019905075** / **NYP004805560**

Relative:
Lower

Actual:
206 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/12/2015
Facility name:	CON EDISON
Facility address:	QUARROPAS ST & MLK BLVD WHITE PLAINS, NY 10601
EPA ID:	NYP004805560
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/12/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

N168
South
< 1/8
0.122 mi.
645 ft.

CON EDISON
QUARROPAS ST & MLK BLVD
WHITE PLAINS, NY 10601

Site 8 of 13 in cluster N

NY MANIFEST | **S119076430** / **N/A**

Relative:
Lower

Actual:
206 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004805560
Facility Status:	Not reported
Location Address 1:	QUAMOPERS ST W OF GROVE
Code:	BP

CON EDISON (Continued) **S119076430**

Location Address 2: MH 11363
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004805560
Mailing Name: CON EDISON
Mailing Contact: DENNIS HUACON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N169 **CON EDISON** **NY MANIFEST** **S117740229**
South **QUARROPAS ST & MARTIN LUTHER** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.122 mi.
645 ft. **Site 9 of 13 in cluster N**

Relative:
Lower

Actual:
206 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004733887
Facility Status: Not reported
Location Address 1: QUARROPAS ST & MARTIN LUTHER KING BLVD
Code: BP
Location Address 2: MH 9778
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004733887
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported

CON EDISON (Continued) **S117740229**

Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/19/2015
Trans1 Recv Date:	02/19/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/19/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004733887
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091832JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N170 **WESTCHESTER COURTHOUSE** **NY Spills** **S104881168**
South **GROVE ST AND QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.122 mi.
645 ft. **Site 10 of 13 in cluster N**

Relative:
Lower

Actual:
206 ft.

SPILLS:

Spill Number/Closed Date:	0010532 / 2002-10-02
Facility ID:	0010532
Facility Type:	ER
DER Facility ID:	140941
Site ID:	167279
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2000-12-19
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2000-12-19
CID:	282
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-19
Spill Record Last Update:	2002-10-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOHN PETERSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 9-27-02 GROUNDWATER REPORT RECEIVED. RESULTS ARE SATISFACTORY FOR CASE CLOSURE. NFA TG"
Remarks:	"THEY WERE DIGGING IN THE AREA AND FOUND CONTAMINATED SOIL. CALL COMPLAINT"

All Materials:

Site ID:	167279
Operable Unit ID:	831667
Operable Unit:	01
Material ID:	544427
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N171 **CON EDISON** **RCRA NonGen / NLR** **1014398972**
South **GROVE ST & QUARROPAS ST** **NJ MANIFEST** **NYP004213476**
< 1/8 **WHITE PLAINS, NY 10601**
0.122 mi.
645 ft. **Site 11 of 13 in cluster N**

Relative: **Lower**

Actual: **206 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/13/2010
Facility name:	CON EDISON
Facility address:	GROVE ST & QUARROPAS ST WHITE PLAINS, NY 10601
EPA ID:	NYP004213476
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004213476
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **1014398972**

Date Change:	Not reported

Manifest:

Manifest Number:	006874772JJK
EPA ID:	NYP004213476
Date Shipped:	08/13/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/13/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	90 G

N172 **CON EDISON** **NJ MANIFEST** **S120673776**
South **QUARROPAS ST & MLK BLVD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.122 mi.
645 ft. **Site 12 of 13 in cluster N**

Relative:
Lower

Actual:
206 ft.

NJ MANIFEST:

EPA Id:	NYP004805560
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473233JJK
EPA ID:	NYP004805560
Date Shipped:	7/12/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673776**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J173 **MITCHELL PLACE ASSOC.** **NY LTANKS** **S100137749**
ESE **10 MITCHELL PLACE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.123 mi.
649 ft. **Site 8 of 10 in cluster J**

Relative:
Higher

Actual:
217 ft.

LTANKS:

Spill Number/Closed Date:	8902485 / 1989-10-02
Facility ID:	8902485
Site ID:	76057
Spill Date:	1989-06-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-10-02
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-06-14
Spill Record Last Update:	1989-10-02
Spiller Name:	Not reported
Spiller Company:	MITCHELL PLACE ASSOC.
Spiller Address:	10 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	71149
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY 10/02/89: SPILLER HIRED EES TO PULL TANK AND REMOVE CONTAMINATED SOIL. SUMP WAS PERIODICALLY CLEANE AND FREE OIL REMOVED. NFA. "
Remarks:	"SPOKE W/BOB HYMAN. DIGGING ON 6/14/89 TO UNCOVER TANK & RETEST."

All TTF:

Facility ID:	8902485
Spill Number:	8902485
Spill Tank Test:	1535567
Site ID:	76057
Tank Number:	Not reported

MITCHELL PLACE ASSOC. (Continued) **S100137749**

Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	76057
Operable Unit ID:	928178
Operable Unit:	01
Material ID:	450186
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

M174 **EXXON DIV OF CFI #70324** **RCRA-CESQG** **1000244746**
North **274 HAMILTON AVE & COTTAGE PLACE** **FINDS** **NYD013387436**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.123 mi. **NY MANIFEST**
650 ft. **Site 10 of 14 in cluster M**

Relative: **Lower**

Actual: **209 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	EXXON DIV OF CFI #70324
Facility address:	274 HAMILTON AVE & COTTAGE PLACE WHITE PLAINS, NY 10601
EPA ID:	NYD013387436
Mailing address:	DEDHAM ST CANTON, MA 02021
Contact:	MAUREEN JERNSTEDT
Contact address:	DEDHAM ST CANTON, MA 02021
Contact country:	US
Contact telephone:	800-225-9702
Telephone ext.:	3378
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

EXXON DIV OF CFI #70324 (Continued) **1000244746**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	09/10/2003
Owner/Op end date:	Not reported

Owner/operator name:	TOSCO
Owner/operator address:	PO BOX 52085
	PHOENIX, AZ 85072
Owner/operator country:	US
Owner/operator telephone:	602-728-8000
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Owner/operator name:	TOSCO
Owner/operator address:	PO BOX 52085
	PHOENIX, AZ 85072
Owner/operator country:	Not reported
Owner/operator telephone:	602-728-8000
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	NO NAME FOUND
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported

EXXON DIV OF CFI #70324 (Continued) **1000244746**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/10/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: EXXON DIV OF CFI #70324
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 10/06/2004
Site name: EXXON DIV OF CFI #70324
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 08/08/2001
Site name: TOSCO#34748
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

EXXON DIV OF CFI #70324 (Continued) **1000244746**

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 07/22/1988
Site name: TOSCO#34748
Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004348386

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000244746
Registry ID: 110004348386
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004348386

NY MANIFEST:
Country: USA
EPA ID: NYD013387436
Facility Status: Not reported
Location Address 1: 274 HAMILTON AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD013387436
Mailing Name: EXXON USA
Mailing Contact: EXXON USA
Mailing Address 1: 274 HAMILTON AVENUE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10602
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

EXXON DIV OF CFI #70324 (Continued) **1000244746**

NY MANIFEST:

Document ID:	NYG3870036
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	CA016
Trans2 State ID:	Not reported
Generator Ship Date:	08/24/2003
Trans1 Recv Date:	08/24/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/26/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013387436
Trans1 EPA ID:	CAR000118992
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD002593887
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TP - Tanks, portable
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

M175 **EXXON SERVICE STATION** **NY LTANKS** **S103571230**
North **274 HAMILTON AVE** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.123 mi.
650 ft. **Site 11 of 14 in cluster M**

Relative: LTANKS:
Lower

Spill Number/Closed Date:	8707486 / 1987-12-18
Facility ID:	8707486
Site ID:	190041

Actual:
209 ft.

EXXON SERVICE STATION (Continued) **S103571230**

Spill Date:	1987-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D3
Cleanup Ceased:	1987-12-18
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-12-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-12-02
Spill Record Last Update:	1988-02-12
Spiller Name:	Not reported
Spiller Company:	EXXON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	93029
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 2-9-88 PASSED RET. ON 12-17-87. N.F.A. L.R. "
Remarks:	"4K TANK SYS. WOULD NOT HOLD COLUMN, TO ESCAVATE & LOCATE LEAK"

All TTF:

Facility ID:	8707486
Spill Number:	8707486
Spill Tank Test:	1532487
Site ID:	190041
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	190041
Operable Unit ID:	911639
Operable Unit:	01
Material ID:	466435
Material Code:	0009

EXXON SERVICE STATION (Continued) **S103571230**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9707887 / Not Reported
Facility ID:	9707887
Facility Type:	ER
DER Facility ID:	93029
Site ID:	105471
DEC Region:	3
Spill Cause:	Other
Spill Class:	A3
SWIS:	6017
Spill Date:	1997-10-03
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	1997-10-03
CID:	282
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	5
Date Entered In Computer:	1997-10-03
Spill Record Last Update:	2017-09-20
Spiller Name:	Not reported
Spiller Company:	EXXON SERVICE STATION
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	MICHAEL MEOLA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 06/08/98 LETTER SENT DEC REQUIRES SOIL AND INVESTIGATION OF SITE IN 6 MONTHS 02/09/01 LETTER SENT TO EXXONMOBIL BY J. HARDY; ADVISE AS TO THE SIGNIFICANCE OF THE WHITE PLAINS MALL DENIAL OF ACCESS. 03/15/01 LETTER SENT TO EXXONMOBIL BY J. HARDY; SCHEDULE FOR SUBMISSION OF AN INVESTIGATION REPORT BY 4/30/01 IS APPROVED & REQUIRED. Letter to K. Bourque, Groundwater & Env. Svcs. from J. Hardy, dated 6/27/2003. Reduce monitor well sampling to semi-annually, report annually. 09/04/03: Letter to Eric Harvey, Groundwater & Env. Services, Inc from J. Hardy. Reduce monitor well sampling to semi-annually. Report annually. 6/22/09 2008 annual report shows persistent contamination of approximately 5k btex at mw1--sent email to lbg sirecting them to define extent of contamination in that vicinity within 45 days--email is in edocs jh 10/26/09 2009 annual report shows all wells stable (and low)except mw-1 which has gone down to approx 3k btex. 11/10/09 as a result of decrease in mw1 above gave cf option, by email, to start quarterly

EXXON SERVICE STATION (Continued) **S103571230**

sampling and reporting instead of investigation at this time. In that case we would consider future action based on whether downward trend continues or not. email in edocs jh 4/21/10 jan 10 sampling shows levels approx same as last period jh 11/22/10 Project transferred to Mastro. 5/25/11 BTEX concentrations remain high in MW-1. Will continue to monitor...mm 5/7/12 See quarterly monitoring reports in edocs...mm 02/12/13 A workplan has been developed and approved to investigate the BTEX in MW-1. Four monitoring wells will be installed and soil samples will be collected for lab analysis. 7/2013 Four monitoring wells were installed..mm 3/30/2017 The BTEX concentrations in MW-1 and MW-4 remain high and unchanged. Off site wells are ND. The consultant, LBG, has been asked to develop a RAP...mm 8/01/17 The 2ndQMR report was submitted by LBG. RAP will be proposed by m10/31/17...mm"

Remarks: "WHILE REMOVING ABANDONED UNDERGROUND 1000 GALLON TANK ELEVATED PID HEAD SPACE READINGS WERE ENCOUNTERED "

All Materials:

Site ID:	105471
Operable Unit ID:	1051107
Operable Unit:	01
Material ID:	329872
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0806742 / 2009-02-24
Facility ID:	0806742
Facility Type:	ER
DER Facility ID:	93029
Site ID:	404037
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-09-15
Investigator:	TDGHIOSA
Referred To:	WCDOH / PBS 3-164135
Reported to Dept:	2008-09-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-15
Spill Record Last Update:	2009-02-24
Spiller Name:	BRAIN HAWE

EXXON SERVICE STATION (Continued) **S103571230**

Spiller Company: CUMBERLAND FARMS # 70324
Spiller Address: 274 HAMILTON AVE
Spiller Company: 999
Contact Name: BRAIN HAWE
DEC Memo: "1K FUEL OIL TANK REMOVAL. NO EVIDENCE OF RELEASE UPON REMOVAL. LAB RESULTS CAME BACK WITH SVOC DETECTION. WILL SUBMIT REPORT. DT 02/2009 UST closure report submitted by Leggette Brashears & Graham. Based on the information contained in that report, no further action required. TG"
Remarks: "CALLER STATES THAT THEY WERE REMOVING TANKS AND NOTICED CONTAMINATED SOIL. CALLER STATES THAT LAB RESULTS CONFIRMED CONTAMINATION."

All Materials:
Site ID: 404037
Operable Unit ID: 1160714
Operable Unit: 01
Material ID: 2151889
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

M176 **AAMA AUTO SERVICE, INC.** **NY UST U003949256**
North **274 HAMILTON AVENUE** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.123 mi.
650 ft. **Site 12 of 14 in cluster M**

Relative: **Lower**
Actual: **209 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-164135 / Active
Operator Name: Syed H. Kirmani
Owner Name: 274 SNK Hamilton Avenue, LLC
Owner Street: 1983 Route 52
Owner Address2: Not reported
Owner City: Hopewell Junction
Owner State: NY
Owner Zipcode: 12533
GDS Number: 3551700304

Tank Number: 01
Status: 1. In-Service
Capacity: 12000
Product Stored: 2712. Gasoline/Ethanol
Product Stored Percent: 10
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 01/01/1989
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection: 0. None
Tank External Protection: 4. Fiberglass
Tank Secondary Containment: 4. Double-Walled (underground only)
Piping Location: 2. Underground/on Ground

AAMA AUTO SERVICE, INC. (Continued) **U003949256**

Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	02
Status:	1. In-Service
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	03
Status:	1. In-Service
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	04
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	Not reported
Product Stored Percent:	Not reported

AAMA AUTO SERVICE, INC. (Continued) **U003949256**

Tank Leak Detection:	0. None
Date Installation:	01/01/1989
Date Perm Closure:	09/01/2008
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	0. Administratively closed
Capacity:	67000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	4. Glass liner
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve,5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	10
Status:	0. Administratively closed
Capacity:	1000
Product Stored:	9999. Other
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1989
Date Perm Closure:	12/01/2001
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported

AAMA AUTO SERVICE, INC. (Continued) **U003949256**

Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	0. Administratively closed
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	3
Status:	0. Administratively closed
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

WESTCHESTER CO. AST:

PBS Number:	3-164135
Site Status:	Active
GDS Number:	3551700304
Operator Name:	Syed H. Kirmani
Owner Name:	274 SNK Hamilton Avenue, LLC
Owner Street:	1983 Route 52
Owner Address2:	Not reported
Owner City/State/Zip:	Hopewell Junction, NY 12533

AAMA AUTO SERVICE, INC. (Continued) **U003949256**

Tank Number:	05
Status:	1. In-Service
Date Installation:	01/01/1997
Capacity:	350
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	1. Diking (aboveground only),9. Modified double-walled (aboveground only)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	06
Status:	3. Closed - Removed
Date Installation:	01/01/1997
Capacity:	350
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	07
Status:	1. In-Service
Date Installation:	09/01/2008
Capacity:	500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating

AAMA AUTO SERVICE, INC. (Continued) **U003949256**

Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

Tank Number:	4
Status:	3a. Closed - Prior to 04/1991
Date Installation:	01/01/1989
Capacity:	550
Product Stored:	0003. #6 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	4. Aboveground: w/ 10% or more below ground
Tank Type:	5. Steel tank in concrete
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	4. fiberglass coated steel
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	5
Status:	0. Administratively closed
Date Installation:	01/01/1997
Capacity:	350
Product Stored:	Not reported
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	0. None

M177 **AMCOTT ASSOCIATES** **NY UST** **U003994325**
North **300 HAMILTON AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.125 mi.
659 ft. **Site 13 of 14 in cluster M**

Relative: **Higher**

Actual: **213 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-259241 / Active
Operator Name:	Amcott Associates
Owner Name:	Amcott Associates
Owner Street:	60 Morrow Avenue
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	002
Status:	0. Administratively closed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	03/01/2003
Date Perm Closure:	12/05/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	Not reported
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/underground combination
Piping Type:	99. Other
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity
Tank Number:	01
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	03/01/2003
Date Perm Closure:	06/08/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AMCOTT ASSOCIATES (Continued) **U003994325**

Tank Number:	02
Status:	1. In-Service
Capacity:	8000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	08/01/2002
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	08/01/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

M178 **AMCOTT ASSOCIATES** **NY AST** **A100468972**
North **300 HAMILTON AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.125 mi.
659 ft. **Site 14 of 14 in cluster M**

Relative: WESTCHESTER CO. AST:
Higher

PBS Number:	3-259241
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Amcott Associates
Owner Name:	Amcott Associates
Owner Street:	60 Morrow Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Scarsdale, NY 10583

Actual:
213 ft.

AMCOTT ASSOCIATES (Continued) **A100468972**

Tank Number:	03
Status:	1. In-Service
Date Installation:	01/01/2010
Capacity:	25
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	12. Double-Walled (AST only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	4. Fiberglass
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	1. Catch Basin
Dispenser:	Not reported

J179 **GAS STATION** **NY LTANKS S102960212**
ESE **9 MITCHELL PL** **NY Spills N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.127 mi.
673 ft. **Site 9 of 10 in cluster J**

Relative: **Higher**
Actual: **217 ft.**

LTANKS:

Spill Number/Closed Date:	9710474 / 1998-10-27
Facility ID:	9710474
Site ID:	199404
Spill Date:	1997-12-12
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-12-12
Spill Record Last Update:	1999-01-20
Spiller Name:	Not reported
Spiller Company:	GAS STATION
Spiller Address:	9 MITCHELL PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

GAS STATION (Continued) **S102960212**

DEC Region: 3
DER Facility ID: 165966
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "Caller doing site work found contaminated soil. Luzon report - no further work required."

All Materials:
Site ID: 199404
Operable Unit ID: 1056851
Operable Unit: 01
Material ID: 328768
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 1200312 / 2012-08-02
Facility ID: 1200312
Facility Type: ER
DER Facility ID: 417359
Site ID: 462934
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: B3
SWIS: 6017
Spill Date: 2012-04-11
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2012-04-11
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-04-11
Spill Record Last Update: 2012-08-02
Spiller Name: LEE LEWITT
Spiller Company: LEE LEWITT
Spiller Address: 9 MITCHELL PL
Spiller Company: 999
Contact Name: LEE LEWITT
DEC Memo: " 4/11/12: Former PBS Facility, Mitchell Place Garage. Barbara McDonald from WCDOH reports all USTs were reportedly removed when the site was deregulated. She will follow up with owner and caller, then update DEC. jod 07/31/12 Northeast Environmental submitted a soil

GAS STATION (Continued) **S102960212**

remediation report. They reported that they unearthed a 1000 gallon fuel oil tank. More than 60% of the tank was under the building making removal impossible. The soil immediately beneath the tank was impacted but left in place. All surrounding soils were removed. A gw monitoring well was installed in the vicinity of the tank and no contaminants were detected. NE Environmental recommended removing any remaining impacted soil once the building is demolished. NFA TG "

Remarks: "cleanup pending - tank under foundation of building"

All Materials:

Site ID:	462934
Operable Unit ID:	1213041
Operable Unit:	01
Material ID:	2210932
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

J180 **DEVON PLAZA REALTY** **NY UST** **U004176326**
ESE **9 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.127 mi.
673 ft. **Site 10 of 10 in cluster J**

Relative: **Higher**

Actual: **217 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-412384 / Unregulated
Operator Name:	Stillman Management
Owner Name:	Devon Plaza Realty
Owner Street:	440 Mamroneck Avenue
Owner Address2:	Suite S-512
Owner City:	Harrison
Owner State:	NY
Owner Zipcode:	10528
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported

DEVON PLAZA REALTY (Continued) **U004176326**

Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	04/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	4. Closed - in place
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	05/16/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1960
Date Perm Closure:	07/27/2016

DEVON PLAZA REALTY (Continued) **U004176326**

Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	5
Status:	1. In-Service
Capacity:	500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	05/01/2012
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	10. Urethane clad steel
Tank Internal Protection:	Not reported
Tank External Protection:	2. Original sacrificial anode,9. Urethane
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	6. Wrapped (Piping),9. Urethane
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

P181 **GHP HAMILTON AVENUE** **NY UST** **U004176517**
WNW **170 HAMILTON AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.130 mi.
689 ft. **Site 1 of 2 in cluster P**

Relative: WESTCHESTER CO. UST:
Lower

Actual:
194 ft.

Id/Status:	3-466034 / Active
Operator Name:	GHP Hamilton Ave. GHP Office
Owner Name:	GHP Hamilton, LLC
Owner Street:	4 West Red Oak Lane
Owner Address2:	Suite 200
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported

Tank Number:	3-466034
Status:	1. In-Service
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None

GHP HAMILTON AVENUE (Continued) **U004176517**

Date Installation:	03/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

P182 **CONSOLIDATED EDISON** **NY Spills** **S102241491**
WNW **170 HAMILTON AVE** **NY MANIFEST** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.130 mi.
689 ft. **Site 2 of 2 in cluster P**

Relative: **Lower**

Actual: **194 ft.**

SPILLS:

Spill Number/Closed Date:	9601379 / 2000-10-06
Facility ID:	9601379
Facility Type:	ER
DER Facility ID:	108424
Site ID:	125352
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C5
SWIS:	6017
Spill Date:	1996-04-26
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-04-26
CID:	323
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-04-26
Spill Record Last Update:	2000-10-16
Spiller Name:	UNKNOWN
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ANTHONY LONGHITANO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/06/2000 LETTER SENT TO ELMENDORF ENVIRONMENTAL BY T. GHIOSAY; SPILL NUMBER IS CLOSED BUT SOME CONTAMINATION REMAINS WHICH MAY HAVE TO BE ADDRESSED AT A LATER TIME. "
Remarks:	"CONTAMINATED GROUND WATER FOUND. DEC INVESTIGATING AT THIS TIME."

CONSOLIDATED EDISON (Continued) **S102241491**

All Materials:

Site ID:	125352
Operable Unit ID:	1029030
Operable Unit:	01
Material ID:	351186
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004108221
Facility Status:	Not reported
Location Address 1:	170 HAMILTON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004108221
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE1279746
Manifest Status:	Not reported
seq:	01
Year:	2003
Trans1 State ID:	46274JM
Trans2 State ID:	Not reported
Generator Ship Date:	03/05/2003
Trans1 Recv Date:	03/05/2003
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/06/2003
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004108221
Trans1 EPA ID:	NYD006982359

CONSOLIDATED EDISON (Continued) **S102241491**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

N183 **RECKSON ASSOCIATES** **RCRA NonGen / NLR** **1004762372**
South **140 GRAND ST** **FINDS** **NYR000096263**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.134 mi. **NY MANIFEST**
705 ft. **Site 13 of 13 in cluster N**

Relative: **Higher**
Actual: **227 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RECKSON ASSOCIATES
Facility address:	140 GRAND ST WHITE PLAINS, NY 10601
EPA ID:	NYR000096263
Mailing address:	BROADHOLLOW RD MELVILLE, NY 11747
Contact:	PHILLIP FALLON
Contact address:	BROADHOLLOW RD MELVILLE, NY 11747
Contact country:	US
Contact telephone:	631-622-6678
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

RECKSON ASSOCIATES (Continued) **1004762372**

Owner/operator name: RECKSON ASSOC REAL ESTATE CORP
Owner/operator address: 225 BROADHOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-622-6678
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: RECKSON ASSOC REAL ESTATE CORP
Owner/operator address: 225 BROADHOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 631-622-6678
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RECKSON ASSOCIATES
Classification: Not a generator, verified

Date form received by agency: 04/25/2001
Site name: RECKSON ASSOCIATES
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

RECKSON ASSOCIATES (Continued) **1004762372**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110006540412

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004762372
Registry ID:	110006540412
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006540412

NY MANIFEST:

Country:	USA
EPA ID:	NYR000096263
Facility Status:	Not reported
Location Address 1:	140 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000096263
Mailing Name:	RECKSON
Mailing Contact:	RECKSON
Mailing Address 1:	140 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9147307200

NY MANIFEST:

Document ID:	NJA3192745
Manifest Status:	Not reported

RECKSON ASSOCIATES (Continued) **1004762372**

seq:	01
Year:	2001
Trans1 State ID:	S50059
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2001
Trans1 Recv Date:	04/30/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096263
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

O184 **CON EDISON - VAULT 4680** **NY MANIFEST** **S120959011**
South **161 GRAND ST** **N/A**
1/8-1/4 **BRONX, NY 10601**
0.136 mi.
717 ft. **Site 2 of 7 in cluster O**

Relative: NY MANIFEST:
Higher

Country:	USA
EPA ID:	NYP004983803
Facility Status:	Not reported
Location Address 1:	161 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

Actual:
235 ft.

CON EDISON - VAULT 4680 (Continued) **S120959011**

Location City: BRONX
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004983803
Mailing Name: CON EDISON - VAULT 4680
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q185 **WHITE PLAINS DEPT OF PUBLIC WORKS** **RCRA NonGen / NLR** **1010325206**
NE **255 MAIN ST** **NYN008015984**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.137 mi.
723 ft. **Site 1 of 12 in cluster Q**

Relative: **Higher**
Actual: **219 ft.**

RCRA NonGen / NLR:
Date form received by agency: 03/29/2007
Facility name: WHITE PLAINS DEPT OF PUBLIC WORKS
Facility address: 255 MAIN ST
WHITE PLAINS, NY 10601
EPA ID: NYN008015984
Contact: Not reported
Contact address: MAIN ST
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Land type: Municipal
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **1010325206**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 03/28/2007
Site name: WHITE PLAINS DEPT OF PUBLIC WORKS
Classification: Not a generator, verified

Date form received by agency: 03/28/2007
Site name: WHITE PLAINS DEPT OF PUBLIC WORKS
Classification: Not a generator, verified

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/15/2007
Date achieved compliance: 03/15/2007
Violation lead agency: EPA
Enforcement action: VERBAL INFORMAL
Enforcement action date: 03/15/2007
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 03/15/2007
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/15/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/15/2007
Evaluation lead agency: EPA

Q186 **WHITE PLAINS DEPT OF PUBLIC WORKS** **NY LTANKS** **S105912883**
NE **255 MAIN STREET** **NY MANIFEST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY SPDES**
0.137 mi.
723 ft. **Site 2 of 12 in cluster Q**

Relative:
Higher

Actual:
219 ft.

LTANKS:
Spill Number/Closed Date: 8707220 / 1988-03-14
Facility ID: 8707220
Site ID: 294455
Spill Date: 1987-11-21
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: D3
Cleanup Ceased: 1988-03-14
SWIS: 6017
Investigator: RICCI
Referred To: Not reported
Reported to Dept: 1987-11-21
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

Last Inspection:	1988-03-14
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-27
Spill Record Last Update:	1988-12-05
Spiller Name:	Not reported
Spiller Company:	MR. BROCCHI
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	238304
DEC Memo:	""
Remarks:	"5K TANK SYSTEM -.1255 GPH"

All TTF:

Facility ID:	8707220
Spill Number:	8707220
Spill Tank Test:	1532403
Site ID:	294455
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	294455
Operable Unit ID:	911097
Operable Unit:	01
Material ID:	466187
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYD000877423
Facility Status:	Not reported

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

Location Address 1:	255 MAIN STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD000877423
Mailing Name:	WHITE PLAINS DEPT OF PUBLIC WORKS
Mailing Contact:	DENNIS DEFILLIPIS
Mailing Address 1:	255 MAIN STREET ATTN TOM
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	914429214

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	CT5000001495
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2011
Trans1 Recv Date:	07/07/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/07/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000877423
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CT5000001495
TSDF ID 2:	Not reported
Manifest Tracking Number:	006572842JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H010
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

Waste Code:	Not reported
Quantity:	933.0
Units:	P - Pounds
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Waste Code:	D009
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

SPDES:

Permit Number:	NYR20A230
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported

Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported

Q187 **MUNICIPAL BUILDING** **NY UST** **U003857220**
NE **255 MAIN ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.137 mi.
723 ft. **Site 3 of 12 in cluster Q**

Relative: **Higher**

Actual: **219 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-169552 / Unregulated: <1101 gal. PBS
Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main St
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	25
Status:	4. Closed - in place
Capacity:	4000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	03/01/1988
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Sacrificial Anode (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	25
Status:	3a. Closed - Prior to 04/1991
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

O188 **COMMERCIAL BUSINESS** **NY LTANKS** **S107410444**
South **158 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.138 mi.
730 ft. **Site 3 of 7 in cluster O**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Spill Number/Closed Date:	0413115 / 2005-09-07
Facility ID:	0413115
Site ID:	338963
Spill Date:	2005-03-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-16
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-16
Spill Record Last Update:	2006-02-03
Spiller Name:	DOROTHY FINGAR
Spiller Company:	DOROTHY FINGAR
Spiller Address:	158 GRAND ST.
Spiller County:	001
Spiller Contact:	DOROTHY FINGAR
Spiller Phone:	(914) 949-0308
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	299193
DEC Memo:	"03/18/05 TEMP TANK SET UP BY WILCO FUEL. SAMPLES RESULTS REPORTED TO BE VERY HIGH LEVELS OF CONTAMINATION. jod September 7, 2005: SEE SPILL 05-06649 FOR ALL UPDATE INFORMATION. NFA THIS SPILL NUMBER. jod"
	Not reported
Remarks:	"Tank was supposed to be tested today. However the tank has a hole in it, soil is compacted. samples were tkaen for testing. The old tank was removed and a new one installed, old tank was pumped out. 03/18/05 Tank has NOT been removed yet. jod"

All Materials:

Site ID:	338963
Operable Unit ID:	1100882
Operable Unit:	01
Material ID:	581014
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

COMMERCIAL BUSINESS (Continued) **S107410444**

Spill Number/Closed Date:	0506649 / 2006-02-03
Facility ID:	0506649
Site ID:	351900
Spill Date:	2005-08-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-08-30
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-30
Spill Record Last Update:	2006-02-03
Spiller Name:	MR FINGERMAN
Spiller Company:	COMMERCIAL BUSINESS
Spiller Address:	158 GRANDE STREET
Spiller County:	001
Spiller Contact:	MR FINGERMAN
Spiller Phone:	(914) 949-0308
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	299193
DEC Memo:	"Caller will inform Todd Ghiosay of the DEC. 9/7/05 Also reported as spill 04-13115. jod February 3, 2006: NES DISPOSED OF LUST AND 39.36 TONS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
	Not reported
Remarks:	"HOLES IN TANK: SEVERAL LARGE HOLES;"

All Materials:

Site ID:	351900
Operable Unit ID:	1109401
Operable Unit:	01
Material ID:	2099431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R189
SE
1/8-1/4
0.138 mi.
730 ft.

NICKY'S RESTAURANT
107 MAMARONECK AVE
WHITE PLAINS, NY

Site 1 of 16 in cluster R

NY LTANKS **S100137599**
N/A

Relative:
Higher

Actual:
219 ft.

LTANKS:

Spill Number/Closed Date:	8900599 / 1989-05-03
Facility ID:	8900599
Site ID:	239748
Spill Date:	1989-04-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1989-05-03
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-04-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-04-25
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	NICKY'S RESTAURANT
Spiller Address:	107 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197197
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : LINES WERE CAPPED OFF AND TANK PASSED. "
Remarks:	"2,000 GAL. PETRO-TITE LINE LEAK >10 GPH, EXCAVATE, REPAIR & RETEST DURING TEST PRODUCT ENTERED BASEMENT THRU WELL. WILL CALL BACK WHEN EXCAVATION IS TO BE DONE."

All TTF:

Facility ID:	8900599
Spill Number:	8900599
Spill Tank Test:	1535369
Site ID:	239748
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

NICKY'S RESTAURANT (Continued) **S100137599**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 239748
Operable Unit ID: 926893
Operable Unit: 01
Material ID: 559486
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

S190 **210 MARTINE AVENUE** **NY UST** **U003994254**
East **210 MARTINE AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.139 mi.
733 ft. **Site 1 of 4 in cluster S**

Relative: **Higher**
Actual: **217 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-801056 / Unregulated
Operator Name: Ron Sinclair
Owner Name: WRG Management
Owner Street: Not reported
Owner Address2: Not reported
Owner City: Not reported
Owner State: Not reported
Owner Zipcode: Not reported
GDS Number: Not reported

Tank Number: 001
Status: 4. Closed - in place
Capacity: 5000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 11/16/2005
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on ground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 0. None

Q191 **CON EDISON** **NY MANIFEST** **S117065994**
ENE **218 MAIN ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.141 mi.
744 ft. **Site 4 of 12 in cluster Q**

Relative:
Higher

Actual:
220 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004586020
Facility Status:	Not reported
Location Address 1:	218 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004586020
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/04/2014
Trans1 Recv Date:	07/04/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004586020
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000705939
TSDF ID 2:	Not reported
Manifest Tracking Number:	006466358FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117065994**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H135
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D018
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R192 **DEVON PLAZA REALITY** **NY LTANKS** **S118953811**
SE **109 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.141 mi.
744 ft. **Site 2 of 16 in cluster R**

Relative: **Higher**
Actual: **220 ft.**

LTANKS:

Spill Number/Closed Date:	9512203 / 1995-12-29
Facility ID:	9512203
Site ID:	254450
Spill Date:	1995-12-29
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1995-12-29
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-29
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-29
Spill Record Last Update:	1996-01-22
Spiller Name:	MR MENDOLA
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD

DEVON PLAZA REALITY (Continued) **S118953811**

Spiller County:	001
Spiller Contact:	NONE
Spiller Phone:	(914) 332-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208418
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"customer over ordered driver clean up spill"

All Materials:

Site ID:	254450
Operable Unit ID:	1026423
Operable Unit:	01
Material ID:	359516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

R193 **110-122 MAMARONECK AVENUE, LLC** **NY UST** **U003949264**
SE **110 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.143 mi.
754 ft. **Site 3 of 16 in cluster R**

Relative: **Higher**

Actual: **223 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-074640 / Unregulated: <1101 gal. PBS
Operator Name:	Ramon Lemus
Owner Name:	110 Mamaroneck Avenue, LLC
Owner Street:	237 Mamroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1971
Date Perm Closure:	11/05/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None

110-122 MAMARONECK AVENUE, LLC (Continued) **U003949264**

Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

R194 **SILVERMAN REALITY** **NY LTANKS** **S104950814**
SE **110 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.143 mi.
754 ft. **Site 4 of 16 in cluster R**

Relative: **Higher**
Actual: **223 ft.**

LTANKS:

Spill Number/Closed Date:	0011270 / 2003-01-22
Facility ID:	0011270
Site ID:	308222
Spill Date:	2001-01-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-01-16
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-16
Spill Record Last Update:	2003-01-28
Spiller Name:	UNKNOWN
Spiller Company:	SILVERMAN REALITY
Spiller Address:	110 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	TARRICONE OIL
Spiller Phone:	(914) 693-1132
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	248921
DEC Memo:	""
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION PERFORMED AT REQUEST OF OIL COMPANY. OIL COMPANY HAS BEEN ADVISED OF RESULTS. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	0011270
Spill Number:	0011270
Spill Tank Test:	1526050
Site ID:	308222
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported

SILVERMAN REALITY (Continued) **S104950814**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	308222
Operable Unit ID:	832660
Operable Unit:	01
Material ID:	541592
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q195 **T S T WHITE PLAINS LLC** **NY Spills** **1004760649**
ENE **220 MAIN ST** **RCRA NonGen / NLR** **NYR000054361**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.143 mi.
755 ft. **Site 5 of 12 in cluster Q**

Relative: **Higher**
Actual: **220 ft.**

SPILLS:

Spill Number/Closed Date:	0000781 / 2002-02-27
Facility ID:	0000781
Facility Type:	ER
DER Facility ID:	283327
Site ID:	327322
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6000
Spill Date:	2000-04-19
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-04-19
CID:	397
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-19
Spill Record Last Update:	2002-03-22
Spiller Name:	DEBBIE SMITH

T S T WHITE PLAINS LLC (Continued) **1004760649**

Spiller Company:	ABANDONED MACY'S STORE
Spiller Address:	220 MAIN ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 04/19/2000 BUILDING UNDER DEMOLITION. TANK WAS REMOVED BUT SLUDGE AND PRODUCT REMAIN. F.D. THOUGHT #4 FUEL OIL. SPOKE WITH WCHD. 02/27/2002 S. GOREAU OF THE WCDOH REPORTED THAT AREA IS UNDER LARGE REDEVELOPMENT. ORIGINAL BUILDING HAS BEEN RAZED AND MAJOR EXCAVAATION WORK HAS ALTERED THE PROPERTY. NO FURTHER ACTION."
Remarks:	"FIRE DEPT DOING A WALK THROUGH OF ABANDONED BUILDING DISCOVERED MATERIAL IN THE OIL TANK VAULT ROOM SUBJECT LISTED AS CONTACT FOR SPILLER IS PROERTY MANAGER ALSO SECURITY GUARD ON SITE."

All Materials:

Site ID:	327322
Operable Unit ID:	822544
Operable Unit:	01
Material ID:	289019
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	T S T WHITE PLAINS LLC
Facility address:	220 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYR000054361
Mailing address:	MADISON AVE NEW YORK, NY 10022
Contact:	CHARLES REID
Contact address:	MADISON AVE NEW YORK, NY 10022
Contact country:	US
Contact telephone:	212-715-0300
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	T S T WHITE PLAINS LLC
Owner/operator address:	520 MADISON AVE NEW YORK, NY 10022
Owner/operator country:	US
Owner/operator telephone:	212-715-0300
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

T S T WHITE PLAINS LLC (Continued) **1004760649**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: T S T WHITE PLAINS LLC
Owner/operator address: 520 MADISON AVE
NEW YORK, NY 10022
Owner/operator country: US
Owner/operator telephone: 212-715-0300
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: T S T WHITE PLAINS LLC
Classification: Not a generator, verified

Date form received by agency: 05/04/1998
Site name: T S T WHITE PLAINS LLC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002

T S T WHITE PLAINS LLC (Continued) **1004760649**

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000054361
Facility Status: Not reported
Location Address 1: 220 MAIN ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000054361
Mailing Name: LC WHITE PLAINS LLC
Mailing Contact: LC WHITE PLAINS LLC
Mailing Address 1: 220 MAIN STREET
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 0000000000

NY MANIFEST:
Document ID: NYB7516719
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: E43375MI

T S T WHITE PLAINS LLC (Continued) **1004760649**

Trans2 State ID:	Not reported
Generator Ship Date:	06/08/1998
Trans1 Recv Date:	06/08/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/19/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000054361
Trans1 EPA ID:	MID982606287
Trans2 EPA ID:	Not reported
TSDF ID 1:	GAD093380814
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00110
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	U051 - CREOSOTE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q196 **CIRCUIT CITY STORE #3696** **RCRA-CESQG** **1010325228**
ENE **220 MAIN ST** **FINDS** **NYN008016099**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.143 mi.
755 ft. **Site 6 of 12 in cluster Q**

Relative:
Higher

Actual:
220 ft.

RCRA-CESQG:

Date form received by agency:	04/03/2007
Facility name:	CIRCUIT CITY STORE #3696
Facility address:	220 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYN008016099
Mailing address:	MAIN ST WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	MAIN ST WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/02/2007
Site name:	CIRCUIT CITY STORE #3696

CIRCUIT CITY STORE #3696 (Continued) **1010325228**

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/02/2007
Site name: CIRCUIT CITY STORE #3696
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/15/2007
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

FINDS:

Registry ID: 110004542889

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1010325228
Registry ID: 110004542889
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004542889

O197 **177 GRAND STREET ASSOCIATES, LLC,LLC C/O DELAURENT** **NY UST** **U003994240**
South **177 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.146 mi.
772 ft. **Site 4 of 7 in cluster O**

Relative: **Higher**
Actual: **237 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-049816 / Active
Operator Name: Paul Halmi
Owner Name: 177 Grand St Assoc.
Owner Street: 384 Mamaroneck Avenue
Owner Address2: Not reported
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10605
GDS Number: Not reported

Tank Number: 177
Status: 1. In-Service
Capacity: 2000
Product Stored: 0002. #4 Fuel Oil

177 GRAND STREET ASSOCIATES, LLC,LLC C/O DELAURENT (Continued) **U003994240**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

O198 **177 GRAND STREET ASSOC LLC** **RCRA NonGen / NLR** **1001233223**
South **177 GRAND ST** **FINDS** **NYR000063727**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.146 mi. **NY MANIFEST**
772 ft. **Site 5 of 7 in cluster O**

Relative: **Higher**
Actual: **237 ft.**

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	177 GRAND STREET ASSOC LLC
Facility address:	177 GRAND ST WHITE PLAINS, NY 10601
EPA ID:	NYR000063727
Mailing address:	PO BOX 310 WHITE PLAINS, NY 10605
Contact:	EDMOND DELAURENTIS
Contact address:	PO BOX 310 WHITE PLAINS, NY 10605
Contact country:	US
Contact telephone:	914-946-1321
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	177 GRAND STREET ASSOC
Owner/operator address:	PO BOX 310 WHITE PLAINS, NY 10605
Owner/operator country:	US
Owner/operator telephone:	914-946-1321
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	177 GRAND STREET ASSOC
Owner/operator address:	PO BOX 310

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

WHITE PLAINS, NY 10605
Owner/operator country: US
Owner/operator telephone: 914-946-1321
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: 177 GRAND STREET ASSOC LLC
Classification: Not a generator, verified

Date form received by agency: 11/23/1998
Site name: 177 GRAND STREET ASSOC LLC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

FINDS:

Registry ID: 110004548927

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001233223
Registry ID:	110004548927
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004548927

NY MANIFEST:

Country:	USA
EPA ID:	NYR000063727
Facility Status:	Not reported
Location Address 1:	177 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10605
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000063727
Mailing Name:	WEST CHESTER HOBBIE
Mailing Contact:	MARGARET HOFFMAN
Mailing Address 1:	177 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10605
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146828236

NY MANIFEST:

Document ID:	PAG0327353
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	PAAH0146
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/1998
Trans1 Recv Date:	12/01/1998

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/02/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000063727
Trans1 EPA ID:	PAD067098822
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

O199 **150 GRAND STREET OFFICE BUILDING** **NY UST** **U003856437**
South **150 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.150 mi.
793 ft. **Site 6 of 7 in cluster O**

Relative:
Higher

Actual:
233 ft.

WESTCHESTER CO. UST:

Id/Status:	3-176885 / Administratively Closed
Operator Name:	Tony Spagnoli
Owner Name:	Grand Realty Co
Owner Street:	110 Corporate Park Drive
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1960
Date Perm Closure:	06/23/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1962
Date Perm Closure:	08/22/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

O200 **OFFICE BLDG BASEMENT** **NY LTANKS** **S102674993**
South **150 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.150 mi.
793 ft. **Site 7 of 7 in cluster O**

Relative:
Higher

Actual:
233 ft.

LTANKS:

Spill Number/Closed Date:	8908740 / 1990-02-07
Facility ID:	8908740
Site ID:	307349
Spill Date:	1989-12-05
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1990-02-07
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1989-12-08
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-12-07
Spill Record Last Update:	2003-10-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	248205
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/07/90: SPILL CLEANED UP BY A.L. EASTMAN . WCHD MONITORED CLEANUP. "
Remarks:	"FUEL SUPPLIER PAC-PETRO/PURE ENERGY GROUP(212-842-1100)CONTRACT HAULERM.B.TRUCKING(212-328-3275) AL EASTMAN IS CLEANUP CONTRACTOR T. GHIOSAYTO LOOK AT"

All Materials:

Site ID:	307349
Operable Unit ID:	933790
Operable Unit:	01
Material ID:	441928
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

T201 **SPILL NUMBER 8809894** **NY LTANKS** **S104619049**
ESE **23 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.154 mi.
813 ft. **Site 1 of 7 in cluster T**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	8809894 / 1991-12-20
Facility ID:	8809894
Site ID:	286069
Spill Date:	1989-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-03-28
Spill Record Last Update:	2003-09-19
Spiller Name:	Not reported
Spiller Company:	SEA MGT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231859
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PLUMBING LEAKED DURING FILLING FOR TEST. TO ISOLATE, EXCAVATE AND RETEST."

All TTF:

Facility ID:	8809894
Spill Number:	8809894
Spill Tank Test:	1535281
Site ID:	286069
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

SPILL NUMBER 8809894 (Continued) **S104619049**

Last Modified Date: Not reported

All Materials:
Site ID: 286069
Operable Unit ID: 926206
Operable Unit: 01
Material ID: 451068
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

T202 **SEA MANAGEMENT** **NY UST** **U003885123**
ESE **23 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.154 mi.
813 ft. **Site 2 of 7 in cluster T**

Relative: **Higher**
Actual: **218 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-600172 / Unregulated: <1101 gal. PBS
Operator Name: Grace
Owner Name: Sea Management
Owner Street: 199 Main Street
Owner Address2: Not reported
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10601
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 2500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 12/01/1991
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Secondary Containment: 0. None
Piping Location: 3. Aboveground/underground combination
Piping Type: 0. No Pippping
Piping External Protection: 0. None
Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

R203 **PER-BAR** **NY LTANKS** **S100140366**
SE **124 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.154 mi.
814 ft. **Site 5 of 16 in cluster R**

Relative:
Higher

Actual:
223 ft.

LTANKS:

Spill Number/Closed Date:	8802839 / 1989-01-18
Facility ID:	8802839
Site ID:	116904
Spill Date:	1988-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-01-18
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-23
Spill Record Last Update:	1989-02-07
Spiller Name:	Not reported
Spiller Company:	BRIAN COMI
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	101701
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"FAILED WITH GROSS LEAK. PBS TO FOLLOW.RETEST NEEDED."

All TTF:

Facility ID:	8802839
Spill Number:	8802839
Spill Tank Test:	1534211
Site ID:	116904
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

PER-BAR (Continued) **S100140366**

All Materials:
Site ID: 116904
Operable Unit ID: 918126
Operable Unit: 01
Material ID: 458404
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Q204 **TARGET STORE T1358** **RCRA-LQG** **1008404423**
ENE **9 CITY PL** **FINDS** **NYR000134106**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.157 mi. **NY MANIFEST**
830 ft. **Site 7 of 12 in cluster Q**

Relative: **Higher**
Actual: **221 ft.**

RCRA-LQG:
Date form received by agency: 02/19/2016
Facility name: TARGET STORE T1358
Facility address: 9 CITY PL
WHITE PLAINS, NY 10601
EPA ID: NYR000134106
Mailing address: PO BOX 111
MINNEAPOLIS, MN 55440
Contact: STEVE MUSSER
Contact address: PO BOX 111
MINNEAPOLIS, MN 55440
Contact country: US
Contact telephone: 800-587-2228
Contact email: POC@TARGET.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:
Owner/operator name: TARGET CORPORATION
Owner/operator address: NICOLLET MALL - TPN-725
MINNEAPOLIS, MN 55403
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported

TARGET STORE T1358 (Continued) **1008404423**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/08/2003
Owner/Op end date: Not reported

Owner/operator name: TARGET CORP
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/08/2003
Owner/Op end date: Not reported

Owner/operator name: TARGET CORP
Owner/operator address: PO BOX 111
MINNEAPOLIS, MN 55440
Owner/operator country: US
Owner/operator telephone: 800-587-2228
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/08/2003
Owner/Op end date: Not reported

Owner/operator name: TARGET CORPORATION
Owner/operator address: PO BOX 111
MINNEAPOLIS, MN 55440
Owner/operator country: US
Owner/operator telephone: 800-587-2228
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 10/08/2003
Owner/Op end date: Not reported

Owner/operator name: NO NAME FOUND
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/08/2003

TARGET STORE T1358 (Continued) **1008404423**

Owner/Op end date: Not reported

Owner/operator name: TARGET CORPORATION
Owner/operator address: PO BOX 111
MINNEAPOLIS, MN 55440
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/08/2003
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006

TARGET STORE T1358 (Continued) **1008404423**

. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U154
. Waste name: METHANOL (I)

Historical Generators:
Date form received by agency: 02/14/2014
Site name: TARGET STORE T1358
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

TARGET STORE T1358 (Continued) **1008404423**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D028
. Waste name: 1,2-DICHLOROETHANE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001

TARGET STORE T1358 (Continued) **1008404423**

. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

Date form received by agency: 02/22/2012
Site name: TARGET STORE #T1358
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

TARGET STORE T1358 (Continued) **1008404423**

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P046
. Waste name: BENZENEETHANAMINE, ALPHA,ALPHA-DIMETHYL-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P081
. Waste name: NITROGLYCERINE (R)

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U044
. Waste name: CHLOROFORM

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

TARGET STORE T1358 (Continued) **1008404423**

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Date form received by agency: 01/01/2007
Site name: TARGET #1358
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: TARGET #1358
Classification: Not a generator, verified

Date form received by agency: 08/02/2005
Site name: TARGET #1358
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D011
. Waste name: SILVER

TARGET STORE T1358 (Continued) **1008404423**

Biennial Reports:

Last Biennial Reporting Year: 2017

Annual Waste Handled:

Waste code:	D001
Waste name:	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
Amount (Lbs):	2001
Waste code:	D002
Waste name:	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
Amount (Lbs):	706
Waste code:	D004
Waste name:	ARSENIC
Amount (Lbs):	16
Waste code:	D005
Waste name:	BARIUM
Amount (Lbs):	1278
Waste code:	D006
Waste name:	CADMIUM
Amount (Lbs):	283
Waste code:	D007
Waste name:	CHROMIUM
Amount (Lbs):	1278
Waste code:	D008
Waste name:	LEAD
Amount (Lbs):	294
Waste code:	D009
Waste name:	MERCURY
Amount (Lbs):	135
Waste code:	D010
Waste name:	SELENIUM
Amount (Lbs):	16
Waste code:	D011
Waste name:	SILVER
Amount (Lbs):	1278
Waste code:	D016

TARGET STORE T1358 (Continued) **1008404423**

Waste name: 2,4-D
Amount (Lbs): 16

Waste code: D018
Waste name: BENZENE
Amount (Lbs): 979

Waste code: D024
Waste name: M-CRESOL
Amount (Lbs): 16

Waste code: D026
Waste name: CRESOL
Amount (Lbs): 16

Waste code: D035
Waste name: METHYL ETHYL KETONE
Amount (Lbs): 1692

Waste code: P001
Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Amount (Lbs): 35

Waste code: P075
Waste name: NICOTINE, & SALTS
Amount (Lbs): 35

Waste code: U002
Waste name: ACETONE (I)
Amount (Lbs): 979

Waste code: U035
Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-
Amount (Lbs): 16

Waste code: U154
Waste name: METHANOL (I)
Amount (Lbs): 979

Violation Status: No violations found

FINDS:

Registry ID: 110022819048

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

TARGET STORE T1358 (Continued) **1008404423**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1008404423
Registry ID:	110022819048
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110022819048

NY MANIFEST:

Country:	USA
EPA ID:	NYR000134106
Facility Status:	Not reported
Location Address 1:	9 CITY PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000134106
Mailing Name:	TARGET 1358
Mailing Contact:	MICHAEL DAVILA
Mailing Address 1:	P O BOX 111
Mailing Address 2:	Not reported
Mailing City:	MINNEAPOLIS
Mailing State:	MN
Mailing Zip:	55440
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9148210012

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAD039322250
Trans2 State ID:	ALD067138891
Generator Ship Date:	06/05/2018
Trans1 Recv Date:	06/05/2018
Trans2 Recv Date:	06/06/2018
TSD Site Recv Date:	06/11/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000134106
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD000648451
TSDF ID 2:	Not reported
Manifest Tracking Number:	011922625FLE
Import Indicator:	N
Export Indicator:	N

TARGET STORE T1358 (Continued) **1008404423**

Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	8
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D002
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
90 additional NY MANIFEST: record(s) in the EDR Site Report.

T205 **SPILL NUMBER 9905959** **NY LTANKS** **S104620381**
ESE **25 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.158 mi.
836 ft. **Site 3 of 7 in cluster T**

Relative: LTANKS:
Higher

Actual:
218 ft.

Spill Number/Closed Date:	9905959 / 1999-10-08
Facility ID:	9905959
Site ID:	111332
Spill Date:	1999-08-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-08-18
CID:	388
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

SPILL NUMBER 9905959 (Continued) **S104620381**

Remediation Phase:	0
Date Entered In Computer:	1999-08-18
Spill Record Last Update:	1999-10-27
Spiller Name:	JAMES MA
Spiller Company:	W P M V INC
Spiller Address:	200 E 61ST ST SUITE 4G
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(914) 472-8779
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97378
DEC Memo:	""
Remarks:	"caller reports they went to clean tank and they saw holes in the tank."

All Materials:

Site ID:	111332
Operable Unit ID:	1084404
Operable Unit:	01
Material ID:	553103
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R206 **CON EDISON** **RCRA NonGen / NLR** **1019905154**
SE **134 MAMARONECK AVE** **NYP004806469**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.158 mi.
836 ft. **Site 6 of 16 in cluster R**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/14/2015
Facility name:	CON EDISON
Facility address:	134 MAMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004806469
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON (Continued) **1019905154**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/14/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

R207 **CON EDISON** **NY Spills** **S102155749**
SE **134 MAMARONECK AVE** **NY MANIFEST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.158 mi.
836 ft. **Site 7 of 16 in cluster R**

Relative: **Higher**
Actual: **226 ft.**

SPILLS:

Spill Number/Closed Date:	1213452 / 2013-01-02
Facility ID:	1213452
Facility Type:	ER
DER Facility ID:	431971
Site ID:	476637
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2012-12-12
Investigator:	jbodee
Referred To:	WCHD
Reported to Dept:	2012-12-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-12
Spill Record Last Update:	2013-01-02
Spiller Name:	MR FRANK
Spiller Company:	M AND T BANK
Spiller Address:	134 MAMMORONECK AVE
Spiller Company:	999
Contact Name:	MR FRANK

CON EDISON (Continued) **S102155749**

DEC Memo: "12/12/12- WCHD reports they are responding. Update from WCHD- Joe Mancini. Curb fill pipe to vaulted tank in basement is leaking near wall. Some oil onto wall and floor from delivery today. WCHD reports that minimal odors noted at this time. MT Bank to retain cleanup contractor to complete cleanup and conduct repairs. WCHD to followup. DT"
Remarks: "broken pipe under sidewalk, c/u pending"

All Materials:
Site ID: 476637
Operable Unit ID: 1226463
Operable Unit: 01
Material ID: 2223728
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Spill Number/Closed Date: 9509489 / 1997-12-04
Facility ID: 9509489
Facility Type: ER
DER Facility ID: 256859
Site ID: 318648
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6017
Spill Date: 1995-11-01
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1995-11-01
CID: 266
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1995-11-01
Spill Record Last Update: 1997-12-04
Spiller Name: JOE TATARKA
Spiller Company: GREEN POINT SAVINGS BANK
Spiller Address: 134 MAMARONECK AVENUE
Spiller Company: 001
Contact Name: JOE TATARKA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "FILL PIPE ROTTED OUT. ONTO SOIL & BLACKTOP. NO FURTHER DELIVERIES UNTIL FILL IS REPAIRED. SOIL REMOVED & FUEL CLEANED UP."

CON EDISON (Continued) **S102155749**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004806469
Facility Status:	Not reported
Location Address 1:	134 MAMARONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004806469
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/2015
Trans1 Recv Date:	07/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004806469
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469294JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON (Continued) **S102155749**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R208 **CON EDISON** **NY MANIFEST** **S119076412**
SE **134 MAMARANECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.158 mi.
836 ft. **Site 8 of 16 in cluster R**

Relative:
Higher

Actual:
226 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004805065
Facility Status:	Not reported
Location Address 1:	134 MAMARONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004805065
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported

CON EDISON (Continued) **S119076412**

Year:	2015
Trans1 State ID:	NYD006932359
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2015
Trans1 Recv Date:	07/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004805065
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469265JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R209 **CON EDISON** **RCRA NonGen / NLR** **1019905036**
SE **134 MAMARANECK AVE** **FINDS** **NYP004805065**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.158 mi.
836 ft. **Site 9 of 16 in cluster R**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/10/2015
Facility name:	CON EDISON
Facility address:	134 MAMARANECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004805065
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/10/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069667104

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CON EDISON (Continued) **1019905036**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019905036
Registry ID: 110069667104
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069667104

R210 **M AND T BANK** **NY AST** **A100096027**
SE **134 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.158 mi.
836 ft. **Site 10 of 16 in cluster R**

Relative:
Higher

Actual:
226 ft.

WESTCHESTER CO. AST:
PBS Number: 3-601013
Site Status: Unregulated
GDS Number: Not reported
Operator Name: unknown
Owner Name: Keating Charitable Remainder Unitrust
Owner Street: P.O. Box 5438
Owner Address2: Not reported
Owner City/State/Zip: Hanover, NH 03755

Tank Number: 1
Status: 3. Closed - Removed
Date Installation: 06/01/1974
Capacity: 2000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Date Perm Closure: 04/26/2018
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 2. Suction

U211 **CON EDISON** **RCRA NonGen / NLR** **1014398867**
West **81 MAIN ST FRONT OF** **NJ MANIFEST** **NYP004212403**
1/8-1/4 **WHITE PLAINS, NY 10603** **NY MANIFEST**
0.159 mi.
840 ft. **Site 1 of 6 in cluster U**

Relative:
Lower

Actual:
200 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/29/2010
Facility name:	CON EDISON
Facility address:	81 MAIN ST FRONT OF WHITE PLAINS, NY 10603
EPA ID:	NYP004212403
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS ROHRER
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004212403
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DENNIS ROHRER
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **1014398867**

Date Change:	Not reported

Manifest:

Manifest Number:	006874670JJK
EPA ID:	NYP004212403
Date Shipped:	07/29/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/29/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/29/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004212403
Facility Status:	Not reported
Location Address 1:	MH10094 - F/O 81 MAIN ST LEXINGTON AVE

CON EDISON (Continued) **1014398867**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004212403
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2010
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/29/2010
Trans1 Recv Date: 07/29/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/29/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004212403
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 006874670JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H111
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1014398867**

Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

S212 **28 MITCHELL PLACE INC.** **NY UST** **U003949291**
ESE **28 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.160 mi.
846 ft. **Site 2 of 4 in cluster S**

Relative: WESTCHESTER CO. UST:
Higher

Id/Status:	3-600900 / Unregulated: <1101 gal. PBS
Operator Name:	John Pelada
Owner Name:	28 Mitchell Place Inc.
Owner Street:	P.O. Box 8
Owner Address2:	Not reported
Owner City:	Hartsdale
Owner State:	NY
Owner Zipcode:	10530
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/01/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	3. Gravity

Actual:
218 ft.

S213 **28 MITCHELL PLACE** **NY LTANKS** **U003647993**
ESE **28 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.160 mi.
846 ft. **Site 3 of 4 in cluster S**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	9901259 / 1999-05-13
Facility ID:	9901259
Site ID:	206822
Spill Date:	1999-05-03
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-05-03
CID:	382
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-05-03
Spill Record Last Update:	1999-07-25
Spiller Name:	PHILLIPS
Spiller Company:	Not reported
Spiller Address:	28 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	PHILLIPS
Spiller Phone:	(914) 472-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	171695
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 5/13/99 TANK PASSED ISOLATION RETEST. LINES TO BE REPLACED. NFA"
	Not reported
Remarks:	"SYSTEM FAILURE. OWNER WAS ADVISED."

All TTF:

Facility ID:	9901259
Spill Number:	9901259
Spill Tank Test:	1547140
Site ID:	206822
Tank Number:	Not reported
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills

28 MITCHELL PLACE (Continued) **U003647993**

Last Modified Date: Not reported

All Materials:
Site ID: 206822
Operable Unit ID: 1079959
Operable Unit: 01
Material ID: 304805
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 9903630 / 2001-11-14
Facility ID: 9903630
Site ID: 206823
Spill Date: 1999-06-29
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: B4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1999-06-29
CID: 388
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-06-29
Spill Record Last Update: 2003-06-02
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: MMP DEVELOPMENT
Spiller Phone: (914) 725-6858
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 171695
DEC Memo: ""
Remarks: "CALLER REPORTS PULLING TANK AND THE TANK WAS LEAKING."

All Materials:
Site ID: 206823
Operable Unit ID: 1082559
Operable Unit: 01
Material ID: 303542
Material Code: 0001A

28 MITCHELL PLACE (Continued) **U003647993**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q214 **CON EDISON** **NY MANIFEST** **S118088159**
ENE **MAIN ST & CITY PL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.161 mi.
850 ft. **Site 8 of 12 in cluster Q**

Relative:
Higher

Actual:
222 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004757043
Facility Status:	Not reported
Location Address 1:	MAIN ST & CITY PL
Code:	BP
Location Address 2:	MH 1433
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004757043
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/24/2015
Trans1 Recv Date:	03/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004757043
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046

CON EDISON (Continued) **S118088159**

TSDF ID 2:	Not reported
Manifest Tracking Number:	014091149JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q215 **CON EDISON MANHOLE** **RCRA NonGen / NLR** **1014398753**
ENE **MAIN ST & CITY PL** **NJ MANIFEST** **NYP004211173**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.161 mi.
850 ft. **Site 9 of 12 in cluster Q**

Relative: **Higher**

Actual: **222 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/12/2010
Facility name:	CON EDISON MANHOLE
Facility address:	MAIN ST & CITY PL WHITE PLAINS, NY 10601
EPA ID:	NYP004211173
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DANIEL PONTECORVO
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	347-203-2573
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE (Continued) **1014398753**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 07/12/2010
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004211173
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DANIEL PONTECORVO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003533276JJK
EPA ID: NYP004211173
Date Shipped: 07/12/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported

CON EDISON MANHOLE (Continued) **1014398753**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/12/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/12/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	200 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004211173
Facility Status:	Not reported
Location Address 1:	TM03263 - CITY PL & MAIN
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004211173
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING
Mailing Address 1:	4 IRVING PL - RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON MANHOLE (Continued) **1014398753**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/12/2010
Trans1 Recv Date:	07/12/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/12/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004211173
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003533276JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON MANHOLE (Continued) **1014398753**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q216 **CON EDISON** **NJ MANIFEST** **S120669520**
ENE **MAIN ST & CITY PL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.161 mi.
850 ft. **Site 10 of 12 in cluster Q**

Relative:
Higher

Actual:
222 ft.

NJ MANIFEST:

EPA Id:	NYP004757043
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091149JJK
EPA ID:	NYP004757043
Date Shipped:	3/24/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S120669520**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q217 **CON EDISON SERVICE BOX: 1431** **RCRA NonGen / NLR** **1016972522**
ENE **MAIN ST & CITY PL** **NY MANIFEST** **NYP004462990**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.161 mi.
850 ft. **Site 11 of 12 in cluster Q**

Relative:
Higher

Actual:
222 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/11/2014
Facility name:	CON EDISON SERVICE BOX: 1431
Facility address:	MAIN ST & CITY PL
	WHITE PLAINS, NY 10602
EPA ID:	NYP004462990
Mailing address:	IRVING PL, 15TH FL NE
	NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported
	Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/11/2014
Site name:	CON EDISON SERVICE BOX: 1431

CON EDISON SERVICE BOX: 1431 (Continued) **1016972522**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004462990
Facility Status: Not reported
Location Address 1: MAIN ST AND CITY PL
Code: BP
Location Address 2: SB 1431
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004462990
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 03/11/2014
Trans1 Recv Date: 03/11/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 03/13/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004462990
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011695240JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported

CON EDISON SERVICE BOX: 1431 (Continued) **1016972522**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Q218 **CON EDISON** **RCRA NonGen / NLR** **1018280798**
ENE **MAIN ST & CITY PL** **FINDS** **NYP004757043**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.161 mi.
850 ft. **Site 12 of 12 in cluster Q**

Relative: **Higher**

Actual: **222 ft.**

RCRA NonGen / NLR:

Date form received by agency:	03/24/2015
Facility name:	CON EDISON
Facility address:	MAIN ST & CITY PL WHITE PLAINS, NY 10601
EPA ID:	NYP004757043
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

CON EDISON (Continued) **1018280798**

Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	03/24/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator
Violation Status:	No violations found

FINDS:

Registry ID: 110067682154

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280798
Registry ID:	110067682154
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067682154

R219 **CON EDISON** **RCRA NonGen / NLR** **1019908523**
SE **128 MAMARONECK AVE** **FINDS** **NYP004846877**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.162 mi.
853 ft. **Site 11 of 16 in cluster R**

Relative:
Higher

Actual:
224 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/01/2015
Facility name:	CON EDISON
Facility address:	128 MAMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004846877
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported

CON EDISON (Continued) **1019908523**

EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/01/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069676185

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019908523
Registry ID: 110069676185
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069676185

R220
SE
1/8-1/4
0.162 mi.
853 ft.

CON EDISON
128 MAMARONECK AVE
WHITE PLAINS, NY 10601

Site 12 of 16 in cluster R

NY MANIFEST **S119078146**
N/A

Relative:
Higher

Actual:
224 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004846877
Facility Status:	Not reported
Location Address 1:	128 MAMORONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004846877
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/2015
Trans1 Recv Date:	10/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004846877
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460357JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S119078146**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

R221 **CON EDISON** **NJ MANIFEST** **S120677447**
SE **128 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.162 mi.
853 ft. **Site 13 of 16 in cluster R**

Relative: **Higher**
Actual: **224 ft.**

NJ MANIFEST:

EPA Id:	NYP004846877
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460357JJK
EPA ID:	NYP004846877
Date Shipped:	10/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120677447**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

---

222 North 1/8-1/4 0.165 mi. 871 ft.

MCI DBA VERIZON BUSINESS
95 CHURCH STREET
WHITE PLAINS, NY 10601

NY UST **U003885496**
N/A

Relative: Higher

Actual: 217 ft.

WESTCHESTER CO. UST:

Id/Status:	3-259233 / Unregulated
Operator Name:	MCI dba Verizon Business
Owner Name:	MCI dba Verizon Business
Owner Street:	2400 N. Glenville Drive
Owner Address2:	Not reported
Owner City:	Richardson
Owner State:	TX
Owner Zipcode:	75082
GDS Number:	Not reported
Tank Number:	001
Status:	0. Administratively closed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported

MCI DBA VERIZON BUSINESS (Continued) **U003885496**

Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	12/29/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	12/29/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	05/01/1987
Date Perm Closure:	06/10/2013
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	plastic & copper
Piping External Protection:	0. None
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None

MCI DBA VERIZON BUSINESS (Continued) **U003885496**

Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

S223 **SPILL NUMBER 0108164** **NY LTANKS** **S105230064**
ESE **32 MITCHELL PL** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.169 mi.
893 ft. **Site 4 of 4 in cluster S**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	0108164 / 2002-07-22
Facility ID:	0108164
Site ID:	255456
Spill Date:	2001-11-12
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-11-12
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-11-12
Spill Record Last Update:	2002-07-24
Spiller Name:	MITCH
Spiller Company:	M AND T DEVELOPEMENT
Spiller Address:	32 MITCHELL PL
Spiller County:	001
Spiller Contact:	MITCH
Spiller Phone:	(914) 472-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 07/22/02 - NORTHEAST DISPOSED OF TANK AND 15.67 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"contaminated soil discovered from tank removal"

All Materials:

Site ID:	255456
Operable Unit ID:	845393
Operable Unit:	01
Material ID:	529414
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 0108164 (Continued) **S105230064**

Oxygenate:	Not reported
Spill Number/Closed Date:	9611678 / 1996-12-24
Facility ID:	9611678
Site ID:	255457
Spill Date:	1996-12-24
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-24
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-24
Spill Record Last Update:	1997-01-14
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MITCHELL SAUNDERS
Spiller Phone:	(914) 421-1742
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/24/96 SPILL CONTAINED ON BLACKTOP WITH SPEEDI-DRI; CLEAN UP COMPLETE. "
Remarks:	"DRIVER OVERFILLED THE TANK - SUPPOSEDLY NO VENT ALARM"

All Materials:

Site ID:	255457
Operable Unit ID:	1043016
Operable Unit:	01
Material ID:	340329
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	18.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Spill Number/Closed Date:	9611679 / 1997-11-10
Facility ID:	9611679
Site ID:	255458
Spill Date:	1996-12-24

SPILL NUMBER 0108164 (Continued) **S105230064**

Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-24
CID:	323
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-24
Spill Record Last Update:	1997-12-10
Spiller Name:	Not reported
Spiller Company:	OIL COMPANY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BOB LYONS
Spiller Phone:	(914) 422-6333
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	276053
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FD ON SCENE CLEANING UP SPILL."

All Materials:

Site ID:	255458
Operable Unit ID:	1043017
Operable Unit:	01
Material ID:	569601
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

R224 **CON EDISON** **NJ MANIFEST** **S120673731**
SE **134 MAMARANECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.171 mi.
905 ft. **Site 14 of 16 in cluster R**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYP004805065
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported

Actual:
224 ft.

CON EDISON (Continued) **S120673731**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469265JJK
EPA ID:	NYP004805065
Date Shipped:	7/10/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R225
SE
1/8-1/4
0.171 mi.
905 ft.

CON EDISON
134 MAMARONECK AVE
WHITE PLAINS, NY 10601

Site 15 of 16 in cluster R

NJ MANIFEST **S120673858**
N/A

Relative:
Higher

Actual:
224 ft.

NJ MANIFEST:

EPA Id:	NYP004806469
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469294JJK
EPA ID:	NYP004806469
Date Shipped:	7/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673858**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

V226 **SLATER NEIGHBORHOOD CTR** **NY UST** **U003857917**
South **2 FISHER COURT** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.172 mi.
907 ft. **Site 1 of 6 in cluster V**

Relative: WESTCHESTER CO. UST:
Lower

Actual: Id/Status:	3-169560 / Unregulated: <1101 gal. PBS
208 ft. Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main St
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	26
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	12/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

V227 **SLADER NEIGHBORHOOD CNTR** **NY LTANKS** **S103558463**
South **2 FISHER CT** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.172 mi.
907 ft. **Site 2 of 6 in cluster V**

Relative: LTANKS:
Lower

Actual: Spill Number/Closed Date:	9810451 / 2003-12-05
208 ft. Facility ID:	9810451
Site ID:	214463

SLADER NEIGHBORHOOD CNTR (Continued) **S103558463**

Spill Date:	1998-11-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-18
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-18
Spill Record Last Update:	2003-12-05
Spiller Name:	MARK
Spiller Company:	SLADER NEIGHBORHOOD CNTR
Spiller Address:	2 FISHER CT
Spiller County:	001
Spiller Contact:	MARK
Spiller Phone:	(914) 328-6549
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177699
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - GOREAU 12/05/03 CLOSED BY STEFAN GOREAU OF WCHD. TANK AND SOIL REMOVED BY ROYAL ENVIRO."
Remarks:	"During tank removal caller found contaminated soil from a hole in tank. 12/11/98 Awaiting closure report. "

All Materials:

Site ID:	214463
Operable Unit ID:	1071357
Operable Unit:	01
Material ID:	314318
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R228 **CON EDISON SERVICE BOX: 1810** **RCRA NonGen / NLR** **1016963902**
SE **133 MAMARONECK AVE IN FRONT OF** **NY MANIFEST** **NYP004368668**
1/8-1/4 **WHITE PLAINS, NY 10610**
0.175 mi.
922 ft. **Site 16 of 16 in cluster R**

Relative:
Higher

Actual:
223 ft.

RCRA NonGen / NLR:

Date form received by agency:	11/01/2013
Facility name:	CON EDISON SERVICE BOX: 1810
Facility address:	133 MAMARONECK AVE IN FRONT OF WHITE PLAINS, NY 10610
EPA ID:	NYP004368668
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	10/01/2013
Site name:	CON EDISON SERVICE BOX: 1810
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004368668
Facility Status:	Not reported
Location Address 1:	MAMARONECK AVE & MAMARONECK PL
Code:	BP
Location Address 2:	SB 1810
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004368668
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/01/2013
Trans1 Recv Date: 10/01/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004368668
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694655JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 100
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V229 **CON EDISON** **RCRA NonGen / NLR** **1019906748**
South **GROVE ST & FISCHER COURT** **FINDS** **NYP004825978**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.175 mi.
922 ft. **Site 3 of 6 in cluster V**

Relative: **Lower**
Actual: **210 ft.**

RCRA NonGen / NLR:

Date form received by agency:	08/19/2015
Facility name:	CON EDISON
Facility address:	GROVE ST & FISCHER COURT WHITE PLAINS, NY 10601
EPA ID:	NYP004825978
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/19/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

CON EDISON (Continued) **1019906748**

Violation Status: No violations found

FINDS:

Registry ID: 110069671554

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019906748
Registry ID: 110069671554
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069671554

V230 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823865**
South **GROVE & FISHER** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.175 mi.
922 ft. **Site 4 of 6 in cluster V**

Relative:
Lower

Actual:
210 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004228116
Facility Status: Not reported
Location Address 1: GROVE & FISHER
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004228116
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported

CONSOLIDATED EDISON (Continued) **S110823865**

seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2011
Trans1 Recv Date:	02/17/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004228116
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007660025JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V231 **CON EDISON SERVICE BOX: 11370** **RCRA NonGen / NLR** **1016969239**
South **GROVE ST & FISCHER AVE** **NY MANIFEST** **NYP004428926**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.175 mi.
922 ft. **Site 5 of 6 in cluster V**

Relative:
Lower

Actual:
210 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/28/2014
Facility name:	CON EDISON SERVICE BOX: 11370
Facility address:	GROVE ST & FISCHER AVE WHITE PLAINS, NY 10602
EPA ID:	NYP004428926
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/29/2014
Site name:	CON EDISON SERVICE BOX: 11370
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004428926
Facility Status:	Not reported
Location Address 1:	GROVE & FISHER
Code:	BP
Location Address 2:	SERVICE BOX # 11370
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004428926
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/29/2014
Trans1 Recv Date: 01/29/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/31/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004428926
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011692778JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 20
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

V232 **CON EDISON** **NJ MANIFEST** **S120675553**
South **GROVE ST & FISCHER COURT** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.175 mi.
922 ft. **Site 6 of 6 in cluster V**

Relative: **Lower**
Actual: **210 ft.**

NJ MANIFEST:

EPA Id:	NYP004825978
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014472095JJK
EPA ID:	NYP004825978
Date Shipped:	8/19/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

CON EDISON (Continued) **S120675553**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

T233 **BARGAM HOME** **NY LTANKS** **S106972377**
East **36-38 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.178 mi.
940 ft. **Site 4 of 7 in cluster T**

Relative: **Higher**
Actual: **218 ft.**

LTANKS:

Spill Number/Closed Date:	0505320 / 2005-12-18
Facility ID:	0505320
Site ID:	350305
Spill Date:	2005-08-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-01
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-01
Spill Record Last Update:	2005-12-18
Spiller Name:	GILL BARGAM
Spiller Company:	BARGAM HOME
Spiller Address:	36-38 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	GILL BARGAM
Spiller Phone:	(914) 310-1500
Spiller Extention:	Not reported
DEC Region:	3

BARGAM HOME (Continued) **S106972377**

DER Facility ID: 296750
DEC Memo: "Have ok to finish job. December 18, 2005: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 19.56 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: " HOLES IN 1000 GALLON TANK, AND SOME CONTAMINATION IN SOIL; "

All Materials:
Site ID: 350305
Operable Unit ID: 1107882
Operable Unit: 01
Material ID: 2097770
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

W234 **RECKSON METRO CENTER** **NY AST 1007796644**
NNE **360 HAMILTON AVE** **US AIRS N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.179 mi.
943 ft. **Site 1 of 10 in cluster W**

Relative:
Higher

Actual:
228 ft.

WESTCHESTER CO. AST:
PBS Number: 3-177342
Site Status: Active
GDS Number: Not reported
Operator Name: David Valentine
Owner Name: 360 Hamilton LLC
Owner Street: 4 International Drive
Owner Address2: Not reported
Owner City/State/Zip: Rye Brook, NY 10573

Tank Number: 001
Status: 1. In-Service
Date Installation: 01/01/1974
Capacity: 5000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1995
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 1. Aboveground
Piping Type: 5. Steel encassed in concrete
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None
Piping Secondary Containment: 0. None
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin

RECKSON METRO CENTER (Continued) **1007796644**

Dispenser:	2. Suction

Tank Number:	002
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	5. Steel encassed in concrete
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	003
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	5. Steel encassed in concrete
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	004
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1995
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle

RECKSON METRO CENTER (Continued) **1007796644**

Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	5. Steel encassed in concrete
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	005
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	275
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	12. Double-Walled (Aboveground Only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	006
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	275
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	12. Double-Walled (Aboveground Only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)

RECKSON METRO CENTER (Continued) **1007796644**

Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	007
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	250
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	008
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	25
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	0. None
Dispenser:	3. Gravity

Tank Number:	009
Status:	1. In-Service
Date Installation:	01/01/1974
Capacity:	88
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900

RECKSON METRO CENTER (Continued) **1007796644**

Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	5. Jacketed
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	0. None
Dispenser:	3. Gravity

US AIRS (AFS):

Envid:	1007796644
Region Code:	02
County Code:	NY119
Programmatic ID:	AIR NY0000003551700249
Facility Registry ID:	110019591538
D and B Number:	Not reported
Facility Site Name:	RECKSON METRO CENTER
Primary SIC Code:	6531
NAICS Code:	999999
Default Air Classification Code:	SMI
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS (AFS):

Region Code:	02
Programmatic ID:	AIR NY0000003551700249
Facility Registry ID:	110019591538
Air Operating Status Code:	OPR
Default Air Classification Code:	SMI
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-10-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

W235 **RECKSON ASSOCIATES** **NY Spills** **1001489143**
NNE **360 HAMILTON AVE - MAIN FLOOR** **RCRA NonGen / NLR** **NYR000071779**
1/8-1/4 **WHITE PLAINS, NY 10601** **FINDS**
0.179 mi. **ECHO**
943 ft. **Site 2 of 10 in cluster W** **NY MANIFEST**

Relative:
Higher

Actual:
228 ft.

SPILLS:

Spill Number/Closed Date:	9907464 / 1999-10-14
Facility ID:	9907464
Facility Type:	ER
DER Facility ID:	243959
Site ID:	301898
DEC Region:	3
Spill Cause:	Equipment Failure

RECKSON ASSOCIATES (Continued) **1001489143**

Spill Class:	B3
SWIS:	6017
Spill Date:	1999-09-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-09-21
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-21
Spill Record Last Update:	1999-10-27
Spiller Name:	PHIL FALLON
Spiller Company:	RECKSON ASSOCIATES
Spiller Address:	360 HAMILTON ROAD
Spiller Company:	001
Contact Name:	PHIL FALLON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 9/21/99 PER P. FALLON--TANK IN BASEMENT 275 GALLONS. DELIVERY 9/21/99. WHILE DELIVERING WENT TO CHECK TANK. ONLY 6 IN TANK-NO OIL IN BASEMENT. LINE MAY BE SEVERED IN GROUND FROM FILL TO WHERE LINE ENTERS BASEMENT. 10/14/99 LETTER SENT; SPILL FILE CLOSED."
Remarks:	"while recieving an oil delivery - oil was not going into the tank - it appears there is a line leak - oil stain is now appearing in the wall - clean up crew will arrive tomorrow to start clean up "

All Materials:

Site ID:	301898
Operable Unit ID:	1081749
Operable Unit:	01
Material ID:	300169
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	RECKSON ASSOCIATES
Facility address:	360 HAMILTON AVE - MAIN FLOOR WHITE PLAINS, NY 10601
EPA ID:	NYR000071779
Mailing address:	GILFORD AVE C-O WASTE MGMT NEW HYDE PARK, NY 11040
Contact:	DANIEL RIVERS

RECKSON ASSOCIATES (Continued) **1001489143**

Contact address: GILFORD AVE C-O WASTE MGMT
NEW HYDE PARK, NY 11040
Contact country: US
Contact telephone: 516-352-7466
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: RICKSON ASSOCIATES
Owner/operator address: 225 BROADHOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 516-622-6678
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RICKSON ASSOCIATES
Owner/operator address: 225 BROADHOLLOW RD
MELVILLE, NY 11747
Owner/operator country: US
Owner/operator telephone: 516-622-6678
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: RECKSON ASSOCIATES

RECKSON ASSOCIATES (Continued) **1001489143**

Classification: Not a generator, verified

Date form received by agency: 05/26/1999
Site name: RECKSON ASSOCIATES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004553297

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001489143
Registry ID: 110004553297
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004553297

NY MANIFEST:
Country: USA
EPA ID: NYR000071779
Facility Status: Not reported
Location Address 1: 360 HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY

RECKSON ASSOCIATES (Continued) **1001489143**

Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000071779
Mailing Name:	RECHSON ASSOCIATES
Mailing Contact:	DANIEL J RIVERS
Mailing Address 1:	360 HAMILTON AVE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	Not reported
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5163527466

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	PAR000043752
Trans2 State ID:	NJD986607380
Generator Ship Date:	06/27/2017
Trans1 Recv Date:	06/27/2017
Trans2 Recv Date:	06/30/2017
TSD Site Recv Date:	07/21/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000071779
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	OHD001926740
TSDF ID 2:	Not reported
Manifest Tracking Number:	009057368FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	33
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.

RECKSON ASSOCIATES (Continued) **1001489143**

Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY MANIFEST: record(s) in the EDR Site Report.

W236 **A T & T** **RCRA-SQG** **1000872181**
NNE **360 HAMILTON AVE** **NY MANIFEST** **NYD986998060**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.179 mi.
943 ft. **Site 3 of 10 in cluster W**

Relative:
Higher

Actual:
228 ft.

RCRA-SQG:

Date form received by agency:	04/20/2012
Facility name:	A T & T
Facility address:	360 HAMILTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYD986998060
Mailing address:	AT&T WAY RRC RECORDKEEPER 2C140 BEDMINSTER, NJ 07921
Contact:	GEOFF SMITH
Contact address:	AT&T WAY RRC RECORDKEEPER 2C140 BEDMINSTER, NJ 07921
Contact country:	US
Contact telephone:	800-566-9347
Telephone ext.:	4
Contact email:	EHSRRC@LIST.ATT.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	AT&T
Owner/operator address:	S AKARD DALLAS, TX 75202
Owner/operator country:	US
Owner/operator telephone:	800-566-9347
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/01/2005
Owner/Op end date:	Not reported

Owner/operator name:	AT&T

A T & T (Continued) **1000872181**

Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2005
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: X001
. Waste name: WASTE OILS

Historical Generators:
Date form received by agency: 01/01/2007
Site name: VERIZON
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: VERIZON
Classification: Not a generator, verified

Date form received by agency: 06/19/2003
Site name: VERIZON
Classification: Large Quantity Generator

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Date form received by agency: 08/24/1993
Site name: A T & T

A T & T (Continued) **1000872181**

Classification: Small Quantity Generator

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP005001854
Facility Status: Not reported
Location Address 1: 360 HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP005001854
Mailing Name: CON EDISON - VAULT SUBMERSIBLE VS9521
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL NE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Country: USA
EPA ID: NYD986998060
Facility Status: Not reported
Location Address 1: 360 HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986998060
Mailing Name: AT&T
Mailing Contact: LOUIS MORELLO
Mailing Address 1: 227 W MONROE SUITE 1004
Mailing Address 2: Not reported
Mailing City: CHICAGO
Mailing State: IL
Mailing Zip: 60606
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 8004723389

A T & T (Continued) **1000872181**

NY MANIFEST:

Document ID:	ARA9303420
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	H0902205
Trans2 State ID:	Not reported
Generator Ship Date:	06/17/1998
Trans1 Recv Date:	06/17/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/30/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986998060
Trans1 EPA ID:	OHD009865825
Trans2 EPA ID:	Not reported
TSDF ID 1:	ARD069748192
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	U220 - TOLUENE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00423
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

T237 **APARTMENT BLDG** **NY LTANKS** **S105997251**
ESE **37-43 MITCHELL PL** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.184 mi.
970 ft. **Site 5 of 7 in cluster T**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	0208214 / 2003-04-07
Facility ID:	0208214
Site ID:	248365

APARTMENT BLDG (Continued) **S105997251**

Spill Date:	2002-11-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-07
CID:	390
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-07
Spill Record Last Update:	2003-09-08
Spiller Name:	PHIL GUSSACK
Spiller Company:	APARTMENT BLDG
Spiller Address:	37-43 MITCHELL PL
Spiller County:	001
Spiller Contact:	PHIL GUSSACK
Spiller Phone:	(914) 497-5310
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	203790
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/15/03: Letter to Philip Gussack from Marc Grazioli, WCHD, dated 4/7/2003. Site closure report has been reviewed. Soil sample results satisfactory. WCHD recommend NFA at this time."
Remarks:	"caller reporting 1000 gal storage tank failed - there is soil contamination - unk amount spilled yet - soil is being stockpiled "

All Materials:

Site ID:	248365
Operable Unit ID:	859738
Operable Unit:	01
Material ID:	515218
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U238 **CON EDISON MANHOLE: 10087** **RCRA-LQG** **1016451333**
West **LEXINGTON AVE & E MAIN ST S** **FINDS** **NYP004303764**
1/8-1/4 **WHITE PLAINS, NY 10605** **ECHO**
0.186 mi.
981 ft. **Site 2 of 6 in cluster U**

Relative:
Lower

Actual:
201 ft.

RCRA-LQG:

Date form received by agency:	03/27/2014
Facility name:	CON EDISON - MANHOLE 10087
Facility address:	S. LEXINGTON AVE & E. MAIN ST WHITE PLAINS, NY 10605
EPA ID:	NYP004303764
Mailing address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact:	DENNIS HUACON
Contact address:	IRVING PLACE, 15TH FL NE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2757
Contact email:	HUACOND@CONED.COM
EPA Region:	02
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/22/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

CON EDISON MANHOLE: 10087 (Continued) **1016451333**

Owner/Operator Type: Owner
Owner/Op start date: 04/22/2013
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 04/22/2013
Site name: CON EDISON MANHOLE: 10087
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110056329414

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016451333
Registry ID: 110056329414
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056329414

U239 **CON EDISON** **NY MANIFEST** **S117538117**
West **S LEXINGTON AV & MAIN ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10801**
0.186 mi.
984 ft. **Site 3 of 6 in cluster U**

Relative:
Lower

Actual:
201 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004707600
Facility Status:	Not reported
Location Address 1:	S LEXINGTON AV & MAIN ST
Code:	BP
Location Address 2:	MH10087
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004707600
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/2014
Trans1 Recv Date:	12/17/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/18/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004707600
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013244434JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117538117**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U240 **CON EDISON VAULT: 70** **RCRA NonGen / NLR** **1016964217**
West **MAIN ST & LEXINGTON AVE** **NY MANIFEST** **NYP004371571**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.186 mi.
984 ft. **Site 4 of 6 in cluster U**

Relative: **Lower**
Actual: **201 ft.**

RCRA NonGen / NLR:

Date form received by agency:	11/08/2013
Facility name:	CON EDISON VAULT: 70
Facility address:	MAIN ST & LEXINGTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004371571
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON VAULT: 70 (Continued) **1016964217**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 10/08/2013
Site name: CON EDISON VAULT: 70
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004371571
Facility Status: Not reported
Location Address 1: MAIN ST & LEXINGTON
Code: BP
Location Address 2: VS 70
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004371571
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/08/2013
Trans1 Recv Date: 10/08/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/11/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004371571

CON EDISON VAULT: 70 (Continued) **1016964217**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694634JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U241 **CON EDISON** **NY MANIFEST** **S119073608**
West **S. LEXINGTON AVE & E. MAIN** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.186 mi.
984 ft. **Site 5 of 6 in cluster U**

Relative: NY MANIFEST:
Lower

Actual: Country:	USA
201 ft. EPA ID:	NYP004303764
Facility Status:	Not reported
Location Address 1:	S. LEXINGTON AVE & E. MAIN
Code:	BP
Location Address 2:	ST
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10605
Location Zip 4:	Not reported

CON EDISON (Continued) **S119073608**

NY MANIFEST:

EPAID:	NYP004303764
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	CON EDISON
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2013
Trans1 Recv Date:	04/22/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004303764
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010845209JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	4000
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CON EDISON (Continued) **S119073608**

Waste Code 1_2: Not reported
Waste Code 1_3: Not reported
Waste Code 1_4: Not reported
Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

U242 **CON EDISON MANHOLE: 10087** **RCRA NonGen / NLR** **1016677185**
West **LEXINGTON AVE & MAIN ST** **NY MANIFEST** **NYP004307484**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.186 mi.
984 ft. **Site 6 of 6 in cluster U**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:
Date form received by agency: 06/06/2013
Facility name: CON EDISON MANHOLE: 10087
Facility address: LEXINGTON AVE & MAIN ST
WHITE PLAINS, NY 10602
EPA ID: NYP004307484
Mailing address: VING PL, RM 828
NEW YORK, NY 10003
Contact: GINO FRABASILE
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 914-925-6219
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/06/2013
Site name: CON EDISON MANHOLE: 10087
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

CON EDISON MANHOLE: 10087 (Continued) **1016677185**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004307484
Facility Status:	Not reported
Location Address 1:	LEXINGTON & MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004307484
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/06/2013
Trans1 Recv Date:	05/06/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/13/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004307484
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007019085JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported

CON EDISON MANHOLE: 10087 (Continued) **1016677185**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

T243 **APT. BUILDING** **NY UST** **U003883925**
East **40 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.187 mi.
988 ft. **Site 6 of 7 in cluster T**

Relative: **Higher**

Actual: **218 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-600486 / Unregulated: <1101 gal. PBS
Operator Name:	Norman Tunnell
Owner Name:	Phyllis Tunnell Dba Yurick Enterprises
Owner Street:	C/o T Square Properties 56 Lafayete Ave
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10603
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/25/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None

APT. BUILDING (Continued) **U003883925**

Dispenser: 0. None

T244 **APARTMENT BUILDING** **NY LTANKS** **S105999478**
East **40 MITCHELL PL** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.187 mi.
988 ft. **Site 7 of 7 in cluster T**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	0304394 / 2003-10-31
Facility ID:	0304394
Site ID:	151265
Spill Date:	2003-07-25
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-07-25
CID:	390
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-25
Spill Record Last Update:	2003-12-12
Spiller Name:	NORMAN TUNNELL
Spiller Company:	APARTMENT BUILDING
Spiller Address:	40 MITCHELL PL
Spiller County:	001
Spiller Contact:	NORMAN TUNNELL
Spiller Phone:	(914) 328-7511
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128562
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 11/4/03: Letter to Toni Palancia, Yurik Enterprises from Stefan Goreau, WCDOH dated 10/31/2003. Site closure report has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"leaking underground storage tank caused spill - tank is still in ground - more will be done next week -- tank has been abandoned and covered"

All Materials:

Site ID:	151265
Operable Unit ID:	871197
Operable Unit:	01
Material ID:	505252
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

APARTMENT BUILDING (Continued) **S105999478**

Units: G
Recovered: .00
Oxygenate: Not reported

X245 **CON EDISON** **NJ MANIFEST** **S120673263**
SE **148 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.191 mi.
1007 ft. **Site 1 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

NJ MANIFEST:

EPA Id:	NYP004799854
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473126JJK
EPA ID:	NYP004799854
Date Shipped:	6/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON (Continued) **S120673263**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X246 **CON EDISON** **RCRA NonGen / NLR** **1014396960**
SE **148 MAMARONECK AVE FRONT OF** **NY MANIFEST** **NYP004192761**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.191 mi.
1007 ft. **Site 2 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	148 MAMARONECK AVE FRONT OF WHITE PLAINS, NY 10603
EPA ID:	NYP004192761
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	NEIL SKOW
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	718-204-4249
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON (Continued) **1014396960**

Historical Generators:
Date form received by agency: 08/31/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004192761
Facility Status: Not reported
Location Address 1: 148 MAMARONECK AVE & & E POST RD - MH 5627
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004192761
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2009
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 08/31/2009
Trans1 Recv Date: 08/31/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/01/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004192761
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD077444263
TSDF ID 2: Not reported
Manifest Tracking Number: 001433284FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON (Continued) **1014396960**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	180.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	B002
Waste Code 1_3:	B007
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Country:	USA
EPA ID:	NYP004799854
Facility Status:	Not reported
Location Address 1:	148 MAMARONECK AVE
Code:	BP
Location Address 2:	MH 5627
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004799854
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359

CON EDISON (Continued) **1014396960**

Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2015
Trans1 Recv Date:	06/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004799854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014473126JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X247 **CON EDISON** **RCRA NonGen / NLR** **1019904587**
SE **148 MAMARONECK AVE** **NYP004799854**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.191 mi.
1007 ft. **Site 3 of 16 in cluster X**

Relative: RCRA NonGen / NLR:
Higher
Date form received by agency: 06/26/2015
Actual: Facility name: CON EDISON
226 ft. Facility address: 148 MAMARONECK AVE
WHITE PLAINS, NY 10601

CON EDISON (Continued) **1019904587**

EPA ID: NYP004799854
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/26/2015
Site name: CON EDISON
Classification: Small Quantity Generator

Violation Status: No violations found

Y248 **MARRIOT INN** **NY LTANKS** **S106972718**
NNW **5 BARKER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.191 mi.
1009 ft. **Site 1 of 5 in cluster Y**

Relative: LTANKS:
Lower
Spill Number/Closed Date: 0503865 / 2005-10-28
Actual: Facility ID: 0503865
193 ft. Site ID: 348566
Spill Date: 2005-06-30
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2005-06-30
CID: 409
Water Affected: Not reported

MARRIOT INN (Continued) **S106972718**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2005-06-30
Spill Record Last Update:	2005-10-28
Spiller Name:	PHIL DANIEL
Spiller Company:	MARIOTT RESIDENT HOTELS
Spiller Address:	5 BARKER AVE
Spiller County:	001
Spiller Contact:	PHIL DANIEL
Spiller Phone:	(301) 657-2130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	294998
DEC Memo:	"06/30/05: Hole found in top of tank. UST was at grad level not undersoil. Castlton will remove UST. 8/22/05 UST Removal report submitted by National Environmental Specialists. One 550 gallon tank was excavated and removed along with 30.30 tons of impacted soil. NFA TG"
Remarks:	"TANK TEST FAILURE AND THEN A SOIL TEST FAILURE. SOIL IS GOING OUT FOR ANALYSIS FIRST. BUILDING DEPT. INSPECTOR WAS THERE FROM THE CITY. ARRANGEMENTS ARE BEING MADE FOR CLEAN UP."

All TTF:

Facility ID:	0503865
Spill Number:	0503865
Spill Tank Test:	1549038
Site ID:	348566
Tank Number:	1
Tank Size:	550
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	18
Test Method 2:	Alert Model 1000 plus 1050 (Formerly Gilbarco Precision)
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	348566
Operable Unit ID:	1106217
Operable Unit:	01
Material ID:	1971137
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00

MARRIOT INN (Continued) **S106972718**

Oxygenate:	Not reported
Spill Number/Closed Date:	1303150 / 2014-02-28
Facility ID:	1303150
Site ID:	483619
Spill Date:	2013-06-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2013-06-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-06-24
Spill Record Last Update:	2014-02-28
Spiller Name:	NELSON SELIMOV
Spiller Company:	Marriot Residence Inn
Spiller Address:	5 BARKER AVE
Spiller County:	999
Spiller Contact:	NELSON SELIMOV
Spiller Phone:	(914) 761-7700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	294998
DEC Memo:	"6/24/13 - Being handled by the Westchester County DOH, according to email: From: Lalak, Chris To: Schneider, Wayne CC: Daniel Bendell , kabrowne@gw.dec.state.ny.... Date: 6/24/2013 12:35 PM Subject: FW: Spill : 1303150 WC PBS Wayne TTF Wayne, Please handle this TTF. It is an unregistered PBS site. It is the Residence Inn, No Tix's if they register promptly. The tank is a 550 UST Diesel tank for a generator. The tested thinks it is just an air leak. It is unknown if other tanks are present. Thank You Chris Christopher J. Lalak MS Radiological and Chemical Analyst Westchester County Department of Health 145 Huguenot Street - 7th Floor New Rochelle, NY 10801 CJL1@westchestergov.com (914) 224-7649 02-26-14 edoc retest, NFA RDB "
	Not reported
Remarks:	"Failed test for diesel generator UST. Repair and retest is being planned."

All TTF:

Facility ID:	1303150
Spill Number:	1303150
Spill Tank Test:	2493627
Site ID:	483619
Tank Number:	G
Tank Size:	550
Material:	0008
EPA UST:	True

MARRIOT INN (Continued) **S106972718**

UST:	True
Cause:	00
Source:	01
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.99
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	483619
Operable Unit ID:	1233321
Operable Unit:	01
Material ID:	2232214
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Y249 **RESIDENCE INN - TTF** **NY LTANKS** **S117853873**
NNW **5 BARKER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.191 mi.
1009 ft. **Site 2 of 5 in cluster Y**

Relative: **Lower**

Actual: **193 ft.**

LTANKS:

Spill Number/Closed Date:	1501552 / 2015-07-20
Facility ID:	1501552
Site ID:	507776
Spill Date:	2015-05-12
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2015-05-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-05-12
Spill Record Last Update:	2015-07-20
Spiller Name:	GREG RICCALDO
Spiller Company:	RESIDENCE INN
Spiller Address:	5 ARKER AVE

RESIDENCE INN - TTF (Continued) **S117853873**

Spiller County: 999
Spiller Contact: GREG RICCALDO
Spiller Phone: (914) 761-7700
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 294998
DEC Memo: "5/12/15 Spoke to tank tester, who said a retest will be done after repairing the tank connections. According to Chris Lalak of WCHD, 550 UST at facility needs to be registered as PBS. dw 07/20/15 Wayne Schneider from the WCHD reported, TTF. tank passed retest 3 days later after a tank top connection was replaced. NFA. TG"
Remarks: "dry leak, retest pending"

All Materials:
Site ID: 507776
Operable Unit ID: 1257101
Operable Unit: 01
Material ID: 2260075
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

X250 **CON EDISON** **NY MANIFEST** **S117536411**
SE **MAMARONECK AVE & E POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.191 mi.
1010 ft. **Site 4 of 16 in cluster X**

Relative: Higher
Actual: 226 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004688784
Facility Status: Not reported
Location Address 1: MAMARONECK AVE & E POST RD
Code: BP
Location Address 2: VS 8314
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004688784
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON (Continued) **S117536411**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2014
Trans1 Recv Date:	11/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004688784
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773152JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X251 **CON EDISON** **NJ MANIFEST** **S120673398**
SE **E POST RD & MAMMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.191 mi.
1010 ft. **Site 5 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

NJ MANIFEST:

EPA Id:	NYP004801361
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469259JJK
EPA ID:	NYP004801361
Date Shipped:	7/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673398**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

X252 **CON EDISON** **NY MANIFEST** **S119076221**
SE **E POST RD & MAMMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.191 mi.
1010 ft. **Site 6 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004801361
Facility Status:	Not reported
Location Address 1:	E POST RD & MAMARONECK AVE
Code:	BP
Location Address 2:	VS 5056
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004801361
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/01/2015
Trans1 Recv Date:	07/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004801361
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

CON EDISON (Continued) **S119076221**

Manifest Tracking Number:	014469259JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X253 **CON EDISON MANHOLE 3343** **RCRA NonGen / NLR** **1014918970**
SE **MAMARONECK AVE & E POST RD** **NJ MANIFEST** **NYP004225892**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.191 mi.
1010 ft. **Site 7 of 16 in cluster X**

Relative: **Higher**
Actual: **226 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/27/2011
Facility name:	CON EDISON MANHOLE 3343
Facility address:	MAMARONECK AVE & E POST RD MH 3343 WHITE PLAINS, NY 10601
EPA ID:	NYP004225892
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/28/2011
Site name: CON EDISON MANHOLE 3343
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004225892
Mail Address: IRVING PL RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DONALD SENNO
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 007655818JJK
EPA ID: NYP004225892
Date Shipped: 1/27/2011
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Country:	USA
EPA ID:	NYP004225892
Facility Status:	Not reported
Location Address 1:	MAMACKROCK AVE & PORT RD
Code:	BP
Location Address 2:	MH 3343
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004225892
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2011
Trans1 Recv Date:	01/27/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004225892
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655818JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X254 **CON EDISON MANHOLE 3334** **RCRA NonGen / NLR** **1014918971**
SE **MAMARONECK AVE & E POST RD** **NJ MANIFEST** **NYP004225900**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.191 mi.
1010 ft. **Site 8 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	02/27/2011
Facility name:	CON EDISON MANHOLE 3334
Facility address:	MAMARONECK AVE & E POST RD MH 3334 WHITE PLAINS, NY 10601
EPA ID:	NYP004225900
Mailing address:	IRVING PL RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	01/28/2011
Site name:	CON EDISON MANHOLE 3334
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NJ MANIFEST:

EPA Id:	NYP004225900
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON MANHOLE 3334 (Continued) **1014918971**

Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655798JJK
EPA ID:	NYP004225900
Date Shipped:	1/27/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008

CON EDISON MANHOLE 3334 (Continued) **1014918971**

Hand Code: H111
Quantity: 75.00 Pounds

NY MANIFEST:
Country: USA
EPA ID: NYP004225900
Facility Status: Not reported
Location Address 1: E POST RD MH 3334
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004225900
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: CONSOLIDATED EDISON
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2011
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 01/27/2011
Trans1 Recv Date: 01/27/2011
Trans2 Recv Date: Not reported
TSD Site Recv Date: 01/31/2011
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004225900
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 007655798JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N

CON EDISON MANHOLE 3334 (Continued) **1014918971**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X255 **CON EDISON** **RCRA NonGen / NLR** **1019904715**
SE **E POST RD & MAMMARONECK AVE** **FINDS** **NYP004801361**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.191 mi.
1010 ft. **Site 9 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/01/2015
Facility name:	CON EDISON
Facility address:	E POST RD & MAMMARONECK AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004801361
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

CON EDISON (Continued) **1019904715**

Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:
Date form received by agency: 07/01/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110069647859

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019904715
Registry ID: 110069647859
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069647859

Z256 **CON EDISON** **RCRA NonGen / NLR** **1019903475**
WSW **N LEXINGTON AVE & MARTINE AVE** **NYP004786067**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.192 mi.
1012 ft. **Site 1 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:
Date form received by agency: 05/24/2015
Facility name: CON EDISON
Facility address: N LEXINGTON AVE & MARTINE AVE
WHITE PLAINS, NY 10606
EPA ID: NYP004786067
Mailing address: IRVING PL 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported

CON EDISON (Continued) **1019903475**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/24/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

Z257 **CON EDISON - MANHOLE 9134** **RCRA-LQG** **1016451272**
WSW **MARTINE AVE & LEXINGTON AV** **NYP004303145**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.192 mi.
1012 ft. **Site 2 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

RCRA-LQG:
Date form received by agency: 03/27/2014
Facility name: CON EDISON - MANHOLE 9134
Facility address: MARTINE AVE & LEXINGTON AV
E
WHITE PLAINS, NY 10605
EPA ID: NYP004303145
Mailing address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact: DENNIS HUACON
Contact address: IRVING PLACE, 15TH FL NE
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-460-2757
Contact email: HUACOND@CONED.COM
EPA Region: 02
Classification: Large Quantity Generator
Description: Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the

CON EDISON - MANHOLE 9134 (Continued) **1016451272**

cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/19/2013
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/19/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D008
. Waste name:	LEAD

CON EDISON - MANHOLE 9134 (Continued) **1016451272**

Historical Generators:
Date form received by agency: 05/19/2013
Site name: CON EDISON MANHOLE: 9134
Classification: Not a generator, verified

Date form received by agency: 04/19/2013
Site name: CON EDISON MANHOLE: 9134
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Z258 **CON EDISON SERVICE BOX: 1342** **RCRA NonGen / NLR** **1016967206**
WSW **S LEXINGTON AVE & MARTINE AVE** **NY MANIFEST** **NYP004408274**
1/8-1/4 **WHITE PLAINS, NY 10610**
0.192 mi.
1012 ft. **Site 3 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/18/2014
Facility name: CON EDISON SERVICE BOX: 1342
Facility address: S LEXINGTON AVE & MARTINE AVE
SB 1342
WHITE PLAINS, NY 10610
EPA ID: NYP004408274
Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 12/18/2013
Site name: CON EDISON SERVICE BOX: 1342
Classification: Conditionally Exempt Small Quantity Generator

CON EDISON SERVICE BOX: 1342 (Continued) **1016967206**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004408274
Facility Status: Not reported
Location Address 1: S LEXINGTON AVE & MARTINE AVE
Code: BP
Location Address 2: SB75789
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10705
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004408274
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 12/18/2013
Trans1 Recv Date: 12/18/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/19/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004408274
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011695235JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110

CON EDISON SERVICE BOX: 1342 (Continued) **1016967206**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z259 **CON EDISON MANHOLE: 9134** **RCRA NonGen / NLR** **1016959956**
WSW **MARTINE AVE & S LEXINGTON AVE** **NY MANIFEST** **NYP004318374**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.192 mi.
1012 ft. **Site 4 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/04/2013
Facility name:	CON EDISON MANHOLE: 9134
Facility address:	MARTINE AVE & S LEXINGTON AVE WHITE PLAINS, NY 10606
EPA ID:	NYP004318374
Mailing address:	IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DONALD SENNO
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

CON EDISON MANHOLE: 9134 (Continued) **1016959956**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/04/2013
Site name: CON EDISON MANHOLE: 9134
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004318374
Facility Status: Not reported
Location Address 1: MARTINE AVE & S LEXINGTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004318374
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 06/04/2013
Trans1 Recv Date: 06/04/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 06/10/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004318374
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046

CON EDISON MANHOLE: 9134 (Continued) **1016959956**

TSDF ID 2:	Not reported
Manifest Tracking Number:	007019103JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z260 **CON EDISON** **NJ MANIFEST** **S120672081**
WSW **N LEXINGTON AVE & MARTINE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.192 mi.
1012 ft. **Site 5 of 12 in cluster Z**

Relative: NJ MANIFEST:
Lower

EPA Id:	NYP004786067
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

Actual:
201 ft.

CON EDISON (Continued) **S120672081**

Date Change:	Not reported

Manifest:

Manifest Number:	014454292JJK
EPA ID:	NYP004786067
Date Shipped:	5/24/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Z261 **CON EDISON** **NY MANIFEST** **S118090959**
WSW **MARTINE AVE & LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.192 mi.
1012 ft. **Site 6 of 12 in cluster Z**

Relative: **Lower**
Actual: **201 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004303145
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & LEXINGTON AV
Code:	BP

CON EDISON (Continued) **S118090959**

Location Address 2:	E
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10605
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004303145
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	04/19/2013
Trans1 Recv Date:	04/19/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/24/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004303145
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010464294JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	5000

CON EDISON (Continued) **S118090959**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z262 **CON EDISON SERVICE BOX: 10084** **RCRA NonGen / NLR** **1016967207**
WSW **S LEXINGTON AVE & MARTINE AVE** **NY MANIFEST** **NYP004408282**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.192 mi.
1012 ft. **Site 7 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/18/2014
Facility name:	CON EDISON SERVICE BOX: 10084
Facility address:	S LEXINGTON AVE & MARTINE AVE SB 10084 WHITE PLAINS, NY 10603
EPA ID:	NYP004408282
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

CON EDISON SERVICE BOX: 10084 (Continued) **1016967207**

Historical Generators:
Date form received by agency: 12/18/2013
Site name: CON EDISON SERVICE BOX: 10084
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004408282
Facility Status: Not reported
Location Address 1: S LEXINGTON AVE & MARTINE AVE
Code: BP
Location Address 2: SB75789
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10705
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004408282
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 12/18/2013
Trans1 Recv Date: 12/18/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 12/19/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004408282
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011695234JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N

CON EDISON SERVICE BOX: 10084 (Continued) **1016967207**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z263 **CON EDISON** **NY MANIFEST** **S119075480**
WSW **N LEXINGTON AVE & MARTINE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.192 mi.
1012 ft. **Site 8 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004786067
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & LEXINGTON AVE
Code:	BP
Location Address 2:	M 9946
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004786067
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON (Continued) **S119075480**

Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/24/2015
Trans1 Recv Date:	05/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/26/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004786067
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454292JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z264 **CON EDISON** **NY MANIFEST** **S117737905**
WSW **S. LEXINGTON AV & MARTINE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.192 mi.
1012 ft. **Site 9 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004688545
Facility Status:	Not reported
Location Address 1:	S. LEXINGTON AV & MARTINE
Code:	BP
Location Address 2:	AV
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004688545
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	11/01/2014
Trans1 Recv Date:	11/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/06/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004688545
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772217JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S117737905**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Z265 **GALLERIA WEST GARAGE 5** **NY UST U003856313**
WSW **MARTINE AVE & SO LEXINGTON AVE** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.192 mi.
1012 ft. **Site 10 of 12 in cluster Z**

Relative: **Lower**
Actual: **201 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-169579 / Unregulated: <1101 gal. PBS
Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main St
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	31
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1980
Date Perm Closure:	11/01/1994
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron

GALLERIA WEST GARAGE 5 (Continued) **U003856313**

Piping External Protection: 0. None
Overfill Prevention: 0. None
Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-169579
Site Status: Unregulated: <1101 gal. PBS
GDS Number: Not reported
Operator Name: City Of White Plains
Owner Name: City Of White Plains
Owner Street: 255 Main St
Owner Address2: Not reported
Owner City/State/Zip: White Plains, NY 10601

Tank Number: 32
Status: 0. Administratively closed
Date Installation: 12/01/1980
Capacity: 300
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 3. Gravity

Tank Number: 33
Status: 0. Administratively closed
Date Installation: 12/01/1980
Capacity: 300
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported

GALLERIA WEST GARAGE 5 (Continued) **U003856313**

Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 3. Gravity

X266 **HALPERN ENTERPRISES** **NY LTANKS** **S100140406**
SE **170 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.193 mi.
1019 ft. **Site 10 of 16 in cluster X**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Spill Number/Closed Date:	8804996 / 2005-04-30
Facility ID:	8804996
Site ID:	154885
Spill Date:	1988-09-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1988-09-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-09-16
Spill Record Last Update:	2005-04-30
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131293
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 04/30/05 ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFIICE."
Remarks:	"3,000 GAL. TANK; -.10 GPH; TO EXCAVATE, ISOLATE & RETEST. TANK TO BE RETESTED THE WEEK OF 9/12. LEAK COULD BE FROM FILL PIPE WHICH IS BENTSPOKE TO GARY GIGLIO. WILL CALL IF TANK IS TO BE REMOVED."

All TTF:

Facility ID:	8804996
Spill Number:	8804996
Spill Tank Test:	1534581
Site ID:	154885
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported

HALPERN ENTERPRISES (Continued) **S100140406**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	154885
Operable Unit ID:	922162
Operable Unit:	01
Material ID:	456917
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

X267 **DEVON PLAZA REALTY** **NY UST** **U003884217**
SE **170 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.193 mi.
1019 ft. **Site 11 of 16 in cluster X**

Relative:
Higher

Actual:
221 ft.

WESTCHESTER CO. UST:

Id/Status:	3-050067 / Unregulated
Operator Name:	Lee J. Lewitt
Owner Name:	Devon Plaza Realty
Owner Street:	141 Halstead Avenue
Owner Address2:	Not reported
Owner City:	Mamaroneck
Owner State:	NY
Owner Zipcode:	10543
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1995
Date Perm Closure:	02/19/2013
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron

DEVON PLAZA REALTY (Continued) **U003884217**

Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Y268 **CON EDISON** **NY MANIFEST** **S116550253**
NNW **COTTAGE PL & BARKER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.194 mi.
1022 ft. **Site 3 of 5 in cluster Y**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004485504
Facility Status:	Not reported
Location Address 1:	COTTAGE PLW
Code:	BP
Location Address 2:	SB5215
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004485504
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2014
Trans1 Recv Date:	04/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/08/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004485504
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693260JJK
Import Indicator:	N

CON EDISON (Continued) **S116550253**

Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Y269 **CON EDISON MANHOLE: 8810** **RCRA NonGen / NLR** **1016968437**
NNW **BARKER ST & COTTAGE PL** **NY MANIFEST** **NYP004420485**
1/8-1/4 **WHITE PLAINS, NY 10607**
0.194 mi.
1022 ft. **Site 4 of 5 in cluster Y**

Relative: **Lower**

Actual: **197 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/16/2014
Facility name:	CON EDISON MANHOLE: 8810
Facility address:	BARKER ST & COTTAGE PL WHITE PLAINS, NY 10607
EPA ID:	NYP004420485
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON MANHOLE: 8810 (Continued) **1016968437**

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/16/2014
Site name: CON EDISON MANHOLE: 8810
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004420485
Facility Status: Not reported
Location Address 1: BARKER/COTTAGE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004420485
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported

CON EDISON MANHOLE: 8810 (Continued) **1016968437**

Generator Ship Date:	01/16/2014
Trans1 Recv Date:	01/16/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/20/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004420485
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011696164JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Y270 **CON EDISON VAULT: 5215** **RCRA NonGen / NLR** **1017771609**
NNW **COTTAGE PL & BARKER AVE** **FINDS** **NYP004485504**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.194 mi.
1022 ft. **Site 5 of 5 in cluster Y**

Relative: RCRA NonGen / NLR:
Lower
Date form received by agency: 05/01/2014
Actual: Facility name: CON EDISON VAULT: 5215
197 ft. Facility address: COTTAGE PL & BARKER AVE
WHITE PLAINS, NY 10602
EPA ID: NYP004485504

CON EDISON VAULT: 5215 (Continued) **1017771609**

Mailing address: IRVING PL, 15TH FL NE
NEW YORK, NY 10003
Contact: THOMAS TEELING
Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/01/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/01/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063786737

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AA271 **EDGAR** **NY LTANKS** **S103479696**
NW **1 BARKER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.194 mi.
1025 ft. **Site 1 of 4 in cluster AA**

Relative:
Lower

Actual:
187 ft.

LTANKS:

Spill Number/Closed Date:	9807932 / 1999-11-19
Facility ID:	9807932
Site ID:	330854
Spill Date:	1998-09-29
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-09-29
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-29
Spill Record Last Update:	1999-12-28
Spiller Name:	FRANK UZZO
Spiller Company:	WHITE PLAINS REALTY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ROB EDGAR
Spiller Phone:	(973) 560-1400
Spiller Extention:	159
DEC Region:	3
DER Facility ID:	266099
DEC Memo:	""
Remarks:	"PBS #3-00999 TANK #001 - NOTIFIER ON SITE FOUND A HOLE IN OIL TANK - NO SOIL CONTAMINATION FOUND AS OF TIME OF THE CALL"

All Materials:

Site ID:	330854
Operable Unit ID:	1069116
Operable Unit:	01
Material ID:	315471
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Z272 **77 SOUTH LEXINGTON AVE** **NY LTANKS** **S105999444**
WSW **77 SOUTH LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.194 mi.
1026 ft. **Site 11 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

LTANKS:

Spill Number/Closed Date:	0304231 / 2003-07-22
Facility ID:	0304231
Site ID:	106697
Spill Date:	2003-07-22
Spill Cause:	Tank Overfill
Spill Source:	Passenger Vehicle
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-07-22
CID:	216
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-22
Spill Record Last Update:	2003-07-25
Spiller Name:	Not reported
Spiller Company:	MARCOS RAMOS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	LINDA RICCO
Spiller Phone:	(718) 383-1400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	93920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"SPILL AT POLICE STATION OVER FILL SPIL IS CLEANED UP "

All Materials:

Site ID:	106697
Operable Unit ID:	871118
Operable Unit:	01
Material ID:	505088
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Z273 **PUBLIC SAFETY BUILDING** **NY UST** **U004177168**
WSW **77 SOUTH LEXINGTON AVENUE** **NY AST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.194 mi.
1026 ft. **Site 12 of 12 in cluster Z**

Relative:
Lower

Actual:
201 ft.

WESTCHESTER CO. UST:

Id/Status:	3-601115 / Active
Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main Street
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	3551700345
Tank Number:	38
Status:	3. Closed - Removed
Capacity:	2385
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	02/01/1990
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	39
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	02/01/1990
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

PUBLIC SAFETY BUILDING (Continued) **U004177168**

WESTCHESTER CO. AST:

PBS Number:	3-601115
Site Status:	Active
GDS Number:	3551700345
Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	38A
Status:	1. In-Service
Date Installation:	01/01/2011
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	5. Steel tank in concrete
Tank Internal Protection:	0. None
Tank External Protection:	concrete
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	3. Stainless Steel Alloy
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible
Tank Number:	38B
Status:	1. In-Service
Date Installation:	01/01/2011
Capacity:	1000
Product Stored:	0009. Gasoline
Product Stored Percent:	85
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	5. Steel tank in concrete
Tank Internal Protection:	0. None
Tank External Protection:	concrete
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	3. Stainless Steel Alloy
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible
Tank Number:	40

PUBLIC SAFETY BUILDING (Continued) **U004177168**

Status:	1. In-Service
Date Installation:	01/01/2011
Capacity:	500
Product Stored:	0008. Diesel
Product Stored Percent:	100
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	5. Steel tank in concrete
Tank Internal Protection:	0. None
Tank External Protection:	concrete
Tank Leak Detection:	2. Manual Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AB274 **COMMERCIAL** **NY LTANKS** **S121988273**
SSE **130-144 EAST POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.195 mi.
1029 ft. **Site 1 of 7 in cluster AB**

Relative: **Higher**
Actual: **234 ft.**

LTANKS:

Spill Number/Closed Date:	0002215 / 2011-02-28
Facility ID:	0002215
Site ID:	159846
Spill Date:	2000-05-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-05-22
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-22
Spill Record Last Update:	2011-02-28
Spiller Name:	ROBERT KIM
Spiller Company:	COMMERCIAL
Spiller Address:	130-144 EAST POST RD
Spiller County:	001
Spiller Contact:	ROBERT KIM
Spiller Phone:	(914) 723-2964
Spiller Extention:	Not reported
DEC Region:	3

COMMERCIAL (Continued) **S121988273**

DER Facility ID: 135018
DEC Memo: "12/28/09: File review. Reported as a TTF of a 1K tank, commercial property, not a registered facility. Call back notes on initial report state: 1K UG - To call & advise WCHD with future . No further information received. jod 2/28/11: This is the same tank as spill 1005304. Tank was never removed or retested after initial failure. Tank was leaking. Tank was removed and clean up was completed ten years later after the shopping center burned down. jod"
Remarks: "UNKNOWN WHAT IS GOING TO BE DONE."

All TTF:
Facility ID: 0002215
Spill Number: 0002215
Spill Tank Test: 1525625
Site ID: 159846
Tank Number: Not reported
Tank Size: 1000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 159846
Operable Unit ID: 823747
Operable Unit: 01
Material ID: 550585
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

X275 **151 EAST POST ROAD CORP.** **NY UST** **U004175916**
SE **151 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.195 mi.
1032 ft. **Site 12 of 16 in cluster X**

Relative: **Higher**
Actual: **227 ft.**

WESTCHESTER CO. UST:
Id/Status: 3-030910 / Active
Operator Name: Allen Management Inc.
Owner Name: 151 East Post Road Corp.
Owner Street: c/o Thomas Derecktor
Owner Address2: 902 Wapping Road
Owner City: Portsmouth
Owner State: RI

151 EAST POST ROAD CORP. (Continued) **U004175916**

Owner Zipcode:	02871-5119
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	12/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

X276 **COMMERCIAL PROERTY** **NY LTANKS** **S107789254**
SE **151 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.195 mi.
1032 ft. **Site 13 of 16 in cluster X**

Relative: LTANKS:
Higher

Actual:
227 ft.

Spill Number/Closed Date:	0601015 / 2006-11-03
Facility ID:	0601015
Site ID:	363155
Spill Date:	2006-04-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-04-26
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-26
Spill Record Last Update:	2006-11-03
Spiller Name:	TONY GASHA
Spiller Company:	COMMERCIAL PROERTY
Spiller Address:	151 EAST POST ROAD
Spiller County:	001
Spiller Contact:	TONY GASHA

COMMERCIAL PROERTY (Continued) **S107789254**

Spiller Phone:	(914) 946-2357
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	313347
DEC Memo:	"5/3/06: Refer to WC PBS August 16, 2006 Tony Gashi 151 East Post Road Corp 47 Mamaroneck Ave, Suite 111 White Plains, Ny 10601 Re: PBS #3-030910 151 East Post Road, White Plains, NY NYSDEC Spill # 06-01015 TTF Dear Facility; The Westchester County Department of Health has received the retest results from July 28, 2006. The results are acceptable to the Department. A request for closure is being sent to NYSDEC for the above spill # and no further action is required regarding the work at this time. If you have any questions, please call me at (914) 813-5971. Sincerely, Danielle Jackson Sanitarian Office of Environmental Health Risk Control "
Remarks:	"NO REMARKS."

All TTF:

Facility ID:	0601015
Spill Number:	0601015
Spill Tank Test:	1549917
Site ID:	363155
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	363155
Operable Unit ID:	1121214
Operable Unit:	01
Material ID:	2110709
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

X277 **OFFICE BLDG** **NY LTANKS** **S103558663**
SE **171 EAST POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.197 mi.
1041 ft. **Site 14 of 16 in cluster X**

Relative:
Higher

Actual:
223 ft.

LTANKS:

Spill Number/Closed Date:	9811157 / 2004-03-30
Facility ID:	9811157
Site ID:	293961
Spill Date:	1998-12-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-12-04
CID:	252
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-04
Spill Record Last Update:	2004-03-30
Spiller Name:	BILL CHRISTOPHER
Spiller Company:	OFFICE BLDG
Spiller Address:	171 EAST POST RD
Spiller County:	001
Spiller Contact:	BILL CHRISTOPHER
Spiller Phone:	(203) 972-0231
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	237886
DEC Memo:	""
Remarks:	"TANK TO BE ISOLATED AND RE-TESTED "

All TTF:

Facility ID:	9811157
Spill Number:	9811157
Spill Tank Test:	1546601
Site ID:	293961
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

OFFICE BLDG (Continued) **S103558663**

All Materials:
Site ID: 293961
Operable Unit ID: 1068550
Operable Unit: 01
Material ID: 315008
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AC278 **170 GRAND STREET ASSOC.** **NY UST U004175922**
South **170 GRAND STREET** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.197 mi.
1042 ft. **Site 1 of 17 in cluster AC**

Relative:
Higher

Actual:
236 ft.

WESTCHESTER CO. UST:
Id/Status: 3-800392 / Active
Operator Name: Jose Francisco
Owner Name: 170 Grand Avenue LLC
Owner Street: 825 East 233rd Street
Owner Address2: Not reported
Owner City: Bronx
Owner State: NY
Owner Zipcode: 10466
GDS Number: Not reported

Tank Number: 1old
Status: 4. Closed - in place
Capacity: 2000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 01/01/1900
Date Perm Closure: 03/03/2005
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 0. No Pippping
Piping External Protection: 0. None
Overfill Prevention: Not reported
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

WESTCHESTER CO. AST:
PBS Number: 3-800392
Site Status: Active
GDS Number: Not reported

170 GRAND STREET ASSOC. (Continued) **U004175922**

Operator Name:	Jose Francisco
Owner Name:	170 Grand Avenue LLC
Owner Street:	825 East 233rd Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10466
Tank Number:	1
Status:	1. In-Service
Date Installation:	04/01/2005
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None,99. Other
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	0. None
Dispenser:	0. None

AC279 **170 GRAND STREET** **NY LTANKS** **S102180212**
South **170 GRAND STREET** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.197 mi.
1042 ft. **Site 2 of 17 in cluster AC**

Relative: **Higher**

Actual: **236 ft.**

LTANKS:

Spill Number/Closed Date:	0408227 / 2007-11-28
Facility ID:	0408227
Site ID:	332894
Spill Date:	2004-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCHD
Reported to Dept:	2004-10-26
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-26
Spill Record Last Update:	2007-11-28
Spiller Name:	CARDINAL TANK

170 GRAND STREET (Continued) **S102180212**

Spiller Company:	APARTMENT
Spiller Address:	170 GRAND STREET
Spiller County:	001
Spiller Contact:	CARDINAL TANK
Spiller Phone:	(718) 625-4350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	260919
DEC Memo:	" Goreau, Stefan <shg1@westchestergov.com> 11/28/2007 2:20 PM >>> Results from sidewall and bottom samples were submitted to the Dept. prior to closure in place. Results were satisfactory. Spill may be closed. Stefan Goreau Sanitarian Office of Environmental Health Risk Control Westchester County Department of Health "
Remarks:	"PBS No: 3-800392 "

All TTF:

Facility ID:	0408227
Spill Number:	0408227
Spill Tank Test:	1548281
Site ID:	332894
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	JBODee
Last Modified Date:	Not reported

All Materials:

Site ID:	332894
Operable Unit ID:	1095101
Operable Unit:	01
Material ID:	575231
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9509189 / 1995-10-25
Facility ID:	9509189
Facility Type:	ER
DER Facility ID:	260919
Site ID:	323874
DEC Region:	3
Spill Cause:	Equipment Failure

170 GRAND STREET (Continued) **S102180212**

Spill Class:	E5
SWIS:	6017
Spill Date:	1995-10-25
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-10-25
CID:	205
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-10-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-25
Spill Record Last Update:	1995-11-01
Spiller Name:	Not reported
Spiller Company:	COSTAL OIL CO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CARLOS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"customers guage was inaccurate."

All Materials:

Site ID:	323874
Operable Unit ID:	1019773
Operable Unit:	01
Material ID:	360149
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AD280 **CON EDISON** **RCRA NonGen / NLR** **1014398735**
WNW **LEXINGTON & HAMILTON AVE** **FINDS** **NYP004210985**
1/8-1/4 **WHITE PLAINS, NY 10605** **ECHO**
0.198 mi. **NJ MANIFEST**
1045 ft. **Site 1 of 6 in cluster AD** **NY MANIFEST**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/08/2010
Facility name:	CON EDISON
Facility address:	LEXINGTON & HAMILTON AVE MH 10101 WHITE PLAINS, NY 10605
EPA ID:	NYP004210985
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE

CON EDISON (Continued) **1014398735**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 917-559-8971
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110042420074

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1014398735
Registry ID: 110042420074
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110042420074

NJ MANIFEST:
EPA Id: NYP004210985
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE

CON EDISON (Continued) **1014398735**

Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003533275JJK
EPA ID:	NYP004210985
Date Shipped:	07/08/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/08/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/12/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	80 P

CON EDISON (Continued) **1014398735**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004210985
Facility Status:	Not reported
Location Address 1:	MH202 SWC S FULTON AVE & E 3RD ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	MOUNT VERNON
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004210985
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/08/2010
Trans1 Recv Date:	07/08/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/12/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004210985
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003533275JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported

CON EDISON (Continued) **1014398735**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD281 **CON EDISON** **RCRA NonGen / NLR** **1014398724**
WNW **HAMILTON & N LEXINGTON AVE** **NJ MANIFEST** **NYP004210852**
1/8-1/4 **WHITE PLAINS, NY 10605** **NY MANIFEST**
0.198 mi.
1045 ft. **Site 2 of 6 in cluster AD**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/07/2010
Facility name:	CON EDISON
Facility address:	HAMILTON & N LEXINGTON AVE WHITE PLAINS, NY 10605
EPA ID:	NYP004210852
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-559-8971
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

CON EDISON (Continued) **1014398724**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

NJ MANIFEST:
EPA Id: NYP004210852
Mail Address: 4 IRVING PL, RM 828
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: DAVID DUKE
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 003533258JJK
EPA ID: NYP004210852
Date Shipped: 07/07/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/07/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 07/08/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported

CON EDISON (Continued) **1014398724**

Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	250 P

NY MANIFEST:

Country:	USA
EPA ID:	NYP004210852
Facility Status:	Not reported
Location Address 1:	MH8306 - HAMILTON AVE W/O LEXINGTON
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004210852
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2010
Trans1 Recv Date:	07/07/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2010
Part A Recv Date:	Not reported

CON EDISON (Continued) **1014398724**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004210852
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003533258JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AD282 **CON EDISON MANHOLE: 8307** **RCRA NonGen / NLR** **1016967051**
WNW **HAMILTON AVE & LEXINGTON AVE** **NY MANIFEST** **NYP004398830**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.198 mi.
1045 ft. **Site 3 of 6 in cluster AD**

Relative: RCRA NonGen / NLR:
Lower
Actual: Date form received by agency: 12/28/2013
201 ft.

Facility name:	CON EDISON MANHOLE: 8307
Facility address:	HAMILTON AVE & LEXINGTON AVE WHITE PLAINS, NY 10602
EPA ID:	NYP004398830
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported

CON EDISON MANHOLE: 8307 (Continued) **1016967051**

Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 11/28/2013
Site name: CON EDISON MANHOLE: 8307
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004398830
Facility Status: Not reported
Location Address 1: HAMILTON AVE 66 FT WO LEXINGTON
Code: BP
Location Address 2: MH 8307
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004398830
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON EDISON MANHOLE: 8307 (Continued) **1016967051**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/28/2013
Trans1 Recv Date:	11/28/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004398830
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695017JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

X283 **CON EDISON MANHOLE: 5050** **RCRA NonGen / NLR** **1016963680**
SE **149 MAMARONECK AVE FRONT OF** **NY MANIFEST** **NYP004366654**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.199 mi.
1053 ft. **Site 15 of 16 in cluster X**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date form received by agency:	10/26/2013
Facility name:	CON EDISON MANHOLE: 5050
Facility address:	149 MAMARONECK AVE FRONT OF WHITE PLAINS, NY 10601
EPA ID:	NYP004366654
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/26/2013
Site name:	CON EDISON MANHOLE: 5050
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004366654
Facility Status:	Not reported
Location Address 1:	F/O 149 MARMARONECK AVE
Code:	BP
Location Address 2:	MH5050
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004366654
Mailing Name: CON EDISON
Mailing Contact: C
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2013
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/26/2013
Trans1 Recv Date: 09/26/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004366654
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694717JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 110
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE284 **MGH CO., LLC** **NY UST** **U003884719**
East **45 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.201 mi.
1061 ft. **Site 1 of 4 in cluster AE**

Relative: **Higher**
Actual: **217 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-800409 / Active
Operator Name:	Not reported
Owner Name:	MGH Co., LLC
Owner Street:	P. O. Box 1755
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10156
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1970
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AE285 **MGH CO** **NY LTANKS** **S102674590**
East **45 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.201 mi.
1061 ft. **Site 2 of 4 in cluster AE**

Relative:
Higher

Actual:
217 ft.

LTANKS:

Spill Number/Closed Date:	9904849 / 2000-01-11
Facility ID:	9904849
Site ID:	78194
Spill Date:	1999-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-07-23
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-23
Spill Record Last Update:	2000-02-04
Spiller Name:	JAY BRENNAN
Spiller Company:	Not reported
Spiller Address:	45 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	JAY BRENNAN
Spiller Phone:	(914) 948-6068
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	""
Remarks:	"tank test failure "

All TTF:

Facility ID:	9904849
Spill Number:	9904849
Spill Tank Test:	1547407
Site ID:	78194
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

MGH CO (Continued) **S102674590**

All Materials:

Site ID:	78194
Operable Unit ID:	1079286
Operable Unit:	01
Material ID:	301173
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9510979 / 1995-12-12
Facility ID:	9510979
Site ID:	143584
Spill Date:	1995-11-29
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1995-12-12
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-01
CID:	349
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-01
Spill Record Last Update:	1999-07-25
Spiller Name:	PHIL MENDOLA
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 948-6068
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER OVERFILLED TANK"

All Materials:

Site ID:	143584
Operable Unit ID:	1021528
Operable Unit:	01
Material ID:	358334
Material Code:	0001A
Material Name:	#2 fuel oil

MGH CO (Continued) **S102674590**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

AE286 **APT BUILDING** **NY LTANKS** **S112810131**
East **45 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.201 mi.
1061 ft. **Site 3 of 4 in cluster AE**

Relative: **Higher**
Actual: **217 ft.**

LTANKS:

Spill Number/Closed Date:	1212688 / Not Reported
Facility ID:	1212688
Site ID:	475842
Spill Date:	2012-11-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2012-11-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2012-11-28
Spill Record Last Update:	2017-05-11
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	UNK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	"11-28-12 Tank to be repaired and retested. 2010 WC database listes owner as MGH Co., LLC jc 04-04-14 WCHD request closure, DEC request TCR RDB 4/13/17 DEC requests retest documentation, not TCR. mt 05-11-17; no test results yet - RDB"
Remarks:	"repair/retest pending - possible vent line issue"

All Materials:

Site ID:	475842
Operable Unit ID:	1225683
Operable Unit:	01
Material ID:	2222965
Material Code:	0001A

APT BUILDING (Continued) **S112810131**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AB287 **WESTCHESTER COUNTY OFFICE BUILDING** **NY UST U003988574**
SSE **112 EAST POST ROAD** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.202 mi.
1064 ft. **Site 2 of 7 in cluster AB**

Relative:
Higher

Actual:
238 ft.

WESTCHESTER CO. UST:

Id/Status:	3-801218 / Active
Operator Name:	David Fazio
Owner Name:	Westchester County DPW
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	4
Status:	1. In-Service
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1998
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	99. Other
Piping External Protection:	99. Other
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-801218
Site Status:	Active
GDS Number:	Not reported
Operator Name:	David Fazio
Owner Name:	Westchester County DPW
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601

WESTCHESTER COUNTY OFFICE BUILDING (Continued) **U003988574**

Tank Number:	004
Status:	1. In-Service
Date Installation:	01/01/1998
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,generator belly tank
Tank Leak Detection:	2. Manual Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	12. Double-Walled (AST only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AB288 **WESTCHESTER OFFICE BLDG.** **NY LTANKS** **S100141797**
SSE **112 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.202 mi.
1064 ft. **Site 3 of 7 in cluster AB**

Relative:
Higher

Actual:
238 ft.

LTANKS:

Spill Number/Closed Date:	9009334 / 1990-12-11
Facility ID:	9009334
Site ID:	243138
Spill Date:	1990-11-27
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1990-12-11
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-11-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1990-12-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-30
Spill Record Last Update:	1991-01-14
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported

WESTCHESTER OFFICE BLDG. (Continued) **S100141797**

DEC Region: 3
DER Facility ID: 199725
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/14/91: FIXED LINE, TANK TECH CHECKED AND REPAIRED. NO CONTAMINATED SOIL. "
Remarks: "TANK LEAKED WHEN 10 LBS. AIR PRESSURE PUT ON IT FUEL LEAKED TO CONCRETE BASEMENT FLOOR WEST,CTY. NOTIFIED DPW SPEEDI-DRY BEING APPLIED WCHD HANDLING"

All Materials:
Site ID: 243138
Operable Unit ID: 949838
Operable Unit: 01
Material ID: 429553
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: G
Recovered: .00
Oxygenate: Not reported

AB289 **WESTCHESTER COUNTY - 112 EAST POST ROAD** **RCRA NonGen / NLR** **1000552792**
SSE **112 E POST RD** **FINDS** **NYD986951978**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.202 mi. **NY MANIFEST**
1064 ft. **Site 4 of 7 in cluster AB**

Relative: **Higher**
Actual: **238 ft.**

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: WESTCHESTER COUNTY - 112 EAST POST ROAD
Facility address: 112 E POST RD
WHITE PLAINS, NY 10601
EPA ID: NYD986951978
Mailing address: MAIN ST NY POWER AUTH
WHITE PLAINS, NY 10601
Contact: Not reported
Contact address: MAIN ST NY POWER AUTH
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: COUNTY OF WESTCHESTER
Owner/operator address: 148 MARTNE AVE
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-285-2593
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: County

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COUNTY OF WESTCHESTER
Owner/operator address: 148 MARTNE AVE
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-285-2593
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WESTCHESTER COUNTY - 112 EAST POST ROAD
Classification: Not a generator, verified

Date form received by agency: 12/07/1994
Site name: WESTCHESTER COUNTY - 112 EAST POST ROAD
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 05/15/1991
Site name: WESTCHESTER COUNTY - 112 EAST POST ROAD
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

FINDS:

Registry ID: 110004466514

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000552792
Registry ID: 110004466514
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004466514

NY MANIFEST:
Country: USA
EPA ID: NYD986951978
Facility Status: Not reported
Location Address 1: 112 EAST POST ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 12603
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986951978
Mailing Name: WESTCHESTER COUNTY OF
Mailing Contact: RANDI SMITH
Mailing Address 1: C/O NY PWR AUTH 123 MAIN ST
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142873296

NY MANIFEST:
Document ID: NYB2299041
Manifest Status: C
seq: Not reported

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Year:	1991
Trans1 State ID:	PTD5889MN
Trans2 State ID:	Not reported
Generator Ship Date:	07/09/1991
Trans1 Recv Date:	07/09/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/18/1991
Part A Recv Date:	07/19/1991
Part B Recv Date:	08/01/1991
Generator EPA ID:	NYD986951978
Trans1 EPA ID:	MND980791321
Trans2 EPA ID:	Not reported
TSDF ID 1:	KSD981506025
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00126
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AF290 **CON EDISON SERVICE BOX: 11370** **RCRA NonGen / NLR** **1017773655**
SSW **FISHER CT & QUARROPAS ST** **FINDS** **NYP004514436**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.202 mi.
1069 ft. **Site 1 of 5 in cluster AF**

Relative: RCRA NonGen / NLR:
Lower

Date form received by agency:	05/28/2014
Facility name:	CON EDISON SERVICE BOX: 11370
Facility address:	FISHER CT & QUARROPAS ST WHITE PLAINS, NY 10603
EPA ID:	NYP004514436
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING

Actual:
197 ft.

CON EDISON SERVICE BOX: 11370 (Continued) **1017773655**

Contact address: Not reported
Not reported
Contact country: Not reported
Contact telephone: 212-460-3770
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/28/2014
Site name: CON EDISON
Classification: Large Quantity Generator

Date form received by agency: 04/28/2014
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

FINDS:

Registry ID: 110063784908

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AF291
SSW
1/8-1/4
0.202 mi.
1069 ft.

CON EDISON
QUARROPAS ST & FISHER CT
WHITE PLAINS, NY 10601

Site 2 of 5 in cluster AF

NY MANIFEST **S113815061**
N/A

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004314833
Facility Status:	Not reported
Location Address 1:	QUARROPAS ST & FISHER CT
Code:	BP
Location Address 2:	MH #11362
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004314833
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2013
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/16/2013
Trans1 Recv Date:	05/16/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004314833
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842720JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON EDISON (Continued) **S113815061**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AF292 **CON EDISON MANHOLE: 11362** **RCRA NonGen / NLR** **1016677744**
SSW **QUARROPAS ST & FISCHER CT** **FINDS** **NYP004314233**
1/8-1/4 **WHITE PLAINS, NY 10606** **ECHO**
0.202 mi. **NY MANIFEST**
1069 ft. **Site 3 of 5 in cluster AF**

Relative: **Lower**

Actual: **197 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/16/2013
Facility name:	CON EDISON MANHOLE: 11362
Facility address:	QUARROPAS ST & FISCHER CT WHITE PLAINS, NY 10606
EPA ID:	NYP004314233
Mailing address:	VING PL, RM 828 NEW YORK, NY 10003
Contact:	CHRISTOPHER BLAICH
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	914-925-6219
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

CON EDISON MANHOLE: 11362 (Continued) **1016677744**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 05/16/2013
Site name: CON EDISON MANHOLE: 11362
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110058878497

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016677744
Registry ID: 110058878497
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058878497

NY MANIFEST:
Country: USA
EPA ID: NYP004314233
Facility Status: Not reported
Location Address 1: QUARROPAS ST & FISHER CT
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004314233
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE 15TH FLOOR
Mailing Address 2: Not reported

CON EDISON MANHOLE: 11362 (Continued) **1016677744**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AF293 **CON EDISON** **NY MANIFEST** **S117059285**
SSW **FISHER CT & QUARROPAS ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.202 mi.
1069 ft. **Site 4 of 5 in cluster AF**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004514436
Facility Status:	Not reported
Location Address 1:	FISHER CT QUARRO PASS
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004514436
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2014
Trans1 Recv Date:	04/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004514436
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117059285**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771810JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AF294 **CHARLES L. BRIEANT U.S. COURTHOUSE** **NY UST U004177654**
SSW **300 QUARROPAS STREET** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.203 mi.
1070 ft. **Site 5 of 5 in cluster AF**

Relative: **Lower**
Actual: **197 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-801467 / Active
Operator Name:	Joseph Wright
Owner Name:	General Services Administration GSA
Owner Street:	26 Federal Plaza
Owner Address2:	Room 1611
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	dot1
Status:	1. In-Service
Capacity:	2500

CHARLES L. BRIEANT U.S. COURTHOUSE (Continued) **U004177654**

Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1995
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	4. Original impressed current
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	ohter
Dispenser:	2. Suction

Tank Number:	fot1
Status:	1. In-Service
Capacity:	15000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1995
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	2. Original sacrificial anode
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	ohter
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-801467
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Joseph Wright
Owner Name:	General Services Administration GSA
Owner Street:	26 Federal Plaza
Owner Address2:	Room 1611
Owner City/State/Zip:	White Plains, NY 10601

Tank Number:	dodt1
Status:	1. In-Service
Date Installation:	01/01/1995
Capacity:	100
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900

CHARLES L. BRIEANT U.S. COURTHOUSE (Continued) **U004177654**

Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	2. Galvanized Steel
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	ohter
Dispenser:	2. Suction

AB295 **COACHMAN HOTEL** **NY LTANKS** **1000912672**
SSE **123 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.204 mi.
1079 ft. **Site 5 of 7 in cluster AB**

Relative: **Higher**
Actual: **236 ft.**

LTANKS:

Spill Number/Closed Date:	9306655 / 1993-09-24
Facility ID:	9306655
Site ID:	211948
Spill Date:	1993-08-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-09-24
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-02
Spill Record Last Update:	1993-11-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175633
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"HOLE IN CROWN OF TANK WILL WORK WITH CTY. TO MAKE SURE NO SOIL CONTAMINATION 8K 35 YEARS OLD TANK W.C. IS LOOKING TO BUY HOTEL"

COACHMAN HOTEL (Continued) **1000912672**

All TTF:

Facility ID:	9306655
Spill Number:	9306655
Spill Tank Test:	1541932
Site ID:	211948
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	211948
Operable Unit ID:	984819
Operable Unit:	01
Material ID:	396502
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AB296 **WESTHAB COACHMAN FAMILY CENTER** **NY UST** **U004177649**
SSE **123 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.204 mi.
1079 ft. **Site 6 of 7 in cluster AB**

Relative: **Higher**

Actual: **236 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-801262 / Unregulated
Operator Name:	Westhab, Inc.
Owner Name:	Westchester County
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	6000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring

WESTHAB COACHMAN FAMILY CENTER (Continued) **U004177649**

Date Installation:	09/01/1993
Date Perm Closure:	04/29/2015
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AB297 **COACHMAN HOTEL** **RCRA-CESQG** **1007111869**
SSE **123 E POST RD** **NY0000895086**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.204 mi.
1079 ft. **Site 7 of 7 in cluster AB**

Relative:
Higher

Actual:
236 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	COACHMAN HOTEL
Facility address:	123 E POST RD WHITE PLAINS, NY 10601
EPA ID:	NY0000895086
Mailing address:	E POST RD WHITE PLAINS, NY 10601
Contact:	FRANK ALEXANDER
Contact address:	E POST RD WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-995-5797
Contact email:	Not reported
EPA Region:	02
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	COUNTY OF WESTCHESTER
Owner/operator address:	148 MARTINE AVE WHITE PLAINS, NY 10601
Owner/operator country:	US

COACHMAN HOTEL (Continued) **1007111869**

Owner/operator telephone: 914-285-2464
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: COACHMAN HOTEL
Owner/operator address: E POST RD
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-995-5797
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: District
Owner/Operator Type: Operator
Owner/Op start date: 12/31/1979
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: COACHMAN HOTEL
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/03/2003
Site name: COACHMAN HOTEL
Classification: Small Quantity Generator

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 07/08/1999
Site name: COACHMAN HOTEL - COUNTY OF WESTCHESTER
Classification: Not a generator, verified

Date form received by agency: 10/20/1994

COACHMAN HOTEL (Continued) **1007111869**

Site name: COACHMAN HOTEL - COUNTY OF WESTCHESTER
Classification: Large Quantity Generator

. Waste code: D008
. Waste name: LEAD

Violation Status: No violations found

AA298 **CON EDISON MANHOLE 4144** **RCRA NonGen / NLR** **1010327462**
NW **BARKER AVE & GROVE ST** **NY MANIFEST** **NYP004146783**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.206 mi.
1088 ft. **Site 2 of 4 in cluster AA**

Relative:
Lower

Actual:
186 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/11/2007
Facility name: CON EDISON MANHOLE 4144
Facility address: BARKER AVE & GROVE ST
WHITE PLAINS, NY 10601
EPA ID: NYP004146783
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: MICHAEL DAUGHTREY
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/10/2007
Site name: CON EDISON
Classification: Not a generator, verified

Date form received by agency: 01/09/2007
Site name: CON EDISON
Classification: Unverified

CON EDISON MANHOLE 4144 (Continued) **1010327462**

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004146783
Facility Status: Not reported
Location Address 1: BARKER ST & GROVE ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004146783
Mailing Name: CONED
Mailing Contact: CONED
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10004
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG299 **CON EDISON MANHOLE** **RCRA NonGen / NLR** **1014398531**
ESE **WALLER AVE & E POST RD** **NY MANIFEST** **NYP004208852**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.207 mi.
1091 ft. **Site 1 of 8 in cluster AG**

Relative:
Higher

Actual:
221 ft.

RCRA NonGen / NLR:
Date form received by agency: 07/17/2010
Facility name: CON EDISON MANHOLE
Facility address: WALLER AVE & E POST RD
54 FT S COR OF E POST RD
WHITE PLAINS, NY 10601
EPA ID: NYP004208852
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: TIMOTHY REGAN
Contact address: Not reported
Not reported
Contact country: US
Contact telephone: 917-416-5436
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

CON EDISON MANHOLE (Continued) **1014398531**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 06/17/2010
Site name: CON EDISON
Classification: Not a generator, verified

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004208852
Facility Status: Not reported
Location Address 1: TM05612 - WALLER AVE & E POST RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004208852
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2010
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 06/17/2010

CON EDISON MANHOLE (Continued) **1014398531**

Trans1 Recv Date:	06/17/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/17/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004208852
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007020924JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	800.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG300 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157642**
ESE **WALLER AVE & EAST POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.207 mi.
1091 ft. **Site 2 of 8 in cluster AG**

Relative: NY MANIFEST:
Higher

Actual: Country:	USA
221 ft. EPA ID:	NYP004229793
Facility Status:	Not reported
Location Address 1:	WALLER AVE & EAST POST RD
Code:	BP
Location Address 2:	Not reported

CONSOLIDATED EDISON (Continued) **S111157642**

Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004229793
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/04/2011
Trans1 Recv Date:	03/04/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/07/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004229793
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655985JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600.0
Units:	P - Pounds

CONSOLIDATED EDISON (Continued) **S111157642**

Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG301 **CON EDISON** **NY MANIFEST** **S118463492**
ESE **POST RD & WALLER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.207 mi.
1091 ft. **Site 3 of 8 in cluster AG**

Relative:
Higher

Actual:
221 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004852394
Facility Status:	Not reported
Location Address 1:	POST RD & WALLER AVE
Code:	BP
Location Address 2:	TM 4540
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004852394
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/13/2015
Trans1 Recv Date:	10/13/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/2015

CON EDISON (Continued) **S118463492**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004852394
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460346JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AH302 **STATION PLAZA** **NY UST** **U003885183**
SW **76 SOUTH LEXINGTON AVENUE** **NY AST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.209 mi.
1102 ft. **Site 1 of 3 in cluster AH**

Relative: WESTCHESTER CO. UST:
Lower

Id/Status:	3-139637 / Administratively Closed
Operator Name:	Resident Supt.
Owner Name:	Station Plaza Housing Co. Mgmt Corp.
Owner Street:	5 West Main Street
Owner Address2:	Not reported
Owner City:	Elmsford
Owner State:	NY
Owner Zipcode:	10523
GDS Number:	Not reported

Actual:
201 ft.

STATION PLAZA (Continued) **U003885183**

Tank Number:	F01
Status:	4. Closed - in place
Capacity:	25000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1976
Date Perm Closure:	05/08/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-139637
Site Status:	Administratively Closed
GDS Number:	Not reported
Operator Name:	Resident Supt.
Owner Name:	Station Plaza Housing Co. Mgmt Corp.
Owner Street:	5 West Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	Elmsford, NY 10523

Tank Number:	DF1
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	DT2
Status:	3. Closed - Removed
Date Installation:	06/01/1998

STATION PLAZA (Continued) **U003885183**

Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Spill Prevention:	Not reported
Dispenser:	2. Suction

AI303 **SAFE FLIGHT INSTRUMENT CORP** **NY UST** **1000196682**
WNW **20 NEW KING ST** **RCRA NonGen / NLR** **NYD001221530**
1/8-1/4 **WHITE PLAINS, NY 10602** **FINDS**
0.209 mi. **ECHO**
1105 ft. **Site 1 of 10 in cluster AI** **NY MANIFEST**

Relative: **Lower**
Actual: **201 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-005754 / Unregulated: <1101 gal. PBS
Operator Name:	Greg Tassio
Owner Name:	Safe Flight Instruction Corp.
Owner Street:	20 New King Street
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	1
Status:	3a. Closed - Prior to 04/1991
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1963
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

SAFE FLIGHT INSTRUMENT CORP (Continued) **1000196682**

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	12/01/1989
Date Perm Closure:	05/11/2005
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Sacrificial Anode (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	SAFE FLIGHT INSTRUMENT CORP
Facility address:	20 NEW KING ST WHITE PLAINS, NY 10602
EPA ID:	NYD001221530
Mailing address:	NEW KING ST PO BOX 550 WHITE PLAINS, NY 10602
Contact:	RICHARD SCHMITT
Contact address:	NEW KING ST PO BOX 550 WHITE PLAINS, NY 10602
Contact country:	US
Contact telephone:	914-946-9500
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LEONARD GREENE
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	LEONARD GREENE
Owner/operator address:	NOT REQUIRED

SAFE FLIGHT INSTRUMENT CORP (Continued) **1000196682**

NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SAFE FLIGHT INSTRUMENT CORP
Classification: Not a generator, verified

Date form received by agency: 06/28/1989
Site name: SAFE FLIGHT INSTRUMENT CORP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

SAFE FLIGHT INSTRUMENT CORP (Continued) **1000196682**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 10/16/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004332696

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000196682
Registry ID: 110004332696
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004332696

NY MANIFEST:
Country: USA
EPA ID: NYD001221530
Facility Status: Not reported
Location Address 1: NEW KING STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10604
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD001221530
Mailing Name: SAFE FLIGHT CORPORATION
Mailing Contact: SAFE FLIGHT CORPORATION
Mailing Address 1: NEW KING STREET
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10604
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9149469500

SAFE FLIGHT INSTRUMENT CORP (Continued) **1000196682**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	PAD982661381
Trans2 State ID:	Not reported
Generator Ship Date:	03/19/2018
Trans1 Recv Date:	03/19/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/23/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD001221530
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	RID040098352
TSDF ID 2:	Not reported
Manifest Tracking Number:	011654916FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	350
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
26 additional NY MANIFEST: record(s) in the EDR Site Report.

AG304 **PIP PRINTING** **RCRA NonGen / NLR** **1000890260**
ESE **190 E POST RD** **FINDS** **NY0000298893**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.212 mi. **NY MANIFEST**
1118 ft. **Site 4 of 8 in cluster AG**

Relative:
Higher

Actual:
220 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	PIP PRINTING
Facility address:	190 E POST RD WHITE PLAINS, NY 10601
EPA ID:	NY0000298893
Mailing address:	E POST RD WHITE PLAINS, NY 10601
Contact:	DON FEDER
Contact address:	E POST RD WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-993-9007
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DON FEDER
Owner/operator address:	190 E POST RD WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-993-9007
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DON FEDER
Owner/operator address:	190 E POST RD WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-993-9007
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

PIP PRINTING (Continued) **1000890260**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PIP PRINTING
Classification: Not a generator, verified

Date form received by agency: 05/18/1994
Site name: PIP PRINTING
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110004315296

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000890260
Registry ID: 110004315296
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004315296

NY MANIFEST:
Country: USA

PIP PRINTING (Continued) **1000890260**

EPA ID:	NY0000298893
Facility Status:	Not reported
Location Address 1:	190 EAST POST RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000298893
Mailing Name:	PIP PRINTING
Mailing Contact:	DONAL FEDER
Mailing Address 1:	190 EAST POST RD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149939007

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	12/17/2010
Trans1 Recv Date:	12/17/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/29/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000298893
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJ0000381962
TSDF ID 2:	Not reported
Manifest Tracking Number:	003881864FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H010
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

PIP PRINTING (Continued) **1000890260**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	250.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1.0
Waste Code:	D011
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG305 **PUCKHINKONNUCK CORP.** **NY UST U004177169**
ESE **190 EAST POST ROAD** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.212 mi.
1118 ft. **Site 5 of 8 in cluster AG**

Relative: **Higher**
Actual: **220 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-032476 / Active
Operator Name:	Eagle Service Corp.
Owner Name:	Puckhinkonnuk Corp.
Owner Street:	855 Lexington Avenue, 3rd Floor
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10065
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	7500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/26/2001
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

PUCKHINKONNUCK CORP. (Continued) **U004177169**

WESTCHESTER CO. AST:

PBS Number:	3-032476
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Eagle Service Corp.
Owner Name:	Puckhinkonnuk Corp.
Owner Street:	855 Lexington Avenue, 3rd Floor
Owner Address2:	Not reported
Owner City/State/Zip:	New York, NY 10065
Tank Number:	2
Status:	1. In-Service
Date Installation:	07/01/2001
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

AI306 **COMMERICAL BUILDING** **NY LTANKS** **S118953530**
WNW **10 NEW KING STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.216 mi.
1139 ft. **Site 2 of 10 in cluster AI**

Relative: **Lower**
Actual: **201 ft.**

LTANKS:

Spill Number/Closed Date:	1006070 / 2010-10-28
Facility ID:	1006070
Site ID:	439407
Spill Date:	2010-09-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-09-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

COMMERICAL BUILDING (Continued) **S118953530**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-01
Spill Record Last Update:	2010-10-28
Spiller Name:	KAREN GOMEZ
Spiller Company:	BENEROFE GROUP
Spiller Address:	10 NEW KING STREET
Spiller County:	999
Spiller Contact:	KAREN GOMEZ
Spiller Phone:	(914) 681-5100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	394398
DEC Memo:	"9-1-10 Spoke with Bob. He says the leak appears to be very minor. They will uncover tank and investigate cause of tank test failure - then repair and retest. This is a 10k UST. 10/28/10 Pased Retest 9/24/10 NFA JO'M"
Remarks:	"The tank is located underground and failed the tank test. Benerofe group is the responsible party."

All Materials:

Site ID:	439407
Operable Unit ID:	1190052
Operable Unit:	01
Material ID:	2185019
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AC307 **WESTCHESTER HOBBIES INC** **RCRA NonGen / NLR** **1001223849**
SSE **104 E POST RD** **FINDS** **NYR000050658**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.216 mi.
1140 ft. **Site 3 of 17 in cluster AC**

Relative:
Higher

Actual:
242 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WESTCHESTER HOBBIES INC
Facility address:	104 E POST RD WHITE PLAINS, NY 10601-5103
EPA ID:	NYR000050658
Mailing address:	E POST RD WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	E POST RD WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

WESTCHESTER HOBBIES INC (Continued) **1001223849**

Owner/Operator Summary:
Owner/operator name: RONALD MIHLRAD
Owner/operator address: 104 E POST RD
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 516-486-2313
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: RONALD MIHLRAD
Owner/operator address: 104 E POST RD
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 516-486-2313
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WESTCHESTER HOBBIES INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WESTCHESTER HOBBIES INC
Classification: Not a generator, verified

Date form received by agency: 02/17/1998
Site name: WESTCHESTER HOBBIES INC
Classification: Small Quantity Generator

WESTCHESTER HOBBIES INC (Continued) **1001223849**

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D018
. Waste name: BENZENE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110004540471

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001223849
Registry ID: 110004540471
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004540471

---

308 East 1/8-1/4 0.216 mi. 1142 ft.

WHITE PLAINS CITY OF
MARTINE AVE PUBLIC LIBRARY
WHITE PLAINS, NY 10601

RCRA NonGen / NLR **1000552793**
NYD986951986

Relative: Higher
Actual: 220 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: WHITE PLAINS CITY OF
Facility address: MARTINE AVE PUBLIC LIBRARY
WHITE PLAINS, NY 10601

WHITE PLAINS CITY OF (Continued) **1000552793**

EPA ID: NYD986951986
Mailing address: MAIN ST NY POWER AUTH
WHITE PLAINS, NY 10601
Contact: Not reported
Contact address: MAIN ST NY POWER AUTH
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CITY OF WHITE PLAINS
Owner/operator address: 255 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-422-1210
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CITY OF WHITE PLAINS
Owner/operator address: 255 MAIN ST
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-422-1210
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

WHITE PLAINS CITY OF (Continued) **1000552793**

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS CITY OF
Classification: Not a generator, verified

Date form received by agency: 12/07/1994
Site name: WHITE PLAINS CITY OF
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 05/15/1991
Site name: WHITE PLAINS CITY OF
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D008
. Waste name: LEAD

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

AD309 **WHITE PLAINS GENL AUTO REP INC** **RCRA NonGen / NLR** **1000397517**
WNW **76 HAMILTON AVE** **FINDS** **NYD013395397**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.216 mi.
1142 ft. **Site 4 of 6 in cluster AD**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:
Date form received by agency: 01/01/2007
Facility name: WHITE PLAINS GENL AUTO REP INC
Facility address: 76 HAMILTON AVE
WHITE PLAINS, NY 10601-1702
EPA ID: NYD013395397
Mailing address: HAMILTON AVE
WHITE PLAINS, NY 10601
Contact: Not reported
Contact address: HAMILTON AVE
WHITE PLAINS, NY 10601
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: SUN OIL COMPANY OF PENNSYLVANIA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212

WHITE PLAINS GENL AUTO REP INC (Continued) **1000397517**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: SUN OIL COMPANY OF PENNSYLVANIA
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS GENL AUTO REP INC
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: WHITE PLAINS GENL AUTO REP INC
Classification: Not a generator, verified

Date form received by agency: 08/18/1980
Site name: WHITE PLAINS GENL AUTO REP INC
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

WHITE PLAINS GENL AUTO REP INC (Continued) **1000397517**

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110004348411

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000397517
Registry ID: 110004348411
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004348411

AD310 **CON EDISON MANHOLE 5562** **RCRA NonGen / NLR** **1010326336**
WNW **LEXINGTON AVE & NEW ST** **NYP004140646**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.217 mi.
1148 ft. **Site 5 of 6 in cluster AD**

Relative:
Lower

Actual:
201 ft.

RCRA NonGen / NLR:
Date form received by agency: 08/30/2006
Facility name: CON EDISON MANHOLE 5562
Facility address: LEXINGTON AVE & NEW ST
WHITE PLAINS, NY 10601
EPA ID: NYP004140646
Mailing address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact: ARTHUR HUDMAN
Contact address: 4 IRVING PL, RM 828
NEW YORK, NY 10003
Contact country: US
Contact telephone: 212-580-8383
Contact email: Not reported
EPA Region: 02
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No

CON EDISON MANHOLE 5562 (Continued) **1010326336**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	08/29/2006
Site name:	CON EDISON
Classification:	Not a generator, verified
Date form received by agency:	08/28/2006
Site name:	CON EDISON
Classification:	Unverified
Violation Status:	No violations found

AD311 **CONSOLIKDATED EDISON** **NY MANIFEST** **S108933464**
WNW **NEW ST & LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.217 mi.
1148 ft. **Site 6 of 6 in cluster AD**

Relative: **Lower**
Actual: **201 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004139705
Facility Status:	Not reported
Location Address 1:	NEW ST & LEXINGTON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004139705
Mailing Name:	CONSOLIKDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

CONSOLIKDATED EDISON (Continued) **S108933464**

Document ID:	NYE1606869
Manifest Status:	Not reported
seq:	01
Year:	2006
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2006
Trans1 Recv Date:	02/08/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004139705
Trans1 EPA ID:	12446JT
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W312 **VAULT 6174** **NY LTANKS** **S102233627**
NNE **400 HAMILTON AVENUE** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.218 mi.
1149 ft. **Site 4 of 10 in cluster W**

Relative: LTANKS:
Higher

Spill Number/Closed Date:	9604857 / 1996-07-22
Facility ID:	9604857
Site ID:	72317
Spill Date:	1996-07-15
Spill Cause:	Tank Failure

Actual:
234 ft.

VAULT 6174 (Continued) **S102233627**

Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-07-15
CID:	297
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-07-15
Spill Record Last Update:	1996-09-05
Spiller Name:	UNKNOWN
Spiller Company:	AT&T TELEPHONE COMPANY
Spiller Address:	400 HAMILTON AV
Spiller County:	001
Spiller Contact:	RICHARD EGAN
Spiller Phone:	(201) 933-5541
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	60149
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 07/22/96 STEVE PONZA FROM TRC ENVIRONMENTAL REPORTED THE SPILL RESULTED FROM AN OLD LINE THAT WAS BROKEN DURING THE TANK REMOVAL SPILL HAS BEEN CLEANED UP "
Remarks:	"CALLER COMPLETED A TANK REMOVAL ON FRIDAY 7/12/96 AND THEY FOUND NO CONTAMINATION - TODAY THEY RETURNED TO THE WORK SITE A FOUND WHAT LOOKS LIKE WASTE OIL COMING FROM AN UNKNOWN SOURCE"

All Materials:

Site ID:	72317
Operable Unit ID:	1035809
Operable Unit:	01
Material ID:	347610
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9610406 / 1996-11-19
Facility ID:	9610406
Facility Type:	ER
DER Facility ID:	60149
Site ID:	61995
DEC Region:	3
Spill Cause:	Housekeeping

VAULT 6174 (Continued) **S102233627**

Spill Class:	C4
SWIS:	6017
Spill Date:	1996-11-19
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-11-19
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-11-19
Spill Record Last Update:	1996-12-16
Spiller Name:	FRAN MAJEAU
Spiller Company:	AT&T CORPORATION
Spiller Address:	400 HAMILTON AVENUE
Spiller Company:	001
Contact Name:	FRAN MAJEAU
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND DURING TANK REMOVAL. FOUR OTHER TANKS TO BE REMOVED STILL. CROSS REFERENCE TO SPILL NUMBER 9604857 FROM PHASE 1 OF PROJECT."

All Materials:

Site ID:	61995
Operable Unit ID:	1038303
Operable Unit:	01
Material ID:	342618
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0507082 / 2005-09-12
Facility ID:	0507082
Facility Type:	ER
DER Facility ID:	60149
Site ID:	352409
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	2005-09-12
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-09-12
CID:	444

VAULT 6174 (Continued) **S102233627**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-12
Spill Record Last Update:	2005-09-21
Spiller Name:	ERT DESK'
Spiller Company:	VAULT#6174
Spiller Address:	400 HAMILTON AVE
Spiller Company:	001
Contact Name:	ERT DESK'
DEC Memo:	"Cable leak. To fix leak equipment has to be replace in an confine space. Leak is contained ConEd arranging equipment and personell to fix the leak."
Remarks:	"FOUND 1 OUNCE ON TOP OF A TRANSFORMER FROM A LEAKY DEFAULT: NO TO 5 QUESTIONS: CONED # 160995"

All Materials:

Site ID:	352409
Operable Unit ID:	1109910
Operable Unit:	01
Material ID:	2099927
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0010086 / 2000-12-07
Facility ID:	0010086
Facility Type:	ER
DER Facility ID:	60149
Site ID:	188187
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2000-12-07
Investigator:	DVWEHRFR
Referred To:	Not reported
Reported to Dept:	2000-12-07
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False

VAULT 6174 (Continued) **S102233627**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-07
Spill Record Last Update:	2000-12-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WEHRFRITZ "
Remarks:	"10 OUNCES SPILLED FROM LEAKING JOINT - CASE #134659"

All Materials:

Site ID:	188187
Operable Unit ID:	831061
Operable Unit:	01
Material ID:	544008
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0010088 / 2000-12-07
Facility ID:	0010088
Facility Type:	ER
DER Facility ID:	60149
Site ID:	188188
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2000-12-07
Investigator:	DVWEHRFR
Referred To:	Not reported
Reported to Dept:	2000-12-07
CID:	312
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-07
Spill Record Last Update:	2000-12-21
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	Not reported

VAULT 6174 (Continued) **S102233627**

DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WEHRFRITZ "
Remarks:	"12 OUNCES FROM LEAKING JOINT - CASE #134660"

All Materials:

Site ID:	188188
Operable Unit ID:	832202
Operable Unit:	01
Material ID:	544010
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9606368 / 1996-08-17
Facility ID:	9606368
Facility Type:	ER
DER Facility ID:	60149
Site ID:	188189
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	1996-08-17
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-08-17
CID:	257
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-17
Spill Record Last Update:	1996-10-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MR FEDORCZAK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/17/96 LESS THAN REPORTABLE"
Remarks:	"fire dept still on scene caller has no further info at this time"

All Materials:

Site ID:	188189
Operable Unit ID:	1034164
Operable Unit:	01
Material ID:	345628

VAULT 6174 (Continued) **S102233627**

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9416809 / 2013-07-19
Facility ID:	9416809
Facility Type:	ER
DER Facility ID:	60149
Site ID:	189820
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-03-27
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-03-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2013-07-19
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTRACTOR DUGGING BELOW BUILDING DISCOVERED CONTAMINATED SOIL"

All Materials:

Site ID:	189820
Operable Unit ID:	1013927
Operable Unit:	01
Material ID:	371955
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

W313 **WHITE PLAINS LL CENTRAL OFFICE** **RCRA NonGen / NLR** **1000397521**
NNE **400 HAMILTON AVE** **NYD980529192**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 5 of 10 in cluster W**

Relative:
Higher

Actual:
234 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WHITE PLAINS LL CENTRAL OFFICE
Facility address:	400 HAMILTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYD980529192
Mailing address:	HAMILTON AVE WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	HAMILTON AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No

WHITE PLAINS LL CENTRAL OFFICE (Continued) **1000397521**

On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS LL CENTRAL OFFICE
Classification: Not a generator, verified

Date form received by agency: 12/31/1979
Site name: WHITE PLAINS LL CENTRAL OFFICE
Classification: Unverified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

W314 **AT&T** **RCRA-SQG** **1000392648**
NNE **400 HAMILTON AVE** **NY MANIFEST** **NYD070955828**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 6 of 10 in cluster W**

Relative:
Higher

Actual:
234 ft.

RCRA-SQG:
Date form received by agency: 09/07/2010
Facility name: AT&T
Facility address: 400 HAMILTON AVE
WHITE PLAINS, NY 10601
EPA ID: NYD070955828
Mailing address: RRC RECORDKEEPER RM 2C140
BEDMINSTER, NJ 07921
Contact: GEOFF SMITH
Contact address: RRC RECORDKEEPER RM 2C140
BEDMINSTER, NJ 07921
Contact country: US
Contact telephone: 800-566-9347
Contact email: EHSRRC@LIST.ATT.COM
EPA Region: 02
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: AT&T LONG LINES DEPARTMENT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212

AT&T (Continued) **1000392648**

Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AT&T LONG LINES DEPARTMENT
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AT &T
Owner/operator address: SOUTH AKARD
DALLAS, TX 75202
Owner/operator country: US
Owner/operator telephone: 800-566-9347
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: 4
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 11/01/2005
Owner/Op end date: Not reported

Owner/operator name: AT &T
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 11/01/2005
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No

AT&T (Continued) **1000392648**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 01/01/2007
Site name: AT&T LONG LINES DEPT/WHIT
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: AT&T LONG LINES DEPT/WHIT
Classification: Not a generator, verified

Date form received by agency: 02/12/1981
Site name: AT&T LONG LINES DEPT/WHIT
Classification: Not a generator, verified

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD070955828
Facility Status: Not reported
Location Address 1: 400 HAMILTON AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD070955828
Mailing Name: AT&T LONG LINES DEPT/WHIT
Mailing Contact: OPERATIONS MANAGER
Mailing Address 1: 400 HAMILTON AVE300C ROOM
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY

AT&T (Continued) **1000392648**

Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9143283472

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	12/02/2010
Trans1 Recv Date:	12/02/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/02/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD070955828
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001057614GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	80.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AT&T (Continued) **1000392648**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W315 **CON EDISON** **NJ MANIFEST** **S111074598**
NNE **400 HAMILTON AVE & EJ CONROY DR** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 7 of 10 in cluster W**

Relative:
Higher

Actual:
234 ft.

NJ MANIFEST:

EPA Id:	NYD070955828
Mail Address:	P O BOX 25000
Mail City/State/Zip:	GREENSBORO 27420
Facility Phone:	9192794899
Emergency Phone:	Not reported
Contact:	Not reported
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001057614GBF
EPA ID:	NYD070955828
Date Shipped:	12/02/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	12/02/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	12/02/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported

CON EDISON (Continued) **S111074598**

Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	GREENSBORO 27420
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H141
Quantity:	80 P

EPA Id:	NYP004763926
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	011692712JJK
EPA ID:	NYP004763926
Date Shipped:	4/7/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S111074598**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

W316 **WHITE PLAINS LL CENTRAL OFFICE** **RCRA NonGen / NLR** **1000397520**
NNE **400 HAMILTON AVE** **NY MANIFEST** **NYD980525919**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 8 of 10 in cluster W**

Relative:
Higher

Actual:
234 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	WHITE PLAINS LL CENTRAL OFFICE
Facility address:	400 HAMILTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYD980525919
Mailing address:	HAMILTON AVE RM 300C EPA WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	HAMILTON AVE RM 300C EPA WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	Not reported
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private

WHITE PLAINS LL CENTRAL OFFICE (Continued) **1000397520**

Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: Not reported
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: WHITE PLAINS LL CENTRAL OFFICE
Classification: Not a generator, verified

Date form received by agency: 10/24/1995
Site name: WHITE PLAINS LL CENTRAL OFFICE
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Date form received by agency: 09/15/1981
Site name: WHITE PLAINS LL CENTRAL OFFICE
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A

WHITE PLAINS LL CENTRAL OFFICE (Continued) **1000397520**

CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYD980525919
Facility Status: Not reported
Location Address 1: 400 HAMILTON AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD980525919
Mailing Name: AMERICAN TELEPHONE & TELEGRAPH
Mailing Contact: AMERICAN TELEPHONE & TELEGRAPH
Mailing Address 1: 400 HAMILTON AVENUE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9143975210

NY MANIFEST:
Document ID: PAB0621456
Manifest Status: K
seq: Not reported
Year: 1988
Trans1 State ID: PA-AHS-81
Trans2 State ID: PA-AH
Generator Ship Date: 01/07/1988
Trans1 Recv Date: 01/07/1988
Trans2 Recv Date: / /
TSD Site Recv Date: 01/17/1988
Part A Recv Date: 01/12/1988
Part B Recv Date: 02/10/1988
Generator EPA ID: NYD980525919
Trans1 EPA ID: NJD067387175
Trans2 EPA ID: Not reported
TSDF ID 1: PAD990753089
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported

WHITE PLAINS LL CENTRAL OFFICE (Continued) **1000397520**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	47250
Units:	P - Pounds
Number of Containers:	027
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W317 **CON EDISON - VAULT 5669** **RCRA NonGen / NLR** **1010325915**
NNE **400 HAMILTON AVE** **NY MANIFEST** **NYP004135695**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 9 of 10 in cluster W**

Relative: **Higher**

Actual: **234 ft.**

RCRA NonGen / NLR:

Date form received by agency:	02/23/2006
Facility name:	CON EDISON - VAULT 5669
Facility address:	400 HAMILTON AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004135695
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLIN MURRAY
Contact address:	4 IRVING PLACE NEW YORK, NY 10003
Contact country:	US
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported

CON EDISON - VAULT 5669 (Continued) **1010325915**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/21/2005
Owner/Op end date: Not reported

Owner/operator name: CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address: 4 IRVING PLACE
NEW YORK, NY 10003
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 09/21/2005
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/22/2006
Site name: CON EDISON - VAULT 5669
Classification: Not a generator, verified

Date form received by agency: 02/21/2006
Site name: CON EDISON - VAULT 5669
Classification: Large Quantity Generator

. Waste code: B002
. Waste name: B002

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004135695
Facility Status: Not reported
Location Address 1: VAULT 5669-400 HAMILTON AVE
Code: BP

CON EDISON - VAULT 5669 (Continued) **1010325915**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004135695
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	NYE0628803
Manifest Status:	Not reported
seq:	Not reported
Year:	2005
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/21/2005
Trans1 Recv Date:	09/21/2005
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/21/2005
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004135695
Trans1 EPA ID:	46233JM
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01173

CON EDISON - VAULT 5669 (Continued) **1010325915**

Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

W318 **CON EDISON** **NY MANIFEST** **S118089911**
NNE **400 HAMILTON AVE & EJ CONROY D** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.218 mi.
1149 ft. **Site 10 of 10 in cluster W**

Relative:
Higher

Actual:
234 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004763926
Facility Status:	Not reported
Location Address 1:	HAMI HON AVE & ?
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004763926
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/07/2015
Trans1 Recv Date:	04/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004763926
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported

CON EDISON (Continued) **S118089911**

TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692712JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AJ319 **CON EDISON MANHOLE: 4147** **RCRA NonGen / NLR** **1016963587**
North **BARKER AVE & CHURCH ST** **NY MANIFEST** **NYP004365813**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.218 mi.
1152 ft. **Site 1 of 4 in cluster AJ**

Relative: RCRA NonGen / NLR:
Higher

Actual: Date form received by agency: 10/25/2013
218 ft.

Facility name:	CON EDISON MANHOLE: 4147
Facility address:	BARKER AVE & CHURCH ST WHITE PLAINS, NY 10606
EPA ID:	NYP004365813
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02

CON EDISON MANHOLE: 4147 (Continued) **1016963587**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/25/2013
Site name: CON EDISON MANHOLE: 4147
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004365813
Facility Status: Not reported
Location Address 1: BARKER & CHURCH
Code: BP
Location Address 2: MH4147
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004365813
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PLACE
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON MANHOLE: 4147 (Continued) **1016963587**

Year:	2013
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/25/2013
Trans1 Recv Date:	09/25/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/03/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004365813
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695938JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AJ320 **CON EDISON SERVICE BOX: 7962** **RCRA NonGen / NLR** **1016971335**
North **BARKER AVE & CHURCH ST** **NY MANIFEST** **NYP004450730**
1/8-1/4 **WHITE PLAINS, NY 10607**
0.218 mi.
1152 ft. **Site 2 of 4 in cluster AJ**

Relative:
Higher

Actual:
218 ft.

RCRA NonGen / NLR:

Date form received by agency:	03/25/2014
Facility name:	CON EDISON SERVICE BOX: 7962
Facility address:	BARKER AVE & CHURCH ST WHITE PLAINS, NY 10607
EPA ID:	NYP004450730
Mailing address:	IRVING PL, 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/25/2014
Site name:	CON EDISON SERVICE BOX: 7962
Classification:	Conditionally Exempt Small Quantity Generator
Violation Status:	No violations found

NY MANIFEST:

Country:	USA
EPA ID:	NYP004450730
Facility Status:	Not reported
Location Address 1:	BARKER AVE & CHURCH ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801

CON EDISON SERVICE BOX: 7962 (Continued) **1016971335**

Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004450730
Mailing Name: CON EDISON
Mailing Contact: CON EDISION
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2014
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 02/25/2014
Trans1 Recv Date: 02/25/2014
Trans2 Recv Date: Not reported
TSD Site Recv Date: 02/25/2014
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004450730
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 012772730JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H110
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Quantity: 50
Units: P - Pounds
Number of Containers: 1
Container Type: TT - Cargo tank, tank trucks
Handling Method: T Chemical, physical, or biological treatment.
Specific Gravity: 1

CON EDISON SERVICE BOX: 7962 (Continued) **1016971335**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AA321 **PEPE CADILLAC** **NY AST** **A100379823**
NW **15 WATER STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.219 mi.
1158 ft. **Site 3 of 4 in cluster AA**

Relative: **Lower**
Actual: **185 ft.**

WESTCHESTER CO. AST:

PBS Number:	3-801848
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Bob O'Connell
Owner Name:	Mr.Joseph Pepe
Owner Street:	15 Water Street
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/2013
Capacity:	500
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	3A
Status:	1. In-Service
Date Installation:	01/01/2013
Capacity:	500
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle

PEPE CADILLAC (Continued) **A100379823**

Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	9. Exempt suction piping
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

Tank Number:	3B
Status:	1. In-Service
Date Installation:	01/01/2013
Capacity:	200
Product Stored:	0021. Transmission Fluid
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AA322 **PEPE CADILLAC** **NY UST** **U004195985**
NW **15 WATER STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.219 mi.
1158 ft. **Site 4 of 4 in cluster AA**

Relative: WESTCHESTER CO. UST:
Lower

Actual: **185 ft.**

Id/Status:	3-801848 / Active
Operator Name:	Bob O'Connell
Owner Name:	Mr.Joseph Pepe
Owner Street:	15 Water Street
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported

Tank Number:	1A
Status:	1. In-Service
Capacity:	3000
Product Stored:	0009. Gasoline

PEPE CADILLAC (Continued) **U004195985**

Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	10/01/2012
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	Not reported
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	1B
Status:	1. In-Service
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	10/01/2012
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

AI323 **OFFICE BLDG** **NY LTANKS** **S103558242**
WNW **4 NEW KING ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.220 mi.
1160 ft. **Site 3 of 10 in cluster AI**

Relative: LTANKS:
Lower

Actual: Spill Number/Closed Date:	9809692 / 2003-12-05
201 ft. Facility ID:	9809692
Site ID:	170684
Spill Date:	1998-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-02

OFFICE BLDG (Continued) **S103558242**

CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-02
Spill Record Last Update:	2003-12-05
Spiller Name:	Not reported
Spiller Company:	OFFICE BLDG
Spiller Address:	4 NEW KING ST
Spiller County:	001
Spiller Contact:	TOM CAFFERTY
Spiller Phone:	(914) 697-7654
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	143629
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MCDONALD 12/05/03 CLOSED BY BARBARA McDONALD OF WCHD. TANK REMOVED JANUARY OF 1999."
Remarks:	"REOMMEND UNCOVER TANK - ISOLATE FOR RETEST"

All TTF:

Facility ID:	9809692
Spill Number:	9809692
Spill Tank Test:	1546478
Site ID:	170684
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	170684
Operable Unit ID:	1066903
Operable Unit:	01
Material ID:	313593
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI324 **WHITE PLAINS MGP SITE** **EDR MGP** **1008408071**
WNW **9 NEW STREET AND 12 WATER STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.220 mi.
1160 ft. **Site 4 of 10 in cluster AI**

Relative:
Lower

Actual:
201 ft.

Manufactured Gas Plants:
No additional information available

AI325 **CONSOLIDATED EDISON** **NY MANIFEST** **S117537516**
WNW **9 NEW STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.220 mi.
1160 ft. **Site 5 of 10 in cluster AI**

Relative:
Lower

Actual:
201 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004700894
Facility Status:	Not reported
Location Address 1:	9 NEW ST
Code:	BP
Location Address 2:	MH186
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004700894
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/2014
Trans1 Recv Date:	12/01/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/02/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004700894
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046

CONSOLIDATED EDISON (Continued) **S117537516**

TSDF ID 2:	Not reported
Manifest Tracking Number:	012773417JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Country:	USA
EPA ID:	NYR000023275
Facility Status:	Not reported
Location Address 1:	9 9 NEW STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000023275
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

CONSOLIDATED EDISON (Continued) **S117537516**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	07/03/2018
Trans1 Recv Date:	07/03/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/06/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000023275
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	012167411FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1600
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	D008
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
3 additional NY MANIFEST: record(s) in the EDR Site Report.

AI326 **CON EDISON - WHITE PLAINS SUBSTATION** **RCRA-SQG** **1001113337**
WNW **9 NEW STREET** **NYR000023275**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.220 mi.
1160 ft. **Site 6 of 10 in cluster AI**

Relative:
Lower

Actual:
201 ft.

RCRA-SQG:

Date form received by agency:	01/01/2007
Facility name:	CON EDISON - WHITE PLAINS SUBSTATION
Facility address:	9 NEW STREET WHITE PLAINS, NY 10601
EPA ID:	NYR000023275
Mailing address:	4 IRVING PLACE NEW YORK, NY 10003
Contact:	FRANKLIN MURRAY
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	212-460-2808
Contact email:	MURRAYFR@CONED.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1925
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2002
Owner/Op end date:	Not reported

Owner/operator name:	CONSOLIDATED EDISON COMPANY OF NY, INC.
Owner/operator address:	4 IRVING PLACE NEW YORK, NY 10003
Owner/operator country:	US

CON EDISON - WHITE PLAINS SUBSTATION (Continued) **1001113337**

Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2002
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 02/21/2006
Site name: CON EDISON - WHITE PLAINS SUBSTATION
Classification: Large Quantity Generator

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: B007
. Waste name: B007

Date form received by agency: 02/20/2006
Site name: CON EDISON - WHITE PLAINS SUBSTATION
Classification: Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: CON EDISON - WHITE PLAINS SUBSTATION
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET,

CON EDISON - WHITE PLAINS SUBSTATION (Continued) **1001113337**

WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: B004
. Waste name: B004

. Waste code: B007
. Waste name: B007

Date form received by agency: 05/31/2002
Site name: CON EDISION - WHITE PLAINS SUBSTATION
Classification: Large Quantity Generator

Date form received by agency: 07/14/1999
Site name: CON EDISON - WHITE PLAINS SUBSTATION
Classification: Small Quantity Generator

Date form received by agency: 05/02/1996
Site name: CON EDISON - WHITE PLAINS SUBSTATION
Classification: Large Quantity Generator

. Waste code: X002
. Waste name: POLYCHLORINATED BIPHENOLS (PCBs)

Violation Status: No violations found

AG327 **SPILL NUMBER 9900622** **NY LTANKS** **S104620122**
SE **179 EAST COAST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.221 mi.
1165 ft. **Site 6 of 8 in cluster AG**

Relative:
Higher

Actual:
223 ft.

LTANKS:

Spill Number/Closed Date:	9900622 / 2000-03-24
Facility ID:	9900622
Site ID:	260731
Spill Date:	1999-04-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-04-16
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-04-16
Spill Record Last Update:	2000-03-30
Spiller Name:	ANN WEST
Spiller Company:	Not reported
Spiller Address:	179 EAST COAST RD
Spiller County:	001
Spiller Contact:	ANN WEST
Spiller Phone:	(914) 946-2370
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 4/16/99 NES REMOVING CONTAMINATED SOIL 03/24/2000 NES DISPOSED OF TANK AND 3.65 TONS OF CONTAMINATED SOIL. NFA "
Remarks:	"550GAL VAULTED TANK IN BASEMENT FULL OF HOLES - LEAKED INTO SAND BELOW THE TANK"

All Materials:

Site ID:	260731
Operable Unit ID:	1079395
Operable Unit:	01
Material ID:	307749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI328 **CE - WHITE PLAINS MGP** **NY ENG CONTROLS** **S106906513**
NW **9 NEW STREET AND 12 WATER STREET** **NY INST CONTROL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY VCP**
0.221 mi.
1166 ft. **Site 7 of 10 in cluster AI**

Relative: **Lower**
Actual: **186 ft.**

ENG CONTROLS:

Site Code:	58617
HW Code:	V00438
Control Code:	13
Control Type:	ENG
Date Record Added:	06/19/2008
Date Rec Updated:	04/10/2018
Updated By:	GWCROSS
Site Description:	The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

CE - WHITE PLAINS MGP (Continued) **S106906513**

Env Problem:	The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
	Not reported
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-10-18 16:09:00
Record Upd:	2012-10-18 16:09:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	03
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 06901
Owner Country:	United States of America
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00438
Waste Type:	COAL TAR

CE - WHITE PLAINS MGP (Continued) **S106906513**

Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Site Code:	58617
HW Code:	V00438
Control Code:	15
Control Type:	ENG
Date Record Added:	06/19/2008
Date Rec Updated:	04/10/2018
Updated By:	GWCROSS
Site Description:	The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the

CE - WHITE PLAINS MGP (Continued) **S106906513**

	remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.
Env Problem:	The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
	Not reported
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2012-10-18 16:09:00
Record Upd:	2012-10-18 16:09:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	03
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 06901
Owner Country:	United States of America
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00438
Waste Type:	COAL TAR

CE - WHITE PLAINS MGP (Continued) **S106906513**

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

INST CONTROL:
Site Code: 58617
Control Name: Soil Management Plan
HW Code: V00438
Control Code: 14
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/10/2018
Updated By: GWCROSS
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet

CE - WHITE PLAINS MGP (Continued) **S106906513**

below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
Not reported
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-10-18 16:09:00
Record Upd: 2012-10-18 16:09:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: 03
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 06901

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner Country: United States of America
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Site Code: 58617
Control Name: Landuse Restriction
HW Code: V00438
Control Code: 25
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/10/2018
Updated By: GWCROSS
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management

CE - WHITE PLAINS MGP (Continued) **S106906513**

plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
Not reported
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-10-18 16:09:00
Record Upd: 2012-10-18 16:09:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: 03
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: Owner

CE - WHITE PLAINS MGP (Continued) **S106906513**

Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 06901
Owner Country: United States of America
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Site Code: 58617
Control Name: Ground Water Use Restriction
HW Code: V00438
Control Code: 08
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/10/2018
Updated By: GWCROSS
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which

CE - WHITE PLAINS MGP (Continued) **S106906513**

is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
Not reported
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-10-18 16:09:00
Record Upd: 2012-10-18 16:09:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: 03
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 06901
Owner Country: United States of America
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Site Code: 58617
Control Name: Deed Restriction
HW Code: V00438
Control Code: A
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/10/2018
Updated By: GWCROSS
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic

CE - WHITE PLAINS MGP (Continued) **S106906513**

hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
Not reported
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 2012-10-18 16:09:00
Record Upd: 2012-10-18 16:09:00
Updated By: ldennist
Own Op: Applicant/Requestor
Sub Type: 03
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: Owner
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 06901
Owner Country: United States of America
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: V00438
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

VCP:
Program Type: VCP
Site Code: 58617
HW Code: V00438
Site Class: C
SWIS: 6017
Region: 3
Town: White Plains (c)
Acres: Not reported
Date Record Added: 02/22/2001
Date Record Updated: 04/10/2018
Updated By: GWCROSS
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the MGP site and the off-site area to the south

CE - WHITE PLAINS MGP (Continued) **S106906513**

which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by MGP operations, including DNAPL MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 IRM by installing a down-gradient NAPL cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 08, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the FER was approved in May 2012.
Not reported
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported

CE - WHITE PLAINS MGP (Continued) **S106906513**

Dell:	Not reported
Record Add:	2012-10-18 16:09:00
Record Upd:	2012-10-18 16:09:00
Updated By:	ldennist
Own Op:	Applicant/Requestor
Sub Type:	03
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 06901
Owner Country:	United States of America
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	V00438
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

AI329 **CONSOLIDATED EDISON** **NY MANIFEST** **S111158158**
NW **12 WATER ST - MH 5617** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.221 mi.
1166 ft. **Site 8 of 10 in cluster AI**

Relative: NY MANIFEST:
Lower

Country:	USA
EPA ID:	NYP004237859
Facility Status:	Not reported
Location Address 1:	12 WATER ST - MH 5617

Actual:
186 ft.

CONSOLIDATED EDISON (Continued) **S111158158**

Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004237859
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AI330 **NUCLEAR DEVELOPMENT CORP. OF AMERICA** **FUSRAP** **1016603375**
WNW **5 NEW STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.222 mi.
1173 ft. **Site 9 of 10 in cluster AI**

Relative: **Lower**
Actual: **201 ft.**

FUSRAP:
Site Name: NUCLEAR DEVELOPMENT CORP. OF AMERICA
Site Id: NY.32
Site Status: Eliminated from consideration under FUSRAP
Designated Name: Not Designated
Alternate Name: None
Location Street Address: 5 NEW STREET
Location City: WHITE PLAINS
Location State: NY
Location County: Not reported
Evaluation Year: 1987
Site Oprerations: Conducted experiments involving uranium recovery from scrap.
Site Disposition: Eliminated - No Authority - Facility was licensed to handle nuclear materials
Radioactice Materials Handled: Yes
Primary Radioactivce Materials Handled: Uranium
Radiological Survey(S): None Indicated
Long Term Care Requirements: Not reported
Historical Operations: Not reported
Website URL: www.lm.doe.gov/Considered_Sites/Nuclear_Development_Corp_of_America_-_NY_32.aspx

AI331 **SPILL NUMBER 0000953** **NY LTANKS** **S104621025**
WNW **1 NEW KING STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.225 mi.
1186 ft. **Site 10 of 10 in cluster AI**

Relative:
Lower

Actual:
201 ft.

LTANKS:

Spill Number/Closed Date:	0000953 / 2001-02-07
Facility ID:	0000953
Site ID:	272947
Spill Date:	2000-04-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-04-24
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-24
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KAREN
Spiller Phone:	(914) 681-5100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222123
DEC Memo:	""
Remarks:	"tank test failure will retest later"

All Materials:

Site ID:	272947
Operable Unit ID:	822651
Operable Unit:	01
Material ID:	289183
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH332 **OUR LADY OF MT CARMEL CHURCH** **NY UST** **U003884891**
SW **92 SOUTH LEXINGTON AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.225 mi.
1190 ft. **Site 2 of 3 in cluster AH**

Relative: **Lower**
Actual: **200 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-074462 / Unregulated
Operator Name:	Rev. Albert Azrak
Owner Name:	Archdioese Of New York
Owner Street:	1011 First Avenue
Owner Address2:	Not reported
Owner City:	New York
Owner State:	NY
Owner Zipcode:	10022
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1966
Date Perm Closure:	08/26/2011
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AH333 **OUR LADY OF MOUNT CARMEL** **NY LTANKS** **S100139372**
SW **92 SOUTH LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.225 mi.
1190 ft. **Site 3 of 3 in cluster AH**

Relative: **Lower**
Actual: **200 ft.**

LTANKS:

Spill Number/Closed Date:	8704169 / 1987-10-21
Facility ID:	8704169
Site ID:	219315
Spill Date:	1987-08-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-10-21
SWIS:	6017
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-08-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

OUR LADY OF MOUNT CARMEL (Continued) **S100139372**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-25
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	""
Remarks:	"1OK SYSTEM- -.1091 GPH. TO BE EMPTIED AND CLEANED. CONTACT:FATHER RIBEZZI"

All TTF:

Facility ID:	8704169
Spill Number:	8704169
Spill Tank Test:	1531431
Site ID:	219315
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	219315
Operable Unit ID:	908038
Operable Unit:	01
Material ID:	466817
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	1100855 / 2012-01-23
Facility ID:	1100855
Site ID:	448286

OUR LADY OF MOUNT CARMEL (Continued) **S100139372**

Spill Date:	2011-04-25
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-25
Spill Record Last Update:	2012-01-23
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF MT CARMEL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 855-3970
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	"4/25/11: This is a 10K heating oil UST, estimated to be at least 60 years old. Thank was re-lined in 1980. WCDOH has required yearly testing of this tank - Kathy Morgan from US Tank Tech reports their company tested the tank every December from 2002 up until 2008. She does not know if anyone else tested it from Dec 08 until now. jod >>> Schneider, Wayne >wts1@westchestergov.com> 1/20/2012 3:52 PM >>> 1100855: 92 South Lexington Ave, White Plains- tank removed. Endpoint samples below cp-51 1/23/12: DEC requires no further action at this time. jod "
Remarks:	"1235 THE CALLER ADVISED DISPATCH THE TANK TEST FAILED. THE CALLER IS REQUESTING SPILLS TO CALL BACK. (PBS 3-074462), 10,000 GALLON TANK"

All Materials:

Site ID:	448286
Operable Unit ID:	1198525
Operable Unit:	01
Material ID:	2194807
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	8703713 / 1987-10-21
Facility ID:	8703713
Site ID:	239739

OUR LADY OF MOUNT CARMEL (Continued) **S100139372**

Spill Date:	1987-08-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-10-21
SWIS:	6017
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-08-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-08-14
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	NYS ARCHDIOCES
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	""
Remarks:	"TTTF 10K -.1100GPH"

All TTF:

Facility ID:	8703713
Spill Number:	8703713
Spill Tank Test:	1531288
Site ID:	239739
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239739
Operable Unit ID:	910351
Operable Unit:	01
Material ID:	469939
Material Code:	0001A
Material Name:	#2 fuel oil

OUR LADY OF MOUNT CARMEL (Continued) **S100139372**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AK334 **WINDBROOK HOUSING** **NY LTANKS** **S105996991**
South **223 DR MARTIN LUTHER KING** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.226 mi.
1193 ft. **Site 1 of 3 in cluster AK**

Relative:
Higher

Actual:
215 ft.

LTANKS:

Spill Number/Closed Date:	0207150 / 2002-11-25
Facility ID:	0207150
Site ID:	243532
Spill Date:	2002-10-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-10-10
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-10
Spill Record Last Update:	2015-03-26
Spiller Name:	ALAN PIO
Spiller Company:	WINDBROOK HOUSING
Spiller Address:	223 DR MARTIN LUTHER KING
Spiller County:	001
Spiller Contact:	ALAN PIO
Spiller Phone:	(914) 949-6462
Spiller Extention:	13
DEC Region:	3
DER Facility ID:	200049
DEC Memo:	"3/26/15: Hard copy file pulled for FOIL request. File being scanned into DecDocs and paper file will be disgarded. jod"
Remarks:	"2 tanks 20000 gals joined together - failed individually & collectively"

All TTF:

Facility ID:	0207150
Spill Number:	0207150
Spill Tank Test:	1527564
Site ID:	243532
Tank Number:	1
Tank Size:	20000

WINDBROOK HOUSING (Continued) **S105996991**

Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	243532
Operable Unit ID:	859974
Operable Unit:	01
Material ID:	517734
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AK335 **WINBROOK HOUSING DEVELOPMENT** **NY UST** **U003995071**
South **223 DR. MARTIN LUTHER KING BLVD.** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.226 mi.
1193 ft. **Site 2 of 3 in cluster AK**

Relative: **Higher**
Actual: **215 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-493597 / Active
Operator Name:	Teddie Henderson
Owner Name:	White Plains Housing Authority
Owner Street:	223 Dr. Martin Luther King Blvd.
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	20000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None

WINBROOK HOUSING DEVELOPMENT (Continued) **U003995071**

Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

Tank Number:	002
Status:	1. In-Service
Capacity:	20000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

AC336 **CON EDISON** **RCRA NonGen / NLR** **1019901420**
South **100 POST RD** **NYP004761797**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.226 mi.
1195 ft. **Site 4 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/01/2015
Facility name:	CON EDISON
Facility address:	100 POST RD WHITE PLAINS, NY 10601
EPA ID:	NYP004761797
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No

CON EDISON (Continued) **1019901420**

Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/01/2015
Site name:	CON EDISON
Classification:	Small Quantity Generator

Violation Status: No violations found

AC337 **CON EDISON** **NJ MANIFEST** **S120669938**
South **100 POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.226 mi.
1195 ft. **Site 5 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

NJ MANIFEST:

EPA Id:	NYP004761797
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091624JJK
EPA ID:	NYP004761797
Date Shipped:	4/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported

CON EDISON (Continued) **S120669938**

Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AC338 **CON EDISON** **NY MANIFEST** **S119074093**
South **100 POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.226 mi.
1195 ft. **Site 6 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004761797
Facility Status:	Not reported
Location Address 1:	E POST RD & GRAND AVE ST
Code:	BP
Location Address 2:	MH 5462
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004761797
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S119074093**

Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2015
Trans1 Recv Date:	04/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004761797
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091624JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AG339 **193-197 EAST POST ROAD WP LLC** **NY UST** **U004175927**
ESE **193-197 EAST POST ROAD** **NY AST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.227 mi.
1199 ft. **Site 7 of 8 in cluster AG**

Relative:
Higher

Actual:
218 ft.

WESTCHESTER CO. UST:

Id/Status:	3-178683 / Active
Operator Name:	George Muto
Owner Name:	193-197 East Post Road WP LLC
Owner Street:	55 Church Street
Owner Address2:	Suite 207
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	12/02/2004
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-178683
Site Status:	Active
GDS Number:	Not reported
Operator Name:	George Muto
Owner Name:	193-197 East Post Road WP LLC
Owner Street:	55 Church Street
Owner Address2:	Suite 207
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	2
Status:	1. In-Service
Date Installation:	05/01/2005
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

193-197 EAST POST ROAD WP LLC (Continued) **U004175927**

Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	0. None

AG340 **APARTMENT BUILDING** **NY LTANKS** **S106124534**
ESE **193 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.227 mi.
1199 ft. **Site 8 of 8 in cluster AG**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Spill Number/Closed Date:	0310631 / 2005-10-11
Facility ID:	0310631
Site ID:	158568
Spill Date:	2003-12-15
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-15
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-15
Spill Record Last Update:	2005-11-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	PAOLA CORONEL
Spiller Phone:	(914) 747-9741
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133999
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 10/11/05 letter from Barbara McDonald of WCDH to Virginia Manning saying submittals have been reviewed. NFA."
Remarks:	"tank test failed. not yet being cleaned up."

All TTF:

Facility ID:	0310631
Spill Number:	0310631
Spill Tank Test:	1528864

APARTMENT BUILDING (Continued) **S106124534**

Site ID:	158568
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	158568
Operable Unit ID:	875713
Operable Unit:	01
Material ID:	499481
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AK341 **WHITE PLAIN HOUSING AUTH.** **NY LTANKS** **S100140591**
South **225 GROVE ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.227 mi.
1200 ft. **Site 3 of 3 in cluster AK**

Relative: **Higher**
Actual: **215 ft.**

LTANKS:

Spill Number/Closed Date:	8904683 / 1992-07-30
Facility ID:	8904683
Site ID:	293104
Spill Date:	1989-08-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1989-08-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

WHITE PLAIN HOUSING AUTH. (Continued) **S100140591**

Date Entered In Computer:	1989-08-21
Spill Record Last Update:	1992-07-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	237240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"TANKS ARE 35 YR. OLD-2 TANKS 1 PASSED, 1 FAILED, TO ISOLATE & RETEST ASAP. VMC ADVISED 35 YRD OLD TANK MAY NOT BE WORTH REPAIRING, SHOULD BE REPLACED. W.W. TO FOLLOW UP."

All TTF:

Facility ID:	8904683
Spill Number:	8904683
Spill Tank Test:	1535834
Site ID:	293104
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	293104
Operable Unit ID:	929941
Operable Unit:	01
Material ID:	448716
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AL342 **REAL ESTATE - TTF** **NY LTANKS** **S118263506**
SSE **6 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.230 mi.
1215 ft. **Site 1 of 4 in cluster AL**

Relative:
Higher

Actual:
243 ft.

LTANKS:

Spill Number/Closed Date:	1506711 / Not Reported
Facility ID:	1506711
Site ID:	514142
Spill Date:	2015-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2015-10-09
Spiller Name:	Unknown
Spiller Company:	Unnamed Owner/Seller
Spiller Address:	6 CHESTER AVE
Spiller County:	999
Spiller Contact:	ANTHONY TIRONE
Spiller Phone:	9146867007
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	468617
DEC Memo:	"9/24/15 Spoke to Kathy Morgan at TT. Mr. Tirone is the buyer. Owner is unknown. dw"
Remarks:	"1000 gallon underground tank"

All Materials:

Site ID:	514142
Operable Unit ID:	1263349
Operable Unit:	01
Material ID:	2267039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AC343 **CON ED** **NY MANIFEST** **S119074703**
South **E NEW YORK POST RD & GRAND ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10607**
0.230 mi.
1215 ft. **Site 7 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004772455
Facility Status:	Not reported
Location Address 1:	E NY POST RD/GRAND ST
Code:	BP
Location Address 2:	MH 3466
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772455
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772455
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454063JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CON ED (Continued) **S119074703**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC344 **CON EDISON** **NJ MANIFEST** **S120670884**
South **E POST RD & GRAND ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.230 mi.
1215 ft. **Site 8 of 17 in cluster AC**

Relative: **Higher**
Actual: **239 ft.**

NJ MANIFEST:

EPA Id:	NYP004772521
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454065JJK
EPA ID:	NYP004772521
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **S120670884**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AC345 **CON EDISON** **RCRA NonGen / NLR** **1019902337**
South **E POST RD & GRAND ST** **NYP004772521**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.230 mi.
1215 ft. **Site 9 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/22/2015
Facility name:	CON EDISON
Facility address:	E POST RD & GRAND ST WHITE PLAINS, NY 10601
EPA ID:	NYP004772521
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator

CON EDISON (Continued) **1019902337**

Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 04/22/2015
Site name: CON EDISON
Classification: Large Quantity Generator

Violation Status: No violations found

AC346 **CON ED** **NY MANIFEST** **S119074708**
South **E POST RD & GRAND ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.230 mi.
1215 ft. **Site 10 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004772521
Facility Status: Not reported
Location Address 1: E POST RD/GRAND ST
Code: BP
Location Address 2: MH 3462
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004772521
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

CON ED (Continued) **S119074708**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772521
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454065JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC347 **CON EDISON** **NJ MANIFEST** **S120670877**
South **E NEW YORK POST RD & GRAND ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10607**
0.230 mi.
1215 ft. **Site 11 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

NJ MANIFEST:

EPA Id:	NYP004772455
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454063JJK
EPA ID:	NYP004772455
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120670877**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AC348 **CON EDISON** **RCRA NonGen / NLR** **1019902331**
South **E POST RD & GRAND ST** **FINDS** **NYP004772455**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.230 mi.
1215 ft. **Site 12 of 17 in cluster AC**

Relative:
Higher

Actual:
239 ft.

RCRA NonGen / NLR:

Date form received by agency:	04/22/2015
Facility name:	CON EDISON
Facility address:	E NEW YORK POST RD & GRAND ST WHITE PLAINS, NY 10607
EPA ID:	NYP004772455
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/22/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

FINDS:

CON EDISON (Continued) **1019902331**

Registry ID: 110069681721

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019902331
Registry ID: 110069681721
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069681721

X349 **STEWARD** **NY LTANKS** **S105999309**
SE **165 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.233 mi.
1228 ft. **Site 16 of 16 in cluster X**

Relative: **Higher**
Actual: **227 ft.**

LTANKS:
Spill Number/Closed Date: 9701601 / 2005-02-12
Facility ID: 9701601
Site ID: 118993
Spill Date: 1997-05-06
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-05-06
CID: 282
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-05-06
Spill Record Last Update: 2005-02-12
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: N/A
Spiller Phone: (914) 934-5992
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 151552

STEWARD (Continued) **S105999309**

DEC Memo: "02/12/05 TANK REPORTEDLY PASSED A RETEST, NO RETEST INFORMATION SUBMITTED TO DEC. TANK WAS REMOVED BY NES ON 6-30-03 AFTER CONTAMINATION WAS DISCOVERED DURING REMOVAL OF NEIGHBORING TANK AT 169 MAMARONECK AVE BY NORTHEAST ENVIRONMENTAL (SEE SPILL 03-01465). WHEN TANK WAS REMOVED BY NES, IT WAS DISCOVERED THAT THE TANK HAD BEEN FIBERGLASS RELINED IN THE PAST. THE TANK WAS NO LONGER LEAKING BUT HAD LEAKED PRIOR TO RELINING. NES REMOVING SOIL, REPORT TO FOLLOW. SEE SPILL 03-03361 FOR ALL UPDATES. NFA THIS SPILL NUMBER. jbo"

Remarks: "TANK FAILED THE VACUUM TEST.COMMERCIAL BUILDING IS WHERE THE TEST WAS DONE."

All TTF:

Facility ID:	9701601
Spill Number:	9701601
Spill Tank Test:	1545105
Site ID:	118993
Tank Number:	1
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Spill Number/Closed Date:	0303361 / 2007-06-22
Facility ID:	0303361
Site ID:	180689
Spill Date:	2003-06-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-06-30
CID:	204
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2003-06-30
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-30
Spill Record Last Update:	2007-06-22
Spiller Name:	BAHRU STEWARD
Spiller Company:	BAHRU STEWARD
Spiller Address:	165 MAMARONECK AVENUE
Spiller County:	001

STEWARD (Continued) **S105999309**

Spiller Contact:	MARIE MULLEN
Spiller Phone:	(914) 741-5472
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	151552
DEC Memo:	"06/30/03: UST lined tank, leaked through lining, tank out, soil will be removed. Waiting on insurance. See also spill #03-01465. 02/12/05 PREVIOUSLY REPORTED AS 97-01601. UST FAILED TANK TEST, TANK WAS RELINED AND PUT BACK IN SERVICE. TANK REMOVED BY NES AFTER CONTAMINATION FOUND DURING REMOVAL OF NEIGHBORING TANK AT 169 MAMARONECK AVE. TANK HAD BEEN LEAKING PRIOR TO RELINING. jbo 06/22/2007: NES COMPLETED CLEAN UP. jod"
Remarks:	"OLD TANK FAILED"

All Materials:

Site ID:	180689
Operable Unit ID:	871405
Operable Unit:	01
Material ID:	504234
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC350 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157653**
South **E NY POST RD & CROMWELL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.234 mi.
1236 ft. **Site 13 of 17 in cluster AC**

Relative:
Higher

Actual:
238 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004230025
Facility Status:	Not reported
Location Address 1:	E NY POST RD & CROMWELL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230025
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CONSOLIDATED EDISON (Continued) **S111157653**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2011
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/2011
Trans1 Recv Date:	03/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230025
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001057793GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC351 **CON EDISON** **RCRA NonGen / NLR** **1019902324**
South **CROMWELL PL & E POST RD** **NYP004772372**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.234 mi.
1236 ft. **Site 14 of 17 in cluster AC**

Relative: **Higher**
Actual: **238 ft.**

RCRA NonGen / NLR:

Date form received by agency:	04/22/2015
Facility name:	CON EDISON
Facility address:	CROMWELL PL & E POST RD WHITE PLAINS, NY 10601
EPA ID:	NYP004772372
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	04/22/2015
Site name:	CON EDISON
Classification:	Large Quantity Generator

Violation Status: No violations found

AC352 **CON ED** **NY MANIFEST** **S119074699**
South **CROMWELL PL & E POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.234 mi.
1236 ft. **Site 15 of 17 in cluster AC**

Relative: **Higher**
Actual: **238 ft.**

NY MANIFEST:

Country:	USA
EPA ID:	NYP004772372
Facility Status:	Not reported
Location Address 1:	CROMWELL PL/E NY POST RD
Code:	BP

CON ED (Continued) **S119074699**

Location Address 2: MH 5599
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004772372
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC353 **CON EDISON** **NY MANIFEST** **S118089630**
South **CROMWELL PL & E. NY POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.234 mi.
1236 ft. **Site 16 of 17 in cluster AC**

Relative:
Higher

Actual:
238 ft.

NY MANIFEST:
Country: USA
EPA ID: NYP004772370
Facility Status: Not reported
Location Address 1: CROMWELL PL & E. NY POST ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004772370
Mailing Name: CON EDISON
Mailing Contact: TOM TELLING
Mailing Address 1: 4 IRVING PLACE-15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported

CON EDISON (Continued) **S118089630**

Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772370
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454064JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AC354 **CON EDISON** **RCRA NonGen / NLR** **1014398716**
South **CROMWELL PL & E POST RD** **NJ MANIFEST** **NYP004210779**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.234 mi.
1236 ft. **Site 17 of 17 in cluster AC**

Relative:
Higher

Actual:
238 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/07/2010
Facility name:	CON EDISON
Facility address:	CROMWELL PL & E POST RD WHITE PLAINS, NY 10601
EPA ID:	NYP004210779
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DAVID DUKE
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	917-559-8971
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

NJ MANIFEST:

EPA Id:	NYP004210779
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported

CON EDISON (Continued) **1014398716**

Date Change: Not reported

Manifest:
Manifest Number: 003533305JJK
EPA ID: NYP004210779
Date Shipped: 07/07/2010
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported
Transporter 9 EPA ID: Not reported
Transporter 10 EPA ID: Not reported
Date Trans1 Transported Waste: 07/07/2010
Date Trans2 Transported Waste: Not reported
Date Trans3 Transported Waste: Not reported
Date Trans4 Transported Waste: Not reported
Date Trans5 Transported Waste: Not reported
Date Trans6 Transported Waste: Not reported
Date Trans7 Transported Waste: Not reported
Date Trans8 Transported Waste: Not reported
Date Trans9 Transported Waste: Not reported
Date Trans10 Transported Waste: Not reported
Date TSDF Received Waste: 07/08/2010
TSDF EPA Facility Name: Not reported
QTY Units: Not reported
Transporter SEQ ID: Not reported
Transporter-1 Date: Not reported
Waste SEQ ID: Not reported
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported
Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: Not reported
Was Load Rejected: NEW YORK, NY 10003
Reason Load Was Rejected: Not reported

Waste:
Manifest Year: Not reported
Waste Code: D008
Hand Code: H111
Quantity: 600 P

NY MANIFEST:
Country: USA
EPA ID: NYP004210779
Facility Status: Not reported
Location Address 1: MH5599 - E POST RD & CROMWELL PL

CON EDISON (Continued) **1014398716**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004210779
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2010
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/07/2010
Trans1 Recv Date:	07/07/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/08/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004210779
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003533305JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **1014398716**

Quantity:	600.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AE355 **URBAN LEAGUE OF WESTCHESTER COUNTY, INC** **NY UST** **U004259590**
East **61 MITCHELL PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.237 mi.
1251 ft. **Site 4 of 4 in cluster AE**

Relative: WESTCHESTER CO. UST:
Higher

Actual: Id/Status:	3-802108 / Unregulated
216 ft. Operator Name:	Urban League of Westchester County
Owner Name:	Urban League of Westchester County, Inc
Owner Street:	61 Mitchell Place
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	01
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AJ356 **BIRCHWOOD ASSOCIATES** **NY UST** **U004176097**
North **35 BARKER AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.237 mi.
1253 ft. **Site 3 of 4 in cluster AJ**

Relative: **Higher**

Actual: **229 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-496502 / Active
Operator Name:	Gani Shehu
Owner Name:	Birchwood Associates LLC
Owner Street:	3010 Westchester Avenue #106
Owner Address2:	Not reported
Owner City:	Purchase
Owner State:	NY
Owner Zipcode:	10577
GDS Number:	Not reported

Tank Number:	001
Status:	1. In-Service
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1957
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	0. Administratively closed
Capacity:	2500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Date Installation:	01/01/1900
Date Perm Closure:	06/01/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AM357 **COLIN SERVICE SYSTEM INC** **NY UST** **U003994451**
ENE **1 BROCKWAY PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.237 mi.
1253 ft. **Site 1 of 6 in cluster AM**

Relative:
Higher

Actual:
220 ft.

WESTCHESTER CO. UST:

Id/Status:	3-411310 / Unregulated: <1101 gal. PBS
Operator Name:	Jay Colin
Owner Name:	Nilco Operating Co.
Owner Street:	1 Brockway Place
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1980
Date Perm Closure:	03/01/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1980
Date Perm Closure:	03/01/1995
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AL358 **RESIDENTS** **NY LTANKS** **S102447976**
SSE **8 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.237 mi.
1254 ft. **Site 2 of 4 in cluster AL**

Relative:
Higher

Actual:
244 ft.

LTANKS:

Spill Number/Closed Date:	9610881 / 2012-04-16
Facility ID:	9610881
Site ID:	71801
Spill Date:	1996-12-03
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1996-12-03
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-03
Spill Record Last Update:	2012-04-16
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	KREISBERG RESIDENTS
Spiller Phone:	(914) 428-3000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67898
DEC Memo:	"8/3/10 Homeowner TTF JO'M 4/16/12 This spill has been closed administratively based on the following: 1) The spill is at least 10 years old 2) It is a Homeowner (non regulated tank) Tank Test Failure 3) There is no indication of an Environmental impact This Closure does not remove the possibility of DEC requiring further work in the future. NFA JO'M"
Remarks:	"THE TAN TESTER THINKS THAT THE LINES ARE BAD OR THE VENT LINES OIL COMPANY ROBISON IS DOING THE FOLLOW UP JIM ROOD IS THE EMPLOYEE FOR ROBISON 914-345-5700"

All TTF:

Facility ID:	9610881
Spill Number:	9610881
Spill Tank Test:	1544908
Site ID:	71801
Tank Number:	1
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

RESIDENTS (Continued) **S102447976**

Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AN359 **GATEWAY BLDG** **NY MANIFEST** **S117563215**
West **1 N LEXINGTON AVE 13TH FL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.238 mi.
1257 ft. **Site 1 of 7 in cluster AN**

Relative:
Lower

Actual:
201 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYD986984698
Facility Status:	Not reported
Location Address 1:	NORTH LEXINGTON AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986984698
Mailing Name:	GATEWAY BLDG
Mailing Contact:	BILL MOSER
Mailing Address 1:	NORTH LEXINGTON AVE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	3159642554

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	CT5000001495
Trans2 State ID:	Not reported
Generator Ship Date:	01/26/2018
Trans1 Recv Date:	01/26/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/26/2018
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986984698
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	CT5000001495
TSDF ID 2:	Not reported

GATEWAY BLDG (Continued) **S117563215**

Manifest Tracking Number:	014040769JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H010
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	846
Units:	P - Pounds
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	D009
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
2 additional NY MANIFEST: record(s) in the EDR Site Report.

AN360 **GATEWAY CENTER ONE** **NY AST** **A100379813**
West **1 NORTH LEXINGTON AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.238 mi.
1257 ft. **Site 2 of 7 in cluster AN**

Relative: WESTCHESTER CO. AST:
Lower

PBS Number:	3-496871
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Cushman & Wakefield
Owner Name:	Gateway I Group, Inc.
Owner Street:	1 North Lexington Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	No. 3
Status:	1. In-Service
Date Installation:	12/01/2008
Capacity:	275
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900

GATEWAY CENTER ONE (Continued) **A100379813**

Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AN361 **CUSHMAN & WAKEFIELD** **PA MANIFEST** **S118068777**
West **1 N LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.238 mi.
1257 ft. **Site 3 of 7 in cluster AN**

Relative: **Lower**

Actual: **201 ft.**

Manifest Details:

Year:	2017
Manifest Number:	010443369FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	07/13/2017
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	217 S First St
TSD Facility City:	Elizabeth
TSD Facility State:	NJ
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	50
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	NJD002200046
Date TSP Sig:	Not reported

Year:	2016
Manifest Number:	001505886FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	01/21/2016
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

CUSHMAN & WAKEFIELD (Continued) **S118068777**

TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	55
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2016
Manifest Number:	001505886FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	01/21/2016
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F003
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	55
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	001502315FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	03/27/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc

CUSHMAN & WAKEFIELD (Continued) **S118068777**

TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	F003
Container Number:	4
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	180
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2014
Manifest Number:	001502315FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	03/27/2014
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	4
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	180
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

AN362 **CUSHMAN & WAKEFIELD** **PA MANIFEST** **S112069200**
West **ONE N LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.238 mi.
1257 ft. **Site 4 of 7 in cluster AN**

Relative: **Lower**

Actual: **201 ft.**

Manifest Details:

Year:	2011
Manifest Number:	001162465FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYD986984698
Generator Date:	11/23/2011
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	Not reported

CUSHMAN & WAKEFIELD (Continued) **S112069200**

TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

AN363 **GATEWAY PLAZA** **NY UST** **U003979121**
West **1 NORTH LEXINGTON AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.238 mi.
1257 ft. **Site 5 of 7 in cluster AN**

Relative: **Lower**
Actual: **201 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-496871 / Active
Operator Name:	Cushman & Wakefield
Owner Name:	Gateway I Group, Inc.
Owner Street:	1 North Lexington Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	100
Tank Leak Detection:	0. None
Date Installation:	11/01/1984
Date Perm Closure:	01/24/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	1

GATEWAY PLAZA (Continued) **U003979121**

Status:	0. Administratively closed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	11/01/1984
Date Perm Closure:	05/01/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	99. Other
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	10
Status:	1. In-Service
Capacity:	10000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	02/01/2012
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	11
Status:	1. In-Service
Capacity:	10000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	02/01/2012
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground

GATEWAY PLAZA (Continued) **U003979121**

Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	2
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	11/01/1984
Date Perm Closure:	11/01/1991
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AN364 **GATEWAY BUILDING** **RCRA-CESQG 1000705553**
West **1 N LEXINGTON AVE 13TH FL** **FINDS NYD986984698**
1/8-1/4 **WHITE PLAINS, NY 10601** **NJ MANIFEST**
0.238 mi.
1257 ft. **Site 6 of 7 in cluster AN**

Relative: **Lower**
Actual: **201 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	GATEWAY BUILDING
Facility address:	1 N LEXINGTON AVE 13TH FL WHITE PLAINS, NY 10601
EPA ID:	NYD986984698
Mailing address:	N LEXINGTON AVE 13TH FL WHITE PLAINS, NY 10601
Contact:	JOE J ROCCUZZO
Contact address:	N LEXINGTON AVE 13TH FL WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-683-5331
Contact email:	Not reported
EPA Region:	02
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

GATEWAY BUILDING (Continued) **1000705553**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	A T & T
Owner/operator address:	1 N LEXINGTON AVE
	WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-397-3519
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	C B RICHARD ELLIS
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/01/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	02/15/2006
Site name:	GATEWAY BUILDING

GATEWAY BUILDING (Continued) **1000705553**

Classification: Small Quantity Generator

Date form received by agency: 02/14/2006
Site name: GATEWAY BUILDING
Classification: Small Quantity Generator

Date form received by agency: 07/08/1999
Site name: A T & T
Classification: Not a generator, verified

Date form received by agency: 01/03/1992
Site name: A T & T
Classification: Small Quantity Generator

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D008
. Waste name: LEAD

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/24/2012
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110004481864

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NJ MANIFEST:
EPA Id: NYD986984698

GATEWAY BUILDING (Continued) **1000705553**

Mail Address:	1 NORTH LEXINGTON AVE
Mail City/State/Zip:	WHITE PLAINS 10601
Facility Phone:	9146835331
Emergency Phone:	Not reported
Contact:	RON PAULSON
Comments:	Not reported
SIC Code:	Not reported
County:	00
Municipal:	00
Previous EPA Id:	Not reported
Gen Flag:	X
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	001162134FLE
EPA ID:	NYD986984698
Date Shipped:	03/24/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000115733
Transporter 2 EPA ID:	NYD980761191
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	03/24/2008
Date Trans2 Transported Waste:	04/04/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/04/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS 10601
Reason Load Was Rejected:	Not reported

GATEWAY BUILDING (Continued) **1000705553**

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	40 G

Manifest Number:	NJA5288045
EPA ID:	NYD986984698
Date Shipped:	02/27/2006
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	VTR000500090
Transporter 2 EPA ID:	NYD980761191
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/27/2006
Date Trans2 Transported Waste:	03/10/2006
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	03/10/2006
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	06190621
Was Load Rejected:	WHITE PLAINS 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	000052581FLE
EPA ID:	NYD986984698
Date Shipped:	02/09/2007
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD980761191
Transporter 2 EPA ID:	NYD980761191
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

GATEWAY BUILDING (Continued) **1000705553**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	02/09/2007
Date Trans2 Transported Waste:	02/19/2007
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	02/20/2007
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H14
Quantity:	50 G

Manifest Number:	001162208FLE
EPA ID:	NYD986984698
Date Shipped:	10/29/2008
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYR000115733
Transporter 2 EPA ID:	NYD980761191
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	10/29/2008
Date Trans2 Transported Waste:	10/29/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

GATEWAY BUILDING (Continued) **1000705553**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	10/29/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H141
Quantity:	47 G

AN365 **GATEWAY BLDG** **NY LTANKS** **S100140904**
West **1 NORTH LEXINGTON AVE** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.238 mi.
1257 ft. **Site 7 of 7 in cluster AN**

Relative: **Lower**
Actual: **201 ft.**

LTANKS:

Spill Number/Closed Date:	8908197 / 1990-01-29
Facility ID:	8908197
Site ID:	276348
Spill Date:	1989-11-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-01-29
SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

GATEWAY BLDG (Continued) **S100140904**

Date Entered In Computer:	1989-11-17
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 01/29/90: TANK PASSED RETEST. "
Remarks:	"WILL PUMP OUT TANK (CAPITAL OIL)"

All TTF:

Facility ID:	8908197
Spill Number:	8908197
Spill Tank Test:	1536421
Site ID:	276348
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	276348
Operable Unit ID:	933238
Operable Unit:	01
Material ID:	559409
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9000726 / 1991-12-06
Facility ID:	9000726
Site ID:	131721
Spill Date:	1990-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18

GATEWAY BLDG (Continued) **S100140904**

SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1990-04-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-05-30
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	WTT CORP.
Spiller Address:	123 MAIN STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"PETRO-TITE -.344"

All TTF:

Facility ID:	9000726
Spill Number:	9000726
Spill Tank Test:	1536975
Site ID:	131721
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	131721
Operable Unit ID:	940390
Operable Unit:	01
Material ID:	439098
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

GATEWAY BLDG (Continued) **S100140904**

Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported
Spill Number/Closed Date:	9108659 / 1991-11-13
Facility ID:	9108659
Site ID:	255792
Spill Date:	1991-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1991-11-13
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-11-18
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	EMERG ENV.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/31/92: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"OIL NOTICED IN MANWAY REPAIR AND RETEST HORNER EZ SYSTEM GROSS"

All TTF:

Facility ID:	9108659
Spill Number:	9108659
Spill Tank Test:	1539301
Site ID:	255792
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

GATEWAY BLDG (Continued) **S100140904**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 255792
Operable Unit ID: 962707
Operable Unit: 01
Material ID: 420787
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 1112860 / 2012-06-06
Facility ID: 1112860
Facility Type: ER
DER Facility ID: 113491
Site ID: 460825
DEC Region: 3
Spill Cause: Unknown
Spill Class: B3
SWIS: 6017
Spill Date: 2012-02-09
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2012-02-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-02-09
Spill Record Last Update: 2012-06-06
Spiller Name: Not reported
Spiller Company: GATE WAY PLAZA
Spiller Address: Not reported
Spiller Company: 999
Contact Name: TONY PEPE
DEC Memo: "2/9/12 - Caller removed one 10K UST and one 2K UST. Post excavation sampling results showed contamination below soil guidance. A TCR will be prepared. Westchester County DOH was notified and was presented at the tank pull. KAB >>> Lalak, Chris >cjl1@westchestergov.com> 2/9/2012 10:56 AM >>> John, I am lead on this one pbs tank pull. Chris jod 06/06/2012: Update received from Chris Lalak of WCDoH PBS: John Please close this spill 1112860 1 North Lex. Ave, WP American

GATEWAY BLDG (Continued) **S100140904**

pulled two tanks *DEC requires no further action at this time. jod"
Remarks: "contamination based on lab results"

All Materials:
Site ID: 460825
Operable Unit ID: 1210927
Operable Unit: 01
Material ID: 2208599
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Spill Number/Closed Date: 1213498 / 2013-01-08
Facility ID: 1213498
Facility Type: ER
DER Facility ID: 113491
Site ID: 476685
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6017
Spill Date: 2012-12-13
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2012-12-13
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-12-13
Spill Record Last Update: 2013-01-08
Spiller Name: Not reported
Spiller Company: PROPERTY OWNER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CHRIS LALAK
DEC Memo: "12/13/12 Assitant Chief Engineer Joseph Rocuzzo reported that a contractor, DP Wolff (143 Bedford Rd, Katonah) was performing mechanical work and had 50 gallon of oil that needed to be pumped back into the diesel storage tank. They set the house pump on manual and turned on the pump. It was explained that the oil first gets pumped up to the 20th floor day tank and the excess then flows out the daytank return line back to the storage tank. However the daytank emergency vent relief valve is lower than the return line, so the oil released from that vent before it could be sent back to the tank via the return line. The oil drained down the glass curtain wall from the

GATEWAY BLDG (Continued) **S100140904**

19th floor to the 16th floor. Elite Environmental was on site removing oily insulation and cleaning oiled surfaces. A minor amount of oil escaped the interior of the building thru the glass curtain and landed on the sidewalk below. Some oil also entered a floor drain next to the day tank. WP sewer dept personnel reported that oil was observed in the sanitary sewer in the street but not in the storm drains. WCHD is requiring indoor air sampling before the 4 impacted floors can be reoccupied. TG "

Remarks: "interior and exterior to sidewalk - cleanup in progress - spilled 14 thru 17 floor elite environmental on site"

All Materials:

Site ID:	476685
Operable Unit ID:	1226510
Operable Unit:	01
Material ID:	2223774
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AO366 **KEMPLER RESIDENCE** **NY LTANKS** **S105998935**
SE **169 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.242 mi.
1279 ft. **Site 1 of 4 in cluster AO**

Relative: **Higher**
Actual: **226 ft.**

LTANKS:

Spill Number/Closed Date:	0301465 / 2003-08-25
Facility ID:	0301465
Site ID:	160482
Spill Date:	2003-05-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-05-09
CID:	195
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2003-06-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-09
Spill Record Last Update:	2005-02-12
Spiller Name:	PETER KEMPLER
Spiller Company:	PETER KEMPLER
Spiller Address:	169 MAMARONECK AVE

KEMPLER RESIDENCE (Continued) **S105998935**

Spiller County:	001
Spiller Contact:	PETER KEMPLER
Spiller Phone:	(914) 946-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	135518
DEC Memo:	"06/30/03 ALSO SPILL 03-03361. 08/25/03 NORTHEAST DISPOSED OF LUST AND 122.09 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"TANK WAS UNCOVERED AND TESTED. TEST FAILED. OWNER (PETER KEMPLER) WAS TOLD TO PUMP TANK OUT WITHIN 48 HOURS AND HAVE TANK REMOVED TO CHECK FOR CONTAMINATION. CALLER CAN BE REACHED AT 845-742-1666."

All TTF:

Facility ID:	0301465
Spill Number:	0301465
Spill Tank Test:	1528363
Site ID:	160482
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	160482
Operable Unit ID:	867853
Operable Unit:	01
Material ID:	505959
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM367 **SEARS ROEBUCK & CO 1444/6504/7024** **RCRA-CESQG** **1000981138**
ENE **MAIN ST** **NY0000923193**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.243 mi.
1283 ft. **Site 2 of 6 in cluster AM**

Relative: **Higher**
Actual: **219 ft.**

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	SEARS ROEBUCK & CO 1444/6504/7024
Facility address:	MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NY0000923193

SEARS ROEBUCK & CO 1444/6504/7024 (Continued) **1000981138**

Mailing address: BEVERLY RD A2-238A
HOFFMAN ESTATES, IL 60179
Contact: KATHLEEN M FLAHERTY
Contact address: BEVERLY RD A2-238A
HOFFMAN ESTATES, IL 60179
Contact country: US
Contact telephone: 847-286-7199
Contact email: KFLAHER@SEARS.COM
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: SEARS ROEBUCK & CO
Owner/operator address: BEVERLY RD A2-238A
HOFFMAN ESTATES, IL 60179
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/01/1968
Owner/Op end date: Not reported

Owner/operator name: SEARS ROEBUCK & CO
Owner/operator address: BEVERLY RD A2-238A
HOFFMAN ESTATES, IL 60179
Owner/operator country: US
Owner/operator telephone: Not reported
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/01/1968
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No

SEARS ROEBUCK & CO 1444/6504/7024 (Continued) **1000981138**

Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: SEARS ROEBUCK & CO 1444/6504/7024
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/25/2004
Site name: SEARS ROEBUCK & CO 1444/6504/7024
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLOROETHYLENE

Date form received by agency: 11/07/1994
Site name: SEARS ROEBUCK & CO 1444
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE

SEARS ROEBUCK & CO 1444/6504/7024 (Continued) **1000981138**

FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: X001
. Waste name: WASTE OILS

Violation Status: No violations found

AM368 **WALMART #3441** **RCRA-SQG** **1008892122**
ENE **275 MAIN ST** **NY MANIFEST** **NYR000134999**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.243 mi.
1283 ft. **Site 3 of 6 in cluster AM**

Relative:
Higher

Actual:
219 ft.

RCRA-SQG:

Date form received by agency:	07/13/2016
Facility name:	WALMART #3441
Facility address:	275 MAIN ST WHITE PLAINS, NY 10601
EPA ID:	NYR000134999
Mailing address:	PO BOX 8041 BENTONVILLE, AR 72712-8041
Contact:	REBECCA HAYNIE
Contact address:	PO BOX 8041 BENTONVILLE, AR 72712-8041
Contact country:	US
Contact telephone:	479-258-6810
Contact email:	REBECCA.HAYNIE@WALMART.COM
EPA Region:	02
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WAL-MART STORES EAST LP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	07/19/2006
Owner/Op end date:	Not reported

Owner/operator name:	WAL-MART STORES EAST LP
Owner/operator address:	PO BOX 841 BENTONVILLE, AR 72712
Owner/operator country:	US
Owner/operator telephone:	479-258-6810
Owner/operator email:	Not reported

WALMART #3441 (Continued) **1008892122**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 07/19/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

WALMART #3441 (Continued) **1008892122**

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

WALMART #3441 (Continued) **1008892122**

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U089
. Waste name: DIETHYLSTILBESTEROL

. Waste code: U112
. Waste name: ACETIC ACID ETHYL ESTER (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T)

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO-

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL

WALMART #3441 (Continued) **1008892122**

ESTER (OR) THIOPHANATE-METHYL

Historical Generators:
Date form received by agency: 09/15/2014
Site name: WALMART #3441
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016

WALMART #3441 (Continued) **1008892122**

. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U112
. Waste name: ACETIC ACID ETHYL ESTER (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

WALMART #3441 (Continued) **1008892122**

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T)

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO-

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Date form received by agency: 11/10/2010
Site name: WALMART #3441
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN

WALMART #3441 (Continued) **1008892122**

OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

WALMART #3441 (Continued) **1008892122**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P046
. Waste name: BENZENEETHANAMINE, ALPHA,ALPHA-DIMETHYL-

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U080
. Waste name: METHANE, DICHLORO-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA,2ALPHA,3BETA,4ALPHA,5ALPHA,6BETA)-

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U182
. Waste name: PARALDEHYDE

. Waste code: U188

WALMART #3441 (Continued) **1008892122**

. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 02/12/2010
Site name: WALMART #3441
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006

WALMART #3441 (Continued) **1008892122**

. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: U002
. Waste name: ACETONE (I)

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO-

. Waste code: U080
. Waste name: METHANE, DICHLORO-

. Waste code: U154
. Waste name: METHANOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279

WALMART #3441 (Continued) **1008892122**

. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 01/01/2007
Site name: WAL-MART STORE #3441
Classification: Small Quantity Generator

Date form received by agency: 01/01/2006
Site name: WAL-MART STORE #3441
Classification: Small Quantity Generator

Date form received by agency: 12/01/2005
Site name: WAL-MART STORE #3441
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

. Waste code: U223
. Waste name: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T)

Date form received by agency: 10/12/2005
Site name: IVY REALTY
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR

WALMART #3441 (Continued) **1008892122**

MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U223
. Waste name: BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T)

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYR000134999
Facility Status: Not reported
Location Address 1: 275 MAIN STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000134999
Mailing Name: WALMART #3441
Mailing Contact: JOHN DULL
Mailing Address 1: 275 MAIN STREET
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2015738400

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: MAD039322250
Trans2 State ID: Not reported
Generator Ship Date: 06/27/2018
Trans1 Recv Date: 06/27/2018
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/12/2018
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000134999

WALMART #3441 (Continued) **1008892122**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD000648451
TSDF ID 2:	Not reported
Manifest Tracking Number:	011172879FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	0.01
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	P001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
120 additional NY MANIFEST: record(s) in the EDR Site Report.

AM369 **SEARS** **NY Spills** **S102153177**
ENE **MAIN ST** **NY MANIFEST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.243 mi.
1283 ft. **Site 4 of 6 in cluster AM**

Relative:
Higher

Actual:
219 ft.

SPILLS:

Spill Number/Closed Date:	0212866 / 2004-04-23
Facility ID:	0212866
Facility Type:	ER
DER Facility ID:	259947
Site ID:	322671
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6017
Spill Date:	2003-03-28
Investigator:	tdghiosa
Referred To:	Not reported

SEARS (Continued) **S102153177**

Reported to Dept:	2003-03-28
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-03-28
Spill Record Last Update:	2004-04-23
Spiller Name:	TERESA KEE
Spiller Company:	SEARS AUTOMOTIVE
Spiller Address:	275 MAIN ST
Spiller Company:	001
Contact Name:	TERESA KEE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 04/07/04 Remedial Action Closure Report submitted by Watterson Environmental Group. Based on the info contained in that report, NFA> TG "
Remarks:	"RESULTS CAME BACK FROM A PHASE 2 INVESTIGATION OF THE ABOVE AND THEY FOUND MISC PETROLEUM PRODUCTS IN THE SOIL 6-12 UNDER THE BLDG"

All Materials:

Site ID:	322671
Operable Unit ID:	863704
Operable Unit:	01
Material ID:	512588
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8803493 / 1988-07-29
Facility ID:	8803493
Facility Type:	ER
DER Facility ID:	259947
Site ID:	322672
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1988-07-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-07-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Citizen
Cleanup Ceased:	1988-07-29

SEARS (Continued) **S102153177**

Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-28
Spill Record Last Update:	1998-05-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DEISEL FUEL LINE BROKE ON TRUCK SPILLER CLEANED UP N.F.A."

All Materials:

Site ID:	322672
Operable Unit ID:	918649
Operable Unit:	01
Material ID:	459040
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NY0000923193
Facility Status:	Not reported
Location Address 1:	275 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000923193
Mailing Name:	SEARS
Mailing Contact:	ADAM BIZENE
Mailing Address 1:	275 MAIN ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	7082868864

SEARS (Continued) **S102153177**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2014
Trans1 State ID:	IND058484114
Trans2 State ID:	Not reported
Generator Ship Date:	11/06/2014
Trans1 Recv Date:	11/06/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/25/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NY0000923193
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	IND093219012
TSDF ID 2:	Not reported
Manifest Tracking Number:	005983732FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AL370 **CHESTER MAPLE PARKING STRUCT** **NY MANIFEST** **S120957590**
SSE **9 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.244 mi.
1288 ft. **Site 3 of 4 in cluster AL**

Relative:
Higher

Actual:
243 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYD986984714
Facility Status:	Not reported
Location Address 1:	9 CHESTER AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986984714
Mailing Name:	CHESTER MAPLE PARKING STRUCT
Mailing Contact:	CHESTER MAPLE PARKING STRUCT
Mailing Address 1:	9 CHESTER AVE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2017
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/2017
Trans1 Recv Date:	06/23/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/23/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986984714
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	016115481JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported

CHESTER MAPLE PARKING STRUCT (Continued) **S120957590**

Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
7 additional NY MANIFEST: record(s) in the EDR Site Report.

AL371 **CHESTER MAPLE PARKING STRUCT** **RCRA NonGen / NLR** **1000555924**
SSE **9 CHESTER AVE** **FINDS** **NYD986984714**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.244 mi.
1288 ft. **Site 4 of 4 in cluster AL**

Relative:
Higher

Actual:
243 ft.

RCRA NonGen / NLR:

Date form received by agency:	01/01/2007
Facility name:	CHESTER MAPLE PARKING STRUCT
Facility address:	9 CHESTER AVE WHITE PLAINS, NY 10601-3505
EPA ID:	NYD986984714
Mailing address:	CHESTER AVE WHITE PLAINS, NY 10601
Contact:	Not reported
Contact address:	CHESTER AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	Not reported
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	WHITE PLAINS PARKING AUTH
Owner/operator address:	65 MITCHELL PL WHITE PLAINS, NY 10601
Owner/operator country:	US
Owner/operator telephone:	914-422-1320
Owner/operator email:	Not reported

CHESTER MAPLE PARKING STRUCT (Continued) **1000555924**

Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: WHITE PLAINS PARKING AUTH
Owner/operator address: 65 MITCHELL PL
WHITE PLAINS, NY 10601
Owner/operator country: US
Owner/operator telephone: 914-422-1320
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Municipal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: CHESTER MAPLE PARKING STRUCT
Classification: Not a generator, verified

Date form received by agency: 07/08/1999
Site name: CHESTER MAPLE PARKING STRUCT
Classification: Not a generator, verified

Date form received by agency: 01/06/1992
Site name: CHESTER MAPLE PARKING STRUCT
Classification: Large Quantity Generator

. Waste code: X003
. Waste name: OTHER STATE REGULATED WASTES [i.e., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Violation Status: No violations found

CHESTER MAPLE PARKING STRUCT (Continued) **1000555924**

FINDS:

Registry ID: 110004481873

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555924
Registry ID:	110004481873
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004481873

AJ372 **BARKER AVENUE OWNERS CORP.** **NY UST U003885499**
North **33 BARKER AVENUE** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.244 mi.
1290 ft. **Site 4 of 4 in cluster AJ**

Relative: **Higher**
Actual: **224 ft.**

WESTCHESTER CO. UST:

Id/Status:	3-169668 / Active
Operator Name:	Andy Pepdjonovic
Owner Name:	Barker Avenue Owners Corp.
Owner Street:	33 Barker Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	169668
Status:	3. Closed - Removed
Capacity:	7500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	09/01/1966
Date Perm Closure:	12/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	2. Galvanized steel
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None

BARKER AVENUE OWNERS CORP. (Continued) **U003885499**

Dispenser: 2. Suction

WESTCHESTER CO. AST:

PBS Number:	3-169668
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Andy Pepdjonovic
Owner Name:	Barker Avenue Owners Corp.
Owner Street:	33 Barker Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1998
Capacity:	5000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

AO373 **JOHN DALE, INC.** **NY UST** **U003856736**
SE **176-180 MAMRONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.246 mi.
1297 ft. **Site 2 of 4 in cluster AO**

Relative:
Higher

Actual:
227 ft.

WESTCHESTER CO. UST:

Id/Status:	3-800038 / Unregulated: <1101 gal. PBS
Operator Name:	Ken Harbour
Owner Name:	John Dale, Inc.
Owner Street:	80 Business Park Drive
Owner Address2:	Not reported
Owner City:	Armonk
Owner State:	NY
Owner Zipcode:	10504
GDS Number:	Not reported
Tank Number:	002
Status:	0. Administratively closed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None

JOHN DALE, INC. (Continued) **U003856736**

Date Installation:	02/01/1999
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Sacrificial Anode (no retrofit)
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/20/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AO374 **JOHN DALE INC** **NY LTANKS** **S103558559**
SE **178 MAMORENECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.246 mi.
1297 ft. **Site 3 of 4 in cluster AO**

Relative: **Higher**
Actual: **227 ft.**

LTANKS:

Spill Number/Closed Date:	9810809 / 1998-12-01
Facility ID:	9810809
Site ID:	325049
Spill Date:	1998-11-25
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-11-25
CID:	282
Water Affected:	Not reported

JOHN DALE INC (Continued) **S103558559**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-25
Spill Record Last Update:	1999-01-16
Spiller Name:	DWAYNE MONICO
Spiller Company:	JOHN DALE INC
Spiller Address:	80 BUSINESS PARK DRIVE
Spiller County:	001
Spiller Contact:	DWAYNE MONICO
Spiller Phone:	(914) 777-1930
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261843
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY SPILL CLOSED BY WCHD, S. GOREAU."
Remarks:	"tank leaked and the soil around the tank was contaminated.soil was removed and stockpiled.site has been cleaned ."

All Materials:

Site ID:	325049
Operable Unit ID:	1071785
Operable Unit:	01
Material ID:	314671
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO375 **CON EDISON** **RCRA NonGen / NLR** **1014397079**
SE **184 MAMARONECK AVE & MAPLE AVE** **NY MANIFEST** **NYP004193967**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.246 mi.
1297 ft. **Site 4 of 4 in cluster AO**

Relative: **Higher**
Actual: **227 ft.**

RCRA NonGen / NLR:

Date form received by agency:	06/01/2016
Facility name:	CON EDISON
Facility address:	184 MAMARONECK AVE & MAPLE AVE WHITE PLAINS, NY 10601
EPA ID:	NYP004193967
Mailing address:	4 IRVING PL, RM 828 NEW YORK, NY 10003
Contact:	DENNIS MICHAELIDES
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	718-204-4297
Contact email:	Not reported
EPA Region:	02

CON EDISON (Continued) **1014397079**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 09/09/2009
Site name: CON EDISON
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

NY MANIFEST:
Country: USA
EPA ID: NYP004193967
Facility Status: Not reported
Location Address 1: MAMARONECK AVE & MAPLE AVE - MH 5628
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: YONKERS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004193967
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported

CON EDISON (Continued) **1014397079**

Year:	2009
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/10/2009
Trans1 Recv Date:	09/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004193967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433374FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200.0
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AP376 **CON EDISON** **NY MANIFEST** **S118257680**
NE **445 HAMILTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.248 mi.
1311 ft. **Site 1 of 4 in cluster AP**

Relative:
Higher

Actual:
234 ft.

NY MANIFEST:

Country:	USA
EPA ID:	NYP004804688
Facility Status:	Not reported
Location Address 1:	445 HAMILTON AVE
Code:	BP
Location Address 2:	MH 8350
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004804688
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AP377 **CON EDISON** **RCRA NonGen / NLR** **1019905006**
NE **445 HAMILTON AVE** **FINDS** **NYP004804688**
1/8-1/4 **WHITE PLAINS, NY 10606** **ECHO**
0.248 mi.
1311 ft. **Site 2 of 4 in cluster AP**

Relative:
Higher

Actual:
234 ft.

RCRA NonGen / NLR:

Date form received by agency:	07/09/2015
Facility name:	CON EDISON
Facility address:	445 HAMILTON AVE WHITE PLAINS, NY 10606
EPA ID:	NYP004804688
Mailing address:	IRVING PL 15TH FL NE NEW YORK, NY 10003
Contact:	THOMAS TEELING
Contact address:	Not reported Not reported
Contact country:	Not reported
Contact telephone:	212-460-3770
Contact email:	Not reported
EPA Region:	02
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

CON EDISON (Continued) **1019905006**

Handler Activities Summary:
- U.S. importer of hazardous waste: No
- Mixed waste (haz. and radioactive): No
- Recycler of hazardous waste: No
- Transporter of hazardous waste: No
- Treater, storer or disposer of HW: No
- Underground injection activity: No
- On-site burner exemption: No
- Furnace exemption: No
- Used oil fuel burner: No
- Used oil processor: No
- User oil refiner: No
- Used oil fuel marketer to burner: No
- Used oil Specification marketer: No
- Used oil transfer facility: No
- Used oil transporter: No

Historical Generators:
- Date form received by agency: 07/09/2015
- Site name: CON EDISON
- Classification: Large Quantity Generator

- Violation Status: No violations found

FINDS:

- Registry ID: 110069663956

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
- Envid: 1019905006
- Registry ID: 110069663956
- DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069663956

AP378 **CON EDISON** **NJ MANIFEST** **S120673697**
NE **445 HAMILTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.248 mi.
1311 ft. **Site 3 of 4 in cluster AP**

Relative: **Higher**
Actual: **234 ft.**

NJ MANIFEST:
- EPA Id: NYP004804688
- Mail Address: IRVING PL 15TH FL NE
- Mail City/State/Zip: NEW YORK, NY 10003
- Facility Phone: Not reported
- Emergency Phone: Not reported

CON EDISON (Continued) **S120673697**

Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469323JJK
EPA ID:	NYP004804688
Date Shipped:	7/9/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AQ379 **APARTMENT BLDG** **NY LTANKS** **S103037425**
NNE **40 BARKER AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.253 mi.
1334 ft. **Site 1 of 2 in cluster AQ**

Relative:
Higher

Actual:
245 ft.

LTANKS:

Spill Number/Closed Date:	9713796 / 2001-01-31
Facility ID:	9713796
Site ID:	271212
Spill Date:	1998-03-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-03-13
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-03-13
Spill Record Last Update:	2001-03-27
Spiller Name:	SUPERINTENDENT
Spiller Company:	APARTMENT BLDG
Spiller Address:	40 BARKER AV
Spiller County:	001
Spiller Contact:	MANNY ZEVALOS
Spiller Phone:	(718) 830-0131
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	220750
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/09/2000 ARMOR REMOVED UST 01/31/2001 PETROSCIENCE SUBMITTED A UST CLOSURE REPORT. 149.1 TONS OF CONTAMINATED SOIL EXCAVATED & DISPOSED. NO FURTHER ACTION."
Remarks:	"TANK FAILED AIR TIGHTNESS TEST - SUCTION LINE, RETURN LINE AND TANK ITSELF FALIED - ATTEMPTED TO CALL LAST NIGHT BUT WAS PUT ON HOLD"

All TTF:

Facility ID:	9713796
Spill Number:	9713796
Spill Tank Test:	1545670
Site ID:	271212
Tank Number:	001
Tank Size:	5000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

APARTMENT BLDG (Continued) **S103037425**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 271212
Operable Unit ID: 1056654
Operable Unit: 01
Material ID: 324789
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

380 ESE 1/4-1/2 0.260 mi. 1372 ft.
240 EAST POST RD
240 EAST POST RD
WHITE PLAINS, NY

NY LTANKS **S103941435**
N/A

Relative: Lower
Actual: 208 ft.

LTANKS:
Spill Number/Closed Date: 9903233 / 1999-12-15
Facility ID: 9903233
Site ID: 135983
Spill Date: 1999-06-21
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1999-06-21
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-06-21
Spill Record Last Update: 2000-04-05
Spiller Name: NATE GORHAM
Spiller Company: 240 EAST POST RD
Spiller Address: 240 EAST POST RD
Spiller County: 001
Spiller Contact: CALLER
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 116709

240 EAST POST RD (Continued) **S103941435**

DEC Memo: ""
Remarks: "TANK REMOVED AND CONTAMINATION FOUND IN SOIL."

All Materials:
Site ID: 135983
Operable Unit ID: 1082158
Operable Unit: 01
Material ID: 303161
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AM381 **LASALLE PARTNERS** **NY LTANKS** **S118953675**
ENE **1 NORTH BROADWAY** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.262 mi.
1382 ft. **Site 5 of 6 in cluster AM**

Relative: **Higher**
Actual: **216 ft.**

LTANKS:
Spill Number/Closed Date: 8807326 / 1989-03-08
Facility ID: 8807326
Site ID: 245085
Spill Date: 1988-12-05
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1989-03-08
SWIS: 6017
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-12-06
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-12-07
Spill Record Last Update: 1989-03-08
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 201325
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
J. OKESSON 03/08/89: BULK STORAGE APPLICATION RECEIVED AND REGISTERED

LASALLE PARTNERS (Continued) **S118953675**

Remarks: AS PER J.OKESSON'S REQUEST. TANK TEST RESULTS ARE INCLUDED WITH APPLICATION SHOWING TANK PASSED RE-TEST AT +.002 GPH. NFA. " "20K -.921 SYSTEM FAILURE. TANK ONLY TEST TO BE DONE SOON. TANK PASSED RETEST. SEE HISTORY. NFA."

All TTF:

Facility ID:	8807326
Spill Number:	8807326
Spill Tank Test:	1534970
Site ID:	245085
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	245085
Operable Unit ID:	922741
Operable Unit:	01
Material ID:	455672
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AQ382 **COMMERCIAL** **NY LTANKS** **S102153972**
NNE **41 BARKER AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.262 mi.
1384 ft. **Site 2 of 2 in cluster AQ**

Relative: **Higher**
Actual: **247 ft.**

LTANKS:

Spill Number/Closed Date:	0909513 / 2010-03-04
Facility ID:	0909513
Site ID:	422220
Spill Date:	2009-11-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2009-11-25

COMMERCIAL (Continued) **S102153972**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-11-25
Spill Record Last Update:	2015-06-08
Spiller Name:	CERDAN LOVELL
Spiller Company:	H AND S PROPRTY MANAGEMENT
Spiller Address:	41 BARKER AVE
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	254318
DEC Memo:	"11-25-09 Tank top is 103 in below grade. Test was done in relation to WCHD NOHC. NE Environmental is handling compliance issues. jc 12/10/09 -- According to WCDOH: They re in our hearing process right now. Major violations include no corrosion protection and no leak detection. They re claiming they don t have to come into compliance because White Plains issued them a certificate that everything was in compliance when the tank was installed in 1990. They re not accepting our explanation that the certificate only applies to White Plains building code. Because the tank is buried so deep, it will be a hardship for them to come into compliance. And The case was adjourned for them to prove compliance. If they can get proper documentation, excavation may not be necessary. They re not performing leak monitoring, at least they re not maintaining any documentation. We don t know if the tank is single- or double-walled because the interstitial port is probably not to grade. They have an ATG but there s no proof that it s performing interstitial monitoring. They need to get a contractor to determine what they ve got since we re not accepting the proof from White Plains Bldg Dept. Resolution to be determined in January, maybe. ELM 1/25/10: See eDocs for 12-31-09 letter from WCDOH/PBS - requiring additional action. jod 3/4/10: As per an e-mail recived from Chris Lalak of WCDOH dated 2-16-10, this tank was retested and passed. E-mail entered into eDocs. Based upon the information provided, DEC requires no further action at this time. jod"
Remarks:	"caller reporting tank test failure on a 10000 gallon ust. caller reports tank is deep, fill pipe is 103 ft long. clean up pending."

All TTF:

Facility ID:	0909513
Spill Number:	0909513
Spill Tank Test:	2488120
Site ID:	422220
Tank Number:	UST
Tank Size:	10000
Material:	0002
EPA UST:	False
UST:	True
Cause:	99
Source:	01

COMMERCIAL (Continued) **S102153972**

Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	422220
Operable Unit ID:	1178070
Operable Unit:	01
Material ID:	2171020
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9004325 / 1990-12-26
Facility ID:	9004325
Facility Type:	ER
DER Facility ID:	254318
Site ID:	315451
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1990-07-19
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-07-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Fire Department
Cleanup Ceased:	1990-12-26
Cleanup Meets Std:	True
Last Inspection:	1990-12-26
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-20
Spill Record Last Update:	1991-01-15
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/15/91: LUZON OIL WAS ON SITE LOADING THE LAST OF THE CONTAMINATED SOIL INTOTRUCKS FOR DISPOSAL. JOB IS COMPLETED. "

COMMERCIAL (Continued) **S102153972**

Remarks: "10K TANK OR PIPING LEAKING FOR COUPLE OF DAYS CASTLE OIL FILLED TANK TODAY EASTMAN TANK IS PUMPING OUT TANK FIRE DEPT.AND DOT SANDING STORMDRAIN LEADS TO SEWER PLANT,WCHD,WC HAZMAT,EPA ALL NOTIFIED"

All Materials:

Site ID:	315451
Operable Unit ID:	942144
Operable Unit:	01
Material ID:	435423
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	80.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM383 **ES GORDON** **NY LTANKS** **S100560022**
ENE **7-11 SOUTH BROADWAY** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.264 mi.
1394 ft. **Site 6 of 6 in cluster AM**

Relative: **Higher**
Actual: **211 ft.**

LTANKS:

Spill Number/Closed Date:	9303840 / 1994-05-04
Facility ID:	9303840
Site ID:	86174
Spill Date:	1993-06-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1994-05-04
SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1993-06-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-01
Spill Record Last Update:	1994-05-26
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	79091
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ES GORDON (Continued) **S100560022**

W. WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks: "SUSPECT LINE LEAK WILL INVESTIGATE HORNER"

All TTF:

Facility ID:	9303840
Spill Number:	9303840
Spill Tank Test:	1541701
Site ID:	86174
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	86174
Operable Unit ID:	982139
Operable Unit:	01
Material ID:	397384
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AR384 **BART GOLDBERG APT. BLDG** **NY LTANKS** **S100141680**
East **277 MARTINE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.266 mi.
1402 ft. **Site 1 of 3 in cluster AR**

Relative: **Higher**
Actual: **214 ft.**

LTANKS:

Spill Number/Closed Date:	9008032 / 1990-11-08
Facility ID:	9008032
Site ID:	255929
Spill Date:	1990-10-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-10-22
CID:	Not reported

BART GOLDBERG APT. BLDG (Continued) **S100141680**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-30
Spill Record Last Update:	1990-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209602
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 11/08/90: TANK PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO E I R PETRO-TITE GROSS LEAK"

All TTF:

Facility ID:	9008032
Spill Number:	9008032
Spill Tank Test:	1537746
Site ID:	255929
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	255929
Operable Unit ID:	948684
Operable Unit:	01
Material ID:	431865
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

385
North
1/4-1/2
0.274 mi.
1446 ft.

VILLANOVA - TTF
144 CHURCH ST
WHITE PLAINS, NY

NY LTANKS **S118707784**
N/A

Relative:
Higher

Actual:
220 ft.

LTANKS:

Spill Number/Closed Date:	1603426 / 2016-09-06
Facility ID:	1603426
Site ID:	529884
Spill Date:	2016-07-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2016-07-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-07-08
Spill Record Last Update:	2016-09-07
Spiller Name:	BRIDGETT VILLANOVA
Spiller Company:	Bridgette Villanova
Spiller Address:	144 CHURCH ST
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	483978
DEC Memo:	"7-8-16 Spoke with Bridget. They plan to remove tank. She says C2G will be doing the work. Informed her to make sure documentation is submitted to close spill. jc 9/6/16: C2G Environmental disposed of the leaking UST and a total of 45.96 tons of petroleum contaminated soil. Soil sample results were submitted for review. Documents entered into DecDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"repair/retest pending"

All Materials:

Site ID:	529884
Operable Unit ID:	1278702
Operable Unit:	01
Material ID:	2283624
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AP386 **OFFICE BUILDING** **NY LTANKS** **S100494055**
NE **15 NORTH BROADWAY** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.280 mi.
1480 ft. **Site 4 of 4 in cluster AP**

Relative:
Higher

Actual:
231 ft.

LTANKS:

Spill Number/Closed Date:	9207265 / 1996-02-01
Facility ID:	9207265
Site ID:	125976
Spill Date:	1992-09-23
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	1992-09-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1992-09-25
Spill Record Last Update:	2003-07-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	108944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. 02/01/96 LETTER FROM JOHN O'MARA TO GEORGE ARDITTI, G&M ENTERPRISES, DEC REQUIRES NO FURTHER ACTION."
Remarks:	"RECOMMEND E.I.R. AIRLAY"

All Materials:

Site ID:	125976
Operable Unit ID:	974235
Operable Unit:	01
Material ID:	554233
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

OFFICE BUILDING (Continued) **S100494055**

SPILLS:

Spill Number/Closed Date:	0403095 / 2004-10-06
Facility ID:	0403095
Facility Type:	ER
DER Facility ID:	108944
Site ID:	125975
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2004-06-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2004-06-21
CID:	408
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-21
Spill Record Last Update:	2004-10-06
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	Not reported
Contact Name:	TONY KLOSS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09-13-04 Spill/discharge investigation and remediation report received from Impact Environmental. Based on the information contained in that report, NFA TG"
Remarks:	"ELEVATOR HYDROLIC OIL: IN THE PROCESS OF BEING CLEANED UP: IT HAS BEEN IDENTIFIED"

All Materials:

Site ID:	125975
Operable Unit ID:	885057
Operable Unit:	01
Material ID:	490698
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	250.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR387 **CEMMEL HOUSE BUILDING** **NY LTANKS** **S105996852**
East **300 MARTINE AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.285 mi.
1504 ft. **Site 2 of 3 in cluster AR**

Relative:
Lower

Actual:
207 ft.

LTANKS:

Spill Number/Closed Date:	0206553 / 2002-12-13
Facility ID:	0206553
Site ID:	293177
Spill Date:	2002-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-24
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2003-03-25
Spiller Name:	Not reported
Spiller Company:	JAINE VOGHAN
Spiller Address:	209 GARTH RD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	147087
DEC Memo:	""
Remarks:	"gross leak coming from manhole cover - resealing manhole cover and retest"

All TTF:

Facility ID:	0206553
Spill Number:	0206553
Spill Tank Test:	1527492
Site ID:	293177
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

CEMMEL HOUSE BUILDING (Continued) **S105996852**

All Materials:
Site ID: 293177
Operable Unit ID: 858167
Operable Unit: 01
Material ID: 517155
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0311391 / 2004-01-08
Facility ID: 0311391
Facility Type: ER
DER Facility ID: 147087
Site ID: 174952
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6017
Spill Date: 2004-01-08
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2004-01-08
CID: 402
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-01-08
Spill Record Last Update: 2004-01-13
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: JAMIE BARNABA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/08/04: Mechanical failure from a fitting on boiler. Nick Barnaba reported cleanup completed tonight. NFA at this time."
Remarks: "Crew on scene to clean it up. "

All Materials:
Site ID: 174952
Operable Unit ID: 879016
Operable Unit: 01
Material ID: 500202
Material Code: 0002A

CEMMEL HOUSE BUILDING (Continued) **S105996852**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AS388 **OFFICE BLDG** **NY LTANKS** **S102960015**
SE **203 MAMARONECK AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.287 mi.
1514 ft. **Site 1 of 3 in cluster AS**

Relative:
Higher

Actual:
227 ft.

LTANKS:

Spill Number/Closed Date:	9710787 / Not Reported
Facility ID:	9710787
Site ID:	329412
Spill Date:	1997-12-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	1997-12-22
Spill Record Last Update:	2010-08-03
Spiller Name:	Not reported
Spiller Company:	OFFICE BLDG
Spiller Address:	203 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	TARRICONE FUEL GREG
Spiller Phone:	(914) 693-1132
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	265043
DEC Memo:	"8/3/10 need Update JO'M"
Remarks:	"TANK FAILED"

All TTF:

Facility ID:	9710787
Spill Number:	9710787
Spill Tank Test:	1545530
Site ID:	329412
Tank Number:	001
Tank Size:	3000
Material:	Not reported

OFFICE BLDG (Continued) **S102960015**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

SPILLS:

Spill Number/Closed Date:	0800340 / 2008-04-25
Facility ID:	0800340
Facility Type:	ER
DER Facility ID:	265043
Site ID:	396080
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-04-09
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-04-09
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-09
Spill Record Last Update:	2008-04-28
Spiller Name:	STORE MANAGER-DAVE
Spiller Company:	SPENCER ADAMS STORE
Spiller Address:	203 MANAMACK AVE
Spiller Company:	001
Contact Name:	STORE MANAGER-DAVE
DEC Memo:	"Spill of 10 to 20 gallons, contained to concrete. Robison completed cleanup. NFA jod"
Remarks:	"BROKEN OIL LINE AND IN PROCESS OF CLEANING AND IS CONTAINED IN A PIT"
	Not reported

All Materials:

Site ID:	396080
Operable Unit ID:	1153026
Operable Unit:	01
Material ID:	2143804
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

OFFICE BLDG (Continued) **S102960015**

Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9711397 / 1998-01-12
Facility ID:	9711397
Facility Type:	ER
DER Facility ID:	265043
Site ID:	329413
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	1998-01-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-01-10
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-10
Spill Record Last Update:	2018-01-18
Spiller Name:	ARNOLD LIPMAN
Spiller Company:	Not reported
Spiller Address:	203 MAMARONECK AVE
Spiller Company:	001
Contact Name:	ARNOLD LIPMAN
DEC Memo:	"01/10/98 BASEMENT FLOOR OF BUILDING; WCHD RESPONDING; 01/12/98 SMALL SPILL ONTO BOILER ROOM FLOOR; NO DRAIN AFFECTED; CONTAINED WITH SPEEDI-DRI; CHRIS LELAK (WCHD);"
Remarks:	"temp oil storage leaked - oil co enroute to clean up "

All Materials:

Site ID:	329413
Operable Unit ID:	1057884
Operable Unit:	01
Material ID:	326067
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT389 **WIND BROOK APTS.** **NY LTANKS** **S104509303**
SW **33 FISHER AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.293 mi.
1548 ft. **Site 1 of 3 in cluster AT**

Relative:
Lower

Actual:
199 ft.

LTANKS:

Spill Number/Closed Date:	1007861 / 2011-07-05
Facility ID:	1007861
Site ID:	441310
Spill Date:	2010-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2010-10-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-25
Spill Record Last Update:	2011-07-25
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	VINNY NANNI
Spiller Phone:	(914) 949-6462
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199379
DEC Memo:	"10/25/10 - Caller believes there is a loose connection between the tanks. Tanks to be uncover, repair and retest. Westchester County DOH will conduct follow up since tanks are PBS regulated. KAB 12/13/10 Tanks were separated and retested. Tank 1 passed. Tank 2 (tank to the right when facing the bldg) failed with bubbling as per phone call from Kathy Morgan, US Tank Tech...mm 7/5/11 as per WCDOH White Plains- ttf 10/25/10. Tank passed isolation test. Lines replaced with no contamination observed. NFA JO'M 7/22/11: Received the retest results from US Tank Tech - will be entered into eDocs. NFA. jod"
Remarks:	"Tank test Failure"

All TTF:

Facility ID:	1007861
Spill Number:	1007861
Spill Tank Test:	2489700
Site ID:	441310
Tank Number:	1
Tank Size:	20000
Material:	0002
EPA UST:	False
UST:	True
Cause:	06

WIND BROOK APTS. (Continued) **S104509303**

Source:	00
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	kabrowne
Last Modified Date:	Not reported
Facility ID:	1007861
Spill Number:	1007861
Spill Tank Test:	2489701
Site ID:	441310
Tank Number:	2
Tank Size:	20000
Material:	0002
EPA UST:	False
UST:	True
Cause:	06
Source:	00
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	kabrowne
Last Modified Date:	Not reported

All Materials:

Site ID:	441310
Operable Unit ID:	1191875
Operable Unit:	01
Material ID:	2187076
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9912180 / 2000-05-30
Facility ID:	9912180
Facility Type:	ER
DER Facility ID:	199379
Site ID:	242722
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2000-01-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-01-21
CID:	322

WIND BROOK APTS. (Continued) **S104509303**

Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-21
Spill Record Last Update:	2000-06-02
Spiller Name:	FRANK MONTIBELLO
Spiller Company:	MONTIBELLO COAL & FUEL
Spiller Address:	424 EAST 81ST ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/21/2000 CLEANUP COMPLETED; NFA 03/20/2000 CASE REOPENED ON INFORMATION PROVIDED THAT THE SPILL SIZE MAY HAVE BEEN UP TO 700 GALLONS 03/08/2000 T. GHIOSAY SPOKE WITH DAN KIRSHNER OF SUN ROYAL ALLIANCE INSURANCE COMPANY AND ADVISED HIM THAT PLAYGROUND ARE NEEDS MORE CLEANUP. HE WILL CALL TRI-STATE AND AUTHORIZE WORK. 05/30/2000 LETTER SENT TO DORSON ENV. MGMT BY T. GHIOSAY; SPILL FILE IS CLOSED."
Remarks:	"fitting popped off pipe causing spill - spill being cleaned up "

All Materials:

Site ID:	242722
Operable Unit ID:	1086701
Operable Unit:	01
Material ID:	294073
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9301205 / 1993-05-13
Facility ID:	9301205
Facility Type:	ER
DER Facility ID:	199379
Site ID:	186162
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	D3
SWIS:	6017
Spill Date:	1993-04-26
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-04-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-05-13

WIND BROOK APTS. (Continued) **S104509303**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-29
Spill Record Last Update:	1993-05-13
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/13/93: SPILL CLEANED UP ACCORDING TO JANET HERNANDEZ OF CASTLE OIL. COMPLETED THE SAME DAY. "
Remarks:	"SPILL ON GROUND CREW ENROUTE"

All Materials:

Site ID:	186162
Operable Unit ID:	983121
Operable Unit:	01
Material ID:	401926
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

390 @ **NY LTANKS S104645518**
East **44 NORTH BROADWAY** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.296 mi.
1562 ft.

Relative: **Lower**
Actual: **205 ft.**

LTANKS:

Spill Number/Closed Date:	0302230 / 2009-11-05
Facility ID:	0302230
Site ID:	328668
Spill Date:	2003-06-02
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jkomara
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	2003-06-02
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

@ **(Continued)** **S104645518**

Remediation Phase:	0
Date Entered In Computer:	2003-06-02
Spill Record Last Update:	2009-11-05
Spiller Name:	KATHRIN KRASOVIC
Spiller Company:	BROADLAKE CO
Spiller Address:	44 NORTH BROADWAY
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	264506
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - JACKSON "
Remarks:	""

All TTF:

Facility ID:	0302230
Spill Number:	0302230
Spill Tank Test:	1528418
Site ID:	328668
Tank Number:	1
Tank Size:	7500
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	328668
Operable Unit ID:	868941
Operable Unit:	01
Material ID:	506707
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0313703 / 2004-03-15
Facility ID:	0313703
Facility Type:	ER
DER Facility ID:	137201
Site ID:	162622
DEC Region:	3

@ **(Continued)** **S104645518**

Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2004-03-15
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2004-03-15
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-15
Spill Record Last Update:	2004-04-02
Spiller Name:	ERT DESK
Spiller Company:	CON ED VAULT #9944
Spiller Address:	44 SOUTH BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MCCARTHY "
Remarks:	"FAULTY TRANSFORMER: NO TO 5 QUESTIONS: SUMP IN HOLE NOTY OPERATING AT TIME BUT FOUND OIL INSIDE OF IT: CON ED # 152504"

All Materials:

Site ID:	162622
Operable Unit ID:	878833
Operable Unit:	01
Material ID:	568399
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0313749 / 2004-03-16
Facility ID:	0313749
Facility Type:	ER
DER Facility ID:	137201
Site ID:	162623
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2004-03-16
Investigator:	DVWEHRFR
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444

@ **(Continued)** **S104645518**

Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2004-04-02
Spiller Name:	ERT DESK
Spiller Company:	CON ED VAULT #6407
Spiller Address:	44 SOUTH BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WEHRFRITZ "
Remarks:	"40 GALLONS OF WATER WITH THE OIL IN HOLE; FAULTY TRANSFORMER: NO TO ALL 5 QUESTIONS: CON ED # 152526 SUMP IN VAULTY AND WAS NOT OPERATING: "

All Materials:

Site ID:	162623
Operable Unit ID:	880842
Operable Unit:	01
Material ID:	495341
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0313751 / 2004-03-16
Facility ID:	0313751
Facility Type:	ER
DER Facility ID:	137201
Site ID:	162624
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2004-03-16
Investigator:	DVWEHRFR
Referred To:	Not reported
Reported to Dept:	2004-03-16
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False

@ **(Continued)** **S104645518**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-16
Spill Record Last Update:	2004-04-02
Spiller Name:	ERT DESK
Spiller Company:	CON ED VAULT #9829
Spiller Address:	44 SOUTH BROADWAY
Spiller Company:	001
Contact Name:	ERT DESK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WEHRFRITZ See e2mis 152527"
Remarks:	"10 GALLONS OIL WITHIN BOTTOM OF HOLE NO WATER SAMPLE TAKEN CLEAN UP IN PROGRESS: CON ED # 152527 NMO TO THE 5 QUESTIONS: "

All Materials:

Site ID:	162624
Operable Unit ID:	880844
Operable Unit:	01
Material ID:	495343
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0703466 / 2007-06-25
Facility ID:	0703466
Facility Type:	ER
DER Facility ID:	137201
Site ID:	383396
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	2007-06-25
Investigator:	JYMCCART
Referred To:	Not reported
Reported to Dept:	2007-06-25
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-25
Spill Record Last Update:	2007-08-15
Spiller Name:	DAVID ANAGONUS
Spiller Company:	WESTCHESTER ONE
Spiller Address:	44 SOUTH BROADWAY
Spiller Company:	001

@ **(Continued)** **S104645518**

Contact Name: DAVID ANAGONUS
DEC Memo: "Clean up completed. NFA."
Remarks: "DURING A TANK CLOSURE, A REMOTE FILL LINE LEAKED SOME OIL : ROUGHLY 4-5 GALLONS: CLEANUP IS COMPLETE: SUPERVISOR ON SCENE IS JIM LEWIS CELL # 908-461-3056, "

All Materials:
Site ID: 383396
Operable Unit ID: 1140750
Operable Unit: 01
Material ID: 2130845
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0308354 / 2003-11-07
Facility ID: 0308354
Facility Type: ER
DER Facility ID: 264506
Site ID: 328669
DEC Region: 3
Spill Cause: Unknown
Spill Class: C3
SWIS: 6017
Spill Date: 2003-11-07
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 2003-11-07
CID: 199
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-11-07
Spill Record Last Update: 2003-11-07
Spiller Name: ROBERT HILL
Spiller Company: CASTLE OIL
Spiller Address: 290 LOCUST AVE
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/7/03 INSPECTED BY GHIOSAY. SATISFACTORY CLEANUP COMPLETED BY 11:30 AM. NFA. TG"
Remarks: "caller states this morning castle oil overfilled the tank of his apt building and it appears approx 10 gal went onto pavement speedy dry has been put down but the area is still able to be accessed by children and animals - caller would like someone to check situtation

@ **(Continued)** **S104645518**

to make sure it is being handled properly"

All Materials:

Site ID:	328669
Operable Unit ID:	874612
Operable Unit:	01
Material ID:	501866
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9610799 / 1996-12-02
Facility ID:	9610799
Facility Type:	ER
DER Facility ID:	264506
Site ID:	328670
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	6017
Spill Date:	1996-12-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-02
CID:	199
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-02
Spill Record Last Update:	1999-07-28
Spiller Name:	JIM CAREY
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	001
Contact Name:	VAL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"BROKEN DECK HOSE (DISCHARGE HOSE) CAUSED MATERAL TO LEAK ONTO STREET (PAVEMENT) ALL MATERAL CONTAINED - SPILL CLEAN UP CREW ON THE WAY TO CLEAN AT THIS TIME"

All Materials:

Site ID:	328670
Operable Unit ID:	1042178
Operable Unit:	01
Material ID:	343015

@ (Continued) **S104645518**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU391 **GARDEN APARTMENTS** **NY LTANKS** **S102619101**
NE **101 N. BROADWAY** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.298 mi.
1571 ft. **Site 1 of 4 in cluster AU**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Spill Number/Closed Date:	8904418 / 1992-07-30
Facility ID:	8904418
Site ID:	77672
Spill Date:	1989-08-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1992-07-30
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-03
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-04
Spill Record Last Update:	2001-10-12
Spiller Name:	Not reported
Spiller Company:	WRG MANAGEMENT CORP.
Spiller Address:	420 WESTCHESTER AVE.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72405
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"WILL PUMP OUT TANK OWNERS WILL CONTACT DEC IN NEW PALTZ #4 FUEL 8K, PETRO TIE -0.382"

All TTF:

Facility ID:	8904418
Spill Number:	8904418
Spill Tank Test:	1535795
Site ID:	77672

GARDEN APARTMENTS (Continued) **S102619101**

Tank Number: Not reported
Tank Size: 0
Material: 0066A
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 77672
Operable Unit ID: 932056
Operable Unit: 01
Material ID: 448472
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AT392 **HYDRAULIC FLUID TO SEWER** **NY LTANKS** **S104877043**
SSW **134 SOUTH LEXINGTON AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.299 mi.
1577 ft. **Site 2 of 3 in cluster AT**

Relative: **Lower**
Actual: **197 ft.**

LTANKS:
Spill Number/Closed Date: 0008525 / 2001-03-12
Facility ID: 0008525
Site ID: 218519
Spill Date: 2000-10-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: D3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2000-10-21
CID: 397
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-10-21

HYDRAULIC FLUID TO SEWER (Continued) **S104877043**

Spill Record Last Update:	2009-12-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	AMY
Spiller Phone:	(914) 592-3117
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	107023
DEC Memo:	"03/12/2001 TANK PULLED BY CORSETTI CONTRACTING FOR DORSON ENVIRONMENTAL. TANK WAS SOUND, NO EVIDENCE OF RELEASE. A SECOND, 550 GALLON WASTE OIL TANK WAS ALSO REMOVED. NO EVIDENCE OF DISCHARGE FROM SECOND TANK WAS FOUND. NO FURTHER ACTION."
Remarks:	"DORSON ENVIRONMENTAL WAS THE SUB CONTRACTOR FOR THE TANK TEST. "

All TTF:

Facility ID:	0008525
Spill Number:	0008525
Spill Tank Test:	1525945
Site ID:	218519
Tank Number:	1
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	218519
Operable Unit ID:	829124
Operable Unit:	01
Material ID:	546030
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0008680 / 2005-03-06
Facility ID:	0008680
Facility Type:	ER
DER Facility ID:	107023
Site ID:	123462
DEC Region:	3

HYDRAULIC FLUID TO SEWER (Continued) **S104877043**

Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2000-10-25
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2000-10-25
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-25
Spill Record Last Update:	2005-03-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"3/6/5 15gallon hydraulic fluid spilled to sewer--close"
Remarks:	"THE SPILL WAS RELEASED FROM AN ELEVATOR DUE TO UNK CAUSES & WENT INTO A STORM SEWER - ACTUAL COMP TO NRC WAS FROM WHITE PLAINS POLICE DEPT, JOSEPH DEPLAO 914-422-6111 - FIRE DEPT WAS REPORTED TO HAVE BEEN ON THE SCENE"

All Materials:

Site ID:	123462
Operable Unit ID:	829269
Operable Unit:	01
Material ID:	546183
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR393 **COUNTY OFFICE BLD** **NY LTANKS** **S102155353**
East **MARTINE AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.303 mi.
1600 ft. **Site 3 of 3 in cluster AR**

Relative: LTANKS:
Lower

Spill Number/Closed Date:	8806957 / 1989-02-06
Facility ID:	8806957
Site ID:	172819
Spill Date:	1988-11-21
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck

Actual:
193 ft.

COUNTY OFFICE BLD (Continued) **S102155353**

Spill Class:	C3
Cleanup Ceased:	1988-11-23
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	1988-11-21
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-01-03
Spill Record Last Update:	1996-01-02
Spiller Name:	Not reported
Spiller Company:	RAD OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	145441
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK OVERFILL"

All Materials:

Site ID:	172819
Operable Unit ID:	923699
Operable Unit:	01
Material ID:	455302
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9414918 / 1995-02-23
Facility ID:	9414918
Facility Type:	ER
DER Facility ID:	150830
Site ID:	179716
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-02-13
Investigator:	tdghiosa
Referred To:	Not reported

COUNTY OFFICE BLD (Continued) **S102155353**

Reported to Dept:	1995-02-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-02-23
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	CON ED
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"LEAK NOTICED DURING ROUTINE INSPECTION CON ED TO CLEAN UP"

All Materials:

Site ID:	179716
Operable Unit ID:	1012341
Operable Unit:	01
Material ID:	373638
Material Code:	0017A
Material Name:	PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

394
ENE
1/4-1/2
0.304 mi.
1607 ft.

PARK ROSE
12 WESTCHESTER AVE
WHITE PLAINS, NY

NY LTANKS **S102152995**
NY Spills **N/A**

Relative:
Lower

Actual:
205 ft.

LTANKS:

Spill Number/Closed Date:	0900020 / 2015-06-05
Facility ID:	0900020
Site ID:	411931
Spill Date:	2009-04-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2009-04-01
CID:	Not reported
Water Affected:	Not reported

PARK ROSE (Continued) **S102152995**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-01
Spill Record Last Update:	2015-06-05
Spiller Name:	DAVID DRASHOW
Spiller Company:	PATRIOT MANAGEMENT
Spiller Address:	12 WESTCHETER AVE
Spiller County:	999
Spiller Contact:	ROBIN WIECZOREK
Spiller Phone:	(845) 434-7805
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	176944
DEC Memo:	"4-1-09: V.Mc.^ DAVID DRASHOW/PATRIOT: UST is 5K, as per Mr.Drashow. To authorize Luzon to proceed with repair of line and retest of system. 5/14/09: During investigation the tank was found to be 7,500 gallons in size. Tank was out of service and partly filled with sand. Reps from Luzon, Lane Engineering and the White Plains Bldg Dept met on site 5-18-09. It was determined the tank cannot be removed without causing severe damage to the structure. Accessible contaminated soil will be remediated and the tank will be abandoned in place. jod 06/24/09 Luzon Environmental Services submitted a Underground Storage Tank Closure Report. Structural concerns prevented the removal of the tank, so the WCHD allowed the oil tank to be cleaned and abandoned in place. Recovery well was placed in an area where oil was seeping from beneath the tank and will be monitored for a year. TG 12/14/09: Well data including sample results from November 19 submitted by Luzon. Further vaccing of well and additional sampling necessary. Results to be entered into eDocs. jod 09/06/11 GW sampling report submitted by Luzon. Report in Edocs. TG 06/02/15 Monitoring Well Sampling Event Report submitted by Northeast Environmental. VOC and SVOC levels reduced to trace levels. No further action is required. TG"
Remarks:	"LINE TEST FAILURE ON 10,000 GALLON VAULTED TANK, WHICH IS IN THE BASEMENT. REMOTE FILL LINE IS LEAKING UNK AMOUNT."

All Materials:

Site ID:	411931
Operable Unit ID:	1168423
Operable Unit:	01
Material ID:	2160029
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	8607154 / 1987-03-07
Facility ID:	8607154

PARK ROSE (Continued) **S102152995**

Facility Type:	ER
DER Facility ID:	176944
Site ID:	213571
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1987-02-24
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-02-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1987-03-07
Cleanup Meets Std:	True
Last Inspection:	1987-03-07
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-27
Spill Record Last Update:	1998-01-29
Spiller Name:	Not reported
Spiller Company:	PARK ROSE MGT
Spiller Address:	22 SAW MILL RIVER RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"OIL SEEPING AFTER DELIVERY"

All Materials:

Site ID:	213571
Operable Unit ID:	903844
Operable Unit:	01
Material ID:	472679
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8710547 / 1988-03-17
Facility ID:	8710547
Facility Type:	ER
DER Facility ID:	176944
Site ID:	213572
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1988-03-17
Investigator:	jeokesso
Referred To:	Not reported

PARK ROSE (Continued) **S102152995**

Reported to Dept:	1988-03-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1988-03-17
Cleanup Meets Std:	True
Last Inspection:	1988-03-17
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	TRUCKERS FOR HESS OIL
Spiller Company:	DAVE UNGEKER, M B TRUCK
Spiller Address:	212-328-3275
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"M B TO TAKE RESPONSIBILITY FOR CLEANUP. UPDATE:3-17-88 AS PER D.UNGEKER: 1GAL SPILLED, DRIVER DID NOT CAUSE SPILL BUT MB TRUCK TAKES RESPONSIBILITY. FUEL SPILLED ON ASPHALT.MB CLEANED UP. N.F.A. D.O'B"

All Materials:

Site ID:	213572
Operable Unit ID:	916420
Operable Unit:	01
Material ID:	462318
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU395 **BUILDING** **NY LTANKS** **S102155428**
NE **20 NORTH BROADWAY** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.306 mi.
1614 ft. **Site 2 of 4 in cluster AU**

Relative:
Higher

Actual:
229 ft.

LTANKS:

Spill Number/Closed Date:	0111039 / 2002-03-11
Facility ID:	0111039
Site ID:	84678
Spill Date:	2002-02-20
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported

BUILDING (Continued) **S102155428**

Reported to Dept:	2002-02-20
CID:	397
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-02-20
Spill Record Last Update:	2002-12-04
Spiller Name:	Not reported
Spiller Company:	APT COMPLEX
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77855
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/11/02 NORTHEAST REMOVED TANK AND DISPOSED OF 364 CUBIC YARDS OF CONTAMINATED SOIL."
Remarks:	"caller co was removing tank and discovered soil contamination"

All Materials:

Site ID:	84678
Operable Unit ID:	848108
Operable Unit:	01
Material ID:	528641
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0800897 / 2008-06-08
Facility ID:	0800897
Site ID:	396726
Spill Date:	2008-04-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2008-04-22
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

BUILDING (Continued) **S102155428**

UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-22
Spill Record Last Update:	2008-06-08
Spiller Name:	ISSAC
Spiller Company:	BUILDING
Spiller Address:	20 NORTH BROADWAY
Spiller County:	001
Spiller Contact:	ISSAC
Spiller Phone:	(718) 378-3000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	77855
DEC Memo:	"PBS 3-167320 June 8, 2008: Tank passed a retest after piping was repaired. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"FAILED DRY LEAK"

All TTF:

Facility ID:	0800897
Spill Number:	0800897
Spill Tank Test:	2453566
Site ID:	396726
Tank Number:	Not reported
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	396726
Operable Unit ID:	1153696
Operable Unit:	01
Material ID:	2144464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9500251 / 1997-12-05
Facility ID:	9500251
Facility Type:	ER
DER Facility ID:	77855

BUILDING (Continued) **S102155428**

Site ID:	84679
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-04-06
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-04-18
Spill Record Last Update:	1997-12-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DEFECTIVE GUAGE TANK OVERFILL ON CONCRETE FLOOR CONTRACTOR DOING CLEAN UP"

All Materials:

Site ID:	84679
Operable Unit ID:	1011023
Operable Unit:	01
Material ID:	368859
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9808000 / 2002-04-01
Facility ID:	9808000
Facility Type:	ER
DER Facility ID:	77855
Site ID:	84680
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	1998-09-30
Investigator:	jbodee
Referred To:	Not reported

BUILDING (Continued) **S102155428**

Reported to Dept:	1998-09-30
CID:	252
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-30
Spill Record Last Update:	2003-09-09
Spiller Name:	WES WOODLEAF
Spiller Company:	APARTMENT BLDG
Spiller Address:	20 NORTH BROADWAY
Spiller Company:	001
Contact Name:	WES WOODLEAF
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/01/2002 SEE NORTHEAST ENVIRONMENTAL UST REMEDIATION REPORT UNDER SPILL NUMBER 01-11039. NO FURTHER ACTION."
Remarks:	"OIL LINES HAVE BEEN EXCAVATED FROM TANK TO BLDG-PIPES HAVE A CRACK IN THEM RUNNING THROUGH FOUNDATION-BOIL HAS BEEN SHUT DOWN AND LEAK TO BE REPAIRED. NORTH EAST ENVIRONMENTAL ON SITE FOR REMOVAL OF CONTAMINATED SOIL."

All Materials:

Site ID:	84680
Operable Unit ID:	1065560
Operable Unit:	01
Material ID:	315536
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

396
SE
1/4-1/2
0.307 mi.
1621 ft.

PIRRO, MONSELL REALTY **NY LTANKS** **S100139873**
40 WALLER AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 222 ft.

LTANKS:

Spill Number/Closed Date:	8709325 / 1988-02-02
Facility ID:	8709325
Site ID:	162080
Spill Date:	1988-02-02
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-02-02
SWIS:	6017
Investigator:	jeokesso

PIRRO, MONSELL REALTY (Continued) **S100139873**

Referred To:	Not reported
Reported to Dept:	1988-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1988-02-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-09
Spill Record Last Update:	1988-02-10
Spiller Name:	MARIE TEDESCHI
Spiller Company:	JOE ZAHENSKY,914-478-5700
Spiller Address:	ROBISON OIL CORP.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : WCHD NOTIFIED, RICH DORAN, SPILL IS CONTAINED. N.F.A. / / : 02-10-88 DRAIN IN CELLAR HAS CAP ON IT. "
Remarks:	"TANK RUPTURE IN BASEMENT 275GAL. A/G TANK. CEMENT FLOOR. USEING SPEEDY DRY TO CLEAN UP."

All Materials:

Site ID:	162080
Operable Unit ID:	914412
Operable Unit:	01
Material ID:	464653
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AS397 **WHITE PLAINS DPW** **NY LTANKS** **S100177896**
SE **MAPLE & MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.310 mi.
1636 ft. **Site 2 of 3 in cluster AS**

Relative:
Higher

Actual:
228 ft.

LTANKS:

Spill Number/Closed Date:	9111846 / 1992-03-10
Facility ID:	9111846
Site ID:	90852
Spill Date:	1992-02-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	1992-02-18
SWIS:	6017

WHITE PLAINS DPW (Continued) **S100177896**

Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-02-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1992-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-02-25
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81978
DEC Memo:	""
Remarks:	"DURING UPGRADE TANK PULL CONTAMINATED SOIL DISCOVERED EXCAVATED AND STOCKPILED WILL TEST AND DISPOSED"

All Materials:

Site ID:	90852
Operable Unit ID:	965509
Operable Unit:	01
Material ID:	567527
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AS398 **WHITE PLAINS-FIRE HOUSE 6** **NY LTANKS** **S100140233**
SE **MAMARONECK & MAPLE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.310 mi.
1636 ft. **Site 3 of 3 in cluster AS**

Relative:
Higher

Actual:
228 ft.

LTANKS:

Spill Number/Closed Date:	8707149 / 1989-01-05
Facility ID:	8707149
Site ID:	311048
Spill Date:	1987-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1989-01-05
SWIS:	6017
Investigator:	jeokesso

WHITE PLAINS-FIRE HOUSE 6 (Continued) **S100140233**

Referred To:	Not reported
Reported to Dept:	1987-11-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-05
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-20
Spill Record Last Update:	1989-01-12
Spiller Name:	MR. BROCCHI
Spiller Company:	CITY OF WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	251062
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K SYSTEM- HIGH VOLUME LEAK.TO E & I & R. TANK REMOVED. NEW TANK INSTALLED"

All TTF:

Facility ID:	8707149
Spill Number:	8707149
Spill Tank Test:	1532377
Site ID:	311048
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	311048
Operable Unit ID:	911037
Operable Unit:	01
Material ID:	466122
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00

WHITE PLAINS-FIRE HOUSE 6 (Continued) **S100140233**

Oxygenate: Not reported

AV399 **GREENRIDGE ESTATES** **NY LTANKS** **S110140617**
SSE **1-13 GREENRIDGE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.311 mi.
1640 ft. **Site 1 of 3 in cluster AV**

Relative:
Higher

Actual:
254 ft.

LTANKS:

Spill Number/Closed Date:	0912193 / 2011-12-22
Facility ID:	0912193
Site ID:	425068
Spill Date:	2010-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-02-22
Spill Record Last Update:	2011-12-22
Spiller Name:	Not reported
Spiller Company:	GREEN RIDGE ESTATES
Spiller Address:	1-13 GREEN RIDGE AVE
Spiller County:	999
Spiller Contact:	WILLIAM
Spiller Phone:	(914) 760-5494
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373978
DEC Memo:	"2/22/10 tank is a 5k ust, will repair and retest...mm >>> Lalak, Chris 6/10/2011 12:51 PM >>> Wayne, Please follow up on these two old open spills 0912193 - 0911533 Chris --This is a PBS regulated facility. Wayne Schneider of WCDOH will follow up. jod >>> Schneider, Wayne 12/22/2011 1:46 PM >>> 0912193: 1-13 Greenridge Ave, White Plains tf 1/22/10. tanks are ASTs and passed retests. 12/22/11: DEC requires NFA at this time. jod"
Remarks:	"TANK TEST FAILURE. RETEST- UNCLEAR WHAT THE NEXT STEP WILL BE."

All Materials:

Site ID:	425068
Operable Unit ID:	1180801
Operable Unit:	01
Material ID:	2174794
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

GREENRIDGE ESTATES (Continued) **S110140617**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AV400 **CITY PARKING GARAGE** **NY LTANKS** **S100177695**
SSE **CHESTER AVE MARBLE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.311 mi.
1641 ft. **Site 2 of 3 in cluster AV**

Relative: Higher
Actual: 246 ft.

LTANKS:

Spill Number/Closed Date:	9109520 / 1992-03-25
Facility ID:	9109520
Site ID:	158538
Spill Date:	1991-12-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1991-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-10
Spill Record Last Update:	1992-03-25
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133970
DEC Memo:	""
Remarks:	"TANK FILLED ON 12/3 5 IN TANK NOW TANK IS IN A VAULT OIL IS LEAKING OUT THE BOTTOM WCHD NOTIFIED"

All Materials:

Site ID:	158538
Operable Unit ID:	963358
Operable Unit:	01
Material ID:	418130
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

CITY PARKING GARAGE (Continued) **S100177695**

Quantity: 250.00
Units: G
Recovered: .00
Oxygenate: Not reported

AU401 **APT BUILDING** **NY LTANKS** **S102153144**
NE **16 NORTH BROADWAY** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.318 mi.
1681 ft. **Site 3 of 4 in cluster AU**

Relative:
Higher

Actual:
231 ft.

LTANKS:
Spill Number/Closed Date: 0412306 / 2005-08-27
Facility ID: 0412306
Site ID: 337751
Spill Date: 2005-02-17
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2005-02-17
CID: 74
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-02-18
Spill Record Last Update: 2005-08-27
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 90153
DEC Memo: "August 27, 2005: PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "PBS No: 3-167223 "

All TTF:
Facility ID: 0412306
Spill Number: 0412306
Spill Tank Test: 1548607
Site ID: 337751
Tank Number: 1
Tank Size: 10000
Material: Not reported
EPA UST: Not reported

APT BUILDING (Continued) **S102153144**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

Spill Number/Closed Date:	0701599 / 2007-12-12
Facility ID:	0701599
Site ID:	381144
Spill Date:	2007-05-08
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2007-05-08
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-05-08
Spill Record Last Update:	2007-12-12
Spiller Name:	ARLENE
Spiller Company:	APARTMENT BUILDING
Spiller Address:	16 NORTH BROADWAY
Spiller County:	001
Spiller Contact:	ARLENE
Spiller Phone:	(914) 779-0405
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	90153
DEC Memo:	"07/31/07 Repaired and retested and closed by D Jackson - WCHD. TG"
Remarks:	"MINIAMAL AMOUNT RELEASED;"

All TTF:

Facility ID:	0701599
Spill Number:	0701599
Spill Tank Test:	1550827
Site ID:	381144
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03

APT BUILDING (Continued) **S102153144**

Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	381144
Operable Unit ID:	1138611
Operable Unit:	01
Material ID:	2128606
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	1104037 / 2011-07-12
Facility ID:	1104037
Facility Type:	ER
DER Facility ID:	90153
Site ID:	451622
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2011-07-12
Investigator:	kabrowne
Referred To:	Not reported
Reported to Dept:	2011-07-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-12
Spill Record Last Update:	2011-09-30
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	16 NORTH BROADWAY
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	""
Remarks:	"Caller reporting a spill of an unknown material contained in concrete Structure. Clean up pending identification."

APT BUILDING (Continued) **S102153144**

All Materials:

Site ID:	451622
Operable Unit ID:	1201809
Operable Unit:	01
Material ID:	2198370
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	8802449 / 1988-06-30
Facility ID:	8802449
Facility Type:	ER
DER Facility ID:	90153
Site ID:	101750
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1988-06-16
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1988-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	1988-06-22
Cleanup Meets Std:	True
Last Inspection:	1988-06-22
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-24
Spill Record Last Update:	1988-03-23
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/30/88: RUPTURED RETURN LINE REPAIRED FROM TANK TO BOILER. CONTAMINATED SOIL EXCAVATED AND REMOVED. 06/30/88: RUPTURED RETURN LINE REPLACED FROM TANK TO BOILER. CONTAMINATED SOIL EXCAVATED AND REMOVED. "
Remarks:	"#6 FUEL OIL LEAKED OUT EXCAVATE THE SOIL AND DEBRIS"

All Materials:

Site ID:	101750
Operable Unit ID:	919673
Operable Unit:	01
Material ID:	458015

APT BUILDING (Continued) **S102153144**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	125.00
Units:	G
Recovered:	125.00
Oxygenate:	Not reported

AT402 **CHURCH** **NY LTANKS** **S107657151**
SW **65 FISHER AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.320 mi.
1688 ft. **Site 3 of 3 in cluster AT**

Relative: **Lower**
Actual: **201 ft.**

LTANKS:

Spill Number/Closed Date:	0509976 / 2006-12-20
Facility ID:	0509976
Site ID:	355853
Spill Date:	2005-11-21
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-11-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-12-20
Spiller Name:	MS RIBELLA
Spiller Company:	ALLEN AME CHURCH
Spiller Address:	65 FISHER AVE
Spiller County:	001
Spiller Contact:	MS RIBELLA
Spiller Phone:	(914) 761-4397
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305892
DEC Memo:	"LEFT MESSAGE 12/02/05 Cross River Environmental to complete clean up. Report to follow. jod 02/24/06 NES removed tank and started excavating contaminated soil. Beneath the fuel oil contamination gasoline contaminated soil was encountered. Reportedly there is a gas station nearby. Chris Lalak of Westchester County Health to inspect. jod 10/24/06 National Environmental Specialists reported that the tank was removed along with 46.5 tons of impacted soil. NFA required. TG"
Remarks:	"1000 GALLON TANK HAD HOLES AND CONTAMINATED SOIL;"

CHURCH (Continued) **S107657151**

All Materials:
Site ID: 355853
Operable Unit ID: 1113186
Operable Unit: 01
Material ID: 2103241
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0513604 / 2006-12-20
Facility ID: 0513604
Facility Type: ER
DER Facility ID: 310223
Site ID: 360107
DEC Region: 3
Spill Cause: Other
Spill Class: C3
SWIS: 6017
Spill Date: 2006-02-24
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-02-24
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-02-24
Spill Record Last Update: 2006-12-20
Spiller Name: REVERAND SANDERS
Spiller Company: CHURCH
Spiller Address: 65 FISHER AVE
Spiller Company: 001
Contact Name: REVERAND SANDERS
DEC Memo: "10 - 15 yards removed & encountered gasoline impacted soil. Todd Ghiosay notified. 12-20-06 See remediation filed under DEC Spill 06-09976. TG"
Remarks: "CONTAMINATED SOIL AT THIS LOCATION AND HE BELIEVES IT MAY BE GASOLINE; OIL TANK HAS ALREADY BEEN REMOVED: DOH HAS BEEN NOTIFIED"

All Materials:
Site ID: 360107
Operable Unit ID: 1117296
Operable Unit: 01
Material ID: 2107798

CHURCH (Continued) **S107657151**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU403 **CON ED** **NY LTANKS** **S105998980**
NE **10 NORTH BROADWAY** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.322 mi.
1702 ft. **Site 4 of 4 in cluster AU**

Relative:
Higher

Actual:
226 ft.

LTANKS:

Spill Number/Closed Date:	0301652 / 2003-12-12
Facility ID:	0301652
Site ID:	302706
Spill Date:	2003-05-15
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-05-15
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-15
Spill Record Last Update:	2003-12-12
Spiller Name:	DONNA
Spiller Company:	BROOK PROPERTIES
Spiller Address:	60 MORROW AVE
Spiller County:	001
Spiller Contact:	RENE LEWIS
Spiller Phone:	(718) 378-7000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	244561
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 12/12/03 TANK PASSED RETEST 6/6/03. CLOSED BY WCHD."
Remarks:	"TANK FAILED THE TEST. "

All TTF:

Facility ID:	0301652
Spill Number:	0301652
Spill Tank Test:	1528379
Site ID:	302706
Tank Number:	1

CON ED (Continued) **S105998980**

Tank Size:	7500
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	302706
Operable Unit ID:	868209
Operable Unit:	01
Material ID:	506144
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0908496 / 2010-10-01
Facility ID:	0908496
Facility Type:	ER
DER Facility ID:	244561
Site ID:	421100
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2009-10-28
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2009-10-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-28
Spill Record Last Update:	2010-10-01
Spiller Name:	Not reported
Spiller Company:	ABEL GONZOLES

CON ED (Continued) **S105998980**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: SAME AS ABOVE
DEC Memo: "10-28-09: V.Mc. ^ JAMES WILSON/R&D SER.: Apt.complex, 7.5K UST, installed 1953, R&D to recomment EIR. 10/1/10 As per WCDOH Tibbets Apartments, 10 North Broadway, White Plains can be closed. Tightness test failure. Tank discovered to be leaking #6 oil, removed. Remediation completed. Numbers are ok. NFA JO'M "
Remarks: "Unk amount of # 6 oil spilled due to leak in underground tank. Clean up is pending at this time."

All Materials:
Site ID: 421100
Operable Unit ID: 1177035
Operable Unit: 01
Material ID: 2169776
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYP004849257
Facility Status: Not reported
Location Address 1: 10 NORTH BROADWAY
Code: BP
Location Address 2: SB 3687
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004849257
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2015

CON ED (Continued) **S105998980**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/07/2015
Trans1 Recv Date:	10/07/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/09/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004849257
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	013245150JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AW404 **PATRIOT MANAGEMENT** **NY LTANKS** **S100165922**
ENE **2 WESTCHESTER AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.325 mi.
1717 ft. **Site 1 of 2 in cluster AW**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Spill Number/Closed Date:	8800351 / 2004-05-06
Facility ID:	8800351
Site ID:	322460
Spill Date:	1988-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1988-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-02
Spill Record Last Update:	2004-05-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	259772
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 05/06/04 TANK WAS REMOVED IN 1988 BUT NO CLOSURE REPORT WAS SUBMITTED. ON 4-6-2004, PROPERTY OWNER HAD SOIL SAMPLES TAKEN FROM BORING IN AREA OF ORIGINAL TANK GRAVE. SAMPLE RESULTS FROM ADVANCED TANK SERVICES WERE ND. BASED UPON REPORT, NFA REQUIRED. jbo"
Remarks:	"5K TANK, LEAK RATE GREATER THAN 10GPH. PUMP TANK OUT."

All TTF:

Facility ID:	8800351
Spill Number:	8800351
Spill Tank Test:	1533629
Site ID:	322460
Tank Number:	Not reported
Tank Size:	0
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

PATRIOT MANAGEMENT (Continued) **S100165922**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 322460
Operable Unit ID: 915986
Operable Unit: 01
Material ID: 463066
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 1112238 / 2012-01-20
Facility ID: 1112238
Facility Type: ER
DER Facility ID: 259772
Site ID: 460167
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6017
Spill Date: 2012-01-20
Investigator: VPMCCABE
Referred To: Not reported
Reported to Dept: 2012-01-20
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-01-20
Spill Record Last Update: 2012-01-20
Spiller Name: MIKE/ROBISON OIL
Spiller Company: ROBISON OIL
Spiller Address: 2 WESTCHESTER AVE
Spiller Company: 999
Contact Name: ROBISON OIL
DEC Memo: "1-20-12: V.Mc. call to MIKE/ Rob.Oil: Outside Ab.Gr.vaulted tank, spilled onto concrete slab to tank. Crew on site completing clean up, expecting to finish clean up today. NFA."
Remarks: "Overfill spilled onto concrete pad. Cleanup underway."

All Materials:
Site ID: 460167

PATRIOT MANAGEMENT (Continued) **S100165922**

Operable Unit ID:	1210261
Operable Unit:	01
Material ID:	2207863
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

405
NNE
1/4-1/2
0.329 mi.
1739 ft.

PRESBYTERIAN CHURCH
39 NORTH BROADWAY
WHITE PLAINS, NY

NY LTANKS **S100139602**
N/A

Relative:
Higher

Actual:
262 ft.

LTANKS:

Spill Number/Closed Date:	0911530 / 2017-05-11
Facility ID:	0911530
Site ID:	424343
Spill Date:	2010-01-27
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	A2
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2010-01-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-01-27
Spill Record Last Update:	2017-06-01
Spiller Name:	VINCENTE VALSCO
Spiller Company:	WHITE PLAINS PRESBYTERIAN CHURCH
Spiller Address:	39 NORTH BROADWAY
Spiller County:	999
Spiller Contact:	BOB URBAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	104243
DEC Memo:	"ProTest to propose to excavate, isolate and retest. DT 1/27/10 3/4/10: WCHD PBS site. JO'M 10/12/11: This tank was repiped and retested in February of 2010. Tank reportedly passed the retest. Prior to documentation being submitted for closure of this spill, several thousand gallons of heating oil from this tank system impacted neighboring properties, storm drains, and the Bronx River. See Spill 0912623 for additional information. jod 05/11/17 This 8,000

PRESBYTERIAN CHURCH (Continued) **S100139602**

LUST was removed under spill number 0912623. NFA for this spill number. TG"
Remarks: "TANK TEST FAILURE ON A 8000 GALLON UST"

All Materials:
Site ID: 424343
Operable Unit ID: 1180125
Operable Unit: 01
Material ID: 2173985
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Spill Number/Closed Date: 8705816 / 1988-03-04
Facility ID: 8705816
Site ID: 120033
Spill Date: 1987-10-09
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: 1988-03-04
SWIS: 6017
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1987-10-09
CID: Not reported
Water Affected: NONE
Spill Notifier: Tank Tester
Last Inspection: 1988-03-04
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1987-11-18
Spill Record Last Update: 2003-08-20
Spiller Name: JACK JONES
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 104243
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 10/13/87-WILL RETEST. / / : 02-16-88 TANK HAS BEEN RELINED & REFILLED. WILL RETEST ASAP. WILL CALL IN RESULTS. L.R. 03/04/88: TANK PASSED RETEST. N.F.A. L.R. "
Remarks: "TTTF-8K TANK;-0.253 GPH"

All TTF:
Facility ID: 8705816

PRESBYTERIAN CHURCH (Continued) **S100139602**

Spill Number:	8705816
Spill Tank Test:	1531881
Site ID:	120033
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	120033
Operable Unit ID:	911852
Operable Unit:	01
Material ID:	468384
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

406
South
1/4-1/2
0.334 mi.
1764 ft.

APARTMENT
8 LONGVIEW AVE
WHITE PLAINS, NY

NY LTANKS **S110045423**
NY Spills **N/A**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Spill Number/Closed Date:	0907812 / 2009-11-04
Facility ID:	0907812
Site ID:	420361
Spill Date:	2009-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2009-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

APARTMENT (Continued) **S110045423**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-12
Spill Record Last Update:	2009-11-04
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOSP
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROSS EDDY
Spiller Phone:	(914) 681-1000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343572
DEC Memo:	"10/15/09: I called the tank tester Ken Gelok from CTT. Confirmed TTF at PBS regulated facilty. He had no further info on a plan of action. WCDOH PBS will follow up. jod 11/04/09: From WCDOH PBS - #0907812 White plains Hospital, 8 Longview Ave, White Plains Tightness test failure - tank passed on 10/20/2009 NFA jod"
Remarks:	""

All Materials:

Site ID:	420361
Operable Unit ID:	1176335
Operable Unit:	01
Material ID:	2169020
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	1007877 / 2011-07-05
Facility ID:	1007877
Site ID:	441326
Spill Date:	2010-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2010-10-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-25
Spill Record Last Update:	2017-12-12
Spiller Name:	Not reported

APARTMENT (Continued) **S110045423**

Spiller Company:	HOMEOWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	STEPHANIE EAGANS
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343572
DEC Memo:	"10/25/10 - Retest. Follow up will be conducted by Westchester County DOH since tank is PBS regulated. KAB 7/5/11 ttf, tank removed, contamination removed, endpoint samples below CP-51 standards NFA JO'M 12/12/17: Also see Spill 1007255. jod"
Remarks:	"TANK TEST FAILURE."

All Materials:

Site ID:	441326
Operable Unit ID:	1191891
Operable Unit:	01
Material ID:	2187096
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	1007255 / 2017-12-12
Facility ID:	1007255
Site ID:	440652
Spill Date:	2010-10-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2010-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-06
Spill Record Last Update:	2017-12-12
Spiller Name:	BOB BIDDISCOMBE
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	8 LONGVIEW AVE
Spiller County:	999
Spiller Contact:	BOB BIDDISCOMBE
Spiller Phone:	(914) 681-1000
Spiller Extention:	Not reported

APARTMENT (Continued) **S110045423**

DEC Region: 3
DER Facility ID: 343572
DEC Memo: "10-6-10 Spoke with Kathy. This is a 4k UST. Loud bubbling during tank test. PBS #3-104469 RP was told by US Tank Tech that they need to empty tank. Undecided about next step. Will notify WCHD. jm
10/14/10 Hospital wanted tank uncover, repaired and retested. There was nothing to repair so a well point sample was collected. Sample is contaminated with petroleum. Tank will not be retested....mm
12/12/17: This 4k UST failed a tightness test on Oct 6, 2010 reported as this Spill 1007255 Callback notes on this case number indicate UST would not be retested as well point was contaminated. The UST was retested on Oct 20, 2010 and failed. Retest was reported as Spill 1007877 That second Spill number was closed on July 5, 2011 with the following notation: 7/5/11 ttf, tank removed, contamination removed, endpoint samples below CP-51 standards NFA JO'M *WCDoH PBS data 3-104469 indicates this 4k UST was closed/removed January 2011 and a new 2k UST was installed. Based upon this information, this Spill case number closed and referred to Spill 1007877. jod"
Remarks: "tank test failure. restest likely"

All Materials:
Site ID: 440652
Operable Unit ID: 1191260
Operable Unit: 01
Material ID: 2186382
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0712395 / 2008-07-16
Facility ID: 0712395
Facility Type: ER
DER Facility ID: 343572
Site ID: 394002
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6017
Spill Date: 2008-02-25
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2008-02-25
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False

APARTMENT (Continued) **S110045423**

UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-25
Spill Record Last Update:	2008-07-16
Spiller Name:	SAL MANCUSO
Spiller Company:	APART
Spiller Address:	8 LONGVIEW AVE
Spiller Company:	001
Contact Name:	WESTCHESTER ESTATES
DEC Memo:	"Spoke with Jeneen Ferrara from National Environmental. Mancuso Oil caused spill. NES will begin cleanup tomorrow. She says that they were informed that it was minor. Tried to contact PRP phone number that was given, but it appears to be a fax machine. 7/19/08: Stefan Goreau of WCHD confirmed NES completed clean up and soil sample results were ND for contamination. NFA jod"
Remarks:	"OVERFILL OF TANK AND CALLERS CLEANING UP"

All Materials:

Site ID:	394002
Operable Unit ID:	1150949
Operable Unit:	01
Material ID:	2141603
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX407 **WHITE PLAINS HOSPITAL CENTER** **NY LTANKS** **S104284805**
South **41 E POST RD** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.335 mi.
1768 ft. **Site 1 of 6 in cluster AX**

Relative:
Higher

Actual:
214 ft.

LTANKS:

Spill Number/Closed Date:	1107393 / 2011-10-31
Facility ID:	1107393
Site ID:	455090
Spill Date:	2011-09-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Remediation Phase:	0
Date Entered In Computer:	2011-09-12
Spill Record Last Update:	2011-10-31
Spiller Name:	BOB
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD
Spiller County:	999
Spiller Contact:	STEPHANIE EAGANS
Spiller Phone:	(845) 528-0370
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	350007
DEC Memo:	"9/12/11- Elite reports failure was below product level. Tank also failed previous test- 1105346. Elite reports that Todd ghiosay and WCHD are involved with site. DT >>> Lalak, Chris 9/12/2011 2:32 PM >>> I am dealing with this site. I have asked them to empty the tank immediately. (product was present in the tank top sump) There is also an old open spill with oil getting into the basement from their other UST. jod 10/31/11: Update received from Chris Lalak of WCDoH: 1107393 NFA WP Hospital (see 1105346 open) jod"
Remarks:	"Failed Tank Test"

All Materials:

Site ID:	455090
Operable Unit ID:	1205238
Operable Unit:	01
Material ID:	2202084
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0504642 / 2006-05-23
Facility ID:	0504642
Facility Type:	ER
DER Facility ID:	65131
Site ID:	349576
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6017
Spill Date:	2005-07-18
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2005-07-18
CID:	38
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-20
Spill Record Last Update:	2006-05-26
Spiller Name:	DAHL, OSSIE
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD
Spiller Company:	001
Contact Name:	DAHL, OSSIE
DEC Memo:	"amount of oil is minimal, slight sheen on water, being cleaned up - nfa"
Remarks:	"Flooding in basement caused residual oil in basement area to mix w/ water. Cleanup is being done by northeast environmental and tradewinds will be responding later."

All Materials:

Site ID:	349576
Operable Unit ID:	1107165
Operable Unit:	01
Material ID:	2097060
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	1105346 / 2017-04-04
Facility ID:	1105346
Facility Type:	ER
DER Facility ID:	350007
Site ID:	452999
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2011-08-10
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2011-08-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2011-08-10
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-08-10
Spill Record Last Update:	2017-04-04
Spiller Name:	Not reported

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Spiller Company: WHITE PLAINS HOSPITAL
Spiller Address: Not reported
Spiller Company: 999
Contact Name: STEPHANIE EAGENS
DEC Memo: "8/10/11 - During a tank test of a 20K UST, No. 6 fuel oil was discovered in the sump. Caller is scheduling for 8/11/11: I responded to the location yesterday. I first checked outfall at Bronx River and no oil or sheen was noted. I spoke with Ray Hilyer, Elite was scheduled to test the tank last week and did not after finding an uncapped feed line. Ray states he notified WCDOH Wayne Schneider. Elite returned yesterday and found a large quantitiy of #6 Oil in a manway sump next to the UST. I met with Hospital Engineer Bob Biddiscombe and observed the oil in the sump. He states it is contained within the secondary containment and stated Elite was en route to vac it out. I again contacted Elite, they have not been hired. Bob Biddiscombe spoke with Elite via phone directly while I was there. Elite will be there first thing in the morning. No oil was observed in the basement sump where previous major spills have occurred. Mr Biddiscombe stated the sump has been re-piped, and now discharges to the sanitary sewer instead of the storm drain. WCDOH will follow up. Chris Lalak is enroute this morning to confirm the sump has been vacuumed out and investigation will continue. jod *Chris Lalak reports that the manway has still not been vacuumed out this morning. Email update from Chris: Lalak, Chris 8/11/2011 11:52 AM They still didn't pump it out Robert Biddiscombe was going to call Elite or Island pump and tank to get it pumped. He doesn't know if it is a contained sump. I gave him 1 week to TT tank and lines. 1 month for env. Investigation and. pump it out today and check daily. I also stated if it is visually found that the sump is leaking an immediate investigation is needed. jod 8/12/11: Chris Lalak reports Envirowaste completed pump out. Further investigation required. jod 10/16/12: See letter from Chris Lalak of WCDoH in EDocs. jod 5/30/13: Report from Elite dated Jan 14th 2013 entered into Edocs. Message sent to Chris Lalak requesting status report. jod 040417- Email, This spill started on 2009 with 6 oil entering a basement Sump. The sump apparently collects water the buildings footing drains. White Plains hospital is a huge urban hospital complex, occupying a full city block. The spill was determined to be from piping leaks associate with two old 6 oil tanks. Tank 1 (20K ust was abandoned in place by Castlton). Removal of this tank was not possible. Free product was encountered around this tank. Castlton installed a monitoring/recovery well thru the tank. The well is identified as 15 . Free product was recovered from the well, into a holding tank. The well was then sampled 4 times 2014/2015. Some minor volatile and semi-volatiles are still present. The highest is 29 PPB pyrene. MW number 4 is located next to the abandoned tank and was sampled at the same time and was essentially clean. Tank 2 was removed by Elite. (the other old 20K UST) Royal remediated the sump for approximately 2 years.(2009-2010) Hydro Environmental Technologies (HETI) performed a GW monitoring investigation in 2012. The Hospital has been cooperatively remediating a very difficult spill. No oil has been found in the sump since 2013. The monitoring/recovery well installed thru the 20 K 6 oil UST, (and thru the concrete Pads) has been substantially remediated. Pristine remediation is not possible in this case. Well sampling performed by Castlton in 2014 and 2015 is attached. The hospital is located in an urban city with no drinking water wells near by. The abandoned UST has been filled in with slurry Concrete

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Remarks: except for the recovery well. It could not be removed. NFA- RDB " "sump is full of oil/investigation underway"

All Materials:
Site ID: 452999
Operable Unit ID: 1203158
Operable Unit: 01
Material ID: 2199776
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: Not reported
Oxygenate: Not reported

Spill Number/Closed Date: 0803913 / 2008-07-07
Facility ID: 0803913
Facility Type: ER
DER Facility ID: 350007
Site ID: 400727
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6017
Spill Date: 2008-07-03
Investigator: mbmastro
Referred To: Not reported
Reported to Dept: 2008-07-03
CID: 406
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Police Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-07-03
Spill Record Last Update: 2008-07-22
Spiller Name: DISP 603 CEPIN
Spiller Company: WHITE PLAINS HOSPITAL
Spiller Address: 41 EAST POST RD.
Spiller Company: 001
Contact Name: DISP 603 CEPIN
DEC Memo: "FD did cleanup, hospital crew will have speedi-dri material disposed of. - NFA"
Remarks: "Material was released from the elevator into the parking structure. Spill is contained. Absorbent material was applied unknown who is completing clean up."

All Materials:
Site ID: 400727
Operable Unit ID: 1157541
Operable Unit: 01

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Material ID:	2148564
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9910974 / 2005-01-02
Facility ID:	9910974
Facility Type:	ER
DER Facility ID:	65131
Site ID:	149038
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1999-12-15
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1999-12-15
CID:	246
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-15
Spill Record Last Update:	2005-01-02
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	SCOTT WILLIAMS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 1/2/05 report that there was a 12 gallon overfill of #6 oil during delivery--close "
Remarks:	"driver making a fuel delivery-a possible broken fill line caused material to come up from ground beneath fill hole. spill contained and being investigated in am."

All Materials:

Site ID:	149038
Operable Unit ID:	1089666
Operable Unit:	01
Material ID:	296448
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Country: USA
EPA ID: NYR000129965
Facility Status: Not reported
Location Address 1: 41 E. POST ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000129965
Mailing Name: WHITE PLAINS HOSPITAL CENTER
Mailing Contact: LISA SILVER
Mailing Address 1: 41 POST ROAD
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146810600

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: 2018
Trans1 State ID: MAD039322250
Trans2 State ID: ALD067138891
Generator Ship Date: 06/01/2018
Trans1 Recv Date: 06/01/2018
Trans2 Recv Date: 06/06/2018
TSD Site Recv Date: 06/18/2018
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000129965
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: OHD000724153
TSDF ID 2: Not reported
Manifest Tracking Number: 011909742FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H070
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	47
Units:	P - Pounds
Number of Containers:	1
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	D011
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
83 additional NY MANIFEST: record(s) in the EDR Site Report.

AX408 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S104513751**
South **41 EAST POST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.335 mi.
1768 ft. **Site 2 of 6 in cluster AX**

Relative: **Higher**
Actual: **214 ft.**

LTANKS:

Spill Number/Closed Date:	9414693 / 1995-02-13
Facility ID:	9414693
Site ID:	68377
Spill Date:	1995-02-08
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1995-02-13
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	HESS OIL

WHITE PLAINS HOSPITAL (Continued) **S104513751**

Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65131
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER WAS TOLD BY HOSPITAL ENGINEER TO OFF LOAD 6000 GALS. OF #6 FUEL OIL INTO TANK TANK IS SUPPOSED TO HOLD 20000 GALS TANK VENTED & SPILLED ABOUT 50 GAL CREW CLEANED UP"

All Materials:

Site ID:	68377
Operable Unit ID:	1012229
Operable Unit:	01
Material ID:	373425
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV409 **JOHN L WHITE RESIDENCE** **NY LTANKS** **S110140588**
SSE **9 GREENRIDGE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.341 mi.
1800 ft. **Site 3 of 3 in cluster AV**

Relative:
Higher

Actual:
260 ft.

LTANKS:

Spill Number/Closed Date:	0911533 / 2011-10-28
Facility ID:	0911533
Site ID:	424347
Spill Date:	2010-01-27
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-01-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-01-27
Spill Record Last Update:	2011-10-28
Spiller Name:	KEN GELOK

JOHN L WHITE RESIDENCE (Continued) **S110140588**

Spiller Company:	JOHN L WHITE RESIDENCE
Spiller Address:	9 GREEN RIDGE AVE
Spiller County:	999
Spiller Contact:	KEN GELOK
Spiller Phone:	(201) 797-1909
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373287
DEC Memo:	"Site is condominimum. Tank size is 5K. Caller states tank is registered with WCHD and he will notify WCHD. dt 1/27/10 5/13/11: Message sent to WCDOH requesting PBS info. jod >>> Lalak, Chris 6/10/2011 12:51 PM >>> Wayne, Please follow up on these two old open spills 0912193 - 0911533 Chris --This is a PBS regulated facility. Wayne Schneider of WCDOH will follow up. jod 10/28/2011 As per WCDOH Greenridge estates. 1-13 Greenridge ave, white plains- passed retest NFA JO'M"
Remarks:	"TANK TEST FAILURE"

All Materials:

Site ID:	424347
Operable Unit ID:	1180129
Operable Unit:	01
Material ID:	2173988
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AY410 **YOUNG COAL & LUMBER SITE** **NY BROWNFIELDS S113492634**
WSW **55 BANK STREET** **NY MANIFEST N/A**
1/4-1/2 **WHITE PLAINS, NY 10601**
0.341 mi.
1801 ft. **Site 1 of 2 in cluster AY**

Relative: **Lower**
Actual: **204 ft.**

BROWNFIELDS:

Program:	BCP
Site Code:	481411
Acres:	2.24
HW Code:	C360131
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	05/01/2013
Record Updated Date:	07/17/2018
Update By:	DACROSBY
Site Description:	Location: The site is located at 55 Bank Street in White Plains, Westchester County. The site is located in the Central Business District of the City of White Plains on the west side of Bank Street, just south of the intersection of Main Street and Bank Street. To the west is the Metro-North railroad right of way. Bank Street is located along the eastern border, a car dealership is located adjacent to the southern border, and a parking lot for the Bank Street Commons Apartment building is located to the north. Site Features: The site is presently under construction as a commercial/residential building.

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

The site was formerly a 2.24-acre parking lot for the nearby commuter railroad station. The site was used as a parking lot for over 40 years. Current Zoning/Use: The current zoning of the site is Core Business-4 (CB-4). Municipally-operated parking lots and multifamily dwellings, a restricted residential use, are permitted uses in CB-4 zones. Past Uses of the Site: The property was used as a coal and lumber yard starting in 1885. The lumber yard comprised of a mill, several small sheds, coal and lumber storage areas, and railroad spurs. By 1911, the property was being used for manufacturing sashes, blinds and trim, and for the storage of grain, fertilizer, and feed. During the late 1800s and early 1900s, portions of the eastern side were occupied by several residential homes. By 1953, the southeastern corner of the property was improved with a commercial building, while the remaining portions were public parking lots. The commercial building was razed by 1974, and the site has been operated as a parking lot since that time. Site Geology and Hydrogeology: The site is level ground and covered with asphalt. Surface water drains to a storm sewer system that runs to the Bronx River which is about 500 yards to the west. The shallow soil horizon consists of historic fill found at a depth from 1.5 -26 feet below grade. Below the fill, subsurface soils consist of predominantly sands with some silts and gravels. Bedrock was located at 80-120 feet below grade and is believed to by gneiss and schist. Overburden groundwater was encountered at a depth of 28 feet below grade and flows to the south. The Bronx River, which flows to the south, is located about 0.25 mile west of the site. However, the site is located above the current 100 year flood elevation. Site storm water is transported via storm drains to a storm water collection system and discharges to the Bronx River. The Bronx River Parkway is located adjacent to the Bronx River just west of the site.

Env Problem: Nature and Extent of Contamination: Remediation of the site to track 1 soil cleanup objectives was completed in November 2016. Soil: Remediation is complete. The entire site was excavated to a depth of approximately 26 feet. No surface soils remain. Based on the investigations conducted the primary contaminants of concern in subsurface soils were inorganics (metals) including mercury, copper lead and zinc. These metals were present above the unrestricted soil cleanup objectives. These compounds were present in the fill materials used to grade the site and surrounding areas, and contamination did not migrated from the site to adjacent parcels. These inorganics were not found in on-site groundwater above NYS Groundwater Standards in filtered samples. Aluminum, iron, and sodium were detected above standards in onsite groundwater but are considered to be naturally occurring. Groundwater: Chlorinated volatile organic compounds (CVOCs) were detected in on-site groundwater including tetracholoethylene (PCE) at a maximum level of 13 parts per billion (ppb), and trichloroethene (TCE) at a maximum level of 28 ppb. The groundwater quality standard for both of these compounds is 5 ppb. CVOCs were not detected in the subsurface soil samples collected from the site, the groundwater investigation suggests that the source originates from an off-groundwater source. The site remediation is complete. The site has a basement foundation that includes a vapor barrier and a subsurface parking garage which is ventilated. Because there is a vapor barrier and a ventilated subsurface parking garage a soil vapor intrusion investigation was not conducted.

Health Problem: People are not drinking the contaminated groundwater because the area

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process which is similar to the movement of radon gas from the subsurface in to the indoor air of buildings, is referred to as soil vapor intrusion. A vapor barrier has been installed beneath the building foundation to minimize the potential of vapors from entering the building. Additionally, a sub-grade parking garage ventilation system required by building codes will be installed prior to building occupancy to prevent vapors from accumulating in the structure.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	2013-05-01 13:48:00
Record Upd:	2016-11-30 10:28:00
Updated By:	GWHEITZM
Own Op:	Owner
Sub Type:	06
Owner Name:	James M. Driscoll
Owner Company:	WP North Tower LLC
Owner Address:	One Penn Plaza, Suite 1801
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	City of White Plains
Owner Address:	255 Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601-2475
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Brian Kenney, Director
Owner Company:	White Plains Central Library
Owner Address:	100 Martine Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	P03
Owner Name:	James Driscoll
Owner Company:	WP South Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	P03

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Owner Name:	Please call for appointment
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Mr. James Driscoll
Owner Company:	WP South Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	Mr. James Driscoll
Owner Company:	WP North Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	P03
Owner Name:	James Driscoll
Owner Company:	LCOR 55 Bank Street LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10199
Owner Country:	United States of America
HW Code:	C360131
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	C360131
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Waste Code:	Not reported
HW Code:	C360131
Waste Type:	COPPER
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Test
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2015-08-03 15:48:00
Record Updated:	2015-08-03 15:48:00
Updated By:	GWHEITZM
Crossref ID:	C360131-12-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2016-10-24 13:35:00
Record Updated:	2016-10-24 13:35:00
Updated By:	DACROSBY

NY MANIFEST:

Country:	USA
EPA ID:	NYR000222273
Facility Status:	Not reported
Location Address 1:	55 BANK STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000222273
Mailing Name:	YOUNG COAL & LUMBER SITE
Mailing Contact:	NP NORTH TONER LLC
Mailing Address 1:	ONE PENN PLAZA
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10119
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127600060

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2015
Trans1 Recv Date:	12/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Generator EPA ID:	NYR000222273
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	009464564FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	44820
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AZ411 **COMMERCIAL PROPERTY** **NY LTANKS** **S106702432**
SSE **235 MAMARONECK AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.342 mi.
1805 ft. **Site 1 of 3 in cluster AZ**

Relative: LTANKS:
Higher

Spill Number/Closed Date:	1112859 / 2012-03-30
Facility ID:	1112859
Site ID:	460824
Spill Date:	2012-02-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported

Actual:
232 ft.

COMMERCIAL PROPERTY (Continued) **S106702432**

Reported to Dept:	2012-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-02-09
Spill Record Last Update:	2012-04-02
Spiller Name:	TONYA BASALYGA
Spiller Company:	SILVERMAN REALTY
Spiller Address:	235 MAMARONECK DR
Spiller County:	999
Spiller Contact:	TONYA BASALYGA
Spiller Phone:	(914) 683-8000
Spiller Extention:	328
DEC Region:	3
DER Facility ID:	110492
DEC Memo:	"2/9/12 - To isolate the tank and retest. KAB 3/30/12 As per WCDOH ttf, passed retest after remote fill and vent replacement."
Remarks:	"retest pending, failed with dry leak"

All Materials:

Site ID:	460824
Operable Unit ID:	1210926
Operable Unit:	01
Material ID:	2208598
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0404588 / 2005-01-10
Facility ID:	0404588
Site ID:	128036
Spill Date:	2004-07-28
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCHD
Reported to Dept:	2004-07-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

COMMERCIAL PROPERTY (Continued) **S106702432**

Remediation Phase:	0
Date Entered In Computer:	2004-07-28
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	SILVERMANN REALITY
Spiller Address:	237 MAMARONECK AVE.
Spiller County:	001
Spiller Contact:	SILVERMANN REALITY
Spiller Phone:	(914) 557-0310
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	110492
DEC Memo:	"01/10/05 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"VACCUM TEST; VENT IS BROKEN"

All TTF:

Facility ID:	0404588
Spill Number:	0404588
Spill Tank Test:	1529478
Site ID:	128036
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	128036
Operable Unit ID:	887658
Operable Unit:	01
Material ID:	488573
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0712619 / 2008-03-06
Facility ID:	0712619
Facility Type:	ER
DER Facility ID:	110492
Site ID:	394259

COMMERCIAL PROPERTY (Continued) **S106702432**

DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-03-02
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-03-02
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-02
Spill Record Last Update:	2008-03-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ABOVE
DEC Memo:	"WCDOH responded, clean up completed."
Remarks:	"OVERFILL OF TANK - OIL COMPANY ON SITE - THREW DRAINING PIPE INTO SUB PUMP - BLDG OWNER WANTS AUTHORIZATION TO HAVE PUMP TURNED BACK ON - REQUESTS CALLBACK ASAP"

All Materials:

Site ID:	394259
Operable Unit ID:	1151204
Operable Unit:	01
Material ID:	2141910
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AY412 **PEPE MOTORS INC** **RCRA-CESQG** **1000197633**
WSW **50 BANK ST** **NY LTANKS** **NYD056298037**
1/4-1/2 **WHITE PLAINS, NY 10606** **FINDS**
0.345 mi. **ECHO**
1823 ft. **Site 2 of 2 in cluster AY** **NY MANIFEST**

Relative:
Lower

Actual:
206 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	PEPE MOTORS INC
Facility address:	50 BANK ST WHITE PLAINS, NY 10606
EPA ID:	NYD056298037
Mailing address:	BANK ST

PEPE MOTORS INC (Continued) **1000197633**

WHITE PLAINS, NY 10606
Contact: Not reported
Contact address: BANK ST
WHITE PLAINS, NY 10606
Contact country: US
Contact telephone: Not reported
Contact email: Not reported
EPA Region: 02
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: EUGENE PEPE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: EUGENE PEPE
Owner/operator address: NOT REQUIRED
NOT REQUIRED, WY 99999
Owner/operator country: US
Owner/operator telephone: 212-555-1212
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

PEPE MOTORS INC (Continued) **1000197633**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/01/2006
Site name: PEPE MOTORS INC
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 04/06/1995
Site name: PEPE MOTORS INC
Classification: Small Quantity Generator

. Waste code: NONE
. Waste name: None

Date form received by agency: 03/28/1994
Site name: PEPE MOTORS INC.
Classification: Large Quantity Generator

Date form received by agency: 11/19/1986
Site name: PEPE MOTORS INC
Classification: Large Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC

PEPE MOTORS INC (Continued) **1000197633**

ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

LTANKS:

Spill Number/Closed Date:	9607100 / 1999-04-29
Facility ID:	9607100
Site ID:	284462
Spill Date:	1996-09-04
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-09-04
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-09-04
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	STEVEN MCGUIRE
Spiller Phone:	(914) 561-1512
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	230673
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY/BUZZELLI 04/29/1999 BASED UPON TANK CLOSURE REPORT, SPILL IS CLOSED."
Remarks:	"contact person - joe sallon - 914-949-4004 on site"

All TTF:

Facility ID:	9607100
Spill Number:	9607100
Spill Tank Test:	1544730
Site ID:	284462
Tank Number:	3000
Tank Size:	3000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20

PEPE MOTORS INC (Continued) **1000197633**

Test Method 2: USTest 2000/P/LL plus USTest 2000/U
Leak Rate: .10
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 284462
Operable Unit ID: 1035061
Operable Unit: 01
Material ID: 346364
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

FINDS:

Registry ID: 110004360423

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000197633
Registry ID: 110004360423
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004360423

NY MANIFEST:
Country: USA
EPA ID: NYD056298037
Facility Status: Not reported
Location Address 1: 50 BANK STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10606
Location Zip 4: Not reported

PEPE MOTORS INC (Continued) **1000197633**

NY MANIFEST:

EPAID:	NYD056298037
Mailing Name:	PEPE MOTOR
Mailing Contact:	PEPE MOTOR
Mailing Address 1:	50 BANK STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149494000

NY MANIFEST:

Document ID:	ILA8347366
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	UPW151288
Trans2 State ID:	UPW203954
Generator Ship Date:	08/10/1999
Trans1 Recv Date:	08/10/1999
Trans2 Recv Date:	08/12/1999
TSD Site Recv Date:	08/17/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056298037
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	ILD980613913
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00007
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

PEPE MOTORS INC (Continued) **1000197633**

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

AW413 **CON ED** **NY LTANKS** **S103558616**
ENE **300 MAIN ST** **NY MANIFEST** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10601**
0.351 mi.
1851 ft. **Site 2 of 2 in cluster AW**

Relative:
Higher

Actual:
222 ft.

LTANKS:

Spill Number/Closed Date:	8708398 / 1988-02-17
Facility ID:	8708398
Site ID:	76155
Spill Date:	1987-12-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1988-02-17
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-12-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	1988-02-17
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-01-28
Spill Record Last Update:	1988-04-04
Spiller Name:	Not reported
Spiller Company:	W.R.G. MANAGEMENT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	130071
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 02/17/88: JOSH SEGEL INDICATED THAT TANK TESTED TIGHT ON 01-21-88 HAZCO. N.F.A.J.OK. 04/04/88: AS PER JOE MCCARTHY: NOTHING DONE AT THIS POINT. CALLED TANK COMPANY TO LOOK AT SITUATION. REQUESTED TANK TO BE EMPTIED ASAP. JOSH SEIGEL TO CALL BACK TODAY. "
Remarks:	"4YRS. TANK WAS CLEANED HAD TO CUT HHOLE IN TANK. SOIL IS CONTAMINATED OOZING WITH PRODUCT LEAK RATE HIGH 5K TANK. WANT DEC ADVICE"

All TTF:

Facility ID:	8708398
Spill Number:	8708398
Spill Tank Test:	1532856
Site ID:	76155
Tank Number:	Not reported
Tank Size:	0
Material:	0002

CON ED (Continued) **S103558616**

EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 76155
Operable Unit ID: 913830
Operable Unit: 01
Material ID: 463792
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 9810968 / 2000-02-09
Facility ID: 9810968
Site ID: 76156
Spill Date: 1998-12-01
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 1998-12-01
CID: 252
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-12-01
Spill Record Last Update: 2000-03-24
Spiller Name: TOM GALLINGER
Spiller Company: APT BUILDING
Spiller Address: 101 ELWOOD AV
Spiller County: 001
Spiller Contact: JOYCE PARKER
Spiller Phone: (914) 939-7100
Spiller Extention: 118
DEC Region: 3
DER Facility ID: 130071

CON ED (Continued) **S103558616**

DEC Memo: ""
Remarks: "ISOLATION TEST TO BE DONE IN NEXT TWO WEEKS"

All TTF:
Facility ID: 9810968
Spill Number: 9810968
Spill Tank Test: 1546589
Site ID: 76156
Tank Number: 1
Tank Size: 5000
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 76156
Operable Unit ID: 1071857
Operable Unit: 01
Material ID: 314826
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 9209346 / 1993-07-19
Facility ID: 9209346
Site ID: 153296
Spill Date: 1992-11-11
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: 1993-07-19
SWIS: 6017
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1992-11-11
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0

CON ED (Continued) **S103558616**

Date Entered In Computer:	1992-11-19
Spill Record Last Update:	1993-08-03
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	130071
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"WILL EIR PETRO-TITE"

All TTF:

Facility ID:	9209346
Spill Number:	9209346
Spill Tank Test:	1540836
Site ID:	153296
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	153296
Operable Unit ID:	972998
Operable Unit:	01
Material ID:	406397
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NYP004859546
Facility Status:	Not reported
Location Address 1:	300 MAIN ST
Code:	BP
Location Address 2:	Not reported

CON ED (Continued) **S103558616**

Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004859546
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2015
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2015
Trans1 Recv Date:	10/24/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/28/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004859546
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014473206JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	11000
Units:	P - Pounds

CON ED (Continued) **S103558616**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

---

414 ESE 1/4-1/2 0.355 mi. 1873 ft.

CROWN PLACE HOTEL
66 HALE AVE
WHITE PLAINS, NY 10601

NY LTANKS **S111836460**
N/A

Relative: Lower

Actual: 168 ft.

LTANKS:

Spill Number/Closed Date:	1105926 / Not Reported
Facility ID:	1105926
Site ID:	453595
Spill Date:	2011-08-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-08-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	2011-08-24
Spill Record Last Update:	2014-08-27
Spiller Name:	HOTETON SMITH
Spiller Company:	CROWN PLAZA HOTEL
Spiller Address:	66 TALE AVE
Spiller County:	999
Spiller Contact:	HOTETON SMITH
Spiller Phone:	(914) 821-1349
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	408220
DEC Memo:	"8-24-11: V.Mc. call to H.Smith: Left Mess.:Req. Call to Dispt. 8-25-11 Mr Smith called. Will be meeting with NE Env to discuss repair and retest. Advised him to submit documentation to close spill. jc 4/11/12 Tank was repaired by Northeast and retested. It failed again. The tank's owner is contacting Northeast to have the

CROWN PLAZA HOTEL (Continued) **S111836460**

tank removed...mm"
Remarks: "tank failure -"

All Materials:
Site ID: 453595
Operable Unit ID: 1203754
Operable Unit: 01
Material ID: 2200483
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AX415 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S100964742**
South **DAVIS AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.356 mi.
1881 ft. **Site 3 of 6 in cluster AX**

Relative: **Higher**
Actual: **221 ft.**

LTANKS:
Spill Number/Closed Date: 9303501 / 1996-06-18
Facility ID: 9303501
Site ID: 66799
Spill Date: 1993-06-14
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1993-06-17
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1993-06-21
Spill Record Last Update: 1996-06-18
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 63920
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "

WHITE PLAINS HOSPITAL (Continued) **S100964742**

Remarks: "TYREE DID TANK REMOVAL WCHD NOTIFIED FAXED TO TODD THEY CONVERTED TO NATURAL GAS"

All Materials:
Site ID: 66799
Operable Unit ID: 985354
Operable Unit: 01
Material ID: 397066
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 9401229 / 1994-05-05
Facility ID: 9401229
Facility Type: ER
DER Facility ID: 174910
Site ID: 210995
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 6017
Spill Date: 1994-04-26
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1994-04-26
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1994-05-05
Spill Record Last Update: 1996-06-18
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/07/94: NO DEC INSPECTION. "
Remarks: "GAGE MALFUNCTION SPILL CONTAINED ON CONCRETE CASTLE TO DO CLEAN UP BEING CLEANED UP"

All Materials:
Site ID: 210995
Operable Unit ID: 998531
Operable Unit: 01

WHITE PLAINS HOSPITAL (Continued) **S100964742**

Material ID:	570100
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX416 **HOSPITAL (UNK NAME)** **NY LTANKS** **S103479243**
South **41 EAST COAST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.356 mi.
1881 ft. **Site 4 of 6 in cluster AX**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Spill Number/Closed Date:	9806058 / 1998-08-17
Facility ID:	9806058
Site ID:	191235
Spill Date:	1998-08-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B2
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-08-14
CID:	199
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-14
Spill Record Last Update:	1998-10-02
Spiller Name:	Not reported
Spiller Company:	MYSTIC BULK CARRIERS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	159508
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 8/17/98 SEE SPILL 9806078. SAME SPILL AND SPILLER. NFA"
Remarks:	"TANK OVERFILL BY CARRIER - CALLER IS ENROUTE AT THIS TIME WITH VACUMN TRUCK FOR CLEAN-UP -- SOME MATERAL ALSO GOT INTO STORM SEWERS"

All Materials:

Site ID:	191235
Operable Unit ID:	1067237
Operable Unit:	01

HOSPITAL (UNK NAME) (Continued) **S103479243**

Material ID:	317230
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX417 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S107417344**
South **MAPLE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.356 mi.
1881 ft. **Site 5 of 6 in cluster AX**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Spill Number/Closed Date:	9304740 / 1994-01-06
Facility ID:	9304740
Site ID:	290020
Spill Date:	1993-07-15
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-01-06
SWIS:	6017
Investigator:	MALONE
Referred To:	Not reported
Reported to Dept:	1993-07-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-27
Spill Record Last Update:	1994-01-06
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81239
DEC Memo:	""
Remarks:	"SOIL DISCOVERED IN TANK PULL WILL SYOCKPILE SOIL"

All Materials:

Site ID:	290020
Operable Unit ID:	983028
Operable Unit:	01
Material ID:	398220
Material Code:	0001A

WHITE PLAINS HOSPITAL (Continued) **S107417344**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BA418 **BUSINESS** **NY LTANKS** **S106125358**
NE **7 LAKE STREET** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.363 mi.
1914 ft. **Site 1 of 2 in cluster BA**

Relative:
Higher

Actual:
249 ft.

LTANKS:

Spill Number/Closed Date:	1401610 / 2015-07-17
Facility ID:	1401610
Site ID:	494900
Spill Date:	2014-05-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2014-05-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-05-14
Spill Record Last Update:	2015-07-17
Spiller Name:	LISA DEROSA
Spiller Company:	PROPERTY OWNER
Spiller Address:	7 LAKE ST
Spiller County:	999
Spiller Contact:	LISA DEROSA
Spiller Phone:	9146821800
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	449814
DEC Memo:	"This is a WC PBS site, no one available for update. WCDOH notified...mm 7-17-15, This was a ttf due to piping or manway gasket issues. Piping excavated without any visible contamination. tank passed isolation test and was closed in place. Soil samples below CP51. Wayne- RDB"
Remarks:	"unknown if any product was lost"

All Materials:

Site ID:	494900
Operable Unit ID:	1244408
Operable Unit:	01

BUSINESS (Continued) **S106125358**

Material ID:	2245225
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0604972 / 2006-11-17
Facility ID:	0604972
Site ID:	368064
Spill Date:	2006-08-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-08-01
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-08-01
Spill Record Last Update:	2006-11-17
Spiller Name:	LISA DEROSA
Spiller Company:	BUSINESS
Spiller Address:	7 LAKE STREET
Spiller County:	001
Spiller Contact:	LISA DEROSA
Spiller Phone:	(914) 682-1800
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	82292
DEC Memo:	"November 17, 2006: TANK PASSED A RETEST AFTER PIPING WAS REPAIRED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-492078 -PBS No. not found in UIS, may be invalid. DRY LEAK"
	Not reported

All TTF:

Facility ID:	0604972
Spill Number:	0604972
Spill Tank Test:	1550165
Site ID:	368064
Tank Number:	1
Tank Size:	8000
Material:	0001
EPA UST:	Not reported
UST:	Not reported

BUSINESS (Continued) **S106125358**

Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	368064
Operable Unit ID:	1125954
Operable Unit:	01
Material ID:	2115478
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0706405 / 2008-07-31
Facility ID:	0706405
Site ID:	386923
Spill Date:	2007-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2007-09-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-07
Spill Record Last Update:	2008-08-01
Spiller Name:	LISA DEROSA
Spiller Company:	COMMERCIAL
Spiller Address:	7 LAKE STREET
Spiller County:	001
Spiller Contact:	LISA DEROSA
Spiller Phone:	(914) 682-1800
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	82292
DEC Memo:	"07/31/08 Danielle Jackson - WCHD reported 7 lake st, white plains, ny - bad petrometer , repaired and retested, passed, NFA. TG "

BUSINESS (Continued) **S106125358**

Remarks: "DRY LEAK- PIN HOLE"

All TTF:
Facility ID: 0706405
Spill Number: 0706405
Spill Tank Test: 1764097
Site ID: 386923
Tank Number: 1
Tank Size: 8000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 386923
Operable Unit ID: 1144147
Operable Unit: 01
Material ID: 2134436
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0701292 / 2007-09-28
Facility ID: 0701292
Site ID: 380826
Spill Date: 2007-05-01
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2007-05-01
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2007-05-02

BUSINESS (Continued) **S106125358**

Spill Record Last Update:	2007-09-28
Spiller Name:	ED ALLEN
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ED ALLEN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	82292
DEC Memo:	"09/25/07 Northeast Environmental reported that they were hired and completed the cleanup. NFA TG"
Remarks:	"THERE WAS NO ROOM IN THE OIL TANK AND CAUSED A SPLASH OUT AND IN PROCESS OF CLEANING UP"

All Materials:

Site ID:	380826
Operable Unit ID:	1138299
Operable Unit:	01
Material ID:	2128284
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0311640 / 2004-03-23
Facility ID:	0311640
Facility Type:	ER
DER Facility ID:	82292
Site ID:	91506
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B4
SWIS:	6017
Spill Date:	2004-01-15
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-01-15
CID:	444
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-15
Spill Record Last Update:	2004-03-23
Spiller Name:	RAY GORHAM

BUSINESS (Continued) **S106125358**

Spiller Company:	TARRICONE OIL
Spiller Address:	59 MAIN STREET
Spiller Company:	001
Contact Name:	DEROSA BUILDERS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/23/04 NORTHEAST COMPLETED CLEAN UP."
Remarks:	"WHILE DELIVERING OIL THE DROP PIPE CAME LOOSE AND SPILLED. ALL CLEANED UP."

All Materials:

Site ID:	91506
Operable Unit ID:	879249
Operable Unit:	01
Material ID:	496892
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

AZ419 **WHITE PLAINS YMCA** **NY LTANKS** **S117395185**
SSE **250 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.366 mi.
1930 ft. **Site 2 of 3 in cluster AZ**

Relative:
Higher

Actual:
235 ft.

LTANKS:

Spill Number/Closed Date:	1410006 / 2015-12-08
Facility ID:	1410006
Site ID:	503665
Spill Date:	2015-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2015-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-01-12
Spill Record Last Update:	2016-01-14
Spiller Name:	THOMAS HAY
Spiller Company:	WHITE PLAINS YMCA
Spiller Address:	250 MAMARONECK RD
Spiller County:	999
Spiller Contact:	THOMAS HAY

WHITE PLAINS YMCA (Continued) **S117395185**

Spiller Phone:	(914) 949-8030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323652
DEC Memo:	"1-12-15 Spoke with Chris, WCDOH. See below. They will be handling. jm Joe, This is a PBS site 3-074071 TTF 12K (AST with 10% or more below grade) Wayne- please follow up on the TTF. Chris Christopher J. Lalak MS Radiological and Chemical Analyst Westchester County Department of Health 145 Huguenot Street - 7th Floor New Rochelle, NY 10801 CJL1@westchestergov.com (914) 224-7649 12-8-15 tank removed and spill under 15-05596; Close this spill before TCR review RDB"
Remarks:	"unknown retest."

All Materials:

Site ID:	503665
Operable Unit ID:	1253015
Operable Unit:	01
Material ID:	2255190
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AX420 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S101658669**
SSW **EAST NEW YORK POST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.370 mi.
1954 ft. **Site 6 of 6 in cluster AX**

Relative:
Lower

Actual:
209 ft.

LTANKS:

Spill Number/Closed Date:	9506062 / 2005-01-02
Facility ID:	9506062
Site ID:	240948
Spill Date:	1995-08-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-08-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-01-02
Spiller Name:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S101658669**

Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	198131
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 1/5/05--this was not a confirmed spill (was tank test failure in 2000 gal diesel tank for emergency generator); plan was to remove and replace tank-- would be handled as pbs matter whether removed or not--close "
Remarks:	"BELIEVE TANK WILL BE PULLED & REPLACED TANK WAS PREVIOUSLY FAILED BY SOMEONE ELSE TANK ONLY TEST"

All TTF:

Facility ID:	9506062
Spill Number:	9506062
Spill Tank Test:	1544090
Site ID:	240948
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	240948
Operable Unit ID:	1016961
Operable Unit:	01
Material ID:	364045
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BB421 **APT. BUILDING** **NY LTANKS** **S100494668**
NNE **50 NORTH BROADWAY** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.372 mi.
1964 ft. **Site 1 of 2 in cluster BB**

Relative:
Higher

Actual:
265 ft.

LTANKS:

Spill Number/Closed Date:	9212081 / 1994-06-29
Facility ID:	9212081
Site ID:	219739
Spill Date:	1993-01-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1994-06-29
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-01-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-01-25
Spill Record Last Update:	1994-06-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181732
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/28/94: TANK REMOVED BY TANK TECH. CLOSURE REPORT SUBMITTED. "
Remarks:	"DURING ROUTINE MAINTENANCE AND TANK CLEANING BY A.L. EASTMAN & CO. TWO SMALL HOLES DISCOVERED TEMPORARY TANK SET UP LEAKING TANK EMPTIED REQUEST CALL BACK MONDAY"

All Materials:

Site ID:	219739
Operable Unit ID:	978925
Operable Unit:	01
Material ID:	557072
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

APT. BUILDING (Continued) **S100494668**

SPILLS:

Spill Number/Closed Date:	8907277 / 1989-10-24
Facility ID:	8907277
Facility Type:	ER
DER Facility ID:	181732
Site ID:	308058
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1989-10-24
Investigator:	DUNN
Referred To:	Not reported
Reported to Dept:	1989-10-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1989-10-24
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	ORIGINAL OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was P. DUNN "
Remarks:	"APPLIED SPEEDY DRY. SPILL IS CONTAINED. A.L. EASTMONT WAS CONTRACTOR THAT CLEANED UP."

All Materials:

Site ID:	308058
Operable Unit ID:	934922
Operable Unit:	01
Material ID:	444070
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC422 **PRIVATE ENTERPRISE** **NY LTANKS** **U000379968**
NW **20 FERRIS AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.372 mi.
1966 ft. **Site 1 of 2 in cluster BC**

Relative:
Lower

Actual:
201 ft.

LTANKS:

Spill Number/Closed Date:	0402326 / 2004-06-02
Facility ID:	0402326
Site ID:	166779
Spill Date:	2004-06-02
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2004-06-02
CID:	406
Water Affected:	Not reported
Spill Notifier:	Police Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-02
Spill Record Last Update:	2004-06-08
Spiller Name:	UNKNOWN NAME
Spiller Company:	VALLEY OIL CO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	UNKNOWN NAME
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140526
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"Had an overfill while filling and underground tank. Caller could give no more information. Spill is contained and no clean up at this time."

All Materials:

Site ID:	166779
Operable Unit ID:	884005
Operable Unit:	01
Material ID:	489950
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8800487 / 1989-01-11

PRIVATE ENTERPRISE (Continued) **U000379968**

Facility ID:	8800487
Site ID:	166780
Spill Date:	1988-04-14
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	1989-01-11
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-04-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-05-04
Spill Record Last Update:	1989-02-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140526
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K TANK LEAK @ GAUGE WILL REPAIR DEC TO CHECK BACK. PBS TO FOLLOW. NO RESULTS"

All TTF:

Facility ID:	8800487
Spill Number:	8800487
Spill Tank Test:	1533659
Site ID:	166780
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	166780
Operable Unit ID:	916111

PRIVATE ENTERPRISE (Continued) **U000379968**

Operable Unit:	01
Material ID:	459675
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8800670 / 1989-01-11
Facility ID:	8800670
Site ID:	166781
Spill Date:	1988-04-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	1989-01-11
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-04-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-04-28
Spill Record Last Update:	1989-02-07
Spiller Name:	Not reported
Spiller Company:	CITY OF WHITE PLAINS
Spiller Address:	TOM MALONEY
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140526
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 11/29/95: This is additional information about material spilled from the translation of the old spill file: UNLEADED."
Remarks:	"2 K SYSTEM FAILED HORNER EASY CHECK AT -.1287GPH. SAME AS 88-00487 NON RESULTS"

All TTF:

Facility ID:	8800670
Spill Number:	8800670
Spill Tank Test:	1533711
Site ID:	166781
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported

PRIVATE ENTERPRISE (Continued) **U000379968**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	166781
Operable Unit ID:	917669
Operable Unit:	01
Material ID:	459844
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9408242 / 1997-12-05
Facility ID:	9408242
Facility Type:	ER
DER Facility ID:	140526
Site ID:	241713
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C3
SWIS:	6017
Spill Date:	1994-09-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-09-21
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-09-28
Spill Record Last Update:	1997-12-05
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported

PRIVATE ENTERPRISE (Continued) **U000379968**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 09/27/95: This is additional information about material spilled from the translation of the old spill file: PAINT/LEAD "

Remarks: "CLEANING A PAINT MACHINE PAINT WENT INTO STORM DRAIN W.C.H.D. INSPECTED SITE 100 GAL OF WATERBASE PAINT NOT LEAD CITY OF WHITE PLAINS SPILLER ORDERED TO CLEAN UP"

All Materials:

Site ID:	241713
Operable Unit ID:	1005838
Operable Unit:	01
Material ID:	377684
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BD423 **PDUZZI - TTF** **NY LTANKS** **S104191606**
North **188 CHURCH ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.376 mi.
1985 ft. **Site 1 of 2 in cluster BD**

Relative: **Higher**
Actual: **262 ft.**

LTANKS:

Spill Number/Closed Date:	9905239 / 2009-12-16
Facility ID:	9905239
Site ID:	108306
Spill Date:	1999-07-31
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	1999-07-31
CID:	196
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-31
Spill Record Last Update:	2016-07-08
Spiller Name:	EDWARD PDUZZI
Spiller Company:	EDWARD PDUZZI
Spiller Address:	188CHURCH ST
Spiller County:	001
Spiller Contact:	JOHN BUETI
Spiller Phone:	(914) 697-7654
Spiller Extention:	Not reported

PDUZZI - TTF (Continued) **S104191606**

DEC Region: 3
DER Facility ID: 276356
DEC Memo: "06/18/05 SPILL FOUND ON DATABASE TODAY. TARRYTOWN SUB-OFFICE NEVER RECEIVED THIS SPILL REPORT FROM NEW PALTZ. jod 12/16/09 NFA JO'M"
Remarks: "TANK TO BE UNCOVERED AND RETESTED."

All TTF:
Facility ID: 9905239
Spill Number: 9905239
Spill Tank Test: 1547440
Site ID: 108306
Tank Number: 1
Tank Size: 550
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: 3.00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 108306
Operable Unit ID: 1079671
Operable Unit: 01
Material ID: 301544
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

BC424 **FIRE STATION 2** **NY LTANKS** **S107410250**
NW **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.378 mi.
1998 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
198 ft.

LTANKS:
Spill Number/Closed Date: 8801791 / 1989-01-24
Facility ID: 8801791
Site ID: 297873
Spill Date: 1988-05-26
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: Not reported
Cleanup Ceased: 1989-01-12
SWIS: 6000
Investigator: jeokesso
Referred To: Not reported

FIRE STATION 2 (Continued) **S107410250**

Reported to Dept:	1988-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-12
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-02
Spill Record Last Update:	1989-02-07
Spiller Name:	Not reported
Spiller Company:	FIRE STATION 2
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	284756
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"TANK ONLY TEST .25851 GPH. PBS TO FOLLOW. NO RESULTS"

All TTF:

Facility ID:	8801791
Spill Number:	8801791
Spill Tank Test:	1533986
Site ID:	297873
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	297873
Operable Unit ID:	917247
Operable Unit:	01
Material ID:	460915
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AZ425 **YMCA** **NY LTANKS** **S100166488**
SSE **260 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.380 mi.
2008 ft. **Site 3 of 3 in cluster AZ**

Relative:
Higher

Actual:
236 ft.

LTANKS:

Spill Number/Closed Date:	9013259 / 2002-03-23
Facility ID:	9013259
Site ID:	263885
Spill Date:	1991-03-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1991-03-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-01
Spill Record Last Update:	2002-04-29
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	215095
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 05/01/91: MAY 1, FRED TOOT DIRECTOR STILL ATTEMPTING TO GET BIDS TO EXCAVATE THE LINES TO RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. 03/23/2002 LETTER SENT TO TEAM ENV. CONSULTANTS BY T. GHIOSAY; BASED ON 3/13/02 CORRESPONDENCE, NO FURTHER ACTION REQUIRED AT THIS TIME. SPILL NUMBER CLOSED."
Remarks:	"E I R TODAY PETRO-TITE -.126"

All TTF:

Facility ID:	9013259
Spill Number:	9013259
Spill Tank Test:	1538385
Site ID:	263885
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

YMCA (Continued) **S100166488**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	263885
Operable Unit ID:	953354
Operable Unit:	01
Material ID:	426138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

426
ENE
1/4-1/2
0.383 mi.
2024 ft.

RESIDENCE **NY LTANKS** **S102960214**
325 MAIN ST **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
211 ft.

LTANKS:

Spill Number/Closed Date:	9710553 / 1998-01-09
Facility ID:	9710553
Site ID:	230651
Spill Date:	1997-12-15
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-15
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-15
Spill Record Last Update:	1998-01-29
Spiller Name:	IZET
Spiller Company:	325 MAIN ST OWNERS CORP
Spiller Address:	12 EAST END AV
Spiller County:	001
Spiller Contact:	JIM CAREY
Spiller Phone:	(718) 579-3414
Spiller Extention:	Not reported

RESIDENCE (Continued) **S102960214**

DEC Region: 3
DER Facility ID: 190083
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/16/97 7,500 GAL TANK IN APT. BUILDING BASEMENT TANK ROOM; #6 FUEL OIL, 100 GAL SPILLED; CONFINED TO TANK ROOM; CONTRACTOR IN PROCESS OF CLEANING ROOM; 01/09/98 TANK HAS BEEN CLEANED; ODORS IN TANK ROOM ARE MINIMAL; NO ODORS OUTSIDE TANK ROOM; NFA; "
Remarks: "CALLER STATES TANK RUPTURED - SPILL IS RECOVERABLE - CLEAN UP CREW ON WAY"

All Materials:
Site ID: 230651
Operable Unit ID: 1056913
Operable Unit: 01
Material ID: 328850
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: .00
Oxygenate: Not reported

BE427 **SPILL NUMBER 0103645** **NY LTANKS** **S105055231**
SSW **12 EAST POST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.385 mi.
2035 ft. **Site 1 of 6 in cluster BE**

Relative: LTANKS:
Lower
Spill Number/Closed Date: 0103645 / 2003-12-09
Actual: Facility ID: 0103645
208 ft. Site ID: 129951
Spill Date: 2001-07-05
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2001-07-05
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-05
Spill Record Last Update: 2003-12-09
Spiller Name: Not reported
Spiller Company: PHILIP WERBEL
Spiller Address: 12 EAST POST RD
Spiller County: 001

SPILL NUMBER 0103645 (Continued) **S105055231**

Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	111992
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 12/09/03 CLOSED BY STEFAN GOREAU OF THE WESTCHESTER COUNTY HEALTH DEPARTMENT."
Remarks:	"u/g tank leaking. pulled. cleanup starting soon."

All Materials:

Site ID:	129951
Operable Unit ID:	840256
Operable Unit:	01
Material ID:	535715
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF428 **35 PARK AVENUE** **NY LTANKS** **S105999311**
NNW **35 PARK AVENUE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.388 mi.
2049 ft. **Site 1 of 2 in cluster BF**

Relative: **Higher**
Actual: **296 ft.**

LTANKS:

Spill Number/Closed Date:	0303364 / 2010-06-29
Facility ID:	0303364
Site ID:	272501
Spill Date:	2003-06-30
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-06-30
CID:	204
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-30
Spill Record Last Update:	2010-06-29
Spiller Name:	DENNIS CHIULLI
Spiller Company:	35 PARK AVENUE
Spiller Address:	35 PARK AVENUE
Spiller County:	001

35 PARK AVENUE (Continued) **S105999311**

Spiller Contact:	MARTY MORGAN
Spiller Phone:	(914) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	221792
DEC Memo:	"6/29/10: File review. Report of a residential TTF. No indication of contamination noted on initial report. No updates or callback information from the dispatch desk. No further information received. jod"
Remarks:	"TANK TEST FAILURE "

All TTF:

Facility ID:	0303364
Spill Number:	0303364
Spill Tank Test:	1528485
Site ID:	272501
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	272501
Operable Unit ID:	871411
Operable Unit:	01
Material ID:	504237
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE429 **GETTY SERVICE STATION** **NY LTANKS** **S104514642**
SSW **11 EAST POST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.391 mi.
2064 ft. **Site 2 of 6 in cluster BE**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Spill Number/Closed Date:	0407127 / 2004-09-27
Facility ID:	0407127
Site ID:	261414
Spill Date:	2004-09-27
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility

GETTY SERVICE STATION (Continued) **S104514642**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	MBMASTRO
Referred To:	WCHD
Reported to Dept:	2004-09-27
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2004-09-27
Spill Record Last Update:	2004-10-18
Spiller Name:	SCOTT HANLEY
Spiller Company:	GETTY GAS #58108
Spiller Address:	11 EAST POST ROAD
Spiller County:	001
Spiller Contact:	SCOTT HANLEY
Spiller Phone:	(516) 542-5273
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	266859
DEC Memo:	""
Remarks:	"Spilled into containment. Spill is being cleanedup, no release into the environment."

All Materials:

Site ID:	261414
Operable Unit ID:	890394
Operable Unit:	01
Material ID:	484968
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9710611 / 1998-05-08
Facility ID:	9710611
Site ID:	261415
Spill Date:	1997-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-17
CID:	205
Water Affected:	Not reported

GETTY SERVICE STATION (Continued) **S104514642**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-12-17
Spill Record Last Update:	1998-06-08
Spiller Name:	Not reported
Spiller Company:	GETTY SERVICE STATION
Spiller Address:	11 EAST POST ROAD
Spiller County:	001
Spiller Contact:	TYREE INC
Spiller Phone:	(203) 740-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	213498
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/08/98 FUTHER INVESTIGATION AND REMEDIATION WILL BE CONDUCTED UNDER SPILL # 97-10575"
Remarks:	"TWO TANKS BOTH 4000 GALLON CAPACITY MANIFOLDED TOGETHER. FAILED TEST."

All TTF:

Facility ID:	9710611
Spill Number:	9710611
Spill Tank Test:	1545523
Site ID:	261415
Tank Number:	003 & 004
Tank Size:	4000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

BE430 **SPILL NUMBER 8600048** **NY LTANKS** **S104619203**
SSW **11 EAST POST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.391 mi.
2064 ft. **Site 3 of 6 in cluster BE**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Spill Number/Closed Date:	8600048 / 1987-02-24
Facility ID:	8600048
Site ID:	200602
Spill Date:	1986-04-02
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1987-02-24

SPILL NUMBER 8600048 (Continued) **S104619203**

SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1986-04-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1987-02-24
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-04-25
Spill Record Last Update:	1997-06-06
Spiller Name:	Not reported
Spiller Company:	POWERTEST GETTY GAS
Spiller Address:	11 EAST POST RD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	266859
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 2/24/87 WCHD INVESTIGATED NFA. "
Remarks:	"PRODUCT OBSERVED IN OBS WELLS-LOSING PRODUCT FROM AUG,85"

All Materials:

Site ID:	200602
Operable Unit ID:	896383
Operable Unit:	01
Material ID:	480238
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

431
East
1/4-1/2
0.392 mi.
2068 ft.

WESTCHESTER SHOPPING CENT
WEST AVE & PAWLING ST
WHITE PLAINS, NY

NY LTANKS **S100782169**
N/A

Relative:
Lower

Actual:
165 ft.

LTANKS:

Spill Number/Closed Date:	9310531 / 1995-01-20
Facility ID:	9310531
Site ID:	213450
Spill Date:	1993-09-09
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1995-01-20
SWIS:	6017

WESTCHESTER SHOPPING CENT (Continued) **S100782169**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-12-28
Spill Record Last Update:	1995-01-20
Spiller Name:	Not reported
Spiller Company:	FASHION MALL PARTNERS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	176839
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"EXCAVATING REMOVING SOIL TANKS ARE REMOVED"

All Materials:

Site ID:	213450
Operable Unit ID:	992245
Operable Unit:	01
Material ID:	393136
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BB432 **SPILL NUMBER 8807217** **NY LTANKS** **S107417139**
NNE **52 NORTH BROADWAY** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.393 mi.
2076 ft. **Site 2 of 2 in cluster BB**

Relative:
Higher

Actual:
275 ft.

LTANKS:

Spill Number/Closed Date:	0509076 / 2006-03-21
Facility ID:	0509076
Site ID:	354798
Spill Date:	2005-10-28
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD

SPILL NUMBER 8807217 (Continued) **S107417139**

Referred To:	WCDOH
Reported to Dept:	2005-10-28
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-28
Spill Record Last Update:	2006-03-21
Spiller Name:	JOHN
Spiller Company:	GOOD COUNCIL CONVENT
Spiller Address:	52 NORTH BROADWAY
Spiller County:	001
Spiller Contact:	JOHN
Spiller Phone:	(914) 557-0334
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	304812
DEC Memo:	"3-14-06 Letter reported submitted by Pro Test. Lines to the tank were excavated, removed and replaced along with 93.87 tons of petroleum impacted soil. Post ex samples were satifactory. NFA. TG"
Remarks:	"NO REMARKS."

All TTF:

Facility ID:	0509076
Spill Number:	0509076
Spill Tank Test:	1549468
Site ID:	354798
Tank Number:	1
Tank Size:	15000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	354798
Operable Unit ID:	1112188
Operable Unit:	01
Material ID:	2102231
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 8807217 (Continued) **S107417139**

Oxygenate:	Not reported
Spill Number/Closed Date:	8807217 / 1988-12-02
Facility ID:	8807217
Site ID:	181366
Spill Date:	1988-12-01
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1988-12-01
SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-12-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1988-12-01
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	304812
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was D. TRAVER "
Remarks:	"SPILLAGE DUE TO PLUGGED VENT. USED SORBENT IN CLEAN-UP. ROBISON OIL - NO RESOURCES AFFECTED. CLEANUP IS COMPLETE. NFA"

All Materials:

Site ID:	181366
Operable Unit ID:	923880
Operable Unit:	01
Material ID:	455561
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE433 **GETTY S/S** **NY LTANKS** **S100494499**
SSW **11 EAST POND ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.397 mi.
2095 ft. **Site 4 of 6 in cluster BE**

Relative:
Higher

Actual:
211 ft.

LTANKS:

Spill Number/Closed Date:	9210753 / 1992-12-31
Facility ID:	9210753
Site ID:	319803
Spill Date:	1992-12-16
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1992-12-31
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	257661
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"UNDERGROUND TANK PUMPED PRODUCT DOWN WILL EXCAVATE AND REPAIR PETRO-TITE GROSS"

All TTF:

Facility ID:	9210753
Spill Number:	9210753
Spill Tank Test:	1540964
Site ID:	319803
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

GETTY S/S (Continued) **S100494499**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 319803
Operable Unit ID: 977395
Operable Unit: 01
Material ID: 404196
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

434
SW
1/4-1/2
0.399 mi.
2109 ft.

APT. HOUSE
82 BANK STREET
WHITE PLAINS, NY

NY LTANKS **S102155221**
NY Spills **N/A**

Relative:
Higher

Actual:
220 ft.

LTANKS:
Spill Number/Closed Date: 0312286 / 2005-03-27
Facility ID: 0312286
Site ID: 301757
Spill Date: 2004-02-04
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 2004-02-04
CID: 405
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-02-04
Spill Record Last Update: 2005-03-27
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: KATHY
Spiller Phone: (914) 946-1320
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 197977
DEC Memo: "03/27/05 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE

APT. HOUSE (Continued) **S102155221**

JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "Re-test or remove"

All TTF:
Facility ID: 0312286
Spill Number: 0312286
Spill Tank Test: 1528959
Site ID: 301757
Tank Number: 1
Tank Size: 4000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

SPILLS:
Spill Number/Closed Date: 9410155 / 1994-11-01
Facility ID: 9410155
Facility Type: ER
DER Facility ID: 197977
Site ID: 240746
DEC Region: 3
Spill Cause: Human Error
Spill Class: D4
SWIS: 6017
Spill Date: 1994-10-28
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1994-10-31
CID: Not reported
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Responsible Party
Cleanup Ceased: 1994-11-01
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2003-12-02
Spiller Name: Not reported
Spiller Company: TARRICONE FUELS
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "

APT. HOUSE (Continued) **S102155221**

Remarks: "MISREAD TANK CLEANED UP BY FUEL CO SIDEWALK AFFECTED"

All Materials:

Site ID:	240746
Operable Unit ID:	1007900
Operable Unit:	01
Material ID:	376026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

435 South 1/4-1/2 0.399 mi. 2109 ft. **RESIDENCE** **NY LTANKS** **S106868939**
25 LONGVIEW AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 241 ft.

LTANKS:

Spill Number/Closed Date:	0413208 / 2005-05-08
Facility ID:	0413208
Site ID:	339072
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-08
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	LIUS LIPKIN
Spiller Phone:	(914) 681-0645
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285687
DEC Memo:	"INVALID TANK TEST METHOD. jod 05/08/05 ADVANCED ENVIRONMENTAL DISPOSED OF LUST AND 3.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS

RESIDENCE (Continued) **S106868939**

TIME. jod"
Remarks: "failure on a tightness test no oil noted in soil mesa 2d 1000 gallon"
Not reported

All Materials:
Site ID: 339072
Operable Unit ID: 1100989
Operable Unit: 01
Material ID: 581136
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

436 **PRIVATE HOME** **NY LTANKS** **S107789514**
North **11 PARK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.401 mi.
2115 ft.

Relative: **Higher**
Actual: **276 ft.**

LTANKS:
Spill Number/Closed Date: 0602237 / 2006-10-22
Facility ID: 0602237
Site ID: 364664
Spill Date: 2006-05-30
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2006-05-30
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-05-30
Spill Record Last Update: 2006-10-22
Spiller Name: LILY CHIN- REALTOR
Spiller Company: PRIVATE HOME
Spiller Address: 11 PARK AVE
Spiller County: 001
Spiller Contact: LILY CHIN- REALTOR
Spiller Phone: (914) 997-0097
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 314863
DEC Memo: "06/09/06: REALTOR IS CONTACTING ENVIROSTAR - TANK HAS 815 GAL IN IT,

PRIVATE HOME (Continued) **S107789514**

COULDN'T HOLD PRESSURE. October 22, 2006: NES DISPOSED OF LUST AND 7.66 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"

Remarks: "OLD TANK- ULIDGE LEAK:"

All TTF:

Facility ID:	0602237
Spill Number:	0602237
Spill Tank Test:	1550017
Site ID:	364664
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	364664
Operable Unit ID:	1122686
Operable Unit:	01
Material ID:	2112163
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA437 **APT BUILDING** **NY LTANKS** **S110243958**
NE **16 LAKE STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.401 mi.
2119 ft. **Site 2 of 2 in cluster BA**

Relative: **Higher**
Actual: **240 ft.**

LTANKS:

Spill Number/Closed Date:	0912833 / 2010-06-23
Facility ID:	0912833
Site ID:	425742
Spill Date:	2010-03-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-03-10

APT BUILDING (Continued) **S110243958**

CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-03-10
Spill Record Last Update:	2010-06-23
Spiller Name:	Not reported
Spiller Company:	FAILED TANK TEST
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MEG @ WHITE MGMT
Spiller Phone:	(914) 874-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	374630
DEC Memo:	"Spoke to Kathy at US tank. Hole in vent pipe below pavement. US Tank advised owner to excavate tank top, isolate and retest. WCHD to be notified also by US Tank. WCHD regulated site. DT 3/10/10 6/23/10 WCDOH reports that ttf 3/10/10.received report from petroleum tank claners indicating replacement of fill port and passing retest JO'M "
Remarks:	""

All Materials:

Site ID:	425742
Operable Unit ID:	1181454
Operable Unit:	01
Material ID:	2175539
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	425742
Operable Unit ID:	1181454
Operable Unit:	01
Material ID:	2175540
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

438
ENE
1/4-1/2
0.404 mi.
2131 ft.

FRANKLIN APTS
25 FRANKLIN AVE
WHITE PLAINS, NY

NY LTANKS
NY Spills

S100136758
N/A

Relative:
Lower

Actual:
166 ft.

LTANKS:

Spill Number/Closed Date:	8801525 / 1988-08-19
Facility ID:	8801525
Site ID:	154120
Spill Date:	1988-05-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-08-19
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-08-19
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-31
Spill Record Last Update:	1988-09-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	130707
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 09/07/88: TANK RELINED.RETEST PASSED. "
Remarks:	"TANK FAILED TEST ATUNREADABLE LEVEL 7500GAL"

All TTF:

Facility ID:	8801525
Spill Number:	8801525
Spill Tank Test:	1533929
Site ID:	154120
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

FRANKLIN APTS (Continued) **S100136758**

All Materials:

Site ID:	154120
Operable Unit ID:	918678
Operable Unit:	01
Material ID:	460668
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0005174 / 2000-10-03
Facility ID:	0005174
Facility Type:	ER
DER Facility ID:	130707
Site ID:	154119
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2000-07-30
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-07-31
CID:	389
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-31
Spill Record Last Update:	2000-11-21
Spiller Name:	Not reported
Spiller Company:	APARTMENT HOUSE
Spiller Address:	25 RANKLIN AVE
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	""
Remarks:	"caller reporting a spill of material from a broken pipe to oil burner material is inthe process of being cleaned up callback ncessary"

All Materials:

Site ID:	154119
Operable Unit ID:	826230
Operable Unit:	01
Material ID:	549906
Material Code:	0002A

FRANKLIN APTS (Continued) **S100136758**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	150.00
Units:	G
Recovered:	150.00
Oxygenate:	Not reported

BG439 **WHITE PLAINS HONDA** **NY LTANKS** **S102675103**
WSW **31 WESTMPORELAND AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.406 mi.
2146 ft. **Site 1 of 5 in cluster BG**

Relative:
Lower

Actual:
209 ft.

LTANKS:

Spill Number/Closed Date:	9514655 / 1996-02-15
Facility ID:	9514655
Site ID:	224484
Spill Date:	1996-02-15
Spill Cause:	Tank Overfill
Spill Source:	Unknown
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	1996-02-23
Spiller Name:	RICK BOLOGNA
Spiller Company:	WESTMORE FUELS
Spiller Address:	86 NO WATER STREET
Spiller County:	001
Spiller Contact:	MR J CAREAGA
Spiller Phone:	(914) 948-3305
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	185537
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"tank over fill caused spill at business-spill has been cleaned up from pavement"

All Materials:

Site ID:	224484
Operable Unit ID:	1029198
Operable Unit:	01
Material ID:	354785
Material Code:	0001A

WHITE PLAINS HONDA (Continued) **S102675103**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	6.00
Oxygenate:	Not reported

BH440 **PRIVATE HOME** **NY LTANKS S106699823**
SE **18 DEKALB AVE** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.407 mi.
2150 ft. **Site 1 of 2 in cluster BH**

Relative:
Lower

Actual:
206 ft.

LTANKS:

Spill Number/Closed Date:	0406991 / 2004-10-04
Facility ID:	0406991
Site ID:	195806
Spill Date:	2004-09-23
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	c3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-09-23
CID:	64
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-23
Spill Record Last Update:	2005-01-05
Spiller Name:	ALAN BAKER
Spiller Company:	PRIVATE HOME
Spiller Address:	18 DEKALB AV
Spiller County:	001
Spiller Contact:	ALAN BAKER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	163125
DEC Memo:	" 10/04/04 CLEAN UP COMPLETED BY TRI-STATE, BUT THERE ARE INDOOR AIR ISSUES BEING HANDLED BY COUNTY HEALTH DEPT."
Remarks:	"Caller states that the oil tank was leaking. Apparently the leak is controlled at this time and he is enroute for clean up. During call, call was lost due to a bad cell phone connection. Caller can be reached on cell - 914-424-0973. Caller called back."

All Materials:

Site ID:	195806
Operable Unit ID:	889588
Operable Unit:	01

PRIVATE HOME (Continued) **S106699823**

Material ID: 484834
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0104393 / 2001-07-25
Facility ID: 0104393
Facility Type: ER
DER Facility ID: 163125
Site ID: 215770
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6017
Spill Date: 2001-07-25
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2001-07-25
CID: 201
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-07-25
Spill Record Last Update: 2003-10-21
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks: "2 QTS ON GRASS AND CONCREAT. CLEAN UP CREW ON THE WAY. CON ED #138458. NON PCB OIL."

All Materials:
Site ID: 215770
Operable Unit ID: 841030
Operable Unit: 01
Material ID: 532888
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00

PRIVATE HOME (Continued) **S106699823**

Units: G
Recovered: .00
Oxygenate: Not reported

BH441 **TORELLI** **NY LTANKS** **S106718922**
SE **21 DEKALB AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.410 mi.
2164 ft. **Site 2 of 2 in cluster BH**

Relative: **Higher**
Actual: **212 ft.**

LTANKS:
Spill Number/Closed Date: 0206319 / 2005-02-02
Facility ID: 0206319
Site ID: 253456
Spill Date: 2002-09-18
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2002-09-18
CID: 257
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-09-18
Spill Record Last Update: 2005-02-02
Spiller Name: MR TORELLI
Spiller Company: Not reported
Spiller Address: 21 DEKALB AVE
Spiller County: 001
Spiller Contact: MR TORELLI
Spiller Phone: (914) 761-2423
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 207634
DEC Memo: "02/02/05 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 43.36 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM HES. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks: "during removal caller found contaminted soil and holes in the tank "

All Materials:
Site ID: 253456
Operable Unit ID: 857806
Operable Unit: 01
Material ID: 516935
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

TORELLI (Continued) **S106718922**

Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BE442 **SPILL NUMBER 0013009** **NY LTANKS** **S104950648**
SSW **1 EAST POST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.415 mi.
2192 ft. **Site 5 of 6 in cluster BE**

Relative: **Lower**
Actual: **208 ft.**

LTANKS:
Spill Number/Closed Date: 0013009 / 2001-03-12
Facility ID: 0013009
Site ID: 156648
Spill Date: 2001-03-12
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: dxtraver
Referred To: Not reported
Reported to Dept: 2001-03-12
CID: 207
Water Affected: Not reported
Spill Notifier: Health Department
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-03-12
Spill Record Last Update: 2001-03-14
Spiller Name: Not reported
Spiller Company: FRANGO OIL CO
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: ELVIRA ALBANO
Spiller Phone: (914) 684-9073
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 132543
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 03/12/2001 WCDOH TO FOLLOW UP. NYSDEC SPILLS NO FURTHER ACTION."
Remarks: "cleanup in progress"

All Materials:
Site ID: 156648
Operable Unit ID: 834948
Operable Unit: 01
Material ID: 539736
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum

SPILL NUMBER 0013009 (Continued) **S104950648**

Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported

BD443 **SPILL NUMBER 0209590** **NY LTANKS** **S105997663**
North **25 PARK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.416 mi.
2194 ft. **Site 2 of 2 in cluster BD**

Relative: **Higher**
Actual: **282 ft.**

LTANKS:
Spill Number/Closed Date: 0209590 / 2002-12-18
Facility ID: 0209590
Site ID: 206038
Spill Date: 2002-12-18
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jghardy
Referred To: Not reported
Reported to Dept: 2002-12-18
CID: 257
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-12-18
Spill Record Last Update: 2003-05-12
Spiller Name: DR. INCH
Spiller Company: Not reported
Spiller Address: 25 PARK AVE
Spiller County: 001
Spiller Contact: DR. INCH
Spiller Phone: (914) 693-8193
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 171101
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY "
Remarks: "tried to fill a tank that was full"

All Materials:
Site ID: 206038
Operable Unit ID: 860847
Operable Unit: 01
Material ID: 513010
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 15.00

SPILL NUMBER 0209590 (Continued) **S105997663**

Units: G
Recovered: .00
Oxygenate: Not reported

444
SSE
1/4-1/2
0.418 mi.
2206 ft.

ROADWAY
285 MAMARONECK AVE
WHITE PLAINS, NY

NY LTANKS **S102240718**
NY Spills **N/A**

Relative:
Higher

Actual:
236 ft.

LTANKS:

Spill Number/Closed Date:	9712450 / Not Reported
Facility ID:	9712450
Site ID:	85909
Spill Date:	1998-02-07
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-02-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	1998-02-07
Spill Record Last Update:	2010-08-03
Spiller Name:	WILLIAM S OLESON
Spiller Company:	C STAR DINER
Spiller Address:	285 MAMARONECK ST
Spiller County:	001
Spiller Contact:	WILLIAM S OLESON
Spiller Phone:	(914) 948-4500
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	78861
DEC Memo:	"02/07/98 ROBISON OIL WILL ARRANGE TO E.I.R. 8/3/10 TTF JO'M "
Remarks:	"REQ DEC REP CONTACT OWNER OF DINER ON MONDAY"

All TTF:

Facility ID:	9712450
Spill Number:	9712450
Spill Tank Test:	1545605
Site ID:	85909
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported

ROADWAY (Continued) **S102240718**

Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	85909
Operable Unit ID:	1058741
Operable Unit:	01
Material ID:	327052
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	9511162 / 1995-12-05
Facility ID:	9511162
Facility Type:	ER
DER Facility ID:	139914
Site ID:	166024
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C5
SWIS:	6017
Spill Date:	1995-12-05
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-05
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-12-05
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-05
Spill Record Last Update:	1995-12-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"tanker truck was leaking as it drove down the road the majority of

ROADWAY (Continued) **S102240718**

the spill is in front of the above address leak is stopped clean up underway "

All Materials:

Site ID:	166024
Operable Unit ID:	1025458
Operable Unit:	01
Material ID:	358513
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG445 **MUNICIPAL GARAGE** **NY LTANKS** **S100140495**
WSW **111** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.419 mi.
2214 ft. **Site 2 of 5 in cluster BG**

Relative: **Lower**

Actual: **208 ft.**

LTANKS:

Spill Number/Closed Date:	8808829 / 1991-08-07
Facility ID:	8808829
Site ID:	129523
Spill Date:	1989-02-10
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-02-16
Spill Record Last Update:	2003-09-19
Spiller Name:	Not reported
Spiller Company:	JOHN HAINLINE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	111644
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "

MUNICIPAL GARAGE (Continued) **S100140495**

Remarks: "2K -.6545. IER. THE GARAGE IS PULLING THE TANKS AND THE GARAGE WILL TELL US WHEN. TANK PULLER WILL BE HAZCO. ROD KING 718-575-3219"

All TTF:

Facility ID:	8808829
Spill Number:	8808829
Spill Tank Test:	1535167
Site ID:	129523
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	129523
Operable Unit ID:	925216
Operable Unit:	01
Material ID:	453596
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE446 **BISCARDI CLEANERS** **NY LTANKS S110246037**
SSW **201 SO. LEXINGTON AVE.** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY 10601** **NY DRYCLEANERS**
0.421 mi.
2223 ft. **Site 6 of 6 in cluster BE**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Spill Number/Closed Date:	0100630 / 2006-05-01
Facility ID:	0100630
Site ID:	322267
Spill Date:	2001-04-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2001-04-17
CID:	382
Water Affected:	Not reported

BISCARDI CLEANERS (Continued) **S110246037**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-17
Spill Record Last Update:	2006-05-01
Spiller Name:	Not reported
Spiller Company:	BISSCARDI CLEANERS
Spiller Address:	201 SOUTH LEXINGTON AVE
Spiller County:	001
Spiller Contact:	BISSCARDI CLEANERS
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	259613
DEC Memo:	"04/17/2001 275 GALLON A/G. NORTHEAST ENVIRONMENTAL RESPONDING -QUANTITY LOST UNKNOWN AT THIS TIME. 150 GALLONS LOST."
Remarks:	"tank let go at location. unknown how much oil on floor of basement. "
	Not reported

All Materials:

Site ID:	322267
Operable Unit ID:	839472
Operable Unit:	01
Material ID:	536346
Material Code:	0032C
Material Name:	wood alcohol
Case No.:	00067561
Material FA:	Hazardous Material
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0013010 / 2001-03-12
Facility ID:	0013010
Facility Type:	ER
DER Facility ID:	259613
Site ID:	254787
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2001-03-12
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	2001-03-12
CID:	323
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True

BISCARDI CLEANERS (Continued) **S110246037**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-12
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	TJ NETHERCOTT
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	TERRY NETHERCOTT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 03/12/2001 WCDOH WAS ON SITE ACCORDING TO SPILLER. MINOR SPILL DUE TO LOOSE GAUGE FITTING. CLEANUP TO BE COMPLETED BY SPILLER. NO FURTHER ACTION."
Remarks:	"GUAGE ON TANK FAILED. SPILL CLEANED UP, GAUGE REPLACED."

All Materials:

Site ID:	254787
Operable Unit ID:	834546
Operable Unit:	01
Material ID:	539737
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

DRYCLEANERS:

Facility ID:	3-5517-00279
Phone Number:	914-684-9073
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	12APR30
Install Date:	92/12
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

447
NNW
1/4-1/2
0.423 mi.
2231 ft.

LAZZARO **NY LTANKS** **S104620069**
47 PARK AVE **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
330 ft.

LTANKS:

Spill Number/Closed Date:	9815351 / 2004-12-07
Facility ID:	9815351
Site ID:	238028
Spill Date:	1999-03-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C6

LAZZARO (Continued) **S104620069**

Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-03-26
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-03-26
Spill Record Last Update:	2004-12-07
Spiller Name:	BATRICE LAZZARO
Spiller Company:	Not reported
Spiller Address:	47 PARK AVE
Spiller County:	001
Spiller Contact:	BATRICE LAZZARO
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196045
DEC Memo:	"04/27/99 Letter sent to tank owner by John O'Dee requesting information on tank/spill status. 12/07/04 TANK TEST FAILURE OF UNREGULATED, RESIDENTIAL HEATING OIL TANK. NO FURTHER INFORMATION RECEIVED BY DEC. SPILL FILE ADMINISTRATIVELY CLOSED. jbo"
Remarks:	"GROSS FAILURE OF TANK TEST "

All TTF:

Facility ID:	9815351
Spill Number:	9815351
Spill Tank Test:	1546986
Site ID:	238028
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	238028
Operable Unit ID:	1076380
Operable Unit:	01
Material ID:	566379
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

LAZZARO (Continued) **S104620069**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG448 **CIVIC CENTER MOTORS** **NY LTANKS** **S105230061**
WSW **31 WESTMORELAND AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.423 mi.
2233 ft. **Site 3 of 5 in cluster BG**

Relative: **Lower**
Actual: **208 ft.**

LTANKS:

Spill Number/Closed Date:	0108090 / 2001-11-08
Facility ID:	0108090
Site ID:	110892
Spill Date:	2001-11-08
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	mbmastro
Referred To:	Not reported
Reported to Dept:	2001-11-08
CID:	207
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-11-08
Spill Record Last Update:	2001-11-27
Spiller Name:	CALLER
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	MIKE PRAILEAU
Spiller Phone:	(914) 847-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97050
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MASTRO 11/08/2001 CONFIRMED INFO - SPILL ON PAVEMENT, CONTAINED, NO WATERWAYS AFFECTED. NO FURTHER ACTION."
Remarks:	"cleanup in progress"

All Materials:

Site ID:	110892
Operable Unit ID:	846126
Operable Unit:	01
Material ID:	529346
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

CIVIC CENTER MOTORS (Continued) **S105230061**

Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0206674 / 2003-02-26
Facility ID: 0206674
Site ID: 110893
Spill Date: 2002-09-25
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-09-27
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-09-27
Spill Record Last Update: 2003-03-26
Spiller Name: DAVID DIDONA
Spiller Company: WHITE PLAINS HONDA
Spiller Address: 31 WESTMORELAND AVE
Spiller County: 001
Spiller Contact: DONNA CAIXERIO
Spiller Phone: (914) 946-4300
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 97050
DEC Memo: ""
Remarks: "VACUM TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER HAS BEEN ADVISED OF TEST RESULTS."

All TTF:
Facility ID: 0206674
Spill Number: 0206674
Spill Tank Test: 1527509
Site ID: 110893
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: F

CIVIC CENTER MOTORS (Continued) **S105230061**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 110893
Operable Unit ID: 858419
Operable Unit: 01
Material ID: 517277
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0010522 / 2001-07-10
Facility ID: 0010522
Site ID: 68432
Spill Date: 2000-12-19
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2000-12-19
CID: 281
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-12-19
Spill Record Last Update: 2002-03-15
Spiller Name: ED ALLAN
Spiller Company: ROBINSON OIL
Spiller Address: 500 EXECUTIVE BLVD
Spiller County: 001
Spiller Contact: ED ALAN
Spiller Phone: (914) 345-5700
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 97050
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 07/10/2001 NEE DISPOSED OF TANK AND 11 DRUMS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks: "TANK OVERFILL DURING DELILVERY AT ABOVE LOCATION. ALL MATERIAL REPORTED RECOVERED. NO CALL BACK REQUESTED."

All Materials:
Site ID: 68432

CIVIC CENTER MOTORS (Continued) **S105230061**

Operable Unit ID:	831663
Operable Unit:	01
Material ID:	571832
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0500300 / 2005-04-07
Facility ID:	0500300
Facility Type:	ER
DER Facility ID:	97050
Site ID:	343238
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-04-07
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2012-01-11
Spiller Name:	TODD ROBINSON
Spiller Company:	NOCO TRUCK
Spiller Address:	625 SAWKILL ROAD
Spiller Company:	001
Contact Name:	TODD ROBINSON
DEC Memo:	""
Remarks:	"IN PROCESS OF CLEANING UP: WHILE SUCKING UP WASTE OIL IT OVERFILLED HIS TANK: LEAKED ON TO ASPHALT:"

All Materials:

Site ID:	343238
Operable Unit ID:	1101923
Operable Unit:	01
Material ID:	582157
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum

CIVIC CENTER MOTORS (Continued) **S105230061**

Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9814172 / 1999-02-24
Facility ID:	9814172
Facility Type:	ER
DER Facility ID:	97050
Site ID:	174406
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-02-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-02-24
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-24
Spill Record Last Update:	1999-07-28
Spiller Name:	TODD ROBINSON
Spiller Company:	NOCO LUBRICANTS
Spiller Address:	625 SAWKILL RD
Spiller Company:	001
Contact Name:	TODD ROBINSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER REMOVING WASTE OIL AT ABOVE LOCATION. TRUCK OVERFILLED AND MATERIAL SPILLED ONTO PROPERTY. CALLER ON SITE AND REQUESTING CALL BACK @ 914-948-3305 IN REFERENCE TO CLEANUP - ASAP. ALL CONTAINED; NO ENVIRONMENTAL IMPACT."

All Materials:

Site ID:	174406
Operable Unit ID:	1071606
Operable Unit:	01
Material ID:	310877
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

449
South
1/4-1/2
0.423 mi.
2235 ft.

WHITE PLAINS MED CENTER
170 MAPLE AVE
WHITE PLAINS, NY

NY LTANKS **S104781873**
N/A

Relative:
Higher

Actual:
228 ft.

LTANKS:

Spill Number/Closed Date:	0004388 / 2001-06-22
Facility ID:	0004388
Site ID:	204425
Spill Date:	2000-07-12
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-07-12
CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-12
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN HOLZINGER
Spiller Phone:	(914) 337-1312
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	169978
DEC Memo:	""
Remarks:	"unk. amt. spilled soil being stockpiled at this time."

All Materials:

Site ID:	204425
Operable Unit ID:	826936
Operable Unit:	01
Material ID:	549126
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

450
SSE
1/4-1/2
0.428 mi.
2258 ft.

APARTMENT BLDG
21 GREENRIDGE AVE
WHITE PLAINS, NY

NY LTANKS
NY Spills

S102152028
N/A

Relative:
Higher

Actual:
270 ft.

LTANKS:

Spill Number/Closed Date:	0410525 / 2005-02-24
Facility ID:	0410525
Site ID:	335499
Spill Date:	2004-12-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCDOH
Reported to Dept:	2004-12-22
CID:	407
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-12-22
Spill Record Last Update:	2005-03-04
Spiller Name:	JOHN PORZIO
Spiller Company:	RESIDENCE
Spiller Address:	21 GREENRIDGE AVE
Spiller County:	001
Spiller Contact:	JOHN PORZIO
Spiller Phone:	(914) 980-5005
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	270748
DEC Memo:	"3/4/05: PBS 3-410608; Letter to John S. Porzio from Karen Magnuson, WCDOH dated 24Feb2005. WCDOH recommends NFA at this time."
Remarks:	"PBS No: 3-410608 "

All TTF:

Facility ID:	0410525
Spill Number:	0410525
Spill Tank Test:	1548433
Site ID:	335499
Tank Number:	1
Tank Size:	2000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

APARTMENT BLDG (Continued) **S102152028**

SPILLS:

Spill Number/Closed Date:	9204409 / 1992-07-20
Facility ID:	9204409
Facility Type:	ER
DER Facility ID:	270748
Site ID:	167659
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	1992-07-16
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-07-20
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	REGENT OIL
Spiller Address:	53 CHARLES STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"EMPTYING OIL HOSE AND FUEL CAME OUT VENT PIPE WPFD WAS ON SCENE AND LUZON ON SCENE PUT DOWN SPEEDI-DRI SPOKE WITH KENNY (LUZON) THEY ARE PICKING UP CONTAMINATED SOIL AND WILL DISPOSE"

All Materials:

Site ID:	167659
Operable Unit ID:	968157
Operable Unit:	01
Material ID:	412135
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

451
NNE
1/4-1/2
0.428 mi.
2259 ft.

YWCA
69 NORTH BROADWAY
WHITE PLAINS, NY

NY LTANKS

S105997109
N/A

Relative:
Higher

Actual:
288 ft.

LTANKS:

Spill Number/Closed Date:	0207697 / 2003-05-09
Facility ID:	0207697
Site ID:	63852
Spill Date:	2002-10-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-10-24
CID:	252
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-24
Spill Record Last Update:	2003-06-25
Spiller Name:	REGINALD BUSH
Spiller Company:	YWCA
Spiller Address:	69 NORTH BROADWAY
Spiller County:	001
Spiller Contact:	REGINALD BUSH
Spiller Phone:	(914) 428-1130
Spiller Extention:	303
DEC Region:	3
DER Facility ID:	61609
DEC Memo:	""
Remarks:	"RECOMMENDATION TO UNCOVER-RE-TEST AND OR REMOVE TANK."

All TTF:

Facility ID:	0207697
Spill Number:	0207697
Spill Tank Test:	1527616
Site ID:	63852
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

YWCA (Continued) **S105997109**

All Materials:

Site ID:	63852
Operable Unit ID:	859285
Operable Unit:	01
Material ID:	514708
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF452 **SPILL NUMBER 9909558** **NY LTANKS** **S104620619**
NNW **7 PARK CIRCLE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.431 mi.
2278 ft. **Site 2 of 2 in cluster BF**

Relative: **Higher**
Actual: **323 ft.**

LTANKS:

Spill Number/Closed Date:	9909558 / 2000-01-12
Facility ID:	9909558
Site ID:	222795
Spill Date:	1999-11-05
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-11-05
CID:	365
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-05
Spill Record Last Update:	2000-01-18
Spiller Name:	LISA MARIE LONGO
Spiller Company:	Not reported
Spiller Address:	7 PARK CIRCLE
Spiller County:	001
Spiller Contact:	LISA MARIE LONGO
Spiller Phone:	(203) 532-9675
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	184228
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/12/2000 ROBISON OIL PULLED TANK. TANK WAS SOUND, NO RELEASE; NFA "
Remarks:	"within 10 days they most likely pull the tank"

SPILL NUMBER 9909558 (Continued) **S104620619**

All TTF:

Facility ID:	9909558
Spill Number:	9909558
Spill Tank Test:	1547817
Site ID:	222795
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	222795
Operable Unit ID:	1088254
Operable Unit:	01
Material ID:	298637
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG453 **COMMERCIAL PROPERTY** **NY LTANKS** **S109374727**
WSW **39 WESTMORELAND AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.432 mi.
2283 ft. **Site 4 of 5 in cluster BG**

Relative: LTANKS:
Lower

Spill Number/Closed Date:	9411173 / 1995-09-22
Facility ID:	9411173
Site ID:	221603
Spill Date:	1994-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-09-22
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

Actual:
209 ft.

COMMERCIAL PROPERTY (Continued) **S109374727**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-20
Spill Record Last Update:	1995-09-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	183270
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TTF UNUSUAL CASE TANK LOCATED UNDER LOADING DOCK US TEST -.105"

All TTF:

Facility ID:	9411173
Spill Number:	9411173
Spill Tank Test:	1543373
Site ID:	221603
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	221603
Operable Unit ID:	1005007
Operable Unit:	01
Material ID:	377037
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0807224 / 2009-01-07
Facility ID:	0807224
Site ID:	404560
Spill Date:	2008-09-26

COMMERCIAL PROPERTY (Continued) **S109374727**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH PBS 3-169102
Reported to Dept:	2008-09-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-26
Spill Record Last Update:	2009-01-07
Spiller Name:	KAREN GOMEZ
Spiller Company:	BENEROFE GROUP
Spiller Address:	4 NEW KING ST
Spiller County:	999
Spiller Contact:	BOB URVAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	183270
DEC Memo:	"9-26-09 Spoke with Bob Urvan. They will isolate the tank by entering manway and plugging lines and then retest. They will contact WCHD with results. Faxed spill report to WCHD. jm Passing retest and repair explanation received by WCDOH on 10/31/08 jod"
Remarks:	"TANK TEST FAILURE ON A 10,000 GALLON TANK, DRY PORTION LEAK. NO PRODUCT WAS SPILLED."

All Materials:

Site ID:	404560
Operable Unit ID:	1161209
Operable Unit:	01
Material ID:	2152403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0111615 / 2002-03-11
Facility ID:	0111615
Facility Type:	ER
DER Facility ID:	183270
Site ID:	283261
DEC Region:	3
Spill Cause:	Equipment Failure

COMMERCIAL PROPERTY (Continued) **S109374727**

Spill Class:	C4
SWIS:	6017
Spill Date:	2002-03-08
Investigator:	mbmastro
Referred To:	Not reported
Reported to Dept:	2002-03-08
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-08
Spill Record Last Update:	2002-03-26
Spiller Name:	CALLER
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	001
Contact Name:	BENEROSS REALTY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MASTRO 03/11/2002 OIL CONTAINED TO PAVEMENT. NO SOILS IMPACTED. CLEANUP COMPLETED W/PADS & SPEEDI DRY. NO FURTHER ACTION."
Remarks:	"VENT ALARM WAS NOT WORKING PROPERLY-DRIVER NOT HEARING IT ACCIDENTALLY OVERFILLED TANK-CASTLE OIL HAS DISPATCHED A CLEANUP CREW."

All Materials:

Site ID:	283261
Operable Unit ID:	850255
Operable Unit:	01
Material ID:	525636
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG454 **IRVINGTON** **NY LTANKS** **S100139823**
SW **IRVINGTON** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.436 mi.
2302 ft. **Site 5 of 5 in cluster BG**

Relative: **Lower**
Actual: **208 ft.**

LTANKS:

Spill Number/Closed Date:	8708811 / 1988-03-03
Facility ID:	8708811
Site ID:	309074
Spill Date:	1988-01-15
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility

IRVINGTON (Continued) **S100139823**

Spill Class:	D3
Cleanup Ceased:	1988-03-03
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-28
Spill Record Last Update:	1988-09-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	249617
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : MAY HAVE ALSO BEEN REPORTED AS SPILL # 879230, WHICH HAS NOT LOGED ONTO SYSTEM. NOTE 879230 SHOWES DIFFERENT ADDRESS. V.MC.2-10-88. 03/03/88: TANK PASSED RETEST. N.F.A. L.R. "
Remarks:	"DON REGISTERED TANK WOULD HAVE TO CALL DPW FOR FURTHER INFO. 1-15 DPW NO ANSWER 1-16 DPW TANK TEST LEFT MESSAGE. 1-19 NO ANSWER"

All TTF:

Facility ID:	8708811
Spill Number:	8708811
Spill Tank Test:	1533010
Site ID:	309074
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	309074
Operable Unit ID:	913482
Operable Unit:	01
Material ID:	464176
Material Code:	0009

IRVINGTON (Continued) **S100139823**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

455 **JSD MANAGEMENT** **NY LTANKS** **S100140548**
NE **15 LAKE ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.438 mi.
2315 ft.

Relative:
Higher

Actual:
228 ft.

LTANKS:

Spill Number/Closed Date:	8902337 / 1992-07-30
Facility ID:	8902337
Site ID:	213796
Spill Date:	1989-06-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-06-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-06-09
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177125
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/27/89: RECEIVED RETEST RESULTS ON 6/27/89. THE TANK PASSED WITH 0.01486 GPH LEAK RATE (EZY CHECK). "
Remarks:	"EXCAVATE, EMPTY TANK & INSPECT. 5,000 GAL TANK. HORNER METHOD. GROSS LEAK."

All TTF:

Facility ID:	8902337
Spill Number:	8902337
Spill Tank Test:	1535549
Site ID:	213796

JSD MANAGEMENT (Continued) **S100140548**

Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	213796
Operable Unit ID:	928098
Operable Unit:	01
Material ID:	450046
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

456
East
1/4-1/2
0.444 mi.
2343 ft.

KEY FORD OF WHITE PLAINS
80 WESTCHESTER AVE
WHITE PLAINS, NY 10601

RCRA-CESQG **1000114327**
NY LTANKS **NYD981559586**
FINDS
ECHO
NY MANIFEST

Relative:
Lower

Actual:
159 ft.

RCRA-CESQG:

Date form received by agency:	01/01/2007
Facility name:	KEY FORD OF WHITE PLAINS
Facility address:	80 WESTCHESTER AVE WHITE PLAINS, NY 10601
EPA ID:	NYD981559586
Mailing address:	WESTCHESTER AVE WHITE PLAINS, NY 10601
Contact:	FRED BAUCHHAM
Contact address:	WESTCHESTER AVE WHITE PLAINS, NY 10601
Contact country:	US
Contact telephone:	914-761-6655
Contact email:	Not reported
EPA Region:	02
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

KEY FORD OF WHITE PLAINS (Continued) **1000114327**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KEY FORD OF WP INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	KEY FORD OF WP INC
Owner/operator address:	NOT REQUIRED NOT REQUIRED, WY 99999
Owner/operator country:	US
Owner/operator telephone:	212-555-1212
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency: 01/01/2006

KEY FORD OF WHITE PLAINS (Continued) **1000114327**

Site name: KEY FORD OF WHITE PLAINS
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 09/10/1986
Site name: KEY FORD OF WHITE PLAINS
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 08/13/1990
Date achieved compliance: 08/13/1990
Violation lead agency: State
Enforcement action: Not reported
Enforcement action date: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: Not reported
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/13/1990
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 08/13/1990
Evaluation lead agency: State

LTANKS:
Spill Number/Closed Date: 8606267 / 1987-01-08
Facility ID: 8606267
Site ID: 320738
Spill Date: 1987-01-08
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1987-01-08
SWIS: 6017
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1987-01-08
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 1987-01-08
Recommended Penalty: False
Meets Standard: True

KEY FORD OF WHITE PLAINS (Continued) **1000114327**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	KEY FORD
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	258406
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : TANK HAS BEEN OUT OF SERVICE FOR YEARS-NFA. 11/29/95: This is additional information about material spilled from the translation of the old spill file: TANK BOTTOM MATERIAL."
Remarks:	"TTTF"

All TTF:

Facility ID:	8606267
Spill Number:	8606267
Spill Tank Test:	1530490
Site ID:	320738
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	320738
Operable Unit ID:	903556
Operable Unit:	01
Material ID:	475400
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110004408800

KEY FORD OF WHITE PLAINS (Continued) **1000114327**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000114327
Registry ID:	110004408800
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004408800

NY MANIFEST:

Country:	USA
EPA ID:	NYD981559586
Facility Status:	Not reported
Location Address 1:	80 WESTCHESTER AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981559586
Mailing Name:	KEY FORD OF WHITE PLAINS
Mailing Contact:	KEY FORD OF WHITE PLAINS
Mailing Address 1:	80 WESTCHESTER AVENUE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5067616760

NY MANIFEST:

Document ID:	NYC7278568
Manifest Status:	Not reported
seq:	Not reported
Year:	2004
Trans1 State ID:	NYCF7875
Trans2 State ID:	Not reported
Generator Ship Date:	01/08/2004
Trans1 Recv Date:	01/08/2004
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/13/2004
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported

KEY FORD OF WHITE PLAINS (Continued) **1000114327**

Generator EPA ID:	NYD981559586
Trans1 EPA ID:	TXR000050930
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00006
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00010
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

457
North
1/4-1/2
0.445 mi.
2348 ft.

SUBODH DESHMUKH RESIDENCE
39 PARKVIEW CT
WHITE PLAINS, NY

NY LTANKS **S110309446**
N/A

Relative:
Higher

Actual:
284 ft.

LTANKS:

Spill Number/Closed Date:	1001726 / 2010-08-03
Facility ID:	1001726
Site ID:	434804
Spill Date:	2010-05-13
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

SUBODH DESHMUKH RESIDENCE (Continued) **S110309446**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-05-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2010-06-18
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-05-13
Spill Record Last Update:	2010-08-03
Spiller Name:	JEFF MCKENZIE
Spiller Company:	UNKNOWN
Spiller Address:	39 PARKVIEW CT
Spiller County:	999
Spiller Contact:	JEFF MCKENZIE
Spiller Phone:	(973) 229-5897
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	389678
DEC Memo:	"5/14/10: Core soil samples were taken around the UST showing f/o contamination. Left message with resident and explained they had to address the mattter (remove tank) ASAP. Told them to call the spill desk for more information...ra > Call back from owner. Tank was tested by his employer (Prudential?) for a pending real estate transaction. He is being relocated by his employer and they are assisting in the sale of his house. He states he already has a prospective buyer who wants to close on the house in early June. Owner has contacted his insurance carrier Travlers and was told he has no coverage for an oil leak. He is contacting ATS to try and get copies of the sample results, and states he will contact a contractor - most likely Northeast Environmental - to address the spill issue. jod 6/17/10: NES has removed the tank. Contamination extends unto the neighboring property at 37 Parkview Court. The owner does not feel he showed be responsible for the clean up over the rpoperty line. Left owner a messge requesting he call me back. jod 6/29/10: Letter from NES entered into eDocs. jod 6/30/10: I spoke with the neighbor Mrs Adele Reus at 37 Parkview 914-948-5279. She has received a copy of the access agreement from NES and will be reviewing it soon. I left my name and number in case she has any questions. jod 8/3/10: NES reports has been entered into eDocs. I confirmed with Al Cianflone of NES that all contaminated soil has been removed from the property. No further action is required at this time. jod"
Remarks:	"Caller reporting tank test failure."

All Materials:

Site ID:	434804
Operable Unit ID:	1185606
Operable Unit:	01
Material ID:	2180349
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

SUBODH DESHMUKH RESIDENCE (Continued) **S110309446**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BI458 **AVIS** **NY LTANKS** **S100165725**
SSW **20 WEST POST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.451 mi.
2379 ft. **Site 1 of 2 in cluster BI**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Spill Number/Closed Date:	8706892 / 1988-07-27
Facility ID:	8706892
Site ID:	159466
Spill Date:	1987-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-06-27
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-13
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Responsible Party
Last Inspection:	1988-06-27
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-18
Spill Record Last Update:	2009-01-23
Spiller Name:	JIM SENECAL
Spiller Company:	AVIS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	134698
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 11/13/87-WILL REPLACE TANKS. / / : 2-2K SYSTEMS REMOVED. 02/17/88: WILL REMOVE TANKS LR 02-17-88. 07/27/88: TANKS TO BE REMOVED.EMPTIED. "
Remarks:	"TTTF-2:2K TANKS"

All TTF:

Facility ID:	8706892
Spill Number:	8706892
Spill Tank Test:	1532256
Site ID:	159466
Tank Number:	Not reported
Tank Size:	0

AVIS (Continued) **S100165725**

Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	159466
Operable Unit ID:	912747
Operable Unit:	01
Material ID:	465880
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

459
NE
1/4-1/2
0.457 mi.
2415 ft.

SPILL NUMBER 0011055 **NY LTANKS** **S104950543**
2 AMHERST PL **N/A**
WHITE PLAINS, NY

Relative:
Lower

Actual:
183 ft.

LTANKS:

Spill Number/Closed Date:	0011055 / 2001-09-18
Facility ID:	0011055
Site ID:	196605
Spill Date:	2000-12-15
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-01-10
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-10
Spill Record Last Update:	2002-03-22
Spiller Name:	CALLER

SPILL NUMBER 0011055 (Continued) **S104950543**

Spiller Company:	KENSICO CO-OP
Spiller Address:	2 AMHERST PL
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	163658
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/10/01 CALLER STATES ALL CONTAMINATION HAS BEEN REMOVED; HOLE WAS CLOSED. WILL BE SENDING CLOSURE REPORT. 09/18/2001 NES DISPOSED OF TANK AND 22.88 TONS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"CALLER REMOVED SOIL AND FOUND CONTAMINATION. NEVER CALLED IN AT TIME OF CLEANUP. JUST NOTICED PAPERWORK ERROR, AND CALLED IT IN."

All Materials:

Site ID:	196605
Operable Unit ID:	832970
Operable Unit:	01
Material ID:	541383
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

460
NNE
1/4-1/2
0.464 mi.
2449 ft.

STEWART PLACE CONDOS
10 STEWART PLACE
WHITE PLAINS, NY

NY LTANKS **S112231243**
NY Spills **N/A**

Relative:
Higher

Actual:
250 ft.

LTANKS:

Spill Number/Closed Date:	1206313 / 2013-05-16
Facility ID:	1206313
Site ID:	469308
Spill Date:	2012-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-09-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-09-26

STEWART PLACE CONDOS (Continued) **S112231243**

Spill Record Last Update:	2013-05-16
Spiller Name:	STACEY FERRARO
Spiller Company:	STEWART PLACE CONDOS
Spiller Address:	10 STEWART PLACE
Spiller County:	999
Spiller Contact:	STACEY FERRARO
Spiller Phone:	914 328-4453
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	423609
DEC Memo:	"9-26-12: V.Mc. call to STACEY FERRARO/MRM: UST is for on site generator, aprx. 15 to 20 years old. To be removed, provided contact info for DUt.Enviro.Const., EnviroStar, Grazi1 & NES. 10/16/12: Received a call from Stacey Ferraro. She states they have been having problems getting estimates from a few of the contractors that were given to her by Vince Mcabe. She asked for additional contractor names, located in Westchester County. jod\\ 04/29/13 Northeast Environmental reported that they excavated and removed the tank and that no contaminated soil was present in the excavation. Post excavation soil sample results were below DEC guidance values. NFA. TG"
Remarks:	"generator tank, test failed"

All Materials:

Site ID:	469308
Operable Unit ID:	1219201
Operable Unit:	01
Material ID:	2217680
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	1404979 / 2014-08-07
Facility ID:	1404979
Facility Type:	ER
DER Facility ID:	453377
Site ID:	498385
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2014-08-07
Investigator:	VPMCCABE
Referred To:	Not reported
Reported to Dept:	2014-08-07
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported

STEWART PLACE CONDOS (Continued) **S112231243**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2014-08-07
Spill Record Last Update:	2014-11-10
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	10 STEWART PL
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"8-7-14: V.Mc. call to ERT/Mike: In process of cleanning up. NFA"
Remarks:	"padmount, concrete, and private property grass. C/u pending"

All Materials:

Site ID:	498385
Operable Unit ID:	1247836
Operable Unit:	01
Material ID:	2249161
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.25
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

461
NW
1/4-1/2
0.465 mi.
2453 ft.

GABERIAL **NY LTANKS** **S104621388**
7 FAIRVIEW AVE **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
288 ft.

LTANKS:

Spill Number/Closed Date:	0000372 / 2000-10-13
Facility ID:	0000372
Site ID:	65789
Spill Date:	2000-04-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-04-10
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-10

GABERIAL (Continued) **S104621388**

Spill Record Last Update:	2000-10-20
Spiller Name:	THEO GABERIAL
Spiller Company:	MR GABERIAL
Spiller Address:	7 FAIRVIEW AV
Spiller County:	001
Spiller Contact:	THEO GABERIAL
Spiller Phone:	(914) 948-2886
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	63092
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/13/2000 TANK FAILED AN ISOLATION RETEST. TANK PULLED BY BARNABA GROUP WITH OVERSITE FROM ERM FOR HOMEOWNER'S INSURANCE. TANK WAS FOUND TO HAVE HOLES BUT NO CONTAMINATION WAS FOUND. NFA"
Remarks:	"UNCOVER ISOLATE AND RETEST"

All TTF:

Facility ID:	0000372
Spill Number:	0000372
Spill Tank Test:	1525468
Site ID:	65789
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	1.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	65789
Operable Unit ID:	822087
Operable Unit:	01
Material ID:	288622
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

462
NNW
1/4-1/2
0.468 mi.
2469 ft.

BERTE HOME
3 CHURCH COURT
WHITE PLAINS, NY

NY LTANKS **S106869335**
N/A

Relative:
Higher

Actual:
302 ft.

LTANKS:

Spill Number/Closed Date:	0501302 / 2005-06-19
Facility ID:	0501302
Site ID:	344494
Spill Date:	2005-05-02
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-05-02
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-02
Spill Record Last Update:	2005-06-19
Spiller Name:	DENNIS BERTE
Spiller Company:	BERTE HOME
Spiller Address:	3 CHURCH COURT
Spiller County:	001
Spiller Contact:	DENNIS BERTE
Spiller Phone:	(914) 761-2877
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	291183
DEC Memo:	"June 19, 2005: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 6.17 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"FOUND HOLES WHILE REMOVING:"

All Materials:

Site ID:	344494
Operable Unit ID:	1103135
Operable Unit:	01
Material ID:	583340
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BJ463 **10 SCHOOL STREET** **NY LTANKS** **S108983095**
West **10 SCHOOL STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.470 mi.
2481 ft. **Site 1 of 2 in cluster BJ**

Relative:
Higher

Actual:
215 ft.

LTANKS:

Spill Number/Closed Date:	0710736 / 2008-05-01
Facility ID:	0710736
Site ID:	392081
Spill Date:	2008-01-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-01-10
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-10
Spill Record Last Update:	2008-05-01
Spiller Name:	LYDIA
Spiller Company:	Not reported
Spiller Address:	10 SCHOOL STREET
Spiller County:	001
Spiller Contact:	LYDIA
Spiller Phone:	(914) 949-2892
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	341690
DEC Memo:	"Tank to be uncovered, checked and retested. 5/1/2008: Advanced Environmental disposed of LUST and 6.02 tons of contaminated soil. Spill closure report submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"FAILED HISSING AND WILL UNCOVER AND REPAIR AND WILL RETEST: HOMEOWNER DOES NOT SPEAK GOOD ENGLISH"

All TTF:

Facility ID:	0710736
Spill Number:	0710736
Spill Tank Test:	2384455
Site ID:	392081
Tank Number:	Not reported
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	03
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

10 SCHOOL STREET (Continued) **S108983095**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 392081
Operable Unit ID: 1149108
Operable Unit: 01
Material ID: 2139612
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

---

464 SE 1/4-1/2 0.472 mi. 2493 ft. **MILLER CENTER FOR NURSING** **NY LTANKS** **S100136824**
37 DEKALD AVE **N/A**
WHITE PLAINS, NY

Relative: Higher
Actual: 248 ft.

LTANKS:
Spill Number/Closed Date: 8802117 / 1988-08-30
Facility ID: 8802117
Site ID: 211184
Spill Date: 1988-06-03
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1988-08-30
SWIS: 6017
Investigator: dxtraver
Referred To: Not reported
Reported to Dept: 1988-06-07
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-06-10
Spill Record Last Update: 1988-12-05
Spiller Name: Not reported
Spiller Company: DR MILLER
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3

MILLER CENTER FOR NURSING (Continued) **S100136824**

DER Facility ID: 175055
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 08/29/88: TANK TO BE FILLED IN PLACE. SWITCHING TO GAS. "
Remarks: "TANK TO BE TAKEN OUT OF SERVICE. NFA"

All TTF:
Facility ID: 8802117
Spill Number: 8802117
Spill Tank Test: 1534060
Site ID: 211184
Tank Number: Not reported
Tank Size: 0
Material: 0002
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 211184
Operable Unit ID: 919447
Operable Unit: 01
Material ID: 461242
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

BJ465 **12 HARMON STREET** **NY LTANKS** **S107410467**
West **12 HARMON STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.474 mi.
2502 ft. **Site 2 of 2 in cluster BJ**

Relative:
Higher

Actual:
214 ft.

LTANKS:
Spill Number/Closed Date: 0506799 / 2012-08-15
Facility ID: 0506799
Site ID: 352081
Spill Date: 2005-09-02
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 2005-09-02

12 HARMON STREET (Continued) **S107410467**

CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-02
Spill Record Last Update:	2012-08-15
Spiller Name:	DEBORAH - REALTY
Spiller Company:	Not reported
Spiller Address:	12 HARMON STREET
Spiller County:	001
Spiller Contact:	DEBORAH - REALTY
Spiller Phone:	(914) 949-8828
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	299377
DEC Memo:	"7/30/10 Homeowner TTF JO'M 8/15/12 Upon Consultation with Albany and the Region all HO TTF's greater then 5 years old and no indications of contamination or problems will be closed. NFA JO'M"
Remarks:	"UNCOVER REPAIR AND RETEST"

All TTF:

Facility ID:	0506799
Spill Number:	0506799
Spill Tank Test:	1549268
Site ID:	352081
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	352081
Operable Unit ID:	1109595
Operable Unit:	01
Material ID:	2099604
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BI466 **WHITE PLAINS LINC/MERCURY** **NY LTANKS** **S104782116**
SSW **25 WEST COAST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.478 mi.
2524 ft. **Site 2 of 2 in cluster BI**

Relative:
Higher

Actual:
211 ft.

LTANKS:

Spill Number/Closed Date:	0005954 / 2001-04-24
Facility ID:	0005954
Site ID:	226425
Spill Date:	2000-08-18
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-08-18
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-18
Spill Record Last Update:	2001-05-08
Spiller Name:	CARY FRANKEL
Spiller Company:	WHITE PLAINS LINC/MERCURY
Spiller Address:	25 WEST COAST RD
Spiller County:	001
Spiller Contact:	CARY FRANKEL
Spiller Phone:	(914) 946-2100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	186890
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/18/2000 INSTRUCTED OWNER TO HAVE CONTRACTOR PREPARE REPORT W/RESULTS AND SUBMIT TO DEC. 01/18/2001 LETTER FROM NORTHEAST ENVIRONMENTAL RECEIVED. 86.48 TONS OF SOIL WERE EXCAVATED & DISPOSED. A FOUR INCH WELL WAS INSTALLED IN THE TANK GRAVE FOR MONITORING AND TESTING PURPOSES. 04/24/2001 LETTER SENT TO NORTHEAST ENVIRONMENTAL BY T. GHIOSAY; BASED ON LETTER & WATER SAMPLE RESULTS, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL REPORT LISTED AS CLOSED."
Remarks:	"during tank removal 1000 gal ust soil contamination discovered"

All Materials:

Site ID:	226425
Operable Unit ID:	826863
Operable Unit:	01
Material ID:	547087
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

WHITE PLAINS LINC/MERCURY (Continued) **S104782116**

Oxygenate: Not reported

BK467 **FIRE HOUSE # 4** **NY LTANKS** **U000379970**
SSW **MAPLE AVE & S LEXINGTON** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.480 mi.
2536 ft. **Site 1 of 2 in cluster BK**

Relative:
Higher

Actual:
224 ft.

LTANKS:

Spill Number/Closed Date:	8707150 / 1989-01-05
Facility ID:	8707150
Site ID:	178231
Spill Date:	1987-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1989-01-05
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-05
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-20
Spill Record Last Update:	1989-02-07
Spiller Name:	MR. BROCCHI
Spiller Company:	CITY OF WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149695
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"K SYSTEM- -.0709GPH. TO E & I & R. PBS TO FOLLOW.NO RESULTS"

All TTF:

Facility ID:	8707150
Spill Number:	8707150
Spill Tank Test:	1532378
Site ID:	178231
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

FIRE HOUSE # 4 (Continued) **U000379970**

Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 178231
Operable Unit ID: 912874
Operable Unit: 01
Material ID: 466123
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

468
North
1/4-1/2
0.480 mi.
2537 ft.

SPILL NUMBER 0310118
79 NORTH BROADWAY
WHITE PLAINS, NY

NY LTANKS **U003645623**
NY Spills **N/A**

Relative:
Higher

Actual:
300 ft.

LTANKS:
Spill Number/Closed Date: 8708679 / 1989-01-06
Facility ID: 8708679
Site ID: 319975
Spill Date: 1988-01-12
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1989-01-06
SWIS: 6017
Investigator: jeokesso
Referred To: Not reported
Reported to Dept: 1988-01-12
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: 1989-01-06
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-01-28
Spill Record Last Update: 1989-02-07
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: SUPT.LACUSTA
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

SPILL NUMBER 0310118 (Continued) **U003645623**

DEC Region: 3
DER Facility ID: 257795
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 11/25/88: TANK TO BE REPLACED. "
Remarks: "3K .556GPH HORNER EASY. PBS TO FOLLOW.RETEST NEEDED."

All TTF:
Facility ID: 8708679
Spill Number: 8708679
Spill Tank Test: 1532969
Site ID: 319975
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 319975
Operable Unit ID: 914029
Operable Unit: 01
Material ID: 464054
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Spill Number/Closed Date: 0310118 / 2003-12-18
Facility ID: 0310118
Facility Type: ER
DER Facility ID: 257795
Site ID: 319974
DEC Region: 3
Spill Cause: Unknown
Spill Class: A3
SWIS: 6017
Spill Date: 2003-11-29
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2003-11-29
CID: 74
Water Affected: Not reported
Spill Source: Commercial/Industrial

SPILL NUMBER 0310118 (Continued) **U003645623**

Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	Not reported
Spill Record Last Update:	2003-12-18
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JOHN DEROCH
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-BADOLATO 12/18/03 CLEAN UP COMPLETED BY NORTHEAST ENVIRONMENTAL." Not reported
Remarks:	"FIRE AT THIS LOCATION. SPILL FOUND AFTER FIRE. NO INJURIES."

All Materials:

Site ID:	319974
Operable Unit ID:	875206
Operable Unit:	01
Material ID:	499055
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL469 **PRIVATE HOME** **NY LTANKS** **S107410732**
South **43 LONGVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.486 mi.
2566 ft. **Site 1 of 2 in cluster BL**

Relative:
Higher

Actual:
241 ft.

LTANKS:

Spill Number/Closed Date:	0507448 / 2006-03-15
Facility ID:	0507448
Site ID:	352870
Spill Date:	2005-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2006-04-21
Recommended Penalty:	False

PRIVATE HOME (Continued) **S107410732**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-21
Spill Record Last Update:	2006-04-26
Spiller Name:	TED BECERRA
Spiller Company:	REAL ESTATE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TED BECERRA
Spiller Phone:	(845) 222-3185
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300164
DEC Memo:	"SEE SPILL 05-08523. NFA THIS NUMBER jod"
Remarks:	"UNCOVER REAPAIR AND RETEST OR REMOVE"

All TTF:

Facility ID:	0507448
Spill Number:	0507448
Spill Tank Test:	1549328
Site ID:	352870
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	352870
Operable Unit ID:	1110343
Operable Unit:	01
Material ID:	2100356
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0508523 / 2006-07-11
Facility ID:	0508523
Site ID:	354077
Spill Date:	2005-10-17
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling

PRIVATE HOME (Continued) **S107410732**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-10-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2006-04-21
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-17
Spill Record Last Update:	2006-07-26
Spiller Name:	TED BECERRA
Spiller Company:	PRIVATE HOME
Spiller Address:	43 LONGVIEW AVE
Spiller County:	001
Spiller Contact:	TED BECERRA
Spiller Phone:	(845) 222-3185
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300164
DEC Memo:	"Pulled tank, found contamination, Elite proposing to remove soil and is awaiting owner's instructions. July 11, 2006: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 323.19 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND SAMPLED. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"HOLES IN TANK: 550 GALLON"

All Materials:

Site ID:	354077
Operable Unit ID:	1111516
Operable Unit:	01
Material ID:	2101557
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BK470 **GREAT GRANT MANOR PROP** **NY LTANKS** **S100879284**
SSW **235 SOUTH LEXINGTON AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.489 mi.
2584 ft. **Site 2 of 2 in cluster BK**

Relative: **Higher**

Actual: **228 ft.**

LTANKS:

Spill Number/Closed Date:	0204243 / 2002-11-06
Facility ID:	0204243
Site ID:	147077

GREAT GRANT MANOR PROP (Continued) **S100879284**

Spill Date:	2002-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-07-23
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-07-23
Spill Record Last Update:	2003-10-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ED OR BETH DEALAUREANTS
Spiller Phone:	(914) 946-1321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	125226
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 11/06/02 TANK PASSED A RETEST AS PER WAYNE SCHNEIDER OF WCHD."
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION PROPERTY OWNER HAS BEEN ADVISED OF PROBLEM. RECOMMENDING UNCOVERED,REPAIR AND RETEST."

All TTF:

Facility ID:	0204243
Spill Number:	0204243
Spill Tank Test:	1527308
Site ID:	147077
Tank Number:	1
Tank Size:	20000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147077
Operable Unit ID:	855411
Operable Unit:	01

GREAT GRANT MANOR PROP (Continued) **S100879284**

Material ID: 518501
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 0304500 / 2003-10-31
Facility ID: 0304500
Site ID: 147078
Spill Date: 2003-07-29
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2003-07-29
CID: 199
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-07-29
Spill Record Last Update: 2003-12-12
Spiller Name: Not reported
Spiller Company: SOUTH LEX PARTNERS LLC C/O DELAURNETIS MANAGEMEN
Spiller Address: 235 S LEXINGTON
Spiller County: 001
Spiller Contact: ED OR BETH DEALAUREANTS
Spiller Phone: (914) 946-1321
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 125226
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 10/15/03 Closure letter sent to DeLaurentis Mgmt. Co from C Lalak from the WCHD note: Any health related questions regarding soil contaminants should be referred to the Health Department. TG"
Remarks: ""

All Materials:
Site ID: 147078
Operable Unit ID: 871313
Operable Unit: 01
Material ID: 505359
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

GREAT GRANT MANOR PROP (Continued) **S100879284**

Units: G
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 9313731 / 1995-01-05
Facility ID: 9313731
Site ID: 147079
Spill Date: 1994-02-22
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: 1995-01-05
SWIS: 6017
Investigator: MONACO
Referred To: Not reported
Reported to Dept: 1994-02-22
CID: Not reported
Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: 1994-09-27
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1994-03-08
Spill Record Last Update: 2003-10-20
Spiller Name: Not reported
Spiller Company: PRESIDENCIAL MANAGEMENT
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 125226
DEC Memo: ""
Remarks: "20,000 GAL IN GROUND TANK SPILL THROUGH WALL INTO SUMP PUMP INTO WASTE LINES LT. DAMAN (FD) TOLD SPT. TO START CLEAN UP FAXED TO TODD EASTMAN TANK PUMPING OUT TANK CLEAN UP IN PROGRESS"

All Materials:
Site ID: 147079
Operable Unit ID: 992182
Operable Unit: 01
Material ID: 389103
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

Spill Number/Closed Date: 9706472 / 1998-02-27
Facility ID: 9706472

GREAT GRANT MANOR PROP (Continued) **S100879284**

Site ID:	147080
Spill Date:	1997-08-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-08-28
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-28
Spill Record Last Update:	2003-10-20
Spiller Name:	LESTER CHAYET
Spiller Company:	GRANT MANOR PROPERTIES
Spiller Address:	235 SOUTH LEXINGTON AV
Spiller County:	001
Spiller Contact:	LESTER CHAYET
Spiller Phone:	(718) 649-9400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	125226
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/27/98 RETEST AFTER REPAIRS; ALL OK; "
Remarks:	"UNABLE TO OBTAIN A VACUUM. WILL REPAIR MANWAY SEALS AND RETEST."

All TTF:

Facility ID:	9706472
Spill Number:	9706472
Spill Tank Test:	1545287
Site ID:	147080
Tank Number:	1
Tank Size:	20000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147080
Operable Unit ID:	1049837
Operable Unit:	01
Material ID:	332052

GREAT GRANT MANOR PROP (Continued) **S100879284**

Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

471 South 1/4-1/2 0.490 mi. 2588 ft. **FELIX DAVILA** **NY LTANKS** **S105999491**
36 DAVIS RD **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 242 ft.

LTANKS:

Spill Number/Closed Date:	0304516 / 2003-10-23
Facility ID:	0304516
Site ID:	187946
Spill Date:	2003-07-29
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-07-29
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-29
Spill Record Last Update:	2003-10-23
Spiller Name:	OWNER
Spiller Company:	FELIX DAVILA
Spiller Address:	36 DAVIS RD
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157053
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/23/03 NETS DISPOSED OF LUST AND 62.66 TONS OF CONTAMINATED SOIL."
Remarks:	"PULLED TANK, CONTAMINATED SOIL."

All Materials:

Site ID:	187946
Operable Unit ID:	872768
Operable Unit:	01
Material ID:	505377

FELIX DAVILA (Continued) **S105999491**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

472 **REALTY TRANSACTION** **NY LTANKS** **S106971986**
NNW **52 PARK CIRCLE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.492 mi.
2597 ft.

Relative:
Higher

Actual:
330 ft.

LTANKS:

Spill Number/Closed Date:	0502737 / 2005-07-25
Facility ID:	0502737
Site ID:	347156
Spill Date:	2005-06-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-06-07
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-07
Spill Record Last Update:	2005-07-25
Spiller Name:	PAUL SCORZELLI
Spiller Company:	REALTY TRANSACTION
Spiller Address:	52 PARK CIRCLE
Spiller County:	001
Spiller Contact:	PAUL SCORZELLI
Spiller Phone:	(914) 946-4300
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	293448
DEC Memo:	"SEE SPILL 05-03444 FOR CLOSURE REPORT. jod July 25, 2005: NES DISPOSED OF LUST AND 7.12 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM JM ASSOCIATES. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"ISOLATE AND TEST AGAIN"

All TTF:

Facility ID:	0502737
Spill Number:	0502737
Spill Tank Test:	1548966

REALTY TRANSACTION (Continued) **S106971986**

Site ID:	347156
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	347156
Operable Unit ID:	1104902
Operable Unit:	01
Material ID:	1262229
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

473 South 1/4-1/2 0.497 mi. 2623 ft.

RESIDENCE
23 OAKWOOD RD
WHITE PLAINS, NY

NY LTANKS **S104191940**
N/A

Relative: Higher

Actual: 249 ft.

LTANKS:

Spill Number/Closed Date:	9906780 / 2000-01-28
Facility ID:	9906780
Site ID:	246760
Spill Date:	1999-09-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-09-07
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

RESIDENCE (Continued) **S104191940**

Date Entered In Computer:	1999-09-07
Spill Record Last Update:	2000-02-07
Spiller Name:	UNK
Spiller Company:	RESIDENCE....
Spiller Address:	23 OAKWOOD RD
Spiller County:	001
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	202609
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/28/2000 DEC INSPECTED SITE. TANK CANNOT BE EXCAVATED OR REMOVED BECUASE IT IS BURIED IN THE FOUNDATION AND BENEATH A CONCRETE PATIO,. TANK WAS CUT, CLEANED AND INSPECTED BY NORTHEAST ENVIRONMENTAL. HOLES WERE FOUND IN TANK. SOIL SAMPLES FROM BENEATH TANK SHOW MINIMAL CONTAMINATION. TANK WAS ABANDONED IN PLACE. NFA"
Remarks:	"tank failed test - no product spillage"

All TTF:

Facility ID:	9906780
Spill Number:	9906780
Spill Tank Test:	1547587
Site ID:	246760
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	246760
Operable Unit ID:	1081085
Operable Unit:	01
Material ID:	299504
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BL474
South
1/4-1/2
0.498 mi.
2627 ft.

RESIDENTS
44 LONGVIEW AVE
WHITE PLAINS, NY

Site 2 of 2 in cluster BL

NY LTANKS **S102556019**
N/A

Relative:
Higher

Actual:
239 ft.

LTANKS:

Spill Number/Closed Date:	9614364 / 1997-03-11
Facility ID:	9614364
Site ID:	166538
Spill Date:	1997-03-11
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-03-11
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-03-11
Spill Record Last Update:	2004-02-20
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MR RIVERSO RESIDENTS
Spiller Phone:	(914) 948-3383
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	140318
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/11/97 NO IMPACT TO THE ENVIRONMENT. "
Remarks:	"HOLES IN THE TANK OCCURRED FROM THE AGE OF THE TANK SPILL IS BEING CLEANED UP BY ENVIORNMENTAL COMPANY THE HOMEOWNER IS SWITCHING TO GAS AND THE TANK WILL BE DISPOSED OF"

All Materials:

Site ID:	166538
Operable Unit ID:	1041801
Operable Unit:	01
Material ID:	339475
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

475 ESE 1/4-1/2 0.498 mi. 2629 ft.

Relative: Lower

Actual: 156 ft.

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISIO
21 BLOOMINGDALE ROAD
WHITE PLAINS, NY 10605

Database(s): RCRA-LQG, NY LTANKS, NY CBS, NY CBS AST, NY Spills, NY AIRS, NY MANIFEST

EDR ID Number: 1000990620
EPA ID Number: NY0001020908

RCRA-LQG:

Date form received by agency:	03/05/2014
Facility name:	NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION
Facility address:	21 BLOOMINGDALE ROAD WHITE PLAINS, NY 10605
EPA ID:	NY0001020908
Mailing address:	BLOOMINGDALE ROAD WHITE PLAINS, NY 10605
Contact:	EDWARD FOMINYAM
Contact address:	EAST 68TH STREET EHS BOX 157 NEW YORK, NY 10065
Contact country:	US
Contact telephone:	212-746-1927
Contact email:	EDF9014@NYP.ORG
EPA Region:	02
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	NEW YORK PRESBYTERIAN HOSPITAL
Owner/operator address:	EAST 68TH STREET NEW YORK, NY 10021
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported
Owner/operator extension:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1998
Owner/Op end date:	Not reported

Owner/operator name:	NEW YORK PRESBYTERIAN HOSPITAL
Owner/operator address:	EAST 68TH STREET NEW YORK, NY 10021
Owner/operator country:	US
Owner/operator telephone:	Not reported
Owner/operator email:	Not reported
Owner/operator fax:	Not reported

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1998
Owner/Op end date: Not reported

Owner/operator name: THE NEW YORK HOSPITAL
Owner/operator address: 21 BLOOMINGDALE RD
WHITE PLAINS, NY 10605
Owner/operator country: Not reported
Owner/operator telephone: 914-682-9100
Owner/operator email: Not reported
Owner/operator fax: Not reported
Owner/operator extension: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

. Waste code: P204
. Waste name: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMAT

. Waste code: U010
. Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U150
. Waste name: MELPHALAN

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Historical Generators:
Date form received by agency: 10/18/2013
Site name: NEW YORK PRESBYTERIAN WESTCHESTER DIVISION
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

. Waste code: P075
. Waste name: NICOTINE, & SALTS

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-

. Waste code: P204
. Waste name: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMAT

. Waste code: U010
. Waste name: AZIRINO[2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA,8AALPHA,8BALPHA)]-

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]-

. Waste code: U058
. Waste name: CYCLOPHOSPHAMIDE

. Waste code: U132
. Waste name: HEXACHLOROPHENE

. Waste code: U150
. Waste name: MELPHALAN

. Waste code: U200
. Waste name: RESERPINE

. Waste code: U205
. Waste name: SELENIUM SULFIDE

. Waste code: B007
. Waste name: B007

Date form received by agency: 01/01/2007
Site name: NEW YORK BLOOD CENTER - CLINICAL SVCS
Classification: Not a generator, verified

Date form received by agency: 01/01/2006
Site name: NEW YORK BLOOD CENTER - CLINICAL SVCS
Classification: Not a generator, verified

Date form received by agency: 02/16/2005
Site name: NEW YORK BLOOD CENTER - CLINICAL SVCS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: P105
. Waste name: SODIUM AZIDE

. Waste code: U151
. Waste name: MERCURY

Date form received by agency: 07/08/1999

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Site name: NEW YORK HOSPITAL THE
Classification: Not a generator, verified

Date form received by agency: 05/20/1998
Site name: NEW YORK HOSPITAL CORNELL MEDICAL CENTER
Classification: Large Quantity Generator

Date form received by agency: 02/02/1995
Site name: NEW YORK HOSPITAL THE
Classification: Small Quantity Generator

. Waste code: D000
. Waste name: Not Defined

. Waste code: D001
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002
. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: D003
. Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: U123
. Waste name: FORMIC ACID (C,T)

. Waste code: U188
. Waste name: PHENOL

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/09/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Date achieved compliance: Not reported
Evaluation lead agency: State

LTANKS:
Spill Number/Closed Date: 0404544 / 2009-06-24
Facility ID: 0404544
Site ID: 267816
Spill Date: 2004-07-27
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: WESTCHESTER CNTY HEALTH DEPT
Reported to Dept: 2004-07-27
CID: 407
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-07-27
Spill Record Last Update: 2009-06-24
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: DOUG MCGRAPH
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 218177
DEC Memo: "Tank test failure reported at New York Presbyterian Hospital. PBS registration 3-170585 WCDOH will follow up. 6/24/09: Tank passed a subsequent test after repair work. NFA jod"
Remarks: "Going to isolate and test the tank."

All TTF:
Facility ID: 0404544
Spill Number: 0404544
Spill Tank Test: 1529475
Site ID: 267816
Tank Number: 1
Tank Size: 1000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Spill Number/Closed Date:	9813782 / 1999-06-02
Facility ID:	9813782
Site ID:	267817
Spill Date:	1999-02-12
Spill Cause:	Tank Overfill
Spill Source:	Unknown
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-02-12
CID:	204
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-12
Spill Record Last Update:	1999-06-08
Spiller Name:	Not reported
Spiller Company:	AMERADA HESS
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	NICHOLAS PASCAL
Spiller Phone:	(201) 489-5100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	218177
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK OVERFILL - OVER 100 GALLONS. SPILL IMPACTED STORM DRAIN ALONG A SERVICE ROAD. CASTLETON ENV. & CLEAN HARBORS ENROUTE FOR CLEANUP."

All Materials:

Site ID:	267817
Operable Unit ID:	1071328
Operable Unit:	01
Material ID:	310487
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

CBS:

CBS Number:	3-000206
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	3

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

UTMX: 604397.54932
UTMY: 4542870.41067

CBS AST:

CBS Number:	3-000206
ICS Number:	3-700591
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	F
Telephone:	(914) 682-9100
Facility Town:	WHITE PLAINS (C)
Region:	STATE
Expiration Date:	07/27/2001
Total Capacity of All Active Tanks(gal):	0
Operator:	GROUNDS SUPERVISOR
Emergency Contact:	KENNETH MUCHERINO
Emergency Phone:	(914) 997-5701
Owner Name:	NEW YORK HOSPITAL CORNELL
Owner Address:	21 BLOOMINGDALE ROAD
Owner City,St,Zip:	WHITE PLAINS, NY 10605
Owner Telephone:	(914) 997-5701
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	NEW YORK HOSPITAL CORNELL
Mail Contact Addr:	21 BLOOMINGDALE ROAD
Mail Contact Addr2:	Not reported
Mail Contact Contact:	KENNETH F. MUCHERINO
Mail Contact City,St,Zip:	WHITE PLAINS, NY 10605
Mail Phone:	(914) 997-5701

Tank Id:	001
CAS Number:	7782505
Federal ID:	Not reported
Tank Status:	0
Install Date:	10/86
Tank Closed:	12/99
Capacity (Gal):	350
Chemical:	Chlorine
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass coated steel
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	Double-Walled Tank
Tank Error Status:	No Missing Data
Date Entered:	07/27/1989
Certified Date:	05/04/1999
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	Other

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Overfill Protection:	Catch Basin
Haz Percent:	100
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	5517
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	04/01/93
Is It There:	False
Delinquent:	False
Date Expired:	07/27/95
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	04/01/1999

SPILLS:

Spill Number/Closed Date:	9512089 / Not Reported
Facility ID:	9512089
Facility Type:	ER
DER Facility ID:	218177
Site ID:	282420
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-12-26
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-26
CID:	257
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	4
Date Entered In Computer:	1995-12-26
Spill Record Last Update:	2018-05-10
Spiller Name:	KEN MUCHERINO
Spiller Company:	NEW YORK HOSPITAL
Spiller Address:	21 BLOOMINDALE RD
Spiller Company:	001
Contact Name:	KEN MUCHERINO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/26/95 UNKNOWWN TANK ENCOUNTERED TO BE REMOVED 10/06/99 LETTER SENT; ORC INJECTION PROPOSAL HAS BEEN APPROVED- ADVISE T. GHIOSAY WHEN GEO-PROBE WORK IS TO BEGIN; 10/25/01 IDC GW MONITORING REPORT SUBMITTED. BTEX REMAINS HIGH AROUND TANK FIELD. IDC PROPOSES PUMPING 3 WELLS WITH A VAC TRUCK FOR TWO WELLS & THEN EVALUATING CONNECTING AREA TO PUMP & TREAT SYSTEM. 06/17/03 Monitoring report submitted by Ira D. Conklin. Report recommended expanding the pumping of ground water from MW-1 & MW-7. 01-07-04 Quarterly monitoring

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

report received from IDC. Significant contamination still exists in the areas around MW1 MW2, MW3 and MW7. Expansion of the treatment system to that area still has not been implemented. TG 07/28/04 Quarterly monitoring report rec'd from IDC. Elevated levels of contaminants in 1,2,3,7,9. Recommends pumping from 1,2,7, & 9. 05/31/05 2nd Quarter Monitoring report submitted be Greg Bendell from Ira Conklin and sons. VOC contamination still present in MW1, MW2 & MW3. Conklin recommended ...targeted monthly vac truck events on MW1, 2, 3 to expedite contamination removal. TG 10/26/06 Quarterly monitoring report submitted by Conklin Services & Construction, formerly Ira Conklin and Sons. TG 10/14/08 Quarterly monitoring report submitted by Conklin Services& Construction. 03/04/09 Monitoring report submitted by Conklin including recommendations for remedial measures to accelerate the pace of the cleanup. Stacey Smit from Conklin was advised that the DEC will require that one or more of the alternatives be selected and implemented. She will respond back to DEC after preparing cost estimates for the client. TG 10/01/09 Quarterly monitoring report received from Conklin. TG 07/12/10 Quarterly monitoring report received from Conklin. TG 01/26/11 Quarterly monitoring report dated 12/17/10 received from Conklin. Report recommends monthly vacuum events be performed on MW-1. TG 03/18/11 New project manager Michael and a staff engineer from Conklin called and a remedial approach was discussed which they will be submitting a letter shortly. TG 04/30/11 GW monitoring report submitted by Conklin. Sudden spike in VOC detected in down gradient well 6. Suggested immediate resampling to confirm. Report in edocs. TG 08/01/13 Remedial Action Reprot submitted by Conklin. Report describes the injection of Hydrogen peroxide and followup sampling of hte monitorin wells. Report in edocs. TG 07/28/14 Remedial Action Report 2014 Summary report received from Conklin Services & Construction. See report in DecDocs. TG 6-16-17 inquiry from WCHD-ZRDB 06/16/17 Natasha Court from the WCHD provided the contact info for the current Director of Facilities, James Dean. Emailed Jim Dean requesting a callback to discuss moving ahead on the remediation. TG 09/19/17 Optima Environmental prepared a QMR for the 2nd Qtr 2017. Report in DecDocs. Elevated VOC's remain in IW-1 and at lower levels in MW-1. 04/23/18 Triumverate Environmental submitted a Groundwater Assessment Report which can be found in DecDec's. TG "

Remarks: "CALLER FOUND CONTAMINATED SOIL WHILE REMOVING TANK"

All Materials:

Site ID:	282420
Operable Unit ID:	1026305
Operable Unit:	01
Material ID:	359407
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	True

Site ID:	282420
Operable Unit ID:	1026305
Operable Unit:	01
Material ID:	2106654

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	True

Spill Number/Closed Date:	9500446 / 1995-10-11
Facility ID:	9500446
Facility Type:	ER
DER Facility ID:	218177
Site ID:	197890
DEC Region:	3
Spill Cause:	Other
Spill Class:	D3
SWIS:	6017
Spill Date:	1995-04-01
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1995-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	1995-10-11
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1948-12-27
Spill Record Last Update:	2004-02-20
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 111111111111 02/20/04 SPILL FILE CORRUPTED ON DATABASE. NO HARD COPY FILE EXISTS IN REGIONAL OFFICE. jbo"
Remarks:	""

All Materials:

Site ID:	197890
Operable Unit ID:	1011209
Operable Unit:	01
Material ID:	369063
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

AIRS:

Permit Type:	AFR
Permit Status:	Issued
Issue Date:	04/13/1999
Expiration Date:	Not reported
County Fips:	Not reported
DEC Id:	3551700138
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	2
Latitude:	Not reported
Longitude:	Not reported

NY MANIFEST:

Country:	USA
EPA ID:	NY0001020908
Facility Status:	Not reported
Location Address 1:	21 BLOOMINGDALE ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10605
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0001020908
Mailing Name:	NEW YORK PRESBYTERIAN HOSPITAL
Mailing Contact:	VAN BENSON
Mailing Address 1:	525 EAST 68TH ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10065
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149974040

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	2018
Trans1 State ID:	MAC300016672
Trans2 State ID:	Not reported
Generator Ship Date:	06/12/2018
Trans1 Recv Date:	06/12/2018
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/14/2018
Part A Recv Date:	Not reported

NEW YORK PRESBYTERIAN HOSPITAL WESTCHESTER DIVISION (Continued) **1000990620**

Part B Recv Date:	Not reported
Generator EPA ID:	NY0001020908
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	011131013FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	0.09
Units:	P - Pounds
Number of Containers:	1
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	P001
Waste Code 1_2:	P075
Waste Code 1_3:	P188
Waste Code 1_4:	P204
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Click this hyperlink while viewing on your computer to access
47 additional NY MANIFEST: record(s) in the EDR Site Report.

476
NE
1/4-1/2
0.498 mi.
2630 ft.

BILTMORE TOWERS APTS
30 LAKE STREET
WHITE PLAINS, NY

NY LTANKS **S109416253**
NY Spills **N/A**

Relative:
Lower

Actual:
205 ft.

LTANKS:

Spill Number/Closed Date:	1010357 / 2011-03-30
Facility ID:	1010357
Site ID:	443959
Spill Date:	2011-01-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA

BILTMORE TOWERS APTS (Continued) **S109416253**

Referred To:	Not reported
Reported to Dept:	2011-01-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-01-04
Spill Record Last Update:	2011-03-30
Spiller Name:	LARRY NEWMAN
Spiller Company:	CONDO TOWER
Spiller Address:	30 LAKE ST
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 855-3970
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	357952
DEC Memo:	"01/05/11 Tank was relined in 1999. Will be uncovered to hopefully find problem and repair and then tank will be retested....mm 3/30/2011 As per WCDOH 30 lake street, white plains- ttf, man way flange fixed and tank passed retest NFA JO'M "
Remarks:	"Caller reporting tank test failure."

All Materials:

Site ID:	443959
Operable Unit ID:	1194403
Operable Unit:	01
Material ID:	2190203
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Spill Number/Closed Date:	0411926 / 2005-03-27
Facility ID:	0411926
Site ID:	337240
Spill Date:	2005-02-08
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	WCHD
Referred To:	Not reported
Reported to Dept:	2005-02-08
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

BILTMORE TOWERS APTS (Continued) **S109416253**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-02-08
Spill Record Last Update:	2005-03-27
Spiller Name:	BILL PALMER
Spiller Company:	COMMERCIAL PROP-ERTY
Spiller Address:	30 LAKE STREET
Spiller County:	001
Spiller Contact:	BILL PALMER
Spiller Phone:	(914) 682-7398
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	272582
DEC Memo:	"03/27/05 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"PBS No: 3-183024 "

All TTF:

Facility ID:	0411926
Spill Number:	0411926
Spill Tank Test:	1548570
Site ID:	337240
Tank Number:	1
Tank Size:	15000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	337240
Operable Unit ID:	1099226
Operable Unit:	01
Material ID:	579539
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	8706628 / 1988-07-27
Facility ID:	8706628
Site ID:	243796

BILTMORE TOWERS APTS (Continued) **S109416253**

Spill Date:	1987-11-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1988-07-25
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-04
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	1988-07-25
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-18
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127288
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 11/5/87-WILL RETEST. 07/27/88: TANK RETESTED AND PASSED. "
Remarks:	"TTTF-15K TANK;HIGH VOLUME LEAK"

All TTF:

Facility ID:	8706628
Spill Number:	8706628
Spill Tank Test:	1532166
Site ID:	243796
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	243796
Operable Unit ID:	912519
Operable Unit:	01
Material ID:	465635

BILTMORE TOWERS APTS (Continued) **S109416253**

Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	9905417 / 2003-12-05
Facility ID:	9905417
Site ID:	149672
Spill Date:	1999-08-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-08-04
CID:	389
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-04
Spill Record Last Update:	2003-12-05
Spiller Name:	Not reported
Spiller Company:	DICK YAKMAN
Spiller Address:	30 LAKE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	127288
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MCDONALD 8/4/99 WCHD TO FOLLOW UP. 12/01/99 LETTER SENT TO BILTMORE TOWERS BY WCHD; TANK SYSTEM MUST BE REPAIRED OR REMOVED. 08/05/03 ALSO SEE SPILLS 02-9355 AND 02-11185. 12/05/03 CLOSED BY BARBARA McDONALD OF WCHD."
Remarks:	"CALLER STATES A FAILED TANK TEST FAILED ON LIQUID PORTION OF THE TEST NO RELEASE 2.58840 LEAK GAIN"

All TTF:

Facility ID:	9905417
Spill Number:	9905417
Spill Tank Test:	1547452
Site ID:	149672
Tank Number:	1
Tank Size:	15000
Material:	0002
EPA UST:	Not reported

BILTMORE TOWERS APTS (Continued) **S109416253**

UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	149672
Operable Unit ID:	1079853
Operable Unit:	01
Material ID:	301712
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0811148 / 2009-04-14
Facility ID:	0811148
Site ID:	408703
Spill Date:	2009-01-08
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2009-01-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-01-08
Spill Record Last Update:	2009-04-14
Spiller Name:	LARRY NEWMAN
Spiller Company:	CONDO COMPLEX
Spiller Address:	30 LAKE ST
Spiller County:	999
Spiller Contact:	LARRY NEWMAN
Spiller Phone:	(914) 337-1312
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	357952
DEC Memo:	"1/8/09 left message for Mr. Newman (ext 319). Waiting for callback.

BILTMORE TOWERS APTS (Continued) **S109416253**

Referred to WCHD PBS dw 04/14/09 W Schneider reported ttf 1-8-09. passing retest after fill, vent line replacement and fitting adj. NFA TG "

Remarks: "Caller states they performed a EZ-3 test and had a failure. No spill or resources affected."

All Materials:

Site ID:	408703
Operable Unit ID:	1165225
Operable Unit:	01
Material ID:	2156629
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Spill Number/Closed Date:	0209355 / 2003-10-29
Facility ID:	0209355
Facility Type:	ER
DER Facility ID:	127288
Site ID:	243794
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2002-12-11
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-12-11
CID:	390
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-12-11
Spill Record Last Update:	2003-12-17
Spiller Name:	UNK
Spiller Company:	UNK
Spiller Address:	30 LAKE ST
Spiller Company:	001
Contact Name:	UNK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MANCINI 12/11/02: CARLOS TORRES, WCHD, NOTIFIED. WCHD RESPONDING. 08/05/03 ALSO SEE SPILLS 99-05417 AND 02-11185. 10/29/03 CLOSED BY WCHD - NES COMPLETED CLEANUP"
Remarks:	"malfunction in a transfer pump caused spill"

BILTMORE TOWERS APTS (Continued) **S109416253**

All Materials:

Site ID:	243794
Operable Unit ID:	860731
Operable Unit:	01
Material ID:	516330
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0211185 / 2003-12-17
Facility ID:	0211185
Facility Type:	ER
DER Facility ID:	127288
Site ID:	243795
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2003-02-07
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-02-07
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-07
Spill Record Last Update:	2003-12-17
Spiller Name:	Not reported
Spiller Company:	HESS OIL
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JULIO - SUPER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/05/03 ALSO SEE SPILLS 99-05417 AND 02-09355."
Remarks:	"in the grass ifo building - the apartments order oil but their gadge is way off and they couldn't take as much oil as the requested - caller will get a contractor there for clean up"

All Materials:

Site ID:	243795
Operable Unit ID:	864358
Operable Unit:	01
Material ID:	514541
Material Code:	0002A

BILTMORE TOWERS APTS (Continued) **S109416253**

Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

477
WSW
1/2-1
0.506 mi.
2670 ft.

AUTOMOBILE CLUB OF NEW YORK
101 WESTMORELAND AVENUE
WHITE PLAINS, NY 10606

NY SHWS **S105057848**
NY ENG CONTROLS **N/A**
NY INST CONTROL
NY Spills

Relative:
Lower

Actual:
205 ft.

SHWS:

Program:	HW
Site Code:	374633
Classification:	C
Region:	3
Acres:	0.2
HW Code:	360095
Record Add:	12/08/2006
Record Upd:	07/18/2018
Updated By:	AMOMOROG

Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	02
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
HW Code:	Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

ENG CONTROLS:
Site Code: 374633
HW Code: 360095
Control Code: 15
Control Type: ENG
Date Record Added: 10/15/2015
Date Rec Updated: 06/06/2018
Updated By: KRKEARNE
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	02
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
HW Code:	Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	D3-0504-06-09
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2015-05-04 15:12:00
Record Updated:	2015-05-04 15:12:00
Updated By:	JLVERRIG
Crossref ID:	563023198
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	2017-07-14 08:08:00
Record Updated:	2017-07-14 08:08:00
Updated By:	JLVERRIG
Site Code:	374633
HW Code:	360095
Control Code:	35
Control Type:	ENG
Date Record Added:	10/15/2015
Date Rec Updated:	06/06/2018
Updated By:	KRKEARNE
Site Description:	Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem:	Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply.

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	02
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

INST CONTROL:
Site Code: 374633
Control Name: IC/EC Plan
HW Code: 360095
Control Code: 34
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials.

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: O&M Plan
HW Code: 360095
Control Code: 33
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Soil Management Plan
HW Code: 360095
Control Code: 14
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Environmental Easement
HW Code: 360095
Control Code: J
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Ground Water Use Restriction
HW Code: 360095
Control Code: 08
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

	soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator
Sub Type:	02
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Monitoring Plan
HW Code: 360095
Control Code: 31
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02
Owner Name: Jack Byrnes

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Landuse Restriction
HW Code: 360095
Control Code: 25
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: On-Site Operator
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: Owner
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: Applicant/Requestor
Sub Type: 01
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: On-Site Operator
Sub Type: 02

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

Site Code: 374633
Control Name: Site Management Plan
HW Code: 360095
Control Code: 32
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 06/06/2018
Updated By: KRKEARNE
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

	petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	On-Site Operator
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	Owner
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	Applicant/Requestor
Sub Type:	01
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	On-Site Operator

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Sub Type: 02
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 2015-05-04 15:12:00
Record Updated: 2015-05-04 15:12:00
Updated By: JLVERRIG
Crossref ID: 563023198
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 2017-07-14 08:08:00
Record Updated: 2017-07-14 08:08:00
Updated By: JLVERRIG

SPILLS:
Spill Number/Closed Date: 0102386 / 2005-03-22
Facility ID: 0102386
Facility Type: ER
DER Facility ID: 100883
Site ID: 276229
DEC Region: 3
Spill Cause: Unknown
Spill Class: B3
SWIS: 6017
Spill Date: 2001-06-02
Investigator: jkomara
Referred To: Not reported
Reported to Dept: 2001-06-02
CID: 281
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2001-06-02
Spill Record Last Update: 2005-03-23
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller Company: 001
Contact Name: BILLY MCBRIDE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 12/04/2001 LETTER SENT TO AUTOMOBILE CLUB BY B. MCDONALD

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

(WCDOH); LAB REPORT INDICAATES GW HAS BEEN IMPACTED. BASED ON RESULTS OF ADDITIONAL SAMPLING PERIODS, FURTHER ACTION MAY BE REQUIRED. 04-24-02 LETTER FROM B MCDONALD SENT TO AUTO CLUB STATING THAT GW SAMPLES EXCEED STATE GUIDELINES. REPORT SENT TO O'MARA FOR REVIEW BY DEC. 3/22/05 minimal petroleum contamination; various solvents up to approx 140ppm--close and refer to haz sites"

Remarks: "SUSPECTED TANK FAILURE AT ABOVE LOCATION. #2 FUEL OIL IS A 550 GALLON UNDERGROUND TANK. WASTE OIL IS A 250 GALLON UNDERGROUND TANK. TANKS HAVE BEEN REMOVED AND EXCAVATION IS UNDERWAY AT SITE."

All Materials:

Site ID:	276229
Operable Unit ID:	839144
Operable Unit:	01
Material ID:	534501
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	276229
Operable Unit ID:	839144
Operable Unit:	01
Material ID:	534502
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Spill Number/Closed Date:	0300596 / 2003-07-09
Facility ID:	0300596
Facility Type:	ER
DER Facility ID:	100883
Site ID:	115839
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6017
Spill Date:	2003-02-15
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	2003-04-16
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-16
Spill Record Last Update:	2007-03-06
Spiller Name:	Not reported
Spiller Company:	RJT MOTORS
Spiller Address:	101 WESTMORELAND AV
Spiller Company:	001
Contact Name:	CHUCK BUTTERSWORTH
DEC Memo:	""
Remarks:	"CALLER STATES HE WAS HIRED BY THE TRUCKING COMPANY'S INSURANCE COMPANY TO CLEAN UP THE AREA OF A TRUCK FIRE THAT OCCURED IN FEBRUARY - CALLER STATED THE FUEL TANK RUPTURED DURING THE FIRE AND IT WAS NOT NOTICED UNTIL THE SNOW MELTED"

All Materials:

Site ID:	115839
Operable Unit ID:	866954
Operable Unit:	01
Material ID:	508676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

478 **MAMARONECK AVENUE DRY CLEANERS** **NY SHWS S106970795**
SSE **359-369 MAMARONECK AVENUE** **NY Spills N/A**
1/2-1 **WHITE PLAINS, NY 10605**
0.539 mi.
2847 ft.

Relative: Higher

Actual: 235 ft.

SHWS:

Program:	HW
Site Code:	387008
Classification:	N
Region:	3
Acres:	0.25
HW Code:	360102
Record Add:	09/10/2007
Record Upd:	08/28/2012
Updated By:	RXKEATIN

Site Description: Location Description: The site is located at 359-369 Mamaroneck Avenue in a mixed use commercial and residential area in the southern part of the City of White Plains, Westchester County NY. Site Features: The site is on approximately 0.25 acres of land which is flat and contains a 6,763 square foot building with a full basement. Current Use: The building contains a drycleaner, a nail salon, an insurance agency, and two restaurants. The remainder of the site consists of a paved parking lot. Surrounding Use: The site is surrounded with businesses to the north and south of the site and residences to the east and west. Immediately to the east of the site is a municipal parking lot. Historical Sources of Contamination: Dry

MAMARONECK AVENUE DRY CLEANERS (Continued) **S106970795**

cleaner operated at this location is a potential source of PCE contamination. Site Hydrology: Groundwater flows though sand at only several feet below ground surface.

Env Problem: Based upon investigations to date, the primary contaminants of concern at the site included tetrachloroetylene (PCE) and its associated breakdown products. After a thorough Site Characterization, as described in a final report dated July 2012, it was determined that this site did not qualify for the registry.

Health Problem: Not reported
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: Not reported
Sub Type: Not reported
Owner Name: Not reported
Owner Company: Not reported
Owner Address: Not reported
Owner Addr2: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

SPILLS:

Spill Number/Closed Date: 0505152 / 2005-10-04
Facility ID: 0505152
Facility Type: ER
DER Facility ID: 296563
Site ID: 350119
DEC Region: 3
Spill Cause: Other
Spill Class: B3
SWIS: 6017
Spill Date: 2005-07-28
Investigator: TDGHIOSA
Referred To: DIV OF HAZWASTE
Reported to Dept: 2005-07-28
CID: 444
Water Affected: Not reported
Spill Source: Commercial/Industrial

MAMARONECK AVENUE DRY CLEANERS (Continued) **S106970795**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2006-09-12
Spiller Name:	ERIC HARVEY
Spiller Company:	BUSINESS
Spiller Address:	359-369 MARNAMEK AVE
Spiller Company:	001
Contact Name:	ERIC HARVEY
DEC Memo:	"08/23/05 Groundwater & Environmental Services, Inc. submitted a subsurface investigation report that documented the presence of chlorinated solvents at a dry cleaner. GES report forwarded to Paul John for a referral to Haz Waste Remediation. NFA by Spills. TG 09/01/06 Quarterly monitoring report for July to September 2006 submitted by GES. Sent to Paul John to forward to Haz Remediation. TG"
	Not reported
Remarks:	"FOUND CONTAMINATION IN SOIL WHILE DOING SOIL BORINGS:"

Count: 5 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
HARRISON	S108925392	FORMER DPW STAGING AREA	OLD LAKE STREET	10604	NY VCP
HARRISON	S108925402	FORMER HANGAR B SEPTIC FIELD	WESTCHESTER CO. AIRPORT (OLD K	10604	NY VCP
SCARSDALE	S104191508	COMMERCIAL PROPERTY	247 CENTRAL PARK AVE		NY LTANKS
SCARSDALE	S118263554	FORECLOSED - TTF	949 POST RD		NY LTANKS
WHITE PLAINS	S112810201	HART RESIDENCE	77 PARK AVE		NY LTANKS

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 02/06/2019
Date Data Arrived at EDR: 02/15/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 28

Source: EPA
Telephone: N/A
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 02/06/2019
Date Data Arrived at EDR: 02/15/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 28

Source: EPA
Telephone: N/A
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 02/06/2019
Date Data Arrived at EDR: 02/15/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 28

Source: EPA
Telephone: N/A
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/06/2019
Date Data Arrived at EDR: 02/15/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 28

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 02/06/2019
Date Data Arrived at EDR: 02/15/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 28

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 10/25/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 43

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 02/07/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 01/31/2019
Date Data Arrived at EDR: 02/04/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/04/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 01/31/2019
Date Data Arrived at EDR: 02/04/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 02/04/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 02/04/2019
Date Data Arrived at EDR: 02/08/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 28

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/26/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 01/04/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-457-2051
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 03/05/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63
Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 36
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 05/15/2017
Date Data Arrived at EDR: 05/30/2017
Date Made Active in Reports: 10/13/2017
Number of Days to Update: 136

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 03/25/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 3

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 3

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 2

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 3

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/01/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/24/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/12/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/25/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/10/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/13/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 05/08/2018
Date Data Arrived at EDR: 05/18/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 63

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 03/05/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing
This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 2
Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations
The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 10/17/2018
Date Data Arrived at EDR: 12/19/2018
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 57
Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 03/19/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing
A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010
Date Data Arrived at EDR: 06/30/2014
Date Made Active in Reports: 07/21/2014
Number of Days to Update: 21
Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 03/22/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls
Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls
Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35
Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

VCP NYC: Voluntary Cleanup Program Listing NYC
New York City voluntary cleanup program sites.

Date of Government Version: 12/14/2018
Date Data Arrived at EDR: 12/19/2018
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 56

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 03/18/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Semi-Annually

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/25/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Varies

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Quarterly

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/17/2018
Date Data Arrived at EDR: 12/18/2018
Date Made Active in Reports: 01/11/2019
Number of Days to Update: 24

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/19/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 01/04/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-8705
Last EDR Contact: 01/04/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 03/11/2019
Next Scheduled EDR Contact: 06/24/2019
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 01/29/2019
Next Scheduled EDR Contact: 05/13/2019
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 01/17/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 02/01/2019
Next Scheduled EDR Contact: 05/13/2019
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/21/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/19/2018
Number of Days to Update: 35

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/21/2018
Date Data Arrived at EDR: 09/21/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 49

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/21/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 09/01/2016
Date Data Arrived at EDR: 02/08/2019
Date Made Active in Reports: 03/22/2019
Number of Days to Update: 42

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 02/08/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

SUFFOLK CO TANKS: Storage Tank Database
Facilities that have no tank information

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/13/2019
Data Release Frequency: Varies

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 02/04/2019
Date Data Arrived at EDR: 02/07/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 7

Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 02/04/2019
Next Scheduled EDR Contact: 05/20/2019
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 03/11/2019
Date Data Arrived at EDR: 03/14/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 02/08/2019
Date Data Arrived at EDR: 02/08/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 41

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/26/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 11/12/2018
Date Data Arrived at EDR: 11/14/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 36

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 03/01/2018
Date Data Arrived at EDR: 03/28/2018
Date Made Active in Reports: 06/22/2018
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 03/27/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 03/20/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 01/11/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 02/06/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 339

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 01/11/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 02/15/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 01/31/2019
Date Data Arrived at EDR: 02/04/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 32

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 03/26/2019
Next Scheduled EDR Contact: 07/08/2019
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 02/08/2019
Next Scheduled EDR Contact: 05/20/2019
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 02/08/2019
Next Scheduled EDR Contact: 05/20/2019
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/21/2017
Date Made Active in Reports: 01/05/2018
Number of Days to Update: 198

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/22/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 01/10/2018
Date Made Active in Reports: 01/12/2018
Number of Days to Update: 2

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 02/20/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 03/25/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/12/2018
Date Data Arrived at EDR: 12/28/2018
Date Made Active in Reports: 01/11/2019
Number of Days to Update: 14

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 02/01/2019
Date Data Arrived at EDR: 02/14/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 01/22/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 08/13/2018
Date Data Arrived at EDR: 10/04/2018
Date Made Active in Reports: 11/09/2018
Number of Days to Update: 36

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 05/20/2019
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 09/14/2018
Date Data Arrived at EDR: 10/11/2018
Date Made Active in Reports: 12/07/2018
Number of Days to Update: 57

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 01/11/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Quarterly

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: Quarterly

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 01/22/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 03/07/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 03/05/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 05/24/2017
Date Data Arrived at EDR: 11/30/2017
Date Made Active in Reports: 12/15/2017
Number of Days to Update: 15
Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 01/25/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/02/2019
Date Data Arrived at EDR: 01/03/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 71
Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 01/03/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing
A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing
A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40
Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data
Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 12/03/2018
Date Data Arrived at EDR: 01/29/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 51
Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 01/29/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees
Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 02/11/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 38

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 09/28/2017
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 01/31/2019
Next Scheduled EDR Contact: 05/20/2019
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 06/23/2017
Date Data Arrived at EDR: 10/11/2017
Date Made Active in Reports: 11/03/2017
Number of Days to Update: 23

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 02/22/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 03/11/2019
Date Data Arrived at EDR: 03/14/2019
Date Made Active in Reports: 03/21/2019
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 03/14/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/01/2018
Date Data Arrived at EDR: 08/29/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 37

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 02/27/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/01/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 03/01/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 09/10/2018
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 03/21/2019
Next Scheduled EDR Contact: 06/24/2019
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 02/15/2019
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 03/15/2019
Number of Days to Update: 10

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 03/05/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 06/19/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 87

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 01/14/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 03/01/2019
Next Scheduled EDR Contact: 06/10/2019
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 09/02/2018
Date Data Arrived at EDR: 09/05/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 9

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 03/05/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/22/2018
Date Data Arrived at EDR: 08/22/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 44

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 02/21/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Quarterly

AIRS: Air Emissions Data
Point source emissions inventory data.

Date of Government Version: 01/22/2019
Date Data Arrived at EDR: 02/01/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 13

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 01/22/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 01/04/2019
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 40

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 12/27/2018
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 03/07/2018
Date Data Arrived at EDR: 03/30/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 67

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 03/11/2019
Next Scheduled EDR Contact: 06/24/2019
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 10/31/2018
Date Data Arrived at EDR: 12/19/2018
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 56

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 03/19/2019
Next Scheduled EDR Contact: 07/01/2019
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 01/15/2019
Date Data Arrived at EDR: 01/17/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 28

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 01/14/2019
Next Scheduled EDR Contact: 04/15/2019
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 12/29/2017
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/05/2018
Number of Days to Update: 60

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 03/11/2019
Next Scheduled EDR Contact: 06/24/2019
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 01/30/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 15

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 01/30/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 01/30/2019
Date Data Arrived at EDR: 02/07/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 7

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 01/22/2019
Next Scheduled EDR Contact: 05/06/2019
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2018
Date Data Arrived at EDR: 02/15/2018
Date Made Active in Reports: 03/27/2018
Number of Days to Update: 40

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 02/13/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 12/03/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 12/20/2018
Number of Days to Update: 14

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 03/06/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 01/08/2019
Date Data Arrived at EDR: 01/16/2019
Date Made Active in Reports: 02/13/2019
Number of Days to Update: 28

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 01/16/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List
The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List
The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing
A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 11/16/2018
Date Data Arrived at EDR: 11/16/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 32

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing
A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 11/16/2018
Date Data Arrived at EDR: 11/16/2018
Date Made Active in Reports: 12/18/2018
Number of Days to Update: 32

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database
A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/04/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189

Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 03/04/2019
Next Scheduled EDR Contact: 06/17/2019
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: No Update Planned

UST - SUFFOLK: Storage Tank Database
A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks
A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 01/02/2019
Date Data Arrived at EDR: 02/08/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 6

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks
A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 01/02/2019
Date Data Arrived at EDR: 02/08/2019
Date Made Active in Reports: 02/14/2019
Number of Days to Update: 6

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 01/28/2019
Next Scheduled EDR Contact: 05/11/2019
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 02/11/2019
Date Data Arrived at EDR: 02/12/2019
Date Made Active in Reports: 03/04/2019
Number of Days to Update: 20

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 02/12/2019
Next Scheduled EDR Contact: 05/27/2019
Data Release Frequency: No Update Planned

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 07/13/2018
Date Made Active in Reports: 08/01/2018
Number of Days to Update: 19

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 01/07/2019
Next Scheduled EDR Contact: 04/22/2019
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 10/23/2018
Date Made Active in Reports: 11/27/2018
Number of Days to Update: 35

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 01/11/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 02/23/2018
Date Made Active in Reports: 04/09/2018
Number of Days to Update: 45

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 02/19/2019
Next Scheduled EDR Contact: 06/03/2019
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 01/17/2019
Date Made Active in Reports: 02/19/2019
Number of Days to Update: 33

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 01/14/2019
Next Scheduled EDR Contact: 04/29/2019
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/15/2018
Date Made Active in Reports: 07/09/2018
Number of Days to Update: 24

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 03/11/2019
Next Scheduled EDR Contact: 06/24/2019
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

MACYS WHITE PLAINS GALLERIA
100 MAIN STREET
WHITE PLAINS, NY 10601

TARGET PROPERTY COORDINATES

Latitude (North):	41.031696 - 41° 1' 54.11''
Longitude (West):	73.768216 - 73° 46' 5.58''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	603549.2
UTM Y (Meters):	4542794.5
Elevation:	211 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5939761 WHITE PLAINS, NY
Version Date:	2013
Northeast Map:	5641951 GLENVILLE, CT
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General WNW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 211 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36119C0267F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
36119C0266F	FEMA FIRM Flood data
36119C0286F	FEMA FIRM Flood data
36119C0268F	FEMA FIRM Flood data
36119C0269F	FEMA FIRM Flood data
36119C0288F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
WHITE PLAINS	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY


Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT **GEOLOGIC AGE IDENTIFICATION**

Era:	Paleozoic	Category:	Stratified Sequence
System:	Ordovicias		
Series:	Lower Ordovician and Cambrian carbonate rocks		
Code:	OC *(decoded above as Era, System & Series)*		

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 5604205.2s



Target Property
SSURGO Soil
Water

0 1/16 1/8 1/4 Miles

N

SITE NAME:	Macys White Plains Galleria	CLIENT:	ATC Group Services LLC
ADDRESS:	100 Main Street White Plains NY 10601	CONTACT:	Chelsea Helm
		INQUIRY #:	5604205.2s
LAT/LONG:	41.031696 / 73.768216	DATE:	March 28, 2019 2:43 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Udorthents

Soil Surface Texture: gravelly loam

Hydrologic Group: Not reported

Soil Drainage Class: Moderately well drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 127 inches

Depth to Watertable Min: > 84 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	3 inches	gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5
2	3 inches	70 inches	very gravelly loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Silty Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 42 Min: 0.42	Max: 8.4 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000837292	0 - 1/8 Mile SE
2	USGS40000837302	1/8 - 1/4 Mile ENE
3	USGS40000839114	1/8 - 1/4 Mile ESE
4	USGS40000837264	1/8 - 1/4 Mile South
A5	USGS40000837317	1/8 - 1/4 Mile NNW
A6	USGS40000837318	1/8 - 1/4 Mile NNW
7	USGS40000837283	1/8 - 1/4 Mile ESE
B8	USGS40000837305	1/4 - 1/2 Mile WNW
B9	USGS40000837306	1/4 - 1/2 Mile WNW
10	USGS40000837246	1/4 - 1/2 Mile South
11	USGS40000837239	1/4 - 1/2 Mile South

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
12	USGS40000837243	1/4 - 1/2 Mile SE
13	USGS40000837255	1/2 - 1 Mile WSW
14	USGS40000837237	1/2 - 1 Mile SE
15	USGS40000837368	1/2 - 1 Mile NNE
16	USGS40000837244	1/2 - 1 Mile SW
17	USGS40000837362	1/2 - 1 Mile NE
C18	USGS40000837260	1/2 - 1 Mile ESE
C19	USGS40000837261	1/2 - 1 Mile ESE
20	USGS40000837348	1/2 - 1 Mile ENE
21	USGS40000837356	1/2 - 1 Mile NW
22	USGS40000837349	1/2 - 1 Mile ENE
D23	USGS40000837338	1/2 - 1 Mile ENE
D24	USGS40000837339	1/2 - 1 Mile ENE
25	USGS40000837312	1/2 - 1 Mile West

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG90000040376	1/2 - 1 Mile NW
2	NYOG90000040377	1/2 - 1 Mile East

PHYSICAL SETTING SOURCE MAP - 5604205.2s



County Boundary
Major Roads
Contour Lines
Earthquake epicenter, Richter 5 or greater
Water Wells
Public Water Supply Wells
Cluster of Multiple Icons

0 1/4 1/2 1 Miles

Groundwater Flow Direction
Indeterminate Groundwater Flow at Location
Groundwater Flow Varies at Location
Closest Hydrogeological Data
Oil, gas or related wells

N

SITE NAME:	Macys White Plains Galleria	CLIENT:	ATC Group Services LLC
ADDRESS:	100 Main Street White Plains NY 10601	CONTACT:	Chelsea Helm
		INQUIRY #:	5604205.2s
LAT/LONG:	41.031696 / 73.768216	DATE:	March 28, 2019 2:43 pm

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
SE
0 - 1/8 Mile
Higher

FED USGS **USGS40000837292**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 4	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	1912
Well Depth:	203	Well Depth Units:	ft
Well Hole Depth:	203.1	Well Hole Depth Units:	ft

2
ENE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000837302**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 161	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	225	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

3
ESE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000839114**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 119	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	350	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

4
South
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000837264**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 96	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	725	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

A5
NNW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000837317**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 87	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	700	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

A6
NNW
1/8 - 1/4 Mile
Lower

FED USGS **USGS40000837318**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 88	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	250	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

7
ESE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000837283**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 118	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	108	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B8
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000837305**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 121	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	310	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

B9
WNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000837306**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 123	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	300	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

10
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837246**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 95	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	495	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

11
South
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837239**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 94	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	302	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

12
SE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837243**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 305	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	484	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

13
WSW
1/2 - 1 Mile
Lower

FED USGS **USGS40000837255**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 133	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	500	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

14
SE
1/2 - 1 Mile
Higher

FED USGS **USGS40000837237**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 120	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	200	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

15
NNE
1/2 - 1 Mile
Higher

FED USGS **USGS40000837368**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 91	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	350	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

16
SW
1/2 - 1 Mile
Higher

FED USGS **USGS40000837244**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE1064	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	508	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

17
NE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837362**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 92	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	332	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

C18
ESE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837260**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 200	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	22
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

C19
ESE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837261**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 220	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	40
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

20
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837348**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 93	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	250	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

21
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000837356**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE1379	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

22
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837349**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE1407	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	298	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

D23
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837338**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 89	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	52
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

D24
ENE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837339**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 90	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	60
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

25
West
1/2 - 1 Mile
Lower

FED USGS **USGS40000837312**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 586	Type:	Well

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	102	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
NW
1/2 - 1 Mile

OIL_GAS **NYOG90000040376**

API Well #:	31119236850000	Well Name:	KCT B-4
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Type:	Stratigraphic
Well Status:	Plugged and Abandoned	Permit Date:	0
Drill Date:	0	Completion Date:	2006 913
Plug Date:	0	Field Name:	Not Applicable
Formation:	Fordham Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	700
True Depth:	560	Measured Length:	560

2
East
1/2 - 1 Mile

OIL_GAS **NYOG90000040377**

API Well #:	31119236860000	Well Name:	KCT B-5
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Type:	Stratigraphic
Well Status:	Plugged and Abandoned	Permit Date:	0
Drill Date:	0	Completion Date:	2006 921
Plug Date:	0	Field Name:	Not Applicable
Formation:	Yonkers Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	700
True Depth:	530	Measured Length:	530

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix F

Aerial Photographs

Macys White Plains Galleria

100 Main Street

White Plains, NY 10601

Inquiry Number: 5604205.11

March 28, 2019

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

03/28/19

Site Name:

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601
EDR Inquiry # 5604205.11

Client Name:

ATC Group Services LLC
104 East 25th Street
New York, NY 10010
Contact: Chelsea Helm

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	*Scale*	*Details*	*Source*
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 20, 1994	USGS/DOQQ
1991	1"=500'	Flight Date: April 03, 1991	USGS
1989	1"=750'	Flight Date: April 20, 1989	NYDOT
1985	1"=500'	Flight Date: March 16, 1985	USDA
1974	1"=500'	Flight Date: October 24, 1974	USDA
1971	1"=500'	Flight Date: April 24, 1971	USGS
1964	1"=500'	Flight Date: March 23, 1964	USGS
1962	1"=500'	Flight Date: January 16, 1962	EDR Proprietary Aerial Viewpoint
1958	1"=500'	Flight Date: August 05, 1958	USGS
1953	1"=500'	Flight Date: December 17, 1953	USGS
1949	1"=500'	Flight Date: March 14, 1949	USGS
1941	1"=500'	Flight Date: October 06, 1941	USGS

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.




INQUIRY #: 5604205.11

YEAR: 2017

= 500'

N

EDR



INQUIRY #: 5604205.11

YEAR: 2013

= 500'

N

EDR



INQUIRY #: 5604205.11


YEAR: 2009

= 500'

N

EDR


INQUIRY #: 5604205.11
YEAR: 2006
= 500'
N
EDR



INQUIRY #: 5604205.11

YEAR: 1994

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.



INQUIRY #: 5604205.11

YEAR: 1991


= 500'

N

EDR


INQUIRY #: 5604205.11
YEAR: 1989
= 750'
N
EDR
Subject boundary not shown because it exceeds image extent or image is not georeferenced.


INQUIRY #: 5604205.11
YEAR: 1985
= 500'
N
EDR



INQUIRY #: 5604205.11

YEAR: 1974

= 500'

N

EDR




INQUIRY #: 5604205.11

YEAR: 1971

= 500'

N

EDR




INQUIRY #: 5604205.11

YEAR: 1964

= 500'

N

EDR




INQUIRY #: 5604205.11

YEAR: 1962

= 500'

N

EDR



INQUIRY #: 5604205.11

YEAR: 1958

= 500'

N

EDR




INQUIRY #: 5604205.11

YEAR: 1953

= 500'

N

EDR



INQUIRY #: 5604205.11

YEAR: 1949

= 500'

N

EDR


INQUIRY #: 5604205.11
YEAR: 1941
= 500'
N
EDR

Appendix G

Historical Research Documentation

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.6
March 28, 2019

The EDR Property Tax Map Report

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

EDR Property Tax Map Report

Environmental Data Resources, Inc.'s EDR Property Tax Map Report is designed to assist environmental professionals in evaluating potential environmental conditions on a target property by understanding property boundaries and other characteristics. The report includes a search of available property tax maps, which include information on boundaries for the target property and neighboring properties, addresses, parcel identification numbers, as well as other data typically used in property location and identification.

NO COVERAGE

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.8
March 28, 2019

EDR Building Permit Report

Target Property and Adjoining Properties

Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

About This Report

Executive Summary

Findings

Glossary

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR BUILDING PERMIT REPORT

About This Report

The EDR Building Permit Report provides a practical and efficient method to search building department records for indications of environmental conditions. Generated via a search of municipal building permit records gathered from more than 1,600 cities nationwide, this report will assist you in meeting the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

Building permit data can be used to identify current and/or former operations and structures/features of environmental concern. The data can provide information on a target property and adjoining properties such as the presence of underground storage tanks, pump islands, sumps, drywells, etc., as well as information regarding water, sewer, natural gas, electrical connection dates, and current/former septic tanks.

ASTM and EPA Requirements

ASTM E 1527-13 lists building department records as a "standard historical source," as detailed in § 8.3.4.7: "Building Department Records - The term building department records means those records of the local government in which the property is located indicating permission of the local government to construct, alter, or demolish improvements on the property." ASTM also states that "Uses in the area surrounding the property shall be identified in the report, but this task is required only to the extent that this information is revealed in the course of researching the property itself."

EPA's Standards and Practices for All Appropriate Inquires (AAI) states: "§312.24: Reviews of historical sources of information. (a) Historical documents and records must be reviewed for the purposes of achieving the objectives and performance factors of §312.20(e) and (f). Historical documents and records may include, but are not limited to, aerial photographs, fire insurance maps, building department records, chain of title documents, and land use records."

Methodology

EDR has developed the EDR Building Permit Report through our partnership with BuildFax, the nation's largest repository of building department records. BuildFax collects, updates, and manages building department records from local municipal governments. The database now includes 30 million permits, on more than 10 million properties across 1,600 cities in the United States.

The EDR Building Permit Report comprises local municipal building permit records, gathered directly from local jurisdictions, including both target property and adjoining properties. Years of coverage vary by municipality. Data reported includes (where available): date of permit, permit type, permit number, status, valuation, contractor company, contractor name, and description.

Incoming permit data is checked at seven stages in a regimented quality control process, from initial data source interview, to data preparation, through final auditing. To ensure the building department is accurate, each of the seven quality control stages contains, on average, 15 additional quality checks, resulting in a process of approximately 105 quality control "touch points."

For more information about the EDR Building Permit Report, please contact your EDR Account Executive at (800) 352-0050.

EDR® Environmental Data Resources Inc

BUILDFAX® PROPERTY HISTORY

EXECUTIVE SUMMARY: SEARCH DOCUMENTATION

A search of building department records was conducted by Environmental Data Resources, Inc (EDR) on behalf of ATC Group Services LLC on Mar 28, 2019.

TARGET PROPERTY

100 Main Street
White Plains, NY 10601

SEARCH METHODS

EDR searches available lists for both the Target Property and Surrounding Properties.

RESEARCH SUMMARY

Building permits identified: **NO PERMITS IDENTIFIED**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

Name: JurisdictionName
Years: Years
Source: Source
Phone: Phone

BUILDING DEPARTMENT RECORDS SEARCHED

Name: Greenburgh town
Years: 1972-2012
Source: Town of Greenburgh, Building Department, WHITE PLAINS, NY
Phone: 914-993-1562

TARGET PROPERTY FINDINGS

TARGET PROPERTY DETAIL

100 Main Street
White Plains, NY 10601

No Permits Found

ADJOINING PROPERTY FINDINGS

ADJOINING PROPERTY DETAIL

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

No Permits Found

GLOSSARY

General Building Department concepts

- **ICC:** The International Code Council. The governing body for the building/development codes used by all jurisdictions who've adopted the ICC guidelines. MOST of the US has done this. Canada, Mexico, and other countries use ICC codes books and guides as well. There are a few states who have added guidelines to the ICC codes to better fit their needs. For example, California has added seismic retrofit requirements for most commercial structures.
- **Building Department (Permitting Authority, Building Codes, Inspections Department, Building and Inspections):** This is the department in a jurisdiction where an owner or contractor goes to obtain permits and inspections for building, tearing down, remodeling, adding to, re-roofing, moving or otherwise making changes to any structure, Residential or Commercial.
- **Jurisdiction:** This is the geographic area representing the properties over which a Permitting Authority has responsibility.
- **GC:** General Contractor. Usually the primary contractor hired for any Residential or Commercial construction work.
- **Sub:** Subordinate contracting companies or subcontractors. Usually a "trades" contractor working for the GC. These contractors generally have an area of expertise in which they are licensed like Plumbing, Electrical, Heating and Air systems, Gas Systems, Pools etc. (called "trades").
- **Journeymen:** Sub contractors who have their own personal licenses in one or more trades and work for different contracting companies, wherever they are needed or there is work.
- **HVAC (Mechanical, Heating & Air companies):** HVAC = Heating, Ventilation, and Air Conditioning.
- **ELEC (Electrical, TempPole, TPole, TPower, Temporary Power, Panel, AMP Change, Power Release):** Electrical permits can be pulled for many reasons. The most common reason is to increase the AMPs of power in an electrical power panel. This requires a permit in almost every jurisdiction. Other commons reason for Electrical permits is to insert a temporary power pole at a new construction site. Construction requires electricity, and in a new development, power has yet to be run to the lot. The temporary power pole is usually the very first permit pulled for new development. The power is released to the home owner when construction is complete and this sometimes takes the form of a Power Release permit or inspection.
- **"Pull" a permit:** To obtain and pay for a building permit.
- **CBO:** Chief Building Official
- **Planning Department:** The department in the development process where the building /structural plans are reviewed for their completeness and compliance with building codes
- **Zoning Department:** The department in the development process where the site plans are reviewed for their compliance with the regulations associated with the zoning district in which they are situated.
- **Zoning District:** A pre-determined geographic boundary within a jurisdiction where certain types of structures are permitted / prohibited. Examples are Residential structure, Commercial/Retail structures, Industrial/Manufacturing structures etc. Each zoning district has regulations associated with it like the sizes of the lots, the density of the structures on the lots, the number of parking spaces required for certain types of structures on the lots etc.
- **PIN (TMS, GIS ID, Parcel#):** Property Identification Number and Tax Map System number.
- **State Card (Business license):** A license card issued to a contractor to conduct business.
- **Building Inspector (Inspector):** The inspector is a building department employee that inspects building construction for compliance to codes.
- **C.O.:** Certificate of Occupancy. This is the end of the construction process and designates that the owners now have permission to occupy a structure after its building is complete. Sometimes also referred to as a Certificate of Compliance.

GLOSSARY

Permit Content Definitions

- Permit Number: The alphanumerical designation assigned to a permit for tracking within the building department system. Sometimes the permit number gives clues to its role, e.g. a "PL" prefix may designate a plumbing permit.
- Description: A field on the permit form that allows the building department to give a brief description of the work being done. More often than not, this is the most important field for EP's to find clues to the prior use(s) of the property.
- Permit Type: Generally a brief designation of the type of job being done. For example BLDG-RES, BLDG-COM, ELEC, MECH etc.

Sample Building Permit Data

Date: Nov 09, 2000
Permit Type: Bldg -
New Permit Number: 101000000405
Status: Valuation: $1,000,000.00
Contractor Company: OWNER-BUILDER
Contractor Name:

Description: New one store retail (SAV-ON) with drive-thru pharmacy. Certificate of Occupancy.

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.5
March 29, 2019

The EDR-City Directory Image Report

EDR® Environmental Data Resources Inc

6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY


DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.



RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2014	☑	☐	EDR Digital Archive
2010	☑	☐	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1987	☑	☐	Cole Criss-Cross Directory
1982	☑	☐	Cole Criss-Cross Directory
1977	☑	☐	Cole Criss-Cross Directory
1972	☑	☐	Cole Criss-Cross Directory

FINDINGS

TARGET PROPERTY STREET

100 Main Street
White Plains, NY 10601

Year	*CD Image*	*Source*
MAIN ST		
2014	pg A2	EDR Digital Archive
2010	pg A4	EDR Digital Archive
2005	pg A8	EDR Digital Archive
2000	pg A13	EDR Digital Archive
1995	pg A17	EDR Digital Archive
1992	pg A21	EDR Digital Archive
1987	pg A26	Cole Criss-Cross Directory
1987	pg A27	Cole Criss-Cross Directory
1982	pg A28	Cole Criss-Cross Directory
1977	pg A29	Cole Criss-Cross Directory
1977	pg A30	Cole Criss-Cross Directory
1972	pg A31	Cole Criss-Cross Directory

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2014

81	81 MAIN LLC
	AMINCO RESOURCES LLC
	DEL VECCHIO & PACOR
	HALLORAN SAGE LLP
	LAWOFFICES OF TIMOTHY A GREEN
	RIGIE LAWRENCE
	WARREN J ROTH ESQ
	WEINGARDEN MITCHELL LAW OFFS
	YOUNG DENNISON
100	A & J RELIABLE INC
	AK ACCESSORIES INC
	AMERICAN EAGLE OUTFITTERS INC
	ART OF BEAUTY
	AT&T CORP
	BOURBON ST CAFE
	C&C MARKET RESEARCH
	CF WHITE PLAINS ASSOCIATES
	CHARLOTTE RUSSE INC
	DOC POPCORN INC
	DOCTOR TOUSEXIS AND ASSOC
	FOOT LOCKER RETAIL INC
	GARAGE CLOTHING
	INTRIGUE JEWELERS
	LELIN ROSS
	MAC MACYS WHITE PLAINS
	MELDISCO-MCE 100 MAIN ST NY
	N & S FINE JEWLERS LLC
	NAILPORT SPA SALON
	NAME ON BUCKLE
	NNHH CONSULTING COMPANY INC
	PAYLESS SHOESOURCE INC
	REGIS CORPORATION
	SHAPE-UP
	SIMPLE GREEN NY INCORPORATED
	SOCIAL NY
	SOCK DRAWER INC
	TRAFFIC SHOE
	TROPICAL SMOOTHI
	WHITE PLINS GLLERIA FOOTACTION
	WHITE PLINS GLLERIA LTD PARTNR
111	A ELECTRIC INCORPORATED
	DIGITAL SATELLITE TV
	EXER FIX INCORPORATED
	HAYNES, SONIA
	MR CHIMNEY
119	SILVIA, SILVA
123	EMPIRE STATE DEVELOPMENT CORP
	INFORMATION SALES ASSOCIATES
	IRA LANGER PC
	LEARY, JOSEPH G

MAIN ST 2014 (Cont'd)

123	NEW YORK POWER AUTHORITY
	RAFFERT & REDLISKY
	STATE NEW YORK DEPARTMENT OF
127	QUINN, DONNA L
135	OCCUPANT UNKNOWN,
152	SERVICE, C
159	DERRICO JEWELRY
	GYU KAKU RESTAURANT
169	AMERICAN EXPRESS TRAVEL
171	LAST CALL NY INC
	VINTAGE BAR RESTAURANT
175	1-866-UNA AYUDA LTD
	BONANNO PAT
	CHILD PRTCTVE WORKERS OF WESTC
	CLASSIC CLG MAINTENANANCE LLC
	HUGHES 175 MAIN ST CORP
	JRJR CONSTRUCTION INC
	NANNAS CAFE
	PICKELLE PAUL W
	POHS MAX S CO
	RINALDI EDWARD J
	SOFRITO INC
	SOMERS SOCCER CLUB INC
	THANKACHAN GHEEVARGHESE
	TROTTERS NY REST GROUP LLC
185	KARAMBA CAFE CORP
187	MANHATTAN BAGEL COMPANY INC
	RITZ-CARLTON HOTEL COMPANY LLC
189	ABF DEVELOPMENT SERVICE CO
	TEFFT BUSINESS SCHL
199	80 APT ASSOC INC
	CARING HME COMPANIONS
	FRIENDSHIP PIZZA LLC
	FROG WORLDWIDE LTD LBLTY CO
	GOLDMAN, LISA
	HECKER LARRY D ATTORNEY AT LAW
	KELSEY COMPANY-NY
	KOLAJ, PAUL
	LEHRMAN STEPHEN J & ASSOCIATES
	MICROCRDITO DEL PCIFICO SA INC
	MIDELTON T GARY
	RANELLONE, STEVEN
	ROBINOWITZ, DUBOW
	RUBY DINER
	SUMMIT TRADING
	SWIFT PROCESS SERVERS INC
200	DUTAN, LUIS
	GREEN EARTH DESIGN CENTER INC
	STARBUCKS CORPORATION
	THOMAS, ROBERTO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2010

76	URRUTIA, ELIAS
80	PORCEL, CELESTE
81	81 MAIN LLC
	ALTA TECHNOLOGYINC
	AMINCO RESOURCES LLC
	ECKERT SMANS CHRIN MELLOTT LLC
	HEIDELL PTTONI MURPHY BACH LLP
	INDUSTRIAL PARTNERS LLC
	ITHACA FUNDING INC
	KAMLER & LEWIS
	LAWOFFICES OF TIMOTHY A GREEN
	LENURIT CORP
	LEON REIMER & CO
	LINCOLN FNCL GROUP WHITE PLINS
	PARK PLACE NEWROC PRPTS LLC
	RIGIE LAWRENCE
	ROACH, THOMAS
	ROBERT E MARTINEZ PLLC
	RUBIN MICHAEL A ATTY
	RUMBOLD & BRESS
	SCHWARTZAPEL SNOVICK
	SERVICE PROS INC
	SPECIALTY BAKERS LLC C/O STONE
	TROPODYNE CORP
	YOUNG DENNISON
100	A & J RELIABLE INC
	AEROPOSTALE INC
	AHK CHARLEYS INCORPORATED
	AK ACCESSORIES INC
	ART OF BEAUTY
	AUNTIE, A P
	BABYFACE STUDIO
	BIG EASY CAJUN AT GALLERIA
	BIJOU BIJOU
	BLOCK, H
	BOURBON ST CAFE
	BYS BRIDAL CO
	CHARLOTTE RUSSE INC
	DESTINATION MATERNITY CORP
	DOCTOR TOUSEXIS AND ASSOC
	ELEPHANT WIRELESS INC
	EOS RS INC
	EVAN DESIGNS
	FOOT LOCKER RETAIL INC
	GALLERIA PORTRAITS INC
	GIFT FOR SPORTS FANS
	ILS WAYPORT
	INTRIGUE JEWELERS
	JACKSON HEWITT TAX SERVICE
	JEWEL, HUT

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2010 (Cont'd)

100	JIN INTERNATIONAL BUSINESS
	KEEP IN TOUCH WIRELESS
	LANE, BRYANT
	LBDS FOODS
	MAGNIFIQUE PARFUMES COSMT INC
	MAIN STREET WATER EXTRACTION
	MELDISCO-MCE 100 MAIN ST NY
	MIRACLE-EAR INC
	NAILPORT SPA SALON
	NAME ON BUCKLE
	NEW DEAL LLC
	NUTTY BAVARIAN
	PAYLESS SHOESOURCE INC
	PEHLIVAN CORPORATION
	PETESAM INC
	PONTELLA
	R & R GALLERIA INC
	RAINBOW USA INC
	SIDS PANTS GREEN ACRES INC
	SOCK DRAWER INC
	THUNDER TECH
	TROPICAL SMOOTHI
	TY EYEWORKS INC A CORP
	VALENTI PERFUMERY
	VALENTI, P
	VBI ACCESSORIES
	WHITE PLINS GLLERIA FOOTACTION
	WIND SPIRIT
	WORLD PREMIERE LIMOUSINE
	XIOS
	Y2K OF WESTCHESTER INC
111	ADT AUTHORIZED SALES
	ALBERT LOCKERS INC
	CREDIT COUNSELING
	DIGITAL SATELLITE TV
	INDEPENDENT VENTURE COMMWL INC
	LAW OFFICES N RICHARD WOOL
	NICOLETTI FASHION DESIGN INC
	TELEVISION SERVICE PROVIDERS
	US POLICE K-9 ASSOCIATION
117	SHAH, DARSHAN
119	SILVIA, SILVA
123	BIRNBAUM, LINDA D
	BOROWICK, FELDMAN
	BUXTON GREGG
	BUXTON, GREGG
	CMS BANCORP INC
	COMMUNITY MUTUAL SAVINGS BANK
	EMPIRE STATE DEVELOPMENT CORP
	FEDERAL BAR CNCL AM INN OF CRT

MAIN ST 2010 (Cont'd)

123	FIORITO, HELENE
	GLEICHER ASSOCIATE
	GRANONE, VERONICA D
	HELLER, BRENDA L
	KELLMAN, NANCY D
	NEW YORK POWER AUTHORITY
	RAFFERT & REDLISKY
	STATE NEW YORK DEPARTMENT OF
125	OCCUPANT UNKNOWN,
152	SERVICE, C
159	DERRICO JEWELRY
161	JOHNSON, SCOTT A
169	AMERICAN EXPRESS TRAVEL
	J & K PRINTING ENTERPRISES
171	LAST CALL NY INC
	VINTAGE BAR RESTAURANT
173	FARAH CHANEL JEWELER INC
175	ABRA MEDIA INC
	ARI TOURS
	BOARDWALK HOLDING CORP
	BONA THOMAS M
	BONANNO PAT
	CHILD PRTCTVE WORKERS OF WESTC
	DARCY RUBBER CORP
	GLADSTONE DAVID M
	GOLDMAN & KLEINBAUM PC
	HUGHES 175 MAIN ST CORP
	LAW OFFICES ROBERT T BRACKMAN
	NANNAS CAFE
	NY AFFRDBLE RLBLE ELEC ALIANCE
	PICKELLE PAUL W
	RAPID PHOTO
	RINALDI EDWARD J
	SHOWGUN INC
	THANKACHAN GHEEVARGHESE
	TROTTERS NY REST GROUP LLC
	YAC AUTO INC
185	KARAMBA CAFE CORP
	LA COLMENA RESTAURANT CORP
187	A J EDIBLES INC
	MANHATTAN BAGEL COMPANY INC
	TARRYTOWN CAFE
189	ABF DEVELOPMENT SERVICE CO
	CTR FOR DRIVING WESTCHESTER
	KC UNLIMITED CORPORATION
	TEFFT BUSINESS SCHL
199	175 MEMORIAL HWY REALTY CORP
	199 MAIN STREET REALTY CORP
	80 APT ASSOC INC
	A&F HUGUENOT REALLY CORP

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2010 (Cont'd)

199	BERLIN PRODUCTIONS INC
	BLUESTONE REALTY ADVISORS INC
	DIGNITY HOME CARE
	EAGLE HARDWARE WHOLESALERS
	ELMSFORD FOOD CORP
	FIECH, STANO
	FRANWYN CONSTRUCTION CO INC
	GARGIULO PAUL G
	GLUCK GEORGE
	GLUCK, GEORGE
	GOLDMAN, LISA
	GOULD, RICHARD A
	GRECO, ALFRED
	HECKER LARRY D ATTORNEY AT LAW
	HILL LINDA M
	JBL SUPPLY INC
	KAAVA
	KELSEY COMPANY-NY
	KOLAJ, PAUL
	LAW OFFICE DAVID S KLAUSNER
	LEHRMAN STEPHEN J & ASSOCIATES
	LIBERTY TITLE AGENCY LLC
	MEGLINO, GARY L
	MICROCRDITO DEL PCIFICO SA INC
	MIDDELTON GARY MD
	MIDELTON T GARY
	NORSONS REALTY CORP
	NORTHERN NAILS INC
	OVERNIGHT FUNDING INC
	PANASCHE, PRIVEE
	PHILLIPS, STEVEN
	PINKER, BRUCE
	RABINOWITZ, SEYMOUR
	RANELLONE, STEVEN
	RUBYS EWR C 2LLC
	SALEHZADEH INC
	SAVILLE, DAVID A
	SWIFT PROCESS SERVERS INC
	VIA, Q
	WESTCHESTER TAXI CORP
	XCEED ENTERPRISES INC
200	STARBUCKS CORPORATION
	THOMAS, ROBERTO

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2005

81	1336 LLC
	240 KENT LLC
	FIELDS STEPHEN H AND ASSOC
	GOLDFARB & ABRANDT
	INDUSTRIAL PARTNERS LLC
	INVESTMENT BENEFITS SVC
	KAMLER & LEWIS
	LAWRENCE P BIONDI CO
	LENURIT CORP
	LEON REIMER & CO
	MCEVOY ANDREW T
	RODRIGUEZ HOLDING GROUP LLC
	SALIBELLO & BRODER
	STRUTT BARRY
	TOP DRAWER CONSTRUCTION GROUP
	TSL LIMOUSINE LLC
	WIILIAM P WEININGER
96	POUGHKEEPSIE FOOD ARTS INC
100	A & H OPTICAL INC
	A & J RELIABLE INC
	A DOLLAR 143
	AEROPOSTALE INC
	AGAINST ALL ODDS
	ALPS MANAGEMENT INC
	AMERICAN EAGLE OUTFITTERS INC
	ANNTAYLOR INC
	BANG BANG BOUTIQUES LLC
	BARBANDEE INC
	BELLEZA SALON & SHOP
	BIG EASY CAJUN AT GALLERIA
	BRADY, LILLIAN R
	BUNNIE TOWNE INC
	BYS BRIDAL CO
	CASUAL MALE RETAIL GROUP INC
	CHILDRENS PLACE RET STORES INC
	CLAIRES BOUTIQUES INC
	COHENS FASHION OPTICAL
	DANIEL LEE INDUSTRIES INC
	DASHING DIVA
	DEMO
	EXPRESS LLC
	FOOT LOCKER RETAIL INC
	GATSBY AT THE GALLERIA INC
	GIANOPOULOS TOM
	GYMBOREE CORPORATION
	H & M RETAIL CLOTHING
	H M FASHION ELEMENTS INC
	HOOP RETAIL STORES LLC
	HOT TOPIC INC
	INTRIGUE JEWELERS

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2005 (Cont'd)

100	J C COLLINS INC
	JAVS TELECOM
	JAVS TELECOM INC
	JEWEL HUT INC
	JIN INTERNATIONAL BUSINESS
	K B TOY OF NEW YORK INC
	KEEP IN TOUCH WIRELESS
	KLEIB SHOES INC
	LACHMANN, DORA
	LANE, BRYANT
	LANY BRYANT INC
	LEATHER BOUND LTD
	LENSCRAFTERS INC
	LIMITED STORES INC
	LIZ CLAIBORNE INC
	M&P QUALITY GOODS
	MASSAGE SENSATIONS INC
	MELDISCO-MCE 100 MAIN ST NY
	MGS WORLD
	MICHAEL MATTHEWS JEWELRY
	MOTHERS WORK INC
	MY KITCHEN
	NAILS & MORE BY DAWN LL INC
	NATURAL SCENTS & MORE INC
	NEWS CORNER
	NEXTEL COMMUNICATIONS INC
	NINE WEST FOOTWEAR CORPORATION
	NOAHS COLLECTORS GALLERY LLC
	NOT JUST TEES INC
	OLD NAVY INC
	ONMI INTERACTIVE
	ORIENTAL EXPRESS
	OVERTHECOUNTER SALES CORP
	PARTY BASKET ENTERPRISE INC
	PAYLESS SHOESOURCE INC
	PETESAM INC
	PRO ACTIV SKIN CARE
	R & R GALLERIA INC
	RAINBOW APPAREL 1179
	RD CANDY SHOP INC
	RETAIL BRAND ALLIANCE INC
	SALON AMERICAS INC
	SARKU JAPAN
	SBARRO INC
	SIDS PANTS GREEN ACRES INC
	SOCK DRAWER INC
	SPORTS STOP
	STITCH THIS
	SUNRISE PRETZEL INC
	THATS HOT INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2005 (Cont'd)

100	TOOTSIE
	TOOTSIES
	TT NAIL & SKIN CARE
	VALENTI PERFUMERY
	VICTORIAS SECRET STORES INC
	VIDEO BUTTON
	VIRGIN WIRELESS
	WATCH STOP
	WENDYS
	WHITE PLAINS CITY OF
	WHITE PLINS GLLERIA FOOTACTION
	WILSONS THE LEATHER EXPERTS
	XIOS
	Y2K OF WESTCHESTER INC
	YAALI NEW YORK INC
	YANKEE CANDLE COMPANY INC
111	ALBERT LOCKERS INC
	ELECTROTEK CONCEPTS INC
	INTERMEDIA TELECOMMUNICATIONS
123	ADVANCED CAREER TECHNOLOGIES
	BANK OF NEW YORK
	BARNES BEARS CORP
	BEACON ASSOC LLC
	BIRNBAUM, LINDA D
	BONA THOMAS M PC
	BONA, THOMAS
	BRAUNSTEIN, LAWRENCE J
	BRIGGS-ROGERS INC
	BUXTON GREGG
	CASA 120
	CENTER GREENMAN ASSOCIATES
	EISENBERG, LAWRENCE J
	FECKE, HELEN R
	FORMES, FRANK J
	GELFAND, BERTRAM
	GLEICHER ASSOCIATE
	GREENWICH TECH PARTNERS INC
	HONGACH, LINDA M
	JOHN, W M
	KELLMAN, NANCY D
	MANCO, LINDA M
	OBARA, TOSHIO
	PARKER GROUP INC
	POWER AUTH OF THE STATE NY
	STATE NEW YORK DEPARTMENT OF
	STERNBERG, KOZERA
	THOMPSON, RICHARD C
	VOLPE, DOCTOR C
	WILSON, RICHARD B
134	KELLMAN NANCY D LAW OFFICE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2005 (Cont'd)

155	GRANITE, T
	MUSICAL ASSOCIATES INC
169	AMERICAN EX TRVL RELATED SVCS
	J & K PRINTING ENTERPRISES
171	LAST CALL NY INC
	VINTAGE BAR RESTAURANT
175	630 CORP
	A & A STAFFING HEATH CARE SVCS
	ABM TITLE SERVICE
	APG MARKETING INC
	BARR ASSOCIATES
	BEECHER REXANNE
	BLISS A
	BLISS EXTERMINATORS CO MA CORP
	CENTRAL TAXI SERVICING CORP
	COURTHOUSE BARBER SHOP
	EVOLUTION MORTGAGE
	FARENGA DESIGN GROUP
	FRANK TOTA CONSULTING
	HIGHLAND APPRAISALS INC
	HUGHES 175 MAIN ST CORP
	KAHN DAVID MILLER ATTY
	MAIN WIRELESS & JEWELRY
	NANAS DELI
	NANNAS CAFE
	NULQ SOFTWARE INC
	ONTARGET RESULTS
	PICKELLE PAUL W
	POLICE FRESH AIR FUND OF WEST
	PROMOTIONAL MAILING SERVICE
	RECLA HOLDINGS LLC
	REILLY GERALD D LWYR
	RICHARD L ARONSON INC
	ROCK CLIFF BUILDING CORP
	ROSENBERG THOMAS L
	SEDOL CORP
	SELF SERVICE INC
	SHACKIE SERVICES LLC
	SHOWGUN INC
	SOFTWARE LINK INC
	SOUNDSHORE AMBULANDT CORP
	SPLENDID INC
	US LEGAL SUPPORT INC
	WEST CHESTER USA
	WESTCHESTER LAW JOURNAL INC
	YORKTOWN COUNTRY INN INC
185	KARAMBA CAFE CORP
	WHITE PLAINS PIZZERIA REST
187	MANHATTAN BAGEL COMPANY INC
189	CAR INSURANCE AGENCY

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2005 (Cont'd)

189	CTR FOR DRIVING WESTCHESTER
	G & R CHECK CASHING
	LA PETITE PATISSERIE INC
	MICHELLE CORP
	TEFFT BUSINESS SCHL
	WESTECH ELEVATOR SERVICE INC
199	AHMAD & THOMAS ESQ
	ALL FOR YOU SALON & DAY SPA
	BLUESTONE REALTY ADVISORS INC
	FAMIGL-DBARTOLO OPERATIONS LLC
	FAMIGLIA-DEBARTOLO LLC
	FIECH, STANO
	FUTURE WORLD TRADING INC
	GARGIULO PAUL G
	GORDON, DAVID
	GOULD, RICHARD A
	GREAT WAY COMMUNICATION
	HILL LINDA M
	HILL, LINDA M
	JBL SUPPLY INC
	JOHN PORZIO & ASSOC LLC
	K&T WHOLESALE FLORIST INC
	KAPLAN MRD INC
	KENNELLY, SHARON G
	KIRVEN STEPHANIE JASMIN
	KRONICK, ARNOLD
	LAW OFFICE DAVID S KLAUSNER
	LEHRMAN STEPHEN J & ASSOCIATES
	LIBERTY TITLE AGENCY
	LOUIS, JAMES
	MARANTIS, ZACHARY
	MONTAUK HOME CENTER LLC
	NORTHERN NAILS INC
	OVERNIGHT FUNDING INC
	PHILLIPS, STEVEN
	PIACENTEJOSEPH, A
	PROSOFT TECHNOLOGY GROUP INC
	RANELLONE, STEVEN
	ROBINOWITZ, COHLAN
	RONAI & RONAI LLP
	SALEHZADEH INC
	SECURITY SERVICES OF CONN
	SPIVACK, JOEL
	STAAB GARY G ESQ
	SWIFT PROCESS SERVERS INC
	YES I CAN FOUNDATION
200	STARBUCKS CORPORATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2000

81	BARTLETT MCDONOUGH MONAGHAN
	ERIC J ROTBARD
	KEEGAN KEEGAN & STRUT LLP
	LUNNEY & MURTAGH LLC
	M C REPROTECHS INC
	MCEVOY ANDREW T
	MCGOWAN & COUSINS PC
100	A & H OPTICAL INC
	A I J J ENTERPRISES INC
	AEROPOSTALE INC
	ALPS MANAGEMENT INC
	ASPASIA AT GALERIA LTD
	AUNTIES ANNES
	BAIRD WILLIAM T DPM
	BANG BANG BOUTIQUE OF FLUSHING
	BARBANDEE INC
	BATH & BODY WORKS INC
	BIG EASY CAJUN AT GALLERIA
	BOMBAY COMPANY INC
	BRENNAN PRTNERS OF WHITE PLINS
	BUNNIE TOWNE INC
	BYS BRIDAL CO
	CANDIES GALLERIA INC
	CASUAL CORNER GROUP INC
	CF WHITE PLAINS ASSOCIATES
	CINNABON WORLD FAMOUS CINNAMON
	CLAIRES BOUTIQUES INC
	DANIEL LEE INDUSTRIES INC
	DISNEY STORE INC
	DOCTOR TOUSEXIS AND ASSOC
	FOOTACTION CENTER INC
	FRIENDLY ICE CREAM CORPORATION
	G+G RETAIL SHOPS INC
	GALLERIA ART EXPO INC
	GALLERIA MALL
	GAP INC
	GATSBY AT THE GALLERIA INC
	GENERAL NUTRITION CORPORATION
	H M FASHION ELEMENTS INC
	HAIR DESIGNERS
	HAIR STYLISTS THE INC
	HOT WHITE PLAINS COOKIES INC
	J C COLLINS INC
	JEANS OF WHITE PLAINS INC
	JEWEL HUT INC
	KAY-BEE CENTER INC
	KEEP IN TOUCH WIRELESS
	KEYNOTE PIANO MOVING INC
	KLEIB SHOES INC
	LANE BRYANT INC

MAIN ST 2000 (Cont'd)

100	LECHTERS NEW YORK INC
	LIMITED STORES INC
	LULU ACCESORIES INC
	MACYS EAST INC
	MANCHU WOK
	MCGRAPH JOE
	MIE HOSPITALITY INC
	MODERN TRAVEL GEAR INC
	MOTHERS WORK INC
	MY KITCHEN
	NAILS & MORE BY DAWN LL INC
	NATURAL SCENTS & MORE INC
	NEW CENTURY INFO SVCS INC
	NOT JUST TEES INC
	OLD NAVY INC
	OVERLAND MANAGEMENT CORP
	OVERTHECOUNTER SALES CORP
	PACIFIC SUNWEAR CALIFORNIA INC
	PARTY BASKET ENTERPRISE INC
	PETESAM INC
	PORTRAIT STUDIO/JC PENENY
	R & R GALLERIA INC
	RAINBOW APPAREL 1179
	RALPH JOBEN LTD
	RETAIL APPAREL SERVICE CORP
	SALON AMERICAS INC
	SARKU JAPAN
	SBARRO INC
	STERNS DEPARTMENT STORES
	STITCH THIS
	STRUCTURE INC
	TREASURE CHEST CELTIC IMPORTS
	TRI DONUTS
	UMBERTOS PIZZA INC
	VALENTI PERFUMERY
	VICTORIAS SECRET STORES INC
	VIDEO BUTTON
	VUMOR OPTICAL INC
	WATCH STOP
	WEISS AND NEUMAN SHOE CO
	WILSONS THE LEATHER EXPERTS
	WORLD EMPORIUM
	ZIA, IQBAL A
111	VERIZON NEW YORK INC
123	ADVANCED CAREER TECHNOLOGIES
	BANK OF NEW YORK (INC)
	BENEFIT TECHNOLOGY INC
	BIRNBAUM LINDA D
	BONA THOMAS M PC
	BORCK, STUART H

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 2000 (Cont'd)

123	BRAUNSTEIN, L
	BRILL, SANDRA A
	GREENWICH TECHNOLOGY PARTNERS
	HALLER, EVELYN
	HAND, EDWARD S
	KELLMAN ARTHUR C ATTY
	KEN II CAFETERIA
	LAWARE, C
	MUKUDAI, O
	NATIONAL PENSION SERVICE INC
	NEW YORK POWER AUTHORITY
	OLSEN, WILLIAM R
	ONEILL, WILLIAM A
	POST, CYNTHIA
	RODRIGUEZ, DAMIAN
	SHEA, PAUL J
	SUNDHEIM STEVEN R
169	AMERICAN EX TRVL RELATED SVCS
173	CAMEO CREATIONS
175	ARONSON RICHARD L INC
	BARRY MC TIERNAN & MOORE
	BEECHER REXANNE
	BLISS A
	BLISS EXTERMINATOR CO
	BLISS EXTERMINATORS CO MA CORP
	BUDERWITZ JOSEPH M
	CENTRAL TAXI SERVICING CORP
	COSSU DENISE M ATTORNEY AT LAW
	COURTHOUSE BARBERS SHOP
	FAYER, ERIC M
	KAPLAN ELIOT L
	METZ STEVEN P
	MURPHY MCPARTLAND & WALSH
	NULQ SOFTWARE INC
	PEREZ JOSEPH
	PICKELLE PAUL W
	POHS MAX S CO
	POLICE FRESH AIR FUND INC
	PROMOTIONAL MAILING SERVICE
	ROSEN MARTIN J PC
	ROSENBERG THOMAS L
	SELF SERVICE INC
	SPLENDED INC
	US LEGAL SUPPORT INC
	USA TAXI SERVICE CORP
	VINK PAUL T
	WESTCHESTER LAW JOURNAL INC
	ZERN MARTIN H
183	INNOVATIONS
185	PIZZAWORKS CAFE INC

MAIN ST 2000 (Cont'd)

187	MANHATTAN BAGEL WHITE PLAINS
189	G & R CHECK CASHING
	LA PETITE PATISSERIE INC
199	ALWAYS DEPENDABLE PROCESS
	CLEARVIEW COUNSELING GROUP
	DITECH CONSULTING INC
	GARGIULO, PAUL
	GARGIULOPAUL G
	GREAT WAY CARS INC
	HOME HEALTHCARE INC
	INTERACTIVE INFORMATION INC
	JJ SEDELMAIER PRODUCTIONS INC
	LEHRMAN STEPHEN J & ASSOCIATES
	MICHAELS, JEROME A
	PREMIER HOME HEALTH CARE INC
	PRESENTS OF TASTE
	PROSOFT TECHNOLOGY GROUP INC
	RYAN JOHN D ATTORNEY
	SALEHZADEH INC
	THOMAS, SOPHY
	U S SECURITY ASSOCIATES INC
	VANDERHEOF JIM
203	WORLD OYAMA KARATE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1995

81	BEAUMONT MANAGEMENT CO
	CARTELLI JAMES ATTORNEY AT LAW
	COMER BRESS BYNTON ATTRNEY LLP
	COSTA JOSEPH S
	COTSWOLD MANAGEMENT INC
	CROCCO & DEMAIO
	DONOHUE JAMES F
	DUBAN MICHAEL C PC
	EINHORN YAFFEE & PRESCOTT
	FACILITIES MANAGEMENT SYSTEMS
	FIRST AMRCN TITLE INSUR OF NY
	FRIEDMAN S WILLIAM
	GASH GARY
	HAROLD SLANT STRSSFELD SPLBERG
	KEEGAN KEEGAN & ASSOCIATES PC
	KITTAY GOLD & KREBSBACH
	LEWITTES PAUL M
	M C REPROTECHS INC
	MCCULLOUGH GOLDBERGER & STAUDT
	MCEVOY ANDREW T
	MENNA & FITZGERALD
	ODESSER EDWARD H
	PITEGOFF OCKO & HARRINGTON
	RAPOPORT JOHN
	RIGIE LAWRENCE
	SERCHUK & ZELERMEYER
	WAGNER MERIKA CPA
	ZUCKERMAN & BRAUNSTEIN
100	A & H OPTICAL INC
	A&S MUSIC & MOVIES
	ACCESSORY PLACE INC
	ACHUNOV ISRAEL
	AEGEAN RESTRNT CORP
	AFTERTHOUGHTS
	ALPS MANAGEMENT INC
	ASPASIA AT GALERIA LTD
	B DALTON BOOKSELLER INC
	BANDER NORMAN I DDS PC
	BARBANDEE INC
	BOMBAY COMPANY INC
	C M SHOE CORP
	CADILLAC FAIRVIEW ASSOCIATES
	CANADIANS CORPORATIONS
	CHIPPIS FRESH FRENCH FRIES IN
	DESIGNS INC
	DISNEY STORE INC
	EDISON BROTHERS APPAREL STORES
	EDISON BROTHERS STORES INC
	EMIGRANT SAVINGS BANK
	ENERGY FASHIONS INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1995 (Cont'd)

100 EXPRESS INC
FEDERATED DEPARTMENT STORES
FILENES BASEMENT INC
FINLAY ENTERPRISES INC
FOR LOVERS ONLY INC
GAP INC
GATSBY AT THE GALLERIA INC
GATSBY CLOTHES INC AT
GENERAL NUTRITION CORPORATION
GREAT BONS INC
H & H EASTERN DISTRIBUTORS
H M FASHION ELEMENTS INC
HAIR DESIGNERS
HERMANS SPORTING GOODS INC
HEROES WORLD
IDEAL JEWELERS II
JAMPH CONSOLIDATED INC
JEANS OF WHITE PLAINS INC
JEWEL HUT INC
KAY-BEE TOY & HOBBY SHOPS INC
KLEIB SHOES INC
LANE BRYANT INC
LECHTERS NEW YORK INC
LIBERTY TRAVEL INC
LIMITED INC
MELVILLE CORPORATION
MERRY-GO-ROUND ENTERPRISES
MOTHERS STORES INC
MR GREENJEANS CORP
MUSICLAND GROUP INC
NATURES ELEMENTS INTERNATIONAL
NEW CENTURY INC
NFWP CORP
OVERTHECOUNTER SALES CORP
PANTS SET INC
PARTY BASKET ENTERPRISES INC
PENNEY J C COMPANY INC
PIPERIE INC
R & R GALLERIA INC
RALPH JOBEN LTD
SILVER & GOLD TRADING CO INC
STERLING JEWELERS INC
SUNGLASS HUT INTERNATIONAL
SURENE CORP
TANDY CORPORATION DEL
UNITED STATES SHOE CORPORATION
VICTORIAS SECRET STORES INC
VUMOR OPTICAL INC
WILSONS THE LEATHER EXPERTS
YOON TRADING CORP INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1995 (Cont'd)

115 WIRTH JOHN JR C
123 BANK OF NEW YORK (INC)
BANK OF NEW YORK TRUST CO
BLEAKLEY & SCHMIDT
BOROWICK FELDMAN & GRONER PC
DANZIGER & MARKHOFF
LEGGAT MCCALL/IMPACT MGT INC
NEW YORK POWER AUTHORITY
RESTAURANT MANAGEMENT SYSTEMS
SIMONE O ROURKE AND HICKEY
133 PINE IRVING CAROLYN PIANO SVCE
169 AMERICAN EX TRVL RELATED SVCS
NEW COMPUTER FACTORY INC
171 J B BEAUTY CORPORATION
173 GELLERMAN W M DOD
175 ADEPT TECH RECRUITING
ARONSON RICHARD L INC
ARONSON ROBERT W
BANNER ABSTRACT CO
BARRY MC TIERNAN & MOORE
BEECHER REXANNE
BLISS EXTERMINATOR CO
BLISS TERMITE CONTROL
BUSMAN KENNETH ATTY
C V REALTY CORP
CENTRAL TAXI SERVICING CORP
CHRISS CAREERS LTD
COURTHOUSE BARBERS SHOP
CRESTWOOD HOLDING CORP
DASH TRAVEL SERVICE INC
DEMARCO JOHN W
DRESDNER IRWIN
EINHORN SIDNEY
F R PADGETT ATTORNEY
FIELDS JULES M
GOLDMAN MARSHALL
GREENSTEIN ALLAN
HUNT-WILDE CORPORATION
ISAAC EVELYN ATTORNEY
KAHN KAHN AND SCUTIERI
KAPLAN ELIOT L
KILLERLANE JAMES
L A PITTORE ATTY
LANGUS SANDRA
LEVINE LESLIE
LICHENTHAL JOS A
MANNION MARTIN P ASSOC
MARASCO PETER AGENCY INC
MARTIN LAWRENCE N JR ESQ
NATIONAL ASSOCIATES CORP

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1995 (Cont'd)

175	NORRELL CORPORATION
	POLICE FRESH AIR FUND INC
	RAPID PHOTO
	RELLA GERARDA M
	SORIANO NICHOLAS M
	STAFFING TEMPORARY
	STEPHENS & BUDERWITZ
	STEPHENS BUDERWITZ BARONI R
	STPHENS BUDERWITZ & BARONI
	USA TAXI SERVICE CORP
	WATKINS JOHN E JR
	WESTCHESTER LAW JOURNAL INC
	ZANDMAN NORMA R
180	TRI LIFT CO DIV CFL
183	INNOVATIONS
185	COLOR COPY & INC
189	ABF DEVELOPMENT SERVICE CO
	G & R CHECK CASHING
	LA PETITE PATISSERIE INC
	ROBINSON FRANK
	STAFF EXCHANGE INC
	WOMANS CNSLING PSYCHTHRAPY SVC
199	BEULAH CLIFF REST
	BROOKS & OLOUGHLIN
	BUNCH N CHURCH SHOPPE
	GREAT WAY CARS INC
	HECKER LARRY D ATTORNEY AT LAW
	HOME HEATHCARE INC
	JJ SEDELMAIER PRODUCTIONS INC
	KENT HAZZARD JAEGER
	KRONICK ARNOLD S
	LARCHMONT HILLS OWNERS CORP
	LEXUS MANAGEMENT CO INC
	MERRAN HAROLD ATTY AT LAW
	ORLOFSKY MANAGEMENT INC
	PREMIER HOME HEALTH CARE INC
	PREMIER TEMPORARY SERVICES
	ROBCO MANUFACTURING CO INC
	ROBERT FOSTER GREENSTONE
	ROBINWITZ
	SALEHZADEH INC
	SLAVITT & FIECH
	SUBURBAN STREET NEWS INC
	SWEENEY ANTHONY E ATTORNEY
	SYSTEM MANAGEMENT ARTS INC
	TOUCH OF GOLD A
	WHELAN DAVID J
203	JONES DIVERSIFIED SERVICES
	WORLD OYAMA KARATE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1992

81	ACKERMAN P B ATTORNEY
	BRINTON & JANUARY
	CARTELLI JAMES ATTORNEY AT LAW
	COTSWOLD MANAGEMENT INC
	COTSWOLD MGMT PARTNERS LP
	DUBAN MICHAEL C PC
	FACILITIES MANAGEMENT SYSTEMS
	FIRST AMRCN TITLE INSUR OF NY
	G E C ALSTHOM TRANSPORTATION
	KEEGAN KEEGAN & ASSOCIATES PC
	LAWYERS TITLE INSURANCE CORP
	LEON C BAKER
	M C REPROTECHS INC
	MITSUBISHI KASEI AMERICA INC
	PERFORMANCE COMMUNICATIONS
	R C KATZ ATTY
	ROSE BEATON ROSE
	RUMBOLD & BRESS
	SERCHUK & ZELERMEYER
	SEROKA GROUP INC
	STELLATO, ANTHONY
	WAGNER MERIKA CPA
	ZUCKERMAN & BRAUNSTEIN
100	A & H OPTICAL INC
	ACHUNOV ISRAEL
	ALPS MANAGEMENT INC
	ANCHOR SAVINGS BANK FSB
	ASPASIA AT GALERIA LTD
	ASSISTANCE IN MARKETING INC
	ATALS LUGGAGE
	B DALTON BOOKSELLER INC
	BANDER NORMAN I DDS PC
	BANK OF NEW YORK THE
	BARBANDEE INC
	C M SHOE CORP
	CFTC GROUP INC
	CHEZ CHOCOLATE
	CHIPPIS FRESH FRENCH FRIES IN
	COLEMAN TUXEDOS
	DESIGNS INC
	EARLY LEARNING CENTRE
	EDISON BROTHERS STORES INC
	EMIGRANT SAVINGS BANK
	ENERGY FASHIONS INC
	EXPRESS INC
	FEDERATED DEPARTMENT STORES
	FOR LOVERS ONLY INC
	FREE FALL
	GAP STORE
	GATSBY AT THE GALLERIA INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1992 (Cont'd)

100 GATSBY CLOTHES INC AT
GENERAL NUTRITION CORPORATION
GREAT BONS INC
H M FASHION ELEMENTS INC
HAIR DESIGNERS
HERMANS SPORTING GOODS INC
HEROES WORLD
IDEAL JEWELERS II
ITAL SPORT INC
J P HOLDING CORP
JEANS OF WHITE PLAINS INC
JEWEL HUT INC
JMB/FEDERATED REALTY ASSOC
KLEIB SHOES INC
LANE BRYANT INC
LEATHER BOUND LTD
LIBERTY TRAVEL INC
LIMITED INC
MAJOR JEWELERS INC
MELVILLE CORPORATION
MERRY-GO-ROUND ENTERPRISES
MEXI-DON OF WHITE PLAINS INC
MR GREENJEANS CORP
MUSICLAND GROUP INC
NEENA INC
NEIMAN-MARCUS GROUP INC
NFWP CORP
OOLA CORP
OVERLAND MANAGEMENT CORP
OVERTHECOUNTER SALES CORP
PANTS PLACE PLUS INC
PANTS SET INC
PARTY BASKET ENTERPRISES INC
PENNEY J C COMPANY INC
PETITE SOPHISTICATE
PIPERIE INC
POLARIS PET CENTER INC
R & R GALLERIA INC
RALPH JOBEN LTD
RAPHAEL CLTHES OF WHITE PLAINS
RODACH ENTERPRISES INC
SAM GOODY
SILVER AND GOLD TRADING CO
SPECTATHLETE
STERLING JEWELERS INC
SUNCOAST MOTION PICTURE CO
SUZETTE HOSIERY INC
TANDY CORPORATION DEL
UNITED STATES SHOE CORPORATION
VALENTIS LTD

MAIN ST 1992 (Cont'd)

100	VICTORS COOKIES INC
	VUMOR OPTICAL INC
	WALDEN BOOK COMPANY INC
	WALLACHS INC
	YOON TRADING CORP
	ZAMANIAN FRANK
111	NEW YORK TELEPHONE COMPANY
123	ASTRON MANAGEMENT CORP
	BANK OF NEW YORK THE
	BANK OF NEW YORK TRUST CO
	CARDINAL RESOURCES INC
	CITIBANK N A
	CORONADO OIL & GAS INC
	DANZIGER & MARKHOFF
	DERDERIAN GEORGE M
	EDWARDS A G & SONS INC
	IMPACT MANAGEMENT GROUP INC
	LH FRISHKOFF & CO PC
	NATIONAL ECONOMIC RES ASSOC
	NEW YORK POWER AUTHORITY
	ODYSSEY MAINTENANCE CORP
	PAPPAS VENTURES INC
	RESTAURANT MANAGEMENT SYSTEMS
	REYMAN, STUART
	SHEARSON LEHMAN BROTHERS INC
	SIMONE O ROURKE AND HICKEY
	TECTON GROUP INC
	W P P CORP
	WEST HARTSDALE AVENUE EQUITIES
169	AMERICAN EX TRVL RELATED SVCS
171	WILFRED AMERICAN EDUCATIONAL
173	GELLERMAN WM D O D
175	A S YALKUT ATTORNEY
	ACCREDITED CARE INC
	AILES OHLANDT & GREELEY
	ARONSON RICHARD L INC
	AVANT SERVICES CORPORATION
	B J SKWIERSKY ATTORNEY
	BANNER ABSTRACT CO
	BARRY MC TIERNAM MOORE & SIRAC
	BLASS HAROLD
	BROWN GERALD
	C V REALTY CORP
	CALGER ARTHUR
	CAPUTO ANTHONY J
	CENTRAL TAXI SERVICING CORP
	CHRISS CAREERS LTD
	COURTHOUSE BARBERS SHOP
	DASH TRAVEL SERVICE INC
	DAVID SAMEL ATTORNEY

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

MAIN ST 1992 (Cont'd)


175 DELANE THOMAS F
DEMARCO JOHN W
DEMPSEY JAMES
DRACHMAN & HELFMAN ATTYS
EINHORN SIDNEY
ENTREE PERSONNEL SERVICES
F R PADGETT ATTORNEY
FIELDS JULES M
FRIIA JO ANN ATTORNEY
GOLDMAN MARSHALL
GREENSTEIN & GRENSTEIN ESQ
HERZFELD ROBERT ESQ
HIRCH WALTER JAY
INCENTIVE PLANNING LTD
J W FINLEY JR ATTORNEY
JACOBS GLORIA S
KAPLAN ELIOT L
KENNETH BUSMAN ATY
KILLERLANE JAMES
KURTZ MARICE
L A PITTORE ATTY
LANE HOMER W
LANGUS SANDRA
LEVINE LESLIE
LICHENTHAL JOS A
MADEN & CO
MANNION MARTIN P ASSOC
MANNIX JR JAMES M ATTY
MARTIN LAWRENCE N JR ESQ
MASTER MESSENGER INC
MAY BRITH YOUTH ORGANIZATION
MICEK ANDREW M
NATIONAL ASSOCIATES CORP
NATIONAL CONFERENCE
NUNZIOS COURTHOUSE BARBER SHOP
OBOYLE JG INSURANCE
OWL LITIGATION SUPPORT SERVICE
PASTORS MAIN STREET CORP
POLICE FRESH AIR FUND INC
PROFESSNAL STFFING WSTCHSTER I
RAPID PHOTO
REILLY & LEWIS
ROSEN MARTIN J PC
SORIANO NICHOLAS M
SPRING ARHTUR
STAFFING TEMPORARY
STAUB BERNARD CPA
STEPHENS & BUDERWITZ
STPHENS BUDERWITZ & BARONI
WATKINS JOHN E JR

MAIN ST 1992 (Cont'd)

175 WESTCHESTER LAW JOURNAL INC
183 INNOVATIONS
LA GUILLOTINE FOR HAIR INC
185 HARDCOPY MEDIA INC
189 A ARISTA ADDICTION SERVICES
ABF DEVELOPMENT SERVICE CO
BONIFAZ, NELLIE
G & R CHECK CASHING
LA PETITE PATISSERIE INC
PAOVELLA MIKE
PENDULUM PRESS INC
ROBINSON FRANK
199 518 EAST 187TH STREET CORP
A E SWEENEY ATTORNEY
ARDSLEY SANDWICH INC
BARR & FAERBER
BEULAH CLIFF REST
BROOKS & OLOUGHLIN
DARLINGTON C F III
DECARO & DECARO
DONOHUE JAMES F
FOX ADVERTISING SERVICE
GALLAGHER ARTHUR J & CO OF NY
HECKER LARRY D ATTORNEY AT LAW
HUMPHREY DONALD
JJ SEDELMAIER PRODUCTIONS INC
KENT HAZZARD JAEGER
KLAVANS GEORGE & CO INC
LARCHMONT HILLS OWNERS CORP
LEXUS MANAGEMENT CO INC
MACHOVER ASSOCIATES CORP
MC GRATH ROBERT P
MERRAN HAROLD ATTY AT LAW
ORLOFSKY MANAGEMENT INC
OWL SCURITY INVESTIGATION SVCS
PREMIER PERSONNEL SERVICES
ROBINOWITZ & BIANCHI
SCARSDALE MEADOWS CONDOMINIUM
SEA MANAGEMENT CORPORATION
SLAVITT & FIECH
SUBURBAN STREET NEWS INC
W S P EXCESS BROKERAGE CO
WHELAN DAVID J
201 LEVEY & LEVEY

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

MAIN ST 1987



RESIDENCE 164 BUSINESS

● MAIN ST
White Plains PO 10605

1– 56 CT 92 $C..H 4
57– 317 CT 93 $C..H 4
318– 399 CT 94 $C..H 4
400– 448 CT 88 $E..H 4
480– END CT 87 $B..H 5

– 1 CENTRAL AV
1★ Adirondack Trlwys .82 949-2342
★ Bonanza Bus Lines .79 428-1683
★ Contintl Trlwy Bus .75 949-2342
★ Trailways Bus Sys .75 949-2342
★ White Plains Bus .72 949-2342
★ WHI Plns Bus Ctr .72 428-1683
★ White Plains Bus .85 949-2342
13★ W R Kohler Aty - 949-2700

– 1 ORAWAUPUM AV
50★ A S Hansen Inc - 285-9100
★ Ast Research Inc H 682-2070
★ Bella Abzug H 948-8862
★ Amer Eqtbl Funding H 682-2063
★ Answerall Technlgy H 684-0411
★ Armada Group H 682-2023
★ J M Aurnou Aty H 993-0400
★ J M Aurnou Aty H 993-0706
★ J M Aurnou Aty H 993-0709
★ Balint Lamb&Assocs - 946-3600
★ Bank If Ireland H 328-7505
★ Benefits Consultin H 285-9100
★ Bradhurst Asoc Inc H 949-2057
★ Caddybag-Uk Golf H 682-2181
★ Chmcl Invstr Svc H 428-9600
★ J P Collins Aty - 948-4500
★ Comprhnsv Devlpmnt H 682-2160
★ Alexius Conroy&Co H 682-2032
★ Rocco Conte Aty - 948-4500
★ S C Cooper Aty .85 684-0004
★ Divrsfd Fncl Mngmn H 682-2007
★ Dollar Dry Dock Bk .85 997-2681
★ Dollar Dry Dk Bk .85 397-2000
★ Dennis T Doyle - 948-4500
★ D A Driscoll Aty - 948-4500
★ F Epstein H 682-2135
★ Federal Express H 997-2100
★ Fensterheim&Assoc - 682-7700
★ Edward L Ford Aty - 997-5162
★ Fortune Systms Cor H 682-2077
★ P T Gahagan Aty H 328-1300
★ Glenn G Geiger Co .85 428-6180
★ J Mollo George ASC H 682-2036
★ J Mollo George ASC - 328-0076
★ U Golden&Wexler PC H 682-2155
★ F Gordon Realty H 682-2005
★ Granger Assoc H 682-2096
★ J H Gurner Aty H 682-2100
★ Hamilton Shipbrkrs - 682-2060
★ Stern Hanigsberg H 428-8800
★ Highground Inc H 682-2056
★ Hitachi Cable AM H 993-0990
★ Imagitech Graphics .85 997-1318
★ Interactive Images H 682-2053
★ L S Jamieson Aty - 948-8855
★ Key Agcy of NY - 683-8200
★ Knox Lent&Tucker .85 946-3600
★ R B Koegel Aty H 328-1300
★ P W Koors Aty H 285-9030
★ Laurel Advertisng H 682-3515
★ Leaton&Hupperler .85 683-1900
★ D Lerner Assocs H 285-9300
★ Life Plan H 682-2065
★ James Lober H 682-2009
★ Lorvin Ltd - 683-5558
★ Philip M Maley Aty H 683-8030
★ Management Consltg H 285-9100
★ Mandeville Assoc H 683-8200
★ Mktg Data Srvc H 682-2072
★ Messinger&Assocs .85 682-8444
★ S Messinger Aty .85 682-8444
★ Metpltn Intrntnl - 682-2180
★ G J Mollo Assocs - 328-0076
★ Anthony V Montalto - 761-6636
★ J L Muscarelle Inc - 682-2027
★ Natl Mngmt Ctr - 682-2061
★ S Neubardt Aty H 948-7733
★ Nippon Zeon Amerca H 683-8500
★ NE Marketing Inc H 682-2025
★ D L OConnor Aty - 948-4500
★ OConnor&Assocs - 948-4500
★ Office Help Temprr - 428-0155
★ R C Oleson Aty - 948-4500
★ W S Oleson Aty - 948-4500
★ Overseas Telecomm H 683-6400
★ R C Owen Aty .83 948-4500
★ A Pagano Jr Inc - 683-6669
★ Pension Plan H 285-9100
★ Period Shop Westch H 682-7751
★ Pitassy&Leslie PC H 328-1300
★ R N Pitassy Aty - 328-1300
★ Platinum Stem&Ptls H 683-3700
★ H N Posner Aty .85 682-8444
★ Posner&Posner Aty .85 682-8444
★ Premium Specialtis - 682-2177
★ Prerau&Teitell Aty H 682-9300
★ Prime Ofc Systems .85 948-5668
★ Promotnl Marketing H 682-2037
★ Proteon Inc H 682-2062
★ Prudntl-Bache Secr - 328-8700
★ Ready Funding Corp - 683-3933
★ W M Sachtjen Assoc - 682-2047
★ Doris L Sassower H 682-2001
★ Seicom Systms Inc H 682-2055
★ Siecor Corp H 682-2015
★ Stern&Keiser PC H 428-8800
★ James Stuart Co .85 682-2278
★ C K Targoff Aty .85 949-1112
★ Telus Systems H 682-2182
★ P T Temple Aty H 682-9300
★ Conrad Tietell Aty H 682-9300
★ Tokyo Zairyo Co - 285-9070
★ Tri-St Hlth Svce - 682-2093
★ Trinet H 682-2095
★ Truth Verificatns - 682-2028
★ Uniglobe Xavier Tr H 682-3100
★ Venco Industries H 948-0272

EXCEPT AS AUTHORIZED BY THE PUBLISHER.
— Census Tract Wealth Rating CL10 — Map Location

MAIN ST 1987

10606
50★ Venex Internatl ... ⌗ 948-0272
★ Ventrac ... ⌗ 948-0551
★ Venture Foods Inc ... ⌗ 948-8877
★ Eli Vigliano ... ⌗ 682-2005
★ Wstchstr Financial .85 948-3233
★ Zobar Management .85 761-7663
★ Zobar Mngmnt Corp ... ⌗ 761-7663
★ Zoldan Equities ... - 761-7663
62 W Taylor ... ⌗ 631-6813

10601
81★ ABA Technologies .84 682-4980
★ Apex 2 Inc ... - 997-6300
★ L C Baker Aty .85 997-7340
★ D Beaton Engr .85 682-4850
★ Daniel S Berman .85 761-7550
★ Henry S Berman .85 761-7550
★ Milton Berner Aty ... 761-9500
★ S D Byron Aty .85 761-7550
★ Gerald Cahn Aty .85 761-7550
★ J A Cartelli Aty .85 993-0100
★ Citytrust Spcl Svc .85 997-6107
★ The Conroy Co ... ⌗ 683-8400
★ J S Costa Aty .85 948-4428
★ David A Doern .84 761-4000
★ Ellenbogen&Assoc .85 681-7177
★ P A Feigenbaum Aty .85 761-7550
★ Fink&Ascs .76 761-7550
★ N A Fredman Aty .85 761-7550
★ S G Fredman Aty .85 761-7550
★ Genrl Elctrc Crdt .85 761-9444
★ A R Giodano Aty .85 761-7550
★ Golenbock&Barell .84 761-9500
★ S L Goodman Aty .85 681-7177
★ Intellimed Corp ... ⌗ 682-7330
★ B M Kauderer Aty .85 761-7550
★ J W Keegan Aty .84 949-7227
★ Keegan&Assoc .84 949-7227
★ M E Horelitz Aty .85 761-7550
★ Georgia D Kramr .84 761-9500
★ Lawyer Title .85 682-3900
★ Lebenson Actuarial ... - 949-4690
★ Jerome T Levy ... - 761-7550
★ E E McCormick Aty .85 949-7227
★ Mitsubishi Chem .84 761-9450
★ MMA-PCI ... .85 328-7703
★ Charles J Moos Aty .85 761-7550
★ Ntl Pension Assoc ... ⌗ 949-4066
★ C M Newman Aty .84 761-7550
★ Perfrmnce Commnctn .85 328-7700
★ Pripps Inc ... ⌗ 683-5566
★ RGB Intl Property .84 683-1418
★ R K Carvill ... .85 681-0098
★ Realty Decisions .85 949-5552
★ Rose Beaton&Rose .85 682-4850
★ W A Rose Engr .85 682-4850
★ W J Rose Jr Archt .85 682-4850
★ Rostenberg-Doern .84 761-4000
★ J H Rostenberg .84 761-4000
★ John P Seligman .85 761-7550
★ Barry Singer Aty .85 761-7550
★ Anthony Stellato .85 684-9795
★ TLI Corp ... .85 946-1141
★ Transway Internat .84 682-7100
★ L W Wagmann Aty .84 761-9500
★ Merika R Wagner ... ⌗ 948-7402
★ M Weinberg Aty .85 761-7550
★ Jos A Weinberger .85 761-7550
96 ... NP

▬ 19 BROOKFIELD
100★ A&S ... - 428-2800
★ A&S ... - 428-2300
★ A&S ... .85 997-0600
★ Acropolis Restrnt .80 684-8794
★ Acropolis Restrnt .80 328-0313
★ Adler Shoe Shops .80 997-8353
★ Anchor Savings Bnk ... - 682-8080
★ Aspasia At Gallera .81 997-8488
★ Athletes Foot ... .80 761-4440
★ Max August ... .80 997-7000
★ Australian Opals .83 948-7265
★ Bakers Shoe Store .81 997-7787
★ Dr Norman I Bander ... - 428-2052
★ Bank of New York .80 997-8200
★ Barnes&Noble Books .80 949-1060
★ Bathique ... .80 682-9418
★ Begg Daigle Inc ... ⌗ 997-9412
★ Benetton ... .84 684-0151
★ Benhil Mens Shop .80 997-7444
★ Boutons White Pln .80 946-8600
★ Butlers Shoe Store .83 948-2377
★ CPI Photo Finish ... ⌗ 946-2066
★ Candies Bar ... .82 683-0965
★ Capezio Shoes ... .80 997-1150
★ Charles Carem ... .80 949-1497
★ Casual Corner ... .80 949-4311
★ Chandlers ... .80 997-8443
★ Charade Fashions .80 949-5605
★ Chess King ... .80 684-8322
★ Chez Chocolat ... .80 997-8191
★ Childrens Place ... .80 997-8133
★ Chops ... .80 997-7410
★ Churchs Frd Chicke ... - 946-2307
★ Cignal ... ⌗ 682-4113
★ The Clothes Horse .82 428-8155
★ Cohens Fashion Opt .83 428-0300
★ Colemans Tuxedos .84 328-7241
★ Collectrs Gld Glry ... ⌗ 682-7050
★ Computer Depot Inc .85 997-6330
★ Ginny Cotton ... ⌗ 681-5147
★ Crab Tree&Evelyn .85 681-0192
★ Creativity ... .85 684-9211
★ Cristinas ... .81 684-8510
★ Dj S Fshn For Men ... ⌗ 948-7133
★ Daniele Trissi Ltd .80 997-8414
★ Designs Exclusivly .80 997-7010
★ Emigrant Svg Bank .80 948-6262
★ Enclosed Mall Rsrh .80 997-7200
★ Engravers Block ... .80 997-7717
★ Express Ltd ... ⌗ 683-5844
★ Farrington Sq Apt .82 681-0340
★ Field Brothers Inc .80 761-8444
★ Jay R Florsheim .81 997-9694
★ Florsheim Shoes .84 997-9694
★ Thayer M Florsheim .80 683-9311
★ Fone Gallery Ltd .83 683-6700
★ Foot Locker ... .84 948-0188
★ For Lovers Only ... .83 948-2222
★ G&G Shops Inc ... .80 684-8788
★ Galleria Cinema ... .80 997-8198
★ Galleria Dental Gr ... - 428-2052
★ Galleria of Wht Pl .80 682-0111
★ The Gap Store ... .80 997-8118
★ Gatsby Clothers ... .80 997-8336

100★ General Nutrition ... .80 684-8792
★ Genroku White Plns .81 761-4444
★ Getting Personal ... .83 428-0476
★ Gilson Uniform Ctr .80 997-8340
★ Glass Oven ... .80 997-8483
★ Golden Egg Roll .80 997-8243
★ Gross Jewelers .80 997-8228
★ H L Gross&Bros ... .80 997-8228
★ Hallmrk Prty Bskt .80 946-4825
★ Heavenly Heros ... ⌗ 997-1452
★ Hermans Wld Spt Gd .80 997-7600
★ Heroes World ... .80 946-8881
★ Hickory Farms ... .81 761-0749
★ Hoffritz Cutlery ... .80 997-7717
★ I–Natural Cosmetcs .81 428-9648
★ Ingenuities ... .83 682-9563
★ Jacobson Bros ... .81 997-8110
★ Ralph Joben Ltd .81 997-8418
★ Josuedibles Inc ... ⌗ 993-0481
★ Hoyce–Selby Shoes .80 997-0242
★ Just Shirts Ltd ... .83 946-4102
★ Kappa Sport ... .84 328-0928
★ Kay–Bee Toy&Hobby .80 948-6686
★ Kay Jewelers ... .80 997-8240
★ Kinney Shoe Corp ... .80 948-2124
★ Koenig Art Emporm .82 997-1998
★ La Baguette Gllria ... ⌗ 948-1780
★ Lane Bryant ... .85 681-0337
★ J P Laurens ... .80 997-0800
★ Lechateau ... ⌗ 761-1751
★ Leather Bound Inc .80 997-8111
★ Lechters Housewars .80 684-8323
★ Lerners ... .80 761-6986
★ Liberty Trvl Retl .83 997-7800
★ Lifetouch Portrait .81 761-1265
★ The Limited ... .80 997-8272
★ Lodge At Harvrd Sq .80 997-8252
★ Mall Foods Inc ... .80 949-4434
★ Margaritaville ... ⌗ 997-1110
★ McDonalds ... .85 946-7156
★ Mr Greenjeans Rest .80 997-8122
★ Mothercare ... .80 997-0690
★ Musicland ... .80 997-8344
★ Nataliz er Shoes .80 997-8445
★ Neena ... .82 997-8331
★ Nine West ... .84 946-1510
★ Oakleys Amer Rest .80 949-2100
★ Over The Counter .80 997-8280
★ Overland Tradng Co .82 428-1994
★ Overthecounter Inc .80 997-8280
★ Pants Place Plus ... .80 948-0090
★ Park Lane Hosiery .80 997-8363
★ Pasta ... ⌗ 993-0835
★ Pastrami Delight ... .82 428-8788
★ J C Penney Co Inc .84 997-1700
★ J C Penney Co Inc .84 328-0607
★ J C Penney Co Inc .84 328-0919
★ J C Penney Co Inc .84 761-1265
★ Pennington Du Cnda .80 946-5511
★ Pet Pourri ... .80 997-0255
★ Petite Sophisticte ... ⌗ 946-1144
★ Phone Gallery Ltd ... .83 683-6700
★ Pildes Opticians ... .80 997-7416
★ Pipe&Bowl ... .80 761-0180
★ Pretty Posies Flrs .80 997-8282
★ Quik–Snax Inc ... .82 946-3676
★ Radio Shack ... .85 997-7157
★ Radio Shack ... .85 997-7141
★ Joben Ralph Ltd ... .81 997-8418
★ Raphael Clothing .81 946-6100
★ Red Cross Shoes .80 997-8110
★ Ress Instant Svcs .85 428-3658
★ S Hecht&Sons Inc ... ⌗ 683-6411
★ Sam Goody Inc ... .80 997-8383
★ Sbarro ... .80 997-8474
★ Scandnvn Dsgn&Gly .80 997-8262
★ Selby Shoes ... .81 997-0242
★ The Singer Co ... .81 682-0595
★ Suzette Lingerie ... .80 997-8355
★ T Shirts Plus Inc .80 761-6613
★ Taco Dons ... .80 997-8360
★ The Hair Designers .85 682-4727
★ Things Remembered ... ⌗ 997-0595
★ This End Up Furn .82 761-4308
★ Thom McAn ... .80 684-8791
★ Thom McAn Store ... .80 681-0263
★ Tru–Stride Shoe ... .85 948-0777
★ Unique Boutique ... .81 997-8100
★ Ups&Downs ... - 946-3192
★ Victorias Secret ... .85 949-5037
★ Victors Cookies ... .82 684-8687
★ Video Concepts ... .84 997-7703
★ Waldenbrooks ... .82 997-8150
★ Wild Pair ... .80 997-9680
★ Yoon Trading Corp .83 328-9739
110★ Assoc Dental Group ... - 428-2052
111★ NY Telephone Co .81 682-8960
★ NY Tel Co ... .81 949-2295
★ NY Tel Co ... .81 949-8464
★ NY Telephone Co .81 997-7149
★ NY Telephone ... .81 390-2755
★ NY Telephone Co .81 949-5264
★ NY Tel Co ... .85 949-6543
114 ... NP

▬ SPRING
123★ Richard P Ackerman .82 948-1556
★ Atlantic Maritime ... .82 949-4141
★ Bsl Gift Shoppe ... ⌗ 682-0814
★ The Bank of New Yk .83 899-6000
★ L L Barnes Lyr ... .84 949-2700
★ N Barrett'iii Lyr ... .83 949-2700
★ J Robert Bleakley .82 949-2700
★ Bleakley Platt&Asc .82 949-2700
★ Bleakley Schmidt ... .82 949-2700
★ James Boyle ... .82 946-2510
★ Centroplex Corp ... .82 948-6600
★ M A Chambers Aty .83 997-1380
★ Churcham Co ... .80 682-8838
★ Citibank N A ... .83 332-1700
★ Coronado Oil&Gas ... .84 946-2510
★ J C Couzens Jr ... .82 949-2700
★ Danziger&Markhoff ... .82 948-1556
★ Digital Graphic ... .84 683-5588
★ Euro Glass Glasrep ... .83 683-1390
★ J J Fergh uson Aty ... ⌗ 949-2700
★ Hugh D Fyfe Lyr ... .82 949-2700
★ J P Glatthaar Aty ... .85 949-2700
★ M Greenspan Lyr ... .82 684-0600
★ A A C Hansen Aty .82 949-4144
★ W F Harrington ... .82 949-2700
★ W P Harrington ... .84 949-2700
★ D J Harris Aty ... .82 949-2700
★ E F Hutton&Co ... .84 682-3800
★ Danziger Joel Aty .82 948-1556
★ Kidder Peabody&Co ... .82 948-7300

123★ L H Frishkoff&Co ... .81 946-4960
★ Ira Langer ... .82 948-1556
★ Manlio M Liccione ... .80 682-8838
★ B E Lilling Lyr ... .82 684-0600
★ B L Lilling Lyr ... .82 684-0600
★ Lilling&Greenspan ... .82 684-0600
★ Raymond Lou Aty ... .79 997-1380
★ Marino&Assocs Aty .83 997-1380
★ Harris Markhoff ... .82 948-1556
★ F J Martin Jr Lyr ... .82 949-2700
★ F S Martinson ... .83 428-7600
★ R D Meade Lyr ... .82 949-2700
★ F Montross Jr Aty .82 949-2700
★ W H Mulligan Jr ... ⌗ 949-2700
★ N L Murphy Aty ... .80 682-8838
★ Ntl Economic Rsrch .83 681-7200
★ Nelson–Vrooman Aso ... - 682-9494
★ Nera Inc ... .83 681-7200
★ New York Power Ath ... ⌗ 681-6200
★ NY St Power Auth .85 681-6200
★ Odyssey Mntnce CRP .82 949-8085
★ Pappas Development .82 948-6600
★ Susan G Parker Lyr .84 949-2700
★ R M Planell Aty ... .82 949-2700
★ Irwin Pronin ... .82 948-1556
★ R&B Petroleum Inc .82 946-2510
★ Relocom ... .84 997-7540
★ Rowe&Hansen Aty ... 949-4144
★ Stewart Rowe Aty ... 949-4144
★ F S Sirota Lyr ... .83 428-7600
★ Cita Stelzer ... .83 681-7280
★ Irwin M Stelzer ... .83 681-7220
★ Murray Steyer Lyr .83 428-7600
★ Steyer&Sirota Aty .83 428-7600
★ Donald J Sullivan ... .84 949-2700
★ Systms Exchnge ... .85 761-4745
★ R K Tanenbaum ... .82 949-2700
★ Richard C Thompson .73 949-4144
★ M J Trainor Lyr ... .82 949-2700
★ Trintex ... .84 993-2400
★ Turner Constr Co ... ⌗ 997-8545
★ WPP Corp ... .82 948-6600
★ Arthur P West Lyr .82 949-2700

▬ 1 GRAND
▬ 1 WILLIAM
169★ American Exprss Co .84 761-6790
★ Computer Factory ... .84 681-6060
171★ OBI Hair Fashn ... 948-3700
★ Queens Bty Inst ... 948-3700
★ Wilfred Academy ... .73 948-3700
173★ Dr W D Gellerman ... 949-7933
★ Main Optical ... 949-7933
174★ Taylor&Asscts ... .84 949-5921
175★ Northcourt Bldg
★ AM Court Reporting ... - 761-6620
★ C K Abeles&Co Inc .85 428-2907
★ Able Bldg Inspectn .84 997-1828
★ Curtis Ailes Aty ... .85 949-7677
★ Airline Delivry Svc .81 428-7909
★ Associated Factors .79 997-0797
★ Banner Abstract Co ... ⌗ 949-2667
★ R A Baroni Jr Lyr ... - 761-0300
★ Mark G Barrett ... .82 761-2252
★ Barry&Assocs Lyr ... 946-1030
★ R Beecher Aty ... - 682-4990
★ Leonard G Bein Aty .79 997-0950
★ Susan L Bender Aty ... - 997-7066
★ Beneficial Ntl Ins .85 428-1290
★ Harold Blass Aty ... 949-6669
★ Bliss Exterminator ... - 631-2233
★ Bliss Termite Ctrl ... 949-8880
★ B Nai B Rith Youth .77 428-4835
★ Boeggeman&Assocs ... 761-2252
★ John E Boeggeman ... 761-2252
★ A D Brennan Aty ... .76 946-3700
★ Sheldon Bross Aty .83 682-0371
★ Gerald Brown Aty .70 949-7791
★ J J Buderwitz Jr ... - 761-0300
★ Burchetta Goldsan .81 682-1999
★ Kenneth Busman Aty .83 946-6555
★ C V Realty Corp ... .85 949-0590
★ A R Calger Aty ... .77 948-1600
★ M A Campbell Aty ... ⌗ 683-8223
★ A J Caputo Aty ... .74 948-5151
★ Cardinel Capital ... .82 684-6899
★ Central Taxi Serv ... .75 949-0110
★ Cerussi ... .83 682-1999
★ M J Cerussi Aty ... .83 682-1999
★ Chriss Careers Ltd .81 949-5800
★ M A Cooper Aty ... .79 428-9200
★ M A Cooper Aty ... - 664-0012
★ Cooper Prep Course ... ⌗ 428-9292
★ Courthouse Barbers .82 946-3131
★ T M Curtin Aty ... .85 946-3700
★ D Appleton Co Inc .85 682-5955
★ Dacom ... .85 682-5955
★ Victor J Dammora .82 761-2252
★ Dash Travel ... .84 946-0060
★ Thomas F Delaney .79 761-6367
★ J W Demarco Aty .79 682-8100
★ D G Donovan Aty ... 946-3700
★ Wm A Donovan Lyr ... 946-3700
★ Martin Drazen Aty ... 946-3700
★ Ann Marie Drescher .81 946-2822
★ S Einhorn Lyr ... 949-3366
★ Entre Personnel ... .85 428-8801
★ Entree Temps ... ⌗ 428-8801
★ J D Errico Aty ... .74 948-6050
★ C M Feuer Aty ... .74 946-3700
★ J G Fine Aty ... .85 946-3700
★ E L Fingar Aty ... 946-3700
★ John A Fowler Aty .74 946-3700
★ A D Fredericks Aty ... 949-5921
★ Fredericks&Asc Aty .84 949-5921
★ Joann Friia Aty ... .84 328-7070
★ Joseph H George ... 761-2252
★ P A Giangrande Aty .70 761-7800
★ C A Goldberger Aty ... 949-5921
★ M S Goldman Aty ... 428-2700
★ A Greenstien Aty ... .78 949-9782
★ S D Greenstien Aty .78 949-9782
★ L W Hansen Aty ... .80 948-3908
★ J P Harrington Aty .74 946-3700
★ F D Hatem Aty ... .73 949-0404
★ R Herzfeld Aty ... .78 428-2700
★ W J Hirsch CPA ... .80 946-1133
★ Walter J Hirsh CPA .85 946-1133
★ George S Hodges ... .82 761-2252
★ Hunt Wildee Corp ... .84 428-3636
★ G S Jacobs Aty ... .77 761-6066
★ James R Jannace ... .73 761-2252
★ Cris E Johnson Aty .85 946-3700
★ H C Johnson Aty ... .75 946-3700
★ Harold Johnson ... .83 997-9488
★ D M Kahn Aty ... .78 761-1800

175★ Kahn&Landau ... .84 761-1800
★ E L Kaplan Aty ... .78 682-0371
★ Koback&Chase Aty ... 949-3311
★ Michael Kramer Aty .77 949-5921
★ Maurice Kurtz Aty .84 949-3444
★ Lagran Patent Dsgn .82 328-9664
★ Harvey G Landau ... .83 761-1800
★ Homer W Lane Aty .74 428-3444
★ Sandra Langus Aty ... ⌗ 684-9890
★ Alfred C Laub ... .83 683-1112
★ T M Leslie Aty ... .85 946-3700
★ L I Levine Aty ... .75 761-2033
★ Murray J Levy ... .79 997-0797
★ Roy G Levy Aty ... .83 761-1550
★ S R Lewis Aty ... .85 683-5185
★ J Liberman Aty ... .73 428-6622
★ J A Lichtenthal ... 949-7101
★ J S Liebowitz Aty .76 761-0330
★ G J Linday Asoc ... .85 949-5125
★ Linsam Marktg Corp .85 949-5125
★ T J Lynch Aty ... ⌗ 948-5544
★ MRCO Constr Corp .70 682-8888
★ W F MacReery Aty .85 946-3700
★ M P Mannion Assocs .76 428-1290
★ J M Mannix Jr Aty .77 946-0310
★ Master Messengr In .81 328-0750
★ Mstr Messenger Inc ... - 632-8043
★ Sally A Maurice ... ⌗ 428-8012
★ McCarthy&Asso Aty ... 946-3700
★ R J McCarthy Aty ... 946-3700
★ John S McMahon Aty .82 948-5544
★ John G McQuaid Aty ... 946-3700
★ A M Micek Aty ... .80 997-9609
★ B S Murdock Aty ... .81 948-5544
★ P A Murphy CPA ... ⌗ 681-0113
★ National Assocs ... .85 949-4677
★ Natl Conf Christns ... 946-1604
★ Neisers Inc ... .75 946-7353
★ New Zeald–Aust Fd .85 949-5125
★ Northcourt Bldg ... 948-5175
★ Northcourt Hldng ... 948-5175
★ J G OBoyle Ins ... .83 949-3845
★ J F Ohlandt Aty ... .72 949-3389
★ John I ONeill Aty ... .85 946-3700
★ Paraledal Svces ... .85 428-8012
★ M S Pohs Rubr Prd ... 948-5175
★ Police Fresh Air ... 949-3512
★ Post Reporting Svc ... 946-0667
★ S C Post Jr Ct Rpr ... 946-0667
★ Premiere Abstract ... ⌗ 997-7730
★ Prudential Abstrct ... .72 949-2667
★ Ragtime Cafe ... .83 328-9411
★ Rapaport Bros Aty ... .72 682-8888
★ M Rapaport Rl Est ... 682-8888
★ M S Rapaport Aty ... 682-8888
★ Rapid Photo ... .71 948-3014
★ Robert M Redis Aty .74 946-3700
★ G D Reilly Aty ... .85 683-5185
★ Reilly&Lewis Aty ... .85 683-5185
★ J W Richardson ... 948-5175
★ D S Rosen Aty ... .85 946-3700
★ M J Rosen PC Aty ... 761-6300
★ A L Rosenblatt Aty .84 946-2772
★ A Sammartano Aty .85 682-4994
★ E A Shandell Aty ... .73 946-1030
★ B Sheridan Aty ... ⌗ 683-8468
★ M F Sirignano Aty .85 946-3700
★ M F Sirignano Aty ... ⌗ 682-1808
★ Ivan S Skura Lyr ... .85 949-9055
★ C B Smith Aty ... .80 761-5225
★ Henry J Smith Aty .70 946-3700
★ L L Smith Aty ... .85 948-5544
★ Stff Bldrs Hlth Cr .73 428-1515
★ Staff Bldrs Persnl ... 428-1515
★ Staff Bldrs Temp ... 949-1300
★ State Farm Ins Co .82 949-3845
★ Bernard Staub CPA .79 948-7116
★ Stephens&Asc Lyr ... - 761-0300
★ T J Stephens Lyr ... 761-0300
★ F W Streng Aty ... .85 946-3700
★ Sweeney&Calabrese .84 948-6566
★ Telecareer Corp ... 761-0300
★ J A Turley Jr Aty .83 681-0140
★ J E Watkins Jr Aty .77 428-1292
★ Westchstr Law Jrnl .71 948-0715
★ Westchstr Spcl Srv .80 428-9292
★ Western Union ... - 761-1502
★ Wiacek&Corcoran ... .85 946-2092
★ Womens Amer Ort .75 761-3560
★ J Yarmus Inc ... .84 997-1828


▬ 1 COURT
183★ Laguillotine Hair .77 948-8878
187★ Murrays Army&Navy ... 949-8143
189★ M&M Field Svc ... .81 946-5532
★ The Munson Co Surv .71 946-8056
★ Tefft Business Sch ... 949-0381
★ G Tefft Scrtrl Sch ... 949-0381
★ Tefft Stationers ... 949-0390
★ Tefft Typwrtr Co ... 949-0390
★ Tefft Typwrtng Sch ... 949-0381
★ The Copy Hut ... .83 428-2828
190 ... NP

▬ MAMARONECK AV
199★ Bar Bldg
★ Alexandra Faulkner .84 683-1448
★ Amer Restrnt Group .84 761-6575
★ Autostop Sales Co .84 761-6575
★ Bar Building ... 949-0392
★ P P Bardunias Aty ... 949-0109
★ S N Barish Aty ... .70 949-4411
★ Barr&Faerber Aty ... .81 997-7707
★ G Beisheim Aty ... .85 948-4700
★ Bethamy Nurses Reg .79 946-5655
★ Bethamy Nurses Reg .79 946-6600
★ J F Bianchi Aty ... .70 949-2826
★ David P Blake CPA .76 949-5333
★ Bramley&Co Jewlers ... 949-8110
★ Brent–Maitland Co ... .76 428-2100
★ Camera Shop Svds ... 949-1091
★ Chapman Assocts ... .85 761-6575
★ Asha Chauhan Aty ... ⌗ 328-9003
★ R M Cohlan Aty ... .77 949-2826
★ Commex Ltd ... - 328-0600
★ E G Condon Aty ... 428-2771
★ K W Conroy Lyr ... .83 948-4700
★ Cnvntn Rgstrtn Per ... ⌗ 997-2927
★ Geo Damashek Aty ... 946-9680
★ C F Darlington III ... .77 949-2422
★ T G Decaro Aty ... .78 761-0150
★ Donohue&Locker ... ⌗ 949-7766
★ J H Erdman Cnsltnt .79 428-2100
★ Estates Supervsn ... .82 328-1800
★ Fanny Farmer Candy .78 949-5832
★ Lawrence F Fay ... .83 948-4700
★ Joseph J Fiech CPA ... 949-3900

© COPYRIGHT INFORMATION ON THIS PAGE MAY NOT BE KEY PUNCHED ENTERED INTO A COMPUTER OR PHOTOGRAPHED IN ANY MANNER WHATSOEVER EXCEPT AS AUTHORIZED BY THE PUBLISHER.
⌗ — New Listing To The Directory - — New Listing To The Street ★ — Business Listing CT — Census Tract 83,84,85,Etc. — Year First Listed 1983,84,85,Etc AB,Etc — Census Tract Wealth Rating CL10 — Map Location

Target Street	Cross Street	Source
✔	-	Cole Criss-Cross Directory

MAIN ST 1982



MAIN ST 10606
White Plains PO
1- 56 TZ 92 $D..N 4
57- 317 TZ 93 $E..N 4
318- 399 TZ 94 $D..N 4
400- 448 TZ 88 $D..N 3
480- END TZ 87 $C..M 3
072740
1 CENTRAL AV
1★Bonanza Bus Lines 428-1683
★Continti Trlwy Bus 949-2342
★Greyhound Bus Line 428-1683
★Trailways Bus Sys 949-2342
★White Plains Bus 949-2342
★Whi Plns Bus Ctr 428-1683
1 ORAWAUPUM AV
10601
96 NP
19 BROOKFIELD
100★Abraham&Straus 428-2800
★Abraham&Straus 428-2300
★Abraham&Straus 997-0600
★Acropolis Restrnt 946-9863
★Acropolis Restrnt 948-5623
★Adler Shoe Shops 997-8353
★Athleisure 997-8266
★Athletes Foot 761-4440
★Max August 997-7000
★Baldwin Piano&Orgn 948-7100
★Bank of New York 997-8200
★Barnes&Noble Book 949-1060
★Bathique 997-9682
★Benhil Mens Shop 997-7444
★Boutons White Pln 946-8600
★Capezio Shoes 997-1150
★Charles Caren 949-1497
★Casual Corner 949-4311
★Chandlers 997-8443
★Charade Fashions 949-5605
★Chess King 946-9823
★Chez Chocolat 997-8191
★Childrens Place 997-8133
★Chocolate Chocalat 997-7211
★Chops 997-7410
★Cinnabar 2000 Hair 997-7161
★Cohens Fshn Optici 428-0300
★Command Performnce 949-5873
★Craft Showcase 948-1800
★Daniele Trissi Ltd 997-8414
★Designs Exclusivly 997-7010
★Eiderdown Shop 997-8322
★Emigrant Svg Bank 948-6262
★Enclosed Mall Rstrn 997-7200
★Engravers Block 997-7717
★Evyan Jewelers Ltd 997-8100
★Fantasia 946-2000
★Field Brothers Inc 761-8444
★Florsheim&Assocts 946-9874
★Franklin Mint Glry 997-8131
★G&G Shops Inc 946-9853
★Galleria Cinema 997-8198
★Galleria of Wht Pl 682-0111
★Galleria Photo Ctr 997-0333
★Galleria Singer 949-3377
★The Gap Store 997-8118
★Gatsby Clothers 997-8336
★General Nutrition 946-9858
★Teh General Store 997-8181
★Gift Box 428-7200
★Gilson Uniform Ctr 997-8340
★Glass Oven 428-8878
★Golden Egg Roll 997-8243
★Gross Jewelers 997-8228
★H L Gross&Bros 997-8228
★Hallmrk Prty Bskt 946-4825
★Hermans Wld Spt Gd 997-7600
★Hermans Wrld Sprt 997-7600
★Heroes World 946-8881
★Hoffritz Cutlery 997-7717
★Hoyce-Selby Shoes 997-0242
★Just Pants 428-7469
★Kay-Bee Toy&Hobby 948-6686
★Kay Jewelers 997-8240
★King Potatoe Rstnt 997-8440
★Kinney Shoe Corp 948-2277
★Krishna 997-8329
★Lady Madonna 946-5666
★J B Laurens 997-0800
★Leather Bound Inc 997-8111
★Lechters Housewars 997-7475
★Lerners 761-3305
★Liberty Travel 997-7800
★The Limited 997-8272
★Lodge At Harvrd Sq 997-8252
★The Magic Pan 997-8144
★Mall Foods Inc 949-4434
★Mr Greenjeans Rest 997-8122
★Monacos Coll Chowc 997-7711
★Mothercare 997-0890
★Musicland 997-8344
★Naturalizer Shoes 946-9824
★Nizza 997-8343
★Oakleys Amer Rest 949-2100
★Over The Counter 997-8280
★Overthecounter Inc 997-8280
★Palm Court Restrnt 997-8222
★Pants Place Plus 946-9854
★Pants Place Plus 948-0090
★Papco Apparel Inc 997-7410
★Pappagallo Shop 761-5250
★Park Lane Hosiery 997-8363
★Pennington Du Cnda 946-5511
★Pet Pourri 997-0255
★Pet Pourri Photo 997-1210
★Photo Ctr Galleria 997-0333
★Pildes Opticians 997-7416
★Pipe&Bowl Galleria 761-5217
★Pretty Posies Flrs 997-8282
★Printways 949-5210
★Proving Ground 946-9856
★Radio Shack Tandy 997-7141
★Red Cross Shoes 997-8110
★Regal Shoe Shop 949-5755
★Sam Goody Inc 997-8383
★Sbarro 997-8474
★Scandnvn Dsgn&Gly 997-8262
★Scholar's Choice 997-8350
★Shelby Shoes 997-0242
★Spectrum 997-8329
★Stride Rite Shoe S 948-0777
★Suzette Lingerie 997-8355
★T Shirts Plus Inc 761-6813
100★Taco Dons 997-8360
★Tano Retail Outlet 949-6900
★Thom McAn 946-9857
★Ups&Downs 946-9855
★Uttals Luggage 428-4434
★Video Concepts 997-7703
★Waldenbrooks 997-8150
★White Plns Gift 428-7200
★White Plns Photo 997-0333
★Wild Pair 997-9680
★Windsor Cntrft Jwl 761-0010
111★S Allan Garge Door 948-5665
★P Bratti Assoc 761-7244
Lundberg W Haines 946-6575
★Lawn Scape America 946-3538
★Trim-Line Tarrytwn 948-6300
114 NP
SPRING
123★Wachtel&Assocs 946-0807
154★Carpenters Locl 53 948-8918
1 GRAND
1 WILLIAM
169★Lincoln Lite Wchtr 948-2525
171★QBI Hair Fashn 948-3700
★Queens Bty Inst 948-3700
★Wilfred Academy 948-3700
173★Dr W D Gellerman 949-7933
★Main Optical 949-7933
175★Northcourt Bldg
★ARA Technical Srvc 761-7717
★Able Bldg Inspect 997-1828
★Curtis Alles Atty 949-7577
★Associated Factors 997-0797
★J M Baltz Jr Lwyr 946-3333
★Bar Ct Assocs 946-7776
★R A Baroni Jr Lwyr 761-0300
★Barry&Assocs Lwyrs 946-1030
★Leonard G Bein ATT 997-0950
★Benfcl Ntl Lfe Ins 428-1290
★H Bernstein Atty 946-2222
★Harold Blass Atty 949-6669
★Bliss Extermntr Co 949-8880
★Bliss Termite Ctrl 949-8880
★B Nai B Rith Youth 428-4835
★Boeggeman&Assocs 761-2252
★John E Boeggeman 761-2252
★Alan R Breiter CPA 946-1133
★A D Brennan Atty 946-3700
★J J Brophy Atty 761-3500
★Gerald Brown Atty 949-7791
★J J Buderwitz Jr 761-0300
★E M Burns Atty 761-2252
★A R Calger Atty 949-1600
★A J Caputo Atty 948-5151
★Central Taxi Serv 949-0110
★Churcham Co 682-8838
★Murry I Cohen 946-6166
★S M Cohen Atty 946-3700
★M A Cooper Atty 428-9200
★Court Hse Brbr Sp 948-9154
★Daily News 946-5557
★Dr Louis M Decicco 761-2660
★Thomas F Delaney 761-6367
★James Dempsey Atty 949-6600
★Dempsey&Spring 949-6600
★D G Donovan Atty 946-3700
★Wm A Donovan Lwyr 946-3700
★Martin Drazen Atty 946-3700
★Howard L Dryer ATT 761-1800
★Howard L Dyer Atty 761-1660
★Eastern Airlines 946-1166
★S Einhorn Lwyr 949-3366
★Charles Eisner Aty 761-1550
★J D Errico Atty 948-6050
★J J Ferguson Atty 946-3700
★C M Feuer Atty 946-3700
★J M Fields Atty 428-5010
★E L Fingar Atty 946-3700
★Dan Foley Atty 948-8769
★Foremost Guaranty 428-7626
★Forster&Kadish Aty 948-8855
★John A Fowler Atty 946-3700
★A D Fredericks Aty 949-5921
★Fredericks&Assoc 949-5921
★D J Freeman Atty 949-3311
★J B Freis Atty 761-4990
★Friends Demnstrtr 946-1690
★L H Frishkoff&Co 946-4960
★C F Fusillo Agcy 946-2422
★A F Gaynor Atty 946-3700
★Joseph H George 761-2252
★P A J Giangrande 761-7800
★E R Giuntini Lwyr 949-5505
★J B Glatthaar Atty 946-3700
★C A Goldberger Aty 949-5921
★M S Goldman Atty 761-1800
★A Greenstein Atty 949-6782
★S D Greenstein Aty 949-9782
★Joseph J Gross ATT 428-5151
★A A C Hansen Atty 949-4144
★L W Hansen Atty 948-3908
★J P Harrington ATT 946-3700
★Hartford Ins Legl 949-9499
★F D Hatem Atty 949-0404
★J R Herold Atty 761-6500
★R Herzfeld Atty 761-1800
★W J Hirsch CPA 946-1133
★Deupree Hunnicutt 946-8027
★J A Izzillo Atty 949-5505
★G S Jacobs Atty 761-6066
★James Jannace 761-2252
★H C Johnson Atty 946-3700
★David M Kahn 761-1800
★Kahn&Goldman Attys 761-1800
★Eliot L Kaplan 682-0371
★Koback&Chase Attys 949-3311
★Michael Kramer Aty 949-3311
★Homer W Lane Atty 428-3444
★L I Levine Atty 761-2033
★Murray J Levy 997-0797
★J Liberman Atty 428-6622
★Manlio M Liccione 682-8838
★J A Lichtenthal 949-7101
★J S Liebowitz Atty 761-0330
★Lincoln 1st Bnk Na 997-1994
★Raymond Lou Atty 997-1380
★MRCO Constr Corp 682-8888
★M P Mannion Assocs 428-1290
★J M Mannix Jr Atty 946-0310
★F P Marino Atty 997-1380
★Marino&Lou Attys 997-1380
★Mary Lerner Inc 949-4355
★P R Mazzelle Agcy 946-7860
★McCarthy&Asso Atty 946-3700
175★R J McCarthy Atty 946-3700
★H A McDevitt Atty 761-3500
★M J McNulty 328-0099
★John G McQuaid Aty 946-3700
★Metropolitn Title 949-2667
★A M Micek Atty 997-9609
★M G Minor RI Est 428-5329
★N L Murphy Atty 682-8838
★National Airlines 946-1515
★Natl Conf Christns 946-1604
★Neisers Inc 946-7353
★Gerald Nolan Atty 946-3700
★Northcourt Bldg 948-5175
★Northcourt Hldng 948-5175
★Northwest Airlines 946-1183
★Office Help Tempry 946-1690
★P J OHagan Atty 949-9499
★William J OHare 428-1292
★J F Ohlandt Atty 949-3389
★R P OKeefe Atty 946-3700
★George OKelly 946-2822
★Pan AM 723-2706
★Pan AM 472-6404
★M S Pohs Rubr Prd 948-5175
★Police Fresh Air 949-3512
★Post Reporting Svc 946-0667
★S C Post Jr Ct Rpr 946-0667
★H E Prezzano Atty 946-3700
★Prudential Abstrct 949-2667
★Rapaport Bros Atty 682-8888
★M Rapaport RI Est 682-8888
★M S Rapaport Atty 682-8888
★Rapid Photo 948-3014
★Robert M Redis Aty 946-3700
★J W Richardson 948-5175
★John R Riley Atty 946-5454
★M Romanoff Atty 428-4200
★M J Rosen PC Atty 761-6300
★S Rosenberg CPA 949-8312
★S Rosenberg CPA 948-1005
★Rowe&Hansen Attys 949-4144
★S W Rowe Atty 949-4144
★Sanford Rose&Assoc 761-8833
★H H Schrecke Lwyr 948-6800
★E A Shandell Atty 946-1030
★S E Sillman Atty 949-6600
★C B Smith Atty 761-5225
★Henry J Smith Atty 946-3700
★G F Smyth Lwyr 948-4003
★A J Spring Atty 949-6600
★Staff Bldr Medl Sv 428-1515
★Staff Bldrs Persnl 428-1515
★Bernard Staub CPA 948-7116
★Stephens&Asc Lwyrs 761-0300
★T J Stephens Lwyr 761-0300
★Wayne Stix Lwyr 761-8791
★Telecarrier Corp 761-0300
★E Thebner Atty 948-6050
★R C Thompson Atty 946-4990
★Thornton Agency 949-8180
★R Thornton Jr Ins 949-8180
★E P Tiihonen Atty 946-6137
★United Air Lines 948-8300
★A Wagner Atty 997-1380
★J E Watkins Jr Aty 428-1292
★Herbert Weiss 946-7222
★Westchstr Law Jrnl 948-0715
★Wchstr Multpl Lstg 428-3809
★Wchstr Multpl Lstg 241-2821
★Westchstr Multiple 428-3808
★Wstchst Mltpl Lstg 723-7796
★Westchstr Spcl Srv 428-9292
★Kenneth R Wolff 761-2252
★Womens Amer Ort 761-3560
★i J Yarmus Inc 997-1828
179★Pip 997-0955
★Postal Instant Prs 997-0955
1 COURT
183★Laguillotine Hair 948-8878
187★Murrays Army&Navy 949-8143
189★Apex Pawnbroking 946-2127
★Apex Pawnbroking 949-6789
★The Copy Hut 428-2828
★The Munson Co Surv 946-8056
★Tefft Business Sch 949-0381
★G Tefft Scrtrl Sch 949-0381
★Tefft Stationers 949-0390
★Tefft Typwrtr Co 949-0390
★Tefft Typwrtng Sch 949-0381
★Rose Ubaldo 946-5532
190 NP
MAMARONECK AV
199★Bar Bldg
★Bank Street Assocs 949-2777
★Bar Building 949-0392
★P P Barounias Aty 949-0109
★S N Barish Atty 949-4411
★Bethamy Nurses Reg 946-5655
★Bethamy Nurses Reg 946-6600
★J F Bianchi Atty 949-2826
★David P Blake CPA 949-5333
★S Blumenthal Atty 949-1012
★Bramley&Co Jewlers 949-8110
★Brent-Maitland Co 428-2100
★C&R Assocs 949-0009
★Camera Shop Syds 949-1091
★R M Cohlan Atty 949-2826
★Colangelo Studios 948-4900
★David C Condon Aty 948-4416
★E G Condon Atty 428-2771
★Rocco Conte Atty 948-4500
★County Properties 949-6665
★Geo Damashek Atty 946-9680
★C F Darlington III 949-2422
★Darlington&Merran 949-9299
★T G Decaro Atty 737-2120
★T G Decaro Atty 761-0150
★V Delturfo Atty 949-8223
★John W Demarco Aty 948-4500
★Diabetes Westchstr 948-0035
★Diabetes Informatn 948-0035
★J F Donohue Atty 949-7766
★Douglas&Assoc Inc 997-0589
★Dennis T Doyle Aty 948-4500
★J H Edwards Atty 948-4500
★Elliman&Assocts 997-0589
★Elto Realties Inc 949-2825
★J H Erdman Cnsltnt 428-2100
★Everfresh Co Inc 761-6467
★Fanny Farmer Candy 949-5832
★Lawrence F Fay Aty 948-4700
★Joseph J Fiech CPA 949-3900
★Fox Advertsng Serv 948-5200
★Frsngo&Yuro 946-6533

AY NOT BE KEY PUNCHED, ENTERED INTO A COMPUTER OR PHOTOGRAPHED IN ANY MANNER WHATSOEVER EXCEPT AS AUTHORIZED IN WRITING BY THE PUBLISHER.
sting to that Street ★ — Business Listing TZ — Trading Zone 73,74,75,ETC. — Year First Listed 1973,74,75,etc. AB,ETC. — Census Tract Wealth Rating CL10 — Map Location

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

MAIN ST 1977



★Dr S L Schmetz 337-6430
313 ★Marine Mdld Bank 337-2000
68 Residence 126 Business

MAIN ST 10601
White Plains PO
1- 56 TZ 92 SD..N 4
57- 317 TZ 93 SE..N 4
318- 399 TZ 94 SD..N 4
400- 448 TZ 88 SD..N 3
480- END TZ 87 SC..M 3

1 CENTRAL AV
1 ★Continti Trlwy Bus 949-2342
★Greyhound Bus Line 428-1683
★Trailways Bus Sys 949-2342
★White Plns Bus Ctr 428-1683

1 ORAWAUPUM AV
96 NP

19 BROOKFIELD
114 NP

SPRING
154 ★Carpenters Locl 53 948-8918


1 GRAND

1 WILLIAM
166 ★County Court House
169 ★Lincoln Lite Wchtr 948-2525
171 ★Qbi Hair Fashn WH8-3700
★Queens Bty Inst WH8-3700
★Wilfred Academy WH8-3700
173 ★Dr W D Gellerman 949-7933
★Main Optical 949-7933
175 ★American Airlines 946-5603
★J M Baltz Jr Lwyr WH6-3333
★G A Barron Atty 948-2060
★Barry&Assocs Lwyrs 946-1030
★G E Bashian Atty 946-3700
★Benfcl Nti Lfe Ins 428-1290
★Bennett Acoustic WH8-0100
★Bennett Hearng Aid WH8-0100
★Bennett Hearng Aid WH8-0100
★H G Bennett Hrg Ad WH8-0100
★H Bernstein Atty 946-2222
★Harold Blass Atty WH9-6669
★Bliss Extermntr Co WH9-8880
★Bliss Termite Ctrl WH9-8880
★Boeggeman&Assocs 761-2252
★John E Boeggeman 761-2252
★A D Brennan Atty ¤ 946-3700
★J J Brophy Atty RO1-3500
★Gerald Brown Atty 949-7791
★J J Buderwitz Jr RO1-0300
★Cabell Martin&Assc 946-1360
★W D Cabell Atty 946-1360
★A J Caputo Atty 948-5151
★O B Carragher Lwyr WH8-6800
★Central Taxi Serv 949-0110
★John J Chase Atty WH9-6600
★L E Cherico Atty 948-2299
★A M Christiansen RO1-0300
★Clark&Assocts Atys 946-8900
★Murry I Cohen ¤ 946-6166
★S M Cohen Atty 946-3700
★Colangelo Stds Inc 948-4900
★Cystic Fibrosis 948-0692
★Dana Process Servg 949-6660
★Dr Louis M Decicco 761-2660
★Delta Air Lines 948-0303
★James Dempsey Atty WH9-6600
★Dempsey&Assocs WH9-6600
★D G Donovan Atty 946-3700
★Wm A Donovan Lwyr 946-3700
★Dorothy Dore Atty WH6-1400
★Martin Drazen Atty 946-3700
★Howard L Dryer ATT RO1-1800
★Eastern Airlines 946-1166
★820 Holding Corp 428-4200
★S Einhorn Lwyr WH9-3366
★Charles Eisner Aty 761-1550
★J D Errico Atty 948-6050
★N Falzone Theatrl 946-2280
★J J Ferguson Atty 946-3700
★C M Feuer Atty 946-3700
★J M Fields Atty 428-5010

AS AUTHORIZED IN WRITING BY THE PUBLISHER
— Census Tract Wealth Rating CL10 — Map Location

Target Street	Cross Street	Source
✔	-	Cole Criss-Cross Directory

MAIN ST 1977




MAIN ST PAGE 434 COLE'S 1977 WESTCHEST

. 10601
175 ★E L Finger Atty 946-3700
★W J Florence Aty WH9-6600
★Forster Tomei&Assc – 948-8855
★John A Fowler Atty 946-3700
★A D Fredericks Aty 949-5921
★Fredericks&Assoc 949-5921
★D J Freeman Atty WH9-3311
★David Jay Freeman WH9-3311
★J B Freis Atty ¤ 761-4990
★C F Fusillo Agcy WH8-2422
★F M Gagliardi Atty 946-8900
★Gansevoort Holding 428-4200
★A F Gaynor Atty 946-3700
★Joseph H George 761-2252
★Giangrande&Herold ¤ 761-7800
★P A J Giangrande 761-7800
★E R Giuntini Lwyr WH9-5505
★J B Glatthaar Atty 946-3700
★I L Goldberg 428-2227
★C A Goldberger ATT 949-5921
★M S Goldman Atty RO1-1800
★T H Goldschmidt 948-1001
★A Greenstein Atty 949-9782
★S D Greenstein ATT 949-9782
★L D Haldimand 949-3165
★Jon H Hammer Atty 946-1360
★A A C Hansen Atty WH9-4144
★J P Harrington ATT 946-3700
★Hastings Refrigrtn 428-4200
★F D Hatem Atty 949-0404
★J R Herold Atty 761-7800
★Hispanic Coalition – 948-8466
★Deupree Hunnicutt 946-8027
★Interpackaging 761-3369
★J A Izzillo Atty WH9-5505
★James Jannace 761-2252
★H C Johnson Atty 946-3700
★David M Kahn Atty WH6-2772
★Kahn&Goldman Attys RO1-1800
★Richard A Katz Aty 761-2252
★R A Katz Atty RO1-1200
★John F King 946-6640
★Betty R Klein Atty 949-9680
★Koback&Chase Attys WH9-3311
★Homer W Lane Atty RO1-2000
★R R Leggett Atty WH6-1400
★L I Levine Atty 761-2033
★J Liberman Atty 428-6622
★J A Lichtenthal 949-7101
★J S Liebowitz Atty ¤ 761-0330
★Listographic Corp WH9-7824
★K P Locker Lwyr 946-8900
★MRCO Constr Corp 428-2800
★R L Magro Atty WH6-1400
★R P Manero Atty 948-6050
★M P Mannion Assocs ¤ 428-1290
★D L Martin Atty 946-1360
★P R Mazzelle Agcy WH6-7860
★McCarthy&Asso Atty 946-3700
★R J McCarthy Atty 946-3700
★H A McDevitt Atty RO1-3500
★John G McQuaid Aty 946-3700
★Donald A Mead Atty WH6-1400
★Mead Dore&Voute WH6-1400
★C C Meleney Lawyer RO1-2000
★Metropoiitn Title 949-2667
★Gordon Miller Atty 949-5188
★H M Miller Atty WH9-8410
★H G Miller Atty 946-8900
★M G Minor Rl Est 428-5329
★National Airlines 946-1515
★Natl Conf Christns WH6-1604
★Bernard Neidenberg 428-5487
★Neisers Inc 946-7353
★W S Newman CPA WH8-6736
★N L Noel Atty WH9-7577
★O G Noel Atty WH9-7577
★Gerald Nolan Atty 946-3700
★N Crt Restrnt RO1-5330
★Northcourt Bldg 948-5175
★Northcourt Hldng 948-5175
★Northwest Airlines 946-1183
★Office Help 946-1690
★J F Ohlandt Atty 949-3389
★R P O'Keefe Atty 946-3700
★George Okelley 761-2252
★W E OLeary Lwyr 948-0272
★Pan AM 472-6404
★Pan AM 723-2706
★Pan AM 949-8212
★Leslie Plump Atty ¤ 428-5050
★Max S Pohs Co 948-5175
★Police Fresh Air WH9-3512
★Post Reporting Svc 946-0667
★S C Post Jr Ct Rpr 946-0667
★Peter M Potletti 761-3369
★H E Prezzano Atty 946-3700
★Prudential Abstrct 949-2667
★Rapaport Bros Atty 428-2800
★M Rapaport Co Inc 428-2800
★M S Rapaport Atty 428-2800
★Rapid Photo 948-3014
★Realty Directory WH9-7824
★Robert M Redis Aty 946-3700
★E Resnick CPA WH8-6736
★Resnick&Newman CP WH8-6736
★J W Richardson 948-5175
★John R Riley Atty 946-5454
★Risk Supervision WH9-7577
★S R J Roach Lwyr WH9-9090
★Gerald Romanoff 428-4200
★Romanoff Mngmnt 428-4200
★M Romanoff Atty 428-4200
★M J Rosen PC Atty 761-6300
★S Rosenberg CPA WH9-8312
★S Rosenberg CPA WH8-1005
★Rowe&Hansen Attys WH9-4144
★S W Rowe Atty WH9-4144
★H H Schrecke Lwyr WH8-6800
★E A Shandell Atty 946-1030
★S E Sillman Atty WH9-6600
★Six Hundrd Nth Bwy WH9-8312
★Henry J Smith Atty 946-3700
★G F Smyth Lwyr 948-4003
★A J Spring Atty WH9-6600
★Staff Bldr Medl Sv 428-1515
★Staff Bldrs Persnl 428-1515
★Stephens&Asc Atty RO1-0300
★A R Stevenson Atty RO1-2000
★Wayne Stix Lwyr ¤ 761-8791
★T H Goldschmidt 948-1001
175 ★R C Thompson Atty 946-4990
★Thornton Agency 949-8180
★R Thornton Jr Ins 949-8180
★E P Tilhonen Atty WH9-6600
★Tri-State Affilts 949-0860
★Twin State Managmt 428-4200
★United Air Lines 948-8300
★Vittoria&King Atty 946-6640
★T J Vittoria Atty 946-6640
★A J Voute Jr Atty WH6-1400
★J W Walsh Jr Atty 428-5900
★W B Ward Estate 949-3165
★Washington Rfrgrtn 428-4200
★M Weinrauch CPA WH6-1133
★Herbert M Weiss 946-7222
★Wchstr Co Rl Est WH9-7824
★Wchstr Hispnc Cltn ¤ 948-8466
★Westchstr Law Jrnl 948-0715
★D J Whelan Atty 946-6108
★Kenneth R Wolff 761-2252
★Womens Amer Ort 761-3560
★Curtis Ailes Atty 949-7677
★Saul Katz Atty RO1-1200
★T J Stephens Lwyr RO1-0300
★Telecarrier Corp RO1-0300
★J W Walsh Jr Atty RO1-0300
1 COURT
180 ★Main Crt Liqr&Wine WH9-0770
182 ★Meiers Linen Stres WH9-5227
183 ★Help The Aged ¤ 761-2433
★Helpage Intl Ltd ¤ 761-2433
184 ★Hose N Clothes Inc 946-1725
186 ★Main Crt Book Fr 428-0330
★Polybook Distrbtrs 428-0330
187 ★Murrays Army&Navy WH9-8143
188 ★Block Shoe Corp WH9-9351
★French Boot Shop 948-9130
★Neighbrhd Yth Crps – 761-1928
★White Plns Nhd Yth ¤ 761-3757
189 ★Accredt Cltn Agcy 428-3566
★Apex Pawnbroking 949-6789
★Apex Pawnbroking WH6-2127
Sharon Enea ¤ 428-2253
★Munson Co Survyrs WH6-8056
★Tefft Business Sch WH9-0381
★G Tefft Scrtrl Sch WH9-0381
★Tefft Stationers WH9-0390
★Tefft Typwrtr Co WH9-0390
★Tefft Typwrtng Sch WH9-0381
190 NP
191 ★Lerner Shops WH8-5725
★Mt Kisco Liqr Stor 666-3232
193 ★Aavon Extermntg Co 949-5154
195 ★F G Shattuck Co WH9-9610
196 ★Chillemi Bros 428-3545
MAMARONECK AV
199 ★Amer Mgt Counsel 948-8011
★Bank Street Assocs ¤ WH9-2777
★Bar Building 949-0392
★P P Bardunias Atty WH9-0109
★S N Barish Atty 949-4411
★J F Bianchi Atty WH9-2826
★David P Blake CPA ¤ 949-5333
★I J Bland Atty 948-1220
★S Blumenthal Atty WH9-1012
★Bramley&Co Jewlers WH9-8110
★Brent-Maitland Co ¤ 428-2100
★C&R Assocs 949-0009
★Camera Shop Syds 949-1091
★Nick Carter ¤ 761-7591
★David C Condon Aty 948-4416
★E G Condon Atty 428-2771
★Rocco Conte Atty WH8-4500
★County Properties WH9-6665
★Creative Age Corp 948-8011
★Geo Damashek Atty 946-9680
★D L Danziger Lwyr WH9-7710
★V Deltufo Atty 949-8223
★Diabetes Westchstr ¤ 948-0035
★J F Donohue Atty WH9-7766
★Dennis T Doyle Aty WH8-4500
★Eastern Elec Contr – 949-9098
★J H Edwards Atty WH8-4500
★W A Egan Jr Atty WH9-2244
★Elto Realties Inc WH9-2825
★John H Erdman ¤ 428-2100
★Executive Security 948-8011
★Lawrence F Fay Aty 948-4700
★Joseph J Fiech CPA WH9-3900
★Fox Advertsng Serv 948-5200
★Frango&Yuro 946-6533
★E J Freeman Lwyr 948-4700
★G C Freeman Lwyr 948-4700
★Garnell Realties WH9-2825
★Gilleran&Bland Aty 948-1220
★J B Gilleran Atty 948-1220
★Gilleran&Assocs 948-1220
★L J Glynn Lwyr 761-0404
★R A Gould Atty ¤ 946-6969
★W J Greer Lwyr 948-4700
★R D Hazzard Atty 948-4700
★Hyman Hecker Atty WH9-3540
★Leonard D Hecker WH9-3540
★Hensol Assocs ¤ 949-6662
★S B Hickman Atty 948-4700
★Dr Ick T Himoff WH9-0324
★J B Hirschfield WH6-9627
★JCB Realty – 428-0930
★O C Jaeger Atty 948-4700
★Kalow&Bass Cpas ¤ 949-6662
★Kent&Associates 948-4700
★King&Assocs Attys WH8-4500
★David G Lewis Atty 948-8011
★Lewis Realty&Const 946-7120
★Henry J Logan Atty 948-8373
★Lombardi&De Caro ¤ 761-0150
★W R Lonergan Atty 948-4700
★MacHover Assocs ¤ 949-3777
★Lee Magnus Atty 761-5540
★J Marbach Real Est 949-0392
★McCaffrey&Condon 428-2771
★F J McCaffrey Atty 428-2771
★R P McGrath Atty 428-3111
★E J McGuinness Aty WH8-4500
★John S Mead Lwyr WH9-7766
★Natl Elec Contrctr RO1-3121
★New Rochelle News 949-2500
★New York Diabetes 948-0035
★NY Court of Claims 946-8200
★L Newman Agncy 428-2100
★D L OConnor Atty WH8-4500
★S Orlofsky Rl Est WH9-2825
199 ★Owl Investigation ¤ 761-7077
★Petrowell Inc ¤ 946-7755
★Ralph Plofsky Lwyr 949-8223
★Eli Ravikoff Atty 948-2580
★James B Reap Lwyr 948-4700
★L R Reich Atty WH9-2126
★Sidney H Reich Aty WH9-2126
★Robinowitz&Bianchi WH9-2826
★Sam Robinowitz WH9-6665
★S Robinowitz Atty WH9-2826
★Rosen&Assoc Attys WH9-0109
★B I Rosen Atty WH9-0109
★W G Ross Atty WH9-2193
★R S Scanlan Atty 949-2560
★J R Schmitt Atty ¤ 761-6700
★G Simons Atty 948-8011
★B Slavitt CPA WH9-3900
★Slavitt&Fiech Cpas WH9-3900
★Slavitt&Fiech Cpas WH9-4778
★S S Slavitt Lwyr WH9-6732
★R M Smith Atty ¤ 948-8432
★Something Fishy ¤ 948-0248
★Sprain Brook Rlty WH9-2825
★Suburbn St News 428-0930
★Syds Camera Shop 949-1091
★R B Travis Atty ¤ WH8-2200
★W W Wells Atty 946-5700
★Warren W Wells Aty 946-5700
★Westchstr Ct Svce 948-5200
★R N Wiener Atty 949-9644
★D S Wilson Atty WH8-4500
★M Wilson Atty 948-4700
★M Wilson Jr Lwyr 948-4700
★S Witner Agncy Inc WH8-7117
★Woodale Realties WH9-2825
★J J Woods Atty WH8-4500
★G Zimmerman Atty WH9-2826
201 ★A L Gagliardi WH6-3600
★L C Gitzen Acctnt WH9-5844
★Knox Lent&Tucker WH6-3600
★Robert F Lacy WH6-3600
★Bruce Lent Ins WH6-3600
★E W Levey Lwyr 946-2882
★I I Levine CPA 428-1916
★Ernest W Levy Lwyr 946-2882
★J M Scott Atty WH9-1629
★W Scott II Atty WH9-1629
★I S Skura Lwyr WH9-9055
★John J Tucker Ins WH6-3600
★J M Vucker Lwyr WH9-5844
★Dr I M Wadler WH9-8436
★R G Wingate Ins WH6-3600
205 ★London Hat Shop WH9-3255
213 ★The Brothers Shop 948-5147
215 ★Gallery of Art – 948-6052
217 ★Hobby Yarn Shop 948-4672
219 ★Rose Jewelers 428-3737
220 ★Lynn Constr Corp ¤ 682-0633
★Macys 946-5000
221 NP
222 ★Olient Gifts&Foods 946-1243
225 ★Buschs Jewelry Co 946-6100
★Century Mens Shop 946-1177
226 ★Macys 946-5015
230 ★Bankers Trust Co 946-3310
235 ★Carl Austin – 682-0660
★The Bank of NY 946-4000
★The Bank of NY 946-4000
★Joel C Bender Atty ¤ 761-7550
★D S Berman Atty ¤ 761-7550
★W N Binderman Atty ¤ 761-7550
★Carl Austin Inc – 682-0660
★Kenneth W Cohn Aty 761-2100
★J P Connors Atty ¤ 946-8800
★Fink&Assocs PC – 761-7550
★S G Fredman Atty – 761-7550
★Samuel G Fredman – 428-0880
★M C Fuerst Atty 761-2100
★A J Gaynor Atty 761-2100
★T R Hardart Atty ¤ 946-8800
★Stephen J Lehrman – 761-7550
★Peter T Manos Lwyr 946-8800
★Myron Marcus Atty – 761-7550
★Medical Equip Inc ¤ 682-8010
★Peter J Mutino Aty 946-8800
★M Nordell Atty 946-8800
★W F Olson Atty 946-8800
★J R Pisani Atty 761-2100
★J M Pollock Atty 946-8800
★W F Ranscht Jr Aty 946-8800
★S W Roberts III 946-8800
★A S Rosenfeld Atty ¤ 761-7550
★E D Rosenfeld Asso ¤ 682-8000
★Serchuk&Assoc Atty ¤ 761-2100
★Smith&Assoc 946-8800
★R P Smith Atty 946-8800
★D G Sullivan Atty 946-8800
★Stuart Troy Atty ¤ 761-7550
★US Life Title Ins 948-4040
★Vernon Rl Est Fnc ¤ 948-1477
★Robert L Wolfe ¤ 761-2100
236 ★Mt Kisco Tlor&Clnr 666-7017
237 ★Baldwin Piano&Orgn 948-7100
★H W Monahan Inc 241-1346
238 ★Clover Donut Shop 949-9788
★Clover Donut Shop 948-9296
240 ★Continental Foods 761-2579
★Little Prof Book 761-4943
241 Ralph E Banks 666-4409
★Sylvester Hrng Ad 949-6479
★Sylvestr Svce Labs 428-7312
244 ★Citibank 428-4010
252 ★Daitch-Shopwell 948-9603
255 ★Civil Def Hdqtrs 946-3221
★City Assessor 682-4223
★City Building Dept 682-4269
★City Clerk 682-4227
★City Hall Gen Info 682-4200
★City Civil Defense 682-4231
★City Finance Dept 682-4234
★City Human Rft Cmm 682-4272
★City Law Dept 682-4241
★City Mayor 682-4411
★City Parkng Authty 682-4232
★City Pubic Wrk Adm 682-4203
★City Water Billing 682-4207
★City Water Permits 682-4205
★City Engnrg&Constn 682-4216
★City Hwy Gen Inftn 682-4202
★City Purchasng Dpt 682-4267
260 ★M&M Restrnt 946-3441
262 ★Della Hayes Cosmtc 948-7310

COPYRIGHT INFORMATION ON THIS PAGE MAY NOT BE KEY PUNCHED, ENTERED INTO A COMPUTER OR PHOTOGRAPHED IN ANY MANNER WHATSOEVER EXCEPT AS
¤ — New Listing to the Directory ‡ — New Listing to that Street ★ — Business Listing TZ — Trading Zone 3,4,5 etc — Year First Listed 1973,74,75 etc AB,ETC — C

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

MAIN ST 1972



MAIN ST 1972 WESTCHESTER COUNTY **COLE'S** PAGE 409 MAIN ST

MAIN ST 10606
WHITE PLAINS PO
... 1- 56 T 92 $D..N 4
... 57- 317 T 93 $D..N 4
... 318- 399 T 94 $D..N 4
... 400- 445 T 88 $D..N 3
... 486- END T 87 $C..M 3
FT OF*FARKAS&ASSOCTS -9460995
*GIRONDO&LEARMONT ¤9460997
.. 1 CENTRAL AV ..
1 KENNETH COOMBS 0 7610440
*GREYHOUND BUS LINE 4288787
*RAILWAYS BUS SYS WH96343
*WHITE PLAINS BUS 9482000
17*A R STEVENSEEN RO12000
29*WILLIAMS HTG ENGRS WH66655
45*MAJESTIC GRILL 9489605
.. 1 ORAWAUPUM ..
.. AV ..
10601
81*PHOTGRPHY BY SPNCR 4281380
96 NP
.. 19 BROOKFIELD ..
98*REV R W GULLETTE WH86372
*MT HOPE AME ZION 9462668
*MT HOPE AME ZION 9469630
114 NP
.. SPRING ..
117*WHITE PLAINS JUDO RO19690
120*WHITE PLAINS URBN 4281300
149*CALLAN FURN W PLNS 9466838
*CALLON FURN W PLNS WH96060
150*BROADWAY ARPRT SRV 9467555
*BROADWAY TAXI 9483100
*CLOVER DO-NUT CORP WH89392
*HOUSE TAXI 9467555
154*CARPENTERS LOCL 53 9489818
*DOUGLAS SHOES WH95506
*FOAM RUBBER CO -9494384
*ELI A HOWARD ATTY -9494384
*MAIN GRV TOBACCO 9489713
*RICHMAN SHOES INC WH95506
*WHITE PLAINS FURN -9494384
155*WCHSTR COTTON STOR WH93289
157*PATERSON DECORATRS 9494112
*PATERSON SILK STRS 9494112
*H SHAPIRO INS 9494112
*JACOB SHAPIRO 9494112
158*KERMAN SHOPS LDS 9498474
160*K&P STORES 7619017
162*B MITCHELLS STORE 7619247
*FRANCIS LARGE SIZE 9496436
*WHITE PLAINS STORE 7619247
.. 1 GRAND ..
.. 1 WILLIAM ..
166*COUNTY COURT HOUSE
*MRS M G SPAULDING WH98484
*CO PASSPORT INFO 9491300
169*CO TRUST CO CITZNS 9464000
171*QBI HAIR FASHN WH83700
*QUEENS BTY INST WH83700
175*NORTHCOURT BLDG
*AMER&FOREIGN INS WH68300
*AMER TRAINING SERV 9485175
*ASSOCTD CRT REPRTG WH82214
*W T BACHMANN INC 9465661
*J M BALTZ JR LWYR WH63333
*DESMOND BARRY ATTY WH61030
*BARRY&ASSOCS LWYRS WH61030
*R L BECKER ATTY 9463700
*BENNETT ACOUSTIC RO10222
*BENNETT HEARNG AID WH80100
*BENNETT HEARNG AID RO10222
*H G BENNETT HRG AD WH80100
*H BERNSTEIN ATTY WH62222
M S BILLMIRE JR WH68000
*HAROLD BLASS ATTY WH96669
*BLISS EXTERMNTR CO WH98880
*BLISS TERMITE CTRL WH98880
*BOEGGEMANE&GEORGE RO12252
*J E BOEGGEMAN ATTY RO12252
*J E BOEGGEMAN ATTY WH65454
*FRANK B BOLGER 9468000
*BRITSH&FRGN INS CO WH68300
*JOSEPH J BROPHY AT RO13505
*GERALD BROWN ATTY 9497791
*J J BUDERWITZ ATTY 9468900
*D B CARRAGHER LWYR WH86800
*JOHN J CHASE ATTY WH96600
*REUBEN CHASE ATTY WH93311
*CLARK&ASSOCTS ATYS 9468900
*COLANGELO STDS INC 9484900
*COMPUTER TEMPORARS 4280494
*CONTACT LENS SPCST WH90697
*CNTY INDSTRL CORP WH62222
THOMAS G DECARO 7610150
*JAMES DEMPSEY ATTY WH96600
*DEMPSEY&ASSOCS WH96600
*D G DONOVAN ATTY 9463700
*WM A DONOVAN LWYR 9463700
*DOROTHY DORE ATTY WH61400
*MARTIN DRAZEN ATTY 9463700
*EASTRN LUMBR WHLSL 9467222
*DAVID EASTON ATTY RO13035
*S EINHORN LWYR WH93366
*CHARLES EISNER ATTY 7611550
*EQUALIZED EST LTD WH81771
*N FALZONE THEATRL 9462280
*J J FERGUSON ATTY 9463700
*A J FERRARO ATTY 7610150
*FERRARO&ASOCS ATYS 7610150
*J M FIELDS ATTY 4285010
*E L FINGAR ATTY 9463700
*IVAN S FLOOD ATTY WH65200
*FLOOD&VOHNOUT ATYS WH65200
*W J FLORENCE ATTY WH96600
*FORRELL TALENT AGN 9462280
*A D FREDERICKS ATTY 9495921
*FREDERICK&ASSOC 9495921
*C F FUSILLO AGCY WH82422
*F M GAGLIARDI ATTY 9468900
*L P GAGLIARDI ATTY 9468900
*W T GALLAGHER ATTY 9468900
*J H GALLOWAY III 9463700
*A F GAYNOR ATTY 9463700
*J W GEORGE ATTY RO12252
*J H GEORGE ATTY WH65454
*P A J GIANGRANDE 4285846
*E R GIUNTINI LWYR WH95505
*J B GLATTHAAR ATTY 9463700
*GLOBE INDEMNITY CO WH68300
*I L GOLDBERG 4282227
*C A GOLDBERGER ATT 9495921
*M S GOLDMAN ATTY RO11800
*T H GOLDSCHMIDT 9481001
175*GRAMERLEE CNSLTG 9485175
*C H GRIFFITHS ATTY 9463700
*S HENRY GRIST LWYR WH91493
*GUNNER&KRAUSS INS 9480202
*L D HALDIMAND 9493165
*A A C HANSEN ATTY WH94144
*EDWARD J HIGGINS ¤4281748
*HOMAR RL EST CO 7618880
*DEUPREE HUNNICUTT 9468027
*INTER PKG INC ¤7613369
*R C IVES RL EST 4280117
*J A IZZILLO ATTY WH95505
*J R JANNACE ATTY 9464794
NORBERT JAY 4280494
*JOHN EARDLIE LWYR 9487100
*JOHN LORD EMPLY SR 4280640
*JOHNSON&WOODWARD RO11100
*A S JULIEN ATTY RO13035
*DAVID M KAHN ATTY WH62772
*KAHN&GOLDMAN ATTYS¤RO11800
*KALMAN FLOOR CO 4286424
*R A KATZ ATTY RO11200
*KOBACK&CHASE ATTYS WH93311
*ROBERT KRAUSS ATTY 9480202
*R E LANDRY CPA WH87625
*P A LATERZA INS WH98400
*R R LEGGETT ATTY WH61400
*LEVINE-RAYNES WH84460
*H LEVINSON ATTY 7617630
*J A LICHTENTHAL 9497101
*LISTOGRAPHIC CORP WH97824
*LIVERPOOL&LNDN&GLB WH68300
*K P LOCKER LWYR 9468900
*M A LOMBARDI ATTY 7610150
*LONDON&LANCASHIRE WH68300
*JOHN LORD EMPLOY 4280640
*MRCO CONSTR CORP 7618880
*LEE MAGNUS ATTY RO12000
*R L MAGRO ATTY WH61400
*T E MAHAFFEY ATTY WH86818
*L N MARTIN JR ATTY 7615540
*P R MAZZELLE AGCY WH67860
*MCCARTHY&ASSO ATTY 9463700
*R J MCCARTHY ATTY 9463700
*MCCLELLAN AGENCY WH96400
*H A MCDEVITT ATTY RO13500
*C B MCGRODDY III 9463700
*JOHN G MCQUAID ATTY 9463700
*MEAD&DORE ATTYS ¤WH61400
*DONALD A MEAD ATTY WH61400
*C C MELENEY LAWYER RO12000
*METE REALTY CORP 9480939
*S H MIGLIACCIO ATY 9467474
*S H MIGLIACCIO ATY WH90910
*H M MILLER ATTY WH98410
*H G MILLER ATTY 9468900
*MINIMATION CORP ¤9463400
*MILLER G MINOR 4285329
*J F MULVEY ATTY WH81468
*NATL CONF CHRISTNS WH61604
*BERNARD NEIDENBERG¤4285487
*NEW YORK TIMES 9495300
*NEWARK INS CO WH68300
*W S NEWMAN CPA WH86736
*NIELSEN SVCE ¤9460991
*N L NOEL ATTY WH97577
*O G NOEL ATTY WH97577
*T A NOON ATTY WH65200
*N CRT RESTRNT RO15330
*T T NORTH INC 9486770
*NORTHCOURT BLDG 9485175
*NORTHCOURT HLDNG 9485175
*NUCLEAR MARKETING 4286264
*R J OKEEFFE ATTY WH96600
*GEORGE OKELLEY ¤7612252
*ONEILL REPORTING WH88222
*CARMEL ORGURKE WH82214
*RICHARD E PETRUCCI WH81771
*C H PHELAN CPA -4287939
*MAX S POHS CO 9485175
*POLICE FRESH AIR WH93512
*POST REPORTING SVC 9460667
*S C POST JR CT RPR 9460667
*PETER M POTTETTI 7613369
*H E PREZZANO ATTY 9463700
*J M PRIZZI CPA ¤9469393
*QUEEN INS CO AMER WH68300
*M S RAPAPORT ATTY 7618880
*RAPID PHOTO SUPL -9483014
*REALTY DIRECTORY WH97824
*E RESNICK CPA WH86736
*RESNICK&NEWMAN CPA WH86736
*J W RICHARDSON 9485175
*JOHN R RILEY ATTY 9465454
*J R RILEY ATTY ¤9480038
*RISK SUPERVISION WH97577
*S R J ROACH LWYR WH99090
*MARTIN J ROSEN ATY RO11800
*S ROSENBERG CPA WH98312
*S ROSENBERG CPA WH81005
*HOWARD V ROSENBLUM 9481991
*ROWE&HANSEN ATTYS WH94144
*S W ROWE ATTY WH94144
*ROYAL-GLOBE INS WH68300
*ROYAL INDEMNITY WH68300
*ROYAL INS CO WH68300
*SAFEGUARD INS CO WH68300
*H H SCHRECKE LWYR WH86800
*R W SCHULZ ATTY ¤7619471
*E A SHANDELL ATTY WH61030
*W SILBERKLEIT ATTY 7611771
*S E SILLMAN ATTY WH96600
*REUBEN M SIWEK ATY 7611771
*SIWEK&SILBERKLEIT 7611771
*SIX HUNDRD NTH BWY WH98312
*THOMAS R SMIDT WH95066
*HENRY J SMITH ATTY 9463700
*G F SMYTH LWYR 9468900
*A J SPRIG ATTY WH96600
*STAFF BLDRS PRSNL 4281515
*B STOCKEL CPA 9493841
*SYSTEMS PROGRMMNG 4280494
*T H GOLDSCHMIDT 9481001
*THAMES&MERSEY INS WH68300
*THORNTON AGENCY ¤9481180
*R THORNTON JR INS 9498180
*E P TILHONEN ATTY WH96600
*J A TRACY ATTY WH86818
*ANDREW W TULLY ATY WH96600
*UNIPLAN PREM FINNC¤9461527
*MATHEW VEDER ATTY RO11350
*VENT-AIR CNTCT LEN WH90697
*J VOHNOUT ATTY WH65200
*A J VOUTE JR ATTY WH61400
*J W WALSH JR ATTY ¤4285900
*W B WARD ESTATE 9493165
*DR BYRON H WEETH WH97512
*M WEINRAUCH CPA WH61133
*WCHSTR CO RL EST WH97824
*WESTCHSTR LAW JRNL-9480715
*D J WHELAN ATTY ¤9466108
*WHITE PLN REALTORS-9484111
*WINDMILL FARM WATR WH93311
*ZUCKER&KRAUSS ATTYS 9480202
*M H ZUCKER ATTY 9480202
175*CURTIS AILES ATTY 9497677
*SAUL KATZ ATTY RO11200
*W STEELA ATTY WH92522
*T J STEPHENS LWYR RO10300
*TELECARRIER CORP RO10300
179*AMER FINANCE CORP 9484600
*GUARDIAN LOAN CO 9484600
.. 1 COURT ..
180*MAIN CRT LIQR&WINE WH90770
182*HEIERS LINEN STR WH95227
183*AP COPIES&OFFC SUP¤9469761
*H&A SUP HOUSE ¤9494955
184*ECONOMY HOSIERY WH61725
185*SAV-ON INC 4289653
186*MAIN CRT BOOK FR 4280330
187*MURRAYS ARMY&NAVY WH98143
188*BLOCK SHOE CORP WH99351
*FRENCH BOOT SHOP 7374999
*FRENCH BOOT SHOP WH99351
*NEIGHBRHD YTH CORP 7613757
189*APEX PAWNBROKING 9496789
*APEX PAWNBROKING WH62127
*MUNSON CO SURVYRS -WH68056
*NUNZIO BARBER SHOP 9489105
*TEFFT BUSINESS SCH WH90381
*G TEFFT SCRTRL SCH WH90381
*TEFFT STATIONERS WH90390
*TEFFT TYPWRTR CO WH90390
*TEFFT TYPWRTNG SCH WH90381
190*B E STRUSS JWLR 9497247
191*LERNER SHOPS WH85725
193*AAVON EXTERMNTG CO¤9495154
*COUNTY TREE SVCE WH88885
*DR ROBT M DONAHUE WH96672
WM D GELLERMAN WH97933
*F J HENDERSON ATTY 7612704
*LAWYERS SVC WSTCHS 9498281
THOMAS J LYNCH WH98573
*MAIN OPTICAL WH97933
FLORENCE B PRICE WH98573
*DR N W PRICE WH98573
*FRED WEISS TREE SV WH88885
195*SCHRAFFTS WH99610
*F G SHATTUCK CO WH99610
196*CHILLEMI BROS 4283545
.. MAMARONECK ..
.. AV ..
199*BAR BUILDING
*E ANSBACHER RL EST 9465492
*ANTI-DEFMTN LGE BN 9464831
*BAR BUILDING 9490392
*P P M BARDUNIAS WH90109
*S N BARISH ATTY 9494411
*G BEISHEIM JR LWYR WH84700
*BENDIX UNIFORM CO WH94180
*J F BIANCHI ATTY WH92826
*I J BLAND ATTY 9481220
*S BLUMENTHAL ATTY WH91012
*BRAMLEY&CO JEWLERS WH98110
*CAMERA SHOP SYDS 9491091
*D C CONDON LWYR WH84416
*E G CONDON ATTY 4282771
*CONDON&ASSOCS LYRS WH84416
*ROCCO CONTE ATTY WH84500
*CORPORATE COMPNSTN 4281042
*GEO DAMASHEK ATTY 9469680
*E J DANNEWITZ CO 9487767
*D L DANZIGER LWYR WH97710
*R J DARCO ATTY WH84500
*STEPHEN DAVIS ATTY WH90661
*V DELTUFO ATTY 9498223
*D C DEMPSEY ATTY 4281233
*JOHN J DILLON 9466901
*JAS F DONOHUE ATTY WH97766
*DENNIS T DOYLE ATY WH84500
*ROSE DREHER RLTR 9491103
*J H EDWARDS ATTY WH84500
*W A EGAN JR ATTY WH92244
*ELTO REALTIES INC WH92825
*EXECUTIVE SECURITY¤9488111
*L F FAY ATTY 9484700
*JOSEPH J FIECH CPA WH93900
*FOX ADVERTSNG SERV-9485200
DR FRANK W FOX WH94565
*E J FREEMAN LWYR 9484700
*JDG J J GAGLIARDI ¤9466901
*GARNELL REALTIES WH92825
*J B J GEREY LWYR WH95778
*GILLERAN&BLAND 9481220
*J B GILLERAN ATTY 9481220
*F M GRANT LWYR 9468833
*W J GREER LAWYR 9484700
SIMONS, CHRISTINE ¤WH84111
*R D HAZZARD ATTY 9484700
*HYMAN HECKER ATTY WH93540
*R J HECKER ATTY WH93540
*J BOYD HENSON ATTY 9463111
*S B HICKMAN ATTY 9484700
*DR JACK C HOEF WH88704
*J B HIRSCHFIELD WH69627
*J HOCHSTEIN ATTY WH82100
*INTER-CO TITLE 6664075
*INTER-CO TITLE WH84040
*B S KAUFMAN ATTY ¤7617605
*KENT HAZZARDS&ASSOC WH84500
*KING EDWARD&ASSOCT WH84500
*DAVID G LEWIS ATTY WH88011
*LCL UN 501 ELCTRCL WH83800
*H J LOGAN LWYR 9484700
*W R LONERGAN JR 9484700
*D LUXENBERG 4282200
*J M MANNIX JR ATTY 9460310
*J MARBACH REAL EST 9490392
*MARCH OF DIMES WH97166
*MARCH OF DIMES WH97166
*MCCAFFREY&CONDON 4282771
*F J MCCAREY ATTY 4282771
*E J MCGUINNESS ATY WH84500
*W MCKINLEY LWYR WH97100
*J J S MEAD LWYR WH97766
*A K MILLER ATTY WH92193
DR IRVING MILLER WH94565
DR SIDNEY T MILLER
0 WH94565
*I H MOSS 9464831
*F M MURPHY ATTY WH63111
*NATL ELEC CONTRCTR RO13121
*NATL MARCH DIMES WH97166
*L NEWMAN AGNCY 4282100
*D L OCONNOR ATTY WH84500
*MYRON ORLOFSKY ATY WH92777
*S ORLOFSKY RL EST WH92825
DR MURRAY PEISER WH94565
*RALPH PLOFSKY LWYR 9498223
*M E RAMEY RL EST 9494245
*ELI RAVIKOFF ATTY -9482580
*JAMES B REAP LWYR 9484700
*L R REICH ATTY WH92126
*SIDNEY H REICH ATY WH92126
*GRANT REYNOLDS ATY 7616161
*ROBINOWITZ&BIANCHI ¤WH92826
*S ROBINOWITZ ATTY WH92826
*ROSEN&BARDUNIA ATY WH90109
*B I ROSEN ATTY WH90109
199*W G ROSS ATTY WH92193
*W ROSTENBERG RL ES 9491103
*E E RUSSELL ATTY 7611747
WARREN J SCHNEIDER
0 4285662
*MAX SCHORR ATTY ¤9462330
*J J SHERLOCK ATTY WH97710
*B SLAVITT CPA WH93900
*B SLAVITT&CO CPAS WH93900
*S S SLAVITT LWYR WH96732
*ARTHUR T SMITH LWY WH97710
*SPORTS DIGEST ¤WH92193
*SFRAIN BRK RLTIES WH92825
*SYDS CAMERA SHOP 9491091
*TOUCHSTONE TOURS ¤9495242
*R B TRAVIS LWYR WH82200
*UNISPORT BLDG CO WH84416
ROBERT WEISSBERG ¤7615461
*CO REGL CRME CNTRL 4285662
*WESTCHSTR CT SVCE -9485200
*WHITE PLN CAPITOL ¤9460849
*D S WILSON ATTY WH84500
*M WILSON LWYR 9484700
*MIZELL WILSON LWYR 9484700
*M WILSON JR LWYR 9484700
*S WITNER AGNCY INC WH87117
*WOODALE REALTIES WH92825
*J J WOODS ATTY WH84500
*COUNTY PROPERTIES WH96665
*ALFRED OLSEN WH65700
*SAM ROBINOWITZ WH96665
*WARREN W WELLS ATY WH65700
201*A L GAGLIARDI WH63600
*L C GITZEN ACCTNT WH95844
*KNOX LENT&TUCKER WH63600
*BRUCE LENT INS WH63600
*E W LEVEY LWYR 9462882
*I I LEVINE CPA 4281916
*ERNEST W LEVY LWYR 9462882
*J M SCOTT ATTY WH91629
*W SCOTT II ATTY WH91629
*I S SKURA LWYR WH99055
*JOHN J TUCKER INS WH63600
*J M VUCKER LWYR WH95844
*DR I M WADLER WH98436
*R G WINGATE INS WH63600
203*CAGE DRUG CNTR -4283616
*CAGE TEEN CENTER -4283616
*CAGE TEEN CENTER -4283729
*CAGE TEEN CENTER -9464158
205*LONDON HAT SHOP WH93255
207*COUNTY CARD SHOP WH85080
211*T MCAN SHOE STR WH89873
215*THE BROTHERS SHOP WH85147
217*HOBBY YARN SHOP 9484672
219*ROSE JEWELRY SHOP WH93228
*ROSENS JWLRY SHOP WH93228
220*MACYS 9465000
*MACYS 9466622
*MACYS 9465015
221*HAMBURG DEN INC WH89149
*HAMBURG DEN INC WH96130
225*BUSCH JEWELRY CO 9466100
*BUSCHS KREDIT JWLR 9466100
*CENTURY MENS SHOP 9461177
230*BANKERS TRUST CO ¤9463310
235*LAWYRS TTL&TRST BG
*COUNTY TRUST CO 9464000
237*DAVIDS MTR CLOTHES WH67840
*MATERNITY CLOTHES WH67840
238*GARYS CHARCL DEN 9489296
239*TITLE BEAUTY SALON WH93988
240*C CHOUKHACHIAN ¤7611844
*CONTINETAL FOODS 7612579
241*SYLVESTER HRNG AD 9496479
*SYLVESTR SVCE LABS¤4287312
244*FIRST NATL CITY BK 4284010
248*RICHARDS RESTAURNT 7619631
250*NANETTE FOX RL EST 9491111
*THE FOXES RL EST 9497903
*FRENCH MENDING SHP WH91014
*EDMUND GREACEN WH60028
*JUSKO TAILORS 9498839
*H H MOGER JR ARCH WH83944
252*DAITCH-SHOPWELL 9489603
255*MUNICIPAL BLDG
*CIVIL DEF HDQTRS 9463221
*WHITE PLN BLDG DPT 9494800
*WHITE PLN CITY HLL 9494800
*WHITE PLN CIVIL DF 9463221
*WHITE PLN WTR WKS 9494800
*WHITEPLN NTH DIRCT 9494800
258*TOPPS PASTRY SHOP 9469119
260*M&M RESTRNT 9463441
262*ALLIED BTY SUPPLS 9487310
*ALLIED BTY SUPPLS 9486404
*DELLA HAYES COSMTC 9487310
264*WHITE SWAN TAVERN 9494885
266*CREATIVE FLOORS 7618848
268*LOVAS WINE&LIQUOR WH98578
½CONTNTL BEAUTY SLN RO19707
270*DAVID PODELL JWLR WH82317
½I COHEN STTNRY 9489729
272*SPLENDID CLEANERS 9496661
274*N TARTAGLIA BARBER WH89339
*WHITE SWAN BARBR WH89339
275*ALLSTATE INS COS 4283220
*EDISON PARKING CRP 4289580
*SEARS ROEBUCK&CO 4281100
*SEARS ROEBUCK&CO 4284200
276*WHITE SWAN FOODS WH82889
*WHITE SWAN PHRMCY WH90373
279*NATELSONS CLOTHING 9465500
*STONES NATELSONS 9465500
292 HERBERT L ANDERSON-7610714
R BERNSTEIN 0 7614636
HELEN M CAREY 0 7614265
BERNARD K CURLEY 0 WH68683
MRS T F CURLEY SR0 WH68683
MRS J W GRANT 0 WH83039
MRS ANNA OCONNOR 0 4284257
MRS JOHN J SARNO 0 4284257
*DAVE WALSH CO WH88022
GUY H WIDMYER 0 RO17572
.. N BROADWAY ..
.. 1 S BWAY ..
.. WESTCHESTER ..
.. AV ..
300*BRENTWOOD APTS /
MAX ABRAMSON WH84698
JOHN G AMELIO 6 9486933
BARNEY ARINOW 9483379
M ASCOLESE WH60858
KARL BACHMANN 0 7616779
GEORGE J BEHRE 5 9488635
THOMAS W BERRY 8 7613579
I A BETTMAN 9481198
MRS M BURRAGE 8 9499409
MIGUEL CARBAJAL 7 9481216
EARL P CARPENTER 8 9485431
STEPHEN CHRISTOS 4 7610736
HAROLD M CLEARY 9497023
JUSTIN D COOPER 3 WH93863
H S CROSS 7 9467828

©COPYRIGHT INFORMATION ON THIS PAGE MAY NOT BE KEY PUNCHED, ENTERED INTO A COMPUTER, OR PHOTOCOPIED, IN ANY MANNER WHATSOEVER EXCEPT AS AUTHORIZED IN WRITING BY THE PUBLISHER.

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.3
March 28, 2019

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

03/28/19

Site Name:

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601
EDR Inquiry # 5604205.3

Client Name:

ATC Group Services LLC
104 East 25th Street
New York, NY 10010
Contact: Chelsea Helm

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by ATC Group Services LLC were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 0AE9-4A49-B3FF

PO # NA

Project Z214DCPRXX

Maps Provided:

2004	1989	1894
2003	1987	1889
2002	1950	1885
1995	1942	
1994	1930	
1993	1911	
1992	1905	
1990	1900	

Sanborn® Library search results

Certification #: 0AE9-4A49-B3FF

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

ATC Group Services LLC (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


2004 Source Sheets



Volume 1, Sheet 7
2004




Volume 1, Sheet 2
2004




Volume 1, Sheet 3
2004

2003 Source Sheets



Volume 1, Sheet 2
2003




Volume 1, Sheet 3
2003




Volume 1, Sheet 7
2003

2002 Source Sheets



Volume 1, Sheet 2
2002




Volume 1, Sheet 3
2002



Volume 1, Sheet 7
2002

1995 Source Sheets



Volume 1, Sheet 2
1995



Volume 1, Sheet 3
1995



Volume 1, Sheet 6
1995




Volume 1, Sheet 7
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets



Volume 1, Sheet 2
1994


Volume 1, Sheet 3
1994


Volume 1, Sheet 7
1994


Volume 1, Sheet 6
1994

1993 Source Sheets


Volume 1, Sheet 2
1993



Volume 1, Sheet 3
1993


Volume 1, Sheet 6
1993


Volume 1, Sheet 7
1993


1992 Source Sheets



Volume 1, Sheet 6
1992


Volume 1, Sheet 2
1992



Volume 1, Sheet 3
1992

1990 Source Sheets


Volume 1, Sheet 2
1990


Volume 1, Sheet 3
1990



Volume 1, Sheet 6
1990



Volume 1, Sheet 7
1990

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1989 Source Sheets



Volume 1, Sheet 2
1989



Volume 1, Sheet 3
1989


Volume 1, Sheet 6
1989


Volume 1, Sheet 7
1989

1987 Source Sheets


Volume 1, Sheet 2
1987


Volume 1, Sheet 3
1987


Volume 1, Sheet 6
1987


Volume 1, Sheet 7
1987

1950 Source Sheets


Volume 1, Sheet 2
1950


Volume 1, Sheet 3
1950


Volume 1, Sheet 7
1950

1942 Source Sheets



Volume 2, Sheet xxxx
1942


Volume 2, Sheet 24
1942

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1930 Source Sheets



Volume 1, Sheet 2
1930




Volume 1, Sheet 3
1930



Volume 1, Sheet 7
1930

1911 Source Sheets



Volume 1, Sheet 7
1911



Volume 1, Sheet 14
1911



Volume 1, Sheet 8
1911

1905 Source Sheets




Volume 1, Sheet 16
1905



Volume 1, Sheet 17
1905




Volume 1, Sheet 21
1905



Volume 1, Sheet 22
1905

1900 Source Sheets



Volume 1, Sheet 6
1900



Volume 1, Sheet 11
1900




Volume 1, Sheet 13
1900


Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.


1894 Source Sheets



Volume 1, Sheet 3
1894



Volume 1, Sheet 4
1894




Volume 1, Sheet 5
1894




Volume 1, Sheet 9
1894

1889 Source Sheets




Volume 1, Sheet 3
1889



Volume 1, Sheet 5
1889


1885 Source Sheets



Volume 1, Sheet Keymap/Sheet1
1885



Volume 1, Sheet 2
1885




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 2
Volume 1, Sheet 7

0 Feet 150 300 600

N



Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	2003

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 6
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 6
Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 6
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #0AE9-4A49-B3FF

© 1992 Sanborn

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 3
Volume 1, Sheet 2
Volume 1, Sheet 6

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 6
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #	0AE9-4A49-B3FF
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 6
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.


Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 7
Volume 1, Sheet 6
Volume 1, Sheet 3
Volume 1, Sheet 2


N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #	0AE9-4A49-B3FF
Copyright	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




Certification #0AE9-4A49-B3FF

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1942

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 2, Sheet 24
Volume 2, Sheet xxxx

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #	0AE9-4A49-B3FF
Copyright	1930

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 7
Volume 1, Sheet 3
Volume 1, Sheet 2

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1911

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 8
Volume 1, Sheet 14
Volume 1, Sheet 7

0 Feet 150 300 600

N

Certified Sanborn® Map

1905




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1905

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 22
Volume 1, Sheet 21
Volume 1, Sheet 17
Volume 1, Sheet 16

0 Feet 150 300 600

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #	0AE9-4A49-B3FF
Copyright	1900

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.


0 Feet 150 300 600





Volume 1, Sheet 13
Volume 1, Sheet 11
Volume 1, Sheet 6

N




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #	0AE9-4A49-B3FF
Copyright	1894

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 9
Volume 1, Sheet 5
Volume 1, Sheet 4
Volume 1, Sheet 3

0 Feet 150 300 600


N



Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1889

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.






Volume 1, Sheet 5
Volume 1, Sheet 3

0 Feet 150 300 600

N

The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF




The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #0AE9-4A49-B3FF

Site Name:	Macys White Plains Galleria
Address:	100 Main Street
City, ST, ZIP:	White Plains, NY 10601
Client:	ATC Group Services LLC
EDR Inquiry:	5604205.3
Order Date:	03/28/2019
Certification #:	0AE9-4A49-B3FF
Copyright	1885

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.





Volume 1, Sheet 2
Volume 1, Sheet Keymap/Sheet1

0 Feet 150 300 600

N

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601

Inquiry Number: 5604205.4
March 28, 2019

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

03/28/19

Site Name:

Macys White Plains Galleria
100 Main Street
White Plains, NY 10601
EDR Inquiry # 5604205.4

Client Name:

ATC Group Services LLC
104 East 25th Street
New York, NY 10010
Contact: Chelsea Helm

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by ATC Group Services LLC were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# NA
Project: Z214DCPRXX

Coordinates:

Latitude:	41.031696 41° 1' 54" North
Longitude:	-73.768216 -73° 46' 6" West
UTM Zone:	Zone 18 North
UTM X Meters:	603546.40
UTM Y Meters:	4543006.38
Elevation:	211.17' above sea level

Maps Provided:

2012, 2013
1994
1979
1967, 1971
1957, 1960
1944, 1947
1938
1932
1899, 1902
1893
1892

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.


Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2012, 2013 Source Sheets




Glenville
2012
7.5-minute, 24000




White Plains
2013
7.5-minute, 24000

1994 Source Sheets




WHITE PLAINS
1994
7.5-minute, 24000

1979 Source Sheets




White Plains
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1967, 1971 Source Sheets



White Plains
1967
7.5-minute, 24000
Aerial Photo Revised 1965




Glenville
1971
7.5-minute, 24000
Aerial Photo Revised 1971

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1957, 1960 Source Sheets



White Plains
1957
7.5-minute, 24000




Glenville
1960
7.5-minute, 24000
Aerial Photo Revised 1949

1944, 1947 Source Sheets



Glenville
1944
7.5-minute, 24000
Aerial Photo Revised 1941



White Plains
1947
7.5-minute, 24000
Aerial Photo Revised 1940

1938 Source Sheets



White Plains
1938
7.5-minute, 31680

1932 Source Sheets



White Plains
1932
7.5-minute, 24000


Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1899, 1902 Source Sheets



Stamford
1899
15-minute, 62500




Tarrytown
1902
15-minute, 62500

1893 Source Sheets



Tarrytown
1893
15-minute, 62500




Stamford
1893
15-minute, 62500

1892 Source Sheets




Tarrytown
1892
15-minute, 62500



Stamford
1892
15-minute, 62500

Historical Topo Map

2012, 2013



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 2013, 7.5-minute
NE, Glenville, 2012, 7.5-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, WHITE PLAINS, 1994, 7.5-minute


SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5



TP, White Plains, 1979, 7.5-minute


SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5



TP, White Plains, 1967, 7.5-minute
NE, Glenville, 1971, 7.5-minute


SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5



TP, White Plains, 1957, 7.5-minute
NE, Glenville, 1960, 7.5-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, White Plains, 1947, 7.5-minute
NE, Glenville, 1944, 7.5-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N

Historical Topo Map

1938



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1938, 7.5-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1932, 7.5-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE


TP, Tarrytown, 1902, 15-minute
NE, Stamford, 1899, 15-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N

Historical Topo Map

1893



This report includes information from the following map sheet(s).


0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tarrytown, 1893, 15-minute
NE, Stamford, 1893, 15-minute


SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Tarrytown, 1892, 15-minute
NE, Stamford, 1892, 15-minute

SITE NAME: Macys White Plains Galleria
ADDRESS: 100 Main Street
White Plains, NY 10601
CLIENT: ATC Group Services LLC

N

CITY OF WHITE PLAINS, NEW YORK

ZONING MAP

ADOPTED BY THE WHITE PLAINS COMMON COUNCIL

JUNE 1, 1981

LAST AMENDED AUGUST 3, 2015

REVISED FEBRUARY 1, 2016

LEGEND

R1-30	Residential One Family
R1-20	Residential One Family
R1-12.5	Residential One Family
R1-7.5	Residential One Family
R1-5	Residential One Family
R2-4	Residential One Family Residential Two Family
R2-2.5	Residential One Family Residential Two Family
RM-2.5	Residential Multi-Family
RM-2	Residential Multi-Family
RM-1.5	Residential Multi-Family
RM-1.5T	Residential Townhouse
RM-1	Residential Multi-Family
RM-0.7	Residential Multi-Family
RM-0.4	Residential Multi-Family
RM-0.35	Residential Multi-Family
PSRDD	Planned Senior Residential Development District
C-O	Campus Office
O-R	Office-Residential
B-1	Restricted Business
B-2	Neighborhood Business
B-3	Intermediate Business
BR-1	Business Residential-1
BR-2	Business Residential-2
CB-1	Core Business-1
CB-2	Core Business-2
CB-3	Core Business-3
CB-4	Core Business-4
UR-4	Urban Renewal Central Business-4
B-6	Enclosed Mall
LI	Light Industrial
LI-M	Light Industrial Mixed

Zoning Boundary

Central Parking Area

Special Building Setback

Former 'S' zones with special provisions applicable to the properties indicated. For details of these provisions consult the Special 'S' District Atlas maintained on file in the Office of the City Clerk of the City of White Plains

NOTE:
This is not an official copy of the Zoning Map. The official copy is maintained on file in the Office of the City Clerk.

800' 0 1600' 3200'

SCALE 1"= 800'

N

TOWN OF NORTH CASTLE

TOWN OF GREENBURGH

TOWN OF HARRISON

VILLAGE OF SCARSDALE

TOWN OF HARRISON

Department of Planning
City of White Plains

20010901

Appendix H

Prior Reports

File: ME White Plains UST

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

April 25, 1997

Privileged and Confidential

Klaus M. Ziermaier, Esq.
FEDERATED DEPARTMENT STORES, INC.
7 West Seventh Street
Cincinnati, OH 45202

Clayton Project No. 40-97140.00

Re: Macy's Department Store - White Plains, New York
Closure of Underground Storage Tanks
Installation of Aboveground Storage Tank

Dear Mr. Ziermaier:

Clayton Environmental Consultants, Inc. is pleased to provide Federated Department Stores, Inc. three copies of its report on the above mentioned project.

Please provide a copy of the report to Mr. Bob Gorman - Director, Environmental Health and Safety of Federated Department Stores, Inc.

It has been a pleasure to provide our services to Federated Department Stores, Inc. If you require further information, please call me at (908) -225-6040.

Sincerely,

Kirit H. Vora
Vice President
Director, Corporate Accounts
Environmental Health and Safety
New York Regional Office

SB/ow

Attachments

Clayton
ENVIRONMENTAL
CONSULTANTS

Privileged and Confidential

FUEL OIL TANK UPGRADE PROJECT REPORT

Tank Closure and Installation
at
Macy's Department Store
Galleria Mall
100 Main Street
White Plains, New York

Prepared for:

Macy's East Inc.
151 West 34th Street
New York, New York 10001

Project No. 40-97140.00

Prepared by:

Clayton Environmental Consultants, Inc.
160 Fieldcrest Avenue
Raritan Center
Edison, New Jersey 08837

April 25, 1997

Privileged and Confidential

TABLE OF CONTENTS

SECTION		PAGE
1.0	EXECUTIVE SUMMARY	1
2.0	INTRODUCTION	2
3.0	PROJECT SITE DESCRIPTION	2
4.0	REGULATORY REQUIREMENTS	3
4.1	NEW YORK STATE REGULATIONS	3
4.2	WHITE PLAINS BUILDING DEPARTMENT	3
5.0	FIELD ACTIVITIES	4
5.1	USTs CLOSURE	4
5.2	AST INSTALLATION	5
6.0	PROJECT COMPLETION	6
7.0	RECOMMENDATIONS FOR NO FURTHER ACTION	6

FIGURES

Figure 1 --	Site Location Map
Figure 2 --	Macy's Department Store Floor Plan
Figure 3 --	USTs Plan View
Figure 4 --	USTs Section View

PHOTOGRAPHS

APPENDICES

Appendix A --	Macy's Tank Upgrade Contract
Appendix B --	NYSDEC and White Plains Building Department Permits
Appendix C --	Site Activities Daily Log
Appendix D --	Project/Site Specific Health and Safety Plan (HASP)
Appendix E --	Project Completion Documentation
Appendix F --	AST and Accessories, Specification and Information

Privileged and Confidential

1.0 EXECUTIVE SUMMARY

Macy's East, Inc. (Macy's) retained Clayton Environmental Consultants, Inc. (Clayton), to provide environmental engineering services for the closure of two 10, 000-gallon underground storage tanks (USTs) and the installation of a 1,000-gallon aboveground storage tank (AST) at Macy's Department Store located at Galleria Mall, White Plains, New York. The scope of Clayton's services is described in its proposal, dated October 23, 1996, which included the terms and conditions under which the work was performed.

Clayton prepared and secured the regulatory requirements regarding the project by December of 1996. The field activities were conducted on January of 1997 during which the two USTs were abandoned in place. The procedure consisted of empting, cleaning, and filling them with concrete slurry. The new AST was installed at the southeast corner of the loading area and was connected to the existing heating system. Final permits from New York State Department of Environmental Conservation and White Plains Building Department were obtained following the completion of the work.

The USTs closure and AST installation was performed in compliance with all applicable regulations, codes, and standards. Therefore, no further action is required regarding the tank system at this location. Please refer to the report for further details.

2.0 INTRODUCTION

Macy's Department Store (Macy's) has been using No. 2 fuel oil for the heating system. The fuel oil was stored inside the two USTs at the loading area. In recent years, the facility has been relying on natural gas as its primary heating source, and the two USTs were used as a secondary back system.

Macy's decided to close the two USTs and install a small AST as a back up system at the facility. The upgrading of the USTs required under the upcoming 1998 Federal regulations and the fact that the natural gas has been the primary heating source were the bases for this decision. The action eliminated the need for compliance with the 1998 federal regulations regarding the UST upgrading, while the availability of a secondary source at the facility made it qualified for the interrupted rates from the natural gas company resulting in an overall savings in heating cost. The scope of work described in the contract is included in Appendix A.

3.0 PROJECT SITE DESCRIPTION

The Galleria Mall is located at 100 Main Street, White Plains, New York. Macy's Department Store (Store) is at the northeast section of the Mall. Court Street is on the east and Main Street is on the north side of the Store. The west and south boundaries of the Store are retail stores, occupied by commercial tenants.

The two USTs are located at the entrance of the loading and parking areas. Access to this area is from Main Street. The loading and parking area is at the street level and is "L" shaped. The pump room for the heating system is at the northeast of the loading area, and the sprinkler room is next to pump room. The location of the new AST, southeast of the loading area, was proposed by Clayton and approved by Macy's representatives familiar with the store operation.

The two USTs were installed in 1979 on a concrete pad, and were constructed of steel with an exterior asphalt coating on both tanks. According to the drawings found at the stores engineer's office, as well as field observations, the USTs were not vaulted and did not have an overflow protection system. However, they were equipped with fuel oil level gauges, located at the security office. A plan view and section of the USTs, as presented on the blue prints found at Store's engineer office, are included in the figure section of this report.

Clayton inspected the site at the beginning the project. Also, thorough interior inspection of the USTs were performed during the field activities. The objectives of the inspection were to identify the presence or likely presence of any petroleum products on the property under conditions that indicate an existing or a past release of petroleum products into the structures on the property or in the ground. New York State Department of Environmental Conservation

(NYSDEC), Region 3 and The City of White Plains, Building Department were contacted regarding any documented past release of petroleum products at the facility. Clayton's inspection and investigation revealed that there have been no past records, present signs and/or evidence of any leak or spill associated with the USTs.

4.0 REGULATORY REQUIREMENTS

Clayton identified, prepared, and secured all necessary notifications, registrations, and permits from regulatory agencies and local authorities prior to project start-up. The regulatory agencies involved included New York State Department of Environmental Conservation (NYSDEC) Petroleum Storage Facilities Division and the City of White Plains Building Department. Since the heating oil is used for consumption at the facility, federal regulations do not apply.

4.1 NEW YORK STATE REGULATIONS

The presence of two 10,000-gallon USTs containing heating oil required the facility to comply with the provisions of Part 612-614 of NYSDEC regulations regarding the Petroleum Storage Facilities. The facility was registered with NYSDEC and the registration number is 3-173665. These regulations require the owner or operator of a facility to notify the NYSDEC within 30-days prior to "substantial modification" of the facility. Tank closure or installation are defined by regulation as substantial modification.

Clayton prepared the application and notified NYSDEC Region 3 of the facility modification, including the in-place closure of the two USTs and installation of the new AST. Upon closure of the two USTs, the remaining petroleum storage tanks included the new 1,000-gallon AST at the loading area, and a small 100-gallon tank at the penthouse. Since NYSDEC Part 612-614 apply only to facilities with total capacity of 1,101 gallons or more, the facility became "unregulated" by NYSDEC upon completion of the project.

4.2 WHITE PLAINS BUILDING DEPARTMENT

The City of White Plains Building Department is the local authority with jurisdiction of construction related activities, including petroleum storage tank closure and installation. It requires a permit application be filed prior to the project start up. Clayton applied for a permit from White Plains Building Department, and provided it with the information, plans and specifications, and obtained the approval prior to the project start up. The White Plains Building Department requires compliance with the National Fire Protection Association (NFPA) 31 Standards for installation of oil burning equipment.

Copies of the NYSDEC and White Plains Building Department correspondence are included in Appendix B of the report.

5.0 FIELD ACTIVITIES

The field activities started on January 13, 1997. Site activities were performed in accordance with the Occupational Safety and Health Administration (OSHA) standards Title 29 CFR 1910 and 1926, and in accordance with other applicable federal, state, and local authority's regulations. Copies of the site activities daily logs are included in Appendix C. Also a copy of the project/site specific Health and Safety Plan (HASP), prepared by Clayton, is presented in Appendix D.

5.1 UST CLOSURE

Clayton subcontracted Environmental Products and Services, Inc. (EP&S), to perform the UST closure activities at the Macy's site in accordance with EP&S and Clayton's itemized scope of services. The NYSDEC guidelines regarding permanent closure of petroleum storage tanks and tank abandonment in-place were followed. These guidelines are specified in a memorandum to Regional Waste Water, and Solid and Hazardous Waste Engineers dated January 20, 1987, and modified July 19, 1988.

The USTs contained a combined residual volume of 7,500 gallons of Number Two (2) heating oil, which was pumped out and transferred to a recycling facility. The sludge in the bottom of the USTs was suctioned directly into a vacuum truck. The air inside of the USTs was continuously monitored by an oxygen meter and a lower explosive limit meter for the concentration of oxygen and the level of explosive gases.

EP&S provided the necessary confined space entry and rescue equipment, including tripod, hoist, and full body harness. Confined space entry trained EP&S personnel entered the USTs in appropriate personnel protective equipment (PPE), clothing, and respirators. Site safety precautions were observed and checked by Clayton.

The EP&S personnel cleaned the USTs using oil absorbent pads. Each UST was completely cleaned and dried. A thorough visual inspection of the USTs interior was performed by the EP&S personnel, using a high power flash light. The inspection revealed no holes, cracks, or pitted areas inside the USTs. The east UST had a polyliner interior coating and was in very good condition. The west UST did not have a polyliner interior coating, but it was also in good condition. The store engineer did not know the reason for one UST being lined and not the other. However, he mentioned that he has been instructed to use only the east UST.

Clayton originally proposed to use Petrofill, a chemically inert material, for in-place closure of the USTs, however due to White Plain Building Department's disapproval of the material, it was not used. January 14, 1997, concrete slurry was used to fill the two USTs up to grade level. The vent lines and other openings were also filled with concrete, thus permanently closing the USTs in-place. In order to avoid creating a heavy concrete bulk load at that location, Clayton specified a light concrete mixture (50 psi) for USTs abandonment. The mixture should be easy to brake, if necessary in the future.

5.2 AST INSTALLATION

Since the facility was unregulated following the closure of the two USTs, Macy's does not have to comply with NYSDEC regulations regarding the Petroleum Storage Facilities. However, compliance with NFPA 31, "Installation of Oil Burning Equipment", is required by White Plains Building Department.

A&P Rainaldi and EP&S were contracted by Clayton to perform the piping installation for the AST. During the week of January 13, 1997, A&P Rainaldi completed the installation of the return and suction lines, the fill line, and the liquid level gauge. EP&S completed the installation of the vent line and the tank high alarm by February 3, 1997.

The 1,000-gallon AST is a pre-fabricated, 10-gauge, steel tank purchased from Mohawk Metal Products Company, Inc. It is a horizontal cylinder 4 feet diameter and 10 feet long, and is situated on 10-gauge steel cradles. It meets the UL58 standards required by NFPA 31 for the aboveground petroleum storage tanks.

The AST is equipped with a 1,100 gallon secondary containment dike (6' x 12' x 2'), also 10-gauge steel, a liquid level gauge, and a battery operated high-level audio alarm. The AST was installed at the southeast corner of the loading and parking area of the Macy's Store. The pressure test was conducted on the AST prior to installation of the piping system. Also, the piping system was pressure tested before connection to the existing heating system. The one inch steel suction and return pipes were installed on the east wall and run to the heating system pump room, and the two-inch steel fill pipe was installed on the south wall of the loading area. The AST is vented outside via a two inch steel pipe. Traffic safety bollards were installed in front of the AST to prevent any potential traffic accidents. The AST filling procedure is mounted on the south wall near the fill port, and is also included in Appendix F, along with copies of the AST accessories specifications and information.

Privileged and Confidential

6.0 PROJECT COMPLETION

Inspectors from The White Plains Building and Fire Departments visited the site during the field activities. They expressed their satisfaction with the site operation. Mr. Peter Russo, Senior Code Enforcement Officer with the White Plains Building Department, was present during the closure of the USTs, and the pressure test of the AST and the pipe lines. He also visited the site after installation of the vent line and the completion of the project. Mr. Russo did not present any concerns regarding the project.

Clayton submitted the documentation regarding the transfer and disposal of the waste resulting from the tank closure activities, including a copy of the waste manifest to White Plains Building Department and received the final approval for the project verbally. Copies of this information is included in Appendix E.

7.0 RECOMMENDATIONS FOR NO FURTHER ACTION

The USTs have been closed in place according to the applicable regulations and NYSDEC guidance regarding the proper methods for abandonment in place. Site restrictions and public safety have been considered during planning and execution of the project. Final closure permits have been received from NYSDEC and White Plains Building Department.

Clayton anticipates no future environmental concerns or problems associated with the closure of the USTs, and therefore, recommends no further action for the USTs at the facility. Clayton recommends a copy of this report be kept at the facility for future use by the facility's management.


Prepared by:

Susan Bayat

Susan Bayat, P.E.
Senior Environmental Engineer
Environmental Management and Remediation
New York Regional Office

Reviewed by:

Kirit H. Vora, Vice President
Director, Corporate Accounts
Environmental Health And Safety
New York Regional Office



Mag 16.00
Wed Mar 05 17:49 1997
Scale 1:7,812 (at center)
500 Feet
200 Meters

- Secondary SR, Road, Hwy Ramp
- Major Connector
- State Route
- Interstate/Limited Access
- Primary State Route
- Railroad
- Point of Interest
- County Seat
- Population Center
- Lake, Ocean
- River

Figure 1
Site Location Map






Figure 2
Macy's Department Store Floor Plan



PLAN - UNDERGROUND FUEL OIL TANKS

SCALE 1/4" = 1'-0"

Figure 3
USTs Plan View




SECTION

SCALE: 1"=1'-0"

SEE STRUCTURAL DRAWINGS FOR ALL SLAB REINFORCING AT FINISHED GRADE

Figure 4
USTs Section View




LOADING AREA - THE UST MANHOLES



HEATING SYSTEM PUMP ROOM

CLAYTON PROJECT NO. 40-97140.00



PLACING THE AST'S SECONDARY CONTAINMENT DIKE



THE AST IS BEING LOCATED INSIDE THE CONTAINMENT DIKE

CLAYTON PROJECT NO. 40-97140.00



EP&S PERSONNEL READY TO ENTER THE UST

CLAYTON PROJECT NO. 97140.00



CONTINUOUS AIR MONITORING DURING THE USTs CLEANING



VACUUM THE BOTTOM SLUDGE IN THE USTs

CLAYTON PROJECT NO. 40-97140.00



DECONTAMINATION

CLAYTON PROJECT NO. 97140.00



CONCRETE SLURRY POURED DIRECTLY INTO THE USTs



CONCRETE SLURRY POURED DIRECTLY INTO THE USTs

CLAYTON PROJECT NO. 97140.00



USTs WERE FILLED WITH CONCRETE SLURRY UP TO THE GRADE LEVEL




USTs WERE FILLED WITH CONCRETE SLURRY UP TO THE GRADE LEVEL

CLAYTON PROJECT NO. 97140.00




AST PIPING AND CONNECTION TO THE HEATING SYSTEM




AST-SUCTION AND RETURN LINES-EMERGENCY VENT

CLAYTON PROJECT NO. 40-97140.00



INSTALLATION OF AST TRAFFIC PROTECTION BOLLARDS



AST 2-INCH VENT LINE INSTALLATION

CLAYTON PROJECT NO. 40-97140.00

Privileged and Confidential

APPENDIX A
MACY'S TANK UPGRADE CONTRACT

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

October 23, 1996

Mr. Paul McConocha
Environmental Program Manager
FEDERATED DEPARTMENT STORES
7 West 7th Street
Cincinnati, Ohio 45202

Clayton Proposal No. 96NYCEMR046
Transmitted Via: Telecopy (513) 579-7735:/7 Pages

Subject: Proposal to Provide Environmental Engineering and Management Services at the Galleria Mall in White Plains, New York

Dear Mr. McConocha:

In response to your Request For Proposal (RFP) dated October 10, 1996, Clayton Environmental Consultants, Inc. is pleased to present this proposal to provide environmental engineering and management services relating to the closure of two underground storage tanks (USTs) and the installation of an aboveground storage tank (AST) at the Galleria Mall in White Plains, New York. Clayton understands that the two USTs are adjacent to each other, have a capacity of 10,000 gallons each, contain a combined residual volume of approximately 7,000 gallons of No. 2 heating oil, and were installed in 1965.

SCOPE OF WORK

Due to their location, it is possible that removal of the tanks could damage the onsite building. Therefore, Clayton is developing this proposal to provide two options to Federated; removal and in-place closure. For either option, Clayton will prepare all necessary notifications forms for the New York State Department of Environmental Conservation (NYSDEC) and the local regulatory authorities, and secure all necessary permits. Clayton will also prepare a site specific Health and Safety Plan (HASP), in accordance with the Occupational Safety and Health Administration (OSHA), and implement traffic control measures. All field activities will be performed in accordance with the NYSDEC Spill Prevention Operations Technology Series (SPOTS) Memo #14: Site Assessments at Bulk Storage Facilities dated August 1, 1994. For the purposes of

this proposal, Clayton assumes that no contamination will be encountered during the tank closure activities.

TASK A: UST DECOMMISSIONING

Option 1: UST Removal

Clayton will oversee and supervise a New York State licensed tank closure contractor, which will perform the following tasks:

- Excavate to the top of the tanks to expose USTs;
- Remove all pumpable product (approximately 7,000 gallons);
- Clean and dispose of tank bottoms;
- Remove tanks from the excavation;
- Cut and properly dispose of the tanks;
- Remove the fill pipe, vent pipe, and product piping up to the building foundation for both tanks;
- Stockpile contaminated soil onsite, if present, and assuming that no extra field days are necessary;
- Backfill the excavation with certified clean fill material;
- Remove concrete debris; and
- Spread 6 inches of clean stone base and 10 inches of concrete.

Clayton will collect 8 post-excavation soil samples for laboratory analysis using USEPA method 8021 and 8270 for volatile organic compounds (VOCs) and semi-volatile organic compounds (SVs). All collected samples will be submitted to a New York-certified laboratory for analysis. Six soil samples will be collected from the base of the excavation sidewalls, and two will be collected from the bottom of the excavations along the center line of each UST. After the receipt of the analytical results, Clayton will prepare a tank closure report for your files.

Option 2: In-Place Closure of USTs

Clayton will oversee and supervise a licensed tank closure contractor, which will perform the following tasks:

- Remove all pumpable product (approximately 7,000 gallons);
- Clean and dispose of tank bottoms;
- Fill each tank with a liquid concrete slurry

Clayton will collect 8 post-excavation soil samples for laboratory analysis using USEPA method 8021 and 8270 for VOCs and SVs. All collected samples will be submitted to a New York-certified laboratory for analysis. Six soil samples will be collected by cutting through the sides of each tank, and two soil samples will be collected by cutting through the tank bottom along the center line of each UST. After the receipt of the analytical results, Clayton will prepare a tank closure report for your files.

TASK B: AST INSTALLATION

Clayton assumes the following regarding the AST installation:

1. The AST will be used as a backup for the building generator;

2. It will be located just outside the wall of the boiler room. No more than 50 feet of piping will be required; and

3. The building is equipped with a pumping system; no pumping system will need to be installed as part of the AST installation.

The AST system will consist of a 1,000-gallon, gauge 10 steel tank mounted on steel cradles just outside the boiler room. The tank and the steel piping will be painted for rust protection. The White Plains Building Department requires that the tank be equipped with secondary containment, and vandalism protection. Clayton will prepare engineering drawings to the White Plains Building Department in order to obtain the necessary permits to install the AST. Because of the tank's size, no State permits will be necessary. For the purposes of this proposal, Clayton assumes that the UST removal activities and the AST installation activities will be performed concurrently.

GENERAL CONSTRUCTION CONDITIONS

The location of all subsurface structures such as pipes, tanks, cables, and utilities within the property lines of the project shall be correctly designated by Federated Department Stores. Clayton will rely on the accuracy of such information provided by Federated Department Stores. If Federated Department Stores fails to provide such information or the information provided is inaccurate, Clayton shall not be responsible for the damage caused to the unknown or incorrectly designated subsurface structures nor for any injury to persons that result from the improper designation.

Clayton will provide these services using its commercially reasonable best efforts consistent with the level and skill ordinarily exercised by members of the profession currently practicing under similar conditions. Clayton will work with site managers during the field activities to attempt to minimize disruption to loading dock activities.

SCHEDULE

Clayton will be pleased to begin this project immediately following receipt of your written authorization to proceed. Approval of the NYSDEC tank closure notification is anticipated to take approximately 4 weeks. The UST closure activities will be performed immediately after the NYSDEC approval is received. Clayton assumes that 3 to 4 days of field work will be required to remove the USTs and repave. Approximately 2 days of field work will be required to abandon the USTs in place. Clayton further assumes that the AST can be installed in 2 to 3 days. Clayton will present the closure assessment summary report and AST installation report within 30 days following completion of field activities.

FEES

Clayton proposes to provide the services described in the scope of work as follows:

TABLE A: UST REMOVAL COST BREAK DOWN	EST. COST
TASK 1: MOBILIZATION	
Prepare NYSDEC and Westchester County Health Department Tank Closure Notification forms and obtain White Plains Building Permit.	$715
Prepare a site specific HASP.	$155
TASK 2: UST REMOVAL ACTIVITIES	
Implement traffic control measures.	No cost
Excavate to expose USTs.	$3,250
Remove 7,000 gallons of pumpable product, clean and dispose of tank bottoms. Additional product will be removed and disposed of at a cost of $0.65 per gallon	$2,550
Remove tanks from the excavation.	$6,050

TABLE A: UST REMOVAL COST BREAK DOWN	EST. COST
Cut and properly dispose of the tanks.	$825
Remove fill pipes, vent pipes, and product piping for each tank.	$550
Stockpile contaminated soil, if necessary (assume same day activities).	$250
Backfill the excavation with approximately 100 cubic yards of certified clean fill.	$2,970
Remove and dispose of concrete debris.	$2,750
Spread 6 inches of clean stone base and 10 inches of concrete (appr. **1,200** square feet).	$2,900
Collect 8 post-excavation samples and analyze using EPA Methods 8021 & 8270	$2,640
Oversee and supervise all field activities.	$2,495
TASK 3: REPORTING	
Prepare tank closure report.	$1,500
TOTALS:	$29,600

Although not specified in the RFP, Clayton assumes that a 30' by 40' area will need to be repaved, and recommends that compaction testing be performed on the backfill prior to paving. Clayton further recommends that rebar be placed over the excavation prior to concrete pouring for structural reasons. Compaction testing and the installation of rebar can be performed for an additional $4,600.

Although not specified in the RFP, Clayton recommends a geophysical survey of the proposed excavation area due to the proximity of underground utilities. The ground-penetrating radar survey can be provided for an additional $2,300.

TABLE B: ABANDON-IN-PLACE COST BREAK DOWN	EST. COST
TASK 1: MOBILIZATION	
Preparation of NYSDEC and Westchester County Health Department Notification.	$715
Preparation of a site specific HASP.	$155
TASK 2: UST IN-PLACE CLOSURE	

TABLE B: ABANDON-IN-PLACE COST BREAK DOWN	EST. COST
Implementation of traffic control measures, if necessary	No cost
Remove approximately 7,000 gallons of pumpable product, clean and dispose of tank bottoms. Additional product will be removed and disposed at a cost of $0.65 per gallon	$2,550
Fill each tank with flowable concrete (approximately 100 cubic yards total)	$11,000
Collect 8 soil samples and analyze using EPA Methods 8021 & 8270	$2,640
Oversee and supervise field activities	$2,715
TASK 3: REPORTING	
Prepare tank closure report	$1,500
TOTALS:	$21,275

The AST can be installed for an estimated cost of **$9,800**. Installation of a level gauge can be performed for an additional $3,900, and installation of an overfill protection alarm can be performed for an additional $1,200. Clayton will assess an additional $600 for oversight if the USTs are to be abandoned in place during the AST installation.

Clayton's will not exceed the estimated fee without your written authorization. Clayton's fee includes out-of-pocket expenses (e.g., travel expenses) reasonably incurred in the performance of the work, and other direct costs, billed on a cost plus 10% basis. Direct costs include subcontractor costs, reproduction costs, mileage, and laboratory analysis.

Any unexpected conditions or concerns that become apparent during the project may require a revision in the project scope and fees. Clayton will immediately notify you of any necessary change in project scope and fees, and obtain written confirmation of such changes.

The project scope and estimated fees presented in this proposal are based on the information provided by Federated and an onsite visual inspection performed on October 14, 1996. Any unexpected conditions or concerns that become apparent during the project may require a revision in the project scope and estimated fees. Clayton will immediately notify Federated Department Stores of any necessary changes in project scope and fees, and obtain written confirmation of such changes.

Clayton will perform the proposed scope of work in accordance the negotiated terms and conditions between Federated Department Stores and Clayton which are incorporated in this proposal. This proposal will be valid for 30 days.

ACCEPTANCE OF PROPOSAL

Clayton appreciates the opportunity to submit this proposal to Federated Department Stores. For your convenience, the proposal is presented in a form that can be accepted as an agreement. To accept this proposal, please sign below and return a copy to me.

If you have any questions or need additional information, please call me at (908) 225-6040. We look forward to working with you on this project.

Sincerely,

Benjamin Alter, P.G.
Manager, Geosciences and Remediation
Environmental Management and Remediation
New York Regional Office

Reviewed by,

Kirit H. Vora
Director, Corporate Accounts
Environmental Health Services
New York Regional Office

Proposal No.: 96NYCEMR046

This proposal accepted by: _____

Title: _____

Company: FEDERATED DEPARTMENT STORES

Date: _____

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

October 23, 1996

Mr. Paul McConocha
Environmental Program Manager
FEDERATED DEPARTMENT STORES
7 West 7th Street
Cincinnati, Ohio 45202

Clayton Proposal No. 96NYCEMR046, Addendum A
Transmitted Via: Telecopy (513) 579-7735:/2 Pages

Subject: **Addendum A to Proposal to Provide Environmental Engineering and Management Services at the Galleria Mall in White Plains, New York**

Dear Mr. McConocha:

In response to our conversation earlier today, Clayton Environmental Consultants, Inc. is pleased to present this Addendum A to Clayton Revised Proposal No. 96NYCEMR046 to provide environmental engineering and management services relating to the closure of two underground storage tanks (USTs) and the installation of an aboveground storage tank (AST) at the Galleria Mall in White Plains, New York.

- If the in-place closure option is chosen for the USTs, Clayton will perform precision tightness testing prior to their closure. Clayton will retain a certified testing firm to conduct the tests. You will be informed immediately if the tests indicate tank failure. Clayton can perform this portion of the scope of work for an estimated fee of $2,000. Clayton will not be responsible for any damages to the USTs caused by the testing.

- Clayton will provide its analytical services for a cost of $330 per sample, as follows:

Volatile Organic Compounds	$110
Base-Neutral Compounds	$220

- Clayton's incremental labor rates are as follows:

TITLE	RATE ($/hr)
Director	$130
Manager	$100
Senior Engineer	$85
Staff Engineer	$65
Admin. Assistant	$35

ACCEPTANCE OF PROPOSAL ADDENDUM

Clayton appreciates the opportunity to submit this proposal addendum to Federated Department Stores. For your convenience, the proposal is presented in a form that can be accepted as an agreement. To accept this addendum, please sign below and return a copy to me.

If you have any questions or need additional information, please call me at (908) 225-6040. We look forward to working with you on this project.

Sincerely,

Benjamin Alter, P.G.
Manager, Geosciences and Remediation
Environmental Management and Remediation
New York Regional Office

Reviewed by,

Kirit H. Vora
Director, Corporate Accounts
Environmental Health Services
New York Regional Office

Proposal No.: 96NYCEMR046, Addendum A

This proposal accepted by: _____

Title: _____

Company: FEDERATED DEPARTMENT STORES

Date: _____

Federated
DEPARTMENT STORES, INC.
7 West Seventh Street · Cincinnati, Ohio 45202-2471

October 29, 1996

REC'D OCT 31 1996

Mr. Kirit Vora
Clayton Environmental
Raritan Center, 160 Field Crest Avenue
Edison, NJ 08837

RE: Macy's East - White Plains
Contract #601073

Dear Kirit:

Attached are two copies of our Agreement for work at the subject project. Please review, sign and return all copies of the contracts to me along with your Certificate of Insurance on or before November 12, 1996. Please note that no changes can be made to these contracts.

All invoices and appropriate back-up for payment should be submitted to the attention of Tom Morehead, Capital Control, at this address. **Please include the contract number on all invoices in order to expedite payment.**

Should you have any questions, please do not hesitate to call me directly at (513) 579-7241.

Very truly yours,

Paul R. McConocha
Environmental Project Manager

Attachments

/bjc

CONTRACT #: 601073

PROJECT: Macy's White Plains UST
PROJECT #: 96608

CLIENT-CONSULTANT AGREEMENT

THIS AGREEMENT is effective on the 24th day of October, 1996, by and between CLAYTON ENVIRONMENTAL (hereinafter "Consultant") and FEDERATED CORPORATE SERVICES, INC., a Delaware corporation (hereinafter "Client" or "Owner").

W I T N E S S E T H

WHEREAS, Client desires that Consultant perform consulting services in connection with Client's asbestos control program as described in the Exhibits hereto; and

WHEREAS, Consultant has agreed to perform such services in accordance with the terms and conditions set forth herein.

NOW, THEREFORE, in consideration of the foregoing and of the mutual covenants contained herein, Client and Consultant agree as follows:

1. Definitions.

As used in this Agreement, the following terms shall have the meanings hereinafter set forth:

(a) "ACM" means asbestos containing material which is material containing greater than 1% of asbestos (PLM method) of any type or mixture of types or as defined by Federal, State and Local laws, regulations, ordinances and rules.

(b) "Agreement" means this Consulting Agreement, together with the following Exhibits attached hereto, and the documents, if any, required thereby, which are made a part hereof for all purposes:

EXHIBIT	DESCRIPTION
A	Description of Services
B	Site Location(s)
C	Consultant's Fee
D	Project Job Book Guidelines/Instructions
E	Duties, Responsibilities and Limitations of Authority of Project Monitor

F	Consultant Travel Guidelines and Information
G	Special Conditions
H	ESA - Specifications
I	Confidentiality Agreement

(c) "Client Parties" shall mean Client, its parent, subsidiaries, divisions, affiliates, and their respective officers, directors, employees, agents, successors and assigns.

(d) "Client's Representative" means the individual or individuals designated by Client from time to time to act for it in all matters relating to this Agreement. The individual initially designated as Client's Representative is set forth in subsection 23(b) with his address, telephone, and telecopier numbers. The Client's Representative may be changed by notice.

(e) "Consultant's Representative" means the individual designated by Consultant from time to time to act for it in all matters relating to this Agreement. The individual initially designated Consultant's Representative is set forth in Section 21 with his address, telephone, and telecopier numbers. The Consultant's Representative may be changed by notice.

(f) "Environmental Law" means any federal, state or local law, statute, ordinance, or regulation now or hereafter enacted, or amended, passed or promulgated pertaining to health, industrial hygiene or environmental conditions, or common law related to the same, including, without limitation, the Comprehensive Environmental Response, Compensation and Liability Act of 1980, 42 U.S.C. Section 9601 et seq., as amended by the Hazardous and Solid Waste Amendments of 1984, Pub.L. No. 98-616, the Superfund Amendments and Reauthorization Act 1976, 42 U.S.C. Section 6901 et seq., as the Solid Waste Disposal Act, 42 U.S.C. Section 6901 et seq., the Federal Clean Air Act, 42 U.S.C. Section 7401 et seq., the Federal Water Pollution Control Act of 1972 and the Federal Clean Water Act of 1977, 33 U.S.C. Section 1251 et seq., the Federal Insecticide, Fungicide, and Rodenticide Act, 7 U.S.C. Section 135 et seq., as amended by the Federal Environmental Pesticide Control Act of 1972, Pub.L. No. 92-516, the Federal Toxic Substances Control Act, 15 U.S.C. Section 2601 et seq., the Federal Safe Drinking Water Act, 42 U.S.C. Section 300 (f) et seq., the Emergency Planning and Community Right-To-Know Act of 1986, 42 U.S.C. Section 11001 et seq., the Occupational Safety and Health Act of 1970, 29 U.S.C. Section 651 et seq., the Hazardous Material Transportation Act, 49 U.S.C. Section 1801 et seq., and the National Emission Standards for

Hazardous Air Pollutants, 40 C.F.R. Part 61, under the Clean Air Act, 42 U.S.C. Section 7412.

(g) "Fee" is defined in subsection 3(d).

(h) "Hazardous Substance" includes without limitation (1) those substances included within the definitions of "hazardous substances," "hazardous materials", "toxic substances", "hazardous wastes" or "solid wastes" in any Environmental Law; (2) petroleum products and petroleum byproducts and, (3) asbestos.

(i) "Services" means those services to be performed by Consultant pursuant to this Agreement.

(j) "Site" means each and every store and/or warehouse location listed in Exhibit B.

(k) "Work Area" means those areas within and around the Site where Consultant is performing its Services.

2. Services.

Consultant shall provide the Services as set forth in Exhibit A and Exhibit E. Consultant shall commence providing the Services upon the earlier of execution of this Agreement or receipt of Client's Notice of Acceptance, or at such other time as the parties shall agree upon in writing.

3. Compensation and Payment.

(a) Client shall pay Consultant as compensation for the Services the amounts set forth in Exhibit C.

(b) Consultant shall submit, in a timely manner, separate reports for each Site to Client's Representative. The reports shall be prepared in such form as Client shall request. Consultant shall submit detailed invoices to Client's Representative on a monthly basis showing the Services performed, who performed the Services, their hourly billing rate and the number of hours billed, the charges therefor and any recoverable expenses for the prior month. In the event Consultant becomes aware of a potential cost over-run, Consultant shall promptly notify Client in writing and provide reasons for the same. Notwithstanding anything to the contrary contained in this Agreement, there shall be no markup for any reimbursable or out-of-pocket items, including, but not limited to insurance, taxes, license fees, permit fees, in-house recoverables, and travel expenses as set forth in Exhibit F.

(c) Client shall pay Consultant's invoice within thirty (30) days of receipt, provided, however, if Client objects

to all or any portion of an invoice, Client's Representative shall notify Consultant's Representative of Client's objection within twenty-one (21) days of receipt of invoice and the parties shall make every effort to settle the disputed portion of the invoice. Client shall pay that portion of the invoice which is not in dispute within the thirty (30) day period for payment.

(d) Notwithstanding the foregoing, compensation and payment to Consultant for Services rendered hereunder shall not exceed, in all respects, the "Fee." The Fee is the sum of the actual cost of the Services performed but in no event to exceed the fixed amount stated in Exhibit C. Standard hourly rates, as set forth on Consultant's Schedule of Charges, shall be charged for all Services not included hereunder pursuant to Exhibit A.

4. Consultant's Obligations

(a) Consultant covenants and warrants that the Services will be performed in a professional manner in accordance with that level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions.

(b) Consultant shall furnish at its expense all labor, services, permits, licenses, materials, insurance, equipment, tools, and other facilities reasonably necessary for performance of the Services and shall pay all applicable taxes.

(c) Consultant shall exercise all reasonable care in the performance of the Services to avoid damaging the property of Client and others on or near the Site.

(d) Consultant shall provide Client, promptly after Consultant's receipt thereof, copies of all notices, permits, licenses, variances and exemptions obtained with respect to the Services, and all applications and supporting documents related thereto.

(e) Consultant shall use its best efforts to ascertain the location of all subterranean structures and hidden conditions (including but not limited to utility lines, pipes, and telephone cables) that might become damaged or otherwise adversely affected by the performance of the Services. Consultant shall be solely liable for all damage to such subterranean structures and conditions, including consequential and incidental damages resulting therefrom, to the extent such damage is proximately caused by Consultant's negligent or willful conduct or omission or the negligent or willful conduct or omission of those under the control of Consultant.

(f) If Consultant breaches the provisions contained in this Section 4, Consultant shall correct any Services at no additional charge to Client. In addition, Consultant shall

repair, correct and remedy any and all of Client's damages arising out of or resulting from such breach unless such damages arise solely from the negligent act or omission or willful misconduct of Client, its agents, employees, and others under Client's sole control.

5. Indemnification.

(a) Consultant shall indemnify, defend, and hold harmless Client Parties against and from all costs, expenses, liabilities, losses, damages, injunctions, suits, actions, fines, penalties, claims, and demands of every kind or nature (including but not limited to attorney's fees and court costs), by or on behalf of any person, entity or governmental authority arising out of (1) any failure by Consultant to perform any of the provisions, agreements, terms, covenants, or conditions of this Agreement or (2) any accident, injury or damage occurring on or about the Site caused by the willful or negligent act or omission of Consultant, its agents, servants, employees, independent contractors or subcontractors. Consultant shall be solely liable for the safety of the Work Area and shall defend, indemnify and hold Client Parties harmless against all claims by persons injured in the Work Area, whether such persons be employees, licensees, invitees, or trespassers; provided, however, that Consultant shall not be liable for any accident, injury or damage caused solely by the negligent act or omission or willful misconduct of Client.

(b) Client shall indemnify, defend, and hold harmless Consultant against and from all costs, expenses, liabilities, losses, damages, injunctions, suits, actions, fines, penalties, claims, and demands of every kind or nature (including but not limited to attorney's fees and court costs), by or on behalf of any person, entity or governmental authority arising out of (1) any failure by Client to perform any of the terms, covenants, or conditions of this Agreement or (2) any accident, injury or damage occurring on, about or outside the Site to the extent caused by the willful or negligent act or omission of Client, its agents, servants, or employees; provided, however, that Client shall not be liable for any accident, injury or damage caused by the negligent act or omission or willful misconduct of Consultant, its agents, employees, or contractors.

(c) Client shall have the right, if it so elects, and at its own expense, to participate in the defense of any claim or action referred to in subsection 5(a), but such participation shall not affect Consultant's liability with respect to such claim or action.

(d) Consultant shall have the right, if it so elects, and at its own expense, to participate in the defense of any claim or action referred to in subsection 5(b), but such

participation shall not affect Client's liability with respect to such claim or action.

6. Insurance.

(a) Policies. Consultant shall procure, pay for and maintain the insurance set forth below:

1. Worker's Compensation as required by law; Employer's Liability Insurance of not less than $100,000 for each accident, $100,000 for each disease, and $500,000 policy limit on diseases with Client as an additional insured.

2. Commercial General Liability Insurance, Including Contractual Liability covering, but not limited to, the liability assumed under subsection 5(a), fully insuring Consultant's liability for injury to or death of Client's employees and third parties, extended to include personal injury liability coverage, and for damage to property of third parties, with the following limits on an "occurrence" basis:

Injury or death	$1,000,000 each occurrence/ $2,000,000 aggregate
Property Damage	$1,000,000 each occurrence/ $2,000,000 aggregate

The policy shall include Broad Form Property Damage coverage extended to apply to completed operations, XCU exclusions removed.

3. Client's Protective Liability Insurance. Coverage shall be on an "occurrence" basis. The policy shall be issued by the same insurance company that carries Consultant's Commercial General Liability Insurance with the following limits for each occurrence:

Bodily Injury	$1,000,000 each occurrence/ $2,000,000 aggregate
Property Damage	$1,000,000 each occurrence/ $2,000,000 aggregate

4. Comprehensive Automobile and Truck Liability Insurance covering owned, hired and non-owned vehicles with $1,000,000 combined single limit coverage.

5. Professional Liability Coverage in a minimum amount of $1,000,000 for each occurrence with a $1,000,000 minimum aggregate limit. If this coverage is included in the Commercial General Liability Insurance, this separate policy is not required provided the limits referred to in this subsection

6(a)(5) are separately available under such Commercial General Liability Insurance.

(b) Consultant shall name Client Parties and Client's Representative as additional insureds under the insurance referred to in subsections 6(a)(2), 6(a)(3), and 6(a)(4), and Consultant warrants that the aggregate limits referred to in subsections 6(a)(2) and 6(a)(3) shall be unimpaired as of the date hereof, and Consultant agrees to maintain an unimpaired aggregate limit of at least $1,000,000 during the term of this Agreement.

Certificates indicating that the required insurance is in force shall be delivered to Client prior to commencement of the Services, and shall provide thirty (30) calendar days prior written notice of cancellation be given Client.

(c) No policy submitted by Consultant shall be subject to any limitations, conditions or restrictions deemed inconsistent with the intent of these insurance requirements. Client's decision thereon shall be final.

(d) All policies are to be written through a company duly authorized to transact that class of insurance business in the state where the Site is located. The insurers providing coverage thereunder must have a rating of "B+" or better in the current edition of Best's Key Rating Guide plus a Best's Financial Size rating of VII or better. All policies should (i) stipulate that such insurance is primary and is not additional to any insurance carried by Client or any additional insureds; (ii) waive any and all rights of subrogation against Client; and (iii) contain cross liability or severability of interest endorsement. Should Consultant fail to maintain or renew any insurance provided for hereunder, or to pay the premium, or to deliver to Client any of such certificates, Client, at its option, but without obligation to do so, may, upon five days' notice to Consultant, procure such insurance and any sums so expended by Client (together with Client's reasonable administrative expense in procuring such insurance) shall be deducted from the compensation due Consultant.

(e) Neither the approval, disapproval or failure to act by Client regarding any insurance supplied by Consultant, nor the bankruptcy, insolvency or denial of liability by any insurance company shall relieve Consultant of full responsibility or liability for damages and accidents as set forth herein.

(f) Any insurance policy may be written in combination with any of the others, where legally permitted, but none of the specified limits may be lowered thereby.

(g) When requested by Client, copies of any of the policies must be furnished to Client; otherwise, Client shall require certificates only.

(h) There shall be no deductibles and/or retention amounts or self-insurance programs maintained by Consultant with respect to any of the foregoing insurance without Client's prior written approval.

7. Compliance with Law.

Consultant, and any persons over whom Consultant has supervision or control (including, without limitation, any agents, employees, contractors or other consultants) shall perform the Services in accordance with and shall comply with all applicable laws, ordinances, requirements, directions, rules, statutes, regulations and orders currently existing or hereafter enacted of any and all governmental authorities or agencies. Client shall cooperate with Consultant in obtaining any permits or licenses required for the performance of the Services.

8. Suspension and Termination of Services.

(a) Client, in its sole discretion, may suspend or terminate at any time, with or without cause, all or any part of the Services. In the event of such suspension or termination, and providing Consultant is not in default of this Agreement, Client shall pay Consultant for all Services properly performed prior to the effective date of said notice for which payment has not already been made, and shall reimburse Consultant for reimbursable expenses incurred by Consultant prior to the effective date of said notice. The effective date of the suspension or termination shall be the date so specified in the notice and, in no event shall the effective date be earlier than the date such notice is received.

(b) Consultant may suspend performance of all, but not less than all, of the Services by giving Client ten (10) days' prior written notice thereof, but only if:

(i) Client gives Consultant written notice of suspension under subsection 8(a) and such suspension materially affects the ability of Consultant to perform the unsuspended Services, or

(ii) Client is in default with regard to its payment obligations under Section 3 (except for any invoice or portion thereof to which Client has objected in accordance with the provisions of Section 3) or is otherwise in default pursuant to this Agreement, and such default continues for a period of ten (10) days following written notice to Client of such default.

9. Confidentiality.

(a) Neither party hereto shall disclose any trade secrets or proprietary information expressly identified as such (collectively, the "Confidential Information"), except such Confidential Information:

(i) which has been published and becomes part of the public domain other than by the acts or omissions of Consultant or its officers and employees,

(ii) which has been lawfully furnished or made known to Consultant by third parties (other than those acting directly or indirectly for or on behalf of Client) without restriction on Consultant as to its disclosure or use,

(iii) which was in Consultant's possession at the time it entered into this Agreement and was not acquired by Consultant or its employees directly or indirectly from Client or anyone acting directly or indirectly for or on behalf of Client,

(iv) which is required by any subpoena, notice of deposition or other discovery request or otherwise as required by law, or

(v) the disclosure of which is consented to in writing by the party to which the Confidential Information relates.

(b) If any legal proceedings (including, but not limited to, any subpoenas, notices of deposition or other discovery requests) are instituted against a party to obtain Confidential Information, such party shall immediately notify the other party in writing with respect thereto.

(c) Each party shall restrict the knowledge of all Confidential Information to its officers, employees and others who are directly connected with the performance of this Agreement and have need of such knowledge.

(d) Confidential Information includes the asbestos surveys prepared by, on behalf of or for Client Parties, including those prepared by Consultant. All reports and surveys concerning the presence or absence of ACM prepared by Consultant shall be clearly marked with the following legend: "Privileged and Confidential: Prepared at the Direction of Legal Counsel" and shall be considered Confidential Information. In addition, any other documents so marked shall also be considered Confidential Information.

(e) Notwithstanding the foregoing, nothing herein shall restrict or otherwise limit Client, its attorneys,

consultants and agents, from disclosing to or using with Client Parties, Client's attorneys, consultants, bankers and other advisors, any and all information, whether oral or written, whether contained in reports, surveys, or otherwise, developed hereunder or required by this Agreement.

(f) Consultant shall not publish or use the names of Client or Client Parties or refer to any of Client's or Client Parties' Sites or to the Services performed by Consultant for Client hereunder for any purpose other than those connected with the performance of the Services herein, without Client's prior written consent.

(g) The parties hereto mutually and expressly agree that all work product produced pursuant to this Agreement is Confidential Information and is the sole property of Client.

(h) In addition to the above referenced terms and conditions, attached as Exhibit I to this Agreement is a Confidentiality Agreement that has been executed by both parties. That Confidentiality Agreement is incorporated by reference into this Agreement as if fully set forth herein.

10. Patents.

Any and all inventions or discoveries relating to the Services, including improvements and modifications to existing products or processes, whether or not patentable, and applications for Letters Patent covering said inventions or discoveries as may be made and/or conceived by Consultant or its employees during the term of this Agreement and for a period of one year thereafter, shall be the sole property of Consultant. Any action by Consultant pursuant to this Section 10 shall be consistent with its confidentiality obligations set forth in Section 9.

11. Status of Consultant.

Consultant is an independent contractor and is not an agent or employee of Client. Neither party shall have any authority to supervise the employees, representatives or subcontractors of the other party, nor to make any statements, representations or commitments of any kind or take any other action which will be binding upon the other party except as specifically provided in this Agreement.

12. Force Majeure.

No delay or failure in performance by either party hereto shall constitute default hereunder or give rise to any claim for damages, if, and to the extent, such delay or failure is caused by an occurrence beyond the control and without the fault or

negligence of the party affected and if such party was unable to prevent or provide against such delay or failure by exercise of reasonable diligence including, but not limited to, acts of God or the public enemy, expropriation or confiscation of facilities, changes in applicable law, war, legal disputes, rebellion, sabotage or riots, floods, unusually severe weather fires, explosions, or other catastrophes, strikes or any other similar acts of employees, or similar occurrences (collectively, "Force Majeure"). Unless such Force Majeure substantially and materially frustrates performance of this Agreement, it shall not operate to excuse, but only to delay, performance hereunder.

13. Access to Site and Information.

In order that Consultant may perform the Services:

(a) Consultant will have reasonable access to the Site(s) and any facilities therein to which access is required to perform the Services.

(b) Client will give prompt notice to Consultant whenever it becomes aware of any development that affects the scope or timing of the Services.

(c) Information or services under Client's control shall be furnished by Client with reasonable promptness to avoid delay in the orderly progress of the Services.

14. Assignment of Agreement.

Consultant may not assign (whether by operation of law or otherwise) this Agreement or any part hereof without the prior written consent of Client, which consent may be granted or withheld in Client's sole discretion.

15. Subcontracts.

Consultant may not subcontract all or any part of the Services without the prior written approval of Client, which approval may be granted or withheld in Client's sole discretion. Consultant shall secure from all approved subcontractors their written agreement to be bound by the terms of this Agreement, except that insurance coverages and limits may differ from those specified in subsection 6(a), and shall promptly provide Client a copy of such subcontractor's written agreement. Consultant shall also provide Client with evidence of proficiency, including documentation of state certification, EPA CLP status, etc. for any laboratories Consultant plans to use in connection with the performance of Services.

16. Survival of Obligations.

The obligations of the parties under this Agreement shall survive any termination or suspension of the Services or the expiration or termination of this Agreement.

17. Consultant's Understanding.

Consultant expressly understands and agrees that Consultant's Services involve or may involve work in, with, or around Hazardous Substances and specifically understands and acknowledges that work involving Hazardous Substances requires special care and control. Consultant represents and warrants that it and its employees and independent contractors each has the knowledge, information, training and skill to perform the Services in compliance with all applicable laws, including but not limited to Environmental Laws. Consultant further represents and warrants that all appropriate personnel have been trained and licensed in health, safety, and Hazardous Substances procedures and management as required by applicable laws (including Environmental Laws) and current industry practice.

18. Consultant's Equipment.

Consultant shall decontaminate and/or properly dispose of, if necessary, and at no additional expense to Client, all Consultant's materials, supplies, and work-related apparatus, including but not limited to machinery, equipment, tools, and accessories used on the Site(s). At the completion of performing Services hereunder Consultant shall remove and properly dispose of all of its waste materials, rubbish, and debris from and about the Site as well as all its tools, appliances, equipment, machinery, and surplus materials, and shall leave the Site clean and ready for its ordinary use.

19. Time.

Time is of the essence of this Agreement.

20. Entire Agreement.

This Agreement constitutes the entire agreement between the parties with respect to the Services and supersedes all prior negotiations, representations or agreements relating thereto, written or oral. Unless otherwise provided for herein, no amendments, changes, alterations or modifications of this Agreement shall be effective unless in writing signed by Client's Representative and Consultant's Representative, or their superiors. Each of the parties has been involved in preparing the provisions of this Agreement and no ambiguity in or interpretation of this Agreement or any of its provisions shall be resolved or determined in favor of or against a party hereto

based on whether or not such party has prepared this Agreement or any provision hereof.

21. Notices.

Any notice required or permitted to be given under this Agreement shall be in writing and shall either be hand delivered, sent by certified mail, return receipt requested, or by commercial messenger service providing a signed receipt, and shall be effective upon receipt and shall be sent to the address hereinafter noted. Each party shall acknowledge in writing the receipt of any notice delivered in person.

If to Consultant, addressed to:

CLAYTON ENVIRONMENTAL
Raritan Center, 160 Field Cres Avenue
Edison, NJ 08837

Attention: Kirit Vora

Telephone: 908/225-6040
Telecopier: 908/225-4577

If to Client, addressed to:

FEDERATED CORPORATE SERVICES, INC.
7 West Seventh Street
Cincinnati, OH 45202

Attention: Paul McConocha

Telephone: 513/579-7241
Telecopier: 513/579-7735

with a copy to Client's Representative:

FEDERATED CORPORATE SERVICES, INC.
7 West Seventh Street
Cincinnati, Ohio 45202

Attention: Law Department

Telephone: 513-579-7900
Telecopier: 513-579-7555

22. Conflicts.

(a) Client shall not be bound by any provisions which are different from or in addition to the provisions of this Agreement (whether or not they would materially alter this

Agreement). Acceptance by Client of a work order on Consultant's form (or other similar Consultant's form) shall not constitute Client's agreement to the provisions printed or otherwise appearing on such form unless each provision is specifically accepted and initialed by Client.

(b) In the event the provisions in the Exhibits are in conflict with the provisions found elsewhere in this Agreement, the provisions in the Exhibits shall control.

23. Successors and Assigns.

This Agreement shall inure to the benefit of and be binding upon the successors and permitted assigns of the parties hereto.

24. Counterparts.

This Agreement may be signed in two or more counterparts, each of which shall be treated as an original but, when taken together, shall constitute one and the same instrument.

25. Governing Law.

This Agreement and the legal relations of the parties hereto concerning each Site shall be governed by the laws of the State in which such Site is located.

26. Captions.

Headings of particular Sections are inserted only for convenience and are in no way to be construed to be a part of this Agreement or as a limitation of the scope of the Sections to which they refer.

27. Severability.

If any provision of this Agreement shall be invalid, illegal, or unenforceable, the validity, legality, and enforceability of the remaining provisions shall not be in any way affected or impaired thereby.

28. Waiver.

(a) No waiver of the provisions of this Agreement shall be binding and effective unless it (1) is in writing, (2) is signed by the party against whom the waiver is sought, (3) specifically sets forth the provision that is being waived, and (4) expressly waives that provision.

(b) A waiver of any breach of a provision of this Agreement shall be for that one time only and not for any subsequent breach.

29. Attorneys Fees, Etc.

In any action to enforce any of the provisions of this Agreement, the party which substantially prevails in such action shall be entitled to its reasonable costs and expenses, including, but not limited to, experts' fees, attorneys' fees, consultants' fees and court costs.

30. Venue.

The parties agree that the state or Federal trial court with subject matter jurisdiction located in Cincinnati, Hamilton County, Ohio is the exclusive jurisdiction and venue for any litigation between the parties under this Agreement.

31. Audit and Records.

(a) Consultant shall maintain and preserve, for the time period described in subsection 31(b), all records and documents (including notes, computer diskettes, etc.) in its possession or under its control (including those held by its employees, agents, accountants, subcontractors, or attorneys) which relate in any way to the Services, despite any document retention policy to the contrary ("Records"). Client, its attorneys, agents and authorized representatives, shall have the right, with or without notice, during the time period described in subsection 31(b), to examine and copy all such Records and shall have open access to said Records for any purpose, including but not limited to the purpose of audit, inspection and reproduction. Consultant shall be given a minimum of one (1) working day to assemble necessary information. Client shall reimburse Consultant for the cost of reproduction of Records (including labor and other reasonable expenses) incurred by Consultant.

(b) The time period for purposes of subsection 31(a) shall be as follows:

(i) Where claims have been made arising out of the performance of the Services, the time period shall end after the later of six (6) years from the date of final payment under this Agreement or when arbitration, litigation, or the claims have been fully resolved;

(ii) Where a governmental authority or agency (such as the U.S.E.P.A.) has required that Client have the Services performed, the time period shall end six (6) years after termination of the order requiring such Services;

(iii) In all other cases, the time period shall end six (6) years after final payment under this Agreement.

(c) Consultant shall not submit to any agency or third party any data, records, reports, summaries, analyses, documents, other materials, or Records developed by Consultant in connection with the Services without first affording Client reasonable opportunity (to be not less than five (5) business days) to review such material. Concerning any draft or final reports, proposals or other communications with any governmental agency, or the agencies' contractors or consultants, or any third party, Consultant shall also allow for consideration of the written or oral comments of Client, its attorneys, and consultants.

IN WITNESS WHEREOF, this Agreement has been executed on behalf of Consultant and on behalf of Client as of the Effective Date.

FEDERATED CORPORATE SERVICES, INC. CLAYTON ENVIRONMENTAL

_____	_____
(Client Signature)	(Consultant Signature)
Please Print:	Please Print:
_____	Kirit H. Vora
(Name)	(Name)
_____	Vice President, Director, Corporate Accounts
(Title)	(Title)
_____	November 6, 1996
(Date)	(Date)

EXHIBIT A

Description of Services

Provide turn-key consulting services as set forth in the Clayton Environmental proposal dated October 23, 1996 and addendum dated October 23, 1996 (copies attached) and in accordance with all applicable Federal, State, Local laws, regulations, rules and ordinances required in the completion of work. Clayton Environmental will proceed with in-place closure of UST (Option 2) first. In the event that the NYSDEC does not provide written approval to close the UST's in-place, Clayton Environmental will conduct tank removal (Option 1) in a manner that allows the store loading docks to remain accessable for truck deliveries and solid waste removal.

SCHEDULE:

Task A UST Decommissioning		
Option 1:	UST Removal	4 days
Option 2:	UST in-place Closure	2 days
Task B AST Installation		
Install 1,000 gallon AST (1) concurrent with UST decommissioning phase of the project.		3 days

EXHIBIT B

Site Location

Macy's
Galleria Mall
White Plains, NY

EXHIBIT C

Consultant's Fee

Base Bid - NOT TO EXCEED	$49,700.00 (1)

(1) Breakdown of Base Bid:

Task A UST Decommissioning	
Option A: UST Removal	$34,200.00
Option B: UST Close In-Place	23,275.00
Task B AST Installation	
Install 1,000 gallon AST	15,500.00
TOTAL TO REMOVE/INSTALL AST	$49,700.00
TOTAL CLOSE IN-PLACE/INSTALL AST	$38,775.00
CONTRACT TOTAL	$49,700.00

NOTE: Sub-contractors cost will be paid on direct pass through basis only.

Unit Prices

Analytical Costs:	
Volatile Organic Compounds	$110.00/sample
Base-Neutral Compounds	220.00/sample
Director	130.00/HR
Manager	100.00/HR
Senior Engineer	85.00/HR
Staff Engineer	65.00/HR
Admin. Assistant	35.00/HR

(ABOVE COSTS INCLUDE APPLICABLE TAXES.)

EXHIBIT D

PROJECT JOB BOOK

Guidelines/Instructions

Intent

The intent of the attached job book format is to provide a standardized manner of recordkeeping for the projects under Federated/Allied Asbestos Control Program.

Volumes

The job book has been divided into four (4) volumes corresponding to the scheduling of tasks and paperwork through the course of an abatement project. The volume divisions do not mandate that all information within one volume be placed in one binder. Depending on the project, the number of binders will vary in the make-up of volumes in direct proportion to the size and scope of the project.

Binders

All information listed in the Table of contents will be submitted in 3" black, 3-ring binders. These binders will have exterior plastic sleeves allowing for spine identification and be of the size to contain 8 1/2" x 11" documentation.

Tabs

Tabs will be numerically progressive in accordance with the job book format. No special printing of these tabs is required and no costs for special printing will be reimbursable by Owner to Consultant for the preparation of the job book. Tabs may be shelf purchased, standard numerical tabs and correspond to the main divisions shown. Sub divisions of each main heading will be separated by blue paper. Sub-sub divisions of the sub-divisions will be separated by pink paper.

Submittal

Job books will be delivered within fourteen (14) calendar days of final information submittal by the Contractor, but not later than thirty (30) calendar days following final completion of the project. Two sets of each job book will be submitted to the Owner. Final payments to consultants will not be made until job books have been completed and accepted by Owner.

Identification

All binders will be identified by typed demarcation on the spine of each binder. The identification cards will be placed in the plastic sleeve with no form of adhesive applied to the binder. The identification card should contain the following:

OWNER:
DIVISION:
PROJECT:
CITY:
STATE:
CONTRACTOR:
VOLUME: ____ OF ____
BINDER: ____ OF ____ (should more than one binder be necessary to contain the information of the volume)

Presentation

Presentation of all project documentation will be submitted in the attached format outlined for the job book. All pages and heading dividers will be 8 1/2" x 11" standard size. Oversized documents will be folded to this size and placed in plastic "pockets" in the book or legibly reduced in size.

Large format drawings will be folded, inserted into plastic "pocket", pre-punched for 3-ring binders, and placed in the appropriate section of the job book.

Miscellaneous information not described in the job book format may be placed at the end of each volume with corresponding numbers and descriptions added to the Table of Contents. If no information is applicable to the description on the outline for an individual project, the section will remain in the job book and contain one sheet with the description - "NO INFORMATION APPLICABLE UNDER THIS SECTION FOR THIS PROJECT". Sheet to include section # and Table of Contents description.

The Table of Contents for each volume will be placed in the first binder of each volume.

Additions

All additions to the job book will be promptly proposed, in writing, by the consultant to the Owner. All changes will be issued by the Owner to all consultants in written form. No changes or modifications will be made to this format without the written authorization of the Owner.

Confidentiality

All binders will include, on the cover sheet, a confidentiality and copy protection paragraph:

NOTE: Certain information contained in this Job Book is confidential. Do not reproduce or distribute any portion of this Job Book without the express written approval of Owner.

Volume I
Job Book

Asbestos Control Program

TABLE OF CONTENTS

1.0 INTRODUCTION
2.0 PROJECT SUMMARY
- 2.1 PROJECT LOCATION
  - 2.1.1 PROJECT SURVEY
- 2.2 PROJECT DIRECTORY

3.0 BIDDING DOCUMENTS
- 3.1 COVER SHEET
  - 3.1.1 PROJECT
  - 3.1.2 BID ADMINISTRATOR
  - 3.1.3 MASTER CONSULTANT
- 3.2 INDEX TO BIDDING DOCUMENTS
- 3.3 INVITATION TO BIDDERS
- 3.4 INSTRUCTIONS TO BIDDERS
  - 3.4.1 GENERAL
  - 3.4.2 EXAMINATION OF CONDITIONS AFFECTING WORK
  - 3.4.3 BID PROPOSALS
  - 3.4.4 PREPARATION AND SUBMISSION OF PROPOSALS
  - 3.4.5 AGENDA
  - 3.4.6 INTERPRETATIONS
  - 3.4.7 MODIFICATIONS AND/OR WITHDRAWAL OF PROPOSALS
  - 3.4.8 REJECTION OF PROPOSALS
  - 3.4.9 SUBSTITUTIONS
  - 3.4.10 OPENING OF PROPOSALS
  - 3.4.11 BIDDER QUALIFICATIONS
  - 3.4.12 PERFORMANCE BOND AND PAYMENT BOND
  - 3.4.13 AWARD AND EXECUTION OF CONTRACT
- 3.5 BID PROPOSAL FORM
- 3.6 SURETY'S BOND AFFIDAVIT
- 3.7 CONTRACTOR'S QUALIFICATION STATEMENT
- 3.8 CONTRACT DOCUMENTS
  - 3.8.1 OWNER-CONTRACTOR AGREEMENT
  - 3.8.2 PERFORMANCE BOND
  - 3.8.3 PAYMENT BOND
- 3.9 NOTIFICATION OF PRE-BID MEETING
  - 3.9.1 ATTENDEES
  - 3.9.2 MINUTES OF PRE-BID MEETING

4.0 MISCELLANEOUS PRE-BID CLARIFICATION CORRESPONDENCE

5.0 PLANS AND TECHNICAL SPECIFICATIONS
- 5.1 DIVISION 1 - GENERAL REQUIREMENTS
- 5.2 DIVISION 2 - SITE WORK
- 5.3 DIVISION 9 - FINISHES
- 5.4 DIVISION 15 - MECHANICAL
- 5.5 DRAWINGS

6.0 REINSULATION SPECIFICATIONS
    6.1 DIVISION 1 - GENERAL REQUIREMENTS
    6.2 DIVISION 15 - MECHANICAL
7.0 BID DOCUMENT ADDENDA/AMENDMENTS

Volume II
Job Book

PRE-CONSTRUCTION DOCUMENTS AND SUBMITTALS

Asbestos Control Program

(DIVISION)
(PROJECT NAME)
(CITY, STATE)

Volume II
Job Book

Asbestos Control Program

TABLE OF CONTENTS

1.0 INTRODUCTION
2.0 PROJECT SUMMARY
    2.1 PROJECT LOCATION
    2.2 PROJECT DIRECTORY
3.0 CONTRACTOR'S BID PACKAGE
4.0 CONSULTANTS BID EVALUATION
5.0 MASTER CONSULTANTS BID EVALUATION
6.0 AWARD OF CONTRACT/LETTER OF INTENT
7.0 NOTICE OF PRE-CONSTRUCTION CONFERENCE
    7.1 TIME
    7.2 LOCATION
    7.3 CONDUCTED BY
    7.4 AGENDA ITEMS
8.0 MINUTES OF PRE-CONSTRUCTION CONFERENCE
9.0 SUPPLEMENTAL BID DOCUMENTS
    9.1 SUPPLEMENTAL BID REQUEST
    9.2 SUPPLEMENTAL BID
10. MISCELLANEOUS PRE-CONSTRUCTION CLARIFICATION CORRESPONDENCE
11.0 EXECUTED OWNER-CONTRACTOR AGREEMENT
    11.1 EXECUTED PAYMENT BOND
    11.2 EXECUTED PERFORMANCE BOND
12.0 QUALITY CONTROL PLAN
13.0 PRE-CONSTRUCTION SUBMITTALS
    13.1 CONTRACTOR'S SUBCONTRACTOR/SUPPLIER LIST
    13.2 CONTRACTOR'S PROGRESS SCHEDULE
    13.3 CONTRACTOR'S PLAN OF ACTION
    13.4 CONTRACTOR'S RESPIRATORY PROTECTION PLAN
    13.5 WASTE DISPOSAL PLAN
    13.6 CONTRACTOR'S STAFF
        13.6.1 RESUMES
        13.6.2 TRAINING AND CERTIFICATES
    13.7 CONTRACTOR'S MEDICAL MONITORING PROGRAM
    13.8 CONTRACTOR'S TRAINING PROGRAM
    13.9 CONTRACTOR'S LICENSE TO DO WORK FROM STATE AND LOCAL AGENCIES
    13.10 WORKER DOCUMENTATION
        13.10.1 CERTIFICATE OF WORKER ACKNOWLEDGMENT FORMS
        13.10.2 EMPLOYEE MEDICAL EXAM RESULTS
        13.10.3 CERTIFICATE OF WORKER RELEASE FORMS
    13.11 NOTIFICATIONS AND PERMITS
        13.11.1 FEDERAL
        13.11.2 STATE
        13.11.3 LOCAL

13.11.3.1 DEPARTMENT OF HEALTH
13.11.3.2 FIRE DEPARTMENT
13.11.3.3 CITY INSPECTION DEPARTMENT
13.11.3.4 AIR QUALITY CONTROL
13.11.3.5 WATER QUALITY CONTROL
13.11.3.6 OTHER LOCAL DEPARTMENTS
13.12 MANUFACTURER'S DATA AND CERTIFICATIONS
13.13 CONTRACTOR'S CONTINGENCY/EMERGENCY PLAN
13.14 CONTRACTOR'S TESTING LABORATORY QUALIFICATIONS AND PROCEDURES
13.15 CONTRACTOR'S CURRENT CERTIFICATE OF INSURANCE/POLICY SHOWING POLICY MATURITY DATE IN ACCORDANCE WITH CONTRACT DOCUMENTS
13.16 SUBCONTRACTOR'S CURRENT CERTIFICATES OF INSURANCE/POLICIES
14.0 NOTICE TO PROCEED

Volume III
Job Book

PROJECT DURATION SUBMITTALS

Asbestos Control Program

(DIVISION)
(PROJECT NAME)
(CITY, STATE)

Volume III
Job Book

Asbestos Control Program

TABLE OF CONTENTS

1.0 INTRODUCTION
2.0 PROJECT SUMMARY
    2.1 PROJECT LOCATION
    2.2 PROJECT DIRECTORY
    2.3 CONSULTANT'S TESTING LABORATORY QUALIFICATIONS AND PROCEDURES
3.0 CONSULTANT'S AIR MONITORING RESULTS
4.0 CONTRACTOR'S OSHA COMPLIANCE MONITORING RESULTS
5.0 CONTAINMENT INSPECTIONS/NEGATIVE PRESSURE SYSTEM
6.0 GLOVE BAG OPERATIONS/INSPECTIONS
7.0 AREA ACCESS
    7.1 CONTRACTOR'S LOG
    7.2 VISITOR'S LOG
    7.3 SIGN IN/SIGN OUT SHEETS
8.0 CONTRACTOR'S DAILY REPORTS
9.0 PROJECT MONITOR'S DAILY REPORTS
10.0 PROGRESS MEETING NOTES (STORE MEETING NOTES)
11.0 CONSULTANT'S WEEKLY PROGRESS REPORTS
12.0 WORK DIRECTIVE CHANGES
13.0 SHOP DRAWINGS/PRODUCT DATA/SAMPLES
14.0 CHANGE ORDER SUMMARY
    14.1 CHANGE ORDERS
15.0 FINAL COMPLETION INSPECTIONS
    15.1 FINAL CLEANING
    15.2 FINAL CLEARANCE
16.0 CERTIFICATE OF VISUAL INSPECTION
17.0 CERTIFICATE OF SUBSTANTIAL COMPLETION
18.0 PUNCH LIST
19.0 CERTIFICATION AND APPLICATION FOR PAYMENT
20.0 ASBESTOS DISPOSAL RECEIPTS/WASTE MANIFESTS
21.0 AUDIT OBSERVATIONS/DOCUMENT CHECKLIST
22.0 CORRESPONDENCE WITH LOCAL, STATE, AND FEDERAL AGENCIES

Volume IV
Job Book

Asbestos Control Program

PROJECT CLOSE-OUT SUBMITTALS

(DIVISION)
(PROJECT NAME)
(CITY, STATE)

Volume IV
Job Book

Asbestos Control Program

TABLE OF CONTENTS

1.0 INTRODUCTION
2.0 PROJECT SUMMARY
    2.1 PROJECT LOCATION
    2.2 PROJECT DIRECTORY
3.0 CERTIFICATE OF FINAL COMPLETION
4.0 LOAN AGREEMENT COMPLETION DOCUMENT
    4.1 CONTRACTOR
    4.2 CONSULTANT
5.0 CERTIFICATE OF FINAL PAYMENT
6.0 COMPLETED PUNCH LISTS
7.0 FINAL WAIVERS OF LIENS
8.0 RECORDKEEPING DOCUMENTS
    8.1 WARRANTY INFORMATION FOR INSTALLED PRODUCTS AND EQUIPMENT
    8.2 CERTIFICATES FOR INSTALLED PRODUCTS & EQUIPMENT
    8.3 GUARANTEES FOR INSTALLED PRODUCTS & EQUIPMENT
    8.4 OPERATION AND MAINTENANCE FOR INSTALLED PRODUCTS AND EQUIPMENT
9.0 RELEASE OF PAYMENT BONDS
10.0 RELEASE OF PERFORMANCE BONDS

EXHIBIT E

DUTIES, RESPONSIBILITIES AND LIMITATION OF AUTHORITY OF THE PROJECT MONITOR

. CONSULTANT will provide administration of performance of the CONTRACTOR's Work and will appoint a Project Manager and a Project Monitor, assistants and other field staff as agreed to by Owner, to assist in observing performance of the Work of CONTRACTOR.

Through on-site observations of CONTRACTOR's execution of the Work and field checks of materials and equipment, CONSULTANT shall provide protection against defects and deficiencies in the execution of the Work, provided, however, the furnishing of such services will not make CONSULTANT responsible for or give CONSULTANT control over construction means, methods, techniques, sequences or procedures or for CONTRACTOR's failure to perform the Work in accordance with the CONTRACT DOCUMENTS.

All capitalized terms used herein are as defined in the General Provisions of the OWNER-CONTRACTOR AGREEMENT.

The duties and responsibilities of the Project Monitor are limited and described below:

A. General

If the Project Manager is not, the Project Monitor will be trained in contract management and asbestos-abatement techniques, and have a working knowledge of air monitoring and ACM analytical techniques.

Project Monitor will act as directed by and under the supervision of CONSULTANT. Project Monitor's dealings in matters pertaining to CONTRACTOR's execution of the Work shall be primarily with CONTRACTOR, keeping OWNER advised as appropriate. Project Monitor's dealings with subcontractors shall only be through or with the full knowledge and approval of CONTRACTOR. All of OWNER's instructions to CONTRACTOR will be issued by CONSULTANT.

B. Duties and Responsibilities of Project Monitor

1. Submittals. Project Monitor shall maintain an inventory and accounting of all submittals called for in the CONTRACT DOCUMENTS. Project Monitor shall secure CONTRACTOR's Schedule of Submittals no later than delivery of CONTRACTOR's preconstruction submittals. Project Monitor shall assist CONSULTANT in obtaining submittals required

from CONTRACTOR including, but not limited to, those required:

(a) Prior to commencement of Work,

(b) For CONTRACTOR's initial payment application,

(c) For CONTRACTOR's application for Substantial Completion, and

(d) For CONTRACTOR's Final Payment Application.

2. Schedules: Project Monitor shall review the Progress Schedule, schedule of Shop Drawing submittals and schedule of values prepared by CONTRACTOR and review with CONSULTANT concerning acceptability.

3. Conference and Meetings: Project Monitor shall attend meetings with CONTRACTOR, such as preconstruction meetings, progress meetings, job conferences and other project-related meetings, and prepare and circulate copies of minutes thereof to CONSULTANT, CONTRACTOR and OWNER.

4. Liaison: Project Monitor shall:

(a) Serve as CONSULTANT's liaison with CONTRACTOR, working principally through CONTRACTOR's superintendent, and assist CONTRACTOR in understanding the intent of the CONTRACT DOCUMENTS.

(b) Assist CONSULTANT in serving as OWNER's liaison with CONTRACTOR.

(c) Assist in obtaining from CONSULTANT for OWNER additional details or information, when required, for proper execution of the Work.

5. Shop Drawings, Samples and Data: Project Monitor shall:

(a) Record date of receipt of Shop Drawings, and Samples and Data.

(b) Receive Samples and Data which are furnished at the Project by CONTRACTOR, and notify CONSULTANT of availability of Samples and Data for examination.

(c) Advise CONSULTANT and CONTRACTOR of the commencement of any Work requiring a Shop Drawing, Sample or Data if the submittal has not been approved by CONSULTANT.

(d) Secure all information required from Contractor for the successful completion of the Project Job Book.

6. CONTRACTOR's Detailed Plan of Action: Once CONTRACTOR's Detailed Plan of Action is accepted, Project Monitor shall observe and report any deviations therefrom to CONSULTANT.

7. Review of Work, Rejection of Defective Work, Inspections and Tests: Project Monitor shall:

(a) Conduct on-site observation of CONTRACTOR's execution of the Work to assist CONSULTANT in determining if the Work is proceeding in accordance with the CONTRACT DOCUMENTS;

(b) Promptly report to CONSULTANT whenever Project Monitor believes that any Work is unsatisfactory, faulty or defective, does not conform to the CONTRACT DOCUMENTS, has been damaged, or does not meet the requirements of any inspection, test or approval required to be made, and promptly advise CONSULTANT of Work that Project Monitor believes should be corrected or rejected or should be uncovered for observation or requires special testing, inspection or approval.

(c) Verify that any required tests, equipment and systems startups and operating and maintenance training are conducted in the presence of appropriate Owner or other personnel, and that CONTRACTOR maintains adequate records thereof; and observe, record and report to CONSULTANT appropriate details relative to the test procedures and startups.

(d) Accompany inspectors representing public or other agencies having jurisdiction over the Project, record the results of these inspections and promptly report to CONSULTANT.

(e) Be provided the services of a Certified Industrial Hygienist and a Certified Testing Laboratory to carry out OWNER's responsibility for an air monitoring program to insure that the building outside of CONTRACTOR's work areas remains uncontaminated. In accordance with CONSULTANT's Quality Assurance Plan, Project Monitor will review the air monitoring test results of CONTRACTOR and conduct independent verification testing on 10% of CONTRACTOR's testing inside CONTRACTOR'S work areas.

Project Monitor will certify the Pre-Clearance Visual Inspection made by CONTRACTOR and will conduct clearance air sampling.

(f) Be responsible for implementation of CONSULTANT's Quality Assurance Plan for the Project.

(g) Have OWNER's authority to stop all Work on the Project if a Hazardous Situation arises.

8. Interpretation of Contract Documents: The Project Monitor shall report to CONSULTANT when clarifications and interpretations of the CONTRACT DOCUMENTS are needed by CONTRACTOR and transmit to CONTRACTOR clarifications and interpretations as issued by CONSULTANT.

9. Modifications: Project Monitor shall consider and evaluate CONTRACTOR's suggestions for responses to Work Directive Changes, Addenda, Change Orders, and Field Orders regarding Drawings or Specifications and report with Project Monitor's recommendations to CONSULTANT. Project Monitor shall promptly transmit to CONTRACTOR decisions as issued by CONSULTANT. Project Monitor shall have authority to issue Change Orders which do not exceed $500.00 per modification in aggregrate direct and incidental costs.

10. Records: Project Monitor shall:

(a) Maintain at the Project orderly files for correspondence, reports of job conferences, Shop Drawings, Samples, and Data, CONTRACT DOCUMENTS including all Work Directive Changes, Addenda, Change Orders, Field orders, Plans and Specifications issued subsequent to the execution of the CONTRACT, CONSULTANT's clarifications and interpretations of the CONTRACT DOCUMENTS, progress reports, and other Project related documents.

(b) Keep a diary or log book recording CONTRACTOR hours on the Project, weather conditions if appropriate, conditions concerning OWNER's employees or customers which may affect the Work, data relative to questions concerning Work Directive Changes, Addenda, Change Orders, Field Orders or changed conditions, list of Project visitors, daily activities, decisions, observations in general, and detailed observations in the case of observing test procedures; and promptly send copies to CONSULTANT.

(c) Record names, addresses and telephone numbers of all CONTRACTORS, subcontractors and major suppliers of materials and equipment.

11. Reports: Project Monitor shall:

(a) Furnish CONSULTANT regular periodic reports of CONTRACTOR's execution of the Work and of CONTRACTOR'S compliance with the progress schedule and schedule of Shop Drawings, Samples, Data and Submittals.

(b) Confer with CONSULTANT, in advance of scheduled major tests, inspections or start of important phases of the Work.

(c) Draft proposed Change Orders, Field Orders, and Work Directive Changes, obtaining backup material from CONTRACTOR, and recommend to CONSULTANT Change Orders, Work Directive Changes, and Field Orders.

(d) Report immediately to CONSULTANT and OWNER upon the occurrence of any accident or Hazardous Situation.

12. Payment Requests: Project Monitor shall review applications for payment with CONTRACTOR for compliance with the established procedure for their submission and forward with recommendations to CONSULTANT, noting particularly the relationship of the payment requested to the schedule of values, Work completed, and materials and equipment delivered at the Project but not incorporated in the Work.

13. Certificates, Maintenance and Operation Manuals: During the course of CONTRACTOR's execution of the Work, Project Monitor shall verify that certificates, maintenance and operations manuals and other data required to be assembled and furnished by CONTRACTOR are applicable to the items actually installed and all in accordance with the CONTRACT DOCUMENTS, and shall have this material delivered to CONSULTANT for review and forwarding to OWNER prior to final payment for the Work.

14. Completion: Before CONSULTANT issues a Certificate of Substantial Completion, the Project Monitor shall:

(a) Submit to CONTRACTOR a list of observed items requiring completion or correction.

(b) Conduct final inspection in the company of CONSULTANT, OWNER and CONTRACTOR and prepare a final list of items to be completed or corrected (punch list).

(c) observe that all items on the punch list have been completed or corrected and make recommendations to CONSULTANT concerning acceptance, and the issuance of CONSULTANT's Certificate of Completion.

.C. **Limitations of Authority of Project Monitor**

The Project Monitor:

1. Shall not authorize any deviation from the CONTRACT DOCUMENTS or substitution of materials or equipment with a value in excess of $500 per modification unless authorized in writing by the OWNER.

2. Shall not undertake any of the responsibilities of CONTRACTOR, subcontractors or CONTRACTOR's superintendent.

3. Shall not advise on, issue directions relative to, or assume control over any aspect of the means, methods, techniques, sequences or procedures of construction unless such advice or directions are specifically required by the CONTRACT DOCUMENTS.

4. Shall not advise on, issue directions regarding, or assume control over safety precautions and programs in connection with the Work.

5. Shall not accept Shop Drawing, Sample or Data submittals from anyone other than CONTRACTOR.

6. Shall, after appropriate clearance, authorize OWNER to occupy the Project in whole or in part.

7. Shall not participate in specialized field or laboratory tests or inspections conducted by others except as specifically authorized by CONSULTANT.

8. Shall not advise on or issue directives of a legal nature concerning the CONTRACT DOCUMENTS, but shall forward questions of this regard through CONSULTANT to OWNER.

EXHIBIT G

SPECIAL CONDITIONS

EXHIBIT H
FEDERATED DEPARTMENT STORES, INC.

SPECIFICATIONS AND SCOPE OF WORK
PHASE I ENVIRONMENTAL SITE ASSESSMENT

Consultant Responsibilities:

1. Obtain the available property information from the applicable Federated Department Stores Inc. ("Federated") representative for the identified property ("Property"). The Federated representative will provide the name of an on-site contact person and arrange with this person for access to the Property.

2. Conduct a walk-through and an evaluation of the Property and all structures on it. Identify and document any evidence of Hazardous Materials (as defined in this Specification) or environmental conditions which would affect the economic value or marketability of the Property, cause any environmental regulatory or enforcement action or give rise to any clean up or remediation action. The Phase I Environmental Site Assesment must be in accordance with current ASTM standards. Topics to be covered include, but are not limited to the following:

(a)Above-ground and underground storage tanks, drums or pipelines, including an evaluation of their operations andmaintenance;

(b)Polychlorinated biphenyl ("PCB's") in electrical transformers, light ballasts, capacitors and hydraulicsystems;

(c)Soil contamination involving the past or current uses at the Property;

(d) Radon gas and radioactive materials;

(e) Environmental concerns involving landfills, ponding, septic tanks, wastewater discharges, ground water contamination monitoring wells, water wells or dry wells;

(f) Surface stains or spills;

(g) Indoor air quality issues;

(h) Suspected Asbestos-Containing Materials (ACM);

(i) The use, handling, storage, shipping and disposal of Hazardous Materials and other chemicals at the Property;

(j) Potential lead contamination in drinking fountains as identified in the USEPA's Lead Contamination Control Act;

(k) Potential existence of lead based paint; and

(l) History of uses and occupancies at the Property.

3. Review available Property records including building(s) plans and specifications, soil reports, permits, construction and maintenance records, current or former environmental reports, and current and historical aerial site photographs or documents, geological or hydrological records, maps, (if applicable) and correspondence regarding the use, storage, history of spills or disposal of any Hazardous Materials on the Property.

4. Obtain from Federated and review a Title Report prepared by a title company to determine the names of prior owners to identify potential environmental concerns.

5. Prepare a chemical inventory of all Hazardous Materials and chemicals stored or used by the Owner at the Property. Review and comment on the use, storage, handling, shipping, and disposal methods currently being used by the Owner.

6. Review and comment on current occupant's business uses and operations at the Property relating to their use, storage, handling, shipping, or disposal of any Hazardous Material, and other chemicals.

7. Identify any known or potential environmental contamination at the Property. Identify any known or potential environmental contamination at other properties within an approximate 1/2 mile distance (extending from the property line on each side of the Property ("Nearby Properties"). Identify which concerns are upgradient from the Property. Identify the approximate distance between the Property and Nearby Properties. Determine what the potential is for environmental impact to the Property from the identified Nearby Properties. This assessment of environmental concerns will include, but not be limited to, the following activities:

a) Conduct interviews with the Property Owner and staff at the Property (engineers, and property management personnel) and federal, state, and local governmental agencies to determine the use, storage, history of spills, and disposal of any Hazardous Materials on the Property or the Nearby Properties;

b) Make a direct inquiry to the regulatory agencies regarding the Nearby Properties and review available files provided by regulatory agencies. Provide to Federated written confirmation from the agency contacted or written results of an in-person agency file review or interview. The Consultant may not rely solely on the outside service information to evaluate the potential environmental hazards to the Property. including, but not limited to; Federal NPL, Federal CERCLIS,

c) Review environmental lists prepared by regulatory agencies, Federal RCRA TSD facilities, Federal RCRA generators, Federal ERNS, state lists of hazardous waste sites, state landfill and/or solid waste disposal sites, state leaking and registered UST lists;

d) Make a "drive-by" or "walk-by" observation of the Nearby Properties from outside of their property lines. The Consultant will not query owners or on-site personnel of the Nearby Properties or access the Nearby Properties, without approval of Federated; and

e) The Consultant will avoid, to the extent possible, creating or adding to any concern regarding the existance of any Hazardous Materials on the Property.

8. Review and document the past and present uses, occupancies, and waste management practices at the Property. Determine and describe the wastes generated and disposed of by the Property. Determine and evaluate the disposal methods, transportation and disposal site. Determine which tenants, if any, arrange and contract for their own waste disposal, describing briefly the kinds of wastes generated.

9. Identify the utilities servicing the Property. Identify and evaluate the source(s) of domestic water for the Property.

10. Describe all current reporting requirements of federal, state and, local regulatory agencies associated with underground or above-ground storage tanks and spill reporting at the Property. Notify Federated if Right-to-Know (i.e., Sara Title III), or similar reporting requirements are applicable.

11. State whether or not the Property is located in a state with a superlien law or a state with specific requirements regarding the environmental condition of the site prior to property transfer, such as notification, inspection or approval. Describe the requirements of the State. If the Property is in a state with a superlien law, state whether or not there is a superlien against the Property.

12. State whether or not the Property is in a "non-attainment" area as established and/or defined by the federal Clean Air Act.

13. Determine whether or not permits for air emissions or storm water discharge are recorded for the Property address(es).

14. State whether or not the property is located in an area identified as a "wetlands" area.

15. State what, if any, ordinances, statutes, regulations or guidelines affect the disposal of fluorescent lamps and PCB-containing fluorescent light ballasts from the Property.

16. Immediately notify the Client of any aspects of the investigation that require further investigation. Provide prompt verbal recommendations and estimates for further studies, testing, samplings, or other work considered appropriate and which fall outside the scope of work as defined in this document. Provide a written description of the type of work, the scope of work, and an estimate of all costs associated with the work.

17. Prepare a written report for the Property documenting the findings of the investigation. The report shall include, but not be limited to, the following items:

I. Cover Letter
II. Table of Contents
III. Executive Summary
IV. Introduction
V. Site Description
VI. Records Review
VII. Site Reconnaissance
VIII. Interviews
IX. Conclusions and Recommendations

Appendix

1. Photographs
2. Site Plan
3. Current 7.5 Minute Topographic May
4. Sample Logs (if any)
5. Previous Environmental Reports regarding the Property
6. List of Persons Interviewed including their employer, title, telephone number and date of interview

The report shall include the following statement in the cover letter:

> The Consultant understands that _____ and its Investors, assignees, designees, successors, and assigns intend to rely upon this report as an evaluation of the environmental conditions at the subject property for the purpose of deciding whether and under what conditions to proceed with the real estate transaction involving the meet the standard diligence practices for an environmental assessment property. The work was performed with sufficient detail and scope to meet the standard diligence practices for an environmental assessment for an institutional investor of real estate in the current marketplace. Consultant understands that the intent is to complete an investigation which will help provide for _____ and its Investors, assignees, designees, successors, and assigns the status of "Innocent Purchaser" as defined in Sec. 101 (35) (A) and (B) of 42 U.S.C.A. SS 9601 (35) and 107 (b) (3) of 42 U.S.C.A. SS 9607 and that _____ and its Investors, assignees, designees, successors, and assigns may rely upon the work for the above purpose.

18. "Hazardous Material" means any material or substance:

(i) defined as a "hazardous substance" pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (42 U.S.C. Section 9601 et.seq.) and amendments thereto and regulations promulgated thereunder;

(ii) containing gasoline, oil, diesel fuel or other petroleum products;

(iii) defined as a "hazardous waste" pursuant to the Federal Resource Conservation and Recovery Act and amendments thereto and regulations promulgated thereunder;

(iv) containing polychlorinated biphenyl (PCB's);

(v) described as radioactive;

(vi) containing or suspected of containing asbestos

(vii) considered infectious or biohazardous or;

(viii) the presence of which requires investigation or remediation under any federal, state or local statute, regulation, ordinance or policy or which is defined as "hazardous waste", "hazardous substance", pollutant or contaminant under any federal, state or local statute, regulation or ordinance, and any other material or substance displaying toxic, reactive, ignitable or corrosive characteristics, as all such terms are used in their broadest sense, and are defined by Environmental Laws; or materials which cause a nuisance upon or waste to the subject property.

CONTRACT #: 601073

CONFIDENTIALITY AGREEMENT

Federated Department Stores, Inc. ("Federated") and Clayton Environmental ("Consultant") are negotiating to enter into or have entered into one or more Consultants, I environmental consultant agreements (hereafter referred to as "Agreement"). Federated and Consultant have agreed to enter into this confidentiality agreement ("Confidentiality Agreement") executed on this 6th day of November, 1996 to set forth standards, procedures and other requirements related to maintaining the confidentiality of all information, documents or other materials provided to or generated or held by Consultant in connection with providing environmental consulting services to Federated prior to and after entry of the Agreement. This Confidentiality Agreement will supplement and/or amend, and will not be superseded by, the Agreement that has been or will be entered into by Federated and Consultant. All environmental consulting services provided prior to entry of the Agreement shall be deemed, for purposes of this Confidentiality Agreement, to have been conducted pursuant to the Agreement.

Wherefore, the parties to this Confidentiality Agreement agree as follows:

1. **Confidentiality of All Communications:** All oral and written communications between Federated and Consultant related to environmental consulting services under the Agreement, and all information, including, without limitation, all documents and samples, obtained, held or developed by Consultant pursuant to the Agreement are and shall be treated as strictly and completely confidential. Consultant understands and agrees that none of its directors, officers, partners, employees, agents, attorneys or subcontractors (hereinafter "Employee(s)") shall disclose to or discuss with any third party, including, without limitation, any local, state or federal government agency, the terms of the Agreement, any documents, information or other materials provided to Consultant by Federated, or any other communications or information directly or indirectly relating to performance of services under the Agreement which Consultant obtains during its performance of services under the Agreement, without the prior written consent of Federated, except as may be required by law. Consultant shall notify Federated in writing prior to making any disclosure that may be required by law, including without limitation, any disclosure pursuant to a subpoena, discovery request or other demand or pursuant to a potential reporting or disclosure obligation under applicable law. Consultant immediately shall notify Federated in writing of any subpoena, discovery request or other demand for information subject to this Confidentiality Agreement or any condition or incident potentially giving rise to a reporting or disclosure requirement under applicable laws, and shall provide Federated with a reasonable opportunity to object to any such disclosure and to pursue legal or other action, as appropriate,

to prevent or restrict such disclosure prior to any such disclosure, or to undertake its own reporting or disclosure.

2. Ownership of Information and Documents.

a. All documents and other materials of any kind supplied to the Consultant by Federated or its agents, or generated, requested or held by Consultant in connection with providing services under the Agreement, and any copies thereof, are and shall remain the property of Federated and shall be returned to Federated upon termination of the Agreement or upon the request of Federated. Consultant agrees that it will not duplicate or otherwise reproduce any portion of said documents without the prior consent of Federated.

b. All documents, including, without limitation, draft and final reports, field notes, evaluations, laboratory results and other information that Consultant generates, prepares, maintains or holds pursuant to the Agreement are and remain the property of Federated and shall be provided to Federated upon Federated's request and/or within fifteen (15) days of the effective date of the termination of the Agreement. Consultant specifically agrees that it shall not be entitled to withhold such documents pending Federated's payment of any final invoice or bills. Consultant may retain, for its own internal records, copies of any final written report that it prepares and/or sampling results that it obtains or completes under the Agreement, provided that Consultant shall prominently label any such copies "CONFIDENTIAL COMPANY PROPRIETARY INFORMATION: DO NOT DISCLOSE TO ANY THIRD PARTY WITHOUT PRIOR WRITTEN CONSENT OF FEDERATED DEPARTMENT STORES, INC." and shall not disclose any such reports or sampling results to any person whatsoever without the prior written consent of Federated.

3. Submission of Draft and Final Reports:

a. Consultant shall submit all written reports summarizing findings and conclusions in draft form to in-house or outside legal counsel, as specified by Federated, for the purpose of allowing such legal counsel to undertake a legal review and provide legal advice to Federated in connection with the draft report.

b. No draft or final report summarizing findings and conclusions will be submitted directly to any other employee of Federated or any third party without the prior consent of Federated. Federated shall approve the draft report before submission in final form.

c. All draft reports shall be marked prominently on each page with the words "DRAFT: PRIVILEGED & CONFIDENTIAL." All final reports shall be marked prominently on each page with the words "PRIVILEGED & CONFIDENTIAL."

4. **Destruction of Draft Reports:** All drafts of written reports prepared by the Consultant shall be destroyed concurrently with the submission of the final report approved by Federated, unless Federated requests in writing that such draft written reports be sent to Federated. Upon such a request, the draft reports shall be sent to Federated.

5. **Services for Legal Counsel:** Consultant may perform services under the Agreement at the request or under the direction of legal counsel for Federated for the purpose of seeking advice of counsel, assisting legal counsel in advising Federated regarding compliance with legal requirements and/or for preparing for potential litigation or other legal proceedings against Federated by public or private parties. With respect to any services under the Agreement that are performed at the request and/or direction of legal counsel, Consultant shall take instructions from and report its findings only to legal counsel and persons specifically authorized by legal counsel. In addition, Consultant shall treat and mark conspicuously all information developed or obtained in performing services for legal counsel by marking all such information as "PRIVILEGED AND CONFIDENTIAL: ATTORNEY-CLIENT COMMUNICATIONS AND ATTORNEY WORK-PRODUCT" and maintaining such information in controlled access files marked with the same language, unless directed otherwise by legal counsel. Consultant further shall maintain the strict confidentiality of this information, as specified in Section 1, and shall limit access to all such files to those Employees directly engaged in providing services in connection with the matter at issue on a need to know basis. In addition, if so directed by legal counsel, Consultant shall inform any employees or agents of Federated that any communications concerning matters within the employee's or agent's duties are made at the request and direction of legal counsel in order that Federated may obtain legal advice.

6. **Breach of Contract:** Consultant's failure to comply with the terms of this Confidentiality Agreement shall constitute a material breach of the Agreement between Consultant and Federated. Federated shall have the right, but not the obligation, to terminate such Agreement based on a breach of this Confidentiality Agreement and/or to pursue injunctive relief to enforce the provisions of this Confidentiality Agreement. For purposes of any action brought by Federated to enforce this Confidentiality Agreement through injunctive relief, the parties agree and acknowledge that irreparable harm will be caused by any breach of this Confidentiality Agreement.

7. **Representation:** Consultant represents and warrants that all Employees of Consultant will and shall be required to comply with the terms and provisions of this Confidentiality Agreement.

8. Acknowledgment: Consultant shall provide each Employee that performs work for Federated with a copy of this Confidentiality Agreement and shall require each such Employee to sign an acknowledgment that the Employee has read, understands and will comply with the terms of this Confidentiality Agreement. Consultant will provide Federated with a copy of each such acknowledgment upon request.

9. Further Assurances: Consultant agrees to obtain the same assurances as to confidentiality and nondisclosure required under this Confidentiality Agreement from all persons or entities that Consultant may call upon to assist Consultant in providing consulting services under the Agreement, including, but not limited to, subcontractors working under Consultant's direction. At Federated's request, Consultant shall have each such subcontractor sign a substantially similar Confidentiality Agreement with Federated.

10. Liability: Consultant assumes liability for any damages and costs to Federated arising from any breach of this Confidentiality Agreement by Consultant, its Employees and any third party to which Consultant or its Employees have disclosed information, documents or other materials subject to this Confidentiality Agreement.

11. Exceptions: The following information shall not be subject to the terms of this Confidentiality Agreement: (i) information that, at the time of disclosure, has become generally available to the public through no act of the Consultant; (ii) information that was already in Consultant's possession as non-confidential information prior to the time of Federated's disclosure of it to Consultant; (iii) information that was independently made available as a matter of right to Consultant by any other person, provided that person had the right to make such disclosures; or (iv) is required to be disclosed by a valid order or subpoena issued by a court or administrative agency of competent jurisdiction, provided that, if that happens, as specified in Section 1, above, Consultant promptly will notify Federated prior to the release of the information to provide Federated with a reasonable opportunity to protect its interests.

12. Conflicting Provisions: This Confidentiality Agreement amends any prior Agreement entered into between the parties and will not be superseded by any Agreement subsequently entered into by the parties. To the extent that any inconsistency or conflict exists between the provisions of this Confidentiality Agreement and the Agreement, the provisions of this Confidentiality Agreement will control. This Confidentiality Agreement further applies to any documents or information previously provided to or generated or held by Consultant under any prior agreement between Federated and Consultant.

13. Survival: The terms of this Confidentiality Agreement shall survive the termination of the Agreement.

14. Notices: All written notices and demands that are required under this Confidentiality Agreement shall be given in by first class mail/return receipt requested, overnight courier, confirmed facsimile transmission or hand delivery to the individuals identified below.

Federated Department Stores, Inc.
7 West Seventh Street
Cincinnati, OH 45202
ATTN: Klaus Ziermaier, Esq.
(513) 579-7900
(513) 579-7555 (FAX)

Consultant:

Clayton Environmental Consultants, Inc.
41650 Gardenbrook Road, Suite 155
Novi, Michigan 48375
ATTN: Rita Repko, Esq.

15. Modification and Waiver: No addition to or modification or waiver of any provisions of this Confidentiality Agreement shall be binding on either party unless made in writing and executed by an authorized representative of Federated and an authorized representative of Consultant. The waiver of any provision of this Confidentiality Agreement by either party shall not be construed as a waiver of any claims arising from a subsequent breach of that or any other provision of this Confidentiality Agreement. The failure of either party to object to, or to take affirmative action with respect to, any conduct of the other party shall not be construed as a waiver of that party's objection to such conduct or as a waiver of any claim arising from a future breach or subsequent wrongful conduct.

16. Severability: If any provision of this Confidentiality Agreement is determined to be unenforceable for any reason, it shall be adjusted rather than voided, if possible, in order to achieve the intent of the parties. In any event, the remaining provisions shall be deemed valid and enforceable to the maximum extent possible.

17. Entire Agreement: This Confidentiality Agreement is the exclusive statement of the agreement of the parties with respect to its subject matter and supersedes all prior written agreements, negotiations, representations or proposals, written or oral, relating to its subject matter.

18. Governing Law and Venue: The validity, performance and construction of this Confidentiality Agreement shall be governed by and interpreted in accordance with the laws of the State of Ohio applicable to contracts made therein. Venue in Hamilton County, Ohio shall be proper in any action brought under this Agreement.

19. Execution: This Confidentiality Agreement may be executed in counterparts, each of which shall be considered an original and all of which together shall constitute one and the same instrument.

20. Authorized Signature: Each person signing this Confidentiality Agreement certifies that he or she is fully authorized by the party he or she represents to enter into this Confidentiality Agreement, to execute it on behalf of Company and to legally bind Company.

IN WITNESS WHEREOF, this Agreement has been executed on behalf of Consultant and on behalf of Federated as of the Effective Date.

*(CONSULTANT)	FEDERATED CORPORATE SERVICES, INC.
_____	_____
(Consultant Signature)	(Client Signature)
Please Print:	Please Print:
Kirit H. Vora	
(Name)	(Name)
Vice President, Director, Corp. Accounts	
(Title)	(Title)
November 6, 1996	
(Date)	(Date)

Privileged and Confidential

APPENDIX B
NYSDEC AND WHITE PLAINS BUILDING DEPARTMENT PERMITS

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

December 18, 1996

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL
CONSERVATION - REGION 3
200 White Plains Road
5th Floor
Tarrytown, NY 10591-5805
Attention: Petroleum Bulk Storage

Clayton Project No. 40-97140.00

Subject: **Macy's White Plains- Petroleum Bulk Storage Facility**
Change of Ownership

Dear Sir:

Enclosed please find the application for change of ownership for the above-mentioned facility. A check in the amount of $250.00 is also enclosed. The facility's petroleum bulk storage registration number is 3-173665.

Please feel free to call me at (908) 225-6040 if you have any questions.

Sincerely,

Susan Bayat

Susan Bayat, P.E.
Senior Engineer Consultant
Environmental Management and Remediation
New York Regional Office

cc: P. McConocha
k. Vora

93-19-1 (8/95)—26c

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF SPILLS MANAGEMENT • BUREAU OF SOURCE CONTROL

PETROLEUM BULK STORAGE APPLICATION

Pursuant to the Petroleum Bulk Storage Law,
Article 17, Title 10 of ECL; 6 NYCRR 612-614 and 6 NYCRR, Subpart 360-14.
(Continued on Reverse Side—Please Be Sure to Complete Section B)

Please Type or Print Clearly and Complete All Items

SECTION A—See Instructions on Cover Sheet

PBS NUMBER
3-173665

Indicate Other Existing DEC Numbers, if any, for this Facility:

CBS Number:

SPDES Number:

TRANSACTION TYPE (Check all that apply)
NOTE: Transaction Types 1, 2 and 5 may require a fee.

1. ☐ Initial/ New Facility
2. ☒ Change of Ownership
3. ☐ Substantial Tank Modification
4. ☐ Information Correction
5. ☐ Renewal

Geographical Locator for this Facility: (If known)

LATITUDE: DEG MIN SEC

LONGITUDE: DEG MIN SEC

FACILITY

NAME: Macy's White Plains

LOCATION (Not P.O. Boxes): 100 Main Street

LOCATION (Continued):

CITY/TOWN/VILLAGE: White Plains | STATE: NY | ZIP CODE: 10601

COUNTY: Westchester | TOWNSHIP OR CITY:

NAME OF OPERATOR AT FACILITY: Frank Steixner | FACILITY TELEPHONE NUMBER: 914)946 5015

EMERGENCY CONTACT NAME: Sean R. Havey | EMERGENCY CONTACT PHONE NO.: (718)802 7645

OWNER

NAME: Macy's East, Inc.

ADDRESS (Street and/or P.O. Box): 151 West 34th Street Room 1206

CITY: New York | STATE: NY | ZIP CODE: 10001

FEDERAL TAX ID NO.: 13-3354541C | OWNER TELEPHONE NUMBER: (718) 802 7645

TYPE OF OWNER (Check only one)
1 ☐ Private Resident 2 ☐ State Government 3 ☐ Local Government
4 ☐ Federal Government 5 ☒ Corporate/Commercial

MAILING CORRESPONDENCE

ATTENTION: Sean R. Havey

NAME OF COMPANY: Macy's East, Inc.

ADDRESS: 151 West 34th Street Room 1206

ADDRESS:

CITY/STATE/ZIP CODE: New York New York 10001

TELEPHONE NUMBER: (718) 802-7645

TYPE OF PETROLEUM FACILITY:
(Check all that apply)

A. ☐ Storage Terminal/Petroleum Distributor
B. ☐ Retail Gasoline Sales
C. ☐ Other Retail Sales
D. ☐ Manufacturing
E. ☐ Utility
F. ☐ Trucking/Transportation
G. ☐ Apartment Building
H. ☐ School
I. ☐ Farm
J. ☐ Private Residence
K. ☐ Airline (Air Taxi)
L. ☒ Other (Specify)

Department Store

I hereby certify under penalty of perjury that the information provided on this form is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to Section 210.45 of the Penal Law.

NAME OF OWNER OR AUTHORIZED REPRESENTATIVE: Sean R. Havey | AMOUNT ENCLOSED: $250.--

TITLE: Regional Engineering Manager

SIGNATURE: Sean Havey | DATE: 12/16/96

OFFICIAL USE ONLY

Page _____ of _____

Date Received: ____/____/____

Date Processed: ____/____/____

Amount Received $ _____

Reviewed By: _____

PBS NUMBER:
3-173665

Tank Information for Petroleum Bulk Storage Facility

SECTION B—See Instructions on Cover Sheet

Action	Tank Number	Tank Location	Status	Installation or Permanent Closure Date (MO)		(YR)		Capacity (Gallons)	Product Stored	Tank Type	Tank Internal Prot.	Tank External Protection		Piping Location	Piping Type	Piping Internal Prot.	Piping External Protection		Secondary Containment		Leak Detection		Spill/ Overfill Prevention		Dispenser	Last Test Date (underground Tanks) (MO)		(YR)	
1	1	4	1	1	2	7	9	10,000	3	1	0		1	2	1	0		0		0		0		4	1	0	7	8	8
1	2	4	1	1	2	7	9	10,000	3	1	0		1	2	1	0		0		0		0		4	1	1	1	8	8
1	3	1	1	1	2	7	9	100	3	1	0		0	1	1	0		0		0		0		4	2				

KEY FOR SECTION B

ACTION
1 Initial Listing
2 Add Tank
3 Close/Remove Tank
4 Information Correction
5 Recondition/Repair/ Reline Tank

TANK LOCATION
1 Aboveground
2 Aboveground on saddles legs, stilts, rack, or cradle
3 Aboveground: 10% or more below ground
4 Underground
5 Underground, vaulted, with access

STATUS
1 In-service
2 Temporarily out-of-service
3 Closed—Removed
4 Closed—In Place
5 Tank Converted to Non-Regulated Use

PRODUCT STORED
0 Empty
1 Leaded Gasoline
2 Unleaded Gasoline
3 Nos. 1, 2, or 4 Fuel Oil
4 Nos. 5 or 6 Fuel Oil
5 Kerosene
6 Diesel
A Lube Oil
B Used Oil (fuel)
C Used Oil
9 Other*

TANK TYPE
1 Steel/Carbon Steel
2 Stainless Steel Alloy
3 Concrete
4 Fiberglass Coated Steel
5 Fiberglass Reinforced Plastic (FRP)
6 Equivalent Technology
9 Other*

PIPING TYPE
0 None
1 Steel/Iron
2 Galvanized Steel
3 Fiberglass (FRP)
4 Copper
9 Other*

INTERNAL PROTECTION: Tank/Piping
0 None
1 Epoxy Liner
2 Rubber Liner
3 Fiberglass Liner (FRP)
4 Glass Liner
9 Other*

EXTERNAL PROTECTION: Tank/Piping
0 None
1 Painted/Asphalt Coating
2 Sacrificial Anode
3 Impressed Current
4 Fiberglass
5 Jacketed
6 Wrapped (Piping)
9 Other*

PIPING LOCATION
0 None
1 Aboveground
2 Underground
3 Aboveground/Underground Combination

SECONDARY CONTAINMENT
0 None
1 Vault
2 Double-Walled Tank
3 Excavation Liner
4 Cut-off Walls
5 Impervious Underlayment
6 Earthen Dike
7 Prefabicated Steel Dike
8 Concrete Dike
A Synthetic Liner
B Natural Liner
9 Other*

LEAK DETECTION
0 None
1 Interstitial Monitoring
2 Vapor Well
3 Groundwater Well
4 In-tank System
5 Concrete Pad w/channels
6 Double Bottom
9 Other*

SPILL/OVERFILL PREVENTION
0 None
1 Float Vent Valve
2 High Level Alarm
3 Automatic Shut-off
4 Product Level Gauge
5 Catch Basin
6 Vent Whistle
9 Other*

DISPENSER
1 Submersible
2 Suction
3 Gravity

* If Other, please list on separate sheet including the Tank Number

93-06-004 (12/94)—26c

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

PETROLEUM BULK STORAGE REGISTRATION CERTIFICATE

NYS DEC - REGION 3
200 WHITE PLAINS RD, 5th Fl
TARRYTOWN, NY 10591-5805
(914) 332-1835, Ext. 363

TANK NUMBER	DATE INSTALLED	TANK TYPE	CAPACITY (GALLONS)	DATE LAST TESTED	TESTING DUE DATE	
1	12/79	Steel/Carbon Steel	10,000	07/88	07/93	
2	12/79	Steel/Carbon Steel	10,000	11/88	11/93	
3	12/79	Steel/Carbon Steel	100			*

* Aboveground tanks require monthly visual inspections and may need documented internal inspections as described in 6NYCRR Pt. 613.

OWNER
MACY'S EAST, INC.
151 WEST 34TH STREET ROOM 120
NEW YORK, NY 10001

SITE
MACY'S WHITE PLAINS
100 MAIN ST
WHITE PLAINS, NY 10601

OPERATOR (Name and Telephone Number)
FRANK STEIXNER
(914) 946-5015

EMERGENCY CONTACT (Name and Telephone Number)
SEAN R. HAVEY
(718) 802-7645

As an authorized representative of the above named facility, I affirm under penalty of perjury that the information displayed on this form is correct to the best of my knowledge. Additionally, I recognize that I am responsible for assuring that this facility is in compliance with all sections of 6 NYCRR Parts 612, 613 and 614, and applicable sections of 6 NYCRR Subpart 360-14 (used oil tanks only), not just those cited below:

- The facility must be re-registered if there is a transfer of ownership.
- The Department must be notified within 30 days prior to adding, replacing, reconditioning, or permanently closing a stationary tank.
- The facility must be operated in accordance with the code for storing petroleum, 6 NYCRR Part 613.
- Any new facility or substantially modified facility must comply with 6 NYCRR Part 614.
- **This certificate must be posted on the premises at all times.** Posting must be at the tank, at the entrance of the facility, or the main office where the storage tanks are located.
- Any person with knowledge of a spill, leak or discharge must report the incident to DEC within two hours (1-800-457-7362).

Sean Havey 1/2/97
Signature of Authorized Representative/Owner Date

SEAN HAVEY
Name of Authorized Representative/Owner (Please Print)

REGIONAL ENGINEERING MANAGER
Title

ISSUE Commissioner Michael Zagata

PETROLEUM BULK STORAGE NUMBER 3-179665

FEE PAID $ 250

MAILING CORRESPONDENCE
SEAN R. HAVEY
MACY'S EAST, INC.
151 WEST 34TH STREET/ROOM 1206
NEW YORK, NY 10001

THIS REGISTRATION CERTIFICATE IS NON-TRANSFERABLE

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

December 30, 1996

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL
CONSERVATION - REGION 3
200 White Plains Road
5th Floor
Tarrytown, NY 10591-5805
Attention: Petroleum Bulk Storage

Clayton Project No. 40-97140.00

Subject: **Macy's Department Store, White Plains, New York**
Petroleum Bulk Storage Facility - Substantial Modification

Dear Sir:

Enclosed please find the application for a "Substantial Tank Modification" of the petroleum storage facility number 3-173665, located at 100 Main Street, White Plains, New York. The two existing fuel oil underground storage tanks, with a capacity of 10,000-gallons each, will be permanently closed in-place and a new 1,000-gallon steel aboveground storage will be installed.

The New York State Department of Environmental Conservation (NYSDEC) guidelines as specified in a memorandum dated January 20, 1987, to Regional Water Engineers and Regional Solid and Hazardous Waste Engineers regarding the permanent closure of petroleum tanks, will be followed for the closure of the two existing tanks.

Macy's personnel are not aware of any documented evidence or information that the tanks are suspected of having leaked in the past. As described in the memorandum under section 4.0 "Tank abandonment In Place" the tanks will be emptied and the piping will be drained into the tank. The remaining waste inside the tanks will be removed manually. A visual inspection of the tank's interior will be performed. If any holes are discovered, then a soil sample from under the tank near the hole will be taken. If petroleum is present in the soil, a spill report will be filed with NYSDEC, and the appropriate regulations and guidelines regarding the situation will be followed.

A:\SB7\MACYDEC1.LTR

If no holes are dicovered, the tanks will be filled with foam (Petro Fill) which has been approved by NYSDEC as an alternative inert material to fill the tanks, when permanently closing them in-place.

These activities have been scheduled to begin on the week of January 6, 1997. Since the combined storage capacity at the facility after closure of the two underground tanks and installation of the new aboveground storage tank will not exceed 1,100 gallon, the facility is not required to be registered as a petroleum bulk storage facility with NYSDEC.

Thank you for your attention to this matter. Please call me if you have any questions or need further information.

Sincerely,

Susan Bayat

Susan Bayat, P.E.
Senior Environmental Engineer
Environmental Management & Remediation
New York Regional Office

93-19-1 (8/95)—26c

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF SPILLS MANAGEMENT • BUREAU OF SOURCE CONTROL

PETROLEUM BULK STORAGE APPLICATION

Pursuant to the Petroleum Bulk Storage Law,
Article 17, Title 10 of ECL; 6 NYCRR 612-614 and 6 NYCRR, Subpart 360-14.
(Continued on Reverse Side—Please Be Sure to Complete Section B)

Please Type or Print Clearly and Complete All Items

SECTION A—See Instructions on Cover Sheet

PBS NUMBER 3-173665

Indicate Other Existing DEC Numbers, if any, for this Facility:

CBS Number: _____

SPDES Number: _____

TRANSACTION TYPE (Check all that apply)
NOTE: Transaction Types 1, 2 and 5 may require a fee:

1. ☐ Initial/ New Facility
2. ☐ Change of Ownership
3. ☒ Substantial Tank Modification
4. ☐ Information Correction
5. ☐ Renewal

Geographical Locator for this Facility: (If known)

LATITUDE: | | | | | | DEG MIN SEC

LONGITUDE: | | | | | | DEG MIN SEC

FACILITY

NAME: MACYS White Plains

LOCATION (Not P.O. Boxes): 100 Main Street

LOCATION (Continued):

CITY/TOWN/VILLAGE: White Plains | STATE: NY | ZIP CODE: 10601

COUNTY: Westchester | TOWNSHIP OR CITY:

NAME OF OPERATOR AT FACILITY: Frank Steixner | FACILITY TELEPHONE NUMBER: (914) 946-5015

EMERGENCY CONTACT NAME: Sean Havey | EMERGENCY CONTACT PHONE NO.: (718) 802-7645

OWNER

NAME: MACYS East Inc.

ADDRESS (Street and/or P.O. Box): 151 West, 34th St. Room 1206

CITY: New York | STATE: NY | ZIP CODE: 10001

FEDERAL TAX ID NO. | OWNER TELEPHONE NUMBER: (718) 802-7645

TYPE OF OWNER (Check only one)
1 ☐ Private Resident 2 ☐ State Government 3 ☐ Local Government
4 ☐ Federal Government 5 ☒ Corporate/Commercial

TYPE OF PETROLEUM FACILITY:
(Check all that apply)

A. ☐ Storage Terminal/Petroleum Distributor
B. ☐ Retail Gasoline Sales
C. ☐ Other Retail Sales
D. ☐ Manufacturing
E. ☐ Utility
F. ☐ Trucking/Transportation
G. ☐ Apartment Building
H. ☐ School
I. ☐ Farm J. ☐ Private Residence
K. ☐ Airline (Air Taxi) L. ☒ Other (Specify)
Department Store

I hereby certify under penalty of perjury that the information provided on this form is true to the best of my knowledge and belief. False statements made herein are punishable as a Class A misdemeanor pursuant to Section 210.45 of the Penal Law.

NAME OF OWNER OR AUTHORIZED REPRESENTATIVE: Sean Havey | AMOUNT ENCLOSED: $00.00

TITLE: Regional Engineering Manger

SIGNATURE: Harvey Howe Jr | DATE: 12/27/96

MAILING CORRESPONDENCE

ATTENTION: Sean Havey

NAME OF COMPANY: MACYS East Inc.

ADDRESS: 151 West, 34th St. Room 1206

ADDRESS:

CITY/STATE/ZIP CODE: New York New York 10001

TELEPHONE NUMBER: (718) 802-7645

OFFICIAL USE ONLY

Page _____ of _____

Date Received: ____/____/____

Date Processed: ____/____/____

Amount Received $ _____

Reviewed By: _____

PBS NUMBER: 3-173665

Tank Information for Petroleum Bulk Storage Facility

SECTION B—See Instructions on Cover Sheet

Action	Tank Number	Tank Location	Status	Installation or Permanent Closure Date (MO)		(YR)		Capacity (Gallons)	Product Stored	Tank Type	Tank Internal Prot.	Tank External Protection		Piping Location	Piping Type	Piping Internal Prot.	Piping External Protection		Secondary Containment		Leak Detection		Spill/ Overfill Prevention		Dispenser	Last Test Date (underground Tanks) (MO)		(YR)	
3	1	4	1	1	2	7	9	10,000	3	1	0		1	2	1	0		0		0		0		4	1	0	7	8	8
3	2	4	1	1	2	7	9	10,000	3	1	0		1	2	1	0		0		0		0		4	1	1	1	8	8
2	4	1	1	0	1	9	7	1,000	3	1	0		1	1	1	0		0		1		0		2& 4	2	N	/A		

KEY FOR SECTION B

ACTION
1 Initial Listing
2 Add Tank
3 Close/Remove Tank
4 Information Correction
5 Recondition/Repair/ Reline Tank

TANK LOCATION
1 Aboveground
2 Aboveground on saddles legs, stilts, rack, or cradle
3 Aboveground: 10% or more below ground
4 Underground
5 Underground, vaulted, with access

STATUS
1 In-service
2 Temporarily out-of-service
3 Closed—Removed
4 Closed—In Place
5 Tank Converted to Non-Regulated Use

PRODUCT STORED
0 Empty
1 Leaded Gasoline
2 Unleaded Gasoline
3 Nos. 1, 2, or 4 Fuel Oil
4 Nos. 5 or 6 Fuel Oil
5 Kerosene
6 Diesel
A Lube Oil
B Used Oil (fuel)
C Used Oil
9 Other*

TANK TYPE
1 Steel/Carbon Steel
2 Stainless Steel Alloy
3 Concrete
4 Fiberglass Coated Steel
5 Fiberglass Reinforced Plastic (FRP)
6 Equivalent Technology
9 Other*

PIPING TYPE
0 None
1 Steel/Iron
2 Galvanized Steel
3 Fiberglass (FRP)
4 Copper
9 Other*

INTERNAL PROTECTION: Tank/Piping
0 None
1 Epoxy Liner
2 Rubber Liner
3 Fiberglass Liner (FRP)
4 Glass Liner
9 Other*

EXTERNAL PROTECTION: Tank/Piping
0 None
1 Painted/Asphalt Coating
2 Sacrificial Anode
3 Impressed Current
4 Fiberglass
5 Jacketed
6 Wrapped (Piping)
9 Other*

PIPING LOCATION
0 None
1 Aboveground
2 Underground
3 Aboveground/Underground Combination

SECONDARY CONTAINMENT
0 None
1 Vault
2 Double-Walled Tank
3 Excavation Liner
4 Cut-off Walls
5 Impervious Underlayment
6 Earthen Dike
7 Prefabricated Steel Dike
8 Concrete Dike
A Synthetic Liner
B Natural Liner
9 Other*

LEAK DETECTION
0 None
1 Interstitial Monitoring
2 Vapor Well
3 Groundwater Well
4 In-tank System
5 Concrete Pad w/channels
6 Double Bottom
9 Other*

SPILL/OVERFILL PREVENTION
0 None
1 Float Vent Valve
2 High Level Alarm
3 Automatic Shut-off
4 Product Level Gauge
5 Catch Basin
6 Vent Whistle
9 Other*

DISPENSER
1 Submersible
2 Suction
3 Gravity

* If Other, please list on separate sheet including the Tank Number

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

December 26, 1996

CITY OF WHITE PLAINS
DEPARTMENT OF BUILDING
255 Main Street
White Plains, New York 10601

Clayton Project No. 40-97140.00

Subject: Application for Building Permit- Galleria Mall in White Plains, New York

Dear Sir/Madam:

Enclosed please find the Building Department permit applications for the Macy's Department Store, located at 100 Main Street, White Plains, New York 10601. The permit request is for the fuel oil storage tanks upgrading activities at the facility, as described here:

- Closure of two 10,000-gallon number 2 fuel oil underground storage tanks located on the loading dock area.

- Installation of a 1,000-gallon aboveground storage tank for number 2 fuel oil on loading dock area and associated piping.

The two 10,000-gallon underground storage tanks will be permanently closed in-place. New York State Department of Environmental Conservation (NYSDEC) will be notified of the tank closure activities. The closure will be performed following the applicable regulations and NYSDEC guidelines.

The aboveground storage tank would be installed in the southeast corner of the loading dock. Please see the attached site plan and information regarding the tank and its accessories.

Clayton has scheduled the site work to begin on the week of January 6, 1997. Environmental Product and Services, Inc. (EP&S) will be the contractor on the tank closure part of the project, with an estimated cost of $16,820.00. In addition, MRO Pump and Tank, Inc. will perform the installation of the new tank and associated piping. The estimated cost for this part is $3,100.00, which does not include the price of the tank and accessories. A check in the amount of $230 is enclosed to cover the permit fee.

A:\SB7\PERMIT.LTR

Please do not hesitate to call me at (908)225-6040 if you have any question or need further information regarding this project.

Sincerely,

Susan Bayat

Susan Bayat, P.E.
Senior Environmental Engineer
Environmental Management and Remediation
New York Regional Office

Enclosure

TOTAL FEE	RECEIPT NO.
AMT. PAID	
DUE	

APPLICATION FOR BUILDING PERMIT

CITY OF WHITE PLAINS
DEPARTMENT OF BUILDING
255 MAIN STREET
WHITE PLAINS, NEW YORK 10601

FORM 5E-79
(MECHANICAL)

Application _____ Date _____
(To be filled in by the Dept. of Building)

To the Commissioner of Building,

The undersigned hereby makes application for a permit to perform the work shown on the drawings accompanying this application and described herein. This application will be abandoned six (6) months from this date unless before then a permit shall have been issued.

LOCATION: No. 100 Main Street White Plains New York 10601 Street

WARD _____ BLOCK _____ LOTS _____

CONSTRUCTION CLASSIFICATION (Circle One) Fireproof 1A 1B Non-combustible 2A 2B 2C Ordinary 3A 3B 3C Frame 4A 4B

PRESENT USE of building: Commercial - Department Store

PROPOSED USE: Same

DESCRIPTION OF THIS WORK: INSTALL 1,000-gal. AST FOR FUEL OIL IN MAIN ST. LOADING DOCK AREA

AREA OR FLOOR OF WORK: Groundfloor - Loading dock

EST. COST OF THIS IMPROVEMENT: $ 3,100.00

OWNER* Macy's East Inc. Tel. No. (718) 8027645

Address 151 West 34th St Room 1206 NY NY 10001

LESSEE* (if any) _____

Address _____

ARCHITECT* (if any) _____ Tel. No. _____

Address _____

BUILDER* or CONTRACTOR MRO Pump & Tank, Inc Tel. No. 914 624-8197

Address 15 Fisher Ave. Nanuet, NY

Has the undersigned (Builder) any employees? Yes

Signature of Builder & Title (Print Name & Title) Greg Chapbell, Manager Greg Chapbell

*Note: If a corporation, give the president's name also. Michael Oliva, President

AFFIDAVIT OF OWNERSHIP

STATE OF NEW YORK }
COUNTY OF WESTCHESTER } ss.:

DO NOT CHANGE THE WORDING OF THIS AFFIDAVIT

S. Bayat, P.E. From Clayton Environmental Consultants being duly sworn, deposes and says:
(owner, lessee, architect or builder)

that Macy's East Inc. is the owner in fee of the premises to which this application applies; that he (the applicant) is duly authorized to make this application; and that the statements contained herein are true to the best of his knowledge and belief.

Sworn to before me this 26th day of December 1996

ROBIN T. STOKES
NOTARY PUBLIC OF NEW JERSEY
My Commission Expires June 1, 1997

Susan Bayat
(Signature of Applicant)

Robin T. Stokes
(Notary Public, Westchester County)

PERMIT NO. _____ ZONE _____ C. O. NO. _____

TOTAL FEE	RECEIPT NO.
UNT. PAID	
UE	

APPLICATION FOR BUILDING PERMIT

CITY OF WHITE PLAINS
DEPARTMENT OF BUILDING
255 MAIN STREET
WHITE PLAINS, NEW YORK 10601

FORM 5E-79
(MECHANICAL)

Application ..... Date .....
(To be filled in by the Dept. of Building)

To the Commissioner of Building,

The undersigned hereby makes application for a permit to perform the work shown on the drawings accompanying this application and described herein. This application will be abandoned six (6) months from this date unless before then a permit shall have been issued.

LOCATION: No. 100 Main Street White Plains New York 10601 Street

WARD ..... BLOCK ..... LOTS .....

CONSTRUCTION CLASSIFICATION (Circle One) Fireproof 1A 1B Non-combustible 2A 2B 2C Ordinary 3A 3B 3C Frame: 4A 4B

PRESENT USE of building: Commercial - Department Store

PROPOSED USE: Same

DESCRIPTION OF THIS WORK: Closure of two 10,000 gallon underground Storage Tanks (Read oil #2)

AREA OR FLOOR OF WORK: Groundfloor - Loading dock

EST. COST OF THIS IMPROVEMENT: $16,820.00

OWNER* Macys East Inc. Tel. No. (718) 802-7645

Address 151 West, 34th St. Room 1206 NY NY 10001

LESSEE* (if any) .....

Address .....

ARCHITECT* (if any) ..... Tel. No. .....

Address .....

BUILDER* or CONTRACTOR Environmental Products & Services Tel. No. 516-755-2165

Address 100-B CABOT STREET, West Babylon, NY 11704

Has the undersigned (Builder) any employees? Yes

Signature of Builder & Title .....
(Print Name & Title) Al Staiti

*Note: If a corporation, give the president's name also.

AFFIDAVIT OF OWNERSHIP

STATE OF NEW YORK }
COUNTY OF ~~WESTCHESTER~~ Suffolk } ss.:

DO NOT CHANGE THE WORDING OF THIS AFFIDAVIT

..... being duly sworn, deposes and says:
(owner, lessee, architect or builder)

that Macy's East Inc ..... is the owner in fee of the premises to which this application applies; that he (the applicant) is duly authorized to make this application; and that the statements contained herein are true to the best of his knowledge and belief.

Sworn to before me this 13th


13th day of Dec

..... (Signature of Applicant)


KRISTINE HOGAN
Notary Public, State of New York
No. 01HO5061809
Qualified in Suffolk County
Commission Expires June 17, 1998

Kristine Hogan
(Notary Public, ~~Westchester~~ Suffolk County)


PERMIT NO. ..... ZONE ..... C. O. NO. .....




FEDERATED DEPARTMENT STORES, INC.
GALLERIA SITE 030012
1ST FLOOR PLAN
(NOT TO SCALE)



TOP VIEW



SIDE VIEW



END VIEW

SPECIFICATIONS

CAPACITY IN GALLONS:	1,000
NUMBER REQUIRED:	(1) ONE
MATERIAL:	A569
THICKNESS OR GAUGE:	10 GA DIKE
INNER TANK	SHELL- 10 GA
	HEAD- 10 GA
OUTER TANK	SHELL- N/A
	HEAD- N/A
LABELING:	ABOVEGROUND UL 142

COATING: EXTERIOR- RED OXIDE

INTERIOR- NONE

SURFACE PREP: TOUCH UP

OPENINGS: SEE SKETCH

(3) 2" NPT FITTINGS
(1) 4" NPT FITTING
(1) 6" NPT FITTING

(2) 2" NPT FITTINGS IN DIKE FOR DRAINS

OTHER ACCESSORIES:

1,100 CONTAINMENT DIKE
(2) 48" SADDLES

MOHAWK METAL PRODUCTS CO., INC.
2175 BEECHGROVE PLACE - UTICA, NY 13501
TELEPHONE (315) 793-3000

1000 GALLON SINGLE WALL TANK
1100 GALLON CONTAINMENT DIKE

SCALE:	CHECKED:	DRAWN BY:	DATE:	APPD BY:	DWG #:
NONE		DHS	3/8/95		5020R
					SHEET 1 OF 1

OVERFILL WARNING DEVICES

TANK ALARM

PART # 1000100


A cost effective overfill alarm system for above ground storage tanks.


Battery powered, intrinsically safe, and easy to install, the TANK ALARM uses a pressure sensing device to sound a 95 decibel audio alarm at 90% fluid level.


The sensing head fits a standard 2 inch threaded opening and is field adjustable for all size tanks.

The TANK ALARM uses no moving parts except for a single toggle switch for ON - OFF - TEST. The system is internally powered with two 9 volt batteries, thus eliminating the need for any external power requirements and making the system intrinsically safe.

OVERFILL ALARM INSTALLATION







SPECIFICATIONS:


TEMPERATURE RANGE: -40 TO 70C
SIZE: 7" X 4.25" X 3.5"
POWER REQUIREMENTS: No external power required. Internal battery power 18VDC.

IMPORTANT: This device is to be used only as an auxiliary warning to the operator of a possible overfill situation and should not be relied upon to prevent tank overfill. It is solely the responsibility of the operator to continuously monitor the tank filling process and prevent any spillage, regardless of the situation or status of any gauge or alarm apparatus.

SEE SECTION 3 OF PRODUCT PRICE LIST FOR PRICING INFORMATION

Setting the Standard for the AST Market

UPFLOW VENT




UPFLOW VENT - Features an upward flow design which rapidly disperses vapors. A grooved drain lip in the cap extends beyond the base for efficient water drain-off. Includes two set screws for easy installation.

Model #	Size	Weight (lbs.)	Height	Width
45-20	2"	1.1	4⅜"	4"

- Assures even pressure in the AST during filling or pumping
- All metal construction
- Flame-retardant 40 mesh bronze screen
- Conforms with NFPA-30

45

PRESSURE VACUUM VENT



PRESSURE VACUUM VENT - Utilized for vapor recovery applications. An internal pressure valve, available in 8, 12, or 16 oz. settings, restricts vapor escape during product drops. All pressure valves have a ½ oz. vacuum setting. The 46 has a 2" pipe thread; the 46S has two set screws.

Model #	Size	Weight (lbs.)	Height	Width	Pressure
46-2080	2"	2.0	5⅞"	4¼"	8 oz.
46S-2080	2"	2.0	5⅞"	4¼"	8 oz.

- Assures even pressure in the AST during filling or pumping
- All metal construction
- Flame-retardant 40 mesh bronze screen
- Conforms with NFPA-30

46

BLOW OFF VENT



BLOW OFF VENT - Provides venting to relieve excessive internal pressure build up in the event of a fire or during filling above ground storage tanks. The emergency vent will open at approximately 1 PSI. The mushroom design prevents water and contaminants from entering the tank.

Model #	Size	Weight (lbs.)	Height	Width
48-60	6"	30.0	6"	10"

- Contains female threads
- Mounts onto the tank
- Non-corrosive polymeric coating
- Flame-retardant 40 mesh brass screen
- Conforms with NFPA-30A

48

For More Information Call Universal [illegible] Fax: 800-443-8258 or 908-351-0369

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

December 31, 1996

CITY OF WHITE PLAINS
DEPARTMENT OF BUILDING
255 Main Street
White Plains, New York 10601

Clayton Project No. 40-97140.00

Subject: **Application for Building Permit- Galleria Mall in White Plains, New York**

Dear Sir/Madam:

Enclosed please find a check in the amount of $41.00 balance due for the Building Department permit applications for the Macy's Department Store, located at 100 Main Street, White Plains, New York 10601. The permit number is 96BA1762.

Please do not hesitate to call me at (908)225-6040 if you have any question or need further information regarding this project.

Sincerely,

Susan Bayat

Susan Bayat, P.E.
Senior Environmental Engineer
Environmental Management and Remediation
New York Regional Office

Enclosure

A:\SB7\PERMIT1.LTR

Privileged and Confidential

APPENDIX C
SITE ACTIVITIES DAILY LOG

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 13, 1997

TEMPERATURE:

WEATHER: Cold Sunny

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayat

EP&S 4 crews
1 Foreman
1 Truck Driver
Equipment: 1 Tanker Truck - 1 Vacuum Truck
2 vans

- The AST and the containment dike were delivered to the site and unloaded by a front loader (5:00 - 8:00 A.M.)

- EP&S cleared the area for access to AST location

- EP&S removed the manhole to east UST at grade level.

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 13, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bryant

- The bolts on the east UST are rusted, cannot be opened by wrench. Need a chain saw to cut them.

- EPES went back to the office to bring a saw.

- Went to Building Dept. met with Pete Russo and John Cutro. Building Dept will not approve Petrofill for the UST Closure. Must arrange for concrete.

- Pete Russo inspected the site 12:00PM

- EPES finished cutting the bolts on East UST manway. Removed the lid

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 13, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayuk

- Oil was pumped out of the east UST. (12:30 PM)

- The bottom sludge was pumped to a vacuum truck (1:30 PM)

- EPLS set the Contined Space Entry equipment. Glenn Suarez from EPLS entred the east UST

- White plains Fire Dept inspected the site Mike Zignani Mike Fitzgeralds Joseph Hardy (2:00 PM) No concerns were raised

- East UST completely Cleaned and dried

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

(page 4)

DATE: Jan 13, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bryant

with oil absorbent pads. Tank interior shell was inspected with high power flush light. The east UST has a poly liner coating. It is in very good conditions. (3:00 pm)

- The west UST manway bolts also in bad conditions, they must be cut.

- The bolts were cut and the lid was removed.

- The oil was pumped out to the Tanker Truck. Total 750 gallons both UST's. The Tanker Truck left the site 3:30 pm.

- The west UST bottom sludge was pumped in the vacuum truck.

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

Page (5)

DATE: Jan 13, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: _____

- Confined space entry equipment set for west UST

- Glen Suarez entered the west UST and cleaned and dried the UST. He inspected the inside of UST no holes or cracks, no poly liner coating - UST in good condition.

- The Tanks were/may left open ~~for~~ overnight but the manhole lids were closed

- EPDS cleaned up the site removed all material and waste (6:30 P.M.)

CLOSED for the Day!

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 14, 1997

TEMPERATURE:

WEATHER: rainy - cold

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayat

F P & S 1 crew 1 foreman

A & P Reinaldi 1 crew

- A & P Reinaldi set the AST pressure test increased the pressure to 8 p.s.i. Some leaks around the fittings fixed it and set the test again.

- Pete Russo from Building Dept inspected the site for pressure test. Test o.k. A & P can start the piping 11:00 A.M.

- Byram concrete trucks came to the site poured concrete directly to the east UST and the west UST to concrete

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 14, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bamat

Trucks, Total 100 CY yard of concrete poured into the Two USTs. The vent lines also closed.

- Pete Russo inspected the USTs closure.
- UST closure completed at 12:30 p.m.
- EP&S left the site at 1:30 P.M.
- A&P continued with piping, and installation of the fittings and accessories.
- A&P closed for the day at 4:00 p.m.

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 15, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: None

- A & P worked on AST piping

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 16, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayat

A&P Rainaldi 2 crews

Equipment Plumbing Tools

- A&P installed the 1 (one) inch Suction and return lines on the east wall of the loading area.
- Installed the Liquid Level Gauge
- Started the installation of the fill line. 2 inch PVC
- Closed for the day at 4:00 PM

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 17, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: None

- A&P Rinaldi Finished the piping for the AST.
- Building Dept inspected the system, and O.K.ed it.

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Jan 23, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayat

EPDS 2 Crews

1 Foreman

Equipment Drilling Tools.

- The location of the bollard was marked on the floor (Traffic safety)
- Checked the Facility's blue prints in the engineers office, for underground utilities
- Cored drilled through the floor slab.
- Installed the three bollards, filled them up with concrete 5:00 PM
- Closed for the Day.

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Feb 3, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: S. Bayat

EP&S 2 crews

1 plumber

Equipment plumbing Tools

- EP&S cleared the area for access to AST
- started the installation of the 2 inch vent line for AST must be vented outside
- Identified the location for the core drill on the east side wall
- Moved the man lift to that location core drilled the outside wall steel panel (6 inch)
- Closed for the Day

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Feb 4, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: None.

EPAS finished the installation of the vent hose for the AST

DAILY LOG
MACY'S TANK UPGRADE PROJECT
WHITE PLAINS, NEW YORK

DATE: Feb 6, 1997

TEMPERATURE: _____

WEATHER: _____

CLAYTON REPRESENTATIVE AT THE SITE: None

- EP & S installed Tnk Tank high level alarm.

- Final inspection by Building Dept. O.K. of Tnk system.

Privileged and Confidential

APPENDIX D
PROJECT/SITE SPECIFIC HEALTH AND SAFETY PLAN (HASP)

Clayton
ENVIRONMENTAL
CONSULTANTS

HEALTH AND SAFETY PLAN
for
Tank Closure and Installation
at
Macy's Department Store
Galleria Mall
100 Main Street
White Plains, New York

Prepared for:

Federated Department Stores, Inc.
7 West 7th Street
Cincinnati, Ohio 45202

Project No. 40-97140.00

Prepared by:

Clayton Environmental Consultants, Inc.
160 Fieldcrest Avenue
Raritan Center
Edison, New Jersey 08837

January 10, 1997

The purpose of this Health and Safety Plan (HASP) is to facilitate compliance with laws and regulations relating to health, safety, and the environment.

As such, Clayton Environmental Consultants, Inc. (Clayton), has prepared this HASP for use by all Clayton personnel, to provide the means to achieve safe working conditions and to protect the health and safety of all personnel involved in this project and the environment.

This project/site-specific HASP has been prepared by Clayton in accordance with 29 Code of Federal Regulations (CFR) 1910.120 Paragraph (a). The HSAP covers the in-place closure of two 10,000-gallon underground storage tanks (USTs) containing fuel oil, and the installation of one 1,000 gallon aboveground storage tank (AST). This plan documents specific requirements and procedures for the protection of Clayton's field personnel while performing the oversight of the project at the facility. Emergency and site contacts are provided in Appendix 1 along with a map to the local emergency care facility. Key Clayton personnel involved with this project and their respective titles are listed below.

Health & Safety Officer and Project Manager:
Susan Bayat, P.E. Date
Susan Bayat 1-10-97


Health & Safety Coordinator:
Sanford E. Garrett Date

Clayton
ENVIRONMENTAL
CONSULTANTS

SITE HEALTH AND SAFETY PLAN ACKNOWLEDGMENT FORM

SITE: Macy's, Galleria Mall, White Plains, New York
PROPOSED DATE OF SITE WORK: January 13, 1997

By placing my signature below, I certify that I have read this site Health and Safety Plan (HASP), fully understand its requirements, and will follow all safety directives set forth by the plan or dictated by Clayton, as long as I am present at this site.

Name (Print)	Signature	Date
Glenn Merto		1-13-97

CONTENTS

Section		Page
1.0	INTRODUCTION	1
2.0	OBJECTIVE	1
2.1	SITE DESCRIPTION	1
2.2	WORK ACTIVITIES	1
3.0	ORGANIZATION OF SITE SAFETY	2
4.0	SITE CHARACTERIZATION	2
4.1	DESCRIPTION OF THE SITE	2
4.2	DESCRIPTION OF THE WASTES	2
5.0	SITE CONTROL	2
5.1	CONTAMINANT CONTROLS	3
6.0	HAZARD ASSESSMENT	3
6.1	CHEMICAL HAZARDS	3
6.2	PHYSICAL HAZARDS	3
6.3	ENVIRONMENTAL HAZARDS	4
6.4	CONFINED SPACE ENTRY HAZARDS	4
7.0	HEALTH AND SAFETY CONCERNS FOR AIRMONITORING AND SAMPLING PROCEDURES	4
7.1	AIR MONITORING PROCEDURES	4
7.2	AIR SAMPLING PROCEDURES	4
8.0	PERSONAL PROTECTION	5
8.1	PRIMARY	5
8.2	CONTINGENCY	5
9.0	DECONTAMINATION AND DISPOSAL	5

APPENDIXES

1 EMERGENCY RESPONSE PLAN
2 MATERIAL DATA SHEETS/CHEMICAL TOXICOLOGICAL DATA
3 PERSONAL PROTECTIVE EQUIPMENT PROGRAM
4 SCOPE OF SERVICES

FIGURES

1 Site Sketch

1.0 INTRODUCTION

This document presents the Health and Safety Plan (HASP) to be implemented during the field activities conducted during the week of January 13, 1997, at Macy's Department Store, Galleria Mall, 100 Main Street, White Plains, New York. This plan is applicable to all Clayton personnel, and its subcontractors at the site. All onsite activities will be performed in accordance with the Occupational Safety and Health Administration (OSHA) standards (Title 29 CFR 1910 and 1926) and in accordance with other applicable federal, state, and local regulations.

2.0 OBJECTIVE

It is the objective of this HASP to establish a means to provide a safe work environment for site personnel, to provide a uniform and concise policy of action, and to provide all site personnel with the necessary guidance to adhere to the policies. The organization of this program and the procedures contained herein have been based on an evaluation of potential hazards at the site and the recognized standard procedures in response to these hazards.

2.1 SITE DESCRIPTION

The site is located in White Plains, New York and includes a four-story department store building. There is a loading dock-parking area at the north side of the building. Two 10,000-gallon underground storage tanks (USTs) are located on the northwest side of the building in the loading dock area and contain a combined residual volume of approximately 7,000 gallons of No. 2 heating oil. The tanks were installed in 1979 and are currently active.

2.2 WORK ACTIVITIES

The work to be performed on the site includes in-place closure of the tanks by a subcontractor and supervised by Clayton. Environmental Products & Services, Inc. (EP&S) has been subcontracted to perform the UST closure activities at the Macy's site, in accordance with scope of services provided in Appendix 4 The New York State Department of Environmental Conservation (NYSDEC) guidelines as specified in a memorandum dated January 20,1987, to Regional Water Engineers and Regional Solid and Hazardous Waste Engineers regarding the permanent closure of petroleum tanks, will be followed for the closure of the two existing tanks. As described in the memorandum under section 4.0 "Tank Abandonment In-Place" the tanks will be emptied and the piping will be drained into the tank. The remaining waste inside the tanks will be removed manually. A visual inspection of the tank's interior will be performed. If any holes are discovered, then soil sampling is required. Since the tanks are located on a concrete pad, the soil sampling will require removal of the tanks and the concrete pad. If petroleum is present in the soil, a spill report will be filed with the NYSDEC, and appropriate regulations and guidelines regarding the situation will be followed.

Clayton has subcontracted A & P Rainaldi, Inc. to install the piping associated with a new 1,000 gallon AST located on the southeast of the loading dock as shown on the site plan. The scope of work is also provided in Appendix 4.

3.0 ORGANIZATION OF SITE SAFETY

All personnel who participate under the authority of Clayton shall be in compliance with all training and medical monitoring requirements as established in, but not limited to, 29 CFR 1910.120, 1910.1200, and 1910.134. In addition, certification of training and medical monitoring shall be documented in EP&S personnel files for each subcontractor employee.

The Health and Safety Officer will have the authority to implement specific health and safety requirements for specific site activities, and to ensure that all Clayton employees and onsite personnel under authority of Clayton follow the policies and procedures of this program. It is the responsibility of other organizations to ensure compliance of this plan by its onsite employees.

4.0 SITE CHARACTERIZATION

4.1 DESCRIPTION OF THE SITE

A site plan which includes the locations of the USTs and the AST inside the loading dock is provided in Figure 1.

There have been no past records or present evidences of any leak or spill at the Macy's site. In addition Macy's personnel are not aware of any documented evidence or information that the tanks are suspected of having leaked in the past. Also, NYSDEC - Region 3 has not been informed or aware of any spills or leaks regarding the tanks.

4.2 DESCRIPTION OF WASTES

If suspected fuel oil has contaminated the subsurface soils, the toxic characteristics of the fuel oil will change the overall hazard present at the site to low.

5.0 SITE CONTROL

Access to the work area will be limited to those directly involved in field investigation. Control of access within 10 feet where possible of all activities will be established by the Site Supervisor or designated representative. Personnel not associated with field investigation activities will not be allowed into the work area unless accompanied by Clayton's Health and Safety Officer or Site Supervisor. Where unauthorized access is a concern, barricades or other mechanisms will be used to restrict access.

If "Exclusion Zones" are identified at the site, minimum two people are required for entry into such zone where level "C" or higher levels of protection is required. Visual and, when possible, audible contact will be maintained while in the Exclusion Zone. The signal for emergency work stoppage and evacuation will be verbal and hand signals, as appropriate.

5.1 CONTAMINANT CONTROLS

Each work area will require the establishment of boundaries, separating the areas defined as exclusion zones (actual remediation areas), decontamination zones (areas in which personal protective equipment is removed) and clean zones (uncontaminated/decontaminated areas). These areas are designed to reduce the risk of transporting contaminants outside the exclusion zone. Upon exiting the exclusion zone all employees will implement decontaminated procedures for the removal of all personal protective equipment (PPE) prior to entering uncontaminated areas.

Any fuel oil removed will be suctioned directly to a vacuum truck or 55-gallon drums. If soils are excavated, a sample will be collected and submitted for laboratory analysis. Pedestrian traffic will be kept to a minimum of ten feet from the work area, where possible. All truck traffic will be restricted to the area outside the limited access area.

6.0 HAZARD ASSESSMENT

6.1 CHEMICAL HAZARDS

All suspected site contaminants and their respective characteristics, symptoms of exposure, chemical and physical hazards are listed in Appendix 2.

6.2 PHYSICAL HAZARDS

- Low Flash Point: No. 2 fuel oil has a relatively low flash point which would make the product highly ignitable.
- General Construction Dangers: Close proximity to heavy equipment poses a crush potential. Hard hats and steel toe boots shall be worn around heavy equipment operations.
- Slip/Trip: Boring work will entail working inclose proximity to heavy equipment, and the associated pipes, cables, and lines.
- Electrical/Shock/Spark: If any excavation becomes necessary, EP&S will notify local utilities prior to start up of excavation. In additions, electrical blueprints and plans will be consulted to mark out the location of underground cables and/or piping, if required.

- Overhead/Underground Power Lines: All large machine equipment should maintain a minimum separation distance of 10 feet from all power lines.

- Noise: The cleaning and vacuuming rigs may increase the noise level across the site during installation.

6.3 ENVIRONMENTAL HAZARDS

Environmental hazards in this project appear to be limited to the potential release of fuel oil into the environment.

6.4 CONFINED SPACE ENTRY HAZARDS

During the UST closure activities, confined space entry hazard will be present when EP&S personnel enters the tank. On the day of initial entry, the EP&S personnel required to enter the confined space should be instructed by EP&S site supervisor as to the nature of the hazard, the necessary precautions, and the use of protective and emergency equipment. EP&S will provide the necessary entry and rescue equipment, such as tripod, hoist, full body harness, lifeline, or equivalent.

7.0 HEALTH AND SAFETY CONCERNS FOR AIR MONITORING AND SAMPLING PROCEDURES

7.1 AIR MONITORING PROCEDURES

EP&S will provide an oxygen meter and a lower explosive limit (LEL) meters. The oxygen meter and LEL meter will be calibrated and used to continuously monitor the risk for explosion and the concentration of oxygen in and around the tank. No sparking equipment will be used until the risk of explosion and flammability have been eliminated. If excavation is necessary, a photo ionization detector (PID), such as an HNu PI-101 or OVM, will be calibrated and used to monitor ambient air conditions during all excavation activities. The purpose of this periodic air monitoring is to assess potential areas of contamination and detect the presence of volatile organic compounds (VOCs). If VOCs are consistently detected in excess of background levels in the breathing zone (unknown chemicals), the area will be evacuated and the use of appropriate respiratory protection will be determined and implemented. As an added precaution, personnel will make every attempt to remain upwind of and at a safe distance from activities at all times.

7.2 AIR SAMPLING PROCEDURES

Air sampling is not required on this project. Clayton will establish Health and Safety requirements for sampling procedures if necessary. In general, all sampling operations will require protection from potential inhalation and skin absorption of contaminants. Real time

ambient monitoring shall be established as outlined in Section 7.1.

8.0 PERSONAL PROTECTION

8.1 PRIMARY

All field personnel shall perform onsite activities using at a minimum Level D personal protective equipment. Level D protection is designed for use when only minor skin and eye protection is needed and airborne contamination is unlikely. Smoking, eating, or drinking will not be permitted in or near exclusion zones. Personal equipment requirements for Level D include:

- Hard hat
- Goggles or safety glasses
- Work gloves
- Coveralls, long-sleeve
- Steel-toe safety boots
- Ear protection, if the noise from the cleaning and vacuuming equipment is substantial.

8.2 CONTINGENCY

Levels of protection may be modified under the direction of the onsite supervisor so long as it is justified and recorded in this HASP.

9.0 DECONTAMINATION AND DISPOSAL

At a minimum, all disposable Personal Protective Equipment (PPE) used for sampling operations shall be removed and containerized for proper disposal. Reusable PPE and small equipment will be decontaminated with a non-phosphate soap and water solution and rinsed with water. All wash and rinse solutions will be collected and containerized for eventual proper disposal. Large equipment, such as the tank cleaning equipment, will be cleaned as necessary prior to removal from the site. Wash and rinse water shall be collected and containerized for proper disposal.

The onsite supervisor or their designated representative shall periodically assess the effectiveness of the decontamination procedure and has the authority to correct the decontamination procedure to preclude the spread of contamination.

APPENDIX 1

EMERGENCY RESPONSE PLAN

EMERGENCY CONTACTS

Ambulance:	911
White Plains Hospital (Emergency):	(914) 681-1155
White Plains Fire Department	911or (914) 422-6300
Police:	911
Department of Health:	(518) 458-6305
Hazardous Materials National Response Center	911 or (800) 424-8802

CLAYTON ENVIRONMENTAL CONSULTANTS, INC. CONTACTS

Jeffrey W. Bradstreet, Director Environmental Management Services:	(908) 225-6040 Office
Sanford E. Garrett, Manager:	(908) 225-6040 Office
Susan Bayat, P.E.	(908) 225-6040 Office

MACY'S CONTACTS

Frank Steixer, Store Engineer	(914) 946-5015 ext. 2359 (914) 421-4359
Sean Havey, Regional Engineer	(718) 802-7645

NEW YORK DEPARTMENT of ENVIRONMENTAL CONSERVATION

New York State Department of Environmental Conservation	(800) 457-7362

HOSPITAL:


Name: White Plains Hospital	(914) 681-0600

Route to hospital from site see following Hospital Location Map.

Direction to Hospital:

- Make a right turn onto Main Street
- Make a right turn onto Court Street
- Follow Court Street approximately half-mile to State Route 22
- Make a right onto SR 22, go approximately half-mile on SR 22 and hospital is on left.

HOSPITAL LOCATION MAP



Macy's
Galleria Mall
100 Main Street
White Plains, New York

FIGURE 1
Hospital Location Map

Clayton Project No.: 40-97140.00

Clayton
ENVIRONMENTAL CONSULTANTS

EMERGENCY RESPONSE GUIDELINES

1. In the event of a life threatening/serious injury emergency, any person has the authority to stop all site work activities.

2. The signal for cessation of work shall be an agreed verbal and/or hand signal. The egress signal shall be verbal or hand signal.

3. The Site Supervisor shall take full responsibility and authority to implement the ER Plan.

4. Access/egress through the decontamination corridor may be modified to expedite the egress of personnel from imminently dangerous situations.

5. No person shall compromise their personal health and safety when attempting to accomplish a task (for example, containing a leak, saving a life).

6. Decontamination procedures shall be followed unless an injury is life threatening where time is a critical factor. In this case, the contaminated injured person shall be covered or wrapped with uncontaminated material (plastic bags, blanket, etc.) for transport to the medical facility.

7. A personal shall accompany the injured individual to the medical facility. That person is instructed to carry a complete copy of the HASP, including MSDSs. That person has the responsibility to answer pertinent questions and give information as to the type and level of exposure and any known acute or chronic health effects of exposure.

8. Appropriate action shall be taken to minimize the spread of contamination to personnel, the public, and the environment in the event of a spill or release.

APPENDIX 2

MATERIAL DATA SHEETS/CHEMICAL TOXICOLOGICAL DATA

TABLE 1

Contaminant Profile

Contaminant	Concentrations on site	IDLH/TLV	Effects	Known Carcinogen	Maximum Concentrations for respirator use
Benzene	Unknown	3,000ppm/ 1ppm	eye irritation, dermatitis, headaches, unconsciousness	Yes	1ppm
Toluene	Unknown	2000ppm/ 100ppm	eye irritation, dermatitis, headaches, unconsciousness	No	1000ppm CCROV/SA/PAPROV/SCBA
Ethylbenzene	Unknown	2000ppm/ 100ppm	eye irritation, dermatitis, headaches, unconsciousness	Yes	1000ppm PAPROV/SA/SCBA
Xylene	Unknown	1000ppm/ 100ppm	eye, nose, throat irritation, headaches, dizziness, dermatitis	No	1000ppm CCROV/PAPROV/SA/SAV

Clayton ENVIRONMENTAL CONSULTANTS

APPENDIX 3

PERSONAL PROTECTIVE EQUIPMENT PROGRAM

The purpose of the Personal Protective equipment (PPE) Program is to protect the wearer from safety and health hazards and to prevent injury to the wearer from incorrect use and/or malfunction of the PPE. To achieve this purpose, Clayton's comprehensive program includes hazard identification; medical monitoring; environmental surveillance; selection, use, maintenance, and decontamination of PPE; and training. These elements are discussed either in this or other sections of this Safety and Health Program and are incorporated in this PPE Program.

Copies of this PPE Program will be made available to all Clayton employees and a reference copy will be made available by the Site Supervisor at each work site. Technical data on equipment, maintenance manuals, relevant regulations, and other essential information will also be collected, maintained and made available.

This PPE Program will be reviewed at least annually to evaluate its effectiveness. Elements which will be considered in the review include:

- A survey of each site to ensure compliance with regulations applicable to the specific site involved.
- The number of persons-hours that workers wear various protective ensembles.
- Accident and illness experience.
- Levels of exposure.
- Adequacy of equipment selection.
- Adequacy of the operational guidelines.

Clayton's program for selection of appropriate PPE is based upon 40 CFR 1910.120, Appendix B, *General Description and Discussion of the Levels of Protection and Protective Gear* and *Guidelines for the Selection of Chemical Protective Clothing*, (Swope, et al., 1985). As required by 40 CFR 1910.120, PPE is selected which will protect employees from the specific hazards which they are likely to encounter during their work onsite.

Key factors which will be addressed in the selection of appropriate PPE are identification of the hazards, or suspected hazards; their routes of potential hazard to employees (inhalation, skin absorption, ingestion, and eye or skin contact), and the performance of the PPE materials (and seams) in providing a barrier to these hazards. The amount of protection provided by PPE is material-hazard specific. That is, protective equipment materials will protect against some hazardous substances and poorly, or not at all, against others. In instances where protective equipment cannot be found which will provide continuous protection from a particular hazardous substance, work durations will be set such that hazardous levels will not be exceeded as a result of breakthroughs.

Other factors in the selection process which will be considered are matching the PPE to the employee's work requirements and task-specific conditions. The durability of PPE materials, such as tear strength and seam strength, will be considered in relation to the employees tasks. Also to be considered are the effects of PPE in relation to heat stress and task duration. Where appropriate, layers of PPE may be selected to provide sufficient protection or to protect expensive PPE inner garments, suits, or equipment. Based on these criteria, PPE categorized as Level A, B, C, or D (or combinations of these levels if appropriate) will be selected to provide the proper level of protection.

Level A protection will be selected for use when:

1. The hazardous substance has been identified and requires the highest level of protection for skin, eyes, and the respiratory system based on either the measured (or potential for) which concentration of atmospheric vapors, gases, or particulates, or materials that are harmful to skin or capable of being absorbed through the skin;

2. Substances with a high degree of hazard to the skin are known or suspected to be present, and skin contact is possible; or

3. Operations are being conducted in confined, poorly ventilated areas, and the absence of conditions requiring Level A have not yet been determined.

Level A protection consists of:

1. Positive pressure, full face-piece self-contained breathing apparatus (SCBA), or positive pressure supplied air respirator (SAR) with escape SCBA, approved by the National Institute for Occupational Safety and Health (NIOSH).

2. Totally-encapsulating chemical-protective suit

3. Coveralls (optional)

4. Long underwear (optional)

5. Chemical-resistant outer gloves

6. Chemical-resistant inner gloves

7. Chemical-resistant boots with steel toe and shank

8. Hard hat (under suit, optional)

9. Disposable protective suit, gloves, and boots (depending on suit construction, may be worn over totally-encapsulating suit).

Level B protection will be selected for use when:

1. The type and atmospheric concentration of substances have been identified and require a high level of respiratory protection, but less skin protection than Level A;

2. The atmosphere contains less than 19.5% oxygen; or

3. The presence of incompletely identified vapors or gases is indicated by a direct reading organic vapor detection instrument, but vapors and gases are not suspected of containing high levels of chemical harmful to skin or capable of being absorbed through the skin.

Level B PPE is the minimum level of protection recommended for initial site entries until the hazards have been further identified or unless the hazard level is known.

Level B protection consists of:

1. Positive pressure, full-face piece self-contained breathing apparatus (SCBA), or positive pressure supplied air respirator with escape SCBA (NIOSH approved).

2. Hooded chemical-resistant clothing (overalls and long-sleeved jacket; coveralls; one or two piece chemical-splash suit; disposable chemical-resistant overalls).

3. Coveralls (optional).

4. Chemical-resistant outer gloves.

5. Chemical-resistant inner gloves.

6. Chemical-resistant outer boots with steel toe and shank.

7. Chemical-resistant outer boot-covers (disposable, options).

8. Hard hat (optional).

9. Face shield (optional).

Level C protection will be selected for use when:

1. The atmospheric contaminants, liquid splashes, or other direct contact will not adversely affect or be absorbed through any exposed skin;

2. The types of air contaminants have been identified, concentrations measured and an air-purifying respirator is available that can remove the contaminants, and;

3. All criteria for the use of air-purifying respirators are met,

Level C protection consists of:

1. Full-face or half-mask, air-purifying respirators (NIOSH approved).

2. Hooded, chemical-resistant clothing (overalls; two-piece chemical-splash suit; disposable chemical-resistant overalls).

3. Coveralls (optional).

4. Chemical-resistant outer gloves.

5. Chemical-resistant inner gloves.

6. Chemical-resistant outer boots with steel toe and shank (optional).

7. Chemical-resistant outer boot-covers (disposable, optional).

8. Hard hat (optional).

9. Escape mask (optional).

10. Face shield (optional).

Level D protection will be selected for use when:

1. The atmosphere contains no known hazard, and;

2. Work functions preclude splashes, immersion, or the potential for unexpected inhalation of or contact with hazardous levels of any chemicals.

Level D protection consists of:

1. Coveralls.

2. Gloves (optional).

3. Chemical-resistant boots/shoes with steel toe and shank.

4. Chemical resistant outer boot-covers (disposable, optional).

5. Safety glasses or chemical-splash goggles (optional).

6. Hard hat (optional).

7. Escape mask (optional).

8. Face shield (optional).

PPE can offer a high degree of protection only if it is used properly. Essential to proper use is adequate PPE training to:

- Allow the user to become familiar with the equipment in a nonhazardous situation.
- Instill confidence of the user in his/her equipment.
- Make the user aware of the limitations and capabilities of the equipment.
- Increase the efficiency of operations performed by workers wearing PPE.
- Possibly increase the protective efficiency of PPE use.
- Reduce the expense of PPE maintenance.

Training will be completed prior to actual PPE use in a hazardous environmental and will be repeated at least annually. The training portion of the PPE program will delineate the user's responsibilities and, utilizing both classroom and field training when necessary, explain the following:

- Applicable OSHA requirements (20 CFR 1910, Subparts I and Z).
- The proper use and maintenance of the selected PPE, including capabilities and limitations.
- The nature of the hazards and the consequences of not using the PPE.
- The human factors influencing PPE performance
- Instruction in inspection, donning, checking, fitting and using PPE.
- Individualized respirator fit testing to ensure proper fit.

- Use of PPE in normal air for a long familiarity period and, finally, wearing PPE in a test atmosphere to evaluate its effectiveness.

- The user's responsibility (if any) for decontamination, cleaning, maintenance, and repair of PPE.

- Emergency procedures and self-rescue in the event of PPE failure.

- The buddy system.

- The Site Safety Plan and the individual's responsibilities and duties in an emergency.

Clayton employees who are required by 40 CFR 1920.120(e) to receive the 40 hour or 24 hour offsite training will receive, as part of that training, instruction in the selection, use, donning and doffing, decontamination and disposal, inspection, and maintenance and storage of PPE. Also, these employees will be respirator fit tested at least annually in accordance with accepted protocols including 20 CFR 1910, Sections 132-140.

Manufacturer's recommendations with respect to PPE use and limitations of the equipment, inspection procedures, donning and doffing procedures, proper fit, decontamination, and maintenance and storage will be followed where available for particular pieces of equipment.

The discomfort and inconvenience of wearing PPE can create a resistance to the conscientious use of PPE. Clayton recognizes that making the user aware of the need for PPE and instilling motivation for the proper use and maintenance of PPE are essential aspects of training.

Before workers actually begin work in their PPE ensembles, the anticipated duration of the work mission will be established. Factors that limit mission length which will be considered include:

- Air supply consumption.
- Suit/ensemble permeation and penetration by chemical contaminants.
- Ambient temperature.
- Coolant supply.

The duration of the air supply will be considered before planning any SCBA-assisted work activity. Although the anticipated operating time of an SCBA is clearly indicated on the breathing apparatus, this designated operating time is based on a moderate work rate. In actual operation, several factors can reduce the rated operating times. Therefore, work actions and operating time will be adjusted based on the following variables:

- Work rate. The actual in-use duration of SCBAs may be reduced by one-third to one-half during strenuous work.

- Fitness. Well-conditioned individuals generally utilize oxygen more efficiently than unfit individuals, thereby slightly increasing the SCBA operating time.

- Body size. Larger individuals generally consume air at a higher rate than small individuals, thereby decreasing SCBA operating time.

- Breathing patterns. Quick, shallow or irregular breaths use air more rapidly than deep, regularly spaced breaths. Heat-induced anxiety and lack of acclimatization may induce hyperventilation, resulting in decreased SCBA operating time.

Mission duration may be limited by the possibility of chemical permeation or penetration of PPE during the work mission. The possibility of valve leakage due to temperature extremes and the ability of the PPE material to remain an effective barrier to chemicals of concern over time will be considered in establishing the duration of work mission.

The ambient temperature has a major influence on work mission duration because it affects both the worker and the protective integrity of the PPE. For the worker, heat stress is the greatest immediate danger of being ensemble-encapsulated. Mission duration will be set to avoid heat stress and workers will be monitored for indications of heat stress where appropriate. The protective integrity of the PPE may be affected because hot and cold ambient temperatures affecting:

- Valve operation on suits and/or respirators.
- The durability and flexibility of suit material.
- The integrity of suit fasteners.
- The breakthrough times and permeation rates of chemicals.
- The concentration of airborne contaminants.

Finally, under warm conditions, if coolant is necessary, the duration of the coolant supply will directly affect mission duration.

During PPE use, employees will be encouraged to report any perceived problems or difficulties to their supervisor(s) in order that they may be expeditiously addressed. These malfunctions may include:

- Degradation of the protective ensemble.
- Skin irritation.
- Unusual residues on PPE.
- Discomfort.
- Resistance to breathing.
- Fatigue due to respirator use.
- Interference with vision or communication.
- Restriction of movement.
- Personal responses such as rapid pulse, nausea, and chest pain.

APPENDIX 4

SCOPE OF WORK

January 8, 1997

ATTACHMENT A: ENVIRONMENTAL PRODUCTS AND SERVICES, INC. (EP&S)
SCOPE OF WORK:

EP&S (Subcontractor) will furnish all labor and materials necessary to complete the in-place closure of the two 10,000 gallon tanks at the Macy's Department Store, White Plains, New York, according to the following scope of work.

- Traffic Control Measures (cones, caution tape, signs)
- Remove all pumpable product, (appr. 7,000 gal.), then clean and dispose of tank bottoms
- Cold saw a four inch diameter sample hole in tank bottoms and collect soil sample from each, if necessary.
- Fill tanks 100% full Petro Fill Foam or concrete
- Remove the fill pipe, vent pipe and product piping

Please make note of the following:

- All work must confirm with applicable standards and local, state, and federal regulations
- Environmental Products & Services, Inc. (EP&S) is responsible for removing all rubbish, debris, unused, and surplus material due to or connected with the closure of the tanks at the site.
- EP&S shall review the Project Health and Safety Plan and comply with the requirements of the Plan. EP&S should advise Clayton of any deviation from the Plan.

The above scope of work shall be performed under the Terms and Conditions of the General Contract Agreement between Clayton and EP&S signed in July 1996.

January 7, 1997

ATTACHMENT A: A&P RAINALDI, INC. SCOPE OF WORK:

A&P Rainaldi, Inc. (Subcontractor) will furnish and install all labor and materials necessary to complete the plumbing work for the installation of the aboveground storage tank at the Macy's loading dock area, according to the following scope of work:

1. Installation 1" steel suction and return line to the pump set inside the boiler room. This includes cutting or drilling a hole on the boiler room's wall in the appropriate location and repairing it after installation is complete.

2. Installation of the tank accessories provided by others, including the tank alarm, tank level gauge, up-flow vent, and emergency vent.

3. Installation of the 2" steel remote fill line along the south wall of the loading dock and secure it to the wall in an appropriate manner.


4. Air test the tank and the new piping.

- All work must confirm with applicable standards and local, state, and federal regulations
- The Subcontractor is responsible for rectifying any problem or malfunctioning of the system after the startup, if the problem is due to installation, including but not limited to any leak from the new piping.
- The Subcontractor is responsible for removing all rubbish, debris, unused, and surplus material due to or connected with the installation of the tank at the site.
- The Subcontractor shall review the Project Health and Safety Plan and comply with the requirements of the Plan. The Subcontractor should advise Clayton of any deviation from the Plan.

The above scope of work will be furnished for the amount of $3,000 (three thousand dollars), as proposed by the A&P Rainaldi Inc.

FIGURE 1

SITE PLAN



FEDERATED DEPARTMENT STORES. INC.
GALLERIA SITE 030012
1ST FLOOR PLAN
(NOT TO SCALE)

Privileged and Confidential

APPENDIX E
PROJECT COMPLETION DOCUMENTATION

New York Regional Office

Raritan Center
160 Fieldcrest Avenue
Edison, NJ 08837
(908) 225-6040
Fax (908) 225-4577

Clayton
ENVIRONMENTAL
CONSULTANTS

February 5, 1997

Mr. Peter A. Russo
Senior Code Enforcement Officer
CITY OF WHITE PLAINS
DEPARTMENT OF BUILDING
255 Main Street Annex
White Plains, New York 10601

Clayton Project No. 40-97140.00

Subject: Tank Closure at Macy's Department Store, White Plains, New York

Dear Mr. Russo:

Enclosed please find the documents regarding the completion of the in- place closure of the two 10,000-gallon underground storage tanks at Macy's Department Store located at 100 Main Street, White Plains, New York.

If you have any question regarding this matter, please do not hesitate to call me at 908-225 6040.

Sincerely,

Susan Bayat

Susan Bayat, P.E.
Senior Environmental Engineer
Environmental Management and Remediation
New York Regional Office

Enclosure

SB:/jw

A:\SBMACYS.WPD

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER COPY

CUSTOMER CODE NO.	RECEIPT NUMBER
COH1	27416
CUSTOMER P.O. NO.	DATE
35929	01/14/97

DELIVERY RECEIPT

9:30 AM

SOLD TO: COD CONTRACTOR

SHIP TO: ENVIRO. PROD. SERV.
MALYS LOADING DOCK
100 MAIN ST------WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
43	RON R.	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CFC60	10.00C Y	FILL CRETE 60 PSI	59.00	590.00
WIN	10.00CY	WINTER SERVICE	4.00	40.00

Pri' Rock
Cust #127
3394

(10)

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE: GALS.	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RETURNED TO PLANT
WATER AUTHORIZED BY	8/	20	529		

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X _____
RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	630.00
TAX 7.75%	48.83
SHORT LOAD	
OVERTIME	
TOTAL	678.83

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
CUST	
CUSTOMER P.O. NO.	DATE
35929	01/14/97

DELIVERY RECEIPT

9:45 AM

SOLD TO: COD CONTRACTOR

SHIP TO: ENVIRO. PROD. & SERV.
MACYS LOADING DOCK
100 MAIN ST------WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
35	Dom S.	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CTC50	12.00C.Y	FTIL CRETE 50 PSI	59.00	708.00
WIN	12.00CY	WINTER SERVICE	4.00	48.00
	22			

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

SUB TOTAL	756.00
TAX 7.5%	56.69
SHORT LOAD	
OVERTIME	
TOTAL	812.69

WATER ADDED ON JOB SITE ____ GALS.	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
WATER AUTHORIZED BY	9:00	9:15	9:34		

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X _____
RECEIVED IN GOOD ORDER BY-SIGN

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
C001	27012
CUSTOMER P.O. NO.	DATE
359291	01/14/97

DELIVERY RECEIPT

SOLD TO: COD CONTRACTOR

SHIP TO: SENVIRO PROD. & SERV.
MACYS LOADING DOCK
100 MAIN ST---WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
33	[redacted] LINTON	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CFC50	12.00C.Y	FILL CRETE 50 PSI	59.00	708.00
WIN	12.00CY	WINTER SERVICE	4.00	48.00
	(34)			

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE GALS.	LEFT PLANT	ARR. JOB	STARTED DISCHARGE	LEFT JOB	RET'D PLANT
WATER AUTHORIZED BY	10:00 AM	10:15 AM	10:30 AM	10:45 AM	

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X [signature]
RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	756.00
TAX 7.75%	58.59
SHORT LOAD	
OVERTIME	
TOTAL	814.59

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
COU1	27413
CUSTOMER P.O. NO.	DATE
35929	01/14/97

DELIVERY RECEIPT

SOLD TO
COD CONTRACTOR
.

SHIP TO
ENVIRO. PROD. & SERV.
MACYS LOADING DOCK
100 MAIN ST----WHITE PLAINS
.

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
34	BOB D	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
C1C50	12.00C.Y	FILL CRETE 50 PSI	59.00	708.00
WIN	12.00CY	WINTER SERVICE	4.00	48.00
	(46)			

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

	SUB TOTAL	756.00
	7.75% TAX	58.69
	SHORT LOAD	
	OVERTIME	
	TOTAL	814.69

WATER ADDED ON JOB SITE _____ GALS.
WATER AUTHORIZED BY _____

LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
950	10	1010	1022	

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

x _____
RECEIVED IN GOOD ORDER BY-SIGN

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
CUSTOMER P.O. NO.	DATE 01/14/97

DELIVERY RECEIPT

SOLD TO: COD CONTRACTOR

SHIP TO: ENVIRO. PROD. SERV.
MACYS
100 MAIN ST-----WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
43	RON RITACCO	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CFC60	10.00C.Y	FILL CRETE 60 PSI	59.00	590.00
WIN	10.00CY	WINTER SERVICE	4.00	40.00
	56	GLENN S.		

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE GALS. / WATER AUTHORIZED BY	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
	1000	1010	1030	1040	

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X _____ RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	630.00
TAX	48.83
SHORT LOAD	
OVERTIME	
TOTAL	678.83

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
COD1	27414
CUSTOMER P.O. NO.	DATE
35929	01/14/97

DELIVERY RECEIPT

SOLD TO
COD CONTRACTOR
.

SHIP TO
ENVIRO. PROD. & SERV.
MACYS LOADING DOCK
100 MAIN ST-----WHITE PLAINS
.

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
35	Dom S.	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CFC60	12.00C.Y	FILL CRETE 60 PSI	59.00	708.00
WIN	12.00CY	WINTER SERVICE	4.00	48.00

68

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE / GALS.	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
WATER AUTHORIZED BY	10:40	10:50	10:55		

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X
RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	756.00
7.75% TAX	58.59
SHORT LOAD (OVERTIME)	
TOTAL	814.59

CUSTOMER COPY

BYRAM Concrete & Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
COD1	27418
CUSTOMER P.O. NO.	DATE
	01/14/97

DELIVERY RECEIPT

SOLD TO: COD CONTRACTOR

SHIP TO: ENVIRO. PROD. & SERV.
MACYS
100 MAIN ST-----WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
34	BUD D.	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
FC50	12.00C.Y	FILL CRETE 50 PSI	59.00	708.00
WIN	12.00CY	WINTER SERVICE	4.00	48.00

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE ____ GALS.	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
WATER AUTHORIZED BY	1045	1035	1125	1145	

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X Glenn Martin
RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	756.00
7.75% TAX	58.59
SHORT LOAD	
OVERTIME	
TOTAL	814.59

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
CODI	27419
CUSTOMER P.O. NO.	DATE
	01/14/97

DELIVERY RECEIPT

SOLD TO
COD CONTRACTOR

SHIP TO
ENVIRO. PROD. & SERV.
MACYS
100 MAIN ST-------WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
43	RON RIACCO	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CFC60	10.00C.Y.	FILL CRETE 60 PSI	59.00	590.00
WIN	10.00CY	WINTER SERVICE	4.00	40.00
	90			

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE GALS	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT
WATER AUTHORIZED BY	1120	1150	1251	1245	

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X _____
RECEIVED IN GOOD ORDER BY-SIGN

SUB TOTAL	630.00
7.75% TAX	48.83
SHORT LOAD	
OVERTIME	
TOTAL	678.83

CUSTOMER COPY

BYRAM
Concrete
& Supply Inc.

145 Virginia Road
White Plains, NY 10603
Billing Office (914) 289-0357
Dispatch (914) 682-4477

CUSTOMER CODE NO.	RECEIPT NUMBER
CODI	27420
CUSTOMER P.O. NO.	DATE
	01/14/97

DELIVERY RECEIPT

SOLD TO: CODI CONTRACTING

SHIP TO: ENVIRO. PROD. & SERV
MACYS
100 MAIN ST WHITE PLAINS

TRUCK NO.	DRIVER	LOCATION	DIRECTIONS
35	Dom S.	00001	

ITEM CODE	QUANTITY	DESCRIPTION	UNIT PRICE	EXTENSION
CTC50	10.00CY	FILL CRETE 50 PSI	59.00	590.00
WIN	10.00CY	WINTER SERVICE	4.00	40.00
	(100)			

FOR DELIVERIES BEYOND CURB LINE, THIS COMPANY WILL NOT ASSUME LIABILITY FOR PROPERTY DAMAGE OR PERSONAL INJURY. REQUEST FOR ADDITIONAL WATER WILL BE AT PURCHASER'S RISK. PURCHASER HAS READ THIS RECEIPT AND AGREES TO ALL TERMS CONTAINED HEREIN.

WATER ADDED ON JOB SITE GALS.	LEFT PLANT	ARR. JOB	STARTED TO DISCHARGE	LEFT JOB	RET'D PLANT	
WATER AUTHORIZED BY	12:01	12:15	12:25			

SUB TOTAL	630.00
7.75% TAX	48.83
SHORT LOAD	
OVERTIME	
TOTAL	678.83

CAUTION
Cement powder or freshly mixed concrete, grout or mortar may cause skin injury. Avoid contact with skin and wash exposed skin areas promptly with water. If any cement powder or mixture gets into eyes, rinse immediately with water and get prompt medical attention.

X Glenn Mart
RECEIVED IN GOOD ORDER BY-SIGN

NON-HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. EXEMPT — Manifest Document No. 8758 — 2. Page 1 of

3. Generator's Name and Mailing Address: MACY's Building G, 100 Main street, White plains N.Y.

4. Generator's Phone ( )

Environmental Products & Services

5. Transporter 1 Company Name: A B OIL SERVICE LTD.

6. US EPA ID Number: N.Y.D.9.8.7.0.2.3.3.7.1

DEC IA-002

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address: A B OIL SERVICE LTD., 1599 OCEAN AVENUE, BOHEMIA, NY 11716

10. US EPA ID Number: N.Y.D.9.8.7.0.2.3.3.7.1

A. Transporter's Phone (516) 567-6545

B. Transporter's Phone

C. Facility's Phone (516) 567-6545

11. Waste Shipping Name and Description	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Combustible Liquid N.O.S. (NOO2) PG III, NA1993 NON Hazardous	1	TT	07500	G
b.				
c.				
d.				

D. Additional Descriptions for Materials Listed Above: Contaminated fuel oil

E. Handling Codes for Wastes Listed Above: 514

15. Special Handling Instructions and Additional Information

EMERGENCY RESPONSE NUMBER (516) 567-6545 TRUCK: # TR-1 PLATE: # PP2063

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste.

Printed/Typed Name: X Glenn Merto AGENT — Signature: X Glenn Merto — Month 01 Day 13 Year 97

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: ANTHONY L. CALIGIURI — Signature: Anthony L. Caligiuri — Month 01 Day 13 Year 97

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month — Day — Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Month — Day — Year

GENERATOR

TRANSPORTER

FACILITY

TRANSPORTER #2

WASTE PROFILE REPORT - SYRACUSE FACILITY

Environmental Products & Services, Inc.
532 State Fair Boulevard
Syracuse, NY 13204
(800) 843-8265 FAX (315) 475-8920

RECD APR 11 1997

Office Use Only
Date
Approval No. 11563
Handling Code PC02

A

Customer	~~Macy's~~ CLAYTON ENVIRON.	Generator Site Address	MACY'S WHITE PLAINS
Address	100 ~~MAIN~~ RARITAN CTR.		100 MAIN STREET
	160 FIELDCREST AVE.		WHITE PLAINS, NY 10603
	EDISON, NJ 08837		
Contact	SUE BAYAT	Contact	~~SAME~~ FRANK STEIXNER
Title		Title	
Phone	(908) 225-6040	Phone	(914) 946-5015

B

Type of plant or facility generating waste: DEPARTMENT STORE

Material Description: #2 FUEL OIL CONTAMINATED PPE

Specific Generating Process: TRUCK WASHOUT FROM CLEAN OUT OF UST.

Is this debris or groundwater from a UST Corrective Action per 40 CFR Part 280? ___ YES X NO

Volume 1 Units DRUM Frequency: X One Time ___/Month X /Year

C

List Components by % (total must equal 100):

	Range: Min - Max
#2 FUEL OIL	10 %
PPE	90 %
	%
	%

Does waste contain free liquids? ___YES X NO If yes, 10 % Free Liquid

Does waste have strong odor? ___YES X NO Describe:

Was a TCLP analysis performed? ___ YES X NO

Sample ID No. N/A
PCB <5PPM
Total Halogens <1000 PPM
Flash Point >140°F
Other (state) SOLID LIQUID

D

Is this a RCRA Hazardous Waste? ___YES X NO

Is this a Regulated Hazardous Waste in your state? X YES ___ NO

NY State Waste Code NO11

Other State Codes N/A

Is this generator a conditionally exempt small quantity generator? ___ YES X NO

Is this a DOT Hazardous Material? ___YES X NO

Proper Shipping Name WASTE NON-RCRA, N.O.S. LIQUID (#2 FUEL OIL CONTAMINATED PPE)

DOT Hazard Class NON HAZARDOUS

DOT Identification No. N/A

E

Additional Information: I-0511

I certify the above information is accurate and the waste is not a hazardous waste according to New York State Department of Environmental Conservation and United States Environmental Protection Agency regulations. Environmental Products & Services, Inc. is not permitted for and will not knowingly accept hazardous waste.

Macy's East, Inc.
Generator Name (Print)

Generator's Agent Susan Bayat from Clayton
Authorized Signature

1/13/97
Date

Kevin Lynch
Environmental Products & Services, Inc. Approval (Print Name)

Authorized Signature

2-11-97
Date

White - FACILITY Canary - CUSTOMER Pink - CUSTOMER SERVICE Goldenrod - EPS REPRESENTATIVE

DO NOT DETACH COPIES OF THIS FORM. PLEASE SEE INSTRUCTIONS ON REVERSE SIDE.

2010.FAC.2009409

STRAIGHT BILL OF LADING/NON-HAZARDOUS WASTE MANIFEST

No.

1. Generator Information
Generator Name: MACY'S EAST, INC.
Generator Mailing Address: 151 WEST 34TH STREET, ROOM 120 NEW YORK, NY 10001
Site Address: MACY'S WHITE PLAINS 100 MAIN STREET WHITE PLAINS, NY 10601
Generator Telephone No.: (914) 946-5015

2. Destination/Disposal Facility Information
Company Name: ENVIRONMENTAL PRODUCTS & SERVICES, INC.
Telephone No.: (315) 471-0503
Facility Site Address: 532 STATE FAIR BOULEVARD SYRACUSE, NY 13204

3. Transporter Information
Transporter 1 Company Name: ENVIRONMENTAL PRODUCTS & SERVICES, INC.
Telephone No.: (315) 471-0503
License Plate No.: XV19RR NJ
Transporter 2 Company Name: Environmental Products & Services
Telephone No.: 315-471-0503
License Plate No.: 242685 N.Y.

4. Material/Waste Description

	Containers No.	Containers Type	¹HM	Material Description/ ¹Proper Shipping Name if DOT Hazardous Material	¹Hazard Class	¹ID Number	¹Packing Group	Total Weight/ Volume	Unit of Weight/ Volume
a.	1	DM		WASTE NON-RCRA LIQUID SOLID, N.O.S. (#2 FUEL OIL	NON HAZARDOUS	NONE ~~NOT~~	NONE	55	GAL
b.				CONTAMINATED PPE)					
c.									
d.				(43153)					

5. Job No.: I-0511
6. Approval Nos.: a. 11563 b. c. d.
7. Purchase Order No.: NONE
8. Additional Information: NO11
9. Required Placard(s): NONE

10. Generator Certification: I hereby certify the above-named materials are properly classified, described, packaged, marked, and are in proper condition for transportation according to the applicable regulations of the Department of Transportation.
Generator Name: Macy's East, Inc.
Generator Signature: Generator's Agent Susan Bayat from Clayton
Shipment Date: 1/13/97

11. Acknowledgement of Receipt of Material - To be Completed by Signatories
Transporter 1 Driver Name (Print): GLENN T. SUAREZ Signature: Glenn Suarez Shipment Date: 2-3-97
Transporter 2 Driver Name (Print): Chester J. Brevalle Signature: Shipment Date: 2-6-97

12. Facility Receiving Wastes - Authorized Agent: Kevin Lynch Signature: Receipt Date: 2-10-97
13. Emergency Telephone No.: (315) 471-0503 Contact Name: TOM SALOMON
¹Required for transportation of DOT Hazardous Material only.

14. Discrepancy Indication Space to be Completed by the Disposal Facility.

This form may not be used for wastes identified as hazardous under state or RCRA regulations.

White: Retained by TSDF Green: Mailed by TSDF to Generator Canary: Mailed by TSDF to EPS Branch Pink: Retained by Final Transporter Goldrenrod: Retained by Generator

Environmental Products & Services, Inc., P.O. Box 315, Syracuse, NY 13209

THIS MEMORANDUM

is an acknowledgment that a bill of lading has been issued and is not the Original Bill of Lading, nor a copy or duplicate, covering the property named herein, and is intended solely for filing or record.

Shipper's No. N47A-010

CARRIER: Environmental Products & Services SCAC

Carrier's No. XV19PR
Date

TO: Environmental Products & Services
Consignee
Street 542 S. Fair Blvd
Destination Syracuse NY Zip 13204

FROM:
Shipper Mobil (Environmental)
Street 1 Mobil Ave
Origin White Plains NY Zip 10601

Route:

Vehicle Number 56

No Shipping Units	HM	Kind of Packages Description of Articles (IF HAZARDOUS MATERIALS - PROPER SHIPPING NAME)	HAZARD CLASS	I.D. Number	PACKING GROUP	WEIGHT (subject to correction)	RATE	LABELS REQUIRED (or exemption)
01		WASTE NON-RCRA ~~Solid~~ NOS ((#2 FUEL OIL (TANK BOTTOMS)) SOLID	NOS	NA1	N/A	55	PC	None

Remit C.O.D. to:
Address:
City: State: Zip:

COD Amt: $

C.O.D. FEE:
Prepaid ☐
Collect ☐ $

NOTE — Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding $ Per

Subject to Section 7 of the conditions of this shipment is to be delivered to the consignee without recourse on the consignor, the consignor shall sign the following statement:
The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.
Signature of Consignor

FREIGHT CHARGES
☐ PREPAID ☐ COLLECT

RECEIVED, subject to the classifications and lawfully filed tariffs in effect on the date of issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents and condition of contents of packages unknown), marked, consigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of said property over all or any portion of said route to destination and as to each party at any time interested in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment.
Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation.
Per

PLACARDS REQUIRED None

PLACARDS SUPPLIED ☐ YES ☒ NO -- FURNISHED BY CARRIER
DRIVER SIGNATURE:

SHIPPER: [illegible]
PER:
DATE: 1-13-97

CARRIER: [illegible]
PER: [illegible]
DATE: 1-13-97

EMERGENCY RESPONSE TELEPHONE NUMBER: 315, 471-0503

Monitored at all times the Hazardous Material is in transportation including storage incidental to transportation (172.604)

9-BLS-A3
(Rev 4/91)

© Copyright 1982 II. Published by: J. J. KELLER & ASSOCIATES, INC. • P.O. Box 368 • Neenah, Wisconsin 54957-0368

THIS MEMORANDUM

is an acknowledgment that a bill of lading has been issued and is not the Original Bill of Lading, nor a copy or duplicate, covering the property named herein, and is intended solely for filing or record.

PO # 35930

NY7A-01D
Shipper's No. [illegible]

CARRIER: [illegible]

SCAC

Carrier's No. [illegible]
Date 1-13-97

TO: H/E OIL EQUIPS
Consignee
Street 15 [illegible] AV
Destination ISLIP NY Zip 11716

FROM: [illegible]
Shipper
Street [illegible] MAIN STREET
Origin [illegible] NY Zip 10601

Route: DIRECT

Vehicle Number 794

No. Shipping Units	HM	Kind of Packages, Description of Articles (IF HAZARDOUS MATERIALS - PROPER SHIPPING NAME)	HAZARD CLASS	I.D. Number	PACKING GROUP	WEIGHT (subject to correction)	RATE	LABELS REQUIRED (or exemption)
1		WASTE NON RCRA LIQUID NOS	[illegible] HAZARDOUS	NOI3	N/A	450	G	NONE

Jason Mallister 1/14/97

Remit C.O.D. to: OIL
Address: AB
City: State: Zip:

COD Amt: $

C.O.D. FEE: Prepaid ☐ Collect ☐ $

FREIGHT CHARGES ☐ PREPAID ☐ COLLECT

NOTE — Where the rate is dependent on value, shippers are required to state specifically in writing the agreed or declared value of the property. The agreed or declared value of the property is hereby specifically stated by the shipper to be not exceeding $ Per

Subject to Section 7 of the conditions, if this shipment is to be delivered to the consignee without recourse on the consignor, the consignor shall sign the following statement:
The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.
(Signature of Consignor)

RECEIVED, subject to the classifications and lawfully filed tariffs in effect on the date of issue of this Bill of Lading, the property described above in apparent good order, except as noted (contents and condition of contents of packages unknown), marked, consigned, and destined as indicated above which said carrier (the word carrier being understood throughout this contract as meaning any person or corporation in possession of the property under the contract) agrees to carry to its usual place of delivery at said destination, if on its route, otherwise to deliver to another carrier on the route to said destination. It is mutually agreed as to each carrier of all or any of, said property over all or any portion of said route to destination and as to each party at any time interested in all or any said property, that every service to be performed hereunder shall be subject to all the bill of lading terms and conditions in the governing classification on the date of shipment.
Shipper hereby certifies that he is familiar with all the bill of lading terms and conditions in the governing classification and the said terms and conditions are hereby agreed to by the shipper and accepted for himself and his assigns.

The carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.

Per

PLACARDS REQUIRED NONE

PLACARDS SUPPLIED ☐ YES ☐ NO — FURNISHED BY CARRIER
DRIVER SIGNATURE:

SHIPPER: [illegible]
PER:
DATE:

CARRIER: [illegible]
PER:
DATE:

EMERGENCY RESPONSE TELEPHONE NUMBER: (315) 471-0503

Monitored at all times the Hazardous Material is in transportation including storage incidental to transportation (172.604).

9-BLS-A3
(Rev 4/91)

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Petroleum Bulk Storage Program
Facility Information Report

Printed : 01/21/97

PBS # : 3-173665

Site : MACY'S WHITE PLAINS
100 MAIN ST
WHITE PLAINS, NY 10601

County : WESTCHESTER Town : WHITE PLAINS (C)
Latitude : N Longitude : W
SPDES# : CBS# :
Site Type : Other

Operator : FRANK STEIXNER (914) 946-5015
Emergency : SEAN R. HAVEY (718) 802-7645

Site status : Under 1101 gal.
Total Active Tanks : 0
Active Capacity : 0 gals.

Reg Expires : 12/20/01
Last Inspection : / /
Cert Printed : 12/31/96

Site Errors : Complete
Owner Error : Complete
Tank Errors : No Data

Owner : MACY'S EAST, INC.
151 WEST 34TH STREET' ROOM 1206
NEW YORK, NY 10001

Phone : (718) 802-7645
Owner Type : Corporate/Commercial

Mail : MACY'S EAST, INC.
151 WEST 34TH STREET/ROOM 1206
NEW YORK, NY 10001

Att : SEAN R. HAVEY (718) 802-7645

TankNo	TankLoc	Stat	DateIn	Capac (g)	Product	TankType	TankInt	TankExt	PipeLoc	PipeType	PipeInt	PipeExt	SecCont	Leak	OverFil	Disp	LastTest	NextTest	TStat
1	4	4	12/79	10,000	3	1		1	2	1			0	0	4	1		CLOSED : 01/97	
2	4	4	12/79	10,000	3	1		1	2	1			0	0	4	1		CLOSED : 01/97	
3	1	5	12/79	100	3	1			1	1			0	0	4	2		CONVERTED : 08/96	
4	1	5	01/97	1,000	3	1		1	1	1			1		4	2		CONVERTED : 08/96	

CITY OF WHITE PLAINS

WILLIAM E. PISANI
COMMISSIONER
(914) 422-1287

REC'D APR 21 1997

DEPARTMENT OF BUILDING

EDWARD D. BRUNNER
DEPUTY COMMISSIONER
(914) 422-1361

April 16, 1997

Macy's
100 Main Street
White Plains, NY 10601

RE: Main & Court Street
White Plains, New York
B-26759
W-3 B-3 L-20C,20D

Gentlemen:

In accordance with your request, all final inspections have been made by this Department for work performed under Building Permit B-26758 for closure of two underground storage tanks at the above referenced premises.

These inspections indicate that the work had been completed to the satisfaction of this Department and permission is hereby granted to occupy and use these premises.

Very truly yours,

Edward D. Brunner

Edward D. Brunner
Deputy Commissioner of Building

dmy
cc: Clayton Environmental Consultants

CITY OF WHITE PLAINS

WILLIAM E. PISANI
COMMISSIONER
(914) 422-1287

DEPARTMENT OF BUILDING

EDWARD D. BRUNNER
DEPUTY COMMISSIONER
(914) 422-1361

April 16, 1997

Macy's
100 Main Street
White Plains, NY 10601

RE: Main & Court Street
White Plains, New York
B-26759
W-3 B-3 L-20C,20D

Gentlemen:

In accordance with your request, all final inspections have been made by this Department for work performed under Building Permit B-26759 for installation of a fuel oil tank at the above referenced premises.

These inspections indicate that the work had been completed to the satisfaction of this Department and permission is hereby granted to occupy and use these premises.

Very truly yours,


Edward D. Brunner
Deputy Commissioner of Building

dmy
cc: Clayton Environmental Consultants


255 MAIN STREET WHITE PLAINS, NEW YORK 10601
(914) 422-1269 FAX (914) 422-1471

Privileged and Confidential


APPENDIX F
AST AND ACCESSORIES, SPECIFICATION AND INFORMATION



TOP VIEW



SIDE VIEW



END VIEW

SPECIFICATIONS

CAPACITY IN GALLONS: 1,000	
NUMBER REQUIRED: (1) ONE	
MATERIAL: A569	
THICKNESS OR GAUGE: 10 GA DIKE	
INNER TANK	SHELL- 10 GA
	HEAD- 10 GA
OUTER TANK	SHELL- N/A
	HEAD- N/A
LABELING:	
ABOVEGROUND UL 142	

COATING: EXTERIOR- RED OXIDE

INTERIOR- NONE

SURFACE PREP: TOUCH UP

OPENINGS: SEE SKETCH

(2) 2" NPT FITTINGS
(1) 4" NPT FITTING
(1) 6" NPT FITTING

(2) 2" NPT FITTINGS IN DIKE FOR DRAINS

OTHER ACCESSORIES:

1,100 CONTAINMENT DIKE
(2) 48" SADDLES


MOHAWK METAL PRODUCTS CO., INC.
2173 BEECHGROVE PLACE - UTICA, NY 13501
TELEPHONE (315) 793-3000

1000 GALLON SINGLE WALL TANK
1100 GALLON CONTAINMENT DIKE

SCALE:	CHECKED:	DRAWN BY:	DATE:	APPD BY:	DWG #:
NONE		DHS	5/8/95		5020R
					SHEET 1 OF 1

PNEUMERCATOR
Liquid Level Control Systems

HYDROSTATIC LIQUID LEVEL TANK GAUGING SYSTEMS




This family of indicators is the same as the hydraulic line only with relation to outside case dimensions and scale length. Based on an adaptation of the hydrostatic principle, air pressure is required to obtain liquid level indication. This is provided either by a built-in hand pump or by a source of clean dry air.


Installation is readily accomplished in either empty tanks or partially filled tanks. A 2" tank opening is required through which the air bell assembly (supplied by Pneumercator) is installed. Once the system has been properly installed, maintenance is practically non-existent. All that is required is an occasional check of the zero position which takes less than a minute.

For constant air systems, high or low level switches can be supplied which will activate a light, audible alarm or start and stop pumps to maintain predetermined levels.

The hydrostatic gaging system described on this page should be used only on tanks vented to the atmosphere.

PRINCIPLE OF OPERATION





Air is introduced in the line between the indicator and the tank by means of either the built in hand pump or a source of clean compressed air. When the pressure in this line equals the pressure at the bottom of the bubble pipe (created by the head of liquid in the tank), the bellows in the indicator mechanism expands—or contracts—and thru suitable linkage moves the pointer over the face of the dial. Excess pressure bubbles out of the bottom of the bubble pipe.

PNEUMERCATOR HYDROSTATIC GAGES

Instructions for Installation and Adjustment

Model P-5 Tank Gage

1. OPERATING PRINCIPLE

1.1 The Pneumercator Tank Gauge is designed to provide remote indication of the contents of storage tanks containing non-corrosive liquids. Operation of the built-in pump forces air through the connecting tubing until it escapes from the air bell opening located 2" above the bottom of the tank. The hydrostatic head of the liquid above this point determines the air pressure in the system and thus the position of the pointer on the scale.

1.2 This gauge should not be used on unvented tanks, for corrosive liquids or on tanks whose diameter and capacity vary from those shown on the dial.

1.3 Each time a reading is desired the pump should be operated until all liquid has been purged from the tubing and the pointer returns to the same spot between successive strokes.

2. INSTALLATION

2.1 Mount the gauge securely on a wall in a location where it will be both visible and accessible.

2.2 Lower the air bell through the tank opening until it rests on the bottom. Screw in the reducing bushing and compression fitting taking the slack from the tubing inside the tank before tightening but making sure the air bell remains on the bottom. Run the tubing to the gauge being careful that it does not become distorted or plugged. It is desirable to have the tubing drain from the gauge to the tank, avoiding low spots or pockets where moisture can collect. Buried tubing can be protected by taping it to the underside of the oil suction pipe.

2.3 Before tubing is attached to gauge make sure the pointer is exactly on the first mark (empty position) on the dial. If it is necessary to zero the pointer, remove cover from the gauge, slightly loosen the red adjusting screw and tap the mechanism as shown in Fig. 1. Be sure to tighten the red adjusting screw before replacing the cover.




FIG. 1




FIG. 2

2.4 Cut off any excess tubing. Install the brass insert into end of tubing, slip first brass nut then sleeve over the tubing as shown in Fig. 2. Insert tubing into fitting on gauge, slide sleeve and brass nut down and fasten tubing securely to gauge.

3. TROUBLE SHOOTING

3.1 If the pointer oscillates between pump strokes and gradually comes to rest, check for a liquid accumulation in a low pocket of the tubing.

3.2 If the pointer remains on "Empty" while the pump is operated, make sure there is liquid in the tank, check for a leaking connection between tubing and gauge, check for damaged tubing and check that the air bell is on the bottom of the tank.

3.3 If the tank is partly empty and the pointer remains on "Full" between strokes of the pump, check for an obstruction in the tubing or crushed tubing.

3.4 It is possible to localize malfunctions in the tank and transmission assembly or in the gauge by disconnecting the tubing from the gauge. Place the thumb over the tubing connection and operate the pump to observe for normal pointer travel.

3.5 If the pointer does not return to "Empty" after the tubing has been disconnected, rezero the gauge by following the procedure described in par. 2.3.

3.6 Additional repair or replacement of gauge parts in the field is not recommended. Return the gauge directly to the factory and attach a letter with your name, address and description of the trouble encountered.

4. CAUTION

4.1 Do not use detergents, solvents, paint thinners, lighter fluids or chemical cleaning compounds to clean the gauge. Use only a damp, soft cloth and a mild soap.

ADJUSTMENT INSTRUCTIONS FOR P-11 AND P-14


These gages are calibrated and adjusted at the factory specifically for the tanks on which they are to be installed. Actually, no further adjustment should be required but due to minor variations in tank diameter it may be necessary to re-position the pointer to the empty position. This is accomplished as follows:


1. Loosen compression nut which secures the tubing to the fitting on top of the gage. This vents the system which is necessary before any adjustment is made.
2. Remove 4 cover screws and cover.
3. The pointer is held to the hub by 2 – #1–72 screws. Loosen each crew slightly.
4. Re-position the pointer so that the pointer tip is in the center of the large increment representing the empty position.
5. Tighten the 1–72 screws and re-check the pointer position.
6. Replace cover and compression nut on top of gage.

NOTE: If inaccurate gage readings are observed after the pointer has been re-positioned to the empty mark, the following procedure is suggested:

(a) Make certain the air bell is on the bottom of the tank.
(b) Check tank diameter and compare with the tank diameter specified on the purchase order.
(c) Check specific gravity or grade of fuel oil.

If (b) or (c) is found to show any appreciable difference the gage must be returned to the factory with new information.





PNEUMERCATOR CO., INC.
120 FINN COURT, FARMINGDALE, N.Y.11735

OVERFILL WARNING DEVICES

TANK ALARM

PART # 1000100


A cost effective overfill alarm system for above ground storage tanks.


Battery powered, intrinsically safe, and easy to install, the TANK ALARM uses a pressure sensing device to sound a 95 decibel audio alarm at 90% fluid level.


The sensing head fits a standard 2 inch threaded opening and is field adjustable for all size tanks.

The TANK ALARM uses no moving parts except for a single toggle switch for ON - OFF - TEST. The system is internally powered with two 9 volt batteries, thus eliminating the need for any external power requirements and making the system intrinsically safe.

OVERFILL ALARM INSTALLATION








SPECIFICATIONS:

TEMPERATURE RANGE: -40 TO 70C
SIZE: 7" X 4.25" X 3.5"
POWER REQUIREMENTS: No external power required. Internal battery power 18VDC.

IMPORTANT: This device is to be used only as an auxiliary warning to the operator of a possible overfill situation and should not be relied upon to prevent tank overfill. It is solely the responsibility of the operator to continuously monitor the tank filling process and prevent any spillage, regardless of the situation or status of any gauge or alarm apparatus.


SEE SECTION 3 OF PRODUCT PRICE LIST FOR PRICING INFORMATION

TANK ALARM



IMPORTANT

This device is to be used only as an auxiliary warning to the operator of a possible overfill situation, and should not be relied upon to prevent tank overfill. It is solely the responsibility of the operator to continuously monitor the tank filling process and prevent any spillage regardless of the situation or status of any gauge or alarm apparatus.



OPERATION

The system consists of the alarm box and the sensor head. Once installed and turned on, you may begin filling the tank. The rising fluid increases the air pressure in the sensing tube and triggers the alarm when the fluid level is 3 inches above the bottom end of the sensing tube.

INCLUDED

1. Alarm Box w/ Batteries
2. Sensor Head
3. Sensing Tube
4. Tube Weight

NOT INCLUDED


1. 3 wires or a single 3 conductor cable to connect the Alarm Box to the Sensor Head
2. Screws and/or clamps to secure the Alarm Box to a pole, wall, stairway, etc.
3. Conduit (optional) - used for protection of wiring only

OPTIONAL EQUIPMENT

1. 110VAC Power Supply

ORDERING INFORMATION

ITEM	PART NUMBER
TANK ALARM SYSTEM	1000100
OPTIONAL POWER SUPPLY	1000101



SENSOR HEAD INSTALLATION

A. Determine the distance from the bottom of the sensor head (when installed) to the overfill level. Be sure to account for any adapter fitting used. See diagram at top left.

B. Add 3 inches to the distance found in step A and cut the tubing to this length (measured from the bottom of the sensor head). Add 1 inch for operation below -20°C (-6°F).

C. Insert the weighted fitting into the end of the sensing tube. DO NOT plug the end of the short tube.

D. Insert the sensor head and tubing into the tank and secure. Hand tight is usually tight enough. The sensor head need not be sealed except to keep rainwater out of the tank.

ALARM BOX INSTALLATION

1. Separate the lid from the box and mount the box to the chosen fixture. If you are using the optional power supply, the alarm box must be mounted outside the Class 1 Division 1 area. While the Alarm Box and the Sensor Head are intrinsically safe, **THE POWER SUPPLY IS NOT.**
2. Run the appropriate wiring from the box location to the sensor head using fuel resistant wire. Conduit is optional but is recommended for protection of the wiring.
3. Connect the Yellow, Red, and Brown wires from the sensor head to the alarm box as shown above. Because this wiring is intrinsically safe, it may not share any junction box, conduit, raceway, etc. with any other circuit(s). If you are using the optional power supply, connect the Black wire to 110 VAC HOT and the White wire to Neutral.
4. Replace the lid onto the box and move the switch to the 'TEST' position to check that the alarm is operational.
5. The installer should be present at the next filling to verify proper operation of the overfill alarm.


OPERATING INSTRUCTIONS

1. Move the control switch to 'TEST' to verify operation of the unit and check its' batteries. Then move the switch to the 'ON' position.
2. Connect the tanker truck and begin pumping. When the tank level reaches 90%, the alarm will sound signaling the operator to STOP fueling.
3. Be certain to turn the Tank Alarm 'OFF' after each filling to prolong the life of the batteries.

IMPORTANT: All appropriate wiring practices as outlined by the National Electrical Code and state and local codes should be followed.

WESTERN ELECTRONICS
2626 SKYWAY DR.
GRAND PRAIRIE, TX U.S.A. 75052
FAX: (214) 660-5793
WATS: 800-654-5002

Setting the Standard for the AST Market




UPFLOW VENT

UPFLOW VENT - Features an upward flow design which rapidly disperses vapors. A grooved drain lip in the cap extends beyond the base for efficient water drain-off. Includes two set screws for easy installation.

Model #	Size	Weight (lbs.)	Height	Width
45-20	2"	1.1	4¾"	4"

- Assures even pressure in the AST during filling or pumping
- All metal construction
- Flame-retardant 40 mesh bronze screen
- Conforms with NFPA-30

45



PRESSURE VACUUM VENT

PRESSURE VACUUM VENT - Utilized for vapor recovery applications. An internal pressure valve, available in 8, 12, or 16 oz. settings, restricts vapor escape during product drops. All pressure valves have a ½ oz. vacuum setting. The 46 has a 2" pipe thread; the 46S has two set screws.

Model #	Size	Weight (lbs.)	Height	Width	Pressure
46-2060	2"	2.0	5⅞"	4¼"	8 oz.
46S-2080	2"	2.0	5⅞"	4¼"	8 oz.

- Assures even pressure in the AST during filling or pumping
- All metal construction
- Flame-retardant 40 mesh bronze screen
- Conforms with NFPA-30

46



BLOW OFF VENT

BLOW OFF VENT - Provides venting to relieve excessive internal pressure build up in the event of a fire or during filling above ground storage tanks. The emergency vent will open at approximately 1 PSI. The mushroom design prevents water and contaminants from entering the tank.

Model #	Size	Weight (lbs.)	Height	Width
48-60	6"	30.0	6"	10"

- Contains female threads
- Mounts onto the tank
- Non-corrosive polymeric coating
- Flame-retardant 40 mesh brass screen
- Conforms with NFPA-30A

48

For More Information Call Universal [illegible] Fax: 800-443-8258 or 908-351-0369

BARRISFORD EQUIPMENT LTD.

15 Fisher Avenue, Nanuet, New York 10954
(914) 624-8310, Fax (914) 624-7320

******* Facsimile Transmission *******

Date : 1/31/97

Pages : 2 4

To : Sue Bayet

Fax Phone : 908-225-4577

From : Gregg T. Chappell

Subject : Please find attached copies of the warranties for the products as per your request. If you need additional information, please contact our office.

THANK YOU.

MOHAWK Metal Products Co., Inc.
2175 Beechgrove Place • Utica, New York 13501 • 315 797-8000 • Fax 315-797-8370

TO: To Whom It May Concern

FROM: Marty Regan

RE: Horizontal Aboveground Tank Warranty

All tanks are tested to the UL standard at the factory. Because the final installation is carried out by someone else, usually a plumber or heating contractor, Mohawk Metal Products cannot assume any responsibility for alledged defects. The NFPA Installation Pamphlet 31 states that the tank and its piping should be retested on site during installation by the installer.

Warranty

Mohawk Metal Products' one year warranty applies to any defects in material or workmanship. Repair or replacement is our option. This limited warranty excludes damages from misuse or improper installation and we disclaim all liability for incidental damages, including but not limited to pollution. This constitutes the entire agreement of the parties.

MR/bl

D*5568

WARRANTY

We warrant that our tank gauges, if installed according to instructions will be free from defects in material and workmanship for a period of one (1) year following the date of original shipment by us.

Our liability under this warranty shall be limited to, at our option, (i) repair of the defective tank gauge, (ii) replacement of the original tank gauge with new, or (iii) refund of the original purchase price; and, we shall not be liable for any labor, other installation costs, indirect or consequential damages, or other damages in connection with such gauge.

This constitutes our obligation and none other stated for any purpose except the above shall apply.

PNEUMERCATOR COMPANY

120 Finn Court, Farmingdale, New York 11735 • TEL.: (516) 293-8450 • FAX: (516) 293-8533

LIMITED WARRANTY

"WESTERN ELECTRONICS guarantees all new parts and equipment sold by WESTERN ELECTRONICS for a period of 2 years from date shipped to the original user by WESTERN ELECTRONICS or an authorized distributor. WESTERN ELECTRONICS will replace parts proved defective in material or workmanship during the 2 year warranty period, provided the parts are returned to the factory at Grand Prairie, Texas, transportation charges prepaid. The replacement parts will be shipped to the authorized distributor or original user with no charge except for transportation.

This warranty is specifically limited to parts and equipment which have been installed and used in accordance with WESTERN ELECTRONICS instructions. This warranty is void for equipment which has not been installed according to WESTERN ELECTRONICS instructions and diagrams. This warranty is void if any unauthorized alterations or additions have been made to the equipment, or if it has been subjected to damage caused by accident, abuse, misapplication, or improper operation.

This warranty does not cover any indirect or consequential damage or loss of product or business. WESTERN ELECTRONICS assumes no other liabilities in connection with this equipment. WESTERN ELECTRONICS assumes no responsibility for any action or representation made by distributors or anyone else, other than the above expressed conditions."

You may have additional rights which vary from state to state.

IMPORTANT NOTICE

It is solely responsibility of THE OPERATOR to continuously monitor the TANK FILLING PROCESS and prevent any spillage regardless of the situation or status of any gauge or alarm apparatus.

FUEL OIL FILLING PROCEDURE

1. **Check the Tank's liquid level gauge located on the wall next to the fill port.**

2. **Test the Tank's HIGH-LEVEL ALARM by switching to test position and back (you should hear the alarm)*. The alarm is located behind the Tank on the east wall.**

3. **Turn on the Tank's alarm.**

4. **Start Filling the Tank, Make sure the connections are tight and there are no leaks.**

5. **Look at the level gauge while filling the Tank to ensure proper operation of the gauge and the liquid level at the Tank.**

6. **Stop the pump when you have reached 900 gallons on the level gauge, or when the alarm sounds. THE TANK SHOULD NOT BE FILLED OVER 900 GALLONS ON THE LEVEL GAUGE.**

7. **Detach the hose and put the alarm in the "off" position.**

***Change the batteries if the alarm does not sound (two 9-Volt batteries).**

Appendix I

Resumes

Denise Cosenza
Project Manager

PROFESSIONAL SUMMARY

Ms. Cosenza is experienced working with large environmental projects for both public/private sector clients. Her project experience includes Phase I and II Environmental Site Assessments, UST closures, soil and groundwater investigation and remediation projects and preparation of associated technical documents and client reports. She is well versed in the interpretation of drawings and specifications and is familiar with New York City, New York State and New Jersey environmental regulations and standards.

PROJECT EXPERIENCE

- **Phase II Site Assessment / FedEx / Brooklyn, New York / 2015**. As part of the redevelopment of an industrial property executed a Remedial Investigation Workplan to define the nature and extent of soil and groundwater contamination, as well as potential soil vapor intrusion. Directed geophysical survey for location of potential underground tanks and utilities. Oversaw and directed the advancement of soil borings and collection of samples for laboratory analyses. On-site geoscientist to direct and log the installation of several monitoring wells, soil vapor points and sub-slab soil vapor points. Lead geoscientist for collection of groundwater samples, soil vapor samples, and coordinated analyses with laboratory. Surveyed monitoring well for development of local groundwater elevation map. Directed subcontractor for a camera investigation of sanitary system and the collection of bottom sediment samples for analyses. Coordinated all site activities whit the client, regulatory agencies, and client site developers.

- **Phase II Site Assessment / Pepsi Bottling Venture, LLC/ Garden City and Patchogue, New York / 2015**. Executed a Limited Subsurface Site Investigation Workplan to define the nature and extent of soil and groundwater contamination at two Pepsi locations on Long Island, NY. Directed geophysical survey for location of potential underground tanks and utilities. Oversaw and directed the advancement of soil borings and collection of samples for laboratory analyses. On-site geoscientist to direct and log the installation of several monitoring wells and collection of soil sample beneath existing floor drains. Lead geoscientist for collection of groundwater elevation data, water samples, and coordinated analyses with laboratory. Surveyed monitoring wells for development of local groundwater elevation map. Directed drilling subcontractor and coordinated all site activities with client and property owner consultant.

- **Phase I and II Environmental Site Assessments / Department of Design and Construction / New York. Project Manager**. Coordinate all aspects of Phase I and II ESAs under $2.0M on-call Requirements Contract for DDC. Project activities include management and execution of site activities including asbestos, mold and lead based paint inspections as part of Phase I ESA; background research, including interviews and document review; determinations as to the potential impact of hazardous materials on soil and groundwater on sites and final reporting.

- **Phase I and II Environmental Site Assessments / Department of Design and Construction / New York. Project Manager**. Coordinate all aspects of Phase I and II ESAs under $2.0M on-call Requirements Contract for DDC. Project activities include management and execution of site activities including asbestos, mold and lead based paint inspections as part of Phase I ESA; background research, including interviews and document review; determinations as to the potential impact of hazardous materials on soil and groundwater on sites and final reporting.

- **Phase I and II Environmental Site Assessments / Preliminary Assessment / Bed, Bath & Beyond / New York / New Jersey**. Project Manager. Coordinate all aspects of Phase I and II ESA and New Jersey Department of Environmental Protection (NJDEP) Preliminary Assessment (PA) for the sale and acquisition of commercial properties as well as redevelopment of commercial properties. Project activities include management and execution of site activities including asbestos, mold and lead based paint inspections as part of Phase I ESA; background research, including interviews and extensive document

review; determinations as to the potential impact of hazardous materials on soil and groundwater on site via a subsurface investigations and final reporting.

- **PCB Assessments and Sampling / New York City School Construction Authority / New York.** Project Manager for the sampling of soil and building material for PCB contaminant. Created sampling plan, developed site health and safety plane, and implemented sampling of soil, caulk and other building material. Created report for abatement and abatement costs.

- **Phase I and II Environmental Site Assessments / Prudential Real Estate Investors / New York / New Jersey.** Project Manager. Coordinate all aspects of Phase I and II ESAs for potential purchase and redevelopment. Project activities include management and execution of site activities including asbestos, mold and lead based paint inspections as part of Phase I ESA; background research, including interviews and document review; determinations as to the potential impact of hazardous materials on soil and groundwater on sites and final reporting.

- **Water Well Evaluation Assessments / Bank of America / New York / New Jersey. Project Manager.** Coordinate all aspects of the water well evaluation services to determine the compliance status of on-site wells at banking facilities. Project activities include management and execution of site activities including site investigation including well water sampling as required by local and federal regulatory agencies, background research, including interviews, document review and regulatory research; determinations as to the potential impact of hazardous materials on groundwater on sites and final reporting.

- **Phase I and II Environmental Site Assessments / Verizon / New York.** Project Manager. Coordinate all aspects of Phase I and II ESAs for potential purchase and redevelopment for franchising purposes. Project activities include management and execution of site activities including asbestos and lead based paint inspections as part of Phase I ESA; background research, including interviews and extensive document review; determinations as to the potential impact of hazardous materials on soil and groundwater on sites and final reporting.

- **Phase I and II Environmental Site Assessments / T-Mobile / New York**. Project Manager. Coordinate all aspects of Phase I and II ESAs for potential lease of land for wireless antennas and associated equipment. Project activities include management and execution of site activities including asbestos and lead based paint inspections as part of Phase I ESA; background research, including interviews and document review; determinations as to the potential impact of hazardous materials on soil and groundwater on sites; collecting and field screening soil samples, and final reporting.

EDUCATION

- B.S., Environmental Science and Geology, City University of New York, Queens College, 2002

TRAINING AND CERTIFICATIONS

- OSHA 40 Hour 29 CFR 1910.120
- OSHA 10 Hour Construction Safety
- Red Cross CPR & First Aid Certified
- OSHA 10 Hour Safety Certification

Chelsea Helm
Industrial Hygiene Technician

PROFESSIONAL SUMMARY

Ms. Helm is experienced working with environmental projects for both public/private sector clients. Her experience includes Phase I Environmental Site Assessments, Risk Management Plans, soil remediation and oversight projects, and preparation of associated technical documents and client reports. She is familiar with New York City and New York State environmental regulations and standards.

Ms. Helm's experience also includes Indoor Air Quality and Mold assessments, water sampling projects, and preparation of associated technical documents and client reports.

PROJECT EXPERIENCE

- **Phase I Environmental Site Assessment / LaSalle Investment Management / New York** Under the supervision of Project Manager, Denise Cosenza; Ms. Helm conducted all aspects of Phase I ESAs to identify *recognized environmental conditions* in connection with the property. Project activities include background research, interviews, document review, determinations as to the potential impact of hazardous materials on soil and groundwater, and final reporting.

- **Phase I Environmental Site Assessment / 1st Source Servall / Zuckerberg Industrial Park, New Jersey** Project activities include management and execution of site activities including hazardous material inspections as part of Phase I ESA; background research, including interviews and document review obtained from local Building Department and Tax Assessor Office; determinations as to the potential impact of hazardous materials on soil and groundwater from adjoining hazardous/contaminated sites within an industrial park, and final reporting.

- **Phase I Environmental Site Assessment / JPMorgan Chase / New Jersey** Project activities include management and execution of site activities including hazardous material inspections as part of Phase I ESA; background research, including interviews and historical document review; determinations as to the potential impact of hazardous materials on soil and groundwater from historical land use, and final reporting.

- **Risk Management Plan / Digital Realty Trust LTD. / New York** Technician for the evaluation of all program components including Risk Assessment, Risk Reduction, and Emergency Response. Project activities include identification of facility operations, quantities of stored and used sulfuric acid, probability and effects of release scenarios, and hazard analysis of equipment and processes. Final reporting includes the identification of sulfuric acid storage and emergency exits in specific site plan format.

- **Indoor Air Quality and Mold Assessment / Metro North / New York** Technician for IAQ sampling and mold assessment. Project activities include use of air sampling instruments, HVAC unit inspection, photo-documentation, and final reporting.

- **Mold Assessment / Manhattan Skyline Management / New York** Technician for the evaluation of water damage at a residential apartment. Limited microbial related services include assessment and survey for suspect visible mold growth and water-damaged building materials. Physical survey includes moisture meter testing, air sampling for airborne fungal spores using Air-O-Cell® cassettes connected to a Zefon Mini-pump, photoionization detector testing, and photo-documentation.

- **Soil Excavation Oversight / Urban Storage LLC / Brooklyn, New York** Project activities include soil removal oversight and coordinating manifest completion with soil transportation.

- **Drinking Water Sampling, Assessments and Reporting / NYC School Construction Authority / New York** Activities include execution of sampling events and procedures, analysis of water sample data for exceedances in lead concentrations, and compilation of sample data into final reports for distribution to Department of Health (DOH) and Department of Education (DOE) review processes.

EDUCATION

- B.A. Environmental Studies and Conservation, Stony Brook University, 2016

TRAINING AND CERTIFICATIONS

- State of New York – Department of Labor Licensed Mold Assessor – Cert. # MA01007
- OSHA 40-hour (29 CFR 1910.120)

Appendix J

Records of Communication

Freedom of Information Law (FOIL) Request Form

FREEDOM OF INFORMATION LAW (FOIL) REQUEST FORM

Date*

4/3/19

This request pertains to records maintained by the (list city department or board):*

Building Department and City Clerk

Records Access Officer for above-named city department or board:*

City Clerk and Commissioner of Building

A link to the list of Records Access Officers may be found on the FOIL page of the city website.

Pursuant to New York Freedom of Information Law, I am requesting an opportunity to:*

- [ ] Inspect copies of the following public records
- [x] Obtain copies of the following public records

Documents requested:*

Aboveground storage tank registration/installation records; Underground storage tank removal/closure reports; spills, releases, hazardous material storage/disposal; site/soil remediation; groundwater monitoring; associated with the Macy's Store in the Galleria Mall at 100 Main Street White Plains; parcel ID 125.75-4-4

Be specific. Describe the record with sufficient detail for the public agency to respond.

Requestor's Name*

Chelsea Helm

Representing

ATC Group Services, LLC

Street Address:*

104 East 25th Street

City, State & Zip Code*

New York, NY 10537

Phone Number* **Email***

2122840631 chelsea.helm@atcgs.com

Requestor's Signature:*

Chelsea Helm



AGENCY USE ONLY - Fees (if applicable):

Please note: There is a photocopying fee of .25 per standard size page, and a $5.00 per page fee for large format plans or maps. Postage fees in the exact amount as levied by the United States Post Office, if mailed.

AGENCY USE ONLY - Date Received:

AGENCY USE ONLY:

- ☐ Request Approved
- ☐ Request Denied

Chelsea Helm

From: FOIL-DOH <FOIL-DOH@westchestergov.com>
Sent: Friday, March 29, 2019 10:16 AM
To: Chelsea Helm
Subject: [EXTERNAL] WCDOH RECORD REQUEST ACKNOWLEDGEMENT 19-156

[External Email] This email originated from outside of the ATC mail system. Please use caution when opening attachments.

Chelsea Helm
chelsea.helm@atcgs.com

WCDOH RECORD REQUEST ACKNOWLEDGEMENT 19-156
This is to acknowledge receipt of your Freedom of Information request for records received here on **March 22, 2019** regarding:

- 100 Main St. – White Plains, NY 10601

Your request has been assigned this number: 19-156

We anticipate providing any records responsive to your request on 4/26/19.

We will contact you when your records are ready.

If you need to communicate with us, please reference the request number indicated above when you email us at FOIL-DOH@WESTCHESTERGOV.COM

Thank You,
Records Request Division on behalf of

Caren Halbfinger
FOIL Officer
Public Affairs

Chelsea Helm

From: New York DEC Support <newyorkdec@mycusthelp.net>
Sent: Thursday, March 21, 2019 12:54 PM
To: Chelsea Helm
Subject: [EXTERNAL] FOIL Request :: W049886-032119

[External Email] This email originated from outside of the ATC mail system. Please use caution when opening attachments.

Dear Chelsea:

Thank you for your Freedom of Information Law (FOIL) request. Your request has been received and is being processed. Your request was received in this office on 3/21/2019 and given the reference number FOIL #W049886-032119 for tracking purposes. You may expect the Department's response to your request no later than **4/18/2019**.

Record Requested: **underground/aboveground storage tank (installation, removal, testing, permits) soil/groundwater investigations, monitoring, remediation, hazardous material spills or releases, etc. associated with Macy's in the Galleria Mall at 100 Main Street, White Plains NY 10601**

You can monitor the progress of your request at the link below and you'll receive an email when your request has been completed. Again, thank you for using the FOIL Center.

https://mycusthelp.com/NEWYORKDEC/_rs/RequestLogin.aspx

New York State Department of Environmental Conservation, Record Access Office

---

Track the issue status and respond at:
https://mycusthelp.com/NEWYORKDEC//_rs/RequestEdit.aspx?rid=49886

Appendix L

Other Supporting Documentation

MACYS WHITE PLAINS GALLERIA
100 MAIN STREET
WHITE PLAINS, NY 10601

Inquiry Number: 5604205.7S
APRIL 2, 2019

EDR Environmental Lien and AUL Search

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Environmental Lien and AUL Search

The EDR Environmental Lien Search Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied address information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' offices, registries of deeds, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved, and description); and
- provide a copy of the deed or cite documents reviewed.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report was prepared for the use of Environmental Data Resources, Inc., and AFX Research, LLC. (AFX) exclusively. This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. **NO WARRANTY, EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WTH THIS REPORT**. Environmental Data Resources, Inc. (EDR) and AFX exclusively specifically disclaim the making of any such warranties, including without limitation, merchantability or fitness for a particular use or purpose. The information contained in this report is retrieved as it is recorded from the various agencies that make it available. The total liability is limited to the fee paid for this report.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EDR Environmental Lien and AUL Search

TARGET PROPERTY INFORMATION

ADDRESS

MACYS WHITE PLAINS GALLERIA
100 MAIN STREET
WHITE PLAINS, NY 10601

RESEARCH SOURCE

Source 1: WESTCHESTER COUNTY RECORDER'S OFFICE

Source 2: NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Source 3: UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

PROPERTY INFORMATION

Deed 1

Type of Deed:	QUIT CLAIM DEED
Title is vested in:	A & S GALLERIA REAL ESTATE INC
Title received from:	FEDERATED DEPARTMENT STORES, INC
Date Executed:	07/29/1988
Date Recorded:	02/28/1989
Book:	9462
Page:	38
Volume:	NA
Instrument#:	NA
Docket:	NA
Land Record Comments:	NA
Miscellaneous Comments:	NA

Legal Description: WBL 3003 20C,20D-2,20M

Current Owner: A & S GALLERIA REAL ESTATE INC

Property Identifiers: 1700-125-075-00004-000-0004

Comments: NA

EDR Environmental Lien and AUL Search

ENVIRONMENTAL LIEN

Environmental Lien: Found ☐ Not Found ☒

If Found:

1st Party:	NA
2nd Party:	NA
Dated:	NA
Recorded:	NA
Book:	NA
Page:	NA
Docket:	NA
Volume:	NA
Instrument #:	NA
Comments:	NA
Miscellaneous:	NA

OTHER ACTIVITY AND USE LIMITATIONS (AULS)

Other AUL's: Found ☐ Not Found ☒

If Found:

1st Party:	NA
2nd Party:	NA
Dated:	NA
Recorded:	NA
Book:	NA
Page:	NA
Docket:	NA
Volume:	NA
Instrument #:	NA
Comments:	NA
Miscellaneous:	NA

EDR Environmental Lien and AUL Search

MISCELLANEOUS

Type of Instrument: NONE IDENTIFIED
First Party:
Second Party:
Date Executed:
Date Recorded:
Instrument #:
Book:
Page:
Comments:

EDR Environmental Lien and AUL Search

DEED EXHIBIT

V07589059

[New York]

File Number: 030012
Division: ABRAHAM & STRAUS

QUITCLAIM DEED

THIS INDENTURE, made as of JULY 29, 1988, between FEDERATED DEPARTMENT STORES, INC., a Delaware corporation, party of the first part, and A&S GALLERIA REAL ESTATE, INC., c/o Federated Department Stores, Inc., 7 West Seventh Street, Cincinnati, Ohio 45202, a Delaware corporation, party of the second part,

WITNESSETH, that the party of the first part, in consideration of one dollar ($1.00) and other good and valuable consideration paid by the party of the second part, does hereby remise, release and quitclaim unto the party of the second part, the successors and assigns of the party of the second part forever;

TOGETHER with the appurtenances and all the estate and rights of the party of the first part in and to said premises;

ALL that certain plot, piece or parcel of land, with the buildings and improvements thereon erected, as described on the attached Exhibit A;

TOGETHER with all right, title and interest, if any, of the party of the first part in and to any streets and roads abutting the described premises to the center lines thereof;

TO HAVE AND TO HOLD the premises herein granted unto the party of the second part, the successors and assigns of the party of the second part forever;

AND the party of the first part, in compliance with Section 13 of the Lien Law, hereby covenants that the party of the first part will receive the consideration for this conveyance and will hold the right to receive such consideration as a trust fund to be applied first for the purpose of paying the cost of the improvement and will apply the same first to the payment of the cost of the improvement before using any part of the total of the same for any other purpose.

The word "party" shall be construed as if it read "parties" whenever the sense of this indenture so requires.

IN WITNESS WHEREOF, the party of the first part has duly executed this deed as of the day and year first above written.

FEDERATED DEPARTMENT STORES, INC.
a Delaware corporation

By: _____

Name: Jack Brown
Title: Vice President

STATE OF OHIO)
) SS:
COUNTY OF HAMILTON)

On JULY 29, 1988, before me personally came Jack Brown to me known, who, being by me duly sworn, did depose and say that he resides at 3927 Cooper Road, Cincinnati, Ohio 45241; that he is the Vice President of FEDERATED DEPARTMENT STORES, INC., the corporation described in and which executed the above instrument; and that he signed his name thereto by order of the board of directors of said corporation.

_____
NOTARY PUBLIC

Name: Gary L. Farmer

My Commission Expires: GARY L. FARMER, Attorney at Law
NOTARY PUBLIC - STATE OF OHIO
My Commission has no expiration date. Section 147.03 O.R.C.

This Instrument prepared by and return to:

PREFERRED LAND TITLE SERVICES, INC.
575 Lexington Avenue
New York, New York 10022
(212) 308-1200

Inc.

[Deed]
File Number: 030012
Division: Abraham & Straus

EXHIBIT A

SUBPARCEL C (Fee)

ALL that certain plot, piece or parcel of land, situate, lying and being in the City of White Plains, County of Westchester and State of New York shown and designated as Parcel "C" on a certain map entitled, "Survey of Central Renewal Project Parcels Nos. 20, 21, 22 & 25 prepared for White Plains Urban Renewal Agency situate in City of White Plains, Westchester County, New York", dated May 15, 1978 made by James W. Delano and filed in the Office of the County Clerk of Westchester County (Division of Land Records) on 6/8/78 as Map No. 19512 said parcel being more particularly bounded and described as follows:

BEGINNING at a point on the proposed northerly right-of-way line of Martine Avenue which is at the westerly end of a curve connecting the proposed westerly right-of-way line of Court Street with the said proposed northerly right-of-way line of Martine Avenue, which point is further identified as North 376, 141.205 and East 655,929.548 in theNew York State Plane Coordinate System, East Zone, and proceeding

thence in an easterly to northerly direction along a curve to the left having a radius of 35.000 feet and a central angle of 89 degrees 05' 28.9" a distance of 54.423 feet to the proposed westerly right-of-way line of Court Street;

thence, along the proposed westerly right-of-way line of Court Street, North 10 degrees 02' 22" West 311.057 feet to a point of curvature;

thence, along a curve to the left having a radius of 35.000 feet and a central angle of 89 degrees 54' 30" a distance of 54.922 feet to the proposed southerly right-of-way line of Main Street;

thence, along the proposed southerly right-of-way line of Main Street, South 80 degrees 03' 08" West 235.670 feet to a point;

thence, the following courses and distances:
South 10 degrees 56' 53.1" East 172.210 feet
North 79 degrees 03' 06.9" East 17.016 feet
South 10 degrees 56' 53.1" East 80.250 feet
North 79 degrees 03' 06.9" East 10/851 feet
South 10 degrees 56' 53.1" East 29.333 feet
South 79 degrees 03' 06.9" West 10/851 feet;

South 10 degrees 56' 53.1" East 103.334 feet to the proposed northerly right-of-way line of Martine Avenue;

thence, along the proposed northerly right-of-way line of Martine Avenue, North 79 degrees 03' 06.9" East 213.080 feet to the Pointof Beginning.

SUBPARCEL D-2 (Fee-above-a-Plane)

ALL that volume of space, situate, lying and being in the City of White Plains, County of Westchester and state of New York shown and designated as Parcel "D-2" on a certain map entitled, "Survey of Central Renewal Project Parcels Nos. 20, 21, 22 & 25, prepared for White Plains Urban Renewal Agency, situate in the City of White Plains, Westchester County, New York" dated May 15, 1978, made by James W. Delano and filed in the Office of the County Clerk of Westchester County (Division of Land Records) on 6/8/78, as Map No. 19512, which lies above the horizontal plane having elevation 223.08 feet above the datum level in use by the City of White Plains, which datum level is the National Geodetic Survey Standard Datum 1929, said volume is bounded by and lies within the vertical planes which are formed by projecting vertically upward the boundaries of all that plot or parcel described as follows:

BEGINNING at a point on the proposed Southerly right-of-way line of Main Street 235.676 feet westerly of the Westerly end of a curve connecting the proposed southerly right-of-way line of Main Street with the proposed westerly right- of - way line of Court Street, which point of Beginning is further identified as North 376,475.625 and East 655,630.497 in the New York State Plane Coordinate System, East Zone, and proceeding:

Thence, along the proposed Southerly right-of-way line of Main Street, South 80 degrees 03' 08" West 66.177 feet to a point;

Thence, South 10 degrees 56' 53.1" East 173.365 feet to a point;
Thence, North 79 degrees 03' 06.9" East 66.167 feet to a point;
Thence, Notth 10 degrees 56' 53.1" West 172.210 feet to the propose southerly right-of-way line of Main Street at the Point of Beginning.

SUBPARCEL M (Fee-above-a-Plane)

ALL that volume of space situate, lying and being in the City of White Plains, County of Westchester and State of New York shown and designated as Parcel "M" on a certain Map entitled "Survey of Central Renewal Project Parcels Nos. 20, 21, 22 and 23, prepared for White Plains Urban Renewal Agency, situate in City of White Plains, Westchester County New York" dated May 15, 1978, made by James W. Delano and filed in the Office of the County Clerk of Westchester County (Division of Land Records) on 6/8/78, as Map No. 19512, which lies above the horizontal plane having elevation 273.50 feet above the datum level in use by the City of White Plains which datum level is the National Geodetic Survey Standard Datum 1929, said volume is bounded by and lies within the vertical planes which are formed by projecting vertically upward the boundaries of all that plot or parcel described as follows:

Beginning at a point on the proposed westerly right-of-way line of Court Street, 75.273 feet southerly of the southerly end of a curve connecting the proposed southerly right-of-way line of Main Street with the proposed westerly right-of-way line of Court Street, which Point of Beginning is further identified as North 376,412.303 and East 685,916.428 in the New York State Plane Coordinate System, East Zone, and proceeding

Thence, along the proposed westerly right-of-way line of Court Street, South 10° 02' 22" East 46.506 feet to a point;

thence, North 79° 03' 06.9" East 4.938 feet to a point

thence, North 10° 56' 53.1" West 46.500 feet to a point;

thence, South 79° 03' 06.9" West 4.900 feet to a point on the proposed westerly right-of-way line of Court Street at the point of Beginning.

LIBER 9462 PAGE 43

QUIT CLAIM
DEED

WARD 3
BLOCK 3
LOTS 20C, 20D-2, 20H

PLTS 67321-W

PREFERRED LAND TITLE SERVICES, INC.
575 Lexington Avenue
New York, New York 10022
(212) 308-1200
ATTN: Mary E. Hibbs

SITE 030012

LIBER 9462 PAGE 44

WESTCHESTER COUNTY RECORDING AND ENDORSEMENT PAGE
(THIS PAGE FORMS PART OF THE INSTRUMENT)

THE FOREGOING INSTRUMENT WAS ENDORSED FOR THE RECORD AS FOLLOWS:

TYPE OF INSTRUMENT ____D-C____
(SEE CODES FOR DEFINITIONS)

THE PROPERTY IS SITUATED IN WESTCHESTER COUNTY, N.Y. IN THE

02 TOWN OF BEDFORD
06 TOWN OF CORTLANDT
09 TOWN OF EASTCHESTER
11 TOWN OF GREENBURGH
12 TOWN OF HARRISON
16 TOWN OF LEWISBORO
17 TOWN OF MAMARONECK
19 TOWN OF MT. KISCO
20 TOWN OF MT. PLEASANT
21 CITY OF MT. VERNON
22 TOWN OF NEW CASTLE
23 CITY OF NEW ROCHELLE
24 TOWN OF NORTH CASTLE
26 TOWN OF NORTH SALEM
28 TOWN OF OSSINING
30 CITY OF PEEKSKILL
31 TOWN OF PELHAM
35 TOWN OF POUND RIDGE
36 CITY OF RYE
37 TOWN OF RYE
38 TOWN OF SCARSDALE
39 TOWN OF SOMERS
42 CITY OF WHITE PLAINS
43 CITY OF YONKERS
44 TOWN OF YORKTOWN

LIBER 9462
PAGE 38
STAT'Y CHARGE 5
REC'ING CHARGE 15
FILING CHARGE 1
CROSS REFERENCE ____
CERT/RECEIPT ____
TOTAL 21
$ -0-
CONSIDERATION

RECEIVED
$ None
FEB 28 1989
REAL ESTATE TRANSFER TAX
WESTCHESTER COUNTY
9755

MORTGE. DATE ____
MORTGE. AMOUNT ____
EXEMPT YES ____ NO ____
REC'D TAX ON ABOVE MTGE:
BASIC $____
ADDTL $____
SUBTOTAL $____
SPECIAL $____
TOTAL $____
SERIAL No. ____
DWELLING:
☐ 1-6 UNITS
☐ OVER 6 UNITS

ANDREW J. SPANO
WESTCHESTER COUNTY CLERK

ADDITIONAL COMMENTS

TERMINAL No. 870920075
DATE RETURNED

EXAMINED BY ____
WITNESS MY HAND AND OFFICIAL SEAL
Andrew J. Spano
ANDREW J. SPANO
WESTCHESTER COUNTY CLERK

THE RECORDING DATE OF THIS INSTRUMENT AS INDICATED BELOW IS THE OFFICIAL DATE ON WHICH THE WESTCHESTER COUNTY CLERK RECEIVED THIS INSTRUMENT.
QUESTIONS REGARDING DELAYS PRIOR TO THIS DATE SHOULD BE ADDRESSED TO YOUR REPRESENTATIVE OR ATTORNEY.

RECEIVED
89 FEB 28 AM 10:37
ANDREW J. SPANO
WESTCHESTER COUNTY CLERK

RECORD AND RETURN

CITY OF WHITE PLAINS, NEW YORK

ZONING MAP

ADOPTED BY THE WHITE PLAINS COMMON COUNCIL

JUNE 1, 1981

LAST AMENDED AUGUST 3, 2015

REVISED FEBRUARY 1, 2016

LEGEND

R1-30	Residential One Family
R1-20	Residential One Family
R1-12.5	Residential One Family
R1-7.5	Residential One Family
R1-5	Residential One Family
R2-4	Residential One Family Residential Two Family
R2-2.5	Residential One Family Residential Two Family
RM-2.5	Residential Multi-Family
RM-2	Residential Multi-Family
RM-1.5	Residential Multi-Family
RM-1.5T	Residential Townhouse
RM-1	Residential Multi-Family
RM-0.7	Residential Multi-Family
RM-0.4	Residential Multi-Family
RM-0.35	Residential Multi-Family
PSRDD	Planned Senior Residential Development District
C-O	Campus Office
O-R	Office-Residential
B-1	Restricted Business
B-2	Neighborhood Business
B-3	Intermediate Business
BR-1	Business Residential-1
BR-2	Business Residential-2
CB-1	Core Business-1
CB-2	Core Business-2
CB-3	Core Business-3
CB-4	Core Business-4
UR-4	Urban Renewal Central Business-4
B-6	Enclosed Mall
LI	Light Industrial
LI-M	Light Industrial Mixed

Zoning Boundary

Central Parking Area

Special Building Setback

Former 'S' zones with special provisions applicable to the properties indicated. For details of these provisions consult the Special 'S' District Atlas maintained on file in the Office of the City Clerk of the City of White Plains

NOTE:
This is not an official copy of the Zoning Map. The official copy is maintained on file in the Office of the City Clerk.

800' 0 1600' 3200'

SCALE 1"= 800'

N

TOWN OF NORTH CASTLE

TOWN OF GREENBURGH

TOWN OF HARRISON

VILLAGE OF SCARSDALE

TOWN OF HARRISON

Department of Planning
City of White Plains

20010901

U.S. Fish and Wildlife Service
National Wetlands Inventory

Wetlands



April 9, 2019

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Annual Drinking Water Quality Report for 2017
City of White Plains
Department of Public Works
255 Main Street
White Plains, New York 10601
(Public Water Supply ID #5903464)

Introduction

To comply with State regulations, the City of White Plains, Department of Public Works ("City") annually issues a report describing the quality of your drinking water. The purpose of this report is to increase your knowledge of drinking water and raise your awareness of the need to protect our drinking water sources. During 2017, your tap water met all State drinking water health standards. We conducted tests for over 170 contaminants last year and are proud to report that our system had no maximum contaminant level violations. Although 18 of those contaminants were at the detectable level, none of those contaminants were above the state's allowable levels. This report provides an overview of the 2017 water quality. Included are details about where your water comes from, what it contains, and how it compares to State standards.

If you have any questions about this report or concerning your drinking water, please contact Richard G. Hope, Commissioner of Public Works, at (914) 422-1220. We want you to be informed about your drinking water.

Where does our water come from?

In general, the sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally occurring minerals and, in some cases, radioactive material, and can pick up substances resulting from the presence of animals or from human activities. Contaminants that may be present in source water include: microbial contaminants; inorganic contaminants; pesticides and herbicides; organic chemical contaminants; and radioactive contaminates. In order to ensure that tap water is safe to drink, the State and the EPA prescribe regulations which limit the amount of certain contaminants in water provided by public water systems. The state Health Departments and the FDA's regulations establish limits for contaminants in bottled water that must provide the same protection for public health.

Source

One hundred percent (100%) of the water delivered by the City of White Plains is purchased from The New York City Department of Environmental Protection through Westchester County Water District No. 1. The raw water purchased from New York City (NYC) is drawn from the Kensico Reservoir, which is an unfiltered surface water source. Kensico Reservoir delivers a high quality water and has sufficient capacity to supply the City. The City's three wells, which supply a total of approximately 150,000 to 200,000 gallons per day, were removed from service in 2009. The Federal EPA had previously enacted the Surface Water Treatment Rule (SWTR), which required us to conduct a study to determine if these wells were under the influence of nearby surface water and that was found to be the case with our wells. Although the water quality from these wells has been consistently high for many decades, the new regulations (stated under NYSDOH PWS 43 Technical Reference) now require us to filter this water. As we had already begun the process of rehabilitating our reservoir filtration plant, we are redesigning the unit to also incorporate the well supply. This will enable us to meet the latest Federal and New York State Regulations pertaining to both our alternate water supplies (reservoirs and wells) using a single filtration plant. We expect to resume using both the reservoirs and the wells in 2020, as they are currently out of service.
The City has an emergency interconnection to the Delaware Aqueduct (Shaft 22). This connection is located in Yonkers and water is distributed to the City of White Plains via the Kensico-Bronx Pipeline. This emergency connection can supply 100% of the City's total requirements. During 2017 our system did not experience any restriction of our water source.

The New York State Department of Health (NYSDOH) has completed a source water assessment for this system, based on available information. Possible and actual threats to this drinking water source were evaluated. The state source water assessment includes a susceptibility rating based on the risk posed by each potential source of contamination and how easily contaminants can move through the subsurface to the wells. The susceptibility rating is an estimate of the potential for contamination of the source water, it does not mean that the water delivered to consumers is, or will become contaminated. While nitrates (and other inorganic contaminants) were detected in our water, it should be noted that all drinking water, including bottled drinking water, may be reasonably expected to contain at least small amounts of some contaminants from natural sources. The presence of contaminants does not necessarily indicate that the water poses a health risk. See section "*Are there contaminants in our drinking water*?" for a list of the contaminants that have been detected, if any. The source water assessments provide resource managers with additional information for protecting source waters into the future.

Source Water Assessment for Reservoirs
The source water assessment on the Reservoir #1 found no noteworthy risks to source water quality. The source water assessment for Reservoir #2 contains no discrete PCSs and none of the land cover contaminant prevalence ratings were above the low risk category. However, because microbial contaminants in reservoirs are generally highly mobile, this drinking water intake has a susceptibility rating of "medium-high" for protozoa and enteric bacteria and viruses.

Furthermore reservoirs are normally susceptible to water quality problems caused by phosphorous addition from surface water runoff of fertilizers and soaps, but our reservoirs have a substantial buffer distance from residential development.

Source Water Assessment for Dug Wells
The source water assessment for the groundwater sources has rated the dug wells as having a "medium-very high" susceptibility to microbials, protozoa, nitrites, nitrates, industrial solvents, metals, petroleum products, herbicides, pesticides and other industrial contaminants. These ratings are due primarily to the close proximity of permitted discharge facilities to the dug wells. This includes industrial/commercial facilities and the associated industrial activity in the assessment area. In addition, the wells draw from an unconfined aquifer of high hydraulic conductivity. While the source water assessment rates our wells as being susceptible to microbials, please note that our water is disinfected to ensure that the finished water delivered into your home meets New York State's drinking water standards for microbial contamination.

A copy of the assessment, including a map of the assessment area, can be obtained by contacting us.

The NYSDOH has evaluated the susceptibility of water supplies statewide to potential contamination under the Source Water Assessment Program (SWAP), and their findings are summarized in the paragraph(s) below. It is important to stress that these assessments were created using available information and only estimate the *potential* for source water contamination. Elevated susceptibility ratings do not mean that source water contamination has or will occur. As your Public Water Supply (PWS), we provide treatment and regular monitoring to ensure the water delivered to consumers meets all applicable standards.

We obtain 100% of our raw water from the New York City water supply system drawn from the Kensico Reservoir. Before it enters the Kensico Reservoir, water either comes from the Catskill/Delaware watersheds east of the Hudson River and/or from the Croton watershed in Putnam and Westchester Counties.

The reservoirs in the Catskill/Delaware watersheds lie within a mountainous rural area. They are relatively deep with little development along their shorelines. The main water quality concerns associated with land cover is agriculture, which can contribute microbial contaminants, pesticides, and algae-producing nutrients. There are also some potential contamination concerns associated with residential lands and associated wastewater discharges. There are also a number of other discrete facilities, such as landfills, chemical bulk storage, etc., that

have the potential to impact local water quality, but large significant water quality problems associated with these facilities are unlikely, due to the size of the watershed and surveillance and management practices.

The New York City Department of Environmental Protection (DEP) implements a series of programs to evaluate and protect source water quality within these watersheds. Their efforts focus on three important program areas:

1) The enforcement of strengthened watershed rules and regulations;
2) The acquisition and protection of watershed lands;
3) The implementation partnership programs that target specific sources of pollution in the watersheds.

Due to these intensive efforts, the SWAP methodologies applied to the rest of the state were not applied for this PWS. Additional information on the water quality and protection efforts in these New York City watersheds can be found at DEP's website www.nyc.gov/dep/watershed.

Treatment

All treatment of the water sources supplying the City of White Plains are treated in accordance with the requirements of the New York State Department of Health as follows:

Chlorination - Chlorine is added to ensure bacteriologically safe water.

Corrosion Control - Westchester County Water District No. 1 which supplies water to the City of White Plains, constructed a corrosion control treatment facility to adjust ph with the addition of ortho-phosphate. This treatment began operation in December 1995.

Fluoridation - Our system is one of the many drinking water systems in New York State that provides drinking water with a controlled, low level of fluoride for consumer dental health protection. According to the United States Centers for disease control, fluoride is very effective in preventing cavities when present in drinking water at an optimal range from 0.7 to 1.2 mg/l (parts per million). The City of White Plains began fluoridation treatment of all water sources on October 1, 1972, as an additional public health measure. The Westchester County Commissioner of Health recently stated that the benefits of fluoridation are not appreciably heightened if the dosage is increased beyond the 0.7 mg/l value. Accordingly, we instituted a reduction in dosing to this level. We will still reap the health benefits of fluoride treatment, while receiving the economics of significantly lowering our fluoride chemical treatment and storage tanks costs.

To ensure that the fluoride supplement in your water provides optimal dental protection, the State Department of Health requires that we monitor fluoride levels on a daily basis. During 2017**,** monitoring showed fluoride at levels in the optimal range 99% of the time. None of the monitoring results showed fluoride at levels that approach the maximum permitted value of 2.2 mg/l.

Filtration - Since August 5, 1999 The City of White Plains has utilized microfiltration for its surface water supply source consisting of two city-owned reservoirs (combined volume of just under 200,000,000 gallons.) As previously noted, our microfiltration plant is being reconstructed to meet the latest regulations and incorporate the wells into the system.

Facts and Figures
The public water supply system of the City of White Plains serves the entire city, an area of approximately 9.8 square miles. The City's residential population is approximately 57,000.

The water is distributed through approximately 160 miles of water mains to provide service to more than 10,000 metered accounts. The total water produced in year 2017 was 2,941.2 million gallons. The daily average of water treated and pumped into the distribution system is 8.06 million gallons per day. Our highest single day was 12.6 million gallons. The amount of water delivered to customers was 2,119.6 million gallons. This leaves an unaccounted for total of 821.6 million gallons, which is 27.9% of the water produced. Unaccounted for water represents water used to flush mains, fight fires, as well as losses from water main breaks, and water service line leaks before the meter.

The City has a progressive water structure wherein the unit rate escalates with increased usage. In 2017, White Plains water customers were charged at unit rates starting at $2.35 per 100 cubic feet of water, and the average family of four (4) had an annual bill of $266.41 (Among the lowest of some fifty water surveyors in Westchester County).

Are there contaminants in our drinking water?
As the State regulations require, we routinely test our drinking water for numerous contaminants. These contaminants include: total coliform, turbidity, inorganic compounds, nitrate, nitrite, lead and copper, volatile organic compounds, total trihalomethanes, haloacetic acids, radiological and synthetic organic compounds. The table presented below depicts which compounds were detected in your drinking water. The State allows us to test for some contaminants less often than once per year because the concentrations of these contaminants do not change frequently. Some of our data, though representative, are more than one year old.

Included as a supplement to this notice is a report of analytical testing results for contaminants required to be tested for by the United States Environmental Protection Agency and the New York State Department of Health. This supplement is available to consumers of the City of White Plains upon request.

It should be noted that all drinking water, including bottled drinking water, may be reasonably expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPA's Safe Drinking Water Hotline (800) 426-4791) or the Westchester County Health Department at (914) 813-5000.

Table of Detected Contaminates							
Central Avenue Pumping Station Entry Point (CAPS)							
Inorganic Chemicals & Physical Characteristics							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected (Maximum or Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Chlorides	No	6/2017	14.7	mg/l	n/a	MCL 250	Naturally occurring or road salt
Nitrate	No	6/2017	0.120	mg/l	10	MCL 10	Runoff from fertilizer use; leaching from septic tanks, sewage; erosion of natural deposits
Barium	No	6/2017	16.9	ug/l	2000	MCL 2000	Erosion of natural Deposits
Fluoride	No	2017	0.55 – 0.76	mg/l	n/a	MCL 2.2	Erosion of natural Deposits, Water additive to promote strong teeth
Sulfate	No	6/2017	4.40	mg/l	n/a	MCL 250	Naturally occurring
Nickel	No	6/2017	0.406	ug/l	n/a	N/A	Naturally occurring
Sodium [(1)]	No	6/2017	9.22	ug/l	n/a	N/A	Naturally occurring or road salt
Turbidity	No	12/27/17	1.0	NTU	n/a	MCL 5	Soil run-off
Chlorine	No	3/13/17	2.0	mg/l	n/a	4mg/l	Water additive used to control microbes
Manganese	No	6/2017	9.88	ug/l	n/a	300 MCL	Naturally occurring
Copper	No	6/2017	42.2	ug/l	1300	AL 1300	Internal Plumbing
Aluminum	No	6/2017	6.93	ug/l	n/a	n/a	Naturally occurring
Zinc	No	6/2017	10.6	ug/l	n/a	MCL 5000	Naturally occurring

Orchard Street Pumping Station Entry Point (OSPS)							
Inorganic Chemicals & Physical Characteristics							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected (Maximum or Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Chlorides	No	6/2017	15.0	mg/l	n/a	MCL 250	Naturally occurring or road salt
Nitrate	No	6/2017	0.117	mg/l	10	MCL 10	Runoff from fertilizer use; leaching from septic tanks, sewage; erosion of natural deposits
Barium	No	6/2017	16.8	ug/l	2000	MCL 2000	Erosion of natural Deposits
Fluoride	No	2017	0.59 – 0.80	mg/l	n/a	MCL 2.2	Erosion of natural Deposits, Water additive to promote strong teeth
Sulfate	No	6/2017	4.37	mg/l	n/a	MCL 250	Naturally occurring
Nickel	No	6/2017	0.337	ug/l	n/a	N/A	Naturally occurring
Sodium [(1)]	No	6/2017	9.69	ug/l	n/a	N/A	Naturally occurring or road salt
Turbidity	No	12/27/17	1.0	NTU	n/a	MCL 5	Soil run-off
Chlorine	No	3/13/17	1.9	mg/l	n/a	4mg/l	Water additive used to control microbes
Manganese	No	6/2017	10.8	ug/l	n/a	300 MCL	Naturally occurring
Aluminum	No	6/2017	7.27	ug/l	n/a	n/a	Naturally occurring

KENSICO RESERVOIR
Gross Alpha, Gross Beta Radium 226, Radium 228, and Uranium

Radiological Contaminants (Source Water - Kensico Reservoir):							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Gross Alpha Activity	No	10/15/2013	0.92	pci/1	n/a	15	Decay of natural deposits & manmade emissions
Gross Beta Activity	No	10/15/2013	0.69	pci/1	n/a	50	Erosion of natural deposits
Combined Radium 226 and Radium 228	No	10/15/2013	0.52	pci/1	n/a	5	Erosion of natural deposits
The state considers 50 pci/1 to be the level of concern for Beta Particles							

Distribution System							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected (Avg / Max Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Fluoride	No	2017	Avg 0.71 Max 1.1 (0.59–1.1)	mg/l	n/a	MCL 2.2	Water additive to promote strong teeth
Orthophosphate Treatment	No	2017	Avg. 0.715 Max 0.862 (0.602–0.862)	mg/l	n/a	n/a	Treatment additive for corrosion control
Turbidity	No	3/23/17	4.0	NTU	n/a	MCL=<5	Soil run off

Distribution System – Disinfection By–Products							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected (Avg / Max Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Total Trihalomethanes (TTHM) [2]	No	1/2017 4/2017 7/2017 10/2017	34.7 [6] (17.4–34.2)	ug/l	n/a	80	By-products of drinking water disinfection needed to kill harmful organisms.
Haloacetic Acids (HAA5) [2]	No	1/2017 4/2017 7/2017 10/2017	39.75 [7] (16.7–46.0)	ug/l	n/a	60	
Contaminants monitored under interim enhanced surface water treatment rule (Disinfection By-Products)							

Kensico Supply Entry Point							
Contaminant	**Violation Yes/No**	**Date of Sample**	**Level Detected (Maximum or Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Turbidity[5] (highest single monthly value)	No	3/10/2017	1.0	NTU	n/a	MCL=<1	Soil run off

Distribution System – Lead And Copper								
Contaminant	**Violation Yes/No**	**Date of Sample**	**Number of Sites Above AL Total Number of Sites (Range of Results Above AL)**	**Level Detected (Maximum or Range)**	**Unit Measurement**	**MCLG**	**Regulatory Limit (MCL,TT or AL)**	**Likely Source of Contamination**
Lead[3]	No	6/2017	2 30 (28.5–47.6)	2.85 <1.0–47.6	ug/l	0	AL 15.0 ug/l	Corrosion of household plumbing systems
Copper[4]	No	6/2017	0 30	349 27.9–471	ug/l	1300	AL 1300 ug/l	

As per State regulations, the City of White Plains routinely monitors your drinking water for various contaminants. Your water is tested for inorganic contaminants, nitrate, lead and copper, volatile organic contaminants, synthetic organic contaminants and total trihalomethanes. The contaminants detected in your drinking water are included in the Table of Detected Contaminants.

In addition, we monitored entry point samples for inorganic contaminants that were not detected. These include, cyanide, ammonia, manganese, antimony, arsenic, beryllium, mercury, lead, copper, thallium, selenium, cadmium, chromium, silver. Organic contaminants that were tested for and not detected in the source water include 3-Hydroxycarbofuran, Aldicarb, Aldicarb sulfone, Aldicarb sulfoxide, Carbaryl, Carbofuran, Methomyl, Oxamyl, Aldrin, Chlordane, Dieldrin, Endrin, Heptachlor, Heptachlor Expoxide, Lindane, Methoxychlor, PCB's, Propachlor, Toxaphene, 2,3,7,8-TCDD (Dioxin), Diquat, Endothall, Glyphosate, 2,4,5,T, 2,4-D, Dalapon, Dicamba, Dinoseb, Pentachlorophenol, Picloram, Silvex, 1,2-Dibromo 3-chloropropane, , 1,2-Dibromoethane, Butachlor, Metolachlor, Metribuzin, Alachlor, Atrazine, Benzo(a)pyrene, bis(2-Ethylhexyl) adipate, bis(2-Ethylhexyl) phthalate, Hexachlorobenzene, Hexachloro-cyclopentadiene, Simazine, 1,1,1,2-tetrachloroethane, 1,1,1-trichloro-ethane, 1,1,2,2-trichloroethane, 1,1,2-trichloroethane, 1,1-dichloro-ethane, 1,1-dichloroethene, 1,1-dichloropropene, 1,2,3-trichloro-benzene, 1,2,3-trichloropropane, 1,2,4-trichlorobenzene, 1,2,4-tri-methylbenzene, 1,2-dichlorobenzene, 1,2-dichloroethane, 1,2-dichloro-propane, 1,3,5-trimethylbenzene, 1,3-dichlorobenzene, 1,3-dichloro-propane, 1,4-dichlorobenzene, 2,2-dichloropropane, 2-butanone, 2-chlorotoluene, 4-chlorotoluene, Benzene, Bromobenzene, Bromochloromethane, Bromomethane, Carbon Tetrachloride, Chlorobenzene, Chloroethane, Chloromethane, cis-1,2-dichloroethene, cis-1,3-dichloro-propene, Dibromomethane,

Dichlorodifluoromethane, Ethylbenzene, Hexachlorobutadiene, Isopropylbenzene, Methy iso-butyl ketone, Methyl tert-butyl ether, Methylene Chloride, N-butylbenzene, N-propylbenzene, Naphthalene, O-Xylene, P & M-xylene, P-isopropyltoluene, SEC-butylenzene, Styrene, TERT-butylbenzene, Tetrachloroethene, Toluene, trans-1,2-dichloroethene, trans-1,3-dichloropropene, Trichloroethene, Trichlorofluoromethane, and Vinyl chloride. Radiological contaminants tested for and not detected in the source water include Strontium-90, and tritium. Unregulated Contaminants that were tested for and not found in the source water are Perchlorate, DCPA di-acid, 2,4-Dinitrotoluene, 2,6-Dinitrotoluene, 4,4-DDE, Acetochlor, EPTC, Molinate, Terbacil, and Nitrobenzene.

The results of the lead and copper testing performed in 2017 fell below the action level threshold. Therefore, additional lead and copper testing is not required until June 2020.

Notes:

(1) Sodium: Water containing more than 20 mg/l of sodium should not be used for drinking by people on severely restricted sodium diets. Water containing more than 270 mg/l of sodium should not be used for drinking by people on moderately restricted sodium diets.
(2) This level represents the locational running average calculated annually from data collected
(3) The level presented represents the 90th percentile of the 30 sites tested. A percentile is a value on a scale of 100 that indicates the percent of a distribution that is equal to or below it. The 90th percentile is equal to or greater than 90$^{\%}$ of the lead values detected in your water system. The lead values ranged from 1.0 ug/l to 47.6 ug/l. The 90th percentile was the 27th highest value (2.85 ug/l); 28 samples passed with TWO (2) failure. Lead results greater than 15 ug/l = "Fail".
(4) The level presented represents 90th percentile of the 30 sites tested. A percentile is a value on a scale of 100 that indicates the percent of a distribution that is equal to or below it. The 90th percentile is equal to or greater than 90$^{\%}$ of the copper values detected in your water system. The action level for copper was not exceeded at any of the 30 sites tested. The copper values ranged from 27.9 ug/l to 471 ug/l. The 90th percentile was the 27th highest value (349 ug/l); all samples passed. Copper results greater than 1300 ug/l = " Fail".
(5) Turbidity is a measure of the cloudiness of the water. Our highest single turbidity measurement for the year occurred in March 23, 2017. (4 NTU). State regulations require that turbidity must always be below 5 NTU. The regulations require that 95% of the turbidity samples collected have measurements below 5NTU.
(6) This level is the maximum locational running annual average for TTHM which occurred in the 2nd Quarter of 2017.
(7) This level is the maximum locational running annual average for HAA5 which occurred in the 1st quarter of 2017.

DEFINITIONS:

Maximum Contaminant Level (MCL)**:** The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible.

Maximum Contaminant Level Goal (MCLG)**:** The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum Residual Disinfectant Level (MRDL): The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

Maximum Residual Disinfectant Level Goal (MRDLG): the level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLG's do not reflect the benefits of the use of disinfectants to control microbial contamination.

Action Level (AL)**:** The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

Treatment Technique (TT): A required process intended to reduce the level of a contaminant in drinking water.

Non-Detects (ND): Laboratory analysis indicates that the constituent is not present.
Nephelometric Turbidity Unit (NTU): A measure of the clarity of water. Turbidity in excess of 5 NTU is just noticeable to the average person.
Milligrams per liter (mg/l): Corresponds to one part of liquid in one million parts of liquid (parts per million - ppm).
Micrograms per liter (ug/l): Corresponds to one part of liquid in one billion parts of liquid (parts per billion - pph).
Not Applicable: (n/a)

What Does This Information Mean?
As you can see by the table, our system had no violations. We have learned through our testing that some contaminants have been detected; however, these contaminants were detected below New York State Requirements. Although the action level for lead was not exceeded, we are required to present the following information on lead in drinking water:

If present, elevated levels of lead can cause serious health problems, especially for pregnant women, infants, and young children. It is possible that lead levels at your home may be higher than at other homes in the community as a result of materials used in your home's plumbing. White Plains is responsible for providing high quality drinking water, but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to 2 minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available for the Safe Drinking Water Hotline (1-800-426-4791) or at http://www.epa.gov/safewater/lead.

Is our water system meeting other rules that govern operations?
During 2017, our system was in compliance with all applicable State drinking water operating, monitoring, and reporting requirements.

Variances, Exemptions, Administrative or Judicial Orders:
The Surface Water Treatment Rule (SWTR) required that all water suppliers drawing water from a surface water source provide filtration by June 29, 1993. After implementing a Watershed Protection Plan, the City of New York has been granted Filtration Avoidance. Early in 1997 the City of New York was granted a long term exemption from the filtration requirement by the U.S. Environmental Protection Agency and the New York State Department of Health for the Catskill source south of Kensico and the Delaware source. The City was granted this exemption based on the exceptional quality of the raw water and the continued demonstration that the City can protect the water at its source. The SWTR requires that treatment for unfiltered surface water sources must achieve at least a 99.9 percent inactivation of Giardia Lamblia cycts and 99.99% inactivation of enteric viruses.

In 1994, The City of White Plains completed the installation of improvements required to achieve the required contact time.

Westchester County Water District No.1 Consent Decree
The City of White Plains currently receives all of its drinking water from the Kensico Reservoir, which is owned and operated by the New York City Department of Environmental Protection. The water is delivered through, and received treatment by, Westchester County Water District (WCWD) #1. WCWD#1 has received a federal violation for not delivering water that meets the requirements of the Long Term 2 Enhanced Surface Water Treatment Rule (LT2ESWTR). The LT2ESWTR addresses health effects associated with Cyrptosporidium in surface water used as a drinking water supply.

WCWD#1 has entered into a Consent Decree with the U.S. Environmental Protection Agency (USEPA), which requires WCWD#1 to provide all consumers LT2ESWTR compliant water by March 15, 2018. The consent decree also required WCWD #1 to undertake a Crytosporidium Action Plan, which includes weekly monitoring.

Test results of samples collected on a weekly basis from April 22, 2015 thru December 28, 2017 for cryptosporidium and giardia from the source water have not indicated the presence of cryptosporidium or giardia in the drinking water during this period except as follows:

> The December 17, 2016 crytosporidium results was 0.02 cycts/liter, well below the action level of 4 cysts/liter, and requires no action based on the approved action plan.
>
> The January 24, February 14, March 7, May 4 and December 21, 2017 results indicate a minor presence of giardia, less than 0.06 cysts/liter.

As of March 13, 2018, WCWD #1 is **no longer** in violation of Federal drinking water requirements, specifically the Safe Drinking Water Act (SDWA) and the Long Term 2 Enhanced Surface Water Treatment Rule (LT2ESWTR).

The White Plains Orchard Street Pump Station Ultraviolet (UV) Facility has been completed, accepted and placed into service on June 24, 2017 providing compliant water to the City of White Plains.
From January 1 to March 12, 2018 the Orchard Street Pumping Station and the UV facility was operated continuously to provide as much compliant water as possible to the City of White Plains. During the morning and evening hours when water demands exceed the capacity of the Orchard Street Pumping Station the water was not in compliance.

The Central Avenue Pumping Station UV Facility has been completed, accepted and placed into service providing compliant water. On March 13, 2018 the City of White Plains was placed into service from this facility.

Information on Cryptosporidium
Cryptosporidium is a microbial pathogen found in surface water and ground water under the influence of surface water. Although filtration removes Cryptosporidium, the most commonly used filtration methods cannot guarantee 100 percent removal. Ingestion of Cryptosporidium may cause Cryptosporidiosis, a gastrointestinal infection. Symptoms of infection include nausea, diarrhea, and abdominal cramps. Most healthy individuals can overcome disease within a few weeks. However, immuno-compromised people are at greater risk of developing life-threatening illness. We encourage immuno-compromised individuals to consult their health care provider regarding appropriate precautions to take to avoid infection. Cryptosporidium must be ingested to cause disease and it may be spread through means other than drinking water. In 2017, the City of New York Department of Environmental Protection (which sells us 100% of our raw water) collected 57 routine samples at their Kensico Reservoir effluents and analyzed them for Cryptosporidium oocysts using Method 1623HV. Of the 57 routine samples, they report that (3) three were positive for Cryptosporidium (0 to 2 oocysts/50L).

Information on Giardia
Giardia is a microbial pathogen present in varying concentrations in may surface waters and groundwater under the influence of surface water. Giardia is removed/inactivated through a combination of filtration and disinfection or by disinfection. The source water is disinfected prior to reaching our distribution system to remove/inactivate the Giardia cyst. Current test methods do not allow us to determine if the organisms are dead or if they are capable of causing disease. Ingestion of Giardia may cause giardiasis, an intestinal illness. People exposed to Giardia may experience mild or severe diarrhea, or in some instances no symptoms at all. Fever is rarely present. Occasionally, some individuals will have chronic diarrhea over several weeks or a month, with significant weight loss. Giardiasis can be tested with anti-parasitic medication. Individuals with weakened immune systems should consult with their health care providers about what steps would best reduce their risks of becoming infected with Giardiasis. Individuals who think that they may have been exposed to Giardiasis should contact their health care providers immediately. The Giardia parasite is passed in the feces of an infected person or animal and may contaminate water or food. Person to person transmission may also occur in day care centers or other settings where hand- washing practices are poor. In 2017, the City of New York Department of Environmental Protection (which sells us 100% of our raw water) collected 57 routine samples at Kensico Reservoir effluents and analyzed

them for Giardia using EPA Method 1623.1. Of the 57 routine samples, they report that 30 were positive for Giardia (0 to 6 cysts/50L).

Do I Need to Take Special Precautions?

Although our drinking water met or exceeded state and federal regulations, some people may be more vulnerable to disease causing microorganisms or pathogens in drinking water that the general population. Immuno-compromised persons such as persons with cancer undergoing chemotherapy**,** persons who have undergone organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice from their health care provider about their drinking water. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium, Giardia and other microbial pathogens are available from the Safe Drinking Water Hotline (800-426-4791).

ISO Rating

The Insurance Services Office, Inc. (ISO) is an independent company that serves companies, communities, fire departments, insurance regulators, and others by providing information about risk. ISO has a team of experts who collect information about municipal fire suppression and water supply and distribution efforts throughout the United States (over 44,000 fire protection areas have been evaluated and classified.) Both National Fire Protection Association and the American Water Works Association standards are applied. The water supply system portion of this Public Protection Classification (PPC) report and rating comprises 40% of the final grade. We are proud to say that in the last evaluation, our City of White Plains Public Works Water Bureau scored 38.55 points out of a possible 40. When combined with the City of White Plains Public Safety Fire Bureau, accounting for the remaining 60% of the rating, a total score of 92.3 (against a 100 point maximum) was achieved. This resulted in the City of White Plains having a final PPC number of "1". In New York State, out of approximately 2,000 rating studies, only the City of White Plains and one other municipality achieved this highest rating of "1", on a scale of "1" to "10"!

Why Save Water and How to Avoid Wasting It?

Although our system has an adequate amount of water to meet present and future demands, there are a number of reasons why it is important to conserve water:

- Saving water saves energy and some of the costs associated with both of these necessities of life;
- Saving water reduces the cost of energy required to pump water and the need to construct costly new wells, pumping systems and water towers; and
- Saving water lessens the strain on the water system during a dry spell or drought, helping to avoid severe water use restrictions so that essential firefighting needs are met.

You can play a role in conserving water by becoming conscious of the amount of water your household is using, and by looking for ways to use less whenever you can. It is not hard to conserve water. Conservation tips include:

- Automatic dishwashers use 15 gallons for every cycle, regardless of how many dishes are loaded. So get a run for your money and load it to capacity.
- Turn off the tap when brushing your teeth.
- Check every faucet in your home for leaks. Just a slow drip can waste 15 to 20 gallons a day. Fix it and you can save almost 6,000 gallons per year.
- Check your toilets for leaks by putting a few drops of food coloring in the tank, watch for a few minutes to see if the color shows up in the bowl. It is not uncommon to lose up to 100 gallons a day from one of these otherwise invisible toilet leaks. Fix it and you save more than 30,000 gallons a year.
- Use your water meter to detect hidden leaks. Simply turn off all taps and water using appliances, then check the meter after 15 minutes, if it moved, you have a leak.

Water System Improvements

In 2017, we completed the following:

1. Installation of new water main valves and hydrants throughout the City
2. Continued with the City's Annual Leak Survey to monitor for underground water main leaks
3. Completed our annual Hydrant Flushing and Water Main Valve Maintenance Program
4. Commenced with Residential Automated Meter Infrastructure (AMI) Project
5. Completed a Cybersecurity Assessment of the City's Water System
6. Assisting Westchester County Water District No. 1 with completion of their Ultraviolet (UV) Treatment facilities at OSPS and CAPS
7. Hydraulic and Water quality modeling of the water distribution system

In 2018, we are completing and/or planning the following capital improvements:

1. Water Main Replacement: Leith Place, Idlewood Road., Ritchey Place. and Miles Avenue
2. Upgrade of Chemical Bulk Storage Facilities at Central Avenue Pump Station (CAPS)
3. Rehabilitation of Filtration Facilities at OSPS to utilize and treat existing on-site well and Reservoir No. 1 and 2 water
3. Upgrade of Chemical Bulk Storage Facilities at Orchard Street Pump Station (OSPS)
4. Evaluation of existing OSPS well and Reservoirs No. 1 and 2 for future use for potable water supply
5. Watershed security upgrades
6. Replace large diameter water main valves throughout the City
7. Replace miscellaneous water lines throughout the City
8. Construction of two (2) – 4 million gallon MG Portland cement concrete water storage tanks
9. Complete Residential Installation of Automated Meter Infrastructure (AMI) Project
10. Update record utilities mapping and upgrade existing City GIS (Geographic Information System) database

Closing

Thank you for allowing us to continue to provide your family with quality drinking water this year. We ask that all our customers help us protect our water sources, which are the heart of our community and our way of life.


If you have any questions or comments, please do not hesitate to contact our office at (914) 422-1220.

City of White Plains
Department of Public Works
255 Main Street, 3rd Floor
White Plains, NY 10601

BULK PERMIT
254

National Flood Hazard Layer FIRMette

FEMA



Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN — Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 / 17.5 — Cross Sections with 1% Annual Chance Water Surface Elevation
- Coastal Transect
- 513 — Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 4/10/2019 at 10:35:24 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.