Phase I Environmental Site Assessment/

EPA All-Appropriate Inquiry

White Plains – Five Parcels

26-28, 34, 42 and 60 East Post Road, 223-225 Dr. Martin Luther King Jr. Boulevard

White Plains, New York

Prepared for

The City of White Plains

Christopher Gomez, AICP – Commissioner of Planning

City of White Plains

70 Church St.

White Plains, NY 10601

June 2021

Barton&Loguidice

26-28, 34, 42 and 60 East Post Road, 223-225 Dr. Martin Luther King Jr. Boulevard
White Plains, New York

Phase I Environmental Site Assessment/ EPA All-Appropriate Inquiry

June 2021

Prepared for:

The City of White Plains
Christopher Gomez, AICP – Commissioner of Planning
City of White Plains
70 Church St.
White Plains, NY 10601

Prepared by:

Barton & Loguidice, D.P.C.
10 Airline Drive
Albany, NY 12205

This document is printed on recycled paper

TABLE OF CONTENTS

Section			Page
EXECUTIVE SUMMARY			1
1.0	INTRODUCTION		5
	1.1	Purpose	5
	1.2	Detailed Scope of Services	5
	1.3	Limitations of Environmental Assessment	5
	1.4	User Reliance	7
	1.5	Deviations from ASTM Scope	7
	1.6	Data Gaps	7
2.0	SITE DESCRIPTION		8
	2.1	Location	8
	2.2	Site and Vicinity General Characteristics	8
3.0	USER PROVIDED INFORMATION		9
	3.1	Title Records	9
	3.2	Environmental Liens	9
	3.3	Specialized Knowledge	9
	3.4	Owner and Occupant Information	9
	3.5	Reason for Performing Phase I	9
4.0	RECORDS REVIEW		11
	4.1	Standard State and Federal Environmental Record Sources	11
	4.2	Physical Setting Sources	36
	4.3	Historical Use Information on the Property	37
	4.4	Historical Use Information on Adjoining Properties	39
5.0	SITE RECONNAISSANCE		40
	5.1	Site Observations	40
	5.2	Adjoining Property Observations	42
	5.3	Interviews and Questions	44
6.0	FINDINGS		46
7.0	OPINIONS		47
8.0	RECOGNIZED ENVIRONMENTAL CONDITIONS (REC)		48

TABLE OF CONTENTS – Continued

Section **Page**

9.0 ADDITIONAL INVESTIGATION 50

10.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 51

11.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONALS 52

Figures

Figure 1 Site Location Map
Figure 2 Site Plan

Attachments

Attachment 1 User Provided Documents
Attachment 2 USGS Topographic Quadrangles
Attachment 3 Aerial Photographs
Attachment 4 City Directory Search Results
Attachment 5 Fire Insurance Maps
Attachment 6 Site Photographs
Attachment 7 ASTM Transaction Screen Questionnaires
Attachment 8 EDR Report

EXECUTIVE SUMMARY

Barton & Loguidice, D.P.C. (B&L) was retained by the City of White Plains to conduct a Phase I Environmental Site Assessment (Phase I ESA) of 5 parcels totaling approximately 2.6 acres owned by private entities and one property owned by the White Plains Housing Authority. The addresses include 26-28 East Post Road (Singer Real Estate), 34 East Post Road (Marianina Oil Corp.), 42 East Post Road (IR 4244 E. Post LLC), 60 East Post Road (Bridgestone), and 223-225 Dr. Martin Luther King Jr. Boulevard (White Plains Housing Authority) and are in the City of White Plains, Westchester County, NY. The purpose of this assessment is to assess the condition of the site prior to acquiring the properties and conducting redevelopment.

B&L's investigation of this property was conducted using a three-part process; an environmental records review, interviews and a site visit. This investigation was conducted in general accordance with the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM Designation E 1527-13). As stated in EPA's 40 CFR Part 312 "Standards and Practices for All Appropriate Inquiries", which was amended December 30, 2013, the ASTM E1527-13 standard is consistent and compliant with the statutory criteria for all appropriate inquiries, and constitutes one of the requirements necessary for CERCLA liability protection.

On May 12, 2021, a representative of B&L conducted a site reconnaissance of the target properties and full site access was allowed at two of the five properties. This assessment has revealed no evidence of recognized environmental conditions (RECs) in connection with the target properties except for the following:

26-28 East Post Road

Multiple petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases have been administratively closed, but one case was closed with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on current soil and groundwater quality have not been provided, but NYSDEC Spill Report Forms and a Remedial Investigation (RI) Report conducted at an adjacent site both indicate petroleum compounds remain present in the subsurface at 26-28 East Post Road. The RI report also references that the 26 East Post Road site may be a source area that contaminated soil and groundwater offsite to the north. Free-phased petroleum product was reported to be present at the adjoining site (22 East Post Road) and there is a potential for petroleum impacts at the adjoining site to affect the 26-28 East Post Road site.

34 East Post Road

The NYSDEC Bulk Storage Tank database indicates that three underground storage tanks are active at the 34 East Post Road site. Multiple petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases appeared to have been administratively closed, but one case was closed with a designation of not meeting cleanup

standards, indicating residual contamination remains. Detailed reports on current soil and groundwater quality on the 34 East Post Road property have not been provided, but NYSDEC Spill Report Forms and the RI Report conducted at an adjacent site both indicate petroleum compounds remain present in the subsurface at 34 East Post Road. The current land owner of 34 East Post Road is a defendant in a lawsuit where a downgradient property owner (White Plains Housing Authority (WPHA) - plaintiff) claims that petroleum contamination emanating from 34 East Post Road has impacted their property. The downgradient WPHA property affected (223-225 Dr. Martin Luther King Jr. Blvd) is a property subject to this current Phase I ESA.

42 East Post Road

Two petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases appeared to have been administratively closed, but one case was closed with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on petroleum release locations or current soil and groundwater quality at the 42 East Post Road property have not been provided, but there is a potential that petroleum compounds are present. Significant petroleum contamination at the adjacent property (34 East Post Road) has the potential to impact soil and groundwater quality at the 42 East Post Road site.

60 East Post Road

Soil contamination associated with hydraulic lifts at this property have been documented and reported to the NYSDEC. The associated NYSDEC Spill Case appeared to have been administratively closed, but with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on remedial measures taken (if any) and current soil and groundwater quality at the 60 East Post Road property have not been provided, but there is a potential for petroleum compounds to be present. A small sump in the basement contains water or oil staining from an unknown source. This observation may be associated with the hydraulic lift release, or another undetermined source.

223-225 Dr. Martin Luther King Jr. Blvd

A Remedial Investigation Report completed in 2016 at this site documents that petroleum impacted soil and groundwater is present. The property owner (WPHA) is a plaintiff in a lawsuit against the current and past land owners of 34 East Post Road claiming that petroleum contamination emanating from 34 East Post Road has impacted their property in the vicinity of Brookfield Street and Building 33. A reference in the Remedial Investigation Report also indicates that contamination from 26 East Post Road has affected the 223-225 Dr. Martin Luther King Jr. Blvd property in the vicinity of Building 159. Free-phased petroleum product has been reported to be present at the adjoining site (22 East Post Road) and this property may be another source of petroleum impacts to the 223-225 Dr. Martin Luther King Jr. Blvd site. Winbrook Housing Development (223 Dr. Martin Luther King Jr. Blvd) was reported to have

operated two 20,000 gallon underground fuel oil tanks. It was not ascertained if these tanks were/are located on the portion of the property subject to this Phase I ESA.

1.0 INTRODUCTION

1.1 Purpose

The City of White Plains has retained Barton & Loguidice, D.P.C. (B&L) to conduct a Phase I Environmental Site Assessment (Phase I ESA) of five parcels in the City of White Plains, Westchester County, New York (Figure 1). This Phase I ESA report was prepared for the exclusive use of the City of White Plains.

1.2 Detailed Scope of Services

The Environmental Site Assessment was conducted in general accordance with the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM Designation: E 1527-13). This practice outlines the accepted methodology for conducting Phase I Environmental Site Assessments that makes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" (ASTM E 1527-13).

The objective of the Phase I Environmental Site Assessment is to identify the presence or likely presence of any hazardous substances or petroleum products on the property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. This objective was met by:

- Conducting a review of standard environmental data sources;
- Conducting a site visit; and
- Conducting an interview with the property owner.

1.3 Limitations of Environmental Assessment

The information, environmental conditions, and conclusions presented in this report as a result of the Phase I Environmental Site Assessment are based on an analysis of available public records, field observations, and information obtained as a result of correspondence and interviews with the current property owners. No intrusive testing or investigative work was conducted as part of the Phase I Environmental Site Assessment.

No environmental site assessment can completely eliminate the uncertainty regarding the potential occurrence of a past release or potential future release of hazardous substances or petroleum on a particular property. The Phase I Environmental Site Assessment is intended to reduce this uncertainty by making appropriate and reasonable inquiry into the past and present uses of the property.

1.4 User Reliance

B&L hereby authorizes the City of White Plains, their successors, and assigns to rely on this Phase I ESA report dated June 2021. Furthermore, B&L warrants that the Phase I ESA report, to the best of our knowledge, is believed to be true, accurate, and complete in all material respects.

1.5 Deviations from ASTM Scope

There were no significant deviations from the ASTM scope during the performance of this Phase I ESA, other than data gaps noted in Section 1.6 below.

1.6 Data Gaps

Due to the coronavirus pandemic, state government and some municipal offices are not accessible to the public. As such, typical ESA I research cannot be conducted in person (typical reasonable ascertainable information was not readily accessible). B & L submitted Freedom of Information Law (FOIL) requests for site specific file information to the New York State Department of Environmental Conservation (NYSDEC) and the Westchester County Department of Health via email. At the time of this report the NYSDEC has responded indicating the Westchester County Health Department keeps the records for that county. The Westchester County FOIL request is on-going and pertinent information provided by the County can be forwarded to the City of White Plains at a later date.

Owner interviews at 34 East Post Road, 42 East Post Road, and 223-225 Dr. Martin Luther King Jr. Blvd were either declined due to a lawsuit with active court proceedings or were not requested per City of White Plains due to ongoing property acquisition negotiations. Full site access for site reconnaissance was only provided for 60 East Post Road. Site reconnaissance at 26-28 East Post Road, 34 East Post Road, 42 East Post Road and 223-225 Dr. Martin Luther King Blvd were conducted by an exterior inspection from public access areas (sidewalks, road right-of-ways, and pedestrian pathways).

2.0 SITE DESCRIPTION

2.1 Location

The target properties are located at 26-28 East Post Road, 34 East Post Road, 42 East Post Road, 60 East Post Road, and 223-225 Dr. Martin Luther King Jr. Boulevard in the City of White Plains, Westchester County, New York. The sites are located in the downtown portion of the City of White Plains. Additional details of each site area provided below.

26-28 East Post Road

The 26-28 East Post Road parcel (Parcel ID: 130.27-2-5) is located to the west of Brookfield Street and to the north of East Post Road. The total parcel size is approximately 0.20 acres.

34 East Post Road

The 34 East Post Road parcel (Parcel ID: 130.27-2-4) is located to the east of Brookfield Street and to the north of East Post Road. The total parcel size is approximately 0.26 acres.

42 East Post Road

The 42 East Post Road parcel (Parcel ID: 130.27-2-3) is located to the east of Brookfield Street and to the north of East Post Road. The total parcel size is approximately 0.24 acres.

60 East Post Road

The 60 East Post Road parcel (Parcel ID: 130.27-2-2) is located to the west of Winchester Street and to the north of East Post Road. The total parcel size is approximately 0.38 acres.

223-225 Dr. Martin Luther King Jr. Blvd

The 223-225 Dr. Martin Luther King Jr. Blvd parcel (Parcel ID: 130.83-7-1) is located to the east of South Lexington Avenue and west of Winchester Street and to the north of East Post Road. The total parcel size is approximately 1.45 acres.

2.2 Site and Vicinity General Characteristics

The sites are located in the downtown portion of the City of White Plains. Land uses adjacent to the site are typical of a downtown city center. The surrounding area is commercially zoned (B-3) and consists of hospital properties, commercial facilities, and urban residential developments.

To the south of the target properties is a hospital and numerous associated buildings, several residential high-rise buildings are to the north, with mainly commercial and mixed use residential properties to the east, and a mix of commercial and residential properties to the west of the target properties. The abutting property to the north is currently under development (residential high-rise building construction). The target parcels are within a relative flat area that slopes gently to the west.

3.0 USER PROVIDED INFORMATION

3.1 Title Records

A review of title records was not part of the scope for this assessment.

3.2 Environmental Liens

Representatives of the user of this Phase I ESA, the City of White Plains, has been made aware during this ESA that a lawsuit is pending between the White Plains Housing Authority (plaintiff) and BP Products North America Inc. Marianina Oil Corp., and Atlantic Richfield Company, the current or former owners of 34 Post Road (defendants). Information on specific liens has not been reviewed, but may exist due to the lawsuit. NYSDEC Spill Case documents also reference an Order on Consent for the 34 Post Road property. The user did not convey any knowledge of environmental liens against the remaining properties to the environmental professionals who conducted this Phase I Environmental Site Assessment.

3.3 Specialized Knowledge

B&L staff conducted a target property site assessment on May 12, 2012. The assessment was conducted for the City of White Plains. B&L does not possess any other specialized knowledge pertaining to the target properties.

3.4 Owner and Occupant Information

Reasonable attempts were made to conduct interviews and/or complete a questionnaire with owners or owner representatives for all five target properties. As directed by the City of White Plains representatives, no owner was contacted for the property at 42 East Post Road due to ongoing property acquisition negotiations. Michael Taub, an owner/member of the 26-28 East Post LLC, completed an owner interview for the 26-28 East Post Road property. Mike Tharpe an Environmental Due Diligence Specialist for Bridgestone Retail Operations completed the questionnaire for the 60 East Post Road property. Designated owner contacts for 34 East Post Road and 223-225 Dr. Martin Luther King Jr. properties declined to be interviewed or complete questionnaires due to a lawsuit with court proceedings being conducted concurrent with this Phase I ESA. Owner information is in Section 5.5 Interviews and Questions.

3.5 Reason for Performing Phase I

The City of White Plains is performing due diligence at the property to identify potential issues of environmental concern prior to purchasing the properties.

3.6 Documents Provided by the User

The City of White Plains obtained and transmitted environmental documents on May 10, 2021 to B&L. These documents (provided in Attachment 1) included NYSDEC Spill Report Forms for petroleum releases at 26 East Post Road and 34 East Post Road, and a Remedial Investigation

Report for the White Plains Housing Authority – Building 33 (much of the investigation was conducted on the 223-225 Dr. Martin Luther King Jr. Blvd property).

The Spill Report Form for Spill Number 9713100 at 26 East Post Road (Closed Getty Station) indicates that petroleum impacts were identified in 1998 and an estimated 5169 tons of impacted soil was present. A dual-phase extraction system operated from 2001 to 2007. Offsite groundwater impacts were identified, but by 2009 only one monitoring well continued to demonstrate impacts. New wells were installed in 2016. A new spill case was opened for petroleum impacts identified at the adjacent property (street address of 22 East Post Road). Another new spill case was opened for petroleum impacts identified at the 34 East Post Road property (former BP Station owned by Marianina Oil Corporation). The dispenser canopy at 26 East Post Road was removed in 2017 and impacts were not identified in excavations when the canopy was removed. The spill case was closed in 2017, but designated as not meeting cleanup standards.

The Spill Report Form for Spill Number 1608924 at 34 East Post Road (former BP Station owned by Marianina Oil Corporation) indicates that petroleum impacts were identified in soil and groundwater samples collected downgradient from this facility since 2014. DEC case entries from 2016 to 2019 do not contain technical details on soil and groundwater investigations, but instead document significant NYSDEC and property owner correspondence and legal interactions. An Order on Consent was issued to the property owner in October 2017. The spill case is active and is designated as not meeting cleanup standards. A Remedial Investigation Report - White Plains Housing Authority Building 33, dated November 29, 2016, was completed for White Plains Housing Authority (WPHA). Soil and groundwater sampling was conducted along Brookfield Road and on the target property for this Phase I ESA (open parking and access area at 223-225 Dr. Martin Luther King Jr. Blvd). The report references two petroleum contaminant plumes one emanating from 26 East Post Road, and another emanating from 34 East Post Road. The report concludes that the contaminant plume emanating from 34 East Post Road has impacted WHPA Building 33. Petroleum impacts appear to be between 6 and 15 feet below ground surface between the potential source area and Building 33.

4.0 RECORDS REVIEW

4.1 Standard State and Federal Environmental Record Sources

In accordance with ASTM Standard E 1527-13, the following standard environmental record sources (federal and state) were reviewed for the property and the surrounding area for the minimum search distances listed:

Federal Sources	Search Distance (in Miles)
Federal National Priorities List (NPL)	1.0
Federal Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) List	0.5
Federal Resource Conservation and Recovery Act (RCRA) Treatment, Storage, and Disposal Facilities Database	0.5
Federal Resource Conservation and Recovery Act (RCRA) Large and Small Quantity Generators Database	Property and Adjoining Properties
Federal List of Institutional Controls / Engineering Controls	Property Only
Federal Emergency Response Notification System (ERNS) Database	Property Only
State Sources	**Search Distance (in Miles)**
State List of Hazardous Waste Disposal Sites	1.0
State List of Solid Waste Disposal Sites	0.5
State List of Leaking Storage Tanks	0.5
State List of Registered Underground Storage Tanks	Property and Adjoining Properties
State List of Institutional Controls / Engineering Controls	Property Only
State List of Brownfield Sites	0.5

The resources listed above were reviewed through the use of Environmental Data Resources (EDR) hazardous site database. EDR uses a computerized system to extract public record information from Federal and State environmental agencies. A customized records search is conducted for the subject property and the area within the appropriate minimum search distances. The report prepared by EDR, which presents the results of the environmental record sources reviewed for the site, can be found in its entirety in Attachment 8 (the EDR report is

provided at the end due to the database page length). The results of this information search are summarized below.

1. Federal NPL List

The National Priorities List (NPL) is a list prepared by the U.S. Environmental Protection Agency (EPA) of uncontrolled or abandoned hazardous waste facilities. No NPL, proposed NPL, or delisted NPL sites were identified within the minimum ASTM search distance (1.0 mile) from the target site.

The Superfund Enterprise Management System (SEMS) database integrates multiple legacy systems into a comprehensive tracking and reporting tool. The inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the NPL, as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. No SEMS listings were identified within one mile from the target site.

2. Federal CERCLIS List

The CERCLIS List is a comprehensive list prepared by the EPA of known or suspected uncontrolled or abandoned hazardous waste facilities. No CERCLIS listings were identified within the minimum ASTM search distance from the target property.

CERCLIS "No Further Remedial Action Planned" (NFRAP) listings were also searched. No CERCLIS NFRAP listings were identified within the minimum ASTM search distance from the target property.

3. Federal RCRA Treatment, Storage, and Disposal Facilities Database

The RCRA Treatment, Storage, and Disposal (TSD) Facilities database contains information pertaining to facilities that treat, store, or dispose of hazardous waste. No RCRA-TSD listings were identified within a 0.5-mile radius of the site.

4. Federal RCRA Generators Database

The RCRA Generators Database contains information pertaining to facilities that either generate between 100 kilograms (Kg) and 1,000 Kg of hazardous waste per month (small quantity generators or SQG), greater than 1,000 Kg of hazardous waste per month (large quantity generators or LQG), or meet other applicable requirements of the Resource Conservation and Recovery Act. Facilities that generate less than 100 Kg of hazardous waste per month are considered conditionally exempt SQG (CESQG). RCRA Non-Generators do not presently generate hazardous waste. One parcel of the target property and six adjacent properties were identified as having RCRA records. Summary information is presented below.

- Westchester Firestone at 60 East Post Road– Target Property (EDR Map ID 14): The target property is listed in database as a RCRA non-generator/no longer reporting. The site was considered a SQG in 1998 of ignitable waste, cadmium, chromium, lead, selenium, and tetrachloroethylene. No violations were reported.
- White Plains Hospital at 41 East Post Road – (EDR Map ID 29): The White Plains Hospital is a LQG of ignitable wastes, various metals, and various spent non-halogenated solvents. The facility received written informal violations in June 2012 but the actions have been satisfactorily closed.
- Swank Drycleaners at 168 South Lexington Avenue (EDR Map ID 24): Swank Drycleaners is a Non-gen/NLR located across the road from the west/southwest corner of the target property. The site was reported as a SQG of spent halogenated solvents in 1991. No violations were reported.
- Bright Side Cleaners at 182 South Lexington Avenue (EDR Map ID 36): The site is currently a Non-gen/NLR located across the road from the west/southwest corner of the target property. The site is a former SQG of spend halogenated solvents, last reportable in 1992. No violations were reported.
- Con Edison Manhole 9169 (EDR Map ID 39): Located in the roadway of South Lexington Avenue, this RCRA Non-gen/NLR was formerly a CESQ in 2013. No wastes or violations were reported.
- Con Edison Service Box 3468 (EDR Map ID 19): Located at the southeast corner of the target property, this Non-gen/NLR is located in the roadway at East Post Road and Winchester Street and was formerly a CESQ in 2014. No records of wastes or violations were reported.
- Con Edison Manhole 3471 (EDR Map ID 20): This manhole is adjacent to the Con Edison Service Box 3468. Formerly a CESQ in 2014, no wastes or violations were reported.

The CORRACTS database lists handlers with RCRA Corrective Action Activity. The EDR report did not identify any facilities in the CORRACTS database within the minimum ASTM search distance from the site.

5. Federal Engineering/Institutional Controls Database

The Federal list of engineering controls and institutional controls is managed by the U.S. Environmental Protection Agency (EPA). This database is used to store information regarding the engineering and/or institutional controls required at a facility as a result of a federally regulated action. The target property is not listed in this Federal database.

6. Federal ERNS Database

The Emergency Response Notification System is managed by the EPA. This database is used to store information on the sudden and/or accidental release of hazardous

substances (including petroleum) into the environment. The target property is not listed in this database.

7. State Hazardous Waste Disposal Sites

The New York State Hazardous Waste Disposal Site (SHWS) List contains information pertaining to those facilities that are deemed hazardous by the NYS Department of Environmental Conservation (NYSDEC). The target property is not listed in this database. Two SHWS listings are located within an approximate 1-mile radius of the site.

- Automobile Club of New York, 101 Westmoreland Avenue (EDR Map ID: 327) – The site is located approximately 0.27 mile northwest of the target property. Groundwater flow is to the north/northwest. The site is currently used as an automobile repair and detailing shop. On site contamination occurred at a former dry well and USTs that were historically present. Remediation is complete and the site is governed under a Site Management Plan for soil and groundwater contaminated with Tetrachloroethylene and related daughter products. Additionally, an unknown source has impacted the groundwater with 1,1,1 TCA. Contact with contaminated materials is unlikely due to site capping and the area has a public water supply.

- Mamaroneck Avenue Drycleaners, 359-369 Mamaroneck Avenue (EDR Map ID: 348) – The site is located approximately 0.3 mile southeast of the target property. Direction of groundwater flow was not reported. The building contains a drycleaner, a nail salon, an insurance agency, and two restaurants. The remainder of the site consists of a paved parking lot. Tetrachloroethylene was identified on site due to the presence of the drycleaner. However, the site did not qualify for the registry.

No Delisted State Hazardous Waste Site (DEL SHWS) listings were identified within the minimum ASTM search distance (1.0 mile) from the site.

8. State Solid Waste Disposal Sites Listing

The NYS Solid Waste Facility Register is a comprehensive listing of all permitted solid waste landfills and processing facilities currently operating in the State of New York. The target property is not listed in this database and there are no listings located within an approximate 0.5-mile radius of the site.

9. Leaking Storage Tanks

The NY Leaking Underground Storage Tank (LTANKS) report is a comprehensive listing of all leaking storage tanks reported to the NYSDEC. The target property was identified in the listing. Two hundred and three LTANK listings were identified within the ASTM search radius of 0.5 miles from the target property. Summary information in the table below.

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
White Plains Hospital – 41 East Post Road	9414693	2/8/1995	2/13/1995	Tank Overfill	Incorrect fill amount given to fuel delivery company. Approximately 50 gallons were spilled and cleaned.	False	0.01
White Plains Hospital – 41 East Post Road	1107393	9/12/2011	10/31/2011	Tank Test Failure	Company reported failure was below product level. Tank also failed previous test- NY Spills ID 1105346. DEC asked them to empty the tank immediately. (product was present in the tank top sump) There is also an old open spill with oil getting into the basement from their other UST.	False	0.01
White Plains Hospital	9506062	8/15/1995	12/20/2005	Tanks Test Failure	Old record that was updated. Not a confirmed spill, tank was to be removed and replaced.	False	0.014
12 East Post Road	0103645	7/5/2001	12/9/2003	Tank Failure	An unknown amount of #2 Fuel Oil was spilled due to an UST leak. The tank was pulled and cleanup occurred.	True	0.33
11 East Post Road	8600048	4/2/1986	2/24/1987	Tank Failure	Product was observed in wells. No further details given.	True	0.036
Getty Service Station – 11 East Post Road	0407127	9/27/2004	9/27/2004	Tank Overfill	Spilled into containment area – no release into environment.	True	0.036
Getty Service Station – 11 East Post Road	9210753	12/16/1992	12/31/1992	Tank Test Failure	Underground tank failed test. Was pumped and repaired.	False	0.036
White Plains Housing Authority – 225 Grove St.	8904683	8/10/1989	7/30/1992	Tank Test Failure	One of two tanks failed test. Owner informed that due to age, may be best to replace instead of repair.	False	0.043
Target Property: Windbrook Housing – 223 Dr. Martin Luther King Drive	**0207150**	**10/10/2002**	**11/25/2002**	**Tank Test Failure**	**Two 20,000 gallon tanks collectively failed. No further information given.**	**True**	**0.044**
White Plains Hospital – Maple Avenue	9304740	7/15/1993	1/6/1994	Tank Overfill	Soil was discovered in a tank. Reported that the tank would be pulled and soil stockpiled.	False	0.048
White Plains Hospital – 41 East Post Road	9806058	8/14/1998	8/17/1998	Tank Overfill	Tank overfilled by carrier. Vacuum truck sent for cleanup.	True	0.048
White Plains Hospital – Davis Avenue and East Post Road	930351	6/14/1993	6/18/1996	Tank Failure	Tank was removed and facility converted to natural gas.	True	0.048
1 East Post Road	0013009	3/12/2001	3/12/2001	Tank Overfill	Approximately 5 gallons of petroleum were spilled, with DOH to follow up.	True	0.056
Bisscardi Cleaners – 201 South Lexington Avenue	0100630	4/17/2001	5/1/2006	Tank Failure	Unknown quantity of petroleum released in basement due to tank failure. Northeast Environmental Responded.	True	0.063

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
134 South Lexington Avenue	0008525	10/20/2000	3/12/2001	Tank Test Failure	Tank test failed; tank was subsequently pulled with no evidence of failure/contamination. A second tank was also discovered and pulled but showed no sign of failure.	True	0.067
White Plains Hospital – 8 Longview Avenue	1007877	10/25/2010	7/5/2011	Tank Test Failure	Tank and contamination were removed.	False	0.078
White Plains Hospital – 8 Longview Avenue	0907812	10/12/2009	11/4/2009	Tank Test Failure	Tightness test failed. Tank was re-tested and passed on 10/20/2009.	True	0.078
White Plains Hospital – 8 Longview Avenue	1007255	10/6/2010	12/12/2017	Tank test Failure	Tank test failed several times. Refer to Spill 1007877. Tank was removed and subsequent contamination.	True	0.078
Slader Neighborhood Center – 2 Fisher Court	9810451	11/18/1998	12/5/2003	Tank Failure	During tank removal caller found contaminated soil from hole in tank. Soil was removed by environmental cleanup crew.	True	0.085
Avis – 20 West Post Road	8706892	11/13/1987	7/27/1988	Tank Test Failure	Tanks were emptied and removed in July 1988.	True	0.087
White Plains Medical Center – 170 Maple Avenue	0004388	7/12/2000	6/22/2001	Tank Failure	Unknown amount of fuel oil spilled. Soil stockpiled for removal.	True	0.091
White Plains Housing Authority – 33 Fisher Avenue	1007861	10/25/2010	7/5/2011	Tank Test Failure	Caller believed a loose connection between tanks caused test failure. Tanks were isolated and retested. Lines between were replaced and no contamination was noted.	True	0.111
White Plains Lincoln/Mercury – 25 West Post Road	0005954	8/18/2000	4/24/2001	Tank Failure	Contamination was noted during tank removal. 86.48 tons of soil were excavated and disposed of by environmental cleanup company.	True	0.114
Allen Ame Church – 65 Fisher Avenue	0509976	11/21/2005	12/20/2006	Tank Failure	During tank removal, contamination was discovered. Believed it may have been from nearby gas station. 46.5 tons of contaminated soils were removed by environmental cleanup company.	False	0.123
Fire House #4 – Maple Avenue and South Lexington Avenue	8707150	11/19/1987	1/5/1989	Tank Test Failure	Failure of 0.07 gallons per hour (no release). Tank was to be excavated, inspected, and retested. No further information.	True	0.124
Apartment – 170 Grand Street	0408227	10/26/2004	11/28/2007	Tank Test Failure	Underground tank to be closed in place. Sidewall and bottom sample results were satisfactory.	False	0.133
6 Chester Avenue	1506711	9/24/2015	2/8/2019	Tank Test Failure	Interested buyer sought report of historic 1,000 gallon UST removal. Documentation was collected; All proper removal procedures and documentation were collected to show removal occurred without contamination.	False	0.137

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
8 Chester Avenue	9610881	12/3/1996	4/16/2012	Tank Test Failure	Report that tank lines were bad. Spill was closed due to being 1. At least 10 years old 2. It is a Homeowner (not regulated tank) 3. No indication of environmental impact.	False	0.137
Commercial Business – 158 Grand Street	0506649	8/30/2005	2/3/2006	Tank Failure	Several large holes reported in tank. Cleanup crew removed tank and 39.36 tons of contaminated soil.	True	0.138
Fingar and Fingar Law Office – 158 Grand Street	0413115	3/16/2005	9/7/2005	Tank Failure	Tank was found to have holes. High levels of contamination reported. See record 0506649.	False	0.138
Office Building – 150 Grand Street	8908740	12/5/1989	2/7/1990	Tank Overfill	Approximately 200 gallons of fuel oil were spilled and cleaned up by Environmental cleanup crew.	True	0.142
Residence – 25 Longview Avenue	0413208	3/18/2005	5/8/2005	Tank Test Failure	Test failure led to removal of UST and 3.3 tons of contaminated soil.	True	0.142
Greenridge Estates – 1-13 Greenridge Avenue	1911181	3/4/2020	Not Reported	Tank Test Failure	One test failed with hissing. Other tanks were to be re-tested. No further information.	False	0.15
Greenridge Estates – 1-13 Greenridge Avenue	0912193	2/22/2010	12/22/2011	Tank Test Failure	Open records followed up on due to being PBS regulated. On 1/22/10, tanks were reported as ASTs and passed retest.	False	0.15
Greenridge Estates – 1-13 Greenridge Avenue	1911256	3/6/2020	Not Reported	Tank Test Failure	Tanks had failed in February 2020. Fitting were replaced but tanks failed subsequent testing. Tanks located in vaults with no evidence of release.	False	0.15
36 Davis Road	0304516	7/29/2003	10/23/2003	Tank Failure	Failed tank was pulled and 62.66 tons of contaminated soil were removed.	True	0.155
Westchester Office Building – 112 East Post Road	9009334	11/27/1990	12/11/1990	Tank Failure	Tank leaked when air pressure added. Leakage contained to basement concrete and cleaned with Speedi-Dry. Tank was repaired.	True	0.155
White Plains Fire Department – Station 4 – 234 South Lexington Avenue	9804511	7/10/1998	8/12/1998	Tank Failure	Leaking tank. Caller performed soil sampling. No further information given.	True	0.156
Grant Manor Properties – 235 South Lexington Avenue	9706472	8/28/1997	2/27/1998	Tank Test Failure	Unable to obtain vacuum during test. Tank was retested after repairs and passed.	True	0.159
Grant Manor Properties – 235 South Lexington Avenue	0204243	7/23/2002	11/6/2002	Tank Test Failure	Tank failed and was repaired. Passed retest.	True	0.159

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
Grant Manor Properties – 235 South Lexington Avenue	0304500	7/29/2003	10/31/2003	Tank Failure	Closure referred to health department.	False	0.159
Grant Manor Properties – 235 South Lexington Avenue	9313731	2/22/1994	1/5/1995	Tank Failure	20,000 gallon tank spilled into sump pump. Cleanup was noted in progress. No further information.	False	0.159
Our Lady of Mount Carmel – 92 South Lexington Avenue	8704169	9/20/1987	10/21/1987	Tank Test Failure	System was emptied and cleaned. No further information given.	True	0.162
Our Lady of Mt. Carmel – 92 South Lexington Avenue	8703713	8/5/1987	10/21/1987	Tank Test Failure	No information given.	True	0.162
Our Lady of Mt. Carmel – 92 South Lexington Avenue	1100855	4/25/2011	1/23/2012	Tank Test Failure	60 year old tank failed; was re-lined in the 1980's and required yearly testing. No record of testing from 2008 on. Tank was removed on 1/20/2012 with no further action.	False	0.162
82 Bank Street	0212286	2/4/2004	3/27/2005	Tank Test Failure	Tank recommended to be re-tested or removed. Tank passed retest.	True	0.162
9 Greenridge Avenue	0911533	1/27/2010	10/28/2011	Tank Test Failure	Old record. Department of Health followed up and found retest was passed.	True	0.162
Coachman Hotel – 123 East Post Road	9306655	8/31/1993	9/24/1993	Tank Test Failure	35 year old tank found with hole in crown during inspection. No further information.	True	0.169
City Parking Garage – Chester Avenue and Marble Avenue	9109520	12/6/1991	3/25/1992	Tank failure	Tank filled in a vault. Approximately 250 gallons of fuel oil were leaked from bottom. No further information given.	True	0.173
130-144 East Post Road	0002215	5/22/2000	2/28/2011	Tank Test Failure	Same tank as spill 1005304. Tank was never removed or retested after initial failure. Ten years later was removed and cleaned up completed after existing shopping center burned down.	True	0.176
Mitchell Estate – 5 Nutgrove Street	1405501	8/20/2014	11/19/2014	Tank Test Failure	Tank was removed without evidence of leak or significant contamination.	True	0.178
43 Davis Avenue	1407225	10/10/2014	9/25/2015	Tank Test Failure	Tank was removed after failing tank test. Found to have holes and contamination in soil. 16.11 tons of soil were removed.	True	0.182
23 Oakwood Road	9906780	9/7/1999	1/28/2000	Tank Test Failure	Tank was cut, cleaned and inspected. Minor contamination was found in soils underneath due to small holes. Tank was abandoned in place as it was located under foundation/concrete patio.	True	0.201

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
135-137 Fisher Avenue	8709424	2/5/1988	3/11/1988	Tank Overfill	Overfill from vent during delivery onto blacktop. Cleaned with Speedi-dry.	True	0.204
5 Charles Street	0504800	7/21/2005	5/1/2006	Tank Test Failure	Tank was removed after failing test. 19.72 tons of contaminated soils were also removed.	True	0.21
77 South Lexington Avenue	0304231	7/22/2003	7/22/2003	Tank Overfill	Spill occurred at police station due to overfill. Cleaned up.	True	0.215
ABCO Refrig – 80 West Post Road	0609508	11/17/2006	1/10/2007	Tank Failure	See spill 06-09498. 1,000 gallon tank reported with holes and contaminated soil.	True	0.216
3 Wyanoke Street	0607149	9/21/2006	2/6/2007	Tank Test Failure	Prospective property buyer was given quote for digging up top of tank and retesting. No further information given.	True	0.218
3 Wyanoke Street	0607758	10/7/2006	2/6/2007	Tank Test Failure	Previously reported TTF is 06-07149.	True	0.218
3 Wyanoke Street	0610630	12/19/2006	2/6/2007	Tank Test Failure	Previously reported TTF is 06-07149. Northeast Environmental disposed of UST and 2 drums of contaminated soil.	True	0.218
11 Roosevelt Street	0708659	11/8/2007	1/20/2013	Tank Test Failure	Tank tested for residential transaction. No further information given. Per NYSDEC policy, record was closed as being open over 5 years.	False	0.22
99 Court Street	9606465	8/20/1996	2/18/2006	Tank Test Failure	Tank passed isolation retest but lines failed; was scheduled to be abandoned in place and lines removed.	False	0.222
43 Longview Avenue	0507448	9/21/2005	3/15/2006	Tank Test Failure	See spill 05-08523.	True	0.224
43 Longview Avenue	0508523	10/17/2005	7/11/2006	Tank Failure	Holes found in 550 gallon fuel tank. Tank was pulled and 323.19 tons of contaminated soils were removed. Groundwater monitoring well was installed.	True	0.224
21 Greenridge Avenue	0410525	12/22/2004	2/24/2005	Tank Test Failure	No further action recommended.	True	0.225
John Dale Inc. – 178 Mamaroneck Avenue	9810809	11/25/1998	12/1/1998	Tank Failure	Tank leaked and contaminated soil. Soils were removed and stockpiled. No further information given.	False	0.228
151 East Post Road	0601015	4/26/2006	11/3/2006	Tank Test Failure	Tank was retested and given approval from the Westchester County Department of Health.	True	0.228
148 Martine Avenue	8701223	5/13/1987	11/6/2004	Tank Test Failure	Tank tested – recommendation for monitoring wells. No further information given.	False	0.229

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
44 Longview Avenue	9614364	3/11/1997	3/11/1997	Tank Failure	Holes in tank due to age. Homeowner disposed and switched to natural gas.	True	0.232
White Plains DPW – Maple and Mamaroneck Avenue	9111846	2/18/1992	3/10/1992	Tank Failure	During a tank upgrade, contaminated soils were discovered, stockpiled, tested, and disposed of.	True	0.235
White Plains Fire House 6 – Maple and Mamaroneck Avenue	8707149	11/19/1987	1/5/1989	Tank Test Failure	High volume leak discovered. Tank excavated, inspected and removed. New tank installed.	True	0.235
203 Mamaroneck Avenue	9710787	12/22/1997	Not Reported	Tank Test Failure	Tank failed. Note states record needs updating as of 2010.	False	0.236
Pepe Motors – 50 Bank Street	9607100	4/4/1999	4/29/1999	Tank Test Failure	Tank closure reported. No further details.	True	0.237
169 Mamaroneck Avenue	0301465	5/9/2003	8/25/2003	Tank Test Failure	Tank test failure led to pump out. UST and 122.09 tons of contaminated soils were disposed of.	True	0.237
165 Mamaroneck Avenue	0303361	6/30/2003	6/22/2007	Tank Failure	A previously lined tank was found to be leaking. Tank and contaminated soils removed. See also spill 03-01465.	False	0.237
165 Mamaroneck Avenue	9701601	5/6/1997	2/12/2005	Tank Test Failure	Tank failed vacuum test. Reportedly passed retest. This tank was removed in June 2003.	False	0.237
Per-Bar – 124 Mamaroneck Avenue	8802839	6/29/1988	1/18/1989	Tank Test Failure	Failed with gross leak, retest recommended. No further information.	True	0.243
235 Mamaroneck Avenue	0404588	7/28/2004	1/10/2005	Tank Test Failure	Failed vacuum test due to broken vent. Repaired and passed retest.	True	0.246
235 Mamaroneck Avenue	1112859	2/9/2012	3/30/2012	Tank Test Failure	Tank failed during test with a dry leak. Vent was replaced and passed retest.	False	0.246
White Plains YMCA – 250 Mamaroneck Avenue	1410006	1/12/2015	12/8/2015	Tank Test Failure	Tank failed test and was removed under spill 15-05596.	False	0.248
Irvington Avenue	8708811	1/15/1988	3/3/1988	Tank Test Failure	Record shows tank passed retest.	True	0.249
29 Cambridge Avenue	1007882	10/25/2010	12/17/2010	Tank Test Failure	Tank failed test and was removed with no evidence of leak or contamination.	False	0.251
36 Oakwood Avenue	1212813	11/29/2012	2/7/2013	Tank Test Failure	Fill pipe issue. Tank was repaired and passed retest.	True	0.251
110 Mamaroneck Avenue	0011270	1/16/2001	1/22/2003	Tank Test Failure	No information regarding retest given.	True	0.255

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
YMCA – 260 Mamaroneck Avenue	9013259	3/21/1991	3/23/2002	Tank Test Failure	In 1991, lines were recommended to be excavated and retested. In 2002, additional correspondence provided to DEC to close the spill.	True	0.255
Office Building – 171 East Post Road	9811157	12/4/1998	3/3/2004	Tank Test Failure	Record states tank to be isolated and retested. No further information given.	True	0.26
White Plains Honda – 31 Westmoreland Avenue	9514655	2/15/1996	2/15/1996	Tank Overfill	Tank overfill onto pavement. Cleaned up.	True	0.261
Michilin Motor Pool – 148 Martine Avenue	0301426	5/8/2003	5/8/2003	Tank Overfill	Driver overfilled tank. Contained and cleaned up.	True	0.262
Michael E. Land Office – 148 Martine Avenue	0503295	6/17/2005	9/26/2005	Tank Overfill	No spill information given. Record closed upon receipt of report and as-builts.	True	0.262
148 Martine Avenue	0109874	1/11/2002	1/14/2002	Tank Test Failure	Line test failure led to some material leaking into containment area. Line to be replaced.	True	0.262
23 Odell Avenue	0204631	8/1/2002	7/14/2008	Tank Test Failure	Tank removed and disposed of along with 19.47 tons of contaminated soils. See also spill 02-06200.	True	0.264
109 Mamaroneck Avenue	9512203	12/29/1995	12/29/1995	Tank Overfill	Customer over-ordered product and spill occurred. Cleaned up.	True	0.264
Nicky's Restaurant – 107 Mamaroneck Avenue	8900599	4/19/1989	5/3/1989	Tank Test Failure	Line leak identified. Lines were excavated, capped off, and tank passed retest.	True	0.265
Municipal Garage – 111	8808829	2/10/1989	8/7/1991	Tank Test Failure	Garage pulling tanks. No further information.	True	0.266
Civic Center Motors – 31 Westmoreland Avenue	0108090	11/8/2001	11/8/2001	Tank Overfill	Spill contained to pavement and cleaned up.	True	0.27
Civic Center Motors – 31 Westmoreland Avenue	0206674	9/25/2002	2/26/2003	Tank Test Failure	Vacuum tank test failure. Owner advised of results.	True	0.27
Civic Center Motors – 31 Westmoreland Avenue	0010522	12/19/2000	7/10/2001	Tank Overfill	Tank overfill occurred – all material, including 11 drums of contaminated soil was recovered.	True	0.27
Court Street and Martine Avenue	8905963	9/18/2989	11/29/1989	Tank Overfill	Tank truck overfilled. Police and fire department responded.	True	0.272
The Michicallian Office – Martine Avenue and Court Street	9310783	11/16/1993	11/18/1993	Tank Failure	Contamination discovered during tank pull. 77.98 tons of soil were removed.	True	0.272

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
Benerofe Association – 39 Westmoreland Avenue	0807224	9/26/2008	1/7/2009	Tank Test Failure	No product spilled. Tank isolated, repaired, and passed retest.	True	0.274
Benerofe Association – 29 Westmoreland Avenue	9411173	11/21/1994	9/22/1995	Tank Test Failure	No information given except that tank was "unusual case tank".	True	0.274
163 Fisher Avenue	1104419	7/20/2011	11/5/2014	Tank Test Failure	Test done during real estate transaction. As record was at least two years old with no known impact, record closed.	False	0.274
16 Odell Avenue	9810325	11/16/1998	1/19/1999	Tank Test Failure	Gross failure reported. No other information included.	True	0.275
Halpern Enterprises – 170 East Post Road	8804996	9/8/1988	4/30/2005	Tank Test Failure	Fill pipe bent. Take to be isolated and retested. Administrative closed in 2005.	False	0.276
C Star Diner – 285 Mamaroneck Street	9712450	2/7/1998	7/10/2020	Tank Test Failure	Follow up to tank test failure in 2020 revealed tank was removed in 1998 and property redeveloped into a bank.	False	0.28
20 Prospect Street	0005555	8/9/2000	8/29/2000	Tank Test Failure	Tank was pulled after failed test. 23.52 tons of contaminated soils were removed.	True	0.282
Mario's S/S – 107 West Post Road	9408490	9/26/1994	9/30/1994	Tank Overfill	Gauge on tank was broken leading to release of 10 gallons of gasoline. RP cleaned up.	False	0.286
Seacon Metal – 7 Intervail Street	8904791	11/30/1989	11/20/1989	Tank Test Failure	Tank to be cleaned and removed or abandoned. No further information given.	True	0.286
179 East Post Road	9900622	4/16/1999	3/24/2000	Tank Failure	Vaulted tank in basement found full of holes. Tank and 3.65 tons of contaminated soils were removed.	True	0.288
Minskoff Corp. - 179 Martine Road	9201879	5/15/1992	5/15/1992	Tank Overfill	Approximately 7 gallons of fuel oil were spilled and contained to concrete floor and cleaned up.	False	0.295
11 Odell Avenue	0803661	6/27/2008	7/14/2008	Tank Test Failure	Tank passed retest after repair.	True	0.296
11 Odell Avenue	1215385	2/7/2013	2/14/2013	Tank Test Failure	Leak in piping. Repaired, tank passed retest.	False	0.296
40 Waller Avenue	8709325	2/2/1988	2/2/1988	Tank Failure	Tank ruptured in basement releasing 275 gallons of fuel oil. All product recovered.	True	0.298
9 Mitchell Place	9710474	12/12/1997	10/27/1998	Tank Failure	Caller doing site work found contaminated soil. No further action required.	True	0.3
Mitchell Place Associates – 10 Mitchell Place	8902485	6/9/1989	10/2/1989	Tank Test Failure	Tank pulled and contaminated soils removed. Sump periodically cleaned to remove free product.	True	0.304

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
179 Fisher Avenue	0712211	2/20/2008	8/31/2009	Tank Test Failure	Tank test failure with no further information. No further action.	False	0.304
Ken Knapp Citgo - 115 West Post Road	9005629	8/21/1990	12/17/1990	Tank Test Failure	Tanks were removed after excavation and inspection. No further information given.	True	0.305
A&S Store – Galleria Plaza	8803673	7/27/1988	8/9/1988	Tank Test Failure	No further information than No further action determination.	True	0.319
A&S Store – Galleria Plaza	8805571	9/29/1988	3/7/1989	Tank Test Failure	Tank was relined and passed test.	True	0.319
29 Prospect Street	0800443	4/11/2008	6/8/2008	Tank Test Failure	Tank passed retest after piping repaired.	True	0.326
JC Penney Co. – 100 Main Street	9102767	6/10/1991	6/13/1991	Tank Overfill	Contained on sidewalk. RP cleaned up.	True	0.327
NY Tel – 111 East Main Street	9314933	3/21/1994	3/1/1995	Tank Test Failure	Tank excavated, inspected, and retested. No further information.	True	0.329
NY Tel – 111 East Main Street	9609101	10/21/1996	11/26/1999	Tank Failure	Contaminated soils found during tank pull. 524.7 tons of contaminated soils removed.	True	0.329
Centroplex Assoc. – 123 Main Street	8906607	10/4/1989	6/12/1991	Tank Test Failure	Tank isolated and passed retest.	True	0.329
Centroplex Assoc. – 123 Main Street	9910168	11/19/1999	11/22/1999	Tank Overfill	Overfold valve released product onto concrete and was cleaned.	True	0.329
Centroplex Assoc. – 123 Main Street	8907663	11/1/1989	6/12/1991	Tank Test Failure	Tank to be pumped out and retested. Refer to record 8906607.	True	0.329
23 Mitchell Place	8809894	3/23/1989	12/20/1991	Tank Test Failure	Plumbing leaked during filling. Tank was to be isolated and retested.	True	0.332
195 Fisher Avenue	0909891	12/7/2009	1/16/2014	Tank Test Failure	Tank tester reported house owned by bank. No indication of spill. Recommended to be closed or reassigned after three years.	False	0.334
139 East Post Road	0310631	12/15/2003	10/11/2005	Tank Test Failure	Tank test failed. Westchester County DOH confirmed no further action necessary.	True	0.336
35 Mitchell Place	9905959	8/17/1999	10/8/1999	Tank Failure	Caller reported seeing holes in tank during cleaning. No further information.	True	0.336
8 Orchard Parkway	8706819	11/10/1987	11/29/1989	Tank Test Failure	Tank failed with high volume leak. Stated that they would retest.	True	0.339
8 Orchard Parkway	9807488	09/18/1998	11/20/1998	Tank Test Failure	Renewal test. Tank was removed with no contamination.	True	0.339

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
Vintage Restaurant – 171-173 Main Street	0602861	6/14/2006	9/26/2008	Tank Test Failure	Tank failed testing in both tank and piping. Tank was not being used and lost several inches of oil after test. Recommended that the tank be pumped and removed. Tank was removed with 2.64 tons of contaminated soils.	False	0.34
2 Ridgeview Avenue	0602736	6/12/2006	7/20/2006	Tank Test Failure	Tank was pulled. No evidence of leak or contamination was found.	True	0.341
28 Mitchell Place	9901259	5/3/1999	5/13/1999	Tank Test Failure	After initial failure, lines were replaced and tank passed.	True	0.345
28 Mitchell Place	9903630	6/29/1999	11/14/2001	Tank Failure	Tank pulled; noted to be leaking.	True	0.345
9 Lafayette Street	0208594	11/19/2002	8/13/2012	Tank Test Failure	Closed as record older than 5 years with no apparent impact.	False	0.345
185-187 Main Street	9708138	10/9/1997	11/10/1997	Tank Failure	Contaminated soils discovered during tank pull. Soils stockpiled and removed.	True	0.347
Gateway Building – 1 North Lexington Avenue	9000726	4/20/1990	12/6/1991	Tank Test Failure	No pertinent information given.	True	0.351
Gateway Building – 1 North Lexington Avenue	9108659	11/13/1991	11/13/1991	Tank Test Failure	Oil was noticed in manway, repaired and retested.	False	0.351
Gateway Building – 1 North Lexington Avenue	8908197	1/29/1990	11/16/1989	Tank Test Failure	Tank was pumped out and passed retest.	True	0.351
73 Longview Avenue	1503444	6/29/2015	10/8/2015	Tank Test Failure	Tank test failed during real estate transaction. Leaking UST and 121.37 tons of contaminated soils were removed.	False	0.352
32 Mitchell Place	0108164	11/12/2001	7/22/2002	Tank Failure	Contaminated soils discovered during tank pull. 15.67 tons removed.	True	0.354
32 Mitchell Place	9611678	12/24/1996	12/24/1996	Tank Overfill	Driver overfilled tank. Spill contained to blacktop and cleaned with Speedi-Dry.	True	0.354
32 Mitchell Place	9611679	12/24/1996	11/10/1997	Tank Overfill	Fire department cleaned up. Appears to be overfill alarm was not functioning.	True	0.345
Office Building – 14 Mamaroneck Avenue	9613653	2/20/1997	3/5/1997	Tank Test Failure	Tank passed retest.	True	0.355
Office Building – 14 Mamaroneck Avenue	0313324	3/4/2004	4/22/2004	Tank Test Failure	Tank excavated and passed retest.	True	0.355
37-43 Mitchell Place	0208214	11/7/2002	4/7/2003	Tank Failure	Unknown amount of fuel oil spilled. Soils stockpiled and results were deemed satisfactory.	True	0.363

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
36-38 Mitchell Place	0505320	8/1/2005	12/18/2005	Tank Failure	Holes in tank led to contaminated soil. UST and 19.56 tons of soil were removed.	True	0.364
203 Main Street	0206130	9/12/2002	9/3/2003	Tank Test Failure	Tank closed in place and vault cleaned.	True	0.37
77 Longview Avenue	0009714	11/16/2000	12/26/2000	Tank Failure	Contaminated soils discovered during tank pull. 6.67 tons were removed.	True	0.371
365 Mamaroneck Avenue	0310423	12/9/2003	3/5/2005	Tank Overfill	Oil delivered to wrong address; fill pipe led to basement with no tank. RP cleaned up.	False	0.373
Apartment Building – 40 Mitchell Place	0304394	7/25/2003	10/31/2003	Tank Failure	Tank was leaking. Abandoned and closed in place.	True	0.373
150 West Post Road	0108396	11/19/2001	3/6/2002	Tank Failure	Old tank found during excavation. Tank and 35.58 tons of contaminated soils were removed.	True	0.374
369 Mamaroneck Avenue	9908980	10/23/1999	2/26/2005	Tank Overfill	Overfill in basement. Owner cleaned up.	False	0.379
45 Mitchell Place	9904849	7/23/1999	1/11/2000	Tank Test Failure	No information provided.	True	0.381
45 Mitchell Place	9510979	11/29/1995	12/12/1995	Tank Overfill	Driver overfilled tank.	True	0.381
45 Mitchell Place	1212688	11/27/2012	2/5/2020	Tank Test Failure	Missing documentation regarding retest in 2012 – all documentation forwarded and tank has passed testing the past two years.	False	0.381
240 East Post Road	9903233	6/21/1999	12/15/1999	Tank Failure	Tank removed and contamination in soil discovered. No further information.	True	0.389
Cameo Coop Apartments – 2 Old Mamaroneck Road	9414514	1/2/1995	8/28/1996	Tank Failure	Leak from tank into vault. Cleanup deemed satisfactory by White Plains Building Department.	True	0.395
Benerofe Properties, Inc. – 179 Westmoreland Avenue	8800315	4/9/1988	11/25/1988	Tank Test Failure	Tank passed retest.	True	0.395
91 Davis Avenue	0501407	5/4/2005	12/18/2005	Tank Failure	Holes discovered in tank during pull. Tank and 108.66 tons of contaminated soils removed.	True	0.407
13 Howard Avenue	0211763	2/27/2003	3/3/2003	Tank Test Failure	Tank passed retest due to discovery of initial testing error.	True	0.410
21 Dekalb Avenue	0206319	9/18/2002	2/2/2005	Tank Failure	Contamination found during tank pull. Tank and 43.36 tons of soil were removed.	True	0.411
Tiffany Towers – 56 Doyer Avenue	0208738	11/22/2002	2/21/2003	Tank Failure	Contaminated soils found. Tank and soils excavated.	True	0.412

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
19 Dekalb Avenue	0406991	9/23/2004	10/4/2004	Tank Failure	Tank was leaking but controlled. Environmental cleanup firm completed.	False	0.417
168 West Post Road	9813367	2/1/1999	4/14/1999	Tank Test Failure	Tank pulled and 126.74 tons of contaminated soils were removed.	True	0.427
168 West Post Road	0808631	10/30/2008	2/9/2009	Tank Test Failure	Piping repaired and tank passed retest.	True	0.427
Miller Center For Nursing – 37 Dekalb Avenue	8802117	6/3/1988	8/30/1988	Tank Test Failure	Tank closed in place, switched to gas service.	True	0.43
50 Linda Avenue	0206302	9/18/2002	11/25/2002	Tank Failure	Tank and 57.79 tons of contaminated soils removed.	True	0.432
Sunonco Gas – 405 Mamaroneck Avenue	9004404	7/20/1990	9/18/1990	Tank Test Failure	Tank removed.	True	0.433
52 Linda Avenue	0402572	6/9/2004	8/9/2004	Tank Failure	Tank and 48.07 tons of contaminated soils removed.	True	0.434
City Hall – 255 Main Street	8707220	11/21/1987	3/14/1988	Tank Test Failure	No information provided.	False	0.435
83 Longview Avenue	9903778	7/1/1999	9/29/1999	Tank Test Failure	Tank passed test but staining was noted. Tank and 90.24 tons of contaminated soils were removed.	True	0.437
2 Grandview Avenue	9909620	11/8/1999	12/21/2000	Tank Failure	Contaminated soil found during a tank abandonment. Tank and 133.45 tons of contaminated soils were removed.	True	0.438
White Plains Police Department – 279 Hamilton Avenue	8606771	2/4/1987	11/29/1989	Tank Test Failure	Signed stipulation agreement.	True	0.439
15 Smith Avenue	0506586	8/29/2005	12/18/2005	Tank Failure	UST and 164.79 tons of contaminated soils removed. Groundwater was impacted and monitoring wells were installed.	True	0.439
Hamilton Main Parking	8708260	11/23/1987	11/29/1989	Tank Test Failure	Tank was to be excavated, inspected, and retested. No further information given.	True	0.445
Former WPPD – 279 Hamilton Avenue	0405806	01/01/1987	7/6/2007	Tank Failure	Site cleaned up and remaining clean up work governed under STIP.	True	0.445
Westley House Limited – 10 Old Mamaroneck Road	0205840	10/2/2002	12/13/2002	Tank Test Failure	Gap in welding repaired after tank cleaning.	True	0.448
Westley House Limited – 10 Old Mamaroneck Road	9810881	11/20/1998	4/30/2004	Tank Test Failure	Failure of one tank. No further information given.	True	0.448
10 Old Mamaroneck Road	0910093	12/11/2009	4/29/2010	Tank Test Failure	Passed retest after tank cleaning.	False	0.448

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
10 New King Street	1006070	9/1/2010	10/28/2010	Tank Test Failure	Tank was uncovered, repaired and retested. Passed retest.	False	0.452
Exxon – 274 Hamilton Avenue	8707486	12/1/1987	12/18/1987	Tank Test Failure	Passed retest.	True	0.452
98 Davis Avenue	0611529	1/17/2007	6/25/2007	Tank Failure	Northeast Environmental responded to clean up leaking tank and contaminated soils.	True	0.453
4 New King Street	9809692	11/2/1998	12/5/2003	Tank Test Failure	Tank removed in January 1999.	True	0.453
3 New King Street	0806330	9/5/2008	3/30/2010	Tank Test Failure	Passed retest after boiler fittings and perometer replaced.	True	0.46
3 New King Street	1600651	4/19/2016	4/4/2017	Tank Test Failure	Two tanks failed with small leaks indicated. Environmental firm removed tanks.	False	0.46
1 New King Street	0000953	4/24/2000	2/7/2001	Tank Test Failure	Retest recommended. No further information.	True	0.461
2 Soundview Avenue	0801427	5/6/2008	11/12/2008	Tank Test Failure	Piping replaced and tank passed retest.	True	0.464
2 Soundview Avenue	2002195	6/24/2020	Not Reported	Tank Test Failure	Tank failed and removed from service. Two existing tanks pumped out to be closed in place and switch to gas service.	False	0.464
27 Smith Avenue	0906385	9/2/2009	12/21/2012	Tank Test Failure	Tank failed test in real estate transaction. Tank removed and replaced. 42.17 tons of impacted soils were removed.	False	0.471
Crown Plaza Hotel – 66 Hale Avenue	1105926	8/24/2011	4/30/2020	Tank Test Failure	Tank was replaced in 2012; documentation was not provided until 2020.	False	0.474
277 Martine Avenue	9008032	10/22/1990	11/8/1990	Tank Test Failure	Tank passed retest.	True	0.479
2-4 Washington Avenue	0300993	4/28/2003	6/13/2003	Tank Test Failure	Recommended to uncover and retest. No further information given.	True	0.481
14 Soundview Avenue	8800187	4/6/1988	1/9/1989	Tank Test Failure	Recommended for repair and retest. No further information given.	True	0.487
14 Grandview Avenue	0502229	5/25/2005	8/28/2005	Tank Failure	Tank had holes. UST and 197.51 tons of contaminated soils removed.	True	0.487
34 Smith Avenue	0507545	9/23/2005	12/3/2005	Tank Failure	Tank pulled. 5 drums of contaminated soils removed.	True	0.498
3 Bryant Avenue	1004584	7/23/2010	1/6/2011	Tank Test Failure	Old UST removed after death of resident.	True	0.496

LTANKS Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
300 Martine Avenue	0206553	9/24/2002	12/13/2002	Tank Test Failure	Leak from manhole cover. Resealed and retested.	True	0.497
1 Barker Avenue	9807932	9/29/1988	11/19/1999	Tank Failure	Hole found in oil tank. No contamination noted.	True	0.497
97 Longview Avenue	0200263	4/8/2002	5/13/2002	Tank Failure	Tank and 12.1 tons of soils removed.	True	0.5
97 Longview Avenue	0200712	4/18/2002	4/22/2002	Tank Failure	Spill is duplicate report. See spill 0200263.	True	0.5

The majority of the records are tank test failures with no releases/minor releases, historical, and have been closed by the NYSDEC. However, several records of concern were noted during this review they include three which occurred at the White Plains Hospital at 41 East Post Road. These LTANKS records did not meet cleanup standards and involve off-site adjacent subsurface impacts. There is also potential for additional off-site impacts from LTANKS records. There are significant records within close proximity to the project site.

10. Bulk Storage Sites

The NYS Petroleum Bulk Storage database contains information pertaining to facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons, including aboveground (AST) and underground storage tanks (UST). The NYS PBS database also includes information pertaining to Major Oil Storage Facilities (MOSF), which are onshore facilities or vessels with petroleum storage capabilities of 400,000 gallons or greater. Additionally, the chemical bulk storage database (CBS), which consists of storage of hazardous chemicals (defined by 6 NYCRR Part 597) in quantities greater than 185 gallons or any size UST, was searched. The target property was not identified on the list. A total of 52 listings were identified within 0.25 miles from the target property; however, only 6 listings were identified within the minimum ASTM search distance from the target property, which is limited to the target property and adjoining properties.

- Firestone Complete Auto Care (60 East Post Road - EDR Map ID: 16): Target property. This site has an active PBS registration (3-801814). The site contains the following ASTs: 001: 500 gallon motor oil, 002: 285 gallon waste/used oil, 003: 120 gallon motor oil, 004: 120 gallon motor oil, 005: 120 gallon lube oil, and 006: 120 gallon motor oil.

- East Post Road Gasmart, Inc. (34 East Post Road – EDR Map ID 12) – This record is located on the target property. This site is an active UST site with the following

tanks currently in service: 001: 10,000 gallon gasoline/ethanol, 002: 10,000 gallon gasoline/ethanol, and 003: 6,000 gallon diesel.

- Winbrook Housing Development (223 Dr. Martin Luther King Jr. Blvd. – EDR Map ID: 61) – A portion of the target property, this site is an active UST site. The following tanks are currently in service: 001: 20,000 gallon fuel oil and 002: 20,000 gallon fuel oil. It was not ascertained if these tank locations are within the area being considered for purchase by the City of White Plains.

- White Plains Hospital (41 East Post Road EDR Map ID: 23): The White Plains Hospital is located 0.01 mile south of the Target Property and is topographically higher. The site is active with both UST and AST registrations. Tanks that are in service include: 11: 15,000 gallon diesel UST, 5A: 5,000 gallon diesel UST, 10: 70 gallon diesel AST, 12: 300 gallon diesel AST, 13: 250 gallon diesel AST, 1A: 8,000 gallon fuel oil AST, 1D: 660 gallon diesel AST, 2D: 250 gallon diesel AST, 3A: 1,000 gallon diesel AST, 4: 3,800 gallon fuel oil AST, 7: 275 gallon diesel AST. At least one former UST was closed in place

- 71 East Post Road (EDR Map ID: 44) – Operated by Post Development Corp., this site is designated as unregulated. It is located 0.019 mile from the target property, adjoining on the southeast corner. A 2000 gallon tank was removed from the site; product was not noted. Potential residual contamination was removed during the tank pull. Therefore, this record is not of environmental concern to the target property.

- Power Test/Getty (26 East Post Road - EDR Map ID: 7) – Located 0.002 mile from the target property at the southwest corner, this site is currently unregulated. The site formerly contained three large capacity USTs for gasoline storage which were removed from the site. Potential residual contamination was removed during the tank pulls. Therefore, this record is not of environmental concern to the target property.

11. NYS Spills

The NYS Spills database contains records of chemical and petroleum spill incidents reported to NYSDEC. The target property was not identified in this database. The EDR report identified 54 NY SPILLS listings within 0.125 miles from the target property.

NY SPILLs Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
42-44 East Post Road	0011872	2/2/2001	2/5/2001	Other	Apartment complex over ordered oil, leading to a release of 70 gallons of fuel oil. Spill was contained and cleaned with no release to the environment.	True	Target Property
Rakoff Realty – 42 East Post Road	0011871	2/2/2001	10/11/2005	Unknown	25 gallon overfill cleaned up using Speedi-dry. Spill record mentions UST removal (SPILL ID:0011872)	False	Target Property
Manhole 3471 – 44 East Post Road	9812506	1/10/1999	1/10/1999	Unknown	One quart of unknown oil was discovered in 50 gallons of water. Cleanup occurred.	True	Target Property
Citgo – 34 East Post Road	9516188	3/18/1996	11/12/1997	Equipment Failure	Tank overfilled due to tilt. Cleaned up.	True	Target Property
BP Gas – 34 East Post Road	1509193	12/9/2015	12/9/2015	Equipment Failure	Caller was concerned that pump overfill protection was not functioning properly after two incidences where tank overfilled. DEC inspected and found no problems.	True	Target Property
BP Gas – 34 East Post Road	1608924	9/1/2014	Not Reported	Unknown	Contamination was identified off site emanating from this site. DEC filed order on consent for removal of tanks and remediation; RP refusal due to the City of White Plains taking property under imminent domain.	False	Target Property
Former Northville Gas Station – 34 East Post Road	9406684	8/16/1994	6/30/1990	Unknown	Test pits showed readings on PID and odor in soil.	True	Target Property
STS Tire Service – 60 East Post Road	0804645	7/23/2008	9/26/2008	Equipment Failure	Contamination identified while removing hydraulic lifts. Environmental cleanup crew submitted closure report.	False	Target Property
Manhole 9169 – 169 Lexington Avenue	0311437	1/8/2004	1/9/2004	Unknown	Record states 10.1 ppm PCB with “no smoke, fire, or anything else”.	True	0.001
Closed Getty Gas Station – 26 East Post Road	9713110	2/24/1998	8/21/2017	Equipment Failure	Contamination found during investigation. Excavation decided against; dual phase hi-vac system installed and operated from 2001 -2007. Groundwater monitoring occurred with request to reduce wells in 2009 due to meeting or below groundwater standards. Additional sampling in 2016 found contamination on 22 East Post Road (separate spill number).	False	Target Property 0.002

NY SPILLs Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
In front of One Stop Deli – East Post Road	8900729	4/24/1989	4/24/1989	Human Error	Backdoor of truck left open and a drum fell out. Small amount of product released to pavement and cleaned up.	True	0.005
22-24 East Post Road	1101872	5/19/2011	Not Reported	Unknown	Traces of diesel picked up from adjacent former spill site.	False	0.007
22-24 East Post Road	1607837	11/10/2016	2/23/2018	Unknown	Free product discovered in monitoring well related to site contamination from nearby location – 26 East Post Road. Tank was pulled revealing contamination. No further information given. Reference to spill 17-00425.	False	0.007
Manhole 7278 – East Post Road	9101572	5/9/1991	6/10/1991	Unknown	Film of gas noted in manhole. Con-Ed was supposed to send test results to DEC.	True	0.009
John Bowen Garage – 176 S. Lexington Avenue	9012850	3/15/1991	5/6/1991	Equipment Failure	Adjacent homeowner's fill line was found to be leaking into garage. Luzon Environmental hired to clean up.	True	0.01
White Plains Hospital – 41 East Post Road	0900120	4/3/2009	4/4/2017	Unknown	An oil tank was found to be grossly leaking. Initially, the tank was to be abandoned in place and cleanup consisted of regular vacuuming. Tank finally removed around 2015 with another tank.	False	0.01
White Plains Hospital – 41 East Post Road	0613444	3/14/2007	4/5/2007	Equipment Failure	Heat exchange failed on tank, leading to oil release. No release to environment. Castleton Environmental cleaned up.	False	0.01
White Plains Hospital – 41 East Post Road	2003833	8/6/2020	Not Reported	Equipment Failure	Contamination discovered from closed in place tank. Vacuum truck removed product. Tank could not be removed due to placement under foundation.	False	0.01
White Plains Hospital – 41 East Post Road	8800316	4/11/1988	5/3/1988	Equipment Failure	Truck backed into loading area and ripped open saddle tank. Cleanup occurred.	True	0.01
White Plains Hospital – 41 East Post Road	0803913	7/3/2008	7/7/2008	Equipment Failure	Material released from elevator into parking area. Hospital staff and fire department cleaned up.	False	0.01
White Plains Hospital – 41 East Post Road	0504642	7/18/2005	5/23/2006	Other	Flooding in basement cause residual oil to mix with water. Minor sheen. Tradewinds Environmental cleaned up.	True	0.01
White Plains Hospital – 41 East Post Road	9910974	12/15/1999	1/2/2005	Unknown	12 gallon overfill of oil during delivery. Record closed due to age.	False	0.01
White Plains Hospital – 41 East Post Road	1105346	8/10/2011	4/4/2017	Unknown	Spill related to piping leaks from two closed tanks. Ongoing remediation with understanding it will not be pristine.	False	0.01

NY SPILLs Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
Manhole 9169 – S. Lexington Avenue	9906715	9/6/1999	9/6/1999	Unknown	Minor oil spill to 500 gallons of water. No further information given.	True	0.014
White Plains Hospital – 41 East Post Road	0206489	11/14/2001	10/29/2003	Human Error	<1 ounce of mercury spilled and cleaned up.	True	0.01
Star Diner Rooftop – 66 ½ East Post Road	8808788	2/9/1989	2/10/1989	Deliberate	5 vials of blood were found on the rooftop. Site next to methadone clinic.	True	0.015
Apartments – 159 South Lexington Avenue	1610459	2/20/2017	2/21/2017	Equipment Failure	Raw sewage spilled onto streets due to clogged line.	False	0.018
Getty – 11 East Post Road	8603012	8/5/1986	8/26/1986	Deliberate	Deliberate discharge of contaminated water to storm sewer system.	True	0.036
Getty – 11 East Post Road	1705804	9/13/2017	7/20/2018	Other	Spill opened for "historical testing."	False	0.036
Getty – 11 East Post Road	0513284	2/17/2006	8/9/2006	Equipment Failure	Dispenser malfunctioned and was shut down for repairs.	True	0.036
Getty – 11 East Post Road	0512391	1/25/2006	1/31/2006	Equipment Failure	Less than an ounce of gasoline spilled due to faulty, dispense; to be replaced.	True	0.036
Getty – 11 East Post Road	0711111	1/21/2008	1/21/2008	Unknown	Less than 1 gallon spilled and cleaned up.	True	0.036
Getty – 11 East Post Road	0603141	6/21/2006	11/3/2006	Equipment Failure	No spill; fuel line repair.	True	0.036
Getty – 11 East Post Road	0713025	3/10/2008	9/26/2008	Equipment Failure	Leak detected in underground lift. Lift was removed and soils excavated.	True	0.036
Getty – 11 East Post Road	9710575	12/12/1997	7/20/2018	Equipment Failure	Leaking underground line lead to contamination of soil. Remedial system was installed (vacuum system). Ran continually and biosolve injections occurred in 2014. Two USTs were discovered and removed in 2018.	False	0.036
Getty – 11 East Post Road	0512154	1/20/2006	8/9/2006	Equipment Failure	Dispenser leak – unit was replaced.	True	0.036
Getty – 11 East Post Road	0807262	9/29/2008	9/29/2008	Equipment Failure	Customer's vehicle leaked small amount of gasoline to pavement and was cleaned up.	False	0.036
White Plains Hotel – Maple Avenue	9003827	7/6/1990	7/10/1990	Unknown	Black smoke reported from chimney.	True	0.036
White Plains Beverage – 234 Martin Luther King, Jr. Boulevard	1304060	7/15/2013	11/27/2013	Equipment Failure	UST tank and contamination discovered during Phase I investigation. Tank and soils were removed.	True	0.048
Post Road and Davis Avenue	9908220	10/6/1999	11/19/1999	Unknown	Odor noted during excavation – believed to be from adjacent Getty station. Covered under spill 9710575.	True	0.048

NY SPILLs Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
White Plains Avenue – East Post Road and Davis Avenue	9401229	4/26/1994	5/5/1994	Equipment Failure	Tank gauge malfunctioned causing minor release of fuel onto concrete.	True	0.048
Little Mount Zion Holy Church – 230 Dr. Martin Luther King, Jr. Boulevard	1006496	9/15/2010	11/15/2010	Unknown	Contamination encounter 8 feet bgs during excavation. Reportedly smelled like gasoline.	False	0.049
135 South Lexington Avenue	2001101	5/19/2020	6/26/2020	Equipment Failure	Two tanks found during Phase I investigation. Both tanks were removed along with 18.97 tons of contaminated soil.	False	0.063
Biscardi Cleaners – 201 South Lexington Avenue	0013010	3/12/2001	3/12/2001	Equipment Failure	Gauge on tank failed. Spill was cleaned up and gauge repaired.	True	0.063
134 South Lexington Avenue	0008680	10/25/2000	3/6/2005	Unknown	Hydraulic fluid released from elevator. Released to storm sewer.	False	0.067
El Paisa Auto Body – 177 Orawamupum Road	9800944	4/2/1998	6/24/1998	Housekeeping	Waste oil spilled around waste oil drums. One yard of affected soil removed.	False	0.068
Trinity Methodist Church – 130 South Lexington Avenue	0610953	12/29/2006	6/25/2007	Human Error	Fuel delivered to wrong line. Fuel oil company cleaned up.	True	0.074
8 Longview Avenue	0712395	2/25/2008	7/16/2008	Human Error	Overfill of oil tank. Environmental cleanup crew responded.	True	0.078
Bethel Baptist Church – 1 Fisher Court	1011299	2/10/2011	4/18/2011	Equipment Failure	Soil and groundwater contamination discovered during tank pull. Approximately 40 tons of impacted soils were removed.	False	0.079
126 South Lexington Avenue	1607231	10/24/2016	10/24/2016	Equipment Failure	Loss of 15 gallons of hydraulic fluid to concrete/asphalt. Cleaned up with no contamination.	False	0.081
126 South Lexington Avenue	1600183	4/6/2016	4/8/2016	Equipment Failure	Two tanks were removed. No contamination was identified.	False	0.081
Gas Station – 124 South Lexington Avenue	0509358	11/4/2005	3/3/2006	Other	Contaminated soil encountered during excavation.	True	0.084
Gas Station – 124 South Lexington Avenue	0611782	1/24/2007	10/12/2012	Unknown	After fuel delivery to station, gasoline was witnessed gushing from dispensers and vent pipes. Environmental cleanup crew responded and deployed boom and vacuum. Tanks were scheduled to be removed and remediation completed in stages.	False	0.084
Lincoln Mercury – 25 West Post Road	0600932	4/24/2006	7/30/2006	Deliberate	Waste oil tank overfilled.	True	0.099

NY SPILLs Records							
Address	**Spill ID**	**Date**	**Date Closed**	**Cause**	**Details**	**Cleanup Met Standards?**	**Distance to Project Site (Miles)**
Lincoln Mercury – 25 West Post Road	9408341	9/21/1994	8/15/2017	Unknown	Found contamination during investigation. Spill closed under 0600932.	False	0.099

Nine NY Spill records were identified with the same addresses as the target properties. Five of these spills are closed meeting cleanup standards, three have not met cleanup standards. There is a history of spills occurring at 26, 34, 42, and 60 East Post Road. These properties all have NY Spill records that had spills administratively closed by NYSDEC but classified as not meeting cleanup standards. The 34 East Post Road remains an open spill case and is under consent order from the NYSDEC to remove and remediate contamination caused by the former gas station on site, and the NY Spill record references offsite contamination migration. Contamination was identified at the closed Getty gas station at 26 East Post Road and may have migrated to adjacent properties. Lastly, the property at 60 East Post Road has a spill that has also not met cleanup standards. The spill record indicates contained soils was present in the vicinity of hydraulic lifts. No record of remediation is included in this spill record. Two NY Spill records for 42 East Post Road indicate fuel oil overfills, both spill cases are closed, but one of the cases was closed not meeting cleanup standards. Spill records at these target properties indicate a likelihood of encountering residual soil contamination. Additionally, due to the nature of the target properties and the location within an urban center with numerous spills and historic releases occurring on adjacent parcels subsurface soil contamination may be present at any of the target properties.

12. State Engineering/Institutional Controls Database

The State list of engineering controls and institutional controls is managed by the NYSDEC. This database is used to store information on engineering and/or institutional controls required at a facility as a result of a state regulated action. The target property is not listed in this State database.

13. State Brownfield Sites Database

The State list of Brownfield Sites is managed by the NYSDEC. The list contains information on properties that are or have been involved in the New York State Voluntary Cleanup Program (VCP), Brownfield Cleanup Program (BCP), or Environmental Restoration Program (ERP). The target property was not identified in these listings; however, five listings were identified within the minimum ASTM search radius (0.5 miles) from the target property.

- Post Road Corridor, 77 West Post Road (EDR Map ID 207): Vacant land to be redeveloped. Site consists of 10 separate parcels that were used as a dry cleaners, a gas station, and automobile repair shops. Hydraulic lifts and multiple USTs with associated contamination have been removed at the site starting in 2005. Primary contaminants of concern include chlorinated volatile organic compounds, petroleum related compounds, and metals. Unlikely for the public to come into contact with contaminated soils or groundwater; however, potential exists for soil vapor intrusion and is recommended to be assessed on site. No evidence of contamination migrating off-site, therefore the record is not of concern to the target property.
- Young and Coal Lumber Yard, 55 Bank Street (EDR Map ID 303): The Young Coal and Lumber yard was established in 1885 and contained a mill, several small sheds, coal and lumber storage areas, and railroad sidings. By 1911, the property was used to manufacture sashes, blinds and trim, and for the storage of grain, fertilizers and feed. The site was razed in 1974, and has served as a parking lot since. In November of 2016, the site achieved Track 1 soil cleanup status. In order to achieve Track 1 soil cleanup status, the entire site was excavated to a depth of 26 feet to remove all surface and subsurface soils. The primary concern with the site was the presence of inorganic metals, including mercury, copper, lead and zinc. The EDR report indicates that the adjacent parcels were not impacted by the metals contamination, and the metals concentrations in the on-site groundwater are in compliance with NYS drinking water standards based on the laboratory analysis of filtered groundwater samples. It is not expected that this site would have an environmental impact on the target property.
- 221 Main Street (EDR Map ID 359): The location reported as 221 Main Street is part of a redevelopment project which includes many tax parcels. Historically, the site contained a total of 10 leaking USTs that contributed to the detected contamination at the site. As of December 19, 2006, a final engineering report was approved indicating that the site remedial activities were completed, and that a track 1 cleanup has been achieved. The site was originally listed due to the presence of petroleum related compounds, including VOCs and polycyclic aromatic hydrocarbons (PAHs). Both the soil and groundwater were found to be contaminated. An interim remedial measure (IRM) that included the removal of nearly all the on-site soil contributed to the cleanup. It is not anticipated that this site would have an environmental impact on the target property.
- Hamilton Green, 200 Hamilton Avenue (EDR Map ID 370): The Hamilton Green site is a 3.74 acre site that historically contained private residences, a candy manufacturer, and two gasoline stations. The gasoline stations operated sometime during the period of 1930 to 1950, and a mall was constructed on the site in 1972. A dry cleaner purportedly operated out of the mall. Information submitted with the Brownfield Cleanup Program application regarding site conditions is currently under review by the NYSDEC. The site is topographically lower and located northeast of the target property. Groundwater flow at the site is directed to the southwest. However, this site is located approximately 3,000 feet away and not of concern to the target property.

- White Plains Manufactured Gas Plant, 9 New Street and 12 Water Street (EDR map ID 386): Coal tar was discovered in the subsurface soil during remedial investigation. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). This contamination appears to have migrated south, west and vertically down from these structures. A cutoff wall and monitoring wells were installed in 2004-2005. Routine monitoring of the wells showed no significant accumulation of contaminants and sampling was reduced in 2006. A site management plan was developed and in-situ treatments occurred from 2008-2010. Given the installation of the cutoff wall and remedial treatments, it is unlikely that contaminants from this site have migrated to the target property.

  The National list of Brownfield projects is managed by the Environmental Protection Agency. This database is used to store information on properties addressed by Cooperative Agreement Recipients and Targeted Brownfield Assessments. There are no VCP listing identified within the minimum ASTM search radius (0.5 miles) from the target property.

14. EDR Orphan Summary

The EDR report provides a listing of unmapped or "orphan" sites that are not included on the EDR maps due to incomplete address information. Four records were reported; however, only one record is located within 1 mile of the target property.

The White Plains Hospital, located at the intersection of East Post Road and Davis Avenue, is listed in the U.S. AIRS database. The database is governed by the National Emission Standards for Hazardous Air Pollutants (NESHAP). No violations were reported for the hospital and therefore the site is not of environmental concern to the target property.

15. Review of Agency Files

Requests for review of NYSDEC files and the Westchester County Health Department files under the Freedom of Information Law (FOIL) were submitted on May 17, 2021 and June 1, 2021 via an online FOIL request form. A response from the NYSDEC indicated they do not keep the records for Westchester County, those records are kept by the Westchester County Health Department. A response from the Westchester County Health Department has not been received at this time.

4.2 Physical Setting Sources

The following physical setting sources were reviewed:

Current USGS Topographic Quadrangle Maps 7.5-minute White Plains quadrangle for the years 1892, 1893, 1899, 1932, 1038, 1944, 1957, 1967, 1979, 1994, and 2021.

The USGS topographic map is the only physical setting source that is required to be reviewed by ASTM Standard E 1527-13.

The initial view of the site in 1892 depicts the site as moderately sloped to the southwest, peaking at about 180 feet above mean sea level (amsl). A roadway is depicted in the eastern 1/3 of the target property. The City of White Plains appears well developed, with a railroad ¼ mile to the northwest of the target property and city blocks depicted with various unlabeled structures. Significant changes were not noted in the maps until 1932. The target property appears to have been graded flat and consists of two city blocks lined with multiple small structures. No further major changes beyond typical urban sprawl are noted until 1957, when the White Plains Hospital (labelled "General Hospital") is shown along the southern border of the target property. By 1967, the crossroads previously shown bisecting the target property are no longer shown. No further changes were noted until 1994, when an access road from East Post Road is shown connecting Dr. Martin Luther King Jr. Boulevard through the target property. No further significant changes were noted in the 2012 map. Copies of the historic topographic maps are included in Attachment 2.

4.3 Historical Use Information on the Property

The historical use of the site was identified through a review of aerial photographs, City Directory search results, and Sanborn Fire Insurance Maps.

1. Aerial Photographs

Aerial photographs (ortho-imagery) of the target property and surrounding area from 1941, 1949, 1953, 1958, 1962, 1964, 1971, 1974, 1985, 1991, 1994, 2006, 2009, 2013, and 2017 were reviewed for this report, as provided by Environmental Data Resources, Inc. (EDR). No historic land uses or other environmental issues were noted for the project site during this historic aerial photography review beyond the target properties urban nature. Aerial photographs are provided in Attachment 3.

Year	Description
1941 – 1949	In 1949 the high-rise buildings north of the target properties were not yet constructed and appeared to be dwellings. The remaining properties are developed with potentially commercial buildings.
1953 - 1964	The high-rise buildings north of the target properties were constructed prior to 1953. Remaining land use at the target sites appears to be commercial buildings with building configuration similar to current building layout.
1971 - 1985	Few changes are noted on the target properties.
1991-1994	Imagery is difficult to see, but no significant changes are noted.
2006-2017	No significant changes are noted, land use and building configuration on the target properties is similar to current.

2. City Directory Search Results

City Directory coverage was provided by EDR, Inc. for the years 1972, 1977, 1982, 1987, 1992, 1995, 2000, 2005, 2010, 2014, and 2017.

The majority of the listings are commercial. Of note, the target property includes the Firestone Store (60 East Post Road) and Post Davis Service Station (34 East Post Road) in 1972 and 1977. The Firestone/tire store is still active in the directory in 1982, 1987, 1992, 1995, 2000 (as the Ramapo Discount Tire Store), 2010, 2014 (As the STS Tire Center), and 2017.

34 East Post Road is listed as a gasoline station and 42 East Post Road is shown as an office building with several businesses listed in 1987. No listing is given for 34 East Post Road in 1992 and 42 East Post Road is shown as a limousine/detailing company.

Thirty-four East Post Road is again listed in 1995 as the Marianina Oil Corporation while 42 East Post Road includes a brake servicing shop, detailing shop, and a surgical center. By 2000, 34 East Post Road is identified as a Citgo Station and the auto service shops are no longer at 42 East Post Road. The Citgo was also listed in 2005 and 2010 but switched to the East Post Road Gasmart in 2014. In 2017, it was again listed as Citgo and Gasmart.

The City Directory listings are included as Attachment 4 of this report.

3. Sanborn Fire Insurance Maps

Sanborn Fire Insurance Maps coverage was available for the following years and are summarized in the table below: 1900, 1905, 1911, 1930, 1942, 1950, 1987, 1989, 1990, 1992, 1993, 1994, 1995, 2002, 2003, and 2004. The maps are available for review in Attachment 5 of this report.

Year	Description
1900 -1905	Buildings are not depicted west of Brookfield Street. Remaining land use on the target properties appears to be dwellings.
1911	By 1911, the first small structure of the White Plains Hospital has been constructed. The hospital is shown with a coal vault.
1930	26 East Post Road has 3 gasoline tanks depicted and is labeled a filling station. Remaining target property land use appears to be dwellings. One block to the northeast contains multiple stores as well as two auto repair garages and a pharmacy. The White Plains Hospital has increased in size. It is indicated the hospital switched to steam heat.
1942	Significant development has occurred. The White Plains Hospital is again expanded. A large structure labelled “Richard Manney” is shown on the target property. Many structures are not labelled due to their concentrated nature.

Year	Description
1950	None of the earlier dwelling structures remain on the target property. Of note, 5 large star shaped structures have been constructed partially on and just north of the target property. These are labelled the Winbrook Apartments. 223-225 Dr. Martin Luther King Blvd property is now parking, recreational land or access areas associated with the Winbrook Apartments. 26 East Post Road and 34 East Post Road are labeled filling stations. Remaining target property structures appear to be commercial.
1987 - 2004	No significant changes were noted in the 1987 to 2004 maps beyond the continued expansion of the White Plains Hospital across East Post Road.

4.4 Historical Use Information on Adjoining Properties

The historical use of adjacent properties is identified through a review of aerial photographs, City Directory search results, and Sanborn Fire Insurance Maps. It appears the target property and adjacent areas were initially residential and became largely commercial by the 1950s.

The target properties in particular have been long term sites of a filling station, tire sales center, and auto repair shop. Additionally, the White Plains Hospital is immediately adjacent to the site and has expanded multiple times over the years.

5.0 SITE RECONNAISSANCE

Site reconnaissance took place on May 12, 2021. Full access was only provided for two of the sites, the other three sites were not accessible during the survey, but exterior inspections were conducted from public access areas. The site reconnaissance consisted of walking through the entire building where access was available, and walking the perimeter each parcel to the accessible property lines. Site photographs are included as Attachment 6 of this report.

5.1 Site Observations

26-28 East Post Road

This property is currently a vacant lot. The former use of this parcel was not easily established in the field. The vacant lot consists of a grassed and weedy areas with small portions of a concrete foundations or pads and asphalt surfaces near the southern and eastern portions of the parcel nearest East Post Road and Brookfield Street. A 6 foot chain link security fence surrounds the property and entry to the interior of the parcel was not completed during the initial site visit.

34 East Post Road

This property is a former fueling station, currently it is semi-vacant and not in use. This property consists of a fueling station canopy, concrete and asphalt pads, parking areas with scattered plastic tarps, cinder blocks, old wires, soil and asphalt piles, a 55-gallon drum, safety cones, with some localized grassy areas. A wooden shed is located at the northeast corner of the parcel. A six foot chain link security fence surrounds the property the interior of the site was not accessed during the initial site visit.

42 East Post Road

There is one building on the 42 East Post Road property that house several commercial businesses. Businesses within this parcel include: OneSource Homecare Pharmacy, White Plains Surgical Supply, Dol Ez Money Transfers, and an unknown store front which appears to be empty. Interior access to these buildings was not available for the site visit. Only the outside of the buildings were observed during the site visit. Two large garage doors/loading areas are located in the eastern and western portions of the building.

60 East Post Road

This property consists of a single automotive business; Firestone Complete Auto Care. A two story building is located on the parcel. The building and outside property was accessed during the site visit.

The eastern portion of the building consists of an automobile repair shop. Several hydraulic lifts are located within the shop area. Numerous 55-gallon drums are located within the shop area.

Stickers attached to these drums indicate some are used for used oil filters. A large used motor oil container is located at the northeast corner of the shop area. Four large new oil containers are stored beside the used oil container. Additionally numerous cardboard coated oil storage containers are located on a shelving unit along the northern wall of the shop. A natural gas furnace which is located along the ceiling provides heat for the shop. The eastern portion of the shop area is mainly a tool storage area with some garbage cans, computer, shelving containing new oil filters. The shop area was inspected and contains hydraulic lifts, waste oil storage bins, compressors, heating systems, chemical storage areas, and part storage areas. Chemical material storage areas were clean and chemicals appeared to be properly stored and appropriately marked. Some minor staining was observed on the concrete floor of the shop.

To the west of the shop behind the showroom is a compressor/battery room. Several shelves shore numerous batteries in this room. Several air compressors are located in this room. Immediately adjacent to this room is a storage room, this storage area has several shelves with various products including canister sprays/lubricants used in automotive repairs as well as individually packaged automotive parts for resale. A break room containing tables and chairs is located immediately west of the storage room. The showroom entry door is located immediately west of the shop. The showroom contained tables/desks, marketing materials, product samples, with carpeted floors. Two restrooms are located to the north of the showroom.

The upstairs portion of the building was also accessed during the on-site inspection. A storage room with numerous cardboard boxes is located in the upstairs portion of the building. This area also duct work for the HVAC system running through it. Aside from these items much of this storage area was empty. Upstairs there was also an open area which overlooked the shop.

Additionally, the basement was inspected during the site visit. The basement is located under the shop portion of the building. The basement was a partial basement and did not extend the full footprint of the building. A sump or floor drain exposed to soil was observed in the basement. There was a small amount wet and possibly oily staining observed on the basement floor leading to the sump and surrounding the sump. The source of the staining was unknown. Odors were not noted at the sump location. A natural gas hot water tank was observed in the basement. Water and wastewater piping was noted traveling through the basement.

The lot outside of the building consists of asphalt parking areas, concrete sidewalks and localized grassed areas. The eastern portion of the exterior consists of a sidewalk while the northern portion of the parcel consists of a sidewalk and asphalt parking area. An employee parking area is located immediately west of the showroom. Two trash dumpsters are located in the northern portion of the parking area. Some pallets and plastic trash items were located near the dumpsters. Staining or leaks from the dumpsters were not observed. Several pieces of household trash items (plastic and cardboard) were noted along the edges of the parking area.

223-225 Dr. Martin Luther King Jr. Blvd

This property primarily consists of an asphalt parking lot with concrete curbs, street lamps, localized grassy areas and intermixed deciduous and conifer trees. Chain link fencing and access control structures are located along the western portion of the property along South Lexington Avenue and along the southeastern extent of the parking lot. Numerous cars were parked in the parking lot during the on-site survey. Minor pavement staining was observed along some parking spaces in the parking lot. Several stormwater drains are located within the parking area. Staining was not observed in the catch basins of these stormwater drains. Additionally, some household trash items were seen along the parking lot in grassed areas. Trash items included cardboard, plastic and glass bottles, tires, and plastic bags. The central portion of the parcel is a construction staging area associated within a building project that is located to the north of the parcel. Currently there are several mobile construction field offices set up within a fenced off construction area. This portion of the site was not accessed during the site visit, due to the active construction project.

5.2 Adjoining Property Observations

Adjoining properties were visually examined from public access right-of-ways to make a cursory assessment of the current land use and potential for RECs that may impact the site.

26-28 East Post Road

North – The 223-225 Dr. Martin Luther King Jr. Blvd parcel is located to the north of the site.

South – The abutting property to the south is the East Post Road ROW (no permanent structures on site), and farther south is White Plains Hospital.

East – The adjoining property to the east is the Brookfield Street ROW (no permanent structures on site), and farther east is the 34 East Post Road parcel (a former gasoline fueling station).

West – The adjoining property to the west is 22-24 East Post Road. This parcel has a three story building which has the Brothers One Stop Deli at the street level and residential housing above.

34 East Post Road

North – The 223-225 Dr. Martin Luther King Jr. Blvd parcel is located to the north of the site.

South – The abutting property to the south is the East Post Road ROW (no permanent structures on site), and farther south is White Plains Hospital.

East – The adjoining property to the east is the 42 East Post Road parcel (with a one single story building with several commercial business located at street level).

West – The adjoining property to the east is the Brookfield Street ROW (no permanent structures on site), and farther west is the 26-28 East Post Road parcel.

42 East Post Road

North – The 223-225 Dr. Martin Luther King Jr. Blvd parcel is located to the north of the site.

South – The abutting property to the south is the East Post Road ROW (no permanent structures on site), and farther south is White Plains Hospital.

East – The adjoining property to the east is the 60 East Post Road parcel. This parcel has one two story building which is an automotive repair shop (Firestone Complete Auto Care).

West – The adjoining property to the west is the 34 East Post Road parcel (once a former gasoline fueling station).

60 East Post Road

North – The 223-225 Dr. Martin Luther King Jr. Blvd parcel is located to the north of the site.

South – The abutting property to the south is the East Post Road ROW (no permanent structures on site), and farther south is White Plains Hospital.

East – The adjoining property to the east is the Winchester Street ROW (no permanent structures on site), and farther east is the 66 East Post Road parcel. This parcel has a three story building which has the Star Diner at the street level and what looks to be residential housing above.

West – The adjoining property to the west is the 66 East Post Road parcel. This parcel has a three story building which has the Star Diner at the street level and what looks to be residential housing above.

223-225 Dr. Martin Luther King Jr. Blvd

North – The remainder of the 223-225 Dr. Martin Luther King Jr. Blvd is located north of the site. There are three residential high-rises associated with the White Plains Housing Authority. On-site amenities at the site include playground, basketball court, and office buildings. During the initial site visit there was a large building construction occurring within the parcel.

South – There are numerous parcels located to the south, they include: 60 East Post Road, 42 East Post Road, 34 East Post Road, 26-28 East Post Road, 22-24 East Post Road, 18-20 East Post Road, 14-16 East Post Road, 12 East Post Road, and 2-4 East Post Road. There are numerous buildings along these parcels. Commercial businesses located on the street and residential properties on the upper levels of much of these buildings.

East – The remainder of the 223-225 Dr. Martin Luther King Jr. Blvd is located east of the site.

West – The abutting property to the west is the South Lexington Avenue ROW (no permanent structures on site), and farther west are several single story commercial businesses. Business

present include: smoke shop, convenient store, and a restaurant. To the west of these businesses is mainly residential housing.

5.3 Interviews and Questions

26-28 East Post Road

B&L sent an ASTM Environmental Site Assessment Transaction Screen Questionnaire (E1528-14-ASTM) to David Cooper of Zarin & Steinmetz, to provide Owner information. Michael Taub an owner/member of the 26-28 East Post LLC completed the Owner information. Mr. Taub indicates the property was once a gas station. Mr. Taub also indicates he has been informed of the past existence of hazardous substances or petroleum products in respect to the site. Mr. Taub indicates the property has been used for an industrial use in the past but does not elaborate. The ASTM Transaction Screen Questionnaire is in Attachment 7. B&L did not conduct an on-site interview during the site inspection on May 12, 2021.

34 East Post Road

B&L sent an ASTM Environmental Site Assessment Transaction Screen Questionnaire (E1528-14-ASTM) to Michael Zarin of Zarin & Steinmetz, to provide Owner information. Mr. Zarin has not yet completed the owner interview. B&L did not conduct an on-site interview during the site inspection on May 12, 2021.

42 East Post Road

Per the City of White Plains directive, B&L did not have direct communication with or send an ASTM Environmental Site Assessment Transaction Screen Questionnaire (E1528-14-ASTM) to owners of 42 East Post Road. B&L did not conduct an on-site interview during the site inspection on May 12, 2021.

60 East Post Road

B&L sent an ASTM Environmental Site Assessment Transaction Screen Questionnaire (E1528-14-ASTM) to Scott Sanderson of Bridgestone Americas, in order to provide the owner information. Mike Tharpe an Environmental Due Diligence Specialist for Bridgestone Retail Operations completed the Owner information. In the description Mr. Tharpe indicates the property is currently used for as an automotive repair business. Mr. Tharpe also indicates that the property was possibly an old gas station because of the presence of fuel pumps on old drawings. The drawings do not show the location of UST's, vent pipes, or fill pipes. Mr. Tharpe indicates that used automotive batteries and 55-gallon drums of waste materials (oil and lubricants) were stored on-site prior to being disposed of by a vendor. The ASTM Transaction Screen Questionnaire is in Attachment 7. B&L conducted an interview with Mr. Ramone Garcia during the May 12, 2021 site visit. Mr. Ramone, is the area manager, he confirmed the presence of various bulk oils, coolants, and oil wastes. During the site inspection, Mr. Garcia referenced his

lack of overall knowledge of the history of the site. Mr. Garcia did provide access to all portions of the building.

223-225 Dr. Martin Luther King Jr. Blvd

B&L sent an ASTM Environmental Site Assessment Transaction Screen Questionnaire (E1528-14-ASTM) to Mack Carter of the White Plains Housing Authority, to provide Owner information. Mr. Carter has not yet completed the owner interview. B&L did not conduct an on-site interview during the site inspection on May 12, 2021.

6.0 FINDINGS

The following findings were made as a result of the site reconnaissance and review of available information:

- The target properties are located within the urban center of the City of White Plains, NY.
- There are multiple historic fueling stations and automotive repair shops within the target parcels.
- The facility at 60 East Post Road is an active automotive repair shop. The facility is used for routine vehicle maintenance and repairs. Waste oil and other automotive lubricants are stored at this site. Oils, coolant, waste products from these materials were observed in both large (55-gallon drums) and small quantities (5 gallons and less) at various locations throughout the automotive repair facility. The facility has had releases from hydraulic lifts in the past.
- The parcels at 34 East Post Road and 26-28 East Post Road are both former fueling stations and are currently vacant. Both of these properties have a history of spills and subsurface contamination.
- The NYSDEC Bulk Storage Tank database indicates that three underground storage tanks are active at the 34 East Post Road site.
- The WPHA has filed a lawsuit against the current and former owners of 34 East Post Road associated with potential offsite migration of petroleum emanating from 34 East Post Road. The affected property includes 223-225 Dr. Martin Luther King Jr. Blvd.
- The property at 42 East Post Road is currently storefronts for several commercial businesses. Petroleum releases have occurred at this site associated with a former underground storage tank.
- Several documented petroleum releases have occurred at facilities surrounding the target properties.

7.0 OPINIONS

During the inspection at 60 East Post Road, minor incidental drippage was observed around some of the machinery. This incidental drippage was observed to be on epoxy coated flooring and addressed by employees using granular sorbents. Incidental drippage is considered to be a de minimus condition. B&L recommends that as a best management practice, all oil and chemical storage be provided with secondary containment (ex. spill control pallets) or have spill control kits staged adjacent to storage areas to address releases if they were to occur.

Potential oil staining was also observed in a basement sump at this facility. Further investigation of this sump appears warranted as part of an overall site investigation of soil and groundwater quality.

There are numerous data gaps due to lack of owner interviews or lack of full site inspections. It is B&L's opinion that interviews and full site inspections would not significantly change the conclusions and identified recognized environmental conditions.

File reviews with NYSDEC and Westchester County have not yet been completed due to delays at the agencies and a file review rejection at NYSDEC that caused delays. Detailed storage tank closure reports, spill reports and remedial reports may be available in agency files that contain pertinent data on environmental condition of the properties.

8.0 RECOGNIZED ENVIRONMENTAL CONDITIONS (REC)

ASTM RECs

B&L has performed a Phase I Environmental Site Assessment, in conformance with the scope and limitations of ASTM Practice E 1527-13, of the properties at 26-28 East Post Road, 34 East Post Road, 42 East Post Road, 60 East Post Road, and 223-225 Dr. Martin Luther King Jr. Blvd. Any exceptions to, or deletions from, this practice are described in Sections 1.5 and 1.6 of this report.

This assessment has revealed no evidence of recognized environmental conditions (RECs) in connection with the target properties except for the following:

26-28 East Post Road

Multiple petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases have been administratively closed, but one case was closed with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on current soil and groundwater quality have not been provided, but NYSDEC Spill Report Forms and a Remedial Investigation (RI) Report conducted at an adjacent site both indicate petroleum compounds remain present in the subsurface at 26-28 East Post Road. The RI report also references that the 26 East Post Road site may be a source area that contaminated soil and groundwater offsite to the north. Free-phased petroleum product was reported to be present at the adjoining site (22 East Post Road) and there is a potential for petroleum impacts at the adjoining site to affect the 26-28 East Post Road site.

34 East Post Road

The NYSDEC Bulk Storage Tank database indicates that three underground storage tanks are active at the 34 East Post Road site. Multiple petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases appeared to have been administratively closed, but one case was closed with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on current soil and groundwater quality on the 34 East Post Road property have not been provided, but NYSDEC Spill Report Forms and the RI Report conducted at an adjacent site both indicate petroleum compounds remain present in the subsurface at 34 East Post Road. The current land owner of 34 East Post Road is a defendant in a lawsuit where a downgradient property owner (White Plains Housing Authority (WPHA) - plaintiff) claims that petroleum contamination emanating from 34 East Post Road has impacted their property. The downgradient WPHA property affected (223-225 Dr. Martin Luther King Jr. Blvd) is a property subject to this current Phase I ESA.

42 East Post Road

Two petroleum releases at this property have been documented and reported to the NYSDEC. NYSDEC Spill Cases appeared to have been administratively closed, but one case was closed with

a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on petroleum release locations or current soil and groundwater quality at the 42 East Post Road property have not been provided, but there is a potential that petroleum compounds are present. Significant petroleum contamination at the adjacent property (34 East Post Road) has the potential to impact soil and groundwater quality at the 42 East Post Road site.

60 East Post Road

Soil contamination associated with hydraulic lifts at this property have been documented and reported to the NYSDEC. The associated NYSDEC Spill Case appeared to have been administratively closed, but with a designation of not meeting cleanup standards, indicating residual contamination remains. Detailed reports on remedial measures taken (if any) and current soil and groundwater quality at the 60 East Post Road property have not been provided, but there is a potential for petroleum compounds to be present. A small sump in the basement contains water or oil staining from an unknown source. This observation may be associated with the hydraulic lift release, or another undetermined source.

223-225 Dr. Martin Luther King Jr. Blvd

A Remedial Investigation Report completed in 2016 at this site documents that petroleum impacted soil and groundwater is present. The property owner (WPHA) is a plaintiff in a lawsuit against the current and past land owners of 34 East Post Road claiming that petroleum contamination emanating from 34 East Post Road has impacted their property in the vicinity of Brookfield Street and Building 33. A reference in the Remedial Investigation Report also indicates that contamination from 26 East Post Road has affected the 223-225 Dr. Martin Luther King Jr. Blvd property in the vicinity of Building 159. Free-phased petroleum product has been reported to be present at the adjoining site (22 East Post Road) and this property may be another source of petroleum impacts to the 223-225 Dr. Martin Luther King Jr. Blvd site. Winbrook Housing Development (223 Dr. Martin Luther King Jr. Blvd) was reported to have operated two 20,000 gallon underground fuel oil tanks. It was not ascertained if these tanks were/are located on the portion of the property subject to this Phase I ESA.

9.0 ADDITIONAL INVESTIGATION

An evaluation of soil and groundwater quality appears warranted at each of the target properties where the City of White Plains intends to conduct site improvements. The goal would be to delineate the current extent of impacted media (if any) and to compare individual contaminant concentrations to applicable cleanup criteria. Volumes of impacted soil and groundwater can be estimated and redevelopment plans can incorporate costs to handle and dispose of impacted media. An investigation of potential vapor intrusion to existing or future onsite structures may be warranted based on contaminant concentrations identified.

Owner interviews and site inspections at some of the properties were attempted but not authorized during this Phase I ESA. Environmental reports associated with releases at 26, 34, 42 and 60 East Post Road may be available, but were not provided for review during this Phase I ESA. Further attempts to coordinate with owners to conduct interviews, site inspections and provide environmental reports can be conducted and the Phase I ESA report amended to incorporate new data. Alternatively, file reviews at the NYSDEC and Westchester County Health Department can be further pursued.

The location of two 20,000 gallon underground fuel oil tanks on the 223-225 Dr. Martin Luther King Jr. Blvd should be clearly identified relative to the portion of the property subject to this Phase I ESA.

The NYSDEC Bulk Storage Tank database indicates that three underground storage tanks are active at the 34 East Post Road site and investigations should include determining if these tanks remain at the site.

10.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

The Phase I Environmental Site Assessment of the properties located at 26-28 East Post Road, 34 East Post Road, 42 East Post Road, 60 East Post Road, and 223-225 Dr. Martin Luther King Jr. Blvd. in the City of White Plains, New York, was conducted by the undersigned of Barton & Loguidice, D.P.C.

Ryan Luppino
Environmental Scientist III

Greg V. Lesniak, P.G.
Managing Hydrogeologist

11.0 QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONALS

Ryan Luppino, has provided environmental due diligence and site investigation consulting services for over 7 years. Mr. Luppino has conducted over 50 Phase I ESA reports during his career. These have included bridges, transportation corridors, commercial properties, gasoline retail stations, dry cleaners, and auto body shops.

Education: B.S. Natural Resources Management, 2013 State University of New York: College of Environmental Science and Forestry, Syracuse, NY

Greg V. Lesniak, has provided environmental due diligence and site investigation consulting services for over 25 years. Mr. Lesniak has conducted or directly supervised over 250 Phase I ESA reports during his career. These have included large industrial parks, brownfield program sites, aggregate mining facilities, gasoline retail stations, railroad maintenance yards, and coal mining facilities.

Education: B.S. Geology, 1993 State University of New York – College at Brockport
M.S. Hydrogeology, 1995 – University of Toledo

We, Ryan Luppino and Greg V. Lesniak, declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

FIGURE 1
Site Location Map



Sources: ESRI USA Topographic Basemap (2018), Westchester County Parcel Mapping (2020)

Path: K:\Projects\2000\2025011\Project\Phase I ESA Figure 1.mxd

Barton & Loguidice

1 inch = 600 feet

White Plains Phase I ESA

Topographic Target Properties Map

Westchester County May 2021 New York

Figure 1

Project No. 2025.001

FIGURE 2
Site Plan



Barton & Loguidice

1 inch = 100 feet

White Plains Phase I ESA

Aerial Target Properties Map

Westchester County May 2021 New York

Figure 2

Project No. 2025.001

ATTACHMENT 1
User Provided Documents

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 9713110

SPILL NAME: CLOSED GETTY GAS STATION **DEC LEAD:** RDBENDEL

SPILL DATE: 02/24/1998 **SPILL TIME:** 10:00 am

CALL RECEIVED DATE: 02/24/1998 **RECEIVED TIME:** 11:35 am

SPILL LOCATION

PLACE: CLOSED GETTY GAS STATION **COUNTY:** Westchester

STREET: 26 EAST POST RD **TOWN/CITY:** White Plains (c)

COMMUNITY: WHITE PLAINS

CONTACT: MARY KENNY **CONTACT PHONE:** (802) 658-2903

CONT. FACTOR: Equipment Failure **SPILL REPORTED BY:** Other

FACILITY TYPE: Gasoline Station or other PBS Facility **WATERBODY:**

CALLER REMARKS:

HISTORICAL SPILL - CALLER IS DOING SITE ASSESSMENT AND FOUND SOIL CONTAMINATION

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
gasoline	Petroleum	0 G	0 G	Soil,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
CLOSED GETTY GAS STATION	26 EAST POST RD WHITE PLAINS NY	MARY KENNEY (802) 658-2903

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead_DEC Field was "HARDY"
03/04/98 BARBARA MCDONALD (WCHD); CLOSED GAS STATION; SITE ASSESSMENT SHOWED SOIL & GROUNDWATER CONTAMINATION ABOVE STARS GUIDELINES; OWNER HAS NOT YET DECIDED ON REMEDIATION OPTION;

06/17/99 LETTER SENT BY T. GHIOSAY RE: WORK PLAN FOR SUBSURFACE INVESTIGATION AT THIS SITE.

04/20/00 TYREE CALCULATES SOIL REMOVAL TONNNAGE. EXCAVATION WOULD REQUIRE 5169 TONS. TYREE RECOMMENDS AGAINST REMOVAL.

Created On: 02/24/1998

Date Printed: 3/15/2018 Last Updated: 08/21/2017

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 9713110

SPILL NAME: CLOSED GETTY GAS STATION **DEC LEAD:** RDBENDEL

12/07/00 LETTTER SENT TO TYREE BY J. HARDY;REMEDIAL ACTION PLAN IS REQUIRED FOR THIS SITE WITHIN 3(DAYS.

01/18/01 LETTER SENT TO TYREE BY J. HARDY; PROPOSAL TO DESIGN A DUAL PHASE HI-VAC SYSTEM FOR THIS SITE IS APPROVED AND REQUIRED.

03/01/01 LETTER SENT TO TYREE BY J. HARDY; PLAN TO SHOW OFF SITE WELLS IN RELATION TO OFF SITE CONTAMINATION IS REQUIRED.

06/07/01 LETTER SENT TO TYREE BY J. HARDY; REQUEST TO EXTEND THE START UP DEADLINE FROM 6/1/01 TO 6/21/01 IS APPROVED.

6/12/03: Letter sent to P.N. Holloway, Tyree Organization Ltd. from J. Hardy. Monitor well sampling and reporting may be recduced to semi-annually.

2/23/04: Letter sent to P. Holloway, Tyree by J. Hardy. Reduce reporting to annual.

A Dual Phase High Vacuum Extraction system operated here from roughly 2001 to 2007. VEFR events on targeted wells wel continued bimonthly for all of 2008. An NFA request was submitted in Oct. 2008 and reiterated by e-mail Feb. 2009. This request was denied based upon coninued impacts to GW in MW-19. Latest QMR and denial e-mail have been added to eDo PJD Feb. 2009

A request for a reduciton in the # of MWs being sampled semi annually has been received and approved based upon contaminant concs. at or below GW standards. PJD Mar. 09

An e-mail request to conduct supplemental investigation in the area of MW-19 was approved and uploaded to eDocs. PJD Ja 2010

5-27-15 project transferred to John O'mara- RDB
8-15 Tyree submitted Remedial Action Report to JOM
8-15 submittal by first environment on behalf of WPHA
9-15 JOM response to submittal?
04-16 submittal of indoor air sampling by 1st Environmental
04-16 response from NYSDOH to First Environmental
04-14-16 project transferred to DB; sent email to Antea looking for updated information - RDB
05-12-16 email from first envir; Tyree does not have acesss to install wells? RDB
06-16- meet with Getty and then meet on site;
07-01-16 sent email approving locations for Getty; copied WPHA
07-16- Access granted; wells installed; sampling to be conducted August 1-RDB
10-18-16 "The replacement wells were installed in the excavated area in late July and a groundwater sampling event was performed on August 1. We are preparing the monitoring report to summarize those results and will be submitting it to you la this week." RDB
11-1-16 revised sample results submitted- RDB

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 9713110

SPILL NAME: CLOSED GETTY GAS STATION **DEC LEAD:** RDBENDEL

11-10-16 next round of sampling collected; MW 14 found to have LNALP; new spill 16-07837 opened for 22 East Post Rd
12-9-16 comments from 1st Environment on August sampling.
12-16 new spill opened for 34 East Post Rd- 16-08924
12-16 letter from owners rep. RDB
01-17 responded to Owners rep looking for spill closure.
01-17 Owner removed canopy. email sent to Antea asking if below was ever sampled.
01-17 response from Antea, "In response to White Plains, I'm reaching out to Ben Rieger to understood the aspects of the canopy with regards to the excavation and will replying to your e-mail." RDB
1-12-17 requested sampling under the footprint of the canopy based on excavation stopping at footings. RDB
1-23-17 As requested, antea and IPT will be on site tomorrow to conduct soil borings,
02-17 Report submitted doc canopy work, nothing found- RDB

PIN **T & A** **COST CENTER**

CLASS: A3 **CLOSE DATE:** 08/21/2017 **MEETS STANDARDS:** False

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 1608924

SPILL NAME: BP STATION- EAST POST RD GASMART **DEC LEAD:** RDBENDEL

SPILL DATE: 09/01/2014 **SPILL TIME:** 1:00 pm

CALL RECEIVED DATE: 12/20/2016 **RECEIVED TIME:** 1:00 pm

SPILL LOCATION

PLACE: BP STATION- EAST POST RD GASMART **COUNTY:** Westchester

STREET: 34 EAST POST ROAD **TOWN/CITY:** White Plains (c)

COMMUNITY: WHITE PLAINS

CONTACT: FAWZI IBRAHIM **CONTACT PHONE:** (914) 760-7721

CONT. FACTOR: Unknown **SPILL REPORTED BY:** DEC

FACILITY TYPE: Gasoline Station or other PBS Facility **WATERBODY:**

CALLER REMARKS:
Significant soil and groundwater identified off- site

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
gasoline	Petroleum			Soil,
gasoline	Petroleum			GW,

POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
Marianina Oil Corp	676 Mamaroneck Ave white plains NY 10605	(914) 403-7471

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

DEC REMARKS:

Samples collected in September 2014, December 2015, and August 2016 reveal soil and groundwater contamination down gradient of this facility. RDB

12-22-*16 Marianina Oil Corp Owner RP letter sent to both owner and operator- RDB
01-4-17 call from Papito
01-6-17 email from TBishop, "I met with the property owner, their counsel and Vince Papitto this morning at the site regarding your December 21, 2016 letter addressed to Marianina Oil Corp. I will be proposing a day of borings to determine soil and groundwater quality as well as calculate groundwater flow direction. I expect to begin drilling next week. " RDB
1-9-17 followed up with 3 emails to Bishop; 2014 tyree report, 2016 Antea report, & 2016 Tetratech report. RDB

2-15-17 check on status? report should be submitted this week? RDB
3-7-17 report submitted- RDB
06-13-17 drove by site; on going demo work?
June 2017- Citizen NOI filed?- RDB
07-17 email sent to Carlos looking for status- RDB

Created On: 12/20/2016

Date Printed: 7/1/2019 Last Updated: 06/26/2019

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 1608924

SPILL NAME: BP STATION- EAST POST RD GASMART **DEC LEAD:** RDBENDEL

07-17- phone call from Jeff Papitto 914 447-1279 and Phil Decaro esq 914-835-6200

07-18-17 spoke to Jeff, he has spoken to Frank, he is on board would like some additional time, they will be using Tim Bishop of Ct. Expressed concern to OGC regarding possible Citizen's suit brought by WPHA. RDB

7-21-17 email from Jeff, "So sorry Tim Bishop has gotten in touch with you as of yet. I know he is vactioning with his family a will be back Monday, July 24, 2017. We have forwarded him all site analyticals last week and he has acknolwedged receivin all the information.We have submitted a budget estimate to Mr. Frank Codella as well and have sent all information to Soil Sa for clearance for disposal. Papitto Construction Co., Inc. plans on mobilizing the first week of August as discussed previously with you.Tim's cell is 914-224-6268 if you need him he will be back on Monday.Any questions please feel frre to contact me a 914 447 1279." RDB

7-24-17 email from TIm Bishop, "I spoke with Jeff last week while I was away and he filled me in about 34 East Post Road in White Plains. I'll be putting together a RAWP for the station in White Plains that Papitto is proposing soil excavation at. I understand the station is currently closed and they're expecting to remove at least 800 tons of contaminated soil... (plus groundwater monitoring).I'll be working on this today, submit it to the client for review and expect to have it to you for review b Wednesday. " RDB
8-14-17 status email to Tim Bishop, response, "I spoke to Jeff today and neither him nor me have the gotten the green light fc anything yet." RDB
8-*22-17 spoke to Phil Decarlo, asked him to contact Ben- RDB
8-28-17, "So this is your two week follow-up.Any progress?" / response, "I took a call from Phil Decaro last week and he said Frank was going to be securing the funds late last week, but I haven't heard anything since nor do I have a signed contract." RDB
09-28-17 RP letter with settlement letter sent- RDB
10-6-17 Owner and attorney came in; asked to have tanks pumped by 10-10-17- RDB
10-11-17 draft OC sent to owner's att; WCHD reports tanks are not pumped out- RDB
10-13-17 email from att; tanks empty
10-13-17 NOV sent to Northville Industries Corp. BTR
10-16-17 email to WCHD to check tanks- RDB
11-6-17, email sent,"Frank and Phil,We met with both of you on October 6, 2017 and forwarded you an Order on Consent on October 11, 2017. To date, we have not received neither an executed Order on Consent nor documentation that the tanks ha been pumped out. The Department would like to meet with both of you on Friday November 17th at 11:00 am to discuss the investigation and remediation of this site.Please confirm your attendance." rdb
11-10-17 email from Phil Decaro received "I have been in depositions all week and traveling today so I do not have access to my files, but I have attached a copy of the receipt for the pump-out of the tanks at 34 East Post Rd. I will be able to send you an executed copy of
the Consent Order on Monday, but in the meantime please accept this email as a representation that my client agrees with ar accepts the terms of the Consent Order." Tank pump out record is on DECDOCs. BTR

12-1-17, "Upon arrival at the site at approximately 11am, the manhole was opened, PID reading was 0. Began to evacuate wi vacuum truck. Significant recharge. Highest PID reading during evacuation process was 125 ppm. Evacuated 2 existing drun of purge water staged on site. Total evacuated 1360 gallons." RDB

02-08-18 Consent Order executed by DEC. GZA has not been contracted for any of the work proposed in November. BTR

08-07-18 Asked Frank & Phil to meet in the New Paltz Office on Friday, August 10. Counsel responded that they are not available until first week of September. BTR

08-14-18 Scheduled meeting for Friday Sept. 7, at 11AM. No response received from Frank & Phil. BTR

08-30-18 B. Conlon asked to confirm meeting attendance. Still no response. BTR

10-9-18 deposed by WPHA counsel- RDB

NYSDEC SPILL REPORT FORM

DEC REGION: 3 **SPILL NUMBER:** 1608924

SPILL NAME: BP STATION- EAST POST RD GASMART **DEC LEAD:** RDBENDEL

11-21-18 Notified Mr. Codella of December 18 meeting in New Paltz. BTR

12-12-18 Mr. Decaro sent email asking for adjournment. No adjournment was granted. BTR

12/18/18 Met with Codella and Dicarro, at the meeting they agreed to let the department conduct the work.

12/30/18 Codella and Dicarro advised department RP is now willing to do the work and sign Orrder on Consent. TJP

1/22/19 RAWP received and uploaded to D2. TJP

1/25/19 Workplan put on hold until Order on Consent is signed, OGC sent out Order on Consent. TJP

02/15/19 First Environment letter received 1/9/2019 and uploaded to D2 --- IN

06-25-2019 No work progressing; OGC working on site- RDB

PIN **T & A** **COST CENTER**

CLASS: **CLOSE DATE:** **MEETS STANDARDS:** False

Remedial Investigation Report
White Plains Housing Authority
Building No. 33
White Plains, New York

November 29, 2016

Prepared for: White Plains Housing Authority
223 Dr. Martin Luther King, Jr. Boulevard
White Plains, New York 10601

Prepared by: First Environment, Inc.
91 Fulton Street
Boonton, New Jersey 07005

FIRST ENVIRONMENT

TABLE OF CONTENTS

Executive Summary 1
Introduction 3
Site Description and History 4
Physical Setting 4
Site Ownership and Operational History 4
Site Topography 4
Local Land Use 5
Soils 5
Surface Water 5
Wetlands and Floodplains 5
Site Geology and Hydrogeology 5
Technical Overview 6
Standards, Criteria, and Guidance 6
Quality Assurance/Quality Control 7
Health and Safety Plan 7
Community Air Monitoring Plan 7
Remedial Investigation Activities 8
Soil Sampling – April 2015 8
Analytical Results 9
Temporary Well Installation – April 2015 9
Temporary Well Groundwater Sampling – April 2015 10
Analytical Results 11
Geophysical Survey – December 2015 11
Soil Investigation – December 2015 12
Analytical Results 13
Permanent Monitoring Well Installation and Groundwater Sampling – December 2015 14
Groundwater Gauging & Flow Direction Determination 14
Groundwater Sampling – December 22, 2015 15
Analytical Results 16
Groundwater Sampling – August 2016 16
Analytical Results 17
Former Getty Station and BP Station Plumes 17
Conclusions 19

TABLES

1 AOC Sample Summary
2A Groundwater Elevations Summary
2B Water Quality Field Parameters
2C Field Sampling Data
3 Soil Analytical Results – December 2015
4 Groundwater Analytical Results – December 2015
5 Comparison of 2015 Groundwater Results
6 Groundwater Analytical Results – August 2016
7 Comparison of Split-GW Analytical Results

FIGURES

1 Site Location Map
2 Site Plan with Soil Boring and Monitoring Well Locations
3 Groundwater Flow – December 2015
4 Total BTEX Concentrations in Groundwater

APPENDICES

A Chain of Title for 34 E Post Rd
B Soil Boring & Monitoring Well Logs
C Quality Assurance Project Plan (QAPP)
D Health and Safety Plan (HASP)
E Community Air Monitoring Plan (CAMP)
F Groundwater Sampling Logs

Executive Summary

First Environment, Inc. (First Environment), on behalf of the White Plains Housing Authority (WPHA), conducted a Remedial Investigation (RI) on April 28-29, 2015 and December 11-18, 2015 at portions of the WPHA property that are adjacent to an active British Petroleum (BP) gasoline service station, located at 34 East Post Road, White Plains, New York, including an area between the BP station and the WPHA's Building at 33 Fisher Court. The area investigated is referred to as "the Site" hereafter. The 33 Fisher Court Building is, in turn, approximately 200 feet east of WPHA's Building at 159 South Lexington Avenue.[1]

The objective of the RI activities included the following tasks:

- to determine the location of subsurface utilities and/or potential anomalies adjacent to the areas of concern (AOCs), which may impede the completion of the remedial investigation;
- to confirm and evaluate the current and potential future status of Site contamination originating from the BP station; and
- to obtain additional data regarding soil and groundwater impacts necessary to develop a remedial strategy.

These tasks included the completion of soil boring installations, soil sampling, permanent monitoring well installations, and two groundwater sampling events.

A review of the soil analytical results collected from the soil boreholes revealed volatile organic compounds (VOCs) at concentrations above their respective New York State Department of Environmental Conservation (NYSDEC) Soil Cleanup Levels (SCL) for Gasoline Contaminated Soils pursuant to CP-51 guidance document in select soil boring locations. The analytical results for the groundwater sampling conducted revealed the presence of petroleum-related VOCs above the NYSDEC Ambient Water Quality Standards (AWQS) in two of the five monitoring wells installed and sampled in December 2015 and August 2016, as well as previously existing MW-106 sampled during the December 2015 event. First Environment, on behalf of the WPHA, is summarizing the activities completed to address the WPHA's concerns that contamination is migrating onto its property from the BP station.

[1] The Building 159 area and its parking lot have been the subject of a prior investigation due to a discharge from a former Getty service station on the other side of Brookfield Street at 26 East Post Road, White Plains, NY.

This Remedial Investigation Report (RIR) has been prepared in accordance with Section 3 of the NYSDEC DER-10 Technical Guidance for Site Investigation and Remediation, dated May 3, 2010, and details the RI activities completed in December 2015 and August 2016 as part of a split-groundwater sampling event conducted with the Antea Group (Antea), who is the consultant for Getty Corporation investigating the Getty related gasoline plume (Spill Case No. 97-13110).

Introduction

In November and December 2014, Tyree Environmental, as part of its investigation of the former Getty Station, installed two temporary wells at the sidewalk of Brookfield Street, immediately adjacent (approximately five feet) to the existing BP station. The groundwater samples obtained from those temporary wells showed elevated levels of gasoline related compounds in excess of the applicable NYSDEC AWQS. Subsequently, First Environment was asked by the WPHA to investigate the potential contamination migrating from the BP station. This Remedial Investigation Report (RIR) contains the results and findings of this investigation, which was performed on April 28-29, 2015, December 11-18, 2015, and August 1, 2016 on portions of the WPHA property identified as Building No. 33 area.

Figure 1 depicts the United States Geologic Survey (USGS) topographic map for the Site location. A Site Plan, consisting of all sampling locations utilized during this investigation, is provided in Figure 2.

The following objectives were developed as part of the RI activities:

- to determine the location of subsurface utilities and/or potential anomalies adjacent to the areas under investigation, which may impede the completion of the remedial investigation;
- to confirm and evaluate the current and future migration pathways and magnitude of Site contamination originating from the BP station; and
- to obtain additional data necessary to develop a remedial action (RA) strategy for the portions of the WPHA property.

The RI activities conducted included soil boring installations, soil sampling, permanent monitoring well installations, and two groundwater sampling events within the general vicinity of WPHA's Building No. 33.

Site Description and History

Physical Setting

The area investigated is located generally to the north of the BP station and south of Building No. 33, including a portion of the basketball court and a playground area located between Building Nos. 159 and 33, and the WPHA parking lot associated with Building No. 33. A site plan layout depicting pertinent features is included as Figure 2.

Site Ownership and Operational History

Adjacent to and south of the WPHA's Building 33 is a gasoline fuel station property currently operated as a British Petroleum (BP) gasoline service station. This site is owned by Marianina Oil Corporation and is believed to be leased to others. Historically, dating back to at least 1936, the property has been used for automobile fueling services. As indicated in Appendix A, Chain of Title for 34 E. Post Road, the property has changed ownership several times with each consecutive owner dealing with the oil and fuel industry. Additionally, Sanborn Fire Insurance Maps reviewed have also confirmed that the property has been identified as a fueling station from current times dating back to prior to 1940. This is noteworthy for this report due to the petroleum contamination found both in soil and groundwater in the vicinity of Building 33 located immediately to the north of the 34 E. Post Road property.

According to the title search results, the BP property was owned by the following entities:

- Deed made by The County Trust Company to Sinclair Refining Company dated 8/20/1936 recorded 8/24/1936 in Liber 3534 Page 183;
- Deed made by Atlantic Richfield Company to BP Oil Corporation dated 3/4/1969 recorded 10/14/1970 in Liber 6952 Page 678;
- Deed made by BP Oil Corporation to BP Oil Inc. dated 12/21/1973 recorded 7/18/1974 in Liber 7209 Page 180;
- Deed made by BP Oil Inc. to Northville Gasoline Corp. dated 10/5/1983 recorded 11/18/1983 in Liber 7878 Page 533; and
- Deed made by Northville Gasoline Corp. to Marianina Oil Corp. dated 6/24/1987 recorded 7/20/1987 in Liber 8893 Page 17.

Site Topography

The ground surface at the Site is generally flat, sloping upwards to the south and southwest towards Brookfield Street. During rainfall events, overland flow is directed towards stormwater catch basins located on Brookfield Street, as well as in the aforementioned

parking lot and basketball court area. The surface elevation at the Site is approximately 206 feet above mean sea level (msl).

Local Land Use

The surrounding area of the Site is highly developed consisting of mixed-use commercial, industrial, and residential properties.

Soils

Soils in this area are classified as Urban Land. Urban Land is typically found in densely developed areas where the soils and foundation material are highly variable. Most areas have been paved or graded, and the original soil materials have been disturbed, filled, or otherwise destroyed prior to construction.

The soils observed at the Site consisted of dark brown, dry to moist, non-cohesive, non-plastic, dense, medium to fine grained, well graded sand with silt from approximately 0.5 feet to approximately 5.0 feet below ground surface (bgs). Soils encountered at a depth greater than 5.0 feet bgs generally consisted of dark brown, wet, non-cohesive, non-plastic, medium density, coarse to fine grained, well graded sand. Soil boring description logs are included with this report as Appendix B.

Surface Water

No surface water bodies were observed on or adjacent to the Site. The nearest surface water body is Bloomingdale Pond, which is located approximately 3,630 feet east-northeast of the Site.

Wetlands and Floodplains

No evidence of wetland vegetation was observed on or adjacent to the Site during the site inspection. As previously stated, soils in this region are classified as Urban Land, which are not considered hydric. A review of the available wetland maps for this area indicate that the Site is not located on or directly adjacent to state and/or federal wetlands.

Site Geology and Hydrogeology

According to the New York State Geological Survey, surficial geology for this region is classified as glacial till deposits. The till is of variable texture, usually poorly sorted diamict deposition beneath glacier ice, relatively impermeable, variable clast content, ranging from

abundant well-rounded diverse lithology in valley tills to relatively angular more limited lithology in upland tills, and tends to be sandy in areas underlain by gneiss or sandstone.

Surficial soils in the vicinity of the Site are predominately silty sands underlain by a thin clay layer. Weathered bedrock is generally encountered around 8.0 feet bgs with competent rock around 9.0 feet bgs. Previous remedial investigations conducted in the vicinity of Building Nos. 159 and No. 33 has determined that groundwater flow in the area is generally to the north and northwest direction. Groundwater level measurements taken as part of this RI confirm that groundwater flow is in a northwesterly direction emanating from the BP Service Station, which is both topographically and hydraulically upgradient and adjacent to Building No. 33 to the south.

Table 2A summarizes the groundwater gauging data collected as part of this investigation. Figure 3 depicts the groundwater elevation contours and the flow direction based on the data collected in August 2016 investigation.

Technical Overview

To evaluate the conditions on the WPHA property downgradient of the BP station, representative soil and groundwater samples were collected in accordance with the Technical Guidance for Site Investigation and Remediation (NYSDEC DER-10, May 2010). All samples were placed in laboratory coolers that were chilled to 4°C with a completed chain-of-custody. Laboratory analyses were performed by Hampton Clark-Veritech (HCV) of Fairfield, New Jersey, a New York State Department of Health ELAP-certified laboratory (Certification No. 11408), using accepted and current United States Environmental Protection Agency (USEPA) analytical methods, as appropriate. Samples were handled and analyzed in compliance with sample holding times, method detection limits, and precision and accuracy criteria for the analytical method. No significant events or seasonal variations occurred that may have influenced sampling procedures or analytical results. A summary of Site sampling from the areas of concerns (AOCs) is provided as Table 1.

Standards, Criteria, and Guidance

The primary NYSDEC Standards, Criteria, and Guidance (SCGs) applicable to the Site are the Soil Cleanup Levels (SCL) for Gasoline Contaminated Soils established in NYSDEC Policy CP-51: Soil Cleanup Guidance, and the Technical and Operational Guidance Series

(TOGS) Ambient Water Quality Standards (AWQS). The SCLs are maximum concentrations that may exist in Site soils. Minimum requirements for the investigation and remediation of the Site, including sampling requirements, are established in DER-10.

The SCLs applicable to the Site were developed based on the Soil Cleanup Objectives for Gasoline Contaminated Soils established in Table 2 of the Supplemental Soil Cleanup Objectives (SSCOs) established in NYSDEC guidance CP-51. Laboratory analytical data for the soil samples collected during the remedial investigation activities have been compared to the CP-51 SCLs.

Quality Assurance/Quality Control

The Quality Assurance/Quality Control (QA/QC) procedures were conducted as described in the Quality Assurance Project Plan (QAPP) provided as Appendix C.

Health and Safety Plan

A site-specific health and safety plan (HASP) is provided as Appendix D of this report.

Community Air Monitoring Plan

A site-specific Community Air Monitoring Plan (CAMP) is provided as Appendix E. The CAMP outlines air-monitoring requirements for Site activities with the potential to introduce particulates and vapors to the atmosphere, and provides action levels for adjusting or ceasing work practices. The CAMP was implemented during all intrusive remedial action activities.

Remedial Investigation Activities

Soil Sampling – April 2015

First Environment, with Environmental Test Boring, Inc. (ETB) of Butler, New Jersey, initiated a soil investigation at the Site on April 28-29, 2015 to investigate the possible contamination of gasoline related impacts in soil and groundwater in relation to the BP station located adjacent to the south of WPHA's Building 33. ETB utilized Geoprobe® direct push drill rig to install a total of six soil borings, TWB-1 through TWB-6, to depths ranging from 8.0 to 15.0 feet below ground surface (bgs). The investigation activities mainly focused on the areas generally to the north and downgradient of BP station, as well as in the southern portion of the Building 33 parking lot.

All recovered soils were field-screened using a properly calibrated photoionization detector (PID) and field observations (i.e., staining, odor) were noted. A complete soil profile was recorded for each boring and soils were classified according to the Unified Soil Classification System (USCS). Soils below the Site generally consisted of dark brown to greenish brown sand with some crushed rocks from surface grade to approximately 5.0 feet bgs, and brown to stained gray sand with some crushed rocks from 5.0 to 15.0 feet bgs. Saturated soils were observed between approximately 5.5 and 6.5 feet bgs, which correspond to the depth-to-groundwater in the on-site monitoring wells. Soil boring description logs are included with this report as Appendix B.

According to the field observations noted during the investigation event, TWB-2 and TWB-4 exhibited the greatest likelihood for impact due to the presence of elevated PID readings, strong petroleum-hydrocarbon odor, and staining from approximately 5.0 to 15.0 feet bgs. The PID readings for these soil borings were detected at concentrations of 15,000 parts per million (ppm) at 6.0 to 10.0 feet bgs in borings TWB-2 and TWB-4, which corresponds to the most visually impacted depth interval.

Furthermore, TWB-3, TWB-5, and TWB-6 each exhibited elevated PID readings and moderate petroleum-hydrocarbon odors; however, minimal staining was observed in these borings and the highest recorded PID readings ranged from 8.8 ppm to 491 ppm. The depth of impact observed in these borings ranged from approximately 10.0 to 12.0 feet bgs. No evidence of impact was observed in boring TWB-1.

In accordance with DER-10 requirements, soil samples were collected from the depth intervals exhibiting the greatest potential for impact in each boring. In addition, a second soil sample was collected from the six-inch interval directly above the perceived groundwater table, or at an interval that would confirm the horizontal extent of impact identified in an adjacent boring.

Appropriate field blanks were also collected in accordance with DER-10 requirements to satisfy QA/QC protocols. Subsequent to collection, all samples were placed in laboratory-supplied jars and stored in a laboratory cooler that was chilled to 4°C with a completed chain-of-custody. All samples were submitted to HCV for analysis for New York STARS volatile organic compounds (VOC) (STARS VO list 2 - EPA Method 8260C) and lead (metal – EPA Method 6010C).

Figure 2 depicts the sampling locations.

Analytical Results

The laboratory analytical results revealed the presence of 1,2,4-trimethylbenzene, ethylbenzene, and total xylenes at concentrations above their respective NYSDEC SCL in the following samples (depth interval provided in feet bgs): TWB-2 (6.0'-6.5') and TWB-5 (9.5'-10.0'). Additionally, 1,2,4-trimethylbenzene was detected at minimal concentrations (below the NYS SCL of 3.6 ppm) in samples TWB-4 (10.5'-11.0') and TWB-5 (9.5'-10.0'). Laboratory analytical results for the remaining soil samples revealed VOC concentrations below the NYS SCL.

Temporary Well Installation – April 2015

To evaluate groundwater conditions below the Site, ETB, under the direct supervision of First Environment, utilized hollow-stem auger drilling techniques to install five temporary monitoring wells (TWB-2 through TWB-6) at the Site on April 28-29, 2015. All temporary wells were installed to an approximate depth of 15.0 feet bgs and were constructed with 5 feet of two-inch PVC casing and 10 feet of 0.020-inch slotted PVC screen; with the exception of TWP-2 which was installed to approximately 10.0 feet bgs with only 10 feet of 0.020-inch slotted PVC screen. A No. 2 sand filter was placed from approximately 2.0 feet to the installed depth of the wells, with a bentonite and cement mixture from 3.0 feet bgs to

surface grade. Bedrock was not encountered during the monitoring well installation process to a depth of 15.0 feet bgs for TWP-3 through TWP-6. However, bedrock was encountered at approximately 8.0 feet bgs in TWP-1 and at 10.0 feet bgs in TWP-2. TWP-1 soils were observed to be dry during boring installation; therefore, a temporary well was not installed in this location. TWP-2 soils were wet at the 6.0 feet bgs interval; therefore, a temporary well was installed in this location.

Figure 2 depicts the sampling locations.

Temporary Well Groundwater Sampling – April 2015

Prior to sampling, all five temporary wells were surged using a whale pump – a process which removes fine silts and soils from the slotted PVC screen allowing groundwater to freely enter the well. Temporary wells TWP-2 through TWP-6 were sampled using the three-volume purge method in accordance with procedures outlined in the NYSDEC DER-10. Prior to initiating the sampling activities, the headspace of each well was monitored using a properly calibrated PID and depth-to-water measurements were recorded for each well using the top-of-casing (TOC) as a reference point. No free-phase floating product was encountered; however, TWP-2 and TWP-4 did exhibit an oily sheen on the surface of the groundwater as it was purged.

Following the recording of water level measurements, First Environment utilized pre-cleaned, dedicated Teflon tubing to properly purge each temporary well of the required three volumes. Once wells were properly purged, groundwater samples were collected directly from dedicated Teflon bailers, and then, using that bailer, the sample was discharged directly into containers provided by the laboratory.

Appropriate field blanks were also collected in accordance with DER-10 requirements to satisfy QA/QC protocols. Subsequent to collection, all samples were stored in a laboratory cooler that was chilled to 4°C with a completed chain-of-custody. All samples were submitted to HCV for analysis for New York STARS volatile organic compounds (VOC) (STARS VO list 2 - EPA Method 8260C), and lead (metal – EPA Method 6010A).

Analytical Results

The laboratory analytical results revealed the presence of 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, benzene, toluene, ethylbenzene, and total xylenes (BTEX) at concentrations above their respective NYSDEC Ambient Groundwater Quality Standards (AWQS) in the following samples: TWB-2, TWB-3, TWB-4, TWB-5, TWB-6, and MW-106.

The details and the results of April 2015 investigations outlined above were submitted to the NYSDEC in October 2015 in a Site Investigation/Remedial Investigation Report. Figure 4 depicts the history of total BTEX concentrations.

Geophysical Survey – December 2015

On December 11, 2015, the remedial investigation activities were initiated with the completion of a geophysical survey of the Site. GPROneCall of Somerville, New Jersey, under the direct supervision of a First Environment on-site representative, utilized a combination of geophysical methods (e.g., metal detection, ground penetrating radar (GPR), and radio frequency) in an attempt to identify the location of any subsurface anomalies (e.g., gas, water, and sewer pipes). The geophysical survey did reveal the presence of near-surface anomalies. Furthermore, the geophysical survey was conducted for only a portion of the whole WPHA property in order to identify any subsurface utilities that may impede the completion of the subsequent soil boring and monitoring well installation activities. Early identification of potential utilities and other anomalies also reduced the potential for encountering unexpected conditions during the proposed soil drilling activities.

A summary of the findings are presented below:

- A subsurface electrical conduit was detected along the eastern and northern fence boundaries of the property, separating Building No. 159 from Building No. 33.
- A subsurface water pipe and steam pipes were detected running primarily east-west between the two aforementioned addresses across the current basketball courts.
- A subsurface sewer pipe was detected running northeast (from the 159 S. Lexington parking lot) through the basketball courts.
- A subsurface gas pipe was detected on the southwestern portion of Building No. 33 in its southern parking lot area.

Based on the results of the geophysical survey, subsurface anomalies were identified within or adjacent to the investigation area; therefore, due to the presence of the subsurface

conduit and pipes, proper care was taken to address these utilities prior to the implementation of the proposed soil boring installation activities. As such, the proposed locations of the soil borings/monitoring wells were adjusted and moved a selected safe distance from the anomalies before installation activities began.

Soil Investigation – December 2015

First Environment, with Environmental Test Boring, Inc. (ETB) of Butler, New Jersey, initiated a soil investigation at the Site on December 11, 2015 to investigate the possible contamination of gasoline related impacts in soil and groundwater in relation to the BP station located adjacent to the south of WPHA's Building No. 33. Soil investigation activities continued on December 14, 2015. ETB utilized a Geoprobe® direct push drill rig to install a total of five soil borings, SB-201 through SB-205, to depths ranging from 10.0 to 20.0 feet bgs. The investigation activities mainly focused on the areas generally to the north and downgradient of the BP station, as well as in the southern portion of the Building No. 33 parking lot, and expanded upon the soil investigation activities conducted in this area in April 2015.

All recovered soils were field-screened using a properly calibrated photoionization detector (PID) and field observations (i.e., staining, odor) were noted. A complete soil profile was recorded for each boring and soils were classified according to the Unified Soil Classification System (USCS). Soils below the Site generally consisted of dark brown to greenish brown sand with some crushed rocks from surface grade to approximately 5.0 feet bgs, and brown to stained gray sand with some crushed rocks from 5.0 to 15.0 feet bgs. Saturated soils were observed between approximately 5.5 and 6.5 feet bgs, which correspond to the depth-to-groundwater in the on-site monitoring wells. Soil boring description logs are included with this report as Appendix B.

According to the field observations noted during the investigation event, SB-201 and SB-203 exhibited the greatest likelihood for impact due to the presence of elevated PID readings, strong petroleum-hydrocarbon odor, and staining from approximately 5.0 to 15.0 feet bgs. The PID readings for these soil borings were detected at concentrations of 1,200 parts per million (ppm) in boring SB-201 and 537 ppm in SB-203, which corresponds to the most visually impacted depth interval of approximately 6.0 to 8.0 feet bgs.

Furthermore, SB-202 and SB-205 did not exhibit any detectable PID readings and no petroleum-hydrocarbon odors. Therefore, no evidence of impact was observed in these soil borings. SB-204 exhibited minimal PID readings (under 5 ppm); however, with no petroleum hydrocarbon odors as well.

In accordance with DER-10 requirements, soil samples were collected from the depth intervals exhibiting the greatest potential for impact in each boring based on PID readings, detection of odors, and observations. A second soil sample was not collected from each borehole as the soil in this area was previously classified during the April 2015 site investigation activities, and soil samples were collected vertically to delineate the highest impacted zone. If the soil borehole did not exhibit any elevated PID readings or showed signs of contamination, then a soil sample was collected from the six-inch interval above the groundwater level zone.

Appropriate field blanks were also collected in accordance with DER-10 requirements to satisfy QA/QC protocols. Subsequent to collection, all samples were placed in laboratory-supplied jars and stored in a laboratory cooler that was chilled to 4°C with a completed chain-of-custody. All samples were submitted to HCV for analysis for targeted compound list volatile organic compounds plus a forward library search (TCL VO+15, which included NY STARS VO list 2 - EPA Method 8260C), and lead (metal – EPA Method 6010C).

Analytical Results

The laboratory analytical results revealed the presence of 1,2,4-trimethylbenzene, ethylbenzene, n-propylbenzene, and total xylenes at concentrations above their respective NYSDEC SCL in the following sample (depth interval provided in feet bgs): SB-201 (6.0-6.5) at concentrations of 37, 3.4, 5, and 8.7 ppm. Additionally, 1,2,4-trimethylbenzene was detected below the NYS SCL of 3.6 ppm in sample SB-203 (7.0-7.5) at 2.4 ppm. Laboratory analytical results for the remaining soil samples revealed VOC concentrations below the NYS SCL.

The laboratory soil analytical results are summarized in Table 3. Figure 2 depicts the sampling locations.

Permanent Monitoring Well Installation and Groundwater Sampling – December 2015

To evaluate groundwater conditions below the Site, ETB, under the direct supervision of First Environment, utilized hollow-stem auger drilling techniques to install five permanent monitoring wells (MW-201 through MW-205) at the Site on December 11, 14, and 18, 2015. The monitoring wells, the locations of which are depicted in Figure 2, were installed directly at the five previously installed soil boring locations from December 11, 2015. All monitoring wells were installed to depths ranging between 10.0 and 20.0 feet bgs and were constructed of 2 to 5 feet of two-inch PVC casing and 8 to 15 feet of 0.020-inch slotted PVC screen dependent on the depth of the initial soil borehole. A No. 2 sand filter was placed from approximately 3.0 feet to the installed depth of the wells, with a bentonite and cement mixture from 3.0 feet bgs to surface grade. Bedrock was encountered during the monitoring well installation process at varying depths ranging from approximately 5.0 to 15.0 feet bgs for MW-201, MW-203, and MW-205. However, bedrock was not encountered to a depth of 20.0 feet bgs in MW-202 and MW-204.

Groundwater Gauging & Flow Direction Determination

Previous remedial investigations conducted at the WPHA property, including those conducted in the vicinity of Building Nos. 159 and No. 33, have determined that groundwater flow in the area is generally to the north and northwest direction. Groundwater level measurements collected as part of this RI confirm that groundwater flow is in a northwesterly direction emanating from the BP Service Station, which is both topographically and hydraulically upgradient and adjacent to Building No. 33 to the south. As part of this process, each monitoring well was individually gauged utilizing an electronic Solinst multi-phase (product-water) level indicator probe to measure the depth-to-product (if any) and depth-to-water. No free-phase product was observed in any of the monitoring wells. Additionally, each monitoring well was surveyed by a licensed land surveyor to determine its location (coordinates in state plane coordinate system in feet) and casing elevation in feet above mean sea level (MSL). With this information and the depth-to-groundwater measurement from each well, the groundwater elevation was calculated for each location. Using groundwater elevations and a software package (i.e., Surfer), groundwater elevation contours (equipotential lines) were developed utilizing Kriging spatial interpolation routine. The groundwater flow direction was determined based on the

groundwater elevation contour lines. Figure 3 depicts the groundwater elevation contours and the flow in the northwest direction based on December 2015 well gauging results.

Groundwater Sampling – December 22, 2015

As part of the groundwater sampling event, First Environment sampled the newly installed monitoring wells, MW-201 through MW-205, as well as previously installed MW-106. Prior to sampling, all five monitoring wells were surged using a whale pump – a process which removes fine silts and soils from the slotted PVC screen allowing groundwater to freely enter the well. Monitoring wells MW-201 through MW-205 and MW-106 were sampled using the low-flow purge method in accordance with procedures outlined in the NYSDEC DER-10. Prior to initiating the sampling activities, the headspace of each well was monitored using a properly calibrated PID and depth-to-water measurements were recorded for each well using the top-of-casing (TOC) as a reference point. No free-phase floating product was encountered and none of the monitoring wells exhibited an oily sheen on the surface of the groundwater as it was purged.

The monitoring wells were surveyed as part of investigation activities; therefore, along with depth-to-water measurements collected prior to sampling, groundwater flow was derived to be flowing in a northerly to north-northwest pattern (Figure 3). Following the recording of water-level measurements, First Environment utilized pre-cleaned, dedicated Teflon tubing and Teflon bladder with bladder pump to properly purge each monitoring well until water quality parameters (pH, dissolved oxygen, specific conductivity, temperature, and turbidity) achieved three consecutive stable readings, recorded every five minutes. All water quality parameters were measured with a properly calibrated Horiba U-50 Series Water Quality Monitoring System. Water quality parameter results obtained during well purging, and at the time of well sampling, are summarized in Tables 3A through 3C. Once wells were properly purged, groundwater samples were collected directly from dedicated Teflon bailers; and then using that bailer to discharge the sample directly into containers provided by the laboratory.

Appropriate field blanks were also collected in accordance with DER-10 requirements to satisfy QA/QC protocols. Subsequent to collection, all samples were stored in a laboratory cooler that was chilled to 4°C with a completed chain-of-custody. All samples were

submitted to HCV for analysis for New York STARS volatile organic compounds (VOC) (STARS VO list 2 - EPA Method 8260C), and lead (metal – EPA Method 6010A).

Groundwater sampling logs are provided in Appendix F.

Analytical Results

The laboratory analytical results revealed the presence of 1,2,4-trimethylbenzene; 1,3,5-trimethylbenzene; benzene; toluene; ethylbenzene; total xylenes (BTEX); chloroform; naphthalene; and n-propylbenzene at concentrations above their respective NYSDEC Ambient Groundwater Quality Standards (AWQS) in samples MW-201 and MW-203. Benzene was detected over the AWQS in the MW-106 sample, while m&p xylenes were detected over the AWQS in the MW-205 sample. Additionally, the analysis of the groundwater sample from MW-204 identified the presence of chlorinated solvents; specifically, tetrachloroethene (PCE), trichloroethene (TCE), and cis-1,2-dichloroethene (DCE), all above their respective AWQS. The presence of gasoline related compounds (i.e., BTEX) was not detected in the MW-204 sample.

The laboratory analytical results are summarized in Table 4. A comparison of the December 2015 groundwater analytical results to the April 2015 groundwater analytical results (initially presented in an October 2015 Site Investigation/Remedial Investigation Report) is presented in Table 5. Figure 4 summarizes the history of total BTEX concentrations.

Groundwater Sampling – August 2016

As part of the split-groundwater sampling event conducted on August 1, 2016 with Antea Group (Antea), which is the current consultant for Getty Corporation investigating the Getty related gasoline plume,[2] First Environment sampled monitoring wells MW-201 through MW-205 associated with Building No. 33. Prior to sampling, all five monitoring wells were opened and allowed to equilibrate and stabilize under ambient air conditions. Monitoring wells MW-201 through MW-205 and MW-106 were sampled using the three-volume purge method in accordance with procedures outlined in the NYSDEC DER-10. No free-phase

[2] The August 2016 sampling event was conducted concurrently with Antea's groundwater monitoring event of all current monitoring wells located on the Former Getty station, WPHA property, and adjacent commercial property. The Former Getty station is involved in an on-going remediation under Spill Case No. 97-13110 and in pending litigation.

floating product was encountered and none of the monitoring wells exhibited an oily sheen on the surface of the groundwater as it was purged.

Following the recording of water level measurements, pre-cleaned, dedicated Teflon bailers were utilized to properly purge each monitoring well. Once wells were properly purged, groundwater samples were collected directly from dedicated Teflon bailers; and then using that bailer to discharge the sample directly into containers provided by the laboratory.

Appropriate field blanks were also collected in accordance with DER-10 requirements to satisfy QA/QC protocols. Subsequent to collection, all samples were stored in a laboratory cooler that was chilled to 4°C with a completed chain-of-custody. All samples were submitted to HCV for analysis for New York STARS volatile organic compounds (VOC) (STARS VO list 2 - EPA Method 8260C).

Analytical Results

The laboratory analytical results revealed the presence of 1,2,4-trimethylbenzene; 1,3,5-trimethylbenzene; benzene; toluene; ethylbenzene; total xylenes (BTEX); chloroform; naphthalene; and n-propylbenzene; as well as additional petroleum-related contaminants, at concentrations above their respective NYSDEC Ambient Groundwater Quality Standards (AWQS) in samples MW-201 and MW-203. Methyl-t-butyl-ether (MTBE) was identified in MW-204; however, no standard exists for this compound. The presence of gasoline related compounds (i.e., BTEX) was not detected in samples MW-202 and MW-205.

The laboratory analytical results are summarized in Table 6. A comparison of the August 2016 groundwater analytical results collected by First Environment to the August 2016 groundwater analytical results collected by Antea is presented in Table 7. It should be noted that for the split-groundwater sampling event conducted in August 2016, monitoring wells MW-201 through MW-205 were temporarily renamed MW-201-33 through MW-205-33 due to additional wells located on the WPHA property with similar identifications. Figure 4 depicts the history of total BTEX concentrations.

Former Getty Station and BP Station Plumes

Remedial investigation and remedial action reports have been previously submitted that have documented the extent of the former Getty station plume. The reports, submitted by

both Tyree Environmental, Inc. (Tyree), consultant to Getty, and First Environment discussed both soil and groundwater investigation activities conducted on the WPHA property to determine the extent of the former Getty station plume. As discussed above, First Environment conducted this remedial investigation to determine the extent of a plume migrating from the current BP station property.

To a reasonable degree of scientific certainty, the location of the two plumes and sampling performed between Buildings Nos. 159 and 33 show that: (1) the BP station and former Getty station plumes are not comingled; (2) the groundwater contaminant plume from the former Getty station is separate and distinct from the groundwater contaminant plume from the BP station; (3) the BP plume has impacted the Building 33 area; and (4) the BP plume has not impacted Building 159 area.

The basis for these conclusions is as follows. The site investigation conducted in 2015 by First Environment identified and delineated the extent of a groundwater contaminant plume migrating from the BP station onto WPHA property in the general location of Building No. 33. Sidewall soil samples (EX-20, EX-21, and EX-23, EX-27, EX-28, and EX-30) were collected on the WPHA Building No. 159 parking lot adjacent to the basketball courts by Tyree in January 8, 2015 as part of the excavation activities. These samples were non-detect for all SVOCs tested except naphthalene, which was detected in two samples (EX-20 and EX-23) below NYSDEC SCL. These soil samples were collected at depths near or below the groundwater table. The location and depth of these samples indicate a zone of clean soil and groundwater between the groundwater contamination from the former Getty station and the BP station. Further, modeling of the groundwater plume from the BP station, based on the April 2015 investigation by First Environment, depicts that the groundwater contamination plume in the Building 33 area from the BP station is not near the areas impacted by operations at the former Getty station.

Conclusions

Based on the investigation activities conducted on December 11, 14, and 18, 2015 and the additional sampling event conducted on August 1, 2016, the horizontal and vertical extent of VOC impacts at the Site have been delineated. The results of the field investigation indicate a larger area of impact than previously believed. Overall, and as to be expected for light-phase contamination, the most impacted interval (7.0 – 8.0 feet bgs) was identified at the groundwater table interface on the Building No. 33 property; however, petroleum-hydrocarbon impact was also identified at shallower and deeper depths ranging from approximately 6.0 to 15.0 feet bgs. This finding supports the presence of a smear zone generated by the seasonal fluctuations in groundwater surface. Therefore, based on the Site geology, horizontal and vertical extent of petroleum impacts in soil and groundwater, the fact that the area is adjacent to and downgradient from the BP station, and the location of the monitoring well network on Building No. 33 property, with a reasonable degree of scientific certainty, the area investigated via wells MW-201 and MW-203 has been impacted by the BP station.

TABLES

TABLE 1
AOC Sample Summary

White Plains Housing Authority
White Plains, New York

AOC	Sample ID	Date Sampled	Laboratory	Medium	Sample Depths (feet bgs)	Analytical Parameters	Sampling Method
Soil	SB-201 through SB-205	12/11/2015	Hampton Clark-Veritech	Soil	0-6" above Water Table; Highest PID 0-6" Interval	TCL VO+15 (incl. STARS), Lead	4-oz jar
Groundwater	MW-106, MW-201 through MW-205	12/22/2015, 8/1/2015	Hampton Clark-Veritech	Groundwater	Water Table	TCL VO+15 (incl. STARS), Lead	Teflon Bailer (three volume purge)
Groundwater	MW-106, MW-201 through MW-205	8/1/2016	Hampton Clark-Veritech	Groundwater	Water Table	VOC STARS	Teflon Bailer (three volume purge)

Notes:

TCL: Targeted Compound List
VOC: Volatile Organic Compounds
BN: Base Neutral / Semi-volatile Organic Compounds

TABLE 2A
Groundwater Elevations Summary
December 2015 August 2016

White Plains Housing Authority
White Plains, New York

WELL NO.	DEPTH OF (1) WELL (FT)	REFERENCE (1) ELEVATION (FT)	Northing	Easting	DATE	HEAD SPACE READING (PPM)	DEPTH TO (1) WATER (FT)	DEPTH TO PRODUCT (FT)	PRODUCT THICKNESS (FT)	CORRECTED WATER LEVEL ELEVATION (FT)
MW-106	18.3	200.04	799870.83	693440.71	12/22/2015	NR	6.10	NE	0.0	193.94
					8/1/2016	NR	6.49	NE	0.0	193.55
MW-201	9.7	202.42	799803.89	693525.27	12/22/2015	653.0	5.52	NE	0.0	196.90
					8/1/2016	NR	5.94	NE	0.0	196.48
MW-202	20.3	202.09	799905.36	693603.56	12/22/2015	1.2	7.02	NE	0.0	195.07
					8/1/2016	NR	7.50	NE	0.0	194.59
MW-203	15.0	202.51	799868.61	693530.89	12/22/2015	55.5	7.45	NE	0.0	195.06
					8/1/2016	NR	7.88	NE	0.0	194.63
MW-204	20.4	199.17	800010.93	693445.87	12/22/2015	12.1	7.40	NE	0.0	191.77
					8/1/2016	NR	7.37	NE	0.0	191.80
MW-205	14.3	200.99	799802.50	693449.34	12/22/2015	NR	5.78	NE	0.0	195.21
					8/1/2016	NR	6.06	NE	0.0	194.93

NOTES:

(1) = Reference point is northside of top of casings; elevations are reported relative to mean sea level.
NM - Well not measured due to blockage
NE - Not Encountered
NR - Not Recorded

TABLE 2B
Water Quality Field Parameters
December 22, 2015

White Plains Housing Authority
White Plains, New York

	FIELD PARAMETERS BEFORE PURGING						FIELD PARAMETERS AFTER PURGING					
			SPECIFIC						SPECIFIC			
	DTW	TEMP		COND.	DO	ORP	DTW	TEMP		COND.	DO	ORP
WELL NO.	(feet)	(°C)	pH	(uS/cm)	(ppm)	(mV)	(feet)	(°C)	pH	(uS/cm)	(ppm)	(mV)
MW-106	6.4	14.75	6.75	2.520	1.64	-51	6.42	14.92	6.64	2.510	0.83	-55
MW-201	5.56	15.21	6.34	2.490	1.18	-77	5.57	14.05	6.47	4.920	0.54	-84
MW-202	7.02	15.74	7.89	0.415	1.28	101	7.02	15.87	7.82	0.395	0.00	94
MW-203	7.45	16.34	7.09	1.930	0.00	-76	7.45	16.08	7.12	1.920	0.00	-78
MW-204	7.4	14.54	7.50	2.110	5.81	137	7.40	14.86	7.45	2.160	4.57	107
MW-205	5.81	13.75	6.85	1.570	2.63	102	5.90	15.66	6.81	1.490	2.09	106

TABLE 2C
Field Sampling Data
December 22, 2015

White Plains Housing Authority
White Plains, New York

WELL NO.	DATE & TIME OF SAMPLING	DEPTH TO WATER IN FEET BEFORE SAMPLING	SAMPLING METHOD	FIELD PARAMETERS AT SAMPLING				
				pH	TEMP (°C)	DO (ppm)	SPEC. COND. (mS/cm)	ORP (mV)
MW-106	12/22/2015; 11:15	6.42	1.5" Teflon Bailer	6.9	16.36	5.96	2.11	-95
MW-201	12/22/2015; 09:00	5.57	1.5" Teflon Bailer	6.47	14.05	0.54	4.92	-84
MW-202	12/22/2015; 09:30	7.02	1.5" Teflon Bailer	7.82	15.87	0	0.395	94
MW-203	12/22/2015; 08:35	7.45	1.5" Teflon Bailer	7.12	16.08	0	1.92	-78
MW-204	12/22/2015; 10:30	7.40	1.5" Teflon Bailer	7.45	14.86	4.57	2.16	107
MW-205	12/22/2015; 10:10	5.90	1.5" Teflon Bailer	6.81	15.66	2.09	1.49	106

Notes:
ppm - parts per million
mS/cm - millisemen per centimeter

TABLE 3
Soil Analytical Results
December 2015

White Plains Housing Authority
White Plains, New York

CLIENT ID:						SB-201 (6.0 - 6.5)			SB-202 (15.0 - 15.5)			SB-203 (7.0-7.5)			SB-204 (11.0-11.5)			SB-205 (5.5 - 6.0)		
COLLECTION DATE:						12/11/2015			12/11/2015			12/11/2015			12/11/2015			12/14/2015		
SAMPLE MATRIX:						Soil			Soil			Soil			Soil			Soil		
SAMPLE UNITS:						mg/kg			mg/kg			mg/kg			mg/kg			mg/kg		
LAB ID:	NY Soil		Part375	Part375		AC88731-001			AC88731-002			AC88731-003			AC88731-004			AC88731-005		
CONSULTANT:	TAGM	NY SCC	Restricted	Unrestricted	Commercial	First Environment			First Environment			First Environment			First Environment			First Environment		
	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL
Metals																				
Lead		**63**	400	63	1000	ND		5.6	**5.8**		5.7	ND		6	ND		5.5	ND		5.7
Volatiles (TCL VO+15 incl. VOC STARS)																				
1,1,1-Trichloroethane	0.8	**0.68**	100	0.68	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,1,2,2-Tetrachloroethane	0.6	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,1,2-Trichloro-1,2,2-trifluoroethane	6	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,1,2-Trichloroethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,1-Dichloroethane	0.2	**0.27**	26	0.27	240	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,1-Dichloroethene	0.4	**0.33**	100	0.33	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2,3-Trichlorobenzene	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2,4-Trichlorobenzene	3.4	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2,4-Trimethylbenzene	NA	**3.6**	NA	NA	190	**37**		0.11	0.0017		0.0012	**2.4**		0.0056	ND		0.0011	0.0013		0.0011
1,2-Dibromo-3-chloropropane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2-Dibromoethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2-Dichlorobenzene	7.9	**1.1**	100	1.1	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,2-Dichloroethane	0.1	**0.02**	3.1	0.02	30	ND		0.057	ND		0.0012	ND		0.0056	ND		0.0011	ND		0.0011
1,2-Dichloropropane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,3,5-Trimethylbenzene	NA	**8.4**	52	8.4	190	**7.1**		0.11	ND		0.0012	0.82		0.0056	ND		0.0011	ND		0.0011
1,3-Dichlorobenzene	1.6	**2.4**	49	2.4	280	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,4-Dichlorobenzene	8.5	**1.8**	13	1.8	130	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
1,4-Dioxane	NA	**0.1**	13	0.1	130	ND		5.7	ND		0.12	ND		0.56	ND		0.11	ND		0.11
2-Butanone	0.3	**0.12**	100	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
2-Hexanone	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
4-Isopropyltoluene	NA	**NA**	NA	NA	NA	0.37		0.11	ND		0.0012	0.068		0.0056	ND		0.0011	ND		0.0011
4-Methyl-2-pentanone	1	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Acetone	0.2	**0.05**	100	0.05	500	ND		0.57	ND		0.012	ND		0.056	ND		0.011	ND		0.011
Benzene	0.06	**0.06**	4.8	0.06	44	ND		0.057	ND		0.0012	ND		0.0056	ND		0.0011	ND		0.0011
Bromochloromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Bromodichloromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Bromoform	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Bromomethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Carbon disulfide	2.7	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Carbon tetrachloride	0.6	**0.76**	2.4	0.76	22	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Chlorobenzene	1.7	**1.1**	100	1.1	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Chloroethane	1.9	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Chloroform	0.3	**0.37**	49	0.37	350	**0.17**		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Chloromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
cis-1,2-Dichloroethene	NA	**0.25**	100	0.25	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
cis-1,3-Dichloropropene	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Cyclohexane	NA	**NA**	NA	NA	NA	**4**		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Dibromochloromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Dichlorodifluoromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Ethylbenzene	5.5	**1**	41	1	390	**3.4**		0.11	ND		0.0012	0.041		0.0056	ND		0.0011	ND		0.0011
Isopropylbenzene	NA	**NA**	NA	NA	NA	1.4		0.11	ND		0.0012	0.13		0.0056	ND		0.0011	ND		0.0011
m&p-Xylenes	1.2	**0.26**	NA	NA	NA	**7.4**		0.11	ND		0.0012	0.043		0.0056	ND		0.0011	ND		0.0011
Methyl Acetate	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Methylcyclohexane	NA	**NA**	NA	NA	NA	**3.4**		0.11	ND		0.0023	0.059		0.011	ND		0.0022	ND		0.0023
Methylene chloride	0.1	**0.05**	NA	0.05	500	ND		0.11	0.0028		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Methyl-t-butyl ether	NA	**0.93**	100	0.93	500	ND		0.057	ND		0.0012	ND		0.0056	0.0015		0.0011	ND		0.0011
Naphthalene	13	**12**	100	12	500	**5**		0.11	ND		0.0012	0.44		0.0056	ND		0.0011	0.0027		0.0011
n-Butylbenzene	NA	**12**	100	12	NA	1.6		0.11	ND		0.0012	0.22		0.0056	ND		0.0011	ND		0.0011
n-Propylbenzene	NA	**3.9**	100	3.9	500	**5**		0.11	ND		0.0012	0.62		0.0056	ND		0.0011	ND		0.0011
o-Xylene	1.2	**0.26**	NA	0.26	NA	**1.3**		0.11	ND		0.0012	0.015		0.0056	ND		0.0011	ND		0.0011
sec-Butylbenzene	NA	**11**	100	11	500	0.85		0.11	ND		0.0012	0.1		0.0056	ND		0.0011	ND		0.0011
Styrene	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
t-Butylbenzene	NA	**NA**	100	5.9	500	ND		0.11	ND		0.0012	ND		0.0056	ND		0.0011	ND		0.0011
Tetrachloroethene	1.4	**1.3**	19	1.3	150	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Toluene	1.5	**0.7**	100	0.7	500	ND		0.11	ND		0.0012	ND		0.0056	ND		0.0011	ND		0.0011
trans-1,2-Dichloroethene	0.3	**0.19**	100	0.19	500	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
trans-1,3-Dichloropropene	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Trichloroethene	0.7	**0.47**	21	0.47	200	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Trichlorofluoromethane	NA	**NA**	NA	NA	NA	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Vinyl chloride	0.2	**0.02**	0.9	0.02	13	ND		0.11	ND		0.0023	ND		0.011	ND		0.0022	ND		0.0023
Xylenes (Total)	NA	**NA**	100	0.26	500	**8.7**		0.11	ND		0.0012	0.058		0.0056	ND		0.0011	ND		0.0011
Total Volatile TICS	NA	**NA**	NA	NA	NA	**54**	J	NA	ND		NA	18	J	NA	ND		NA	ND		NA

NA — No criterion derived for this contaminant.
ND — Not Detected at or above the Laboratory Reporting Limit (RL)
840 — Concentration exceeds the most stringent NYS SCC.

TABLE 4
Groundwater Analytical Results
December 2015

White Plains Housing Authority
White Plains, New York

CLIENT ID:				MW-106		MW-201		MW-202		MW-203		MW-204		MW-205		FB		TB	
COLLECTION DATE:				12/22/2015		12/22/2015		12/22/2015		12/22/2015		12/22/2015		12/22/2015		12/22/2015		12/22/2015	
SAMPLE MATRIX:				Aqueous		Aqueous		Aqueous		Aqueous		Aqueous		Aqueous		Aqueous		Aqueous	
SAMPLE UNITS:				ug/L		ug/L		ug/L		ug/L		ug/L		ug/L		ug/L		ug/L	
LAB ID:	NY Water	NY TOGS WaterEffluent	NY TOGS																
CONSULTANT:	TAGM	Tagm	WaterQualStds	First Environment		First Environment		First Environment		First Environment		First Environment		First Environment		First Environment		First Environment	
	ug/L	ug/L	ug/L	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL
Metals																			
Lead	NA	50	**25**	**9.9**	3	**11**	3	**17**	3	**6.6**	3	**28**	3	**6.8**	3	ND	3		
Volatiles (TCL VO+15 incl. VOC STARS)																			
1,1,1-Trichloroethane	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,1,2,2-Tetrachloroethane	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,1,2-Trichloro-1,2,2-trifluoroethane	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,1,2-Trichloroethane	NA	1	**1**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,1-Dichloroethane	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,1-Dichloroethene	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2,3-Trichlorobenzene	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2,4-Trichlorobenzene	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2,4-Trimethylbenzene	5	NA	**5**	**3.5**	1	**2100**	10	**1.9**	1	**1400**	10	ND	10	**3.1**	1	ND	1	ND	1
1,2-Dibromo-3-chloropropane	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2-Dibromoethane	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2-Dichlorobenzene	4.7	3	**3**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,2-Dichloroethane	5	0.6	**0.6**	ND	0.5	ND	5	ND	0.5	ND	5	ND	5	ND	0.5	ND	0.5	ND	0.5
1,2-Dichloropropane	NA	1	**1**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,3,5-Trimethylbenzene	5	NA	**5**	ND	1	**540**	10	ND	1	**320**	10	ND	10	ND	1	ND	1	ND	1
1,3-Dichlorobenzene	5	3	**3**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,4-Dichlorobenzene	5	3	**3**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
1,4-Dioxane	NA	NA	**NA**	ND	50	ND	500	ND	50	ND	500	ND	500	ND	50	ND	50	ND	50
2-Butanone	50	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
2-Hexanone	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
4-Isopropyltoluene	5	NA	**5**	ND	1	**10**	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
4-Methyl-2-pentanone	50	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Acetone	50	NA	**NA**	ND	5	ND	50	ND	5	ND	50	ND	50	ND	5	ND	5	ND	5
Benzene	0.7	1	**1**	**2.1**	0.5	**59**	5	ND	0.5	ND	5	ND	5	ND	0.5	ND	0.5	ND	0.5
Bromochloromethane	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Bromodichloromethane	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Bromoform	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Bromomethane	NA	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Carbon disulfide	50	120	**60**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Carbon tetrachloride	5	5	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Chlorobenzene	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Chloroethane	50	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Chloroform	7	7	**7**	ND	1	**14**	10	ND	1	**10**	10	ND	10	ND	1	ND	1	ND	1
Chloromethane	NA	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
cis-1,2-Dichloroethene	NA	NA	**5**	ND	1	ND	10	ND	1	ND	10	**20**	10	ND	1	ND	1	ND	1
cis-1,3-Dichloropropene	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Cyclohexane	NA	NA	**NA**	**9**	1	**170**	10	ND	1	**58**	10	ND	10	ND	1	ND	1	ND	1
Dibromochloromethane	50	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Dichlorodifluoromethane	NA	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Ethylbenzene	5	NA	**5**	ND	1	**1000**	10	ND	1	**120**	10	ND	10	**1.2**	1	ND	1	ND	1
Isopropylbenzene	NA	NA	**5**	ND	1	**150**	10	ND	1	**91**	10	ND	10	ND	1	ND	1	ND	1
m&p-Xylenes	5	NA	**5**	**2.7**	1	**2200**	10	ND	1	**160**	10	ND	10	**5.1**	1	ND	1	ND	1
Methyl Acetate	NA	NA	**NA**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Methylcyclohexane	NA	NA	**NA**	1	1	**110**	10	ND	1	**96**	10	ND	10	ND	1	ND	1	ND	1
Methylene chloride	5	NA	**5**	ND	1	ND	10	ND	1	ND	10	ND	10	ND	1	ND	1	ND	1
Methyl-t-butyl ether	NA	NA	**NA**	0.99	0.5	ND	5	ND	0.5	ND	5	**47**	5	ND	0.5	ND	0.5	ND	0.5
Naphthalene	10	NA	**NA**	ND	1	**450**	10	ND	1	**220**	10	ND	10	ND	1	ND	1	ND	1
n-Butylbenzene	NA	NA	**5**	ND	1	**37**	10	ND	1	**15**	10	ND	10	ND	1	ND	1	ND	1
n-Propylbenzene	NA	NA	**5**	ND	1	**430**	10	ND	1	**280**	10	ND	10	ND	1	ND	1	ND	1

TABLE 4
Groundwater Analytical Results
December 2015

White Plains Housing Authority
White Plains, New York

CLIENT ID:				MW-106			MW-201			MW-202			MW-203			MW-204			MW-205			FB			TB		
COLLECTION DATE:				12/22/2015			12/22/2015			12/22/2015			12/22/2015			12/22/2015			12/22/2015			12/22/2015			12/22/2015		
SAMPLE MATRIX:				Aqueous			Aqueous			Aqueous			Aqueous			Aqueous			Aqueous			Aqueous			Aqueous		
SAMPLE UNITS:				ug/L			ug/L			ug/L			ug/L			ug/L			ug/L			ug/L			ug/L		
LAB ID:																											
CONSULTANT:	NY Water TAGM	NY TOGS WaterEffluent Tagm	**NY TOGS WaterQualStds**	First Environment			First Environment			First Environment			First Environment			First Environment			First Environment			First Environment			First Environment		
	ug/L	ug/L	**ug/L**	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL
o-Xylene	5	NA	**5**	ND		1	**480**		10	ND		1	**38**		10	ND		10	ND		1	ND		1	ND		1
sec-Butylbenzene	NA	NA	**5**	ND		1	**27**		10	ND		1	**22**		10	ND		10	ND		1	ND		1	ND		1
Styrene	NA	5	**5**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
t-Butylbenzene	NA	NA	**NA**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
Tetrachloroethene	5	NA	**5**	ND		1	ND		10	ND		1	ND		10	**960**		10	ND		1	ND		1	ND		1
Toluene	5	NA	**5**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
trans-1,2-Dichloroethene	5	NA	**5**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
trans-1,3-Dichloropropene	NA	NA	**NA**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
Trichloroethene	5	5	**5**	ND		1	ND		10	ND		1	ND		10	**56**		10	ND		1	ND		1	ND		1
Trichlorofluoromethane	NA	NA	**5**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
Vinyl chloride	2	2	**2**	ND		1	ND		10	ND		1	ND		10	ND		10	ND		1	ND		1	ND		1
Xylenes (Total)	5	NA	**5**	**2.7**		1	**2650**		10	ND		1	**380**			ND		10	**5.1**		1	ND		1	ND		1
Total Volatile TICS	NA	NA	**NA**	23	J	NA	**6100**	J	NA	ND		NA	**4000**	J	NA	ND		NA	ND		NA	ND		NA	ND		NA

NA
ND
840

Table 5
Groundwater Analytical Results Comparison for Eastern Building 159 and Building 33 Areas
January 2016

White Plains Housing Authority
White Plains, New York

CLIENT ID:				MW-106			MW-106			TWB-2			MW-201		
COLLECTION DATE:				4/28/2015			12/22/2015			4/29/2015			12/22/2015		
SAMPLE MATRIX:				Aqueous			Aqueous			Aqueous			Aqueous		
SAMPLE UNITS:	NY Water	NY TOGS WaterEffluent	NY TOGS	ug/L			ug/L			ug/L			ug/L		
CONSULTANT:	TAGM	Tagm	WaterQualStds	First Environment			First Environment			First Environment			First Environment		
	ug/L	ug/L	ug/L	Result		RL	Result		RL	Result		RL	Result		RL
Metals															
Lead	NA	50	**25**	**39**		3	**9.9**		3	**7.4**		3	**11**		3
Volatiles (TCL VO+15 incl. VOC STARS)															
1,2,4-Trimethylbenzene	5	NA	**5**	**3**		1	**3.5**		1	**2,600**		10	**2100**		10
1,3,5-Trimethylbenzene	5	NA	**5**	**1.7**		1	ND		1	**680**		10	**540**		10
4-Isopropyltoluene	5	NA	**5**	**5.5**		1	ND		1	**19**		10	**10**		10
Benzene	0.7	1	**1**	**28**		0.5	**2.1**		0.5	**30**		5	**59**		5
Chloroform	7	7	**7**	**----**		**----**	ND		1	**----**		**----**	**14**		10
cis-1,2-Dichloroethene	NA	NA	**5**	**----**		**----**	ND		1	**----**		**----**	ND		10
Cyclohexane	NA	NA	**NA**	**----**		**----**	**9**		1	**----**		**----**	**170**		10
Ethylbenzene	5	NA	**5**	**3**		1	ND		1	**1,200**		10	**1000**		10
Isopropylbenzene	NA	NA	**5**	**17**		1	ND		1	**170**		10	**150**		10
m&p-Xylenes	5	NA	**5**	**6.8**		1	**2.7**		1	**2,700**		10	**2200**		10
Methylcyclohexane	NA	NA	**NA**	**----**		**----**	1		1	**----**		**----**	**110**		10
Methyl-t-butyl ether	NA	NA	**NA**	**1.8**		0.5	0.99		0.5	ND		5	ND		5
Naphthalene	10	NA	**NA**	**16**		1	ND		1	**220**		10	**450**		10
n-Butylbenzene	NA	NA	**5**	**2.5**		1	ND		1	**30**		10	**37**		10
n-Propylbenzene	NA	NA	**5**	**13**		1	ND		1	**450**		10	**430**		10
o-Xylene	5	NA	**5**	ND		1	ND		1	**600**		10	**480**		10
sec-Butylbenzene	NA	NA	**5**	**6.3**		1	ND		1	**26**		10	**27**		10
t-Butylbenzene	NA	NA	**NA**	ND		1	ND		1	ND		10	ND		10
Tetrachloroethene	5	NA	**5**	**----**		**----**	ND		1	**----**		**----**	ND		10
Toluene	5	NA	**5**	ND		1	ND		1	ND		10	ND		10
Trichloroethene	5	5	**5**	**----**		**----**	ND		1	**----**		**----**	ND		10
Xylenes (Total)	5	NA	**5**	**6.8**		1	**2.7**		1	**3,300**		10	**2680**		10
Total Volatile TICS	NA	NA	**NA**	**----**		**----**	23	J	NA	**----**		**----**	**6100**	J	NA

No Criteria developed for this standard.	NA
Concentration was not detectable by intrument.	ND
Compound was not analyzed for.	----
Compound was detected, however did not exceed any standard.	**3**
Concentration exceeded the most stringest NYSDEC AWQS.	**840**

Table 5
Groundwater Analytical Results Comparison for Eastern Building 159 and Building 33 Areas
January 2016

White Plains Housing Authority
White Plains, New York

CLIENT ID:				MW-202			TWB-3			TWB-4			TWB-5		
COLLECTION DATE:				12/22/2015			4/29/2015			4/29/2015			4/28/2015		
SAMPLE MATRIX:				Aqueous			Aqueous			Aqueous			Aqueous		
SAMPLE UNITS:	NY Water	NY TOGS WaterEffluent	NY TOGS	ug/L			ug/L			ug/L			ug/L		
CONSULTANT:	TAGM	Tagm	WaterQualStds	First Environment			First Environment			First Environment			First Environment		
	ug/L	ug/L	ug/L	Result		RL	Result		RL	Result		RL	Result		RL
Metals															
Lead	NA	50	**25**	**17**		3	**51**		3	ND		3	**95**		3
Volatiles (TCL VO+15 incl. VOC STARS)															
1,2,4-Trimethylbenzene	5	NA	**5**	**1.9**		1	**6**		1	**27**		1	**2,900**		20
1,3,5-Trimethylbenzene	5	NA	**5**	ND		1	1.8		1	**7.6**		1	**730**		20
4-Isopropyltoluene	5	NA	**5**	ND		1	ND		1	**2.1**		1	**22**		20
Benzene	0.7	1	**1**	ND		0.5	ND		0.5	0.56		0.5	ND		10
Chloroform	7	7	**7**	ND		1	----		----	----		----	----		----
cis-1,2-Dichloroethene	NA	NA	**5**	ND		1	----		----	----		----	----		----
Cyclohexane	NA	NA	**NA**	ND		1	----		----	----		----	----		----
Ethylbenzene	5	NA	**5**	ND		1	**6.3**		1	**15**		1	**1,700**		20
Isopropylbenzene	NA	NA	**5**	ND		1	**1.1**		1	**4.2**		1	**150**		20
m&p-Xylenes	5	NA	**5**	ND		1	**13**		1	**31**		1	**5,100**		20
Methylcyclohexane	NA	NA	**NA**	ND		1	----		----	----		----	----		----
Methyl-t-butyl ether	NA	NA	**NA**	ND		0.5	ND		0.5	**0.63**		0.5	ND		10
Naphthalene	10	NA	**NA**	ND		1	**1.3**		1	**17**		1	**410**		20
n-Butylbenzene	NA	NA	**5**	ND		1	ND		1	**11**		1	**39**		20
n-Propylbenzene	NA	NA	**5**	ND		1	**3**		1	**12**		1	**460**		20
o-Xylene	5	NA	**5**	ND		1	**2.9**		1	**5.6**		1	**980**		20
sec-Butylbenzene	NA	NA	**5**	ND		1	**1.4**		1	**4.3**		1	**39**		20
t-Butylbenzene	NA	NA	**NA**	ND		1	ND		1	ND		1	ND		20
Tetrachloroethene	5	NA	**5**	ND		1	----		----	----		----	----		----
Toluene	5	NA	**5**	ND		1	ND		1	ND		1	ND		20
Trichloroethene	5	5	**5**	ND		1	----		----	----		----	----		----
Xylenes (Total)	5	NA	**5**	ND		1	**15.9**		1	**36.6**		1	**6,080**		20
Total Volatile TICS	NA	NA	**NA**	ND		NA	----		----	----		----	----		----

No Criteria developed for this standard.	NA
Concentration was not detectable by intrument.	ND
Compound was not analyzed for.	----
Compound was detected, however did not exceed any standard.	**3**
Concentration exceeded the most stringest NYSDEC AWQS.	**840**

Table 5
Groundwater Analytical Results Comparison for Eastern Building 159 and Building 33 Areas
January 2016

White Plains Housing Authority
White Plains, New York

CLIENT ID:				MW-203			MW-204			TWB-6			MW-205		
COLLECTION DATE:				12/22/2015			12/22/2015			4/28/2015			12/22/2015		
SAMPLE MATRIX:				Aqueous			Aqueous			Aqueous			Aqueous		
SAMPLE UNITS:	NY Water	NY TOGS WaterEffluent	NY TOGS	ug/L			ug/L			ug/L			ug/L		
CONSULTANT:	TAGM	Tagm	WaterQualStds	First Environment			First Environment			First Environment			First Environment		
	ug/L	ug/L	**ug/L**	Result		RL	Result		RL	Result		RL	Result		RL
Metals															
Lead	NA	50	**25**	**6.6**		3	**28**		3	**270**		3	**6.8**		3
Volatiles (TCL VO+15 incl. VOC STARS)															
1,2,4-Trimethylbenzene	5	NA	**5**	**1400**		10	ND		10	**15**		1	**3.1**		1
1,3,5-Trimethylbenzene	5	NA	**5**	**320**		10	ND		10	**2.8**		1	ND		1
4-Isopropyltoluene	5	NA	**5**	ND		10	ND		10	ND		1	ND		1
Benzene	0.7	1	**1**	ND		5	ND		5	**10**		0.5	ND		0.5
Chloroform	7	7	**7**	**10**		10	ND		10				ND		1
cis-1,2-Dichloroethene	NA	NA	**5**	ND		10	**20**		10				ND		1
Cyclohexane	NA	NA	**NA**	**58**		10	ND		10				ND		1
Ethylbenzene	5	NA	**5**	**120**		10	ND		10	**13**		1	**1.2**		1
Isopropylbenzene	NA	NA	**5**	**91**		10	ND		10	**2.5**		1	ND		1
m&p-Xylenes	5	NA	**5**	**160**		10	ND		10	**44**		1	**5.1**		1
Methylcyclohexane	NA	NA	**NA**	**96**		10	ND		10				ND		1
Methyl-t-butyl ether	NA	NA	**NA**	ND		5	**47**		5	**1**		0.5	ND		0.5
Naphthalene	10	NA	**NA**	**220**		10	ND		10	**2.3**		1	ND		1
n-Butylbenzene	NA	NA	**5**	**15**		10	ND		10	ND		1	ND		1
n-Propylbenzene	NA	NA	**5**	**280**		10	ND		10	**4**		1	ND		1
o-Xylene	5	NA	**5**	**38**		10	ND		10	**8.3**		1	ND		1
sec-Butylbenzene	NA	NA	**5**	**22**		10	ND		10	ND		1	ND		1
t-Butylbenzene	NA	NA	**NA**	ND		10	ND		10	ND		1	ND		1
Tetrachloroethene	5	NA	**5**	ND		10	**960**		10				ND		1
Toluene	5	NA	**5**	ND		10	ND		10	ND		1	ND		1
Trichloroethene	5	5	**5**	ND		10	**56**		10				ND		1
Xylenes (Total)	5	NA	**5**	**198**		10	ND		10	**52.3**		1	**5.1**		1
Total Volatile TICS	NA	NA	**NA**	**4000**	J	NA	ND		NA	**----**		**----**	ND		NA

No Criteria developed for this standard.	NA
Concentration was not detectable by intrument.	ND
Compound was not analyzed for.	----
Compound was detected, however did not exceed any standard.	**3**
Concentration exceeded the most stringest NYSDEC AWQS.	**840**

TABLE 6
Building 33
Groundwater Analytical Results
August 2016

White Plains Housing Authority
WPHA001

CLIENT ID:				MW-201-33			MW-202-33			MW-203-33			MW-204-33			MW-205-33			MW-106			FB 8116		
COLLECTION DATE:				8/1/2016			8/1/2016			8/1/2016			8/1/2016			8/1/2016			8/1/2016			8/1/2016		
SAMPLE MATRIX:				Aqueous			Aqueous			Aqueous			Aqueous			Aqueous			Aqueous			Aqueous		
SAMPLE UNITS:				ug/L			ug/L			ug/L			ug/L			ug/L			ug/L			ug/L		
LAB ID:	NY Water	NY TOGS WaterEffluent	**NY TOGS WaterQual**	AC92722-015			AC92722-014			AC92722-013			AC92722-012			AC92722-011			AC92722-010			AC92722-016		
CONSULTANT:	TAGM	Tagm	**Stds**	First Environment			First Environment			First Environment			First Environment			First Environment			First Environment			First Environment		
	ug/L	ug/L	**ug/L**	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL	Result		RL
Volatiles (TCL VO+15 incl. VOC STARS)																								
1,2,4-Trimethylbenzene	5	NA	**5**	**1,100**		5	ND		1	**2600**		10	ND		1	ND		1	ND		1	ND		1
1,3,5-Trimethylbenzene	5	NA	**5**	**430**		5	ND		1	**650**		10	ND		1	ND		1	ND		1	ND		1
4-Isopropyltoluene	5	NA	**5**	**9.5**		5	ND		1	**21**		10	ND		1	ND		1	ND		1	ND		1
Benzene	0.7	1	**1**	**16**		2.5	ND		0.5	ND		5	ND		0.5	ND		0.5	ND		0.5	ND		0.5
Ethylbenzene	5	NA	**5**	**750**		5	ND		1	**270**		10	ND		1	ND		1	ND		1	ND		1
Isopropylbenzene	NA	NA	**5**	**120**		5	ND		1	**170**		10	ND		1	ND		1	ND		1	ND		1
m&p-Xylenes	5	NA	**5**	**1,000**		5	ND		1	**260**		10	ND		1	ND		1	ND		1	ND		1
Methyl-t-butyl ether	NA	NA	**NA**	ND		2.5	ND		0.5	ND		5	**39**		0.5	ND		0.5	ND		0.5	ND		0.5
Naphthalene	10	NA	**NA**	**380**		5	ND		1	**470**		10	ND		1	ND		1	ND		1	ND		1
n-Butylbenzene	NA	NA	**5**	**32**		5	ND		1	ND		10	ND		1	ND		1	ND		1	ND		1
n-Propylbenzene	NA	NA	**5**	**290**		5	ND		1	**500**		10	ND		1	ND		1	ND		1	ND		1
o-Xylene	5	NA	**5**	**150**		5	ND		1	**61**		10	ND		1	ND		1	ND		1	ND		1
sec-Butylbenzene	NA	NA	**5**	**28**		5	ND		1	**44**		10	ND		1	ND		1	ND		1	ND		1
t-Butylbenzene	NA	NA	**NA**	ND		5	ND		1	ND		10	ND		1	ND		1	ND		1	ND		1
Toluene	5	NA	**5**	ND		5	ND		1	ND		10	ND		1	ND		1	ND		1	ND		1
Xylenes (Total)	NA	NA	**NA**	**1,200**		5	ND		1	**320**		10	ND		1	ND		1	ND		1	ND		1

TABLE 6
Building 33
Groundwater Analytical Results
August 2016

White Plains Housing Authority
WPHA001

CLIENT ID:				TB		
COLLECTION DATE:				8/1/2016		
SAMPLE MATRIX:				Aqueous		
SAMPLE UNITS:		NY TOGS	**NY TOGS**	ug/L		
LAB ID:	NY Water	WaterEffluent	**WaterQual**	AC92722-017		
CONSULTANT:	TAGM	Tagm	**Stds**	First Environment		
	ug/L	ug/L	**ug/L**	Result		RL
Volatiles (TCL VO+15 incl. VOC STARS)						
1,2,4-Trimethylbenzene	5	NA	**5**	ND		1
1,3,5-Trimethylbenzene	5	NA	**5**	ND		1
4-Isopropyltoluene	5	NA	**5**	ND		1
Benzene	0.7	1	**1**	ND		0.5
Ethylbenzene	5	NA	**5**	ND		1
Isopropylbenzene	NA	NA	**5**	ND		1
m&p-Xylenes	5	NA	**5**	ND		1
Methyl-t-butyl ether	NA	NA	**NA**	ND		0.5
Naphthalene	10	NA	**NA**	ND		1
n-Butylbenzene	NA	NA	**5**	ND		1
n-Propylbenzene	NA	NA	**5**	ND		1
o-Xylene	5	NA	**5**	ND		1
sec-Butylbenzene	NA	NA	**5**	ND		1
t-Butylbenzene	NA	NA	**NA**	ND		1
Toluene	5	NA	**5**	ND		1
Xylenes (Total)	NA	NA	**NA**	ND		1

TABLE 7
Building 33 Split-Sampling
Groundwater Analytical Results Comparison
August 2016

White Plains Housing Authority
WPHA001

CLIENT ID:				MW-106				MW-201-33				MW-202-33				MW-203-33				MW-204-33				MW-205-33				FB 8116		TB	
COLLECTION DATE:				8/1/2016				8/1/2016				8/1/2016				8/1/2016				8/1/2016				8/1/2016				8/1/2016		8/1/2016	
SAMPLE MATRIX:				Aqueous				Aqueous				Aqueous				Aqueous				Aqueous				Aqueous				Aqueous		Aqueous	
SAMPLE UNITS:				ug/L				ug/L				ug/L				ug/L				ug/L				ug/L				ug/L		ug/L	
LAB ID:	NY Water	NY TOGS WaterEffluent	NY TOGS	AC92722-010				AC92722-015				AC92722-014				AC92722-013				AC92722-012				AC92722-011				AC92722-016		AC92722-017	
CONSULTANT:	TAGM	Tagm	WaterQualStds	First Environment		Antea Group		First Environment		Antea Group		First Environment		Antea Group		First Environment		Antea Group		First Environment		Antea Group		First Environment		Antea Group		First Environment		First Environment	
	ug/L	ug/L	ug/L	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL	Result	RL
Volatiles (TCL VO+15 incl. VOC STARS)																															
1,2,4-Trimethylbenzene	5	NA	**5**	ND	1	ND	1	**1,100**	5	**750**	20	ND	1	ND	1	**2600**	10	**2,100**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
1,3,5-Trimethylbenzene	5	NA	**5**	ND	1	ND	1	**430**	5	**190**	20	ND	1	ND	1	**650**	10	**360**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
4-Isopropyltoluene	5	NA	**5**	ND	1	ND	1	**9.5**	5	ND	20	ND	1	ND	1	**21**	10	ND	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
Benzene	0.7	1	**1**	ND	0.5	ND	1	**16**	2.5	ND	20	ND	0.5	ND	1	ND	5	ND	50	ND	0.5	ND	1	ND	0.5	ND	1	ND	0.5	ND	0.5
Ethylbenzene	5	NA	**5**	ND	1	ND	1	**750**	5	**450**	20	ND	1	ND	1	**270**	10	**220**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
Isopropylbenzene	NA	NA	**5**	ND	1	ND	1	**120**	5	**89**	20	ND	1	ND	1	**170**	10	**160**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
m&p-Xylenes	5	NA	**5**	ND	1	ND	2	**1,000**	5	**540**	40	ND	1	ND	2	**260**	10	**160**	100	ND	1	ND	2	ND	1	ND	2	ND	1	ND	1
Methyl-t-butyl ether	NA	NA	**NA**	ND	0.5	ND	1	ND	2.5	ND	20	ND	0.5	ND	1	ND	5	ND	50	**39**	0.5	**41**	1	ND	0.5	ND	1	ND	0.5	ND	0.5
Naphthalene	10	NA	**NA**	ND	1	ND	2	**380**	5	**400**	40	ND	1	ND	2	**470**	10	**530**	100	ND	1	ND	2	ND	1	ND	2	ND	1	ND	1
n-Butylbenzene	NA	NA	**5**	ND	1	ND	1	**32**	5	**32**	20	ND	1	ND	1	ND	10	**52**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
n-Propylbenzene	NA	NA	**5**	ND	1	ND	1	**290**	5	**200**	20	ND	1	ND	1	**500**	10	**400**	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
o-Xylene	5	NA	**5**	ND	1	ND	1	**150**	5	**83**	20	ND	1	ND	1	**61**	10	ND	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
sec-Butylbenzene	NA	NA	**5**	ND	1	ND	1	**28**	5	ND	20	ND	1	ND	1	**44**	10	ND	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
t-Butylbenzene	NA	NA	**NA**	ND	1	ND	1	ND	5	ND	20	ND	1	ND	1	ND	10	ND	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
Toluene	5	NA	**5**	ND	1	ND	1	ND	5	ND	20	ND	1	ND	1	ND	10	ND	50	ND	1	ND	1	ND	1	ND	1	ND	1	ND	1
Xylenes (Total)	NA	NA	**NA**	ND	1	ND		**1,200**	5	**623**		ND	1	ND		**320**	10	**160**		ND	1	ND		ND	1	ND		ND	1	ND	1

** Certain contaminants are not detected by Antea's laboratory due to the high Reporting Limit's (RLs) of that laboratory.
First Environment's laboratory utilized lower RLs, and therefore detected these contaminants.

FIGURES



N
W E
S

1 inch = 2,000 feet

United States Geological Survey, New York, NY Topographic Quadrangle, 1967, Photorevised 1981

FIRST ENVIRONMENT

91 Fulton Street
Boonton, New Jersey 07005

WHITE PLAINS HOUSING AUTHORITY
26 EAST POST ROAD
WHITE PLAINS, WESTCHESTER COUNTY, NY

FIGURE 1
SITE LOCATION MAP

Revised	Drawn	Checked	Approved	Date
	SW	KNF	TCB	10/08/15

MW-204

Building 33

MW-202

MW-106

MW-203

TWB-4

TWB-5

TWB-6

TWB-3

MW-205

TWB-2

Building 159

PMW-111

BP Station

PMW-110

Former Getty Station

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Legend

- Temporary Well Points Installed in September 2014
- Temporary Well Points Installed in April 2015
- Permanent Monitoring Wells Installed in December 2015

0 25 50 100 Feet

1 inch = 50 feet

N W E S

FIRST ENVIRONMENT

91 Fulton Street
Boonton, New Jersey 07005

WHITE PLAINS HOUSING AUTHORITY
Building 33
White Plains, New York

FIGURE 2

SITE PLAN

Revised	Drawn	Checked	Approved	Date
	NMT			11/4/2016

Legend

- Monitoring Wells Installed by First Environment
- Groundwater Elevation Contours (ft, MSL)
- **196.48** Groundwater Elevation as of August 2016 (ft, MSL)

0 25 50 100 Feet

1 inch = 50 feet

N W E S

FIRST ENVIRONMENT

91 Fulton Street
Boonton, New Jersey 07005

WHITE PLAINS HOUSING AUTHORITY
Building 33
White Plains, New York

FIGURE 3

GROUNDWATER ELEVATION CONTOUR MAP

Revised	Drawn	Checked	Approved	Date
	NMT			11/7/2016



Legend

- Temporary Well Points Installed in September 2014
- Temporary Well Points Installed in April 2015
- Permanent Monitoring Wells Installed in December 2015

NA: Not Available

ND: Not Detected above Laboratory Reported Detection Limits

0 25 50 100 Feet

1 inch = 50 feet

N W E S

FIRST ENVIRONMENT

91 Fulton Street
Boonton, New Jersey 07005

WHITE PLAINS HOUSING AUTHORITY
Building 33
White Plains, New York

FIGURE 4

TOTAL BTEX CONCENTRATIONS IN GROUNDWATER (ug/L)

Revised	Drawn	Checked	Approved	Date
	NMT			11/4/2016

ATTACHMENT 2
Historical Topo Map Report

White Plains - 5 Parcels

42 East Post Road

White Plains, NY 10601

Inquiry Number: 6284645.4

December 01, 2020

EDR Historical Topo Map Report

with QuadMatch™

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

12/01/20

Site Name:

White Plains - 5 Parcels
42 East Post Road
White Plains, NY 10601
EDR Inquiry # 6284645.4

Client Name:

Barton & Loguidice, D.P.C.
443 Electronics Parkway
Liverpool, NY 13088
Contact: Corinne Steinmuller

EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Barton & Loguidice, D.P.C. were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:

P.O.# 2025.003.001
Project: White Plains - 5 Parcels

Coordinates:

Latitude:	41.026718 41° 1' 36" North
Longitude:	-73.769558 -73° 46' 10" West
UTM Zone:	Zone 18 North
UTM X Meters:	603441.37
UTM Y Meters:	4542452.17
Elevation:	211.33' above sea level

Maps Provided:

2012, 2013
1994
1979
1967, 1971
1957, 1960
1944, 1947
1938
1932
1899, 1902
1893
1892

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2012, 2013 Source Sheets

Glenville
2012
7.5-minute, 24000

White Plains
2013
7.5-minute, 24000

1994 Source Sheets



WHITE PLAINS
1994
7.5-minute, 24000

1979 Source Sheets



White Plains
1979
7.5-minute, 24000
Aerial Photo Revised 1977

1967, 1971 Source Sheets

White Plains
1967
7.5-minute, 24000
Aerial Photo Revised 1965

Glenville
1971
7.5-minute, 24000
Aerial Photo Revised 1971

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1957, 1960 Source Sheets



White Plains
1957
7.5-minute, 24000

Glenville
1960
7.5-minute, 24000
Aerial Photo Revised 1949

1944, 1947 Source Sheets

Glenville
1944
7.5-minute, 24000
Aerial Photo Revised 1941

White Plains
1947
7.5-minute, 24000
Aerial Photo Revised 1940

1938 Source Sheets

White Plains
1938
7.5-minute, 31680

1932 Source Sheets

White Plains
1932
7.5-minute, 24000

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1899, 1902 Source Sheets

Stamford
1899
15-minute, 62500

Tarrytown
1902
15-minute, 62500

1893 Source Sheets

Tarrytown
1893
15-minute, 62500

Stamford
1893
15-minute, 62500

1892 Source Sheets

Tarrytown
1892
15-minute, 62500



Stamford
1892
15-minute, 62500

Historical Topo Map

2012, 2013



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 2013, 7.5-minute
NE, Glenville, 2012, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, WHITE PLAINS, 1994, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1979, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1967, 7.5-minute
NE, Glenville, 1971, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1957, 7.5-minute
NE, Glenville, 1960, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, White Plains, 1947, 7.5-minute
NE, Glenville, 1944, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1938, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, White Plains, 1932, 7.5-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tarrytown, 1902, 15-minute
NE, Stamford, 1899, 15-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5

NW N NE
W E
SW S SE

TP, Tarrytown, 1893, 15-minute
NE, Stamford, 1893, 15-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N



This report includes information from the following map sheet(s).

0 Miles 0.25 0.5 1 1.5



TP, Tarrytown, 1892, 15-minute
NE, Stamford, 1892, 15-minute

SITE NAME: White Plains - 5 Parcels
ADDRESS: 42 East Post Road
White Plains, NY 10601
CLIENT: Barton & Loguidice, D.P.C.

N

ATTACHMENT 3
Aerial Photographs

White Plains - 5 Parcels

42 East Post Road

White Plains, NY 10601

Inquiry Number: 6284645.8

December 01, 2020

The EDR Aerial Photo Decade Package

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Aerial Photo Decade Package

12/01/20

Site Name:

White Plains - 5 Parcels
42 East Post Road
White Plains, NY 10601
EDR Inquiry # 6284645.8

Client Name:

Barton & Loguidice, D.P.C.
443 Electronics Parkway
Liverpool, NY 13088
Contact: Corinne Steinmuller

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

Year	Scale	Details	Source
2017	1"=500'	Flight Year: 2017	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2009	1"=500'	Flight Year: 2009	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1994	1"=500'	Acquisition Date: April 20, 1994	USGS/DOQQ
1991	1"=500'	Flight Date: April 03, 1991	USGS
1985	1"=500'	Flight Date: March 16, 1985	USDA
1974	1"=500'	Flight Date: October 24, 1974	USDA
1971	1"=500'	Flight Date: April 24, 1971	USGS
1964	1"=500'	Flight Date: March 23, 1964	USGS
1962	1"=500'	Flight Date: January 16, 1962	EDR Proprietary Aerial Viewpoint
1958	1"=500'	Flight Date: August 05, 1958	USGS
1953	1"=500'	Flight Date: December 17, 1953	USGS
1949	1"=500'	Flight Date: March 14, 1949	USGS
1941	1"=500'	Flight Date: October 06, 1941	USGS

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


INQUIRY #: 6284645.8
YEAR: 2017
= 500'
N
EDR

INQUIRY #: 6284645.8
YEAR: 2013
= 500'
N
EDR



INQUIRY #: 6284645.8

YEAR: 2009

= 500'

N

EDR

INQUIRY #: 6284645.8
YEAR: 2006
= 500'
N
EDR

INQUIRY #: 6284645.8

YEAR: 1994

= 500'

N

EDR

Subject boundary not shown because it exceeds image extent or image is not georeferenced.

INQUIRY #: 6284645.8

YEAR: 1991

= 500'

N

EDR

INQUIRY #: 6284645.8
YEAR: 1985
= 500'
N
EDR

INQUIRY #: 6284645.8
YEAR: 1974
= 500'
N
EDR


INQUIRY #: 6284645.8
YEAR: 1971
= 500'
N
EDR


INQUIRY #: 6284645.8
YEAR: 1964
= 500'
N
EDR


INQUIRY #: 6284645.8
YEAR: 1962
= 500'
N
EDR

INQUIRY #: 6284645.8

YEAR: 1958

= 500'

N

EDR


INQUIRY #: 6284645.8
YEAR: 1953
= 500'
N
EDR


INQUIRY #: 6284645.8
YEAR: 1949
= 500'
N
EDR

INQUIRY #: 6284645.8

YEAR: 1941

= 500'

N

EDR

ATTACHMENT 4
City Directory Search Results

White Plains - 5 Parcels
42 East Post Road
White Plains, NY 10601

Inquiry Number: 6284645.5
December 02, 2020

The EDR-City Directory Image Report

Environmental Data Resources Inc
6 Armstrong Road
Shelton, CT 06484
800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RECORD SOURCES

EDR's Digital Archive combines historical directory listings from sources such as Cole Information and Dun & Bradstreet. These standard sources of property information complement and enhance each other to provide a more comprehensive report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

Data by
infoUSA®
Copyright©2008
All Rights Reserved

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

Year	Target Street	Cross Street	Source
2017	☑	☐	EDR Digital Archive
2014	☑	☐	EDR Digital Archive
2010	☑	☐	EDR Digital Archive
2005	☑	☐	EDR Digital Archive
2000	☑	☐	EDR Digital Archive
1995	☑	☐	EDR Digital Archive
1992	☑	☐	EDR Digital Archive
1987	☑	☐	Cole Criss-Cross Directory
1982	☑	☐	Cole Criss-Cross Directory
1977	☑	☐	Cole Criss-Cross Directory
1972	☑	☐	Cole Criss-Cross Directory

FINDINGS

TARGET PROPERTY STREET

42 East Post Road
White Plains, NY 10601

Year	*CD Image*	*Source*
E POST RD		
2017	pg A2	EDR Digital Archive
2014	pg A4	EDR Digital Archive
2010	pg A6	EDR Digital Archive
2005	pg A9	EDR Digital Archive
2000	pg A11	EDR Digital Archive
1995	pg A14	EDR Digital Archive
1992	pg A17	EDR Digital Archive
1987	pg A20	Cole Criss-Cross Directory
1982	pg A21	Cole Criss-Cross Directory
1982	pg A22	Cole Criss-Cross Directory
1977	pg A23	Cole Criss-Cross Directory
1972	pg A24	Cole Criss-Cross Directory

FINDINGS

CROSS STREETS

No Cross Streets Identified

City Directory Images

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2017

1	FRANCIS X MCHUGH DDS
	JOSEPH LEANZA DDS
	REGINA CHECK CASHING
	THE CENTER FOR CAREER FREEDOM
	URBAN TACTICAL CONDINTIONING
	WHITE PLAINS DENTAL MEDICAL
2	MINI MARKET & DELI
	WESTSIDE LOCKSMITH
4	KENNEDY FRIED CHICKEN
6	YOUNGS CHINESE KITCHEN
11	ADAMS SERVICE STATION AT 11 E POST R
	CARIBBEAN LITTLE MARKET
	EAGLE SERVICE INC
	VDR EXPRESS
	VDR EXPRESS MULTIPLE SERVICES
12	ARELLANO, JORGE
	CAMPOS INSURANCE AGENCY
	GARCIA, ADALJISA
	KLEIN WAGNER & MORRIS
	MICHAEL WAGNER ATTY
	RUEDA, ARMANDO G
	SANCHEZ, PABLO F
14	CRYSTA GROCERY LTD
	CRYSTAL GROCERY LTD
16	CANCUN DELIGHTS INC
	REYES, MARIA
18	CORTES, MARIA
	ROSALES, EDGAR G
	SUZANNE WEISMAN CSW
20	BURKE & MCCOWEN INC
22	BROTHERS ONE STOP DELI
24	EL TRI MULTY SERVICE
34	BARRIER WHITE PLAINS CITGO
	EAST POST ROAD GASMART INC
41	DR MARK GORDON MD PC
	ENT & ALLERGY ASSOCIATES
	ONCOLOGY & HEMATOLOGY
	SLATTERY MOVING & STORAGE
	WHITE PLAINS HOSPITAL
42	DOLLAR RENT A CAR
	WHITE PLAINS SURGICAL SUPPLIES
44	WHITE PLAINS SURGICAL SUPPLIES
60	FIRESTONE COMPLETE AUTO CARE
66	JACK & LOU REALTY CORP
	MUFFETTAS WESTCHESTER & WHITE PLAIN
	STAR DINER
68	BINDER JEFFREY PC & ASSOCIATES ATTOR
	PLAZA MEXICO
70	QUICK CASH
71	LINSCOTT, ROBERT B

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2017 (Cont'd)

71	MARTINEZ, ESTEBAN
72	NEW COUNTY OPTICAL CORPORATE OFFICE
	UNITED STATES CREDIT EXPORT CORP
79	STATE OF NEW YORK
82	FERNANDEZ & ASSOCIATES
	RENTACENTER
85	OPEN ARMS
86	LIFTING UP WESTCHESTE
87	BELLE HAIR
88	MONARCH AUTO CLUB INC
	ROSOL AGENCY
89	SIDEKICK BOTANICA ANA
92	7 DAY 24 HOURS EMERGENCY LOCKSMITH
	DIRECT LOCKSMITH SERVICE
	NEW STAR CHINESE RESTAURANT
95	GOLDEN TICKET LOCKSMITH
	LISAS HAIR SALON
96	JANILSSY BARBER SHOP
98	GALAXY SERVICENTER
	HERE WHEN YOU NEED US LOCKSMITH
	PIZZA NINI
	QUINONEZ, LUCAS
	TAOUERLA & GROCERY MEXICO
99	ROYAL SCARLET STORE
100	ROEOEOS DELI CAFE
	YOUR EMERGENCY LOCKSMITH
101	STATE OF NEW YORK
	WHITE PLAINS HOSPITAL MEDICALCENTER
102	ROBERTOS GRILL CAFE
104	JCF DECOPST & WINDOW
	JCF DECORATIONS & UPHOLSTERY
106	SUNNY NAILS
108	UNITRAVE
109	LA FONDA PAISA INC
110	WALDORF HAIRSTYLISTS
112	COUNTY GOVERNMENT SOCIAL SERVICES DE
	COUNTY OF WESTCHESTER
	CVR ASSOCIATES
	FAMILY TIES OF WESTCHESTER
	WESTCHESTER COUNTY GOVERNMENT
	WESTCHESTER COUNTY SOCIAL SERVICES D
	WESTCHESTER MEDICAL CENTER
115	MARKET MEAT & PRODUCE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2014

1	CENTER FOR CAREER FREEDOM
	FARMERS INSURANCE GROUP
	LEANZA, JOSEPH
	URBAN TACTICAL CONDINTIONING
	WHITE PLAINS DENTAL MEDICAL
2	MINI MARKET & DELI
	WESTSIDE LOCKSMITH
4	KENNEDY FRIED CHICKEN
6	YOUNGS CHINESE KITCHEN
11	EAGLE SERVICE INCORPORATED
12	ACEVEDO, ORTIZ Y
	ARELLANO, JORGE
	CAMPOS INSURANCE AGENCY
	GONZALEZ, MARTA
	HUAMAN, MIGUEL A
	KLEIN WAGNER & MORRIS
	PEREZ, EMILIA
	QUINTERO, MARIA
	RIVERA, VICTOR M
	RUEDA, ARMANDO
	SANCHEZ, PABLO F
	WAGNER MICHAEL ATTY
	WERBEL PHILLIP A
	WERBEL, PHILLIP S
14	CRYSTA GROCERY LIMITED
16	CANCUN DELIGHTS INCORPORATED
	REYES, MARIA
18	ACA, JACOBO
	MOLINA, ANDRES
	ORTIZ, CESAR
	QUINTERO, FAUSTINO
20	BURKE & MCCOWEN INC
22	BROTHERS ONE STOP DELI INCORPORATED
34	EAST POST ROAD GASMART INCORPORATED
41	DICKSTEIN CANCER TREATMENT CENTER
	GORDON MARK MD PC
	GRETZ HERBERT
	WESTCHESTER ORTHOPAEDIC INSTITUTE
	WHITE PLAINS BILLING SERVICE INCORPO
	WHITE PLAINS HOSPITAL
	WHITE PLAINS HOSPITAL CENTER
	WHITE PLAINS HOSPITAL MAIN INFORMATI
	WHITE PLAINS OPEN MRI
	WHITE PLALNS HOSPITAL
42	DOLEX
	WHITE PLAINS SURGICAL SUPPLIES
44	ONE SOURCE HOMECARE SUPPLIES INC
	ONE SOURCE HOMECARE SUPPLIES INCORPO
60	FIRESTONE COMPLETE AUTO CARE STORE
66	JACK LOU REALTY CORPORATION

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2014 (Cont'd)

66	STAR DINER
68	BINDER JEFFREY PC & ASSOCIATES ATTOR
70	QUICK CASH OF WHITE PLAINS
71	CUMMINGS, NANCY R
72	COUNTY OPTICAL COMPANY
	NEW COUNTY OPTICAL COMPANY
	NEW COUNTY OPTICAL CORPORATE OFFICE
	UNITED STATES CREDIT EXPORT CORPORAT
79	STATE OF NEW YORK
82	FERNANDEZ ASSOCIATES
	RENTACENTER
85	OPEN ARMS
86	GRACE CHURCH COMMUNITY CENTER
87	BELLE HAIR
88	MONARCH AUTOMOBILE CLUB INCORPORATED
	ROSOL AGENCY
89	SIDEKICK BOTANICA ANA
90	WESTCHESTER FURNITURE
92	DIRECT LOCKSMITH SERVICE
	LO TIN SING
	NEW STAR CHINESE RESTAURANT
93	VDR EXPRESS MULTIPLE
95	GOLDEN TICKET LOCKSMITH
	LISAS HAIR SALON
96	JANILSSY BARBER SHOP
98	ANTONIO, REYES
	HERE WHEN YOU NEED US LOCKSMITH
	LA PINIATA BAKERY TWO
99	ROYAL SCARLET STORE
100	ROEOEOS DELI CAFE
	YOUR EMERGENCY LOCKSMITH
101	OCTF
	STATE OF NEW YORK
102	ROBERTOS GRILL CAFE
104	JCF DECORATIONS & UPHOLSTERY
106	SUNNY NAILS
107	ONE STOP BOOKKEEP
108	UNITRAVE
109	LA FONDA PAISA INCORPORATED
110	WALDORF HAIRSTYLISTS
112	FAMILY TIES OF WESTCHESTER INCORPORA
	WESTCHESTER COUNTY GOVERNMENT
	WESTCHESTER COUNTY OF SOCIAL SERVICE
115	MARKET MEAT & PRODUCE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2010

1	AKIO CO
	CENTER FOR CAREER FREEDOM INC
	REGINA CHECK CASHING
	WHITE PLAINS DENTAL
	WHITE PLAINS DENTAL MEDICAL
2	MINI MARKET & DELI
	POST ROAD MINI MARKET
3	OCCUPANT UNKNOWN,
4	KENNEDY FRIED CHICKEN
6	YOUNGS CHINESE KITCHEN
11	GETTY ADAMS SVC STATION
12	ACEVEDO, ORTIZ Y
	ARELLANO, JORGE
	CAMPOS INSURANCE
	DOMINGUEZ, EMILIO T
	GOMEZ, TORIBIA
	GONZALEZ, IRENE
	HERNANDEZ, CECILIA
	KLEIN WAGNER & MORRIS
	LUNDER CENTER
	MATA, GISSELLE
	PEREZ, EMILIA
	RIVERA, VICTOR
	SANCHEZ, PABLO F
	SAYAGOS, ADRIAN
	TECUAPETLA, JOSE
	WAGNER, MICHAEL
	WERBEL, PHILLIP S
16	ADORNO, DOMINGO
	ANZURES, NISEFORO
	CANCUN DELIGHTS INC
	ROMERO, GREGORIO
18	BONILLA, ALBERTO O
	MOLINA, ANDRES
	ORTIZ, CESAR
	ZANE, JOSE T
20	BURKE & MC COWEN INC
22	BROTHERS ONE STOP DELI
	MR T LOAN CLOSER SIGNING AGENT
41	ANXIETY & PHOBIA TREATMENT CTR
	BEJINARIU DANIELA MD
	DEPARTMENT OF BEHAVIORAL HLTH
	DIABETES EDUCATION & TREATMENT
	FAMILY HEALTH CTR
	GRETZ HERBERT MD
	JAILEMARTI JESUS MD
	LABORATORY SERVICES
	NESCI MARCELLE G
	PEREIRA ANGELA MD
	PHYSICAL MEDICINE & REHAB

E POST RD 2010 (Cont'd)

41	SEIZURE DIAGNOSTIC CTR
	SIAO KATHRYN CAR MD
	SIEGEL REGIONAL STROKE CTR
	SINGH NANDITA DO
	SLEEP DIAGNOSTIC CTR
	WHITE PLAINS BREAST IMAGING
	WHITE PLAINS HIGH FIELD MRI
	WHITE PLAINS HOSPITAL
	WHITE PLAINS HOSPITAL CTR
	WHITE PLAINS HOSPITAL EMERGENC
	WHITE PLAINS HOSPITAL MED LIBR
	WHITE PLAINS PATHOLOGY ASSOC
	WHITE PLAINS RADIOLOGY ASSOC
42	DOLEX DOLLAR EXPRESS
44	ONE SOURCE HOMECARE SVC
	RAKOFF REALTY
60	STS TIRE & AUTO CTR
66	STAR DINER
	YALE PRESS
68	JEFFREY BINDER PC & ASSOC
69	SALZER SENIOR SVC PROGRAM
	WESTCHESTER CARING SVC
71	AWAD, MERVAT
	EHNES, PETRINA H
	LINSCOTT, ROBERT B
	MARTINEZ, LUCIA
	NORVILLE, A
	OHLSSON, BEN
	STREET, ALLENE H
	WAY, KEN A
72	NEW COUNTY OPTICAL CO
	NEW YORK STATE EYEGLASSES
	UNITED STATES CREDIT EXPORT
79	MENTAL HEALTH OFFICE
82	FERNANDEZ & ASSOC
84	RENTACENTER
86	OPEN ARMS SHELTER & SOCIAL SVC
87	CHRIS BEAUTY SALON
88	CY MARK AGENCY INC
	LINSCO PRIVATE LEDGER FNCL SVC
89	VDR EXPRESS MULTIPLE SVC
90	WHITE PLAINS FURNITURE
92	NEW STAR CHINESE RESTAURANT
93	ALO BRASIL CORP
94	ALEXANDER WINES & SPIRITS
95	LISAS HAIR SALON
98	ANTONIO, REYES
	BEST DOMINICAN HAIR SALON
	GRACIELLA BAKERY
99	ROYAL SCARLET STORE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2010 (Cont'd)

100	ROEOEOS DELI CAFE
101	ATTORNEY GENERAL
	OCTF
	ORGANIZED CRIME TASK FORCE
	US ATTORNEY
102	ROBERTOS GRILL CAFE
104	JCF DECORATIONS & UPHOLSTERY
106	LIBERTY NAIL SALON INC
107	1 STOP BOOKKEEPING INC
	ONE STOP BOOKKEEP
	STORMS BARBER SHOP
109	LA FONDA PAISA INC
110	WALDORF HAIRSTYLISTS
111	COMMUNICATION WIRELESS
112	ADOPTION & FOSTER CARE
	FAMILY TIES OF WESTCHESTER INC
	STOP DWI
	WESTCHESTER BUREAURESOURCES
	WESTCHESTER CNTY CONSUMER PRO
	WESTCHESTER CNTY WEIGHTS & MSR
	WESTCHESTER COMMISSIONER OFF
	WESTCHESTER COUNTY CSEA
	WESTCHESTER COUNTY EMPLOYMENT
	WESTCHESTER COUNTY HEAP
	WESTCHESTER COUNTY HOME
	WESTCHESTER COUNTY HUMAN RIGHT
	WESTCHESTER COUNTY MENTAL HLTH
	WESTCHESTER COUNTY OFC WOMEN
	WESTCHESTER COUNTY SOCIAL SVC
	WESTCHESTER COUNTY VETERAN SVC
	WESTCHESTER COUNTY WATER AGNCY
	WESTCHESTER COUNTY YOUTH BUR
	WESTCHESTER HEAP PROGRAM
115	INTERNATIONAL MERCHANT SVC
	MARKET MEAT & PRODUCE

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2005

1	CENTER FOR CAREER FREEDOM INC
	COMPREHENSIVE HOME CARE
	MCHUGH, FRANCIS X
	REGINA CHECK CASHING
2	MINI MARKET & DELI
4	KENNEDY FRIED CHICKEN
11	POST ROAD GETTY
12	372 5TH AVENUE LLC
	ACEVEDO, ORTIZ Y
	ARELLANO, JORGE
	CAMPOS INSURANCE AGENCY
	CAMPOS, NANCY
	COLON, MARIA
	DIAZ, LUZ
	GOMEZ, REYNA
	GONZALEZ, MARTA
	HERNADEZ, C
	SANCHEZ, PABLO F
	SAYAGOS, ADRIAN
	TECUAPETLA, JOSE
	WAGNER, MICHAEL
	WERBEL, PHILLIP S
16	CANCUN DELIGHTS INC
	GONZALEZ, IRENE
	HILDAGO, ALCADIO
	REYES, MARIA
	ROJAS, FELIPE
	SERRANO, SYLVIA
18	ARENAS, IRENE
	BURKE & MC COWEN INC
	LLANOS, ERICK
	LOPEZ, LAURA
	MOLINA, ANDRES
	ORTIZ, CESAR
	RENDON, T
	VASQUEZ, GREGORI
	VERDIN, DELIA
	ZANE, JOSE T
20	BURKE & MCCOWEN INC
22	TUNDES MERCHANDISE MART
24	ZAMBRANO, EDITH
34	BARRIER WHITE PLAINS CITGO
41	FAMILY HEALTH CENTER
	WHITE PLAINS RADIOLOGY ASSOCS MRI FA
42	UNION ENTERPRISES
44	CORNELL CONSTRUCTION LLC
	GRAND DEVELOPMENT LLC
	RAKOFF REALTY
65	MARIEM HAIR BRAIDING
66	CHARKOW PRINTING INC

E POST RD 2005 (Cont'd)

66	STAR DINER
	YALE PRESS
68	LA SALLE & BINDER LLP
	LASALLE & BINDER LLP
	NEW YORK STATE EYEGLASSES
	VERNON OPTICAL INC
71	AWAD, MERVAT
	COLEMAN, DAVID A
	CUMMINGS, DANIEL J
	EHNES, PETRINA H
	FRANCISCHELLI, BETH A
	PURRIER, KERRIEANNE A
	SHERLOCK, TARA M
	WILHELM, ANNMARIE M
77	WHITE PLAINS HOSPITAL SENIOR SERVICE
79	JEROME CYNTHIA
84	SALVATION ARMY
86	OPEN ARMS MENS SOCIAL SERVICE
	PHOENEX MCGEACHEYS SHIRTS
88	CY MARK AGENCY INC
	L P L FINANCIAL SERVICES
	WATERMAN WILLIAM J AGENCY
89	ALO BRASIL CORP
92	0 & 0 & 0 1 24 HOUR A EMRGNCY
93	ALO BRASIL
96	ERIC GROCERY
98	BEST DOMINICAN HAIR SALON
	TAQUERIA & GROCERY MEXICO LINDO
99	ROYAL SCARLET STORE
100	OCCUPANT UNKNOWN,
101	NEW YORK STATE DEPARTMENT OF LAW OFF
	NEW YORK STATE ORGANIZE CRIME TASK F
104	RIO GEM
107	MARIA IRIZARRY CALL AMERICA EXPRESS
109	LA FONDA PAISA INC
110	WALDORF HAIRSTYLISTS
111	FERNANDEZ, EDUARDO
	WIRELESS SOLUTION CTR
112	CANNARIATO, THOMAS A
	CSEA
	LEXINGTON CENTER FOR RECOVERY 2003
	WESTCHESTER CNTY SOC SERVICE
	WINCHESTER COUNTY DEPT OF COMMUNITY
115	GABRIEL FOOD MARKET

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2000

1	COMPREHENSIVE HOME CARE INCORPORATED
	LEANZA JOSEPH DDS
	MCHUGH FRANCIS X DDS
	REGINA CHECK CASHING
	WESTCHESTER COUNTY DEMOCRATIC COMMITTEE
	WHITE PLAINS DENTAL MEDICAL
2	POST ROAD MINI MARKET
4	KENNEDY FRIED CHICKEN
6	YOUNGS CHINESE KITCHEN
11	POST ROAD GETTY
12	ARELLANO, JORGE
	DELATORRE, F
	DOMINGUEZ, EMILIO
	GOMEZ, ALFREDO
	KLEIN WAGNER & MORRIS
	MARTINEZ, JORGE A
	MOLNAR INSURANCE AGENCY
	PADRO, L
	RUEDA, ARMANDO
	WAGNER MICHAEL ATTORNEY
	WERBEL PHILLIP A ATTORNEY
	XELO, R D
14	JARA, MARIA
	ZHUMI, DANIEL
16	BUSTAMANTE, MARIA
	CANCUN DELIGHTS INCORPORATED
	GONZALEZ, IRENE
	QUINTERO, JUAN
	REYES, JUAN C
18	ADORNOPAVON, DOMINGO
	LOPEZ, LAURA
	MINCHALO, FABIAN A
	MOLINA, ANDRES
	ORTIZ, CESAR
	QUINDE, MARIA
	QUINTERO, MIGUEL
	VERDIN, DELIA
	ZANE, T
20	BURKE & MCCOWEN INCORPORATED HARDWARE
22	TUNDE COCKTAIL LOUNGE
	TUNDES ONE STOP DELI
34	BARRIER WHITE PLAINS CITGO
	OCCUPANT UNKNOWN,
41	WHITE PLAINS BILLING SERVICE INCORPORATED
	WHITE PLAINS HOSPITAL HOME CARE
	WHITE PLAINS OPEN MRI
42	UNION ENTERPRISES
	WALKER RESPIRATORY HOME CARE
44	RAKOFF REALTY
	UNITED STATES K 9 ACADEMY

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2000 (Cont'd)

60	RAMAPO DISCOUNT TIRE CENTERS
66	CHARKOW PRINTING INCORPORATED
	STAR DINER
	YALE PRESS THE
68	VERNON OPTICAL
69	LAMARIA TRAVEL AGENCY
70	WALKER SURGICAL ASSOCIATES
71	AUBRY, JILL
	BERNARD, ODETTE
	CHIARAMIDA, ANDREW
	COMPUZANO, FRANZIA
	CUMMINGS, DANIEL
	EBERHART, MAJA
	EHNES, PETRINA
	HINDLEY, C
	PRIBILA, ANTHONY
	SHERLOCK, TARA
	SMITH, ELSA M
	STEPHENS, EDWIN C
	STROTHERS, CAROL A
	WAY, KEN
	WILHELM, A
72	COMPU GRAPHIC
	COUNTY OPTICAL COMPANY
	NEW COUNTY OPTICAL COMPANY
	NEW COUNTY OPTICAL INCORPORATED CORPORATION OFFICE
	UNITED STATES CREDIT EXPORT CORPORATION
73	YORK HUNTER
79	BERGSTEIN & MOSKOWITZ FACIAL PLASTICS
	BLOTNER MICHAEL B
	EISMAN WAYNE B MD
	ROSENBERG RICHARD MD
	RYBACK HYMAN MD
	SEVERINO LAWRENCE J MD
	TONSE, JACK S
	WESTCHESTER FERTILITY REPRODUCTIVE ENDOCRINOLOGY
84	SALVATION ARMY THE
86	GATTISON, PAUL
	OPEN ARMS SHELTER & SOCIAL SVCE CENTER
87	CHRIS BEAUTY SALON
88	ABC SURCO LIMITED
	CY MARK AGENCY INCORPORATED
	MONARCH AUTO CLUB INCORPORATED
	ROSOL AGENCY
	WATERMAN WILLIAM J AGENCY
89	ALO BRASIL
	EAST COAST MOTOR CLUB MARKETING INCORPORATED
90	AMERICAN FACTORY FURNITURE WHOSL DISTRBTRS
	WHITE PLAINS FURNITURE & BEDDING
91	COPIES & ENGRAVING CENTER

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 2000 (Cont'd)

92	CHEUNG TIN HO
	LO TIN SING
	NEW STAR CHINESE RESTRNT
94	CALLAHANS WINES & LIQUORS
95	LISA HAIR SALON
96	GREEN FARMS
97	ANTHONYS CUSTOM TAILOR
	JOHN CURRAN CUSTOM MADE KILTS
98	TAQUERIA & GROCERY MEXICO LINDO
99	ROYAL SCARLET STORE
100	GRAND POST MARKET
101	POST ROAD ASSOCIATES LLC
	UNITED STATES GOVERNMENT OFFICES JSTC DEPARTMENT OF
	ZAK, J J
102	PHIL AM FOOD MART
106	INDEPENDENT PRINTING COMPANY INCORPORATED
	INDEPENDENT PRINTING INCORPORATED
107	TORRES, JUAN H
109	A & L SPORTS CENTER INCORPORATED
	LAFONDA PAISA INCORPORATED
110	WALDORF HAIRSTYLISTS
111	ANGELICAS MULTI SVCE
112	ADOPTION & FOSTER CARE WESTCHESTER COUNTY SOCIAL SERVICES
	ADPTN & FSTR CARE WESTCHESTER CNTY SCL SERVICES
	BEE LINE SYSTEM
	DRUG HELPLINE
	WESTCHESTER CNTY ARPRT WHT PLAINS ARPRT TRANSPORTATION
	WESTCHESTER CNTY OF ALL DEPARTMENTS & COURTS CONSUMER P
	WESTCHESTER CNTY OF ALL DEPARTMENTS & COURTS MENTAL HEALTH
	WESTCHESTER CNTY OF ALL DEPARTMENTS & COURTS PROBATION
	WESTCHESTER CNTY OF ALL DEPARTMENTS & COURTS SCL SERVICE
	WESTCHESTER CNTY OF ALL DEPARTMENTS & COURTS TRANSPORTATION
	WESTCHESTER CNTY OF CONTD COURTHOUSE CALENDAR CLE
	WESTCHESTER CNTY OF CONTD SCL SERVICES DEPARTMENT
	WESTCHESTER COUNTY OF ALL DEPARTMENTS & COURTS
	WESTCHESTER COUNTY OF CONSUMER PROTECTION
	WESTCHESTER COUNTY OF CONTD BRANCH OFFICES
	WESTCHESTER COUNTY OF CONTD WOMEN OFFICE FOR
	WESTCHESTER COUNTY OF MENTAL HEALTH DEPARTMENT OF
115	GABRIEL FOOD MARKET

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1995

1	COMPREHENSIVE HOME CARE INC
	LEANZA, JOSEPH, DDS
	MCHUGH, FRANCIS X, DDS
	REGINA CHECK CASHING
	WESTERN UNION-TO PICK-UP OR SEND MONEY OR TR-REGINA CHECK CA
	WHITE PLAINS DENTAL MEDICAL
2	POST ROAD MINI MARKET INC
4	KENNEDY FRIED CHICKEN
6	YOUNG'S CHINESE KITCHEN
11	FRANK'S AUTO SERVICE
	FRANK'S TOWING
12	KLEIN WAGNER & MORRIS
	MOLNAR INSURANCE AGENCY
	WAGNER, MICHAEL, ATTY
	WERBEL, PHILLIP A, ATTY
14	UNION FOOD MARKET
16	CANCUN DELIGHTS INC
20	BURKE & MCCOWEN INC, HRDWR
22	OLADIPO, HAZEL, NOTARY PUBLIC
	OLADIPO, OLATUNDE, NOTARY PUBLIC
	ONE STOP DELI
	TUNDE'S COCKTAIL LOUNGE
	TUNDE'S ONE STOP DELI
	WESTERN UNION-TO PICK-UP OR SEND MONEY OR TR-ONE STOP DELI
34	MARIANINA OIL CORP
41	BARR & BARR INC
	MECHANICAL CONSTR CORP
	SECO CONCRETE CONSTRCTN
42	BRAKES FOR LESS
	RRR WAXING & DETAILING LTD
	UNION ENTERPRISES
	WALKER RESPIRATORY HOME CARE
	WALKER SURGICAL ASSOCIATES
44	RAKOFF REALTY
60	FIRESTONE OF WHITE PLAINS
	WESTCHESTER TIRE CO INC
65	BRITTANY & THE BOYS
	COOKIE MANAGEMENT
66	CHARKOW PRNTNG INC
	F P O GRAPHICS
	STAR DINER
	YALE PRESS THE
68	VERNON OPTICAL
	WESTCHESTER COUNTY CORRECTION OFFICERS BENEVOLENT ASSN
69	LA MARIA TRAVEL AGENCY
72	COMPU GRAPHIC
	COUNTY OPTICAL CO
	NEW COUNTY OPTICAL CO
	NEW COUNTY OPTICAL INC, CORP OFC
	UNITED STATES CREDIT EXPORT CORP

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1995 (Cont'd)

79	BERGSTEIN & MOSKOWITZ FACIAL PLASTICS
	BLOTNER, MICHAEL B
	EISMAN, WAYNE B, MD
	MOSKOWITZ, DAN, MD
	NATIONAL HEALTH LABS
	ROSENBERG, RICHARD, MD
	RYBACK, HYMAN, MD
	SEVERINO, LAWRENCE J, MD
	SOLOMON, ELLIOTT, MD
	VALDES, MARIE E, MD
	WESTCHESTER FERTILITY REPRODUCTIVE ENDOCRINOLOGY
	WESTCHESTER HEARING SVCE
	WESTCHESTER OTOLARYNGOLOGY ASSOCS PC
82	NEW POST PHARMACY
86	OPEN ARMS SHELTER & SOCIAL SVCE CENTER
87	CHRIS' BEAUTY SALON
88	ABC SURCO LTD
	CY MARK AGENCY INC
	MONARCH AUTO CLUB INC
	ROSOL AGENCY
	WATERMAN, WILLIAM
89	ALO BRASIL
91	COPIES & ENGRAVING CTR
92	CHEUNG TIN HO
	LO TIN SING
	NEW STAR CHINESE RESTRNT
94	CALLAHAN'S WINES & LIQUORS
95	LISA HAIR SALON
96	GREEN FARMS
97	ANTHONY'S CUSTOM TAILOR
98	EL MAMBO RESTAURANT
99	ROYAL SCARLET STORE
100	GRAND POST MKT
101	RAHMANI CONSTR CORP
	US GOVERNMENT-JUSTICE DEPT OF-US ATTORNEYS OFCC
102	PHIL-AM FOOD MART
	WESTCHESTER HOBBIES
104	SCHLEICHER ELECTRONIC INC
106	INDEPENDENT BLUE PRINT & SUPL INC
	INDEPENDENT PRINTING INC
	INDEPENDENT PRNTNG CO INC
109	A & L SPORTS CENTER INC
	ANL SPORTS CENTER INC
	LA FONDA PAISA INC
	LETTER PERFECT MONOGRAMS
110	WALDORF HAIRSTYLISTS
112	ADOPTION & FOSTER CARE WESTCHESTER COUNTY SOCIAL SERVICES
	DRUG HELPLINE
	WESTCHESTER COUNTY AIRPORT-WHITE PLAINS-AIRPORT TRANSPORTATI
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-CRIMINAL JUSTICE S

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1995 (Cont'd)

112 WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-DRUG HELPLINEE
WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-MENTAL HEALTH DEPT
WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-SOCIAL SERVICES DE
WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-WEIGHTS & MEASURES
115 ANGELICA FOOD MARKET

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1992

1	CARLONI, EDMUND, MD
	COMPREHENSIVE HOME CARE INC
	LEANZA, JOSEPH, DDS
	MCHUGH, FRANCIS X, DDS
	PAN AMERICAN INVESTIGATION SVCE
	REGINA CHECK CASHING
	WESTERN UNION-TO PICK UP OR SEND MONEY TRANS-REGINA CHECK CA
	WHITE PLAINS DENTAL MEDICAL
4	HUTTON'S WEST INDIAN INN
11	FRANK'S AUTO REPR
12	DE LA TORRE, FRANCISCO
	DEBUONO, MARY
	DOMINGUEZ, EMILIO
	DOMINGUEZ, GAUDENCIA
	EADIE, B
	KLEIN WAGNER & MORRIS
	MEZA, MARIO
	MOLNAR INSURANCE AGENCY
	PADRO, L
	RUEDA, ARMANDO
	TAYLOR, MARGARET
	WAGNER, MICHAEL, ATTY
	WERBEL, PHILLIP A, ATTY
16	CANCUN DELIGHTS INC
18	AAROZ, MARTIN
	ARELLANO, JORGE
	FLOOK, TARA
	MAYA, VICTOR
	VASQUEZ, BENITO
20	BURKE & MCCOWEN INC, HRDWR
22	BOWEN, TRALISA
	BROWN, MORTIMER
	CAMPBELL, AZARIAH
	HILL, AGNES
	TUNDE COCKTAIL LOUNGE
	TUNDE'S COCKTAIL LOUNGE
24	MIRTHIL, JOSEPH
27	MINIT-MAN CAR WASH
41	SONNEBORN, WALTER, OFC
42	LHR LIMOUSINE LTD
	RRR WAXING & DETAILING LTD
44	RAKOFF REALTY
60	FIRESTONE OF WHITE PLAINS
	WESTCHESTER TIRE CO INC
65	BRITTANY & THE BOYS
66	CHARKOW PRNTNG INC
	YALE PRESS THE
68	WESTCHESTER COUNTY CORRECTION OFFICERS BENEVOLENT ASSN
69	LA MARIA TRAVEL AGENCY
	VIGO REMITTANCE TRAILWAYS INC

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1992 (Cont'd)

70	SCHLEICHER ELECTRONIC INC
71	BARTH, KATHERINE
	BESSETTE, MARIE E
	DABY, JANET
	DAHLSTROM, FRANCES
	EBERHART, MAJA
	FORRESTER, JOHN
	LUCHI, C
	LYNCH, MARJORIE H
	MAENZA, LEONARD M
	MATA, FAYE F
	MAYERS, MARJORIE
	MCGAHREN, WM
	MEEHAN, DESMOND
	QUINN, F
	SHERLOCK, T
	STEPHENS, EDWIN C
	WHITE, FRED
72	COUNTY OPTICAL CO
	NEW COUNTY OPTICAL CO
	NEW COUNTY OPTICAL INC
75	ONE STOP DELI
	TUNDE'S, MDSE MART
77	COUNTY HOME CLNG SVCE INC
79	EISMAN, WAYNE B, MD
	MOSKOWITZ, DAN, MD
	NATIONAL HEALTH LABS
	ROSENBERG, RICHARD, MD
	RYBACK, HYMAN, MD
	SEVERINO, LAWRENCE J, MD
	SOLOMON, ELLIOTT, MD
	VALDES, MARIE E, MD
	WESTCHESTER HEARING SVCE
	WESTCHESTER OTOLARYNGOLOGY ASSOCS PC
82	POST PHARMACY
84	DUN-RITE PRNTNG & MAILING
	SALVATION ARMY THE-THRIFT STORES
86	OPEN ARMS SHELTER & SOCIAL SVCE CENTER
87	CHRIS' BEAUTY SALON
88	ABC SURCO LTD
	CY MARK AGENCY INC
	MONARCH AUTO CLUB INC
	NALVEN & NALVEN INC
	NAVY RECRUITING STAS WHITE PLAINS
	ROSOL AGENCY
	ROSOL ASSOCS
	WATERMAN, WILLIAM
91	COPIES & ENGRAVING CTR
92	CHEUNG TIN HO
	LO TIN SING

Target Street	Cross Street	Source
✓	-	EDR Digital Archive

E POST RD 1992 (Cont'd)

92	NEW STAR CHINESE RESTRNT
93	ENRICO'S LATIN VIDEO
94	CALLAHAN'S WINES & LIQUORS
95	PROMOTIONAL MAILING SVCES
96	GREEN FARMS
97	ANTHONY'S CUSTOM TAILOR
99	ROYAL SCARLET STORE
100	GRAND POST MKT
101	RAHMANI CONSTR CORP
	US GOVERNMENT-JUSTICE DEPT OF-US ATTORNEYS OFC
102	PHIL-AM FOOD MART
	WESTCHESTER HOBBIES
104	SUBURBAN FLOOR COVERING SPECIALISTS INC-BRANCH OFFICE
	SUBURBAN RESILIENT FLOORS INC-MAIN OFFICE
106	INDEPENDENT BLUE PRINT & SUPL INC
	INDEPENDENT PRINTING INC
	INDEPENDENT PRNTNG CO INC
109	A & L SPORTS CENTER INC
	ANL SPORTS CENTER INC
	LA FONDA PAISA INC
	LETTER PERFECT MONOGRAMS
110	WALDORF HAIRSTYLISTS
112	ADOPTION & FOSTER CARE WESTCHESTER COUNTY SOCIAL SERVICES
	DRUG HELPLINE
	WESTCHESTER COUNTY OF ALL DEPTS & COURTS SOCIAL SERVICES DEP
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-CRIMINAL JUSTICE S
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-DEPT OF HEALTH-MAI
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-DEPT OF SOCIAL SER
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-MENTAL HEALTH DEPT
	WESTCHESTER COUNTY OF, ALL DEPTS & COURTS-OFC FOR WOMEN-INFO
115	EHMER KARL QUALITY MEATS
6612	STAR DINER

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

E POST RD 1987



POST RD E

968 Alexander T Molloy .74 723-7384
972 J Gerard .79 472-4484
973 NP
975★ All Star Phtgrphy .83 725-5701
Deborah Feuerstein .79 725-5701
978 NP
979 Kenichi Futamura .81 725-1738
980 Paul C Molloy .62 725-2688
981 Emma R Maclsco .73 472-6729
John J Maclsco Jr .72 723-0312
983 K Bauernfeind .79 472-6345
★ Durco Realty Co .79 472-1116
986 Ted S Chang .77 723-8693
988 NP
990 Ed Yeaker .76 472-8936
Edward Yeaker .76 725-0560
994 James Wetmur .75 472-5868
999★ Scarsdale Amoco .85 723-6998
1000 Leonard C R Langer .65 723-4977
1005★ Commercl Flooring .83 723-0060
1015 A Galvani .77 472-1803
Diana Gomez .85 725-3358
Peter Jeffcote - 472-8483
Edw B Schneiderman .77 472-1803
1020 Barbara S Curran .79 472-3064
1023★ R H Behr ¤ 723-9211
1025★ Benchmark Consultn - 328-0131
★ Benchmark Consultn ¤ 472-5010
1039★ Jr League Cntrl WC .84 723-6130
★ Jr League Scarsdle 723-6130
Larry Kelly .75 725-4404
★ Scarsdale Bd Educ .85 723-7343
★ Wayside Cottage 723-6130
1084 Walter J Hasselman .65 723-4653
1108 E Carrington ¤ 723-5323
Charles Harris .76 472-9873
1109 Kimberly H Lanoil .79 723-2188
1112 A Darienzo .78 472-2047
★ Armand Darienzo .78 472-3489
★ Darienzo Sweet Stu .82 472-3489
★ MCS Ltd .83 472-3489
1120 S R Mehta .84 472-0564
1126 M C McDermott .84 725-4324
1130 Thomas P Vagi .78 723-3764
1134 Joseph Meliti .81 725-5275
1140 Augilino Capone .85 472-7652
1146 Peter Schneckner .78 723-1293
1147★ Dr Sachdev&Assoc .77 472-3682
1156 D Frasca .76 628-2888
D Frasca ¤ 472-5731
D Frasca .76 472-8863
P Madden - 472-9022
A Giuseppe Occhicone .74 725-0105
1157 Joseph A Bruno .74 723-2044
1158 Matthew Przistup .85 472-8554
1159 NP
1162 Neal S Comer .80 472-3324
1175 B Bianco .83 725-4129
1177 NP
1178 Kouji Fujino .77 472-6486
David Lo ¤ 725-2944
1179 Barney Eisenberg .72 472-3239
Barney Eisenberg .72 472-4319
1181 Robert W Murray .70 472-1017
1183 A Harutunian .61 472-9008
1184 John D Furniss .74 472-6581
John D Furniss ¤ 723-1993
1185 NP
1186 S Dumbrouzksy ¤ 472-7117
Naomi L Lipman .67 723-6192
1187 C L Bailey .84 472-1085
1189 Robert A Klein .84 472-1365
1191 NP
1197★ Dr D J W Escher 723-5039
★ Dr George C Escher 723-5039
1198★ Dr Y Taketomo .85 472-8168
1199 Leonard Levine .61 472-1521
1201 Mark Kleinman .82 725-4875
1203 Malcolm C Weiss .61 723-3787
1205 Howard L Fried .54 723-5091
1207 E L Paisner .81 723-4270
David M Stern .85 723-4270
1209★ Dr T Cherbuliez 723-0920
Dr Theo Cherbuliez .63 472-1291
Sheila Flynn .85 472-9454
Timothy Scott .85 472-9454
1216 Edward Tostanoski .62 723-5794
Tim Tostanoski .81 472-9574
1217 Toshio Shigamatsu .73 723-5180
1219 NP
1221 Janice Cohen .82 472-0489
Jonathan Cohen .84 472-0489
Nancy Cohen .84 472-3759
1230★ Dr Milton M Zaret 723-9129
Dr Milton M Zaret .61 723-9150
1231 Albert Rosenthal .70 472-3526
1234 James Vath - 472-5247
1235 Frank B Foster .73 723-8815
1237 Evan F Friedman .77 472-2052
Herbert J Friedman .75 472-9752
1238 E G Ehrlich .68 723-3087
1239 Elliot Rosen .79 725-2668
★ Dr Elliott J Rosen .79 723-0316
P K Rosen .84 725-2774
1241 NP
1243 Bertram Slanoff 472-4823
1245★ Kuttner Ins Brkrge 725-4090
1247 C Goebel .61 472-4770
1248 Burton M Fendelman .68 725-0292
1250 Edwin B Giventer .61 472-4035
1251 Joaquin A Amero ¤ 723-5825
1253 John D Hawkins Jr .81 725-1448
1255 W M Schwartzenberg .61 472-2098
1258 NP
1259 Stephen Ciccone .72 472-2511
NO #★ Vlg Recr Dept .85 723-6602
NO #★ Vlg Pulbic Wks ¤ 723-8238
144 RESIDENCE 59 BUSINESS

● **POST RD E** **10601**
White Plains PO
1- 159 CT 93 $C,H 4
160- END CT 94 $C,H 4
1★ AA Best Ofc Furn .78 682-9700
★ A A Ofc Furniture .81 682-9700
★ Cncl Arts Wstrchtr .83 428-4220
★ East West Design .83 997-5686
★ Dr Joseph Leanza ¤ 682-5105
★ Dr F X McHugh ¤ 682-5105
★ Pan Amer Investgtn .77 949-0118
★ Wht Plns Dntl Med ¤ 682-5105
2★ Hollywd Grdn Flwr 949-6330
6★ D&C Simons Inc ¤ 683-5888
11★ Franks Auto Repair .82 946-7799
★ G Lambros Serv Ctr .82 948-9860

12 Wanda Alvarez .85 946-6342
Mary Debuono .68 949-2585
B Eadie .71 949-1293
I Lopez .85 948-3377
★ Molnar Ins Agency .81 761-3220
Francisa Reyes ¤ 428-2100
Petra Sanchez .82 949-3824
Mrs Margt Taylor .68 949-2853
14★ Yeagers Cycle Str 949-3305
16 NP
18 Joseph Arone .78 761-5373
Fransico Cruz - 946-5349
Emilio Dominguez ¤ 949-3809
Wayne Hughes ¤ 681-0411
Marcelino Quintero ¤ 681-0611
B Rainford .83 946-1676
20★ Burke&Mccowen Inc 949-2289
24 NP
27★ Minit-Man Car Wash 946-7012
34★ Nrthvll Gasoline .84 684-8126
41★ Dr G Rinzler .72 946-6646
★ Dr Mira Rinzler .72 946-6646
★ Dr W Sonneborn .82 946-9898
42-42★ Walker Surg ASC .83 946-1436
42-44★ Autosound Unlmtd .81 761-2226
★ Autosound Cnsltnts ¤ 328-0822
★ Cher-Robs .84 681-0646
★ Walkr Resptry .83 948-1696
44★ Penn Auto&Plt Glss .79 997-7777
60★ Firestone Wht Plns 948-2348
★ Wchstr Tire Co Inc .73 949-2346
66★ Charkow Printing .75 949-6154
★ The Yale Press 949-9154
½★ Star Diner 684-8701
68★ Alvin R Yapalater .73 949-7688
70★ Schleicher Electrn .76 948-7575
71 Mrs K Barth .59 946-8161
Marie E Bessette .70 946-8355
Ruth Briggs .76 949-9210
Frances Dahlstrom .68 946-8954
Maja Eberhart .84 948-3388
John Forrester .79 428-4928
C Luchi .76 948-7184
Mrs M H Lynch .70 948-6965
Leonard Maenza .53 946-2826
Mrs M Mayers .70 949-5551
William McCahren .81 761-5921
Desmond Meehan .82 948-2028
F Quinn .65 946-6109
T Sherlock .84 946-5814
Joseph Sposato .74 946-0464
Edwin C Stephens .63 946-1812
Fred White .62 949-9478
72★ County Optical Co .71 949-9108
★ New County Optical .83 949-9108
75★ One Stop Deli .85 682-9320
★ Tundes Mdse Mart .84 682-9320
77★ County Home Cleang .79 957-7966
★ County Home Paint .79 957-7966
79★ D M Foreign Car .81 328-5911
★ Galleria Servc Stn .83 328-5911
82★ Post Pharmacy .81 949-9454
84★ Dun-Rite Prntg&Mal .81 946-1621
★ Salvation Army Inc .84 946-7106
87★ Central Ofc Equipt 948-4419
88★ Abortion Referral .73 948-5533
★ Air Force US Rcrt .85 946-1149
★ Dr Edmund Carloni .85 997-3111
★ Family Planning .73 948-5533
★ Food Substn Abuse .85 949-7898
★ Navy Recruitng Sta .78 949-3412
★ Psychiatc Serv Ctr .77 948-7898
★ US Army Recruitng 328-0021
90★ Ctr For Safety .80 761-6748
★ Ctr For Safety .80 946-5208
★ Gabmar Rlty Corp .85 946-5258
★ White Plns Drvg Sc .80 761-6748
91★ Amer Engrvng&Copy ¤ 328-0909
91-93★ Amer Engrvng&Copy - 761-2356
92★ New Star Chns Rst .85 997-5268
94★ Callahans Wines&Lq 945-1444
95★ Promotionl Mailing 761-2610
96★ Qlty Electrncs Inc .85 948-2701
97★ Anthonys Cstm Tlr 948-1130
98★ Shamrock Cafe 684-9448
★ Shamrock Cafe ¤ 684-9454
99★ Royal Scarlet Str 946-1826
100★ Grand Post Mrkt 949-4522
101★ Rahmani Constr .84 949-6801
★ US Ct Bnkrpt Jdge .85 683-9755
★ US Marshalls Ofce .84 683-9561
★ US Attorney .84 683-9550
★ US Probatn-Curry - 761-3808
★ US Probatn-Spann - 761-3809
★ US Probatn-Tyne - 761-3856
★ US Dist Ct Clrk .84 683-9501
★ US District Judge .84 683-9552
★ US Magistrate .84 683-9510
★ US Probation .84 761-3803
102★ Thomsons Art Store .70 945-4885
★ Westchestr Hobbies 949-7943
104★ Suburban Fir Cvrng 949-1148
★ Subrbn Resint Flrs 949-1148
106★ Indpdt Blue Print .82 946-7406
★ Indpd Prntng Co .82 946-7406
109★ ANL Sports Center .74 946-1665
★ Ltr Prfct Mngrms .85 946-1665
★ Ristorante G .84 946-3272
110★ Waldorf Hairstylst 946-4209
111★ Caprice Beauty SLN 946-8113
★ Military Athletic ¤ 683-8508
112★ Adoption&Foster Cr ¤ 285-5260
★ Cou Crmnl Planng ¤ 285-5566
★ Co Health Ofc .82 285-5100
★ Co Air Plution .82 285-5021
★ Co Chld Hlth Svcs .82 285-5140
★ Co Commncbl Dises .82 285-5111
★ Co Hlth Complaint .82 285-5100
★ Co Hlth Comptrlr .82 285-5170
★ Co Dentl Hlth Sv .82 285-5110
★ Co Health Food 285-5100
★ Co Hlth Food Sani .82 285-5020
★ Co Handicp Childrn .82 285-5202
★ Co Hlth Edu Info .82 285-5150
★ Co Hyprtnsn Info .82 285-5027
★ Co Intr Hlth Certf .82 285-5111
★ Co Land Dvlpmt .82 285-5042
★ Co Lead Informtn .82 285-5130
★ Co Mdcl Rehab .82 285-5202
★ Co Hlth Nutritn .82 285-5123
★ Co Orthodontic .82 285-5197
★ Co Prsnl Hlth Sv .82 285-5070
★ Co Plng&Evltn .82 285-5080
★ Co Pblc Hlth Nrsg .82 285-5091
★ Co Pblc Wtr Sply .82 285-5025

R OR PHOTOGRAPHED IN ANY MANNER WHATSOEVER EXCEPT AS AUTHORIZED BY THE PUBLISHER.
83,84,85,Etc. — Year First Listed 1983,84,85,Etc $A1B,Etc — Census Tract Wealth Rating CL10 — Map Location

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

E POST RD 1982

POST RD E 10601

White Plains PO

1- 159 TZ 93 $E..N 4

160- END TZ 94 $D..N 4

095450

1	★AA Best Ofc Furn	682-9700
	★Fairfield Stereo	761-7569
	★R C Kleinberger	949-3639
	★L&C Dental Lab	946-0418
	★Pan American Inv	949-0118
	★Pan American Inv	949-1888
	★Westchstr Stereo	761-7569
2	★Hollywd Grdn Flwr	949-6330
4	★Post Pizza Shop	761-9888
6	★Molnar Ins Agency ¤	761-3226
11	★Prestos Flying A	948-9860
	★Prestos Serv Sta	948-9860
	★Prestos Svc Sta	946-1471
12	Mary Debuono .68	949-0645
	B Eadie .71	949-1263
	John Henry .74	428-7234
	James Hoffman .78	946-7194
	Mike Soto ¤	428-3208
	J Stover .78	949-3518
	Mrs Margt Taylor .68	949-2851
14	★Yeagers Cycle Str	949-3305
16	S P Canseco .68	761-0061
18	Joseph Arone .78	761-5275
	Verna J Fuller	949-9219
	Richard Gehrung .63	946-2693
	E Hendricks .78	428-3671
	Mrs Anette Tart	946-8260
20	★Burke&Mccowen Inc	949-2389
	Bishop M Minter .73	761-4319
22	★Ggs Place	946-9894
	★G Gs Place	949-9336
24	NP	
26	★Carrousel Pwr Tst ¤	946-8257
	★Carrousel Pwr Tst ¤	948-9771
27	★Minit-Man Car Wash	949-7072
41	★Dr G Rinzler	949-6049
	★Dr Mira Rinzler	949-6049

AUTHORIZED IN WRITING BY THE PUBLISHER
— Census Tract Wealth Rating CL10 — Map Location

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

E POST RD 1982

POST RD E

		10601
42	★Landauer Hm Hl Cr	997-8356
	★S&H Uniform Corp	761-0763
44	★Penn Auto&Plt Glss	997-7777
60	★Firestone	949-2346
	★Wchstr Tire Co Inc	949-2346
65	★Warner Weather	949-8167
56	★Charkow Printing	949-6154
	★The Yale Press	949-6154
	½Star Diner	946-9742
67	★Koepper Movg&Storg	948-8622
	★Koepper Movg&Storg	967-8537
68	★Behavior Thpy Inst	949-7880
	★Food As Substance	949-7880
	★Dr H B Hartman	761-6868
	★Hypnosis Svces	949-7880
	★Psychiarc Serv Ctr	949-7880
	★Dr A R Yapalater	949-7880
69	★Alfredo Srfc Cl&Rs	946-1852
70	★Schleicher Electrn	949-7575
71	Mrs K Barth	946-8951
	Marie E Besselte ..70	946-8355
	Ruth Briggs ..76	949-9031
	Frances Dahlstrom ..68	946-8954
	Andy Dowdell ..77	946-7420
	John Forrester ..79	428-4939
	C Luchi ..76	948-7184
	Mrs M H Lynch	949-6555
	Leonard Maenza ..63	949-2926
	Mrs M Mayers ..70	949-6555
	Bridget McCabe	948-0665
	Aine M Naghton ..77	948-3308
	T Rocks ..76	948-1327
	Joseph Sposato Jr ..74	946-0454
	Edwin C Stephens ..63	946-1842
	Istvan Tassy ..76	948-4560
	C Vanvoorhies ..63	949-9033
	Fred White	949-9476
72	★County Optical Co	949-8100
	★Dr M J Marks	946-9699
73	★E C Stephens Lncht	948-9439
75	★W H Boerner Jwlrs	949-4222
77	★County Home Cleang	949-2202
	★County Home Cleang	997-7696
	Robert Singer ..79	997-7221
79	★Dons Towing	949-7889
	★Tops Svc Garage	948-9046
82	★Vexlers Pharmcy	948-6464
84	★Omnigraphics	997-7244
	★PDQ Copy Center	946-4417
87	★H Lau	949-2495
88	★Abortion Referral	948-5533
	★Airforce US Recrtn	946-1146
	★Family Planning	948-5533
	★Navy Recruitng Sta	949-3413
	★St Yth Picmt&Cnslg	948-7095
	★Planned Parenthood	948-5533
	★Planned Parenthood	428-7876
	★Planned Parenthood	761-6566
	★US Air Frc Recrtng	946-1146
	★US Army Recruiting	328-0092
	★US Marine Corps	761-1601
	★US Navy Dept	949-3413
	★White Plns Comm Ac	428-7030
	★White Plns Neighbr	761-3757
89	★G Thorell Furler	948-2515
90	★Ctr For Safety	761-6740
	★Ctr For Safety	946-5200
	★Colber Agency	761-8307
	★C G Scudi Ins	946-1464
	★White Plns Drvg Sc	761-6740
91	★Central Ofc Equipt	948-4419
92	★Tulipans Lunchntte	948-9405
94	★Callahans Wines&Lq	949-1444
95	★Promotionl Mailing	761-2610
	★M A Wilton Ins	761-2610
96	★Metro Press	683-9350
97	★Anthonys Cstm Tlr	948-1138
98	★Shamrock Cafe	948-9831
99	★M Doherty Grocrs	948-8976
	★Royal Scarlet Stre	948-8976
	★Royal Scarlet Str	946-1820
100	★Grand Post Mrkt	949-4522
102	★Thomsons Art Store	949-4885
	★Westchestr Hobbies	949-7943
104	★Suburban Flr Cvrng	949-1140
	★Subrbn Reslnt Flrs	949-1140
106	★Everett Studios	761-4784
109	★ANL Sports Center	946-1685
	★Henrys Fur Studio	949-7525
110	★Waldorf Barbr Shop	761-9600
111	★Caprice Beauty SLN	946-8113
	★Caprice Beauty SLN	948-6767
	★Depot Mattress	946-0033
	★Foamcraft	946-0033
112	★Newmark&Co Rl Est	948-7138
	★112 East Post RD	428-0633
115	★K Ehmer Qlty Meats	946-7810
117	★Deutsch Inc	946-6860
120	★Fournier IDS Apprl	949-8904
	★Office Concepts	949-5277
	★H I Ratet Asid	949-5277
	★Vogue Decorators	949-5277
122	★Ila of Wchster Inc	948-6556
	★Zee Vacuum	949-6663
	★Zee Vacuum Stores	949-6663
123	★Coachman Hotel	949-1000
	★The Coachman	949-1000
	★Deutsch Inc	949-1517
	★Mary Nelson Rl Est	948-7170
	★R Smith Htl Catrng	949-1000
	★Roger Smith Hotel	949-1000
	★R Smith Restrnt	949-1000
	★W H Vrooman Rl Est	948-7170
126	★Amer Frml Wr Rntl	946-1234
	★Fashion Floors	949-4922
128	★Hse Hlf&Lrge Sizes	946-1277
129	★Coachman Hair	949-5515
130	★County Art Supl Co	949-7188
131	★Stitching Post	428-4828
134	★The Charcoal Pit	946-7424
	★Sunnys Deliette	948-9367
135	★Meson Castellano	428-8445
136	★Martens Gifts Inc	761-2570
137	★Darling Baby Carrg	949-6777
	★Darling White Plns	949-6777
138	★Radio Shack	428-8816
139	★Allen Organs	948-8213
140	★Annettes Buttons	949-3827
	★Bengal Tiger Restr	948-5191
	★Indian Restaurant	948-9765

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

E POST RD 1977



POST RD PAGE 570

10583
1207 Ron Paisner 5 723-6626
1209★Dr T Cherbuliez 723-0920
Dr Theo Cherbuliez 472-1291
1216 Edward Tostanoski SC3-5794
1217 Toshio Shigamatsu 3 723-5180
1219 R P Badola 3 725-1586
1221 Joseph A Cohen 472-0489
Susan Cohen 0 472-3759
1230★Dr Milton M Zaret SC3-9129
Dr Milton M Zaret SC3-9150
1231 Albert Rosenthal 0 472-3526
1234 L Gordon Harriss 5 723-7648
1235 Frank B Foster 3 723-8815
1237 Beth Friedman 472-9085
Herbert J Friedman 5 472-9752
1238 E G Ehrlich 8 723-3087
1239 Michael Munoz 472-3149
1241 Joseph Wolhandler SC3-8340
1243 Bertram Stanhoff 472-5175
★Stanhoff Mfg Co GR2-4823
1245 Mrs G Kuttner GR2-4441
★Kuttner Ins 725-4090
1247 Carl W Goebel GR2-4770
1248★Fendelman&Assocts 472-2266
Burton M Fendelman 8 725-0292
1250 Edwin B Giventer 472-4035
1251 Robert A Berry 0 SC3-6442
1255 W M Schwartzenberg GR2-2098
1258 Murray J Landman 3 725-1617
1259 Stephen Ciccone 2 472-2511
No #★City Police Dept ¤ 723-2300
No #★Senior High School 723-5500
No #★Scarsdl Attrntv Sc 723-9593
No #★Scars Superintndnt 723-5500
No #★Scarsdale Recr Dpt 723-6602
No #★Scarsdale Assessor 723-3300
No #★Scarsdl Bg Inspctr 723-3300
No #★Scrdl Vlg Hl Ct Ck 723-3300
No #★Scrsdl Vlg Hl Engr 723-3300
No #★Scrsdl Vlg Hl Hwy 723-3300
No #★Scrsdl Vlg Hl Clrk 723-3300
No #★Scrsdl Vlg Hl Tax 723-3300
No #★Scrsdl Vlg Hl Mngr 723-3300
No #★Scarsdl Waste Cltn 723-5030
No #★Scrsdl Youth Board 725-1836
120 Residence 58 Business

POST RD E 10601
White Plains PO
1- 159 TZ 93 $E..N 4
160- END TZ 94 $D..N 4
1★Apartment Advisory 946-2626
★Assoc Brick&Block 946-2626
★Atlas Flooring Inc RO1-3844
★Builders Inst 946-2626
★Bldg Trades Assn 946-2626
★Commercial Buildrs 946-2626
★Creative Floors 761-8848
Andrios Davoudpour 2 969-3384
★Drywall Empl Assn 946-2626
★Fairfield Stereo 761-7569
★Max Garsen RO1-3844
★Home Builders 428-5971
★H L Hughes Bldr 949-1320
★P M Hughes&Sons 949-1320
★R C Kleinberger WH9-3639
★L&C Dental Lab WH6-0418
★Residential Bldrs 946-2626
★Wstchstr Bldrs Ins 946-2626
★Westchester Fndtn - 761-1750
★Wchstr Stereo Tape 761-7569
2★Hollywd Grdn Flwr 949-6330
4★Post Pizza Shop 761-9888
6★Westchstr Action 761-0516
11★Prestos Flying A 948-9860
★Prestos Serv Sta 948-9860
12 Mary Debuono 8 949-0645
M Donohue 8 948-6331
B Eadie 1 949-1263
John Henry 4 428-7234
Grace D Macintyre ¤ 946-9150
Felix Ramos - 428-5162
★Red Lion Restrnt 428-9634
Mrs Margt Taylor 8 949-2851
½Selinos Taxi 949-6988
14★Yeagers Cycle Str WH9-3305
16 S P Canseco 8 761-0061
Peter Solana 946-7220
18 Catherine Arone 3 761-5275
Verna J Fuller 949-9219
Richard Genrung WH6-2693
Mrs Anette Tarl 946-8260
20★Burke&Mccowen Inc WH9-2389
Bishop M Minter 3 761-4319
22★Gga Place WH6-9894
★G Ga Place 949-9336
24 F Valenti WH8-7109
27★Minit-Man Car Wash 949-7072
★Minit-Man Auto 949-7072
34★Post Davis Svc Sta WH8-9362
41★Dr G Rinzler 949-6049
★Dr Mira Rinzler 949-6049
★White Plains Hosp 949-4500
42★S&H Uniform Corp 428-8888
44★Autoscope Inc 428-7200
60★Firestone WH9-2346
★Firestone Stores WH9-2346
★Wchstr Tire Co Inc WH9-2346
65★Warner Weather WH9-8167
66★Charkow Printing 949-6154
★The Yale Press 949-6154
½Star Diner 946-9742
½Star Diner 946-9832
68★Behavior Thpy Inst 949-7880
★Hypnosis Svces 949-7880
★Psychiatric Svcs 949-7880
★Dr A R Yapalater 949-7880
69★Antonios Coiffure 946-7680
70★Anroder Leasing 949-7575
★Electronic Room 949-7575
★Schleicher Electrn 949-7575
71 Mrs K Barth 946-8951
Marie E Bessette 0 WH6-8355
Ruth Briggs ¤ 949-9031
Frances Dahlstrom 8 946-8954
William Hackett ¤ 428-4939
C Luchi - 948-7184
Mrs M H Lynch 949-6555
Leonard Maenza WH9-2926
Mrs M Mayers 0 949-6555
Bridget McCabe 948-0665
71 Austin McElroy 4 428-2094
T Rocks ¤ 948-1327
Joseph Sposato Jr 4 946-0454
Edwin C Stephens WH6-1842
Istvan Tassy ¤ 948-4560
C Vanvoorhies 949-9033
Fred White 949-9476
72★County Optical Co 949-8100
★Dr H Sheppard 761-3091
73★E C Stephens Lnchr 948-9439
75★Oppen Jewelers WH9-4222
77★United Remodeling ¤ 948-8808
79★Smiths Shell Serv WH8-9046
82★Vexlers Pharmcy WH8-6464
84★Graphic Guidance ¤ 428-6620
★PDQ Copy Center 946-4417
87★H Lau WH9-2495
88★Abortion-Fmly Plan 948-5533
★Family Plnng Info 948-5533
★Planned Parenthood 948-5533
★Planned Parenthood 761-6566
★US Air Force Recrt 761-4250
★US Air Frc Recrtng WH6-1146
★US Army Recruiting 949-0499
★US Marine Corps 761-1601
★US Selctv Svc Locl 761-4250
89★G Thorell Furler WH8-2515
90★The Needleworks 428-3177
91★Central Ofc Equipt 948-4419
92★Lillos Luncheonett ¤ 948-9405
94★Callahans Wines&Lq WH9-1444
95★Promotionl Mailing 761-2610
★M A Wilton Ins 761-2610
96★The Rug Mart WH9-0100
97★Anthonys Cstm Tlr 948-1138
98★Shamrock Cafe 948-9831
99★M Doherty Grocrs WH8-8976
★Royal Scarlet Stre WH8-8976
★Royal Scarlet Str WH6-1820
100★Grand Post Mrkt 949-4522
101★Rahmani Bldg Svc ¤ 948-2296
102★Thomsons Art Store 949-4885
★Westchestr Hobbies WH9-7943
104★Suburban Flr Cvrng 949-1140
★Subrbn Resint Flrs 949-1140
106★Everett Studios 761-4764
108★Wises Wig Salon 428-4373
109★ANL Sports Center 946-1685
★Henrys Fur Studio WH9-7525
110★Waldorf Barbr Shop 761-9600
111★Caprice Beauty SLN 948-6767
★Caprice Bty Salon WH6-8113
★Depot Mattress 946-0033
★Foamcraft 946-0033
112★I Silverman Rl Est 428-0633
115★K Ehmer Qlty Meats WH6-7810
117★Clares Beauty Salo 946-6860
120★Fournier IDS Apprl WH9-6904
★H I Ratet Asid 949-5277
★Vogue Decorators 949-5277
122★Ila of Wchster Inc WH8-6556
★Zee Vacuum WH9-6663
★Zee Vacuum Stores WH9-6663
123 Richard Conetta 1 949-4529
★Hotl R Smith Motor 949-1000
★M E Nelson Rl Est 948-7170
★R Smith Htl Catrng 949-1000
★Roger Smith Hotel 949-1000
★R Smith Restrnt 949-1000
★W H Vrooman Rl Est 948-7170
Fredk H Williams 948-0328
124★Pottery N Things WH9-7117
★Max Richter Gifts WH9-7117
126★Amer Frml Wr Rntl WH6-1234
★Fashion Floors 949-4922
128★Hse Hlf&Lrge Sizes 946-1277
130★County Art Supl Co WH9-7188
131★Stitching Post 428-4828
134★Meet&Eat Charcl Pt 948-9367
135★Meson Castellano 428-8445
136★Martens Gifts Inc 761-2570
137★Ellie Conason WH9-4796
★Conasons Inc WH9-4796
★Darling Baby Carrg WH9-6777
★Darling White Plns WH9-6777
★Ellie Conason Asso ¤ WH9-4796
138★Radio Shack Div 428-8816
139★Allen Organs WH8-8213
140★Annettes Dramkr WH9-3827
★Bengal Tiger 948-9765
★Bengal Tiger Restr 948-5191
★Uniform Center WH9-4944
141★Homer-Rich Opticns WH9-3343
★M P Rich Optcn WH9-3343
★Tall&Big Mens Stre RO1-3540
★White Plains Stors RO1-3540
143★Giulianos Cstm Gtr 428-2405
145★Wchstr Cstm Ktchns WH6-8100
146★Lyric High Fidelty 949-7500
147★Clocks of The Wrld - 761-5225
★Vicki Glasgow - 761-5225
Eugene Ocker WH8-9183
149★Tonsher Inc ¤ 428-4040
150★Antique Boutique 428-4091
151★Anefco Inc 946-4631
★M S Ahrens Rl Est RO1-4432
★Alson Trading Co RO1-2795
★J Beliantoni Travl WH6-7016
★Henry Bloch Jr WH8-7743
★Mrs M L Bowman 761-0294
★Bridal Center WH9-0228
★Carin Sybil Realty 946-4140
★N E Derecktor 946-2357
★Fara Bridal Ctr 949-3400
★Fara Bridal Cntr WH9-0228
★A W Faranda Gowns WH9-0228
★P Faranda Gowns WH9-0228
★47 Mamornck Av Crp 946-2357
★Dr Bernard D Fox WH9-3745
★Nanette Fox Rl Est 949-7903
★The Foxes Rl Est 949-7903
★Guardsmark Inc 761-6064
★Dr R B Herman WH9-3371
★Jill Beliantoni Tr WH6-7016
★Dr L P Lipton ¤ WH9-3371
★Reliable Nurse Aid ¤ 949-2444
★Roger L Saunders 761-0294
★B Schuman Elctrlss WH6-8855
★Sybil Carin Realty 946-4140
★Thomas Brokerag Co WH9-6900
★Westchstr Counselg 761-7673
152★Dr Harvey A Dubin 949-6001

© COPYRIGHT INFORMATION ON THIS PAGE MAY NOT BE KEY PUNCHED, ENTERED INTO A COMPUTER OR
¤ — New Listing to the Directory - — New Listing to that Street ★ — Business Listing TZ — Trading Zon

Target Street	Cross Street	Source
✓	-	Cole Criss-Cross Directory

E POST RD 1972



1*S H LEITMAN CPA 9488404
*C W PAUL RL EST B9462379
**WCHSTR STEREO TAPE 7617564
2*HOLLYWD GRDN FLWR 9496330
4*POST PIZZA SHOP 7619888
6*DISCOUNT DRIVR TRN 7616514
*R H TIMNEY AUTO DR 9484660
*R H TIMNEY AUTO DR 6323252
*R H TIMNEY AUTO DR 6313133
*R H TIMNEY AUTO DR 7232258
*R H TIMNEY DRV SCH 9484660
*R H TIMNEY DRIV SCH6323252
*R H TIMNEY DRV SCH6313133
*TOWN&COUNTRY CYCLE B7610547
7*TOWN&COUNTRY CYCLE B9489110
11*INTRNTL MOTR SALS 9498887
*PRESTOS FLYING A 9489860
*PRESTOS SERV STA 9489860
12 WILLIAM ALBOHN -4280197
HAROLD A BATES B4286685
JOHN A CAREY WH99604
MARY DEBUONO 8 9490645
CHARLES DESMOND B4286309
M DONOHUE 8 9486331
B EADIE B9491263
*LEINGTON TAXI BWH91363
ROBERT B MOORE WH68307
*RED LION RESTRNT B4289634
FRANK M SELINO WH91363
MRS M TAYLOR 8 WH92851
½SAFEWAY TAXI -WH88900
14*YEAGERS CYCLE STR WH93305
16 JULIANA CANSECO 8 7610061
A LIVACCARI 0 7613158
MRS MAE ORTON 9484338
PETER SOLANA 5 9467220
18 VERNA J FULLER 9499219
RICHARD GEHRUNG 3 WH62693
GILBERT PAGE 3 RO16184
MRS ANETTE TART 9468260
20*BURKE&MCCOWEN WH92389
MRS A MCCLUSKY WH61049
*A C RENINO TLVSN WH96611
MRS RUTH VAUGHN 0 9499031
22 RICHARD BARTH WH88837
*GGS PLACE WH69894
*GGS PLACE OFC 9499136
JOHN PETERSHAGEN 5 9461921
24 F VALENTI WH87109
27*MINIT-MAN AUTO 9497072
*WHITE PLAINS AUTO 9497072
34*POST DAVIS SVC STA WH89362
41*WHITE PLAINS HOSP 9494500
*WHITE PLAINS HOSP 9494500
*WHITE PLAINS HOSP 9494500
42*S&H UNIFORM CORP 4288888
44*ABBEY RICHMOND WH97788
*ARCO MDCL SPL BWH97788
*MEDICAL APPLNCE WH90266
*WHITE PLAINS AMBLN 9499766
60*FIRESTONE STORES WH92346
65*WARNER WEATHER WH98167
66*CHARKOW BROS PRNTR 9496154
*THE YALE PRESS 9496154
½STAR DINER 9469832
½W P STAR DINER B9469742
67*DOLL SHOP&HOSP WH92183
*RUTH RICHARDS WH92183
69*ANTONIOS COIFFURE -9467680
71 MRS K BARTH 9468951
MARIE E BESSETTE 0 WH68355
FRANCES DAHLSTROM8 9468954
ABA DEAK 0 4282087
MRS JOSEPH A DOLAN 3 WH66821
EMANUELE M DRAGO 0 9462306
JANIA GENERAZZO 9 WH94039
MRS VIOLET GUIDDY3 WH81807
MICHAEL J LUKSE 8 4283238
MRS MARJ H LYNCH 3 WH96555
LEONARD MAENZA 3 WH92926
MRS M MAYERS 0 WH96555
BRIDGET MCCABE 9480665
ALFRED W PINCHBECK 3 WH66982
EDWIN C STEPHENS 3 WH61842
C VANVOORHIES 3 9499033
FRED WHITE 3 WH99476
72*CO HEARING AID CTR-9498975
*COUNTY OPTICAL CO -9498100
73*E C STEPHENS LNCHT 9489439
75*SAYKY JEWELERS WH94222
77*THE LUMBER YARD WH80388
79*SMITHS SHELL SERV WH89046
82*VEXLERS PHARMCY WH86464
84*MILLERS CLNRS&DYER WH98797
87*H LAU WH92495
88*US AIR FRC RECRTNG WH61146
*US AIR FRC RECRTNG 7614250
*US ARMY RECRUITING 9490499
*US ARMY WAC CNSLR 9497036
*US MARINE RECRUITG 9464790
*US SELCTV SVC LOCL 7614250
89*G THORELL FURIER WH82515
90*POST RADIO&TV SVCE WH80441
*WCHSTR TV WH PLNS WH95044
91*CENTRAL OFC EQUIPT 9484419
92*LILLO LNCH&STATNRY 9489405
93*PEAR TR CHLD APPRL RO10607
*PEARTREE APPAREL RO10607
94*CALLAHANS WINE&LIQ WH91444
95*PROMOTIONL MAILING 7612610
*M A WILTON INS 7612610
96*THE RUG MART WH90100
97*ANTHONYS CSTM TLR 9481138
98*SHAMROCK CAFE 9489831
99*M DOHERTY GROCRS WH88976
*ROYAL SCARLET STOR WH88976
*ROYAL SCARLET STR WH61820
100*GRAND-POST MKT WH97746
101*IBM CORP 9491900
102*MONTGOMERY WARD RO13000
*THOMSONS ART STORE 9494885
*WESTCHESTR HOBBIES WH97943
104*SUBURBAN FLR CVRNG 9491140
*SUBRBN RESLNT FLRS 9491140
106*EVERETT STUDIOS 7614764
*E MONTAGUE 7614764
108*OFFICE HELP TEMPR 9461690
109*HENRYS FUR STUDIO WH97525
½LEO FELDMAN UPHLS 9492962
½LEO UPHLSTRY 9492962
110*WALDORF BARBR SHOP 7619600
111*CAPRICE BTY SALON WH68113
*PROPENSITY GIFT SH 7613420
112*IBM CORP 9491900
*I SILVERMAN RL EST 4280633
113*CNSLG CTR BTR HRNG 9491243
*SONOTONE CTR HRNG 9491243
*SONOTONE WHIT PLNS 9491243
115*CRAIG PHOTOGRPH 9492321
*CREST PHOTOGRPHRS WH84744
117*CLARES BEAUTY BRQU 9466860
120*FOURNIER IDS APPRL WH96904
*VOGUE DECORATORS 9495277

OR PHOTOCOPIED, IN ANY MANNER WHATSOEVER EXCEPT AS

ATTACHMENT 5
Fire Insurance Maps

White Plains - 5 Parcels

42 East Post Road

White Plains, NY 10601

Inquiry Number: 6284645.3

December 01, 2020

Certified Sanborn® Map Report

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

12/01/20

Site Name:

White Plains - 5 Parcels
42 East Post Road
White Plains, NY 10601
EDR Inquiry # 6284645.3

Client Name:

Barton & Loguidice, D.P.C.
443 Electronics Parkway
Liverpool, NY 13088
Contact: Corinne Steinmuller

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Barton & Loguidice, D.P.C. were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 9C9D-4EBD-BA49

PO # 2025.003.001

Project White Plains - 5 Parcels

Maps Provided:

2004	1989
2003	1987
2002	1950
1995	1942
1994	1930
1993	1911
1992	1905
1990	1900

Sanborn® Library search results

Certification #: 9C9D-4EBD-BA49

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☑ Library of Congress
- ☑ University Publications of America
- ☑ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Barton & Loguidice, D.P.C. (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

2004 Source Sheets



Volume 1, Sheet 12
2004



Volume 1, Sheet 80
2004

2003 Source Sheets



Volume 1, Sheet 12
2003



Volume 1, Sheet 80
2003

2002 Source Sheets



Volume 1, Sheet 12
2002



Volume 1, Sheet 80
2002

1995 Source Sheets

Volume 1, Sheet 12
1995



Volume 1, Sheet 80
1995

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1994 Source Sheets

Volume 1, Sheet 12
1994

Volume 1, Sheet 80
1994

1993 Source Sheets

Volume 1, Sheet 12
1993



Volume 1, Sheet 80
1993

1992 Source Sheets

Volume 1, Sheet 12
1992

Volume 1, Sheet 80
1992

1990 Source Sheets



Volume 1, Sheet 12
1990



Volume 1, Sheet 80
1990

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1989 Source Sheets

Volume 1, Sheet 12
1989



Volume 1, Sheet 80
1989

1987 Source Sheets



Volume 1, Sheet 12
1987



Volume 1, Sheet 80
1987

1950 Source Sheets

Volume 1, Sheet 12
1950



Volume 1, Sheet 80
1950

1942 Source Sheets



Volume 2, Sheet 23
1942

Volume 2, Sheet xxxx
1942

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.

1930 Source Sheets



Volume 1, Sheet 6
1930

Volume 1, Sheet 12
1930

1911 Source Sheets

Volume 1, Sheet 20
1911



Volume 1, Sheet 31
1911

1905 Source Sheets

Volume 1, Sheet 20
1905

Volume 1, Sheet 28
1905

1900 Source Sheets

Volume 1, Sheet 8
1900



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	2004

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 80
Volume 1, Sheet 12

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	2003

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	2002

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #	9C9D-4EBD-BA49
Copyright	1995

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1994

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #	9C9D-4EBD-BA49
Copyright	1993

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1992

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 80
Volume 1, Sheet 12

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1990

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1989

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 80
Volume 1, Sheet 12

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1987

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1950

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 80
Volume 1, Sheet 12

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #	9C9D-4EBD-BA49
Copyright	1942

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 2, Sheet xxxx
Volume 2, Sheet 23

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1930

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 12
Volume 1, Sheet 6

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1911

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 31
Volume 1, Sheet 20

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1905

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.



Volume 1, Sheet 28
Volume 1, Sheet 20

0 Feet 150 300 600

N



The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn, and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by The Sanborn Library LLC, the copyright holder for the collection.

Certification #9C9D-4EBD-BA49

Site Name:	White Plains - 5 Parcels
Address:	42 East Post Road
City, ST, ZIP:	White Plains, NY 10601
Client:	Barton & Loguidice, D.P.C.
EDR Inquiry:	6284645.3
Order Date:	12/01/2020
Certification #:	9C9D-4EBD-BA49
Copyright	1900

This Certified Sanborn Map combines the following sheets.
Outlined areas indicate map sheets within the collection.

0 Feet 150 300 600



Volume 1, Sheet 8

N

ATTACHMENT 6
Site Photographs

Photograph 1: 26-28 East Post Road, looking south from parking lot (223-225 Dr. Martin Luther King Jr. Blvd.).

Photograph 2: 26-28 East Post Road, looking north from East Post Road.

Photograph 3: Security fence along 26-28 East Post Road, photograph looking north along fence line.

Photograph 4: Access gate at 26-28 East Post Road, photograph looking west.

Photograph 5: 34 East Post Road, photograph looking east along sidewalk.

Photograph 6: 34 East Post Road, photograph looking southwest.

Photograph 7: 34 East Post Road, photograph looking north no access to site during site visit.

Photograph 8: Asphalt spoils pile at the 34 East Post Road site, photograph looking east.

Photograph 9: 34 East Post Road, photograph looking northwest no access inside fence during site visit.

Photograph 10: Storefront at 42 East Post Road, photograph looking northeast.



Photograph 11: Pharmacy at 42 East Post Road, photograph looking northwest.

Photograph 12: Firestone automobile maintenance business at 60 East Post Road.

Photograph 13: Oil storage area at Firestone business at 60 East Post Road.

Photograph 14: Drain in basement of Firestone business – 60 East Post Road, some staining observed.

Photograph 15: Dumpsters in employee parking area at 60 East Post Road, photograph looking north.

Photograph 16: Dumpsters at site 223-225 Dr. Martin Luther King Blvd, photograph looking north.

Photograph 17: Parking lot at 223-225 Dr. Martin Luther King Blvd, photograph looking northeast.

Photograph 18: Household trash items in grassed area along parking lot 223-225 Dr. Martin Luther King Blvd, photograph looking southeast.

Photograph 19: Household trash items along parking lot at 223-225 Dr. Martin Luther King Blvd parcel, photograph looking east.

Photograph 20: Construction entrance to adjacent site at the central portion of 223-225 Dr. Martin Luther King Blvd parcel, photograph looking north.

ATTACHMENT 7
ASTM
Transaction Screen Questionnaires

Completed OWNER questionnaire

process, including, in particular, the *site visit* and the government records/historical sources inquiry. If the *user* decides no further inquiry is warranted after receiving no response, an answer of unknown, or an affirmative answer, the *user* must document the reasons for any such conclusion.

5.6.1 Upon obtaining an affirmative answer, an answer of unknown or no response, the *user* should first refer to the guide. The guide may provide sufficient explanation to allow a *user* to conclude that no further inquiry is appropriate with respect to the particular question.

5.6.2 If the guide to a particular question does not, in itself, permit a *user* to conclude that no further inquiry is appropriate, then the *user* should consider other information obtained from the *transaction screen process* relating to this question. For example, while on the site performing a *site visit*, a person may find a storage tank on the *property* and therefore answer Question 10 of the *transaction screen questionnaire* in the affirmative. However, during or subsequent to the *owner/occupant* inquiry, the *owner* may establish that substances now or historically contained in the tank (for example, water) are not likely to cause contamination.

5.6.3 If either the guide to the question or other information obtained during the *transaction screen process* does not permit a *user* to conclude no further inquiry is appropriate with respect to such question, then the *user* must determine, in the exercise of the *user's* reasonable business judgment, based upon the totality of unresolved affirmative answers or answers of unknown received during the *transaction screen process*, whether further inquiry may be limited to those specific issues identified as of concern.

5.7 *Presumption*—A presumption exists that further inquiry is necessary if an affirmative answer is given to a question or because the answer was unknown or no response was given. In rebutting this presumption, the *user* should evaluate information obtained from each component of the *transaction screen process* and consider whether sufficient information has been obtained to conclude that no further inquiry is necessary. The *user* must determine, in the exercise of the *user's* reasonable business judgment, the scope of such further inquiry.

5.8 *Further Inquiry*—Upon completing the *transaction screen questionnaire*, if the *user* concludes that further inquiry or action is needed (for example, consult with an environmental consultant, contractor, governmental authority, or perform additional governmental and/or historical records review), the *user* should proceed with such inquiry. (Note that if the *user* determines to proceed with a Phase I Environment Site Assessment, the *user* may apply the current Practice E1527, Practice E2247, or alternatively the provisions of EPA's regulation "Standards and Practices for All Appropriate Inquiries," 40 C.F.R. Part 312.)

5.9 *Signature*—The *user* and the *preparer* of the *transaction screen questionnaire* must complete and sign the questionnaire as provided at the end of the questionnaire.

6. Transaction Screen Questionnaire

6.1 *Persons to Be Questioned*—The following questions should be asked of *(1)* the current *owner* of the *property*, *(2)* any major *occupant* of the *property* or, if the *property* does not have any *major occupants*, at least 10 % of the *occupants* of the *property*, and *(3)* in addition to the current *owner* and the *occupants* identified in *(2)*, any *occupant* likely to be using, treating, generating, storing, or disposing of *hazardous substances* or *petroleum products* on or from the *property*. A major *occupant* is any *occupant* using at least 40 % of the leasable area of the *property* or any anchor tenant when the *property* is a shopping center. In a multifamily *property* containing both residential and commercial uses, the *preparer* does not need to ask questions of the residential *occupants*. The *preparer* should ask each person to answer all questions to the best of the respondent's *actual knowledge* and in good faith. When completing the *site visit* column, the *preparer* should be sure to observe the *property* and any buildings and other structures on the *property*. The guide to this *transaction screen questionnaire* (see Sections 7 – 10) provides further details on the appropriate use of this questionnaire. (See Note 1.)

NOTE 1—Unk = "unknown" or "no response."

Description of Site/Address:
26-28 East Pond Road
City of White Plains, NY

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
1a. Is the *property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
1b. Is any *adjoining property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
2a. Did you observe evidence or do you have any prior knowledge that the *property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
2b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	No	
3a. Is the *property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	No	
3b. Is any *adjoining property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	No	
4a. Did you observe evidence or do you have any prior knowledge that the *property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	No	gas station
4b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	No	
5a. Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	No	
5b. Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, or pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	No	
6a. Are there currently any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
6b. Did you observe evidence or do you have any prior knowledge that there have been previously any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	No	
7a. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that originated from a contaminated site?	Yes	No	Unk	Yes	No	Unk	Yes	No	
7b. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that is of an unknown origin?	Yes	No	Unk	Yes	No	Unk	Yes	No	
8a. Are there currently any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	No	
8b. Did you observe evidence or do you have any prior knowledge that there have been previously, any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	No	
9a. Is there currently any stained soil on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
9b. Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
10a. Are there currently any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
10b. Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
11a. Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
11b. Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	
12a. Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors, associated with any flooring, drains, walls, ceilings, or exposed grounds on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
12b. Did you observe evidence or do you have any prior knowledge that there have been previously any leaks, spills, or staining by substances other than water, or foul odors, associated with any flooring drains, walls, ceilings or exposed grounds on the *property* ?	Yes	No	Unk	Yes	No	Unk	Yes	No	
13a. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes	No	Unk	Yes	No	Unk	Yes	No	
13b. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well has been designated as contaminated by any government environmental/health agency?	Yes	No	Unk	Yes	No	Unk	Yes	No	
14. Does the *owner* or *occupant* of the *property* have any knowledge of *environmental liens* or governmental notification relating to past or recurrent violations of environmental laws with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15a. Has the *owner* or *occupant* of the *property* been informed of the past existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15b. Has the *owner* or *occupant* of the *property* been informed of the current existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15c. Has the *owner* or *occupant* of the *property* been informed of the past existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15d. Has the *owner* or *occupant* of the *property* been informed of the current existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
16. Does the *owner* or *occupant* of the *property* have any knowledge of any *environmental site assessment* of the *property* or facility that indicated the presence of *hazardous substances* or *petroleum products* on, or contamination of, the *property* or recommended further assessment of the *property*?	Yes	No	Unk	Yes	No	Unk			

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
17. Does the *owner* or *occupant* of the *property* know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any *hazardous substance* or *petroleum products* involving the *property* by any *owner* or *occupant* of the *property*?	Yes	No	Unk	Yes	No	Unk			
18a. Does the *property* discharge *waste-water* (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a storm water system?	Yes	No	Unk	Yes	No	Unk	Yes	No	
18b. Does the *property* discharge waste water (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a sanitary sewer system?	Yes	No	Unk	Yes	No	Unk	Yes	No	
19. Did you observe evidence or do you have any prior knowledge that any *hazardous substances* or *petroleum products*, unidentified waste materials, tires, automotive or industrial batteries, or any other waste materials have been dumped above grade, buried and/or burned on the *property* ?	Yes	No	Unk	Yes	No	Unk	Yes	No	
20. Is there a transformer, capacitor, or any hydraulic equipment for which there are any records indicating the presence of *PCBs*?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Government Records/Historical Sources Inquiry
(See guide, Section 10, and Practice E1527)

21. Do any of the following federal, state, or tribal government record systems list the *property* or any *property* within the search distance noted below (where available):

	Approximate Minimum Search Distance, miles (kilometres)		
Federal *NPL* site list	1.0 (1.6)	Yes	No
Federal Delisted *NPL* site list	0.5 (0.8)	Yes	No
Federal CERCLIS list	0.5 (0.8)	Yes	No
Federal CERCLIS NFRAP site list	0.5 (0.8)	Yes	No
Federal RCRA CORRACTS facilities list	1.0 (1.6)	Yes	No
Federal RCRA non-CORRACTS TSD Facilities list	0.5 (0.8)	Yes	No
Federal *RCRA generators list*	*property* and *adjoining properties*	Yes	No
Federal institutional control/engineering control registries	*property* only		
Federal *ERNS list*	*property* only	Yes	No
State and tribal lists of *hazardous waste sites* identified for investigation or remediation:			
State-and tribal-equivalent *NPL*	1.0 (1.6)	Yes	No
State-and tribal-equivalent CERCLIS	0.5 (0.8)	Yes	No
State-and tribal-*landfill* and/or *solid waste disposal site lists*	0.5 (0.8)	Yes	No
State-and tribal-leaking storage tank lists	0.5 (0.8)	Yes	No
State and tribal registered storage tank lists	*property* and *adjoining properties*	Yes	No
State and tribal *institutional control*/engineering control registries	*property* only	Yes	No
State and tribal voluntary cleanup sites	0.5 (0.8)	Yes	No
State and tribal Brownfield sites	0.5 (0.8)	Yes	No

22. Based upon a review of *fire insurance maps, local street directories*, or *aerial photographs*, all as specified in the guide (10.2.1), are any buildings or other improvements on the *property* or on an *adjoining property* identified as having been used for an industrial use or that could possibly lead to contamination of the *property*?

Yes No Unavailable Unknown

Result: _____

The *Owner* questionnaire answers were provided was completed by:

Name Michael Taub

Michael Taub
Title Owner/member
Firm 26-28 East Art, [redacted] LLC
Address 76 S. Lexington Ave. White Plains, NY 10606
Phone number 914-714-1515
Date 5/6/2021
Role(s) at the site Developer
Number of years at the site 2
Relationship to *user* (for example, principal, employee, agent, consultant) Principal

The *Occupant* questionnaire answers were provided by:

Name
Title
Firm
Address

Phone number NA
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Site Visit* questionnaire was completed by:

Name
Title
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Government Records* and *Historical Sources Inquiry* questionnaire was completed by:

Name
Title
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

User's relationship to the site (for example, *owner*, prospective purchaser, lender, etc.)

If the *preparer*(s) is different from the *user*, complete the following:

Name of *User*
User's address

User's phone number

Copies of the completed questionnaires have been filed at:

Copies of the completed questionnaires have been mailed or delivered to:

Preparer represents that to the best of the *preparer's* knowledge the above statements and facts are true and correct and to the best of the *preparer's actual knowledge* no material facts have been suppressed or misstated.

Signature _____ Date 5/18/21
Signature _____ Date _____
Signature _____ Date _____

If the *user* is different from the *preparer(s)*, the *user* shall sign below affirming that the completed questionnaire has been received. *It is the user's responsibility to draw conclusions regarding affirmative or unknown answers.*
Signature _____ Date _____

Completed SITE VISIT questionnaire

process, including, in particular, the *site visit* and the government records/historical sources inquiry. If the *user* decides no further inquiry is warranted after receiving no response, an answer of unknown, or an affirmative answer, the *user* must document the reasons for any such conclusion.

5.6.1 Upon obtaining an affirmative answer, an answer of unknown or no response, the *user* should first refer to the guide. The guide may provide sufficient explanation to allow a *user* to conclude that no further inquiry is appropriate with respect to the particular question.

5.6.2 If the guide to a particular question does not, in itself, permit a *user* to conclude that no further inquiry is appropriate, then the *user* should consider other information obtained from the *transaction screen process* relating to this question. For example, while on the site performing a *site visit*, a person may find a storage tank on the *property* and therefore answer Question 10 of the *transaction screen questionnaire* in the affirmative. However, during or subsequent to the *owner/occupant* inquiry, the *owner* may establish that substances now or historically contained in the tank (for example, water) are not likely to cause contamination.

5.6.3 If either the guide to the question or other information obtained during the *transaction screen process* does not permit a *user* to conclude no further inquiry is appropriate with respect to such question, then the *user* must determine, in the exercise of the *user's* reasonable business judgment, based upon the totality of unresolved affirmative answers or answers of unknown received during the *transaction screen process*, whether further inquiry may be limited to those specific issues identified as of concern.

5.7 *Presumption*—A presumption exists that further inquiry is necessary if an affirmative answer is given to a question or because the answer was unknown or no response was given. In rebutting this presumption, the *user* should evaluate information obtained from each component of the *transaction screen process* and consider whether sufficient information has been obtained to conclude that no further inquiry is necessary. The *user* must determine, in the exercise of the *user's* reasonable business judgment, the scope of such further inquiry.

5.8 *Further Inquiry*—Upon completing the *transaction screen questionnaire*, if the *user* concludes that further inquiry or action is needed (for example, consult with an environmental consultant, contractor, governmental authority, or perform additional governmental and/or historical records review), the *user* should proceed with such inquiry. (Note that if the *user* determines to proceed with a Phase I Environment Site Assessment, the *user* may apply the current Practice E1527, Practice E2247, or alternatively the provisions of EPA's regulation "Standards and Practices for All Appropriate Inquiries," 40 C.F.R. Part 312.)

5.9 *Signature*—The *user* and the *preparer* of the *transaction screen questionnaire* must complete and sign the questionnaire as provided at the end of the questionnaire.

6. Transaction Screen Questionnaire

6.1 *Persons to Be Questioned*—The following questions should be asked of *(1)* the current *owner* of the *property*, *(2)* any major *occupant* of the *property* or, if the *property* does not have any *major occupants*, at least 10 % of the *occupants* of the *property*, and *(3)* in addition to the current *owner* and the *occupants* identified in *(2)*, any *occupant* likely to be using, treating, generating, storing, or disposing of *hazardous substances* or *petroleum products* on or from the *property*. A major *occupant* is any *occupant* using at least 40 % of the leasable area of the *property* or any anchor tenant when the *property* is a shopping center. In a multifamily *property* containing both residential and commercial uses, the *preparer* does not need to ask questions of the residential *occupants*. The *preparer* should ask each person to answer all questions to the best of the respondent's *actual knowledge* and in good faith. When completing the *site visit* column, the *preparer* should be sure to observe the *property* and any buildings and other structures on the *property*. The guide to this *transaction screen questionnaire* (see Sections 7 – 10) provides further details on the appropriate use of this questionnaire. (See Note 1.)

NOTE 1—Unk = "unknown" or "no response."

Description of Site/Address:
26-28 East Pond Road
City of White Plains, NY

NOTE:
Access to site on May 12, 2021 was not granted. Property inspected from the ROW.

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
1a. Is the *property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
1b. Is any *adjoining property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
2a. Did you observe evidence or do you have any prior knowledge that the *property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
2b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
3a. Is the *property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Property was formerly gasoline fueling station
3b. Is any *adjoining property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Former gasoline fueling station at 34 East Post Road.
4a. Did you observe evidence or do you have any prior knowledge that the *property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Property was formerly gasoline fueling station
4b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Former gasoline fueling station at 34 East Post Road.
5a. Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
5b. Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, or pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
6a. Are there currently any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
6b. Did you observe evidence or do you have any prior knowledge that there have been previously any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
7a. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that originated from a contaminated site?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
7b. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that is of an unknown origin?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	
8a. Are there currently any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
8b. Did you observe evidence or do you have any prior knowledge that there have been previously, any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
9a. Is there currently any stained soil on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
9b. Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Former gasoline fueling station with NYSDEC spill records
10a. Are there currently any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
10b. Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Former gasoline fueling station with NYSDEC spill records
11a. Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
11b. Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
12a. Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors, associated with any flooring, drains, walls, ceilings, or exposed grounds on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
12b. Did you observe evidence or do you have any prior knowledge that there have been previously any leaks, spills, or staining by substances other than water, or foul odors, associated with any flooring drains, walls, ceilings or exposed grounds on the *property* ?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Several NYSDEC Spill records pertain to this site.
13a. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
13b. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well has been designated as contaminated by any government environmental/health agency?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
14. Does the *owner* or *occupant* of the *property* have any knowledge of *environmental liens* or governmental notification relating to past or recurrent violations of environmental laws with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15a. Has the *owner* or *occupant* of the *property* been informed of the past existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15b. Has the *owner* or *occupant* of the *property* been informed of the current existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15c. Has the *owner* or *occupant* of the *property* been informed of the past existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15d. Has the *owner* or *occupant* of the *property* been informed of the current existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
16. Does the *owner* or *occupant* of the *property* have any knowledge of any *environmental site assessment* of the *property* or facility that indicated the presence of *hazardous substances* or *petroleum products* on, or contamination of, the *property* or recommended further assessment of the *property*?	Yes	No	Unk	Yes	No	Unk			

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
17. Does the *owner* or *occupant* of the *property* know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any *hazardous substance* or *petroleum products* involving the *property* by any *owner* or *occupant* of the *property*?	Yes	No	Unk	Yes	No	Unk			
18a. Does the *property* discharge *waste-water* (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a storm water system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
18b. Does the *property* discharge waste water (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a sanitary sewer system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
19. Did you observe evidence or do you have any prior knowledge that any *hazardous substances* or *petroleum products*, unidentified waste materials, tires, automotive or industrial batteries, or any other waste materials have been dumped above grade, buried and/or burned on the *property* ?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
20. Is there a transformer, capacitor, or any hydraulic equipment for which there are any records indicating the presence of *PCBs*?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	

Government Records/Historical Sources Inquiry
(See guide, Section 10, and Practice E1527)

21. Do any of the following federal, state, or tribal government record systems list the *property* or any *property* within the search distance noted below (where available):

	Approximate Minimum Search Distance, miles (kilometres)		
Federal *NPL* site list	1.0 (1.6)	Yes	(No)
Federal Delisted *NPL* site list	0.5 (0.8)	Yes	(No)
Federal CERCLIS list	0.5 (0.8)	Yes	(No)
Federal CERCLIS NFRAP site list	0.5 (0.8)	Yes	(No)
Federal RCRA CORRACTS facilities list	1.0 (1.6)	Yes	(No)
Federal RCRA non-CORRACTS TSD Facilities list	0.5 (0.8)	Yes	(No)
Federal *RCRA generators list*	*property* and *adjoining properties*	(Yes)	No
Federal institutional control/engineering control registries	*property* only		
Federal *ERNS list*	*property* only	Yes	(No)
State and tribal lists of *hazardous waste sites* identified for investigation or remediation:			
State-and tribal-equivalent *NPL*	1.0 (1.6)	Yes	(No)
State-and tribal-equivalent CERCLIS	0.5 (0.8)	Yes	(No)
State-and tribal-*landfill* and/or *solid waste disposal site lists*	0.5 (0.8)	Yes	(No)
State-and tribal-leaking storage tank lists	0.5 (0.8)	(Yes)	No
State and tribal registered storage tank lists	*property* and *adjoining properties*	(Yes)	No
State and tribal *institutional control*/engineering control registries	*property* only	Yes	(No)
State and tribal voluntary cleanup sites	0.5 (0.8)	(Yes)	No
State and tribal Brownfield sites	0.5 (0.8)	(Yes)	No

22. Based upon a review of *fire insurance maps*, *local street directories*, or *aerial photographs*, all as specified in the guide (10.2.1), are any buildings or other improvements on the *property* or on an *adjoining property* identified as having been used for an industrial use or that could possibly lead to contamination of the *property*?

(Yes) No Unavailable

Result: There is a possibility of subsurface contamination this property.

The *Owner* questionnaire answers were provided was completed by:

Name

Title
Firm
Address

Phone number
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Occupant* questionnaire answers were provided by:

Name
Title
Firm
Address

Phone number
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Site Visit* questionnaire was completed by:

Name Ryan Luppino
Title Environmental Scientist III
Firm Barton & Loguidice DPC
Address 443 Electronics Parkway
Liverpool NY, 13088

Phone number (315) 457-5200
Date 6/2/2021
Relationship to site Consultant
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Government Records* and *Historical Sources Inquiry* questionnaire was completed by:

Name
Title Same as above (Site Visit questionnaire)
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

User's relationship to the site (for example, *owner*, prospective purchaser, lender, etc.)

If the *preparer*(s) is different from the *user*, complete the following:

Name of *User*
User's address

User's phone number

Copies of the completed questionnaires have been filed at:

Copies of the completed questionnaires have been mailed or delivered to:

Preparer represents that to the best of the *preparer's* knowledge the above statements and facts are true and correct and to the best of the *preparer's actual knowledge* no material facts have been suppressed or misstated.

Signature _____ Date 6/2/2021
Signature _____ Date _____
Signature _____ Date _____

If the *user* is different from the *preparer(s)*, the *user* shall sign below affirming that the completed questionnaire has been received. *It is the user's responsibility to draw conclusions regarding affirmative or unknown answers.*
Signature _____ Date _____

Completed OWNER questionnaire

process, including, in particular, the *site visit* and the government records/historical sources inquiry. If the *user* decides no further inquiry is warranted after receiving no response, an answer of unknown, or an affirmative answer, the *user* must document the reasons for any such conclusion.

5.6.1 Upon obtaining an affirmative answer, an answer of unknown or no response, the *user* should first refer to the guide. The guide may provide sufficient explanation to allow a *user* to conclude that no further inquiry is appropriate with respect to the particular question.

5.6.2 If the guide to a particular question does not, in itself, permit a *user* to conclude that no further inquiry is appropriate, then the *user* should consider other information obtained from the *transaction screen process* relating to this question. For example, while on the site performing a *site visit*, a person may find a storage tank on the *property* and therefore answer Question 10 of the *transaction screen questionnaire* in the affirmative. However, during or subsequent to the *owner/occupant* inquiry, the *owner* may establish that substances now or historically contained in the tank (for example, water) are not likely to cause contamination.

5.6.3 If either the guide to the question or other information obtained during the *transaction screen process* does not permit a *user* to conclude no further inquiry is appropriate with respect to such question, then the *user* must determine, in the exercise of the *user's* reasonable business judgment, based upon the totality of unresolved affirmative answers or answers of unknown received during the *transaction screen process*, whether further inquiry may be limited to those specific issues identified as of concern.

5.7 *Presumption*—A presumption exists that further inquiry is necessary if an affirmative answer is given to a question or because the answer was unknown or no response was given. In rebutting this presumption, the *user* should evaluate information obtained from each component of the *transaction screen process* and consider whether sufficient information has been obtained to conclude that no further inquiry is necessary. The *user* must determine, in the exercise of the *user's* reasonable business judgment, the scope of such further inquiry.

5.8 *Further Inquiry*—Upon completing the *transaction screen questionnaire*, if the *user* concludes that further inquiry or action is needed (for example, consult with an environmental consultant, contractor, governmental authority, or perform additional governmental and/or historical records review), the *user* should proceed with such inquiry. (Note that if the *user* determines to proceed with a Phase I Environment Site Assessment, the *user* may apply the current Practice E1527, Practice E2247, or alternatively the provisions of EPA's regulation "Standards and Practices for All Appropriate Inquiries," 40 C.F.R. Part 312.)

5.9 *Signature*—The *user* and the *preparer* of the *transaction screen questionnaire* must complete and sign the questionnaire as provided at the end of the questionnaire.

6. Transaction Screen Questionnaire

6.1 *Persons to Be Questioned*—The following questions should be asked of *(1)* the current *owner* of the *property*, *(2)* any major *occupant* of the *property* or, if the *property* does not have any *major occupants*, at least 10 % of the *occupants* of the *property*, and *(3)* in addition to the current *owner* and the *occupants* identified in *(2)*, any *occupant* likely to be using, treating, generating, storing, or disposing of *hazardous substances* or *petroleum products* on or from the *property*. A major *occupant* is any *occupant* using at least 40 % of the leasable area of the *property* or any anchor tenant when the *property* is a shopping center. In a multifamily *property* containing both residential and commercial uses, the *preparer* does not need to ask questions of the residential *occupants*. The *preparer* should ask each person to answer all questions to the best of the respondent's *actual knowledge* and in good faith. When completing the *site visit* column, the *preparer* should be sure to observe the *property* and any buildings and other structures on the *property*. The guide to this *transaction screen questionnaire* (see Sections 7 – 10) provides further details on the appropriate use of this questionnaire. (See Note 1.)

NOTE 1—Unk = "unknown" or "no response."

Description of Site/Address:

60 East Post Road
City of White Plains, NY

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
1a. Is the *property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
1b. Is any *adjoining property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
2a. Did you observe evidence or do you have any prior knowledge that the *property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
2b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used for an industrial use in the past?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
3a. Is the *property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	Automotive repair business.
3b. Is any *adjoining property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
4a. Did you observe evidence or do you have any prior knowledge that the *property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	Possible gas station. Old drawings show fuel pumps. No other documentation.
4b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
5a. Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	Used automotive batteries are stored until they are picked up for recycling by vendor.
5b. Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, or pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
6a. Are there currently any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	55-gallon drums are used to store waste materials until they are picked up for recycling by vendor.

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
6b. Did you observe evidence or do you have any prior knowledge that there have been previously any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	55-gallon drums have always been used to store waste materials until they are picked up for recycling by vendor.
7a. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that originated from a contaminated site?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
7b. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that is of an unknown origin?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
8a. Are there currently any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
8b. Did you observe evidence or do you have any prior knowledge that there have been previously, any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
9a. Is there currently any stained soil on the *property*?	Yes	No	**Unk**	Yes	No	Unk	Yes	No	
9b. Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil on the *property*?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
10a. Are there currently any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	**Unk**	Yes	No	Unk	Yes	No	
10b. Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks (above or underground) located on the *property*?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	Old drawings show fuel pumps, but not location of USTs.
11a. Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
11b. Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	**Yes**	No	Unk	Yes	No	Unk	Yes	No	Old drawings show fuel pumps, but not location of vent pipes or fill pipes.
12a. Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors, associated with any flooring, drains, walls, ceilings, or exposed grounds on the *property*?	Yes	No	**Unk**	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
12b. Did you observe evidence or do you have any prior knowledge that there have been previously any leaks, spills, or staining by substances other than water, or foul odors, associated with any flooring drains, walls, ceilings or exposed grounds on the *property* ?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
13a. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
13b. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well has been designated as contaminated by any government environmental/health agency?	Yes	**No**	Unk	Yes	No	Unk	Yes	No	
14. Does the *owner* or *occupant* of the *property* have any knowledge of *environmental liens* or governmental notification relating to past or recurrent violations of environmental laws with respect to the *property* or any facility located on the *property*?	Yes	**No**	Unk	Yes	No	Unk			
15a. Has the *owner* or *occupant* of the *property* been informed of the past existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	**Yes**	No	Unk	Yes	No	Unk			Historic automotive service business which includes oil changes.
15b. Has the *owner* or *occupant* of the *property* been informed of the current existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	**Yes**	No	Unk	Yes	No	Unk			Current automotive service business which includes oil changes.
15c. Has the *owner* or *occupant* of the *property* been informed of the past existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	**No**	Unk	Yes	No	Unk			
15d. Has the *owner* or *occupant* of the *property* been informed of the current existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	**No**	Unk	Yes	No	Unk			
16. Does the *owner* or *occupant* of the *property* have any knowledge of any *environmental site assessment* of the *property* or facility that indicated the presence of *hazardous substances* or *petroleum products* on, or contamination of, the *property* or recommended further assessment of the *property*?	Yes	**No**	Unk	Yes	No	Unk			

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
17. Does the *owner* or *occupant* of the *property* know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any *hazardous substance* or *petroleum products* involving the *property* by any *owner* or *occupant* of the *property*?	Yes	[No]	Unk	Yes	No	Unk			
18a. Does the *property* discharge *waste-water* (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a storm water system?	Yes	[No]	Unk	Yes	No	Unk	Yes	No	
18b. Does the *property* discharge waste water (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a sanitary sewer system?	Yes	[No]	Unk	Yes	No	Unk	Yes	No	
19. Did you observe evidence or do you have any prior knowledge that any *hazardous substances* or *petroleum products*, unidentified waste materials, tires, automotive or industrial batteries, or any other waste materials have been dumped above grade, buried and/or burned on the *property* ?	Yes	[No]	Unk	Yes	No	Unk	Yes	No	
20. Is there a transformer, capacitor, or any hydraulic equipment for which there are any records indicating the presence of *PCBs*?	Yes	No	[Unk]	Yes	No	Unk	Yes	No	

Government Records/Historical Sources Inquiry
(See guide, Section 10, and Practice E1527)

21. Do any of the following federal, state, or tribal government record systems list the *property* or any *property* within the search distance noted below (where available):

	Approximate Minimum Search Distance, miles (kilometres)		
Federal *NPL* site list	1.0 (1.6)	Yes	No
Federal Delisted *NPL* site list	0.5 (0.8)	Yes	No
Federal CERCLIS list	0.5 (0.8)	Yes	No
Federal CERCLIS NFRAP site list	0.5 (0.8)	Yes	No
Federal RCRA CORRACTS facilities list	1.0 (1.6)	Yes	No
Federal RCRA non-CORRACTS TSD Facilities list	0.5 (0.8)	Yes	No
Federal *RCRA generators list*	*property* and *adjoining properties*	Yes	No
Federal institutional control/engineering control registries	*property* only		
Federal *ERNS list*	*property* only	Yes	No
State and tribal lists of *hazardous waste sites* identified for investigation or remediation:			
State-and tribal-equivalent *NPL*	1.0 (1.6)	Yes	No
State-and tribal-equivalent CERCLIS	0.5 (0.8)	Yes	No
State-and tribal-*landfill* and/or *solid waste disposal site lists*	0.5 (0.8)	Yes	No
State-and tribal-leaking storage tank lists	0.5 (0.8)	Yes	No
State and tribal registered storage tank lists	*property* and *adjoining properties*	Yes	No
State and tribal *institutional control*/engineering control registries	*property* only	Yes	No
State and tribal voluntary cleanup sites	0.5 (0.8)	Yes	No
State and tribal Brownfield sites	0.5 (0.8)	Yes	No

22. Based upon a review of *fire insurance maps*, *local street directories*, or *aerial photographs*, all as specified in the guide (10.2.1), are any buildings or other improvements on the *property* or on an *adjoining property* identified as having been used for an industrial use or that could possibly lead to contamination of the *property*?

Yes No Unavailable

Result: _____

The *Owner* questionnaire answers were provided was completed by:

Name Mike Tharpe

Title Environmental Due Diligence Specialist
Firm Bridgestone Retail Operations, LLC
Address 200 4th Avenue South, Nashville, TN 37201

Phone number (615) 937-9377
Date 06/02/21
Role(s) at the site NA
Number of years at the site NA
Relationship to *user* (for example, principal, employee, agent, consultant) Owner

The *Occupant* questionnaire answers were provided by:

Name
Title
Firm
Address

Phone number
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Site Visit* questionnaire was completed by:

Name
Title
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Government Records* and *Historical Sources Inquiry* questionnaire was completed by:

Name
Title
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

User's relationship to the site (for example, *owner*, prospective purchaser, lender, etc.)

If the *preparer*(s) is different from the *user*, complete the following:

Name of *User*
User's address

User's phone number

Copies of the completed questionnaires have been filed at:

Copies of the completed questionnaires have been mailed or delivered to:

Preparer represents that to the best of the *preparer's* knowledge the above statements and facts are true and correct and to the best of the *preparer's actual knowledge* no material facts have been suppressed or misstated.

Signature _____ Date _____
Signature _____ Date _____
Signature _____ Date _____

If the *user* is different from the *preparer(s)*, the *user* shall sign below affirming that the completed questionnaire has been received. *It is the user's responsibility to draw conclusions regarding affirmative or unknown answers.*
Signature _____ Date _____

Completed SITE VISIT questionnaire

process, including, in particular, the *site visit* and the government records/historical sources inquiry. If the *user* decides no further inquiry is warranted after receiving no response, an answer of unknown, or an affirmative answer, the *user* must document the reasons for any such conclusion.

5.6.1 Upon obtaining an affirmative answer, an answer of unknown or no response, the *user* should first refer to the guide. The guide may provide sufficient explanation to allow a *user* to conclude that no further inquiry is appropriate with respect to the particular question.

5.6.2 If the guide to a particular question does not, in itself, permit a *user* to conclude that no further inquiry is appropriate, then the *user* should consider other information obtained from the *transaction screen process* relating to this question. For example, while on the site performing a *site visit*, a person may find a storage tank on the *property* and therefore answer Question 10 of the *transaction screen questionnaire* in the affirmative. However, during or subsequent to the *owner/occupant* inquiry, the *owner* may establish that substances now or historically contained in the tank (for example, water) are not likely to cause contamination.

5.6.3 If either the guide to the question or other information obtained during the *transaction screen process* does not permit a *user* to conclude no further inquiry is appropriate with respect to such question, then the *user* must determine, in the exercise of the *user's* reasonable business judgment, based upon the totality of unresolved affirmative answers or answers of unknown received during the *transaction screen process*, whether further inquiry may be limited to those specific issues identified as of concern.

5.7 *Presumption*—A presumption exists that further inquiry is necessary if an affirmative answer is given to a question or because the answer was unknown or no response was given. In rebutting this presumption, the *user* should evaluate information obtained from each component of the *transaction screen process* and consider whether sufficient information has been obtained to conclude that no further inquiry is necessary. The *user* must determine, in the exercise of the *user's* reasonable business judgment, the scope of such further inquiry.

5.8 *Further Inquiry*—Upon completing the *transaction screen questionnaire*, if the *user* concludes that further inquiry or action is needed (for example, consult with an environmental consultant, contractor, governmental authority, or perform additional governmental and/or historical records review), the *user* should proceed with such inquiry. (Note that if the *user* determines to proceed with a Phase I Environment Site Assessment, the *user* may apply the current Practice E1527, Practice E2247, or alternatively the provisions of EPA's regulation "Standards and Practices for All Appropriate Inquiries," 40 C.F.R. Part 312.)

5.9 *Signature*—The *user* and the *preparer* of the *transaction screen questionnaire* must complete and sign the questionnaire as provided at the end of the questionnaire.

6. Transaction Screen Questionnaire

6.1 *Persons to Be Questioned*—The following questions should be asked of *(1)* the current *owner* of the *property*, *(2)* any major *occupant* of the *property* or, if the *property* does not have any *major occupants*, at least 10 % of the *occupants* of the *property*, and *(3)* in addition to the current *owner* and the *occupants* identified in *(2)*, any *occupant* likely to be using, treating, generating, storing, or disposing of *hazardous substances* or *petroleum products* on or from the *property*. A major *occupant* is any *occupant* using at least 40 % of the leasable area of the *property* or any anchor tenant when the *property* is a shopping center. In a multifamily *property* containing both residential and commercial uses, the *preparer* does not need to ask questions of the residential *occupants*. The *preparer* should ask each person to answer all questions to the best of the respondent's *actual knowledge* and in good faith. When completing the *site visit* column, the *preparer* should be sure to observe the *property* and any buildings and other structures on the *property*. The guide to this *transaction screen questionnaire* (see Sections 7 – 10) provides further details on the appropriate use of this questionnaire. (See Note 1.)

NOTE 1—Unk = "unknown" or "no response."

Description of Site/Address:

60 East Pond Road
City of White Plains, NY

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
1a. Is the *property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
1b. Is any *adjoining property* used for an industrial use?	Yes	No	Unk	Yes	No	Unk	Yes	No	
2a. Did you observe evidence or do you have any prior knowledge that the *property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	No	

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
2b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used for an industrial use in the past?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
3a. Is the *property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Property is currently an automotive repair shop
3b. Is any *adjoining property* used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
4a. Did you observe evidence or do you have any prior knowledge that the *property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	Property is currently an automotive repair shop
4b. Did you observe evidence or do you have any prior knowledge that any *adjoining property* has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	**No**	
5a. Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	This property stores discarded automotive parts and lubricants including batteries and oil.
5b. Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, or pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	This property stores discarded automotive parts and lubricants including batteries and oil.
6a. Are there currently any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	**Yes**	No	55 gallon and larger use and new oil observed in shop area. No leaking was observed.

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
6b. Did you observe evidence or do you have any prior knowledge that there have been previously any industrial *drums* (typically 55 gal (208 L)) or sacks of chemicals located on the *property* or at the facility?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Property is currently an automotive repair shop
7a. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that originated from a contaminated site?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
7b. Did you observe evidence or do you have any prior knowledge that *fill dirt* has been brought onto the *property* that is of an unknown origin?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
8a. Are there currently any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
8b. Did you observe evidence or do you have any prior knowledge that there have been previously, any *pits, ponds*, or *lagoons* located on the *property* in connection with waste treatment or waste disposal?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
9a. Is there currently any stained soil on the *property*?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
9b. Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	NYSDEC spill records indicate soil contamination from hydraulic lift.
10a. Are there currently any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Registered AST on-site
10b. Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks (above or underground) located on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Automotive repair shop with a registered AST on-site.
11a. Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
11b. Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the *property* or adjacent to any structure located on the *property*?	Yes	No	Unk	Yes	No	(Unk)	Yes	No	
12a. Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors, associated with any flooring, drains, walls, ceilings, or exposed grounds on the *property*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	A spill on a concrete floor in the basement. Shows signs of flow towards a floor drain. Spill area was dried up. Dark stained soils observed at drain to subsurface soils.

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
12b. Did you observe evidence or do you have any prior knowledge that there have been previously any leaks, spills, or staining by substances other than water, or foul odors, associated with any flooring drains, walls, ceilings or exposed grounds on the *property* ?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Several NYSDEC Spill records pertain to this site.
13a. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
13b. If the *property* is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well has been designated as contaminated by any government environmental/health agency?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
14. Does the *owner* or *occupant* of the *property* have any knowledge of *environmental liens* or governmental notification relating to past or recurrent violations of environmental laws with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15a. Has the *owner* or *occupant* of the *property* been informed of the past existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15b. Has the *owner* or *occupant* of the *property* been informed of the current existence of *hazardous substances* or *petroleum products* with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15c. Has the *owner* or *occupant* of the *property* been informed of the past existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
15d. Has the *owner* or *occupant* of the *property* been informed of the current existence of environmental violations with respect to the *property* or any facility located on the *property*?	Yes	No	Unk	Yes	No	Unk			
16. Does the *owner* or *occupant* of the *property* have any knowledge of any *environmental site assessment* of the *property* or facility that indicated the presence of *hazardous substances* or *petroleum products* on, or contamination of, the *property* or recommended further assessment of the *property*?	Yes	No	Unk	Yes	No	Unk			

Question	Owner			Occupants (if applicable)			Observed During Site Visit		If yes, provide description
17. Does the *owner* or *occupant* of the *property* know of any past, threatened, or pending lawsuits or administrative proceedings concerning a release or threatened release of any *hazardous substance* or *petroleum products* involving the *property* by any *owner* or *occupant* of the *property*?	Yes	No	Unk	Yes	No	Unk			
18a. Does the *property* discharge *waste-water* (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a storm water system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
18b. Does the *property* discharge waste water (not including sanitary waste or storm water) onto or adjacent to the *property* and/or into a sanitary sewer system?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
19. Did you observe evidence or do you have any prior knowledge that any *hazardous substances* or *petroleum products*, unidentified waste materials, tires, automotive or industrial batteries, or any other waste materials have been dumped above grade, buried and/or burned on the *property* ?	Yes	No	Unk	Yes	No	Unk	Yes	(No)	
20. Is there a transformer, capacitor, or any hydraulic equipment for which there are any records indicating the presence of *PCBs*?	Yes	No	Unk	Yes	No	Unk	(Yes)	No	Hydraulic lifts are used at this site.

Government Records/Historical Sources Inquiry
(See guide, Section 10, and Practice E1527)

21. Do any of the following federal, state, or tribal government record systems list the *property* or any *property* within the search distance noted below (where available):

	Approximate Minimum Search Distance, miles (kilometres)		
Federal *NPL* site list	1.0 (1.6)	Yes	(No)
Federal Delisted *NPL* site list	0.5 (0.8)	Yes	(No)
Federal CERCLIS list	0.5 (0.8)	Yes	(No)
Federal CERCLIS NFRAP site list	0.5 (0.8)	Yes	(No)
Federal RCRA CORRACTS facilities list	1.0 (1.6)	Yes	(No)
Federal RCRA non-CORRACTS TSD Facilities list	0.5 (0.8)	Yes	(No)
Federal *RCRA generators list*	*property* and *adjoining properties*	(Yes)	No
Federal institutional control/engineering control registries	*property* only		
Federal *ERNS list*	*property* only	Yes	(No)
State and tribal lists of *hazardous waste sites* identified for investigation or remediation:			
State-and tribal-equivalent *NPL*	1.0 (1.6)	Yes	(No)
State-and tribal-equivalent CERCLIS	0.5 (0.8)	Yes	(No)
State-and tribal-*landfill* and/or *solid waste disposal site lists*	0.5 (0.8)	Yes	(No)
State-and tribal-leaking storage tank lists	0.5 (0.8)	(Yes)	No
State and tribal registered storage tank lists	*property* and *adjoining properties*	(Yes)	No
State and tribal *institutional control*/engineering control registries	*property* only	Yes	(No)
State and tribal voluntary cleanup sites	0.5 (0.8)	(Yes)	No
State and tribal Brownfield sites	0.5 (0.8)	(Yes)	No

22. Based upon a review of *fire insurance maps*, *local street directories*, or *aerial photographs*, all as specified in the guide (10.2.1), are any buildings or other improvements on the *property* or on an *adjoining property* identified as having been used for an industrial use or that could possibly lead to contamination of the *property*?

(Yes) No Unavailable

Result: There is a possibility of subsurface contamination this property.

The *Owner* questionnaire answers were provided was completed by:

Name

Title
Firm
Address

Phone number
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Occupant* questionnaire answers were provided by:

Name
Title
Firm
Address

Phone number
Date
Role(s) at the site
Number of years at the site
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Site Visit* questionnaire was completed by:

Name Ryan Luppino
Title Environmental Scientist III
Firm Barton & Loguidice DPC
Address 443 Electronics Parkway
Liverpool NY, 13088
Phone number (315) 457-5200
Date 6/2/2021
Relationship to site Consultant
Relationship to *user* (for example, principal, employee, agent, consultant)

The *Government Records* and *Historical Sources Inquiry* questionnaire was completed by:

Name
Title Same as above (Site Visit questionnaire)
Firm
Address

Phone number
Date
Relationship to site
Relationship to *user* (for example, principal, employee, agent, consultant)

User's relationship to the site (for example, *owner*, prospective purchaser, lender, etc.)

If the *preparer*(s) is different from the *user*, complete the following:

Name of *User*
User's address

User's phone number

Copies of the completed questionnaires have been filed at:

Copies of the completed questionnaires have been mailed or delivered to:

Preparer represents that to the best of the *preparer's* knowledge the above statements and facts are true and correct and to the best of the *preparer's actual knowledge* no material facts have been suppressed or misstated.

Signature _____ Date 6/2/2021
Signature _____ Date _____
Signature _____ Date _____

If the *user* is different from the *preparer(s)*, the *user* shall sign below affirming that the completed questionnaire has been received. *It is the user's responsibility to draw conclusions regarding affirmative or unknown answers.*
Signature _____ Date _____

ATTACHMENT 8
EDR Report

White Plains - 5 Parcels
42 East Post Road
White Plains, NY 10601

Inquiry Number: 06284645.2r
December 01, 2020

The EDR Radius Map™ Report with GeoCheck®

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	929
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-9
Physical Setting Source Map Findings	A-11
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

42 EAST POST ROAD
WHITE PLAINS, NY 10601

COORDINATES

Latitude (North):	41.0267180 - 41° 1' 36.18''
Longitude (West):	73.7695580 - 73° 46' 10.40''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	603444.2
UTM Y (Meters):	4542240.0
Elevation:	211 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	5939761 WHITE PLAINS, NY
Version Date:	2013
Northeast Map:	5641951 GLENVILLE, CT
Version Date:	2012

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20150522, 20150624
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	APARTMENT HOUSE	42-44 EAST POST RD	NY Spills		TP
A2	RAKOFF REALTY	42 EAST POST RD	NY Spills		TP
A3	MANHOLE 3471	44 POST RD	NY Spills	Higher	1 ft.
B4	CON ED MANHOLE 9169	169 LEXINGTON AVE	NY Spills	Lower	7, 0.001, West
C5	POWER TEST CORP	26 EAST POST ROAD	EDR Hist Auto	Lower	12, 0.002, SW
C6	CLOSED GETTY GAS STA	26 EAST POST RD	NY Spills	Lower	12, 0.002, SW
C7	POWER TEST/GETTY COS	26 EAST POST ROAD	NY UST	Lower	12, 0.002, SW
A8	WHITE PLAINS CITGO	34 EAST POST ROAD	NY Spills	Lower	12, 0.002, SSW
A9	BP GAS STATION	34 EAST POST RD	NY Spills	Lower	12, 0.002, SSW
A10	BP STATION- EAST POS	34 EAST POST ROAD	NY Spills	Lower	12, 0.002, SSW
A11	FORMER NORTHVILLE GA	34 EAST POST ROAD	NY Spills	Lower	12, 0.002, SSW
A12	EAST POST ROAD GASMA	34 EAST POST ROAD	NY UST	Lower	12, 0.002, SSW
A13	POST-DAVIS SERVICE S	34 E POST RD	EDR Hist Auto	Lower	12, 0.002, SSW
A14	WESTCHESTER FIRESTON	60 E POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	16, 0.003, ENE
A15	STS TIRE SERVICE	60 EAST POST ROAD	NY Spills	Higher	16, 0.003, ENE
A16	FIRESTONE COMPLETE A	60 EAST POST ROAD	NY AST	Higher	16, 0.003, ENE
C17	FRONT OF ONE STOP DE	POST ROAD	NY Spills	Lower	28, 0.005, SW
C18	COMMERCIAL UST	22-24 EAST POST RD	NY Spills	Lower	35, 0.007, SW
A19	CON EDISON SERVICE B	E POST RD & WINCHEST	RCRA NonGen / NLR, NY MANIFEST	Higher	37, 0.007, ENE
A20	CON EDISON MANHOLE:	E POST RD & WINCHEST	RCRA NonGen / NLR, NY MANIFEST	Higher	37, 0.007, ENE
C21	MANHOLE # 7278	EAST NEW YORK POST R	NY Spills	Lower	49, 0.009, SSW
B22	JOHN BOWEN GARAGE	176 S. LEXINGTON AVE	NY Spills	Lower	51, 0.010, WSW
A23	WHITE PLAINS HOSPITA	41 EAST POST ROAD,	NY UST, NY AST	Higher	53, 0.010, South
A24	WHITE PLAINS HOSPITA	41 EAST POST RD	NY Spills	Higher	53, 0.010, South
A25	WHITE PLAINS HOSPITA	41 EAST POST ROAD	NY Spills	Higher	53, 0.010, South
A26	WHITE PLAINS HOSPITA	41 POST RD	PA MANIFEST	Higher	53, 0.010, South
A27	WHITE PLAINS HOSPITA	41 E POST ROAD	NY Spills, NY SPDES	Higher	53, 0.010, South
A28	WHITE PLAINS HOSPITA	41 POST ROAD	PA MANIFEST	Higher	53, 0.010, South
A29	WHITE PLAINS HOSPITA	41 E POST RD	RCRA-LQG	Higher	53, 0.010, South
A30	WHITE PLAINS HOSPITA	41 EAST POST RD	NY Spills	Higher	53, 0.010, South
A31	WHITE PLAINS HOSPITA	41 EAST POST ROAD	NY LTANKS	Higher	53, 0.010, South
A32	WHITE PLAINS HOSPITA	41 POST RD	NY LTANKS, NY Spills, NY MANIFEST	Higher	53, 0.010, South
A33	WHITE PLAINS HOSPITA	41 POST RD	NJ MANIFEST	Higher	53, 0.010, South
B34	SWANK DRY CLEANERS	168 S LEXINGTON AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	53, 0.010, West
B35	CILIM CLEANERS CORP	168 S LEXINGTON AVE	EDR Hist Cleaner	Lower	53, 0.010, West
B36	BRIGHT SIDE CLEANERS	182 S LEXINGTON AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	67, 0.013, WSW
B37	BRIGHT SIDE CLEANERS	182 S LEXINGTON AVE	EDR Hist Cleaner	Lower	67, 0.013, WSW
C38	WHITE PLAINS HOSPITA	EAST NEW YORK POST R	NY LTANKS	Lower	72, 0.014, SW
B39	CON EDISON MANHOLE:	S LEXINGTON AVE & DE	RCRA NonGen / NLR, NY MANIFEST	Lower	74, 0.014, WSW

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
B40	MANHOLE 9169	SO LEXINGTON AVE/DEN	NY Spills	Lower	76, 0.014, WSW
C41	WHITE PLAINS HOSPITA	DAVIS AVE & EAST POS	NY Spills	Lower	77, 0.015, SSW
D42	STAR DINER ROOFTOP	66 1/2 EAST POST ROA	NY Spills	Higher	81, 0.015, ENE
B43	APARTMENT BLDG	159 SOUTH LEXINGTON	NY Spills	Lower	97, 0.018, West
D44	71 EAST POST ROAD	71 EAST POST ROAD	NY UST	Higher	98, 0.019, ENE
C45	PHILLIP WERBEL	12 EAST POST ROAD	NY UST	Lower	175, 0.033, SW
C46	SPILL NUMBER 0103645	12 EAST POST RD	NY LTANKS	Lower	175, 0.033, SW
C47	GETTY PETROLEUM CORP	11 E POST RD	NY Spills, RCRA NonGen / NLR, NY MANIFEST	Lower	191, 0.036, SW
C48	STATION #58108	11 EAST POST ROAD	NY UST	Lower	191, 0.036, SW
C49	GETTY # 58108	11 EAST POST ROAD	NY Spills	Lower	191, 0.036, SW
C50	GETTY 58108	11 EAST POST ROAD	NY Spills	Lower	191, 0.036, SW
C51	SPILL NUMBER 8600048	11 EAST POST ROAD	NY LTANKS	Lower	191, 0.036, SW
C52	GETTY 58108	11 EAST POST RD / WI	NY Spills	Lower	191, 0.036, SW
C53	POST ROAD GETTY	11 E POST RD	EDR Hist Auto	Lower	191, 0.036, SW
C54	GETTY #58108	11 EAST POST ROAD	NY Spills	Lower	191, 0.036, SW
C55	GETTY SERVICE STATIO	11 EAST POST ROAD	NY LTANKS	Lower	191, 0.036, SW
C56	STATION #58108	11 EAST POST ROAD	NY AST	Lower	191, 0.036, SW
C57	GETTY # 58108	11 EAST POST RD	NY Spills	Lower	191, 0.036, SW
C58	WHITE PLAINS HOTEL	MAPLE AVE	NY Spills	Higher	192, 0.036, SSW
C59	GETTY S/S	11 EAST POND ROAD	NY LTANKS	Higher	216, 0.041, SSW
E60	WHITE PLAIN HOUSING	225 GROVE ST	NY LTANKS	Higher	229, 0.043, NE
E61	WINBROOK HOUSING DEV	223 DR. MARTIN LUTHE	NY UST	Higher	232, 0.044, NE
E62	WINDBROOK HOUSING	223 DR MARTIN LUTHER	NY LTANKS	Higher	232, 0.044, NE
D63	WHITE PLAINS BEVERAG	234 MARTIN LUTHER KI	NY Spills	Higher	254, 0.048, NE
F64	POST RD	DAVIS AVE	NY Spills	Higher	256, 0.048, SSE
F65	WHITE PLAINS HOSPITA	MAPLE AVE	NY LTANKS	Higher	256, 0.048, SSE
F66	HOSPITAL (UNK NAME)	41 EAST COAST ROAD	NY LTANKS	Higher	256, 0.048, SSE
F67	WHITE PLAINS HOSPITA	DAVIS AVE & EAST POS	NY LTANKS, NY Spills	Higher	256, 0.048, SSE
E68	LITTLE MOUNT ZION HO	230 DR. MARTIN LUTHE	NY Spills	Higher	259, 0.049, NE
D69	SMITH SAMUEL	79 E POST ROAD	EDR Hist Auto	Higher	264, 0.050, ENE
G70	PHILLIP WERBEL	1 EAST POST ROAD	NY UST	Lower	298, 0.056, SW
G71	SPILL NUMBER 0013009	1 EAST POST RD	NY LTANKS	Lower	298, 0.056, SW
D72	CILIM CLEANERS CORP	82-84 E POST RD	EDR Hist Cleaner	Higher	332, 0.063, NE
H73	UST REMOVAL	135 SOUTH LEXINGTON	NY Spills	Lower	333, 0.063, WNW
G74	BISCARDI CLEANERS	201 SO. LEXINGTON AV	NY LTANKS, NY Spills, NY DRYCLEANERS	Lower	335, 0.063, SW
G75	BISCARDI CLEANERS	201 S LEXINGTON AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	335, 0.063, SW
G76	BISCARDI CLEANERS IN	201 S LEXINGTON AVE	EDR Hist Cleaner	Lower	335, 0.063, SW
H77	HYDRAULIC FLUID TO S	134 SOUTH LEXINGTON	NY LTANKS, NY Spills	Lower	355, 0.067, WNW
78	EL PAISA AUTO BODY	177 ORAWAMPUM ROAD	NY Spills	Higher	361, 0.068, WSW

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H79	TRINITY METHODIST CH	130 SOUTH LEXINGTON	NY Spills	Lower	391, 0.074, WNW
I80	WHITE PLAINS HOSPITA	8 LONGVIEW AVE	NY LTANKS, NY Spills	Higher	414, 0.078, ESE
I81	8 LONGVIEW DEVELOPME	8 LONGVIEW AVENUE	NY UST	Higher	414, 0.078, ESE
E82	BETHEL BAPTIST CHURC	1 FISHER COURT	NY Spills	Lower	415, 0.079, NNE
H83	CON ED	126 SOUTH LEXINGTON	NY Spills	Lower	426, 0.081, WNW
H84	COMMERCIAL	126 SOUTH LEXINGTON	NY Spills	Lower	426, 0.081, WNW
E85	CONSOLIDATED EDISON	F/O 89 EAST POST RD	NY MANIFEST	Higher	426, 0.081, ENE
I86	CON EDISON	MAPLE AVE & LONGVIEW	RCRA NonGen / NLR	Higher	433, 0.082, ESE
J87	CON EDISON	GROVE ST & FISCHER C	NJ MANIFEST	Lower	440, 0.083, NNE
J88	CON EDISON SERVICE B	GROVE ST & FISCHER A	RCRA NonGen / NLR, NY MANIFEST	Lower	440, 0.083, NNE
J89	CON EDISON	GROVE ST & FISCHER C	RCRA NonGen / NLR, FINDS, ECHO	Lower	440, 0.083, NNE
J90	CONSOLIDATED EDISON	GROVE & FISHER	NY MANIFEST	Lower	440, 0.083, NNE
H91	124 SOUTH LEXINGTON	124 SOUTH LEXINGTON	NY UST	Lower	442, 0.084, WNW
H92	GEIS SERVICE STATION	124 S LEXINGTON AVE	EDR Hist Auto	Lower	442, 0.084, WNW
H93	GAS STATION	124 SOUTH LEXINGTON	NY Spills	Lower	442, 0.084, WNW
J94	SLATER NEIGHBORHOOD	2 FISHER COURT	NY UST	Lower	449, 0.085, NNE
J95	SLADER NEIGHBORHOOD	2 FISHER CT	NY LTANKS	Lower	449, 0.085, NNE
G96	AVIS	20 WEST POST RD	NY LTANKS	Lower	457, 0.087, SW
K97	WHITE PLAINS HOSPITA	170 MAPLE AVENUE	NY UST	Higher	478, 0.091, South
K98	WHITE PLAINS MED CEN	170 MAPLE AVE	NY LTANKS	Higher	478, 0.091, South
L99	CON EDISON	CROMWELL PL & E POST	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	497, 0.094, NE
L100	CON EDISON	CROMWELL PL & E POST	RCRA NonGen / NLR	Higher	497, 0.094, NE
L101	CON EDISON	CROMWELL PL & E. NY	NY MANIFEST	Higher	497, 0.094, NE
L102	CONSOLIDATED EDISON	E NY POST RD & CROMW	NY MANIFEST	Higher	497, 0.094, NE
L103	CON ED	CROMWELL PL & E POST	NY MANIFEST	Higher	497, 0.094, NE
M104	CON EDISON MANHOLE:	QUARROPAS ST & FISCH	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	513, 0.097, NNW
M105	CON EDISON	QUARROPAS ST & FISHE	NY MANIFEST	Lower	513, 0.097, NNW
M106	CON EDISON SERVICE B	FISHER CT & QUARROPA	RCRA NonGen / NLR, FINDS	Lower	513, 0.097, NNW
M107	CON EDISON	FISHER CT & QUARROPA	NY MANIFEST	Lower	513, 0.097, NNW
N108	LINCOLN MERCURY	25 WEST POST ROAD	NY Spills	Lower	523, 0.099, SW
N109	WHITE PLAINS LINC-ME	25 W POST RD	RCRA-VSQG, NY AST, NY Spills, FINDS, ECHO, NY...	Lower	523, 0.099, SW
L110	CON EDISON	100 POST RD	RCRA NonGen / NLR	Higher	536, 0.102, NE
L111	CON EDISON	100 POST RD	NY MANIFEST	Higher	536, 0.102, NE
L112	CON EDISON	100 POST RD	NJ MANIFEST	Higher	536, 0.102, NE
H113	CON EDISON MANHOLE:	S LEXINGTON AVE & FI	RCRA NonGen / NLR, NY MANIFEST	Lower	537, 0.102, NW
H114	CON EDISON	LEXINGTON AVE & QUAR	RCRA NonGen / NLR	Lower	537, 0.102, NW
H115	CON EDISON	QUARRAPUS ST & LEXIN	NY MANIFEST	Lower	537, 0.102, NW
H116	CON EDISON	S LEXINGTON AVE & QU	NJ MANIFEST	Lower	537, 0.102, NW
H117	CON EDISON	S LEXINGTON AVE & QU	NY MANIFEST	Lower	537, 0.102, NW

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
H118	CON EDISON MANHOLE 1	S LEXINGTON AVE & FI	RCRA NonGen / NLR, NY MANIFEST	Lower	537, 0.102, NW
H119	CON EDISON	QUARROPAS ST & LEXIN	NY MANIFEST	Lower	537, 0.102, NW
H120	CON EDISON	S LEXINGTON AVE & QU	RCRA NonGen / NLR, FINDS, ECHO	Lower	537, 0.102, NW
H121	CON EDISON	LEXINGTON AVE & QUAR	NY MANIFEST	Lower	537, 0.102, NW
H122	CON EDISON	LEXINGTON AVE & QUAR	NJ MANIFEST	Lower	537, 0.102, NW
L123	CON EDISON	E POST RD & GRAND ST	NJ MANIFEST	Higher	539, 0.102, NE
L124	CON EDISON	E NEW YORK POST RD &	RCRA NonGen / NLR, FINDS, ECHO	Higher	539, 0.102, NE
L125	CON ED	E POST RD & GRAND ST	NY MANIFEST	Higher	539, 0.102, NE
L126	CON EDISON	E NEW YORK POST RD &	NJ MANIFEST	Higher	539, 0.102, NE
L127	CON ED	E NEW YORK POST RD &	NY MANIFEST	Higher	539, 0.102, NE
L128	CON EDISON	E POST RD & GRAND ST	RCRA NonGen / NLR	Higher	539, 0.102, NE
N129	CON EDISON	W POST RD & ORAWAUPU	NY MANIFEST	Higher	565, 0.107, SW
O130	WHITE PLAINS HOUSING	33 FISHER AVE	NY LTANKS, NY Spills	Lower	586, 0.111, WNW
N131	ROYAL MOTORS INC	32 W POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	587, 0.111, SW
N132	ROADWAY	32 WEST POST ROAD	NY Spills	Higher	587, 0.111, SW
N133	WHITE PLAINS LINC/ME	25 WEST COAST RD	NY LTANKS	Higher	604, 0.114, SW
N134	SHOLTZ OLDSMOBILE BU	35-55 W POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	623, 0.118, SW
N135	RRC PROPERTIES LLC	35 WEST POST ROAD	NY UST, NY AST	Higher	623, 0.118, SW
P136	MOORE - AST	8 CHESTNUT HILL AVE	NY Spills	Higher	625, 0.118, West
P137	NY OIL RECYCLING INC	9 CHESNUT HILL AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	626, 0.119, West
Q138	PARKING LOT	SOUTH LEXINGTON AVE.	NY Spills	Higher	643, 0.122, SSW
Q139	MVA	MAPLE AVE SOUTH LEXI	NY Spills	Higher	643, 0.122, SSW
Q140	POLE#40	LEXINGTON AVE& MAPLE	NY Spills	Higher	643, 0.122, SSW
L141	GRAND STREET CLEANER	104 E POST RD	EDR Hist Cleaner	Higher	647, 0.123, NE
L142	WESTCHESTER HOBBIES	104 E POST RD	RCRA NonGen / NLR, FINDS, ECHO	Higher	647, 0.123, NE
O143	CHURCH	65 FISHER AVE	NY LTANKS, NY Spills	Lower	648, 0.123, WNW
Q144	FIRE HOUSE # 4	MAPLE AVE & S LEXING	NY LTANKS	Higher	654, 0.124, SSW
Q145	CON EDISON	LEXINGTON AVE & MAPL	NJ MANIFEST	Higher	654, 0.124, SSW
Q146	CON EDISON MANHOLE:	LEXINGTON AVE & MAPL	RCRA NonGen / NLR, NY MANIFEST	Higher	654, 0.124, SSW
Q147	CON EDISON	LEXINGTON AVE & MAPL	RCRA NonGen / NLR, FINDS, ECHO	Higher	654, 0.124, SSW
Q148	CON ED	LEXINGTON AVE & MAPL	NY MANIFEST	Higher	654, 0.124, SSW
Q149	MAGNOGTA'S PARKING L	S. LEXINGTON & MAPLE	NY Spills	Higher	654, 0.124, SSW
P150	BERGMAN PROPERTY	1820 CHESTNUT HILL	NY UST	Higher	664, 0.126, West
R151	CON EDISON	GROVE ST & QUARROPAS	RCRA NonGen / NLR, NJ MANIFEST	Lower	700, 0.133, NNE
R152	CON EDISON	QUARROPAS ST & MLK B	RCRA NonGen / NLR	Lower	700, 0.133, NNE
R153	CON EDISON	QUARROPAS ST & MLK B	NJ MANIFEST	Lower	700, 0.133, NNE
R154	CONSOLIDATED EDISON	GROVE & QUERROPAS	NY MANIFEST	Lower	700, 0.133, NNE
R155	CON EDISON	QUARROPAS ST & MLK B	NY MANIFEST	Lower	700, 0.133, NNE
S156	170 GRAND STREET	170 GRAND STREET	NY LTANKS, NY Spills	Higher	703, 0.133, NNE

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
S157	170 GRAND STREET ASS	170 GRAND STREET	NY UST, NY AST	Higher	703, 0.133, NNE
N158	MH3471	F/O 44 POST ROAD	RCRA NonGen / NLR, NY MANIFEST	Higher	704, 0.133, SW
L159	REAL ESTATE - TTF	6 CHESTER AVE	NY LTANKS	Higher	722, 0.137, ENE
L160	RESIDENTS	8 CHESTER AVE	NY LTANKS	Higher	725, 0.137, ENE
S161	177 GRAND STREET ASS	177 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	731, 0.138, NNE
S162	177 GRAND STREET ASS	177 GRAND STREET	NY UST	Higher	731, 0.138, NNE
S163	COMMERCIAL BUSINESS	158 GRAND STREET	NY LTANKS	Higher	731, 0.138, NNE
S164	OFFICE BLDG BASEMENT	150 GRAND STREET	NY LTANKS	Higher	750, 0.142, NNE
S165	150 GRAND STREET OFF	150 GRAND STREET	NY UST	Higher	750, 0.142, NNE
166	RESIDENCE	25 LONGVIEW AVE	NY LTANKS	Higher	750, 0.142, SE
T167	GREENRIDGE GARDENS O	2 GREENRIDGE AVENUE	NY AST	Higher	756, 0.143, East
U168	CHESTER MAPLE PARKIN	9 CHESTER AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	766, 0.145, ENE
U169	CHESTER MAPLE PARKIN	9 CHESTER AVE	NY MANIFEST	Higher	766, 0.145, ENE
S170	CON EDISON - VAULT 4	161 GRAND ST	NY MANIFEST	Higher	768, 0.145, NNE
R171	RECKSON ASSOCIATES	140 GRAND ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	775, 0.147, NNE
T172	GREENRIDGE ESTATES C	1-13 GREENRIDGE AVE	NY LTANKS	Higher	793, 0.150, East
T173	GREENRIDGE ESTATES C	1-13 GREENRIDGE AVEN	NY AST	Higher	793, 0.150, East
T174	GREENRIDGE ESTATES	1-13 GREENRIDGE AVE	NY LTANKS	Higher	793, 0.150, East
T175	CONDO - TTF 3 TANKS	1-13 GREENRIDGE AVE	NY LTANKS	Higher	793, 0.150, East
R176	CON EDISON	111 MARTIN LUTHER KI	RCRA NonGen / NLR	Lower	804, 0.152, North
R177	CON EDISON	111 MARTIN LUTHER KI	NJ MANIFEST	Lower	804, 0.152, North
R178	WESTCHESTER COUNTY C	111 GROVE ST	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	804, 0.152, North
V179	SHOLZ BUICK, INC.	55 WEST POST ROAD	NY UST	Higher	814, 0.154, SW
V180	SHOLZ BUICK, INC.	55 WEST POST ROAD	NY AST	Higher	814, 0.154, SW
V181	SHOLZ BUICK-OLDSMOBI	55 W POST RD	NY Spills, RCRA NonGen / NLR, FINDS, ECHO, NY...	Higher	814, 0.154, SW
W182	FELIX DAVILA	36 DAVIS RD	NY LTANKS	Higher	816, 0.155, South
U183	WESTCHESTER COUNTY -	112 E POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	817, 0.155, NE
U184	WESTCHESTER OFFICE B	112 EAST POST ROAD	NY LTANKS	Higher	817, 0.155, NE
R185	WESTCHESTER COUNTY C	110 DR MARTIN LUTHER	RCRA-VSQG	Lower	817, 0.155, North
Q186	WHITE PLAINS FD STAT	234 SOUTH LEXINGTON	NY LTANKS	Higher	825, 0.156, SSW
Q187	GRANT MANOR PROPERTI	235 SOUTH LEXINGTON	NY LTANKS	Higher	840, 0.159, SSW
Q188	235 SOUTH LEXINGTON	235 SOUTH LEXINGTON	NY AST	Higher	840, 0.159, SSW
X189	MT CARMEL	92 SOUTH LEXINGTON A	NY LTANKS	Lower	857, 0.162, NW
Y190	APT. HOUSE	82 BANK STREET	NY LTANKS, NY Spills	Higher	857, 0.162, West
Y191	BSA ASSOCIATES, LLC	82 BANK STREET	NY UST	Higher	857, 0.162, West
T192	JOHN LWHITE CONDO	9 GREENRIDGE AVE	NY LTANKS	Higher	858, 0.162, East
S193	NYSDEC	GRAND & QUARRAPUS	NY MANIFEST	Higher	885, 0.168, NNE
U194	WESTHAB COACHMAN FAM	123 EAST POST ROAD	NY UST	Higher	891, 0.169, NE
U195	COACHMAN HOTEL	123 E POST RD	RCRA-VSQG	Higher	891, 0.169, NE

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
U196	COACHMAN HOTEL	123 EAST POST ROAD	NY LTANKS	Higher	891, 0.169, NE
Y197	CON EDISON GAS DRIP:	107 FISHER AVE	RCRA NonGen / NLR	Lower	914, 0.173, WNW
T198	CITY PARKING GARAGE	CHESTER AVE MARBLE A	NY LTANKS	Higher	916, 0.173, East
199	COMMERCIAL	130-144 EAST POST RD	NY LTANKS	Higher	930, 0.176, NE
200	MITCHELL ESTATE - TT	5 NUTGROVE ST	NY LTANKS	Higher	942, 0.178, WSW
Z201	GREENRIDGE MEDICAL P	12 GREENRIDGE ROAD	NY UST	Higher	961, 0.182, ESE
W202	LOPEZ - TTF	43 DAVIS AVE	NY LTANKS	Higher	963, 0.182, South
AA203	BELL ATLANTIC NY	S LEXINGTON AVE & CH	RCRA NonGen / NLR	Higher	1027, 0.195, SSW
X204	STATION PLAZA	76 SOUTH LEXINGTON A	NY UST, NY AST	Lower	1038, 0.197, NNW
X205	CON EDISON	76-78 S LEXINGTON AV	NY MANIFEST	Lower	1038, 0.197, NNW
AA206	PURDY MANOR APARTMEN	1 CHARLES STREET	NY AST	Higher	1049, 0.199, SSW
V207	POST ROAD CORRIDOR -	77 WEST POST ROAD	NY BROWNFIELDS, NY Spills	Higher	1051, 0.199, SW
Y208	US POSTAL SERVICE	100 FISHER AVE	RCRA NonGen / NLR, NY MANIFEST	Lower	1054, 0.200, WNW
Y209	CON EDISON GAS MAIN:	100 FISHER AVE	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Lower	1054, 0.200, WNW
W210	CAROD ASSOCIATES, L.	47 DAVIS AVENUE	NY UST	Higher	1058, 0.200, South
211	RESIDENCE	23 OAKWOOD RD	NY LTANKS	Higher	1061, 0.201, SSE
Y212	WHITE PLAINS MART	69 BANK STREET	NY AST	Lower	1067, 0.202, WNW
Y213	GETTY PETROLEUM CORP	69 BANK ST	RCRA NonGen / NLR, NY MANIFEST	Lower	1067, 0.202, WNW
Y214	WHITE PLAINS MART	69 BANK STREET	NY UST	Lower	1067, 0.202, WNW
Y215	CASTILLO	125-127 FISHER AVE	NY LTANKS	Lower	1077, 0.204, West
AA216	LAFRDO HOME	5 CHARLES STREET	NY LTANKS	Higher	1111, 0.210, SSW
217	77 SOUTH LEXINGTON A	77 SOUTH LEXINGTON A	NY LTANKS	Lower	1135, 0.215, NNW
AB218	COMMERCIAL BLDG	80 WEST POST ROAD	NY LTANKS, NY Spills	Higher	1142, 0.216, SW
AB219	ABCO REFRIGERATION S	80 W POST RD	RCRA NonGen / NLR, FINDS, ECHO, NY MANIFEST	Higher	1142, 0.216, SW
220	WINSTON HOME	3 WYANOKE STREET	NY LTANKS	Higher	1153, 0.218, WSW
221	PRIVATE DWELLING	11 ROOSEVELT STREET	NY LTANKS	Higher	1163, 0.220, SSW
AC222	INNS OF COURT	99 COURT ST	NY LTANKS	Higher	1173, 0.222, NNE
AC223	THE INNS OF COURT PR	99 COURT ST.	NY UST	Higher	1173, 0.222, NNE
AD224	HOME	43 LONGVIEW AVE	NY LTANKS	Higher	1184, 0.224, SE
Z225	APARTMENT BLDG	21 GREENRIDGE AVE	NY LTANKS, NY Spills	Higher	1186, 0.225, ESE
Z226	21 GREENRIDGE APARTM	21-25 GREENRIDGE AVE	NY UST	Higher	1186, 0.225, ESE
AE227	BART'S AUTO SERVICE	7 IRVING PLACE	NY AST	Lower	1187, 0.225, WNW
AF228	CON EDISON	184 MAMARONECK AVE &	RCRA NonGen / NLR, NY MANIFEST	Higher	1187, 0.225, ENE
AF229	CON ED V 5613	200 MAMORONECK AVE	RCRA NonGen / NLR, NY MANIFEST	Higher	1201, 0.227, ENE
AF230	MAMARAHAN CO.	200 MAMARONECK AVENU	NY UST	Higher	1201, 0.227, ENE
AF231	NYSDEC	202 MAMARONECK AVENU	NY Spills, NY MANIFEST	Higher	1202, 0.228, ENE
AF232	200 MAMARONECK AVENU	202 MAMARONECK AVENU	NY UST	Higher	1202, 0.228, ENE
AF233	JOHN DALE INC	178 MAMORENECK AVE	NY LTANKS	Higher	1203, 0.228, ENE
AG234	151 EAST POST ROAD C	151 EAST POST ROAD	NY UST	Higher	1206, 0.228, NE

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG235	COMMERCIAL PROERTY	151 EAST POST ROAD	NY LTANKS	Higher	1206, 0.228, NE
AH236	WEST HEALTH DEPT	148 MARTINE AVE	NY LTANKS	Higher	1209, 0.229, NNE
AF237	JOHN DALE, INC.	176-180 MAMRONECK AV	NY UST	Higher	1212, 0.230, ENE
AD238	RESIDENTS	44 LONGVIEW AVE	NY LTANKS	Higher	1223, 0.232, SE
AE239	CITY CARS METROPOLIT	25 IRVING PLACE	NY AST	Lower	1229, 0.233, WNW
AE240	CITY CARS METROPOLIT	25 IRVING PLACE	NY UST	Lower	1229, 0.233, WNW
AI241	SMITH'S DAIRY,INC.	61 BANK STREET	NY UST	Lower	1239, 0.235, WNW
AJ242	CON EDISON SERVICE B	MAMAROENCK AVE & MAP	RCRA NonGen / NLR, NY MANIFEST	Higher	1241, 0.235, East
AJ243	CON EDISON VAULT: 53	MAMARONECK AVE & MAP	RCRA NonGen / NLR, NY MANIFEST	Higher	1241, 0.235, East
AJ244	WHITE PLAINS DPW	MAPLE & MAMARONECK A	NY LTANKS	Higher	1241, 0.235, East
AJ245	CON EDISON MANHOLE:	MAMARONECK AVE & MAP	RCRA NonGen / NLR, NY MANIFEST	Higher	1241, 0.235, East
AJ246	CON EDISON	MAMARONECK AVE & MAP	RCRA NonGen / NLR, NY MANIFEST	Higher	1241, 0.235, East
AJ247	CON EDISON MANHOLE:	MAMARONECK AVE & MAP	RCRA NonGen / NLR, NY MANIFEST	Higher	1241, 0.235, East
AJ248	WHITE PLAINS-FIRE HO	MAMARONECK & MAPLE A	NY LTANKS	Higher	1241, 0.235, East
AF249	GREENWICH RIVERVIEW	193-203 MAMARONECK A	NY UST	Higher	1242, 0.235, ENE
AG250	CON EDISON	148 MAMARONECK AVE	RCRA NonGen / NLR	Higher	1242, 0.235, NE
AG251	CON EDISON	148 MAMARONECK AVE	NJ MANIFEST	Higher	1242, 0.235, NE
AG252	CON EDISON	148 MAMARONECK AVE F	RCRA NonGen / NLR, NY MANIFEST	Higher	1242, 0.235, NE
AK253	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1244, 0.236, North
AK254	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1244, 0.236, North
AK255	CON EDISON MANHOLE 9	MARTINE AVE & GROVE	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Lower	1244, 0.236, North
AF256	BASEMENT	203 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	1244, 0.236, ENE
AJ257	ANEFCO INC	222 MAMARONECK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1245, 0.236, East
AJ258	222 MAMARONECK AVENU	222 MAMARONECK AVENU	NY UST	Higher	1245, 0.236, East
AK259	CON EDISON	MARTINE & GROVE ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	1249, 0.237, North
AK260	CON EDISON	MARTINE & GROVE ST	NY MANIFEST	Lower	1249, 0.237, North
AI261	PEPE MOTORS INC	50 BANK ST	RCRA-VSQG, NY LTANKS, FINDS, ECHO, NY MANIFEST	Lower	1251, 0.237, WNW
AI262	MERCEDES- BENZ OF WH	50 BANK STREET	NY UST, NY AST	Lower	1251, 0.237, WNW
AF263	KEMPLER RESIDENCE	169 MAMARONECK AVE	NY LTANKS	Higher	1252, 0.237, ENE
AF264	STEWARD	165 MAMARONECK AVENU	NY LTANKS	Higher	1254, 0.237, ENE
AG265	CON EDISON MANHOLE 3	MAMARONECK AVE & E P	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1262, 0.239, NE
AG266	CON EDISON	E POST RD & MAMMARON	RCRA NonGen / NLR, FINDS, ECHO	Higher	1262, 0.239, NE
AG267	CON EDISON	E POST RD & MAMMARON	NJ MANIFEST	Higher	1262, 0.239, NE
AG268	CON EDISON	E POST RD & MAMMARON	NY MANIFEST	Higher	1262, 0.239, NE
AG269	CON EDISON	MAMARONECK AVE & E P	NY MANIFEST	Higher	1262, 0.239, NE
AG270	CON EDISON SB1820	MAMARONECK AVE & E P	RCRA NonGen / NLR	Higher	1262, 0.239, NE
AG271	CON EDISON MANHOLE 3	MAMARONECK AVE & E P	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1262, 0.239, NE
AG272	CON EDISON	134 MAMARANECK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1268, 0.240, NE
AG273	CON EDISON	134 MAMARONECK AVE	NY Spills, NY MANIFEST	Higher	1268, 0.240, NE

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AG274	M AND T BANK	134 MAMARONECK AVENU	NY AST	Higher	1268, 0.240, NE
AG275	CON EDISON	134 MAMARANECK AVE	NJ MANIFEST	Higher	1268, 0.240, NE
AG276	CON EDISON	134 MAMARANECK AVE	NY MANIFEST	Higher	1268, 0.240, NE
AG277	CON EDISON	134 MAMARONECK AVE	RCRA NonGen / NLR	Higher	1268, 0.240, NE
AG278	CON EDISON	134 MAMARONECK AVE	NJ MANIFEST	Higher	1268, 0.240, NE
AC279		85 COURT STREET	NY AST, NY COOLING TOWERS	Higher	1268, 0.240, NNE
AG280	CON EDISON	128 MAMARONECK AVE	RCRA NonGen / NLR, FINDS, ECHO	Higher	1271, 0.241, NE
AG281	CON EDISON	128 MAMARONECK AVE	NJ MANIFEST	Higher	1271, 0.241, NE
AG282	CON EDISON	128 MAMARONECK AVE	NY MANIFEST	Higher	1271, 0.241, NE
AG283	CON EDISON MANHOLE:	149 MAMARONECK AVE F	RCRA NonGen / NLR, NY MANIFEST	Higher	1275, 0.241, NE
AG284	PER-BAR	124 MAMARONECK AVE	NY LTANKS	Higher	1284, 0.243, NE
AJ285	SILVERMAN REALTY	235 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	1300, 0.246, East
AJ286	CON EDISON	235 MAMARONECK AVE F	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1300, 0.246, East
AJ287	CONSOLIDATED EDISON	235-237 MAMARONECK A	NY MANIFEST	Higher	1300, 0.246, East
AJ288	SILVERMAN 237, LLC	235 MAMARONECK AVENU	NY AST	Higher	1300, 0.246, East
AJ289	CON EDISON	237 MAMARONECK AVE S	RCRA NonGen / NLR, NJ MANIFEST, NY MANIFEST	Higher	1308, 0.248, East
AG290	CON EDISON SERVICE B	133 MAMARONECK AVE I	RCRA NonGen / NLR, NY MANIFEST	Higher	1308, 0.248, NE
AL291	YMCA OF CENTRAL & NO	250 MAMARONECK AVENU	NY CBS AST	Higher	1311, 0.248, East
AL292	WHITE PLAINS YMCA	250 MAMARONECK AVE	NY LTANKS	Higher	1311, 0.248, East
AL293	YMCA OF CENTRAL & NO	250 MAMARONECK AVENU	NY CBS, NY Spills	Higher	1311, 0.248, East
AL294	WHITE PLAINS FAMILY	250 MAMARONECK AVENU	NY UST	Higher	1311, 0.248, East
AE295	IRVINGTON	IRVINGTON	NY LTANKS	Lower	1313, 0.249, WNW
296	PRIVATE RESIDENCE	29 CAMBRIDGE AVE	NY LTANKS	Higher	1324, 0.251, South
297	PRIVATE RESIDENCE	36 OAKWOOD AVE	NY LTANKS	Higher	1327, 0.251, SSE
AM298	SILVERMAN REALITY	110 MAMARONECK AVE	NY LTANKS	Higher	1344, 0.255, NE
AL299	YMCA	260 MAMARONECK AVE	NY LTANKS	Higher	1345, 0.255, East
AG300	OFFICE BLDG	171 EAST POST RD	NY LTANKS	Higher	1374, 0.260, NE
AI301	WHITE PLAINS HONDA	31 WESTMPORELAND AVE	NY LTANKS	Lower	1379, 0.261, WNW
AH302	MICHAEL E LAND OFFIC	148 MARTINE AVE	NY LTANKS, NY Spills	Higher	1386, 0.262, NNE
AI303	YOUNG COAL & LUMBER	55 BANK STREET	NY BROWNFIELDS, NY MANIFEST	Lower	1390, 0.263, NW
AN304	CAMACHO	23 ODELL AVE	NY LTANKS, NY Spills	Higher	1393, 0.264, SSW
AM305	DEVON PLAZA REALITY	109 MAMARONECK AVE	NY LTANKS	Higher	1394, 0.264, NE
AM306	NICKY'S RESTAURANT	107 MAMARONECK AVE	NY LTANKS	Higher	1400, 0.265, NE
AO307	MUNICIPAL GARAGE	111	NY LTANKS	Lower	1406, 0.266, WNW
AO308	CIVIC CENTER MOTORS	31 WESTMORELAND AVE	NY LTANKS, NY Spills	Lower	1425, 0.270, WNW
AH309	INTERSECTION OF COUR	COURT ST. & MARITINE	NY LTANKS	Higher	1436, 0.272, NNE
AH310	THE MICHICALLIAN OFF	MARTINE AVE & COURT	NY LTANKS	Higher	1436, 0.272, NNE
AO311	BENEROFE ASSOCIATION	39 WESTMORELAND AVE	NY LTANKS, NY Spills	Lower	1446, 0.274, WNW
AP312	UNK HOMEOWNER	163 FISHER AVE	NY LTANKS	Higher	1447, 0.274, West

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AN313	MAGNOTTI RESIDENCE	16 ODELL AVE	NY LTANKS	Higher	1451, 0.275, SSW
AQ314	HALPERN ENTERPRISES	170 EAST POST ROAD	NY LTANKS	Higher	1458, 0.276, NE
315	ROADWAY	285 MAMARONECK AVE	NY LTANKS, NY Spills	Higher	1477, 0.280, East
316	SPILL NUMBER 0005555	20 PROSPECT ST	NY LTANKS	Higher	1488, 0.282, SSE
AR317	MARIO'S S/S	107 WEST POST ROAD	NY LTANKS, NY Spills	Higher	1509, 0.286, SW
AS318	SEACON METAL	7 INTERVAIL ST	NY LTANKS	Higher	1511, 0.286, West
AQ319	SPILL NUMBER 9900622	179 EAST COAST RD	NY LTANKS	Higher	1523, 0.288, ENE
320	MINSKOFF CORP.	179 MARTINE AVE	NY LTANKS	Higher	1557, 0.295, NNE
321	RLS REALTY CO	11 ODELL AVE	NY LTANKS, NY Spills	Higher	1561, 0.296, SSW
322	PIRRO, MONSELL REALT	40 WALLER AVE	NY LTANKS	Higher	1576, 0.298, ENE
AM323	DEVON PLAZA REALTY	9 MITCHELL PLACE	NY LTANKS, NY Spills	Higher	1585, 0.300, NE
AT324	MITCHELL PLACE ASSOC	10 MITCHELL PLACE	NY LTANKS	Higher	1605, 0.304, NE
AP325	179 FISHER AVE	179 FISHER AVE	NY LTANKS	Higher	1607, 0.304, West
AR326	KEN KNAPP CITGO	115 WEST POST ROAD	NY LTANKS, NY Spills	Higher	1613, 0.305, SW
AS327	AUTOMOBILE CLUB OF N	101 WESTMORELAND AVE	NY SHWS, NY ENG CONTROLS, NY INST CONTROL, NY...	Lower	1652, 0.313, West
AU328	A & S STORE	GALLERIA PLAZA	NY LTANKS	Lower	1686, 0.319, North
AU329	A&S STORE	GALLERIA PLAZA	NY LTANKS	Lower	1686, 0.319, North
330	SAVANELLA HOME	29 PROSPECT STREET	NY LTANKS	Higher	1723, 0.326, South
331	J C PENNEY CO INC	100 MAIN ST	NY LTANKS, NY Spills, RCRA NonGen / NLR, NY...	Lower	1726, 0.327, NNW
AU332	NY TEL	111 EAST MAIN STREET	NY LTANKS, NY Spills	Lower	1737, 0.329, North
AU333	CENTROPLEX ASSOC.	123 MAIN STREET	NY LTANKS, NY Spills	Lower	1739, 0.329, North
AT334	SPILL NUMBER 8809894	23 MITCHELL PLACE	NY LTANKS	Higher	1751, 0.332, NE
AV335	PVT DWELLING	195 FISHER AVE	NY LTANKS	Higher	1762, 0.334, WSW
336	APARTMENT BUILDING	193 EAST POST ROAD	NY LTANKS	Higher	1772, 0.336, NE
AT337	SPILL NUMBER 9905959	25 MITCHELL PLACE	NY LTANKS	Higher	1775, 0.336, NE
338	SPILL NUMBER 9807488	8 ORCHARD PARKWAY	NY LTANKS	Higher	1791, 0.339, WSW
AW339	VINTAGE RESTAURANT	171-173 MAIN STREET	NY LTANKS	Lower	1796, 0.340, North
340	JANOWSKI RESIDENCE	2 RIDGEVIEW AVE	NY LTANKS	Higher	1801, 0.341, WSW
AT341	28 MITCHELL PLACE	28 MITCHELL PLACE	NY LTANKS	Higher	1824, 0.345, NE
AV342	9 LAFAYETTE STREET	9 LAFAYETTE STREET	NY LTANKS	Higher	1824, 0.345, West
AW343	RESIDENCE	185- 187 MAIN ST	NY LTANKS	Lower	1832, 0.347, NNE
344	GATEWAY BLDG	1 NORTH LEXINGTON AV	NY LTANKS, NY Spills	Lower	1855, 0.351, NNW
AX345	DATTORRE/REAL ESTATE	73 LONGVIEW AVE	NY LTANKS	Higher	1861, 0.352, SE
AY346	SPILL NUMBER 0108164	32 MITCHELL PL	NY LTANKS	Higher	1871, 0.354, NE
AZ347	OFFICE BUILDING	14 MAMARONECK AVE	NY LTANKS	Higher	1872, 0.355, NNE
BA348	MAMARONECK AVENUE DR	359-369 MAMARONECK A	NY SHWS, NY Spills	Higher	1913, 0.362, ESE
AY349	APARTMENT BLDG	37-43 MITCHELL PL	NY LTANKS	Higher	1918, 0.363, NE
AY350	BARGAM HOME	36-38 MITCHELL PLACE	NY LTANKS	Higher	1921, 0.364, NE
AZ351	SPILL NUMBER 0206130	203 MAIN ST	NY LTANKS	Higher	1952, 0.370, NNE

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
AX352	SPILL NUMBER 0009714	77 LONGVIEW AVE	NY LTANKS	Higher	1960, 0.371, SE
BA353	COMMERCIAL PROPERTY	365 MAMARONECK AVE	NY LTANKS	Higher	1968, 0.373, ESE
AY354	APARTMENT BUILDING	40 MITCHELL PL	NY LTANKS	Higher	1970, 0.373, NE
355	SPILL NUMBER 0108396	150 WEST POST RD	NY LTANKS	Higher	1977, 0.374, SW
BA356	BASEMENT	369 MAMARONECK AVE	NY LTANKS	Higher	2003, 0.379, ESE
AY357	MGH CO	45 MITCHELL PLACE	NY LTANKS	Higher	2014, 0.381, NE
AY358	APT BUILDING	45 MITCHELL PLACE	NY LTANKS	Higher	2014, 0.381, NE
AZ359	221 MAIN STREET	221 MAIN ST	NY BROWNFIELDS, NY Spills	Higher	2015, 0.382, NNE
360	240 EAST POST RD	240 EAST POST RD	NY LTANKS	Lower	2056, 0.389, NE
BA361	WRCO MCOT	2 OLD MAMARONECK ROA	NY LTANKS, NY Spills	Higher	2085, 0.395, ESE
362	WHITE PLAINS PROJECT	179 WESTMORELAND AVE	NY LTANKS, NY Spills	Higher	2087, 0.395, West
BB363	MCTERNANA RESIDENCE	91 DAVIS AVE	NY LTANKS	Higher	2149, 0.407, SSE
364	SPILL NUMBER 0211763	13 HOWARD AVE	NY LTANKS	Higher	2165, 0.410, SSW
BC365	TORELLI	21 DEKALB AVE	NY LTANKS	Higher	2170, 0.411, East
366	TIFFANY TOWERS	56 DOYER AVE	NY LTANKS	Higher	2177, 0.412, SE
BC367	POLE #W6	18 DEKALB AVE	NY LTANKS, NY Spills	Lower	2203, 0.417, ENE
BD368	GLEASON RESIDENCE	168 WEST POST RD	NY LTANKS	Higher	2252, 0.427, SW
369	MILLER CENTER FOR NU	37 DEKALD AVE	NY LTANKS	Higher	2269, 0.430, East
BE370	HAMILTON GREEN	200 HAMILTON AVENUE	NY BROWNFIELDS, NY Spills, NY MANIFEST	Lower	2279, 0.432, North
BF371	SPILL NUMBER 0206302	50 LINDA AVE	NY LTANKS	Higher	2283, 0.432, SE
372	SUNOCO GAS S/S,WHITE	405 MAMARONECK AVENU	NY LTANKS, NY Spills	Higher	2286, 0.433, ESE
BF373	DUBBS RESIDENCE	52 LINDA AVE	NY LTANKS	Higher	2290, 0.434, SE
374	WHITE PLAINS DEPT OF	255 MAIN STREET	NY LTANKS, NY MANIFEST, NY SPDES	Higher	2296, 0.435, NNE
375	MEIER	83 LONGVIEW AVE	NY LTANKS	Higher	2309, 0.437, SSE
BF376	SPILL NUMBER 9909620	2 GRANDVIEW AVE	NY LTANKS	Higher	2315, 0.438, SE
BE377	WHITE PLAINS POLICE	279 HAMILTON AVENUE	NY LTANKS, NY MANIFEST	Lower	2317, 0.439, North
BB378	RESIDENCE	15 SMITH AVE	NY LTANKS	Higher	2320, 0.439, SSE
379	HAMILTON MAIN PARKIN	HAMILTON AVE & MAIN	NY LTANKS	Higher	2348, 0.445, NNE
BE380	FORMER WPPD	279 HAMITON AVE	NY LTANKS	Higher	2350, 0.445, North
381	APARTMENT BUILDING	10 OLD MAMARONECK RO	NY LTANKS, NY Spills	Higher	2364, 0.448, SE
BG382	COMMERICAL BUILDING	10 NEW KING STREET	NY LTANKS	Lower	2386, 0.452, NNW
BE383	EXXON, WHITE PLAINS	274 HAMILTON AVE	NY LTANKS, NY Spills	Lower	2386, 0.452, North
BB384	BASS HOME	98 DAVIS AVE	NY LTANKS	Higher	2392, 0.453, SSE
BG385	OFFICE BLDG	4 NEW KING ST	NY LTANKS	Lower	2392, 0.453, NNW
BG386	CE - WHITE PLAINS MG	9 NEW STREET AND 12	NY ENG CONTROLS, NY INST CONTROL, NY VCP	Lower	2424, 0.459, NNW
BG387	WHITE PLAINS MGP SIT	9 NEW STREET AND 12	EDR MGP	Lower	2424, 0.459, NNW
BG388	NUCLEAR DEVELOPMENT	5 NEW STREET	FUSRAP	Lower	2429, 0.460, NNW
BG389	COMMERCIAL	3 NEW KING STREET	NY LTANKS	Lower	2431, 0.460, NNW
BG390	SPILL NUMBER 0000953	1 NEW KING STREET	NY LTANKS	Lower	2433, 0.461, NNW

MAPPED SITES SUMMARY

Target Property Address:
42 EAST POST ROAD
WHITE PLAINS, NY 10601

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
BD391	COMMERCIAL BLDG	2 SOUNDVIEW AVE	NY LTANKS	Higher	2452, 0.464, SW
BH392	RESIDENCE	27 SMITH AVE	NY LTANKS	Higher	2489, 0.471, SSE
393	CROWN PLAZA HOTEL	66 HALE AVE	NY LTANKS	Lower	2502, 0.474, ENE
BI394	BART GOLDBERG APT. B	277 MARTINE AVE	NY LTANKS	Higher	2529, 0.479, NE
395	BUSINESS	2-4 WASHINGTON AVE	NY LTANKS	Higher	2542, 0.481, WNW
396	BADDERS RESIDENCE	14 SOUNDVIEW AVE	NY LTANKS, NY Spills	Higher	2569, 0.487, SSW
397	HIRSCHON HOME	14 GRANDVIEW AVE	NY LTANKS	Higher	2573, 0.487, SSE
BH398	RESIDENCE	34 SMITH AVE	NY LTANKS	Higher	2601, 0.493, SSE
399	O'NEILL RESIDENCE	3 BRYANT AVE	NY LTANKS	Higher	2617, 0.496, South
BI400	CEMMEL HOUSE BUILDIN	300 MARTINE AVE	NY LTANKS, NY Spills	Lower	2623, 0.497, NE
401	EDGAR	1 BARKER AVE	NY LTANKS	Lower	2623, 0.497, North
BJ402	SPILL NUMBER 0200263	97 LONGVIEW AVE	NY LTANKS	Higher	2639, 0.500, SSE
BJ403	RESIDENTS	97 LONVIEW AVE	NY LTANKS	Higher	2639, 0.500, SSE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
APARTMENT HOUSE 42-44 EAST POST RD WHITE PLAINS, NY	NY Spills Spill Number/Closed Date: 0011872 / 2001-02-05 Site ID: 325324 Spill Date: 2001-02-02	N/A
RAKOFF REALTY 42 EAST POST RD WHITE PLAINS, NY	NY Spills Spill Number/Closed Date: 0011871 / 2005-10-11 Site ID: 223814 Spill Date: 2001-02-02	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL ---------- National Priority List
Proposed NPL ---------- Proposed National Priority List Sites
NPL LIENS ---------- Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL ---------- National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY ---------- Federal Facility Site Information listing
SEMS ---------- Superfund Enterprise Management System

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE ---------- Superfund Enterprise Management System Archive

Federal RCRA CORRACTS facilities list

CORRACTS ---------- Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF ---------- RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-SQG ---------- RCRA - Small Quantity Generators

Federal institutional controls / engineering controls registries

LUCIS ---------- Land Use Control Information System
US ENG CONTROLS ---------- Engineering Controls Sites List
US INST CONTROLS ---------- Institutional Controls Sites List

Federal ERNS list

ERNS ---------- Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF ---------- Facility Register

State and tribal leaking storage tank lists

INDIAN LUST ---------- Leaking Underground Storage Tanks on Indian Land
NY HIST LTANKS ---------- Listing of Leaking Storage Tanks

State and tribal registered storage tank lists

FEMA UST ---------- Underground Storage Tank Listing
NY CBS UST ---------- Chemical Bulk Storage Database
NY MOSF UST ---------- Major Oil Storage Facilities Database
NY MOSF ---------- Major Oil Storage Facility Site Listing
NY MOSF AST ---------- Major Oil Storage Facilities Database
INDIAN UST ---------- Underground Storage Tanks on Indian Land
NY TANKS ---------- Storage Tank Faciliy Listing

State and tribal institutional control / engineering control registries

NY RES DECL ---------- Restrictive Declarations Listing

State and tribal voluntary cleanup sites

INDIAN VCP ---------- Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP ---------- Environmental Restoration Program Listing

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS ---------- A Listing of Brownfields Sites

EXECUTIVE SUMMARY

Local Lists of Landfill / Solid Waste Disposal Sites

NY SWRCY ---- Registered Recycling Facility List
NY SWTIRE ---- Registered Waste Tire Storage & Facility List
INDIAN ODI ---- Report on the Status of Open Dumps on Indian Lands
ODI ---- Open Dump Inventory
DEBRIS REGION 9 ---- Torres Martinez Reservation Illegal Dump Site Locations
IHS OPEN DUMPS ---- Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL ---- Delisted National Clandestine Laboratory Register
NY DEL SHWS ---- Delisted Registry Sites
US CDL ---- National Clandestine Laboratory Register
NY PFAS ---- PFAS Contamination Site Location Listing

Local Lists of Registered Storage Tanks

NY HIST UST ---- Historical Petroleum Bulk Storage Database
NY HIST AST ---- Historical Petroleum Bulk Storage Database

Local Land Records

NY LIENS ---- Spill Liens Information
LIENS 2 ---- CERCLA Lien Information

Records of Emergency Release Reports

HMIRS ---- Hazardous Materials Information Reporting System
NY Hist Spills ---- SPILLS Database
NY SPILLS 90 ---- SPILLS 90 data from FirstSearch
NY SPILLS 80 ---- SPILLS 80 data from FirstSearch

Other Ascertainable Records

FUDS ---- Formerly Used Defense Sites
DOD ---- Department of Defense Sites
SCRD DRYCLEANERS ---- State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR ---- Financial Assurance Information
EPA WATCH LIST ---- EPA WATCH LIST
2020 COR ACTION ---- 2020 Corrective Action Program List
TSCA ---- Toxic Substances Control Act
TRIS ---- Toxic Chemical Release Inventory System
SSTS ---- Section 7 Tracking Systems
ROD ---- Records Of Decision
RMP ---- Risk Management Plans
RAATS ---- RCRA Administrative Action Tracking System
PRP ---- Potentially Responsible Parties
PADS ---- PCB Activity Database System
ICIS ---- Integrated Compliance Information System
FTTS ---- FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS ---- Material Licensing Tracking System
COAL ASH DOE ---- Steam-Electric Plant Operation Data

COAL ASH EPA ---- Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER ---- PCB Transformer Registration Database
RADINFO ---- Radiation Information Database
HIST FTTS ---- FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS ---- Incident and Accident Data
CONSENT ---- Superfund (CERCLA) Consent Decrees
INDIAN RESERV ---- Indian Reservations
UMTRA ---- Uranium Mill Tailings Sites
LEAD SMELTERS ---- Lead Smelter Sites
US AIRS ---- Aerometric Information Retrieval System Facility Subsystem
US MINES ---- Mines Master Index File
ABANDONED MINES ---- Abandoned Mines
UXO ---- Unexploded Ordnance Sites
DOCKET HWC ---- Hazardous Waste Compliance Docket Listing
FUELS PROGRAM ---- EPA Fuels Program Registered Listing
NY AIRS ---- Air Emissions Data
NY COAL ASH ---- Coal Ash Disposal Site Listing
NY E DESIGNATION ---- E DESIGNATION SITE LISTING
NY Financial Assurance ---- Financial Assurance Information Listing
NY HSWDS ---- Hazardous Substance Waste Disposal Site Inventory
NY VAPOR REOPENED ---- Vapor Intrusion Legacy Site List
NY UIC ---- Underground Injection Control Wells
NY LEAD ---- Lead-based Paint Testing Results
MINES MRDS ---- Mineral Resources Data System

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

NY RGA HWS ---- Recovered Government Archive State Hazardous Waste Facilities List
NY RGA LF ---- Recovered Government Archive Solid Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.
Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA)

of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/15/2020 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA EPA ID:: NYR000129965	41 E POST RD	S 0 - 1/8 (0.010 mi.)	A29	69

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/15/2020 has revealed that there are 4 RCRA-VSQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
COACHMAN HOTEL EPA ID:: NY0000895086	123 E POST RD	NE 1/8 - 1/4 (0.169 mi.)	U195	430

Lower Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS LINC-ME EPA ID:: NYD052088754	***25 W POST RD***	***SW 0 - 1/8 (0.099 mi.)***	***N109***	***241***
WESTCHESTER COUNTY C EPA ID:: NYR000124206	110 DR MARTIN LUTHER	N 1/8 - 1/4 (0.155 mi.)	R185	410
PEPE MOTORS INC EPA ID:: NYD056298037	***50 BANK ST***	***WNW 1/8 - 1/4 (0.237 mi.)***	***AI261***	***579***

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 08/10/2020 has revealed that there are 2 NY SHWS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MAMARONECK AVENUE DR Site Code: 387008	***359-369 MAMARONECK A***	***ESE 1/4 - 1/2 (0.362 mi.)***	***BA348***	***813***

Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTOMOBILE CLUB OF N	***101 WESTMORELAND AVE***	***W 1/4 - 1/2 (0.313 mi.)***	***AS327***	***736***

EXECUTIVE SUMMARY

Site Code: 374633

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 08/10/2020 has revealed that there are 168 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA Spill Number/Closed Date: 9414693 / 1995-02-13 Site ID: 68377 Spill Date: 1995-02-08	41 EAST POST ROAD	S 0 - 1/8 (0.010 mi.)	A31	80
WHITE PLAINS HOSPITA Spill Number/Closed Date: 1107393 / 2011-10-31 Site ID: 455090 Spill Date: 2011-09-12	***41 POST RD***	***S 0 - 1/8 (0.010 mi.)***	***A32***	***81***
GETTY S/S Spill Number/Closed Date: 9210753 / 1992-12-31 Site ID: 319803 Spill Date: 1992-12-16	11 EAST POND ROAD	SSW 0 - 1/8 (0.041 mi.)	C59	156
WHITE PLAIN HOUSING Spill Number/Closed Date: 8904683 / 1992-07-30 Site ID: 293104 Spill Date: 1989-08-10	225 GROVE ST	NE 0 - 1/8 (0.043 mi.)	E60	157
WINDBROOK HOUSING Spill Number/Closed Date: 0207150 / 2002-11-25 Site ID: 243532 Spill Date: 2002-10-10	223 DR MARTIN LUTHER	NE 0 - 1/8 (0.044 mi.)	E62	160
WHITE PLAINS HOSPITA Spill Number/Closed Date: 9304740 / 1994-01-06 Site ID: 290020 Spill Date: 1993-07-15	MAPLE AVE	SSE 0 - 1/8 (0.048 mi.)	F65	164
HOSPITAL (UNK NAME) Spill Number/Closed Date: 9806058 / 1998-08-17 Site ID: 191235 Spill Date: 1998-08-14	41 EAST COAST ROAD	SSE 0 - 1/8 (0.048 mi.)	F66	165
WHITE PLAINS HOSPITA Spill Number/Closed Date: 9303501 / 1996-06-18 Site ID: 66799 Spill Date: 1993-06-14	***DAVIS AVE & EAST POS***	***SSE 0 - 1/8 (0.048 mi.)***	***F67***	***166***
WHITE PLAINS HOSPITA Spill Number/Closed Date: 1007877 / 2011-07-05 Spill Number/Closed Date: 0907812 / 2009-11-04 Spill Number/Closed Date: 1007255 / 2017-12-12	***8 LONGVIEW AVE***	***ESE 0 - 1/8 (0.078 mi.)***	***I80***	***186***

Site ID: 441326
Site ID: 420361
Site ID: 440652
Spill Date: 2010-10-25
Spill Date: 2009-10-12
Spill Date: 2010-10-06

WHITE PLAINS MED CEN	170 MAPLE AVE	S 0 - 1/8 (0.091 mi.)	K98	219
Spill Number/Closed Date: 0004388 / 2001-06-22				
Site ID: 204425				
Spill Date: 2000-07-12				
WHITE PLAINS LINC/ME	25 WEST COAST RD	SW 0 - 1/8 (0.114 mi.)	N133	299
Spill Number/Closed Date: 0005954 / 2001-04-24				
Site ID: 226425				
Spill Date: 2000-08-18				
FIRE HOUSE # 4	MAPLE AVE & S LEXING	SSW 0 - 1/8 (0.124 mi.)	Q144	323
Spill Number/Closed Date: 8707150 / 1989-01-05				
Site ID: 178231				
Spill Date: 1987-11-19				
170 GRAND STREET	***170 GRAND STREET***	***NNE 1/8 - 1/4 (0.133 mi.)***	***S156***	***344***
Spill Number/Closed Date: 0408227 / 2007-11-28				
Site ID: 332894				
Spill Date: 2004-10-26				
REAL ESTATE - TTF	6 CHESTER AVE	ENE 1/8 - 1/4 (0.137 mi.)	L159	351
Spill Number/Closed Date: 1506711 / 2019-02-08				
Site ID: 514142				
Spill Date: 2015-09-24				
RESIDENTS	8 CHESTER AVE	ENE 1/8 - 1/4 (0.137 mi.)	L160	353
Spill Number/Closed Date: 9610881 / 2012-04-16				
Site ID: 71801				
Spill Date: 1996-12-03				
COMMERCIAL BUSINESS	158 GRAND STREET	NNE 1/8 - 1/4 (0.138 mi.)	S163	361
Spill Number/Closed Date: 0506649 / 2006-02-03				
Spill Number/Closed Date: 0413115 / 2005-09-07				
Site ID: 351900				
Site ID: 338963				
Spill Date: 2005-08-30				
Spill Date: 2005-03-16				
OFFICE BLDG BASEMENT	150 GRAND STREET	NNE 1/8 - 1/4 (0.142 mi.)	S164	363
Spill Number/Closed Date: 8908740 / 1990-02-07				
Site ID: 307349				
Spill Date: 1989-12-05				
RESIDENCE	25 LONGVIEW AVE	SE 1/8 - 1/4 (0.142 mi.)	166	365
Spill Number/Closed Date: 0413208 / 2005-05-08				
Site ID: 339072				
Spill Date: 2005-03-18				
GREENRIDGE ESTATES C	1-13 GREENRIDGE AVE	E 1/8 - 1/4 (0.150 mi.)	T172	378
Spill Number/Closed Date: 1911181 / Not Reported				
Site ID: 601870				
Spill Date: 2020-03-04				
GREENRIDGE ESTATES	1-13 GREENRIDGE AVE	E 1/8 - 1/4 (0.150 mi.)	T174	380
Spill Number/Closed Date: 0912193 / 2011-12-22				

Site ID: 425068
Spill Date: 2010-02-22

CONDO - TTF 3 TANKS	1-13 GREENRIDGE AVE	E 1/8 - 1/4 (0.150 mi.)	T175	381
Spill Number/Closed Date: 1911256 / Not Reported				
Site ID: 601947				
Spill Date: 2020-03-06				
FELIX DAVILA	36 DAVIS RD	S 1/8 - 1/4 (0.155 mi.)	W182	402
Spill Number/Closed Date: 0304516 / 2003-10-23				
Site ID: 187946				
Spill Date: 2003-07-29				
WESTCHESTER OFFICE B	112 EAST POST ROAD	NE 1/8 - 1/4 (0.155 mi.)	U184	409
Spill Number/Closed Date: 9009334 / 1990-12-11				
Site ID: 243138				
Spill Date: 1990-11-27				
WHITE PLAINS FD STAT	234 SOUTH LEXINGTON	SSW 1/8 - 1/4 (0.156 mi.)	Q186	414
Spill Number/Closed Date: 9804511 / 1998-08-12				
Site ID: 320194				
Spill Date: 1998-07-10				
GRANT MANOR PROPERTI	235 SOUTH LEXINGTON	SSW 1/8 - 1/4 (0.159 mi.)	Q187	415
Spill Number/Closed Date: 9706472 / 1998-02-27				
Spill Number/Closed Date: 0204243 / 2002-11-06				
Spill Number/Closed Date: 0304500 / 2003-10-31				
Spill Number/Closed Date: 9313731 / 1995-01-05				
Site ID: 147080				
Site ID: 147077				
Site ID: 147078				
Site ID: 147079				
Spill Date: 1997-08-28				
Spill Date: 2002-07-23				
Spill Date: 2003-07-29				
Spill Date: 1994-02-22				
APT. HOUSE	***82 BANK STREET***	***W 1/8 - 1/4 (0.162 mi.)***	***Y190***	***424***
Spill Number/Closed Date: 0312286 / 2005-03-27				
Site ID: 301757				
Spill Date: 2004-02-04				
JOHN LWHITE CONDO	9 GREENRIDGE AVE	E 1/8 - 1/4 (0.162 mi.)	T192	426
Spill Number/Closed Date: 0911533 / 2011-10-28				
Site ID: 424347				
Spill Date: 2010-01-27				
COACHMAN HOTEL	123 EAST POST ROAD	NE 1/8 - 1/4 (0.169 mi.)	U196	434
Spill Number/Closed Date: 9306655 / 1993-09-24				
Site ID: 211948				
Spill Date: 1993-08-31				
CITY PARKING GARAGE	CHESTER AVE MARBLE A	E 1/8 - 1/4 (0.173 mi.)	T198	437
Spill Number/Closed Date: 9109520 / 1992-03-25				
Site ID: 158538				
Spill Date: 1991-12-06				
COMMERCIAL	130-144 EAST POST RD	NE 1/8 - 1/4 (0.176 mi.)	199	438
Spill Number/Closed Date: 0002215 / 2011-02-28				
Site ID: 159846				
Spill Date: 2000-05-22				
MITCHELL ESTATE - TT	5 NUTGROVE ST	WSW 1/8 - 1/4 (0.178 mi.)	200	440

Spill Number/Closed Date: 1405501 / 2014-11-19
Site ID: 498930
Spill Date: 2014-08-20

LOPEZ - TTF	43 DAVIS AVE	S 1/8 - 1/4 (0.182 mi.)	W202	442
Spill Number/Closed Date: 1407225 / 2015-09-25				
Site ID: 500733				
Spill Date: 2014-10-10				
RESIDENCE	23 OAKWOOD RD	SSE 1/8 - 1/4 (0.201 mi.)	211	467
Spill Number/Closed Date: 9906780 / 2000-01-28				
Site ID: 246760				
Spill Date: 1999-09-07				
LAFRDO HOME	5 CHARLES STREET	SSW 1/8 - 1/4 (0.210 mi.)	AA216	479
Spill Number/Closed Date: 0504800 / 2006-05-01				
Site ID: 349713				
Spill Date: 2005-07-21				
COMMERCIAL BLDG	***80 WEST POST ROAD***	***SW 1/8 - 1/4 (0.216 mi.)***	***AB218***	***481***
Spill Number/Closed Date: 0609508 / 2007-01-10				
Site ID: 373822				
Spill Date: 2006-11-17				
WINSTON HOME	3 WYANOKE STREET	WSW 1/8 - 1/4 (0.218 mi.)	220	489
Spill Number/Closed Date: 0607149 / 2007-02-06				
Spill Number/Closed Date: 0607758 / 2007-02-06				
Spill Number/Closed Date: 0610630 / 2007-02-06				
Site ID: 370661				
Site ID: 371575				
Site ID: 375107				
Spill Date: 2006-09-21				
Spill Date: 2006-10-07				
Spill Date: 2006-12-19				
PRIVATE DWELLING	11 ROOSEVELT STREET	SSW 1/8 - 1/4 (0.220 mi.)	221	492
Spill Number/Closed Date: 0708659 / 2013-01-30				
Site ID: 389600				
Spill Date: 2007-11-08				
INNS OF COURT	99 COURT ST	NNE 1/8 - 1/4 (0.222 mi.)	AC222	493
Spill Number/Closed Date: 9606465 / 2006-02-28				
Site ID: 204590				
Spill Date: 1996-08-20				
HOME	43 LONGVIEW AVE	SE 1/8 - 1/4 (0.224 mi.)	AD224	496
Spill Number/Closed Date: 0507448 / 2006-03-15				
Spill Number/Closed Date: 0508523 / 2006-07-11				
Site ID: 352870				
Site ID: 354077				
Spill Date: 2005-09-21				
Spill Date: 2005-10-17				
APARTMENT BLDG	***21 GREENRIDGE AVE***	***ESE 1/8 - 1/4 (0.225 mi.)***	***Z225***	***498***
Spill Number/Closed Date: 0410525 / 2005-02-24				
Site ID: 335499				
Spill Date: 2004-12-22				
JOHN DALE INC	178 MAMORENECK AVE	ENE 1/8 - 1/4 (0.228 mi.)	AF233	513
Spill Number/Closed Date: 9810809 / 1998-12-01				
Site ID: 325049				

Spill Date: 1998-11-25				
COMMERCIAL PROERTY Spill Number/Closed Date: 0601015 / 2006-11-03 Site ID: 363155 Spill Date: 2006-04-26	151 EAST POST ROAD	NE 1/8 - 1/4 (0.228 mi.)	AG235	515
WEST HEALTH DEPT Spill Number/Closed Date: 8701223 / 2004-11-06 Site ID: 126440 Spill Date: 1987-05-13	148 MARTINE AVE	NNE 1/8 - 1/4 (0.229 mi.)	AH236	516
RESIDENTS Spill Number/Closed Date: 9614364 / 1997-03-11 Site ID: 166538 Spill Date: 1997-03-11	44 LONGVIEW AVE	SE 1/8 - 1/4 (0.232 mi.)	AD238	519
WHITE PLAINS DPW Spill Number/Closed Date: 9111846 / 1992-03-10 Site ID: 90852 Spill Date: 1992-02-18	MAPLE & MAMARONECK A	E 1/8 - 1/4 (0.235 mi.)	AJ244	530
WHITE PLAINS-FIRE HO Spill Number/Closed Date: 8707149 / 1989-01-05 Site ID: 311048 Spill Date: 1987-11-19	MAMARONECK & MAPLE A	E 1/8 - 1/4 (0.235 mi.)	AJ248	542
BASEMENT Spill Number/Closed Date: 9710787 / Not Reported Site ID: 329412 Spill Date: 1997-12-22	***203 MAMARONECK AVE***	***ENE 1/8 - 1/4 (0.236 mi.)***	***AF256***	***567***
KEMPLER RESIDENCE Spill Number/Closed Date: 0301465 / 2003-08-25 Site ID: 160482 Spill Date: 2003-05-09	169 MAMARONECK AVE	ENE 1/8 - 1/4 (0.237 mi.)	AF263	591
STEWARD Spill Number/Closed Date: 0303361 / 2007-06-22 Spill Number/Closed Date: 9701601 / 2005-02-12 Site ID: 180689 Site ID: 118993 Spill Date: 2003-06-30 Spill Date: 1997-05-06	165 MAMARONECK AVENU	ENE 1/8 - 1/4 (0.237 mi.)	AF264	592
PER-BAR Spill Number/Closed Date: 8802839 / 1989-01-18 Site ID: 116904 Spill Date: 1988-06-29	124 MAMARONECK AVE	NE 1/8 - 1/4 (0.243 mi.)	AG284	636
SILVERMAN REALTY Spill Number/Closed Date: 0404588 / 2005-01-10 Spill Number/Closed Date: 1112859 / 2012-03-30 Site ID: 128036 Site ID: 460824 Spill Date: 2004-07-28 Spill Date: 2012-02-09	***235 MAMARONECK AVE***	***E 1/8 - 1/4 (0.246 mi.)***	***AJ285***	***637***
WHITE PLAINS YMCA Spill Number/Closed Date: 1410006 / 2015-12-08 Site ID: 503665 Spill Date: 2015-01-12	250 MAMARONECK AVE	E 1/8 - 1/4 (0.248 mi.)	AL292	657
PRIVATE RESIDENCE	29 CAMBRIDGE AVE	S 1/4 - 1/2 (0.251 mi.)	296	672

Spill Number/Closed Date: 1007882 / 2010-12-17 Site ID: 441331 Spill Date: 2010-10-25				
PRIVATE RESIDENCE Spill Number/Closed Date: 1212813 / 2013-02-07 Site ID: 475969 Spill Date: 2012-11-29	36 OAKWOOD AVE	SSE 1/4 - 1/2 (0.251 mi.)	297	673
SILVERMAN REALITY Spill Number/Closed Date: 0011270 / 2003-01-22 Site ID: 308222 Spill Date: 2001-01-16	110 MAMARONECK AVE	NE 1/4 - 1/2 (0.255 mi.)	AM298	674
YMCA Spill Number/Closed Date: 9013259 / 2002-03-23 Site ID: 263885 Spill Date: 1991-03-28	260 MAMARONECK AVE	E 1/4 - 1/2 (0.255 mi.)	AL299	676
OFFICE BLDG Spill Number/Closed Date: 9811157 / 2004-03-30 Site ID: 293961 Spill Date: 1998-12-04	171 EAST POST RD	NE 1/4 - 1/2 (0.260 mi.)	AG300	677
MICHAEL E LAND OFFIC Spill Number/Closed Date: 0301426 / 2003-05-08 Spill Number/Closed Date: 0503295 / 2005-09-26 Spill Number/Closed Date: 0109874 / 2002-01-14 Site ID: 214706 Site ID: 347878 Site ID: 126439 Spill Date: 2003-05-08 Spill Date: 2005-06-17 Spill Date: 2002-01-11	***148 MARTINE AVE***	***NNE 1/4 - 1/2 (0.262 mi.)***	***AH302***	***680***
CAMACHO Spill Number/Closed Date: 0204631 / 2008-07-14 Site ID: 153929 Spill Date: 2002-08-01	***23 ODELL AVE***	***SSW 1/4 - 1/2 (0.264 mi.)***	***AN304***	***691***
DEVON PLAZA REALITY Spill Number/Closed Date: 9512203 / 1995-12-29 Site ID: 254450 Spill Date: 1995-12-29	109 MAMARONECK AVE	NE 1/4 - 1/2 (0.264 mi.)	AM305	693
NICKY'S RESTAURANT Spill Number/Closed Date: 8900599 / 1989-05-03 Site ID: 239748 Spill Date: 1989-04-19	107 MAMARONECK AVE	NE 1/4 - 1/2 (0.265 mi.)	AM306	694
INTERSECTION OF COUR Spill Number/Closed Date: 8905963 / 1989-11-29 Site ID: 187446 Spill Date: 1989-09-18	COURT ST. & MARITINE	NNE 1/4 - 1/2 (0.272 mi.)	AH309	702
THE MICHICALLIAN OFF Spill Number/Closed Date: 9310783 / 1993-11-18 Site ID: 276042 Spill Date: 1993-11-16	MARTINE AVE & COURT	NNE 1/4 - 1/2 (0.272 mi.)	AH310	703
UNK HOMEOWNER Spill Number/Closed Date: 1104419 / 2014-11-05	163 FISHER AVE	W 1/4 - 1/2 (0.274 mi.)	AP312	708

Site ID: 452024
Spill Date: 2011-07-20

MAGNOTTI RESIDENCE Spill Number/Closed Date: 9810325 / 1999-01-19 Site ID: 124170 Spill Date: 1998-11-16	16 ODELL AVE	SSW 1/4 - 1/2 (0.275 mi.)	AN313	709
HALPERN ENTERPRISES Spill Number/Closed Date: 8804996 / 2005-04-30 Site ID: 154885 Spill Date: 1988-09-08	170 EAST POST ROAD	NE 1/4 - 1/2 (0.276 mi.)	AQ314	710
ROADWAY Spill Number/Closed Date: 9712450 / 2020-07-10 Site ID: 85909 Spill Date: 1998-02-07	***285 MAMARONECK AVE***	***E 1/4 - 1/2 (0.280 mi.)***	***315***	***711***
SPILL NUMBER 0005555 Spill Number/Closed Date: 0005555 / 2000-08-29 Site ID: 122722 Spill Date: 2000-08-09	20 PROSPECT ST	SSE 1/4 - 1/2 (0.282 mi.)	316	714
MARIO'S S/S Spill Number/Closed Date: 9408490 / 1994-09-30 Site ID: 255844 Spill Date: 1994-09-26	***107 WEST POST ROAD***	***SW 1/4 - 1/2 (0.286 mi.)***	***AR317***	***715***
SEACON METAL Spill Number/Closed Date: 8904791 / 1989-11-30 Site ID: 252170 Spill Date: 1989-08-14	7 INTERVAIL ST	W 1/4 - 1/2 (0.286 mi.)	AS318	720
SPILL NUMBER 9900622 Spill Number/Closed Date: 9900622 / 2000-03-24 Site ID: 260731 Spill Date: 1999-04-16	179 EAST COAST RD	ENE 1/4 - 1/2 (0.288 mi.)	AQ319	721
MINSKOFF CORP. Spill Number/Closed Date: 9201879 / 1992-05-15 Site ID: 217944 Spill Date: 1992-05-15	179 MARTINE AVE	NNE 1/4 - 1/2 (0.295 mi.)	320	722
RLS REALTY CO Spill Number/Closed Date: 0803661 / 2008-07-14 Spill Number/Closed Date: 1215385 / 2013-02-14 Site ID: 400429 Site ID: 478685 Spill Date: 2008-06-27 Spill Date: 2013-02-07	***11 ODELL AVE***	***SSW 1/4 - 1/2 (0.296 mi.)***	***321***	***723***
PIRRO, MONSELL REALT Spill Number/Closed Date: 8709325 / 1988-02-02 Site ID: 162080 Spill Date: 1988-02-02	40 WALLER AVE	ENE 1/4 - 1/2 (0.298 mi.)	322	726
DEVON PLAZA REALTY Spill Number/Closed Date: 9710474 / 1998-10-27 Site ID: 199404 Spill Date: 1997-12-12	***9 MITCHELL PLACE***	***NE 1/4 - 1/2 (0.300 mi.)***	***AM323***	***727***
MITCHELL PLACE ASSOC Spill Number/Closed Date: 8902485 / 1989-10-02	10 MITCHELL PLACE	NE 1/4 - 1/2 (0.304 mi.)	AT324	730

Site ID: 76057
Spill Date: 1989-06-09

179 FISHER AVE Spill Number/Closed Date: 0712211 / 2009-08-31 Site ID: 393798 Spill Date: 2008-02-20	179 FISHER AVE	W 1/4 - 1/2 (0.304 mi.)	AP325	731
KEN KNAPP CITGO Spill Number/Closed Date: 9005629 / 1990-12-17 Site ID: 255569 Spill Date: 1990-08-21	***115 WEST POST ROAD***	***SW 1/4 - 1/2 (0.305 mi.)***	***AR326***	***732***
SAVANELLA HOME Spill Number/Closed Date: 0800443 / 2008-06-08 Site ID: 396199 Spill Date: 2008-04-11	29 PROSPECT STREET	S 1/4 - 1/2 (0.326 mi.)	330	764
SPILL NUMBER 8809894 Spill Number/Closed Date: 8809894 / 1991-12-20 Site ID: 286069 Spill Date: 1989-03-23	23 MITCHELL PLACE	NE 1/4 - 1/2 (0.332 mi.)	AT334	782
PVT DWELLING Spill Number/Closed Date: 0909891 / 2014-01-16 Site ID: 422623 Spill Date: 2009-12-07	195 FISHER AVE	WSW 1/4 - 1/2 (0.334 mi.)	AV335	784
APARTMENT BUILDING Spill Number/Closed Date: 0310631 / 2005-10-11 Site ID: 158568 Spill Date: 2003-12-15	193 EAST POST ROAD	NE 1/4 - 1/2 (0.336 mi.)	336	785
SPILL NUMBER 9905959 Spill Number/Closed Date: 9905959 / 1999-10-08 Site ID: 111332 Spill Date: 1999-08-17	25 MITCHELL PLACE	NE 1/4 - 1/2 (0.336 mi.)	AT337	786
SPILL NUMBER 9807488 Spill Number/Closed Date: 8706819 / 1989-11-29 Spill Number/Closed Date: 9807488 / 1998-11-20 Site ID: 135632 Site ID: 135633 Spill Date: 1987-11-10 Spill Date: 1998-09-18	8 ORCHARD PARKWAY	WSW 1/4 - 1/2 (0.339 mi.)	338	787
JANOWSKI RESIDENCE Spill Number/Closed Date: 0602736 / 2006-07-30 Site ID: 365284 Spill Date: 2006-06-12	2 RIDGEVIEW AVE	WSW 1/4 - 1/2 (0.341 mi.)	340	793
28 MITCHELL PLACE Spill Number/Closed Date: 9901259 / 1999-05-13 Spill Number/Closed Date: 9903630 / 2001-11-14 Site ID: 206822 Site ID: 206823 Spill Date: 1999-05-03 Spill Date: 1999-06-29	28 MITCHELL PLACE	NE 1/4 - 1/2 (0.345 mi.)	AT341	795
9 LAFAYETTE STREET Spill Number/Closed Date: 0208594 / 2012-08-13 Site ID: 322970	9 LAFAYETTE STREET	W 1/4 - 1/2 (0.345 mi.)	AV342	797

Spill Date: 2002-11-19

DATTORRE/REAL ESTATE — 73 LONGVIEW AVE — SE 1/4 - 1/2 (0.352 mi.) — AX345 — 806
Spill Number/Closed Date: 1503444 / 2015-10-08
Site ID: 509746
Spill Date: 2015-06-29

SPILL NUMBER 0108164 — 32 MITCHELL PL — NE 1/4 - 1/2 (0.354 mi.) — AY346 — 808
Spill Number/Closed Date: 0108164 / 2002-07-22
Spill Number/Closed Date: 9611678 / 1996-12-24
Spill Number/Closed Date: 9611679 / 1997-11-10
Site ID: 255456
Site ID: 255457
Site ID: 255458
Spill Date: 2001-11-12
Spill Date: 1996-12-24

OFFICE BUILDING — 14 MAMARONECK AVE — NNE 1/4 - 1/2 (0.355 mi.) — AZ347 — 811
Spill Number/Closed Date: 9613653 / 1997-03-05
Spill Number/Closed Date: 0313324 / 2004-04-22
Site ID: 284245
Site ID: 229197
Spill Date: 1997-02-20
Spill Date: 2004-03-04

APARTMENT BLDG — 37-43 MITCHELL PL — NE 1/4 - 1/2 (0.363 mi.) — AY349 — 815
Spill Number/Closed Date: 0208214 / 2003-04-07
Site ID: 248365
Spill Date: 2002-11-07

BARGAM HOME — 36-38 MITCHELL PLACE — NE 1/4 - 1/2 (0.364 mi.) — AY350 — 816
Spill Number/Closed Date: 0505320 / 2005-12-18
Site ID: 350305
Spill Date: 2005-08-01

SPILL NUMBER 0206130 — 203 MAIN ST — NNE 1/4 - 1/2 (0.370 mi.) — AZ351 — 817
Spill Number/Closed Date: 0206130 / 2003-09-03
Site ID: 176565
Spill Date: 2002-09-12

SPILL NUMBER 0009714 — 77 LONGVIEW AVE — SE 1/4 - 1/2 (0.371 mi.) — AX352 — 818
Spill Number/Closed Date: 0009714 / 2000-12-26
Site ID: 155379
Spill Date: 2000-11-16

COMMERCIAL PROPERTY — 365 MAMARONECK AVE — ESE 1/4 - 1/2 (0.373 mi.) — BA353 — 819
Spill Number/Closed Date: 0310423 / 2005-03-05
Site ID: 156660
Spill Date: 2003-12-09

APARTMENT BUILDING — 40 MITCHELL PL — NE 1/4 - 1/2 (0.373 mi.) — AY354 — 821
Spill Number/Closed Date: 0304394 / 2003-10-31
Site ID: 151265
Spill Date: 2003-07-25

SPILL NUMBER 0108396 — 150 WEST POST RD — SW 1/4 - 1/2 (0.374 mi.) — 355 — 822
Spill Number/Closed Date: 0108396 / 2002-03-06
Site ID: 69570
Spill Date: 2001-11-19

BASEMENT — 369 MAMARONECK AVE — ESE 1/4 - 1/2 (0.379 mi.) — BA356 — 823
Spill Number/Closed Date: 9908980 / 2005-02-26

Site ID: 195010
Spill Date: 1999-10-23

MGH CO — 45 MITCHELL PLACE — NE 1/4 - 1/2 (0.381 mi.) — AY357 — 824
Spill Number/Closed Date: 9904849 / 2000-01-11
Spill Number/Closed Date: 9510979 / 1995-12-12
Site ID: 78194
Site ID: 143584
Spill Date: 1999-07-23
Spill Date: 1995-11-29

APT BUILDING — 45 MITCHELL PLACE — NE 1/4 - 1/2 (0.381 mi.) — AY358 — 826
Spill Number/Closed Date: 1212688 / 2020-02-05
Site ID: 475842
Spill Date: 2012-11-27

WRCO MCOT — ***2 OLD MAMARONECK ROA*** — ***ESE 1/4 - 1/2 (0.395 mi.)*** — ***BA361*** — ***836***
Spill Number/Closed Date: 9414514 / 1996-08-28
Site ID: 279763
Spill Date: 1995-01-02

WHITE PLAINS PROJECT — ***179 WESTMORELAND AVE*** — ***W 1/4 - 1/2 (0.395 mi.)*** — ***362*** — ***838***
Spill Number/Closed Date: 8800315 / 1988-11-25
Site ID: 317805
Spill Date: 1988-04-08

MCTERNANA RESIDENCE — 91 DAVIS AVE — SSE 1/4 - 1/2 (0.407 mi.) — BB363 — 841
Spill Number/Closed Date: 0501407 / 2005-12-18
Site ID: 345543
Spill Date: 2005-05-04

SPILL NUMBER 0211763 — 13 HOWARD AVE — SSW 1/4 - 1/2 (0.410 mi.) — 364 — 842
Spill Number/Closed Date: 0211763 / 2003-03-03
Site ID: 89203
Spill Date: 2003-02-27

TORELLI — 21 DEKALB AVE — E 1/4 - 1/2 (0.411 mi.) — BC365 — 843
Spill Number/Closed Date: 0206319 / 2005-02-02
Site ID: 253456
Spill Date: 2002-09-18

TIFFANY TOWERS — 56 DOYER AVE — SE 1/4 - 1/2 (0.412 mi.) — 366 — 844
Spill Number/Closed Date: 0208738 / 2003-02-21
Site ID: 272332
Spill Date: 2002-11-22

GLEASON RESIDENCE — 168 WEST POST RD — SW 1/4 - 1/2 (0.427 mi.) — BD368 — 847
Spill Number/Closed Date: 9813367 / 1999-04-14
Spill Number/Closed Date: 0808631 / 2009-02-09
Site ID: 133051
Site ID: 406032
Spill Date: 1999-02-01
Spill Date: 2008-10-30

MILLER CENTER FOR NU — 37 DEKALD AVE — E 1/4 - 1/2 (0.430 mi.) — 369 — 850
Spill Number/Closed Date: 8802117 / 1988-08-30
Site ID: 211184
Spill Date: 1988-06-03

SPILL NUMBER 0206302 — 50 LINDA AVE — SE 1/4 - 1/2 (0.432 mi.) — BF371 — 856
Spill Number/Closed Date: 0206302 / 2002-11-25
Site ID: 155727

Spill Date: 2002-09-18

SUNOCO GAS S/S,WHITE	***405 MAMARONECK AVENU***	***ESE 1/4 - 1/2 (0.433 mi.)***	***372***	***857***
Spill Number/Closed Date: 9004404 / 1990-09-18				
Spill Number/Closed Date: 9710178 / 2005-02-12				
Spill Number/Closed Date: 8709700 / 1995-02-14				
Site ID: 227021				
Site ID: 181736				
Site ID: 67631				
Spill Date: 1990-07-20				
Spill Date: 1997-12-04				
Spill Date: 1988-02-17				
DUBBS RESIDENCE	52 LINDA AVE	SE 1/4 - 1/2 (0.434 mi.)	BF373	863
Spill Number/Closed Date: 0402572 / 2004-08-09				
Site ID: 232412				
Spill Date: 2004-06-09				
WHITE PLAINS DEPT OF	***255 MAIN STREET***	***NNE 1/4 - 1/2 (0.435 mi.)***	***374***	***865***
Spill Number/Closed Date: 8707220 / 1988-03-14				
Site ID: 294455				
Spill Date: 1987-11-21				
MEIER	83 LONGVIEW AVE	SSE 1/4 - 1/2 (0.437 mi.)	375	868
Spill Number/Closed Date: 9903776 / 1999-09-29				
Site ID: 165399				
Spill Date: 1999-07-01				
SPILL NUMBER 9909620	2 GRANDVIEW AVE	SE 1/4 - 1/2 (0.438 mi.)	BF376	870
Spill Number/Closed Date: 9909620 / 2000-12-21				
Site ID: 280509				
Spill Date: 1999-11-08				
RESIDENCE	15 SMITH AVE	SSE 1/4 - 1/2 (0.439 mi.)	BB378	873
Spill Number/Closed Date: 0506586 / 2005-12-18				
Site ID: 351821				
Spill Date: 2005-08-29				
HAMILTON MAIN PARKIN	HAMILTON AVE & MAIN	NNE 1/4 - 1/2 (0.445 mi.)	379	874
Spill Number/Closed Date: 8707260 / 1989-11-29				
Site ID: 286661				
Spill Date: 1987-11-23				
FORMER WPPD	279 HAMITON AVE	N 1/4 - 1/2 (0.445 mi.)	BE380	876
Spill Number/Closed Date: 0405806 / 2007-07-06				
Site ID: 306552				
Spill Date: 1987-01-01				
APARTMENT BUILDING	***10 OLD MAMARONECK RO***	***SE 1/4 - 1/2 (0.448 mi.)***	***381***	***877***
Spill Number/Closed Date: 0206840 / 2002-12-13				
Spill Number/Closed Date: 9810881 / 2004-04-30				
Spill Number/Closed Date: 0910093 / 2010-04-29				
Site ID: 263963				
Site ID: 263964				
Site ID: 422835				
Spill Date: 2002-10-02				
Spill Date: 1998-11-30				
Spill Date: 2009-12-11				
BASS HOME	98 DAVIS AVE	SSE 1/4 - 1/2 (0.453 mi.)	BB384	886
Spill Number/Closed Date: 0611529 / 2007-06-25				

Site ID: 376177
Spill Date: 2007-01-17

COMMERCIAL BLDG	2 SOUNDVIEW AVE	SW 1/4 - 1/2 (0.464 mi.)	BD391	908
Spill Number/Closed Date: 0801427 / 2008-11-12				
Spill Number/Closed Date: 2002195 / Not Reported				
Site ID: 397346				
Site ID: 606872				
Spill Date: 2008-05-06				
Spill Date: 2020-06-24				
RESIDENCE	27 SMITH AVE	SSE 1/4 - 1/2 (0.471 mi.)	BH392	911
Spill Number/Closed Date: 0906385 / 2010-12-21				
Site ID: 418719				
Spill Date: 2009-09-02				
BART GOLDBERG APT. B	277 MARTINE AVE	NE 1/4 - 1/2 (0.479 mi.)	BI394	914
Spill Number/Closed Date: 9008032 / 1990-11-08				
Site ID: 255929				
Spill Date: 1990-10-22				
BUSINESS	2-4 WASHINGTON AVE	WNW 1/4 - 1/2 (0.481 mi.)	395	915
Spill Number/Closed Date: 0300993 / 2003-06-13				
Site ID: 86277				
Spill Date: 2003-04-28				
BADDERS RESIDENCE	***14 SOUNDVIEW AVE***	***SSW 1/4 - 1/2 (0.487 mi.)***	***396***	***916***
Spill Number/Closed Date: 8800187 / 1989-01-09				
Site ID: 313762				
Spill Date: 1988-04-06				
HIRSCHON HOME	14 GRANDVIEW AVE	SSE 1/4 - 1/2 (0.487 mi.)	397	919
Spill Number/Closed Date: 0502229 / 2005-08-28				
Site ID: 346546				
Spill Date: 2005-05-25				
RESIDENCE	34 SMITH AVE	SSE 1/4 - 1/2 (0.493 mi.)	BH398	920
Spill Number/Closed Date: 0507545 / 2005-12-03				
Site ID: 353014				
Spill Date: 2005-09-23				
O'NEILL RESIDENCE	3 BRYANT AVE	S 1/4 - 1/2 (0.496 mi.)	399	921
Spill Number/Closed Date: 1004584 / 2011-01-06				
Site ID: 437863				
Spill Date: 2010-07-23				
SPILL NUMBER 0200263	97 LONGVIEW AVE	SSE 1/4 - 1/2 (0.500 mi.)	BJ402	926
Spill Number/Closed Date: 0200263 / 2002-05-13				
Site ID: 139618				
Spill Date: 2002-04-08				
RESIDENTS	97 LONVIEW AVE	SSE 1/4 - 1/2 (0.500 mi.)	BJ403	927
Spill Number/Closed Date: 0200712 / 2002-04-22				
Site ID: 256918				
Spill Date: 2002-04-18				

Lower Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA	EAST NEW YORK POST R	SW 0 - 1/8 (0.014 mi.)	C38	116
Spill Number/Closed Date: 9506062 / 2005-01-02				
Site ID: 240948				

Spill Date: 1995-08-15

SPILL NUMBER 0103645 — 12 EAST POST RD — SW 0 - 1/8 (0.033 mi.) — C46 — 127
Spill Number/Closed Date: 0103645 / 2003-12-09
Site ID: 129951
Spill Date: 2001-07-05

SPILL NUMBER 8600048 — 11 EAST POST ROAD — SW 0 - 1/8 (0.036 mi.) — C51 — 143
Spill Number/Closed Date: 8600048 / 1987-02-24
Site ID: 200602
Spill Date: 1986-04-02

GETTY SERVICE STATIO — 11 EAST POST ROAD — SW 0 - 1/8 (0.036 mi.) — C55 — 150
Spill Number/Closed Date: 0407127 / 2004-09-27
Spill Number/Closed Date: 9710611 / 1998-05-08
Site ID: 261414
Site ID: 261415
Spill Date: 2004-09-27
Spill Date: 1997-12-17

SPILL NUMBER 0013009 — 1 EAST POST RD — SW 0 - 1/8 (0.056 mi.) — G71 — 170
Spill Number/Closed Date: 0013009 / 2001-03-12
Site ID: 156648
Spill Date: 2001-03-12

BISCARDI CLEANERS — ***201 SO. LEXINGTON AV*** — ***SW 0 - 1/8 (0.063 mi.)*** — ***G74*** — ***173***
Spill Number/Closed Date: 0100630 / 2006-05-01
Site ID: 322267
Spill Date: 2001-04-17

HYDRAULIC FLUID TO S — ***134 SOUTH LEXINGTON*** — ***WNW 0 - 1/8 (0.067 mi.)*** — ***H77*** — ***181***
Spill Number/Closed Date: 0008525 / 2001-03-12
Site ID: 218519
Spill Date: 2000-10-20

SLADER NEIGHBORHOOD — 2 FISHER CT — NNE 0 - 1/8 (0.085 mi.) — J95 — 215
Spill Number/Closed Date: 9810451 / 2003-12-05
Site ID: 214463
Spill Date: 1998-11-18

AVIS — 20 WEST POST RD — SW 0 - 1/8 (0.087 mi.) — G96 — 216
Spill Number/Closed Date: 8706892 / 1988-07-27
Site ID: 159466
Spill Date: 1987-11-13

WHITE PLAINS HOUSING — ***33 FISHER AVE*** — ***WNW 0 - 1/8 (0.111 mi.)*** — ***O130*** — ***287***
Spill Number/Closed Date: 1007861 / 2011-07-05
Site ID: 441310
Spill Date: 2010-10-25

CHURCH — ***65 FISHER AVE*** — ***WNW 0 - 1/8 (0.123 mi.)*** — ***O143*** — ***321***
Spill Number/Closed Date: 0509976 / 2006-12-20
Site ID: 355853
Spill Date: 2005-11-21

MT CARMEL — 92 SOUTH LEXINGTON A — NW 1/8 - 1/4 (0.162 mi.) — X189 — 420
Spill Number/Closed Date: 8704169 / 1987-10-21
Spill Number/Closed Date: 8703713 / 1987-10-21
Spill Number/Closed Date: 1100855 / 2012-01-23
Site ID: 219315
Site ID: 239739
Site ID: 448286

Spill Date: 1987-08-20
Spill Date: 1987-08-05
Spill Date: 2011-04-25

CASTILLO — 125-127 FISHER AVE — W 1/8 - 1/4 (0.204 mi.) — Y215 — 478
Spill Number/Closed Date: 8709424 / 1988-03-11
Site ID: 210582
Spill Date: 1988-02-05

77 SOUTH LEXINGTON A — 77 SOUTH LEXINGTON A — NNW 1/8 - 1/4 (0.215 mi.) — 217 — 480
Spill Number/Closed Date: 0304231 / 2003-07-22
Site ID: 106697
Spill Date: 2003-07-22

PEPE MOTORS INC — 50 BANK ST — WNW 1/8 - 1/4 (0.237 mi.) — AI261 — 579
Spill Number/Closed Date: 9607100 / 1999-04-29
Site ID: 284462
Spill Date: 1996-09-04

IRVINGTON — IRVINGTON — WNW 1/8 - 1/4 (0.249 mi.) — AE295 — 671
Spill Number/Closed Date: 8708811 / 1988-03-03
Site ID: 309074
Spill Date: 1988-01-15

WHITE PLAINS HONDA — 31 WESTMPORELAND AVE — WNW 1/4 - 1/2 (0.261 mi.) — AI301 — 679
Spill Number/Closed Date: 9514655 / 1996-02-15
Site ID: 224484
Spill Date: 1996-02-15

MUNICIPAL GARAGE — 111 — WNW 1/4 - 1/2 (0.266 mi.) — AO307 — 696
Spill Number/Closed Date: 8808829 / 1991-08-07
Site ID: 129523
Spill Date: 1989-02-10

CIVIC CENTER MOTORS — 31 WESTMORELAND AVE — WNW 1/4 - 1/2 (0.270 mi.) — AO308 — 697
Spill Number/Closed Date: 0108090 / 2001-11-08
Spill Number/Closed Date: 0206674 / 2003-02-26
Spill Number/Closed Date: 0010522 / 2001-07-10
Site ID: 110892
Site ID: 110893
Site ID: 68432
Spill Date: 2001-11-08
Spill Date: 2002-09-25
Spill Date: 2000-12-19

BENEROFE ASSOCIATION — 39 WESTMORELAND AVE — WNW 1/4 - 1/2 (0.274 mi.) — AO311 — 704
Spill Number/Closed Date: 0807224 / 2009-01-07
Spill Number/Closed Date: 9411173 / 1995-09-22
Site ID: 404560
Site ID: 221603
Spill Date: 2008-09-26
Spill Date: 1994-11-21

A & S STORE — GALLERIA PLAZA — N 1/4 - 1/2 (0.319 mi.) — AU328 — 761
Spill Number/Closed Date: 8803673 / 1988-08-09
Site ID: 187318
Spill Date: 1988-07-27

A&S STORE — GALLERIA PLAZA — N 1/4 - 1/2 (0.319 mi.) — AU329 — 762
Spill Number/Closed Date: 8805571 / 1989-03-07
Site ID: 187319

Spill Date: 1988-09-29

J C PENNEY CO INC ***100 MAIN ST*** ***NNW 1/4 - 1/2 (0.327 mi.)*** ***331*** ***765***
Spill Number/Closed Date: 9102767 / 1991-06-13
Site ID: 137993
Spill Date: 1991-06-10

NY TEL ***111 EAST MAIN STREET*** ***N 1/4 - 1/2 (0.329 mi.)*** ***AU332*** ***775***
Spill Number/Closed Date: 9314933 / 1995-03-01
Spill Number/Closed Date: 9609101 / 1999-11-26
Site ID: 145113
Site ID: 239422
Spill Date: 1994-03-21
Spill Date: 1996-10-21

CENTROPLEX ASSOC. ***123 MAIN STREET*** ***N 1/4 - 1/2 (0.329 mi.)*** ***AU333*** ***778***
Spill Number/Closed Date: 8906607 / 1991-06-12
Spill Number/Closed Date: 9910168 / 1999-11-22
Spill Number/Closed Date: 8907663 / 1991-06-12
Site ID: 160999
Site ID: 161000
Site ID: 74955
Spill Date: 1989-10-04
Spill Date: 1999-11-19
Spill Date: 1989-11-01

VINTAGE RESTAURANT 171-173 MAIN STREET N 1/4 - 1/2 (0.340 mi.) AW339 790
Spill Number/Closed Date: 0602861 / 2008-09-26
Site ID: 365437
Spill Date: 2006-06-14

RESIDENCE 185- 187 MAIN ST NNE 1/4 - 1/2 (0.347 mi.) AW343 799
Spill Number/Closed Date: 9708138 / 1997-11-10
Site ID: 81930
Spill Date: 1997-10-09

GATEWAY BLDG ***1 NORTH LEXINGTON AV*** ***NNW 1/4 - 1/2 (0.351 mi.)*** ***344*** ***800***
Spill Number/Closed Date: 9000726 / 1991-12-06
Spill Number/Closed Date: 9108659 / 1991-11-13
Spill Number/Closed Date: 8908197 / 1990-01-29
Site ID: 131721
Site ID: 255792
Site ID: 276348
Spill Date: 1990-04-20
Spill Date: 1991-11-13
Spill Date: 1989-11-16

240 EAST POST RD 240 EAST POST RD NE 1/4 - 1/2 (0.389 mi.) 360 835
Spill Number/Closed Date: 9903233 / 1999-12-15
Site ID: 135983
Spill Date: 1999-06-21

POLE #W6 ***18 DEKALB AVE*** ***ENE 1/4 - 1/2 (0.417 mi.)*** ***BC367*** ***845***
Spill Number/Closed Date: 0406991 / 2004-10-04
Site ID: 195806
Spill Date: 2004-09-23

WHITE PLAINS POLICE ***279 HAMILTON AVENUE*** ***N 1/4 - 1/2 (0.439 mi.)*** ***BE377*** ***871***
Spill Number/Closed Date: 8606771 / 1989-11-29
Site ID: 92789
Spill Date: 1987-02-04

COMMERICAL BUILDING 10 NEW KING STREET NNW 1/4 - 1/2 (0.452 mi.) BG382 881

Spill Number/Closed Date: 1006070 / 2010-10-28
Site ID: 439407
Spill Date: 2010-09-01

EXXON, WHITE PLAINS ***274 HAMILTON AVE*** ***N 1/4 - 1/2 (0.452 mi.)*** ***BE383*** ***883***
Spill Number/Closed Date: 8707486 / 1987-12-18
Site ID: 190041
Spill Date: 1987-12-01

OFFICE BLDG 4 NEW KING ST NNW 1/4 - 1/2 (0.453 mi.) BG385 887
Spill Number/Closed Date: 9809692 / 2003-12-05
Site ID: 170684
Spill Date: 1998-11-02

COMMERCIAL 3 NEW KING STREET NNW 1/4 - 1/2 (0.460 mi.) BG389 905
Spill Number/Closed Date: 0806330 / 2010-03-30
Spill Number/Closed Date: 1600651 / 2017-04-04
Site ID: 403607
Site ID: 525932
Spill Date: 2008-09-05
Spill Date: 2016-04-19

SPILL NUMBER 0000953 1 NEW KING STREET NNW 1/4 - 1/2 (0.461 mi.) BG390 907
Spill Number/Closed Date: 0000953 / 2001-02-07
Site ID: 272947
Spill Date: 2000-04-24

CROWN PLAZA HOTEL 66 HALE AVE ENE 1/4 - 1/2 (0.474 mi.) 393 912
Spill Number/Closed Date: 1105926 / 2020-04-30
Site ID: 453595
Spill Date: 2011-08-24

CEMMEL HOUSE BUILDIN ***300 MARTINE AVE*** ***NE 1/4 - 1/2 (0.497 mi.)*** ***BI400*** ***922***
Spill Number/Closed Date: 0206553 / 2002-12-13
Site ID: 293177
Spill Date: 2002-09-24

EDGAR 1 BARKER AVE N 1/4 - 1/2 (0.497 mi.) 401 925
Spill Number/Closed Date: 9807932 / 1999-11-19
Site ID: 330854
Spill Date: 1998-09-29

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, has revealed that there are 36 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA	***41 EAST POST ROAD,***	***S 0 - 1/8 (0.010 mi.)***	***A23***	***46***

Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Status: 3. Closed - Removed

Status: 4. Closed - in place
Id/Status:: 3-177148
Site Status: Active

71 EAST POST ROAD | 71 EAST POST ROAD | ENE 0 - 1/8 (0.019 mi.) | D44 | 126
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-048569
Site Status: Unregulated: <1101 gal. PBS

WINBROOK HOUSING DEV | 223 DR. MARTIN LUTHE | NE 0 - 1/8 (0.044 mi.) | E61 | 158
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-493597
Site Status: Active

8 LONGVIEW DEVELOPME | 8 LONGVIEW AVENUE | ESE 0 - 1/8 (0.078 mi.) | I81 | 190
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-104469
Site Status: Unregulated

WHITE PLAINS HOSPITA | 170 MAPLE AVENUE | S 0 - 1/8 (0.091 mi.) | K97 | 218
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 1. In-Service
Id/Status:: 3-175102
Site Status: Active

RRC PROPERTIES LLC | 35 WEST POST ROAD | SW 0 - 1/8 (0.118 mi.) | N135 | 305
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Status: 3. Closed - Removed
Id/Status:: 3-800369
Site Status: Unregulated

BERGMAN PROPERTY | 1820 CHESTNUT HILL | W 1/8 - 1/4 (0.126 mi.) | P150 | 334
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-800980
Site Status: Unregulated: <1101 gal. PBS

170 GRAND STREET ASS | 170 GRAND STREET | NNE 1/8 - 1/4 (0.133 mi.) | S157 | 346
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-800392
Site Status: Active

177 GRAND STREET ASS | 177 GRAND STREET | NNE 1/8 - 1/4 (0.138 mi.) | S162 | 360
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-049816
Site Status: Active

150 GRAND STREET OFF | 150 GRAND STREET | NNE 1/8 - 1/4 (0.142 mi.) | S165 | 364
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Status: 0. Administratively closed
Id/Status:: 3-800119
Id/Status:: 3-176885
Site Status: Unregulated

Site Status: Administratively Closed

SHOLZ BUICK, INC. 55 WEST POST ROAD SW 1/8 - 1/4 (0.154 mi.) V179 391
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-800357
Site Status: Unregulated

BSA ASSOCIATES, LLC 82 BANK STREET W 1/8 - 1/4 (0.162 mi.) Y191 426
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-048526
Site Status: Active

WESTHAB COACHMAN FAM 123 EAST POST ROAD NE 1/8 - 1/4 (0.169 mi.) U194 429
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-801262
Site Status: Unregulated

GREENRIDGE MEDICAL P 12 GREENRIDGE ROAD ESE 1/8 - 1/4 (0.182 mi.) Z201 441
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-801123
Site Status: Unregulated: <1101 gal. PBS

CAROD ASSOCIATES, L. 47 DAVIS AVENUE S 1/8 - 1/4 (0.200 mi.) W210 467
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-600886
Site Status: Active

THE INNS OF COURT PR 99 COURT ST. NNE 1/8 - 1/4 (0.222 mi.) AC223 495
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-601002
Site Status: Unregulated: <1101 gal. PBS

21 GREENRIDGE APARTM 21-25 GREENRIDGE AVE ESE 1/8 - 1/4 (0.225 mi.) Z226 500
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 1. In-Service
Id/Status:: 3-410608
Site Status: Unregulated

MAMARAHAN CO. 200 MAMARONECK AVENU ENE 1/8 - 1/4 (0.227 mi.) AF230 509
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-601008
Site Status: Unregulated: <1101 gal. PBS

200 MAMARONECK AVENU 202 MAMARONECK AVENU ENE 1/8 - 1/4 (0.228 mi.) AF232 512
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-601010
Site Status: Unregulated: <1101 gal. PBS

151 EAST POST ROAD C 151 EAST POST ROAD NE 1/8 - 1/4 (0.228 mi.) AG234 514
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-030910

Site Status: Active

JOHN DALE, INC. 176-180 MAMRONECK AV ENE 1/8 - 1/4 (0.230 mi.) AF237 518
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 0. Administratively closed
Id/Status:: 3-800038
Site Status: Unregulated: <1101 gal. PBS

GREENWICH RIVERVIEW 193-203 MAMARONECK A ENE 1/8 - 1/4 (0.235 mi.) AF249 543
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Status: 4. Closed - in place
Id/Status:: 3-411906
Site Status: Active

222 MAMARONECK AVENU 222 MAMARONECK AVENU E 1/8 - 1/4 (0.236 mi.) AJ258 574
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3a. Closed - Prior to 04/1991
Status: 1. In-Service
Id/Status:: 3-074608
Site Status: Active

WHITE PLAINS FAMILY 250 MAMARONECK AVENU E 1/8 - 1/4 (0.248 mi.) AL294 670
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-074071
Site Status: Unregulated

Lower Elevation	Address	Direction / Distance	Map ID	Page

POWER TEST/GETTY COS 26 EAST POST ROAD SW 0 - 1/8 (0.002 mi.) C7 14
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-137596
Site Status: Unregulated

EAST POST ROAD GASMA 34 EAST POST ROAD SSW 0 - 1/8 (0.002 mi.) A12 22
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Id/Status:: 3-601177
Site Status: Active

PHILLIP WERBEL 12 EAST POST ROAD SW 0 - 1/8 (0.033 mi.) C45 126
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-800795
Site Status: Unregulated: <1101 gal. PBS

STATION #58108 11 EAST POST ROAD SW 0 - 1/8 (0.036 mi.) C48 136
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-137820
Site Status: Active

PHILLIP WERBEL 1 EAST POST ROAD SW 0 - 1/8 (0.056 mi.) G70 169
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-800796
Site Status: Unregulated: <1101 gal. PBS

124 SOUTH LEXINGTON 124 SOUTH LEXINGTON WNW 0 - 1/8 (0.084 mi.) H91 207
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020

Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-497231
Site Status: Active

SLATER NEIGHBORHOOD | 2 FISHER COURT | NNE 0 - 1/8 (0.085 mi.) | J94 | 215
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-169560
Site Status: Unregulated: <1101 gal. PBS

STATION PLAZA | 76 SOUTH LEXINGTON A | NNW 1/8 - 1/4 (0.197 mi.) | X204 | 446
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 4. Closed - in place
Id/Status:: 3-139637
Site Status: Administratively Closed

WHITE PLAINS MART | 69 BANK STREET | WNW 1/8 - 1/4 (0.202 mi.) | Y214 | 475
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 1. In-Service
Status: 3. Closed - Removed
Id/Status:: 3-137286
Site Status: Active

CITY CARS METROPOLIT | 25 IRVING PLACE | WNW 1/8 - 1/4 (0.233 mi.) | AE240 | 521
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-802149
Site Status: Unregulated

SMITH'S DAIRY,INC. | 61 BANK STREET | WNW 1/8 - 1/4 (0.235 mi.) | AI241 | 521
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Id/Status:: 3-600496
Site Status: Unregulated

MERCEDES- BENZ OF WH | 50 BANK STREET | WNW 1/8 - 1/4 (0.237 mi.) | AI262 | 586
Database: WESTCHESTER CO. UST, Date of Government Version: 06/09/2020
Status: 3. Closed - Removed
Status: 4. Closed - in place
Status: 0. Administratively closed
Status: 1. In-Service
Id/Status:: 3-452122
Site Status: Active

NY CBS: These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

A review of the NY CBS list, as provided by EDR, and dated 06/22/2020 has revealed that there is 1 NY CBS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
YMCA OF CENTRAL & NO	***250 MAMARONECK AVENU***	***E 1/8 - 1/4 (0.248 mi.)***	***AL293***	***659***

Facility Status: Unregulated/Closed
CBS Number: 3-000313

EXECUTIVE SUMMARY

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, has revealed that there are 19 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FIRESTONE COMPLETE A	60 EAST POST ROAD	ENE 0 - 1/8 (0.003 mi.)	A16	30
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-801814 Status: 1. In-Service				
WHITE PLAINS HOSPITA	***41 EAST POST ROAD,***	***S 0 - 1/8 (0.010 mi.)***	***A23***	***46***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-177148 Status: 1. In-Service Status: 3. Closed - Removed				
RRC PROPERTIES LLC	***35 WEST POST ROAD***	***SW 0 - 1/8 (0.118 mi.)***	***N135***	***305***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-800369 Status: 3. Closed - Removed Status: 0. Administratively closed				
170 GRAND STREET ASS	***170 GRAND STREET***	***NNE 1/8 - 1/4 (0.133 mi.)***	***S157***	***346***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-800392 Status: 1. In-Service				
GREENRIDGE GARDENS O	2 GREENRIDGE AVENUE	E 1/8 - 1/4 (0.143 mi.)	T167	366
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-039144 Status: 1. In-Service				
GREENRIDGE ESTATES C	1-13 GREENRIDGE AVEN	E 1/8 - 1/4 (0.150 mi.)	T173	379
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-039128 Status: 1. In-Service				
SHOLZ BUICK, INC.	55 WEST POST ROAD	SW 1/8 - 1/4 (0.154 mi.)	V180	393
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-800357 Status: 3. Closed - Removed				
235 SOUTH LEXINGTON	235 SOUTH LEXINGTON	SSW 1/8 - 1/4 (0.159 mi.)	Q188	419
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-165468 Status: 1. In-Service				
PURDY MANOR APARTMEN	1 CHARLES STREET	SSW 1/8 - 1/4 (0.199 mi.)	AA206	449
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-800733 Status: 1. In-Service				
M AND T BANK	134 MAMARONECK AVENU	NE 1/8 - 1/4 (0.240 mi.)	AG274	619
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-601013 Status: 3. Closed - Removed				
Not reported	***85 COURT STREET***	***NNE 1/8 - 1/4 (0.240 mi.)***	***AC279***	***626***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-801525				

Status: 1. In-Service

SILVERMAN 237, LLC | 235 MAMARONECK AVENU | E 1/8 - 1/4 (0.246 mi.) | AJ288 | 647
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020
PBS Number: 3-074616
Status: 1. In-Service

Lower Elevation	Address	Direction / Distance	Map ID	Page
STATION #58108	11 EAST POST ROAD	SW 0 - 1/8 (0.036 mi.)	C56	152
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-137820 Status: 3. Closed - Removed				
WHITE PLAINS LINC-ME	***25 W POST RD***	***SW 0 - 1/8 (0.099 mi.)***	***N109***	***241***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-801370 Status: 1. In-Service				
STATION PLAZA	***76 SOUTH LEXINGTON A***	***NNW 1/8 - 1/4 (0.197 mi.)***	***X204***	***446***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-139637 Status: 0. Administratively closed Status: 3. Closed - Removed				
WHITE PLAINS MART	69 BANK STREET	WNW 1/8 - 1/4 (0.202 mi.)	Y212	469
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-137286 Status: 3. Closed - Removed				
BART'S AUTO SERVICE	7 IRVING PLACE	WNW 1/8 - 1/4 (0.225 mi.)	AE227	501
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-802186 Status: 1. In-Service				
CITY CARS METROPOLIT	25 IRVING PLACE	WNW 1/8 - 1/4 (0.233 mi.)	AE239	520
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-802149 Status: 3. Closed - Removed				
MERCEDES- BENZ OF WH	***50 BANK STREET***	***WNW 1/8 - 1/4 (0.237 mi.)***	***AI262***	***586***
Database: WESTCHESTER CO. AST, Date of Government Version: 06/09/2020 PBS Number: 3-452122 Status: 3. Closed - Removed Status: 1. In-Service				

NY CBS AST: Chemical Bulk Storage Database. Registration data collected as required by 6 NYCRR Part 596. It includes facilities storing hazardous substances listed in 6 NYCRR Part 597, in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size. Includes facilities registered (and closed) since effective date of CBS regulations (July 15, 1988) through the date request is processed.

A review of the NY CBS AST list, as provided by EDR, and dated 01/01/2002 has revealed that there is 1 NY CBS AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
YMCA OF CENTRAL & NO	250 MAMARONECK AVENU	E 1/8 - 1/4 (0.248 mi.)	AL291	656

Facility Status: 2
Facility Status: 1
CBS Number: 3-000313

State and tribal institutional control / engineering control registries

NY ENG CONTROLS: Environmental Remediation sites that have engineering controls in place.

A review of the NY ENG CONTROLS list, as provided by EDR, and dated 08/10/2020 has revealed that there are 2 NY ENG CONTROLS sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTOMOBILE CLUB OF N	***101 WESTMORELAND AVE***	***W 1/4 - 1/2 (0.313 mi.)***	***AS327***	***736***
Site Code: 374633				
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NNW 1/4 - 1/2 (0.459 mi.)***	***BG386***	***889***
Site Code: 58617				

Environmental Remediation sites that have institutional controls in place.

A review of the NY INST CONTROL list, as provided by EDR, and dated 08/10/2020 has revealed that there are 2 NY INST CONTROL sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTOMOBILE CLUB OF N	***101 WESTMORELAND AVE***	***W 1/4 - 1/2 (0.313 mi.)***	***AS327***	***736***
Site Code: 374633				
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NNW 1/4 - 1/2 (0.459 mi.)***	***BG386***	***889***
Site Code: 58617				

State and tribal voluntary cleanup sites

NY VCP: Voluntary Cleanup Agreements. The voluntary remedial program uses private monies to get contaminated sites remediated to levels allowing for the sites' productive use. The program covers virtually any kind of site and contamination.

A review of the NY VCP list, as provided by EDR, has revealed that there is 1 NY VCP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
CE - WHITE PLAINS MG	***9 NEW STREET AND 12***	***NNW 1/4 - 1/2 (0.459 mi.)***	***BG386***	***889***
Database: VCP, Date of Government Version: 08/10/2020				
Site Code: 58617				

EXECUTIVE SUMMARY

State and tribal Brownfields sites

NY BROWNFIELDS: Brownfields Site List

A review of the NY BROWNFIELDS list, as provided by EDR, and dated 08/10/2020 has revealed that there are 4 NY BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
POST ROAD CORRIDOR - Site Code: 544843 Site Code: 477447	***77 WEST POST ROAD***	***SW 1/8 - 1/4 (0.199 mi.)***	***V207***	***450***
221 MAIN STREET Site Code: 58997	***221 MAIN ST***	***NNE 1/4 - 1/2 (0.382 mi.)***	***AZ359***	***828***

Lower Elevation	Address	Direction / Distance	Map ID	Page
YOUNG COAL & LUMBER Site Code: 481411	***55 BANK STREET***	***NW 1/4 - 1/2 (0.263 mi.)***	***AI303***	***686***
HAMILTON GREEN Site Code: 570663	***200 HAMILTON AVENUE***	***N 1/4 - 1/2 (0.432 mi.)***	***BE370***	***851***

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 08/10/2020 has revealed that there are 52 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MANHOLE 3471 Spill Number/Closed Date: 9812506 / 1999-01-10 Site ID: 125914 Spill Date: 1999-01-10	44 POST RD	0 - 1/8 (0.000 mi.)	A3	10
STS TIRE SERVICE Spill Number/Closed Date: 0804645 / 2008-09-26 Site ID: 401590 Spill Date: 2008-07-23	60 EAST POST ROAD	ENE 0 - 1/8 (0.003 mi.)	A15	29
WHITE PLAINS HOSPITA Spill Number/Closed Date: 0900120 / 2017-04-04 Site ID: 412037 Spill Date: 2009-04-03	41 EAST POST RD	S 0 - 1/8 (0.010 mi.)	A24	54
WHITE PLAINS HOSPITA Spill Number/Closed Date: 0613444 / 2007-04-05 Site ID: 378477	41 EAST POST ROAD	S 0 - 1/8 (0.010 mi.)	A25	55

Spill Date: 2007-03-14

WHITE PLAINS HOSPITA	***41 E POST ROAD***	***S 0 - 1/8 (0.010 mi.)***	***A27***	***62***
Spill Number/Closed Date: 2003833 / Not Reported				
Site ID: 609568				
Spill Date: 2020-08-06				
WHITE PLAINS HOSPITA	41 EAST POST RD	S 0 - 1/8 (0.010 mi.)	A30	79
Spill Number/Closed Date: 8800316 / 1988-05-03				
Site ID: 276877				
Spill Date: 1988-04-11				
WHITE PLAINS HOSPITA	***41 POST RD***	***S 0 - 1/8 (0.010 mi.)***	***A32***	***81***
Spill Number/Closed Date: 0803913 / 2008-07-07				
Spill Number/Closed Date: 0504642 / 2006-05-23				
Spill Number/Closed Date: 9910974 / 2005-01-02				
Spill Number/Closed Date: 1105346 / 2017-04-04				
Site ID: 400727				
Site ID: 349576				
Site ID: 149038				
Site ID: 452999				
Spill Date: 2008-07-03				
Spill Date: 2005-07-18				
Spill Date: 1999-12-15				
Spill Date: 2011-08-10				
STAR DINER ROOFTOP	66 1/2 EAST POST ROA	ENE 0 - 1/8 (0.015 mi.)	D42	123
Spill Number/Closed Date: 8808788 / 1989-02-10				
Site ID: 118842				
Spill Date: 1989-02-09				
WHITE PLAINS HOTEL	MAPLE AVE	SSW 0 - 1/8 (0.036 mi.)	C58	155
Spill Number/Closed Date: 9003827 / 1990-07-10				
Site ID: 233667				
Spill Date: 1990-07-06				
WHITE PLAINS BEVERAG	234 MARTIN LUTHER KI	NE 0 - 1/8 (0.048 mi.)	D63	161
Spill Number/Closed Date: 1304060 / 2013-11-27				
Site ID: 484569				
Spill Date: 2013-07-15				
POST RD	DAVIS AVE	SSE 0 - 1/8 (0.048 mi.)	F64	163
Spill Number/Closed Date: 9908220 / 1999-11-19				
Site ID: 165382				
Spill Date: 1999-10-06				
WHITE PLAINS HOSPITA	***DAVIS AVE & EAST POS***	***SSE 0 - 1/8 (0.048 mi.)***	***F67***	***166***
Spill Number/Closed Date: 9401229 / 1994-05-05				
Site ID: 210995				
Spill Date: 1994-04-26				
LITTLE MOUNT ZION HO	230 DR. MARTIN LUTHE	NE 0 - 1/8 (0.049 mi.)	E68	168
Spill Number/Closed Date: 1006496 / 2010-11-15				
Site ID: 439851				
Spill Date: 2010-09-15				
EL PAISA AUTO BODY	177 ORAWAMPUM ROAD	WSW 0 - 1/8 (0.068 mi.)	78	183
Spill Number/Closed Date: 9800944 / 1998-06-24				
Site ID: 137985				
Spill Date: 1998-04-02				
WHITE PLAINS HOSPITA	***8 LONGVIEW AVE***	***ESE 0 - 1/8 (0.078 mi.)***	***I80***	***186***

Spill Number/Closed Date: 0712395 / 2008-07-16
Site ID: 394002
Spill Date: 2008-02-25

ROADWAY — 32 WEST POST ROAD — SW 0 - 1/8 (0.111 mi.) — N132 — 297
Spill Number/Closed Date: 8902440 / 1989-06-12
Spill Number/Closed Date: 9504578 / 2006-02-07
Site ID: 268640
Site ID: 119065
Spill Date: 1989-06-08
Spill Date: 1995-07-17

MOORE - AST — 8 CHESTNUT HILL AVE — W 0 - 1/8 (0.118 mi.) — P136 — 309
Spill Number/Closed Date: 1703345 / 2017-07-11
Site ID: 554518
Spill Date: 2017-07-06

PARKING LOT — SOUTH LEXINGTON AVE. — SSW 0 - 1/8 (0.122 mi.) — Q138 — 313
Spill Number/Closed Date: 9304026 / 1994-11-10
Site ID: 158125
Spill Date: 1993-06-21

MVA — MAPLE AVE SOUTH LEXI — SSW 0 - 1/8 (0.122 mi.) — Q139 — 314
Spill Number/Closed Date: 1101460 / 2011-05-09
Site ID: 448912
Spill Date: 2011-05-09

POLE#40 — LEXINGTON AVE& MAPLE — SSW 0 - 1/8 (0.122 mi.) — Q140 — 315
Spill Number/Closed Date: 0706257 / 2007-09-07
Site ID: 386740
Spill Date: 2007-09-04

MAGNOGTA'S PARKING L — S. LEXINGTON & MAPLE — SSW 0 - 1/8 (0.124 mi.) — Q149 — 333
Spill Number/Closed Date: 9002687 / 1990-08-01
Site ID: 201938
Spill Date: 1990-06-08

Lower Elevation	Address	Direction / Distance	Map ID	Page
CON ED MANHOLE 9169 Spill Number/Closed Date: 0311437 / 2004-01-09 Site ID: 298419 Spill Date: 2004-01-08	169 LEXINGTON AVE	W 0 - 1/8 (0.001 mi.)	B4	11
CLOSED GETTY GAS STA Spill Number/Closed Date: 9713110 / 2017-08-21 Site ID: 178917 Spill Date: 1998-02-24	26 EAST POST RD	SW 0 - 1/8 (0.002 mi.)	C6	12
WHITE PLAINS CITGO Spill Number/Closed Date: 9516188 / 1997-11-12 Site ID: 167943 Spill Date: 1996-03-18	34 EAST POST ROAD	SSW 0 - 1/8 (0.002 mi.)	A8	16
BP GAS STATION Spill Number/Closed Date: 1509193 / 2015-12-09 Site ID: 519791 Spill Date: 2015-12-09	34 EAST POST RD	SSW 0 - 1/8 (0.002 mi.)	A9	17
BP STATION- EAST POS Spill Number/Closed Date: 1608924 / Not Reported	34 EAST POST ROAD	SSW 0 - 1/8 (0.002 mi.)	A10	18

Site ID: 537673
Spill Date: 2014-09-01

FORMER NORTHVILLE GA Spill Number/Closed Date: 9406684 / 1999-06-30 Site ID: 171620 Spill Date: 1994-08-16	34 EAST POST ROAD	SSW 0 - 1/8 (0.002 mi.)	A11	21
FRONT OF ONE STOP DE Spill Number/Closed Date: 8900729 / 1989-04-24 Site ID: 148648 Spill Date: 1989-04-24	POST ROAD	SW 0 - 1/8 (0.005 mi.)	C17	33
COMMERCIAL UST Spill Number/Closed Date: 1101872 / Not Reported Spill Number/Closed Date: 1607837 / 2018-02-23 Site ID: 449350 Site ID: 535514 Spill Date: 2011-05-19 Spill Date: 2016-11-10	22-24 EAST POST RD	SW 0 - 1/8 (0.007 mi.)	C18	34
MANHOLE # 7278 Spill Number/Closed Date: 9101572 / 1991-06-10 Site ID: 194912 Spill Date: 1991-05-09	EAST NEW YORK POST R	SSW 0 - 1/8 (0.009 mi.)	C21	44
JOHN BOWEN GARAGE Spill Number/Closed Date: 9012850 / 1991-05-06 Site ID: 307443 Spill Date: 1991-03-15	176 S. LEXINGTON AVE	WSW 0 - 1/8 (0.010 mi.)	B22	45
MANHOLE 9169 Spill Number/Closed Date: 9906715 / 1999-09-06 Site ID: 254861 Spill Date: 1999-09-06	SO LEXINGTON AVE/DEN	WSW 0 - 1/8 (0.014 mi.)	B40	121
WHITE PLAINS HOSPITA Spill Number/Closed Date: 0206489 / 2003-10-29 Site ID: 78704 Spill Date: 2001-11-14	DAVIS AVE & EAST POS	SSW 0 - 1/8 (0.015 mi.)	C41	122
APARTMENT BLDG Spill Number/Closed Date: 1610459 / 2017-02-21 Site ID: 541288 Spill Date: 2017-02-20	159 SOUTH LEXINGTON	W 0 - 1/8 (0.018 mi.)	B43	125
GETTY PETROLEUM CORP Spill Number/Closed Date: 8603012 / 1986-08-26 Spill Number/Closed Date: 1705804 / 2018-07-20 Site ID: 168401 Site ID: 559105 Spill Date: 1986-08-05 Spill Date: 2017-09-13	***11 E POST RD***	***SW 0 - 1/8 (0.036 mi.)***	***C47***	***128***
GETTY # 58108 Spill Number/Closed Date: 0513284 / 2006-08-09 Site ID: 359748 Spill Date: 2006-02-17	11 EAST POST ROAD	SW 0 - 1/8 (0.036 mi.)	C49	138
GETTY 58108 Spill Number/Closed Date: 0512391 / 2006-01-31 Spill Number/Closed Date: 0711111 / 2008-01-21	11 EAST POST ROAD	SW 0 - 1/8 (0.036 mi.)	C50	139

Spill Number/Closed Date: 0603141 / 2006-11-03
Spill Number/Closed Date: 0713025 / 2008-09-26
Site ID: 358706
Site ID: 392529
Site ID: 365800
Site ID: 394715
Spill Date: 2006-01-25
Spill Date: 2008-01-21
Spill Date: 2006-06-21
Spill Date: 2008-03-10

GETTY 58108 — 11 EAST POST RD / WI — SW 0 - 1/8 (0.036 mi.) — C52 — 144
Spill Number/Closed Date: 9710575 / 2018-07-20
Site ID: 228215
Spill Date: 1997-12-12

GETTY #58108 — 11 EAST POST ROAD — SW 0 - 1/8 (0.036 mi.) — C54 — 149
Spill Number/Closed Date: 0512154 / 2006-08-09
Site ID: 358427
Spill Date: 2006-01-20

GETTY # 58108 — 11 EAST POST RD — SW 0 - 1/8 (0.036 mi.) — C57 — 153
Spill Number/Closed Date: 0807262 / 2008-09-29
Spill Number/Closed Date: 0902231 / 2009-10-07
Site ID: 404601
Site ID: 414266
Spill Date: 2008-09-29
Spill Date: 2009-05-26

UST REMOVAL — 135 SOUTH LEXINGTON — WNW 0 - 1/8 (0.063 mi.) — H73 — 171
Spill Number/Closed Date: 2001101 / 2020-06-26
Site ID: 605737
Spill Date: 2020-05-19

BISCARDI CLEANERS — 201 SO. LEXINGTON AV — SW 0 - 1/8 (0.063 mi.) — G74 — 173
Spill Number/Closed Date: 0013010 / 2001-03-12
Site ID: 254787
Spill Date: 2001-03-12

HYDRAULIC FLUID TO S — 134 SOUTH LEXINGTON — WNW 0 - 1/8 (0.067 mi.) — H77 — 181
Spill Number/Closed Date: 0008680 / 2005-03-06
Site ID: 123462
Spill Date: 2000-10-25

TRINITY METHODIST CH — 130 SOUTH LEXINGTON — WNW 0 - 1/8 (0.074 mi.) — H79 — 184
Spill Number/Closed Date: 0610953 / 2007-06-25
Site ID: 375495
Spill Date: 2006-12-29

BETHEL BAPTIST CHURC — 1 FISHER COURT — NNE 0 - 1/8 (0.079 mi.) — E82 — 191
Spill Number/Closed Date: 1011299 / 2011-04-18
Site ID: 445152
Spill Date: 2011-02-10

CON ED — 126 SOUTH LEXINGTON — WNW 0 - 1/8 (0.081 mi.) — H83 — 192
Spill Number/Closed Date: 1607231 / 2016-10-24
Site ID: 534865
Spill Date: 2016-10-24

COMMERCIAL — 126 SOUTH LEXINGTON — WNW 0 - 1/8 (0.081 mi.) — H84 — 193
Spill Number/Closed Date: 1600183 / 2016-04-08

Site ID: 525442
Spill Date: 2016-04-06

GAS STATION	124 SOUTH LEXINGTON	WNW 0 - 1/8 (0.084 mi.)	H93	211
Spill Number/Closed Date: 0509358 / 2006-03-03				
Spill Number/Closed Date: 0611782 / 2012-10-12				
Site ID: 355125				
Site ID: 376490				
Spill Date: 2005-11-04				
Spill Date: 2007-01-24				
LINCOLN MERCURY	25 WEST POST ROAD	SW 0 - 1/8 (0.099 mi.)	N108	240
Spill Number/Closed Date: 0600932 / 2006-07-30				
Site ID: 363048				
Spill Date: 2006-04-24				
WHITE PLAINS LINC-ME	***25 W POST RD***	***SW 0 - 1/8 (0.099 mi.)***	***N109***	***241***
Spill Number/Closed Date: 9408341 / 2017-08-15				
Site ID: 327886				
Spill Date: 1994-09-21				
WHITE PLAINS HOUSING	***33 FISHER AVE***	***WNW 0 - 1/8 (0.111 mi.)***	***O130***	***287***
Spill Number/Closed Date: 9912180 / 2000-05-30				
Spill Number/Closed Date: 9301205 / 1993-05-13				
Site ID: 242722				
Site ID: 186162				
Spill Date: 2000-01-21				
Spill Date: 1993-04-26				
CHURCH	***65 FISHER AVE***	***WNW 0 - 1/8 (0.123 mi.)***	***O143***	***321***
Spill Number/Closed Date: 0513604 / 2006-12-20				
Site ID: 360107				
Spill Date: 2006-02-24				

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/15/2020 has revealed that there are 69 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WESTCHESTER FIRESTON	***60 E POST RD***	***ENE 0 - 1/8 (0.003 mi.)***	***A14***	***24***
EPA ID:: NYR000052357				
CON EDISON SERVICE B	***E POST RD & WINCHEST***	***ENE 0 - 1/8 (0.007 mi.)***	***A19***	***36***
EPA ID:: NYP004479127				
CON EDISON MANHOLE:	***E POST RD & WINCHEST***	***ENE 0 - 1/8 (0.007 mi.)***	***A20***	***40***
EPA ID:: NYP004472841				
CON EDISON	MAPLE AVE & LONGVIEW	ESE 0 - 1/8 (0.082 mi.)	I86	196
EPA ID:: NYP004207084				
CON EDISON	***CROMWELL PL & E POST***	***NE 0 - 1/8 (0.094 mi.)***	***L99***	***220***

EPA ID:: NYP004210779				
CON EDISON EPA ID:: NYP004772372	CROMWELL PL & E POST	NE 0 - 1/8 (0.094 mi.)	L100	225
CON EDISON EPA ID:: NYP004761797	100 POST RD	NE 0 - 1/8 (0.102 mi.)	L110	251
CON EDISON EPA ID:: NYP004772455	***E NEW YORK POST RD &***	***NE 0 - 1/8 (0.102 mi.)***	***L124***	***276***
CON EDISON EPA ID:: NYP004772521	E POST RD & GRAND ST	NE 0 - 1/8 (0.102 mi.)	L128	283
ROYAL MOTORS INC EPA ID:: NYD006995617	***32 W POST RD***	***SW 0 - 1/8 (0.111 mi.)***	***N131***	***291***
SHOLTZ OLDSMOBILE BU EPA ID:: NYD061987947	***35-55 W POST RD***	***SW 0 - 1/8 (0.118 mi.)***	***N134***	***300***
NY OIL RECYCLING INC EPA ID:: NYR000209650	***9 CHESNUT HILL AVE***	***W 0 - 1/8 (0.119 mi.)***	***P137***	***310***
WESTCHESTER HOBBIES EPA ID:: NYR000050658	***104 E POST RD***	***NE 0 - 1/8 (0.123 mi.)***	***L142***	***317***
CON EDISON MANHOLE: EPA ID:: NYP004297370	***LEXINGTON AVE & MAPL***	***SSW 0 - 1/8 (0.124 mi.)***	***Q146***	***325***
CON EDISON EPA ID:: NYP004768131	***LEXINGTON AVE & MAPL***	***SSW 0 - 1/8 (0.124 mi.)***	***Q147***	***329***
MH3471 EPA ID:: NYP004034625	***F/O 44 POST ROAD***	***SW 1/8 - 1/4 (0.133 mi.)***	***N158***	***348***
177 GRAND STREET ASS EPA ID:: NYR000063727	***177 GRAND ST***	***NNE 1/8 - 1/4 (0.138 mi.)***	***S161***	***355***
CHESTER MAPLE PARKIN EPA ID:: NYD986984714	***9 CHESTER AVE***	***ENE 1/8 - 1/4 (0.145 mi.)***	***U168***	***367***
RECKSON ASSOCIATES EPA ID:: NYR000096263	***140 GRAND ST***	***NNE 1/8 - 1/4 (0.147 mi.)***	***R171***	***373***
SHOLZ BUICK-OLDSMOBI EPA ID:: NYD981875727	***55 W POST RD***	***SW 1/8 - 1/4 (0.154 mi.)***	***V181***	***395***
WESTCHESTER COUNTY - EPA ID:: NYD986951978	***112 E POST RD***	***NE 1/8 - 1/4 (0.155 mi.)***	***U183***	***403***
BELL ATLANTIC NY EPA ID:: NYP000937300	S LEXINGTON AVE & CH	SSW 1/8 - 1/4 (0.195 mi.)	AA203	443
ABCO REFRIGERATION S EPA ID:: NYR000105197	***80 W POST RD***	***SW 1/8 - 1/4 (0.216 mi.)***	***AB219***	***483***
CON EDISON EPA ID:: NYP004193967	***184 MAMARONECK AVE &***	***ENE 1/8 - 1/4 (0.225 mi.)***	***AF228***	***502***
CON ED V 5613 EPA ID:: NYP000930958	***200 MAMORONECK AVE***	***ENE 1/8 - 1/4 (0.227 mi.)***	***AF229***	***505***
CON EDISON SERVICE B EPA ID:: NYP004429403	***MAMAROENCK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ242***	***522***
CON EDISON VAULT: 53 EPA ID:: NYP004341160	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ243***	***526***
CON EDISON MANHOLE:	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ245***	***531***

EPA ID:: NYP004379244				
CON EDISON	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ246***	***534***
EPA ID:: NYP004193744				
CON EDISON MANHOLE:	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ247***	***538***
EPA ID:: NYP004429429				
CON EDISON	148 MAMARONECK AVE	NE 1/8 - 1/4 (0.235 mi.)	AG250	544
EPA ID:: NYP004799854				
CON EDISON	***148 MAMARONECK AVE F***	***NE 1/8 - 1/4 (0.235 mi.)***	***AG252***	***548***
EPA ID:: NYP004192761				
ANEFCO INC	***222 MAMARONECK AVE***	***E 1/8 - 1/4 (0.236 mi.)***	***AJ257***	***570***
EPA ID:: NYD075426924				
CON EDISON MANHOLE 3	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG265***	***595***
EPA ID:: NYP004225900				
CON EDISON	***E POST RD & MAMMARON***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG266***	***599***
EPA ID:: NYP004801361				
CON EDISON SB1820	MAMARONECK AVE & E P	NE 1/8 - 1/4 (0.239 mi.)	AG270	606
EPA ID:: NYP005242110				
CON EDISON MANHOLE 3	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG271***	***609***
EPA ID:: NYP004225892				
CON EDISON	***134 MAMARANECK AVE***	***NE 1/8 - 1/4 (0.240 mi.)***	***AG272***	***613***
EPA ID:: NYP004805065				
CON EDISON	134 MAMARONECK AVE	NE 1/8 - 1/4 (0.240 mi.)	AG277	623
EPA ID:: NYP004806469				
CON EDISON	***128 MAMARONECK AVE***	***NE 1/8 - 1/4 (0.241 mi.)***	***AG280***	***627***
EPA ID:: NYP004846877				
CON EDISON MANHOLE:	***149 MAMARONECK AVE F***	***NE 1/8 - 1/4 (0.241 mi.)***	***AG283***	***632***
EPA ID:: NYP004366654				
CON EDISON	***235 MAMARONECK AVE F***	***E 1/8 - 1/4 (0.246 mi.)***	***AJ286***	***641***
EPA ID:: NYP004207423				
CON EDISON	***237 MAMARONECK AVE S***	***E 1/8 - 1/4 (0.248 mi.)***	***AJ289***	***648***
EPA ID:: NYP004207829				
CON EDISON SERVICE B	***133 MAMARONECK AVE I***	***NE 1/8 - 1/4 (0.248 mi.)***	***AG290***	***652***
EPA ID:: NYP004368668				

Lower Elevation	Address	Direction / Distance	Map ID	Page
SWANK DRY CLEANERS	***168 S LEXINGTON AVE***	***W 0 - 1/8 (0.010 mi.)***	***B34***	***104***
EPA ID:: NYD986938553				
BRIGHT SIDE CLEANERS	***182 S LEXINGTON AVE***	***WSW 0 - 1/8 (0.013 mi.)***	***B36***	***110***
EPA ID:: NYD987013109				
CON EDISON MANHOLE:	***S LEXINGTON AVE & DE***	***WSW 0 - 1/8 (0.014 mi.)***	***B39***	***118***
EPA ID:: NYP004324869				
GETTY PETROLEUM CORP	***11 E POST RD***	***SW 0 - 1/8 (0.036 mi.)***	***C47***	***128***
EPA ID:: NYD981556152				
BISCARDI CLEANERS	***201 S LEXINGTON AVE***	***SW 0 - 1/8 (0.063 mi.)***	***G75***	***175***
EPA ID:: NYD013386511				
CON EDISON SERVICE B	***GROVE ST & FISCHER A***	***NNE 0 - 1/8 (0.083 mi.)***	***J88***	***199***

EPA ID:: NYP004428926				
CON EDISON EPA ID:: NYP004825978	***GROVE ST & FISCHER C***	***NNE 0 - 1/8 (0.083 mi.)***	***J89***	***203***
CON EDISON MANHOLE: EPA ID:: NYP004314233	***QUARROPAS ST & FISCH***	***NNW 0 - 1/8 (0.097 mi.)***	***M104***	***231***
CON EDISON SERVICE B EPA ID:: NYP004514436	***FISHER CT & QUARROPA***	***NNW 0 - 1/8 (0.097 mi.)***	***M106***	***236***
CON EDISON MANHOLE: EPA ID:: NYP004379814	***S LEXINGTON AVE & FI***	***NW 0 - 1/8 (0.102 mi.)***	***H113***	***256***
CON EDISON EPA ID:: NYP004764643	LEXINGTON AVE & QUAR	NW 0 - 1/8 (0.102 mi.)	H114	260
CON EDISON MANHOLE 1 EPA ID:: NYP004140307	***S LEXINGTON AVE & FI***	***NW 0 - 1/8 (0.102 mi.)***	***H118***	***265***
CON EDISON EPA ID:: NYP004749677	***S LEXINGTON AVE & QU***	***NW 0 - 1/8 (0.102 mi.)***	***H120***	***270***
CON EDISON EPA ID:: NYP004213476	***GROVE ST & QUARROPAS***	***NNE 1/8 - 1/4 (0.133 mi.)***	***R151***	***335***
CON EDISON EPA ID:: NYP004805560	QUARROPAS ST & MLK B	NNE 1/8 - 1/4 (0.133 mi.)	R152	338
CON EDISON EPA ID:: NYP004885055	111 MARTIN LUTHER KI	N 1/8 - 1/4 (0.152 mi.)	R176	382
WESTCHESTER COUNTY C EPA ID:: NYR000028902	***111 GROVE ST***	***N 1/8 - 1/4 (0.152 mi.)***	***R178***	***386***
CON EDISON GAS DRIP: EPA ID:: NYP004302253	107 FISHER AVE	WNW 1/8 - 1/4 (0.173 mi.)	Y197	435
US POSTAL SERVICE EPA ID:: NYD986992790	***100 FISHER AVE***	***WNW 1/8 - 1/4 (0.200 mi.)***	***Y208***	***457***
CON EDISON GAS MAIN: EPA ID:: NYP004278610	***100 FISHER AVE***	***WNW 1/8 - 1/4 (0.200 mi.)***	***Y209***	***462***
GETTY PETROLEUM CORP EPA ID:: NY0000861518	***69 BANK ST***	***WNW 1/8 - 1/4 (0.202 mi.)***	***Y213***	***470***
CON EDISON MANHOLE 9 EPA ID:: NYP004224192	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK253***	***553***
CON EDISON MANHOLE 9 EPA ID:: NYP004224101	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK254***	***558***
CON EDISON MANHOLE 9 EPA ID:: NYP004224465	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK255***	***562***
CON EDISON EPA ID:: NYP004398962	***MARTINE & GROVE ST***	***N 1/8 - 1/4 (0.237 mi.)***	***AK259***	***575***

FUSRAP: DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

A review of the FUSRAP list, as provided by EDR, and dated 08/08/2017 has revealed that there is 1

FUSRAP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NUCLEAR DEVELOPMENT Site Status: Eliminated from consideration under FUSRAP Site ID: NY.32	5 NEW STREET	NNW 1/4 - 1/2 (0.460 mi.)	BG388	905

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 06/08/2020 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BISCARDI CLEANERS Facility Id: 3-5517-00279	***201 SO. LEXINGTON AV***	***SW 0 - 1/8 (0.063 mi.)***	***G74***	***173***

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/01/2019 has revealed that there are 76 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WESTCHESTER FIRESTON EPA ID: NYR000052357	***60 E POST RD***	***ENE 0 - 1/8 (0.003 mi.)***	***A14***	***24***
CON EDISON SERVICE B EPA ID: NYP004479127	***E POST RD & WINCHEST***	***ENE 0 - 1/8 (0.007 mi.)***	***A19***	***36***
CON EDISON MANHOLE: EPA ID: NYP004472841	***E POST RD & WINCHEST***	***ENE 0 - 1/8 (0.007 mi.)***	***A20***	***40***
WHITE PLAINS HOSPITA EPA ID: NYR000129965	***41 POST RD***	***S 0 - 1/8 (0.010 mi.)***	***A32***	***81***
CONSOLIDATED EDISON EPA ID: NYP004227298	F/O 89 EAST POST RD	ENE 0 - 1/8 (0.081 mi.)	E85	194
CON EDISON EPA ID: NYP004210779	***CROMWELL PL & E POST***	***NE 0 - 1/8 (0.094 mi.)***	***L99***	***220***
CON EDISON EPA ID: NYP004772370	CROMWELL PL & E. NY	NE 0 - 1/8 (0.094 mi.)	L101	227
CONSOLIDATED EDISON EPA ID: NYP004230025	E NY POST RD & CROMW	NE 0 - 1/8 (0.094 mi.)	L102	229
CON ED EPA ID: NYP004772372	CROMWELL PL & E POST	NE 0 - 1/8 (0.094 mi.)	L103	230
CON EDISON EPA ID: NYP004761797	100 POST RD	NE 0 - 1/8 (0.102 mi.)	L111	253
CON ED EPA ID: NYP004772521	E POST RD & GRAND ST	NE 0 - 1/8 (0.102 mi.)	L125	279
CON ED EPA ID: NYP004772455	E NEW YORK POST RD &	NE 0 - 1/8 (0.102 mi.)	L127	282
CON EDISON	W POST RD & ORAWAUPU	SW 0 - 1/8 (0.107 mi.)	N129	285

EPA ID: NYP004504866				
ROYAL MOTORS INC	***32 W POST RD***	***SW 0 - 1/8 (0.111 mi.)***	***N131***	***291***
EPA ID: NYD006995617				
SHOLTZ OLDSMOBILE BU	***35-55 W POST RD***	***SW 0 - 1/8 (0.118 mi.)***	***N134***	***300***
EPA ID: NYD061987947				
CON EDISON MANHOLE:	***LEXINGTON AVE & MAPL***	***SSW 0 - 1/8 (0.124 mi.)***	***Q146***	***325***
EPA ID: NYP004297370				
CON ED	LEXINGTON AVE & MAPL	SSW 0 - 1/8 (0.124 mi.)	Q148	332
EPA ID: NYP004768131				
MH3471	***F/O 44 POST ROAD***	***SW 1/8 - 1/4 (0.133 mi.)***	***N158***	***348***
EPA ID: NYP004034625				
177 GRAND STREET ASS	***177 GRAND ST***	***NNE 1/8 - 1/4 (0.138 mi.)***	***S161***	***355***
EPA ID: NYR000063727				
CHESTER MAPLE PARKIN	9 CHESTER AVE	ENE 1/8 - 1/4 (0.145 mi.)	U169	371
EPA ID: NYD986984714				
CON EDISON - VAULT 4	161 GRAND ST	NNE 1/8 - 1/4 (0.145 mi.)	S170	372
EPA ID: NYP004983803				
RECKSON ASSOCIATES	***140 GRAND ST***	***NNE 1/8 - 1/4 (0.147 mi.)***	***R171***	***373***
EPA ID: NYR000096263				
SHOLZ BUICK-OLDSMOBI	***55 W POST RD***	***SW 1/8 - 1/4 (0.154 mi.)***	***V181***	***395***
EPA ID: NYD981875727				
WESTCHESTER COUNTY -	***112 E POST RD***	***NE 1/8 - 1/4 (0.155 mi.)***	***U183***	***403***
EPA ID: NYD986951978				
NYSDEC	GRAND & QUARRAPUS	NNE 1/8 - 1/4 (0.168 mi.)	S193	427
EPA ID: NYP003600954				
ABCO REFRIGERATION S	***80 W POST RD***	***SW 1/8 - 1/4 (0.216 mi.)***	***AB219***	***483***
EPA ID: NYR000105197				
CON EDISON	***184 MAMARONECK AVE &***	***ENE 1/8 - 1/4 (0.225 mi.)***	***AF228***	***502***
EPA ID: NYP004193967				
CON ED V 5613	***200 MAMORONECK AVE***	***ENE 1/8 - 1/4 (0.227 mi.)***	***AF229***	***505***
EPA ID: NYP000930958				
NYSDEC	***202 MAMARONECK AVENU***	***ENE 1/8 - 1/4 (0.228 mi.)***	***AF231***	***510***
EPA ID: NYP000857680				
CON EDISON SERVICE B	***MAMAROENCK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ242***	***522***
EPA ID: NYP004429403				
CON EDISON VAULT: 53	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ243***	***526***
EPA ID: NYP004341160				
CON EDISON MANHOLE:	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ245***	***531***
EPA ID: NYP004379244				
CON EDISON	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ246***	***534***
EPA ID: NYP004193744				
CON EDISON MANHOLE:	***MAMARONECK AVE & MAP***	***E 1/8 - 1/4 (0.235 mi.)***	***AJ247***	***538***
EPA ID: NYP004429429				
CON EDISON	***148 MAMARONECK AVE F***	***NE 1/8 - 1/4 (0.235 mi.)***	***AG252***	***548***
EPA ID: NYP004192761				
EPA ID: NYP004799854				
CON EDISON MANHOLE 3	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG265***	***595***

EPA ID: NYP004225900				
CON EDISON EPA ID: NYP004801361	E POST RD & MAMMARON	NE 1/8 - 1/4 (0.239 mi.)	AG268	603
CON EDISON EPA ID: NYP004688784	MAMARONECK AVE & E P	NE 1/8 - 1/4 (0.239 mi.)	AG269	605
CON EDISON MANHOLE 3 EPA ID: NYP004225892	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG271***	***609***
CON EDISON EPA ID: NYP004806469	***134 MAMARONECK AVE***	***NE 1/8 - 1/4 (0.240 mi.)***	***AG273***	***616***
CON EDISON EPA ID: NYP004805065	134 MAMARANECK AVE	NE 1/8 - 1/4 (0.240 mi.)	AG276	621
CON EDISON EPA ID: NYP004846877	128 MAMARONECK AVE	NE 1/8 - 1/4 (0.241 mi.)	AG282	631
CON EDISON MANHOLE: EPA ID: NYP004366654	***149 MAMARONECK AVE F***	***NE 1/8 - 1/4 (0.241 mi.)***	***AG283***	***632***
CON EDISON EPA ID: NYP004207423	***235 MAMARONECK AVE F***	***E 1/8 - 1/4 (0.246 mi.)***	***AJ286***	***641***
CONSOLIDATED EDISON EPA ID: NYP004211553	235-237 MAMARONECK A	E 1/8 - 1/4 (0.246 mi.)	AJ287	645
CON EDISON EPA ID: NYP004207829	***237 MAMARONECK AVE S***	***E 1/8 - 1/4 (0.248 mi.)***	***AJ289***	***648***
CON EDISON SERVICE B EPA ID: NYP004368668	***133 MAMARONECK AVE I***	***NE 1/8 - 1/4 (0.248 mi.)***	***AG290***	***652***

Lower Elevation	Address	Direction / Distance	Map ID	Page
SWANK DRY CLEANERS EPA ID: NYD986938553	***168 S LEXINGTON AVE***	***W 0 - 1/8 (0.010 mi.)***	***B34***	***104***
BRIGHT SIDE CLEANERS EPA ID: NYD987013109	***182 S LEXINGTON AVE***	***WSW 0 - 1/8 (0.013 mi.)***	***B36***	***110***
CON EDISON MANHOLE: EPA ID: NYP004324869	***S LEXINGTON AVE & DE***	***WSW 0 - 1/8 (0.014 mi.)***	***B39***	***118***
GETTY PETROLEUM CORP EPA ID: NYD981556152 EPA ID: NYP000860718	***11 E POST RD***	***SW 0 - 1/8 (0.036 mi.)***	***C47***	***128***
BISCARDI CLEANERS EPA ID: NYD013386511	***201 S LEXINGTON AVE***	***SW 0 - 1/8 (0.063 mi.)***	***G75***	***175***
CON EDISON SERVICE B EPA ID: NYP004428926	***GROVE ST & FISCHER A***	***NNE 0 - 1/8 (0.083 mi.)***	***J88***	***199***
CONSOLIDATED EDISON EPA ID: NYP004228116	GROVE & FISHER	NNE 0 - 1/8 (0.083 mi.)	J90	206
CON EDISON MANHOLE: EPA ID: NYP004314233	***QUARROPAS ST & FISCH***	***NNW 0 - 1/8 (0.097 mi.)***	***M104***	***231***
CON EDISON EPA ID: NYP004314833	QUARROPAS ST & FISHE	NNW 0 - 1/8 (0.097 mi.)	M105	234
CON EDISON EPA ID: NYP004514436	FISHER CT & QUARROPA	NNW 0 - 1/8 (0.097 mi.)	M107	238
WHITE PLAINS LINC-ME	***25 W POST RD***	***SW 0 - 1/8 (0.099 mi.)***	***N109***	***241***

EPA ID: NYD052088754				
CON EDISON MANHOLE: EPA ID: NYP004379814	***S LEXINGTON AVE & FI***	***NW 0 - 1/8 (0.102 mi.)***	***H113***	***256***
CON EDISON EPA ID: NYP000471120	QUARRAPUS ST & LEXIN	NW 0 - 1/8 (0.102 mi.)	H115	262
CON EDISON EPA ID: NYP004749677	S LEXINGTON AVE & QU	NW 0 - 1/8 (0.102 mi.)	H117	264
CON EDISON MANHOLE 1 EPA ID: NYP004140307	***S LEXINGTON AVE & FI***	***NW 0 - 1/8 (0.102 mi.)***	***H118***	***265***
CON EDISON EPA ID: NYP004711206	QUARROPAS ST & LEXIN	NW 0 - 1/8 (0.102 mi.)	H119	269
CON EDISON EPA ID: NYP004764643	LEXINGTON AVE & QUAR	NW 0 - 1/8 (0.102 mi.)	H121	272
CONSOLIDATED EDISON EPA ID: NYP004227207	GROVE & QUERROPAS	NNE 1/8 - 1/4 (0.133 mi.)	R154	342
CON EDISON EPA ID: NYP004805560	QUARROPAS ST & MLK B	NNE 1/8 - 1/4 (0.133 mi.)	R155	343
WESTCHESTER COUNTY C EPA ID: NYR000028902	***111 GROVE ST***	***N 1/8 - 1/4 (0.152 mi.)***	***R178***	***386***
CON EDISON EPA ID: NYP004508313	76-78 S LEXINGTON AV	NNW 1/8 - 1/4 (0.197 mi.)	X205	447
US POSTAL SERVICE EPA ID: NYD986992790	***100 FISHER AVE***	***WNW 1/8 - 1/4 (0.200 mi.)***	***Y208***	***457***
CON EDISON GAS MAIN: EPA ID: NYP004278610	***100 FISHER AVE***	***WNW 1/8 - 1/4 (0.200 mi.)***	***Y209***	***462***
GETTY PETROLEUM CORP EPA ID: NY0000861518	***69 BANK ST***	***WNW 1/8 - 1/4 (0.202 mi.)***	***Y213***	***470***
CON EDISON MANHOLE 9 EPA ID: NYP004224192	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK253***	***553***
CON EDISON MANHOLE 9 EPA ID: NYP004224101	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK254***	***558***
CON EDISON MANHOLE 9 EPA ID: NYP004224465	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK255***	***562***
CON EDISON EPA ID: NYP004398962	MARTINE & GROVE ST	N 1/8 - 1/4 (0.237 mi.)	AK260	578
PEPE MOTORS INC EPA ID: NYD056298037	***50 BANK ST***	***WNW 1/8 - 1/4 (0.237 mi.)***	***AI261***	***579***

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, and dated 12/31/2018 has revealed that there are 25 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA EPA Id: NYR000129965	41 POST RD	S 0 - 1/8 (0.010 mi.)	A33	88
CON EDISON	***CROMWELL PL & E POST***	***NE 0 - 1/8 (0.094 mi.)***	***L99***	***220***

EPA Id: NYP004210779				
CON EDISON EPA Id: NYP004761797	100 POST RD	NE 0 - 1/8 (0.102 mi.)	L112	255
CON EDISON EPA Id: NYP004772521	E POST RD & GRAND ST	NE 0 - 1/8 (0.102 mi.)	L123	275
CON EDISON EPA Id: NYP004772455	E NEW YORK POST RD &	NE 0 - 1/8 (0.102 mi.)	L126	280
CON EDISON EPA Id: NYP004768131	LEXINGTON AVE & MAPL	SSW 0 - 1/8 (0.124 mi.)	Q145	324
CON EDISON EPA Id: NYP004799854	148 MAMARONECK AVE	NE 1/8 - 1/4 (0.235 mi.)	AG251	546
CON EDISON MANHOLE 3 EPA Id: NYP004225900	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG265***	***595***
CON EDISON EPA Id: NYP004801361	E POST RD & MAMMARON	NE 1/8 - 1/4 (0.239 mi.)	AG267	602
CON EDISON MANHOLE 3 EPA Id: NYP004225892	***MAMARONECK AVE & E P***	***NE 1/8 - 1/4 (0.239 mi.)***	***AG271***	***609***
CON EDISON EPA Id: NYP004805065	134 MAMARANECK AVE	NE 1/8 - 1/4 (0.240 mi.)	AG275	620
CON EDISON EPA Id: NYP004806469	134 MAMARONECK AVE	NE 1/8 - 1/4 (0.240 mi.)	AG278	625
CON EDISON EPA Id: NYP004846877	128 MAMARONECK AVE	NE 1/8 - 1/4 (0.241 mi.)	AG281	630
CON EDISON EPA Id: NYP004207423	***235 MAMARONECK AVE F***	***E 1/8 - 1/4 (0.246 mi.)***	***AJ286***	***641***
CON EDISON EPA Id: NYP004207829	***237 MAMARONECK AVE S***	***E 1/8 - 1/4 (0.248 mi.)***	***AJ289***	***648***

Lower Elevation	**Address**	**Direction / Distance**	**Map ID**	**Page**
CON EDISON EPA Id: NYP004825978	GROVE ST & FISCHER C	NNE 0 - 1/8 (0.083 mi.)	J87	198
WHITE PLAINS LINC-ME EPA Id: NYD052088754	***25 W POST RD***	***SW 0 - 1/8 (0.099 mi.)***	***N109***	***241***
CON EDISON EPA Id: NYP004749677	S LEXINGTON AVE & QU	NW 0 - 1/8 (0.102 mi.)	H116	263
CON EDISON EPA Id: NYP004764643	LEXINGTON AVE & QUAR	NW 0 - 1/8 (0.102 mi.)	H122	274
CON EDISON EPA Id: NYP004213476	***GROVE ST & QUARROPAS***	***NNE 1/8 - 1/4 (0.133 mi.)***	***R151***	***335***
CON EDISON EPA Id: NYP004805560	QUARROPAS ST & MLK B	NNE 1/8 - 1/4 (0.133 mi.)	R153	341
CON EDISON EPA Id: NYP004885055	111 MARTIN LUTHER KI	N 1/8 - 1/4 (0.152 mi.)	R177	385
CON EDISON MANHOLE 9 EPA Id: NYP004224192	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK253***	***553***
CON EDISON MANHOLE 9	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK254***	***558***

EPA Id: NYP004224101

CON EDISON MANHOLE 9	***MARTINE AVE & GROVE***	***N 1/8 - 1/4 (0.236 mi.)***	***AK255***	***562***
EPA Id: NYP004224465				

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, and dated 06/30/2018 has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS HOSPITA Generator EPA Id: NYR000129965	41 POST RD	S 0 - 1/8 (0.010 mi.)	A26	57
WHITE PLAINS HOSPITA Generator EPA Id: NYR000129965	41 POST ROAD	S 0 - 1/8 (0.010 mi.)	A28	64

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WHITE PLAINS MGP SIT	9 NEW STREET AND 12	NNW 1/4 - 1/2 (0.459 mi.)	BG387	904

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 5 EDR Hist Auto sites within approximately 0.125 miles of the target property.

EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SMITH SAMUEL	79 E POST ROAD	ENE 0 - 1/8 (0.050 mi.)	D69	169

Lower Elevation	Address	Direction / Distance	Map ID	Page
POWER TEST CORP	26 EAST POST ROAD	SW 0 - 1/8 (0.002 mi.)	C5	12
POST-DAVIS SERVICE S	34 E POST RD	SSW 0 - 1/8 (0.002 mi.)	A13	23
POST ROAD GETTY	11 E POST RD	SW 0 - 1/8 (0.036 mi.)	C53	148
GEIS SERVICE STATION	124 S LEXINGTON AVE	WNW 0 - 1/8 (0.084 mi.)	H92	211

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 5 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CILIM CLEANERS CORP	82-84 E POST RD	NE 0 - 1/8 (0.063 mi.)	D72	171
GRAND STREET CLEANER	104 E POST RD	NE 0 - 1/8 (0.123 mi.)	L141	316

Lower Elevation	Address	Direction / Distance	Map ID	Page
CILIM CLEANERS CORP	168 S LEXINGTON AVE	W 0 - 1/8 (0.010 mi.)	B35	109
BRIGHT SIDE CLEANERS	182 S LEXINGTON AVE	WSW 0 - 1/8 (0.013 mi.)	B37	116
BISCARDI CLEANERS IN	201 S LEXINGTON AVE	SW 0 - 1/8 (0.063 mi.)	G76	180

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped. Count: 4 records.

Site Name	Database(s)
WHITE PLAINS HOSPITAL MEDICAL CTR	US AIRS
GEDNEY WAY LANDFILL	NY SHWS, NY HSWDS
MICA PRODUCTS LANDFILL	NY SWF/LF
FORECLOSED - TTF	NY LTANKS

OVERVIEW MAP - 06284645.2R



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory
- State Wetlands

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	White Plains - 5 Parcels	CLIENT:	Barton & Loguidice, D.P.C.
ADDRESS:	42 East Post Road White Plains NY 10601	CONTACT:	Corinne Steinmuller
LAT/LONG:	41.026718 / 73.769558	INQUIRY #:	06284645.2r
		DATE:	December 01, 2020 12:17 pm

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

DETAIL MAP - 06284645.2R



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME:	White Plains - 5 Parcels	CLIENT:	Barton & Loguidice, D.P.C.
ADDRESS:	42 East Post Road White Plains NY 10601	CONTACT:	Corinne Steinmuller
		INQUIRY #:	06284645.2r
LAT/LONG:	41.026718 / 73.769558	DATE:	December 01, 2020 12:26 pm

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
Federal NPL site list								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
Federal Delisted NPL site list								
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
Federal CERCLIS NFRAP site list								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG	0.250		1	0	NR	NR	NR	1
RCRA-SQG	0.250		0	0	NR	NR	NR	0
RCRA-VSQG	0.250		1	3	NR	NR	NR	4
Federal institutional controls / engineering controls registries								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
NY SHWS	1.000		0	0	2	0	NR	2
State and tribal landfill and/or solid waste disposal site lists								
NY SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
INDIAN LUST	0.500		0	0	0	NR	NR	0
NY LTANKS	0.500		23	45	100	NR	NR	168
NY HIST LTANKS	0.500		0	0	0	NR	NR	0
State and tribal registered storage tank lists								
FEMA UST	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY UST	0.250		13	23	NR	NR	NR	36
NY CBS UST	0.250		0	0	NR	NR	NR	0
NY MOSF UST	0.500		0	0	0	NR	NR	0
NY CBS	0.250		0	1	NR	NR	NR	1
NY MOSF	0.500		0	0	0	NR	NR	0
NY AST	0.250		5	14	NR	NR	NR	19
NY CBS AST	0.250		0	1	NR	NR	NR	1
NY MOSF AST	0.500		0	0	0	NR	NR	0
INDIAN UST	0.250		0	0	NR	NR	NR	0
NY TANKS	0.250		0	0	NR	NR	NR	0
State and tribal institutional control / engineering control registries								
NY RES DECL	0.125		0	NR	NR	NR	NR	0
NY ENG CONTROLS	0.500		0	0	2	NR	NR	2
NY INST CONTROL	0.500		0	0	2	NR	NR	2
State and tribal voluntary cleanup sites								
NY VCP	0.500		0	0	1	NR	NR	1
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfields sites								
NY BROWNFIELDS	0.500		0	1	3	NR	NR	4
NY ERP	0.500		0	0	0	NR	NR	0
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
NY SWRCY	0.500		0	0	0	NR	NR	0
NY SWTIRE	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
Local Lists of Hazardous waste / Contaminated Sites								
US HIST CDL	TP		NR	NR	NR	NR	NR	0
NY DEL SHWS	1.000		0	0	0	0	NR	0
US CDL	TP		NR	NR	NR	NR	NR	0
NY PFAS	0.500		0	0	0	NR	NR	0
Local Lists of Registered Storage Tanks								
NY HIST UST	0.250		0	0	NR	NR	NR	0
NY HIST AST	TP		NR	NR	NR	NR	NR	0
Local Land Records								
NY LIENS	TP		NR	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
NY Spills	0.125	2	52	NR	NR	NR	NR	54
NY Hist Spills	0.125		0	NR	NR	NR	NR	0
NY SPILLS 90	0.125		0	NR	NR	NR	NR	0
NY SPILLS 80	0.125		0	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR	0.250		28	41	NR	NR	NR	69
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	TP		NR	NR	NR	NR	NR	0
TRIS	TP		NR	NR	NR	NR	NR	0
SSTS	TP		NR	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
ICIS	TP		NR	NR	NR	NR	NR	0
FTTS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
COAL ASH DOE	TP		NR	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
HIST FTTS	TP		NR	NR	NR	NR	NR	0
DOT OPS	TP		NR	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	1	0	NR	1
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	TP		NR	NR	NR	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
ECHO	TP		NR	NR	NR	NR	NR	0
DOCKET HWC	TP		NR	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
NY AIRS	TP		NR	NR	NR	NR	NR	0
NY COAL ASH	0.500		0	0	0	NR	NR	0
NY DRYCLEANERS	0.250		1	0	NR	NR	NR	1
NY E DESIGNATION	0.125		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY Financial Assurance	TP		NR	NR	NR	NR	NR	0
NY HSWDS	0.500		0	0	0	NR	NR	0
NY MANIFEST	0.250		34	42	NR	NR	NR	76
NJ MANIFEST	0.250		10	15	NR	NR	NR	25
PA MANIFEST	0.250		2	0	NR	NR	NR	2
NY SPDES	TP		NR	NR	NR	NR	NR	0
NY VAPOR REOPENED	0.500		0	0	0	NR	NR	0
NY UIC	TP		NR	NR	NR	NR	NR	0
NY COOLING TOWERS	TP		NR	NR	NR	NR	NR	0
NY LEAD	TP		NR	NR	NR	NR	NR	0
MINES MRDS	TP		NR	NR	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	1	0	NR	1
EDR Hist Auto	0.125		5	NR	NR	NR	NR	5
EDR Hist Cleaner	0.125		5	NR	NR	NR	NR	5
EDR RECOVERED GOVERNMENT ARCHIVES								
Exclusive Recovered Govt. Archives								
NY RGA HWS	TP		NR	NR	NR	NR	NR	0
NY RGA LF	TP		NR	NR	NR	NR	NR	0
- Totals --		2	180	186	112	0	0	480

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

A1
Target
Property

APARTMENT HOUSE
42-44 EAST POST RD
WHITE PLAINS, NY

NY Spills **S104952565**
N/A

Site 1 of 25 in cluster A

Actual:
211 ft.

SPILLS:

Name:	APARTMENT HOUSE
Address:	42-44 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0011872 / 2001-02-05
Facility ID:	0011872
Facility Type:	ER
DER Facility ID:	262050
Site ID:	325324
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6017
Spill Date:	2001-02-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2001-02-02
CID:	252
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-02
Spill Record Last Update:	2001-03-01
Spiller Name:	ROBERT CIRILLO
Spiller Company:	APARTMENT HOUSE
Spiller Address:	42-44 EAST POST RD
Spiller Company:	001
Contact Name:	ROBERT CIRILLO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/05/2001 SAME AS SPILL NUMBER 0011871. THIS NUMBER CLOSED OUT."
Remarks:	"APARTMENT COMPLEX OVER ORDERED HEATING OIL WHICH WHEN DELIVERED CAUSED APPROX 70 GALLONS TO BE SPILLED ON TO BASEMENT FLOOR-SPILL HAS BEEN CONTAINED AND IS BEING CLEANED UP."

All Materials:

Site ID:	325324
Operable Unit ID:	833250
Operable Unit:	01
Material ID:	542164
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	70.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A2 Target Property **RAKOFF REALTY**
42 EAST POST RD
WHITE PLAINS, NY

NY Spills **S104952564**
N/A

Site 2 of 25 in cluster A

Actual: 211 ft.

SPILLS:

Name:	RAKOFF REALTY
Address:	42 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0011871 / 2005-10-11
Facility ID:	0011871
Facility Type:	ER
DER Facility ID:	185016
Site ID:	223814
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2001-02-02
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2001-02-02
CID:	397
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-02-02
Spill Record Last Update:	2005-10-11
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/02/2001 FIRE DEPT. USING SPEEDI DRY FOR CLEANUP. 3/6/5 25 gallon overfill cleaned up--close 8/05/05 UST Removal and Soil/Groundwater Remediation Report submitted by National Env. Specialists. Based on the info contained in that report, NFA required. TG"
Remarks:	"caller states a delivery service made a delivery adn spilled oil. fd is on the scene and clean up is in progress"

All Materials:

Site ID:	223814
Operable Unit ID:	833249
Operable Unit:	01
Material ID:	542163
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G

RAKOFF REALTY (Continued) **S104952564**

Recovered: .00
Oxygenate: Not reported

A3 **MANHOLE 3471** **NY Spills** **S103827140**
44 POST RD **N/A**
< 1/8 **WHITE PLAINS, NY**
1 ft.

Site 3 of 25 in cluster A

Relative: Higher
Actual: 211 ft.

SPILLS:

Name:	MANHOLE 3471
Address:	44 POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9812506 / 1999-01-10
Facility ID:	9812506
Facility Type:	ER
DER Facility ID:	108898
Site ID:	125914
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-01-10
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-01-10
CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-01-10
Spill Record Last Update:	1999-02-09
Spiller Name:	Not reported
Spiller Company:	CON EDISON
Spiller Address:	4 IRVING PLACE
Spiller Company:	001
Contact Name:	STEVE ROMERO
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"1 quart of unk oil on 50 gallosn of water - treat it as 50-400 ppm pcbs - clean up waiting test results - con ed ref #122355"

All Materials:

Site ID:	125914
Operable Unit ID:	1073058
Operable Unit:	01
Material ID:	312788
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum

MANHOLE 3471 (Continued) **S103827140**

Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported

B4 **CON ED MANHOLE 9169** **NY Spills** **S106125245**
West **169 LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.001 mi.
7 ft. **Site 1 of 9 in cluster B**

Relative:
Lower

Actual:
203 ft.

SPILLS:
Name: CON ED MANHOLE 9169
Address: 169 LEXINGTON AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0311437 / 2004-01-09
Facility ID: 0311437
Facility Type: ER
DER Facility ID: 241430
Site ID: 298419
DEC Region: 3
Spill Cause: Unknown
Spill Class: C4
SWIS: 6017
Spill Date: 2004-01-08
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2004-01-09
CID: 403
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2004-01-09
Spill Record Last Update: 2004-02-03
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: RON ELLIOTT
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE E2mis indicates 10.1 ppm of pcb. TG"
Remarks: "No smoke, fire or anything else. Cleanup hasn't started yet."

All Materials:
Site ID: 298419
Operable Unit ID: 876789
Operable Unit: 01
Material ID: 500245
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported

CON ED MANHOLE 9169 (Continued) **S106125245**

Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C5 **POWER TEST CORP** **EDR Hist Auto** **1021117863**
SW **26 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.002 mi.
12 ft. **Site 1 of 23 in cluster C**

Relative: EDR Hist Auto
Lower

Actual:
208 ft.

Year:	Name:	Type:
1982	POWER TEST CORP	Gasoline Service Stations
1983	POWER TEST CORP	Gasoline Service Stations
1985	POWER TEST CORP	Gasoline Service Stations
1986	GETTY PETROLEUM CORP DEL	Gasoline Service Stations

C6 **CLOSED GETTY GAS STATION** **NY Spills** **S103036219**
SW **26 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.002 mi.
12 ft. **Site 2 of 23 in cluster C**

Relative: SPILLS:
Lower

Actual:
208 ft.

Name:	CLOSED GETTY GAS STATION
Address:	26 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9713110 / 2017-08-21
Facility ID:	9713110
Facility Type:	ER
DER Facility ID:	150182
Site ID:	178917
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	A3
SWIS:	6017
Spill Date:	1998-02-24
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	1998-02-24
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-24
Spill Record Last Update:	2017-08-21

CLOSED GETTY GAS STATION (Continued) **S103036219**

Spiller Name: MARY KENNEY
Spiller Company: CLOSED GETTY GAS STATION
Spiller Address: 26 EAST POST RD
Spiller Company: 001
Contact Name: MARY KENNY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 03/04/98 BARBARA MCDONALD (WCHD); CLOSED GAS STATION; SITE ASSESSMENT SHOWED SOIL & GROUNDWATER CONTAMINATION ABOVE STARS GUIDELINES; OWNER HAS NOT YET DECIDED ON REMEDIATION OPTION; 06/17/99 LETTER SENT BY T. GHIOSAY RE: WORK PLAN FOR SUBSURFACE INVESTIGATION AT THIS SITE. 04/20/00 TYREE CALCULATES SOIL REMOVAL TONNNAGE. EXCAVATION WOULD REQUIRE 5169 TONS. TYREE RECOMMENDS AGAINST REMOVAL. 12/07/00 LETTTER SENT TO TYREE BY J. HARDY;REMEDIAL ACTION PLAN IS REQUIRED FOR THIS SITE WITHIN 30 DAYS. 01/18/01 LETTER SENT TO TYREE BY J. HARDY; PROPOSAL TO DESIGN A DUAL PHASE HI-VAC SYSTEM FOR THIS SITE IS APPROVED AND REQUIRED. 03/01/01 LETTER SENT TO TYREE BY J. HARDY; PLAN TO SHOW OFF SITE WELLS IN RELATION TO OFF SITE CONTAMINATION IS REQUIRED. 06/07/01 LETTER SENT TO TYREE BY J. HARDY; REQUEST TO EXTEND THE START UP DEADLINE FROM 6/1/01 TO 6/21/01 IS APPROVED. 6/12/03: Letter sent to P.N. Holloway, Tyree Organization Ltd. from J. Hardy. Monitor well sampling and reporting may be recduced to semi-annually. 2/23/04: Letter sent to P. Holloway, Tyree by J. Hardy. Reduce reporting to annual. A Dual Phase High Vacuum Extraction system operated here from roughly 2001 to 2007. VEFR events on targeted wells were continued bimonthly for all of 2008. An NFA request was submitted in Oct. 2008 and reiterated by e-mail Feb. 2009. This request was denied based upon coninued impacts to GW in MW-19. Latest QMR and denial e-mail have been added to eDocs. PJD Feb. 2009 A request for a reduciton in the # of MWs being sampled semi annually has been received and approved based upon contaminant concs. at or below GW standards. PJD Mar. 09 An e-mail request to conduct supplemental investigation in the area of MW-19 was approved and uploaded to eDocs. PJD Jan. 2010 5-27-15 project transferred to John O'mara- RDB 8-15 Tyree submitted Remedial Action Report to JOM 8-15 submittal by first environment on behalf of WPHA 9-15 JOM response to submittal? 04-16 submittal of indoor air sampling by 1st Environmental 04-16 response from NYSDOH to First Environmental 04-14-16 project transferred to DB; sent email to Antea looking for updated information - RDB 05-12-16 email from first envir; Tyree does not have acesss to install wells? RDB 06-16- meet with Getty and then meet on site; 07-01-16 sent email approving locations for Getty; copied WPHA 07-16- Access granted; wells installed; sampling to be conducted August 1-RDB 10-18-16 The replacement wells were installed in the excavated area in late July and a groundwater sampling event was performed on August 1. We are preparing the monitoring report to summarize those results and will be submitting it to you later this week. RDB 11-1-16 revised sample results submitted- RDB 11-10-16 next round of sampling collected; MW 14 found to have LNALP; new spill 16-07837 opened for 22 East Post Rd 12-9-16 comments from 1st Environment on August sampling. 12-16 new spill opened for 34 East Post Rd- 16-08924 12-16 letter from owners rep. RDB 01-17 responded to Owners rep looking for spill closure. 01-17 Owner removed canopy. email sent to Antea asking if below was ever sampled. 01-17 response from Antea, In response to White Plains, I m reaching out to Ben Rieger to understood the aspects of the canopy with regards to the excavation and will replying to your e-mail. RDB 1-12-17 requested sampling under the footprint of the canopy based on excavation

CLOSED GETTY GAS STATION (Continued) **S103036219**

stopping at footings. RDB 1-23-17 As requested, antea and IPT will be on site tomorrow to conduct soil borings, 02-17 Report submitted doc canopy work, nothing found- RDB"

Remarks: "HISTORICAL SPILL - CALLER IS DOING SITE ASSESSMENT AND FOUND SOIL CONTAMINATION "

All Materials:

Site ID:	178917
Operable Unit ID:	1056077
Operable Unit:	01
Material ID:	563710
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C7 **POWER TEST/GETTY COS** **NY UST** **U003857535**
SW **26 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.002 mi.
12 ft. **Site 3 of 23 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

WESTCHESTER CO. UST:

Name:	POWER TEST/GETTY COS
Address:	26 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-137596 / Unregulated
Operator Name:	William Manning Sales Rep
Owner Name:	Power Test Petroleum Dist Inc
Owner Street:	125 Jericho Turnpike
Owner Address2:	Not reported
Owner City:	Jericho
Owner State:	NY
Owner Zipcode:	11753
GDS Number:	Not reported
Tank Number:	2
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1977
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None

POWER TEST/GETTY COS (Continued) **U003857535**

Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	3
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1977
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	10000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1977
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

A8
SSW
< 1/8
0.002 mi.
12 ft.

WHITE PLAINS CITGO
34 EAST POST ROAD
WHITE PLAINS, NY

Site 4 of 25 in cluster A

NY Spills **U003648099**
N/A

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	WHITE PLAINS CITGO
Address:	34 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9516188 / 1997-11-12
Facility ID:	9516188
Facility Type:	ER
DER Facility ID:	144434
Site ID:	167943
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1996-03-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-03-18
CID:	297
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1996-03-18
Spill Record Last Update:	2016-12-15
Spiller Name:	GARY GIGLIO
Spiller Company:	BARRIER OIL
Spiller Address:	184 WEST MAIN STREET
Spiller Company:	001
Contact Name:	UNKNOWN
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TANK OVERFILLED BECAUSE IT WAS TILTED AND THE DRIVER WAS UNAWARE THE TANK WAS TILTED - SPILL CLEANED UP WITH ABSORBANT PADS"

All Materials:

Site ID:	167943
Operable Unit ID:	1027156
Operable Unit:	01
Material ID:	352727
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

A9
SSW
< 1/8
0.002 mi.
12 ft.

BP GAS STATION
34 EAST POST RD
WHITE PLAINS, NY

Site 5 of 25 in cluster A

NY Spills **S118460294**
N/A

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	BP GAS STATION
Address:	34 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1509193 / 2015-12-09
Facility ID:	1509193
Facility Type:	ER
DER Facility ID:	474102
Site ID:	519791
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2015-12-09
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2015-12-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-12-09
Spill Record Last Update:	2016-12-15
Spiller Name:	Not reported
Spiller Company:	BP GAS STATION
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	N/A
DEC Memo:	"12/9/15 - WCDOH conduct an inspection and did not find active leak. WCDOH recommended spill to be closed. WCDOH email and report are in DecDocs. NFA. KAB"
Remarks:	"What Occurred: Gas Pump #7 does not shut off automatically when the fuel tank is full. As a result, the tank overflows and a significant amount of gas overflows and pools on the ground. This first occurred to me about 2 months ago. At that time, I thought there was a problem with my car and I had it checked out by the dealer. I used the same pump again this morning at 7:30am and the same problem occurred. I informed the gas station attendant and it appeared he knew this pump was a problem. I am concerned because it appears they have not corrected the issue in at least two months (based upon the two times it happened to me) and significant amounts of gas are routinely spilling on the ground."

All Materials:

Site ID:	519791
Operable Unit ID:	1268856
Operable Unit:	01
Material ID:	2272811

BP GAS STATION (Continued) **S118460294**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A10 **BP STATION- EAST POST RD GASMART** **NY Spills** **S119028898**
SSW **34 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.002 mi.
12 ft. **Site 6 of 25 in cluster A**

Relative: **Lower**

Actual: **209 ft.**

SPILLS:

Name:	BP STATION- EAST POST RD GASMART
Address:	34 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Spill Number/Closed Date:	1608924 / Not Reported
Facility ID:	1608924
Facility Type:	ER
DER Facility ID:	491534
Site ID:	537673
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2014-09-01
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2016-12-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	1
Date Entered In Computer:	2016-12-20
Spill Record Last Update:	2019-08-26
Spiller Name:	Not reported
Spiller Company:	Marianina Oil Corp
Spiller Address:	676 Mamaroneck Ave
Spiller Company:	999
Contact Name:	FAWZI IBRAHIM
DEC Memo:	"Samples collected in September 2014, December 2015, and August 2016 reveal soil and groundwater contamination down gradient of this facility. RDB 12-22-*16 Marianina Oil Corp Owner RP letter sent to both owner and operator- RDB 01-4-17 call from Papito 01-6-17 email from TBishop, I met with the property owner, their counsel and Vince Papitto this morning at the site regarding your December 21, 2016 letter addressed to Marianina Oil Corp. I will be proposing a day of borings to determine soil and groundwater quality as well as

BP STATION- EAST POST RD GASMART (Continued) **S119028898**

calculate groundwater flow direction. I expect to begin drilling next week. RDB 1-9-17 followed up with 3 emails to Bishop; 2014 tyree report, 2016 Antea report, & 2016 Tetratech report. RDB 2-15-17 check on status? report should be submitted this week? RDB 3-7-17 report submitted- RDB 06-13-17 drove by site; on going demo work? June 2017- Citizen NOI filed?- RDB 07-17 email sent to Carlos looking for status- RDB 07-17- phone call from Jeff Papitto 914 447-1279 and Phil Decaro esq 914-835-6200 07-18-17 spoke to Jeff, he has spoken to Frank, he is on board would like some additional time, they will be using Tim Bishop of Ct. Expressed concern to OGC regarding possible Citizen's suit brought by WPHA. RDB 7-21-17 email from Jeff, So sorry Tim Bishop has gotten in touch with you as of yet. I know he is vactioning with his family and will be back Monday, July 24, 2017. We have forwarded him all site analyticals last week and he has acknolwedged receiving all the information.We have submitted a budget estimate to Mr. Frank Codella as well and have sent all information to Soil Safe for clearance for disposal. Papitto Construction Co., Inc. plans on mobilizing the first week of August as discussed previously with you.Tim's cell is 914-224-6268 if you need him he will be back on Monday.Any questions please feel frre to contact me at 914 447 1279. RDB 7-24-17 email from TIm Bishop, I spoke with Jeff last week while I was away and he filled me in about 34 East Post Road in White Plains. I ll be putting together a RAWP for the station in White Plains that Papitto is proposing soil excavation at. I understand the station is currently closed and they re expecting to remove at least 800 tons of contaminated soil... (plus groundwater monitoring).I ll be working on this today, submit it to the client for review and expect to have it to you for review by Wednesday. RDB 8-14-17 status email to Tim Bishop, response, I spoke to Jeff today and neither him nor me have the gotten the green light for anything yet. RDB 8-*22-17 spoke to Phil Decarlo, asked him to contact Ben- RDB 8-28-17, So this is your two week follow-up.Any progress? / response, I took a call from Phil Decaro last week and he said Frank was going to be securing the funds late last week, but I haven t heard anything since nor do I have a signed contract. RDB 09-28-17 RP letter with settlement letter sent- RDB 10-6-17 Owner and attorney came in; asked to have tanks pumped by 10-10-17- RDB 10-11-17 draft OC sent to owner's att; WCHD reports tanks are not pumped out- RDB 10-13-17 email from att; tanks empty 10-13-17 NOV sent to Northville Industries Corp. BTR 10-16-17 email to WCHD to check tanks- RDB 11-6-17, email sent, Frank and Phil,We met with both of you on October 6, 2017 and forwarded you an Order on Consent on October 11, 2017. To date, we have not received neither an executed Order on Consent nor documentation that the tanks have been pumped out. The Department would like to meet with both of you on Friday November 17th at 11:00 am to discuss the investigation and remediation of this site.Please confirm your attendance. rdb 11-10-17 email from Phil Decaro received I have been in depositions all week and traveling today so I do not have access to all my files, but I have attached a copy of the receipt for the pump-out of the tanks at 34 East Post Rd. I will be able to send you an executed copy of the Consent Order on Monday, but in the meantime please accept this email as a representation that my client agrees with and accepts the terms of the Consent Order. Tank pump out record is on DECDOCs. BTR 12-1-17, Upon arrival at the site at approximately 11am, the manhole was opened, PID reading was 0. Began to evacuate with vacuum truck. Significant recharge. Highest PID reading during evacuation process

BP STATION- EAST POST RD GASMART (Continued) **S119028898**

was 125 ppm. Evacuated 2 existing drums of purge water staged on site. Total evacuated 1360 gallons. RDB 02-08-18 Consent Order executed by DEC. GZA has not been contracted for any of the work proposed in November. BTR 08-07-18 Asked Frank & Phil to meet in the New Paltz Office on Friday, August 10. Counsel responded that they are not available until first week of September. BTR 08-14-18 Scheduled meeting for Friday Sept. 7, at 11AM. No response received from Frank & Phil. BTR 08-30-18 B. Conlon asked to confirm meeting attendance. Still no response. BTR 10-9-18 deposed by WPHA counsel- RDB 11-21-18 Notified Mr. Codella of December 18 meeting in New Paltz. BTR 12-12-18 Mr. Decaro sent email asking for adjournment. No adjournment was granted. BTR 12/18/18 Met with Codella and Dicarro, at the meeting they agreed to let the department conduct the work. 12/30/18 Codella and Dicarro advised department RP is now willing to do the work and sign Orrder on Consent. TJP 1/22/19 RAWP received and uploaded to D2. TJP 1/25/19 Workplan put on hold until Order on Consent is signed, OGC sent out Order on Consent. TJP 02/15/19 First Environment letter received 1/9/2019 and uploaded to D2 --- IN 06-25-2019 No work progressing; OGC working on site- RDB 7/3/19 email sent to white plains I am the contact person for the site located at 34 East Post Road moving forward. I know you and Dan Bendell had spoken a few times but I wanted to let you know that this Department has not approved any remedial work that is being conducted on the site. This Department has instructed Mariana Oil to cease pumping operations and remove their tanks via consent order, to date we have not received a signed consent order and will be having pre-hearing conference in the NYSDEC Region 3 New Paltz office on July 16, 2019 regarding a notice of hearing and complaint for failure to sign and complete the original consent order. BW 8-23-19 email from RP's attorney- Decarlo, Please be advised that we have be informed by the City of White Plains, NY that it intends to take my client s property, located at 34 East Post Road, White Plains, NY, through the eminent domain process. - ??? RDB"

Remarks: "Significant soil and groundwater identified off- site"

All Materials:

Site ID:	537673
Operable Unit ID:	1286295
Operable Unit:	01
Material ID:	2291900
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A11
SSW
< 1/8
0.002 mi.
12 ft.

FORMER NORTHVILLE GAS STA
34 EAST POST ROAD
WHITE PLAINS, NY

Site 7 of 25 in cluster A

NY Spills **S102155118**
N/A

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	FORMER NORTHVILLE GAS STA
Address:	34 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9406684 / 1999-06-30
Facility ID:	9406684
Facility Type:	ER
DER Facility ID:	144434
Site ID:	171620
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1994-08-16
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-08-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-08-19
Spill Record Last Update:	2016-12-15
Spiller Name:	Not reported
Spiller Company:	FRANKCODELLA
Spiller Address:	11 EAST POST ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 6/30/99 INVESTIGATION/REMEDIATION OF SITE BEING PERFORMED UNDER SPILL NO. 97-13110. 02/12/07 An additional file review was performed and it was determined that this spill number is not related to spill 97-13310 which corresponds to another gas station at 26 East Post Road. TG"
Remarks:	"THRE TEST PITS SHOWED READINGS ON PID METER ALSO ODOR NOTICED SOIL SAMPLES HAVE BEEN SENT TO LAB"

All Materials:

Site ID:	171620
Operable Unit ID:	1004106
Operable Unit:	01
Material ID:	379715
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L

FORMER NORTHVILLE GAS STA (Continued) **S102155118**

Recovered: .00
Oxygenate: Not reported

A12 **EAST POST ROAD GASMART, INC.** **NY UST** **U004176875**
SSW **34 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10605**
0.002 mi.
12 ft. **Site 8 of 25 in cluster A**

Relative: **Lower**
Actual: **209 ft.**

WESTCHESTER CO. UST:

Name:	EAST POST ROAD GASMART, INC.
Address:	34 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10605
Id/Status:	3-601177 / Active
Operator Name:	Fawzi Ibrahim
Owner Name:	Marianina Oil Corp.
Owner Street:	676 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	3551700183
Tank Number:	001
Status:	1. In-Service
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,2. Manual Interstitial Monitoring
Date Installation:	08/01/1994
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	002
Status:	1. In-Service
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,2. Manual Interstitial Monitoring
Date Installation:	08/01/1994
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass

EAST POST ROAD GASMART, INC. (Continued) **U004176875**

Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	003
Status:	1. In-Service
Capacity:	6000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,2. Manual Interstitial Monitoring
Date Installation:	08/01/1994
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	6. Fiberglass reinforced plastic (FRP)
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	0. None
Dispenser:	2. Suction

A13 **POST-DAVIS SERVICE STATION** **EDR Hist Auto** **1020257726**
SSW **34 E POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.002 mi.
12 ft. **Site 9 of 25 in cluster A**

Relative: EDR Hist Auto
Lower

Actual:
209 ft.

Year:	Name:	Type:
1969	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1970	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1971	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1972	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1973	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1974	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1975	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1976	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1977	POST-DAVIS SERVICE STATION	Gasoline Service Stations
1995	MARIANINA OIL CORP	Gasoline Service Stations
2001	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2001	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2002	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2003	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2004	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2005	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2006	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2007	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations

POST-DAVIS SERVICE STATION (Continued) **1020257726**

2008	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations
2009	BARRIER WHITE PLAINS CITGO	Gasoline Service Stations

A14 **WESTCHESTER FIRESTONE** **RCRA NonGen / NLR** **1001224019**
ENE **60 E POST RD** **FINDS** **NYR000052357**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.003 mi. **NY MANIFEST**
16 ft. **Site 10 of 25 in cluster A**

Relative:
Higher

Actual:
214 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER FIRESTONE
Handler Address:	60 E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000052357
Contact Name:	MICHAEL OLSEN
Contact Address:	W GOLF RD
Contact City,State,Zip:	ROLLING MEADOWS, NY 60008
Contact Telephone:	847-981-2388
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W GOLF RD
Mailing City,State,Zip:	ROLLING MEADOWS, NY 60008
Owner Name:	BRIDGESTONE & FIRESTONE INC
Owner Type:	Private
Operator Name:	BRIDGESTONE & FIRESTONE INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No

WESTCHESTER FIRESTONE (Continued) **1001224019**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D006
Waste Description:	CADMIUM
Waste Code:	D007
Waste Description:	CHROMIUM
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D010
Waste Description:	SELENIUM
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE

Handler - Owner Operator:

WESTCHESTER FIRESTONE (Continued) **1001224019**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BRIDGESTONE & FIRESTONE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2550 W GOLF RD
Owner/Operator City,State,Zip:	ROLLING MEADOWS, IL 60008
Owner/Operator Telephone:	847-981-2388
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	BRIDGESTONE & FIRESTONE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2550 W GOLF RD
Owner/Operator City,State,Zip:	ROLLING MEADOWS, IL 60008
Owner/Operator Telephone:	847-981-2388
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	BRIDGESTONE & FIRESTONE INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	2550 W GOLF RD
Owner/Operator City,State,Zip:	ROLLING MEADOWS, IL 60008
Owner/Operator Telephone:	847-981-2388
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WESTCHESTER FIRESTONE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER FIRESTONE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

WESTCHESTER FIRESTONE (Continued) **1001224019**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1998-03-25 00:00:00.0
Handler Name:	WESTCHESTER FIRESTONE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004541489

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1001224019
Registry ID:	110004541489
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004541489
Name:	WESTCHESTER FIRESTONE
Address:	60 E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601

NY MANIFEST:

Name:	BRIDGESTONE/FIRESTONE INC
Address:	60 E POST RD

WESTCHESTER FIRESTONE (Continued) **1001224019**

City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYR000052357
Facility Status: Not reported
Location Address 1: 60 E POST RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000052357
Mailing Name: BRIDGESTONE/FIRESTONE INC
Mailing Contact: WILLIAM ZAPMEY
Mailing Address 1: 60 E POST RD
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9149492346

NY MANIFEST:
Document ID: CTF0683743
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: NYAV4489
Trans2 State ID: Not reported
Generator Ship Date: 07/01/1998
Trans1 Recv Date: 07/01/1998
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/07/1998
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYR000052357
Trans1 EPA ID: ILD984908202
Trans2 EPA ID: Not reported
TSDF ID 1: CTD001156009
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP

WESTCHESTER FIRESTONE (Continued) **1001224019**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00075
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

A15 **STS TIRE SERVICE** **NY Spills** **S109206474**
ENE **60 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.003 mi.
16 ft. **Site 11 of 25 in cluster A**

Relative:
Higher

Actual:
214 ft.

SPILLS:

Name:	STS TIRE SERVICE
Address:	60 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0804645 / 2008-09-26
Facility ID:	0804645
Facility Type:	ER
DER Facility ID:	350817
Site ID:	401590
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-07-23
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2008-07-23
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-23
Spill Record Last Update:	2008-09-26
Spiller Name:	TED HAASE
Spiller Company:	STS TIRE
Spiller Address:	60 EAST POST ROAD
Spiller Company:	999
Contact Name:	TED HAASE
DEC Memo:	"08/12/08 C2G Environemntal consultants submitted a Underground Hydualic Lift Closure Report. NFA required. TG"
Remarks:	"REMOVING LIFTS AND FOUND CONTAMINATED SOIL"

All Materials:

STS TIRE SERVICE (Continued) **S109206474**

Site ID:	401590
Operable Unit ID:	1158376
Operable Unit:	01
Material ID:	2149444
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A16 **FIRESTONE COMPLETE AUTO CARE #347242** **NY AST** **A100364643**
ENE **60 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.003 mi.
16 ft. **Site 12 of 25 in cluster A**

Relative: WESTCHESTER CO. AST:
Higher

Name:	FIRESTONE COMPLETE AUTO CARE #347242
Address:	60 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-801814
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Bridgestone Retail Operations, LLC
Owner Name:	Bridgestone Retail Operations, LLC
Owner Street:	333 East Lake Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bloomingdale, IL 60108

Actual:
214 ft.

Tank Number:	001
Status:	1. In-Service
Date Installation:	12/14/2010
Capacity:	500
Product Stored:	0015. Motor Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	11. Flexible Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	002
Status:	1. In-Service

FIRESTONE COMPLETE AUTO CARE #347242 (Continued) **A100364643**

Date Installation:	12/14/2010
Capacity:	285
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	003
Status:	1. In-Service
Date Installation:	01/01/2016
Capacity:	120
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	99. High Density Polyethlene Resin
Tank Internal Protection:	Not reported
Tank External Protection:	Plastic Tote on Rack
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	3. Gravity

Tank Number:	004
Status:	1. In-Service
Date Installation:	01/08/2016
Capacity:	120
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	. High Density Polyethlene Resin
Tank Internal Protection:	Not reported
Tank External Protection:	Plastic Tote on Rack
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)

FIRESTONE COMPLETE AUTO CARE #347242 (Continued) **A100364643**

Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	3. Gravity

Tank Number:	005
Status:	1. In-Service
Date Installation:	01/08/2016
Capacity:	120
Product Stored:	0013. Lube Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	. High Density Polyethlene Resin
Tank Internal Protection:	Not reported
Tank External Protection:	Plastic Tote on Rack
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	3. Gravity

Tank Number:	006
Status:	1. In-Service
Date Installation:	01/01/2019
Capacity:	120
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	High Density Polyethlene Resin
Tank Internal Protection:	Not reported
Tank External Protection:	Plastic Tote on Rack
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

C17
SW
< 1/8
0.005 mi.
28 ft.

FRONT OF ONE STOP DELI
POST ROAD
WHITE PLAINS, NY

Site 4 of 23 in cluster C

NY Spills **S102153418**
N/A

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	FRONT OF ONE STOP DELI
Address:	POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8900729 / 1989-04-24
Facility ID:	8900729
Facility Type:	ER
DER Facility ID:	275083
Site ID:	148648
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6000
Spill Date:	1989-04-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-04-24
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1989-04-24
Cleanup Meets Std:	True
Last Inspection:	1989-04-24
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-05-01
Spill Record Last Update:	2003-10-21
Spiller Name:	Not reported
Spiller Company:	SAFETY KLEEN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: SOLVENTS / MINERAL SPI. "
Remarks:	"DRIVER LEFT BACKDOOR ON TRUCK OPEN AND DRUM FELL OFF. SORBANTS & SPEEDY DRY USED--SPILL ON PAVEMENT. WHITE PLAINS P.D. & F.D. ON SCENE. SPILL CLEANED UP N.F.A. L.R. 4/24/89"

All Materials:

Site ID:	148648
Operable Unit ID:	927297
Operable Unit:	01
Material ID:	452057
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00

FRONT OF ONE STOP DELI (Continued) **S102153418**

Oxygenate: Not reported

C18 **COMMERCIAL UST** **NY Spills** **S111012101**
SW **22-24 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.007 mi.
35 ft. **Site 5 of 23 in cluster C**

Relative: **Lower**

Actual: **208 ft.**

SPILLS:

Name:	OFF SITE FOR MONITORING SITE
Address:	22-24 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1101872 / Not Reported
Facility ID:	1101872
Facility Type:	ER
DER Facility ID:	403938
Site ID:	449350
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	6017
Spill Date:	2011-05-19
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2011-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2011-05-19
Spill Record Last Update:	2016-12-15
Spiller Name:	THOMAS FRANCO
Spiller Company:	UNKNOWN
Spiller Address:	2224 EAST POST RD
Spiller Company:	999
Contact Name:	THOMAS FRANCO
DEC Memo:	"5/19/11 - Work was directed by P. DeCicco, DEC, to determine if associated with a nearby gas station. Finger printing of the materal results most likely diesel. KAB 5-27-15 project transferred to JOM-RDB 12-15-16 new spill called in 16-07837; RDB"
Remarks:	"Monitoring site is picking up traces of deisel on their site from a adjacent former spill site. Caller has been in contact with DEC Spill personnel."

All Materials:

Site ID:	449350
Operable Unit ID:	1199563
Operable Unit:	01
Material ID:	2195940
Material Code:	0008
Material Name:	diesel

COMMERCIAL UST (Continued) **S111012101**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	COMMERCIAL UST
Address:	22-24 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1607837 / 2018-02-23
Facility ID:	1607837
Facility Type:	ER
DER Facility ID:	403938
Site ID:	535514
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A3
SWIS:	6017
Spill Date:	2016-11-10
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2016-11-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-11-10
Spill Record Last Update:	2018-02-23
Spiller Name:	Oladipo Olatunde
Spiller Company:	Adeogun Owonikoko LLC
Spiller Address:	22-24 EAST POST RD
Spiller Company:	999
Contact Name:	TIM FISHER
DEC Memo:	"11/10/16 Getty Realty and White Plains Housing Authority working on nearby site. There is what appears to be #2fo in MW-14 from Spill # 9713110 at 26 East Post Road. There is a #2 UST approximately 40' from MW-14 on 22-24 East Post Rd. mt 12-15-16 This spill is not associated with 97-13110; just so happens that during that investigation, this was detected. RDB 12-22-16 Adeogun owonikoko company LLC owner- RP letter sent - RDB 1-10-17 met on site with property owner, Oladipo Olatunde 914-262-2583. explained the situation and the need to remove his tank that is still in the ground, provided him pieces from both First environment and Antea . still need to send him names, figures, PBS FIR and tetra's report- RDB 1-13-17, Attached is a letter from TetraTech. Tetratech is an environmental consultant representing Singer Properties, the property owner of 26 East Post Road. Also attached is a copy of the Westchester County Dept. of Health records for the tanks previously registered at 26 East Post Road. The records indicate that the site

COMMERCIAL UST (Continued) **S111012101**

only stored gasoline at the station and not diesel. RDB 2/3/17 Spoke to Lina from Envirostar. Tank was pulled today - was 1000 gal. UST. Multiple holes found in tank. Samples to be pulled for CP-51. ga. 2-7-17, response to Envirostar, I am disappointed that you did not contact me prior to the removal of this tank. If you had, I would have been able to provide you with the background and explained what I needed accomplished at the site. For now, I need a summary of the work completed and the plan forward. I do not need several unlabeled photos spread out over multiple emails. Please assemble the photos and resubmit in a letter format. Please do not send emails without the Spill number referenced in the subject line. RDB 3-24-17, email We are planning to start the initial soil remediation work at the site starting on Monday April 3, 2017. The initial plan is to excavate an area approximately 12 by 12 by 8 feet (estimating about 25-50 tons of soil) immediately surrounding the tank grave. I will be on site with the contractor (Envirostar) to record conditions (PID readings, observations) and to collect site assessment soil samples.Please email me back to let me know that you have received this email and if want to meet us on site during the excavation work. My direct cell is 914-382-8673. RDB 4/13/17 Contamination discovered in tank grave. New spill reported, #17-00425, closed and referred back to this one..mm 4-19-17 stopped by site, email from Gallinger on 4-20- RDB 02-2018 TCR reviewed NFA RDB"

Remarks: "free product discovered in a monitoring well. Suspected to be fuel oil at this time. clean up is undetermined at this time."

All Materials:

Site ID:	535514
Operable Unit ID:	1284200
Operable Unit:	01
Material ID:	2289692
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

A19 **CON EDISON SERVICE BOX: 3468** **RCRA NonGen / NLR 1016974101**
ENE **E POST RD & WINCHESTER ST** **NY MANIFEST NYP004479127**
< 1/8 **WHITE PLAINS, NY 10606**
0.007 mi.
37 ft. **Site 13 of 25 in cluster A**

Relative:
Higher

Actual:
216 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-04-26 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3468
Handler Address:	E POST RD & WINCHESTER ST
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYP004479127
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported

CON EDISON SERVICE BOX: 3468 (Continued) **1016974101**

Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A

CON EDISON SERVICE BOX: 3468 (Continued) **1016974101**

Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-10-14 12:33:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-03-26 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3468
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2014-04-26 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3468
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 3468 (Continued) **1016974101**

NY MANIFEST:

Name:	CON EDISION
Address:	E POST RD & WINCHESTER ST
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYP004479127
Facility Status:	Not reported
Location Address 1:	E POST RD WINCHESTER ST
Code:	BP
Location Address 2:	SB3468
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004479127
Mailing Name:	CON EDISION
Mailing Contact:	CON EDISION
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/26/2014
Trans1 Recv Date:	03/26/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/01/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004479127
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693263JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 3468 (Continued) **1016974101**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A20 **CON EDISON MANHOLE: 3471** **RCRA NonGen / NLR** **1016973481**
ENE **E POST RD & WINCHESTER ST** **NY MANIFEST** **NYP004472841**
< 1/8 **WHITE PLAINS, NY 10607**
0.007 mi.
37 ft. **Site 14 of 25 in cluster A**

Relative:
Higher

Actual:
216 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-04-20 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 3471
Handler Address:	E POST RD & WINCHESTER ST
Handler City,State,Zip:	WHITE PLAINS, NY 10607
EPA ID:	NYP004472841
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON MANHOLE: 3471 (Continued) **1016973481**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-10-14 12:33:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-03-20 00:00:00.0

CON EDISON MANHOLE: 3471 (Continued) **1016973481**

Handler Name:	CON EDISON MANHOLE: 3471
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2014-04-20 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 3471
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	E POST RD & WINCHESTER ST
City,State,Zip:	WHITE PLAINS, NY 10607
Country:	USA
EPA ID:	NYP004472841
Facility Status:	Not reported
Location Address 1:	E POST RD & WINCHESTER ST
Code:	BP
Location Address 2:	SB3471
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004472841
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING ST

CON EDISON MANHOLE: 3471 (Continued) **1016973481**

Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/20/2014
Trans1 Recv Date:	03/20/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/21/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004472841
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012772691JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	160
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

C21
SSW
< 1/8
0.009 mi.
49 ft.

MANHOLE # 7278
EAST NEW YORK POST ROAD
WHITE PLAINS, NY

Site 6 of 23 in cluster C

NY Spills **S102151115**
N/A

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	MANHOLE # 7278
Address:	EAST NEW YORK POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9101572 / 1991-06-10
Facility ID:	9101572
Facility Type:	ER
DER Facility ID:	198131
Site ID:	194912
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1991-05-09
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-05-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-05-15
Spill Record Last Update:	1992-02-12
Spiller Name:	Not reported
Spiller Company:	GETTY S/S ?
Spiller Address:	DAVIS & POST RD.
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/08/91: CONED SAMPLED MATERIAL AND WAS TO SEND RESULTS TO DEC. NO RESULTS WERE RECEIVED. 09/27/95: This is additional information about material spilled from the translation of the old spill file: 1/2 FILM ON WATER."
Remarks:	"NOTICED FILM OF GAS IN MANHOLE 6 FT. DEEP CON ED DOING TESTS WCHD NOTIFIED TODD GHIOSAY TO MEET CON ED"

All Materials:

Site ID:	194912
Operable Unit ID:	955158
Operable Unit:	01
Material ID:	427677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00

MANHOLE # 7278 (Continued) **S102151115**

Oxygenate: Not reported

B22 **JOHN BOWEN GARAGE** **NY Spills** **S102151541**
WSW **176 S. LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
51 ft. **Site 2 of 9 in cluster B**

Relative: **Lower**

Actual: **204 ft.**

SPILLS:

Name:	JOHN BOWEN GARAGE
Address:	176 S. LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9012850 / 1991-05-06
Facility ID:	9012850
Facility Type:	ER
DER Facility ID:	248285
Site ID:	307443
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1991-03-15
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-03-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Fire Department
Cleanup Ceased:	1991-03-26
Cleanup Meets Std:	True
Last Inspection:	1991-03-26
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1991-04-05
Spill Record Last Update:	1995-02-14
Spiller Name:	Not reported
Spiller Company:	VINTON ELLIS
Spiller Address:	2 DENISON ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/06/91: LUZON CLEANED UP AND REMOVED ALL CONTAMINATION. "
Remarks:	"FUEL OIL LEAKING THROUGH THE BACK WALL OF A GARAGE HOMEOWNER NEXT DOOR HAS LONG FILL LINE FROM CURBSIDE WHICH MAY BE LEAKING"

All Materials:

Site ID:	307443
Operable Unit ID:	950188
Operable Unit:	01
Material ID:	429308
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

JOHN BOWEN GARAGE (Continued) **S102151541**

Units: Not reported
Recovered: .00
Oxygenate: Not reported

A23 **WHITE PLAINS HOSPITAL** **NY UST U003917986**
South **41 EAST POST ROAD,** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
53 ft. **Site 15 of 25 in cluster A**

Relative: WESTCHESTER CO. UST:
Higher

Actual:
214 ft.

Name: WHITE PLAINS HOSPITAL
Address: 41 EAST POST ROAD,
City,State,Zip: WHITE PLAINS, NY 10601
Id/Status: 3-177148 / Active
Operator Name: Robert W. Biddiscombe
Owner Name: White Plains Hospital
Owner Street: 41 East Post Road,
Owner Address2: Davis Avenue at East Post Road
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10601
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 20000
Product Stored: 0003. #6 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: 06/01/1984
Date Perm Closure: 10/01/2012
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 2. Underground/on Ground
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 0. None
Overfill Prevention: 5. Vent Whistle
Piping Secondary Containment: Not reported
Spill Prevention: Not reported
Dispenser: 2. Suction

Tank Number: 11
Status: 1. In-Service
Capacity: 15000
Product Stored: 0008. Diesel
Product Stored Percent: Not reported
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 04/01/2013
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection: 3. Fiberglass liner (FRP)

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	4. Fiberglass Coated Steel
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	2
Status:	4. Closed - in place
Capacity:	20000
Product Stored:	0003. #6 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/2013
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	10/01/1998
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	5
Status:	3. Closed - Removed

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	12/01/1995
Date Perm Closure:	12/05/2013
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	5A
Status:	1. In-Service
Capacity:	5000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	12/01/2013
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	4. Fiberglass Coated Steel
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm,5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	Not reported
Date Installation:	05/01/1996
Date Perm Closure:	11/01/2013
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Piping External Protection:	Not reported
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Capacity:	0
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/01/1993
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST ROAD,
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-177148
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Robert W. Biddiscombe
Owner Name:	White Plains Hospital
Owner Street:	41 East Post Road,
Owner Address2:	Davis Avenue at East Post Road
Owner City/State/Zip:	White Plains, NY 10601

Tank Number:	10
Status:	1. In-Service
Date Installation:	06/01/1984
Capacity:	75
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	piped from master tank
Dispenser:	2. Suction

Tank Number:	12
Status:	1. In-Service
Date Installation:	04/01/2013
Capacity:	300
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	ohter
Dispenser:	2. Suction

Tank Number:	13
Status:	1. In-Service
Date Installation:	12/01/2013
Capacity:	250
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	1. Electronic Interstitial Monitoring
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1A
Status:	1. In-Service
Date Installation:	07/15/2011
Capacity:	8000

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Leak Detection:	1. Electronic Interstitial Monitoring,
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	4. Fiberglass
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1D
Status:	1. In-Service
Date Installation:	11/01/2015
Capacity:	660
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	9. Urethane
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	1. Electronic Interstitial Monitoring
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	2D
Status:	1. In-Service
Date Installation:	11/01/2015
Capacity:	250
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Piping External Protection:	0. None
Piping Leak Detection:	1. Electronic Interstitial Monitoring
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3A
Status:	1. In-Service
Date Installation:	10/01/1998
Capacity:	1000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	4
Status:	1. In-Service
Date Installation:	10/01/1998
Capacity:	3800
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	7
Status:	1. In-Service
Date Installation:	10/01/1994

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Capacity:	275
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	pump shut off
Spill Prevention:	piped from master
Dispenser:	2. Suction

Tank Number:	8
Status:	3. Closed - Removed
Date Installation:	06/01/1984
Capacity:	275
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/01/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	piped from master tank
Dispenser:	2. Suction

Tank Number:	9
Status:	3. Closed - Removed
Date Installation:	06/01/1984
Capacity:	150
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	10/01/2015
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground

WHITE PLAINS HOSPITAL (Continued) **U003917986**

Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	piped from master tank
Dispenser:	2. Suction

A24 **WHITE PLAINS HOSPITAL** **NY Spills** **S109581565**
South **41 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
53 ft. **Site 16 of 25 in cluster A**

Relative: **Higher**
Actual: **214 ft.**

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0900120 / 2017-04-04
Facility ID:	0900120
Facility Type:	ER
DER Facility ID:	350007
Site ID:	412037
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A3
SWIS:	6017
Spill Date:	2009-04-03
Investigator:	RDBENDEL
Referred To:	WCDOH
Reported to Dept:	2009-04-03
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2009-04-03
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-04-03
Spill Record Last Update:	2020-08-07
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	EAST BOSTON POST RD
Spiller Company:	999
Contact Name:	AMY DUFFY
DEC Memo:	"4-3-09: Chris/WCHD ^ V.Mc./Dispt.: Brain/WCHD responding to inspect site. 5/27/09: PBS Facility 3-177148. See eDocs. jod 10/7/09 WCHD is getting Monthly reports JO'M 9/21/10: Updates received from Royal Environmental. Royal was hired to remove free product from the sump pit and change out pads as needed. Royal was NOT hired to remove the leaking USTs which are the suspected source of the leak. Between April thru August of 2009, Royal Environmental removed and disposed of a total of 74 drums of contaminted sorbants from the sump, and removed a total of 6,805 gallons of #6 Oil and contaminated water using a vacuum truck. Royal provided a letter from Robert

WHITE PLAINS HOSPITAL (Continued) **S109581565**

Biddiscombe, Director of Engineering for the White Plains Hospital, dated August 12th 2009 and addressed to Chris Lalak of WCDOH which states AKF Engineers will now handle the remediation. Royal has had no further involvement. jod 10/16/12: See letter from Chris Lalak of WCDoH in EDocs. jod 11/16/12: Update from Chris Lalak of WCDoH PBS: Lalak, Chris cjl1@westchestergov.com greater than 10/26/2012 4:01 PM:: Spill 0900120 Todd know about this one. Three years ago 6 oil started getting into the basement of the White Plains Hospital. They went to abandon tank 1 in place a 20 k UST. It cant possibly be removed and hit free product seeping back into the tank. Castlton Broke thru the bottom of the tank and thru a 2 foot thick concrete pad and set up a sump to recover the oil. They are building a second sump and putting the oily water into a holding tank. The spill is a nightmare and the hospital has been slow to act. And they have their own hospital issues about being self sufficient in case of emergencies. The put in a new Large AST and have a temp tank. They also have another 20k that is being removed any day now. -Chris jod 12/19/12: Update from Chris Lalak. The 20K UST is scheduled to be removed tomorrow. Elite Environmental will be doing the work. Several tons of contaminated soil has already been removed. This is the #6 Oil tank. WCDoH will be on site to inspect. jod 10-16-13 another tank at facility being removed, Need and update on this spill. RDB 0402-14 letter from WCHD in edocs RDB 2-27-15 Attached are the samples collected from White Plains Hospital this month. 06-15- june data submitted; checking with WCHD"

Remarks: "3RD PARTY CALL: CALLER STATES THAT THEY FOUND ABOUT 200 GALLONS OF PRODUCT IN THE SUMP PIT UNK IF ANY RESOURCES ARE AFFECTED UNK SOURCE. CLEAN UP IS PENDING."

All Materials:

Site ID:	412037
Operable Unit ID:	1168530
Operable Unit:	01
Material ID:	2160135
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

A25 **WHITE PLAINS HOSPITAL** **NY Spills** **S108466749**
South **41 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
53 ft. **Site 17 of 25 in cluster A**

Relative:
Higher

Actual:
214 ft.

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0613444 / 2007-04-05
Facility ID:	0613444
Facility Type:	ER
DER Facility ID:	65131

WHITE PLAINS HOSPITAL (Continued) **S108466749**

Site ID:	378477
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2007-03-14
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-03-14
CID:	406
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-03-14
Spill Record Last Update:	2007-04-05
Spiller Name:	OSSIE DAHL
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD.
Spiller Company:	001
Contact Name:	OSSIE DAHL
DEC Memo:	"SPOKE WITH DEAN DELPRIONE @ WP HOSPITAL. LEAK IN LINE WAS LOCATED AND HAS BEEN REPAIRED. NO OIL LEFT THE BASEMENT. CASTLETON OIL WAS HIRED TO COMPLETE THE CLEAN UP. CALLED AND LEFT MASSAGE FOR CASTLETON TO RETURN CALL."
Remarks:	"heat exchanger failed... oil was coming out of the condensate line. Spill impacted the floor of the boiler room. Absorbent material has been applied to the spill and Castle Oil is on route for clean up."

All Materials:

Site ID:	378477
Operable Unit ID:	1135981
Operable Unit:	01
Material ID:	2125912
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A26 **WHITE PLAINS HOSPITAL CENTER** **PA MANIFEST** **S118071145**
South **41 POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
53 ft. **Site 18 of 25 in cluster A**

Relative: **Higher**

Actual: **214 ft.**

Manifest Details:

Year:	2018
Manifest Number:	011655631FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	01/30/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D001
Container Number:	2
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	220
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011656895FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	05/30/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592

WHITE PLAINS HOSPITAL CENTER (Continued) **S118071145**

Date TSP Sig:	Not reported
Year:	2018
Manifest Number:	011656894FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	05/30/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	3
Waste Number:	U058
Container Number:	6
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	60
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2018
Manifest Number:	011513710FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	01/16/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P075
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported
Year:	2018

WHITE PLAINS HOSPITAL CENTER (Continued) **S118071145**

Manifest Number:	011655151FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	03/26/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D007
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	350
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011655152FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	03/26/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	2
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011654704FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965

WHITE PLAINS HOSPITAL CENTER (Continued) **S118071145**

Generator Date:	04/13/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D005
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	390
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011656894FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	05/30/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	P001
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	630
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011513709FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	01/16/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

WHITE PLAINS HOSPITAL CENTER (Continued) **S118071145**

Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D005
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Year:	2018
Manifest Number:	011513709FLE
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	01/16/2018
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Republic Environmental Systems (Pennsylvania) LLC
TSD Facility Address:	2869 Sandstone Dr
TSD Facility City:	Hatfield
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	300
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD085690592
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
94 additional PA_MANIFEST: record(s) in the EDR Site Report.

A27
South
< 1/8
0.010 mi.
53 ft.

WHITE PLAINS HOSPITAL MODERNIZATION PROJ.
41 E POST ROAD
WHITE PLAINS, NY 10601

Site 19 of 25 in cluster A

NY Spills **S122262427**
NY SPDES **N/A**

Relative:
Higher

Actual:
214 ft.

SPILLS:

Name:	HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	2003833 / Not Reported
Facility ID:	2003833
Facility Type:	ER
DER Facility ID:	350007
Site ID:	609568
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2020-08-06
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2020-08-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	1
Date Entered In Computer:	2020-08-06
Spill Record Last Update:	2020-08-06
Spiller Name:	Not reported
Spiller Company:	HOSPITAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	JIM INGERSOLL
DEC Memo:	"8/6/20 White Plains Hospital, PBS #3-177148. A 20k-gal #6 Fuel Oil UST was previously closed-in-place in 2013 by Castlton. The hospital says it's Tank #1, but based on PBS record it looks like Tank #2. At the time of closure, a 18 dewatering well was installed and the tank was filled with K-Crete flowable fill. The Hospital is currently doing major construction and their engineering department opened the dewatering well manhole and observed product. There are two sumps within 20 ft and no impact observed in either sump. Bill Jacobson from Castlton is on-site now. They will mobilize a vac truck to remove product and water from the dewatering well, but the Hospital needs to move a lot of equipment first to make room for the vac truck and it might not be accessible until tomorrow. Tank could not be removed because it is beneath foundations of a 5-story and a 6-story building. JG"
Remarks:	"Contained to put...cleanup pending"

All Materials:

Site ID:	609568
Operable Unit ID:	1356720
Operable Unit:	01

WHITE PLAINS HOSPITAL MODERNIZATION PROJ. (Continued) **S122262427**

Material ID:	2368041
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPDES:

Name:	WHITE PLAINS HOSPITAL MODERNIZATION PROJ.
Address:	41 E POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601-
Permit Number:	NYR10U142
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	603423 / 4542380
DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	Construction
Affiliation Type Description:	Not reported
Name:	STEVEN L. GROGG
Contacts Title:	Not reported
Contacts Email:	Not reported
NOI Submission Date:	04/05/2011

A28
South
< 1/8
0.010 mi.
53 ft.

WHITE PLAINS HOSPITAL CENTER
41 POST ROAD
WHITE PLAINS, NY 10601

Site 20 of 25 in cluster A

PA MANIFEST **S110049528**
N/A

Relative:
Higher

Actual:
214 ft.

Manifest Details:

Year:	2013
Manifest Number:	011621093JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/02/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U151
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012168408JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	10/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	40
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822

WHITE PLAINS HOSPITAL CENTER (Continued) **S110049528**

Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	011621093JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/02/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	15
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported
Year:	2013
Manifest Number:	011607258JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/09/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	75
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported
Year:	2013

WHITE PLAINS HOSPITAL CENTER (Continued) **S110049528**

Manifest Number:	012168417JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	10/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	D009
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	011607258JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/09/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U151
Container Number:	3
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	75
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012168417JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965

WHITE PLAINS HOSPITAL CENTER (Continued) **S110049528**

Generator Date:	10/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U151
Container Number:	1
Container Type:	Fiberboard or plastic drums, barrels, kegs
Waste Quantity:	1
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2013
Manifest Number:	012168417JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	10/04/2013
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	Not reported
TSD Date:	Not reported
TSD Facility Name:	Cycle Chem Inc
TSD Facility Address:	550 Industrial Rd
TSD Facility City:	Lewisberry
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D009
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	150
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	PAD067098822
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	003535759JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported

WHITE PLAINS HOSPITAL CENTER (Continued) **S110049528**

Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	1
Waste Number:	U188
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	55
Unit:	Gallons (liquids only)
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Year:	2008
Manifest Number:	003535759JJK
Manifest Type:	TSD Copy
Generator EPA Id:	NYR000129965
Generator Date:	08/27/2008
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact Name:	Not reported
Contact Phone:	914-681-0600
TSD EPA Id:	PAD067098822
TSD Date:	Not reported
TSD Facility Name:	CYCLE CHEM INC
TSD Facility Address:	550 INDUSTRIAL DRIVE
TSD Facility City:	LEWISBERRY
TSD Facility State:	PA
Facility Telephone:	Not reported
Page Number:	1
Line Number:	2
Waste Number:	D009
Container Number:	1
Container Type:	Metal drums, barrels, kegs
Waste Quantity:	5
Unit:	Pounds
Handling Code:	Not reported
TSP EPA Id:	Not reported
Date TSP Sig:	Not reported

Click this hyperlink while viewing on your computer to access
5 additional PA_MANIFEST: record(s) in the EDR Site Report.

A29 **WHITE PLAINS HOSPITAL** **RCRA-LQG** **1007881071**
South **41 E POST RD** **NYR000129965**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
53 ft. **Site 21 of 25 in cluster A**

Relative: **Higher**
Actual: **214 ft.**

RCRA-LQG:

Date Form Received by Agency:	2016-05-19 00:00:00.0
Handler Name:	WHITE PLAINS HOSPITAL
Handler Address:	41 E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000129965
Contact Name:	RAMO RIZVANI
Contact Address:	E POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	914-681-1095
Contact Fax:	914-681-2895
Contact Email:	RRIZVANI@WPHOSPITAL.ORG
Contact Title:	DIRECTOR OF ENVIRONMENTAL SERVICES
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Large Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	2015
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	E POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	WHITE PLAINS HOSPITAL
Owner Type:	Private
Operator Name:	WHITE PLAINS HOSPITAL
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	Yes
Universal Waste Destination Facility:	Yes
Federal Universal Waste:	Yes
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-11-07 13:10:02.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Biennial: List of Years
Year: 2015

Click Here for Biennial Reporting System Data:
Year: 2013

Click Here for Biennial Reporting System Data:

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D022
Waste Description: CHLOROFORM

Waste Code: D024
Waste Description: M-CRESOL

Waste Code: F003
Waste Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: P001
Waste Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P075
Waste Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Waste Code: P188
Waste Description: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL-5-YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

Waste Code: P204
Waste Description: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

Waste Code: U010
Waste Description: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METHOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

Waste Code: U035
Waste Description: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

Waste Code: U058
Waste Description: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

Waste Code: U129
Waste Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA,

WHITE PLAINS HOSPITAL (Continued) **1007881071**

5ALPHA, 6BETA)- (OR) LINDANE

Waste Code: U150
Waste Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U151
Waste Description: MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	1900-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 EAST POST ROAD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-0600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	2005-01-05 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	2005-01-05 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	1993-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	1900-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 EAST POST ROAD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	1900-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	2005-01-05 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	1900-06-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-0600
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WHITE PLAINS HOSPITAL
Legal Status:	Private
Date Became Current:	2005-01-05 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	41 POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-681-6000
Owner/Operator Telephone Ext:	Not reported

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: WHITE PLAINS HOSPITAL
Legal Status: Private
Date Became Current: 1993-06-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2014-03-11 00:00:00.0
Handler Name: WHITE PLAINS HOSPITAL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: Yes
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2016-05-19 00:00:00.0
Handler Name: WHITE PLAINS HOSPITAL
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: Yes
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2006-01-01 00:00:00.0
Handler Name: WHITE PLAINS HOSPITAL CENTER
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2007-01-01 00:00:00.0
Handler Name: WHITE PLAINS HOSPITAL CENTER

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2005-01-07 00:00:00.0
Handler Name:	WHITE PLAINS HOSPITAL CENTER
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-07-24 00:00:00.0
Handler Name:	WHITE PLAINS HOSPITAL CENTER
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	62211
NAICS Description:	GENERAL MEDICAL AND SURGICAL HOSPITALS

NAICS Code:	81392
NAICS Description:	PROFESSIONAL ORGANIZATIONS

Facility Has Received Notices of Violation:

Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	2012-06-07 00:00:00.0
Actual Return to Compliance Date:	2012-06-07 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	2012-06-12 00:00:00.0
Enforcement Responsible Agency:	State

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 2012-06-12 00:00:00.0
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Found Violation: Yes
Agency Which Determined Violation: State
Violation Short Description: Universal Waste - Small Quantity Handlers
Date Violation was Determined: 2012-06-07 00:00:00.0
Actual Return to Compliance Date: 2012-06-07 00:00:00.0
Return to Compliance Qualifier: Observed
Violation Responsible Agency: State
Scheduled Compliance Date: Not reported
Enforcement Identifier: 001
Date of Enforcement Action: 2012-06-12 00:00:00.0
Enforcement Responsible Agency: State
Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: No
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: 2012-06-12 00:00:00.0
Disposition Status: AS
Disposition Status Description: ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: WRITTEN INFORMAL
Enforcement Responsible Person: NYWME
Enforcement Responsible Sub-Organization: R3
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported

WHITE PLAINS HOSPITAL (Continued) **1007881071**

SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	Yes
Agency Which Determined Violation:	State
Violation Short Description:	Universal Waste - Small Quantity Handlers
Date Violation was Determined:	2012-06-07 00:00:00.0
Actual Return to Compliance Date:	2012-06-07 00:00:00.0
Return to Compliance Qualifier:	Observed
Violation Responsible Agency:	State
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	001
Date of Enforcement Action:	2012-06-12 00:00:00.0
Enforcement Responsible Agency:	State
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	No
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	2012-06-12 00:00:00.0
Disposition Status:	AS
Disposition Status Description:	ACTION SATISFIED (CASE CLOSED)
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	WRITTEN INFORMAL
Enforcement Responsible Person:	NYWME
Enforcement Responsible Sub-Organization:	R3
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported
Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Enforcement Docket Number: Not reported
Enforcement Attorney: Not reported
Corrective Action Component: Not reported
Appeal Initiated Date: Not reported
Appeal Resolution Date: Not reported
Disposition Status Date: Not reported
Disposition Status: Not reported
Disposition Status Description: Not reported
Consent/Final Order Sequence Number: Not reported
Consent/Final Order Respondent Name: Not reported
Consent/Final Order Lead Agency: Not reported
Enforcement Type: Not reported
Enforcement Responsible Person: Not reported
Enforcement Responsible Sub-Organization: Not reported
SEP Sequence Number: Not reported
SEP Expenditure Amount: Not reported
SEP Scheduled Completion Date: Not reported
SEP Actual Date: Not reported
SEP Defaulted Date: Not reported
SEP Type: Not reported
SEP Type Description: Not reported
Proposed Amount: Not reported
Final Monetary Amount: Not reported
Paid Amount: Not reported
Final Count: Not reported
Final Amount: Not reported

Evaluation Action Summary:
Evaluation Date: 2012-06-07 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 2012-06-07 00:00:00.0
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 2012-06-07 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: Yes
Evaluation Type Description: COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier: NYWME
Evaluation Responsible Sub-Organization: R3
Actual Return to Compliance Date: 2012-06-07 00:00:00.0
Scheduled Compliance Date: Not reported
Date of Request: Not reported
Date Response Received: Not reported
Request Agency: Not reported
Former Citation: Not reported

Evaluation Date: 2012-06-07 00:00:00.0
Evaluation Responsible Agency: State
Found Violation: Yes

WHITE PLAINS HOSPITAL (Continued) **1007881071**

Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYWME
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	2012-06-07 00:00:00.0
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported
Evaluation Date:	2017-04-27 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYWME
Evaluation Responsible Sub-Organization:	R3
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

A30 **WHITE PLAINS HOSPITAL** **NY Spills** **S102153061**
South **41 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
53 ft. **Site 22 of 25 in cluster A**

Relative: **Higher**

Actual: **214 ft.**

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8800316 / 1988-05-03
Facility ID:	8800316
Facility Type:	ER
DER Facility ID:	350007
Site ID:	276877
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	1988-04-11
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Fire Department
Cleanup Ceased:	1988-05-03
Cleanup Meets Std:	True
Last Inspection:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S102153061**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2013-05-30
Spiller Name:	Not reported
Spiller Company:	HERTZ-PENSKY
Spiller Address:	RT 10 GREENHILLS RD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER "
Remarks:	"BACKED INTO LOADING PLATFORM RIPPED OPEN SADDLE TANK AREA HAS BEEN SANDED SOME INTO STORM DRAIN W.C.H.D. HANDLEING N.F.A."

All Materials:

Site ID:	276877
Operable Unit ID:	917152
Operable Unit:	01
Material ID:	463029
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A31 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S104513751**
South **41 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.010 mi.
53 ft. **Site 23 of 25 in cluster A**

Relative:
Higher

Actual:
214 ft.

LTANKS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9414693 / 1995-02-13
Facility ID:	9414693
Site ID:	68377
Spill Date:	1995-02-08
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1995-02-13
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-02-08
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

WHITE PLAINS HOSPITAL (Continued) **S104513751**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	HESS OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	65131
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER WAS TOLD BY HOSPITAL ENGINEER TO OFF LOAD 6000 GALS. OF #6 FUEL OIL INTO TANK TANK IS SUPPOSED TO HOLD 20000 GALS TANK VENTED & SPILLED ABOUT 50 GAL CREW CLEANED UP"

All Materials:

Site ID:	68377
Operable Unit ID:	1012229
Operable Unit:	01
Material ID:	373425
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

A32 **WHITE PLAINS HOSPITAL CENTER** **NY LTANKS** **S104284805**
South **41 POST RD** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.010 mi.
53 ft. **Site 24 of 25 in cluster A**

Relative:
Higher

Actual:
214 ft.

LTANKS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1107393 / 2011-10-31
Facility ID:	1107393
Site ID:	455090
Spill Date:	2011-09-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-09-12
CID:	Not reported
Water Affected:	Not reported

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-09-12
Spill Record Last Update:	2011-10-31
Spiller Name:	BOB
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD
Spiller County:	999
Spiller Contact:	STEPHANIE EAGANS
Spiller Phone:	(845) 528-0370
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	350007
DEC Memo:	"9/12/11- Elite reports failure was below product level. Tank also failed previous test- 1105346. Elite reports that Todd ghiosay and WCHD are involved with site. DT >>> Lalak, Chris 9/12/2011 2:32 PM >>> I am dealing with this site. I have asked them to empty the tank immediately. (product was present in the tank top sump) There is also an old open spill with oil getting into the basement from their other UST. jod 10/31/11: Update received from Chris Lalak of WCDoH: 1107393 NFA WP Hospital (see 1105346 open) jod"
Remarks:	"Failed Tank Test"

All Materials:

Site ID:	455090
Operable Unit ID:	1205238
Operable Unit:	01
Material ID:	2202084
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0803913 / 2008-07-07
Facility ID:	0803913
Facility Type:	ER
DER Facility ID:	350007
Site ID:	400727
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-07-03
Investigator:	mbmastro

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Referred To:	Not reported
Reported to Dept:	2008-07-03
CID:	406
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-07-03
Spill Record Last Update:	2008-07-22
Spiller Name:	DISP 603 CEPIN
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD.
Spiller Company:	001
Contact Name:	DISP 603 CEPIN
DEC Memo:	"FD did cleanup, hospital crew will have speedi-dri material disposed of. - NFA"
Remarks:	"Material was released from the elevator into the parking structure. Spill is contained. Absorbent material was applied unknown who is completing clean up."

All Materials:

Site ID:	400727
Operable Unit ID:	1157541
Operable Unit:	01
Material ID:	2148564
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0504642 / 2006-05-23
Facility ID:	0504642
Facility Type:	ER
DER Facility ID:	65131
Site ID:	349576
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6017
Spill Date:	2005-07-18
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	2005-07-18
CID:	38
Water Affected:	Not reported

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-20
Spill Record Last Update:	2006-05-26
Spiller Name:	DAHL, OSSIE
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	41 EAST POST RD
Spiller Company:	001
Contact Name:	DAHL, OSSIE
DEC Memo:	"amount of oil is minimal, slight sheen on water, being cleaned up - nfa"
Remarks:	"Flooding in basement caused residual oil in basement area to mix w/ water. Cleanup is being done by northeast environmental and tradewinds will be responding later."

All Materials:

Site ID:	349576
Operable Unit ID:	1107165
Operable Unit:	01
Material ID:	2097060
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9910974 / 2005-01-02
Facility ID:	9910974
Facility Type:	ER
DER Facility ID:	65131
Site ID:	149038
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1999-12-15
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	1999-12-15
CID:	246
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-12-15
Spill Record Last Update:	2019-11-07
Spiller Name:	UNKNOWN
Spiller Company:	Unknown
Spiller Address:	UNKNOWN
Spiller Company:	999
Contact Name:	SCOTT WILLIAMS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 1/2/05 report that there was a 12 gallon overfill of #6 oil during delivery--close "
Remarks:	"driver making a fuel delivery-a possible broken fill line caused material to come up from ground beneath fill hole. spill contained and being investigated in am."

All Materials:

Site ID:	149038
Operable Unit ID:	1089666
Operable Unit:	01
Material ID:	296448
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	12.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITE PLAINS HOSPITAL
Address:	41 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1105346 / 2017-04-04
Facility ID:	1105346
Facility Type:	ER
DER Facility ID:	350007
Site ID:	452999
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2011-08-10
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2011-08-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2011-08-10
Recommended Penalty:	False
UST Trust:	False

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Remediation Phase:	0
Date Entered In Computer:	2011-08-10
Spill Record Last Update:	2017-04-04
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	STEPHANIE EAGENS
DEC Memo:	"8/10/11 - During a tank test of a 20K UST, No. 6 fuel oil was discovered in the sump. Caller is scheduling for 8/11/11: I responded to the location yesterday. I first checked outfall at Bronx River and no oil or sheen was noted. I spoke with Ray Hilyer, Elite was scheduled to test the tank last week and did not after finding an uncapped feed line. Ray states he notified WCDOH Wayne Schneider. Elite returned yesterday and found a large quantitiy of #6 Oil in a manway sump next to the UST. I met with Hospital Engineer Bob Biddiscombe and observed the oil in the sump. He states it is contained within the secondary containment and stated Elite was en route to vac it out. I again contacted Elite, they have not been hired. Bob Biddiscombe spoke with Elite via phone directly while I was there. Elite will be there first thing in the morning. No oil was observed in the basement sump where previous major spills have occurred. Mr Biddiscombe stated the sump has been re-piped, and now discharges to the sanitary sewer instead of the storm drain. WCDOH will follow up. Chris Lalak is enroute this morning to confirm the sump has been vacuumed out and investigation will continue. jod *Chris Lalak reports that the manway has still not been vacuumed out this morning. Email update from Chris: Lalak, Chris 8/11/2011 11:52 AM They still didn't pump it out Robert Biddiscombe was going to call Elite or Island pump and tank to get it pumped. He doesn't know if it is a contained sump. I gave him 1 week to TT tank and lines. 1 month for env. Investigation and. pump it out today and check daily. I also stated if it is visually found that the sump is leaking an immediate investigation is needed. jod 8/12/11: Chris Lalak reports Envirowaste completed pump out. Further investigation required. jod 10/16/12: See letter from Chris Lalak of WCDoH in EDocs. jod 5/30/13: Report from Elite dated Jan 14th 2013 entered into Edocs. Message sent to Chris Lalak requesting status report. jod 040417- Email, This spill started on 2009 with 6 oil entering a basement Sump. The sump apparently collects water the buildings footing drains. White Plains hospital is a huge urban hospital complex, occupying a full city block. The spill was determined to be from piping leaks associate with two old 6 oil tanks. Tank 1 (20K ust was abandoned in place by Castlton). Removal of this tank was not possible. Free product was encountered around this tank. Castlton installed a monitoring/recovery well thru the tank. The well is identified as 15 . Free product was recovered from the well, into a holding tank. The well was then sampled 4 times 2014/2015. Some minor volatile and semi-volatiles are still present. The highest is 29 PPB pyrene. MW number 4 is located next to the abandoned tank and was sampled at the same time and was essentially clean. Tank 2 was removed by Elite. (the other old 20K UST) Royal remediated the sump for approximately 2 years.(2009-2010) Hydro Environmental Technologies (HETI) performed a GW monitoring investigation in 2012. The Hospital has been cooperatively remediating a very difficult spill. No oil has been found in the sump since 2013. The monitoring/recovery well installed thru the 20 K 6 oil UST, (and thru the concrete Pads) has been substantially

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

remediated. Pristine remediation is not possible in this case. Well sampling performed by Castlton in 2014 and 2015 is attached. The hospital is located in an urban city with no drinking water wells near by. The abandoned UST has been filled in with slurry Concrete except for the recovery well. It could not be removed. NFA- RDB "

Remarks: "sump is full of oil/investigation underway"

All Materials:

Site ID:	452999
Operable Unit ID:	1203158
Operable Unit:	01
Material ID:	2199776
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	WHITE PLAINS HOSPITAL CENTER
Address:	41 POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYR000129965
Facility Status:	Not reported
Location Address 1:	41 E. POST ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000129965
Mailing Name:	WHITE PLAINS HOSPITAL CENTER
Mailing Contact:	LISA SILVER
Mailing Address 1:	41 POST ROAD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146810600

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	MAD985286988

WHITE PLAINS HOSPITAL CENTER (Continued) **S104284805**

Trans2 State ID:	Not reported
Generator Ship Date:	12/26/2006
Trans1 Recv Date:	12/26/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/27/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000129965
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001020237JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	120
Units:	P - Pounds
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D001
Waste Code 1_2:	F003
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

A33 **WHITE PLAINS HOSPITAL** **NJ MANIFEST** **S120678766**
South **41 POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
53 ft. **Site 25 of 25 in cluster A**

Relative: NJ MANIFEST:
Higher

EPA Id:	NYR000129965
Mail Address:	POST RD
Mail City/State/Zip:	WHITE PLAINS, NY 10601
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GARY REUSENBERGER
Comments:	Not reported

Actual:
214 ft.

WHITE PLAINS HOSPITAL (Continued) **S120678766**

SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015029095JJK
EPA ID:	NYR000129965
Date Shipped:	9/22/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	007790784FLE
EPA ID:	NYR000129965
Date Shipped:	2/3/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	015668850JJK
EPA ID:	NYR000129965
Date Shipped:	3/8/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	PAD982661381
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	010602022FLE
EPA ID:	NYR000129965
Date Shipped:	3/1/2017
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported
Manifest Number:	004716845JJK
EPA ID:	NYR000129965
Date Shipped:	04/03/2009
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	TXR000050930
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	04/03/2009
Date Trans2 Transported Waste:	04/09/2009
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	04/09/2009
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	315 P

Manifest Number:	012168416JJK
EPA ID:	NYR000129965
Date Shipped:	10/4/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 D024 U058 U010 U129
Hand Code:	Not reported
Quantity:	400.00 Pounds

Manifest Number:	015542890JJK
EPA ID:	NYR000129965
Date Shipped:	1/11/2016
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	007879693JJK
EPA ID:	NYR000129965
Date Shipped:	8/2/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 D018
Hand Code:	Not reported
Quantity:	30.00 gallons

Manifest Number:	009055880FLE
EPA ID:	NYR000129965
Date Shipped:	2/2/2016
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	015019031JJK
EPA ID:	NYR000129965

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Shipped:	8/11/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	014687963JJK
EPA ID:	NYR000129965
Date Shipped:	6/16/2015
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Manifest Number:	008788090FLE
EPA ID:	NYR000129965
Date Shipped:	9/8/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported
Manifest Number:	008017220FLE
EPA ID:	NYR000129965
Date Shipped:	6/2/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported
Manifest Number:	011621088JJK
EPA ID:	NYR000129965
Date Shipped:	8/2/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 D024 U010 U058 U129
Hand Code:	Not reported
Quantity:	325.00 Pounds

Manifest Number:	006629093FLE
EPA ID:	NYR000129965
Date Shipped:	9/27/2013
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001 F003
Hand Code:	Not reported
Quantity:	270.00 Pounds

Manifest Number:	003748817JJK
EPA ID:	NYR000129965
Date Shipped:	06/30/2008
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD985286988
Transporter 2 EPA ID:	TXR000050930
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/30/2008
Date Trans2 Transported Waste:	07/10/2008
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/10/2008
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D001
Hand Code:	H061
Quantity:	360 P

Manifest Number:	008018498FLE
EPA ID:	NYR000129965
Date Shipped:	8/4/2015
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Reason Load Was Rejected:	Not reported
Manifest Number:	011009899FLE
EPA ID:	NYR000129965
Date Shipped:	1/12/2018
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
Generator EPA Facility Name:	WHITE PLAINS HOSPITAL
Transporter-1 EPA Facility Name:	CLEAN HARBORS ENVIRONMENTAL SRVS INC
TSDF EPA Facility Name:	SAFETY KLEEN SYSTEMS INC
QTY Units:	Pounds
Transporter SEQ ID:	Not reported
Transporter-1 Date:	1/12/2018
Waste SEQ ID:	1
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	1/18/2018
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported
Manifest Number:	010982671JJK
EPA ID:	NYR000129965
Date Shipped:	5/7/2013
TSDF EPA ID:	NJD980536593
Transporter EPA ID:	NJR000063677
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	P001 P075 P188 P204
Hand Code:	Not reported
Quantity:	2.00 Pounds

Manifest Year:	Not reported
Waste Code:	D001 D005 D024 U058 U150
Hand Code:	Not reported
Quantity:	75.00 Pounds

Manifest Number:	010507475FLE
EPA ID:	NYR000129965
Date Shipped:	1/30/2017
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	MAD039322250
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S120678766**

Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10601
Reason Load Was Rejected:	Not reported

B34 **SWANK DRY CLEANERS** **RCRA NonGen / NLR** **1000551513**
West **168 S LEXINGTON AVE** **FINDS** **NYD986938553**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.010 mi. **NY MANIFEST**
53 ft. **Site 3 of 9 in cluster B**

Relative: **Lower**
Actual: **204 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	SWANK DRY CLEANERS
Handler Address:	168 S LEXINGTON AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10606-2510
EPA ID:	NYD986938553
Contact Name:	Not reported
Contact Address:	S LEXINGTON AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	S LEXINGTON AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	THOMAS SCOTT
Owner Type:	Private
Operator Name:	THOMAS SCOTT

SWANK DRY CLEANERS (Continued) **1000551513**

Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

SWANK DRY CLEANERS (Continued) **1000551513**

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

Waste Code: F002
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: THOMAS SCOTT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 168 S LEXINGTON AVE
Owner/Operator City,State,Zip: WHITE PLAINS, NY 10601
Owner/Operator Telephone: 914-761-8137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THOMAS SCOTT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 168 S LEXINGTON AVE
Owner/Operator City,State,Zip: WHITE PLAINS, NY 10601
Owner/Operator Telephone: 914-761-8137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: THOMAS SCOTT
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 168 S LEXINGTON AVE
Owner/Operator City,State,Zip: WHITE PLAINS, NY 10601
Owner/Operator Telephone: 914-761-8137
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 1999-07-08 00:00:00.0
Handler Name: SWANK DRY CLEANERS
Federal Waste Generator Description: Not a generator, verified

SWANK DRY CLEANERS (Continued) **1000551513**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	SWANK DRY CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	SWANK DRY CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1991-02-01 00:00:00.0
Handler Name:	SWANK DRY CLEANERS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

SWANK DRY CLEANERS (Continued) **1000551513**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004459773

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000551513
Registry ID:	110004459773
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004459773
Name:	SWANK DRY CLEANERS
Address:	168 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	SWANK CLEANERS
Address:	168 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10606-2510
Country:	USA
EPA ID:	NYD986938553
Facility Status:	Not reported
Location Address 1:	168 SOUTH LEXINGTON AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986938553
Mailing Name:	SWANK CLEANERS
Mailing Contact:	BOBBY MURPHY
Mailing Address 1:	168 SOUTH LEXINGTON AVENUE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9147618137

SWANK DRY CLEANERS (Continued) **1000551513**

NY MANIFEST:

Document ID:	NYC0616904
Manifest Status:	K
seq:	Not reported
Year:	1991
Trans1 State ID:	NJDEPS869
Trans2 State ID:	AV4489NY
Generator Ship Date:	04/03/1991
Trans1 Recv Date:	04/03/1991
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/03/1991
Part A Recv Date:	06/10/1991
Part B Recv Date:	04/12/1991
Generator EPA ID:	NYD986938553
Trans1 EPA ID:	ILD051060408
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708172
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00070
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

B35 **CILIM CLEANERS CORP** **EDR Hist Cleaner** **1018495151**
West **168 S LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.010 mi.
53 ft. **Site 4 of 9 in cluster B**

Relative: EDR Hist Cleaner
Lower

Actual: **204 ft.**

Year:	Name:	Type:
1971	SWANK DRIVE IN SERVICE CORP	Drycleaning Plants, Except Rugs
1972	SWANK DRIVE IN SERVICE CORP	Drycleaning Plants, Except Rugs
1973	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1974	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs

CILIM CLEANERS CORP (Continued) **1018495151**

1975	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1976	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1977	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1978	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1979	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1980	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1982	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1983	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1985	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1986	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1987	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1988	NEW SWANK CLEANERS AND LAUNDRI	Drycleaning Plants, Except Rugs
1988	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1989	NEW SWANK CLEANERS AND LAUNDRI	Drycleaning Plants, Except Rugs, NEC
1989	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1989	SWANK CLEANERS	Garment Pressing And Cleaners' Agents
1990	NEW SWANK DRY CLEANERS & LAUDN	Coin-Operated Laundries And Cleaning
1990	NEW SWANK CLEANERS AND LAUNDRI	Drycleaning Plants, Except Rugs, NEC
1990	SWANK CLEANERS	Garment Pressing And Cleaners' Agents
1996	DINGLE JOHN	Drycleaning Plants, Except Rugs
1997	DINGLE JOHN	Drycleaning Plants, Except Rugs

B36 **BRIGHT SIDE CLEANERS** **RCRA NonGen / NLR** **1000789846**
WSW **182 S LEXINGTON AVE** **FINDS** **NYD987013109**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.013 mi. **NY MANIFEST**
67 ft. **Site 5 of 9 in cluster B**

Relative: **Lower**
Actual: **204 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	BRIGHT SIDE CLEANERS
Handler Address:	182 S LEXINGTON AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10606-2510
EPA ID:	NYD987013109
Contact Name:	Not reported
Contact Address:	S LEXINGTON AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	S LEXINGTON AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	FLO TALBERT
Owner Type:	Private
Operator Name:	FLO TALBERT
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No

BRIGHT SIDE CLEANERS (Continued) **1000789846**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:
Waste Code: F002

BRIGHT SIDE CLEANERS (Continued) **1000789846**

Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	FLO TALBERT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FLO TALBERT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FLO TALBERT
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, NY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	BRIGHT SIDE CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

BRIGHT SIDE CLEANERS (Continued) **1000789846**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2006-01-01 00:00:00.0
Handler Name: BRIGHT SIDE CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2007-01-01 00:00:00.0
Handler Name: BRIGHT SIDE CLEANERS
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1992-08-28 00:00:00.0
Handler Name: BRIGHT SIDE CLEANERS
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:

BRIGHT SIDE CLEANERS (Continued) **1000789846**

Registry ID: 110004494413

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000789846
Registry ID:	110004494413
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004494413
Name:	BRIGHT SIDE CLEANERS
Address:	182 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	BRIGHT SIDE CLEANERS
Address:	182 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10606-2510
Country:	USA
EPA ID:	NYD987013109
Facility Status:	Not reported
Location Address 1:	182 S LEXINGTONAVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD987013109
Mailing Name:	BRIGHT SIDE CLEANERS
Mailing Contact:	FLORINA TALBERT
Mailing Address 1:	182 S LEXINGTON AVE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149464787

NY MANIFEST:

Document ID:	NYC6929796
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	NYDW9495

BRIGHT SIDE CLEANERS (Continued) **1000789846**

Trans2 State ID:	T22L8DNJ
Generator Ship Date:	11/11/2002
Trans1 Recv Date:	11/11/2002
Trans2 Recv Date:	11/13/2002
TSD Site Recv Date:	11/14/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD987013109
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	NJD071629976
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00360
Units:	P - Pounds
Number of Containers:	006
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00780
Units:	P - Pounds
Number of Containers:	004
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

B37 **BRIGHT SIDE CLEANERS** **EDR Hist Cleaner** **1019943369**
WSW **182 S LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10606**
0.013 mi.
67 ft. **Site 6 of 9 in cluster B**

Relative: EDR Hist Cleaner
Lower

Actual:
204 ft.

Year:	Name:	Type:
1976	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1977	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1978	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1979	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1979	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1980	SILVERMANS CLEANERS INC	Drycleaning Plants, Except Rugs
1982	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1983	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1985	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1986	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1987	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1988	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1989	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1990	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1991	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1992	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1993	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1994	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1995	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1996	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1997	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1998	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
1999	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2000	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2001	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2002	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2003	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2004	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2005	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2006	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2007	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs
2008	BRIGHT SIDE CLEANERS	Drycleaning Plants, Except Rugs

C38 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S101658669**
SW **EAST NEW YORK POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.014 mi.
72 ft. **Site 7 of 23 in cluster C**

Relative: LTANKS:
Lower

Actual:
209 ft.

Name:	WHITE PLAINS HOSPITAL
Address:	EAST NEW YORK POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9506062 / 2005-01-02
Facility ID:	9506062
Site ID:	240948
Spill Date:	1995-08-15
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S101658669**

SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-08-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2005-01-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	198131
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 1/5/05--this was not a confirmed spill (was tank test failure in 2000 gal diesel tank for emergency generator); plan was to remove and replace tank-- would be handled as pbs matter whether removed or not--close "
Remarks:	"BELIEVE TANK WILL BE PULLED & REPLACED TANK WAS PREVIOUSLY FAILED BY SOMEONE ELSE TANK ONLY TEST"

All TTF:

Facility ID:	9506062
Spill Number:	9506062
Spill Tank Test:	1544090
Site ID:	240948
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	240948
Operable Unit ID:	1016961
Operable Unit:	01
Material ID:	364045
Material Code:	0008
Material Name:	diesel

WHITE PLAINS HOSPITAL (Continued) **S101658669**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

B39 **CON EDISON MANHOLE: 9169** **RCRA NonGen / NLR** **1016960489**
WSW **S LEXINGTON AVE & DENNISON ST** **NY MANIFEST** **NYP004324869**
< 1/8 **WHITE PLAINS, NY 10605**
0.014 mi.
74 ft. **Site 7 of 9 in cluster B**

Relative: **Lower**
Actual: **205 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-08-04 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 9169
Handler Address:	S LEXINGTON AVE & DENNISON ST
Handler City,State,Zip:	WHITE PLAINS, NY 10605
EPA ID:	NYP004324869
Contact Name:	DOMINIC BIZZARO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

CON EDISON MANHOLE: 9169 (Continued) **1016960489**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-07-04 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 9169
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-08-04 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 9169

CON EDISON MANHOLE: 9169 (Continued) **1016960489**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	S LEXINGTON AVE & DENNISON ST
City,State,Zip:	WHITE PLAINS, NY 10605
Country:	USA
EPA ID:	NYP004324869
Facility Status:	Not reported
Location Address 1:	WS SO LEXINGTON AVE NO DENISON ST
Code:	BP
Location Address 2:	MH #9169
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004324869
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported

CON EDISON MANHOLE: 9169 (Continued) **1016960489**

Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/04/2013
Trans1 Recv Date:	07/04/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/10/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004324869
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693256JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

B40 **MANHOLE 9169** **NY Spills** **S104194737**
WSW **SO LEXINGTON AVE/DENISON** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.014 mi.
76 ft. **Site 8 of 9 in cluster B**

Relative: SPILLS:
Lower

Actual: Name:	MANHOLE 9169
205 ft. Address:	SO LEXINGTON AVE/DENISON
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9906715 / 1999-09-06
Facility ID:	9906715
Facility Type:	ER

MANHOLE 9169 (Continued) **S104194737**

DER Facility ID:	208757
Site ID:	254861
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-09-06
Investigator:	VPMCCABE
Referred To:	Not reported
Reported to Dept:	1999-09-06
CID:	382
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-06
Spill Record Last Update:	1999-09-07
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BILL MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MCCABE "
Remarks:	"OIL SPILL ON 500 GALS OF WATER CONTAINED IN MANHOLE. CLEAN UP PENDING LAB RESULTS. CON ED 127-610"

All Materials:

Site ID:	254861
Operable Unit ID:	1081051
Operable Unit:	01
Material ID:	299437
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C41 **WHITE PLAINS HOSPITAL** **NY Spills** **S106007754**
SSW **DAVIS AVE & EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.015 mi.
77 ft. **Site 8 of 23 in cluster C**

Relative: **Lower**

Actual: **210 ft.**

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	DAVIS AVE & EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206489 / 2003-10-29

WHITE PLAINS HOSPITAL (Continued) **S106007754**

Facility ID:	0206489
Facility Type:	ER
DER Facility ID:	174910
Site ID:	78704
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	6017
Spill Date:	2001-11-14
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-23
CID:	207
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-23
Spill Record Last Update:	2003-10-29
Spiller Name:	LES HORRELL
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	DAVIS AVE & EAST POST RD
Spiller Company:	001
Contact Name:	LES HORRELL
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - BECK 10/29/03 CLOSED BY WCHD - CLEAN UP COMPLETED"
Remarks:	"<1 oz spilled - cleaned up partially"

All Materials:

Site ID:	78704
Operable Unit ID:	858093
Operable Unit:	01
Material ID:	517094
Material Code:	0031A
Material Name:	mercury
Case No.:	07439976
Material FA:	Hazardous Material
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D42 **STAR DINER ROOFTOP** **NY Spills** **S102153333**
ENE **66 1/2 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.015 mi.
81 ft. **Site 1 of 5 in cluster D**

Relative: **Higher**
Actual: **216 ft.**

SPILLS:

Name:	STAR DINER ROOFTOP
Address:	66 1/2 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY

STAR DINER ROOFTOP (Continued) **S102153333**

Spill Number/Closed Date:	8808788 / 1989-02-10
Facility ID:	8808788
Facility Type:	ER
DER Facility ID:	103265
Site ID:	118842
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1989-02-09
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	1989-02-09
Cleanup Meets Std:	True
Last Inspection:	1989-02-09
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was T. GHIOSAY 11/29/95: This is additional information about material spilled from the translation of the old spill file: VIALS OF BLOOD."
Remarks:	"5 VIALS OF BLOOD FOUND ON ROOFTOP. AMBULENCE SERVICE BEHIND BLDG. AND NEXT TO METHYDONE CLINIC. 1 BLOCK FROM WPS HOSPITAL. CESARE TO CONTACT BECI. NFA"

All Materials:

Site ID:	118842
Operable Unit ID:	925191
Operable Unit:	01
Material ID:	453554
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

B43 **APARTMENT BLDG** **NY Spills** **S120700630**
West **159 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.018 mi.
97 ft. **Site 9 of 9 in cluster B**

Relative:
Lower

Actual:
202 ft.

SPILLS:

Name:	APARTMENT BLDG
Address:	159 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1610459 / 2017-02-21
Facility ID:	1610459
Facility Type:	ER
DER Facility ID:	495047
Site ID:	541288
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	D4
SWIS:	6017
Spill Date:	2017-02-20
Investigator:	DXTRAVER
Referred To:	Not reported
Reported to Dept:	2017-02-20
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	Not reported
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-02-20
Spill Record Last Update:	2017-02-21
Spiller Name:	RODNEY PERSON
Spiller Company:	WHITE PLAINS SEWER LINE
Spiller Address:	159 SOUTH LEXINGTON AVE
Spiller Company:	999
Contact Name:	RODNEY PERSON
DEC Memo:	"Referred Div. of Water NFA DT"
Remarks:	"at least 100 gallons in roadway. street was washed down, sewage washed into catch basin. may have been caused by grease build-up in line."

All Materials:

Site ID:	541288
Operable Unit ID:	1289849
Operable Unit:	01
Material ID:	2295632
Material Code:	0062A
Material Name:	raw sewage
Case No.:	Not reported
Material FA:	Other
Quantity:	100.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

D44 **71 EAST POST ROAD** **NY UST** **U003883866**
ENE **71 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.019 mi.
98 ft. **Site 2 of 5 in cluster D**

Relative: **Higher**
Actual: **218 ft.**

WESTCHESTER CO. UST:

Name:	71 EAST POST ROAD
Address:	71 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-048569 / Unregulated: <1101 gal. PBS
Operator Name:	Post Development Corp
Owner Name:	Post Development Corp
Owner Street:	199 Main St
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	71
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	06/01/1993
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	1. Submersible

C45 **PHILLIP WERBEL** **NY UST** **U003884940**
SW **12 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.033 mi.
175 ft. **Site 9 of 23 in cluster C**

Relative: **Lower**
Actual: **208 ft.**

WESTCHESTER CO. UST:

Name:	PHILLIP WERBEL
Address:	12 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-800795 / Unregulated: <1101 gal. PBS
Operator Name:	Phillip Werbel
Owner Name:	Phillip Werbel
Owner Street:	12 East Post Road
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported

PHILLIP WERBEL (Continued) **U003884940**

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/05/2001
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

C46 **SPILL NUMBER 0103645** **NY LTANKS** **S105055231**
SW **12 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.033 mi.
175 ft. **Site 10 of 23 in cluster C**

Relative: **Lower**
Actual: **208 ft.**

LTANKS:

Name:	SPILL NUMBER 0103645
Address:	12 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0103645 / 2003-12-09
Facility ID:	0103645
Site ID:	129951
Spill Date:	2001-07-05
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-07-05
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-05
Spill Record Last Update:	2003-12-09
Spiller Name:	Not reported
Spiller Company:	PHILIP WERBEL
Spiller Address:	12 EAST POST RD
Spiller County:	001
Spiller Contact:	CALLER

SPILL NUMBER 0103645 (Continued) **S105055231**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	111992
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 12/09/03 CLOSED BY STEFAN GOREAU OF THE WESTCHESTER COUNTY HEALTH DEPARTMENT."
Remarks:	"u/g tank leaking. pulled. cleanup starting soon."

All Materials:

Site ID:	129951
Operable Unit ID:	840256
Operable Unit:	01
Material ID:	535715
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C47 **GETTY PETROLEUM CORP** **NY Spills** **1000423253**
SW **11 E POST RD** **RCRA NonGen / NLR** **NYD981556152**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.036 mi.
191 ft. **Site 11 of 23 in cluster C**

Relative: **Lower**

Actual: **209 ft.**

SPILLS:

Name:	GETTY
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8603012 / 1986-08-26
Facility ID:	8603012
Facility Type:	ER
DER Facility ID:	266859
Site ID:	168401
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1986-08-05
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1986-08-05
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Citizen
Cleanup Ceased:	1986-08-26
Cleanup Meets Std:	True
Last Inspection:	1986-08-26
Recommended Penalty:	True
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1986-08-25

GETTY PETROLEUM CORP (Continued) **1000423253**

Spill Record Last Update:	1986-10-27
Spiller Name:	Not reported
Spiller Company:	GETTY
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"DELIBERATE DISCHARGE OF CONTAMINATED WATER TO STORM DRAIN"

All Materials:

Site ID:	168401
Operable Unit ID:	900292
Operable Unit:	01
Material ID:	475855
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	FORMER GETTY PBS 3-137820
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1705804 / 2018-07-20
Facility ID:	1705804
Facility Type:	ER
DER Facility ID:	266859
Site ID:	559105
DEC Region:	3
Spill Cause:	Other
Spill Class:	B4
SWIS:	6017
Spill Date:	2017-09-13
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2017-09-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-09-13
Spill Record Last Update:	2018-07-20
Spiller Name:	WILLIAM
Spiller Company:	11 EAST POST ROAD REALITY
Spiller Address:	11 EAST POST ROAD
Spiller Company:	999
Contact Name:	WILLIAM
DEC Memo:	""

GETTY PETROLEUM CORP (Continued) **1000423253**

Remarks: "historical testing spilled clean up is pending"

All Materials:

Site ID:	559105
Operable Unit ID:	1307108
Operable Unit:	01
Material ID:	2313982
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Handler Address:	11 E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601-4603
EPA ID:	NYD981556152
Contact Name:	Not reported
Contact Address:	JERICHO TNPK
Contact City,State,Zip:	JERICHO, NY 11735
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	JERICHO TNPK
Mailing City,State,Zip:	JERICHO, NY 11735
Owner Name:	GETTY PETROLEUM CORP
Owner Type:	Private
Operator Name:	GETTY PETROLEUM CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No

GETTY PETROLEUM CORP (Continued) **1000423253**

Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

GETTY PETROLEUM CORP (Continued) **1000423253**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP

GETTY PETROLEUM CORP (Continued) **1000423253**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1994-10-04 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	GETTY PETROLEUM CO
Address:	11 E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601-4603
Country:	USA
EPA ID:	NYD981556152
Facility Status:	Not reported
Location Address 1:	11 E POST RD

GETTY PETROLEUM CORP (Continued) **1000423253**

Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	4603

NY MANIFEST:

EPAID:	NYD981556152
Mailing Name:	GETTY PETROLEUM CO
Mailing Contact:	FRANK CODELLA
Mailing Address 1:	11 E POST RD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	4603
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	CTF0571790
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	CTHW231
Trans2 State ID:	Not reported
Generator Ship Date:	10/12/1998
Trans1 Recv Date:	10/12/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/16/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD981556152
Trans1 EPA ID:	CTD021816889
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

GETTY PETROLEUM CORP (Continued) **1000423253**

Quantity:	00175
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	004
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

Name:	GETTY STATION
Address:	11 E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP000860718
Facility Status:	Not reported
Location Address 1:	11 E POST RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	4603

NY MANIFEST:

EPAID:	NYP000860718
Mailing Name:	GETTY STATION
Mailing Contact:	GETTY STATION
Mailing Address 1:	11 E POST RD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	4603
Mailing Country:	USA
Mailing Phone:	9149467799

NY MANIFEST:

Document ID:	CTB0047638
Manifest Status:	K
seq:	Not reported
Year:	1986
Trans1 State ID:	CT/96192
Trans2 State ID:	Not reported
Generator Ship Date:	08/22/1986
Trans1 Recv Date:	08/22/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	08/22/1986
Part A Recv Date:	09/25/1986
Part B Recv Date:	09/17/1986
Generator EPA ID:	NYP000860718
Trans1 EPA ID:	CTD981065758
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD021816889
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

GETTY PETROLEUM CORP (Continued) **1000423253**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	05000
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

Click this hyperlink while viewing on your computer to access
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

C48 **STATION #58108** **NY UST** **U003994563**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.036 mi.
191 ft. **Site 12 of 23 in cluster C**

Relative: WESTCHESTER CO. UST:
Lower

Actual:
209 ft.

Name:	STATION #58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-137820 / Active
Operator Name:	Eagle Service Station Inc.
Owner Name:	11 East Post Road Realty, LLC
Owner Street:	555 South Columbus Avenue, Suite 201
Owner Address2:	Not reported
Owner City:	Mount Vernon
Owner State:	NY
Owner Zipcode:	10550
GDS Number:	3551700144
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	09/01/1986
Date Perm Closure:	09/13/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode

STATION #58108 (Continued) **U003994563**

Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	09/01/1986
Date Perm Closure:	09/13/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	09/01/1986
Date Perm Closure:	09/14/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	4000

STATION #58108 (Continued) **U003994563**

Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	09/01/1986
Date Perm Closure:	09/14/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	2. Galvanized Steel
Piping External Protection:	2. Original sacrificial anode
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	7
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	09/19/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

C49 **GETTY # 58108** **NY Spills** **S107656918**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 13 of 23 in cluster C**

Relative: **Lower**
Actual: **209 ft.**

SPILLS:

Name:	GETTY # 58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0513284 / 2006-08-09
Facility ID:	0513284
Facility Type:	ER
DER Facility ID:	266859
Site ID:	359748
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4

GETTY # 58108 (Continued) **S107656918**

SWIS:	6017
Spill Date:	2006-02-17
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-02-17
CID:	408
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-02-17
Spill Record Last Update:	2006-08-09
Spiller Name:	SCOTT HANLY
Spiller Company:	GETTY # 58108
Spiller Address:	11 EAST POST RD
Spiller Company:	001
Contact Name:	SCOTT HANLY
DEC Memo:	""
Remarks:	"DISDPENSER SHUTDOWN PENDING REPAIRS, SOIL IMPACTED, NOT CLEANED UP"

All Materials:

Site ID:	359748
Operable Unit ID:	1116942
Operable Unit:	01
Material ID:	2107407
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C50 **GETTY 58108** **NY Spills** **S107522390**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 14 of 23 in cluster C**

Relative: **Lower**
Actual: **209 ft.**

SPILLS:

Name:	GETTY 58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0512391 / 2006-01-31
Facility ID:	0512391
Facility Type:	ER
DER Facility ID:	266859
Site ID:	358706
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4

GETTY 58108 (Continued) **S107522390**

SWIS:	6017
Spill Date:	2006-01-25
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2006-01-25
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-26
Spill Record Last Update:	2006-02-13
Spiller Name:	MIKE CARR
Spiller Company:	GETTY 58108
Spiller Address:	11 EAST POST ROAD
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	"1/31/06 Vinnie McCabe 1.) less then 1 gal, stain under dispencer 2.) old dispencer & island to be replaced"
Remarks:	"LESS THAN AN OUNCE THAT HAS BEEN CLEANED UP. THERE IS NO CONTAINMENT UNDERNEATH THE DISPENSER SO SOME OF THE SOIL WAS STAINED BUT NOT WET. EQUIPMENT HAS BEEN SHUT DOWN AND ISLAND NEEDS TO BE REPLACED."

All Materials:

Site ID:	358706
Operable Unit ID:	1115934
Operable Unit:	01
Material ID:	2106045
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

Name:	GETTY 58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0711111 / 2008-01-21
Facility ID:	0711111
Facility Type:	ER
DER Facility ID:	266859
Site ID:	392529
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	2008-01-21
Investigator:	mbmastro
Referred To:	Not reported

GETTY 58108 (Continued) **S107522390**

Reported to Dept:	2008-01-21
CID:	404
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-01-22
Spill Record Last Update:	2008-01-28
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	MIKE CARR\\
DEC Memo:	"NFA."
Remarks:	"less than 1 gallon of both materials spilled; all cleaned up"

All Materials:

Site ID:	392529
Operable Unit ID:	1149523
Operable Unit:	01
Material ID:	2140048
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Site ID:	392529
Operable Unit ID:	1149523
Operable Unit:	01
Material ID:	2140049
Material Code:	0021
Material Name:	transmission fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0603141 / 2006-11-03
Facility ID:	0603141
Facility Type:	ER
DER Facility ID:	266859
Site ID:	365800
DEC Region:	3

GETTY 58108 (Continued) **S107522390**

Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-06-21
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-06-21
CID:	409
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-06-21
Spill Record Last Update:	2006-11-03
Spiller Name:	GUSTAVO MAGUINA
Spiller Company:	GETTY 58108
Spiller Address:	11 EAST POST ROAD
Spiller Company:	001
Contact Name:	GUSTAVO MAGUINA
DEC Memo:	"06-03141 11 East Post Road, White Plains NY - piping repair and retest - passed line test. NFA"
Remarks:	"THERE IS NO SPILL THERE IS A LINE FAILURE BACK INTO THE TANK,"

All Materials:

Site ID:	365800
Operable Unit ID:	1123774
Operable Unit:	01
Material ID:	2113251
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GETTY 58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0713025 / 2008-09-26
Facility ID:	0713025
Facility Type:	ER
DER Facility ID:	266859
Site ID:	394715
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-03-10
Investigator:	TDGHIOSA
Referred To:	Not reported

GETTY 58108 (Continued) **S107522390**

Reported to Dept:	2008-03-10
CID:	73
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-10
Spill Record Last Update:	2008-09-26
Spiller Name:	IVAN GARCES
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JACKIE TROSCLAIR
DEC Memo:	""
Remarks:	"LEAK IN UNDERGROUND LIFT. LIFT IS BEING TAKEN OUT AND SOIL WILL BE REMOVED."

All Materials:

Site ID:	394715
Operable Unit ID:	1151666
Operable Unit:	01
Material ID:	2142413
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C51 **SPILL NUMBER 8600048** **NY LTANKS** **S104619203**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 15 of 23 in cluster C**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Name:	SPILL NUMBER 8600048
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8600048 / 1987-02-24
Facility ID:	8600048
Site ID:	200602
Spill Date:	1986-04-02
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1987-02-24
SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported

SPILL NUMBER 8600048 (Continued) **S104619203**

Reported to Dept:	1986-04-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Citizen
Last Inspection:	1987-02-24
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1986-04-25
Spill Record Last Update:	1997-06-06
Spiller Name:	Not reported
Spiller Company:	POWERTEST GETTY GAS
Spiller Address:	11 EAST POST RD.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	266859
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 2/24/87 WCHD INVESTIGATED NFA. "
Remarks:	"PRODUCT OBSERVED IN OBS WELLS-LOSING PRODUCT FROM AUG,85"

All Materials:

Site ID:	200602
Operable Unit ID:	896383
Operable Unit:	01
Material ID:	480238
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

C52 **GETTY 58108** **NY Spills** **S102962370**
SW **11 EAST POST RD / WINCHESTER** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 16 of 23 in cluster C**

Relative: SPILLS:
Lower

Actual:
209 ft.

Name:	GETTY 58108
Address:	11 EAST POST RD / WINCHESTER
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9710575 / 2018-07-20
Facility ID:	9710575
Facility Type:	ER
DER Facility ID:	188254
Site ID:	228215
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017

GETTY 58108 (Continued) **S102962370**

Spill Date:	1997-12-12
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	1997-12-16
CID:	999
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-16
Spill Record Last Update:	2018-07-20
Spiller Name:	SCOTT HANLEY
Spiller Company:	GETTY STATION
Spiller Address:	11 EAST POST ROAD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"12/16/97 TYREE TESTED TANKS AT GETTY; PREMIUM LINE FAILED BENEATH DISPENSER; LINE REPAIRED AND WILL BE RETESTED; TYREE PERFORMING GEO PROBE ON 12/18/97 TO DETERMINE EXTENT OF CONTAMINATION; 06/8/98 CAUSE OF SPILL IS A LEAKING LINE AT GETTY S/S. GROUNDWATER INVESTIGATION AND REMEDIATION REQUIRED. ALSO SEE CASE 97-10611 06/11/98 LETTER SEND TO INFORM OF A REMEDIAL ACTION PLAN MUST BE INSTALLED WITHIN 3 MONTHS. 06/18/98: LETTER SENT APPROVAL OF PROPOSED SYSTEM 01/30/01 LETTER SENT TO TYREE BY J. HARDY; IF SYSTEM WILL NOT BE OPERATING BY 2/15/01, PROPOSE AN INTERIM REMEDIAL ACTION PLAN TO CONTROL MIGRATION WHILE THE PERMANENT SYSTEM IS DOWN. 02/02/01 LETTER SENT TO GETTY PROPERTIES CORP. BY J.HARDY; COPIES OF LETTERS RECENTLY SENT TO TYREE ATTACHED. 03/22/01 LETTER SENT TO TYREE BY J. HARDY; PROVIDE SCHEDULE FOR ACTIONS DESCRIBED IN 2/6/01 LETTER. 04/19/01 LETTER SENT TO TYREE BY J. HARDY; ADVISE AS TO STATUS AND SCHEDULE FOR UPGRADES TO ELECTRICAL & REMEDIATION SYSTEMS AT THIS SITE 05/10/01 LETTER SENT TO TYREE BY J. HARADY; IN ACCORDANCE WITH SCHEDULE, STARTUP IS EXPECTED BY JUNE 15, 2001. 06/07/01 LETTER SENT TO TYREE BY J. HARDY; PROVIDE SCHEDULE FOR INSTALLATION OF NEW EQUIPMENT AT THIS SITE WITHIN 7DAYS 3/6/08 following sent to tyree:confirming our tel conversation you may shut down this system. continue vacuum removals and monitoring.(levels in recovery wells low, system not productive--no off site problems and hi vac removals to continue) jh Periodic VEFR to supplement the Dual Phase High Vacuum remedial system is continueing at 3 of the more impacted wells. QMRs in eDocs. PJD Apr. 2009. DPHV system continueing with minor but consistent removals. GP-4A was drilled in late 2009 and connected to the system in early 2010. GW quality conitnues to improve w/ 3 wells at moderate concentrations. PJD Sept. 2010 DPHV System down as of 2010. Review of additional monitoring data in the interim and the last few months of system data lead the DEC to accept that additional system operation is not warranted at this time. Targeted removal by VEFR with the addition of biosolve approved for use in June 2013. DOH found inventory discrepency in early 2013 and required subsurface investigation. DOH requested DEC review. Most severe soil impacts found just downgradient of pump island. No significant new release indicated. Current remedial plan sufficient at this time. PJD July

GETTY 58108 (Continued) **S102962370**

2013 5-29-2014: RDB & SWC met with Getty Realty. RAP approved by DEC awaiting UIC from EPA. 1-26-15 3q and 4th quarter 2014 data submitted; biosolve injection in June 2014; planned for Feb 2014 RDB 6-10-15 met with Antea and Getty to discuss;- going to check construction plans and await results of Lake Katrine and Shrub Oak injections RDB second quarter results submitted RDB 11-20-15 third quarter results 12-2- met with Antea and Getty need to address the contamination, need a workplan for the soil removal around gp4 and the dispenser island possibly removing MW4. RDB 1-12-16 sent email to Getty for update RDB 1-23-17 met with Antea and Getty; owner is planning to remove tanks in next 2 months and Getty will overexcavate the dispenser area and around canopy ; In addition consultant for WPH called looking for data. ; sent last report RDB 2-15-17 Consultant calling returned call LM RDB 2-15-17 reported that they found gw contamination on edge of property at levels that do not match Getty's numbers RDB 04-21-2017- first QMR submitted; emailed Antea looking for station updatel supposed to be razed, response, Yes it is.Note to John Have you received an update from the current owner on their schedule? Please see below note from Dan as reference. RDB 7-6-17 call from TFisher, the new owner Atlantis is planning to remove tanks this summer, Getty will remove contamination, building demo up in air- RDB 09-6-17 email from Antea, We have a schedule for the start date of the UST removal, canopy removal, and remedial soil excavation activities for Spill No. 97-10757 - 11 E. Post Road, White Plains Getty 58108.The work is currently scheduled to begin Monday Sept. 11. The work is being conducted by Metro Environmental Services (MES). MES will be removing the USTs on behalf of the White Plains Hospital and will be performing remedial activities on-behalf of Getty to include the excavation of impaced soil below the dispensers. Antea Group will be on-site on-behalf of Getty and I believe Woodward & Curran will be on-site on behalf of the White Plains Hospital. RDB 09-13-17, email from Antea, As an update to the below e-mail chain, MES removed the two USTs located on the southern side of the UST pit today. By 9am tomorrow (9/14) they expect to be ready to remove the two remaining UST located on the northern half of the UST pit. As reference attached is a site plan showing the approx. location, depth, and, PIDs of the endpoint soil samples that were collected today by Woodard & Curran as part of the UST closure. Four sidewall samples, and two bottom samples have been collected. PIDs have been low, with the exception of the sidewall toward the dispensers. On that sidewall a PID of 1,080ppm was observed. Not unexpected as we plan to over-excavate impacted soil below the dispenser. RDB new spill 17- 05804 called in RDB 9-14-17 Email from Antea, MES was able to remove the two additional USTs today, so all four USTs have now been removed.Attached is an updated map showing the UST removal endpoint soil samples collected by Woodard & Curran.You ll see on the attachment that some higher PID readings were observed along the northwest, north, and northeast sidewalls today. Further excavation in the northwest and north directions is not safe due to the proximity to the adjacent property and the sidewalk. We have stockpiled impacted soil from these areas for transport off-site & disposal. We will be excavation the eastern side of the tank pit as part of the remedial excavation below the dispenser.Today MES observed a concrete slab below the former tanks. Soil above the concrete slab did not exhibit impacts, with the exception of endpoint soil sample S-11 at the northeastern corner of the tank pit. A PID reading of 480ppm was recorded at this location and that soil was

GETTY 58108 (Continued) **S102962370**

removed down to the concrete slab that is present at approx. 10 feet below ground surface. - RDB 9-29-17, update from Antea, MES has completed the tank pit over-excavation. Please see attached map for details regarding sample locations, depths, and associated PID readings. MES was unable to remove any additional soil on the sidewall and bottom along East Post Road due to the close proximity of the sidewalk. We began the over-excavation beneath the dispenser area today. A White Plains Department of Buildings inspector, Cris Dellaripa, implement a stop work. He cited non-conformance with permit requirements MES is addressing these items. We re hoping to have the issues resolved and be excavating again towards the end of next week. Antea Group will be on site to screen soil and collect samples when MES continues the excavation beneath the former dispenser island. Depending on the PID readings of the sidewall samples, we may request a spill closure at that point or recommend additional excavation when the site building is demolished. The building is likely not going to be demoed until next year due to the pending permit process. RDB 1-16-18, MES and Antea Group conducted additional excavation activities at this site last week since the building has been removed. We submitted sidewall and bottom samples on a quick turnaround to understand if we needed to excavate further. There were no exceedances in the endpoint soil samples collected last week. Please see attached updated map and soil analytical table. We ll be on site tomorrow with MES to extend the northeastern-most portion of the excavation to a depth of 12 ft. The majority of the excavation in that area extends to around 10 ft. We collected a sample (B-8) at 11.5-12 ft, and we will be removing the soil in that area to a final depth of 12 ft. The northwestern-most portion of the excavation had a final depth of 9 ft, and the middle portion of the excavation had a depth of 11 ft. These details are included on the attached site map. RDB 02-07-18 Stopped by site to observe the open excavation. Photos on D2. BTR 4/27/18 email sent to Tim Fisher of Antea Group requesting site update. BW"

Remarks: "unknown petroleum in storm drain on east post rd in front of the white plains hospital. dec investigating."

All Materials:

Site ID:	228215
Operable Unit ID:	1056931
Operable Unit:	01
Material ID:	328868
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C53 **POST ROAD GETTY** **EDR Hist Auto** **1020554122**
SW **11 E POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.036 mi.
191 ft. **Site 17 of 23 in cluster C**

Relative: EDR Hist Auto
Lower

Actual:
209 ft.

Year:	Name:	Type:
1969	PRESTOS FLYING A	Gasoline Service Stations
1970	PRESTOS FLYING A	Gasoline Service Stations
1971	PRESTOS SERVICE STATION	Gasoline Service Stations
1972	PRESTOS SERVICE STATION	Gasoline Service Stations
1973	PRESTOS SERVICE STATION	Gasoline Service Stations
1974	PRESTOS SERVICE STATION	Gasoline Service Stations
1975	PRESTOS SERVICE STATION	Gasoline Service Stations
1978	ELEVEN E POST RD ENTERPRISES*	Gasoline Service Stations
1979	ELEVEN E POST RD ENTERPRISES*	Gasoline Service Stations
1980	ELEVEN E POST RD ENTERPRISES*	Gasoline Service Stations
1982	FRANKS AUTO REPAIR	General Automotive Repair Shops
1982	ELEVEN E POST RD ENTERPRISES*	Gasoline Service Stations
1983	FRANKS AUTO REPAIR	General Automotive Repair Shops
1983	ELEVEN E POST RD ENTERPRISES*	Gasoline Service Stations
1985	FRANKS AUTO REPAIR	General Automotive Repair Shops
1986	FRANKS AUTO REPAIR	General Automotive Repair Shops
1987	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1988	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1989	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1990	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1991	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1992	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1993	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1994	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1995	FRANKS AUTO SERVICE INC	General Automotive Repair Shops
1998	KPOST ROAD GETTY	Gasoline Service Stations
1999	KPOST ROAD GETTY	Gasoline Service Stations
2000	POST ROAD GETTY	Gasoline Service Stations
2001	POST ROAD GETTY	Gasoline Service Stations
2002	POST ROAD GETTY	Gasoline Service Stations
2003	POST ROAD GETTY	Gasoline Service Stations
2004	POST ROAD GETTY	Gasoline Service Stations
2005	POST ROAD GETTY	Gasoline Service Stations
2006	POST ROAD GETTY	Gasoline Service Stations
2007	POST ROAD GETTY	Gasoline Service Stations
2008	POST ROAD GETTY	Gasoline Service Stations
2010	POST ROAD GETTY	Gasoline Service Stations
2011	POST ROAD GETTY	Gasoline Service Stations
2012	POST ROAD GETTY	Gasoline Service Stations
2013	POST ROAD GETTY	Gasoline Service Stations
2014	POST ROAD GETTY	Gasoline Service Stations

C54 **GETTY #58108** **NY Spills** **S107522213**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 18 of 23 in cluster C**

Relative:
Lower

Actual:
209 ft.

SPILLS:

Name:	GETTY #58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0512154 / 2006-08-09
Facility ID:	0512154
Facility Type:	ER
DER Facility ID:	266859
Site ID:	358427
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2006-01-20
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-01-20
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2006-01-20
Spill Record Last Update:	2006-08-09
Spiller Name:	MIKE CARR
Spiller Company:	GETTY #58108
Spiller Address:	11 EAST POST ROAD
Spiller Company:	001
Contact Name:	MIKE CARR
DEC Memo:	""
Remarks:	"DAMP PIPING IN DISPENSER: SHUT DOWN: PENDING REPAIRS"

All Materials:

Site ID:	358427
Operable Unit ID:	1115670
Operable Unit:	01
Material ID:	2105757
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

C55 **GETTY SERVICE STATION** **NY LTANKS** **S104514642**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 19 of 23 in cluster C**

Relative: **Lower**

Actual: **209 ft.**

LTANKS:

Name:	GETTY GAS #58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0407127 / 2004-09-27
Facility ID:	0407127
Site ID:	261414
Spill Date:	2004-09-27
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	MBMASTRO
Referred To:	WCHD
Reported to Dept:	2004-09-27
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2004-09-27
Spill Record Last Update:	2004-10-18
Spiller Name:	SCOTT HANLEY
Spiller Company:	GETTY GAS #58108
Spiller Address:	11 EAST POST ROAD
Spiller County:	001
Spiller Contact:	SCOTT HANLEY
Spiller Phone:	(516) 542-5273
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	266859
DEC Memo:	""
Remarks:	"Spilled into containment. Spill is being cleanedup, no release into the environment."

All Materials:

Site ID:	261414
Operable Unit ID:	890394
Operable Unit:	01
Material ID:	484968
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	4.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

GETTY SERVICE STATION (Continued) **S104514642**

Name:	GETTY SERVICE STATION
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9710611 / 1998-05-08
Facility ID:	9710611
Site ID:	261415
Spill Date:	1997-12-17
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-17
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-12-17
Spill Record Last Update:	1998-06-08
Spiller Name:	Not reported
Spiller Company:	GETTY SERVICE STATION
Spiller Address:	11 EAST POST ROAD
Spiller County:	001
Spiller Contact:	TYREE INC
Spiller Phone:	(203) 740-8200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	213498
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/08/98 FUTHER INVESTIGATION AND REMEDIATION WILL BE CONDUCTED UNDER SPILL # 97-10575"
Remarks:	"TWO TANKS BOTH 4000 GALLON CAPACITY MANIFOLDED TOGETHER. FAILED TEST."

All TTF:

Facility ID:	9710611
Spill Number:	9710611
Spill Tank Test:	1545523
Site ID:	261415
Tank Number:	003 & 004
Tank Size:	4000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

C56 **STATION #58108** **NY AST** **A100276702**
SW **11 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.036 mi.
191 ft. **Site 20 of 23 in cluster C**

Relative:
Lower

Actual:
209 ft.

WESTCHESTER CO. AST:

Name:	STATION #58108
Address:	11 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-137820
Site Status:	Active
GDS Number:	3551700144
Operator Name:	Eagle Service Station Inc.
Owner Name:	11 East Post Road Realty, LLC
Owner Street:	555 South Columbus Avenue, Suite 201
Owner Address2:	Not reported
Owner City/State/Zip:	Mount Vernon, NY 10550
Tank Number:	5
Status:	3. Closed - Removed
Date Installation:	12/01/1998
Capacity:	240
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	3. Automatic Shut-off
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	12/01/1998
Capacity:	180
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	09/29/2013
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None

STATION #58108 (Continued) **A100276702**

Piping Secondary Containment: 0. None
Overfill Prevention: 3. Automatic Shut-off
Spill Prevention: 1. Catch Basin
Dispenser: 0. None

C57 **GETTY # 58108** **NY Spills** **S109371927**
SW **11 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
191 ft. **Site 21 of 23 in cluster C**

Relative: **Lower**
Actual: **209 ft.**

SPILLS:

Name:	GETTY GAS #58108
Address:	11 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0807262 / 2008-09-29
Facility ID:	0807262
Facility Type:	ER
DER Facility ID:	353877
Site ID:	404601
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2008-09-29
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-09-29
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-29
Spill Record Last Update:	2008-10-04
Spiller Name:	MIKE CARR
Spiller Company:	CUSTOMER
Spiller Address:	11 EAST POST RD
Spiller Company:	999
Contact Name:	MIKE CARR
DEC Memo:	"confirmed clean up - nfa mm"
Remarks:	"A customers vehicle leaked less than 1 gallon of oil onto the parking lot. Spill was cleaned."

All Materials:

Site ID:	404601
Operable Unit ID:	1161249
Operable Unit:	01
Material ID:	2152444
Material Code:	0015
Material Name:	motor oil
Case No.:	Not reported
Material FA:	Petroleum

GETTY # 58108 (Continued) **S109371927**

Quantity:	1.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GETTY # 58108
Address:	11 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0902231 / 2009-10-07
Facility ID:	0902231
Facility Type:	ER
DER Facility ID:	353877
Site ID:	414266
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2009-05-26
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2009-05-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2009-05-26
Spill Record Last Update:	2009-10-07
Spiller Name:	CARRIE WILSEY
Spiller Company:	GETTY # 58108
Spiller Address:	11 EAST POST RD
Spiller Company:	999
Contact Name:	CARRIE WILSEY
DEC Memo:	""
Remarks:	"DUE TO POOR RECORD KEEPING TANK 1 AND 2 FAILED FOR 10 DAY INVENTORY. FURTHER INVESTIGATION IS PENDING."

All Materials:

Site ID:	414266
Operable Unit ID:	1170656
Operable Unit:	01
Material ID:	2162397
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

C58 **WHITE PLAINS HOTEL** **NY Spills** **S102153955**
SSW **MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.036 mi.
192 ft. **Site 22 of 23 in cluster C**

Relative:
Higher

Actual:
214 ft.

SPILLS:

Name:	WHITE PLAINS HOTEL
Address:	MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9003827 / 1990-07-10
Facility ID:	9003827
Facility Type:	ER
DER Facility ID:	81239
Site ID:	233667
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	6017
Spill Date:	1990-07-06
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-10
Spill Record Last Update:	2019-07-09
Spiller Name:	Not reported
Spiller Company:	White Plains Hotel
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"UNKNOWN QUANTITY OF BLACK SMOKE CLOUD COMING FROM WHITE PLAINS HOTEL CHIMNEY WCHD INVESTIGATING"

All Materials:

Site ID:	233667
Operable Unit ID:	941642
Operable Unit:	01
Material ID:	434959
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

C59 **GETTY S/S** **NY LTANKS** **S100494499**
SSW **11 EAST POND ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.041 mi.
216 ft. **Site 23 of 23 in cluster C**

Relative:
Higher

Actual:
211 ft.

LTANKS:

Name:	GETTY S/S
Address:	11 EAST POND ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9210753 / 1992-12-31
Facility ID:	9210753
Site ID:	319803
Spill Date:	1992-12-16
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	1992-12-31
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1992-12-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-12-18
Spill Record Last Update:	1993-02-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	257661
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"UNDERGROUND TANK PUMPED PRODUCT DOWN WILL EXCAVATE AND REPAIR PETRO-TITE GROSS"

All TTF:

Facility ID:	9210753
Spill Number:	9210753
Spill Tank Test:	1540964
Site ID:	319803
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

GETTY S/S (Continued) **S100494499**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	319803
Operable Unit ID:	977395
Operable Unit:	01
Material ID:	404196
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

E60 **WHITE PLAIN HOUSING AUTH.** **NY LTANKS** **S100140591**
NE **225 GROVE ST** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.043 mi.
229 ft. **Site 1 of 6 in cluster E**

Relative:
Higher

Actual:
215 ft.

LTANKS:

Name:	WHITE PLAIN HOUSING AUTH.
Address:	225 GROVE ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8904683 / 1992-07-30
Facility ID:	8904683
Site ID:	293104
Spill Date:	1989-08-10
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1992-07-30
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1989-08-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-21
Spill Record Last Update:	1992-07-30
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001

WHITE PLAIN HOUSING AUTH. (Continued) **S100140591**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	237240
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"TANKS ARE 35 YR. OLD-2 TANKS 1 PASSED, 1 FAILED, TO ISOLATE & RETEST ASAP. VMC ADVISED 35 YRD OLD TANK MAY NOT BE WORTH REPAIRING, SHOULD BE REPLACED. W.W. TO FOLLOW UP."

All TTF:

Facility ID:	8904683
Spill Number:	8904683
Spill Tank Test:	1535834
Site ID:	293104
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	293104
Operable Unit ID:	929941
Operable Unit:	01
Material ID:	448716
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E61 **WINBROOK HOUSING DEVELOPMENT** **NY UST** **U003995071**
NE **223 DR. MARTIN LUTHER KING BLVD.** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.044 mi.
232 ft. **Site 2 of 6 in cluster E**

Relative: **Higher**
Actual: **215 ft.**

WESTCHESTER CO. UST:

Name:	WINBROOK HOUSING DEVELOPMENT
Address:	223 DR. MARTIN LUTHER KING BLVD.
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-493597 / Active
Operator Name:	Teddie Henderson
Owner Name:	White Plains Housing Authority

WINBROOK HOUSING DEVELOPMENT (Continued) **U003995071**

Owner Street:	223 Dr. Martin Luther King Blvd.
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	20000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None
Tank Number:	002
Status:	1. In-Service
Capacity:	20000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	11. Flexible Piping
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

E62 **WINDBROOK HOUSING** **NY LTANKS** **S105996991**
NE **223 DR MARTIN LUTHER KING** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.044 mi.
232 ft. **Site 3 of 6 in cluster E**

Relative:
Higher

Actual:
215 ft.

LTANKS:

Name:	WINDBROOK HOUSING
Address:	223 DR MARTIN LUTHER KING
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0207150 / 2002-11-25
Facility ID:	0207150
Site ID:	243532
Spill Date:	2002-10-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-10-10
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-10
Spill Record Last Update:	2015-03-26
Spiller Name:	ALAN PIO
Spiller Company:	WINDBROOK HOUSING
Spiller Address:	223 DR MARTIN LUTHER KING
Spiller County:	001
Spiller Contact:	ALAN PIO
Spiller Phone:	(914) 949-6462
Spiller Extention:	13
DEC Region:	3
DER Facility ID:	200049
DEC Memo:	"3/26/15: Hard copy file pulled for FOIL request. File being scanned into DecDocs and paper file will be disgarded. jod"
Remarks:	"2 tanks 20000 gals joined together - failed individually & collectively"

All TTF:

Facility ID:	0207150
Spill Number:	0207150
Spill Tank Test:	1527564
Site ID:	243532
Tank Number:	1
Tank Size:	20000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

WINDBROOK HOUSING (Continued) **S105996991**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 243532
Operable Unit ID: 859974
Operable Unit: 01
Material ID: 517734
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

D63 **WHITE PLAINS BEVERAGE** **NY Spills** **S113819104**
NE **234 MARTIN LUTHER KING JR BLVD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
254 ft. **Site 3 of 5 in cluster D**

Relative:
Higher

Actual:
217 ft.

SPILLS:
Name: WHITE PLAINS BEVERAGE
Address: 234 MARTIN LUTHER KING JR BLVD
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 1304060 / 2013-11-27
Facility ID: 1304060
Facility Type: ER
DER Facility ID: 439722
Site ID: 484569
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: A3
SWIS: 6017
Spill Date: 2013-07-15
Investigator: JBODEE
Referred To: Not reported
Reported to Dept: 2013-07-16
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-07-16
Spill Record Last Update: 2013-11-27
Spiller Name: Not reported
Spiller Company: WHITE PLAINS BEVERAGE

WHITE PLAINS BEVERAGE (Continued) **S113819104**

Spiller Address: Not reported
Spiller Company: 999
Contact Name: BRIAN TURTHETTA
DEC Memo: "7-16-13 Spoke with Brian. They did borings around tank and found contamination. Owner has agreed that they will be removing tank. They believe it is a 550. Told Brian to contact WP office regarding work schedule. jm Email from Envirostar::9/5/2013 5:16:01 PM: We pulled a 1000 Gallon UST yesterday. Scott Jerutis 234 Dr. Martin Luther King Boulevard White Plains 914-299-4778 It s a commercial building He sold the property but held money in escrow. I will keep you informed jod Email from Envirostar::9/19/2013 4:39:25 PM: We removed 4 containers of contaminated soil today its still dirty. The owner hired Tom Gallinger to do oversite during the clean up and close the spill. jod 11/27/13: Tank removal and cleanup of contaminated soil completed by Envirostar. Tank closure report from Tom Gallinger reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks: "Phase 1 on old UST. Positive reading on PID from nearby soil sample."
Not reported

All TTF:
Facility ID: 1304060
Spill Number: 1304060
Spill Tank Test: 2493932
Site ID: 484569
Tank Number: 1
Tank Size: 1000
Material: 9999
EPA UST: False
UST: True
Cause: 00
Source: 00
Test Method: NN
Test Method 2: Testing Not Required
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: JBODEE
Last Modified Date: Not reported

All Materials:
Site ID: 484569
Operable Unit ID: 1234248
Operable Unit: 01
Material ID: 2233255
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

F64 **POST RD** **NY Spills** **S104282789**
SSE **DAVIS AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
256 ft. **Site 1 of 4 in cluster F**

Relative: **Higher**

Actual: **221 ft.**

SPILLS:

Name:	POST RD
Address:	DAVIS AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9908220 / 1999-11-19
Facility ID:	9908220
Facility Type:	ER
DER Facility ID:	63920
Site ID:	165382
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	1999-10-06
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-10-06
CID:	211
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-06
Spill Record Last Update:	1999-12-06
Spiller Name:	Not reported
Spiller Company:	POSS GETTY GAS STATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BRIAN MURPHY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/19/99 REMEDIATION ONGOING @ GETTY UNDER SPILL #97-10575"
Remarks:	"caller has crew excavating and there is a strong odor of gasoline in hole - there is a getty gas station in close proximity to site and caller believes onr of the tanks is leaking"

All Materials:

Site ID:	165382
Operable Unit ID:	1086882
Operable Unit:	01
Material ID:	300897
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F65 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S107417344**
SSE **MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
256 ft. **Site 2 of 4 in cluster F**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	WHITE PLAINS HOSPITAL
Address:	MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9304740 / 1994-01-06
Facility ID:	9304740
Site ID:	290020
Spill Date:	1993-07-15
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	1994-01-06
SWIS:	6017
Investigator:	MALONE
Referred To:	Not reported
Reported to Dept:	1993-07-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-27
Spill Record Last Update:	1994-01-06
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81239
DEC Memo:	""
Remarks:	"SOIL DISCOVERED IN TANK PULL WILL SYOCKPILE SOIL"

All Materials:

Site ID:	290020
Operable Unit ID:	983028
Operable Unit:	01
Material ID:	398220
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

F66 **HOSPITAL (UNK NAME)** **NY LTANKS** **S103479243**
SSE **41 EAST COAST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
256 ft. **Site 3 of 4 in cluster F**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	HOSPITAL (UNK NAME)
Address:	41 EAST COAST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9806058 / 1998-08-17
Facility ID:	9806058
Site ID:	191235
Spill Date:	1998-08-14
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B2
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-08-14
CID:	199
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-08-14
Spill Record Last Update:	1998-10-02
Spiller Name:	Not reported
Spiller Company:	MYSTIC BULK CARRIERS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	159508
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 8/17/98 SEE SPILL 9806078. SAME SPILL AND SPILLER. NFA"
Remarks:	"TANK OVERFILL BY CARRIER - CALLER IS ENROUTE AT THIS TIME WITH VACUMN TRUCK FOR CLEAN-UP -- SOME MATERAL ALSO GOT INTO STORM SEWERS"

All Materials:

Site ID:	191235
Operable Unit ID:	1067237
Operable Unit:	01
Material ID:	317230
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2000.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

F67 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S100964742**
SSE **DAVIS AVE & EAST POST ROAD** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.048 mi.
256 ft. **Site 4 of 4 in cluster F**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	WHITE PLAINS HOSPITAL
Address:	DAVIS AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9303501 / 1996-06-18
Facility ID:	9303501
Site ID:	66799
Spill Date:	1993-06-14
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-06-17
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-06-21
Spill Record Last Update:	1996-06-18
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	63920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TYREE DID TANK REMOVAL WCHD NOTIFIED FAXED TO TODD THEY CONVERTED TO NATURAL GAS"

All Materials:

Site ID:	66799
Operable Unit ID:	985354
Operable Unit:	01
Material ID:	397066
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S100964742**

SPILLS:

Name:	WHITE PLAINS HOSPITAL
Address:	DAVIS AVE & EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9401229 / 1994-05-05
Facility ID:	9401229
Facility Type:	ER
DER Facility ID:	174910
Site ID:	210995
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1994-04-26
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-04-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1994-05-05
Spill Record Last Update:	1996-06-18
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 06/07/94: NO DEC INSPECTION. "
Remarks:	"GAGE MALFUNCTION SPILL CONTAINED ON CONCRETE CASTLE TO DO CLEAN UP BEING CLEANED UP"

All Materials:

Site ID:	210995
Operable Unit ID:	998531
Operable Unit:	01
Material ID:	570100
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

E68 **LITTLE MOUNT ZION HOLY CHURCH** **NY Spills** **S110540042**
NE **230 DR. MARTIN LUTHER KING JR. BLVD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.049 mi.
259 ft. **Site 4 of 6 in cluster E**

Relative:
Higher

Actual:
217 ft.

SPILLS:

Name:	LITTLE MOUNT ZION HOLY CHURCH
Address:	230 DR. MARTIN LUTHER KING JR. BLVD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1006496 / 2010-11-15
Facility ID:	1006496
Facility Type:	ER
DER Facility ID:	394852
Site ID:	439851
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D4
SWIS:	6017
Spill Date:	2010-09-15
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-09-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-15
Spill Record Last Update:	2010-11-15
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DEBRAH THOMPSON
DEC Memo:	"9-15-10 While excavating for foundation near property line for planned addition, contamination encountered at 8'-10'. Soil down to 8' is clean. Deb says soil smells like gas. Sample taken for analysis. jc 10/01/10 Soil sample report submitted by DT Consulting Service. Sample results for TAGM parameters were below the DEC guidance values. No further acton required. TG"
Remarks:	"WHILE DIGGING FOR FOUNDATION ENCOUNTERED CONTAMINATED SOIL APPROX 8-10 FEET BELOW GRADE."

All Materials:

Site ID:	439851
Operable Unit ID:	1190484
Operable Unit:	01
Material ID:	2185491
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported

LITTLE MOUNT ZION HOLY CHURCH (Continued) **S110540042**

Recovered: Not reported
Oxygenate: Not reported

D69 **SMITH SAMUEL** **EDR Hist Auto** **1020405856**
ENE **79 E POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.050 mi.
264 ft. **Site 4 of 5 in cluster D**

Relative: EDR Hist Auto
Higher

Actual: **226 ft.**

Year:	Name:	Type:
1969	SMITH SAMUEL JOSEPH	Gasoline Service Stations
1970	SMITH SAMUEL JOSEPH	Gasoline Service Stations
1971	SMITH SAMUEL JOSEPH	Gasoline Service Stations
1972	SMITH SAMUEL JOSEPH	Gasoline Service Stations
1973	SMITH SAMUEL	Gasoline Service Stations
1974	SMITH SAMUEL	Gasoline Service Stations
1975	SMITH SAMUEL	Gasoline Service Stations
1976	SMITH SAMUEL	Gasoline Service Stations
1977	SMITH SAMUEL	Gasoline Service Stations
1978	SMITH SAMUEL	Gasoline Service Stations
1979	SMITH SAMUEL	Gasoline Service Stations
1980	SMITH SAMUEL	Gasoline Service Stations
1982	SMITH SAMUEL	Gasoline Service Stations
1983	SMITH SAMUEL	Gasoline Service Stations
1983	GALLERIA SERVICE STATION	General Automotive Repair Shops
1985	GALLERIA SERVICE STATION	General Automotive Repair Shops
1986	GALLERIA SERVICE STATION	General Automotive Repair Shops
1987	GALLERIA SERVICE STATION	General Automotive Repair Shops
1988	GALLERIA SERVICE STATION	General Automotive Repair Shops
1989	GALLERIA SERVICE STATION	General Automotive Repair Shops
1990	GALLERIA SERVICE STATION	General Automotive Repair Shops
1991	GALLERIA SERVICE STATION	General Automotive Repair Shops
1992	GALLERIA SERVICE STATION	General Automotive Repair Shops
1993	GALLERIA SERVICE STATION	General Automotive Repair Shops
1994	GALLERIA SERVICE STATION	General Automotive Repair Shops
1995	GALLERIA SERVICE STATION	General Automotive Repair Shops

---

G70 **PHILLIP WERBEL** **NY UST** **U003857492**
SW **1 EAST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.056 mi.
298 ft. **Site 1 of 6 in cluster G**

Relative: WESTCHESTER CO. UST:
Lower

Actual: **208 ft.**

Name:	PHILLIP WERBEL
Address:	1 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-800796 / Unregulated: <1101 gal. PBS
Operator Name:	Phillip Werbel
Owner Name:	Phillip Werbel
Owner Street:	12 East Post Road
Owner Address2:	Not reported
Owner City:	White Plains

PHILLIP WERBEL (Continued) **U003857492**

Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	07/17/2001
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

G71 **SPILL NUMBER 0013009** **NY LTANKS** **S104950648**
SW **1 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.056 mi.
298 ft. **Site 2 of 6 in cluster G**

Relative: LTANKS:
Lower

Actual: Name:	SPILL NUMBER 0013009
208 ft. Address:	1 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0013009 / 2001-03-12
Facility ID:	0013009
Site ID:	156648
Spill Date:	2001-03-12
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	2001-03-12
CID:	207
Water Affected:	Not reported
Spill Notifier:	Health Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-12
Spill Record Last Update:	2001-03-14
Spiller Name:	Not reported

SPILL NUMBER 0013009 (Continued) **S104950648**

Spiller Company:	FRANGO OIL CO
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ELVIRA ALBANO
Spiller Phone:	(914) 684-9073
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132543
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 03/12/2001 WCDOH TO FOLLOW UP. NYSDEC SPILLS NO FURTHER ACTION."
Remarks:	"cleanup in progress"

All Materials:

Site ID:	156648
Operable Unit ID:	834948
Operable Unit:	01
Material ID:	539736
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

D72 **CILIM CLEANERS CORP** **EDR Hist Cleaner** **1019954432**
NE **82-84 E POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.063 mi.
332 ft. **Site 5 of 5 in cluster D**

Relative: EDR Hist Cleaner
Higher

Actual:
227 ft.

Year:	Name:	Type:
1970	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1971	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs
1972	CILIM CLEANERS CORP	Drycleaning Plants, Except Rugs

H73 **UST REMOVAL** **NY Spills** **S126399498**
WNW **135 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.063 mi.
333 ft. **Site 1 of 18 in cluster H**

Relative: SPILLS:
Lower

Actual:
197 ft.

Name:	UST REMOVAL
Address:	135 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	2001101 / 2020-06-26
Facility ID:	2001101
Facility Type:	ER
DER Facility ID:	554224
Site ID:	605737
DEC Region:	3

UST REMOVAL (Continued) **S126399498**

Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2020-05-19
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2020-05-19
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2020-05-19
Spill Record Last Update:	2020-06-26
Spiller Name:	Not reported
Spiller Company:	TRINITY BROOKFIELD COMMONS FOUR TWO LIMITED PARTNERSHIP
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	COLLEEN GRIFFITHS
DEC Memo:	"5/19/20 Caller was doing a phase 1 assessment. Site is an apartment complex. Came across a UST said to date from 1950, according to caller. They also found a 2nd tank. Soil samples have been taken to determine what the product is/was. dw 06/01/20 Colleen Griffith called and stated that the tank was removed along with 200 cubic yds. of soil. She will be submitting a report shortly. TG 06/24/20 AKRF submitted a Spill Closure Report. See report in DedDocs. AKRP reported that A 1000 gallon UST was excavated and removed along with 18.97 tons of contaminated soil. Post excavation soil sample results were below DEC soil guidance values. NFA. TG"
Remarks:	"tank removal"

All Materials:

Site ID:	605737
Operable Unit ID:	1352888
Operable Unit:	01
Material ID:	2363813
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

G74 **BISCARDI CLEANERS** **NY LTANKS** **S110246037**
SW **201 SO. LEXINGTON AVE.** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY 10601** **NY DRYCLEANERS**
0.063 mi.
335 ft. **Site 3 of 6 in cluster G**

Relative:
Lower

Actual:
209 ft.

LTANKS:

Name:	BISSCARDI CLEANERS
Address:	201 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0100630 / 2006-05-01
Facility ID:	0100630
Site ID:	322267
Spill Date:	2001-04-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2001-04-17
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-04-17
Spill Record Last Update:	2006-05-01
Spiller Name:	Not reported
Spiller Company:	BISSCARDI CLEANERS
Spiller Address:	201 SOUTH LEXINGTON AVE
Spiller County:	001
Spiller Contact:	BISSCARDI CLEANERS
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	259613
DEC Memo:	"04/17/2001 275 GALLON A/G. NORTHEAST ENVIRONMENTAL RESPONDING -QUANTITY LOST UNKNOWN AT THIS TIME. 150 GALLONS LOST."
Remarks:	"tank let go at location. unknown how much oil on floor of basement. "
	Not reported

All Materials:

Site ID:	322267
Operable Unit ID:	839472
Operable Unit:	01
Material ID:	536346
Material Code:	0032C
Material Name:	wood alcohol
Case No.:	00067561
Material FA:	Hazardous Material
Quantity:	150.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BISCARDI CLEANERS (Continued) **S110246037**

SPILLS:

Name:	ALBANO
Address:	201 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0013010 / 2001-03-12
Facility ID:	0013010
Facility Type:	ER
DER Facility ID:	259613
Site ID:	254787
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2001-03-12
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	2001-03-12
CID:	323
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-03-12
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	TJ NETHERCOTT
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	TERRY NETHERCOTT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 03/12/2001 WCDOH WAS ON SITE ACCORDING TO SPILLER. MINOR SPILL DUE TO LOOSE GAUGE FITTING. CLEANUP TO BE COMPLETED BY SPILLER. NO FURTHER ACTION."
Remarks:	"GUAGE ON TANK FAILED. SPILL CLEANED UP, GAUGE REPLACED."

All Materials:

Site ID:	254787
Operable Unit ID:	834546
Operable Unit:	01
Material ID:	539737
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

DRYCLEANERS:

Name:	BISCARDI CLEANERS

BISCARDI CLEANERS (Continued) **S110246037**

Address:	201 SO. LEXINGTON AVE.
City,State,Zip:	WHITE PLAINS, NY 10601
Facility ID:	3-5517-00279
Phone Number:	914-684-9073
Region:	Not reported
Registration Effective Date:	N/A
Inspection Date:	1930-04-12 00:00:00
Install Date:	92/12
Expiration Date:	Not reported
Removal Date:	Not reported
Drop Shop:	Not reported
Shutdown:	Y
Alternate Solvent:	Not reported
Current Business:	Not reported

G75 **BISCARDI CLEANERS** **RCRA NonGen / NLR** **1000167952**
SW **201 S LEXINGTON AVE** **FINDS** **NYD013386511**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.063 mi. **NY MANIFEST**
335 ft. **Site 4 of 6 in cluster G**

Relative: **Lower**
Actual: **209 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	BISCARDI CLEANERS
Handler Address:	201 S LEXINGTON AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYD013386511
Contact Name:	Not reported
Contact Address:	S LEXINGTON AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	S LEXINGTON AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	OWNERNAME
Owner Type:	Private
Operator Name:	OWNERNAME
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No

BISCARDI CLEANERS (Continued) **1000167952**

Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND

BISCARDI CLEANERS (Continued) **1000167952**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-14 00:00:00.0
Handler Name:	BISCARDI CLEANERS
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	BISCARDI CLEANERS

BISCARDI CLEANERS (Continued) **1000167952**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	BISCARDI CLEANERS
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1985-04-16 00:00:00.0
Handler Name:	BISCARDI CLEANERS
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004348377

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

BISCARDI CLEANERS (Continued) **1000167952**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000167952
Registry ID:	110004348377
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004348377
Name:	BISCARDI CLEANERS
Address:	201 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10601

NY MANIFEST:

Name:	BISCARDI
Address:	201 S LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYD013386511
Facility Status:	Not reported
Location Address 1:	201 SOUTH LEXINGTON AVENUE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD013386511
Mailing Name:	BISCARDI
Mailing Contact:	BISCARDI
Mailing Address 1:	201 SOUTH LEXINGTON AVENUE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146849033

NY MANIFEST:

Document ID:	NYC5574003
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	NYCR2436
Trans2 State ID:	T218034TN
Generator Ship Date:	06/09/1999
Trans1 Recv Date:	06/09/1999
Trans2 Recv Date:	06/11/1999

BISCARDI CLEANERS (Continued) **1000167952**

TSD Site Recv Date:	06/22/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD013386511
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	OHD980587364
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00195
Units:	P - Pounds
Number of Containers:	001
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

G76 **BISCARDI CLEANERS INC** **EDR Hist Cleaner** **1019940040**
SW **201 S LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.063 mi.
335 ft. **Site 5 of 6 in cluster G**

Relative: EDR Hist Cleaner
Lower

Actual:
209 ft.

Year:	Name:	Type:
1979	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1980	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1982	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1983	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1985	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1986	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1987	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1988	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1989	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1990	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1991	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1992	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1993	BISCARDI FRANK	Drycleaning Plants, Except Rugs
1994	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
1995	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents

BISCARDI CLEANERS INC (Continued) **1019940040**

1996	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
1997	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
1998	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
1999	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
2000	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
2001	BISCARDI CLEANERS INC	Garment Pressing And Cleaners' Agents
2002	SOUTH LEXINGTON CORP	Garment Pressing And Cleaners' Agents
2003	SOUTH LEXINGTON CORP	Garment Pressing And Cleaners' Agents
2004	BISCARDI CLEANERS INC	Drycleaning Plants, Except Rugs
2004	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2005	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2006	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2007	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2008	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2010	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs
2011	BISCARDI CLEANERS	Drycleaning Plants, Except Rugs

H77 **HYDRAULIC FLUID TO SEWER** **NY LTANKS S104877043**
WNW **134 SOUTH LEXINGTON AVE** **NY Spills N/A**
< 1/8 **WHITE PLAINS, NY**
0.067 mi.
355 ft. **Site 2 of 18 in cluster H**

Relative: LTANKS:
Lower

Name:	UNK
Address:	134 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0008525 / 2001-03-12
Facility ID:	0008525
Site ID:	218519
Spill Date:	2000-10-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-10-21
CID:	397
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-21
Spill Record Last Update:	2009-12-28
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	AMY
Spiller Phone:	(914) 592-3117
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	107023

Actual:
197 ft.

HYDRAULIC FLUID TO SEWER (Continued) **S104877043**

DEC Memo: "03/12/2001 TANK PULLED BY CORSETTI CONTRACTING FOR DORSON ENVIRONMENTAL. TANK WAS SOUND, NO EVIDENCE OF RELEASE. A SECOND, 550 GALLON WASTE OIL TANK WAS ALSO REMOVED. NO EVIDENCE OF DISCHARGE FROM SECOND TANK WAS FOUND. NO FURTHER ACTION."
Remarks: "DORSON ENVIRONMENTAL WAS THE SUB CONTRACTOR FOR THE TANK TEST. "

All TTF:
Facility ID: 0008525
Spill Number: 0008525
Spill Tank Test: 1525945
Site ID: 218519
Tank Number: 1
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 218519
Operable Unit ID: 829124
Operable Unit: 01
Material ID: 546030
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: HYDRAULIC FLUID TO SEWER
Address: 134 SOUTH LEXINGTON AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0008680 / 2005-03-06
Facility ID: 0008680
Facility Type: ER
DER Facility ID: 107023
Site ID: 123462
DEC Region: 3
Spill Cause: Unknown
Spill Class: C3
SWIS: 6017
Spill Date: 2000-10-25
Investigator: WCHD
Referred To: WESTCHESTER CNTY HEALTH D
Reported to Dept: 2000-10-25

HYDRAULIC FLUID TO SEWER (Continued) **S104877043**

CID:	365
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Federal Government
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-10-25
Spill Record Last Update:	2005-03-06
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"3/6/5 15gallon hydraulic fluid spilled to sewer--close"
Remarks:	"THE SPILL WAS RELEASED FROM AN ELEVATOR DUE TO UNK CAUSES & WENT INTO A STORM SEWER - ACTUAL COMP TO NRC WAS FROM WHITE PLAINS POLICE DEPT, JOSEPH DEPLAO 914-422-6111 - FIRE DEPT WAS REPORTED TO HAVE BEEN ON THE SCENE"

All Materials:

Site ID:	123462
Operable Unit ID:	829269
Operable Unit:	01
Material ID:	546183
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

78
WSW
< 1/8
0.068 mi.
361 ft.

EL PAISA AUTO BODY
177 ORAWAMPUM ROAD
WHITE PLAINS, NY

NY Spills **S103273762**
N/A

Relative:
Higher

Actual:
224 ft.

SPILLS:

Name:	EL PAISA AUTO BODY
Address:	177 ORAWAMPUM ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9800944 / 1998-06-24
Facility ID:	9800944
Facility Type:	ER
DER Facility ID:	117995
Site ID:	137985
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	C4
SWIS:	6017
Spill Date:	1998-04-02

EL PAISA AUTO BODY (Continued) **S103273762**

Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-04-22
CID:	266
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-04-22
Spill Record Last Update:	1998-07-21
Spiller Name:	GIOVANNY ARIAS
Spiller Company:	EL PAISA AUTO BODY
Spiller Address:	177 ORAWAMPUM ROAD
Spiller Company:	001
Contact Name:	GIOVANNY ARIAS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 04/21/98 BARBARA McDONALD; SLOPPY HOUSEKEEPING AROUND OIL DRUMS; APPROX. ONE SQUARE YARD AFFECTED SOIL; SHOP OWNER WILL EXCAVATE; ADVISED OF PROPER HOUSEKEEPING; 06/24/98 CLEANUP COMPLETED. NFA. "
Remarks:	"WASTE OIL SPILLED ON GROUND WHEN BEING POURED INTO WASTE OIL TANK. APPROXIMATELY ONE YARD OF SOIL TO BE REMOVED."

All Materials:

Site ID:	137985
Operable Unit ID:	1061736
Operable Unit:	01
Material ID:	322885
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	2.00
Oxygenate:	Not reported

H79 **TRINITY METHODIST CHURCH** **NY Spills** **S108299213**
WNW **130 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.074 mi.
391 ft. **Site 3 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

SPILLS:

Name:	TRINITY METHODIST CHURCH
Address:	130 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0610953 / 2007-06-25
Facility ID:	0610953
Facility Type:	ER
DER Facility ID:	325127
Site ID:	375495

TRINITY METHODIST CHURCH (Continued) **S108299213**

DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-12-29
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2006-12-29
CID:	62
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2007-04-04
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-30
Spill Record Last Update:	2015-08-25
Spiller Name:	BILLY SMITH
Spiller Company:	ROBISON OIL
Spiller Address:	500 EXC BLVD
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Trinity Church stated that clean up was in progress by Robison Oil. Fuel (#2) was delivered to the wrong fill line and went to the elevator shaft. Robison pumped out the fuel and placed absorbent pads in shaft. There is a fuel odor present as of Jan. 02, 2007. NE Environmental responded. 6/25/2007: Spill closure report received and reviewed by DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	""

All Materials:

Site ID:	375495
Operable Unit ID:	1133129
Operable Unit:	01
Material ID:	2122931
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I80 **WHITE PLAINS HOSPITAL** **NY LTANKS** **S110045423**
ESE **8 LONGVIEW AVE** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.078 mi.
414 ft. **Site 1 of 3 in cluster I**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Name:	4K GALLON UST/TTF
Address:	8 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1007877 / 2011-07-05
Facility ID:	1007877
Site ID:	441326
Spill Date:	2010-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2010-10-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-25
Spill Record Last Update:	2017-12-12
Spiller Name:	Not reported
Spiller Company:	HOMEOWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	STEPHANIE EAGANS
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343572
DEC Memo:	"10/25/10 - Retest. Follow up will be conducted by Westchester County DOH since tank is PBS regulated. KAB 7/5/11 ttf, tank removed, contamination removed, endpoint samples below CP-51 standards NFA JO'M 12/12/17: Also see Spill 1007255. jod"
Remarks:	"TANK TEST FAILURE."

All Materials:

Site ID:	441326
Operable Unit ID:	1191891
Operable Unit:	01
Material ID:	2187096
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S110045423**

Name:	WHITE PLAINS HOSPITAL
Address:	8 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0907812 / 2009-11-04
Facility ID:	0907812
Site ID:	420361
Spill Date:	2009-10-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2009-10-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-10-12
Spill Record Last Update:	2009-11-04
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOSP
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ROSS EDDY
Spiller Phone:	(914) 681-1000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343572
DEC Memo:	"10/15/09: I called the tank tester Ken Gelok from CTT. Confirmed TTF at PBS regulated facilty. He had no further info on a plan of action. WCDOH PBS will follow up. jod 11/04/09: From WCDOH PBS - #0907812 White plains Hospital, 8 Longview Ave, White Plains Tightness test failure - tank passed on 10/20/2009 NFA jod"
Remarks:	""

All Materials:

Site ID:	420361
Operable Unit ID:	1176335
Operable Unit:	01
Material ID:	2169020
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WHITE PLAINS HOSPITAL
Address:	8 LONGVIEW AVE

WHITE PLAINS HOSPITAL (Continued) **S110045423**

City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1007255 / 2017-12-12
Facility ID:	1007255
Site ID:	440652
Spill Date:	2010-10-06
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	WCDOH
Reported to Dept:	2010-10-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-06
Spill Record Last Update:	2017-12-12
Spiller Name:	BOB BIDDISCOMBE
Spiller Company:	WHITE PLAINS HOSPITAL
Spiller Address:	8 LONGVIEW AVE
Spiller County:	999
Spiller Contact:	BOB BIDDISCOMBE
Spiller Phone:	(914) 681-1000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343572
DEC Memo:	"10-6-10 Spoke with Kathy. This is a 4k UST. Loud bubbling during tank test. PBS #3-104469 RP was told by US Tank Tech that they need to empty tank. Undecided about next step. Will notify WCHD. jm 10/14/10 Hospital wanted tank uncover, repaired and retested. There was nothing to repair so a well point sample was collected. Sample is contaminated with petroleum. Tank will not be retested....mm 12/12/17: This 4k UST failed a tightness test on Oct 6, 2010 reported as this Spill 1007255 Callback notes on this case number indicate UST would not be retested as well point was contaminated. The UST was retested on Oct 20, 2010 and failed. Retest was reported as Spill 1007877 That second Spill number was closed on July 5, 2011 with the following notation: 7/5/11 ttf, tank removed, contamination removed, endpoint samples below CP-51 standards NFA JO'M *WCDoH PBS data 3-104469 indicates this 4k UST was closed/removed January 2011 and a new 2k UST was installed. Based upon this information, this Spill case number closed and referred to Spill 1007877. jod"
Remarks:	"tank test failure. restest likely"

All Materials:

Site ID:	440652
Operable Unit ID:	1191260
Operable Unit:	01
Material ID:	2186382
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S110045423**

Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	APARTMENT
Address:	8 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0712395 / 2008-07-16
Facility ID:	0712395
Facility Type:	ER
DER Facility ID:	343572
Site ID:	394002
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-02-25
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-02-25
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-25
Spill Record Last Update:	2008-07-16
Spiller Name:	SAL MANCUSO
Spiller Company:	APART
Spiller Address:	8 LONGVIEW AVE
Spiller Company:	001
Contact Name:	WESTCHESTER ESTATES
DEC Memo:	"Spoke with Jeneen Ferrara from National Environmental. Mancuso Oil caused spill. NES will begin cleanup tomorrow. She says that they were informed that it was minor. Tried to contact PRP phone number that was given, but it appears to be a fax machine. 7/19/08: Stefan Goreau of WCHD confirmed NES completed clean up and soil sample results were ND for contamination. NFA jod"
Remarks:	"OVERFILL OF TANK AND CALLERS CLEANING UP"

All Materials:

Site ID:	394002
Operable Unit ID:	1150949
Operable Unit:	01
Material ID:	2141603
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

WHITE PLAINS HOSPITAL (Continued) **S110045423**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

I81 **8 LONGVIEW DEVELOPMENT CORPORATION** **NY UST** **U004175968**
ESE **8 LONGVIEW AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.078 mi.
414 ft. **Site 2 of 3 in cluster I**

Relative: WESTCHESTER CO. UST:
Higher

Actual:
234 ft.

Name:	8 LONGVIEW DEVELOPMENT CORPORATION
Address:	8 LONGVIEW AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-104469 / Unregulated
Operator Name:	Edward Leonard
Owner Name:	White Plains Hospital Center
Owner Street:	Davis Avenue at East Post Road
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	001
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	90
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	01/01/1983
Date Perm Closure:	01/04/2011
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/underground combination
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction
Tank Number:	002
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	04/05/2011
Date Perm Closure:	10/29/2018
Tank Location:	5. Underground including vaulted with no access for inspection

8 LONGVIEW DEVELOPMENT CORPORATION (Continued) **U004175968**

Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	2. Original sacrificial anode,9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	Not reported
Piping External Protection:	9. Urethane,PVC outer pipe
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	PVC outer pipe,Envirotube
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

E82 **BETHEL BAPTIST CHURCH** **NY Spills** **S110752068**
NNE **1 FISHER COURT** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.079 mi.
415 ft. **Site 5 of 6 in cluster E**

Relative: **Lower**

Actual: **209 ft.**

SPILLS:

Name:	BETHEL BAPTIST CHURCH
Address:	1 FISHER COURT
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1011299 / 2011-04-18
Facility ID:	1011299
Facility Type:	ER
DER Facility ID:	399994
Site ID:	445152
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2011-02-10
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2011-03-28
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-02-10
Spill Record Last Update:	2011-04-18
Spiller Name:	Not reported
Spiller Company:	BETHEL BAPTIST CHURCH
Spiller Address:	1 FISHER COURT
Spiller Company:	999
Contact Name:	STU FREEMAN
DEC Memo:	"2/10/11 Spoke to Stu Freeman at Advanced Environmental, who referred me to the person at the site , Declan MacAnnanie (Zack) at cell # 914-906-8878. 550 UST was pulled, and there is contaminated dirt and groundwater impact reported by Advanced. They will be continuing the remediation pending insurance coverage. dw 3/28/11: DEC site inspection, met with Advanced Environmental and rep from the Church

BETHEL BAPTIST CHURCH (Continued) **S110752068**

Board. Contamination is extensive, ground water has been impacted. Approx 40 tons of contaminated soil has been removed to date. Remediation is being hampered by a sewer main pipe and a large tree. Main excavation is being backfilled, and overburden will be removed on the other side of the sewer pipe to access additional contamination. jod 4/18/2011: Clean up completed by Advanced Environmental. Report reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Not reported
Remarks: "during tank removal soil and gw were discovered. clean up penidng."

All Materials:
Site ID: 445152
Operable Unit ID: 1195380
Operable Unit: 01
Material ID: 2191507
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

H83 **CON ED** **NY Spills** **S118952846**
WNW **126 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.081 mi.
426 ft. **Site 4 of 18 in cluster H**

Relative: **Lower**
Actual: **196 ft.**

SPILLS:
Name: CON ED
Address: 126 SOUTH LEXINGTON AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 1607231 / 2016-10-24
Facility ID: 1607231
Facility Type: ER
DER Facility ID: 479680
Site ID: 534865
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6017
Spill Date: 2016-10-24
Investigator: GAAHLERS
Referred To: Not reported
Reported to Dept: 2016-10-24
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

CON ED (Continued) **S118952846**

Remediation Phase:	0
Date Entered In Computer:	2016-10-24
Spill Record Last Update:	2016-10-24
Spiller Name:	ERT
Spiller Company:	CON ED
Spiller Address:	126 SOUTH LEXINGTON AVE
Spiller Company:	999
Contact Name:	ERT
DEC Memo:	"10/24/16 Spoke to Con Ed. Contractor Vehicle (Northline Utilities) lost 15 gals hydrolic fluid to soil. Loss to concrete / asphalt. No environmental impact (no soil, no water, no gw, etc.) Northline to do cleanup. Cleanup pending Northline crew. NFA. ga"
Remarks:	"contractor vehicle had loss to soil, c/u pending"

All Materials:

Site ID:	534865
Operable Unit ID:	1283580
Operable Unit:	01
Material ID:	2288956
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

H84 **COMMERCIAL** **NY Spills** **S118637452**
WNW **126 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.081 mi.
426 ft. **Site 5 of 18 in cluster H**

Relative:
Lower

Actual:
196 ft.

SPILLS:

Name:	COMMERCIAL
Address:	126 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1600183 / 2016-04-08
Facility ID:	1600183
Facility Type:	ER
DER Facility ID:	479680
Site ID:	525442
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2016-04-06
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2016-04-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

COMMERCIAL (Continued) **S118637452**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2016-04-06
Spill Record Last Update:	2016-04-08
Spiller Name:	Not reported
Spiller Company:	CEDAR HILL HOLDINGS REALTY
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WAYNE JAFFERS
DEC Memo:	"4/6/16- WCDOH reports: Site registered to remove. Very old tanks in parking lot. Likely historic S/S. No obvious contamination during tank removal. Soil sample likely showed contamination? William of WCDOH to inspect/handle PBS 3-802064 126 South Lexington Ave White Plains 04/08/16 Barrier Contracting reported that they removed two tank and that no contaminated soil was present around either tank. Post excavation soil sample results were below DEC guidance values. NFA. TG"
Remarks:	"It was a tank removal and there was a spill, they don't know the amount. The cleanup is pending."

All Materials:

Site ID:	525442
Operable Unit ID:	1274400
Operable Unit:	01
Material ID:	2278976
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

E85 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823799**
ENE **F/O 89 EAST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.081 mi.
426 ft. **Site 6 of 6 in cluster E**

Relative: **Higher**
Actual: **235 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	F/O 89 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004227298
Facility Status:	Not reported
Location Address 1:	F/O 89 EAST POST RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

CONSOLIDATED EDISON (Continued) **S110823799**

NY MANIFEST:

EPAID:	NYP004227298
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2011
Trans1 Recv Date:	02/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004227298
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655814JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	990
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008

CONSOLIDATED EDISON (Continued) **S110823799**

Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

I86 **CON EDISON** **RCRA NonGen / NLR** **1014398356**
ESE **MAPLE AVE & LONGVIEW AVE** **NYP004207084**
< 1/8 **WHITE PLAINS, NY 10601**
0.082 mi.
433 ft. **Site 3 of 3 in cluster I**

Relative: **Higher**
Actual: **235 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	MAPLE AVE & LONGVIEW AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004207084
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---

CON EDISON (Continued) **1014398356**

Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:28:24.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2010-05-23 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1014398356**

State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: No
Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

J87 **CON EDISON** **NJ MANIFEST** **S120675553**
NNE **GROVE ST & FISCHER COURT** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.083 mi.
440 ft. **Site 1 of 6 in cluster J**

Relative: **Lower**
Actual: **210 ft.**

NJ MANIFEST:
EPA Id: NYP004825978
Mail Address: IRVING PL 15TH FL NE
Mail City/State/Zip: NEW YORK, NY 10003
Facility Phone: Not reported
Emergency Phone: Not reported
Contact: THOMAS TEELING
Comments: Not reported
SIC Code: Not reported
County: NY119
Municipal: Not reported
Previous EPA Id: Not reported
Gen Flag: Not reported
Trans Flag: Not reported
TSDF Flag: Not reported
Name Change: Not reported
Date Change: Not reported

Manifest:
Manifest Number: 014472095JJK
EPA ID: NYP004825978
Date Shipped: 8/19/2015
TSDF EPA ID: NJD002200046
Transporter EPA ID: NYD006982359
Transporter 2 EPA ID: Not reported
Transporter 3 EPA ID: Not reported
Transporter 4 EPA ID: Not reported
Transporter 5 EPA ID: Not reported
Transporter 6 EPA ID: Not reported
Transporter 7 EPA ID: Not reported
Transporter 8 EPA ID: Not reported

CON EDISON (Continued) **S120675553**

Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

J88 **CON EDISON SERVICE BOX: 11370** **RCRA NonGen / NLR** **1016969239**
NNE **GROVE ST & FISCHER AVE** **NY MANIFEST** **NYP004428926**
< 1/8 **WHITE PLAINS, NY 10602**
0.083 mi.
440 ft. **Site 2 of 6 in cluster J**

Relative: **Lower**

Actual: **210 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 11370
Handler Address:	GROVE ST & FISCHER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10602
EPA ID:	NYP004428926
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-10-14 12:33:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-01-29 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 11370
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 11370
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	GROVE ST & FISCHER AVE
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004428926
Facility Status:	Not reported
Location Address 1:	GROVE & FISHER
Code:	BP
Location Address 2:	SERVICE BOX # 11370
Total Tanks:	Not reported

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004428926
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2014
Trans1 Recv Date:	01/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004428926
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692778JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	20
Units:	P - Pounds
Number of Containers:	1

CON EDISON SERVICE BOX: 11370 (Continued) **1016969239**

Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

J89 **CON EDISON** **RCRA NonGen / NLR** **1019906748**
NNE **GROVE ST & FISCHER COURT** **FINDS** **NYP004825978**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.083 mi.
440 ft. **Site 3 of 6 in cluster J**

Relative: **Lower**
Actual: **210 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-08-19 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	GROVE ST & FISCHER COURT
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004825978
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON (Continued) **1019906748**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:28:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-08-19 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1019906748**

Receive Date:	2015-08-19 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069671554

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019906748
Registry ID:	110069671554
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069671554
Name:	CON EDISON
Address:	GROVE ST & FISCHER COURT
City,State,Zip:	WHITE PLAINS, NY 10601

J90 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823865**
NNE **GROVE & FISHER** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.083 mi.
440 ft. **Site 4 of 6 in cluster J**

Relative:
Lower

Actual:
210 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	GROVE & FISHER
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004228116
Facility Status:	Not reported
Location Address 1:	GROVE & FISHER
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004228116
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/17/2011
Trans1 Recv Date:	02/17/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/24/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004228116
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007660025JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N

CONSOLIDATED EDISON (Continued) **S110823865**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H91 **124 SOUTH LEXINGTON AVE. INC.** **NY UST** **U003949767**
WNW **124 SOUTH LEXINGTON AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.084 mi.
442 ft. **Site 6 of 18 in cluster H**

Relative: WESTCHESTER CO. UST:
Lower

Name:	124 SOUTH LEXINGTON AVE. INC.
Address:	124 SOUTH LEXINGTON AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-497231 / Active
Operator Name:	124 South Lexington Ave. Inc.
Owner Name:	124 South Lexington Ave. Inc.
Owner Street:	124 South Lexington Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	3551700223
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	06/01/1991
Date Perm Closure:	05/01/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)

Actual:
196 ft.

124 SOUTH LEXINGTON AVE. INC. (Continued) **U003949767**

Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	10
Status:	1. In-Service
Capacity:	10000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	09/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	11
Status:	1. In-Service
Capacity:	5000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	09/01/2007
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	4000

124 SOUTH LEXINGTON AVE. INC. (Continued) **U003949767**

Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	06/01/1991
Date Perm Closure:	05/01/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	3
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	06/01/1991
Date Perm Closure:	05/01/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	06/01/1991
Date Perm Closure:	05/01/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported

124 SOUTH LEXINGTON AVE. INC. (Continued) **U003949767**

Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	5
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	06/01/1991
Date Perm Closure:	05/01/2007
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	4. Impressed Current (no retrofit)
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	Not reported
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	6
Status:	3. Closed - Removed
Capacity:	500
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	11/16/2005
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	7
Status:	3. Closed - Removed
Capacity:	275
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900

124 SOUTH LEXINGTON AVE. INC. (Continued) **U003949767**

Date Perm Closure:	08/31/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

H92 **GEIS SERVICE STATION INC** **EDR Hist Auto** **1020295746**
WNW **124 S LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10606**
0.084 mi.
442 ft. **Site 7 of 18 in cluster H**

Relative: EDR Hist Auto
Lower

Actual:
196 ft.

Year:	Name:	Type:
1969	GEIS SERVICE STATION INC	Gasoline Service Stations
1970	GEIS SERVICE STATION INC	Gasoline Service Stations
1971	GEIS SERVICE STATION INC	Gasoline Service Stations
1972	GEIS SERVICE STATION INC	Gasoline Service Stations
1973	GEIS SERVICE STATION INC	Gasoline Service Stations
1974	GEIS SERVICE STATION INC	Gasoline Service Stations
1975	GEIS SERVICE STATION INC	Gasoline Service Stations
1976	GEIS SERVICE STATION INC	Gasoline Service Stations
1987	RICKYS TOWING	Automotive Services, NEC
1988	RICKYS TOWING	Automotive Services, NEC
1994	WHITE PLAINS SVCE STATION	Gasoline Service Stations
1995	WHITE PLAINS SVCE STATION	Gasoline Service Stations
1996	WHITE PLAINS SVCE STATION	Gasoline Service Stations
1997	WHITE PLAINS SVCE STATION	Gasoline Service Stations

H93 **GAS STATION** **NY Spills** **S107416663**
WNW **124 SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.084 mi.
442 ft. **Site 8 of 18 in cluster H**

Relative: SPILLS:
Lower

Actual:
196 ft.

Name:	GAS STATION
Address:	124 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0509358 / 2006-03-03
Facility ID:	0509358
Facility Type:	ER
DER Facility ID:	305125
Site ID:	355125
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3

GAS STATION (Continued) **S107416663**

SWIS:	6017
Spill Date:	2005-11-04
Investigator:	WCHD
Referred To:	Not reported
Reported to Dept:	2005-11-04
CID:	444
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-04
Spill Record Last Update:	2006-03-03
Spiller Name:	RICKY
Spiller Company:	GAS STATION
Spiller Address:	124 SOUTH LEXINGTON AVE
Spiller Company:	001
Contact Name:	RICKY
DEC Memo:	"Refer to WCHD PBS 03/03/06 - Letter Dated 2/13/06 from Cindy Badolato from WCHOD to Richard S. Futia - NFA."
Remarks:	"WHILE DIGGING CAME ACCROSS CONTAMINATED SOIL;"

All Materials:

Site ID:	355125
Operable Unit ID:	1112495
Operable Unit:	01
Material ID:	2102537
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GAS STATION
Address:	124 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0611782 / 2012-10-12
Facility ID:	0611782
Facility Type:	ER
DER Facility ID:	305125
Site ID:	376490
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A3
SWIS:	6017
Spill Date:	2007-01-24
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-01-24
CID:	444

GAS STATION (Continued) **S107416663**

Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2007-01-24
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-24
Spill Record Last Update:	2012-10-12
Spiller Name:	DEPUTY CHIEF
Spiller Company:	GAS STATION
Spiller Address:	124 SOUTH LEXINGTON AVE
Spiller Company:	001
Contact Name:	DEPUTY CHIEF
DEC Memo:	"01/25/07 Contacts: Trucking company: All Aboard Transport - owner David Board 2 Kit Court Monroe, NY 845-782-4727 Station owner: JKSG Inc. 124 South Lexington Ave White Plains, NY Dharminder Singh 46 Beaumaont Circle Yonkers, NY 914-482-2560 All Aboard Transport driver Joseph Graff reported that he arrived at the station at approximately 6:30 am to deliver 8500 gallons of gas, 7500 gallons of regular and 1000 gallons of premium. The regular load was dropped into three tanks, 1800 gallons into a 2k reserve tank , 2500 gallons into a 4k tank which is connected to the reserve tank, and the remaining 3200 was dropped into another 4k tank. A pump in the 2k is used to tranfer gas from the 2k tank to the 4k tank when the level in the 4k tank is low. Driver Joseph Graff stated that the delivery was made with without incident. Paperwork was completed and he was about to leave the station when gasoline unexpectedly began gushing out of the dispensers and then out a vent pipe located next to Efficiency Printing. Gasoline ran across the station asphalt into a storm drain and also puddled on the rooftop of the print shop. Station owner Dharminder Singh attempted to shut the power to the dispensers, but this failed to stem the discharge of gas. He then called 911 to the FD who responded and foamed the gasoline. The USTs were later gauged and the 2k tank only contained 7 of product, indicating that the pump in the 2k tank was activated, transferring product into the 4K tank. Once the ullage space in the 4k tank was filled, the product discharged out of the tank at the points outlined above. The station owner hired Castlton Environmental Contractors (CEC). CEC crew deployed booms in the Bronx river and vacuumed gas from the rooftop, the station property, and a gw monitoring well that had been impacted. WCHD a delegated PBS county followed up with the PBS issues. TG June 11, 2007 JKSG 124 South Lexington Avenue White Plains, NY 10601 Re 124 South Lexington Avenue, White Plains NY PBS 3-497231 Spill number 06-11782 Dear Sirs This Department has received an interim closure report from American Petroleum regarding the tank removal and spill clean up at your facility. Staff from this office inspected the tank removals. Significant contamination was removed. However, significant accessible and inaccessible contamination remains. Further remediation is required. This Department understands the site limitation and the need to perform the remediation in stages. Your contractor has requested that the tanks be installed before further excavation is performed in the southern edge of the property near the printing company. This is acceptable only if a remediation plan has been submitted and approved prior to the tank

GAS STATION (Continued) **S107416663**

installation. This accessible area of contamination must be remediated. At least three monitoring wells are required to be installed. The wells must be positioned across the property. The wells must be sampled quarterly for one year, and then the need for continued sampling will be reviewed. The well must be sampled for volatiles (EPA method 624). A remediation plan must be submitted by July 1, 2007. The submittal from interim closure report from American Petroleum may be modified into the remediation plan. This letter was prepared in conjunction with the New York State Department of Environmental Conservation. Please continue to address all submittals to both agencies. Sincerely, Christopher J. Lalak Radiological and Chemical Analyst 12/17/10: Letter entered into eDocs - notice of overdue for sampling sent from WCDOH. jod 12/10/11: Letter to RP from WCDoH entered into eDocs. jod 10/12/12: Update from WCDoH: >>> Lalak, Chris 10/10/2012 9:22 AM >>> John, 0611782 NFA 124 s. Lexington, wp Conklin, long term MW sampling satisfactory -Chris Christopher J. Lalak Radiological and Chemical Analyst Westchester County Department of Health - Peekskill District Office 750 Washington Street Peekskill, NY 10566 CJL1@westchestergov.com 10/12/12: DEC requires NFA jod "

Remarks: "FIRE DEPT ON SCENE AND WOULD LIKE DEC TO RESPOND"

All Materials:

Site ID:	376490
Operable Unit ID:	1134065
Operable Unit:	01
Material ID:	2124365
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	376490
Operable Unit ID:	1134065
Operable Unit:	01
Material ID:	2123923
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	450.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

J94 **SLATER NEIGHBORHOOD CTR** **NY UST** **U003857917**
NNE **2 FISHER COURT** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.085 mi.
449 ft. **Site 5 of 6 in cluster J**

Relative: WESTCHESTER CO. UST:
Lower

Actual: Name:	SLATER NEIGHBORHOOD CTR
208 ft. Address:	2 FISHER COURT
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-169560 / Unregulated: <1101 gal. PBS
Operator Name:	City Of White Plains
Owner Name:	City Of White Plains
Owner Street:	255 Main St
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	26
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1979
Date Perm Closure:	12/01/1998
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

J95 **SLADER NEIGHBORHOOD CNTR** **NY LTANKS** **S103558463**
NNE **2 FISHER CT** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.085 mi.
449 ft. **Site 6 of 6 in cluster J**

Relative: LTANKS:
Lower

Actual: Name:	SLADER NEIGHBORHOOD CNTR
208 ft. Address:	2 FISHER CT
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9810451 / 2003-12-05
Facility ID:	9810451
Site ID:	214463
Spill Date:	1998-11-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017

SLADER NEIGHBORHOOD CNTR (Continued) **S103558463**

Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-18
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-18
Spill Record Last Update:	2003-12-05
Spiller Name:	MARK
Spiller Company:	SLADER NEIGHBORHOOD CNTR
Spiller Address:	2 FISHER CT
Spiller County:	001
Spiller Contact:	MARK
Spiller Phone:	(914) 328-6549
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	177699
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - GOREAU 12/05/03 CLOSED BY STEFAN GOREAU OF WCHD. TANK AND SOIL REMOVED BY ROYAL ENVIRO."
Remarks:	"During tank removal caller found contaminated soil from a hole in tank. 12/11/98 Awaiting closure report. "

All Materials:

Site ID:	214463
Operable Unit ID:	1071357
Operable Unit:	01
Material ID:	314318
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

G96 **AVIS** **NY LTANKS** **S100165725**
SW **20 WEST POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.087 mi.
457 ft. **Site 6 of 6 in cluster G**

Relative: LTANKS:
Lower

Actual: Name:	AVIS
209 ft. Address:	20 WEST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8706892 / 1988-07-27
Facility ID:	8706892
Site ID:	159466
Spill Date:	1987-11-13
Spill Cause:	Tank Test Failure

AVIS (Continued) **S100165725**

Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1988-06-27
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-13
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Responsible Party
Last Inspection:	1988-06-27
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-18
Spill Record Last Update:	2009-01-23
Spiller Name:	JIM SENECAL
Spiller Company:	AVIS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	134698
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 11/13/87-WILL REPLACE TANKS. / / : 2-2K SYSTEMS REMOVED. 02/17/88: WILL REMOVE TANKS LR 02-17-88. 07/27/88: TANKS TO BE REMOVED.EMPTIED. "
Remarks:	"TTTF-2:2K TANKS"

All TTF:

Facility ID:	8706892
Spill Number:	8706892
Spill Tank Test:	1532256
Site ID:	159466
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	159466
Operable Unit ID:	912747
Operable Unit:	01
Material ID:	465880
Material Code:	0009

AVIS (Continued) **S100165725**

Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

K97 **WHITE PLAINS HOSPITAL MEDICAL CENTER** **NY UST** **U004177656**
South **170 MAPLE AVENUE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.091 mi.
478 ft. **Site 1 of 2 in cluster K**

Relative: **Higher**

Actual: **228 ft.**

WESTCHESTER CO. UST:

Name:	WHITE PLAINS HOSPITAL MEDICAL CENTER
Address:	170 MAPLE AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-175102 / Active
Operator Name:	Barhite & Holzinger, Inc.
Owner Name:	White Plains Hospital Medical Center
Owner Street:	71 Pondfield Road
Owner Address2:	c/o Barhite & Holzinger, Inc.
Owner City:	Bronxville
Owner State:	NY
Owner Zipcode:	10708
GDS Number:	Not reported
Tank Number:	002
Status:	1. In-Service
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring,5. In-Tank System (auto tank gauge)
Date Installation:	07/01/2000
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	10. Urethane clad steel
Tank Internal Protection:	0. None
Tank External Protection:	5. Jacketed,9. Urethane
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	10. Copper
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm,5. Vent Whistle
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	003
Status:	3. Closed - Removed
Capacity:	1500
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported

WHITE PLAINS HOSPITAL MEDICAL CENTER (Continued) **U004177656**

Date Perm Closure:	07/01/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	1
Status:	3. Closed - Removed
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1965
Date Perm Closure:	07/01/2000
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

K98 **WHITE PLAINS MED CENTER** **NY LTANKS** **S104781873**
South **170 MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.091 mi.
478 ft. **Site 2 of 2 in cluster K**

Relative: LTANKS:
Higher

Actual: Name:	WHITE PLAINS MED CENTER
228 ft. Address:	170 MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0004388 / 2001-06-22
Facility ID:	0004388
Site ID:	204425
Spill Date:	2000-07-12
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-07-12

WHITE PLAINS MED CENTER (Continued) **S104781873**

CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-07-12
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	JOHN HOLZINGER
Spiller Phone:	(914) 337-1312
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	169978
DEC Memo:	""
Remarks:	"unk. amt. spilled soil being stockpiled at this time."

All Materials:

Site ID:	204425
Operable Unit ID:	826936
Operable Unit:	01
Material ID:	549126
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L99 **CON EDISON** **RCRA NonGen / NLR** **1014398716**
NE **CROMWELL PL & E POST RD** **NJ MANIFEST** **NYP004210779**
< 1/8 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.094 mi.
497 ft. **Site 1 of 18 in cluster L**

Relative: **Higher**
Actual: **238 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	CROMWELL PL & E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004210779
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private

CON EDISON (Continued) **1014398716**

Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No

CON EDISON (Continued) **1014398716**

Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:34:38.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2010-07-07 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004210779
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported

CON EDISON (Continued) **1014398716**

Emergency Phone:	Not reported
Contact:	DAVID DUKE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003533305JJK
EPA ID:	NYP004210779
Date Shipped:	07/07/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/07/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/08/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008

CON EDISON (Continued) **1014398716**

Hand Code: H111
Quantity: 600 P

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: CROMWELL PL & E POST RD
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYP004210779
Facility Status: Not reported
Location Address 1: MH5599 - E POST RD & CROMWELL PL
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004210779
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: THOMAS TEELING
Mailing Address 1: 4 IRVING PL RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 07/07/2010
Trans1 Recv Date: 07/07/2010
Trans2 Recv Date: Not reported
TSD Site Recv Date: 07/08/2010
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004210779
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 003533305JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N

CON EDISON (Continued) **1014398716**

Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	600
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L100 **CON EDISON** **RCRA NonGen / NLR** **1019902324**
NE **CROMWELL PL & E POST RD** **NYP004772372**
< 1/8 **WHITE PLAINS, NY 10601**
0.094 mi.
497 ft. **Site 2 of 18 in cluster L**

Relative: **Higher**

Actual: **238 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	CROMWELL PL & E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004772372
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003

CON EDISON (Continued) **1019902324**

Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported

CON EDISON (Continued) **1019902324**

Manifest Broker: Not reported
Sub-Part P Indicator: Not reported

Historic Generators:
Receive Date: 2015-04-22 00:00:00.0
Handler Name: CON EDISON
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2015-04-22 00:00:00.0
Handler Name: CON EDISON
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

L101 **CON EDISON** **NY MANIFEST** **S118089630**
NE **CROMWELL PL & E. NY POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.094 mi.
497 ft. **Site 3 of 18 in cluster L**

Relative:
Higher

Actual:
238 ft.

NY MANIFEST:
Name: CON EDISON
Address: CROMWELL PL & E. NY POST ROAD
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYP004772370
Facility Status: Not reported
Location Address 1: CROMWELL PL & E. NY POST ROAD
Code: BP

CON EDISON (Continued) **S118089630**

Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772370
Mailing Name:	CON EDISON
Mailing Contact:	TOM TELLING
Mailing Address 1:	4 IRVING PLACE-15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772370
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454064JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100

CON EDISON (Continued) **S118089630**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L102 **CONSOLIDATED EDISON** **NY MANIFEST** **S111157653**
NE **E NY POST RD & CROMWELL** **N/A**
< 1/8 **WHITE PLAINS, NY 10602**
0.094 mi.
497 ft. **Site 4 of 18 in cluster L**

Relative:
Higher

Actual:
238 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	E NY POST RD & CROMWELL
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004230025
Facility Status:	Not reported
Location Address 1:	E NY POST RD & CROMWELL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004230025
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/2011
Trans1 Recv Date:	03/08/2011
Trans2 Recv Date:	Not reported

CONSOLIDATED EDISON (Continued) **S111157653**

TSD Site Recv Date:	03/10/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004230025
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	001057793GBF
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	300
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D003
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L103 **CON ED** **NY MANIFEST** **S119074699**
NE **CROMWELL PL & E POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.094 mi.
497 ft. **Site 5 of 18 in cluster L**

Relative: **Higher**
Actual: **238 ft.**

NY MANIFEST:

Name:	CON ED
Address:	CROMWELL PL & E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004772372
Facility Status:	Not reported
Location Address 1:	CROMWELL PL/E NY POST RD
Code:	BP
Location Address 2:	MH 5599
Total Tanks:	Not reported
Location City:	WHITE PLAINS

CON ED (Continued) **S119074699**

Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004772372
Mailing Name: CON ED
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

M104 **CON EDISON MANHOLE: 11362** **RCRA NonGen / NLR** **1016677744**
NNW **QUARROPAS ST & FISCHER CT** **FINDS** **NYP004314233**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.097 mi. **NY MANIFEST**
513 ft. **Site 1 of 4 in cluster M**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-06-16 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 11362
Handler Address:	QUARROPAS ST & FISCHER CT
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYP004314233
Contact Name:	CHRISTOPHER BLAICH
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	VING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

CON EDISON MANHOLE: 11362 (Continued) **1016677744**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-04-02 12:56:58.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-05-16 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 11362
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON MANHOLE: 11362 (Continued) **1016677744**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2013-06-16 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 11362
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110058878497

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016677744
Registry ID:	110058878497
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110058878497
Name:	CON EDISON MANHOLE: 11362
Address:	QUARROPAS ST & FISCHER CT
City,State,Zip:	WHITE PLAINS, NY 10606

CON EDISON MANHOLE: 11362 (Continued) **1016677744**

NY MANIFEST:

Name:	CON EDISON
Address:	QUARROPAS ST & FISCHER CT
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYP004314233
Facility Status:	Not reported
Location Address 1:	QUARROPAS ST & FISHER CT
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004314233
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

M105 **CON EDISON** **NY MANIFEST** **S113815061**
NNW **QUARROPAS ST & FISHER CT** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.097 mi.
513 ft. **Site 2 of 4 in cluster M**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	QUARROPAS ST & FISHER CT
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004314833
Facility Status:	Not reported
Location Address 1:	QUARROPAS ST & FISHER CT
Code:	BP
Location Address 2:	MH #11362
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004314833
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported

CON EDISON (Continued) **S113815061**

Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	05/16/2013
Trans1 Recv Date:	05/16/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/17/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004314833
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	010842720JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

M106 **CON EDISON SERVICE BOX: 11370** **RCRA NonGen / NLR** **1017773655**
NNW **FISHER CT & QUARROPAS ST** **FINDS** **NYP004514436**
< 1/8 **WHITE PLAINS, NY 10603**
0.097 mi.
513 ft. **Site 3 of 4 in cluster M**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-05-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 11370
Handler Address:	FISHER CT & QUARROPAS ST
Handler City,State,Zip:	WHITE PLAINS, NY 10603
EPA ID:	NYP004514436
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON SERVICE BOX: 11370 (Continued) **1017773655**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-02-11 11:48:56.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-04-28 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2014-04-28 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

CON EDISON SERVICE BOX: 11370 (Continued) **1017773655**

Electronic Manifest Broker:	Not reported
Receive Date:	2014-05-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 11370
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110063784908

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

M107 **CON EDISON** **NY MANIFEST** **S117059285**
NNW **FISHER CT & QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10603**
0.097 mi.
513 ft. **Site 4 of 4 in cluster M**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	FISHER CT & QUARROPAS ST
City,State,Zip:	WHITE PLAINS, NY 10603
Country:	USA
EPA ID:	NYP004514436
Facility Status:	Not reported
Location Address 1:	FISHER CT QUARRO PASS
Code:	BP
Location Address 2:	Not reported

CON EDISON (Continued) **S117059285**

Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004514436
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/28/2014
Trans1 Recv Date:	04/28/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004514436
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012771810JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	60
Units:	P - Pounds

CON EDISON (Continued) **S117059285**

Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

N108 **LINCOLN MERCURY** **NY Spills** **S102155179**
SW **25 WEST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.099 mi.
523 ft. **Site 1 of 9 in cluster N**

Relative: **Lower**

Actual: **210 ft.**

SPILLS:

Name:	LINCOLN MERCURY
Address:	25 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0600932 / 2006-07-30
Facility ID:	0600932
Facility Type:	ER
DER Facility ID:	263929
Site ID:	363048
DEC Region:	3
Spill Cause:	Deliberate
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-04-24
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-04-24
CID:	409
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2006-04-25
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-24
Spill Record Last Update:	2006-07-30
Spiller Name:	LT TOGLIA
Spiller Company:	LINCOLN MERCURY
Spiller Address:	25 WEST POST ROAD
Spiller Company:	001
Contact Name:	LT TOGLIA
DEC Memo:	"04/26/06: Waste oil tank (AST)? overflowed to land. Spiller has cleaned up and bagged material. Contact is LT. Toglia of Fire Control. Called/informed WCHD because this should be a PBS facility due to having a waste oil tank. RA 07/30/06 Clean up completed. NFA jod"
Remarks:	"CLEAN UP IS IN PROCESS."

LINCOLN MERCURY (Continued) **S102155179**

All Materials:

Site ID:	363048
Operable Unit ID:	1121115
Operable Unit:	01
Material ID:	2110600
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N109 **WHITE PLAINS LINC-MERC** **RCRA-VSQG** **1000397518**
SW **25 W POST RD** **NY AST** **NYD052088754**
< 1/8 **WHITE PLAINS, NY 10606** **NY Spills**
0.099 mi. **FINDS**
523 ft. **Site 2 of 9 in cluster N** **ECHO**
NY MANIFEST
Relative: **NJ MANIFEST**
Lower

Actual: **210 ft.**

RCRA-VSQG:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WHITE PLAINS LINC-MERC
Handler Address:	25 W POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYD052088754
Contact Name:	JOE ROSSI
Contact Address:	W POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	914-946-2100
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	UNKNOWN
Owner Type:	Private
Operator Name:	UNKNOWN
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	UNKNOWN
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WHITE PLAINS LINC-MERC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	WHITE PLAINS LINC-MERC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1986-09-10 00:00:00.0
Handler Name:	WHITE PLAINS LINC-MERC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

WESTCHESTER CO. AST:

Name:	WHITE PLAINS LINCOLN MERCURY
Address:	25 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-801370
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Automobile Sales & Services
Owner Name:	Cary S. Frankel
Owner Street:	25 West Post Road
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10606
Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	500
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

Tank Number:	2
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	500
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	3
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	500
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	4

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	275
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	5
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	275
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	6
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	275
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	7
Status:	1. In-Service
Date Installation:	01/01/1990
Capacity:	275
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

SPILLS:

Name:	WHITE PLAINS LINCOLN MERCURY
Address:	25 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9408341 / 2017-08-15
Facility ID:	9408341
Facility Type:	ER
DER Facility ID:	263929
Site ID:	327886
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D6
SWIS:	6017
Spill Date:	1994-09-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-09-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2017-08-15
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 8/15/17 This spill was closed under 0600932 in 2006. PP "
Remarks:	"FOUND DISCOLORED SOIL DURING SUBSURFACE INVESTIGATION SOIL TO BE TESTED"

All Materials:

Site ID:	327886
Operable Unit ID:	1002467
Operable Unit:	01
Material ID:	377782
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110009467068

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000397518
Registry ID:	110009467068
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009467068
Name:	WHITE PLAINS LINC-MERC
Address:	25 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	WHITE PLAINS LINCOLN MERCURY
Address:	25 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Country:	USA
EPA ID:	NYD052088754
Facility Status:	Not reported
Location Address 1:	25 WEST POST ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD052088754
Mailing Name:	WHITE PLAINS LINCOLN MERCURY
Mailing Contact:	WHITE PLAINS LINCOLN MERCURY
Mailing Address 1:	25 WEST POTS ROAD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149462100

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	TXR000050930
Trans2 State ID:	Not reported
Generator Ship Date:	07/13/2010
Trans1 Recv Date:	07/13/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/15/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD052088754
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002182897
TSDF ID 2:	Not reported
Manifest Tracking Number:	003366603FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H020
Waste Code:	Not reported
Waste Code:	Not reported

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	3
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	1
Waste Code:	D039
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

NJ MANIFEST:

EPA Id:	NYD052088754
Mail Address:	W POST RD
Mail City/State/Zip:	WHITE PLAINS, NY 10606
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	JOE ROSSI
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	003366603FLE
EPA ID:	NYD052088754
Date Shipped:	07/13/2010
TSDF EPA ID:	NJD002182897
Transporter EPA ID:	TXR000050930
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	07/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

WHITE PLAINS LINC-MERC (Continued) **1000397518**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	07/15/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	WHITE PLAINS, NY 10606
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D039
Hand Code:	H020
Quantity:	45 G

L110 **CON EDISON** **RCRA NonGen / NLR** **1019901420**
NE **100 POST RD** **NYP004761797**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
536 ft. **Site 6 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	100 POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004761797
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2

CON EDISON (Continued) **1019901420**

Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

CON EDISON (Continued) **1019901420**

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-04-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-04-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

L111 **CON EDISON** **NY MANIFEST** **S119074093**
NE **100 POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
536 ft. **Site 7 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	100 POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004761797
Facility Status:	Not reported

CON EDISON (Continued) **S119074093**

Location Address 1:	E POST RD & GRAND AVE ST
Code:	BP
Location Address 2:	MH 5462
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004761797
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/01/2015
Trans1 Recv Date:	04/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/07/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004761797
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091624JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CON EDISON (Continued) **S119074093**

Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L112 **CON EDISON** **NJ MANIFEST** **S120669938**
NE **100 POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
536 ft. **Site 8 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NJ MANIFEST:

EPA Id:	NYP004761797
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091624JJK
EPA ID:	NYP004761797
Date Shipped:	4/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported

CON EDISON (Continued) **S120669938**

Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

H113 **CON EDISON MANHOLE: 8162** **RCRA NonGen / NLR** **1016965084**
NW **S LEXINGTON AVE & FISHER AVE** **NY MANIFEST** **NYP004379814**
< 1/8 **WHITE PLAINS, NY 10607**
0.102 mi.
537 ft. **Site 9 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-11-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 8162
Handler Address:	S LEXINGTON AVE & FISHER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10607
EPA ID:	NYP004379814
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported

CON EDISON MANHOLE: 8162 (Continued) **1016965084**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

CON EDISON MANHOLE: 8162 (Continued) **1016965084**

Historic Generators:

Receive Date:	2013-10-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 8162
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-11-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 8162
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	S LEXINGTON AVE & FISHER AVE
City,State,Zip:	WHITE PLAINS, NY 10607
Country:	USA
EPA ID:	NYP004379814
Facility Status:	Not reported
Location Address 1:	SO LEXINGTON AVE FISHER
Code:	BP
Location Address 2:	SB8162
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10471
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004379814

CON EDISON MANHOLE: 8162 (Continued) **1016965084**

Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/24/2013
Trans1 Recv Date:	10/24/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/31/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004379814
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693660JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	15
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported

CON EDISON MANHOLE: 8162 (Continued) **1016965084**

Waste Code 1_5: Not reported
Waste Code 1_6: Not reported

H114 **CON EDISON** **RCRA NonGen / NLR** **1019901668**
NW **LEXINGTON AVE & QUARROPAS ST** **NYP004764643**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
537 ft. **Site 10 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-08 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	LEXINGTON AVE & QUARROPAS ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004764643
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

CON EDISON (Continued) **1019901668**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-04-08 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-04-08 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1019901668**

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

H115 **CON EDISON** **NY MANIFEST** **S117535428**
NW **QUARRAPUS ST & LEXINGTON AV** **N/A**
< 1/8 **WHITE PLAINS, NY 10801**
0.102 mi.
537 ft. **Site 11 of 18 in cluster H**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:
Name: CON EDISON
Address: QUARRAPUS ST & LEXINGTON AV
City,State,Zip: WHITE PLAINS, NY 10801
Country: USA
EPA ID: NYP000471120
Facility Status: Not reported
Location Address 1: QUARRAPUS ST & LEXINGTON AV
Code: BP
Location Address 2: MH11362
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10801
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000471120
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL
Mailing Address 2: 15TH FL
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

H116 **CON EDISON** **NJ MANIFEST** **S120668868**
NW **S LEXINGTON AVE & QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10605**
0.102 mi.
537 ft. **Site 12 of 18 in cluster H**

Relative:
Lower

Actual:
197 ft.

NJ MANIFEST:

EPA Id:	NYP004749677
Mail Address:	IRVING PL, 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014091664JJK
EPA ID:	NYP004749677
Date Shipped:	3/12/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120668868**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

H117 **CON EDISON** **NY MANIFEST** **S117741723**
NW **S LEXINGTON AVE & QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10605**
0.102 mi.
537 ft. **Site 13 of 18 in cluster H**

Relative:
Lower

Actual:
197 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	S LEXINGTON AVE & QUARROPAS ST
City,State,Zip:	WHITE PLAINS, NY 10605
Country:	USA
EPA ID:	NYP004749677
Facility Status:	Not reported
Location Address 1:	S LEXINGTON AVE & QUARROPUS ST
Code:	BP
Location Address 2:	MH100400
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004749677
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH FL
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/12/2015
Trans1 Recv Date:	03/12/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	03/12/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004749677
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117741723**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014091664JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H118 **CON EDISON MANHOLE 10129** **RCRA NonGen / NLR** **1010326270**
NW **S LEXINGTON AVE & FISHER AVE** **NY MANIFEST** **NYP004140307**
< 1/8 **WHITE PLAINS, NY 10606**
0.102 mi.
537 ft. **Site 14 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2006-07-05 00:00:00.0
Handler Name:	CON EDISON MANHOLE 10129
Handler Address:	S LEXINGTON AVE & FISHER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYP004140307
Contact Name:	ANTONIO DELGADO
Contact Address:	4 IRVING PL, RM 828
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	718-204-4201
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON MANHOLE 10129 (Continued) **1010326270**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON MANHOLE 10129 (Continued) **1010326270**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2006-07-03 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not reported
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-07-04 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-07-05 00:00:00.0
Handler Name:	CON EDISON MANHOLE 10129
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON MANHOLE 10129 (Continued) **1010326270**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	SOUTH LEXINGTON AVE AND FISHER
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYP004140307
Facility Status:	Not reported
Location Address 1:	LEX & FISHER MH10129
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004140307
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLIN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/25/2006
Trans1 Recv Date:	02/25/2006
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/27/2006
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004140307
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	NYE1541484
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N

CON EDISON MANHOLE 10129 (Continued) **1010326270**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H119 **CON EDISON** **NY MANIFEST** **S117738201**
NW **QUARROPAS ST & LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
537 ft. **Site 15 of 18 in cluster H**

Relative: **Lower**

Actual: **197 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	QUARROPAS ST & LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004711206
Facility Status:	Not reported
Location Address 1:	QUARROPAS ST & LEXINGTON AVE
Code:	BP
Location Address 2:	MH 11362
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004711206
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003

CON EDISON (Continued) **S117738201**

Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: Not reported

H120 **CON EDISON** **RCRA NonGen / NLR** **1018280106**
NW **S LEXINGTON AVE & QUARROPAS ST** **FINDS** **NYP004749677**
< 1/8 **WHITE PLAINS, NY 10605** **ECHO**
0.102 mi.
537 ft. **Site 16 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-03-12 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	S LEXINGTON AVE & QUARROPAS ST
Handler City,State,Zip:	WHITE PLAINS, NY 10605
EPA ID:	NYP004749677
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN

CON EDISON (Continued) **1018280106**

Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-05-02 12:51:50.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-03-12 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-03-12 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

CON EDISON (Continued) **1018280106**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067701605

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018280106
Registry ID:	110067701605
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067701605
Name:	CON EDISON
Address:	LEXINGTON AVE & QUARROPAS ST
City,State,Zip:	WHITE PLAINS, NY 10601

H121 **CON EDISON** **NY MANIFEST** **S118088878**
NW **LEXINGTON AVE & QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
537 ft. **Site 17 of 18 in cluster H**

Relative: **Lower**
Actual: **197 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	LEXINGTON AVE & QUARROPAS ST
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004764643
Facility Status:	Not reported
Location Address 1:	LEXINGTON AVE & QUARROPAS ST
Code:	BP

CON EDISON (Continued) **S118088878**

Location Address 2:	MH 10040
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004764643
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/08/2015
Trans1 Recv Date:	04/08/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/14/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004764643
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692694JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100

CON EDISON (Continued) **S118088878**

Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

H122 **CON EDISON** **NJ MANIFEST** **S120670187**
NW **LEXINGTON AVE & QUARROPAS ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
537 ft. **Site 18 of 18 in cluster H**

Relative: **Lower**

Actual: **197 ft.**

NJ MANIFEST:

EPA Id:	NYP004764643
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	011692694JJK
EPA ID:	NYP004764643
Date Shipped:	4/8/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120670187**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L123 **CON EDISON** **NJ MANIFEST** **S120670884**
NE **E POST RD & GRAND ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
539 ft. **Site 9 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NJ MANIFEST:

EPA Id:	NYP004772521
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454065JJK
EPA ID:	NYP004772521
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported

CON EDISON (Continued) **S120670884**

Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L124 **CON EDISON** **RCRA NonGen / NLR** **1019902331**
NE **E NEW YORK POST RD & GRAND ST** **FINDS** **NYP004772455**
< 1/8 **WHITE PLAINS, NY 10607** **ECHO**
0.102 mi.
539 ft. **Site 10 of 18 in cluster L**

Relative: **Higher**

Actual: **239 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	E NEW YORK POST RD & GRAND ST
Handler City,State,Zip:	WHITE PLAINS, NY 10607
EPA ID:	NYP004772455
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported

CON EDISON (Continued) **1019902331**

Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0

CON EDISON (Continued) **1019902331**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069681721

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

CON EDISON (Continued) **1019902331**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019902331
Registry ID:	110069681721
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069681721
Name:	CON EDISON
Address:	E POST RD & GRAND ST
City,State,Zip:	WHITE PLAINS, NY 10601

L125 **CON ED** **NY MANIFEST** **S119074708**
NE **E POST RD & GRAND ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
539 ft. **Site 11 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:

Name:	CON ED
Address:	E POST RD & GRAND ST
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004772521
Facility Status:	Not reported
Location Address 1:	E POST RD/GRAND ST
Code:	BP
Location Address 2:	MH 3462
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772521
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015

CON ED (Continued) **S119074708**

Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772521
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454065JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L126 **CON EDISON** **NJ MANIFEST** **S120670877**
NE **E NEW YORK POST RD & GRAND ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10607**
0.102 mi.
539 ft. **Site 12 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NJ MANIFEST:

EPA Id:	NYP004772455
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119

CON EDISON (Continued) **S120670877**

Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014454063JJK
EPA ID:	NYP004772455
Date Shipped:	4/22/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

L127 **CON ED** **NY MANIFEST** **S119074703**
NE **E NEW YORK POST RD & GRAND ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10607**
0.102 mi.
539 ft. **Site 13 of 18 in cluster L**

Relative:
Higher

Actual:
239 ft.

NY MANIFEST:

Name:	CON ED
Address:	E NEW YORK POST RD & GRAND ST
City,State,Zip:	WHITE PLAINS, NY 10607
Country:	USA
EPA ID:	NYP004772455
Facility Status:	Not reported
Location Address 1:	E NY POST RD/GRAND ST
Code:	BP
Location Address 2:	MH 3466
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004772455
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2015
Trans1 Recv Date:	04/22/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004772455
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014454063JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON ED (Continued) **S119074703**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

L128 **CON EDISON** **RCRA NonGen / NLR** **1019902337**
NE **E POST RD & GRAND ST** **NYP004772521**
< 1/8 **WHITE PLAINS, NY 10601**
0.102 mi.
539 ft. **Site 14 of 18 in cluster L**

Relative: **Higher**
Actual: **239 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	E POST RD & GRAND ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004772521
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON (Continued) **1019902337**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

CON EDISON (Continued) **1019902337**

Historic Generators:

Receive Date:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-04-22 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

N129 **CON EDISON** **NY MANIFEST** **S117058385**
SW **W POST RD & ORAWAUPUM ST** **N/A**
< 1/8 **WHITE PLAINS, NY 10606**
0.107 mi.
565 ft. **Site 3 of 9 in cluster N**

Relative:
Higher

Actual:
211 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	W POST RD & ORAWAUPUM ST
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYP004504866
Facility Status:	Not reported
Location Address 1:	W POST RD & ORAWAUPUM ST
Code:	BP
Location Address 2:	SB 10312
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY

CON EDISON (Continued) **S117058385**

Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004504866
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10602
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/18/2014
Trans1 Recv Date:	04/18/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/22/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004504866
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770736JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	188
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.

CON EDISON (Continued) **S117058385**

Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

O130 **WHITE PLAINS HOUSING AUTHORITY** **NY LTANKS S104509303**
WNW **33 FISHER AVE** **NY Spills N/A**
< 1/8 **WHITE PLAINS, NY**
0.111 mi.
586 ft. **Site 1 of 2 in cluster O**

Relative: **Lower**
Actual: **199 ft.**

LTANKS:

Name:	WHITE PLAINS HOUSING AUTHORITY
Address:	33 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1007861 / 2011-07-05
Facility ID:	1007861
Site ID:	441310
Spill Date:	2010-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2010-10-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-25
Spill Record Last Update:	2011-07-25
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS HOUSING AUTHORITY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	VINNY NANNI
Spiller Phone:	(914) 949-6462
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199379
DEC Memo:	"10/25/10 - Caller believes there is a loose connection between the tanks. Tanks to be uncover, repair and retest. Westchester County DOH will conduct follow up since tanks are PBS regulated. KAB 12/13/10 Tanks were separated and retested. Tank 1 passed. Tank 2 (tank to the right when facing the bldg) failed with bubbling as per phone call from Kathy Morgan, US Tank Tech...mm 7/5/11 as per WCDOH White Plains- ttf 10/25/10. Tank passed isolation test. Lines replaced with no contamination observed. NFA JO'M 7/22/11: Received the retest

WHITE PLAINS HOUSING AUTHORITY (Continued) **S104509303**

results from US Tank Tech - will be entered into eDocs. NFA. jod"
Remarks: "Tank test Failure"

All TTF:
Facility ID: 1007861
Spill Number: 1007861
Spill Tank Test: 2489700
Site ID: 441310
Tank Number: 1
Tank Size: 20000
Material: 0002
EPA UST: False
UST: True
Cause: 06
Source: 00
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: kabrowne
Last Modified Date: Not reported

Facility ID: 1007861
Spill Number: 1007861
Spill Tank Test: 2489701
Site ID: 441310
Tank Number: 2
Tank Size: 20000
Material: 0002
EPA UST: False
UST: True
Cause: 06
Source: 00
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: Not reported
Gross Fail: Not reported
Modified By: kabrowne
Last Modified Date: Not reported

All Materials:
Site ID: 441310
Operable Unit ID: 1191875
Operable Unit: 01
Material ID: 2187076
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

SPILLS:
Name: WHITE PLAINS HOUSING

WHITE PLAINS HOUSING AUTHORITY (Continued) **S104509303**

Address:	33 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9912180 / 2000-05-30
Facility ID:	9912180
Facility Type:	ER
DER Facility ID:	199379
Site ID:	242722
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2000-01-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-01-21
CID:	322
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2000-01-21
Spill Record Last Update:	2000-06-02
Spiller Name:	FRANK MONTIBELLO
Spiller Company:	MONTIBELLO COAL & FUEL
Spiller Address:	424 EAST 81ST ST
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/21/2000 CLEANUP COMPLETED; NFA 03/20/2000 CASE REOPENED ON INFORMATION PROVIDED THAT THE SPILL SIZE MAY HAVE BEEN UP TO 700 GALLONS 03/08/2000 T. GHIOSAY SPOKE WITH DAN KIRSHNER OF SUN ROYAL ALLIANCE INSURANCE COMPANY AND ADVISED HIM THAT PLAYGROUND ARE NEEDS MORE CLEANUP. HE WILL CALL TRI-STATE AND AUTHORIZE WORK. 05/30/2000 LETTER SENT TO DORSON ENV. MGMT BY T. GHIOSAY; SPILL FILE IS CLOSED."
Remarks:	"fitting popped off pipe causing spill - spill being cleaned up "

All Materials:

Site ID:	242722
Operable Unit ID:	1086701
Operable Unit:	01
Material ID:	294073
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	30.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WIND BROOK APTS.
Address:	33 FISHER AVE

WHITE PLAINS HOUSING AUTHORITY (Continued) **S104509303**

City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9301205 / 1993-05-13
Facility ID:	9301205
Facility Type:	ER
DER Facility ID:	199379
Site ID:	186162
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	D3
SWIS:	6017
Spill Date:	1993-04-26
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-04-26
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1993-05-13
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-04-29
Spill Record Last Update:	1993-05-13
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/13/93: SPILL CLEANED UP ACCORDING TO JANET HERNANDEZ OF CASTLE OIL. COMPLETED THE SAME DAY. "
Remarks:	"SPILL ON GROUND CREW ENROUTE"

All Materials:

Site ID:	186162
Operable Unit ID:	983121
Operable Unit:	01
Material ID:	401926
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N131 **ROYAL MOTORS INC** **RCRA NonGen / NLR** **1000147960**
SW **32 W POST RD** **FINDS** **NYD006995617**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.111 mi. **NY MANIFEST**
587 ft. **Site 4 of 9 in cluster N**

Relative:
Higher

Actual:
211 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	ROYAL MOTORS INC
Handler Address:	32 W POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10606-2903
EPA ID:	NYD006995617
Contact Name:	Not reported
Contact Address:	W POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	OWNERNAME
Owner Type:	Private
Operator Name:	OWNERNAME
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

ROYAL MOTORS INC (Continued) **1000147960**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999

ROYAL MOTORS INC (Continued) **1000147960**

Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	OWNERNAME
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	ROYAL MOTORS INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	ROYAL MOTORS INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	ROYAL MOTORS INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

ROYAL MOTORS INC (Continued) **1000147960**

Receive Date:	1985-09-19 00:00:00.0
Handler Name:	ROYAL MOTORS INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violation:

Found Violation:	No
Agency Which Determined Violation:	Not reported
Violation Short Description:	Not reported
Date Violation was Determined:	Not reported
Actual Return to Compliance Date:	Not reported
Return to Compliance Qualifier:	Not reported
Violation Responsible Agency:	Not reported
Scheduled Compliance Date:	Not reported
Enforcement Identifier:	Not reported
Date of Enforcement Action:	Not reported
Enforcement Responsible Agency:	Not reported
Enforcement Docket Number:	Not reported
Enforcement Attorney:	Not reported
Corrective Action Component:	Not reported
Appeal Initiated Date:	Not reported
Appeal Resolution Date:	Not reported
Disposition Status Date:	Not reported
Disposition Status:	Not reported
Disposition Status Description:	Not reported
Consent/Final Order Sequence Number:	Not reported
Consent/Final Order Respondent Name:	Not reported
Consent/Final Order Lead Agency:	Not reported
Enforcement Type:	Not reported
Enforcement Responsible Person:	Not reported
Enforcement Responsible Sub-Organization:	Not reported
SEP Sequence Number:	Not reported
SEP Expenditure Amount:	Not reported
SEP Scheduled Completion Date:	Not reported
SEP Actual Date:	Not reported
SEP Defaulted Date:	Not reported
SEP Type:	Not reported
SEP Type Description:	Not reported
Proposed Amount:	Not reported
Final Monetary Amount:	Not reported
Paid Amount:	Not reported
Final Count:	Not reported
Final Amount:	Not reported

ROYAL MOTORS INC (Continued) **1000147960**

Evaluation Action Summary:

Evaluation Date:	1988-10-19 00:00:00.0
Evaluation Responsible Agency:	State
Found Violation:	No
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Evaluation Responsible Person Identifier:	NYDEC
Evaluation Responsible Sub-Organization:	Not reported
Actual Return to Compliance Date:	Not reported
Scheduled Compliance Date:	Not reported
Date of Request:	Not reported
Date Response Received:	Not reported
Request Agency:	Not reported
Former Citation:	Not reported

FINDS:

Registry ID: 110004342792

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000147960
Registry ID:	110004342792
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004342792
Name:	ROYAL MOTORS INC
Address:	32 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	ROYAL MOTORS INCORPORATED
Address:	32 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606-2903
Country:	USA
EPA ID:	NYD006995617
Facility Status:	Not reported
Location Address 1:	32 WEST POST ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID: NYD006995617

ROYAL MOTORS INC (Continued) **1000147960**

Mailing Name:	ROYAL MOTORS INCORPORATED
Mailing Contact:	ROYAL MOTORS INCORPORATED
Mailing Address 1:	32 WEST POST ROAD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149467200

NY MANIFEST:

Document ID:	NJA0627996
Manifest Status:	C
seq:	Not reported
Year:	1989
Trans1 State ID:	NJDEPS103
Trans2 State ID:	Not reported
Generator Ship Date:	05/17/1989
Trans1 Recv Date:	05/17/1989
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/18/1989
Part A Recv Date:	05/25/1989
Part B Recv Date:	06/05/1989
Generator EPA ID:	NYD006995617
Trans1 EPA ID:	NJD980787147
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002454544
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F005 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00040
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

N132 **ROADWAY** **NY Spills** **S103568772**
SW **32 WEST POST ROAD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.111 mi.
587 ft. **Site 5 of 9 in cluster N**

Relative:
Higher

Actual:
211 ft.

SPILLS:

Name:	ROADWAY
Address:	32 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8902440 / 1989-06-12
Facility ID:	8902440
Facility Type:	ER
DER Facility ID:	103438
Site ID:	268640
DEC Region:	3
Spill Cause:	Other
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1989-06-08
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-06-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Police Department
Cleanup Ceased:	1989-06-08
Cleanup Meets Std:	True
Last Inspection:	1989-06-08
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1989-06-12
Spill Record Last Update:	1989-07-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was T. GHIOSAY "
Remarks:	"CONTAINER FELL OFF TRUCK, LEAKED SMALL AMT. OF HYDROLIC OIL ON ROAD. WHITE PLAINS FIRE DEPT. CLEANED UP."

All Materials:

Site ID:	268640
Operable Unit ID:	928152
Operable Unit:	01
Material ID:	450141
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

ROADWAY (Continued) **S103568772**

Name:	SCHULTZ BUICK
Address:	32 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9504578 / 2006-02-07
Facility ID:	9504578
Facility Type:	ER
DER Facility ID:	103438
Site ID:	119065
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-07-17
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-07-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2006-02-07
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"09/01/95 National Environmental Specialist reported that three tanks were removed along with 187.13 tons of petroleum impacted soil. More than 20,000 gallons of impacted groundwater was also pumped form the excavation. TG "
Remarks:	"DIGGING UP OLD TANKS FOUND CONTAMINATED SOIL"

All Materials:

Site ID:	119065
Operable Unit ID:	1019343
Operable Unit:	01
Material ID:	366093
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

N133 **WHITE PLAINS LINC/MERCURY** **NY LTANKS** **S104782116**
SW **25 WEST COAST RD** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.114 mi.
604 ft. **Site 6 of 9 in cluster N**

Relative:
Higher

Actual:
211 ft.

LTANKS:

Name:	WHITE PLAINS LINC/MERCURY
Address:	25 WEST COAST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0005954 / 2001-04-24
Facility ID:	0005954
Site ID:	226425
Spill Date:	2000-08-18
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2000-08-18
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-08-18
Spill Record Last Update:	2001-05-08
Spiller Name:	CARY FRANKEL
Spiller Company:	WHITE PLAINS LINC/MERCURY
Spiller Address:	25 WEST COAST RD
Spiller County:	001
Spiller Contact:	CARY FRANKEL
Spiller Phone:	(914) 946-2100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	186890
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/18/2000 INSTRUCTED OWNER TO HAVE CONTRACTOR PREPARE REPORT W/RESULTS AND SUBMIT TO DEC. 01/18/2001 LETTER FROM NORTHEAST ENVIRONMENTAL RECEIVED. 86.48 TONS OF SOIL WERE EXCAVATED & DISPOSED. A FOUR INCH WELL WAS INSTALLED IN THE TANK GRAVE FOR MONITORING AND TESTING PURPOSES. 04/24/2001 LETTER SENT TO NORTHEAST ENVIRONMENTAL BY T. GHIOSAY; BASED ON LETTER & WATER SAMPLE RESULTS, NO FURTHER ACTION IS REQUIRED AT THIS TIME. SPILL REPORT LISTED AS CLOSED."
Remarks:	"during tank removal 1000 gal ust soil contamination discovered"

All Materials:

Site ID:	226425
Operable Unit ID:	826863
Operable Unit:	01
Material ID:	547087
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

WHITE PLAINS LINC/MERCURY (Continued) **S104782116**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

N134 **SHOLTZ OLDSMOBILE BUICK** **RCRA NonGen / NLR** **1000292827**
SW **35-55 W POST RD** **FINDS** **NYD061987947**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.118 mi. **NY MANIFEST**
623 ft. **Site 7 of 9 in cluster N**

Relative: **Higher**
Actual: **212 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	SHOLTZ OLDSMOBILE BUICK
Handler Address:	35-55 W POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYD061987947
Contact Name:	ALICE MAINIERO
Contact Address:	W POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	914-949-4300
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	ROBERT T SCHOLZ
Owner Type:	Private
Operator Name:	ROBERT T SCHOLZ
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported

SHOLTZ OLDSMOBILE BUICK (Continued) **1000292827**

Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	D039
Waste Description:	TETRACHLOROETHYLENE
Waste Code:	F001
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:

SHOLTZ OLDSMOBILE BUICK (Continued) **1000292827**

TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROBERT T SCHOLZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 W POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10606
Owner/Operator Telephone:	914-949-4300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	ROBERT T SCHOLZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 W POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10606
Owner/Operator Telephone:	914-949-4300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	ROBERT T SCHOLZ
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	77 W POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10606
Owner/Operator Telephone:	914-949-4300
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	SHOLTZ OLDSMOBILE BUICK
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

SHOLTZ OLDSMOBILE BUICK (Continued) **1000292827**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	SHOLTZ OLDSMOBILE BUICK
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1991-09-20 00:00:00.0
Handler Name:	SHOLTZ OLDSMOBILE BUICK
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004362984

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

SHOLTZ OLDSMOBILE BUICK (Continued) **1000292827**

Envid:	1000292827
Registry ID:	110004362984
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004362984
Name:	SHOLTZ OLDSMOBILE BUICK
Address:	35-55 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	SHOLZ BUICK
Address:	35-55 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYD061987947
Facility Status:	Not reported
Location Address 1:	55 WEST POST ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD061987947
Mailing Name:	SHOLZ BUICK
Mailing Contact:	SHOLZ BUICK
Mailing Address 1:	35 WEST POST ROAD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149494300

NY MANIFEST:

Document ID:	NYC6455204
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	NY64628TC
Trans2 State ID:	Not reported
Generator Ship Date:	05/18/2001
Trans1 Recv Date:	05/18/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/21/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD061987947
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000708198
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported

SHOLTZ OLDSMOBILE BUICK (Continued) **1000292827**

Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D039 - TETRACHLOROETHYLENE 0.73 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00008
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	002
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

N135 **RRC PROPERTIES LLC** **NY UST U003949306**
SW **35 WEST POST ROAD** **NY AST N/A**
< 1/8 **WHITE PLAINS, NY 10606**
0.118 mi.
623 ft. **Site 8 of 9 in cluster N**

Relative: **Higher**
Actual: **212 ft.**

WESTCHESTER CO. UST:

Name:	RRC PROPERTIES LLC
Address:	35 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-800369 / Unregulated
Operator Name:	Sholz Auto Olds / Buick
Owner Name:	BRK Acquisition Holdings, LLC
Owner Street:	9 Valenza Lane
Owner Address2:	Not reported
Owner City:	Blauvelt
Owner State:	NY
Owner Zipcode:	10913
GDS Number:	Not reported
Tank Number:	04
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	10/13/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported

RRC PROPERTIES LLC (Continued) **U003949306**

Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	05
Status:	4. Closed - in place
Capacity:	1000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	0
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	10/13/2010
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	Not reported

Tank Number:	4OLDS
Status:	4. Closed - in place
Capacity:	550
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

Name:	RRC PROPERTIES LLC
Address:	35 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-800369
Site Status:	Unregulated
GDS Number:	Not reported

RRC PROPERTIES LLC (Continued) **U003949306**

Operator Name:	Sholz Auto Olds / Buick
Owner Name:	BRK Acquisition Holdings, LLC
Owner Street:	9 Valenza Lane
Owner Address2:	Not reported
Owner City/State/Zip:	Blauvelt, NY 10913
Tank Number:	01
Status:	3. Closed - Removed
Date Installation:	10/01/2003
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/13/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	02
Status:	3. Closed - Removed
Date Installation:	10/01/2003
Capacity:	275
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/13/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction
Tank Number:	03
Status:	3. Closed - Removed
Date Installation:	10/01/2003
Capacity:	275
Product Stored:	0022. Waste/Used Oil

RRC PROPERTIES LLC (Continued) **U003949306**

Product Stored Percent:	Not reported
Date Perm Closure:	10/13/2010
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	1OLDS
Status:	3. Closed - Removed
Date Installation:	01/01/1975
Capacity:	550
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	10/01/2003
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	2OLDS
Status:	3. Closed - Removed
Date Installation:	01/01/1975
Capacity:	275
Product Stored:	9999. Other
Product Stored Percent:	Not reported
Date Perm Closure:	10/01/2003
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	0. No Pippping
Piping External Protection:	0. None

RRC PROPERTIES LLC (Continued) **U003949306**

Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	3olds
Status:	0. Administratively closed
Date Installation:	12/01/1998
Capacity:	330
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	02/06/2004
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

P136 **MOORE - AST** **NY Spills** **S121100280**
West **8 CHESTNUT HILL AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.118 mi.
625 ft. **Site 1 of 3 in cluster P**

Relative: **Higher**
Actual: **265 ft.**

SPILLS:

Name:	MOORE - AST
Address:	8 CHESTNUT HILL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1703345 / 2017-07-11
Facility ID:	1703345
Facility Type:	ER
DER Facility ID:	508106
Site ID:	554518
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	D5
SWIS:	6017
Spill Date:	2017-07-06
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2017-07-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False

MOORE - AST (Continued) **S121100280**

Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-07-06
Spill Record Last Update:	2017-07-11
Spiller Name:	JANET MOORE
Spiller Company:	Janet Moore
Spiller Address:	08 CHESTNUT HILL AVE
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"7/6/17 Spoke to Castlton - building inspector asked them to call in a spill - AST with staining under the filter and the lines on concrete basement floor. No staining under tank proper. PID readings of 70-80. Castlton to give owner proposal for possible remediation / investigation of soil under concrete. Spoke to homeowner. She said the staining was from when Palisades Oil was cleaning the filter, and some oil spilled over. AST has been removed - home is being switched to gas. Carmine from Castlton will do soil borings to see if further remediation is needed. Sending Draft Guidance by regular mail. ga 7/11/17: There is no spill, stain on floor. Message sent to Castlton. DEC requires no further action at this time. jod"
Remarks:	"basement concrete stain clean up pending insurance"

All Materials:

Site ID:	554518
Operable Unit ID:	1302593
Operable Unit:	01
Material ID:	2308983
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

P137 **NY OIL RECYCLING INC** **RCRA NonGen / NLR** **1016678218**
West **9 CHESNUT HILL AVE** **FINDS** **NYR000209650**
< 1/8 **WHITE PLAINS, NY 10606** **ECHO**
0.119 mi.
626 ft. **Site 2 of 3 in cluster P**

Relative: **Higher**
Actual: **268 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-05-21 00:00:00.0
Handler Name:	NY OIL RECYCLING INC
Handler Address:	9 CHESNUT HILL AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYR000209650
Contact Name:	CARLOS M MEJIA
Contact Address:	CHESNUT HILL AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	914-714-2566
Contact Fax:	813-447-5323
Contact Email:	KAPA2317@HOTMAIL.COM
Contact Title:	PRESIDENT OWNER

NY OIL RECYCLING INC (Continued) **1016678218**

EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	CHESNUT HILL AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	CARLOS M MEJIA
Owner Type:	Private
Operator Name:	NY OIL RECYCLING INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported

NY OIL RECYCLING INC (Continued) **1016678218**

Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2017-05-24 10:52:30.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CARLOS M MEJIA
Legal Status:	Private
Date Became Current:	2010-03-16 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	MEJIATRADE@YAHOO.COM

Owner/Operator Indicator:	Operator
Owner/Operator Name:	NY OIL RECYCLING INC
Legal Status:	Private
Date Became Current:	2013-04-15 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2014-05-21 00:00:00.0
Handler Name:	NY OIL RECYCLING INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	484110

NY OIL RECYCLING INC (Continued) **1016678218**

NAICS Description: GENERAL FREIGHT TRUCKING, LOCAL

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110059761039

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016678218
Registry ID:	110059761039
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110059761039
Name:	NY OIL RECYCLING INC
Address:	9 CHESNUT HILL AVE
City,State,Zip:	WHITE PLAINS, NY 10606

Q138 **PARKING LOT** **NY Spills** **S103563791**
SSW **SOUTH LEXINGTON AVE.** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.122 mi.
643 ft. **Site 1 of 12 in cluster Q**

Relative:
Higher

Actual:
224 ft.

SPILLS:

Name:	PARKING LOT
Address:	SOUTH LEXINGTON AVE.
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9304026 / 1994-11-10
Facility ID:	9304026
Facility Type:	ER
DER Facility ID:	133678
Site ID:	158125
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	1993-06-21
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-06-29
CID:	Not reported

PARKING LOT (Continued) **S103563791**

Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-11-10
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1993-07-08
Spill Record Last Update:	1994-11-10
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAMINATED SOIL FOUND"

All Materials:

Site ID:	158125
Operable Unit ID:	982316
Operable Unit:	01
Material ID:	397560
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Q139 **MVA** **NY Spills** **S111011833**
SSW **MAPLE AVE SOUTH LEXINGTON AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.122 mi.
643 ft. **Site 2 of 12 in cluster Q**

Relative:
Higher

Actual:
224 ft.

SPILLS:

Name:	MVA
Address:	MAPLE AVE SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1101460 / 2011-05-09
Facility ID:	1101460
Facility Type:	ER
DER Facility ID:	403517
Site ID:	448912
DEC Region:	3
Spill Cause:	Traffic Accident
Spill Class:	C3
SWIS:	6017
Spill Date:	2011-05-09
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2011-05-09

MVA (Continued) **S111011833**

CID:	Not reported
Water Affected:	Not reported
Spill Source:	Passenger Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2011-05-09
Spill Record Last Update:	2016-10-14
Spiller Name:	Not reported
Spiller Company:	DMV ACCIDENT NUMBER 1117533
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BARSKDALE
DEC Memo:	"5-9-11: V.Mc. call to Whiteplains' PD: Fire Chief on site (914) 422 6325. 5-9-11: V.Mc. call to Fire Chief: Left Mess.: Req.Callbk. 5-9-11: V.Mc. call to C.Tor./WCHD: WCHD to site inspect. 5-9-11: Chris/WCHD callbk. to V.Mc./Didpt.: Clean up completed by FD, with HD guideance. NFA"
Remarks:	"1016 THE CALLER ADVISED DISPATCH THE SPILL WAS DUE TO A VEHICLE ACCIDENT. UNKNOWN AMOUNT AND STORM DRAIN HAS BEEN IMPACTED. CLEAN UP IS IN PROGRESS."

All Materials:

Site ID:	448912
Operable Unit ID:	1199142
Operable Unit:	01
Material ID:	2195493
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Q140 **POLE#40** **NY Spills** **S108764246**
SSW **LEXINGTON AVE& MAPLE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.122 mi.
643 ft. **Site 3 of 12 in cluster Q**

Relative: **Higher**
Actual: **224 ft.**

SPILLS:

Name:	POLE#40
Address:	LEXINGTON AVE& MAPLE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0706257 / 2007-09-07
Facility ID:	0706257
Facility Type:	ER
DER Facility ID:	336142
Site ID:	386740
DEC Region:	3
Spill Cause:	Equipment Failure

POLE#40 (Continued) **S108764246**

Spill Class:	C3
SWIS:	6017
Spill Date:	2007-09-04
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-09-04
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-04
Spill Record Last Update:	2007-09-11
Spiller Name:	ERTSDESK
Spiller Company:	POLE#40
Spiller Address:	LEXINGTON AVE& MAPLE
Spiller Company:	001
Contact Name:	ERTSDESK
DEC Memo:	"Spoke w/ Dave Duke from Con Ed. 8 oz. of fluid lost. Will be reparing ASAP. Will need to shut power off on line before repair."
Remarks:	"ARIEL JOINT LEAKED: CONTROLS WILL BE PUT PLACE"

All Materials:

Site ID:	386740
Operable Unit ID:	1143972
Operable Unit:	01
Material ID:	2134255
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

L141 **GRAND STREET CLEANERS** **EDR Hist Cleaner** **1019997908**
NE **104 E POST RD** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.123 mi.
647 ft. **Site 15 of 18 in cluster L**

Relative: EDR Hist Cleaner
Higher

Actual: **242 ft.**

Year:	Name:	Type:
2005	GRAND STREET CLEANERS	Drycleaning Plants, Except Rugs, NEC
2006	GRAND STREET CLEANERS	Drycleaning Plants, Except Rugs, NEC
2007	GRAND STREET CLEANERS	Drycleaning Plants, Except Rugs, NEC
2008	GRAND STREET CLEANERS	Drycleaning Plants, Except Rugs, NEC

L142 **WESTCHESTER HOBBIES INC** **RCRA NonGen / NLR** **1001223849**
NE **104 E POST RD** **FINDS** **NYR000050658**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.123 mi.
647 ft. **Site 16 of 18 in cluster L**

Relative: **Higher**
Actual: **242 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER HOBBIES INC
Handler Address:	104 E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601-5103
EPA ID:	NYR000050658
Contact Name:	Not reported
Contact Address:	E POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	E POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	RONALD MIHLRAD
Owner Type:	Private
Operator Name:	RONALD MIHLRAD
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

WESTCHESTER HOBBIES INC (Continued) **1001223849**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D018
Waste Description:	BENZENE
Waste Code:	F003
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RONALD MIHLRAD
Legal Status:	Private
Date Became Current:	Not reported

WESTCHESTER HOBBIES INC (Continued) **1001223849**

Date Ended Current:	Not reported
Owner/Operator Address:	104 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	516-486-2313
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	RONALD MIHLRAD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	104 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	516-486-2313
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	RONALD MIHLRAD
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	104 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	516-486-2313
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	WESTCHESTER HOBBIES INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WESTCHESTER HOBBIES INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

WESTCHESTER HOBBIES INC (Continued) **1001223849**

Electronic Manifest Broker: Not reported

Receive Date: 2007-01-01 00:00:00.0
Handler Name: WESTCHESTER HOBBIES INC
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1998-02-17 00:00:00.0
Handler Name: WESTCHESTER HOBBIES INC
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004540471

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001223849

WESTCHESTER HOBBIES INC (Continued) **1001223849**

Registry ID:	110004540471
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004540471
Name:	WESTCHESTER HOBBIES INC
Address:	104 E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601

O143 **CHURCH** **NY LTANKS** **S107657151**
WNW **65 FISHER AVE** **NY Spills** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.123 mi.
648 ft. **Site 2 of 2 in cluster O**

Relative: LTANKS:
Lower

Actual: Name:	ALLEN AME CHURCH
201 ft. Address:	65 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0509976 / 2006-12-20
Facility ID:	0509976
Site ID:	355853
Spill Date:	2005-11-21
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-11-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-11-21
Spill Record Last Update:	2006-12-20
Spiller Name:	MS RIBELLA
Spiller Company:	ALLEN AME CHURCH
Spiller Address:	65 FISHER AVE
Spiller County:	001
Spiller Contact:	MS RIBELLA
Spiller Phone:	(914) 761-4397
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	305892
DEC Memo:	"LEFT MESSAGE 12/02/05 Cross River Environmental to complete clean up. Report to follow. jod 02/24/06 NES removed tank and started excavating contaminated soil. Beneath the fuel oil contamination gasoline contaminated soil was encountered. Reportedly there is a gas station nearby. Chris Lalak of Westchester County Health to inspect. jod 10/24/06 National Environmental Specialists reported that the tank was removed along with 46.5 tons of impacted soil. NFA required. TG"
Remarks:	"1000 GALLON TANK HAD HOLES AND CONTAMINATED SOIL;"

All Materials:

CHURCH (Continued) **S107657151**

Site ID: 355853
Operable Unit ID: 1113186
Operable Unit: 01
Material ID: 2103241
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: CHURCH
Address: 65 FISHER AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0513604 / 2006-12-20
Facility ID: 0513604
Facility Type: ER
DER Facility ID: 310223
Site ID: 360107
DEC Region: 3
Spill Cause: Other
Spill Class: C3
SWIS: 6017
Spill Date: 2006-02-24
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-02-24
CID: 444
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-02-24
Spill Record Last Update: 2006-12-20
Spiller Name: REVERAND SANDERS
Spiller Company: CHURCH
Spiller Address: 65 FISHER AVE
Spiller Company: 001
Contact Name: REVERAND SANDERS
DEC Memo: "10 - 15 yards removed & encountered gasoline impacted soil. Todd Ghiosay notified. 12-20-06 See remediation filed under DEC Spill 06-09976. TG"
Remarks: "CONTAMINATED SOIL AT THIS LOCATION AND HE BELIEVES IT MAY BE GASOLINE; OIL TANK HAS ALREADY BEEN REMOVED: DOH HAS BEEN NOTIFIED"

All Materials:
Site ID: 360107
Operable Unit ID: 1117296

CHURCH (Continued) **S107657151**

Operable Unit:	01
Material ID:	2107798
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q144 **FIRE HOUSE # 4** **NY LTANKS** **U000379970**
SSW **MAPLE AVE & S LEXINGTON** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.124 mi.
654 ft. **Site 4 of 12 in cluster Q**

Relative:
Higher

Actual:
224 ft.

LTANKS:

Name:	FIRE HOUSE # 4
Address:	MAPLE AVE & S LEXINGTON
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8707150 / 1989-01-05
Facility ID:	8707150
Site ID:	178231
Spill Date:	1987-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1989-01-05
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-05
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-20
Spill Record Last Update:	1989-02-07
Spiller Name:	MR. BROCCHI
Spiller Company:	CITY OF WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	149695
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"K SYSTEM- -.0709GPH. TO E & I & R. PBS TO FOLLOW.NO RESULTS"

All TTF:

FIRE HOUSE # 4 (Continued) **U000379970**

Facility ID:	8707150
Spill Number:	8707150
Spill Tank Test:	1532378
Site ID:	178231
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	178231
Operable Unit ID:	912874
Operable Unit:	01
Material ID:	466123
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Q145 **CON EDISON** **NJ MANIFEST** **S120670497**
SSW **LEXINGTON AVE & MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.124 mi.
654 ft. **Site 5 of 12 in cluster Q**

Relative: **Higher**
Actual: **224 ft.**

NJ MANIFEST:

EPA Id:	NYP004768131
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

CON EDISON (Continued) **S120670497**

Manifest:

Manifest Number:	014085131JJK
EPA ID:	NYP004768131
Date Shipped:	4/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Q146 **CON EDISON MANHOLE: 4512** **RCRA NonGen / NLR** **1016450710**
SSW **LEXINGTON AVE & MAPLE AVE S** **NY MANIFEST** **NYP004297370**
< 1/8 **WHITE PLAINS, NY 10601**
0.124 mi.
654 ft. **Site 6 of 12 in cluster Q**

Relative:
Higher

Actual:
224 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-04-29 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 4512
Handler Address:	LEXINGTON AVE & MAPLE AVE S
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004297370
Contact Name:	DOMINIC BIZZARO

CON EDISON MANHOLE: 4512 (Continued) **1016450710**

Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking

CON EDISON MANHOLE: 4512 (Continued) **1016450710**

Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2013-09-10 16:26:21.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-03-29 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 4512
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-04-29 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 4512
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

CON EDISON MANHOLE: 4512 (Continued) **1016450710**

Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	LEXINGTON AVE & MAPLE AVE S
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004297370
Facility Status:	Not reported
Location Address 1:	S LEXINGTON AVE AND MAPLE
Code:	BP
Location Address 2:	MH 4512
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004297370
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	03/29/2013
Trans1 Recv Date:	03/29/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/09/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004297370
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007658279JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N

CON EDISON MANHOLE: 4512 (Continued) **1016450710**

Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q147 **CON EDISON** **RCRA NonGen / NLR** **1019901974**
SSW **LEXINGTON AVE & MAPLE AVE** **FINDS** **NYP004768131**
< 1/8 **WHITE PLAINS, NY 10601** **ECHO**
0.124 mi.
654 ft. **Site 7 of 12 in cluster Q**

Relative: **Higher**
Actual: **224 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-04-14 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	LEXINGTON AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004768131
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported

CON EDISON (Continued) **1019901974**

Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

CON EDISON (Continued) **1019901974**

Historic Generators:

Receive Date:	2015-04-14 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-04-14 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069665954

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019901974
Registry ID: 110069665954

CON EDISON (Continued) **1019901974**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069665954
Name:	CON EDISON
Address:	LEXINGTON AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10601

Q148 **CON ED** **NY MANIFEST** **S119074448**
SSW **LEXINGTON AVE & MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY 10601**
0.124 mi.
654 ft. **Site 8 of 12 in cluster Q**

Relative:
Higher

Actual:
224 ft.

NY MANIFEST:

Name:	CON ED
Address:	LEXINGTON AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004768131
Facility Status:	Not reported
Location Address 1:	S LEXINGTON AVE & MAPLE AVE
Code:	BP
Location Address 2:	MH 7277
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004768131
Mailing Name:	CON ED
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE - 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/14/2015
Trans1 Recv Date:	04/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/20/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004768131
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported

CON ED (Continued) **S119074448**

Manifest Tracking Number:	014085131JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Q149 **MAGNOGTA'S PARKING LOT** **NY Spills** **S102153897**
SSW **S. LEXINGTON & MAPLE AVE** **N/A**
< 1/8 **WHITE PLAINS, NY**
0.124 mi.
654 ft. **Site 9 of 12 in cluster Q**

Relative: **Higher**
Actual: **224 ft.**

SPILLS:

Name:	MAGNOGTA'S PARKING LOT
Address:	S. LEXINGTON & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9002687 / 1990-08-01
Facility ID:	9002687
Facility Type:	ER
DER Facility ID:	167982
Site ID:	201938
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1990-06-08
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-06-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

MAGNOGTA'S PARKING LOT (Continued) **S102153897**

Spill Notifier:	Fire Department
Cleanup Ceased:	1990-07-12
Cleanup Meets Std:	True
Last Inspection:	1990-07-12
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-06-11
Spill Record Last Update:	1990-08-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 08/01/90: EES SENT TO CLEAN UP STORM DRAIN. "
Remarks:	"FIRE DEPT. IS ON SCENE & USING SPEEDI-DRY FOR CLEAN UP SPOKE WITH WPFDDELIVERY TRUCK HIT BLDG. OIL RAN INTO STORM DRAIN FAXED TO TODD"

All Materials:

Site ID:	201938
Operable Unit ID:	942809
Operable Unit:	01
Material ID:	437429
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

P150 **BERGMAN PROPERTY** **NY UST** **U003885501**
West **1820 CHESTNUT HILL** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.126 mi.
664 ft. **Site 3 of 3 in cluster P**

Relative: WESTCHESTER CO. UST:
Higher

Actual: Name:	BERGMAN PROPERTY
267 ft. Address:	1820 CHESTNUT HILL
City,State,Zip:	WHITE PLAINS, NY 10605
Id/Status:	3-800980 / Unregulated: <1101 gal. PBS
Operator Name:	Gil Bergman
Owner Name:	Gil Bergman
Owner Street:	282 Rideway
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10606
GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported

BERGMAN PROPERTY (Continued) **U003885501**

Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	10/19/2002
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

R151 **CON EDISON** **RCRA NonGen / NLR** **1014398972**
NNE **GROVE ST & QUARROPAS ST** **NJ MANIFEST** **NYP004213476**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.133 mi.
700 ft. **Site 1 of 10 in cluster R**

Relative: **Lower**
Actual: **206 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	GROVE ST & QUARROPAS ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004213476
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No

CON EDISON (Continued) **1014398972**

Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:38:43.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2010-08-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

CON EDISON (Continued) **1014398972**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004213476
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	006874772JJK
EPA ID:	NYP004213476
Date Shipped:	08/13/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NJ0000027193
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported

CON EDISON (Continued) **1014398972**

Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	08/13/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	08/13/2010
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	90 G

R152 **CON EDISON** **RCRA NonGen / NLR** **1019905075**
NNE **QUARROPAS ST & MLK BLVD** **NYP004805560**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.133 mi.
700 ft. **Site 2 of 10 in cluster R**

Relative: **Lower**
Actual: **206 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-07-12 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	QUARROPAS ST & MLK BLVD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004805560
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON (Continued) **1019905075**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON (Continued) **1019905075**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:28:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-07-12 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-07-12 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

R153
NNE
1/8-1/4
0.133 mi.
700 ft.

CON EDISON
QUARROPAS ST & MLK BLVD
WHITE PLAINS, NY 10601

Site 3 of 10 in cluster R

NJ MANIFEST **S120673776**
N/A

Relative:
Lower

Actual:
206 ft.

NJ MANIFEST:

EPA Id:	NYP004805560
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473233JJK
EPA ID:	NYP004805560
Date Shipped:	7/12/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120673776**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R154 **CONSOLIDATED EDISON** **NY MANIFEST** **S110823791**
NNE **GROVE & QUERROPAS** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.133 mi.
700 ft. **Site 4 of 10 in cluster R**

Relative:
Lower

Actual:
206 ft.

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	GROVE & QUERROPAS
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004227207
Facility Status:	Not reported
Location Address 1:	GROVE & QUERROPAS
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004227207
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	02/08/2011
Trans1 Recv Date:	02/08/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	02/09/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004227207
Trans1 EPA ID:	Not reported

CONSOLIDATED EDISON (Continued) **S110823791**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655773JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

R155 **CON EDISON** **NY MANIFEST** **S119076430**
NNE **QUARROPAS ST & MLK BLVD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.133 mi.
700 ft. **Site 5 of 10 in cluster R**

Relative: NY MANIFEST:
Lower

Actual:
206 ft.

Name:	CON EDISON
Address:	QUARROPAS ST & MLK BLVD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004805560
Facility Status:	Not reported
Location Address 1:	QUAMOPERS ST W OF GROVE
Code:	BP
Location Address 2:	MH 11363
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

CON EDISON (Continued) **S119076430**

EPAID:	NYP004805560
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

S156 **170 GRAND STREET** **NY LTANKS** **S102180212**
NNE **170 GRAND STREET** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.133 mi.
703 ft. **Site 1 of 9 in cluster S**

Relative: LTANKS:
Higher

Actual:
235 ft.

Name:	APARTMENT
Address:	170 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0408227 / 2007-11-28
Facility ID:	0408227
Site ID:	332894
Spill Date:	2004-10-26
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCHD
Reported to Dept:	2004-10-26
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-10-26
Spill Record Last Update:	2007-11-28
Spiller Name:	CARDINAL TANK
Spiller Company:	APARTMENT
Spiller Address:	170 GRAND STREET
Spiller County:	001
Spiller Contact:	CARDINAL TANK
Spiller Phone:	(718) 625-4350
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	260919
DEC Memo:	" Goreau, Stefan <shg1@westchestergov.com> 11/28/2007 2:20 PM >>> Results from sidewall and bottom samples were submitted to the Dept. prior to closure in place. Results were satisfactory. Spill may be closed. Stefan Goreau Sanitarian Office of Environmental Health Risk

170 GRAND STREET (Continued) **S102180212**

Control Westchester County Department of Health "
Remarks: "PBS No: 3-800392 "

All TTF:
Facility ID: 0408227
Spill Number: 0408227
Spill Tank Test: 1548281
Site ID: 332894
Tank Number: 1
Tank Size: 2000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 21
Test Method 2: Horner EZY3/EZY3 Locator Plus
Leak Rate: .00
Gross Fail: Not reported
Modified By: JBODee
Last Modified Date: Not reported

All Materials:
Site ID: 332894
Operable Unit ID: 1095101
Operable Unit: 01
Material ID: 575231
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: 170 GRAND STREET
Address: 170 GRAND STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9509189 / 1995-10-25
Facility ID: 9509189
Facility Type: ER
DER Facility ID: 260919
Site ID: 323874
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: E5
SWIS: 6017
Spill Date: 1995-10-25
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1995-10-25
CID: 205
Water Affected: Not reported
Spill Source: Private Dwelling

170 GRAND STREET (Continued) **S102180212**

Spill Notifier:	Responsible Party
Cleanup Ceased:	1995-10-25
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-10-25
Spill Record Last Update:	1995-11-01
Spiller Name:	Not reported
Spiller Company:	COSTAL OIL CO
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CARLOS
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"customers guage was inaccurate."

All Materials:

Site ID:	323874
Operable Unit ID:	1019773
Operable Unit:	01
Material ID:	360149
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

S157 **170 GRAND STREET ASSOC.** **NY UST** **U004175922**
NNE **170 GRAND STREET** **NY AST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.133 mi.
703 ft. **Site 2 of 9 in cluster S**

Relative: **Higher**

Actual: **235 ft.**

WESTCHESTER CO. UST:

Name:	170 GRAND STREET ASSOC.
Address:	170 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-800392 / Active
Operator Name:	Jose Francisco
Owner Name:	170 Grand Avenue LLC
Owner Street:	825 East 233rd Street
Owner Address2:	Not reported
Owner City:	Bronx
Owner State:	NY
Owner Zipcode:	10466
GDS Number:	Not reported
Tank Number:	1old
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported

170 GRAND STREET ASSOC. (Continued) **U004175922**

Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	03/03/2005
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	0. No Pippping
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	170 GRAND STREET ASSOC.
Address:	170 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-800392
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Jose Francisco
Owner Name:	170 Grand Avenue LLC
Owner Street:	825 East 233rd Street
Owner Address2:	Not reported
Owner City/State/Zip:	Bronx, NY 10466

Tank Number:	1
Status:	1. In-Service
Date Installation:	04/01/2005
Capacity:	2000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None,99. Other
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	0. None
Dispenser:	0. None

N158 **MH3471** **RCRA NonGen / NLR** **1007206958**
SW **F/O 44 POST ROAD** **NY MANIFEST** **NYP004034625**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.133 mi.
704 ft. **Site 9 of 9 in cluster N**

Relative: **Higher**
Actual: **213 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2001-01-03 00:00:00.0
Handler Name:	MH3471
Handler Address:	F/O 44 POST ROAD
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYP004034625
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CONSOLIDATED EDISON INC.
Contact City,State,Zip:	NEW YORK, NY 10003
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	CONSOLIDATED EDISON INC.
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

MH3471 (Continued) **1007206958**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2001-01-02 00:00:00.0
Handler Name:	MH3471
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2001-01-03 00:00:00.0
Handler Name:	MH3471
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

MH3471 (Continued) **1007206958**

Electronic Manifest Broker: Not reported

Receive Date: 2001-01-01 00:00:00.0
Handler Name: MH3471
Federal Waste Generator Description: Large Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Address: F/O 44 POST ROAD
City,State,Zip: WHITE PLAINS, NY 10606
Country: USA
EPA ID: NYP004034625
Facility Status: Not reported
Location Address 1: MH3471-44 POST RD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: N/S
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004034625
Mailing Name: CONSOLIDATED EDISON COMPANY OF NEW YORK
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA

MH3471 (Continued) **1007206958**

Mailing Phone: 2124602808

NY MANIFEST:

Document ID:	NYE0279551
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	80680AE
Trans2 State ID:	Not reported
Generator Ship Date:	01/11/1999
Trans1 Recv Date:	01/11/1999
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/11/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004034625
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00204
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	01.00

L159 **REAL ESTATE - TTF** **NY LTANKS** **S118263506**
ENE **6 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.137 mi.
722 ft. **Site 17 of 18 in cluster L**

Relative:
Higher

Actual:
243 ft.

LTANKS:

Name:	REAL ESTATE - TTF
Address:	6 CHESTER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1506711 / 2019-02-08

REAL ESTATE - TTF (Continued) **S118263506**

Facility ID:	1506711
Site ID:	514142
Spill Date:	2015-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-09-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-09-24
Spill Record Last Update:	2019-02-08
Spiller Name:	Unknown
Spiller Company:	Unnamed Owner/Seller
Spiller Address:	6 CHESTER AVE
Spiller County:	999
Spiller Contact:	ANTHONY TIRONE
Spiller Phone:	914-686-7007
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	468617
DEC Memo:	"9/24/15 Spoke to Kathy Morgan at TT. Mr. Tirone is the buyer. Owner is unknown. dw 2/06/19: I spoke with Kathy Morgan at US Tank Tech, she pulled the file on this TTF. She states there is a note on the file indicating #6 and #8 Chester Ave were together on one parcel. She states #8 had an out of service 1K gallon underground fuel tank at the time they tested #6. She believes #6 was still in service at the time they tested it for a prospective buyer. Tank failed with hissing, may have been an ullage failure. US Tank Tech did not test #8 tank. They only other info provided is that this property was a Robison customer at the time of the test and Robison was notified of the failure. US Tank Tech forwarded a site diagram showing the location of the UST at #6. There was a direct fill in the center of the front yard and a remote curb fill that was capped. Diagram will be entered into DecDocs. jod I then spoke to Tony Magnotta of the White Plains Bldg Dept. He is checking his files and will forward any information on permits that may have been filed for UST removals at this property. jod 2/06/19: White Plains Bldg Dept issued a permit for removal of USTs at this property in October of 2018. Certificate of completion was issued by the Bldg Dept on Dec 20, 2018. Work was performed by Madison Environmental. Permit and Certificate scanned into DecDocs. jod 2/07/19: I sent a message to Joe Tomasulo of Madison Environmental. He states they removed both tanks. He will forward soil sample results. He states he was never informed about the tightness test failure or the open spill number. Sample results from Madison indicate some SVOC contamination below CP-51 Guidance values. Samples will be entered into DecDocs. I left a message with Joe Tomasulo stating I will need more information on the removal of

REAL ESTATE - TTF (Continued) **S118263506**

these USTs. jod 2/08/19: I spoke to Joe at Madison. He has forwarded the sample results for the UST removal at 8 Chester as well. He states neither tank was leaking. The two buidings are currently part of a construction project and are being demo'ed. Joe states White Plains Buildning Dept was onsite to inspect the removals. I also spoke with Tony Magnotta at the Bldg Dept again. He confirms the USTs and the excavations were inspected by his Dept, no evidence of any leak or release was noted. Photos and additional sample results in DecDocs. Based upon the information received, no further action is required at this time. jod"

Remarks: "1000 gallon underground tank"

All TTF:

Facility ID:	1506711
Spill Number:	1506711
Spill Tank Test:	2506521
Site ID:	514142
Tank Number:	UST
Tank Size:	1000
Material:	0001
EPA UST:	False
UST:	True
Cause:	99
Source:	00
Test Method:	34
Test Method 2:	EZY 3 Locator Plus
Leak Rate:	Not reported
Gross Fail:	Not reported
Modified By:	JBODEE
Last Modified Date:	Not reported

All Materials:

Site ID:	514142
Operable Unit ID:	1263349
Operable Unit:	01
Material ID:	2267039
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

L160 **RESIDENTS** **NY LTANKS** **S102447976**
ENE **8 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.137 mi.
725 ft. **Site 18 of 18 in cluster L**

Relative: **Higher**
Actual: **244 ft.**

LTANKS:

Name:	RESIDENTS
Address:	8 CHESTER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9610881 / 2012-04-16
Facility ID:	9610881

RESIDENTS (Continued) **S102447976**

Site ID:	71801
Spill Date:	1996-12-03
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1996-12-03
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-03
Spill Record Last Update:	2012-04-16
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	KREISBERG RESIDENTS
Spiller Phone:	(914) 428-3000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	67898
DEC Memo:	"8/3/10 Homeowner TTF JO'M 4/16/12 This spill has been closed administratively based on the following: 1) The spill is at least 10 years old 2) It is a Homeowner (non regulated tank) Tank Test Failure 3) There is no indication of an Environmental impact This Closure does not remove the possibility of DEC requiring further work in the future. NFA JO'M"
Remarks:	"THE TAN TESTER THINKS THAT THE LINES ARE BAD OR THE VENT LINES OIL COMPANY ROBISON IS DOING THE FOLLOW UP JIM ROOD IS THE EMPLOYEE FOR ROBISON 914-345-5700"

All TTF:

Facility ID:	9610881
Spill Number:	9610881
Spill Tank Test:	1544908
Site ID:	71801
Tank Number:	1
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

S161 **177 GRAND STREET ASSOC LLC** **RCRA NonGen / NLR** **1001233223**
NNE **177 GRAND ST** **FINDS** **NYR000063727**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.138 mi. **NY MANIFEST**
731 ft. **Site 3 of 9 in cluster S**

Relative:
Higher

Actual:
237 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	177 GRAND STREET ASSOC LLC
Handler Address:	177 GRAND ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000063727
Contact Name:	EDMOND DELAURENTIS
Contact Address:	PO BOX 310
Contact City,State,Zip:	WHITE PLAINS, NY 10605
Contact Telephone:	914-946-1321
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	PO BOX 310
Mailing City,State,Zip:	WHITE PLAINS, NY 10605
Owner Name:	177 GRAND STREET ASSOC
Owner Type:	Private
Operator Name:	177 GRAND STREET ASSOC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	D002
Waste Description:	CORROSIVE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	177 GRAND STREET ASSOC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 310
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10605
Owner/Operator Telephone:	914-946-1321
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	177 GRAND STREET ASSOC
Legal Status:	Private
Date Became Current:	Not reported

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 310
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10605
Owner/Operator Telephone:	914-946-1321
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	177 GRAND STREET ASSOC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 310
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10605
Owner/Operator Telephone:	914-946-1321
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	177 GRAND STREET ASSOC LLC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	177 GRAND STREET ASSOC LLC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1998-11-23 00:00:00.0
Handler Name:	177 GRAND STREET ASSOC LLC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004548927

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001233223
Registry ID: 110004548927
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110004548927
Name: 177 GRAND STREET ASSOC LLC
Address: 177 GRAND ST
City,State,Zip: WHITE PLAINS, NY 10601

NY MANIFEST:
Name: WEST CHESTER HOBBIE
Address: 177 GRAND ST
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYR000063727
Facility Status: Not reported
Location Address 1: 177 GRAND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10605
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYR000063727
Mailing Name: WEST CHESTER HOBBIE

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Mailing Contact:	MARGARET HOFFMAN
Mailing Address 1:	177 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10605
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146828236

NY MANIFEST:

Document ID:	PAG0327353
Manifest Status:	Not reported
seq:	01
Year:	1998
Trans1 State ID:	PAAH0146
Trans2 State ID:	Not reported
Generator Ship Date:	12/01/1998
Trans1 Recv Date:	12/01/1998
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/02/1998
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000063727
Trans1 EPA ID:	PAD067098822
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD067098822
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F003 - UNKNOWN
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

177 GRAND STREET ASSOC LLC (Continued) **1001233223**

Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

S162 **177 GRAND STREET ASSOCIATES, LLC,LLC C/O DELAURENT** **NY UST** **U003994240**
NNE **177 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.138 mi.
731 ft. **Site 4 of 9 in cluster S**

Relative: **Higher**
Actual: **237 ft.**

WESTCHESTER CO. UST:

Name:	177 GRAND STREET ASSOCIATES, LLC,LLC C/O DELAURENT
Address:	177 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-049816 / Active
Operator Name:	Paul Halmi
Owner Name:	177 Grand St Assoc.
Owner Street:	384 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	177
Status:	1. In-Service
Capacity:	2000
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1950
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

S163 **COMMERCIAL BUSINESS** **NY LTANKS** **S107410444**
NNE **158 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.138 mi.
731 ft. **Site 5 of 9 in cluster S**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Name:	COMMERCIAL BUSINESS
Address:	158 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0506649 / 2006-02-03
Facility ID:	0506649
Site ID:	351900
Spill Date:	2005-08-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-08-30
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-30
Spill Record Last Update:	2006-02-03
Spiller Name:	MR FINGERMAN
Spiller Company:	COMMERCIAL BUSINESS
Spiller Address:	158 GRANDE STREET
Spiller County:	001
Spiller Contact:	MR FINGERMAN
Spiller Phone:	(914) 949-0308
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	299193
DEC Memo:	"Caller will inform Todd Ghiosay of the DEC. 9/7/05 Also reported as spill 04-13115. jod February 3, 2006: NES DISPOSED OF LUST AND 39.36 TONS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
	Not reported
Remarks:	"HOLES IN TANK: SEVERAL LARGE HOLES;"

All Materials:

Site ID:	351900
Operable Unit ID:	1109401
Operable Unit:	01
Material ID:	2099431
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00

COMMERCIAL BUSINESS (Continued) **S107410444**

Oxygenate: Not reported

Name: FINGAR AND FINGAR LAW OFFICE
Address: 158 GRAND STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0413115 / 2005-09-07
Facility ID: 0413115
Site ID: 338963
Spill Date: 2005-03-16
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-03-16
CID: 408
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-03-16
Spill Record Last Update: 2006-02-03
Spiller Name: DOROTHY FINGAR
Spiller Company: DOROTHY FINGAR
Spiller Address: 158 GRAND ST.
Spiller County: 001
Spiller Contact: DOROTHY FINGAR
Spiller Phone: (914) 949-0308
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 299193
DEC Memo: "03/18/05 TEMP TANK SET UP BY WILCO FUEL. SAMPLES RESULTS REPORTED TO BE VERY HIGH LEVELS OF CONTAMINATION. jod September 7, 2005: SEE SPILL 05-06649 FOR ALL UPDATE INFORMATION. NFA THIS SPILL NUMBER. jod"
Not reported
Remarks: "Tank was supposed to be tested today. However the tank has a hole in it, soil is compacted. samples were tkaen for testing. The old tank was removed and a new one installed, old tank was pumped out. 03/18/05 Tank has NOT been removed yet. jod"

All Materials:
Site ID: 338963
Operable Unit ID: 1100882
Operable Unit: 01
Material ID: 581014
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00

COMMERCIAL BUSINESS (Continued) **S107410444**

Oxygenate: Not reported

S164 **OFFICE BLDG BASEMENT** **NY LTANKS** **S102674993**
NNE **150 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.142 mi.
750 ft. **Site 6 of 9 in cluster S**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Name:	OFFICE BLDG BASEMENT
Address:	150 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8908740 / 1990-02-07
Facility ID:	8908740
Site ID:	307349
Spill Date:	1989-12-05
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1990-02-07
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-12-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1989-12-08
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-12-07
Spill Record Last Update:	2003-10-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	248205
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/07/90: SPILL CLEANED UP BY A.L. EASTMAN . WCHD MONITORED CLEANUP. "
Remarks:	"FUEL SUPPLIER PAC-PETRO/PURE ENERGY GROUP(212-842-1100)CONTRACT HAULERM.B.TRUCKING(212-328-3275) AL EASTMAN IS CLEANUP CONTRACTOR T. GHIOSAYTO LOOK AT"

All Materials:

Site ID:	307349
Operable Unit ID:	933790
Operable Unit:	01
Material ID:	441928
Material Code:	0001A
Material Name:	#2 fuel oil

OFFICE BLDG BASEMENT (Continued) **S102674993**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	200.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

S165 **150 GRAND STREET OFFICE BUILDING** **NY UST** **U003856437**
NNE **150 GRAND STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.142 mi.
750 ft. **Site 7 of 9 in cluster S**

Relative: WESTCHESTER CO. UST:
Higher

Actual:
234 ft.

Name:	GRAND REALTY COMPANY
Address:	150 GRAND STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-176885 / Administratively Closed
Operator Name:	Tony Spagnoli
Owner Name:	Grand Realty Co
Owner Street:	110 Corporate Park Drive
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	1
Status:	0. Administratively closed
Capacity:	10000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	03/01/1960
Date Perm Closure:	06/23/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity
Tank Number:	1
Status:	4. Closed - in place
Capacity:	10000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1962
Date Perm Closure:	08/22/2012

150 GRAND STREET OFFICE BUILDING (Continued) **U003856437**

Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

166
SE
1/8-1/4
0.142 mi.
750 ft.

RESIDENCE
25 LONGVIEW AVE
WHITE PLAINS, NY

NY LTANKS **S106868939**
N/A

Relative:
Higher

Actual:
241 ft.

LTANKS:

Name:	RESIDENCE
Address:	25 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0413208 / 2005-05-08
Facility ID:	0413208
Site ID:	339072
Spill Date:	2005-03-18
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-03-18
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-18
Spill Record Last Update:	2005-05-08
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	LIUS LIPKIN
Spiller Phone:	(914) 681-0645
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	285687
DEC Memo:	"INVALID TANK TEST METHOD. jod 05/08/05 ADVANCED ENVIRONMENTAL DISPOSED OF LUST AND 3.30 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"

RESIDENCE (Continued) **S106868939**

Remarks: "failure on a tightness test no oil noted in soil mesa 2d 1000 gallon"
Not reported

All Materials:
Site ID: 339072
Operable Unit ID: 1100989
Operable Unit: 01
Material ID: 581136
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

T167 **GREENRIDGE GARDENS OWNERS** **NY AST** **A100386137**
East **2 GREENRIDGE AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.143 mi.
756 ft. **Site 1 of 7 in cluster T**

Relative: **Higher**
Actual: **256 ft.**

WESTCHESTER CO. AST:
Name: GREENRIDGE GARDENS OWNERS
Address: 2 GREENRIDGE AVENUE
City,State,Zip: WHITE PLAINS, NY 10605
PBS Number: 3-039144
Site Status: Active
GDS Number: Not reported
Operator Name: Greenridge Gardens
Owner Name: Greenridge Gardens Condominium, Inc.
Owner Street: 119 Montgomery Avenue
Owner Address2: c/o White Management
Owner City/State/Zip: White Plains, NY 10605

Tank Number: 1
Status: 1. In-Service
Date Installation: 08/01/1982
Capacity: 4000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: 100
Date Perm Closure: 01/01/1900
Tank Location: 6. Aboveground in subterranean vault with access for inspections
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 1. Epoxy liner
Tank External Protection: 1. Painted/Asphalt Coating
Tank Leak Detection: 0. None
Tank Secondary Containment: 2. Vault (w/ access)
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Piping Leak Detection: 0. None
Piping Secondary Containment: 2. Vault (w/ access)
Overfill Prevention: 4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

U168 **CHESTER MAPLE PARKING STRUCT** **RCRA NonGen / NLR** **1000555924**
ENE **9 CHESTER AVE** **FINDS** **NYD986984714**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.145 mi.
766 ft. **Site 1 of 7 in cluster U**

Relative:
Higher

Actual:
243 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	CHESTER MAPLE PARKING STRUCT
Handler Address:	9 CHESTER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601-3505
EPA ID:	NYD986984714
Contact Name:	Not reported
Contact Address:	CHESTER AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Municipal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	CHESTER AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	WHITE PLAINS PARKING AUTH
Owner Type:	Municipal
Operator Name:	WHITE PLAINS PARKING AUTH
Operator Type:	Municipal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CHESTER MAPLE PARKING STRUCT (Continued) **1000555924**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS PARKING AUTH
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	65 MITCHELL PL
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-422-1320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	WHITE PLAINS PARKING AUTH
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	65 MITCHELL PL
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601

CHESTER MAPLE PARKING STRUCT (Continued) **1000555924**

Owner/Operator Telephone:	914-422-1320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WHITE PLAINS PARKING AUTH
Legal Status:	Municipal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	65 MITCHELL PL
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-422-1320
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	CHESTER MAPLE PARKING STRUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	CHESTER MAPLE PARKING STRUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	CHESTER MAPLE PARKING STRUCT
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CHESTER MAPLE PARKING STRUCT (Continued) **1000555924**

Receive Date:	1992-01-06 00:00:00.0
Handler Name:	CHESTER MAPLE PARKING STRUCT
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004481873

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000555924
Registry ID:	110004481873
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004481873
Name:	CHESTER MAPLE PARKING STRUCT
Address:	9 CHESTER AVE
City,State,Zip:	WHITE PLAINS, NY 10601

U169 **CHESTER MAPLE PARKING STRUCT** **NY MANIFEST** **S120957590**
ENE **9 CHESTER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.145 mi.
766 ft. **Site 2 of 7 in cluster U**

Relative:
Higher

Actual:
243 ft.

NY MANIFEST:

Name:	CHESTER MAPLE PARKING STRUCT
Address:	9 CHESTER AVE
City,State,Zip:	WHITE PLAINS, NY 10601-3505
Country:	USA
EPA ID:	NYD986984714
Facility Status:	Not reported
Location Address 1:	9 CHESTER AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD986984714
Mailing Name:	CHESTER MAPLE PARKING STRUCT
Mailing Contact:	CHESTER MAPLE PARKING STRUCT
Mailing Address 1:	9 CHESTER AVE
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJ0000027193
Trans2 State ID:	Not reported
Generator Ship Date:	06/23/2017
Trans1 Recv Date:	06/23/2017
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/23/2017
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986984714
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	016115481JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CHESTER MAPLE PARKING STRUCT (Continued) **S120957590**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	3
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

S170 **CON EDISON - VAULT 4680** **NY MANIFEST** **S120959011**
NNE **161 GRAND ST** **N/A**
1/8-1/4 **BRONX, NY 10601**
0.145 mi.
768 ft. **Site 8 of 9 in cluster S**

Relative:
Higher

Actual:
235 ft.

NY MANIFEST:

Name:	CON EDISON - VAULT 4680
Address:	161 GRAND ST
City,State,Zip:	BRONX, NY 10601
Country:	USA
EPA ID:	NYP004983803
Facility Status:	Not reported
Location Address 1:	161 GRAND ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	BRONX
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004983803
Mailing Name:	CON EDISON - VAULT 4680
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported

CON EDISON - VAULT 4680 (Continued) **S120959011**

Mailing Country: USA
Mailing Phone: Not reported

R171 **RECKSON ASSOCIATES** **RCRA NonGen / NLR** **1004762372**
NNE **140 GRAND ST** **FINDS** **NYR000096263**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.147 mi. **NY MANIFEST**
775 ft. **Site 6 of 10 in cluster R**

Relative: **Higher**
Actual: **233 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	RECKSON ASSOCIATES
Handler Address:	140 GRAND ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000096263
Contact Name:	PHILLIP FALLON
Contact Address:	BROADHOLLOW RD
Contact City,State,Zip:	MELVILLE, NY 11747
Contact Telephone:	631-622-6678
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	BROADHOLLOW RD
Mailing City,State,Zip:	MELVILLE, NY 11747
Owner Name:	RECKSON ASSOC REAL ESTATE CORP
Owner Type:	Private
Operator Name:	RECKSON ASSOC REAL ESTATE CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported

RECKSON ASSOCIATES (Continued) **1004762372**

Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RECKSON ASSOC REAL ESTATE CORP
Legal Status:	Private
Date Became Current:	2001-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	225 BROADHOLLOW RD
Owner/Operator City,State,Zip:	MELVILLE, NY 11747
Owner/Operator Telephone:	631-622-6678
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	RECKSON ASSOC REAL ESTATE CORP

RECKSON ASSOCIATES (Continued) **1004762372**

Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	225 BROADHOLLOW RD
Owner/Operator City,State,Zip:	MELVILLE, NY 11747
Owner/Operator Telephone:	631-622-6678
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	RECKSON ASSOC REAL ESTATE CORP
Legal Status:	Private
Date Became Current:	2001-01-01 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	225 BROADHOLLOW RD
Owner/Operator City,State,Zip:	MELVILLE, NY 11747
Owner/Operator Telephone:	631-622-6678
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	RECKSON ASSOCIATES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	RECKSON ASSOCIATES
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2001-04-25 00:00:00.0
Handler Name:	RECKSON ASSOCIATES
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No

RECKSON ASSOCIATES (Continued) **1004762372**

Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110006540412

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004762372
Registry ID: 110006540412
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110006540412
Name: RECKSON ASSOCIATES
Address: 140 GRAND ST
City,State,Zip: WHITE PLAINS, NY 10601

NY MANIFEST:
Name: RECKSON
Address: 140 GRAND ST
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYR000096263
Facility Status: Not reported
Location Address 1: 140 GRAND ST
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:

RECKSON ASSOCIATES (Continued) **1004762372**

EPAID:	NYR000096263
Mailing Name:	RECKSON
Mailing Contact:	RECKSON
Mailing Address 1:	140 GRAND ST
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9147307200

NY MANIFEST:

Document ID:	NJA3192745
Manifest Status:	Not reported
seq:	01
Year:	2001
Trans1 State ID:	S50059
Trans2 State ID:	Not reported
Generator Ship Date:	04/30/2001
Trans1 Recv Date:	04/30/2001
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/04/2001
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000096263
Trans1 EPA ID:	NJD986607380
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00330
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	006
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00

T172 **GREENRIDGE ESTATES CONDOMINIUMS** **NY LTANKS** **S126222167**
East **1-13 GREENRIDGE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.150 mi.
793 ft. **Site 2 of 7 in cluster T**

Relative:
Higher

Actual:
254 ft.

LTANKS:

Name:	GREENRIDGE ESTATES CONDOMINIUMS
Address:	1-13 GREENRIDGE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1911181 / Not Reported
Facility ID:	1911181
Site ID:	601870
Spill Date:	2020-03-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2020-03-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2020-03-04
Spill Record Last Update:	2020-03-09
Spiller Name:	Trey White - White Management company
Spiller Company:	GREENRIDGE ESTATES
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TREY WHITE
Spiller Phone:	(914) 874-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373978
DEC Memo:	"3/4/2020 US Tank Tech retested tank # 9 which failed with hissing. Other tanks to be re-tested on Friday. ga"
Remarks:	"failed w/hissing sound and a loss of vacuum (retest) PBS 3-039128"

All Materials:

Site ID:	601870
Operable Unit ID:	1348984
Operable Unit:	01
Material ID:	2359551
Material Code:	9999
Material Name:	other - TANK TEST FAILURE
Case No.:	Not reported
Material FA:	Other
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

T173 **GREENRIDGE ESTATES CONDOMINIUM** **NY AST** **A100276712**
East **1-13 GREENRIDGE AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.150 mi.
793 ft. **Site 3 of 7 in cluster T**

Relative:
Higher

Actual:
254 ft.

WESTCHESTER CO. AST:

Name:	GREENRIDGE ESTATES CONDOMINIUM
Address:	1-13 GREENRIDGE AVENUE
City,State,Zip:	WHITE PLAINS, NY 10603
PBS Number:	3-039128
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Greenridge Estates Condominium
Owner Name:	Greenridge Estates Condominium c/o White Mgmt.
Owner Street:	119 Montgomery Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	Scarsdale, NY 10583
Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1946
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	5
Status:	1. In-Service
Date Installation:	01/01/1946
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	3. Vault (w/ no access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None

GREENRIDGE ESTATES CONDOMINIUM (Continued) **A100276712**

Piping Secondary Containment:	2. Vault (w/ access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	9
Status:	1. In-Service
Date Installation:	01/01/1946
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	3. Vault (w/ no access)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

T174 **GREENRIDGE ESTATES** **NY LTANKS** **S110140617**
East **1-13 GREENRIDGE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.150 mi.
793 ft. **Site 4 of 7 in cluster T**

Relative: **Higher**
Actual: **254 ft.**

LTANKS:

Name:	GREENRIDGE ESTATES
Address:	1-13 GREENRIDGE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0912193 / 2011-12-22
Facility ID:	0912193
Site ID:	425068
Spill Date:	2010-02-22
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0

GREENRIDGE ESTATES (Continued) **S110140617**

Date Entered In Computer:	2010-02-22
Spill Record Last Update:	2020-02-14
Spiller Name:	Not reported
Spiller Company:	GREEN RIDGE ESTATES
Spiller Address:	1-13 GREEN RIDGE AVE
Spiller County:	999
Spiller Contact:	WILLIAM
Spiller Phone:	(914) 760-5494
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373978
DEC Memo:	"2/22/10 tank is a 5k ust, will repair and retest...mm From Lalak, Chris 6/10/2011 12:51 PM :: Wayne, Please follow up on these two old open spills 0912193 - 0911533 Chris --This is a PBS regulated facility. Wayne Schneider of WCDOH will follow up. jod Schneider, Wayne 12/22/2011 1:46 PM 0912193: 1-13 Greenridge Ave, White Plains tf 1/22/10. tanks are ASTs and passed retests. 12/22/11: DEC requires NFA at this time. jod"
Remarks:	"TANK TEST FAILURE. RETEST- UNCLEAR WHAT THE NEXT STEP WILL BE."

All Materials:

Site ID:	425068
Operable Unit ID:	1180801
Operable Unit:	01
Material ID:	2174794
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

T175 **CONDO - TTF 3 TANKS** **NY LTANKS** **S126222168**
East **1-13 GREENRIDGE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.150 mi.
793 ft. **Site 5 of 7 in cluster T**

Relative: **Higher**
Actual: **254 ft.**

LTANKS:

Name:	CONDO - TTF 3 TANKS
Address:	1-13 GREENRIDGE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1911256 / Not Reported
Facility ID:	1911256
Site ID:	601947
Spill Date:	2020-03-06
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	KABROWNE
Referred To:	Not reported
Reported to Dept:	2020-03-06
CID:	Not reported

CONDO - TTF 3 TANKS (Continued) **S126222168**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2020-03-06
Spill Record Last Update:	2020-03-30
Spiller Name:	WHITE MANAGEMENT-TREY WHITE
Spiller Company:	PRIVATE RESD-CONDO
Spiller Address:	1-13 GREENRIDGE AVE
Spiller County:	999
Spiller Contact:	WHITE MANAGEMENT-TREY WHITE
Spiller Phone:	(914) 874-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373978
DEC Memo:	"3/6/2020 - Talked to Cathy Morgan of US Tank: they had tested 3-5000 gal tanks on 2/25 and all failed. They then removed all fittings and replaced with plugs and then retested but 2 have failed. PBS # 3-039128. No leakage has been observed. Tanks are in vaults. Westchester Co (Chris Lalak) was called. No product to the environment. fjk 03/30/20 Emailed Chris Lalak for a status. TG"
Remarks:	"Retest failure. Already spill # in place for the location, but R3 Spills wants a new spill number for a retest on the same tank."

All Materials:

Site ID:	601947
Operable Unit ID:	1349080
Operable Unit:	01
Material ID:	2359635
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

R176 **CON EDISON** **RCRA NonGen / NLR** **1019909457**
North **111 MARTIN LUTHER KING JR BLVD** **NYP004885055**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.152 mi.
804 ft. **Site 7 of 10 in cluster R**

Relative: **Lower**
Actual: **199 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-12-30 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	111 MARTIN LUTHER KING JR BLVD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004885055
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770

CON EDISON (Continued) **1019909457**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON (Continued) **1019909457**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:53:31.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-12-30 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-12-30 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

R177
North
1/8-1/4
0.152 mi.
804 ft.

CON EDISON
111 MARTIN LUTHER KING JR BLVD
WHITE PLAINS, NY 10601

Site 8 of 10 in cluster R

NJ MANIFEST **S120678603**
N/A

Relative:
Lower

Actual:
199 ft.

NJ MANIFEST:

EPA Id:	NYP004885055
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	015323084JJK
EPA ID:	NYP004885055
Date Shipped:	12/30/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported

CON EDISON (Continued) **S120678603**

Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

R178 **WESTCHESTER COUNTY COURTHOUSE** **RCRA NonGen / NLR** **1001119601**
North **111 GROVE ST** **FINDS** **NYR000028902**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.152 mi. **NY MANIFEST**
804 ft. **Site 9 of 10 in cluster R**

Relative: **Lower**
Actual: **199 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURTHOUSE
Handler Address:	111 GROVE ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000028902
Contact Name:	Not reported
Contact Address:	GROVE ST
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	County
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	GROVE ST
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	WESTCHESTER COUNTY
Owner Type:	County
Operator Name:	WESTCHESTER COUNTY
Operator Type:	County
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	D009
Waste Description:	MERCURY

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	WESTCHESTER COUNTY
Legal Status:	County
Date Became Current:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2559
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	WESTCHESTER COUNTY
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2559
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	WESTCHESTER COUNTY
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2559
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURTHOUSE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURTHOUSE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Electronic Manifest Broker: Not reported

Receive Date: 2007-01-01 00:00:00.0
Handler Name: WESTCHESTER COUNTY COURTHOUSE
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 1996-09-06 00:00:00.0
Handler Name: WESTCHESTER COUNTY COURTHOUSE
Federal Waste Generator Description: Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004528182

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001119601

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Registry ID:	110004528182
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004528182
Name:	WESTCHESTER COUNTY COURTHOUSE
Address:	111 GROVE ST
City,State,Zip:	WHITE PLAINS, NY 10601

NY MANIFEST:

Name:	WESTCHESTER COUNTY COURTHOUSE
Address:	111 GROVE ST
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYR000028902
Facility Status:	Not reported
Location Address 1:	111 GROVE STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000028902
Mailing Name:	WESTCHESTER COUNTY COURTHOUSE
Mailing Contact:	JOHN BLAKE/RANDI SMITH
Mailing Address 1:	123 MAIN STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9146816384

NY MANIFEST:

Document ID:	NYB8450235
Manifest Status:	K
seq:	Not reported
Year:	1997
Trans1 State ID:	MA102
Trans2 State ID:	Not reported
Generator Ship Date:	05/07/1997
Trans1 Recv Date:	05/07/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	05/12/1997
Part A Recv Date:	05/20/1997
Part B Recv Date:	06/10/1997
Generator EPA ID:	NYR000028902
Trans1 EPA ID:	MA5000002394
Trans2 EPA ID:	Not reported
TSDF ID 1:	AZ0000337360
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported

WESTCHESTER COUNTY COURTHOUSE (Continued) **1001119601**

Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00855
Units:	P - Pounds
Number of Containers:	011
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00170
Units:	P - Pounds
Number of Containers:	015
Container Type:	CF - Fiber or plastic boxes, cartons
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

V179 **SHOLZ BUICK, INC.** **NY UST** **U003994935**
SW **55 WEST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.154 mi.
814 ft. **Site 1 of 4 in cluster V**

Relative: WESTCHESTER CO. UST:
Higher

Name:	SHOLZ BUICK, INC.
Address:	55 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-800357 / Unregulated
Operator Name:	Sholz Buick, Inc.
Owner Name:	55 West Post Road, Inc.
Owner Street:	55 West Post Road
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10606
GDS Number:	Not reported
Tank Number:	4bk
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported

Actual:
215 ft.

SHOLZ BUICK, INC. (Continued) **U003994935**

Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	5BK
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1969
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	6bk
Status:	3. Closed - Removed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	0
Tank Leak Detection:	Not reported
Date Installation:	01/01/1900
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	Not reported
Tank Internal Protection:	Not reported
Tank External Protection:	Not reported
Tank Secondary Containment:	Not reported
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported

SHOLZ BUICK, INC. (Continued) **U003994935**

Spill Prevention: Not reported
Dispenser: Not reported

V180 **SHOLZ BUICK, INC.** **NY AST** **A100276867**
SW **55 WEST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.154 mi.
814 ft. **Site 2 of 4 in cluster V**

Relative: WESTCHESTER CO. AST:
Higher

Actual: Name: SHOLZ BUICK, INC.
215 ft. Address: 55 WEST POST ROAD
City,State,Zip: WHITE PLAINS, NY 10606
PBS Number: 3-800357
Site Status: Unregulated
GDS Number: Not reported
Operator Name: Sholz Buick, Inc.
Owner Name: 55 West Post Road, Inc.
Owner Street: 55 West Post Road
Owner Address2: Not reported
Owner City/State/Zip: White Plains, NY 10606

Tank Number: 1BK/A
Status: 3. Closed - Removed
Date Installation: 01/01/1969
Capacity: 275
Product Stored: 9999. Other
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: 0. None
Piping Location: Not reported
Piping Type: Not reported
Piping External Protection: 0. None
Piping Leak Detection: Not reported
Piping Secondary Containment: Not reported
Overfill Prevention: 0. None
Spill Prevention: 0. None
Dispenser: 1. Submersible

Tank Number: 1bk/b
Status: 3. Closed - Removed
Date Installation: 01/01/1969
Capacity: 275
Product Stored: 9999. Other
Product Stored Percent: Not reported
Date Perm Closure: 01/01/1900
Tank Location: 3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Leak Detection: 0. None
Tank Secondary Containment: Not reported

SHOLZ BUICK, INC. (Continued) **A100276867**

Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	2BK
Status:	3. Closed - Removed
Date Installation:	01/01/1969
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	3BK
Status:	3. Closed - Removed
Date Installation:	12/01/1998
Capacity:	275
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	0. None

V181 **SHOLZ BUICK-OLDSMOBILE** **NY Spills** **1000293849**
SW **55 W POST RD** **RCRA NonGen / NLR** **NYD981875727**
1/8-1/4 **WHITE PLAINS, NY 10606** **FINDS**
0.154 mi. **ECHO**
814 ft. **Site 3 of 4 in cluster V** **NY MANIFEST**

Relative:
Higher

Actual:
215 ft.

SPILLS:

Name:	WHITE PLAINS MAZDA
Address:	35 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0508992 / 2011-10-05
Facility ID:	0508992
Facility Type:	ER
DER Facility ID:	395814
Site ID:	354696
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-10-04
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-10-27
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-10-27
Spill Record Last Update:	2011-10-05
Spiller Name:	PATRICIA BADDING
Spiller Company:	WHITE PLAINS MAZDA
Spiller Address:	34 WEST POST ROAD
Spiller Company:	001
Contact Name:	PATRICIA BADDING
DEC Memo:	"02/02/06 Consultant Mark Pascow worked for Mazda who is a tenant at the facility. Mazda hired Royal Environmental to remove the lifts, but once contamination was found, Mazda took the position that it was the building owner's reponsiblity to do the cleanup. Owner was unknown to Pascow. TG 11/18/10 Site meeting held to review current status. Two property developers were present and a representative for Dave Pelletier from Jade Environmental. Site owners: Bob Slingsby - cell 914 715-1974 Joshua Schwartz -VP All Med 161 West 61st St. Apt 9A NY NY 10023 Bob from Jade Environmental Pointed out two locations were a waste oil tank and a #2 FO tank were removed. Impacted soil around the tanks was excavated and stockpiled awaiting disposal. Dave Pelletier reported by phone that 14 lifts had been removed and that gray impacted soil was observed at the smear zone a 6'bg. He will be drafting a soil and groundwater sampling plan and will submit the plan for Dept review. TG 10/05/11 See remedaition report under dupicate spill number 1007370"
Remarks:	"FOUND CONTAMINATION WHILE REMOVING LIFTS:"

All Materials:

Site ID:	354696

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Operable Unit ID:	1112090
Operable Unit:	01
Material ID:	2102132
Material Code:	0010
Material Name:	hydraulic oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	BRK AQUISITIONS PROJECT
Address:	35 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1007370 / 2011-10-06
Facility ID:	1007370
Facility Type:	ER
DER Facility ID:	395814
Site ID:	440784
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2010-10-08
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2010-10-08
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	2010-11-18
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-08
Spill Record Last Update:	2011-10-06
Spiller Name:	Not reported
Spiller Company:	BRK AQUISITIONS
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	DAVE PELLETIER
DEC Memo:	"10-8-10: V.Mc. to DAVE PELLETIER/Jade Enviro.: Likely a pre existing active file for loc. PBS facility, WCHD records only show 3 275 AST's but Jde found 2 more 1K UST, #2 fuel oil & waste oil. Non-standard size tank. Name under PBS records: RCC Properties, maybe under Shults. Waiting on permit, prior to removal. TCR to be submitted to WCHD. 10-8-10: V.Mc.: Poss. cross ref. 090-1804 & 091-1783, but address for both spill #'s is given as 55 West Post. 11/18/10 Site meeting held to review current status. Two property developers were present and a representative for Dave Pelletier from Jade Environmental. Site owners: Bob Slingsby - cell 914 715-1974 Joshua Schwartz -VP All Med 161 West 61st St. Apt 9A NY NY 10023 Bob from

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Jade Environmental Pointed out two locations were a waste oil tank and a #2 FO tank were removed. Impacted soil around the tanks was excavated and stockpiled awaiting disposal. Dave Pelletier reported by phone that 14 lifts had been removed and that gray impacted soil was observed at the smear zone a 6'bg. He will be drafting a soil and groundwater sampling plan and will submit the plan for Dept review. TG 09/26/11 Cleanup performed by Jade Environmental. See Final Cleanup report in Edocs. NFA. TG "

Remarks: "Caller advised found contaminated soil after removing tank."

All Materials:

Site ID:	440784
Operable Unit ID:	1191378
Operable Unit:	01
Material ID:	2186503
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	SHOLZ BUICK-OLDSMOBILE
Handler Address:	55 W POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10606-2907
EPA ID:	NYD981875727
Contact Name:	Not reported
Contact Address:	W POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	ROBERT SHOLZ
Owner Type:	Private
Operator Name:	ROBERT SHOLZ
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: F001
Waste Description: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: X001
Waste Description: Not Defined

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERT SHOLZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ROBERT SHOLZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ROBERT SHOLZ
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: NOT REQUIRED
Owner/Operator City,State,Zip: NOT REQUIRED, WY 99999
Owner/Operator Telephone: 212-555-1212
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 1999-07-08 00:00:00.0
Handler Name: SHOLZ BUICK-OLDSMOBILE

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	SHOLZ BUICK-OLDSMOBILE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	SHOLZ BUICK-OLDSMOBILE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1987-01-15 00:00:00.0
Handler Name:	SHOLZ BUICK-OLDSMOBILE
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004413135

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000293849
Registry ID:	110004413135
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004413135
Name:	SHOLZ BUICK-OLDSMOBILE
Address:	55 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	SHOLZ BUICK OLDSMOBILE
Address:	55 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606-2907
Country:	USA
EPA ID:	NYD981875727
Facility Status:	Not reported
Location Address 1:	35-55 WEST POST ROAD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD981875727
Mailing Name:	SHOLZ BUICK OLDSMOBILE
Mailing Contact:	FRANK SEYMOUR
Mailing Address 1:	35-55 WEST POST ROAD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149494300

SHOLZ BUICK-OLDSMOBILE (Continued) **1000293849**

NY MANIFEST:

Document ID:	NYC2030466
Manifest Status:	K
seq:	Not reported
Year:	1993
Trans1 State ID:	Not reported
Trans2 State ID:	Not reported
Generator Ship Date:	07/02/1993
Trans1 Recv Date:	07/02/1993
Trans2 Recv Date:	/ /
TSD Site Recv Date:	07/27/1993
Part A Recv Date:	/ /
Part B Recv Date:	08/10/1993
Generator EPA ID:	NYD981875727
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	Not reported
TSDF ID 1:	VAD105838874
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D008 - LEAD 5.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00200
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	100

W182 **FELIX DAVILA** **NY LTANKS** **S105999491**
South **36 DAVIS RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.155 mi.
816 ft. **Site 1 of 3 in cluster W**

Relative:
Higher

Actual:
242 ft.

LTANKS:

Name:	FELIX DAVILA
Address:	36 DAVIS RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0304516 / 2003-10-23
Facility ID:	0304516
Site ID:	187946

FELIX DAVILA (Continued) **S105999491**

Spill Date:	2003-07-29
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-07-29
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-29
Spill Record Last Update:	2003-10-23
Spiller Name:	OWNER
Spiller Company:	FELIX DAVILA
Spiller Address:	36 DAVIS RD
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	157053
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 10/23/03 NETS DISPOSED OF LUST AND 62.66 TONS OF CONTAMINATED SOIL."
Remarks:	"PULLED TANK, CONTAMINATED SOIL."

All Materials:

Site ID:	187946
Operable Unit ID:	872768
Operable Unit:	01
Material ID:	505377
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

U183 **WESTCHESTER COUNTY - 112 EAST POST ROAD** **RCRA NonGen / NLR** **1000552792**
NE **112 E POST RD** **FINDS** **NYD986951978**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.155 mi. **NY MANIFEST**
817 ft. **Site 3 of 7 in cluster U**

Relative: **Higher**
Actual: **238 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY - 112 EAST POST ROAD
Handler Address:	112 E POST RD

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYD986951978
Contact Name:	Not reported
Contact Address:	MAIN ST NY POWER AUTH
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	MAIN ST NY POWER AUTH
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	COUNTY OF WESTCHESTER
Owner Type:	County
Operator Name:	COUNTY OF WESTCHESTER
Operator Type:	County
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D008
Waste Description:	LEAD
Waste Code:	NONE
Waste Description:	Not Defined
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTNE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2593
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTNE AVE

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2593
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTNE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2593
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTNE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2593
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1994-12-07 00:00:00.0
Handler Name:	WESTCHESTER COUNTY - 112 EAST POST ROAD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY - 112 EAST POST ROAD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY - 112 EAST POST ROAD
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1991-05-15 00:00:00.0
Handler Name:	WESTCHESTER COUNTY - 112 EAST POST ROAD
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004466514

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000552792
Registry ID:	110004466514
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004466514

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Name: WESTCHESTER COUNTY - 112 EAST POST ROAD
Address: 112 E POST RD
City,State,Zip: WHITE PLAINS, NY 10601

NY MANIFEST:
Name: WESTCHESTER COUNTY OF
Address: 112 E POST RD
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYD986951978
Facility Status: Not reported
Location Address 1: 112 EAST POST ROAD
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 12603
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986951978
Mailing Name: WESTCHESTER COUNTY OF
Mailing Contact: RANDI SMITH
Mailing Address 1: C/O NY PWR AUTH 123 MAIN ST
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142873296

NY MANIFEST:
Document ID: NYB2299041
Manifest Status: C
seq: Not reported
Year: 1991
Trans1 State ID: PTD5889MN
Trans2 State ID: Not reported
Generator Ship Date: 07/09/1991
Trans1 Recv Date: 07/09/1991
Trans2 Recv Date: / /
TSD Site Recv Date: 07/18/1991
Part A Recv Date: 07/19/1991
Part B Recv Date: 08/01/1991
Generator EPA ID: NYD986951978
Trans1 EPA ID: MND980791321
Trans2 EPA ID: Not reported
TSDF ID 1: KSD981506025
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported

WESTCHESTER COUNTY - 112 EAST POST ROAD (Continued) **1000552792**

Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B007 - OTHER MISCELLANEOUS PCB WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00126
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	100

U184 **WESTCHESTER OFFICE BLDG.** **NY LTANKS** **S100141797**
NE **112 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.155 mi.
817 ft. **Site 4 of 7 in cluster U**

Relative: **Higher**
Actual: **238 ft.**

LTANKS:

Name:	WESTCHESTER OFFICE BLDG.
Address:	112 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9009334 / 1990-12-11
Facility ID:	9009334
Site ID:	243138
Spill Date:	1990-11-27
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1990-12-11
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-11-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1990-12-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-11-30
Spill Record Last Update:	1991-01-14
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported

WESTCHESTER OFFICE BLDG. (Continued) **S100141797**

Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	199725
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/14/91: FIXED LINE, TANK TECH CHECKED AND REPAIRED. NO CONTAMINATED SOIL. "
Remarks:	"TANK LEAKED WHEN 10 LBS. AIR PRESSURE PUT ON IT FUEL LEAKED TO CONCRETE BASEMENT FLOOR WEST,CTY. NOTIFIED DPW SPEEDI-DRY BEING APPLIED WCHD HANDLING"

All Materials:

Site ID:	243138
Operable Unit ID:	949838
Operable Unit:	01
Material ID:	429553
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

R185 **WESTCHESTER COUNTY COURT HOUSE** **RCRA-VSQG** **1007371355**
North **110 DR MARTIN LUTHER KING JR BLVD** **NYR000124206**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.155 mi.
817 ft. **Site 10 of 10 in cluster R**

Relative: **Lower**
Actual: **203 ft.**

RCRA-VSQG:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURT HOUSE
Handler Address:	110 DR MARTIN LUTHER KING JR BLVD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYR000124206
Contact Name:	DAVID W LOMASNEY
Contact Address:	DR MARTIN LUTHER KING JR BLVD
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	914-946-9681
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	County
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	DR MARTIN LUTHER KING JR BLVD
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	NO NAME FOUND
Owner Type:	County
Operator Name:	NO NAME FOUND

WESTCHESTER COUNTY COURT HOUSE (Continued) **1007371355**

Operator Type:	County
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

WESTCHESTER COUNTY COURT HOUSE (Continued) **1007371355**

Hazardous Waste Summary:
Waste Code: D007
Waste Description: CHROMIUM

Handler - Owner Operator:
Owner/Operator Indicator: Operator
Owner/Operator Name: NO NAME FOUND
Legal Status: County
Date Became Current: 2004-04-21 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: NO NAME FOUND
Legal Status: County
Date Became Current: 2004-04-21 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: WESTCHESTER COUNTY
Legal Status: County
Date Became Current: 2004-04-21 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: DON MACDONALD DPW
Legal Status: County
Date Became Current: 2004-04-21 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: Not reported
Owner/Operator City,State,Zip: Not reported
Owner/Operator Telephone: Not reported
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2004-04-30 00:00:00.0
Handler Name: WESTCHESTER COUNTY COURT HOUSE

WESTCHESTER COUNTY COURT HOUSE (Continued) **1007371355**

Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURT HOUSE
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	WESTCHESTER COUNTY COURT HOUSE
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	92211
NAICS Description:	COURTS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

Q186
SSW
1/8-1/4
0.156 mi.
825 ft.

WHITE PLAINS FD STATION 4
234 SOUTH LEXINGTON AVE
WHITE PLAINS, NY

Site 10 of 12 in cluster Q

NY LTANKS **S103478832**
N/A

Relative:
Higher

Actual:
231 ft.

LTANKS:

Name:	WHITE PLAINS FD STATION 4
Address:	234 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9804511 / 1998-08-12
Facility ID:	9804511
Site ID:	320194
Spill Date:	1998-07-10
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-07-10
CID:	312
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-07-10
Spill Record Last Update:	1998-10-02
Spiller Name:	Not reported
Spiller Company:	C/O WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MARK TSCHANTRE
Spiller Phone:	(914) 328-6549
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	257972
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"LEAKING 2000 GAL UST - CALLER HAS ONLY PERFORMED SOIL SAMPLING SO FAR"

All Materials:

Site ID:	320194
Operable Unit ID:	1065392
Operable Unit:	01
Material ID:	319224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Q187
SSW
1/8-1/4
0.159 mi.
840 ft.

GRANT MANOR PROPERTIES
235 SOUTH LEXINGTON AVE
WHITE PLAINS, NY

Site 11 of 12 in cluster Q

NY LTANKS **S100879284**
N/A

Relative:
Higher

Actual:
233 ft.

LTANKS:

Name:	GRANT MANOR PROPERTIES
Address:	235 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9706472 / 1998-02-27
Facility ID:	9706472
Site ID:	147080
Spill Date:	1997-08-28
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-08-28
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-08-28
Spill Record Last Update:	2003-10-20
Spiller Name:	LESTER CHAYET
Spiller Company:	GRANT MANOR PROPERTIES
Spiller Address:	235 SOUTH LEXINGTON AV
Spiller County:	001
Spiller Contact:	LESTER CHAYET
Spiller Phone:	(718) 649-9400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	125226
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/27/98 RETEST AFTER REPAIRS; ALL OK; "
Remarks:	"UNABLE TO OBTAIN A VACUUM. WILL REPAIR MANWAY SEALS AND RETEST."

All TTF:

Facility ID:	9706472
Spill Number:	9706472
Spill Tank Test:	1545287
Site ID:	147080
Tank Number:	1
Tank Size:	20000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00

GRANT MANOR PROPERTIES (Continued) **S100879284**

Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 147080
Operable Unit ID: 1049837
Operable Unit: 01
Material ID: 332052
Material Code: 0003A
Material Name: #6 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: GREAT GRANT MANOR PROP
Address: 235 SOUTH LEXINGTON AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0204243 / 2002-11-06
Facility ID: 0204243
Site ID: 147077
Spill Date: 2002-07-23
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-07-23
CID: 281
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-07-23
Spill Record Last Update: 2003-10-20
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: ED OR BETH DEALAUREANTS
Spiller Phone: (914) 946-1321
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 125226
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 11/06/02 TANK PASSED A RETEST AS PER WAYNE SCHNEIDER OF WCHD."
Remarks: "TANK TEST FAILURE AT ABOVE LOCATION PROPERTY OWNER HAS BEEN ADVISED

GRANT MANOR PROPERTIES (Continued) **S100879284**

OF PROBLEM. RECOMMENDING UNCOVERED,REPAIR AND RETEST."

All TTF:

Facility ID:	0204243
Spill Number:	0204243
Spill Tank Test:	1527308
Site ID:	147077
Tank Number:	1
Tank Size:	20000
Material:	0003
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	147077
Operable Unit ID:	855411
Operable Unit:	01
Material ID:	518501
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPILL NUMBER 0304500
Address:	235 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0304500 / 2003-10-31
Facility ID:	0304500
Site ID:	147078
Spill Date:	2003-07-29
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-07-29
CID:	199
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

GRANT MANOR PROPERTIES (Continued) **S100879284**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-29
Spill Record Last Update:	2003-12-12
Spiller Name:	Not reported
Spiller Company:	SOUTH LEX PARTNERS LLC C/O DELAURNETIS MANAGEMEN
Spiller Address:	235 S LEXINGTON
Spiller County:	001
Spiller Contact:	ED OR BETH DEALAUREANTS
Spiller Phone:	(914) 946-1321
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	125226
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-LALAK 10/15/03 Closure letter sent to DeLaurentis Mgmt. Co from C Lalak from the WCHD note: Any health related questions regarding soil contaminants should be referred to the Health Department. TG"
Remarks:	""

All Materials:

Site ID:	147078
Operable Unit ID:	871313
Operable Unit:	01
Material ID:	505359
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	235 SOUTH LEXINGTON AVE
Address:	235 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9313731 / 1995-01-05
Facility ID:	9313731
Site ID:	147079
Spill Date:	1994-02-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-01-05
SWIS:	6017
Investigator:	MONACO
Referred To:	Not reported
Reported to Dept:	1994-02-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	1994-09-27
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-03-08

GRANT MANOR PROPERTIES (Continued) **S100879284**

Spill Record Last Update:	2003-10-20
Spiller Name:	Not reported
Spiller Company:	PRESIDENCIAL MANAGEMENT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	125226
DEC Memo:	""
Remarks:	"20,000 GAL IN GROUND TANK SPILL THROUGH WALL INTO SUMP PUMP INTO WASTE LINES LT. DAMAN (FD) TOLD SPT. TO START CLEAN UP FAXED TO TODD EASTMAN TANK PUMPING OUT TANK CLEAN UP IN PROGRESS"

All Materials:

Site ID:	147079
Operable Unit ID:	992182
Operable Unit:	01
Material ID:	389103
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Q188 **235 SOUTH LEXINGTON AVENUE** **NY AST** **U003968059**
SSW **235 SOUTH LEXINGTON AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.159 mi.
840 ft. **Site 12 of 12 in cluster Q**

Relative:
Higher

Actual:
233 ft.

WESTCHESTER CO. AST:

Name:	235 SOUTH LEXINGTON AVENUE
Address:	235 SOUTH LEXINGTON AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-165468
Site Status:	Active
GDS Number:	Not reported
Operator Name:	South Lexington Management
Owner Name:	South Lexington Associates, LLC
Owner Street:	35-01 30th Avenue, Suite 300
Owner Address2:	Not reported
Owner City/State/Zip:	Astoria, NY 11103
Tank Number:	002
Status:	1. In-Service
Date Installation:	03/01/2004
Capacity:	12800
Product Stored:	0002. #4 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron

235 SOUTH LEXINGTON AVENUE (Continued) **U003968059**

Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access),10. Impervious Underlayment (AST Only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	9. Urethane
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	4. Double-Walled (underground only)
Overfill Prevention:	4. Product Level Gauge (Aboveground Only),5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

X189 **MT CARMEL** **NY LTANKS** **S100139372**
NW **92 SOUTH LEXINGTON AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.162 mi.
857 ft. **Site 1 of 3 in cluster X**

Relative: **Lower**

Actual: **200 ft.**

LTANKS:

Name:	OUR LADY OF MOUNT CARMEL
Address:	92 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8704169 / 1987-10-21
Facility ID:	8704169
Site ID:	219315
Spill Date:	1987-08-20
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-10-21
SWIS:	6017
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-08-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-09-25
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	""
Remarks:	"1OK SYSTEM- -.1091 GPH. TO BE EMPTIED AND CLEANED. CONTACT:FATHER RIBEZZI"

MT CARMEL (Continued) **S100139372**

All TTF:

Facility ID:	8704169
Spill Number:	8704169
Spill Tank Test:	1531431
Site ID:	219315
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	219315
Operable Unit ID:	908038
Operable Unit:	01
Material ID:	466817
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	OUR LADY OF MT CARMEL CHURCH
Address:	92 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8703713 / 1987-10-21
Facility ID:	8703713
Site ID:	239739
Spill Date:	1987-08-05
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1987-10-21
SWIS:	6017
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-08-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

MT CARMEL (Continued) **S100139372**

Remediation Phase:	0
Date Entered In Computer:	1987-08-14
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	NYS ARCHDIOCES
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	""
Remarks:	"TTTF 10K -.1100GPH"

All TTF:

Facility ID:	8703713
Spill Number:	8703713
Spill Tank Test:	1531288
Site ID:	239739
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239739
Operable Unit ID:	910351
Operable Unit:	01
Material ID:	469939
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	MT CARMEL
Address:	92 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1100855 / 2012-01-23
Facility ID:	1100855
Site ID:	448286
Spill Date:	2011-04-25
Spill Cause:	Tank Test Failure

MT CARMEL (Continued) **S100139372**

Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-04-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-04-25
Spill Record Last Update:	2012-01-23
Spiller Name:	Not reported
Spiller Company:	OUR LADY OF MT CARMEL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 855-3970
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	181357
DEC Memo:	"4/25/11: This is a 10K heating oil UST, estimated to be at least 60 years old. Thank was re-lined in 1980. WCDOH has required yearly testing of this tank - Kathy Morgan from US Tank Tech reports their company tested the tank every December from 2002 up until 2008. She does not know if anyone else tested it from Dec 08 until now. jod >>> Schneider, Wayne >wts1@westchestergov.com> 1/20/2012 3:52 PM >>> 1100855: 92 South Lexington Ave, White Plains- tank removed. Endpoint samples below cp-51 1/23/12: DEC requires no further action at this time. jod "
Remarks:	"1235 THE CALLER ADVISED DISPATCH THE TANK TEST FAILED. THE CALLER IS REQUESTING SPILLS TO CALL BACK. (PBS 3-074462), 10,000 GALLON TANK"

All Materials:

Site ID:	448286
Operable Unit ID:	1198525
Operable Unit:	01
Material ID:	2194807
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Y190 **APT. HOUSE** **NY LTANKS** **S102155221**
West **82 BANK STREET** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.162 mi.
857 ft. **Site 1 of 9 in cluster Y**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Name:	PBS
Address:	82 BANK STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0312286 / 2005-03-27
Facility ID:	0312286
Site ID:	301757
Spill Date:	2004-02-04
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2004-02-04
CID:	405
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-02-04
Spill Record Last Update:	2005-03-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	KATHY
Spiller Phone:	(914) 946-1320
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197977
DEC Memo:	"03/27/05 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Re-test or remove"

All TTF:

Facility ID:	0312286
Spill Number:	0312286
Spill Tank Test:	1528959
Site ID:	301757
Tank Number:	1
Tank Size:	4000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

APT. HOUSE (Continued) **S102155221**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

SPILLS:

Name:	APT. HOUSE
Address:	82 BANK STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9410155 / 1994-11-01
Facility ID:	9410155
Facility Type:	ER
DER Facility ID:	197977
Site ID:	240746
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	D4
SWIS:	6017
Spill Date:	1994-10-28
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	1994-11-01
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	TARRICONE FUELS
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"MISREAD TANK CLEANED UP BY FUEL CO SIDEWALK AFFECTED"

All Materials:

Site ID:	240746
Operable Unit ID:	1007900
Operable Unit:	01
Material ID:	376026
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Y191 **BSA ASSOCIATES, LLC** **NY UST** **U003994405**
West **82 BANK STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.162 mi.
857 ft. **Site 2 of 9 in cluster Y**

Relative:
Higher

Actual:
220 ft.

WESTCHESTER CO. UST:

Name:	BSA ASSOCIATES, LLC
Address:	82 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-048526 / Active
Operator Name:	DeLaurentis Investment Co, Inc.
Owner Name:	BSA Associates, LLC c/o DeLaurentis Investment
Owner Street:	384 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	82
Status:	1. In-Service
Capacity:	4000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	04/01/1980
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	0. None

T192 **JOHN LWHITE CONDO** **NY LTANKS** **S110140588**
East **9 GREENRIDGE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.162 mi.
858 ft. **Site 6 of 7 in cluster T**

Relative:
Higher

Actual:
260 ft.

LTANKS:

Name:	JOHN LWHITE CONDO
Address:	9 GREENRIDGE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0911533 / 2011-10-28
Facility ID:	0911533
Site ID:	424347
Spill Date:	2010-01-27
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017

JOHN LWHITE CONDO (Continued) **S110140588**

Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-01-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-01-27
Spill Record Last Update:	2020-02-14
Spiller Name:	KEN GELOK
Spiller Company:	JOHN L WHITE RESIDENCE
Spiller Address:	9 GREEN RIDGE AVE
Spiller County:	999
Spiller Contact:	KEN GELOK
Spiller Phone:	(201) 797-1909
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	373287
DEC Memo:	"Site is condominimum. Tank size is 5K. Caller states tank is registered with WCHD and he will notify WCHD. dt 1/27/10 5/13/11: Message sent to WCDOH requesting PBS info. jod From Lalak, Chris 6/10/2011 12:51 PM :: Wayne, Please follow up on these two old open spills 0912193 - 0911533 Chris --This is a PBS regulated facility. Wayne Schneider of WCDOH will follow up. jod 10/28/2011 As per WCDOH Greenridge estates. 1-13 Greenridge ave, white plains- passed retest NFA JO'M"
Remarks:	"TANK TEST FAILURE"

All Materials:

Site ID:	424347
Operable Unit ID:	1180129
Operable Unit:	01
Material ID:	2173988
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

S193 **NYSDEC** **NY MANIFEST** **1009235252**
NNE **GRAND & QUARRAPUS** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.168 mi.
885 ft. **Site 9 of 9 in cluster S**

Relative: NY MANIFEST:
Higher

Name:	NYSDEC
Address:	GRAND & QUARRAPUS
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA

Actual:
229 ft.

NYSDEC (Continued) **1009235252**

EPA ID: NYP003600954
Facility Status: Not reported
Location Address 1: GRAND & QUARRAPUS
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP003600954
Mailing Name: NYSDEC
Mailing Contact: ROBERT SMITH
Mailing Address 1: 21 S PUTT CORNERS RD
Mailing Address 2: Not reported
Mailing City: NEW PALTZ
Mailing State: NY
Mailing Zip: 12561
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142555453

NY MANIFEST:
Document ID: NYB2077632
Manifest Status: C
seq: Not reported
Year: 1991
Trans1 State ID: Not reported
Trans2 State ID: Not reported
Generator Ship Date: 03/19/1991
Trans1 Recv Date: 03/19/1991
Trans2 Recv Date: / /
TSD Site Recv Date: 04/02/1991
Part A Recv Date: 04/12/1991
Part B Recv Date: 04/12/1991
Generator EPA ID: NYP003600954
Trans1 EPA ID: NYD986908085
Trans2 EPA ID: Not reported
TSDF ID 1: NYD082785429
TSDF ID 2: Not reported
Manifest Tracking Number: Not reported
Import Indicator: Not reported
Export Indicator: Not reported
Discr Quantity Indicator: Not reported
Discr Type Indicator: Not reported
Discr Residue Indicator: Not reported
Discr Partial Reject Indicator: Not reported
Discr Full Reject Indicator: Not reported
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: Not reported
Waste Code: F003 - UNKNOWN
Waste Code: Not reported
Waste Code: Not reported

NYSDEC (Continued) **1009235252**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00050
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

U194 **WESTHAB COACHMAN FAMILY CENTER** **NY UST** **U004320208**
NE **123 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.169 mi.
891 ft. **Site 5 of 7 in cluster U**

Relative: WESTCHESTER CO. UST:
Higher

Actual:
236 ft.

Name:	WESTHAB COACHMAN FAMILY CENTER
Address:	123 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-801262 / Unregulated
Operator Name:	Westhab, Inc.
Owner Name:	Westchester County
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	6000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	09/01/1993
Date Perm Closure:	04/29/2015
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	9. Urethane
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

U195 **COACHMAN HOTEL** **RCRA-VSQG** **1007111869**
NE **123 E POST RD** **NY0000895086**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.169 mi.
891 ft. **Site 6 of 7 in cluster U**

Relative: **Higher**
Actual: **236 ft.**

RCRA-VSQG:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	COACHMAN HOTEL
Handler Address:	123 E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NY0000895086
Contact Name:	FRANK ALEXANDER
Contact Address:	E POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10601
Contact Telephone:	914-995-5797
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	District
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	E POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10601
Owner Name:	COUNTY OF WESTCHESTER
Owner Type:	County
Operator Name:	COACHMAN HOTEL
Operator Type:	District
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

COACHMAN HOTEL (Continued) **1007111869**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D008
Waste Description:	LEAD

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	COACHMAN HOTEL
Legal Status:	District
Date Became Current:	1979-12-31 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	123 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-995-5797
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601

COACHMAN HOTEL (Continued) **1007111869**

Owner/Operator Telephone:	914-285-2464
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	COACHMAN HOTEL
Legal Status:	District
Date Became Current:	1979-12-31 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	123 E POST RD
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-995-5797
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	District
Date Became Current:	1979-12-31 00:00:00.
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-995-5797
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	COUNTY OF WESTCHESTER
Legal Status:	County
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	148 MARTINE AVE
Owner/Operator City,State,Zip:	WHITE PLAINS, NY 10601
Owner/Operator Telephone:	914-285-2464
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	COACHMAN HOTEL - COUNTY OF WESTCHESTER
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	COACHMAN HOTEL

COACHMAN HOTEL (Continued) **1007111869**

Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	COACHMAN HOTEL
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1994-10-20 00:00:00.0
Handler Name:	COACHMAN HOTEL - COUNTY OF WESTCHESTER
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2003-04-03 00:00:00.0
Handler Name:	COACHMAN HOTEL
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	72111
NAICS Description:	HOTELS (EXCEPT CASINO HOTELS) AND MOTELS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

COACHMAN HOTEL (Continued) **1007111869**

Evaluation Action Summary:
Evaluations: No Evaluations Found

U196 **COACHMAN HOTEL** **NY LTANKS** **1000912672**
NE **123 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.169 mi.
891 ft. **Site 7 of 7 in cluster U**

Relative:
Higher

Actual:
236 ft.

LTANKS:

Name:	COACHMAN HOTEL
Address:	123 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9306655 / 1993-09-24
Facility ID:	9306655
Site ID:	211948
Spill Date:	1993-08-31
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1993-09-24
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1993-08-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1993-09-02
Spill Record Last Update:	1993-11-16
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175633
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"HOLE IN CROWN OF TANK WILL WORK WITH CTY. TO MAKE SURE NO SOIL CONTAMINATION 8K 35 YEARS OLD TANK W.C. IS LOOKING TO BUY HOTEL"

All TTF:

Facility ID:	9306655
Spill Number:	9306655
Spill Tank Test:	1541932
Site ID:	211948
Tank Number:	Not reported
Tank Size:	0
Material:	0001

COACHMAN HOTEL (Continued) **1000912672**

EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 211948
Operable Unit ID: 984819
Operable Unit: 01
Material ID: 396502
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

Y197 **CON EDISON GAS DRIP: 0** **RCRA NonGen / NLR** **1016451184**
WNW **107 FISHER AVE** **NYP004302253**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.173 mi.
914 ft. **Site 3 of 9 in cluster Y**

Relative: **Lower**
Actual: **209 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 2013-05-17 00:00:00.0
Handler Name: CON EDISON GAS DRIP: 0
Handler Address: 107 FISHER AVE
Handler City,State,Zip: WHITE PLAINS, NY 10606
EPA ID: NYP004302253
Contact Name: ERIK THOMPSON
Contact Address: Not reported
Contact City,State,Zip: Not reported
Contact Telephone: 718-319-2340
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: TROUBLE SHOOTER DISPATCHERL1-2
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R2
Mailing Address: Not reported
Mailing City,State,Zip: NEW YORK, NY 10003
Owner Name: Not reported

CON EDISON GAS DRIP: 0 (Continued) **1016451184**

Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2013-09-10 16:26:21.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported

CON EDISON GAS DRIP: 0 (Continued) **1016451184**

Sub-Part P Indicator: Not reported

Historic Generators:

Receive Date:	2013-04-17 00:00:00.0
Handler Name:	CON EDISON GAS DRIP: 0
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-05-17 00:00:00.0
Handler Name:	CON EDISON GAS DRIP: 0
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

T198 **CITY PARKING GARAGE** **NY LTANKS** **S100177695**
East **CHESTER AVE MARBLE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.173 mi.
916 ft. **Site 7 of 7 in cluster T**

Relative:
Higher

Actual:
246 ft.

LTANKS:

Name:	CITY PARKING GARAGE
Address:	CHESTER AVE MARBLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9109520 / 1992-03-25
Facility ID:	9109520
Site ID:	158538
Spill Date:	1991-12-06
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other

CITY PARKING GARAGE (Continued) **S100177695**

Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1991-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-12-10
Spill Record Last Update:	1992-03-25
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133970
DEC Memo:	""
Remarks:	"TANK FILLED ON 12/3 5 IN TANK NOW TANK IS IN A VAULT OIL IS LEAKING OUT THE BOTTOM WCHD NOTIFIED"

All Materials:

Site ID:	158538
Operable Unit ID:	963358
Operable Unit:	01
Material ID:	418130
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	250.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

199
NE
1/8-1/4
0.176 mi.
930 ft.

COMMERCIAL **NY LTANKS** **S121988273**
130-144 EAST POST RD **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
234 ft.

LTANKS:

Name:	COMMERCIAL
Address:	130-144 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0002215 / 2011-02-28
Facility ID:	0002215
Site ID:	159846
Spill Date:	2000-05-22

COMMERCIAL (Continued) **S121988273**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-05-22
CID:	323
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-05-22
Spill Record Last Update:	2011-02-28
Spiller Name:	ROBERT KIM
Spiller Company:	COMMERCIAL
Spiller Address:	130-144 EAST POST RD
Spiller County:	001
Spiller Contact:	ROBERT KIM
Spiller Phone:	(914) 723-2964
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	135018
DEC Memo:	"12/28/09: File review. Reported as a TTF of a 1K tank, commercial property, not a registered facility. Call back notes on initial report state: 1K UG - To call & advise WCHD with future . No further information received. jod 2/28/11: This is the same tank as spill 1005304. Tank was never removed or retested after initial failure. Tank was leaking. Tank was removed and clean up was completed ten years later after the shopping center burned down. jod"
Remarks:	"UNKNOWN WHAT IS GOING TO BE DONE."

All TTF:

Facility ID:	0002215
Spill Number:	0002215
Spill Tank Test:	1525625
Site ID:	159846
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	159846

COMMERCIAL (Continued) **S121988273**

Operable Unit ID:	823747
Operable Unit:	01
Material ID:	550585
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

200 WSW 1/8-1/4 0.178 mi. 942 ft. **MITCHELL ESTATE - TTF** **NY LTANKS** **S117364448**
5 NUTGROVE ST **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 285 ft.

LTANKS:

Name:	MITCHELL ESTATE - TTF
Address:	5 NUTGROVE ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1405501 / 2014-11-19
Facility ID:	1405501
Site ID:	498930
Spill Date:	2014-08-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-08-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-08-20
Spill Record Last Update:	2014-11-19
Spiller Name:	CHRISTINA LAFARO (LISTING AGENT)
Spiller Company:	ESTATE OF MITCHELL
Spiller Address:	5 NUTGROVE ST
Spiller County:	999
Spiller Contact:	CHRISTINA LAFARO (LISTING AGENT)
Spiller Phone:	9143370900
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	453887
DEC Memo:	"8/20/14 Spoke to tank tester, who said there was hissing, popping, and bonging . Part of a real estate transaction involving an estate. Not known what will happen. dw 11/19/2014: UST removed by C2G Environmental. No evidence of a leak or any significant contamination

MITCHELL ESTATE - TTF (Continued) **S117364448**

found. Closure Report/Documentation has been reviewed and will be entered into DecDocs. Based upon information provided, no further action required at this time. jod"

Remarks: "550G UST failed test, no known losses."

All Materials:

Site ID:	498930
Operable Unit ID:	1248365
Operable Unit:	01
Material ID:	2249796
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Z201 **GREENRIDGE MEDICAL PLAZA** **NY UST** **U003949576**
ESE **12 GREENRIDGE ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.182 mi.
961 ft. **Site 1 of 3 in cluster Z**

Relative: **Higher**

Actual: **272 ft.**

WESTCHESTER CO. UST:

Name:	GREENRIDGE MEDICAL PLAZA
Address:	12 GREENRIDGE ROAD
City,State,Zip:	WHITE PLAINS, NY 10605
Id/Status:	3-801123 / Unregulated: <1101 gal. PBS
Operator Name:	Malka Shalit
Owner Name:	Greenridge Management
Owner Street:	701 Westchester Avenue Suite 310W
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10604
GDS Number:	Not reported
Tank Number:	01
Status:	4. Closed - in place
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	12/20/2003
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported

GREENRIDGE MEDICAL PLAZA (Continued) **U003949576**

Spill Prevention: 0. None
Dispenser: 2. Suction

W202 **LOPEZ - TTF** **NY LTANKS** **S117364530**
South **43 DAVIS AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.182 mi.
963 ft. **Site 2 of 3 in cluster W**

Relative: **Higher**

Actual: **248 ft.**

LTANKS:

Name:	LOPEZ - TTF
Address:	43 DAVIS AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1407225 / 2015-09-25
Facility ID:	1407225
Site ID:	500733
Spill Date:	2014-10-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2014-10-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2014-10-10
Spill Record Last Update:	2015-09-25
Spiller Name:	Not reported
Spiller Company:	TANK TEST FAILURE
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	ANDREA LOPEZ
Spiller Phone:	(914) 681-1791
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	455735
DEC Memo:	"Spoke to caller. Tank tester has recom'd removal. Could not reach homeowner - confirmed number with caller and it is correct....mm 12/08/14: Update from Envirostar: We pulled a 1000 UST at 43 Davis Ave White Plains NY that had previously failed a tank test (spill # 1407225). The tank did have holes and there was contamination in the soil. The home owner is contacting there insurance. Customer info: Lopez 43 Davis Ave White Plains NY jod 2/10/2015: Envirostar reports they removed and disposed of the leaking UST and petroleum contaminated soil. Closure Report/Documentation submiited by H2M has been reviewed and entered into DecDocs. Based upon information provided, no further action required at this time. jod 9/25/2015: Envirostar disposed of the leaking UST and 16.11 tons of petroleum contaminated soil. Post excavation soil sample results submitted for review. Closure Report has been entered into DecDocs. Based upon

LOPEZ - TTF (Continued) **S117364530**

information provided, no further action required at this time. jod"
Remarks: "recommend removal - 1000 gall ust"

All Materials:
Site ID: 500733
Operable Unit ID: 1250128
Operable Unit: 01
Material ID: 2251809
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

AA203 **BELL ATLANTIC NY** **RCRA NonGen / NLR** **1007205629**
SSW **S LEXINGTON AVE & CHARLES ST** **NYP000937300**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.195 mi.
1027 ft. **Site 1 of 3 in cluster AA**

Relative: **Higher**
Actual: **238 ft.**

RCRA NonGen / NLR:
Date Form Received by Agency: 1998-03-01 00:00:00.0
Handler Name: BELL ATLANTIC NY
Handler Address: S LEXINGTON AVE & CHARLES ST
Handler City,State,Zip: WHITE PLAINS, NY 10606
EPA ID: NYP000937300
Contact Name: JOHN QUATRALE
Contact Address: BELL ATLANTIC-ENV AFFAIRS
Contact City,State,Zip: NEW YORK, NY 10016
Contact Telephone: 212-338-7141
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 02
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: NY
State District: NYSDEC R3
Mailing Address: BELL ATLANTIC-ENV AFFAIRS
Mailing City,State,Zip: NEW YORK, NY 10016
Owner Name: Not reported
Owner Type: Not reported
Operator Name: Not reported
Operator Type: Not reported
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No

BELL ATLANTIC NY (Continued) **1007205629**

Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	1998-02-28 00:00:00.0
Handler Name:	BELL ATLANTIC-NY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

BELL ATLANTIC NY (Continued) **1007205629**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1998-03-01 00:00:00.0
Handler Name:	BELL ATLANTIC NY
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1998-02-27 00:00:00.0
Handler Name:	BELL ATLANTIC-NY
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	5133
NAICS Description:	TELECOMMUNICATIONS

NAICS Code:	51331
NAICS Description:	WIRED TELECOMMUNICATIONS CARRIERS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

X204 **STATION PLAZA** **NY UST** **U003885183**
NNW **76 SOUTH LEXINGTON AVENUE** **NY AST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.197 mi.
1038 ft. **Site 2 of 3 in cluster X**

Relative: **Lower**

Actual: **201 ft.**

WESTCHESTER CO. UST:

Name:	STATION PLAZA
Address:	76 SOUTH LEXINGTON AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-139637 / Administratively Closed
Operator Name:	Resident Supt.
Owner Name:	Station Plaza Housing Co. Mgmt Corp.
Owner Street:	5 West Main Street
Owner Address2:	Not reported
Owner City:	Elmsford
Owner State:	NY
Owner Zipcode:	10523
GDS Number:	Not reported
Tank Number:	F01
Status:	4. Closed - in place
Capacity:	25000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1976
Date Perm Closure:	05/08/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	1. Painted/Asphalt Coating
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

WESTCHESTER CO. AST:

Name:	STATION PLAZA
Address:	76 SOUTH LEXINGTON AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-139637
Site Status:	Administratively Closed
GDS Number:	Not reported
Operator Name:	Resident Supt.
Owner Name:	Station Plaza Housing Co. Mgmt Corp.
Owner Street:	5 West Main Street
Owner Address2:	Not reported
Owner City/State/Zip:	Elmsford, NY 10523
Tank Number:	DF1
Status:	0. Administratively closed
Date Installation:	06/01/1998
Capacity:	330
Product Stored:	0008. Diesel

STATION PLAZA (Continued) **U003885183**

Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	10. Impervious Underlayment (AST Only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	DT2
Status:	3. Closed - Removed
Date Installation:	06/01/1998
Capacity:	25
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Spill Prevention:	Not reported
Dispenser:	2. Suction

X205 **CON EDISON** **NY MANIFEST** **S117058697**
NNW **76-78 S LEXINGTON AVE & FISCHE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.197 mi.
1038 ft. **Site 3 of 3 in cluster X**

Relative: **Lower**
Actual: **201 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	76-78 S LEXINGTON AVE & FISCHE
City,State,Zip:	WHITE PLAINS, NY 10603
Country:	USA
EPA ID:	NYP004508313
Facility Status:	Not reported
Location Address 1:	F/O 76-78 S LEXINGTON AVE
Code:	BP
Location Address 2:	VS6599
Total Tanks:	Not reported
Location City:	WHITE PLAINS

CON EDISON (Continued) **S117058697**

Location State:	NY
Location Zip:	10801
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004508313
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL
Mailing Address 2:	15TH ST
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	04/22/2014
Trans1 Recv Date:	04/22/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/23/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004508313
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012770975JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks

CON EDISON (Continued) **S117058697**

Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AA206 **PURDY MANOR APARTMENTS LTD.** **NY AST** **A100204408**
SSW **1 CHARLES STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.199 mi.
1049 ft. **Site 2 of 3 in cluster AA**

Relative:
Higher

Actual:
238 ft.

WESTCHESTER CO. AST:

Name:	PURDY MANOR APARTMENTS LTD.
Address:	1 CHARLES STREET
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-800733
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Eugene Szpynda
Owner Name:	Purdy Manor Apartments Ltd.
Owner Street:	1 Charles Street
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10606
Tank Number:	1
Status:	1. In-Service
Date Installation:	01/01/1985
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	1. Diking (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	1. Diking (aboveground only)
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	1. Catch Basin
Dispenser:	3. Gravity

V207 **POST ROAD CORRIDOR - WHITE PLAINS** **NY BROWNFIELDS** **S111458201**
SW **77 WEST POST ROAD** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.199 mi.
1051 ft. **Site 4 of 4 in cluster V**

Relative:
Higher

Actual:
223 ft.

BROWNFIELDS:

Name:	POST ROAD CORRIDOR - WHITE PLAINS - OFF-SITE
Address:	77 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
Program:	BCP
Site Code:	544843
Acres:	Not reported
HW Code:	C360129A
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	04/07/2017
Record Updated Date:	02/21/2018
Update By:	AMOMOROG
Site Description:	Site Location: The site is located in the City of White Plains, Westchester County. To the west of the site is Rathbun Avenue and commercial properties, to the north are residential properties, to the east is South Lexington Avenue, and to the south is Maple Avenue and residential properties. Site Features: The site consists of several tax parcels adjacent to the Post Road Corridor BCP site C360129. Several commercial buildings and parking lots make up the site. Current Zoning and Land Use: The site is zoned B-3, which is a general retail district allowing retail, office and service business uses and multi-family dwellings. Surrounding land use is mixed, consisting of residential and commercial properties. Past Use of the Site: Former commercial uses at the Post Road Corridor BCP site included dry cleaners; gas stations with underground storage tanks (USTs); automobile sales and service facilities with USTs, above ground storage tanks (ASTs), hydraulic lifts, and associated parking lots; various commercial businesses and offices; and commercial parking lots. Site Geology and Hydrogeology: The site geology consists of historic fill material, native till, highly weathered bedrock. The depth to bedrock ranges from approximately 17 to 52 feet below grade. Groundwater at the site most likely ranges from 3 to 11 feet below ground surface and flows to the northeast.
Env Problem:	The on-site investigation results shows potential for off-site impact from the previous uses on-site as well as a potential upgradient source of contamination as groundwater impacted with both petroleum related hydrocarbons and chlorinated volatile organic compounds appears to be migrating on-site. An off-site investigation has not been conducted at this time. High concentrations of tetrachloroethene (PCE) in groundwater lead to an on-site significant threat determination. The potential exists for vapor intrusion impacts in off-site buildings.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

Lat/Long:	Not reported
Dell:	Not reported
Record Add:	4/11/2017 11:29:00 AM
Record Upd:	4/11/2017 11:29:00 AM
Updated By:	JLVERRIG
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Name:	POST ROAD CORRIDOR - WHITE PLAINS
Address:	77 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10606
Program:	BCP
Site Code:	477447
Acres:	3.69
HW Code:	C360129
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	01/02/2013
Record Updated Date:	06/10/2020
Update By:	AMOMOROG
Site Description:	Location: The Post Road Corridor - White Plains site is located at 77 West Post Road in the City of White Plains, Westchester County. This site is made up of 10 tax parcels occupying 3.69 acres of the overall 5-acre redevelopment project. The site is bounded by West Post Road to the north, Maple Avenue to the south, Rathbun Avenue to the west, and South Lexington Avenue to the east, with a separate out-parcel lot on the northwest corner of West Post Road and South Lexington Avenue. Site Features: All 10 parcels are currently vacant. Abandoned former commercial buildings of varying size on the site have been demolished, leaving only grass, trees and former parking lots. Current Zoning and Land Use: Nine of the 10 parcels are zoned B-3, which is a general retail district allowing retail, office and service business uses and multi-family dwellings. The other parcel is zoned B-2, which is an intermediate business district. The site is part of a planned mixed-use (commercial and residential) development. Surrounding land use is mixed, consisting of residential and commercial properties including a church. Past Use of the Site: The site's 10 parcels initially contained residential buildings as early as 1905 which later were used for commercial purposes beginning in the 1930s. Former commercial uses included dry cleaners; gas stations with underground storage tanks (USTs); automobile sales and service

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

facilities with USTs, aboveground storage tanks (ASTs), hydraulic lifts, and associated parking lots; various commercial businesses and offices; and commercial parking lots. In 2005 two in-ground hydraulic lifts were removed from the site. In 2010 two USTs, eleven in-ground hydraulic lifts, a floor drain and an oil water separator were also removed from the site. Approximately 408 tons of impacted soil and 1,180 gallons of contaminated groundwater were removed from the site during this work. In 2012 four USTs and approximately 360 tons of petroleum impacted soil were removed from the site. These removals were completed under the DEC spill program and associated spill numbers have been closed. Site Geology and Hydrogeology: The site geology consists of historic fill material, native till, and highly weathered bedrock. The depth to bedrock ranges across the site from approximately 17 to 52 feet below grade. Groundwater at the site ranges from approximately 3 to 11 feet below ground surface and flows to the northeast.

Env Problem:

Nature and Extent of Contamination: Soil and groundwater were analyzed for volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), metals, polychlorinated biphenyls (PCBs), and pesticides. Based upon investigation conducted to date, the primary contaminants of concern include chlorinated VOCs, petroleum related compounds and metals. No other VOCs, SVOCs, metals or PCBs/pesticides than those identified below were found in soil or groundwater at levels exceeding restricted residential soil cleanup objectives, protection of groundwater soil cleanup objectives or groundwater standards. Soil - Soil samples collected from across the site indicate the presence of certain contaminants in varying degrees generally consistent with the former use of each parcel. VOCs, including acetone up to 0.51 parts per million (ppm)(protection of groundwater soil cleanup objective (PGWSCO)of 0.50 parts per million (ppm)), benzene up to 3.4 ppm (PGWSCO of 0.060 ppm), cis-1,2-dichloroethene (cis-1,2-DCE) up to 1.2 ppm (PGWSCO of 0.25 ppm), ethylbenzene up to 140 ppm (PGWSCO of 1 and restricted residential soil cleanup objective (RRSCO) of 41 ppm), tetrachloroethene (PCE) up to 2.32 ppm (PGWSCO of 1.3 ppm), toluene up to 37 ppm (PGWSCO of 0.7 ppm) and xylenes up to 430 ppm (PGWSCO of 1.6 ppm and RRSCO 100 ppm), SVOCs, including benzo(a)anthracene up to 8.9 ppm (PGWSCO and RRSCO of 1 ppm), benzo(b)fluoranthene up to 8.8 ppm (PGWSCO of 1.7 ppm and RRSCO of 1 ppm), benzo(k)fluoranthene up to 3.7 ppm (PGWSCO of 1.7 ppm), benzo(a)pyrene up to 7 ppm (RRSCO of 1 ppm), chrysene up to 7.6 ppm (PGWRSCO of 1 ppm and RRSCO of 3.9 ppm), naphthalene up to 26 ppm (PGWSCO of 12 ppm), indeno(1,2,3-cd)pyrene up to 4.6 ppm (RRSCO of 0.5 ppm) and dibenzo(a,h)anthracene up to 2 ppm (RRSCO of .33 ppm) and metals including arsenic up to 18 ppm (PGWSCO and RRSCO of 16 ppm), barium up to 490 ppm (RRSCO of 400 ppm), lead up to 1,100 ppm (PGWSCO of 450 ppm and RRSCO of 400 ppm), and mercury up to 2.9 ppm (PGWSCO of 0.73 ppm and RRSCO of 0.81 ppm) were detected in the soil above PGWSCOs and/or RRSCOs. There is no evidence of off-site contamination in soils. Groundwater - Groundwater samples collected from across the site indicate the presence of certain contaminants in varying degrees generally consistent with the former use of each parcel. VOCs, including benzene up to 530 parts per billion (ppb) (SCG of 1 ppb), cis-1,2-DCE up to 340 ppb (SCG of 5 ppb), ethylbenzene up to 1,100 ppb (SCG of 5 ppb), isopropylbenzene up to 95 ppb (SCG of 5 ppb), xylene (total) up to 3,000 ppb (SCG of 5 ppb), methyl tert-butyl ether (MTBE) up to 120 ppb (SCG of 10 ppb), tetrachloroethene up to

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

	3,300 ppb (SCG of 5 ppb), toluene up to 110 ppb (SCG of 5 ppb), trans-1,2-dichloroethene up to 18 ppb (SCG of 5 ppb), trichloroethene up to 420 ppb (SCG of 5 ppb) and vinyl chloride up to 49 ppb (SCG of 2 ppb), SVOCs, including naphthalene up to 180 ppb (SCG of 10 ppb) and pentachlorophenol up to 2 ppb (SCG of 1 ppb) and metals including antimony up to 5.03 ppb (SCG of 3 ppb), iron up to 35,500 ppb (SCG of 300 ppb), manganese up to 4,724 ppb (SCG of 300 ppb) and sodium up to 583,000 ppb (SCG of 20,000 ppb) were found in excess of ambient water quality standards and guidance. Groundwater contaminated with chlorinated VOCs appear to be migrating from the site to off-site locations. Soil Vapor - On-site soil vapor was not completed during the RI based on the lack of existing structures, but is presumed to be contaminated given the results in other environmental media. Some petroleum related compounds, including 2-hexanone up to 75 ug/m3, ethanol up to 211 ug/m3, hexane up to 20.4 ug/m3, benzene up to 17.6 ug/m3, toluene up to 68.2 ug/m3, xylenes up to 92.1 ug/m3, heptane up to 23.7 ug/m3, and cyclohexane up to 164 ug/m3 were detected in off-site soil vapor samples along Maple Avenue. The potential exists for soil vapor intrusion impacts in off-site buildings.
Health Problem:	People will not come into contact with soil and groundwater contamination unless they dig below the ground surface. People are not drinking the contaminated groundwater because the area is served by a public supply that is not affected by this contamination. Volatile organic compounds in the groundwater and/or soil may move into the soil vapor (air spaces within the soil), which in turn may move into the overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. The site is vacant so inhalation of contaminants in indoor air via vapor intrusion is not a current concern. However, the potential exists for the inhalation of contaminants due to soil vapor intrusion for any future on-site development. An evaluation is needed to determine whether soil vapor intrusion is a concern for any off-site buildings.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	1/3/2013 9:37:00 AM
Record Upd:	7/15/2016 9:52:00 AM
Updated By:	JLVERRIG
Own Op:	1
Sub Type:	Not reported
Owner Name:	Drew Greenwald
Owner Company:	Post Maple 77, LLC
Owner Address:	c/o Grid Properties
Owner Addr2:	2309 Frederick Douglass Boulevard
Owner City,St,Zip:	New York, NY
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	James tuman

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

Owner Company:	Post Maple 77, LLC
Owner Address:	c/o Grid Properties, Inc.
Owner Addr2:	2309 Frederick Douglass Boulevard
Owner City,St,Zip:	New York, NY
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Drew Greenwald
Owner Company:	Post Maple 77, LLC
Owner Address:	c/o Grid Poperties
Owner Addr2:	2309 Frederick Douglass Boulevard
Owner City,St,Zip:	New York, NY
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Tim Baird
Owner Company:	White Plains Public Library
Owner Address:	100 Martine Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Please call for an appointment
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	vinyl chloride
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	trichloroethene (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	n-propylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	naphthalene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	cis-1,2-dichloroethene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,3,5-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	xylene (mixed)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	ethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	1,2,4-trimethylbenzene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	toluene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(k)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	mercury
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	barium
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	dibenz[a,h]anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	MTBE (methyl-tert-butyl ether)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	chrysene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo[k]fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(b)fluoranthene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	lead
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

Waste Type:	benzo(a)anthracene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	benzo(a)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	indeno(1,2,3-CD)pyrene
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	arsenic
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	C360129-03-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	2/10/2020 9:22:00 AM
Record Updated:	2/10/2020 9:22:00 AM
Updated By:	JCSTARR

SPILLS:

Name:	SHOLZ BUICK
Address:	77 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1112748 / 2013-09-25
Facility ID:	1112748
Facility Type:	ER
DER Facility ID:	415184
Site ID:	460706
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2012-02-06
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-02-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-02-06
Spill Record Last Update:	2013-09-25
Spiller Name:	Not reported
Spiller Company:	SHOLZ BUICK
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"2/6/12: Tank removal at former car dealership. This does not appear

POST ROAD CORRIDOR - WHITE PLAINS (Continued) **S111458201**

to be a PBS regulated site. Chris Lalak of WCDoH is checking records. Message sent to Royal Environmental requesting additional information on the property owner. jod 3/15/12: Closure report from DRE (received from Royal Environmental) entered into Edocs. It appears this property is part of the Sholz Ford Property at 55 West Post, Spill numbers 0901783 and 0901804. Report states that no ground water was encountered during excavation, so no ground water samples were taken. Next paragraph states ground water samples results were negative for contamination. Later in report, photographs show ground water within the excavation. jod 4/9/12: Message sent to Royal requesting clarification on ground water sampling. jod 4/12/12: I received a corrected copy of the closure report from DRE - entered into eDocs. jod 9/25/13: No further action is required on this tank removal spill number. Spill 0709611 is the active spill number for the ground water contamination at this site. jod"

Remarks: "HOLES IN 550 UST, FOUND DURING REMOVAL."

All Materials:

Site ID:	460706
Operable Unit ID:	1210805
Operable Unit:	01
Material ID:	2208470
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Y208 **US POSTAL SERVICE** **RCRA NonGen / NLR** **1000556704**
WNW **100 FISHER AVE** **NY MANIFEST** **NYD986992790**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.200 mi.
1054 ft. **Site 4 of 9 in cluster Y**

Relative: **Lower**

Actual: **208 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	US POSTAL SERVICE
Handler Address:	100 FISHER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10602
EPA ID:	NYD986992790
Contact Name:	Not reported
Contact Address:	FISHER AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10602
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Federal
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported

US POSTAL SERVICE (Continued) **1000556704**

State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	FISHER AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10602
Owner Name:	US POSTAL SERVICE
Owner Type:	Federal
Operator Name:	US POSTAL SERVICE
Operator Type:	Federal
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	The land is federally-owned, The site is federally-owned, The site is federally-operated
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0

US POSTAL SERVICE (Continued) **1000556704**

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	X003
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	US POSTAL SERVICE
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	475 LENFANTE PLZ
Owner/Operator City,State,Zip:	WASHINGTON, DC 20260
Owner/Operator Telephone:	202-268-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	US POSTAL SERVICE
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	475 LENFANTE PLZ
Owner/Operator City,State,Zip:	WASHINGTON, DC 20260
Owner/Operator Telephone:	202-268-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	US POSTAL SERVICE
Legal Status:	Federal
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	475 LENFANTE PLZ
Owner/Operator City,State,Zip:	WASHINGTON, DC 20260
Owner/Operator Telephone:	202-268-2000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	US POSTAL SERVICE

US POSTAL SERVICE (Continued) **1000556704**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2003-07-16 00:00:00.0
Handler Name:	US POSTAL SERVICE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	US POSTAL SERVICE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	US POSTAL SERVICE
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1992-01-31 00:00:00.0
Handler Name:	US POSTAL SERVICE
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

US POSTAL SERVICE (Continued) **1000556704**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: US POSTAL SERVICE
Address: 100 FISHER AVE
City,State,Zip: WHITE PLAINS, NY 10602
Country: USA
EPA ID: NYD986992790
Facility Status: Not reported
Location Address 1: 100 FISHER AVE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD986992790
Mailing Name: US POSTAL SERVICE
Mailing Contact: DONALD CUCURULLO
Mailing Address 1: 100 FISHER AVE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10602
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9142872500

NY MANIFEST:
Document ID: MAK7304960
Manifest Status: Not reported
seq: 01
Year: 1998
Trans1 State ID: 28038MA
Trans2 State ID: Not reported
Generator Ship Date: 12/28/1998
Trans1 Recv Date: 12/28/1998
Trans2 Recv Date: Not reported

US POSTAL SERVICE (Continued) **1000556704**

TSD Site Recv Date:	01/07/1999
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD986992790
Trans1 EPA ID:	MAD985290469
Trans2 EPA ID:	Not reported
TSDF ID 1:	MA5000004713
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D009 - MERCURY 0.2 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00900
Units:	P - Pounds
Number of Containers:	003
Container Type:	DF - Fiberboard or plastic drums (glass)
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

Y209 **CON EDISON GAS MAIN: TRANSMISSION MAIN** **RCRA NonGen / NLR** **1016149200**
WNW **100 FISHER AVE** **FINDS** **NYP004278610**
1/8-1/4 **WHITE PLAINS, NY 10606** **ECHO**
0.200 mi. **NY MANIFEST**
1054 ft. **Site 5 of 9 in cluster Y**

Relative: RCRA NonGen / NLR:
Lower

Actual: Date Form Received by Agency:	2017-07-28 00:00:00.0
208 ft. Handler Name:	CON EDISON GAS MAIN: TRANSMISSION MAIN
Handler Address:	100 FISHER AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYP004278610
Contact Name:	CHARLES CALDERON
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-319-2310
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	TROUBLE SHOOTER DISPATCHERL1-2
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported

CON EDISON GAS MAIN: TRANSMISSION MAIN (Continued) **1016149200**

Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported

CON EDISON GAS MAIN: TRANSMISSION MAIN (Continued) **1016149200**

Handler Date of Last Change:	2017-11-22 10:31:57.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2012-11-19 00:00:00.0
Handler Name:	CON EDISON GAS MAIN: TRANSMISSION MAIN
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	2017-07-28 00:00:00.0
Handler Name:	CON EDISON GAS MAIN: TRANSMISSION MAIN
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110029258693

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

CON EDISON GAS MAIN: TRANSMISSION MAIN (Continued) **1016149200**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.
ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1016149200
Registry ID:	110029258693
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110029258693
Name:	CON EDISON GAS MAIN: TRANSMISSION MAIN
Address:	100 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	CON EDISON
Address:	100 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYP004278610
Facility Status:	Not reported
Location Address 1:	100 FISHER AVE & BANK ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WESTCHESTER
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004278610
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

CON EDISON GAS MAIN: TRANSMISSION MAIN (Continued) **1016149200**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/19/2012
Trans1 Recv Date:	11/19/2012
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/20/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004278610
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	004806783FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	810
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	18
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	B007
Waste Code 1_6:	Not reported

W210 **CAROD ASSOCIATES, L.P.** **NY UST** **U003994419**
South **47 DAVIS AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.200 mi.
1058 ft. **Site 3 of 3 in cluster W**

Relative: WESTCHESTER CO. UST:
Higher

Actual: Name: CAROD ASSOCIATES, L.P.
255 ft. Address: 47 DAVIS AVENUE
City,State,Zip: WHITE PLAINS, NY 10605
Id/Status: 3-600886 / Active
Operator Name: Carod Associates, L.P.
Owner Name: Carod Associates, L.P.
Owner Street: 47 Davis Avenue
Owner Address2: Not reported
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10605
GDS Number: Not reported

Tank Number: 1
Status: 1. In-Service
Capacity: 4000
Product Stored: 0001. #2 Fuel Oil
Product Stored Percent: Not reported
Tank Leak Detection: 1. Electronic Interstitial Monitoring
Date Installation: 06/01/1996
Date Perm Closure: 01/01/1900
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 4. Fiberglass coated steel
Tank Internal Protection: 1. Epoxy liner
Tank External Protection: 4. Fiberglass
Tank Secondary Containment: 4. Double-Walled (underground only)
Piping Location: 3. Aboveground/Underground Combination
Piping Type: 1. Steel/Carbon/ Steel/Iron
Piping External Protection: 1. Painted/Asphalt Coating
Overfill Prevention: 2. High Level Alarm,5. Vent Whistle
Piping Secondary Containment: 4. Double-Walled (underground only)
Spill Prevention: 1. Catch Basin
Dispenser: 2. Suction

---

211 **RESIDENCE** **NY LTANKS** **S104191940**
SSE **23 OAKWOOD RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.201 mi.
1061 ft.

Relative: LTANKS:
Higher

Actual: Name: RESIDENCE
249 ft. Address: 23 OAKWOOD RD
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9906780 / 2000-01-28
Facility ID: 9906780
Site ID: 246760
Spill Date: 1999-09-07
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017

RESIDENCE (Continued) **S104191940**

Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-09-07
CID:	390
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-09-07
Spill Record Last Update:	2000-02-07
Spiller Name:	UNK
Spiller Company:	RESIDENCE....
Spiller Address:	23 OAKWOOD RD
Spiller County:	001
Spiller Contact:	UNK
Spiller Phone:	(000) 000-0000
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	202609
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 01/28/2000 DEC INSPECTED SITE. TANK CANNOT BE EXCAVATED OR REMOVED BECUASE IT IS BURIED IN THE FOUNDATION AND BENEATH A CONCRETE PATIO,. TANK WAS CUT, CLEANED AND INSPECTED BY NORTHEAST ENVIRONMENTAL. HOLES WERE FOUND IN TANK. SOIL SAMPLES FROM BENEATH TANK SHOW MINIMAL CONTAMINATION. TANK WAS ABANDONED IN PLACE. NFA"
Remarks:	"tank failed test - no product spillage"

All TTF:

Facility ID:	9906780
Spill Number:	9906780
Spill Tank Test:	1547587
Site ID:	246760
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	246760
Operable Unit ID:	1081085
Operable Unit:	01
Material ID:	299504
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

RESIDENCE (Continued) **S104191940**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Y212 **WHITE PLAINS MART** **NY AST** **U003856357**
WNW **69 BANK STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.202 mi.
1067 ft. **Site 6 of 9 in cluster Y**

Relative: **Lower**

Actual: **207 ft.**

WESTCHESTER CO. AST:

Name:	WHITE PLAINS MART
Address:	69 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-137286
Site Status:	Active
GDS Number:	3551700146
Operator Name:	Tariq Choudhry
Owner Name:	Refleg Corp
Owner Street:	8 Susan Court
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605
Tank Number:	5
Status:	3. Closed - Removed
Date Installation:	07/01/1997
Capacity:	240
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/2012
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	1. Electronic Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible
Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	07/01/1997
Capacity:	240
Product Stored:	2642. Used Oil (Heating)
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/2012
Tank Location:	1. Aboveground (contact w/ soil)
Tank Type:	1. Steel/Carbon steel/Iron

WHITE PLAINS MART (Continued) **U003856357**

Tank Internal Protection:	0. None
Tank External Protection:	8. Retrofitted Impressed Current
Tank Leak Detection:	1. Electronic Interstitial Monitoring,6. Impervious Barrier/Concrete Pad (Aboveground Only)
Tank Secondary Containment:	2. Vault (w/ access)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	0. None

Y213 **GETTY PETROLEUM CORP** **RCRA NonGen / NLR** **1000912543**
WNW **69 BANK ST** **NY MANIFEST** **NY0000861518**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.202 mi.
1067 ft. **Site 7 of 9 in cluster Y**

Relative: **Lower**
Actual: **207 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Handler Address:	69 BANK ST
Handler City,State,Zip:	WHITE PLAINS, NY 10606-1902
EPA ID:	NY0000861518
Contact Name:	Not reported
Contact Address:	JERICHO TNPK
Contact City,State,Zip:	JERICHO, NY 11735
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	JERICHO TNPK
Mailing City,State,Zip:	JERICHO, NY 11735
Owner Name:	GETTY PETROLEUM CORP
Owner Type:	Private
Operator Name:	GETTY PETROLEUM CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No

GETTY PETROLEUM CORP (Continued) **1000912543**

Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

GETTY PETROLEUM CORP (Continued) **1000912543**

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	GETTY PETROLEUM CORP
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	125 JERICHO TNPK
Owner/Operator City,State,Zip:	JERICHO, NY 11735
Owner/Operator Telephone:	516-338-6000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1999-07-08 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No

GETTY PETROLEUM CORP (Continued) **1000912543**

Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1994-10-04 00:00:00.0
Handler Name:	GETTY PETROLEUM CORP
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	GETTY SERVICE STATION
Address:	69 BANK ST
City,State,Zip:	WHITE PLAINS, NY 10606-1902
Country:	USA
EPA ID:	NY0000861518
Facility Status:	Not reported
Location Address 1:	69 BANK STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported

GETTY PETROLEUM CORP (Continued) **1000912543**

Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000861518
Mailing Name:	GETTY SERVICE STATION
Mailing Contact:	JOSEPH CAPORICCI
Mailing Address 1:	69 BANK STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	0000000000

NY MANIFEST:

Document ID:	CTF0345553
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	XG2539
Trans2 State ID:	Not reported
Generator Ship Date:	03/08/1995
Trans1 Recv Date:	03/08/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/09/1995
Part A Recv Date:	04/12/1995
Part B Recv Date:	03/23/1995
Generator EPA ID:	NY0000861518
Trans1 EPA ID:	NYD173735192
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD000604488
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00055
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001

GETTY PETROLEUM CORP (Continued) **1000912543**

Container Type: DM - Metal drums, barrels
Handling Method: B Incineration, heat recovery, burning.
Specific Gravity: 100

Y214 **WHITE PLAINS MART** **NY UST** **U004192463**
WNW **69 BANK STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.202 mi.
1067 ft. **Site 8 of 9 in cluster Y**

Relative: **Lower**
Actual: **207 ft.**

WESTCHESTER CO. UST:

Name:	WHITE PLAINS MART
Address:	69 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-137286 / Active
Operator Name:	Tariq Choudhry
Owner Name:	Refleg Corp
Owner Street:	8 Susan Court
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	3551700146
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	10
Tank Leak Detection:	3. Vapor Well
Date Installation:	07/01/1975
Date Perm Closure:	09/05/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	7. Retrofitted Sacrificial Anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	1 New
Status:	1. In-Service
Capacity:	12000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	04/22/2013
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)

WHITE PLAINS MART (Continued) **U004192463**

Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	2
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	10
Tank Leak Detection:	3. Vapor Well,99. Other
Date Installation:	07/01/1975
Date Perm Closure:	09/05/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	7. Retrofitted Sacrificial Anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	1. Float Vent Valve,3. Automatic Shut-off
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	2 New
Status:	1. In-Service
Capacity:	8000
Product Stored:	2712. Gasoline/Ethanol
Product Stored Percent:	10
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	04/22/2013
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	3
Status:	3. Closed - Removed

WHITE PLAINS MART (Continued) **U004192463**

Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	10
Tank Leak Detection:	3. Vapor Well,99. Other
Date Installation:	07/01/1975
Date Perm Closure:	09/05/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	7. Retrofitted Sacrificial Anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	3 New
Status:	1. In-Service
Capacity:	4000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	04/22/2013
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	2. High Level Alarm,3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Tank Number:	4
Status:	3. Closed - Removed
Capacity:	4000
Product Stored:	0009. Gasoline
Product Stored Percent:	10
Tank Leak Detection:	3. Vapor Well,99. Other
Date Installation:	07/01/1975
Date Perm Closure:	09/05/2012
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	1. Epoxy liner
Tank External Protection:	7. Retrofitted Sacrificial Anode
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel

WHITE PLAINS MART (Continued) **U004192463**

Piping External Protection:	7. Retrofitted Sacrificial Anode
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	1. Submersible

Y215 **CASTILLO** **NY LTANKS** **S104276655**
West **125-127 FISHER AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.204 mi.
1077 ft. **Site 9 of 9 in cluster Y**

Relative: **Lower**

Actual: **210 ft.**

LTANKS:

Name:	CASTILLO
Address:	125-127 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8709424 / 1988-03-11
Facility ID:	8709424
Site ID:	210582
Spill Date:	1988-02-05
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-03-11
SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-02-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	1988-03-11
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-10
Spill Record Last Update:	1988-03-11
Spiller Name:	Not reported
Spiller Company:	JOE JAHENSKY,ROBINSON OIL
Spiller Address:	RIVER RD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	174577
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER / / : W.C.H.D. TO INSPECT 2-18-88 LR. "
Remarks:	"OVERFILL FROM VENT DURING DELIVERY ONTO BLACKTOP DRIVEWAY. ROBINSON OIL CLEANING UP W/SPEEDY DRY."

All Materials:

Site ID:	210582
Operable Unit ID:	914522
Operable Unit:	01
Material ID:	464746
Material Code:	0001A

CASTILLO (Continued) **S104276655**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AA216 **LAFRDO HOME** **NY LTANKS** **S106972540**
SSW **5 CHARLES STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.210 mi.
1111 ft. **Site 3 of 3 in cluster AA**

Relative:
Higher

Actual:
234 ft.

LTANKS:

Name:	LAFRDO HOME
Address:	5 CHARLES STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0504800 / 2006-05-01
Facility ID:	0504800
Site ID:	349713
Spill Date:	2005-07-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2006-05-01
Spiller Name:	MARIA LAFRDO
Spiller Company:	LAFRDO HOME
Spiller Address:	5 CHARLES STREET
Spiller County:	001
Spiller Contact:	MARIA LAFRDO
Spiller Phone:	(914) 948-4468
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	296146
DEC Memo:	"May 1, 2006: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 19.72 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"RECOMMEND- EXPOSE RETEST OR REMOVE"

All TTF:

Facility ID:	0504800
Spill Number:	0504800

LAFRDO HOME (Continued) **S106972540**

Spill Tank Test:	1549101
Site ID:	349713
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	349713
Operable Unit ID:	1107301
Operable Unit:	01
Material ID:	2097193
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

217
NNW
1/8-1/4
0.215 mi.
1135 ft.

77 SOUTH LEXINGTON AVE **NY LTANKS** **S105999444**
77 SOUTH LEXINGTON AVE **N/A**
WHITE PLAINS, NY

Relative:
Lower

Actual:
201 ft.

LTANKS:

Name:	77 SOUTH LEXINGTON AVE
Address:	77 SOUTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0304231 / 2003-07-22
Facility ID:	0304231
Site ID:	106697
Spill Date:	2003-07-22
Spill Cause:	Tank Overfill
Spill Source:	Passenger Vehicle
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-07-22
CID:	216
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

77 SOUTH LEXINGTON AVE (Continued) **S105999444**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-22
Spill Record Last Update:	2003-07-25
Spiller Name:	Not reported
Spiller Company:	MARCOS RAMOS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	LINDA RICCO
Spiller Phone:	(718) 383-1400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	93920
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"SPILL AT POLICE STATION OVER FILL SPIL IS CLEANED UP "

All Materials:

Site ID:	106697
Operable Unit ID:	871118
Operable Unit:	01
Material ID:	505088
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

AB218 **COMMERCIAL BLDG** **NY LTANKS** **S108298896**
SW **80 WEST POST ROAD** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.216 mi.
1142 ft. **Site 1 of 2 in cluster AB**

Relative: **Higher**
Actual: **228 ft.**

LTANKS:

Name:	ABCO REFRIG
Address:	80 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0609508 / 2007-01-10
Facility ID:	0609508
Site ID:	373822
Spill Date:	2006-11-17
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-11-17
CID:	444
Water Affected:	Not reported

COMMERCIAL BLDG (Continued) **S108298896**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-20
Spill Record Last Update:	2018-12-11
Spiller Name:	MICHELLE LAPIN
Spiller Company:	ABCO REFRIG
Spiller Address:	80 WEST POST ROAD
Spiller County:	001
Spiller Contact:	MICHELLE LAPIN
Spiller Phone:	(646) 388-9520
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	325489
DEC Memo:	"See spill 06-09498. 12/11/18: File pulled from archives for FOIL. File scanned to PDF and entered into DecDocs. Hard copy file discarded. jod"
Remarks:	"1000 gallon tank had holes and contaminated soil"

All Materials:

Site ID:	373822
Operable Unit ID:	1131517
Operable Unit:	01
Material ID:	2121227
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	COMMERCIAL BLDG
Address:	80 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0609498 / 2008-06-03
Facility ID:	0609498
Facility Type:	ER
DER Facility ID:	325489
Site ID:	373812
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2006-11-17
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-11-17
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial

COMMERCIAL BLDG (Continued) **S108298896**

Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-20
Spill Record Last Update:	2018-12-11
Spiller Name:	BRIAN OMAHONEY
Spiller Company:	COMMERCIAL BLDG
Spiller Address:	80 WEST POST ROAD
Spiller Company:	001
Contact Name:	LOU MARIBAL
DEC Memo:	"Also reported as Spill 0609508. 6/03/2008: Spill closure report submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod 12/11/18: File pulled from archives for FOIL. File scanned to PDF and entered into DecDocs. Hard copy file discarded. jod"
Remarks:	"REMOVING TANK AND FOUND HOLES IN TANK AND CONTAMINATION IN SOIL"

All Materials:

Site ID:	373812
Operable Unit ID:	1131507
Operable Unit:	01
Material ID:	2121217
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AB219 **ABCO REFRIGERATION SUPPLY CORP** **RCRA NonGen / NLR** **1005417393**
SW **80 W POST RD** **FINDS** **NYR000105197**
1/8-1/4 **WHITE PLAINS, NY 10606** **ECHO**
0.216 mi. **NY MANIFEST**
1142 ft. **Site 2 of 2 in cluster AB**

Relative: **Higher**
Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	ABCO REFRIGERATION SUPPLY CORP
Handler Address:	80 W POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYR000105197
Contact Name:	PHILIP RUSH
Contact Address:	W POST RD
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	718-497-4302
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

ABCO REFRIGERATION SUPPLY CORP (Continued) **1005417393**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	W POST RD
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	ABCO REFRIGERATION SUPPLY CORP
Owner Type:	Private
Operator Name:	ABCO REFRIGERATION SUPPLY CORP
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

ABCO REFRIGERATION SUPPLY CORP (Continued) **1005417393**

Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 2015-04-14 00:00:00.0
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: Not reported

Hazardous Waste Summary:
Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D002
Waste Description: CORROSIVE WASTE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: ABCO REFRIGERATION SUPPLY CORP
Legal Status: Private
Date Became Current: 2001-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 49-70 31ST ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-497-4302
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ABCO REFRIGERATION SUPPLY CORP
Legal Status: Private
Date Became Current: 2001-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 49-70 31ST ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-497-4302
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ABCO REFRIGERATION SUPPLY CORP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: 49-70 31ST ST
Owner/Operator City,State,Zip: LONG ISLAND CITY, NY 11101
Owner/Operator Telephone: 718-497-4302
Owner/Operator Telephone Ext: Not reported

ABCO REFRIGERATION SUPPLY CORP (Continued) **1005417393**

Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 2006-01-01 00:00:00.0
Handler Name: ABCO REFRIGERATION SUPPLY CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2007-01-01 00:00:00.0
Handler Name: ABCO REFRIGERATION SUPPLY CORP
Federal Waste Generator Description: Not a generator, verified
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2002-04-08 00:00:00.0
Handler Name: ABCO REFRIGERATION SUPPLY CORP
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
State District Owner: NY
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110012264469

ABCO REFRIGERATION SUPPLY CORP (Continued) **1005417393**

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1005417393
Registry ID:	110012264469
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012264469
Name:	ABCO REFRIGERATION SUPPLY CORP
Address:	80 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	ABCO
Address:	80 W POST RD
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYR000105197
Facility Status:	Not reported
Location Address 1:	80 W POST RD
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000105197
Mailing Name:	ABCO
Mailing Contact:	CHARLES DEJESUS
Mailing Address 1:	80 W POST RD
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149422020

NY MANIFEST:

Document ID:	MDC0891036
Manifest Status:	Not reported
seq:	01
Year:	2002
Trans1 State ID:	HWH427004
Trans2 State ID:	Not reported

ABCO REFRIGERATION SUPPLY CORP (Continued) **1005417393**

Generator Ship Date:	04/17/2002
Trans1 Recv Date:	04/17/2002
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	04/25/2002
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000105197
Trans1 EPA ID:	SCR000075150
Trans2 EPA ID:	Not reported
TSDF ID 1:	MDD980554653
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00131
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00380
Units:	P - Pounds
Number of Containers:	002
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00128
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	01.00

220
WSW
1/8-1/4
0.218 mi.
1153 ft.

WINSTON HOME
3 WYANOKE STREET
WHITE PLAINS, NY

NY LTANKS **S108298451**
N/A

Relative:
Higher

Actual:
248 ft.

LTANKS:

Name:	RESIDENCE
Address:	3 WYANOKE STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0607149 / 2007-02-06
Facility ID:	0607149
Site ID:	370661
Spill Date:	2006-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-09-21
CID:	410
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-09-21
Spill Record Last Update:	2007-02-06
Spiller Name:	JUAN ROSAS
Spiller Company:	RESIDENCE
Spiller Address:	3 WYANOKE STREET
Spiller County:	001
Spiller Contact:	JUAN ROSAS
Spiller Phone:	(914) 671-1924
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	321454
DEC Memo:	"(D. Weitz) Elite was called in by prospective buyer of property. A proposal has been sent to the owners to dig up top of tank & retest. See spills 06-07758 and 06-10630. NFA jod"
Remarks:	"None:"

All TTF:

Facility ID:	0607149
Spill Number:	0607149
Spill Tank Test:	1550297
Site ID:	370661
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

WINSTON HOME (Continued) **S108298451**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	370661
Operable Unit ID:	1128450
Operable Unit:	01
Material ID:	2118064
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	PARKER RES
Address:	3 WYANOKE STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0607758 / 2007-02-06
Facility ID:	0607758
Site ID:	371575
Spill Date:	2006-10-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-10-07
CID:	27
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-10-07
Spill Record Last Update:	2007-02-06
Spiller Name:	Not reported
Spiller Company:	PARKER RES
Spiller Address:	3 WYANOKE STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 316-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	321454
DEC Memo:	"Previously reported TTF is 06-07149 See spill 06-10630 for closure. NFA jod"
Remarks:	"Winston Parker tank failed due to bubbling."

WINSTON HOME (Continued) **S108298451**

All TTF:

Facility ID:	0607758
Spill Number:	0607758
Spill Tank Test:	1550343
Site ID:	371575
Tank Number:	1
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	21
Test Method 2:	Horner EZY3/EZY3 Locator Plus
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	JBODee
Last Modified Date:	Not reported

Name:	WINSTON HOME
Address:	3 WYANOKE STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0610630 / 2007-02-06
Facility ID:	0610630
Site ID:	375107
Spill Date:	2006-12-19
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-12-19
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-12-19
Spill Record Last Update:	2007-02-06
Spiller Name:	WINSTON PARKER
Spiller Company:	WINSTON HOME
Spiller Address:	3 WYANOKE STREET
Spiller County:	001
Spiller Contact:	WINSTON PARKER
Spiller Phone:	(914) 316-0784
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	321454
DEC Memo:	"PREVIOUSLY REPORTED TTFs ARE 06-07149 AND 06-07758 February 6, 2007: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 2 DRUMS OF CONTAMINATED SOIL. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION

WINSTON HOME (Continued) **S108298451**

PROVIDED, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "1000 GALLON TANK HAD HOLES AND CONTAMINATED SOIL"

All Materials:
Site ID: 375107
Operable Unit ID: 1132758
Operable Unit: 01
Material ID: 2122543
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

221
SSW
1/8-1/4
0.220 mi.
1163 ft.

PRIVATE DWELLING
11 ROOSEVELT STREET
WHITE PLAINS, NY

NY LTANKS **S108957776**
N/A

Relative:
Higher

Actual:
227 ft.

LTANKS:
Name: PRIVATE DWELLING
Address: 11 ROOSEVELT STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0708659 / 2013-01-30
Facility ID: 0708659
Site ID: 389600
Spill Date: 2007-11-08
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: D5
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: JBODEE
Referred To: Not reported
Reported to Dept: 2007-11-08
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: Not reported
Remediation Phase: 0
Date Entered In Computer: 2007-11-08
Spill Record Last Update: 2020-07-21
Spiller Name: ANGEL- REALTY CO
Spiller Company: Real Estate Trans
Spiller Address: 11 ROOSERVELT
Spiller County: 001
Spiller Contact: ANGEL- REALTY CO
Spiller Phone: (914) 949-8828
Spiller Extention: Not reported
DEC Region: 3

PRIVATE DWELLING (Continued) **S108957776**

DER Facility ID: 339188
DEC Memo: "11/09/09: Residential TTF - tested for real estate transaction. No further information on the initial report. jod 1/30/2013 With Albany Approval all Homeowner TTF failures greater then 5 years old can be closed NFA JO'M"
Remarks: "RECOMMEND ISOLATION AND RETEST"

All TTF:
Facility ID: 0708659
Spill Number: 0708659
Spill Tank Test: 1815811
Site ID: 389600
Tank Number: Not reported
Tank Size: 1000
Material: 0001
EPA UST: Not reported
UST: True
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 389600
Operable Unit ID: 1146738
Operable Unit: 01
Material ID: 2137122
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AC222 **INNS OF COURT** **NY LTANKS** **S102399524**
NNE **99 COURT ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.222 mi.
1173 ft. **Site 1 of 3 in cluster AC**

Relative: **Higher**
Actual: **229 ft.**

LTANKS:
Name: INNS OF COURT
Address: 99 COURT ST
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9606465 / 2006-02-28
Facility ID: 9606465
Site ID: 204590
Spill Date: 1996-08-20
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3

INNS OF COURT (Continued) **S102399524**

Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-08-20
CID:	349
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-08-20
Spill Record Last Update:	2006-02-28
Spiller Name:	SUSAN HARVEY
Spiller Company:	INNS OF COURT
Spiller Address:	99 COURT ST
Spiller County:	001
Spiller Contact:	SUSAN HARVEY
Spiller Phone:	(914) 947-8400
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	170073
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 02/28/06 Tank passed an isolation retest but lines failed in Aug of 1996. Tank was scheduled to be abandoned in place and lines removed by NES Oct 1996. WCHD PBS databse lists site as Unregulated as of June 1997. NFA jod"
Remarks:	""

All TTF:

Facility ID:	9606465
Spill Number:	9606465
Spill Tank Test:	1544695
Site ID:	204590
Tank Number:	Not reported
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	204590
Operable Unit ID:	1034262
Operable Unit:	01
Material ID:	561159
Material Code:	0001A
Material Name:	#2 fuel oil

INNS OF COURT (Continued) **S102399524**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AC223 **THE INNS OF COURT PROPERTIES** **NY UST** **U003994986**
NNE **99 COURT ST.** **N/A**
1/8-1/4 **, NY 10601**
0.222 mi.
1173 ft. **Site 2 of 3 in cluster AC**

Relative: **Higher**
Actual: **229 ft.**

WESTCHESTER CO. UST:

Name:	THE INNS OF COURT PROPERTIES
Address:	99 COURT ST.
City,State,Zip:	NY 10601
Id/Status:	3-601002 / Unregulated: <1101 gal. PBS
Operator Name:	None
Owner Name:	Henry J. Miller
Owner Street:	85 Birchall Drive
Owner Address2:	Not reported
Owner City:	Scarsdale
Owner State:	NY
Owner Zipcode:	10583
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1997
Date Perm Closure:	01/01/1997
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	1. Painted/Asphalt Coating
Overfill Prevention:	2. High Level Alarm
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None

AD224 **HOME** **NY LTANKS** **S107410732**
SE **43 LONGVIEW AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.224 mi.
1184 ft. **Site 1 of 2 in cluster AD**

Relative:
Higher

Actual:
241 ft.

LTANKS:

Name:	HOME
Address:	43 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0507448 / 2006-03-15
Facility ID:	0507448
Site ID:	352870
Spill Date:	2005-09-21
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-21
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2006-04-21
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-21
Spill Record Last Update:	2006-04-26
Spiller Name:	TED BECERRA
Spiller Company:	REAL ESTATE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	TED BECERRA
Spiller Phone:	(845) 222-3185
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300164
DEC Memo:	"SEE SPILL 05-08523. NFA THIS NUMBER jod"
Remarks:	"UNCOVER REAPAIR AND RETEST OR REMOVE"

All TTF:

Facility ID:	0507448
Spill Number:	0507448
Spill Tank Test:	1549328
Site ID:	352870
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

HOME (Continued) **S107410732**

Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 352870
Operable Unit ID: 1110343
Operable Unit: 01
Material ID: 2100356
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Name: PRIVATE HOME
Address: 43 LONGVIEW AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0508523 / 2006-07-11
Facility ID: 0508523
Site ID: 354077
Spill Date: 2005-10-17
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: JBODee
Referred To: Not reported
Reported to Dept: 2005-10-17
CID: 444
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: 2006-04-21
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2005-10-17
Spill Record Last Update: 2006-07-26
Spiller Name: TED BECERRA
Spiller Company: PRIVATE HOME
Spiller Address: 43 LONGVIEW AVE
Spiller County: 001
Spiller Contact: TED BECERRA
Spiller Phone: (845) 222-3185
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 300164
DEC Memo: "Pulled tank, found contamination, Elite proposing to remove soil and is awaiting owner's instructions. July 11, 2006: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 323.19 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, AND A MONITORING WELL WAS INSTALLED AND SAMPLED. CLOSURE REPORT REVIEWED BY DEC. BASED UPON INFORMATION PROVIDED, NO

HOME (Continued) **S107410732**

FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: "HOLES IN TANK: 550 GALLON"

All Materials:
Site ID: 354077
Operable Unit ID: 1111516
Operable Unit: 01
Material ID: 2101557
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: Not reported
Oxygenate: Not reported

Z225 **APARTMENT BLDG** **NY LTANKS** **S102152028**
ESE **21 GREENRIDGE AVE** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.225 mi.
1186 ft. **Site 2 of 3 in cluster Z**

Relative: **Higher**
Actual: **270 ft.**

LTANKS:
Name: RESIDENCE
Address: 21 GREENRIDGE AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0410525 / 2005-02-24
Facility ID: 0410525
Site ID: 335499
Spill Date: 2004-12-22
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: WCDOH
Reported to Dept: 2004-12-22
CID: 407
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2004-12-22
Spill Record Last Update: 2005-03-04
Spiller Name: JOHN PORZIO
Spiller Company: RESIDENCE
Spiller Address: 21 GREENRIDGE AVE
Spiller County: 001
Spiller Contact: JOHN PORZIO
Spiller Phone: (914) 980-5005
Spiller Extention: Not reported
DEC Region: 3

APARTMENT BLDG (Continued) **S102152028**

DER Facility ID: 270748
DEC Memo: "3/4/05: PBS 3-410608; Letter to John S. Porzio from Karen Magnuson, WCDOH dated 24Feb2005. WCDOH recommends NFA at this time."
Remarks: "PBS No: 3-410608 "

All TTF:
Facility ID: 0410525
Spill Number: 0410525
Spill Tank Test: 1548433
Site ID: 335499
Tank Number: 1
Tank Size: 2000
Material: Not reported
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

SPILLS:
Name: APARTMENT BLDG
Address: 21 GREENRIDGE AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9204409 / 1992-07-20
Facility ID: 9204409
Facility Type: ER
DER Facility ID: 270748
Site ID: 167659
DEC Region: 3
Spill Cause: Human Error
Spill Class: C3
SWIS: 6017
Spill Date: 1992-07-16
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-07-17
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: 1992-07-20
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2003-12-02
Spill Record Last Update: 2005-02-12
Spiller Name: Not reported
Spiller Company: REGENT OIL
Spiller Address: 53 CHARLES STREET

APARTMENT BLDG (Continued) **S102152028**

Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "EMPTYING OIL HOSE AND FUEL CAME OUT VENT PIPE WPFD WAS ON SCENE AND LUZON ON SCENE PUT DOWN SPEEDI-DRI SPOKE WITH KENNY (LUZON) THEY ARE PICKING UP CONTAMINATED SOIL AND WILL DISPOSE"

All Materials:
Site ID: 167659
Operable Unit ID: 968157
Operable Unit: 01
Material ID: 412135
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported

Z226 **21 GREENRIDGE APARTMENTS** **NY UST** **U004175933**
ESE **21-25 GREENRIDGE AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.225 mi.
1186 ft. **Site 3 of 3 in cluster Z**

Relative:
Higher

Actual:
270 ft.

WESTCHESTER CO. UST:
Name: 21 GREENRIDGE APARTMENTS
Address: 21-25 GREENRIDGE AVENUE
City,State,Zip: WHITE PLAINS, NY 10605
Id/Status: 3-410608 / Unregulated
Operator Name: Robison Oil
Owner Name: John Porzio
Owner Street: 15 Chester Street
Owner Address2: P.O. Box 254
Owner City: White Plains
Owner State: NY
Owner Zipcode: 10605
GDS Number: Not reported

Tank Number: 1
Status: 3. Closed - Removed
Capacity: 2500
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 02/01/2005
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 0. None
Tank Secondary Containment: 0. None
Piping Location: 0. No Pipiing
Piping Type: 1. Steel/Carbon/ steel/iron

21 GREENRIDGE APARTMENTS (Continued) **U004175933**

Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	UL714475
Status:	1. In-Service
Capacity:	1000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	100
Tank Leak Detection:	0. None
Date Installation:	02/01/2005
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	Not reported
Piping External Protection:	Not reported
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

AE227 **BART'S AUTO SERVICE** **NY AST** **A100486712**
WNW **7 IRVING PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.225 mi.
1187 ft. **Site 1 of 4 in cluster AE**

Relative: **Lower**

Actual: **208 ft.**

WESTCHESTER CO. AST:

Name:	BART'S AUTO SERVICE
Address:	7 IRVING PLACE
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-802186
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Bart's Auto Service Inc.
Owner Name:	Bart Massi
Owner Street:	7 Irving Olace
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10606

Tank Number:	W01
Status:	1. In-Service
Date Installation:	04/30/2018
Capacity:	150
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	7. Plastic
Tank Internal Protection:	Not reported
Tank External Protection:	5. Jacketed

BART'S AUTO SERVICE (Continued) **A100486712**

Tank Leak Detection:	0. None
Tank Secondary Containment:	12. Double-Walled (AST only)
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	1. Catch Basin
Dispenser:	Not reported

AF228 **CON EDISON** **RCRA NonGen / NLR 1014397079**
ENE **184 MAMARONECK AVE & MAPLE AVE** **NY MANIFEST NYP004193967**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.225 mi.
1187 ft. **Site 1 of 11 in cluster AF**

Relative: **Higher**
Actual: **227 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	184 MAMARONECK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004193967
Contact Name:	DENNIS MICHAELIDES
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-204-4297
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No

CON EDISON (Continued) **1014397079**

Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-11-03 12:35:05.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2009-09-09 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

CON EDISON (Continued) **1014397079**

Receive Date:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	184 MAMARONECK AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004193967
Facility Status:	Not reported
Location Address 1:	MAMARONECK AVE & MAPLE AVE - MH 5628
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	YONKERS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004193967
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	FRANKLYN MURRAY
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602808

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **1014397079**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/10/2009
Trans1 Recv Date:	09/10/2009
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	09/11/2009
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004193967
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433374FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	200
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF229 **CON ED V 5613** **RCRA NonGen / NLR** **1007205413**
ENE **200 MAMORONECK AVE** **NY MANIFEST** **NYP000930958**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.227 mi.
1201 ft. **Site 2 of 11 in cluster AF**

Relative: **Higher**
Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	1998-02-28 00:00:00.0
Handler Name:	CON ED V 5613
Handler Address:	200 MAMORONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601-0000

CON ED V 5613 (Continued) **1007205413**

EPA ID:	NYP000930958
Contact Name:	ANTHONY DRUMMINGS
Contact Address:	CON EDISON INC
Contact City,State,Zip:	NEW YORK, NY 10003-0000
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	CON EDISON INC
Mailing City,State,Zip:	NEW YORK, NY 10003-0000
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON ED V 5613 (Continued) **1007205413**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	1998-02-27 00:00:00.0
Handler Name:	CON ED V 5613
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1998-02-28 00:00:00.0
Handler Name:	CON ED V 5613
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1998-02-26 00:00:00.0
Handler Name:	CON ED V 5613
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON ED V 5613 (Continued) **1007205413**

Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 2211
NAICS Description: ELECTRIC POWER GENERATION, TRANSMISSION AND DISTRIBUTION

NAICS Code: 22111
NAICS Description: ELECTRIC POWER GENERATION

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON CO
Address: 200 MAMORONECK AVE
City,State,Zip: WHITE PLAINS, NY 10601-0000
Country: USA
EPA ID: NYP000930958
Facility Status: Not reported
Location Address 1: V1853-BEDFORD PK MARIAN
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: QUEENS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000930958
Mailing Name: CONSOLIDATED EDISON CO
Mailing Contact: FRANKLIN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: NYG0249291
Manifest Status: C
seq: Not reported
Year: 1997
Trans1 State ID: GX3216

CON ED V 5613 (Continued) **1007205413**

Trans2 State ID:	Not reported
Generator Ship Date:	04/29/1997
Trans1 Recv Date:	04/29/1997
Trans2 Recv Date:	/ /
TSD Site Recv Date:	04/29/1997
Part A Recv Date:	05/08/1997
Part B Recv Date:	05/09/1997
Generator EPA ID:	NYP000930958
Trans1 EPA ID:	NYD006982359
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD980593636
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	B003 - PETROLEUM OIL WITH 500 PPM OR > PCB
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	01082
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	001
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

AF230 **MAMARAHAN CO.** **NY UST** **U003994708**
ENE **200 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.227 mi.
1201 ft. **Site 3 of 11 in cluster AF**

Relative: **Higher**
Actual: **228 ft.**

WESTCHESTER CO. UST:

Name:	MAMARAHAN CO.
Address:	200 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-601008 / Unregulated: <1101 gal. PBS
Operator Name:	James Cohen
Owner Name:	Mamarahan Company
Owner Street:	200 Mamaroneck Ave
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601
GDS Number:	Not reported

MAMARAHAN CO. (Continued) **U003994708**

Tank Number:	1
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1962
Date Perm Closure:	09/15/1999
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AF231 **NYSDEC** **NY Spills** **S106010782**
ENE **202 MAMARONECK AVENUE** **NY MANIFEST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.228 mi.
1202 ft. **Site 4 of 11 in cluster AF**

Relative:
Higher

Actual:
228 ft.

SPILLS:

Name:	MH 1814
Address:	202 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0210480 / 2004-10-22
Facility ID:	0210480
Facility Type:	ER
DER Facility ID:	82377
Site ID:	91602
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C4
SWIS:	6017
Spill Date:	2003-01-17
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2003-01-17
CID:	396
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-17
Spill Record Last Update:	2004-10-22
Spiller Name:	Not reported
Spiller Company:	UNKNOWN

NYSDEC (Continued) **S106010782**

Spiller Address: Not reported
Spiller Company: 001
Contact Name: CHARLIE MCARTHY
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/17/03: 1,800 GAL IS OIL AND WATER MIXTURE, MANHOLE IS CONTAINED, NO SEWERS AFFECTED. CLEAN HARBORS WILL DO CLEANUP."
Remarks: "3rd party spill - samples taken clean up pending - this man hole has a history of 3rd party oil spills. ref # 146789"

All Materials:
Site ID: 91602
Operable Unit ID: 863911
Operable Unit: 01
Material ID: 513862
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 1800.00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Name: NYSDEC
Address: 202 MAMARONECK AVENUE
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYP000857680
Facility Status: Not reported
Location Address 1: 202 MAMARONECK AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000857680
Mailing Name: NYSDEC
Mailing Contact: NYSDEC
Mailing Address 1: 202 MAMARONECK
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9147616660

NY MANIFEST:
Document ID: CTB0030038
Manifest Status: K
seq: Not reported

NYSDEC (Continued) **S106010782**

Year:	1986
Trans1 State ID:	G-37854
Trans2 State ID:	Not reported
Generator Ship Date:	03/13/1986
Trans1 Recv Date:	03/13/1986
Trans2 Recv Date:	/ /
TSD Site Recv Date:	03/20/1986
Part A Recv Date:	04/25/1986
Part B Recv Date:	04/01/1986
Generator EPA ID:	NYP000857680
Trans1 EPA ID:	CTD072138969
Trans2 EPA ID:	Not reported
TSDF ID 1:	CTD072138969
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00020
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

AF232 **200 MAMARONECK AVENUE CO.** **NY UST** **U003994250**
ENE **202 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.228 mi.
1202 ft. **Site 5 of 11 in cluster AF**

Relative: **Higher**
Actual: **228 ft.**

WESTCHESTER CO. UST:

Name:	200 MAMARONECK AVENUE CO.
Address:	202 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-601010 / Unregulated: <1101 gal. PBS
Operator Name:	James Cohen
Owner Name:	200 Mamaroneck Avenue Co.
Owner Street:	202 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10601

200 MAMARONECK AVENUE CO. (Continued) **U003994250**

GDS Number:	Not reported
Tank Number:	1
Status:	4. Closed - in place
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1962
Date Perm Closure:	09/15/1999
Tank Location:	6. Underground, vaulted, with access
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	2. Suction

AF233 **JOHN DALE INC** **NY LTANKS** **S103558559**
ENE **178 MAMORENECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.228 mi.
1203 ft. **Site 6 of 11 in cluster AF**

Relative: **Higher**
Actual: **227 ft.**

LTANKS:

Name:	JOHN DALE INC
Address:	178 MAMORENECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9810809 / 1998-12-01
Facility ID:	9810809
Site ID:	325049
Spill Date:	1998-11-25
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-11-25
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-25
Spill Record Last Update:	1999-01-16
Spiller Name:	DWAYNE MONICO
Spiller Company:	JOHN DALE INC
Spiller Address:	80 BUSINESS PARK DRIVE

JOHN DALE INC (Continued) **S103558559**

Spiller County:	001
Spiller Contact:	DWAYNE MONICO
Spiller Phone:	(914) 777-1930
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	261843
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY SPILL CLOSED BY WCHD, S. GOREAU."
Remarks:	"tank leaked and the soil around the tank was contaminated.soil was removed and stockpiled.site has been cleaned ."

All Materials:

Site ID:	325049
Operable Unit ID:	1071785
Operable Unit:	01
Material ID:	314671
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AG234 **151 EAST POST ROAD CORP.** **NY UST** **U004175916**
NE **151 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.228 mi.
1206 ft. **Site 1 of 26 in cluster AG**

Relative: **Higher**

Actual: **227 ft.**

WESTCHESTER CO. UST:

Name:	151 EAST POST ROAD CORP.
Address:	151 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-030910 / Active
Operator Name:	Allen Management Inc.
Owner Name:	151 East Post Road Corp.
Owner Street:	c/o Thomas Derecktor
Owner Address2:	902 Wapping Road
Owner City:	Portsmouth
Owner State:	RI
Owner Zipcode:	02871-5119
GDS Number:	Not reported
Tank Number:	1
Status:	1. In-Service
Capacity:	1500
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	4. Groundwater Well
Date Installation:	12/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None

151 EAST POST ROAD CORP. (Continued) **U004175916**

Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AG235 **COMMERCIAL PROERTY** **NY LTANKS** **S107789254**
NE **151 EAST POST ROAD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.228 mi.
1206 ft. **Site 2 of 26 in cluster AG**

Relative: **Higher**

Actual: **227 ft.**

LTANKS:

Name:	COMMERCIAL PROERTY
Address:	151 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0601015 / 2006-11-03
Facility ID:	0601015
Site ID:	363155
Spill Date:	2006-04-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2006-04-26
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-04-26
Spill Record Last Update:	2006-11-03
Spiller Name:	TONY GASHA
Spiller Company:	COMMERCIAL PROERTY
Spiller Address:	151 EAST POST ROAD
Spiller County:	001
Spiller Contact:	TONY GASHA
Spiller Phone:	(914) 946-2357
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	313347
DEC Memo:	"5/3/06: Refer to WC PBS August 16, 2006 Tony Gashi 151 East Post Road Corp 47 Mamaroneck Ave, Suite 111 White Plains, Ny 10601 Re: PBS #3-030910 151 East Post Road, White Plains, NY NYSDEC Spill # 06-01015 TTF Dear Facility; The Westchester County Department of Health has received the retest results from July 28, 2006. The results are acceptable to the Department. A request for closure is being sent to NYSDEC for the above spill # and no further action is required regarding the work at this time. If you have any questions,

COMMERCIAL PROERTY (Continued) **S107789254**

please call me at (914) 813-5971. Sincerely, Danielle Jackson Sanitarian Office of Environmental Health Risk Control "
Remarks: "NO REMARKS."

All TTF:
Facility ID: 0601015
Spill Number: 0601015
Spill Tank Test: 1549917
Site ID: 363155
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 363155
Operable Unit ID: 1121214
Operable Unit: 01
Material ID: 2110709
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AH236 **WEST HEALTH DEPT** **NY LTANKS** **S106703105**
NNE **148 MARTINE AVE** **N/A**
1/8-1/4 **YONKERS, NY**
0.229 mi.
1209 ft. **Site 1 of 4 in cluster AH**

Relative: **Higher**
Actual: **225 ft.**

LTANKS:
Name: WEST HEALTH DEPT
Address: 148 MARTINE AVE
City,State,Zip: YONKERS, NY
Spill Number/Closed Date: 8701223 / 2004-11-06
Facility ID: 8701223
Site ID: 126440
Spill Date: 1987-05-13
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C5
Cleanup Ceased: Not reported
SWIS: 6018
Investigator: WXWADSWO

WEST HEALTH DEPT (Continued) **S106703105**

Referred To:	Not reported
Reported to Dept:	1987-05-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-25
Spill Record Last Update:	2004-11-05
Spiller Name:	Not reported
Spiller Company:	TOM ZIMINSKY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	109305
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH "
Remarks:	"TANK TESTED. WILL HAVE TO PLACE MONTORING WELLS."

All TTF:

Facility ID:	8701223
Spill Number:	8701223
Spill Tank Test:	1530809
Site ID:	126440
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	126440
Operable Unit ID:	907699
Operable Unit:	01
Material ID:	471174
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AF237 **JOHN DALE, INC.** **NY UST** **U003856736**
ENE **176-180 MAMRONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.230 mi.
1212 ft. **Site 7 of 11 in cluster AF**

Relative: **Higher**
Actual: **227 ft.**

WESTCHESTER CO. UST:

Name:	JOHN DALE, INC.
Address:	176-180 MAMRONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Id/Status:	3-800038 / Unregulated: <1101 gal. PBS
Operator Name:	Ken Harbour
Owner Name:	John Dale, Inc.
Owner Street:	80 Business Park Drive
Owner Address2:	Not reported
Owner City:	Armonk
Owner State:	NY
Owner Zipcode:	10504
GDS Number:	Not reported
Tank Number:	002
Status:	0. Administratively closed
Capacity:	1000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	02/01/1999
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	2. Sacrificial Anode (no retrofit)
Tank Secondary Containment:	Not reported
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	0. None
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	2000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	02/20/1999
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None

JOHN DALE, INC. (Continued) **U003856736**

Piping Secondary Containment: Not reported
Spill Prevention: 0. None
Dispenser: 2. Suction

AD238 **RESIDENTS** **NY LTANKS** **S102556019**
SE **44 LONGVIEW AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.232 mi.
1223 ft. **Site 2 of 2 in cluster AD**

Relative: **Higher**
Actual: **239 ft.**

LTANKS:
Name: RESIDENTS
Address: 44 LONGVIEW AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9614364 / 1997-03-11
Facility ID: 9614364
Site ID: 166538
Spill Date: 1997-03-11
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1997-03-11
CID: 282
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1997-03-11
Spill Record Last Update: 2004-02-20
Spiller Name: SAME
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: MR RIVERSO RESIDENTS
Spiller Phone: (914) 948-3383
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 140318
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/11/97 NO IMPACT TO THE ENVIRONMENT. "
Remarks: "HOLES IN THE TANK OCCURRED FROM THE AGE OF THE TANK SPILL IS BEING CLEANED UP BY ENVIORNMENTAL COMPANY THE HOMEOWNER IS SWITCHING TO GAS AND THE TANK WILL BE DISPOSED OF"

All Materials:
Site ID: 166538
Operable Unit ID: 1041801
Operable Unit: 01
Material ID: 339475
Material Code: 0001A
Material Name: #2 fuel oil

RESIDENTS (Continued) **S102556019**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AE239 **CITY CARS METROPOLITAN LTD** **NY AST** **A100445931**
WNW **25 IRVING PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.233 mi.
1229 ft. **Site 2 of 4 in cluster AE**

Relative: WESTCHESTER CO. AST:
Lower

Actual: **208 ft.**

Name:	CITY CARS METROPOLITAN LTD
Address:	25 IRVING PLACE
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-802149
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	-
Owner Name:	Peter A. Plati Jr.
Owner Street:	68 Edgewood Road
Owner Address2:	Not reported
Owner City/State/Zip:	Ossining, NY 10562
Tank Number:	2
Status:	3. Closed - Removed
Date Installation:	01/01/1900
Capacity:	500
Product Stored:	2642. Used Oil (Heating)
Product Stored Percent:	Not reported
Date Perm Closure:	10/31/2017
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

AE240 **CITY CARS METROPOLITAN LTD** **NY UST** **U004276679**
WNW **25 IRVING PLACE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.233 mi.
1229 ft. **Site 3 of 4 in cluster AE**

Relative: WESTCHESTER CO. UST:
Lower

Name:	CITY CARS METROPOLITAN LTD
Address:	25 IRVING PLACE
City,State,Zip:	WHITE PLAINS, NY 10601
Id/Status:	3-802149 / Unregulated
Operator Name:	-
Owner Name:	Peter A. Plati Jr.
Owner Street:	68 Edgewood Road
Owner Address2:	Not reported
Owner City:	Ossining
Owner State:	NY
Owner Zipcode:	10562
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	2642. Used Oil (Heating)
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	01/01/1900
Date Perm Closure:	10/31/2017
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Piping
Piping Type:	0. No Piping
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	Not reported

Actual:
208 ft.

AI241 **SMITH'S DAIRY,INC.** **NY UST** **U003885152**
WNW **61 BANK STREET** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.235 mi.
1239 ft. **Site 1 of 5 in cluster AI**

Relative: WESTCHESTER CO. UST:
Lower

Name:	SMITH'S DAIRY,INC.
Address:	61 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10602
Id/Status:	3-600496 / Unregulated
Operator Name:	Michael Shames
Owner Name:	William & Loretta Shames
Owner Street:	2 Southdale Road
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported

Actual:
207 ft.

SMITH'S DAIRY,INC. (Continued) **U003885152**

Tank Number:	001
Status:	3. Closed - Removed
Capacity:	550
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	1. Submersible

Tank Number:	002
Status:	3. Closed - Removed
Capacity:	555
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	Not reported
Date Perm Closure:	Not reported
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	1. Submersible

AJ242 **CON EDISON SERVICE BOX: 3575** **RCRA NonGen / NLR** **1016969284**
East **MAMAROENCK AVE & MAPLE AVE** **NY MANIFEST** **NYP004429403**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.235 mi.
1241 ft. **Site 1 of 14 in cluster AJ**

Relative: **Higher**
Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3575
Handler Address:	MAMAROENCK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10602
EPA ID:	NYP004429403
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported

CON EDISON SERVICE BOX: 3575 (Continued) **1016969284**

Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No

CON EDISON SERVICE BOX: 3575 (Continued) **1016969284**

Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-10-14 12:33:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-01-29 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3575
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 3575
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON SERVICE BOX: 3575 (Continued) **1016969284**

NY MANIFEST:

Name:	CON EDISON
Address:	MAMAROENCK AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004429403
Facility Status:	Not reported
Location Address 1:	MAYORONECK AVE & MAPLE AVE
Code:	BP
Location Address 2:	SERVICE BOX # 3575
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004429403
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2014
Trans1 Recv Date:	01/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004429403
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692774JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON SERVICE BOX: 3575 (Continued) **1016969284**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	125
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ243 **CON EDISON VAULT: 5359** **RCRA NonGen / NLR** **1016961423**
East **MAMARONECK AVE & MAPLE AVE** **NY MANIFEST** **NYP004341160**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.235 mi.
1241 ft. **Site 2 of 14 in cluster AJ**

Relative: **Higher**

Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-09-02 00:00:00.0
Handler Name:	CON EDISON VAULT: 5359
Handler Address:	MAMARONECK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10602
EPA ID:	NYP004341160
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No

CON EDISON VAULT: 5359 (Continued) **1016961423**

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-08-02 00:00:00.0

CON EDISON VAULT: 5359 (Continued) **1016961423**

Handler Name:	CON EDISON VAULT: 5359
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-09-02 00:00:00.0
Handler Name:	CON EDISON VAULT: 5359
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	MAMARONECK AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10602
Country:	USA
EPA ID:	NYP004341160
Facility Status:	Not reported
Location Address 1:	MAMARONECK AVE & MAPLE AVE
Code:	BP
Location Address 2:	VS #5359
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10605
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004341160
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR

CON EDISON VAULT: 5359 (Continued) **1016961423**

Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	08/02/2013
Trans1 Recv Date:	08/02/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	08/12/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004341160
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693274JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ244 **WHITE PLAINS DPW** **NY LTANKS** **S100177896**
East **MAPLE & MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.235 mi.
1241 ft. **Site 3 of 14 in cluster AJ**

Relative:
Higher

Actual:
228 ft.

LTANKS:

Name:	WHITE PLAINS DPW
Address:	MAPLE & MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9111846 / 1992-03-10
Facility ID:	9111846
Site ID:	90852
Spill Date:	1992-02-18
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	1992-02-18
SWIS:	6017
Investigator:	TAYLOR
Referred To:	Not reported
Reported to Dept:	1992-02-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1992-02-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1992-02-25
Spill Record Last Update:	1992-03-10
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81978
DEC Memo:	""
Remarks:	"DURING UPGRADE TANK PULL CONTAMINATED SOIL DISCOVERED EXCAVATED AND STOCKPILED WILL TEST AND DISPOSED"

All Materials:

Site ID:	90852
Operable Unit ID:	965509
Operable Unit:	01
Material ID:	567527
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AJ245 **CON EDISON MANHOLE: 5369** **RCRA NonGen / NLR** **1016965028**
East **MAMARONECK AVE & MAPLE AVE** **NY MANIFEST** **NYP004379244**
1/8-1/4 **WHITE PLAINS, NY 10602**
0.235 mi.
1241 ft. **Site 4 of 14 in cluster AJ**

Relative:
Higher

Actual:
228 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-11-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5369
Handler Address:	MAMARONECK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10602
EPA ID:	NYP004379244
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE: 5369 (Continued) **1016965028**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-10-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5369
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-11-24 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5369
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE: 5369 (Continued) **1016965028**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: MAMARONECK AVE & MAPLE AVE
City,State,Zip: WHITE PLAINS, NY 10602
Country: USA
EPA ID: NYP004379244
Facility Status: Not reported
Location Address 1: MAMARONECK AVE & MAPLE AVE
Code: BP
Location Address 2: MH 5369
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10605
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004379244
Mailing Name: CON EDISON
Mailing Contact: TOM TEELING
Mailing Address 1: 4 IRVING PLACE - 15TH FLOOR
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/24/2013
Trans1 Recv Date: 10/24/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/25/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004379244

CON EDISON MANHOLE: 5369 (Continued) **1016965028**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011693684JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ246 **CON EDISON** **RCRA NonGen / NLR** **1014397057**
East **MAMARONECK AVE & MAPLE AVE** **NY MANIFEST** **NYP004193744**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.235 mi.
1241 ft. **Site 5 of 14 in cluster AJ**

Relative: **Higher**
Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	MAMARONECK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004193744
Contact Name:	DANIEL PONTECORVO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	347-203-2573
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified

CON EDISON (Continued) **1014397057**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

CON EDISON (Continued) **1014397057**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-11-03 12:48:11.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2009-09-04 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MAMARONECK AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004193744

CON EDISON (Continued) **1014397057**

Facility Status: Not reported
Location Address 1: MAMARONECK AVE & MAPLE AVE - MH 5644
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: YONKERS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004193744
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 09/08/2009
Trans1 Recv Date: 09/08/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/09/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004193744
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NYD980593636
TSDF ID 2: Not reported
Manifest Tracking Number: 001440733FLE
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: Y
Discr Residue Indicator: N
Discr Partial Reject Indicator: N
Discr Full Reject Indicator: N
Manifest Ref Number: Not reported
Alt Facility RCRA ID: Not reported
Alt Facility Sign Date: Not reported
MGMT Method Type Code: H141
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported
Waste Code: Not reported

CON EDISON (Continued) **1014397057**

Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	45
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	1
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B007
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ247 **CON EDISON MANHOLE: 3573** **RCRA NonGen / NLR** **1016969286**
East **MAMARONECK AVE & MAPLE AVE** **NY MANIFEST** **NYP004429429**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.235 mi.
1241 ft. **Site 6 of 14 in cluster AJ**

Relative: **Higher**

Actual: **228 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 3573
Handler Address:	MAMARONECK AVE & MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10603
EPA ID:	NYP004429429
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No

CON EDISON MANHOLE: 3573 (Continued) **1016969286**

Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-10-14 12:33:48.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2014-01-29 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 3573
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON MANHOLE: 3573 (Continued) **1016969286**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2014-02-28 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 3573
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:

Name:	CON EDISON
Address:	MAMARONECK AVE & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY 10603
Country:	USA
EPA ID:	NYP004429429
Facility Status:	Not reported
Location Address 1:	C/O MAMARONECK AVE & MAPLES
Code:	BP
Location Address 2:	STRUCTURE # 3573
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004429429
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE 15TH FLOOR
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA

CON EDISON MANHOLE: 3573 (Continued) **1016969286**

Mailing Phone: 2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/29/2014
Trans1 Recv Date:	01/29/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004429429
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011692691JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ248 **WHITE PLAINS-FIRE HOUSE 6** **NY LTANKS** **S100140233**
East **MAMARONECK & MAPLE AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.235 mi.
1241 ft. **Site 7 of 14 in cluster AJ**

Relative:
Higher

Actual:
228 ft.

LTANKS:

Name:	WHITE PLAINS-FIRE HOUSE 6
Address:	MAMARONECK & MAPLE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8707149 / 1989-01-05
Facility ID:	8707149
Site ID:	311048
Spill Date:	1987-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	Not reported
Cleanup Ceased:	1989-01-05
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-11-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-05
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-20
Spill Record Last Update:	1989-01-12
Spiller Name:	MR. BROCCHI
Spiller Company:	CITY OF WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	251062
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"2K SYSTEM- HIGH VOLUME LEAK.TO E & I & R. TANK REMOVED. NEW TANK INSTALLED"

All TTF:

Facility ID:	8707149
Spill Number:	8707149
Spill Tank Test:	1532377
Site ID:	311048
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

WHITE PLAINS-FIRE HOUSE 6 (Continued) **S100140233**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 311048
Operable Unit ID: 911037
Operable Unit: 01
Material ID: 466122
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

AF249 **GREENWICH RIVERVIEW LLC** **NY UST** **U003885170**
ENE **193-203 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.235 mi.
1242 ft. **Site 8 of 11 in cluster AF**

Relative:
Higher

Actual:
227 ft.

WESTCHESTER CO. UST:
Name: GREENWICH RIVERVIEW LLC
Address: 193-203 MAMARONECK AVENUE
City,State,Zip: WHITE PLAINS, NY 10601
Id/Status: 3-411906 / Active
Operator Name: Greenwich Riverview LLC
Owner Name: Greenwich Riverview LLC
Owner Street: 2334 Boston Post Road
Owner Address2: Not reported
Owner City: Bronx
Owner State: NY
Owner Zipcode: 10467
GDS Number: Not reported

Tank Number: 1
Status: 4. Closed - in place
Capacity: 3000
Product Stored: Not reported
Product Stored Percent: Not reported
Tank Leak Detection: 0. None
Date Installation: Not reported
Date Perm Closure: 02/03/1998
Tank Location: 5. Underground including vaulted with no access for inspection
Tank Type: 1. Steel/Carbon steel/Iron
Tank Internal Protection: 0. None
Tank External Protection: 1. Painted/Asphalt Coating
Tank Secondary Containment: 0. None
Piping Location: 1. Aboveground
Piping Type: 1. Steel/Carbon/ steel/iron
Piping External Protection: 0. None
Overfill Prevention: 0. None

GREENWICH RIVERVIEW LLC (Continued) **U003885170**

Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	3. Gravity

Tank Number:	2
Status:	1. In-Service
Capacity:	3000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	2. Manual Interstitial Monitoring
Date Installation:	01/01/1998
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating,2. Original sacrificial anode
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	3. Aboveground/Underground Combination
Piping Type:	10. Copper
Piping External Protection:	0. None
Overfill Prevention:	5. Vent Whistle
Piping Secondary Containment:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AG250 **CON EDISON** **RCRA NonGen / NLR** **1019904587**
NE **148 MAMARONECK AVE** **NYP004799854**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.235 mi.
1242 ft. **Site 3 of 26 in cluster AG**

Relative: **Higher**
Actual: **226 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-06-26 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	148 MAMARONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004799854
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON (Continued) **1019904587**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 13:09:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

CON EDISON (Continued) **1019904587**

Historic Generators:

Receive Date:	2015-06-26 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-06-26 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AG251 **CON EDISON** **NJ MANIFEST** **S120673263**
NE **148 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.235 mi.
1242 ft. **Site 4 of 26 in cluster AG**

Relative:
Higher

Actual:
226 ft.

NJ MANIFEST:

EPA Id:	NYP004799854
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported

CON EDISON (Continued) **S120673263**

Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014473126JJK
EPA ID:	NYP004799854
Date Shipped:	6/26/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AG252 **CON EDISON** **RCRA NonGen / NLR** **1014396960**
NE **148 MAMARONECK AVE FRONT OF** **NY MANIFEST** **NYP004192761**
1/8-1/4 **WHITE PLAINS, NY 10603**
0.235 mi.
1242 ft. **Site 5 of 26 in cluster AG**

Relative: **Higher**
Actual: **226 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	148 MAMARONECK AVE FRONT OF
Handler City,State,Zip:	WHITE PLAINS, NY 10603
EPA ID:	NYP004192761
Contact Name:	NEIL SKOW
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	718-204-4249
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	4 IRVING PL, RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON (Continued) **1014396960**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-11-03 13:03:19.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2009-08-31 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2016-06-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1014396960**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CONSOLIDATED EDISON
Address: 148 MAMARONECK AVE FRONT OF
City,State,Zip: WHITE PLAINS, NY 10603
Country: USA
EPA ID: NYP004192761
Facility Status: Not reported
Location Address 1: 148 MAMARONECK AVE & & E POST RD - MH 5627
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10602
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004192761
Mailing Name: CONSOLIDATED EDISON
Mailing Contact: FRANKLYN MURRAY
Mailing Address 1: 4 IRVING PLACE RM 828
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124602808

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 08/31/2009
Trans1 Recv Date: 08/31/2009
Trans2 Recv Date: Not reported
TSD Site Recv Date: 09/01/2009
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004192761

CON EDISON (Continued) **1014396960**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD077444263
TSDF ID 2:	Not reported
Manifest Tracking Number:	001433284FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	180
Units:	K - Kilograms (2.2 pounds)
Number of Containers:	2
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	B002
Waste Code 1_3:	B007
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

Name:	CON EDISON
Address:	148 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004799854
Facility Status:	Not reported
Location Address 1:	148 MAMARONECK AVE
Code:	BP
Location Address 2:	MH 5627
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004799854
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK

CON EDISON (Continued) **1014396960**

Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/26/2015
Trans1 Recv Date:	06/26/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/30/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004799854
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014473126JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	Not reported
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	D008
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

CON EDISON (Continued) **1014396960**

Click this hyperlink while viewing on your computer to access
1 additional NY MANIFEST: record(s) in the EDR Site Report.

AK253 **CON EDISON MANHOLE 9130** **RCRA NonGen / NLR** **1014918800**
North **MARTINE AVE & GROVE ST MH 9130** **NJ MANIFEST** **NYP004224192**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.236 mi.
1244 ft. **Site 1 of 5 in cluster AK**

Relative: **Lower**
Actual: **198 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2011-02-15 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9130
Handler Address:	MARTINE AVE & GROVE ST MH 9130
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004224192
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No

CON EDISON MANHOLE 9130 (Continued) **1014918800**

Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2011-07-01 13:05:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2011-01-16 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9130
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2011-02-15 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9130
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No

CON EDISON MANHOLE 9130 (Continued) **1014918800**

Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004224192
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GINO FRABASILE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655817JJK
EPA ID:	NYP004224192
Date Shipped:	1/16/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported

CON EDISON MANHOLE 9130 (Continued) **1014918800**

Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MARTINE AVE & GROVE ST MH 9130
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004224192
Facility Status:	Not reported
Location Address 1:	MARTINE AVE BET. GROVE ST & COURT ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224192
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

CON EDISON MANHOLE 9130 (Continued) **1014918800**

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/16/2011
Trans1 Recv Date:	01/16/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/17/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224192
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655817JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK254 **CON EDISON MANHOLE 9128** **RCRA NonGen / NLR** **1014918791**
North **MARTINE AVE & GROVE ST MH 9128** **NJ MANIFEST** **NYP004224101**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.236 mi.
1244 ft. **Site 2 of 5 in cluster AK**

Relative: **Lower**
Actual: **198 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2011-02-14 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9128
Handler Address:	MARTINE AVE & GROVE ST MH 9128
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004224101
Contact Name:	GINO FRABASILE
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2011-07-01 13:05:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2011-01-15 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9128
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2011-02-14 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9128
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004224101
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	GINO FRABASILE
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655565JJK
EPA ID:	NYP004224101
Date Shipped:	1/15/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MARTINE AVE & GROVE ST MH 9128
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004224101
Facility Status:	Not reported
Location Address 1:	MARTINE AVE & GRANE ST
Code:	BP
Location Address 2:	MH 9128
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224101
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124602757

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON MANHOLE 9128 (Continued) **1014918791**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/15/2011
Trans1 Recv Date:	01/15/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/18/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224101
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655565JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AK255 **CON EDISON MANHOLE 9772** **RCRA NonGen / NLR** **1014918827**
North **MARTINE AVE & GROVE ST SE COR** **NJ MANIFEST** **NYP004224465**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.236 mi.
1244 ft. **Site 3 of 5 in cluster AK**

Relative: RCRA NonGen / NLR:
Lower

Date Form Received by Agency:	2011-02-17 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9772
Handler Address:	MARTINE AVE & GROVE ST SE COR
Handler City,State,Zip:	WHITE PLAINS, NY 10601

Actual:
198 ft.

CON EDISON MANHOLE 9772 (Continued) **1014918827**

EPA ID:	NYP004224465
Contact Name:	DOMINIC BIZZARO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON MANHOLE 9772 (Continued) **1014918827**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2011-07-01 13:05:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2011-01-18 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9772
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2011-02-17 00:00:00.0
Handler Name:	CON EDISON MANHOLE 9772
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON MANHOLE 9772 (Continued) **1014918827**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004224465
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DOMINIC BIZZARO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655782JJK
EPA ID:	NYP004224465
Date Shipped:	1/18/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported

CON EDISON MANHOLE 9772 (Continued) **1014918827**

Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	500.00 Pounds

NY MANIFEST:

Name:	CONED - MH9772
Address:	MARTINE AVE & GROVE ST SE COR
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004224465
Facility Status:	Not reported
Location Address 1:	MARTINE AVE
Code:	BP
Location Address 2:	GROVE AVE
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004224465
Mailing Name:	CONED - MH9772
Mailing Contact:	CONED - MH9772
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10004
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/18/2011
Trans1 Recv Date:	01/18/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/19/2011
Part A Recv Date:	Not reported

CON EDISON MANHOLE 9772 (Continued) **1014918827**

Part B Recv Date:	Not reported
Generator EPA ID:	NYP004224465
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655782JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	500
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AF256 **BASEMENT** **NY LTANKS S102960015**
ENE **203 MAMARONECK AVE** **NY Spills N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.236 mi.
1244 ft. **Site 9 of 11 in cluster AF**

Relative: LTANKS:
Higher

Actual: **227 ft.**

Name:	OFFICE BLDG
Address:	203 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9710787 / Not Reported
Facility ID:	9710787
Site ID:	329412
Spill Date:	1997-12-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa

BASEMENT (Continued) **S102960015**

Referred To:	Not reported
Reported to Dept:	1997-12-22
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	4
Date Entered In Computer:	1997-12-22
Spill Record Last Update:	2010-08-03
Spiller Name:	Not reported
Spiller Company:	OFFICE BLDG
Spiller Address:	203 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	TARRICONE FUEL GREG
Spiller Phone:	(914) 693-1132
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	265043
DEC Memo:	"8/3/10 need Update JO'M"
Remarks:	"TANK FAILED"

All TTF:

Facility ID:	9710787
Spill Number:	9710787
Spill Tank Test:	1545530
Site ID:	329412
Tank Number:	001
Tank Size:	3000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

SPILLS:

Name:	BASEMENT
Address:	203 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9711397 / 1998-01-12
Facility ID:	9711397
Facility Type:	ER
DER Facility ID:	265043
Site ID:	329413
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017

BASEMENT (Continued) **S102960015**

Spill Date:	1998-01-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-01-10
CID:	207
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1998-01-10
Spill Record Last Update:	2018-01-18
Spiller Name:	ARNOLD LIPMAN
Spiller Company:	Not reported
Spiller Address:	203 MAMARONECK AVE
Spiller Company:	001
Contact Name:	ARNOLD LIPMAN
DEC Memo:	"01/10/98 BASEMENT FLOOR OF BUILDING; WCHD RESPONDING; 01/12/98 SMALL SPILL ONTO BOILER ROOM FLOOR; NO DRAIN AFFECTED; CONTAINED WITH SPEEDI-DRI; CHRIS LELAK (WCHD);"
Remarks:	"temp oil storage leaked - oil co enroute to clean up "

All Materials:

Site ID:	329413
Operable Unit ID:	1057884
Operable Unit:	01
Material ID:	326067
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	SPENCER ADAMS STORE
Address:	203 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0800340 / 2008-04-25
Facility ID:	0800340
Facility Type:	ER
DER Facility ID:	265043
Site ID:	396080
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-04-09
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-04-09
CID:	444

BASEMENT (Continued) **S102960015**

Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-09
Spill Record Last Update:	2008-04-28
Spiller Name:	STORE MANAGER-DAVE
Spiller Company:	SPENCER ADAMS STORE
Spiller Address:	203 MANAMACK AVE
Spiller Company:	001
Contact Name:	STORE MANAGER-DAVE
DEC Memo:	"Spill of 10 to 20 gallons, contained to concrete. Robison completed cleanup. NFA jod"
Remarks:	"BROKEN OIL LINE AND IN PROCESS OF CLEANING AND IS CONTAINED IN A PIT"
	Not reported

All Materials:

Site ID:	396080
Operable Unit ID:	1153026
Operable Unit:	01
Material ID:	2143804
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ257 **ANEFCO INC** **RCRA NonGen / NLR** **1000227927**
East **222 MAMARONECK AVE** **FINDS** **NYD075426924**
1/8-1/4 **WHITE PLAINS, NY 10607** **ECHO**
0.236 mi.
1245 ft. **Site 8 of 14 in cluster AJ**

Relative: **Higher**
Actual: **232 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	ANEFCO INC
Handler Address:	222 MAMARONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10607
EPA ID:	NYD075426924
Contact Name:	MARK KIRSHE
Contact Address:	MAMARONECK AVE
Contact City,State,Zip:	WHITE PLAINS, NY 10607
Contact Telephone:	914-946-4631
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified

ANEFCO INC (Continued) **1000227927**

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	MAMARONECK AVE
Mailing City,State,Zip:	WHITE PLAINS, NY 10607
Owner Name:	AMEFCO
Owner Type:	Private
Operator Name:	AMEFCO
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No

ANEFCO INC (Continued) **1000227927**

Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	IGNITABLE WASTE

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AMEFCO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	AMEFCO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	AMEFCO
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	ANEFCO INC

ANEFCO INC (Continued) **1000227927**

Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	ANEFCO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1980-12-19 00:00:00.0
Handler Name:	ANEFCO INC
Federal Waste Generator Description:	Not reported
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110004368577

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

ANEFCO INC (Continued) **1000227927**

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000227927
Registry ID:	110004368577
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004368577
Name:	ANEFCO INC
Address:	222 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10607

AJ258 **222 MAMARONECK AVENUE, LLC** **NY UST** **U003994258**
East **222 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.236 mi.
1245 ft. **Site 9 of 14 in cluster AJ**

Relative: **Higher**

Actual: **232 ft.**

WESTCHESTER CO. UST:

Name:	222 MAMARONECK AVENUE, LLC
Address:	222 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10605
Id/Status:	3-074608 / Active
Operator Name:	Silverman Realty
Owner Name:	222 Mamaroneck Avenue, LLC
Owner Street:	c/o Silverman Realty Group, Inc.
Owner Address2:	237 Mamaroneck Avenue
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605
GDS Number:	Not reported
Tank Number:	001
Status:	1. In-Service
Capacity:	8000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	11/01/1989
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	6. Fiberglass reinforced plastic (FRP)
Tank Internal Protection:	3. Fiberglass liner (FRP)
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	9. Concrete
Piping External Protection:	6. Wrapped (Piping)
Overfill Prevention:	1. Float Vent Valve
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction
Tank Number:	1

222 MAMARONECK AVENUE, LLC (Continued) **U003994258**

Status:	3a. Closed - Prior to 04/1991
Capacity:	5000
Product Stored:	Not reported
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	12/01/1956
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	Not reported
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

AK259 **CON EDISON** **RCRA NonGen / NLR** **1018277456**
North **MARTINE & GROVE ST** **FINDS** **NYP004398962**
1/8-1/4 **WHITE PLAINS, NY 10610** **ECHO**
0.237 mi.
1249 ft. **Site 4 of 5 in cluster AK**

Relative: **Lower**
Actual: **198 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-12-03 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	MARTINE & GROVE ST
Handler City,State,Zip:	WHITE PLAINS, NY 10610
EPA ID:	NYP004398962
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

CON EDISON (Continued) **1018277456**

Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-05-02 12:51:50.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-12-03 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator

CON EDISON (Continued) **1018277456**

State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-12-03 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110067680290

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1018277456
Registry ID:	110067680290
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110067680290
Name:	CON EDISON
Address:	MARTINE & GROVE ST
City,State,Zip:	WHITE PLAINS, NY 10610

AK260 **CON EDISON** **NY MANIFEST** **S116043535**
North **MARTINE & GROVE ST** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10610**
0.237 mi.
1249 ft. **Site 5 of 5 in cluster AK**

Relative:
Lower

Actual:
198 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MARTINE & GROVE ST
City,State,Zip:	WHITE PLAINS, NY 10610
Country:	USA
EPA ID:	NYP004398962
Facility Status:	Not reported
Location Address 1:	NS MARTIN AVE 85 FT NO GROVE ST
Code:	BP
Location Address 2:	MH 9130
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004398962
Mailing Name:	CON EDISON
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	12/03/2013
Trans1 Recv Date:	12/03/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/04/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004398962
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011695018JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N

CON EDISON (Continued) **S116043535**

Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	400
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AI261 **PEPE MOTORS INC** **RCRA-VSQG** **1000197633**
WNW **50 BANK ST** **NY LTANKS** **NYD056298037**
1/8-1/4 **WHITE PLAINS, NY 10606** **FINDS**
0.237 mi. **ECHO**
1251 ft. **Site 2 of 5 in cluster AI** **NY MANIFEST**

Relative: **Lower**
Actual: **206 ft.**

RCRA-VSQG:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	PEPE MOTORS INC
Handler Address:	50 BANK ST
Handler City,State,Zip:	WHITE PLAINS, NY 10606
EPA ID:	NYD056298037
Contact Name:	Not reported
Contact Address:	BANK ST
Contact City,State,Zip:	WHITE PLAINS, NY 10606
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	BANK ST
Mailing City,State,Zip:	WHITE PLAINS, NY 10606
Owner Name:	EUGENE PEPE
Owner Type:	Private

PEPE MOTORS INC (Continued) **1000197633**

Operator Name:	EUGENE PEPE
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

PEPE MOTORS INC (Continued) **1000197633**

Hazardous Waste Summary:

Waste Code:	D000
Waste Description:	Not Defined
Waste Code:	D001
Waste Description:	IGNITABLE WASTE
Waste Code:	F002
Waste Description:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F004
Waste Description:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	EUGENE PEPE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	EUGENE PEPE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator

PEPE MOTORS INC (Continued) **1000197633**

Owner/Operator Name:	EUGENE PEPE
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	NOT REQUIRED
Owner/Operator City,State,Zip:	NOT REQUIRED, WY 99999
Owner/Operator Telephone:	212-555-1212
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1995-04-06 00:00:00.0
Handler Name:	PEPE MOTORS INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2006-01-01 00:00:00.0
Handler Name:	PEPE MOTORS INC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2007-01-01 00:00:00.0
Handler Name:	PEPE MOTORS INC
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1986-11-19 00:00:00.0
Handler Name:	PEPE MOTORS INC
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No

PEPE MOTORS INC (Continued) **1000197633**

Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	1994-03-28 00:00:00.0
Handler Name:	PEPE MOTORS INC.
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Code:	44111
NAICS Description:	NEW CAR DEALERS

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

LTANKS:

Name:	PEPE MOTORS
Address:	50 BANK ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9607100 / 1999-04-29
Facility ID:	9607100
Site ID:	284462
Spill Date:	1996-09-04
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jghardy
Referred To:	Not reported
Reported to Dept:	1996-09-04
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0

PEPE MOTORS INC (Continued) **1000197633**

Date Entered In Computer:	1996-09-04
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	STEVEN MCGUIRE
Spiller Phone:	(914) 561-1512
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	230673
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY/BUZZELLI 04/29/1999 BASED UPON TANK CLOSURE REPORT, SPILL IS CLOSED."
Remarks:	"contact person - joe sallon - 914-949-4004 on site"

All TTF:

Facility ID:	9607100
Spill Number:	9607100
Spill Tank Test:	1544730
Site ID:	284462
Tank Number:	3000
Tank Size:	3000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	20
Test Method 2:	USTest 2000/P/LL plus USTest 2000/U
Leak Rate:	.10
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	284462
Operable Unit ID:	1035061
Operable Unit:	01
Material ID:	346364
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

FINDS:

Registry ID: 110004360423

Click Here:

Environmental Interest/Information System:

RCRAInfo is a national information system that supports the Resource

PEPE MOTORS INC (Continued) **1000197633**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000197633
Registry ID:	110004360423
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110004360423
Name:	PEPE MOTORS INC
Address:	50 BANK ST
City,State,Zip:	WHITE PLAINS, NY 10606

NY MANIFEST:

Name:	PEPE MOTOR
Address:	50 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606-0000
Country:	USA
EPA ID:	NYD056298037
Facility Status:	Not reported
Location Address 1:	50 BANK STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYD056298037
Mailing Name:	PEPE MOTOR
Mailing Contact:	PEPE MOTOR
Mailing Address 1:	50 BANK STREET
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10606
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	9149494000

NY MANIFEST:

Document ID:	ILA8347366
Manifest Status:	Not reported
seq:	01
Year:	1999
Trans1 State ID:	UPW151288
Trans2 State ID:	UPW203954
Generator Ship Date:	08/10/1999
Trans1 Recv Date:	08/10/1999
Trans2 Recv Date:	08/12/1999
TSD Site Recv Date:	08/17/1999

PEPE MOTORS INC (Continued) **1000197633**

Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD056298037
Trans1 EPA ID:	ILD984908202
Trans2 EPA ID:	SCD987574647
TSDF ID 1:	ILD980613913
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D006 - CADMIUM 1.0 MG/L TCLP
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00007
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	R Material recovery of more than 75 percent of the total material.
Specific Gravity:	01.00

AI262 **MERCEDES- BENZ OF WHITE PLAINS** **NY UST U003857474**
WNW **50 BANK STREET** **NY AST N/A**
1/8-1/4 **WHITE PLAINS, NY 10606**
0.237 mi.
1251 ft. **Site 3 of 5 in cluster AI**

Relative: **Lower**
Actual: **206 ft.**

WESTCHESTER CO. UST:

Name:	MERCEDES- BENZ OF WHITE PLAINS
Address:	50 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
Id/Status:	3-452122 / Active
Operator Name:	Eugene Pepe
Owner Name:	Eugene Pepe
Owner Street:	869 Old Quaker Hill Road
Owner Address2:	Not reported
Owner City:	Pawling
Owner State:	NY
Owner Zipcode:	12564
GDS Number:	3551700341
Tank Number:	1
Status:	1. In-Service
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported

MERCEDES- BENZ OF WHITE PLAINS (Continued) **U003857474**

Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	03/01/1997
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)
Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	1 old
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0009. Gasoline
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	06/01/1979
Date Perm Closure:	02/01/1997
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	2
Status:	1. In-Service
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	1. Electronic Interstitial Monitoring
Date Installation:	03/01/1997
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	4. Fiberglass coated steel
Tank Internal Protection:	0. None
Tank External Protection:	4. Fiberglass
Tank Secondary Containment:	4. Double-Walled (underground only)
Piping Location:	2. Underground/on Ground
Piping Type:	6. Fiberglass Reinforced Plastic (FRP)
Piping External Protection:	4. Fiberglass
Overfill Prevention:	3. Automatic Shut-off
Piping Secondary Containment:	4. Double-Walled (underground only)

MERCEDES- BENZ OF WHITE PLAINS (Continued) **U003857474**

Spill Prevention:	1. Catch Basin
Dispenser:	2. Suction

Tank Number:	2 old
Status:	3. Closed - Removed
Capacity:	3000
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Tank Leak Detection:	99. Other
Date Installation:	06/01/1979
Date Perm Closure:	02/01/1997
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	0. No Pipiing
Piping Type:	1. Steel/Carbon/ steel/iron
Piping External Protection:	0. None
Overfill Prevention:	Not reported
Piping Secondary Containment:	Not reported
Spill Prevention:	Not reported
Dispenser:	2. Suction

Tank Number:	3
Status:	4. Closed - in place
Capacity:	550
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1979
Date Perm Closure:	12/02/2008
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	4
Status:	4. Closed - in place
Capacity:	550
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1979
Date Perm Closure:	12/02/2008
Tank Location:	5. Underground including vaulted with no access for inspection

MERCEDES- BENZ OF WHITE PLAINS (Continued) **U003857474**

Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	5
Status:	0. Administratively closed
Capacity:	1000
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Tank Leak Detection:	0. None
Date Installation:	06/01/1979
Date Perm Closure:	01/01/1900
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on ground
Piping Type:	2. Galvanized steel
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	Not reported
Spill Prevention:	0. None
Dispenser:	0. None

WESTCHESTER CO. AST:

Name:	MERCEDES- BENZ OF WHITE PLAINS
Address:	50 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
PBS Number:	3-452122
Site Status:	Active
GDS Number:	3551700341
Operator Name:	Eugene Pepe
Owner Name:	Eugene Pepe
Owner Street:	869 Old Quaker Hill Road
Owner Address2:	Not reported
Owner City/State/Zip:	Pawling, NY 12564

Tank Number:	6
Status:	3. Closed - Removed
Date Installation:	06/01/1979
Capacity:	275
Product Stored:	0015. Motor Oil
Product Stored Percent:	Not reported
Date Perm Closure:	12/02/2008
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None

MERCEDES- BENZ OF WHITE PLAINS (Continued) **U003857474**

Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	10. Copper
Piping External Protection:	0. None
Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	0. None

Tank Number:	7
Status:	1. In-Service
Date Installation:	06/01/2004
Capacity:	800
Product Stored:	0022. Waste/Used Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	2. Suction

Tank Number:	8
Status:	1. In-Service
Date Installation:	03/02/2009
Capacity:	500
Product Stored:	0013. Lube Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	2. Suction

MERCEDES- BENZ OF WHITE PLAINS (Continued) **U003857474**

Tank Number:	9
Status:	1. In-Service
Date Installation:	03/02/2009
Capacity:	500
Product Stored:	0013. Lube Oil
Product Stored Percent:	0
Date Perm Closure:	01/01/1900
Tank Location:	2. Aboveground (contact w/ impervious barrier)
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	2. Manual Interstitial Monitoring
Tank Secondary Containment:	9. Modified double-walled (aboveground only)
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	1. Painted/Asphalt Coating
Piping Leak Detection:	2. Manual Interstitial Monitoring
Piping Secondary Containment:	0. None
Overfill Prevention:	1. Float Vent Valve
Spill Prevention:	0. None
Dispenser:	2. Suction

AF263 **KEMPLER RESIDENCE** **NY LTANKS** **S105998935**
ENE **169 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.237 mi.
1252 ft. **Site 10 of 11 in cluster AF**

Relative: **Higher**
Actual: **226 ft.**

LTANKS:

Name:	KEMPLER RESIDENCE
Address:	169 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0301465 / 2003-08-25
Facility ID:	0301465
Site ID:	160482
Spill Date:	2003-05-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-05-09
CID:	195
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	2003-06-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-09
Spill Record Last Update:	2005-02-12
Spiller Name:	PETER KEMPLER
Spiller Company:	PETER KEMPLER
Spiller Address:	169 MAMARONECK AVE
Spiller County:	001

KEMPLER RESIDENCE (Continued) **S105998935**

Spiller Contact:	PETER KEMPLER
Spiller Phone:	(914) 946-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	135518
DEC Memo:	"06/30/03 ALSO SPILL 03-03361. 08/25/03 NORTHEAST DISPOSED OF LUST AND 122.09 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"TANK WAS UNCOVERED AND TESTED. TEST FAILED. OWNER (PETER KEMPLER) WAS TOLD TO PUMP TANK OUT WITHIN 48 HOURS AND HAVE TANK REMOVED TO CHECK FOR CONTAMINATION. CALLER CAN BE REACHED AT 845-742-1666."

All TTF:

Facility ID:	0301465
Spill Number:	0301465
Spill Tank Test:	1528363
Site ID:	160482
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	160482
Operable Unit ID:	867853
Operable Unit:	01
Material ID:	505959
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AF264 **STEWARD** **NY LTANKS** **S105999309**
ENE **165 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.237 mi.
1254 ft. **Site 11 of 11 in cluster AF**

Relative: **Higher**
Actual: **227 ft.**

LTANKS:

Name:	STEWARD
Address:	165 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0303361 / 2007-06-22
Facility ID:	0303361
Site ID:	180689

STEWARD (Continued) **S105999309**

Spill Date:	2003-06-30
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-06-30
CID:	204
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2003-06-30
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-30
Spill Record Last Update:	2007-06-22
Spiller Name:	BAHRU STEWARD
Spiller Company:	BAHRU STEWARD
Spiller Address:	165 MAMARONECK AVENUE
Spiller County:	001
Spiller Contact:	MARIE MULLEN
Spiller Phone:	(914) 741-5472
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	151552
DEC Memo:	"06/30/03: UST lined tank, leaked through lining, tank out, soil will be removed. Waiting on insurance. See also spill #03-01465. 02/12/05 PREVIOUSLY REPORTED AS 97-01601. UST FAILED TANK TEST, TANK WAS RELINED AND PUT BACK IN SERVICE. TANK REMOVED BY NES AFTER CONTAMINATION FOUND DURING REMOVAL OF NEIGHBORING TANK AT 169 MAMARONECK AVE. TANK HAD BEEN LEAKING PRIOR TO RELINING. jbo 06/22/2007: NES COMPLETED CLEAN UP. jod"
Remarks:	"OLD TANK FAILED"

All Materials:

Site ID:	180689
Operable Unit ID:	871405
Operable Unit:	01
Material ID:	504234
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	165 MAMARONECK AVE
Address:	165 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9701601 / 2005-02-12
Facility ID:	9701601
Site ID:	118993

STEWARD (Continued) **S105999309**

Spill Date:	1997-05-06
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-05-06
CID:	282
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-05-06
Spill Record Last Update:	2005-02-12
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	N/A
Spiller Phone:	(914) 934-5992
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	151552
DEC Memo:	"02/12/05 TANK REPORTEDLY PASSED A RETEST, NO RETEST INFORMATION SUBMITTED TO DEC. TANK WAS REMOVED BY NES ON 6-30-03 AFTER CONTAMINATION WAS DISCOVERED DURING REMOVAL OF NEIGHBORING TANK AT 169 MAMARONECK AVE BY NORTHEAST ENVIRONMENTAL (SEE SPILL 03-01465). WHEN TANK WAS REMOVED BY NES, IT WAS DISCOVERED THAT THE TANK HAD BEEN FIBERGLASS RELINED IN THE PAST. THE TANK WAS NO LONGER LEAKING BUT HAD LEAKED PRIOR TO RELINING. NES REMOVING SOIL, REPORT TO FOLLOW. SEE SPILL 03-03361 FOR ALL UPDATES. NFA THIS SPILL NUMBER. jbo"
Remarks:	"TANK FAILED THE VACUUM TEST.COMMERCIAL BUILDING IS WHERE THE TEST WAS DONE."

All TTF:

Facility ID:	9701601
Spill Number:	9701601
Spill Tank Test:	1545105
Site ID:	118993
Tank Number:	1
Tank Size:	1000
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

AG265 **CON EDISON MANHOLE 3334** **RCRA NonGen / NLR** **1014918971**
NE **MAMARONECK AVE & E POST RD** **NJ MANIFEST** **NYP004225900**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.239 mi.
1262 ft. **Site 6 of 26 in cluster AG**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2011-02-27 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3334
Handler Address:	MAMARONECK AVE & E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004225900
Contact Name:	DONALD SENNO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE 3334 (Continued) **1014918971**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2011-07-01 13:05:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2011-01-28 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3334
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2011-02-27 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3334
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE 3334 (Continued) **1014918971**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004225900
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655798JJK
EPA ID:	NYP004225900
Date Shipped:	1/27/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON MANHOLE 3334 (Continued) **1014918971**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	75.00 Pounds

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MAMARONECK AVE & E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004225900
Facility Status:	Not reported
Location Address 1:	E POST RD MH 3334
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004225900
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON MANHOLE 3334 (Continued) **1014918971**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2011
Trans1 Recv Date:	01/27/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004225900
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655798JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	75
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG266 **CON EDISON** **RCRA NonGen / NLR** **1019904715**
NE **E POST RD & MAMMARONECK AVE** **FINDS** **NYP004801361**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.239 mi.
1262 ft. **Site 7 of 26 in cluster AG**

Relative: **Higher**
Actual: **226 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-07-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	E POST RD & MAMMARONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601

CON EDISON (Continued) **1019904715**

EPA ID:	NYP004801361
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON (Continued) **1019904715**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:28:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-07-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-07-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON (Continued) **1019904715**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069647859

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019904715
Registry ID:	110069647859
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069647859
Name:	CON EDISON
Address:	E POST RD & MAMMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601

AG267 **CON EDISON** **NJ MANIFEST** **S120673398**
NE **E POST RD & MAMMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.239 mi.
1262 ft. **Site 8 of 26 in cluster AG**

Relative: Higher
Actual: 226 ft.

NJ MANIFEST:

EPA Id:	NYP004801361
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469259JJK
EPA ID:	NYP004801361
Date Shipped:	7/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359

CON EDISON (Continued) **S120673398**

Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AG268 **CON EDISON** **NY MANIFEST** **S119076221**
NE **E POST RD & MAMMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.239 mi.
1262 ft. **Site 9 of 26 in cluster AG**

Relative: **Higher**
Actual: **226 ft.**

NY MANIFEST:

Name:	CON EDISON
Address:	E POST RD & MAMMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004801361
Facility Status:	Not reported
Location Address 1:	E POST RD & MAMARONECK AVE
Code:	BP
Location Address 2:	VS 5056
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601

CON EDISON (Continued) **S119076221**

Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004801361
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/01/2015
Trans1 Recv Date:	07/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/02/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004801361
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469259JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	700
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1

CON EDISON (Continued) **S119076221**

Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG269 **CON EDISON** **NY MANIFEST** **S117536411**
NE **MAMARONECK AVE & E POST RD** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.239 mi.
1262 ft. **Site 10 of 26 in cluster AG**

Relative:
Higher

Actual:
226 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	MAMARONECK AVE & E POST RD
City,State,Zip:	WHITE PLAINS, NY
Country:	USA
EPA ID:	NYP004688784
Facility Status:	Not reported
Location Address 1:	MAMARONECK AVE & E POST RD
Code:	BP
Location Address 2:	VS 8314
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004688784
Mailing Name:	CON EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	11/03/2014
Trans1 Recv Date:	11/03/2014
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	11/04/2014
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004688784
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S117536411**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	012773152JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG270 **CON EDISON SB1820** **RCRA NonGen / NLR** **1025504702**
NE **MAMARONECK AVE & E POST RD** **NYP005242110**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.239 mi.
1262 ft. **Site 11 of 26 in cluster AG**

Relative: RCRA NonGen / NLR:
Higher

Actual: **226 ft.**

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON SB1820
Handler Address:	MAMARONECK AVE & E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP005242110
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	State
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported

CON EDISON SB1820 (Continued) **1025504702**

Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No

CON EDISON SB1820 (Continued) **1025504702**

Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:43:43.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2018-12-14 00:00:00.0
Handler Name:	CON EDISON SB1820
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON SB1820
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

AG271 **CON EDISON MANHOLE 3343** **RCRA NonGen / NLR** **1014918970**
NE **MAMARONECK AVE & E POST RD** **NJ MANIFEST** **NYP004225892**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.239 mi.
1262 ft. **Site 12 of 26 in cluster AG**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2011-02-27 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3343
Handler Address:	MAMARONECK AVE & E POST RD
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004225892
Contact Name:	DONALD SENNO
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	914-925-6219
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SR SPECIALIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL RM 828
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2011-07-01 13:05:47.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2011-01-28 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3343
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2011-02-27 00:00:00.0
Handler Name:	CON EDISON MANHOLE 3343
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004225892
Mail Address:	IRVING PL RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	DONALD SENNO
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007655818JJK
EPA ID:	NYP004225892
Date Shipped:	1/27/2011
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	100.00 Pounds

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	MAMARONECK AVE & E POST RD
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004225892
Facility Status:	Not reported
Location Address 1:	MAMACKROCK AVE & PORT RD
Code:	BP
Location Address 2:	MH 3343
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004225892
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	CONSOLIDATED EDISON
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON MANHOLE 3343 (Continued) **1014918970**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	01/27/2011
Trans1 Recv Date:	01/27/2011
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/31/2011
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004225892
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007655818JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG272 **CON EDISON** **RCRA NonGen / NLR** **1019905036**
NE **134 MAMARANECK AVE** **FINDS** **NYP004805065**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.240 mi.
1268 ft. **Site 13 of 26 in cluster AG**

Relative: RCRA NonGen / NLR:
Higher

Date Form Received by Agency:	2015-07-10 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	134 MAMARANECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601

Actual:
224 ft.

CON EDISON (Continued) **1019905036**

EPA ID:	NYP004805065
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON (Continued) **1019905036**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:28:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-07-10 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-07-10 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON (Continued) **1019905036**

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069667104

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1019905036
Registry ID:	110069667104
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069667104
Name:	CON EDISON
Address:	134 MAMARANECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601

AG273 **CON EDISON** **NY Spills S102155749**
NE **134 MAMARONECK AVE** **NY MANIFEST N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 14 of 26 in cluster AG**

Relative: Higher
Actual: 224 ft.

SPILLS:

Name:	GREEN POINT SAVINGS BANK
Address:	134 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9509489 / 1997-12-04
Facility ID:	9509489
Facility Type:	ER
DER Facility ID:	256859
Site ID:	318648
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-11-01
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-11-01
CID:	266
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported

CON EDISON (Continued) **S102155749**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-11-01
Spill Record Last Update:	1997-12-04
Spiller Name:	JOE TATARKA
Spiller Company:	GREEN POINT SAVINGS BANK
Spiller Address:	134 MAMARONECK AVENUE
Spiller Company:	001
Contact Name:	JOE TATARKA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FILL PIPE ROTTED OUT. ONTO SOIL & BLACKTOP. NO FURTHER DELIVERIES UNTIL FILL IS REPAIRED. SOIL REMOVED & FUEL CLEANED UP."
Name:	M&T BANK
Address:	134 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1213452 / 2013-01-02
Facility ID:	1213452
Facility Type:	ER
DER Facility ID:	431971
Site ID:	476637
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2012-12-12
Investigator:	jbodee
Referred To:	WCHD
Reported to Dept:	2012-12-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-12-12
Spill Record Last Update:	2013-01-02
Spiller Name:	MR FRANK
Spiller Company:	M AND T BANK
Spiller Address:	134 MAMMORONECK AVE
Spiller Company:	999
Contact Name:	MR FRANK
DEC Memo:	"12/12/12- WCHD reports they are responding. Update from WCHD- Joe Mancini. Curb fill pipe to vaulted tank in basement is leaking near wall. Some oil onto wall and floor from delivery today. WCHD reports that minimal odors noted at this time. MT Bank to retain cleanup contractor to complete cleanup and conduct repairs. WCHD to followup. DT"
Remarks:	"broken pipe under sidewalk, c/u pending"

All Materials:

Site ID:	476637

CON EDISON (Continued) **S102155749**

Operable Unit ID:	1226463
Operable Unit:	01
Material ID:	2223728
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON
Address:	134 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004806469
Facility Status:	Not reported
Location Address 1:	134 MAMARONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004806469
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/14/2015
Trans1 Recv Date:	07/14/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/17/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004806469
Trans1 EPA ID:	Not reported

CON EDISON (Continued) **S102155749**

Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469294JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	25
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG274 **M AND T BANK** **NY AST** **A100096027**
NE **134 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 15 of 26 in cluster AG**

Relative: **Higher**
Actual: **224 ft.**

WESTCHESTER CO. AST:

Name:	M AND T BANK
Address:	134 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-601013
Site Status:	Unregulated
GDS Number:	Not reported
Operator Name:	unknown
Owner Name:	Keating Charitable Remainder Unitrust
Owner Street:	P.O. Box 5438
Owner Address2:	Not reported
Owner City/State/Zip:	Hanover, NH 03755
Tank Number:	1
Status:	3. Closed - Removed
Date Installation:	06/01/1974
Capacity:	2000

M AND T BANK (Continued) **A100096027**

Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	04/26/2018
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	0. None
Tank Secondary Containment:	Not reported
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	0. None
Spill Prevention:	0. None
Dispenser:	2. Suction

AG275 **CON EDISON** **NJ MANIFEST** **S120673731**
NE **134 MAMARANECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 16 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

NJ MANIFEST:

EPA Id:	NYP004805065
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469265JJK
EPA ID:	NYP004805065
Date Shipped:	7/10/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported

CON EDISON (Continued) **S120673731**

Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AG276 **CON EDISON** **NY MANIFEST** **S119076412**
NE **134 MAMARANECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 17 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	134 MAMARANECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004805065
Facility Status:	Not reported
Location Address 1:	134 MAMARONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004805065
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY

CON EDISON (Continued) **S119076412**

Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006932359
Trans2 State ID:	Not reported
Generator Ship Date:	07/10/2015
Trans1 Recv Date:	07/10/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/13/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004805065
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014469265JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	50
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG277 **CON EDISON** **RCRA NonGen / NLR** **1019905154**
NE **134 MAMARONECK AVE** **NYP004806469**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 18 of 26 in cluster AG**

Relative: **Higher**
Actual: **224 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-07-14 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	134 MAMARONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004806469
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON (Continued) **1019905154**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:28:59.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2015-07-14 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-07-14 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

CON EDISON (Continued) **1019905154**

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

AG278 **CON EDISON** **NJ MANIFEST** **S120673858**
NE **134 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 19 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

NJ MANIFEST:

EPA Id:	NYP004806469
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014469294JJK
EPA ID:	NYP004806469
Date Shipped:	7/14/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported

CON EDISON (Continued) **S120673858**

Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AC279 **NY AST** **S121995547**
NNE **85 COURT STREET** **NY COOLING TOWERS** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.240 mi.
1268 ft. **Site 3 of 3 in cluster AC**

Relative: **Higher**
Actual: **226 ft.**

WESTCHESTER CO. AST:

Name:	COUNTY OF WESTCHESTER
Address:	85 COURT STREET
City,State,Zip:	WHITE PLAINS, NY 10601
PBS Number:	3-801525
Site Status:	Administratively Closed
GDS Number:	Not reported
Operator Name:	John Varmon
Owner Name:	County of Westchester
Owner Street:	148 Martine Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10601
Tank Number:	11
Status:	1. In-Service
Date Installation:	07/01/2008
Capacity:	336
Product Stored:	0008. Diesel
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	3. Aboveground on saddles,legs,stilts,racks or cradle
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	1. Painted/Asphalt Coating
Tank Leak Detection:	5. In-Tank System (auto tank gauge),GEN BELLY TANK
Tank Secondary Containment:	GEN BELLY TANK
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	Not reported

(Continued) **S121995547**

Piping Leak Detection:	Not reported
Piping Secondary Containment:	Not reported
Overfill Prevention:	2. High Level Alarm,4. Product Level Gauge (Aboveground Only)
Spill Prevention:	0. None
Dispenser:	2. Suction

COOLING TOWERS:

Name:	Not reported
Address:	85 COURT STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Equipment Unique ID:	5994
Equipment Borough:	Not reported
Intended Use:	Air Conditioning
Manufacturer:	BAC
Model:	VTO-78-JMLTX
Cooling Capacity:	200
Cooling Capacity Unit:	Tonnage
Commissioned Date:	09/01/1982
Inspection Date:	04/29/2020
Date of Bacteriological Collection:	06/11/2020
Date of Legionella Collection:	04/29/2020
Last Legionella Result > 1,000 CFU/mL:	no
Latitude:	41.030400618
Longitude:	-73.767012923

AG280 **CON EDISON** **RCRA NonGen / NLR** **1019908523**
NE **128 MAMARONECK AVE** **FINDS** **NYP004846877**
1/8-1/4 **WHITE PLAINS, NY 10601** **ECHO**
0.241 mi.
1271 ft. **Site 20 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2015-10-01 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	128 MAMARONECK AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004846877
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported

CON EDISON (Continued) **1019908523**

Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2016-09-09 15:53:31.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

CON EDISON (Continued) **1019908523**

Historic Generators:

Receive Date:	2015-10-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Large Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2015-10-01 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

FINDS:
Registry ID: 110069676185

Click Here:

Environmental Interest/Information System:
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1019908523
Registry ID: 110069676185

CON EDISON (Continued) **1019908523**

DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110069676185
Name:	CON EDISON
Address:	128 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601

AG281 **CON EDISON** **NJ MANIFEST** **S120677447**
NE **128 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.241 mi.
1271 ft. **Site 21 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

NJ MANIFEST:

EPA Id:	NYP004846877
Mail Address:	IRVING PL 15TH FL NE
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	THOMAS TEELING
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	014460357JJK
EPA ID:	NYP004846877
Date Shipped:	10/1/2015
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	Not reported
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	Not reported
TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported

CON EDISON (Continued) **S120677447**

Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

AG282 **CON EDISON** **NY MANIFEST** **S119078146**
NE **128 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.241 mi.
1271 ft. **Site 22 of 26 in cluster AG**

Relative:
Higher

Actual:
224 ft.

NY MANIFEST:

Name:	CON EDISON
Address:	128 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004846877
Facility Status:	Not reported
Location Address 1:	128 MAMORONECK AVE
Code:	BP
Location Address 2:	SB 1807
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004846877
Mailing Name:	CON EDISON
Mailing Contact:	DENNIS HUACON
Mailing Address 1:	4 IRVING PL 15TH FL
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	10/01/2015

CON EDISON (Continued) **S119078146**

Trans1 Recv Date:	10/01/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/05/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004846877
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	014460357JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG283 **CON EDISON MANHOLE: 5050** **RCRA NonGen / NLR** **1016963680**
NE **149 MAMARONECK AVE FRONT OF** **NY MANIFEST** **NYP004366654**
1/8-1/4 **WHITE PLAINS, NY 10601**
0.241 mi.
1275 ft. **Site 23 of 26 in cluster AG**

Relative:
Higher

Actual:
226 ft.

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-10-26 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5050
Handler Address:	149 MAMARONECK AVE FRONT OF
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004366654
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-09-26 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5050
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-10-26 00:00:00.0
Handler Name:	CON EDISON MANHOLE: 5050
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

NY MANIFEST:

Name:	CON EDISON
Address:	149 MAMARONECK AVE FRONT OF
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004366654
Facility Status:	Not reported
Location Address 1:	F/O 149 MARMARONECK AVE
Code:	BP
Location Address 2:	MH5050
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004366654
Mailing Name:	CON EDISON
Mailing Contact:	C
Mailing Address 1:	4 IRVING PLACE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	09/26/2013
Trans1 Recv Date:	09/26/2013
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	10/02/2013
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004366654
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	011694717JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported

CON EDISON MANHOLE: 5050 (Continued) **1016963680**

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	110
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG284 **PER-BAR** **NY LTANKS** **S100140366**
NE **124 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.243 mi.
1284 ft. **Site 24 of 26 in cluster AG**

Relative: **Higher**

Actual: **223 ft.**

LTANKS:

Name:	PER-BAR
Address:	124 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8802839 / 1989-01-18
Facility ID:	8802839
Site ID:	116904
Spill Date:	1988-06-29
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-01-18
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-03-23
Spill Record Last Update:	1989-02-07
Spiller Name:	Not reported
Spiller Company:	BRIAN COMI
Spiller Address:	Not reported
Spiller County:	001

PER-BAR (Continued) **S100140366**

Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	101701
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"FAILED WITH GROSS LEAK. PBS TO FOLLOW.RETEST NEEDED."

All TTF:

Facility ID:	8802839
Spill Number:	8802839
Spill Tank Test:	1534211
Site ID:	116904
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	116904
Operable Unit ID:	918126
Operable Unit:	01
Material ID:	458404
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AJ285 **SILVERMAN REALTY** **NY LTANKS** **S106702432**
East **235 MAMARONECK AVE** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.246 mi.
1300 ft. **Site 10 of 14 in cluster AJ**

Relative:
Higher

Actual:
232 ft.

LTANKS:

Name:	PBS
Address:	235 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0404588 / 2005-01-10
Facility ID:	0404588
Site ID:	128036
Spill Date:	2004-07-28
Spill Cause:	Tank Test Failure

SILVERMAN REALTY (Continued) **S106702432**

Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WCHD
Reported to Dept:	2004-07-28
CID:	408
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-07-28
Spill Record Last Update:	2005-01-10
Spiller Name:	Not reported
Spiller Company:	SILVERMANN REALITY
Spiller Address:	237 MAMARONECK AVE.
Spiller County:	001
Spiller Contact:	SILVERMANN REALITY
Spiller Phone:	(914) 557-0310
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	110492
DEC Memo:	"01/10/05 PBS SITE. TANK PASSED RETEST. SPILL FILE CLOSED BY DANIELLE JACKSON OF THE WESTCHESTER COUNTY HEALTH DEPT. NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"VACCUM TEST; VENT IS BROKEN"

All TTF:

Facility ID:	0404588
Spill Number:	0404588
Spill Tank Test:	1529478
Site ID:	128036
Tank Number:	1
Tank Size:	5000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	128036
Operable Unit ID:	887658
Operable Unit:	01
Material ID:	488573
Material Code:	0001A
Material Name:	#2 fuel oil

SILVERMAN REALTY (Continued) **S106702432**

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	SILVERMAN REALTY
Address:	235 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1112859 / 2012-03-30
Facility ID:	1112859
Site ID:	460824
Spill Date:	2012-02-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-02-09
Spill Record Last Update:	2012-04-02
Spiller Name:	TONYA BASALYGA
Spiller Company:	SILVERMAN REALTY
Spiller Address:	235 MAMARONECK DR
Spiller County:	999
Spiller Contact:	TONYA BASALYGA
Spiller Phone:	(914) 683-8000
Spiller Extention:	328
DEC Region:	3
DER Facility ID:	110492
DEC Memo:	"2/9/12 - To isolate the tank and retest. KAB 3/30/12 As per WCDOH ttf, passed retest after remote fill and vent replacement."
Remarks:	"retest pending, failed with dry leak"

All Materials:

Site ID:	460824
Operable Unit ID:	1210926
Operable Unit:	01
Material ID:	2208598
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

SILVERMAN REALTY (Continued) **S106702432**

Oxygenate: Not reported

SPILLS:

Name:	COMMERCIAL PROPERTY
Address:	235 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0712619 / 2008-03-06
Facility ID:	0712619
Facility Type:	ER
DER Facility ID:	110492
Site ID:	394259
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-03-02
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-03-02
CID:	41
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-03-02
Spill Record Last Update:	2008-03-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	ABOVE
DEC Memo:	"WCDOH responded, clean up completed."
Remarks:	"OVERFILL OF TANK - OIL COMPANY ON SITE - THREW DRAINING PIPE INTO SUB PUMP - BLDG OWNER WANTS AUTHORIZATION TO HAVE PUMP TURNED BACK ON - REQUESTS CALLBACK ASAP"

All Materials:

Site ID:	394259
Operable Unit ID:	1151204
Operable Unit:	01
Material ID:	2141910
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

AJ286 **CON EDISON** **RCRA NonGen / NLR** **1014398389**
East **235 MAMARONECK AVE FO** **NJ MANIFEST** **NYP004207423**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.246 mi.
1300 ft. **Site 11 of 14 in cluster AJ**

Relative: **Higher**
Actual: **232 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	235 MAMARONECK AVE FO
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004207423
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON (Continued) **1014398389**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:29:22.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2010-05-27 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON (Continued) **1014398389**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004207423
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	NEIL SKOW
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007020816JJK
EPA ID:	NYP004207423
Date Shipped:	05/27/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	05/27/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	05/28/2010

CON EDISON (Continued) **1014398389**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	150 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	235 MAMARONECK AVE FO
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004207423
Facility Status:	Not reported
Location Address 1:	F/O 235 MAMARONECK AVE - MH 3572
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10602
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004207423
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **1014398389**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	05/27/2010
Trans1 Recv Date:	05/27/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	05/28/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004207423
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007020816JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	150
Units:	P - Pounds
Number of Containers:	100
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ287 **CONSOLIDATED EDISON** **NY MANIFEST** **S110610759**
East **235-237 MAMARONECK AV** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.246 mi.
1300 ft. **Site 12 of 14 in cluster AJ**

Relative: **Higher**
Actual: **232 ft.**

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	235-237 MAMARONECK AV
City,State,Zip:	WHITE PLAINS, NY
Country:	USA

CONSOLIDATED EDISON (Continued) **S110610759**

EPA ID:	NYP004211553
Facility Status:	Not reported
Location Address 1:	235-237 MAMARONECK AV
Code:	BP
Location Address 2:	TM 3571
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	Not reported
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004211553
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	TOM TEELING
Mailing Address 1:	4 IRVING PLACE RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	07/15/2010
Trans1 Recv Date:	07/15/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	07/18/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004211553
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	003533342JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported

CONSOLIDATED EDISON (Continued) **S110610759**

Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	10
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AJ288 **SILVERMAN 237, LLC** **NY AST** **A100364604**
East **235 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.246 mi.
1300 ft. **Site 13 of 14 in cluster AJ**

Relative: **Higher**
Actual: **232 ft.**

WESTCHESTER CO. AST:

Name:	SILVERMAN 237, LLC
Address:	235 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10605
PBS Number:	3-074616
Site Status:	Active
GDS Number:	Not reported
Operator Name:	Silverman Realty
Owner Name:	Silverman 237, LLC
Owner Street:	237 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City/State/Zip:	White Plains, NY 10605
Tank Number:	1
Status:	1. In-Service
Date Installation:	12/01/1956
Capacity:	5000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	Not reported
Date Perm Closure:	01/01/1900
Tank Location:	6. Aboveground in subterranean vault with access for inspections
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Leak Detection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	1. Aboveground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Piping Leak Detection:	0. None
Piping Secondary Containment:	0. None
Overfill Prevention:	5. Vent Whistle
Spill Prevention:	0. None
Dispenser:	2. Suction

AJ289 **CON EDISON** **RCRA NonGen / NLR** **1014398429**
East **237 MAMARONECK AVE S OF MAPLE AVE** **NJ MANIFEST** **NYP004207829**
1/8-1/4 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.248 mi.
1308 ft. **Site 14 of 14 in cluster AJ**

Relative: **Higher**
Actual: **232 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Handler Address:	237 MAMARONECK AVE S OF MAPLE AVE
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NYP004207829
Contact Name:	Not reported
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	Not reported
Mailing City,State,Zip:	Not reported
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

CON EDISON (Continued) **1014398429**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2020-04-13 15:29:24.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Historic Generators:

Receive Date:	2010-06-03 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2020-04-13 00:00:00.0
Handler Name:	CON EDISON
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No

CON EDISON (Continued) **1014398429**

Electronic Manifest Broker: No

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

NJ MANIFEST:

EPA Id:	NYP004207829
Mail Address:	4 IRVING PL, RM 828
Mail City/State/Zip:	NEW YORK, NY 10003
Facility Phone:	Not reported
Emergency Phone:	Not reported
Contact:	NEIL SKOW
Comments:	Not reported
SIC Code:	Not reported
County:	NY119
Municipal:	Not reported
Previous EPA Id:	Not reported
Gen Flag:	Not reported
Trans Flag:	Not reported
TSDF Flag:	Not reported
Name Change:	Not reported
Date Change:	Not reported

Manifest:

Manifest Number:	007020821JJK
EPA ID:	NYP004207829
Date Shipped:	06/03/2010
TSDF EPA ID:	NJD002200046
Transporter EPA ID:	NYD006982359
Transporter 2 EPA ID:	Not reported
Transporter 3 EPA ID:	Not reported
Transporter 4 EPA ID:	Not reported
Transporter 5 EPA ID:	Not reported
Transporter 6 EPA ID:	Not reported
Transporter 7 EPA ID:	Not reported
Transporter 8 EPA ID:	Not reported
Transporter 9 EPA ID:	Not reported
Transporter 10 EPA ID:	Not reported
Date Trans1 Transported Waste:	06/03/2010
Date Trans2 Transported Waste:	Not reported
Date Trans3 Transported Waste:	Not reported
Date Trans4 Transported Waste:	Not reported
Date Trans5 Transported Waste:	Not reported
Date Trans6 Transported Waste:	Not reported
Date Trans7 Transported Waste:	Not reported
Date Trans8 Transported Waste:	Not reported
Date Trans9 Transported Waste:	Not reported
Date Trans10 Transported Waste:	Not reported
Date TSDF Received Waste:	06/03/2010

CON EDISON (Continued) **1014398429**

TSDF EPA Facility Name:	Not reported
QTY Units:	Not reported
Transporter SEQ ID:	Not reported
Transporter-1 Date:	Not reported
Waste SEQ ID:	Not reported
Waste Type Code 2:	Not reported
Waste Type Code 3:	Not reported
Waste Type Code 4:	Not reported
Waste Type Code 5:	Not reported
Waste Type Code 6:	Not reported
Date Accepted:	Not reported
Manifest Discrepancy Type:	Not reported
Data Entry Number:	Not reported
Was Load Rejected:	NEW YORK, NY 10003
Reason Load Was Rejected:	Not reported

Waste:

Manifest Year:	Not reported
Waste Code:	D008
Hand Code:	H111
Quantity:	210 P

NY MANIFEST:

Name:	CONSOLIDATED EDISON
Address:	237 MAMARONECK AVE S OF MAPLE
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004207829
Facility Status:	Not reported
Location Address 1:	F/O 271 E HOUSTON ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	NEW YORK
Location State:	NY
Location Zip:	10002
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004207829
Mailing Name:	CONSOLIDATED EDISON
Mailing Contact:	THOMAS TEELING
Mailing Address 1:	4 IRVING PL RM 828
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2124603770

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported

CON EDISON (Continued) **1014398429**

seq:	Not reported
Year:	Not reported
Trans1 State ID:	NYD006982359
Trans2 State ID:	Not reported
Generator Ship Date:	06/03/2010
Trans1 Recv Date:	06/03/2010
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	06/03/2010
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYP004207829
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	NJD002200046
TSDF ID 2:	Not reported
Manifest Tracking Number:	007020821JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	Y
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H111
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	210
Units:	P - Pounds
Number of Containers:	100
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AG290 **CON EDISON SERVICE BOX: 1810** **RCRA NonGen / NLR** **1016963902**
NE **133 MAMARONECK AVE IN FRONT OF** **NY MANIFEST** **NYP004368668**
1/8-1/4 **WHITE PLAINS, NY 10610**
0.248 mi.
1308 ft. **Site 25 of 26 in cluster AG**

Relative: **Higher**
Actual: **223 ft.**

RCRA NonGen / NLR:

Date Form Received by Agency:	2013-11-01 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 1810
Handler Address:	133 MAMARONECK AVE IN FRONT OF
Handler City,State,Zip:	WHITE PLAINS, NY 10610

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

EPA ID:	NYP004368668
Contact Name:	THOMAS TEELING
Contact Address:	Not reported
Contact City,State,Zip:	Not reported
Contact Telephone:	212-460-3770
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	SENIOR SCIENTIST
EPA Region:	02
Land Type:	Private
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R2
Mailing Address:	IRVING PL, 15TH FL NE
Mailing City,State,Zip:	NEW YORK, NY 10003
Owner Name:	Not reported
Owner Type:	Not reported
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported
Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2014-07-01 11:43:40.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Historic Generators:

Receive Date:	2013-10-01 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 1810
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

Receive Date:	2013-11-01 00:00:00.0
Handler Name:	CON EDISON SERVICE BOX: 1810
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

Evaluation Action Summary:
Evaluations: No Evaluations Found

NY MANIFEST:
Name: CON EDISON
Address: 133 MAMARONECK AVE IN FRONT OF
City,State,Zip: WHITE PLAINS, NY 10610
Country: USA
EPA ID: NYP004368668
Facility Status: Not reported
Location Address 1: MAMARONECK AVE & MAMARONECK PL
Code: BP
Location Address 2: SB 1810
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: Not reported
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP004368668
Mailing Name: CON EDISON
Mailing Contact: CON EDISON
Mailing Address 1: 4 IRVING PL 15TH FL
Mailing Address 2: Not reported
Mailing City: NEW YORK
Mailing State: NY
Mailing Zip: 10003
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 2124603770

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NYD006982359
Trans2 State ID: Not reported
Generator Ship Date: 10/01/2013
Trans1 Recv Date: 10/01/2013
Trans2 Recv Date: Not reported
TSD Site Recv Date: 10/02/2013
Part A Recv Date: Not reported
Part B Recv Date: Not reported
Generator EPA ID: NYP004368668
Trans1 EPA ID: Not reported
Trans2 EPA ID: Not reported
TSDF ID 1: NJD002200046
TSDF ID 2: Not reported
Manifest Tracking Number: 011694655JJK
Import Indicator: N
Export Indicator: N
Discr Quantity Indicator: N
Discr Type Indicator: N

CON EDISON SERVICE BOX: 1810 (Continued) **1016963902**

Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	100
Units:	P - Pounds
Number of Containers:	1
Container Type:	TT - Cargo tank, tank trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AL291 **YMCA OF CENTRAL & NORTHERN WESTCHESTER** **NY CBS AST** **U000378191**
East **250 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.248 mi.
1311 ft. **Site 1 of 5 in cluster AL**

Relative: **Higher**

Actual: **235 ft.**

CBS AST:

CBS Number:	3-000313
ICS Number:	Not reported
PBS Number:	Not reported
MOSF Number:	Not reported
SPDES Number:	Not reported
Facility Status:	IN SERVICE
Facility Type:	I
Telephone:	(914) 949-8030
Facility Town:	WHITE PLAINS (C)
Region:	STATE
Expiration Date:	06/03/2000
Total Capacity of All Active Tanks(gal):	0
Operator:	RICHARD GEHRUNG
Emergency Contact:	RICHARD GEHRUNG
Emergency Phone:	(914) 949-8030
Owner Name:	YMCA OF CENTRAL & NORTHERN WESTCHESTER
Owner Address:	250 MAMARONECK AVENUE
Owner City,St,Zip:	WHITE PLAINS, NY 10605
Owner Telephone:	(914) 949-8030
Owner Type:	Corporate/Commercial
Owner Sub Type:	Not reported
Mail Name:	YMCA OF CENTRAL & NORTHERN WESTCHESTER
Mail Contact Addr:	250 MAMARONECK AVENUE
Mail Contact Addr2:	Not reported

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **U000378191**

Mail Contact Contact:	FRED P. TOOT, VICE PRESIDENT
Mail Contact City,St,Zip:	WHITE PLAINS, NY 10605
Mail Phone:	(914) 949-8030
Tank Id:	001
CAS Number:	7681529
Federal ID:	Not reported
Tank Status:	0
Install Date:	09/92
Tank Closed:	00/00
Capacity (Gal):	500
Chemical:	Sodium hypochlorite
Tank Location:	Indoors, Aboveground
Tank Type:	Fiberglass reinforced plastic [FRP]
Total Tanks:	0
Tank Secret:	False
Tank Secondary Containment:	None
Tank Error Status:	No Missing Data
Date Entered:	05/27/1994
Certified Date:	03/13/1998
Substance:	Single Hazardous Substance on DEC List
Internal Protection:	None
External Protection:	None
Pipe Location:	Aboveground
Pipe Type:	Double Walled Fiberglass
Pipe Internal:	None
Pipe External:	None
Pipe Flag:	None
Leak Detection:	None
Overfill Protection:	None
Haz Percent:	15
Last Test:	Not reported
Due Date:	Not reported
SWIS Code:	5517
Lat/Long:	Not reported
Is Updated:	False
Renew Date:	Not reported
Is It There:	False
Delinquent:	False
Date Expired:	Not reported
Owner Mark:	1
Certificate Needs to be Printed:	False
Fiscal Amt for Registration Fee Correct:	True
Renewal Has Been Printed for Facility:	True
Pre-Printed Renewal App Last Printed:	03/02/1998

AL292 **WHITE PLAINS YMCA** **NY LTANKS** **S117395185**
East **250 MAMARONECK AVE** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.248 mi.
1311 ft. **Site 2 of 5 in cluster AL**

Relative: **Higher**
Actual: **235 ft.**

LTANKS:

Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1410006 / 2015-12-08
Facility ID:	1410006

WHITE PLAINS YMCA (Continued) **S117395185**

Site ID:	503665
Spill Date:	2015-01-12
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2015-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-01-12
Spill Record Last Update:	2016-01-14
Spiller Name:	THOMAS HAY
Spiller Company:	WHITE PLAINS YMCA
Spiller Address:	250 MAMARONECK RD
Spiller County:	999
Spiller Contact:	THOMAS HAY
Spiller Phone:	(914) 949-8030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	323652
DEC Memo:	"1-12-15 Spoke with Chris, WCDOH. See below. They will be handling. jm Joe, This is a PBS site 3-074071 TTF 12K (AST with 10% or more below grade) Wayne- please follow up on the TTF. Chris Christopher J. Lalak MS Radiological and Chemical Analyst Westchester County Department of Health 145 Huguenot Street - 7th Floor New Rochelle, NY 10801 CJL1@westchestergov.com (914) 224-7649 12-8-15 tank removed and spill under 15-05596; Close this spill before TCR review RDB"
Remarks:	"unknown retest."

All Materials:

Site ID:	503665
Operable Unit ID:	1253015
Operable Unit:	01
Material ID:	2255190
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AL293 **YMCA OF CENTRAL & NORTHERN WESTCHESTER** **NY CBS** **S105058672**
East **250 MAMARONECK AVENUE** **NY Spills** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.248 mi.
1311 ft. **Site 3 of 5 in cluster AL**

Relative:
Higher

Actual:
235 ft.

CBS:

Name:	YMCA OF CENTRAL & NORTHERN WESTCHESTER
Address:	250 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10605
CBS Number:	3-000313
Program Type:	CBS
Facility Status:	Unregulated/Closed
Expiration Date:	Not reported
Dec Region:	3
UTMX:	603883.39681
UTMY:	4542444.03426

SPILLS:

Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1505596 / 2015-12-08
Facility ID:	1505596
Facility Type:	ER
DER Facility ID:	323652
Site ID:	512969
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	2015-08-25
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2015-08-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2015-08-25
Spill Record Last Update:	2018-01-18
Spiller Name:	THOMAS HAY
Spiller Company:	WHITE PLAINS YMCA
Spiller Address:	250 MAMARONECK AVE
Spiller Company:	999
Contact Name:	THOMAS HAY
DEC Memo:	"8/25/15 - The tank is being prepare to be removed. The Westchester County DOH will be on site on 8/26. KAB"
Remarks:	"overburdened soils are impacted, c/u pending"

All Materials:

Site ID:	512969
Operable Unit ID:	1262211

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Operable Unit:	01
Material ID:	2265725
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0609639 / 2007-01-10
Facility ID:	0609639
Facility Type:	ER
DER Facility ID:	323652
Site ID:	373926
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2006-11-22
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-11-22
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2006-11-22
Spill Record Last Update:	2007-01-10
Spiller Name:	HEDI RAHIMI FACILITY DIRECTOR
Spiller Company:	WHITE PLAINS YMCA
Spiller Address:	250 MAMARONECK AVE
Spiller Company:	999
Contact Name:	DWAYNE MONACO
DEC Memo:	"11/22/06 Two valves feeding oil to the boiler failed, resulting in the constant pumping of oil into the boiler. The boiler failed and oil eventually drained out of the bottom of the boiler and flooded a large section of the boiler room floor. Oil entered a drainage pump pit but no evidence of a discharge of oil into the storm drain system was observed. YMCA hired Northeast Environmental for the spill cleanup. NE will vac up the oil and decon the floor and the pit. TG"
Remarks:	"BOILER MALFUNCTION, AND CALLER ENROUTE TO CLEAN UP: SOME DID GO INTO DRAINAGE:"

All Materials:

Site ID:	373926
Operable Unit ID:	1131616

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Operable Unit:	01
Material ID:	2121327
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1709377 / Not Reported
Facility ID:	1709377
Facility Type:	ER
DER Facility ID:	323652
Site ID:	565820
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B1
SWIS:	6017
Spill Date:	2018-01-12
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2018-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2018-01-12
Spill Record Last Update:	2020-07-01
Spiller Name:	TOM HAY
Spiller Company:	YMCA
Spiller Address:	250 MAMARONECK AVE
Spiller Company:	999
Contact Name:	CYNTHIA RUBINA
DEC Memo:	"1/12/18 US Tank was called to try to find leaking UST at YMCA Oil was coming into the basement through the back wall. No evidence of buried tank found. A tank was removed at the front of the property years ago. Sheen was noticed at the back of the property coming up from cracks in the asphalt, believed to be coming from a retaining wall. Other side of wall is condos / townhouses. US Tank told YMCA to call Northeast, their usual cleanup contractor, to put booms in place in storm drain at parking lot, sump pump, and cubby of basement to prevent further oil impact. Rain is causing oil to sheen on parking lot, making it easy to trace path from property behind them. Spoke to Tom @ YMCA - confirmed that Northeast Env. was called, did boom the sump in the basement, the storm drain at back of parking lot, and the

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

pipe cubby in basement were evidence of residual oil was found. Northeast would like to speak to DEC for advice on how to proceed. ga 01/17/18 Received a report prepared by US Tank Tech describing their effort to locate a tank on the property. No tank was located. Report in DecDocs. TG 02/07/18 Inspected the site on a rainy day. No sign of oil observed at the time of the inspection. TG 04/16/18 YMCA hired HydroEnvironmental Solutions to conduct an investigation both outside in the rear parking lot and inside the basement to try to determine where the oil is originating. All outside soil boring locations were clean, eliminating the idea that there is an offsite source. Report concludes that the oil is from the numerous past spills that have occurred in their basement. See report in DecDocs. TG 09/25/18 Spoke to Tom Hay. He stated that the building may be sold in the near future. GW in the basement is being pumped through an oil water separator before being discharged. Little if any oil is accumulating in the separator according to Tom. TG 07/01/20 The YMCA had not funds to do any type of cleanup and was sold to a developer. It is anticipated that the cleanup will be performed once the building is razed. TG"

Remarks: "leaking at base of wall - in basement of YMCA unknown were it is coming from - off site clean up pending crew."

All Materials:

Site ID:	565820
Operable Unit ID:	1313761
Operable Unit:	01
Material ID:	2321241
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1709377 / Not Reported
Facility ID:	1709377
Facility Type:	ER
DER Facility ID:	323652
Site ID:	565820
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B1
SWIS:	6017
Spill Date:	2018-01-12
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2018-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2018-01-12
Spill Record Last Update:	2020-07-01
Spiller Name:	TOM HAY
Spiller Company:	YMCA
Spiller Address:	250 MAMARONECK AVE
Spiller Company:	999
Contact Name:	TOM HAYES
DEC Memo:	"1/12/18 US Tank was called to try to find leaking UST at YMCA Oil was coming into the basement through the back wall. No evidence of buried tank found. A tank was removed at the front of the property years ago. Sheen was noticed at the back of the property coming up from cracks in the asphalt, believed to be coming from a retaining wall. Other side of wall is condos / townhouses. US Tank told YMCA to call Northeast, their usual cleanup contractor, to put booms in place in storm drain at parking lot, sump pump, and cubby of basement to prevent further oil impact. Rain is causing oil to sheen on parking lot, making it easy to trace path from property behind them. Spoke to Tom @ YMCA - confirmed that Northeast Env. was called, did boom the sump in the basement, the storm drain at back of parking lot, and the pipe cubby in basement were evidence of residual oil was found. Northeast would like to speak to DEC for advice on how to proceed. ga 01/17/18 Received a report prepared by US Tank Tech describing their effort to locate a tank on the property. No tank was located. Report in DecDocs. TG 02/07/18 Inspected the site on a rainy day. No sign of oil observed at the time of the inspection. TG 04/16/18 YMCA hired HydroEnvironmental Solutions to conduct an investigation both outside in the rear parking lot and inside the basement to try to determine where the oil is originating. All outside soil boring locations were clean, eliminating the idea that there is an offsite source. Report concludes that the oil is from the numerous past spills that have occurred in their basement. See report in DecDocs. TG 09/25/18 Spoke to Tom Hay. He stated that the building may be sold in the near future. GW in the basement is being pumped through an oil water separator before being discharged. Little if any oil is accumulating in the separator according to Tom. TG 07/01/20 The YMCA had not funds to do any type of cleanup and was sold to a developer. It is anticipated that the cleanup will be performed once the building is razed. TG"
Remarks:	"leaking at base of wall - in basement of YMCA unknown were it is coming from - off site clean up pending crew."

All Materials:

Site ID:	565820
Operable Unit ID:	1313761
Operable Unit:	01
Material ID:	2321241
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Oxygenate:	Not reported
Name:	WHITE PLAINS YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1709377 / Not Reported
Facility ID:	1709377
Facility Type:	ER
DER Facility ID:	323652
Site ID:	565820
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B1
SWIS:	6017
Spill Date:	2018-01-12
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2018-01-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Tank Tester
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2018-01-12
Spill Record Last Update:	2020-07-01
Spiller Name:	TOM HAY
Spiller Company:	YMCA
Spiller Address:	250 MAMARONECK AVE
Spiller Company:	999
Contact Name:	TOM HAYES
DEC Memo:	"1/12/18 US Tank was called to try to find leaking UST at YMCA Oil was coming into the basement through the back wall. No evidence of buried tank found. A tank was removed at the front of the property years ago. Sheen was noticed at the back of the property coming up from cracks in the asphalt, believed to be coming from a retaining wall. Other side of wall is condos / townhouses. US Tank told YMCA to call Northeast, their usual cleanup contractor, to put booms in place in storm drain at parking lot, sump pump, and cubby of basement to prevent further oil impact. Rain is causing oil to sheen on parking lot, making it easy to trace path from property behind them. Spoke to Tom @ YMCA - confirmed that Northeast Env. was called, did boom the sump in the basement, the storm drain at back of parking lot, and the pipe cubby in basement were evidence of residual oil was found. Northeast would like to speak to DEC for advice on how to proceed. ga 01/17/18 Received a report prepared by US Tank Tech describing their effort to locate a tank on the property. No tank was located. Report in DecDocs. TG 02/07/18 Inspected the site on a rainy day. No sign of oil observed at the time of the inspection. TG 04/16/18 YMCA hired HydroEnvironmental Solutions to conduct an investigation both outside in the rear parking lot and inside the basement to try to determine where the oil is originating. All outside soil boring locations were

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

clean, eliminating the idea that there is an offsite source. Report concludes that the oil is from the numerous past spills that have occurred in their basement. See report in DecDocs. TG 09/25/18 Spoke to Tom Hay. He stated that the building may be sold in the near future. GW in the basement is being pumped through an oil water separator before being discharged. Little if any oil is accumulating in the separator according to Tom. TG 07/01/20 The YMCA had not funds to do any type of cleanup and was sold to a developer. It is anticipated that the cleanup will be performed once the building is razed. TG"

Remarks: "leaking at base of wall - in basement of YMCA unknown were it is coming from - off site clean up pending crew."

All Materials:

Site ID:	565820
Operable Unit ID:	1313761
Operable Unit:	01
Material ID:	2321241
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0103636 / 2002-02-19
Facility ID:	0103636
Facility Type:	ER
DER Facility ID:	323652
Site ID:	111311
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2001-07-05
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-07-05
CID:	201
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Fire Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-05
Spill Record Last Update:	2002-04-29
Spiller Name:	HEDI RAHIMI
Spiller Company:	YMCA

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Spiller Address:	250 MAMARONECK AV
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCDOH 07/05/2001 GAUGE BROKE IN BOILER ROOM. FIRE DEPT. ESTIMATES 30 GALLONS CONTAINED ON FLOOR AND 10 GALLONS INTO FLOOR DRAIN. YMCA HAS CONTACTED CASTLE OIL FOR CLEANUP. YMCA STATES FLOOR DRAIN GOES TO SANITARY SEWER. ODORS EVIDENT IN POOL AREA; POOL AREA; POOL AREA IS CLOSED AND YMCA TO VENT WITH FANS. CONTACTED WCDOH - STEFAN GOREAU. WCDOH TO FOLLOW UP DUE TO ODOR PROBLEM & CHECK CLEANUP. 02/19/2002 LETTER SENT TO YMCA BY S. GOREAU (WCDOH); SPILL CLEANUP BY CONTRACTOR WAS SATISFACTORY. WCDOH REQUIRES NO FURTHER ACTION."
Remarks:	"VALVE CAUSED SPILL. FLOOR HAS A LARGE POOL OF OIL. SOME OF THE OIL WENT INTO THE FLOOR DRAIN. THE DRAIN HAS BEEN PLUGED SO NO MORE PRODUCT WILL GO INTO DRAIN."

All Materials:

Site ID:	111311
Operable Unit ID:	840246
Operable Unit:	01
Material ID:	535707
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9009604 / 1990-12-14
Facility ID:	9009604
Facility Type:	ER
DER Facility ID:	323652
Site ID:	315712
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1990-12-04
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-12-04
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-12-14

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Spill Record Last Update:	1991-01-03
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"SPOKE WITH MR.CAREY SPILL MOSTLY ON PAVEMENT SOME ENTERED STORM DRAIN CASTLE OIL CALLED AE EASTMAN TO CLEAN UP MR.CAREY TO CALL BACK WITH UPDATE TODD GHIOSAY INSPECTED"

All Materials:

Site ID:	315712
Operable Unit ID:	949993
Operable Unit:	01
Material ID:	429813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9010124 / 1990-12-20
Facility ID:	9010124
Facility Type:	ER
DER Facility ID:	323652
Site ID:	315713
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1990-12-18
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1990-12-18
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE.

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "BLOCKAGE IN LINE AND SPILL CAME OUT FILL ONTO PAVEMENT CASTLE OIL SENDING CLEAN UP CREW"

All Materials:
Site ID: 315713
Operable Unit ID: 950603
Operable Unit: 01
Material ID: 430294
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: YMCA
Address: 250 MAMARONECK AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9010653 / 1991-05-01
Facility ID: 9010653
Facility Type: ER
DER Facility ID: 323652
Site ID: 315714
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: Not reported
SWIS: 6017
Spill Date: 1991-01-05
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1991-01-05
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: 1953-06-18
Cleanup Meets Std: True
Last Inspection: 1990-01-05
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-01-10
Spill Record Last Update: 1991-05-02
Spiller Name: Not reported
Spiller Company: CASTLE OIL CO.
Spiller Address: 290 LOCUST AVE.
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 05/01/91: SPILL CAUSE SIMILAR TO SPILL NUMBER 90-10124. SUPPLY LINE BLOCKAGE. LINE HAS BEEN REPAIRED. FACILITY WAS INSTRUCTED

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

TO TEST THE SYSTEM. TEST RESULTS INDICATE FAILURE. SEE SPILL90-13259. "

Remarks: "SPILL HAS BEEN CLEANED UP WITH SPEEDI-DRY INSPECTION WILL BE PERFORMEDTO VERIFY CLEAN UP"

All Materials:

Site ID:	315714
Operable Unit ID:	950901
Operable Unit:	01
Material ID:	430791
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	YMCA
Address:	250 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9204628 / 1997-11-07
Facility ID:	9204628
Facility Type:	ER
DER Facility ID:	323652
Site ID:	315715
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C3
SWIS:	6017
Spill Date:	1992-07-22
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-07-22
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-07-23
Spill Record Last Update:	1997-12-01
Spiller Name:	Not reported
Spiller Company:	CASTLE OIL CO.
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CALLER SUSPECTS DRIVER MISREAD TANK STICK READINGS OIL WENT TO PAVED PARKING LOT DRIVER APPLIED SPEEDI-DRI AND SPILL TEAM ENROUTE TO COMPLETE CLEAN UP"

YMCA OF CENTRAL & NORTHERN WESTCHESTER (Continued) **S105058672**

All Materials:

Site ID:	315715
Operable Unit ID:	968275
Operable Unit:	01
Material ID:	412329
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Click this hyperlink while viewing on your computer to access additional NY SPILL: detail in the EDR Site Report.

AL294 **WHITE PLAINS FAMILY YMCA** **NY UST** **U004240672**
East **250 MAMARONECK AVENUE** **N/A**
1/8-1/4 **WHITE PLAINS, NY 10605**
0.248 mi.
1311 ft. **Site 4 of 5 in cluster AL**

Relative:
Higher

Actual:
235 ft.

WESTCHESTER CO. UST:

Name:	WHITE PLAINS FAMILY YMCA
Address:	250 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10605-1398
Id/Status:	3-074071 / Unregulated
Operator Name:	Francisco Arizmendi
Owner Name:	YMCA of Central & Northern Westchester
Owner Street:	250 Mamaroneck Avenue
Owner Address2:	Not reported
Owner City:	White Plains
Owner State:	NY
Owner Zipcode:	10605-1398
GDS Number:	Not reported
Tank Number:	1
Status:	3. Closed - Removed
Capacity:	12000
Product Stored:	0001. #2 Fuel Oil
Product Stored Percent:	100
Tank Leak Detection:	0. None
Date Installation:	01/01/1970
Date Perm Closure:	08/26/2015
Tank Location:	5. Underground including vaulted with no access for inspection
Tank Type:	1. Steel/Carbon steel/Iron
Tank Internal Protection:	0. None
Tank External Protection:	0. None
Tank Secondary Containment:	0. None
Piping Location:	2. Underground/on Ground
Piping Type:	1. Steel/Carbon/ Steel/Iron
Piping External Protection:	0. None
Overfill Prevention:	0. None
Piping Secondary Containment:	0. None
Spill Prevention:	1. Catch Basin

WHITE PLAINS FAMILY YMCA (Continued) **U004240672**

Dispenser: 3. Gravity

AE295 **IRVINGTON** **NY LTANKS** **S100139823**
WNW **IRVINGTON** **N/A**
1/8-1/4 **WHITE PLAINS, NY**
0.249 mi.
1313 ft. **Site 4 of 4 in cluster AE**

Relative: **Lower**
Actual: **208 ft.**

LTANKS:

Name:	IRVINGTON
Address:	IRVINGTON
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8708811 / 1988-03-03
Facility ID:	8708811
Site ID:	309074
Spill Date:	1988-01-15
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D3
Cleanup Ceased:	1988-03-03
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-01-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-01-28
Spill Record Last Update:	1988-09-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	249617
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : MAY HAVE ALSO BEEN REPORTED AS SPILL # 879230, WHICH HAS NOT LOGED ONTO SYSTEM. NOTE 879230 SHOWES DIFFERENT ADDRESS. V.MC.2-10-88. 03/03/88: TANK PASSED RETEST. N.F.A. L.R. "
Remarks:	"DON REGISTERED TANK WOULD HAVE TO CALL DPW FOR FURTHER INFO. 1-15 DPW NO ANSWER 1-16 DPW TANK TEST LEFT MESSAGE. 1-19 NO ANSWER"

All TTF:

Facility ID:	8708811
Spill Number:	8708811
Spill Tank Test:	1533010
Site ID:	309074
Tank Number:	Not reported
Tank Size:	0
Material:	0009

IRVINGTON (Continued) **S100139823**

EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	309074
Operable Unit ID:	913482
Operable Unit:	01
Material ID:	464176
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

296
South
1/4-1/2
0.251 mi.
1324 ft.

PRIVATE RESIDENCE **NY LTANKS** **S110611340**
29 CAMBRIDGE AVE **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
274 ft.

LTANKS:

Name:	PRIVATE RESIDENCE
Address:	29 CAMBRIDGE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1007882 / 2010-12-17
Facility ID:	1007882
Site ID:	441331
Spill Date:	2010-10-25
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-10-25
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-10-25

PRIVATE RESIDENCE (Continued) **S110611340**

Spill Record Last Update:	2010-12-17
Spiller Name:	DIANNE MCGOVERN
Spiller Company:	DIANNE MCGOVERN
Spiller Address:	29 CAMBRIDGE AVE
Spiller County:	999
Spiller Contact:	DON PYATT
Spiller Phone:	(973) 390-6675
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	396359
DEC Memo:	"10-26-10 Tank to be retested. jc 12/17/10: Tank removed by HVEC. No evidence of leak or contamination was found. Report to be entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"550 gallon tank failed tank test. Tank will be repaired and retested."

All Materials:

Site ID:	441331
Operable Unit ID:	1191896
Operable Unit:	01
Material ID:	2187101
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

297
SSE
1/4-1/2
0.251 mi.
1327 ft.

PRIVATE RESIDENCE
36 OAKWOOD AVE
WHITE PLAINS, NY

NY LTANKS **S112810136**
N/A

Relative:
Higher

Actual:
262 ft.

LTANKS:

Name:	PRIVATE RESIDENCE
Address:	36 OAKWOOD AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1212813 / 2013-02-07
Facility ID:	1212813
Site ID:	475969
Spill Date:	2012-11-29
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-11-30
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

PRIVATE RESIDENCE (Continued) **S112810136**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-30
Spill Record Last Update:	2013-02-14
Spiller Name:	CAMILLA CHACHRA
Spiller Company:	PRIVATE RESD
Spiller Address:	36 OAKWOOD AVE
Spiller County:	999
Spiller Contact:	CAMILLA CHACHRA
Spiller Phone:	(914) 588-2349
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	431288
DEC Memo:	"11/30/ - To repair and retest. KAB 2/6/13: Tank reportedly passed a retest. Property owner representative states they received a copy of the report from ATS, stating it would be sent to DEC as well. DEC has not yet received a copy. She will forward a copy of the report. jod 02/05/13 DEC has received a report prepared by Absolute Tank Testing Inc certifying that they tested the tank and that the tank passed a tank tighness test. NFA. TG"
Remarks:	"Test failure due to fill pipe problem. Repair and retest will be schedule."

All Materials:

Site ID:	475969
Operable Unit ID:	1225810
Operable Unit:	01
Material ID:	2223133
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AM298 **SILVERMAN REALITY** **NY LTANKS** **S104950814**
NE **110 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.255 mi.
1344 ft. **Site 1 of 4 in cluster AM**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	SILVERMAN REALITY
Address:	110 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0011270 / 2003-01-22
Facility ID:	0011270
Site ID:	308222
Spill Date:	2001-01-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported

SILVERMAN REALITY (Continued) **S104950814**

SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2001-01-16
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-01-16
Spill Record Last Update:	2003-01-28
Spiller Name:	UNKNOWN
Spiller Company:	SILVERMAN REALITY
Spiller Address:	110 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	TARRICONE OIL
Spiller Phone:	(914) 693-1132
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	248921
DEC Memo:	""
Remarks:	"TANK TEST FAILURE AT ABOVE LOCATION PERFORMED AT REQUEST OF OIL COMPANY. OIL COMPANY HAS BEEN ADVISED OF RESULTS. NO CALL BACK REQUESTED."

All TTF:

Facility ID:	0011270
Spill Number:	0011270
Spill Tank Test:	1526050
Site ID:	308222
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	308222
Operable Unit ID:	832660
Operable Unit:	01
Material ID:	541592
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

SILVERMAN REALITY (Continued) **S104950814**

Units: G
Recovered: .00
Oxygenate: Not reported

AL299 **YMCA** **NY LTANKS** **S100166488**
East **260 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.255 mi.
1345 ft. **Site 5 of 5 in cluster AL**

Relative: **Higher**
Actual: **236 ft.**

LTANKS:
Name: YMCA
Address: 260 MAMARONECK AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9013259 / 2002-03-23
Facility ID: 9013259
Site ID: 263885
Spill Date: 1991-03-28
Spill Cause: Tank Test Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1991-03-28
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1991-04-01
Spill Record Last Update: 2002-04-29
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 215095
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 05/01/91: MAY 1, FRED TOOT DIRECTOR STILL ATTEMPTING TO GET BIDS TO EXCAVATE THE LINES TO RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST. 03/23/2002 LETTER SENT TO TEAM ENV. CONSULTANTS BY T. GHIOSAY; BASED ON 3/13/02 CORRESPONDENCE, NO FURTHER ACTION REQUIRED AT THIS TIME. SPILL NUMBER CLOSED."
Remarks: "E I R TODAY PETRO-TITE -.126"

All TTF:
Facility ID: 9013259
Spill Number: 9013259

YMCA (Continued) **S100166488**

Spill Tank Test:	1538385
Site ID:	263885
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	263885
Operable Unit ID:	953354
Operable Unit:	01
Material ID:	426138
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AG300 **OFFICE BLDG** **NY LTANKS** **S103558663**
NE **171 EAST POST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.260 mi.
1374 ft. **Site 26 of 26 in cluster AG**

Relative:
Higher

Actual:
223 ft.

LTANKS:

Name:	OFFICE BLDG
Address:	171 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9811157 / 2004-03-30
Facility ID:	9811157
Site ID:	293961
Spill Date:	1998-12-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-12-04
CID:	252
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

OFFICE BLDG (Continued) **S103558663**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-12-04
Spill Record Last Update:	2004-03-30
Spiller Name:	BILL CHRISTOPHER
Spiller Company:	OFFICE BLDG
Spiller Address:	171 EAST POST RD
Spiller County:	001
Spiller Contact:	BILL CHRISTOPHER
Spiller Phone:	(203) 972-0231
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	237886
DEC Memo:	""
Remarks:	"TANK TO BE ISOLATED AND RE-TESTED "

All TTF:

Facility ID:	9811157
Spill Number:	9811157
Spill Tank Test:	1546601
Site ID:	293961
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	293961
Operable Unit ID:	1068550
Operable Unit:	01
Material ID:	315008
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI301 **WHITE PLAINS HONDA** **NY LTANKS** **S102675103**
WNW **31 WESTMPORELAND AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.261 mi.
1379 ft. **Site 4 of 5 in cluster AI**

Relative: **Lower**

Actual: **209 ft.**

LTANKS:

Name:	WHITE PLAINS HONDA
Address:	31 WESTMPORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9514655 / 1996-02-15
Facility ID:	9514655
Site ID:	224484
Spill Date:	1996-02-15
Spill Cause:	Tank Overfill
Spill Source:	Unknown
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-02-15
CID:	252
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-02-15
Spill Record Last Update:	1996-02-23
Spiller Name:	RICK BOLOGNA
Spiller Company:	WESTMORE FUELS
Spiller Address:	86 NO WATER STREET
Spiller County:	001
Spiller Contact:	MR J CAREAGA
Spiller Phone:	(914) 948-3305
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	185537
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"tank over fill caused spill at business-spill has been cleaned up from pavement"

All Materials:

Site ID:	224484
Operable Unit ID:	1029198
Operable Unit:	01
Material ID:	354785
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	6.00
Units:	G
Recovered:	6.00
Oxygenate:	Not reported

AH302 **MICHAEL E LAND OFFICE BLD** **NY LTANKS** **S102151229**
NNE **148 MARTINE AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.262 mi.
1386 ft. **Site 2 of 4 in cluster AH**

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	MICHILIN MOTOR POOL
Address:	148 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0301426 / 2003-05-08
Facility ID:	0301426
Site ID:	214706
Spill Date:	2003-05-08
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	VPMCCABE
Referred To:	Not reported
Reported to Dept:	2003-05-08
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-05-08
Spill Record Last Update:	2003-05-12
Spiller Name:	CALLER
Spiller Company:	KENN ORICCHIO
Spiller Address:	500 KINGSLAND
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 995-3905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	153551
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MCCABE "
Remarks:	"DRIVER OVERFILLED TANK. ALL CLEANED UP"

All Materials:

Site ID:	214706
Operable Unit ID:	867817
Operable Unit:	01
Material ID:	505918
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Name:	MICHAEL E LAND OFFICE BLD
Address:	148 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0503295 / 2005-09-26
Facility ID:	0503295
Site ID:	347878
Spill Date:	2005-06-17
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCDOH
Reported to Dept:	2005-06-17
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-06-17
Spill Record Last Update:	2005-09-26
Spiller Name:	LOU MASTRO
Spiller Company:	MICHAEL E LAND OFFICE BLD
Spiller Address:	148 MARTINE AVE
Spiller County:	001
Spiller Contact:	LOU MASTRO
Spiller Phone:	(845) 565-9600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	153551
DEC Memo:	"09/26/05: Letter to J. Varmon, County of Westchester DPW, from C. Lalak, WCDOH, dated 13Sep2005. Spill closure report, reporting requirement and as-built plans received. Department still needs a copy of the passing tightness test. Submit results asap. No further remdiation required regarding this spill number."
Remarks:	"Located on the court st side of the building."

All Materials:

Site ID:	347878
Operable Unit ID:	1105557
Operable Unit:	01
Material ID:	1521369
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WESTCHESTER CO DPW
Address:	148 MARTINE AVE

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0109874 / 2002-01-14
Facility ID:	0109874
Site ID:	126439
Spill Date:	2002-01-11
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6018
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-01-12
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2002-01-12
Spill Record Last Update:	2003-09-02
Spiller Name:	SAME
Spiller Company:	WESTCHESTER CO DPW
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	MIKE CIRCOSTA
Spiller Phone:	(914) 995-3905
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	304255
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"LINE TEST FAILURE AT ABOVE LOCATION. SOME MATERIAL DID LEAK AND WAS RECOVERED IN CONTAINMENT AREA. LINE TO BE REPLACED."

All TTF:

Facility ID:	0109874
Spill Number:	0109874
Spill Tank Test:	1526811
Site ID:	126439
Tank Number:	5
Tank Size:	3000
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	01
Test Method 2:	Petro-Tite/Petro Comp
Leak Rate:	.10
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Site ID:	126439
Operable Unit ID:	848218
Operable Unit:	01
Material ID:	552679
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	MICHAELIAN OFFICE BLDG
Address:	148 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9103040 / 1991-06-18
Facility ID:	9103040
Facility Type:	ER
DER Facility ID:	304255
Site ID:	126441
DEC Region:	3
Spill Cause:	Housekeeping
Spill Class:	D3
SWIS:	6018
Spill Date:	1991-06-12
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-06-12
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Citizen
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-06-18
Spill Record Last Update:	2003-09-02
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FOUND CONTAMINATION WHILE REMOVING TANKS ARBEN CORP. IS PULLING THE TANKS STOCKPILE OF SOIL IS NOT TO DEC REQUIREMENTS LAURI TAYLOR INSTRUCTED THEM TO STOCKPILE ON PLASTIC SOIL STOCKPILE TO BE REMOVED"

All TTF:

Facility ID:	9103040
Spill Number:	9103040

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Spill Tank Test:	1538674
Site ID:	126441
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	126441
Operable Unit ID:	957062
Operable Unit:	01
Material ID:	425507
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	COUNTY OF WESTCHESTER DGS
Address:	148 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0412020 / 2008-12-18
Facility ID:	0412020
Facility Type:	ER
DER Facility ID:	153551
Site ID:	337374
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-02-10
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2005-02-10
CID:	409
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Date Entered In Computer:	2005-02-10
Spill Record Last Update:	2008-12-18
Spiller Name:	UNKNOWN
Spiller Company:	MODEL PERTROLEUM
Spiller Address:	UNKNOWN
Spiller Company:	001
Contact Name:	EDDIE
DEC Memo:	"2/17/05: Letter to John Varmon, Westchester DPW from Karen Magnuson, WCDOH dated 11Feb2005. Details work required. First report due 15Mar2005. 2/17/05: Letter to Al Cirino, Model Transportation, Inc from Karen Magnuson, WCDOH dated 11Feb2005. Tanks must be tightness tested by 18Feb2005. Details work required. First report due 15Mar2005."
Remarks:	"CLEAN UP IS IN PROCESS AND MANAGEMENT ON THE WAY TO LOOK AT LOCATION. LOCATED IN A PAVED PARKING LOT."

All Materials:

Site ID:	337374
Operable Unit ID:	1099339
Operable Unit:	01
Material ID:	579677
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CITY OF WHITE PLAINS
Address:	148 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9202919 / 1992-07-13
Facility ID:	9202919
Facility Type:	ER
DER Facility ID:	153551
Site ID:	183296
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6017
Spill Date:	1992-06-10
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	1992-06-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Tank Truck
Spill Notifier:	Responsible Party
Cleanup Ceased:	1992-07-13
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1992-06-11

MICHAEL E LAND OFFICE BLD (Continued) **S102151229**

Spill Record Last Update:	2005-02-12
Spiller Name:	Not reported
Spiller Company:	IS. TRANSPORTATION
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	""
Remarks:	"SPILL CONTAINED ON PAVEMENT MOST EVAPORATED SPEEDI-DRI WAS APPLIED AND F.D. WASHED AREA MARINE POLLUTION CONTROL ON WAY TO VAC OUT STORM DRAIN VICKI WCHD ON SCENE"

All Materials:

Site ID:	183296
Operable Unit ID:	970249
Operable Unit:	01
Material ID:	554262
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	23.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AI303 **YOUNG COAL & LUMBER SITE** **NY BROWNFIELDS S113492634**
NW **55 BANK STREET** **NY MANIFEST N/A**
1/4-1/2 **WHITE PLAINS, NY 10606**
0.263 mi.
1390 ft. **Site 5 of 5 in cluster AI**

Relative: **Lower**
Actual: **204 ft.**

BROWNFIELDS:

Name:	YOUNG COAL & LUMBER SITE
Address:	55 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Program:	BCP
Site Code:	481411
Acres:	2.24
HW Code:	C360131
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	05/01/2013
Record Updated Date:	07/17/2018
Update By:	DACROSBY
Site Description:	Location: The site is located at 55 Bank Street in White Plains, Westchester County. The site is located in the Central Business District of the City of White Plains on the west side of Bank Street, just south of the intersection of Main Street and Bank Street. To the west is the Metro-North railroad right of way. Bank Street is located along the eastern border, a car dealership is located adjacent to the southern border, and a parking lot for the Bank Street Commons Apartment building is located to the north. Site Features: The site is presently under construction as a commercial/residential building. The site was formerly a 2.24-acre parking lot for the nearby commuter railroad station. The site was used as a parking lot for over 40 years. Current Zoning/Use: The current zoning of the site is Core Business-4 (CB-4). Municipally-operated parking lots and multifamily

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

dwellings, a restricted residential use, are permitted uses in CB-4 zones. Past Uses of the Site: The property was used as a coal and lumber yard starting in 1885. The lumber yard comprised of a mill, several small sheds, coal and lumber storage areas, and railroad spurs. By 1911, the property was being used for manufacturing sashes, blinds and trim, and for the storage of grain, fertilizer, and feed. During the late 1800s and early 1900s, portions of the eastern side were occupied by several residential homes. By 1953, the southeastern corner of the property was improved with a commercial building, while the remaining portions were public parking lots. The commercial building was razed by 1974, and the site has been operated as a parking lot since that time. Site Geology and Hydrogeology: The site is level ground and covered with asphalt. Surface water drains to a storm sewer system that runs to the Bronx River which is about 500 yards to the west. The shallow soil horizon consists of historic fill found at a depth from 1.5 -26 feet below grade. Below the fill, subsurface soils consist of predominantly sands with some silts and gravels. Bedrock was located at 80-120 feet below grade and is believed to by gneiss and schist. Overburden groundwater was encountered at a depth of 28 feet below grade and flows to the south. The Bronx River, which flows to the south, is located about 0.25 mile west of the site. However, the site is located above the current 100 year flood elevation. Site storm water is transported via storm drains to a storm water collection system and discharges to the Bronx River. The Bronx River Parkway is located adjacent to the Bronx River just west of the site.

Env Problem:

Nature and Extent of Contamination: Remediation of the site to track 1 soil cleanup objectives was completed in November 2016. Soil: Remediation is complete. The entire site was excavated to a depth of approximately 26 feet. No surface soils remain. Based on the investigations conducted the primary contaminants of concern in subsurface soils were inorganics (metals) including mercury, copper lead and zinc. These metals were present above the unrestricted soil cleanup objectives. These compounds were present in the fill materials used to grade the site and surrounding areas, and contamination did not migrated from the site to adjacent parcels. These inorganics were not found in on-site groundwater above NYS Groundwater Standards in filtered samples. Aluminum, iron, and sodium were detected above standards in onsite groundwater but are considered to be naturally occurring. Groundwater: Chlorinated volatile organic compounds (CVOCs) were detected in on-site groundwater including tetracholoethylene (PCE) at a maximum level of 13 parts per billion (ppb), and trichloroethene (TCE) at a maximum level of 28 ppb. The groundwater quality standard for both of these compounds is 5 ppb. CVOCs were not detected in the subsurface soil samples collected from the site, the groundwater investigation suggests that the source originates from an off-groundwater source. The site remediation is complete. The site has a basement foundation that includes a vapor barrier and a subsurface parking garage which is ventilated. Because there is a vapor barrier and a ventilated subsurface parking garage a soil vapor intrusion investigation was not conducted.

Health Problem:

People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

process which is similar to the movement of radon gas from the subsurface in to the indoor air of buildings, is referred to as soil vapor intrusion. A vapor barrier has been installed beneath the building foundation to minimize the potential of vapors from entering the building. Additionally, a sub-grade parking garage ventilation system required by building codes will be installed prior to building occupancy to prevent vapors from accumulating in the structure.

Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	5/1/2013 1:48:00 PM
Record Upd:	11/30/2016 10:28:00 AM
Updated By:	GWHEITZM
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Brian Kenney, Director
Owner Company:	White Plains Central Library
Owner Address:	100 Martine Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	City of White Plains
Owner Address:	255 Main Street
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY
Owner Country:	United States of America
Own Op:	1
Sub Type:	Not reported
Owner Name:	James M. Driscoll
Owner Company:	WP North Tower LLC
Owner Address:	One Penn Plaza, Suite 1801
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	P03
Owner Name:	Please call for appointment
Owner Company:	NYSDEC Region 3
Owner Address:	21 S. Putt Corners Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY 12561
Owner Country:	United States of America
Own Op:	1
Sub Type:	P03
Owner Name:	James Driscoll
Owner Company:	WP South Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mr. James Driscoll
Owner Company:	WP South Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Mr. James Driscoll
Owner Company:	WP North Tower LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10119
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	James Driscoll
Owner Company:	LCOR 55 Bank Street LLC
Owner Address:	One Penn Plaza
Owner Addr2:	Suite 1801
Owner City,St,Zip:	New York, NY 10199
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	tetrachloroethene (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	TRICHLOROETHENE (TCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	TETRACHLOROETHYLENE (PCE)
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	LEAD
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	ZINC
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	BENZO(A)PYRENE
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	MERCURY
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COPPER
Waste Quantity:	UNKNOWN

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Waste Code:	Not reported
Crossref ID:	Test
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	8/3/2015 3:48:00 PM
Record Updated:	8/3/2015 3:48:00 PM
Updated By:	GWHEITZM
Crossref ID:	C360131-12-13
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	10/24/2016 1:35:00 PM
Record Updated:	10/24/2016 1:35:00 PM
Updated By:	DACROSBY

NY MANIFEST:

Name:	YOUNG COAL & LUMBER SITE
Address:	55 BANK STREET
City,State,Zip:	WHITE PLAINS, NY 10606
Country:	USA
EPA ID:	NYR000222273
Facility Status:	Not reported
Location Address 1:	55 BANK STREET
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10606
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYR000222273
Mailing Name:	YOUNG COAL & LUMBER SITE
Mailing Contact:	NP NORTH TONER LLC
Mailing Address 1:	ONE PENN PLAZA
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10119
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2127600060

NY MANIFEST:

Document ID:	Not reported
Manifest Status:	Not reported
seq:	Not reported
Year:	Not reported
Trans1 State ID:	NJR000029967
Trans2 State ID:	Not reported
Generator Ship Date:	12/23/2015
Trans1 Recv Date:	12/23/2015
Trans2 Recv Date:	Not reported
TSD Site Recv Date:	12/23/2015
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000222273

YOUNG COAL & LUMBER SITE (Continued) **S113492634**

Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	009464564FLE
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	Y
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H110
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	44820
Units:	P - Pounds
Number of Containers:	1
Container Type:	DT - Dump trucks
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	1
Waste Code:	D008
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

AN304 **CAMACHO** **NY LTANKS** **S105996433**
SSW **23 ODELL AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.264 mi.
1393 ft. **Site 1 of 2 in cluster AN**

Relative: **Higher**

Actual: **227 ft.**

LTANKS:

Name:	CAMACHO
Address:	23 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0204631 / 2008-07-14
Facility ID:	0204631
Site ID:	153929
Spill Date:	2002-08-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-08-01

CAMACHO (Continued) **S105996433**

CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-08-01
Spill Record Last Update:	2008-07-14
Spiller Name:	PAUL SCORZELLI
Spiller Company:	Not reported
Spiller Address:	23 ODELL AVE
Spiller County:	001
Spiller Contact:	PAUL SCORZELLI
Spiller Phone:	(914) 946-4300
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	130566
DEC Memo:	"NES DISPOSED OF TANK AND 19.47 TONS OF CONTAMIN SOIL. ALSO REPORTED AS SPILL 02-06200. NFA jod"
Remarks:	""

All Materials:

Site ID:	153929
Operable Unit ID:	855778
Operable Unit:	01
Material ID:	518872
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CAMACHO
Address:	23 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206200 / 2002-12-26
Facility ID:	0206200
Facility Type:	ER
DER Facility ID:	130566
Site ID:	173558
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2002-09-16
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-09-16
CID:	365
Water Affected:	Not reported

CAMACHO (Continued) **S105996433**

Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-16
Spill Record Last Update:	2008-07-14
Spiller Name:	CAMACHO RESIDENCE
Spiller Company:	Not reported
Spiller Address:	23 ODELL AV
Spiller Company:	001
Contact Name:	CAMACHO RESIDENCE
DEC Memo:	"12/26/02 NES DISPOSED OF 19.47 TONS OF CONTAMIN SOIL."
Remarks:	"HOLES IN THE TANK - 15 TONS OF CONTAMINATED SOIL EXCAVATED"

All Materials:

Site ID:	173558
Operable Unit ID:	857702
Operable Unit:	01
Material ID:	516812
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM305 **DEVON PLAZA REALITY** **NY LTANKS** **S118953811**
NE **109 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.264 mi.
1394 ft. **Site 2 of 4 in cluster AM**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Name:	DEVON PLAZA REALITY
Address:	109 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9512203 / 1995-12-29
Facility ID:	9512203
Site ID:	254450
Spill Date:	1995-12-29
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	1995-12-29
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-29
CID:	257
Water Affected:	Not reported
Spill Notifier:	Responsible Party

DEVON PLAZA REALITY (Continued) **S118953811**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-29
Spill Record Last Update:	1996-01-22
Spiller Name:	MR MENDOLA
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	NONE
Spiller Phone:	(914) 332-0600
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	208418
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"customer over ordered driver clean up spill"

All Materials:

Site ID:	254450
Operable Unit ID:	1026423
Operable Unit:	01
Material ID:	359516
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	3.00
Units:	G
Recovered:	3.00
Oxygenate:	Not reported

AM306 **NICKY'S RESTAURANT** **NY LTANKS** **S100137599**
NE **107 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.265 mi.
1400 ft. **Site 3 of 4 in cluster AM**

Relative: **Higher**
Actual: **219 ft.**

LTANKS:

Name:	NICKY'S RESTAURANT
Address:	107 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8900599 / 1989-05-03
Facility ID:	8900599
Site ID:	239748
Spill Date:	1989-04-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1989-05-03
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-04-19
CID:	Not reported

NICKY'S RESTAURANT (Continued) **S100137599**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-04-25
Spill Record Last Update:	2003-09-29
Spiller Name:	Not reported
Spiller Company:	NICKY'S RESTAURANT
Spiller Address:	107 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	197197
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY / / : LINES WERE CAPPED OFF AND TANK PASSED. "
Remarks:	"2,000 GAL. PETRO-TITE LINE LEAK >10 GPH, EXCAVATE, REPAIR & RETEST DURING TEST PRODUCT ENTERED BASEMENT THRU WELL. WILL CALL BACK WHEN EXCAVATION IS TO BE DONE."

All TTF:

Facility ID:	8900599
Spill Number:	8900599
Spill Tank Test:	1535369
Site ID:	239748
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	239748
Operable Unit ID:	926893
Operable Unit:	01
Material ID:	559486
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AO307 **MUNICIPAL GARAGE** **NY LTANKS** **S100140495**
WNW **111** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.266 mi.
1406 ft. **Site 1 of 3 in cluster AO**

Relative:
Lower

Actual:
208 ft.

LTANKS:

Name:	MUNICIPAL GARAGE
Address:	111
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8808829 / 1991-08-07
Facility ID:	8808829
Site ID:	129523
Spill Date:	1989-02-10
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-02-10
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1989-02-16
Spill Record Last Update:	2003-09-19
Spiller Name:	Not reported
Spiller Company:	JOHN HAINLINE
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	111644
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"2K -.6545. IER. THE GARAGE IS PULLING THE TANKS AND THE GARAGE WILL TELL US WHEN. TANK PULLER WILL BE HAZCO. ROD KING 718-575-3219"

All TTF:

Facility ID:	8808829
Spill Number:	8808829
Spill Tank Test:	1535167
Site ID:	129523
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

MUNICIPAL GARAGE (Continued) **S100140495**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 129523
Operable Unit ID: 925216
Operable Unit: 01
Material ID: 453596
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AO308 **CIVIC CENTER MOTORS** **NY LTANKS S105230061**
WNW **31 WESTMORELAND AVE** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.270 mi.
1425 ft. **Site 2 of 3 in cluster AO**

Relative: **Lower**

Actual: **208 ft.**

LTANKS:
Name: SPILL NUMBER 0108090
Address: 31 WESTMORELAND AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0108090 / 2001-11-08
Facility ID: 0108090
Site ID: 110892
Spill Date: 2001-11-08
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: mbmastro
Referred To: Not reported
Reported to Dept: 2001-11-08
CID: 207
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2001-11-08
Spill Record Last Update: 2001-11-27
Spiller Name: CALLER
Spiller Company: ROBISON OIL
Spiller Address: 500 EXECUTIVE BLVD
Spiller County: 001
Spiller Contact: MIKE PRAILEAU

CIVIC CENTER MOTORS (Continued) **S105230061**

Spiller Phone:	(914) 847-0288
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97050
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MASTRO 11/08/2001 CONFIRMED INFO - SPILL ON PAVEMENT, CONTAINED, NO WATERWAYS AFFECTED. NO FURTHER ACTION."
Remarks:	"cleanup in progress"

All Materials:

Site ID:	110892
Operable Unit ID:	846126
Operable Unit:	01
Material ID:	529346
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITE PLAINS HONDA
Address:	31 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206674 / 2003-02-26
Facility ID:	0206674
Site ID:	110893
Spill Date:	2002-09-25
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-27
CID:	281
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-27
Spill Record Last Update:	2003-03-26
Spiller Name:	DAVID DIDONA
Spiller Company:	WHITE PLAINS HONDA
Spiller Address:	31 WESTMORELAND AVE
Spiller County:	001
Spiller Contact:	DONNA CAIXERIO
Spiller Phone:	(914) 946-4300
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97050

CIVIC CENTER MOTORS (Continued) **S105230061**

DEC Memo: ""
Remarks: "VACUM TANK TEST FAILURE AT ABOVE LOCATION. PROPERTY OWNER HAS BEEN ADVISED OF TEST RESULTS."

All TTF:
Facility ID: 0206674
Spill Number: 0206674
Spill Tank Test: 1527509
Site ID: 110893
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 110893
Operable Unit ID: 858419
Operable Unit: 01
Material ID: 517277
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: WHITE PLAINS HONDA
Address: 31 WESTMORELAND AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0010522 / 2001-07-10
Facility ID: 0010522
Site ID: 68432
Spill Date: 2000-12-19
Spill Cause: Tank Overfill
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2000-12-19
CID: 281
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported

CIVIC CENTER MOTORS (Continued) **S105230061**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-12-19
Spill Record Last Update:	2002-03-15
Spiller Name:	ED ALLAN
Spiller Company:	ROBINSON OIL
Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	ED ALAN
Spiller Phone:	(914) 345-5700
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97050
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 07/10/2001 NEE DISPOSED OF TANK AND 11 DRUMS OF CONTAMINATED SOIL. NO FURTHER ACTION."
Remarks:	"TANK OVERFILL DURING DELILVERY AT ABOVE LOCATION. ALL MATERIAL REPORTED RECOVERED. NO CALL BACK REQUESTED."

All Materials:

Site ID:	68432
Operable Unit ID:	831663
Operable Unit:	01
Material ID:	571832
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	5.00
Oxygenate:	Not reported

SPILLS:

Name:	CIVIC CENTER MOTORS
Address:	31 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0500300 / 2005-04-07
Facility ID:	0500300
Facility Type:	ER
DER Facility ID:	97050
Site ID:	343238
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-04-07
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-04-07
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party

CIVIC CENTER MOTORS (Continued) **S105230061**

Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-07
Spill Record Last Update:	2012-01-11
Spiller Name:	TODD ROBINSON
Spiller Company:	NOCO TRUCK
Spiller Address:	625 SAWKILL ROAD
Spiller Company:	001
Contact Name:	TODD ROBINSON
DEC Memo:	""
Remarks:	"IN PROCESS OF CLEANING UP: WHILE SUCKING UP WASTE OIL IT OVERFILLED HIS TANK: LEAKED ON TO ASPHALT:"

All Materials:

Site ID:	343238
Operable Unit ID:	1101923
Operable Unit:	01
Material ID:	582157
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WHITEPLAINS HONDA
Address:	31 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9814172 / 1999-02-24
Facility ID:	9814172
Facility Type:	ER
DER Facility ID:	97050
Site ID:	174406
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6017
Spill Date:	1999-02-24
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-02-24
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

CIVIC CENTER MOTORS (Continued) **S105230061**

Date Entered In Computer:	1999-02-24
Spill Record Last Update:	1999-07-28
Spiller Name:	TODD ROBINSON
Spiller Company:	NOCO LUBRICANTS
Spiller Address:	625 SAWKILL RD
Spiller Company:	001
Contact Name:	TODD ROBINSON
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER REMOVING WASTE OIL AT ABOVE LOCATION. TRUCK OVERFILLED AND MATERIAL SPILLED ONTO PROPERTY. CALLER ON SITE AND REQUESTING CALL BACK @ 914-948-3305 IN REFERENCE TO CLEANUP - ASAP. ALL CONTAINED; NO ENVIRONMENTAL IMPACT."

All Materials:

Site ID:	174406
Operable Unit ID:	1071606
Operable Unit:	01
Material ID:	310877
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH309 **INTERSECTION OF COURT ST.** **NY LTANKS** **S102674960**
NNE **COURT ST. & MARITINE AVE.** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.272 mi.
1436 ft. **Site 3 of 4 in cluster AH**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Name:	INTERSECTION OF COURT ST.
Address:	COURT ST. & MARITINE AVE.
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8905963 / 1989-11-29
Facility ID:	8905963
Site ID:	187446
Spill Date:	1989-09-18
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	Not reported
Cleanup Ceased:	1989-11-29
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-09-18
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False

INTERSECTION OF COURT ST. (Continued) **S102674960**

Remediation Phase:	0
Date Entered In Computer:	1989-09-21
Spill Record Last Update:	1989-11-29
Spiller Name:	Not reported
Spiller Company:	RAD OIL
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	156611
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY "
Remarks:	"TANK TRUCK WAS OVERFILLED. WHITE PLAINS P.D. & F.D. ON SCENE."

All Materials:

Site ID:	187446
Operable Unit ID:	931170
Operable Unit:	01
Material ID:	446358
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AH310 **THE MICHICALLIAN OFFICE** **NY LTANKS** **S100782193**
NNE **MARTINE AVE & COURT ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.272 mi.
1436 ft. **Site 4 of 4 in cluster AH**

Relative:
Higher

Actual:
220 ft.

LTANKS:

Name:	THE MICHICALLIAN OFFICE
Address:	MARTINE AVE & COURT ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9310783 / 1993-11-18
Facility ID:	9310783
Site ID:	276042
Spill Date:	1993-11-16
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1993-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1993-11-16
Recommended Penalty:	False

THE MICHICALLIAN OFFICE (Continued) **S100782193**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1994-01-03
Spill Record Last Update:	1997-07-29
Spiller Name:	Not reported
Spiller Company:	W.C. DPW
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	224426
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/16/93 DEC ON SITE TO DETERMINE CONTAMINATION; 11/18/93 REMOVAL OF 77.98 TONS OF SOIL; "
Remarks:	"DISCOVERED OIL IN TANK PULL FAXED TO TODD GHIOSAY"

All Materials:

Site ID:	276042
Operable Unit ID:	989528
Operable Unit:	01
Material ID:	389858
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

AO311 **BENEROFE ASSOCIATION** **NY LTANKS** **S109374727**
WNW **39 WESTMORELAND AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.274 mi.
1446 ft. **Site 3 of 3 in cluster AO**

Relative: **Lower**
Actual: **209 ft.**

LTANKS:

Name:	BENEROFE ASSOCIATION
Address:	39 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0807224 / 2009-01-07
Facility ID:	0807224
Site ID:	404560
Spill Date:	2008-09-26
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH PBS 3-169102
Reported to Dept:	2008-09-26
CID:	Not reported
Water Affected:	Not reported

BENEROFE ASSOCIATION (Continued) **S109374727**

Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-26
Spill Record Last Update:	2009-01-07
Spiller Name:	KAREN GOMEZ
Spiller Company:	BENEROFE GROUP
Spiller Address:	4 NEW KING ST
Spiller County:	999
Spiller Contact:	BOB URVAN
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	183270
DEC Memo:	"9-26-09 Spoke with Bob Urvan. They will isolate the tank by entering manway and plugging lines and then retest. They will contact WCHD with results. Faxed spill report to WCHD. jm Passing retest and repair explanation received by WCDOH on 10/31/08 jod"
Remarks:	"TANK TEST FAILURE ON A 10,000 GALLON TANK, DRY PORTION LEAK. NO PRODUCT WAS SPILLED."

All Materials:

Site ID:	404560
Operable Unit ID:	1161209
Operable Unit:	01
Material ID:	2152403
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL PROPERTY
Address:	39 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9411173 / 1995-09-22
Facility ID:	9411173
Site ID:	221603
Spill Date:	1994-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-09-22
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported

BENEROFE ASSOCIATION (Continued) **S109374727**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-09-20
Spill Record Last Update:	1995-09-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	183270
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"TTF UNUSUAL CASE TANK LOCATED UNDER LOADING DOCK US TEST -.105"

All TTF:

Facility ID:	9411173
Spill Number:	9411173
Spill Tank Test:	1543373
Site ID:	221603
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	221603
Operable Unit ID:	1005007
Operable Unit:	01
Material ID:	377037
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	COMMERCIAL BLDG
Address:	39 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY

BENEROFE ASSOCIATION (Continued) **S109374727**

Spill Number/Closed Date:	0111615 / 2002-03-11
Facility ID:	0111615
Facility Type:	ER
DER Facility ID:	183270
Site ID:	283261
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2002-03-08
Investigator:	mbmastro
Referred To:	Not reported
Reported to Dept:	2002-03-08
CID:	252
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-03-08
Spill Record Last Update:	2002-03-26
Spiller Name:	CALLER
Spiller Company:	CASTLE OIL
Spiller Address:	290 LOCUST AVE
Spiller Company:	001
Contact Name:	BENEROSS REALTY
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was MASTRO 03/11/2002 OIL CONTAINED TO PAVEMENT. NO SOILS IMPACTED. CLEANUP COMPLETED W/PADS & SPEEDI DRY. NO FURTHER ACTION."
Remarks:	"VENT ALARM WAS NOT WORKING PROPERLY-DRIVER NOT HEARING IT ACCIDENTALLY OVERFILLED TANK-CASTLE OIL HAS DISPATCHED A CLEANUP CREW."

All Materials:

Site ID:	283261
Operable Unit ID:	850255
Operable Unit:	01
Material ID:	525636
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AP312 **UNK HOMEOWNER** **NY LTANKS** **S111160003**
West **163 FISHER AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.274 mi.
1447 ft. **Site 1 of 2 in cluster AP**

Relative:
Higher

Actual:
238 ft.

LTANKS:

Name:	UNK HOMEOWNER
Address:	163 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1104419 / 2014-11-05
Facility ID:	1104419
Site ID:	452024
Spill Date:	2011-07-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2011-07-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-07-21
Spill Record Last Update:	2014-11-05
Spiller Name:	REED SMERSNIA
Spiller Company:	UNK HOMEOWNER
Spiller Address:	163 FISHER AVE
Spiller County:	999
Spiller Contact:	REED SMERSNIA
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	406615
DEC Memo:	"7/21/11 done for real estate transaction...mm 11/05/2014 Homeowner Tank Test Failure at least two years old with no known impact, as per Albany, will be closed. NFA JO M"
Remarks:	"test done for potential buyer, unk retest or repair"

All Materials:

Site ID:	452024
Operable Unit ID:	1202203
Operable Unit:	01
Material ID:	2198771
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AN313 **MAGNOTTI RESIDENCE** **NY LTANKS** **S103558430**
SSW **16 ODELL AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.275 mi.
1451 ft. **Site 2 of 2 in cluster AN**

Relative:
Higher

Actual:
238 ft.

LTANKS:

Name:	MAGNOTTI RESIDENCE
Address:	16 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9810325 / 1999-01-19
Facility ID:	9810325
Site ID:	124170
Spill Date:	1998-11-16
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-16
CID:	198
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-16
Spill Record Last Update:	1999-02-02
Spiller Name:	JOHN/JENNI MAGNOTTI
Spiller Company:	MAGNOTTI RESIDENCE
Spiller Address:	16 ODELL AVE
Spiller County:	001
Spiller Contact:	JOHN/JENNI MAGNOTTI
Spiller Phone:	(914) 949-5080
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	107585
DEC Memo:	""
Remarks:	"GROSS FAILURE ON TANK AT RESIDENCE. NO PBS # FOR TANK."

All TTF:

Facility ID:	9810325
Spill Number:	9810325
Spill Tank Test:	1546538
Site ID:	124170
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported

MAGNOTTI RESIDENCE (Continued) **S103558430**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 124170
Operable Unit ID: 1071241
Operable Unit: 01
Material ID: 314190
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AQ314 **HALPERN ENTERPRISES** **NY LTANKS** **S100140406**
NE **170 EAST POST ROAD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.276 mi.
1458 ft. **Site 1 of 2 in cluster AQ**

Relative: **Higher**
Actual: **221 ft.**

LTANKS:
Name: HALPERN ENTERPRISES
Address: 170 EAST POST ROAD
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 8804996 / 2005-04-30
Facility ID: 8804996
Site ID: 154885
Spill Date: 1988-09-08
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: D4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WXWADSWO
Referred To: Not reported
Reported to Dept: 1988-09-08
CID: Not reported
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1988-09-16
Spill Record Last Update: 2005-04-30
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

HALPERN ENTERPRISES (Continued) **S100140406**

DEC Region: 3
DER Facility ID: 131293
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 04/30/05 ADMINISTRATIVELY CLOSED AS PER DIRECTIVE FROM CENTRAL OFFIICE."
Remarks: "3,000 GAL. TANK; -.10 GPH; TO EXCAVATE, ISOLATE & RETEST. TANK TO BE RETESTED THE WEEK OF 9/12. LEAK COULD BE FROM FILL PIPE WHICH IS BENTSPOKE TO GARY GIGLIO. WILL CALL IF TANK IS TO BE REMOVED."

All TTF:
Facility ID: 8804996
Spill Number: 8804996
Spill Tank Test: 1534581
Site ID: 154885
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 154885
Operable Unit ID: 922162
Operable Unit: 01
Material ID: 456917
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

---

315 East 1/4-1/2 0.280 mi. 1477 ft.

ROADWAY
285 MAMARONECK AVE
WHITE PLAINS, NY

NY LTANKS **S102240718**
NY Spills **N/A**

Relative: Higher

Actual: 236 ft.

LTANKS:
Name: C STAR DINER
Address: 285 MAMARONECK ST
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9712450 / 2020-07-10
Facility ID: 9712450
Site ID: 85909
Spill Date: 1998-02-07
Spill Cause: Tank Test Failure

ROADWAY (Continued) **S102240718**

Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1998-02-07
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-02-07
Spill Record Last Update:	2020-07-10
Spiller Name:	WILLIAM S OLESON
Spiller Company:	C STAR DINER
Spiller Address:	285 MAMARONECK ST
Spiller County:	001
Spiller Contact:	WILLIAM S OLESON
Spiller Phone:	(914) 948-4500
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	78861
DEC Memo:	"02/07/98 ROBISON OIL WILL ARRANGE TO E.I.R. 8/3/10 TTF JO'M 07/10/20 Emailed Chris Lalak about the status of this tank. He responded that a tank for the facility was removed in 1998. Facility has been redeveloped and is now a TD Bank. NFA. TG"
Remarks:	"REQ DEC REP CONTACT OWNER OF DINER ON MONDAY"

All TTF:

Facility ID:	9712450
Spill Number:	9712450
Spill Tank Test:	1545605
Site ID:	85909
Tank Number:	1
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	85909
Operable Unit ID:	1058741
Operable Unit:	01
Material ID:	327052
Material Code:	0001A

ROADWAY (Continued) **S102240718**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	ROADWAY
Address:	285 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9511162 / 1995-12-05
Facility ID:	9511162
Facility Type:	ER
DER Facility ID:	139914
Site ID:	166024
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C5
SWIS:	6017
Spill Date:	1995-12-05
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-05
CID:	233
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department
Cleanup Ceased:	1995-12-05
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-05
Spill Record Last Update:	1995-12-12
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"tanker truck was leaking as it drove down the road the majority of the spill is in front of the above address leak is stopped clean up underway "

All Materials:

Site ID:	166024
Operable Unit ID:	1025458
Operable Unit:	01
Material ID:	358513
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported

ROADWAY (Continued) **S102240718**

Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported

316
SSE
1/4-1/2
0.282 mi.
1488 ft.

SPILL NUMBER 0005555 **NY LTANKS** **S104782052**
20 PROSPECT ST **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
286 ft.

LTANKS:
Name: SPILL NUMBER 0005555
Address: 20 PROSPECT ST
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0005555 / 2000-08-29
Facility ID: 0005555
Site ID: 122722
Spill Date: 2000-08-09
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2000-08-09
CID: 270
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2000-08-09
Spill Record Last Update: 2000-09-14
Spiller Name: ROBERTO SALAVERRA
Spiller Company: ROBERTO SALAVERRA
Spiller Address: 20 PROSPECT ST
Spiller County: 001
Spiller Contact: ROBERTO SALAVERRA
Spiller Phone: (914) 948-7605
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 106379
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/29/2000 TAKE PRIDE PULLED TANK, DISPOSED OF 23.52 TONS OF CONTAMINATED SOIL AT TT MATERIALS. NFA"
Remarks: "isolated tank test"

All TTF:
Facility ID: 0005555
Spill Number: 0005555
Spill Tank Test: 1525821
Site ID: 122722

SPILL NUMBER 0005555 (Continued) **S104782052**

Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	122722
Operable Unit ID:	828130
Operable Unit:	01
Material ID:	546706
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR317 **MARIO'S S/S** **NY LTANKS** **U001842534**
SW **107 WEST POST ROAD** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.286 mi.
1509 ft. **Site 1 of 2 in cluster AR**

Relative:
Higher

Actual:
241 ft.

LTANKS:

Name:	MARIO'S S/S
Address:	107 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9408490 / 1994-09-30
Facility ID:	9408490
Site ID:	255844
Spill Date:	1994-09-26
Spill Cause:	Tank Overfill
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D4
Cleanup Ceased:	1994-09-30
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1994-09-26
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False

MARIO'S S/S (Continued) **U001842534**

UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	MYSTIC OAK CARRIER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209542
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"GAUGE ON TANK BROKEN SPILLER TO CLEANUP NCB"

All Materials:

Site ID:	255844
Operable Unit ID:	1002615
Operable Unit:	01
Material ID:	377924
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	10.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	POLE TOP
Address:	107 WEST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1701733 / 2017-06-12
Facility ID:	1701733
Facility Type:	ER
DER Facility ID:	502466
Site ID:	548843
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2017-05-23
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-05-23
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False

MARIO'S S/S (Continued) **U001842534**

UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-05-23
Spill Record Last Update:	2017-06-12
Spiller Name:	Not reported
Spiller Company:	POLE TOP
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	WHITE PLAINS PD
DEC Memo:	"5-23-17 Hotline described caller as saying a small spill, but some amount of transformer oil was washed into sewer. Spoke with PD. Officer said that overhead transformer exploded. FD responded and put out fire. During fire, an unknown amount of oil was washed into sewer. He said that Con Ed was on scene now and DPW was coming to location also. Called ERT and spoke to Chris. Chris confirmed they have an emergency crew on scene de-energizing unit. He confirms an unknown amount washed into sewer. Chris estimates that type of transformer involved in incident holds a maximum of about 30 gallons. I thas been reported to him that top of transformer was on fire, so it spill is not believed to be near that amount. They will know more once they can inspect transformer. TG will be updated by EMIS report. jc 05/23/17 Transformer on pole 44 at W. Post Rd, White Plains has been updated. Transformer is a 150 kVa sensing transformer which has a capacity of 113 gallons. It is a 7/15/2010 unit which is non PCB. Emergency crew is estimating possibly half the capacity is out of the unit and it remains unknown amount of material into the drain. Crew remain on location. TG 05/23/17 Inspected the Bronx River at Exit 21 the White Plains exit since that is where the storm drain discharges. An oil slick was present on the water surface and no absorbents were in place. So I went to the spill origin on West Post Rd and met with the on scene supervisor, Gregory C. Lee Sr. He was not aware that the transformer oil traveled to the Bronx River. He was advised that a crew was a the river to deploy booms. He called his office for guidance. Meanwhile, I called Tri State who said they had a crew at their facility that they could send without delay. Gregory Lee could not provide and ETA for his cleanup crew, so he said he would like me to call TriState to have them respond to the outfall. I then left the site to travel back to meet TriState at the outfall. They deployed absorbents at the outfall. Con Ed operations supervisor, Jos Detres arrived and was briefed. Mr. Detres met Nanci from TriState. Jose advised Nanci that she should email him the invoice and he would see that TriState would be paid directly by Con Ed. I then returned again to West Post Road location and by then Allstate Power Vac was on scene waiting to begin the street and storm drain catch basin cleaning. TG 06/12/17 Excerpt from EMIS 258350/7: 5/23/2017 9:10 AM Emergency No 9 reported transformer fire out and transformer off line. BTicket WE17020993, WR 3927931. Serial number is 61009057096 ERNCO unit with blue date 07-15-2010. Unit badged as holding 113 gallons and is a 150 kVa sensing transformer. Possibility of half capacity spilled out to street and unknown amount into drain mixed with water from white plains FD operations. Blaich, Christopher 5/23/2017 11:40 AM Transformer off line and bagged. DEC spill response reported a sheen in the water at exit 21 on Bronx River Expressway. Env Ops J. Detres responded and reported there is a sheen on the water and DEC boomed area. DEC called Tri-State Env for a response. Env ops took sample of material on the water for analysis. Unclear at this time is product is a CE material and from the

MARIO'S S/S (Continued) **U001842534**

overhead transformer on West Post Road at pole 44. Env ops has a contractor on location to begin cleaning the area at pole 44 and to investigate the drain at the location that was reported as being impacted. Blaich, Christopher 5/23/2017 7:40 PM All-State double washed and rinsed (Using Safe Wash) street, sidewalk, 4 catch basins and 1 sewer Manhole and clean customer (107 W. Post Rd) driveway. Unit has been bagged up. The unit is removed and bagged up and OH crew in the process of putting up the new unit. Baxter, Brandon 5/26/2017 10:39 AM EH&S Senior Specialist R.Young (85857) to report that NYSDEC Reg III Rep Todd Ghiosay had contacted Tri-State Environmental Services (Hawthorne, NY) requesting that the two booms be removed from the Bronx River; booms located just north of Exit 21...one boom at the outfall and one boom at the pedestrian bridge. Duke, David "

Remarks: "pole top"

All Materials:

Site ID:	548843
Operable Unit ID:	1296936
Operable Unit:	01
Material ID:	2303050
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	POST ROAD SUNOCO
Address:	107 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9416930 / 2014-05-27
Facility ID:	9416930
Facility Type:	ER
DER Facility ID:	209542
Site ID:	255845
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	1995-03-29
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1995-03-30
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	2003-12-02

MARIO'S S/S (Continued) **U001842534**

Spill Record Last Update:	2014-05-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 3/24/2010 - Email to WCDOH for input. ELM 4/1/10 WCDOH awaiting response back from their archive. JO'M 8/10/12 Mtg notes:The August 9, 2012 meeting at the DEC office reviewed the current status of the 107 West Post Road Sunoco Station. The discussion concluded the two sets of groundwater sample data available, one from each 2009 and 2010, was insufficient to make any determine on the current status of the site. As per our discussion, the department is requiring that groundwater samples from the two wells be collected, analyzed and the results be submitted quarterly for a minimum of 8 quarters. A site map locating the wells on the site must be included in each report. Additionally, relative groundwater elevations are to be measured at each sampling event and included in the quarterly status report. After review of a minimum of 6 quarters and a maximum of 8 quarters of analytical data, the site status will be discussed and further work may be necessary. Once the contamination is remediated, spill numbers 9406301 and 9416930 will be closed concurrently.--mt 7/9/2013 -- When asked, the attorney said he would work on it. The contractor said he had plans. Waiting for true schedule to conduct sampling. Unknown if or how many rounds of samples have been collected to date. ELM 11/25/13 Site visit on 11/22/13, There are two separate sites, the repair garage at 107 Post Road and the gas station at 115 Post Road. Two wells were recently installed proximal to the old tank farm at 107 Post Road. Samples have been taken and sent to a lab. A report is pending. mt 5/27/14 GW analytical data slight continual decrease over the past years, NFA. MT"
Remarks:	"EXCAVATING CONTAMINATED SOIL AFTER REMOVAL OF SIXTH TANK FOUR ABANDONED TANKS WHERE FOUND ON SITE TANKS WHERE OBSERVED TO BE FILLED WITH WATER/GAS MIXTURE"

All Materials:

Site ID:	255845
Operable Unit ID:	1014043
Operable Unit:	01
Material ID:	368556
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AS318 **SEACON METAL** **NY LTANKS** **S100137946**
West **7 INTERVAIL ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.286 mi.
1511 ft. **Site 1 of 2 in cluster AS**

Relative:
Higher

Actual:
214 ft.

LTANKS:

Name:	SEACON METAL
Address:	7 INTERVAIL ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8904791 / 1989-11-30
Facility ID:	8904791
Site ID:	252170
Spill Date:	1989-08-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-11-30
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-08-14
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-08-21
Spill Record Last Update:	1989-11-30
Spiller Name:	Not reported
Spiller Company:	SEACON METAL
Spiller Address:	7 INTERVAIL ST.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	206645
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY 08/18/89: TANK IS TO BE CLEANED BY MONDAY 8/21/89. TANK TO BE REMOVED OR ABANDONED. "
Remarks:	"2K, PETRO, -.160, EXCAVATE, ISOLATE & RETEST ASAP"

All TTF:

Facility ID:	8904791
Spill Number:	8904791
Spill Tank Test:	1535847
Site ID:	252170
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

SEACON METAL (Continued) **S100137946**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 252170
Operable Unit ID: 930043
Operable Unit: 01
Material ID: 448822
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AQ319 **SPILL NUMBER 9900622** **NY LTANKS** **S104620122**
ENE **179 EAST COAST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.288 mi.
1523 ft. **Site 2 of 2 in cluster AQ**

Relative:
Higher

Actual:
223 ft.

LTANKS:
Name: SPILL NUMBER 9900622
Address: 179 EAST COAST RD
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9900622 / 2000-03-24
Facility ID: 9900622
Site ID: 260731
Spill Date: 1999-04-16
Spill Cause: Tank Failure
Spill Source: Commercial/Industrial
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 1999-04-16
CID: 312
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-04-16
Spill Record Last Update: 2000-03-30
Spiller Name: ANN WEST
Spiller Company: Not reported
Spiller Address: 179 EAST COAST RD
Spiller County: 001
Spiller Contact: ANN WEST

SPILL NUMBER 9900622 (Continued) **S104620122**

Spiller Phone:	(914) 946-2370
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	212944
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 4/16/99 NES REMOVING CONTAMINATED SOIL 03/24/2000 NES DISPOSED OF TANK AND 3.65 TONS OF CONTAMINATED SOIL. NFA "
Remarks:	"550GAL VAULTED TANK IN BASEMENT FULL OF HOLES - LEAKED INTO SAND BELOW THE TANK"

All Materials:

Site ID:	260731
Operable Unit ID:	1079395
Operable Unit:	01
Material ID:	307749
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

320 NNE 1/4-1/2 0.295 mi. 1557 ft. **MINSKOFF CORP.** **NY LTANKS** **S102673852**
179 MARTINE AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 217 ft.

LTANKS:

Name:	MINSKOFF CORP.
Address:	179 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9201879 / 1992-05-15
Facility ID:	9201879
Site ID:	217944
Spill Date:	1992-05-15
Spill Cause:	Tank Overfill
Spill Source:	Tank Truck
Spill Class:	C3
Cleanup Ceased:	1992-05-15
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-05-15
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported

MINSKOFF CORP. (Continued) **S102673852**

Spiller Company:	ORIG. CONSUMERS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	180303
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAINED ON CONCRETE FLOOR IN CELLAR SPILLER DOING CLEAN UP"

All Materials:

Site ID:	217944
Operable Unit ID:	969292
Operable Unit:	01
Material ID:	413166
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	7.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

321
SSW
1/4-1/2
0.296 mi.
1561 ft.

RLS REALTY CO
11 ODELL AVE
WHITE PLAINS, NY

NY LTANKS **S102153884**
NY Spills **N/A**

Relative:
Higher

Actual:
248 ft.

LTANKS:

Name:	RLS REALTY CO
Address:	11 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0803661 / 2008-07-14
Facility ID:	0803661
Site ID:	400429
Spill Date:	2008-06-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-06-27
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-06-27

RLS REALTY CO (Continued) **S102153884**

Spill Record Last Update:	2008-07-14
Spiller Name:	RICK SUAREZ
Spiller Company:	RLS REALTY CO
Spiller Address:	11 ODELL AVE
Spiller County:	001
Spiller Contact:	RICK SUAREZ
Spiller Phone:	(914) 428-0790
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	349712
DEC Memo:	"July 14, 2008: Tank passed a retest after piping was repaired. Based upon the information provided to DEC, No Further Action is required at this time. jod"
Remarks:	"UNCOVER REAPIR AND RETEST"

All TTF:

Facility ID:	0803661
Spill Number:	0803661
Spill Tank Test:	2486386
Site ID:	400429
Tank Number:	Not reported
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	400429
Operable Unit ID:	1157256
Operable Unit:	01
Material ID:	2148274
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	RLS REALTY
Address:	11 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1215385 / 2013-02-14
Facility ID:	1215385
Site ID:	478685
Spill Date:	2013-02-07
Spill Cause:	Tank Test Failure

RLS REALTY CO (Continued) **S102153884**

Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2013-02-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2013-02-07
Spill Record Last Update:	2013-02-14
Spiller Name:	RICK SUAREZ
Spiller Company:	RLS REALTY
Spiller Address:	9 WESTFIELD LANE
Spiller County:	999
Spiller Contact:	RICK SUARZE
Spiller Phone:	(914) 428-0790
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	349712
DEC Memo:	"Spoke to caller, the tank was installed in 1998. Leak appears to be in the piping. Robison has been contacted to uncover and repair for a retest...mm 02/14/13 US Tank Tech reported that they retested the tank on 02/13/13 and that the tank passed a retest. See test report in Edocs. NFA. TG"
Remarks:	""

All Materials:

Site ID:	478685
Operable Unit ID:	1228450
Operable Unit:	01
Material ID:	2226086
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	APT BUILDING
Address:	11 ODELL AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9905495 / 2000-01-31
Facility ID:	9905495
Facility Type:	ER
DER Facility ID:	349712
Site ID:	110859

RLS REALTY CO (Continued) **S102153884**

DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	1999-08-06
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-08-06
CID:	257
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-06
Spill Record Last Update:	2009-01-02
Spiller Name:	MR SUAREZ
Spiller Company:	APT. BUILDING
Spiller Address:	11 O'DELL AVE
Spiller Company:	001
Contact Name:	MR SUAREZ
DEC Memo:	"01/31/2000 ENVIRO SHIELD DISPOSED OF TANK AND 51.63 TONS OF CONTAMINATED OIL. NFA"
Remarks:	"during a tank removal caller found contaminated soil"

All Materials:

Site ID:	110859
Operable Unit ID:	1084088
Operable Unit:	01
Material ID:	301790
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

322
ENE
1/4-1/2
0.298 mi.
1576 ft.

PIRRO, MONSELL REALTY **NY LTANKS** **S100139873**
40 WALLER AVE **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
221 ft.

LTANKS:

Name:	PIRRO, MONSELL REALTY
Address:	40 WALLER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8709325 / 1988-02-02
Facility ID:	8709325
Site ID:	162080
Spill Date:	1988-02-02

PIRRO, MONSELL REALTY (Continued) **S100139873**

Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-02-02
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-02-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	1988-02-02
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-02-09
Spill Record Last Update:	1988-02-10
Spiller Name:	MARIE TEDESCHI
Spiller Company:	JOE ZAHENSKY,914-478-5700
Spiller Address:	ROBISON OIL CORP.
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	136800
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : WCHD NOTIFIED, RICH DORAN, SPILL IS CONTAINED. N.F.A. / / : 02-10-88 DRAIN IN CELLAR HAS CAP ON IT. "
Remarks:	"TANK RUPTURE IN BASEMENT 275GAL. A/G TANK. CEMENT FLOOR. USEING SPEEDY DRY TO CLEAN UP."

All Materials:

Site ID:	162080
Operable Unit ID:	914412
Operable Unit:	01
Material ID:	464653
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AM323 **DEVON PLAZA REALTY** **NY LTANKS** **S102960212**
NE **9 MITCHELL PLACE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.300 mi.
1585 ft. **Site 4 of 4 in cluster AM**

Relative: **Higher**

Actual: **217 ft.**

LTANKS:

Name:	GAS STATION
Address:	9 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY

DEVON PLAZA REALTY (Continued) **S102960212**

Spill Number/Closed Date:	9710474 / 1998-10-27
Facility ID:	9710474
Site ID:	199404
Spill Date:	1997-12-12
Spill Cause:	Tank Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-12
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1997-12-12
Spill Record Last Update:	1999-01-20
Spiller Name:	Not reported
Spiller Company:	GAS STATION
Spiller Address:	9 MITCHELL PL
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	165966
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"Caller doing site work found contaminated soil. Luzon report - no further work required."

All Materials:

Site ID:	199404
Operable Unit ID:	1056851
Operable Unit:	01
Material ID:	328768
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	DEVON PLAZA REALTY
Address:	9 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1200312 / 2012-08-02
Facility ID:	1200312

DEVON PLAZA REALTY (Continued) **S102960212**

Facility Type:	ER
DER Facility ID:	417359
Site ID:	462934
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	2012-04-11
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2012-04-11
Spill Record Last Update:	2012-08-02
Spiller Name:	LEE LEWITT
Spiller Company:	LEE LEWITT
Spiller Address:	9 MITCHELL PL
Spiller Company:	999
Contact Name:	LEE LEWITT
DEC Memo:	" 4/11/12: Former PBS Facility, Mitchell Place Garage. Barbara McDonald from WCDOH reports all USTs were reportedly removed when the site was deregulated. She will follow up with owner and caller, then update DEC. jod 07/31/12 Northeast Environmental submitted a soil remediation report. They reported that they unearthed a 1000 gallon fuel oil tank. More than 60% of the tank was under the building making removal impossible. The soil immediately beneath the tank was impacted but left in place. All surrounding soils were removed. A gw monitoring well was installed in the vicinity of the tank and no contaminants were detected. NE Environmental recommended removing any remaining impacted soil once the building is demolished. NFA TG "
Remarks:	"cleanup pending - tank under foundation of building"

All Materials:

Site ID:	462934
Operable Unit ID:	1213041
Operable Unit:	01
Material ID:	2210932
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AT324 **MITCHELL PLACE ASSOC.** **NY LTANKS** **S100137749**
NE **10 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.304 mi.
1605 ft. **Site 1 of 4 in cluster AT**

Relative:
Higher

Actual:
217 ft.

LTANKS:

Name:	MITCHELL PLACE ASSOC.
Address:	10 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8902485 / 1989-10-02
Facility ID:	8902485
Site ID:	76057
Spill Date:	1989-06-09
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1989-10-02
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-06-14
Spill Record Last Update:	1989-10-02
Spiller Name:	Not reported
Spiller Company:	MITCHELL PLACE ASSOC.
Spiller Address:	10 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	71149
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TODD GHIOSAY 10/02/89: SPILLER HIRED EES TO PULL TANK AND REMOVE CONTAMINATED SOIL. SUMP WAS PERIODICALLY CLEANE AND FREE OIL REMOVED. NFA. "
Remarks:	"SPOKE W/BOB HYMAN. DIGGING ON 6/14/89 TO UNCOVER TANK & RETEST."

All TTF:

Facility ID:	8902485
Spill Number:	8902485
Spill Tank Test:	1535567
Site ID:	76057
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

MITCHELL PLACE ASSOC. (Continued) **S100137749**

Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	76057
Operable Unit ID:	928178
Operable Unit:	01
Material ID:	450186
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AP325 **179 FISHER AVE** **NY LTANKS** **S109064135**
West **179 FISHER AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.304 mi.
1607 ft. **Site 2 of 2 in cluster AP**

Relative:
Higher

Actual:
240 ft.

LTANKS:

Name:	179 FISHER AVE
Address:	179 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0712211 / 2009-08-31
Facility ID:	0712211
Site ID:	393798
Spill Date:	2008-02-20
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	Unassigned
Referred To:	Not reported
Reported to Dept:	2008-02-20
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-20
Spill Record Last Update:	2009-08-31
Spiller Name:	PATRICIA REMAREZ
Spiller Company:	Not reported
Spiller Address:	179 FISHER AVE
Spiller County:	001

179 FISHER AVE (Continued) **S109064135**

Spiller Contact:	PATRICIA REMAREZ
Spiller Phone:	(914) 391-5176
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	343382
DEC Memo:	"8/31/2009 -- Tank test failure with no details on method or appropriateness of the method. WCDOH would have required additional testing. No information in 1 1/2 years. NFA at this time. ELM"
Remarks:	""

All TTF:

Facility ID:	0712211
Spill Number:	0712211
Spill Tank Test:	2384714
Site ID:	393798
Tank Number:	Not reported
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	False
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	393798
Operable Unit ID:	1150752
Operable Unit:	01
Material ID:	2141391
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AR326 **KEN KNAPP CITGO** **NY LTANKS S100142096**
SW **115 WEST POST ROAD** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.305 mi.
1613 ft. **Site 2 of 2 in cluster AR**

Relative:
Higher

Actual:
243 ft.

LTANKS:

Name:	KEN KNAPP CITGO
Address:	115 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9005629 / 1990-12-17
Facility ID:	9005629
Site ID:	255569
Spill Date:	1990-08-21

KEN KNAPP CITGO (Continued) **S100142096**

Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-08-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-08-23
Spill Record Last Update:	1991-05-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209317
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 12/17/90: TANKS REMOVED. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"EIR ASAP CALLED FOR TIM BORMAN,RECEIVED CALL BACK FROM STEVE THEY WILLBE EXCAVATING ON MONDAY (8/27) I & R ON TUESDAY PETRO-TITE -.267"

All TTF:

Facility ID:	9005629
Spill Number:	9005629
Spill Tank Test:	1537457
Site ID:	255569
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	255569
Operable Unit ID:	946114
Operable Unit:	01

KEN KNAPP CITGO (Continued) **S100142096**

Material ID:	433117
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	115 WEST POST ROAD S/S
Address:	115 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9012261 / 1991-03-21
Facility ID:	9012261
Facility Type:	ER
DER Facility ID:	209317
Site ID:	255570
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	1991-02-25
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	1991-02-25
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-02-27
Spill Record Last Update:	2012-06-28
Spiller Name:	Not reported
Spiller Company:	ELMSFORD AUTO BODY INC.
Spiller Address:	1 HAVERS STREET
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 3/24/10 TG will investigate JO'M 06/28/12 Karl Weed sent NFA letter dated May 21, 1991. The residual contamination at this site will be addressed under spill # 94-16930 mt"
Remarks:	"CONTAMINATION FOUND WHILE EXCAVATING THE TANKS AN ODOR WAS IN THE AIR AND SOIL REMOVED THIS IS TO BE REFERRED FOR GROUNDWATER INVESTIGATION TO BE PERFORMED"

All Materials:

Site ID:	255570
Operable Unit ID:	949281
Operable Unit:	01

KEN KNAPP CITGO (Continued) **S100142096**

Material ID:	428766
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	SUNOCO
Address:	115 WEST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9406301 / 2014-05-27
Facility ID:	9406301
Facility Type:	ER
DER Facility ID:	209317
Site ID:	110771
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	1994-08-08
Investigator:	mxtipple
Referred To:	Not reported
Reported to Dept:	1994-08-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2014-05-27
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"4/28/10 Active site reports in Edocs JO'M 8/10/12 Spill # transferred to Tipple. The August 9, 2012 meeting at the DEC office reviewed the current status of the 107and 115 West Post Road Sites. We are tracking the site contaminants through spill # 9416930. Once the contamination is remediated, spill numbers 9406301 and 9416930 will be closed concurrently. mt 5/27/14 GW analytical data slight continual decrease over the past years, NFA. MT"
Remarks:	"INSTALLING TANKS DEC ON SITE YESTERDAY WILL STOCKPILE SOIL AND PERFORM SITE ASSESSMENT"

All Materials:

Site ID:	110771
Operable Unit ID:	1003668
Operable Unit:	01

KEN KNAPP CITGO (Continued) **S100142096**

Material ID:	379349
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AS327 **AUTOMOBILE CLUB OF NEW YORK** **NY SHWS** **S105057848**
West **101 WESTMORELAND AVENUE** **NY ENG CONTROLS** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10606** **NY INST CONTROL**
0.313 mi. **NY Spills**
1652 ft. **Site 2 of 2 in cluster AS**

Relative: **Lower**
Actual: **205 ft.**

SHWS:

Name:	AUTOMOBILE CLUB OF NEW YORK
Address:	101 WESTMORELAND AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
Program:	HW
Site Code:	374633
Classification:	Not reported
Region:	3
Acres:	0.20000000000000001
HW Code:	360095
Record Add:	12/08/2006
Record Upd:	03/02/2020
Updated By:	AMOMOROG

Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

	soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	4
Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

ENG CONTROLS:
Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
HW Code: 360095
Control Code: 35
Control Type: ENG
Date Record Added: 10/15/2015
Date Rec Updated: 04/10/2019
Updated By: JJTEETER
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

	petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606
Owner Country:	United States of America
Own Op:	4

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	D3-0504-06-09
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	5/4/2015 3:12:00 PM
Record Updated:	5/4/2015 3:12:00 PM
Updated By:	JLVERRIG
Crossref ID:	Not reported
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	7/14/2017 8:08:00 AM
Record Updated:	7/14/2017 8:08:00 AM
Updated By:	JLVERRIG
Name:	AUTOMOBILE CLUB OF NEW YORK
Address:	101 WESTMORELAND AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
Site Code:	374633
HW Code:	360095
Control Code:	15
Control Type:	ENG
Date Record Added:	10/15/2015
Date Rec Updated:	04/10/2019
Updated By:	JJTEETER
Site Description:	Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem:	Nature and Extent of Contamination: Remediation at the site is

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

	complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem:	Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	NNN
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York, Inc. (AAA)
Owner Address:	1415 KELLUM PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	GARDEN CITY, NY 11530
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Place
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
Own Op:	4
Sub Type:	NNN
Owner Name:	RJT MOROTIST SERVICES
Owner Company:	RJT MOROTIST SERVICES
Owner Address:	101 WESTMORELAND AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	WHITE PLAINS, NY 10606

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Country:	United States of America
Own Op:	4
Sub Type:	Not reported
Owner Name:	Jack Byrnes
Owner Company:	Automobile Club of New York
Owner Address:	1415 Kellum Pl
Owner Addr2:	Not reported
Owner City,St,Zip:	Garden City, NY 11530
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	D3-0504-06-09
Cross Ref Type Code:	23
Cross Ref Type:	Agreement/Consent Order Number
Record Added Date:	5/4/2015 3:12:00 PM
Record Updated:	5/4/2015 3:12:00 PM
Updated By:	JLVERRIG
Crossref ID:	Not reported
Cross Ref Type Code:	25
Cross Ref Type:	County Recording Identifier
Record Added Date:	7/14/2017 8:08:00 AM
Record Updated:	7/14/2017 8:08:00 AM
Updated By:	JLVERRIG

INST CONTROL:

Name:	AUTOMOBILE CLUB OF NEW YORK
Address:	101 WESTMORELAND AVENUE
City,State,Zip:	WHITE PLAINS, NY 10606
Site Code:	374633
Control Name:	Site Management Plan
HW Code:	360095
Control Code:	32
Control Type:	INST
Dt record added:	10/15/2015
Dt rec updated:	04/10/2019
Updated By:	JJTEETER
Site Code:	374633
Site Description:	Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: Environmental Easement
HW Code: 360095
Control Code: Not reported
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: Monitoring Plan
HW Code: 360095
Control Code: 31
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: IC/EC Plan
HW Code: 360095
Control Code: 34
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: Landuse Restriction
HW Code: 360095
Control Code: 25
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.

Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.

Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.

Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: O&M Plan
HW Code: 360095
Control Code: 33
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE
City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: Soil Management Plan
HW Code: 360095

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Control Code: 14
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump: Not reported
Structure: Not reported
Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM
Updated By: JLVERRIG

Name: AUTOMOBILE CLUB OF NEW YORK
Address: 101 WESTMORELAND AVENUE

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

City,State,Zip: WHITE PLAINS, NY 10606
Site Code: 374633
Control Name: Ground Water Use Restriction
HW Code: 360095
Control Code: 8
Control Type: INST
Dt record added: 10/15/2015
Dt rec updated: 04/10/2019
Updated By: JJTEETER
Site Code: 374633
Site Description: Location: The Automobile Club of New York site is located on the northwest side of Westmoreland Avenue, approximately 100 feet west of the intersection of Westmoreland Avenue and Home Place in the City of White Plains. The site is approximately 0.2 acres Site Features: The site is essentially flat and includes a one-story, concrete block, L-shaped occupied building that covers approximately 75 percent of the site. The northeastern portion of the property is covered with an asphalt parking area, while the western portion of the site contains a gravel parking area. The Bronx River is located approximately 700 feet to the northwest of the site. Current Zoning and Land Use: The site is zoned light industrial and is currently used as an AAA of NY auto-repair shop, which utilizes the building for auto repairs and exterior detailing. Past Use of the Site: A former on-site dry well and former fuel and waste oil underground storage tanks (USTs) appear to be the sources of on-site contamination. There also appears to be an off-site source of 1,1,1 TCA entering the property from the east. Site Geology and Hydrogeology: The site consists of approximately 2 feet of fill, represented by dark gray to black fine coarse sand and gravel with fragments of coal, underlined by light gray to yellow-brown, well sorted fine-medium sand to a depth of 40 feet below grade. Groundwater depth at the site ranges from approximately 25 to 29 feet below grade. Groundwater flows to the north-northwest.
Env Problem: Nature and Extent of Contamination: Remediation at the site is complete. The primary contaminants of concern include Tetrachloroethene (PCE) and related daughter products and residual petroleum contamination in shallow site soils, groundwater and/or soil vapor. An unknown off-site source of 1,1,1 TCA is also impacting site groundwater. Residual contamination in the soil, groundwater and soil vapor are being managed under a Site Management Plan.
Health Problem: Since some contaminated soils remain at the site below the building foundation or pavement, people will not come in contact with contaminated soils unless they dig below the surface materials. Contaminated groundwater in the area is not used for drinking or other purposes and the site is served by a public water supply. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. If the site is redeveloped, the need to take measures to prevent soil vapor intrusion will be re-evaluated. There are no off-site soil vapor concerns associated with this site. However, there is the potential for soil vapor intrusion concerns in off-site buildings due to the presence of off-site contamination not related to this site.
Dump: Not reported
Structure: Not reported

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Lagoon: Not reported
Landfill: Not reported
Pond: Not reported
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: Not reported
Record Upd: Not reported
Updated By: Not reported
Own Op: 1
Sub Type: NNN
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York, Inc. (AAA)
Owner Address: 1415 KELLUM PLACE
Owner Addr2: Not reported
Owner City,St,Zip: GARDEN CITY, NY 11530
Owner Country: United States of America
Own Op: 6
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Place
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
Own Op: 4
Sub Type: NNN
Owner Name: RJT MOROTIST SERVICES
Owner Company: RJT MOROTIST SERVICES
Owner Address: 101 WESTMORELAND AVENUE
Owner Addr2: Not reported
Owner City,St,Zip: WHITE PLAINS, NY 10606
Owner Country: United States of America
Own Op: 4
Sub Type: Not reported
Owner Name: Jack Byrnes
Owner Company: Automobile Club of New York
Owner Address: 1415 Kellum Pl
Owner Addr2: Not reported
Owner City,St,Zip: Garden City, NY 11530
Owner Country: United States of America
HW Code: Not reported
Waste Type: Not reported
Waste Quantity: Not reported
Waste Code: Not reported
Crossref ID: D3-0504-06-09
Cross Ref Type Code: 23
Cross Ref Type: Agreement/Consent Order Number
Record Added Date: 5/4/2015 3:12:00 PM
Record Updated: 5/4/2015 3:12:00 PM
Updated By: JLVERRIG
Crossref ID: Not reported
Cross Ref Type Code: 25
Cross Ref Type: County Recording Identifier
Record Added Date: 7/14/2017 8:08:00 AM
Record Updated: 7/14/2017 8:08:00 AM

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Updated By: JLVERRIG

SPILLS:

Name:	AUTOMOBILE CLUB OF NY
Address:	101 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0102386 / 2005-03-22
Facility ID:	0102386
Facility Type:	ER
DER Facility ID:	100883
Site ID:	276229
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2001-06-02
Investigator:	jkomara
Referred To:	Not reported
Reported to Dept:	2001-06-02
CID:	281
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-06-02
Spill Record Last Update:	2005-03-23
Spiller Name:	SAME
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	BILLY MCBRIDE
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'MARA 12/04/2001 LETTER SENT TO AUTOMOBILE CLUB BY B. MCDONALD (WCDOH); LAB REPORT INDICAATES GW HAS BEEN IMPACTED. BASED ON RESULTS OF ADDITIONAL SAMPLING PERIODS, FURTHER ACTION MAY BE REQUIRED. 04-24-02 LETTER FROM B MCDONALD SENT TO AUTO CLUB STATING THAT GW SAMPLES EXCEED STATE GUIDELINES. REPORT SENT TO O'MARA FOR REVIEW BY DEC. 3/22/05 minimal petroleum contamination; various solvents up to approx 140ppm--close and refer to haz sites"
Remarks:	"SUSPECTED TANK FAILURE AT ABOVE LOCATION. #2 FUEL OIL IS A 550 GALLON UNDERGROUND TANK. WASTE OIL IS A 250 GALLON UNDERGROUND TANK. TANKS HAVE BEEN REMOVED AND EXCAVATION IS UNDERWAY AT SITE."

All Materials:

Site ID:	276229
Operable Unit ID:	839144
Operable Unit:	01
Material ID:	534501
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	276229
Operable Unit ID:	839144
Operable Unit:	01
Material ID:	534502
Material Code:	0022
Material Name:	waste oil/used oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Name:	RJT MOTORS
Address:	101 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0300596 / 2003-07-09
Facility ID:	0300596
Facility Type:	ER
DER Facility ID:	100883
Site ID:	115839
DEC Region:	3
Spill Cause:	Other
Spill Class:	C4
SWIS:	6017
Spill Date:	2003-02-15
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH DEPT
Reported to Dept:	2003-04-16
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-04-16
Spill Record Last Update:	2007-03-06
Spiller Name:	Not reported
Spiller Company:	RJT MOTORS
Spiller Address:	101 WESTMORELAND AV
Spiller Company:	001
Contact Name:	CHUCK BUTTERSWORTH
DEC Memo:	""
Remarks:	"CALLER STATES HE WAS HIRED BY THE TRUCKING COMPANY'S INSURANCE COMPANY TO CLEAN UP THE AREA OF A TRUCK FIRE THAT OCCURED IN FEBRUARY - CALLER STATED THE FUEL TANK RUPTURED DURING THE FIRE AND IT WAS NOT NOTICED UNTIL THE SNOW MELTED"

AUTOMOBILE CLUB OF NEW YORK (Continued) **S105057848**

All Materials:

Site ID:	115839
Operable Unit ID:	866954
Operable Unit:	01
Material ID:	508676
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	25.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AU328 **A & S STORE** **NY LTANKS** **S100136963**
North **GALLERIA PLAZA** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.319 mi.
1686 ft. **Site 1 of 4 in cluster AU**

Relative: **Lower**
Actual: **193 ft.**

LTANKS:

Name:	A & S STORE
Address:	GALLERIA PLAZA
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8803673 / 1988-08-09
Facility ID:	8803673
Site ID:	187318
Spill Date:	1988-07-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-08-09
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-07-27
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-02
Spill Record Last Update:	2003-12-02
Spiller Name:	Not reported
Spiller Company:	DENNIS MURPHY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	156504
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was J

A & S STORE (Continued) **S100136963**

OKESSON "
Remarks: "10K -.155 PBS TO FOLLOW UP. NFA"

All TTF:
Facility ID: 8803673
Spill Number: 8803673
Spill Tank Test: 1534356
Site ID: 187318
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 187318
Operable Unit ID: 918836
Operable Unit: 01
Material ID: 459213
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AU329 **A&S STORE** **NY LTANKS** **S100137114**
North **GALLERIA PLAZA** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.319 mi.
1686 ft. **Site 2 of 4 in cluster AU**

Relative: LTANKS:
Lower
Actual: Name: A&S STORE
193 ft. Address: GALLERIA PLAZA
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 8805571 / 1989-03-07
Facility ID: 8805571
Site ID: 187319
Spill Date: 1988-09-29
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: Not reported
Cleanup Ceased: 1989-03-07
SWIS: 6017
Investigator: tdghiosa
Referred To: Not reported

A&S STORE (Continued) **S100137114**

Reported to Dept:	1988-09-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-10-19
Spill Record Last Update:	1989-03-07
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	156504
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/07/89: TANK WAS RELINED AND PUT BACK INTO SERVIVE. 03/07/89: TANK WAS RELINED AND PUT BACK INTO SERVIVE. "
Remarks:	"-.068 GPH; NO COMMENTS (RETEST). 10K TANK. PBS #173665"

All TTF:

Facility ID:	8805571
Spill Number:	8805571
Spill Tank Test:	1534700
Site ID:	187319
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	187319
Operable Unit ID:	920745
Operable Unit:	01
Material ID:	457473
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

330 South 1/4-1/2 0.326 mi. 1723 ft. | **SAVANELLA HOME**
29 PROSPECT STREET
WHITE PLAINS, NY | **NY LTANKS** | **S109064241**
N/A

Relative: Higher

Actual: 292 ft.

LTANKS:

Name:	SAVANELLA HOME
Address:	29 PROSPECT STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0800443 / 2008-06-08
Facility ID:	0800443
Site ID:	396199
Spill Date:	2008-04-11
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-04-11
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-04-11
Spill Record Last Update:	2008-06-08
Spiller Name:	LEONARD SAVANELLA
Spiller Company:	SAVANELLA HOME
Spiller Address:	29 PROSPECT STREET
Spiller County:	001
Spiller Contact:	LEONARD SAVANELLA
Spiller Phone:	(914) 815-5080
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	345695
DEC Memo:	"June 8, 2008: Tank passed a retest after piping was repaired. Based upon information provided to DEC, no further action is required at this time. jod"
Remarks:	"uncover repair and test"

All TTF:

Facility ID:	0800443
Spill Number:	0800443
Spill Tank Test:	2453493
Site ID:	396199
Tank Number:	Not reported
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	True
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II

SAVANELLA HOME (Continued) **S109064241**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 396199
Operable Unit ID: 1153145
Operable Unit: 01
Material ID: 2143923
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

331
NNW
1/4-1/2
0.327 mi.
1726 ft.

J C PENNEY CO INC
100 MAIN ST
WHITE PLAINS, NY 10601

NY LTANKS **1000912475**
NY Spills **NY0000806901**
RCRA NonGen / NLR
NY MANIFEST

Relative:
Lower

Actual:
198 ft.

LTANKS:
Name: GALLARIA
Address: 100 MAIN STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9102767 / 1991-06-13
Facility ID: 9102767
Site ID: 137993
Spill Date: 1991-06-10
Spill Cause: Tank Overfill
Spill Source: Tank Truck
Spill Class: Not reported
Cleanup Ceased: 1953-06-18
SWIS: 6017
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1991-06-10
CID: Not reported
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1991-06-13
Spill Record Last Update: 1991-07-10
Spiller Name: Not reported
Spiller Company: CASTLE OIL
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: Not reported

J C PENNEY CO INC (Continued) **1000912475**

Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	118002
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"CONTAINED ON SIDEWALK CASTLE OIL TO CLEAN UP"

All Materials:

Site ID:	137993
Operable Unit ID:	956636
Operable Unit:	01
Material ID:	425258
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GALLERIA MALL
Address:	100 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0302779 / 2003-06-16
Facility ID:	0302779
Facility Type:	ER
DER Facility ID:	118002
Site ID:	137992
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2003-06-16
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-06-16
CID:	204
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-06-16
Spill Record Last Update:	2003-06-18
Spiller Name:	Not reported
Spiller Company:	GALLERIA MALL
Spiller Address:	100 MAIN STREET
Spiller Company:	001
Contact Name:	PATRICK MURPHY

J C PENNEY CO INC (Continued) **1000912475**

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks: "SUBJECT STUCK IN ELEVATOR - FIRE DEPARTMENT ON SCENE "

All Materials:
Site ID: 137992
Operable Unit ID: 870528
Operable Unit: 01
Material ID: 507231
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 20.00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: J.C.PENNY DEPT. STORE
Address: 100 MAIN STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9204133 / 1992-08-04
Facility ID: 9204133
Facility Type: ER
DER Facility ID: 118002
Site ID: 137995
DEC Region: 3
Spill Cause: Unknown
Spill Class: C3
SWIS: 6017
Spill Date: 1992-07-10
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1992-07-10
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: 1992-08-04
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1992-07-13
Spill Record Last Update: 1995-05-19
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "OIL DISCOVERED IN BASEMENT SUMP; SUMP PUMP WAS BROKEN AND TO BE REPAIRED WHEN OIL WAS DISCOVERED LUZON TO VAC SUMP PICK UP AND DISPOSE TODD GHIOSAY NOTIFIED"

J C PENNEY CO INC (Continued) **1000912475**

All Materials:

Site ID:	137995
Operable Unit ID:	967942
Operable Unit:	01
Material ID:	411881
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GALLERIA MALL
Address:	100 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0703055 / 2007-06-14
Facility ID:	0703055
Facility Type:	ER
DER Facility ID:	118002
Site ID:	382912
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	C4
SWIS:	6017
Spill Date:	2007-06-13
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2007-06-14
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Health Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-06-14
Spill Record Last Update:	2007-06-14
Spiller Name:	DENISE
Spiller Company:	GALLERIA MALL
Spiller Address:	100 MAIN STREET
Spiller Company:	001
Contact Name:	DENISE
DEC Memo:	"7/14/07 WPPD reported that the WPFD recovered the gas. NFA TG"
Remarks:	"a person dumped out his gas into storm drain when he could not return it: less then 1 gallon"

All Materials:

Site ID:	382912
Operable Unit ID:	1140291
Operable Unit:	01
Material ID:	2130355

J C PENNEY CO INC (Continued) **1000912475**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	GALLERIA MALL
Address:	100 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0211359 / 2005-02-27
Facility ID:	0211359
Facility Type:	ER
DER Facility ID:	118002
Site ID:	104864
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2003-02-13
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2003-02-13
CID:	297
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-13
Spill Record Last Update:	2005-02-27
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	D.C. CIOCCA - WPFD
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was 2/27/05 surface spill from vehicle--close "
Remarks:	"WHITE PLAINS FD ON SCENE AND THEY NEED A RESPONSE FROM DEC"

All Materials:

Site ID:	104864
Operable Unit ID:	864691
Operable Unit:	01
Material ID:	565743
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G

J C PENNEY CO INC (Continued) **1000912475**

Recovered: .00
Oxygenate: Not reported

RCRA NonGen / NLR:

Date Form Received by Agency:	2007-01-01 00:00:00.0
Handler Name:	J C PENNEY CO INC
Handler Address:	100 MAIN ST
Handler City,State,Zip:	WHITE PLAINS, NY 10601
EPA ID:	NY0000806901
Contact Name:	Not reported
Contact Address:	PO BOX 250
Contact City,State,Zip:	WAYNE, NY 07470
Contact Telephone:	Not reported
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	Not reported
EPA Region:	02
Land Type:	Not reported
Federal Waste Generator Description:	Not a generator, verified
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Not reported
State District Owner:	NY
State District:	NYSDEC R3
Mailing Address:	PO BOX 250
Mailing City,State,Zip:	WAYNE, NY 07470
Owner Name:	J C PENNEY CO INC
Owner Type:	Private
Operator Name:	J C PENNEY CO INC
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site Fed-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site Converter Treatment storage and Disposal Facility:	Not reported
Active Site State-Reg Treatment Storage and Disposal Facility:	Not reported
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	NN
Sub-Part K Indicator:	Not reported
Commercial TSD Indicator:	No
Treatment Storage and Disposal Type:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
Permit Renewals Workload Universe:	Not reported

J C PENNEY CO INC (Continued) **1000912475**

Permit Workload Universe:	Not reported
Permit Progress Universe:	Not reported
Post-Closure Workload Universe:	Not reported
Closure Workload Universe:	Not reported
202 GPRA Corrective Action Baseline:	No
Corrective Action Workload Universe:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe:	No
TSDFs Only Subject to CA under Discretionary Auth Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Operating TSDF Universe:	Not reported
Full Enforcement Universe:	Not reported
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	2015-04-14 00:00:00.0
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	Not reported
Manifest Broker:	Not reported
Sub-Part P Indicator:	Not reported

Hazardous Waste Summary:

Waste Code:	D002
Waste Description:	CORROSIVE WASTE
Waste Code:	NONE
Waste Description:	Not Defined

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	J C PENNEY CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1001
Owner/Operator City,State,Zip:	DALLAS, TX 75301-0001
Owner/Operator Telephone:	214-591-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Owner
Owner/Operator Name:	J C PENNEY CO INC
Legal Status:	Private
Date Became Current:	Not reported

J C PENNEY CO INC (Continued) **1000912475**

Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1001
Owner/Operator City,State,Zip:	DALLAS, TX 75301-0001
Owner/Operator Telephone:	214-591-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported
Owner/Operator Indicator:	Operator
Owner/Operator Name:	J C PENNEY CO INC
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 1001
Owner/Operator City,State,Zip:	DALLAS, TX 75301-0001
Owner/Operator Telephone:	214-591-1000
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	1995-01-24 00:00:00.0
Handler Name:	J C PENNEY CO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2006-01-01 00:00:00.0
Handler Name:	J C PENNEY CO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	2007-01-01 00:00:00.0
Handler Name:	J C PENNEY CO INC
Federal Waste Generator Description:	Not a generator, verified
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

J C PENNEY CO INC (Continued) **1000912475**

Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported
Receive Date:	1994-09-20 00:00:00.0
Handler Name:	J C PENNEY CO INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	NY
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	No
Non Storage Recycler Activity:	Not reported
Electronic Manifest Broker:	Not reported

List of NAICS Codes and Descriptions:

NAICS Codes:	No NAICS Codes Found

Facility Has Received Notices of Violations:

Violations:	No Violations Found

Evaluation Action Summary:

Evaluations:	No Evaluations Found

NY MANIFEST:

Name:	J C PENNEYS
Address:	100 MAIN ST
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NY0000806901
Facility Status:	Not reported
Location Address 1:	100 MAIN ST
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NY0000806901
Mailing Name:	J C PENNEYS
Mailing Contact:	ROY LANGBRIDGE
Mailing Address 1:	P O BOX 250 RT 46
Mailing Address 2:	Not reported
Mailing City:	WHITE PLAINS
Mailing State:	NY
Mailing Zip:	10601
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	2017851881

J C PENNEY CO INC (Continued) **1000912475**

NY MANIFEST:

Document ID:	NYB4480794
Manifest Status:	K
seq:	Not reported
Year:	1994
Trans1 State ID:	TW56975PA
Trans2 State ID:	Not reported
Generator Ship Date:	10/26/1994
Trans1 Recv Date:	10/26/1994
Trans2 Recv Date:	/ /
TSD Site Recv Date:	11/01/1994
Part A Recv Date:	11/30/1994
Part B Recv Date:	11/18/1994
Generator EPA ID:	NY0000806901
Trans1 EPA ID:	PAD064035819
Trans2 EPA ID:	Not reported
TSDF ID 1:	NCD980842132
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00075
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100
Waste Code:	D002 - NON-LISTED CORROSIVE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00100
Units:	P - Pounds
Number of Containers:	001
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

AU332 **NY TEL** **NY LTANKS** **S101102877**
North **111 EAST MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.329 mi.
1737 ft. **Site 3 of 4 in cluster AU**

Relative: **Lower**

Actual: **192 ft.**

LTANKS:

Name:	NY TEL
Address:	111 EAST MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9314933 / 1995-03-01
Facility ID:	9314933
Site ID:	145113
Spill Date:	1994-03-21
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	1995-03-01
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1994-03-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1994-03-22
Spill Record Last Update:	1995-03-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	123666
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"E I R UST 2000"

All TTF:

Facility ID:	9314933
Spill Number:	9314933
Spill Tank Test:	1542517
Site ID:	145113
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

NY TEL (Continued) **S101102877**

Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	145113
Operable Unit ID:	993211
Operable Unit:	01
Material ID:	386709
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	NYNEX
Address:	111 MAIN ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9609101 / 1999-11-26
Facility ID:	9609101
Site ID:	239422
Spill Date:	1996-10-21
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-10-21
CID:	365
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1996-10-21
Spill Record Last Update:	1999-12-06
Spiller Name:	Not reported
Spiller Company:	NYNEX
Spiller Address:	111 MAIN ST
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(914) 793-5200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	196913
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/26/99 FEBRUARY 1998 TANK CLOSURE REPORT PREPARED BY S&W SERVICES DOCUMENTING TWO 20K DIESEL TANK REMOVALS. HAS BEEN REVIEWED.

NY TEL (Continued) **S101102877**

524.7 TONS OF CONTAMINATED SOIL REMOVED. NFA"
Remarks: "DURING REMOVAL OF TWO TANKS THEY FOUND CONTAMINATED SOIL UNDER THE SECOND TANK"

All Materials:
Site ID: 239422
Operable Unit ID: 1040314
Operable Unit: 01
Material ID: 344831
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: BELL ATLANTIC
Address: 111 MAIN ST
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9808850 / 1998-10-16
Facility ID: 9808850
Facility Type: ER
DER Facility ID: 196913
Site ID: 239423
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 6017
Spill Date: 1998-10-15
Investigator: tdghiosa
Referred To: Not reported
Reported to Dept: 1998-10-16
CID: 384
Water Affected: Not reported
Spill Source: Institutional, Educational, Gov., Other
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-10-16
Spill Record Last Update: 1998-10-21
Spiller Name: TOM OBRIEN
Spiller Company: BELL ATLANTIC
Spiller Address: 111 MAIN ST
Spiller Company: 001
Contact Name: TOM OBRIEN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks: "RUPTURE IN THE LINE CAUSED SPILL ON THE 5TH FLOOR OF BLDG. UNSURE IF IT GOT INTO STORM DRAIN."

NY TEL (Continued) **S101102877**

All Materials:

Site ID:	239423
Operable Unit ID:	1066233
Operable Unit:	01
Material ID:	566481
Material Code:	0028A
Material Name:	ethylene glycol
Case No.:	00107211
Material FA:	Hazardous Material
Quantity:	700.00
Units:	G
Recovered:	700.00
Oxygenate:	Not reported

AU333 **CENTROPLEX ASSOC.** **NY LTANKS** **S104278796**
North **123 MAIN STREET** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.329 mi.
1739 ft. **Site 4 of 4 in cluster AU**

Relative: **Lower**
Actual: **195 ft.**

LTANKS:

Name:	ODDESY CORP MAINT DEPT
Address:	123 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8906607 / 1991-06-12
Facility ID:	8906607
Site ID:	160999
Spill Date:	1989-10-04
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-10-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-10-16
Spill Record Last Update:	2003-09-26
Spiller Name:	Not reported
Spiller Company:	ODDESY CORP MAINT DEPT
Spiller Address:	123 MAIN ST
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

CENTROPLEX ASSOC. (Continued) **S104278796**

GHIOSAY "
Remarks: "PETRO TITE, 10K, -.483 GPH, SYSTEM FAILED W/PLUMBING INCLUDED. WILL E.I.R. NEXT WEEK THEY PLAN TO ISOLATE TANK TO RETEST. PASSED RETEST"

All TTF:
Facility ID: 8906607
Spill Number: 8906607
Spill Tank Test: 1536167
Site ID: 160999
Tank Number: Not reported
Tank Size: 0
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 00
Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 160999
Operable Unit ID: 931611
Operable Unit: 01
Material ID: 447023
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: OFFICE BLDG
Address: 123 MAIN STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9910168 / 1999-11-22
Facility ID: 9910168
Site ID: 161000
Spill Date: 1999-11-19
Spill Cause: Tank Overfill
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: PJDECICC
Referred To: Not reported
Reported to Dept: 1999-11-22
CID: 323
Water Affected: Not reported
Spill Notifier: Affected Persons
Last Inspection: Not reported

CENTROPLEX ASSOC. (Continued) **S104278796**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-22
Spill Record Last Update:	2000-01-26
Spiller Name:	JOHN MORABIDO
Spiller Company:	COMFORCE (CONTRACTOR)
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	JOSEPH DOSSO
Spiller Phone:	(914) 287-3144
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was DECICCO 11/22/99 OVERFOLD VALVE LET GO WHEN TESTING GENERATOR; CONTAINED IN CONCRETE CONTAINMENT. NFA"
Remarks:	"ON A Y2K GENERATOR ON THE 17TH FLOOR. SPILL WAS CLEANED UP. "

All Materials:

Site ID:	161000
Operable Unit ID:	1084933
Operable Unit:	01
Material ID:	555904
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	42.00
Units:	G
Recovered:	42.00
Oxygenate:	Not reported

Name:	CENTROPLEX ASSOC.
Address:	123 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8907663 / 1991-06-12
Facility ID:	8907663
Site ID:	74955
Spill Date:	1989-11-01
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-11-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

CENTROPLEX ASSOC. (Continued) **S104278796**

Date Entered In Computer:	1989-11-09
Spill Record Last Update:	1993-12-09
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	70243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH "
Remarks:	"HIRED CASTLE OIL CO. TO PUMP OUT WILL RETEST SPILL # 8906607 IS THE ORIGINAL # GIVEN TO THIS SITE REFER TO 8906607 FOR MORE INFORMATION PASSED RETEST"

All TTF:

Facility ID:	8907663
Spill Number:	8907663
Spill Tank Test:	1536349
Site ID:	74955
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	74955
Operable Unit ID:	935283
Operable Unit:	01
Material ID:	444449
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	SHARP
Address:	123 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8606381 / 1987-03-16
Facility ID:	8606381

CENTROPLEX ASSOC. (Continued) **S104278796**

Facility Type:	ER
DER Facility ID:	70243
Site ID:	160998
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1987-01-13
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-01-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Unknown
Spill Notifier:	Affected Persons
Cleanup Ceased:	1987-03-16
Cleanup Meets Std:	True
Last Inspection:	1987-03-16
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-09
Spill Record Last Update:	1988-02-24
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	""
Remarks:	""

All Materials:

Site ID:	160998
Operable Unit ID:	903964
Operable Unit:	01
Material ID:	475507
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

AT334 **SPILL NUMBER 8809894** **NY LTANKS** **S104619049**
NE **23 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.332 mi.
1751 ft. **Site 2 of 4 in cluster AT**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Name:	SPILL NUMBER 8809894
Address:	23 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8809894 / 1991-12-20
Facility ID:	8809894

SPILL NUMBER 8809894 (Continued) **S104619049**

Site ID:	286069
Spill Date:	1989-03-23
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1989-03-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-03-28
Spill Record Last Update:	2003-09-19
Spiller Name:	Not reported
Spiller Company:	SEA MGT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	231859
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"PLUMBING LEAKED DURING FILLING FOR TEST. TO ISOLATE, EXCAVATE AND RETEST."

All TTF:

Facility ID:	8809894
Spill Number:	8809894
Spill Tank Test:	1535281
Site ID:	286069
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286069
Operable Unit ID:	926206
Operable Unit:	01

SPILL NUMBER 8809894 (Continued) **S104619049**

Material ID:	451068
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV335 **PVT DWELLING** **NY LTANKS** **S110140532**
WSW **195 FISHER AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.334 mi.
1762 ft. **Site 1 of 2 in cluster AV**

Relative: **Higher**
Actual: **239 ft.**

LTANKS:

Name:	PVT DWELLING
Address:	195 FISHER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0909891 / 2014-01-16
Facility ID:	0909891
Site ID:	422623
Spill Date:	2009-12-07
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D5
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2009-12-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-07
Spill Record Last Update:	2020-07-22
Spiller Name:	SID WALKER
Spiller Company:	PVT DWELLING
Spiller Address:	195 FISHER AVE
Spiller County:	999
Spiller Contact:	KEITH SINISTORE
Spiller Phone:	(845) 255-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	371554
DEC Memo:	"12/7/09 Tank tester says house is owned by bank, who would not divulge any other info. dw 1/16/14 With Albany's OK any HOTTF with no indication odf a spill will be closed or assigned to someone after 3 years. NFA JO'M"
Remarks:	"TANK TEST FAILURE ON A 550 GALLON UST."

PVT DWELLING (Continued) **S110140532**

All Materials:

Site ID:	422623
Operable Unit ID:	1178458
Operable Unit:	01
Material ID:	2171834
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

336
NE
1/4-1/2
0.336 mi.
1772 ft.

APARTMENT BUILDING **NY LTANKS** **S106124534**
193 EAST POST ROAD **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
218 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	193 EAST POST ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0310631 / 2005-10-11
Facility ID:	0310631
Site ID:	158568
Spill Date:	2003-12-15
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-15
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-15
Spill Record Last Update:	2005-11-01
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	PAOLA CORONEL
Spiller Phone:	(914) 747-9741
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	133999
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

APARTMENT BUILDING (Continued) **S106124534**

WCHD-JACKSON 10/11/05 letter from Barbara McDonald of WCDH to Virginia Manning saying submittals have been reviewed. NFA."
Remarks: "tank test failed. not yet being cleaned up."

All TTF:
Facility ID: 0310631
Spill Number: 0310631
Spill Tank Test: 1528864
Site ID: 158568
Tank Number: 1
Tank Size: 3000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 158568
Operable Unit ID: 875713
Operable Unit: 01
Material ID: 499481
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: L
Recovered: .00
Oxygenate: Not reported

AT337 **SPILL NUMBER 9905959** **NY LTANKS** **S104620381**
NE **25 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.336 mi.
1775 ft. **Site 3 of 4 in cluster AT**

Relative: **Higher**
Actual: **218 ft.**

LTANKS:
Name: SPILL NUMBER 9905959
Address: 25 MITCHELL PLACE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 9905959 / 1999-10-08
Facility ID: 9905959
Site ID: 111332
Spill Date: 1999-08-17
Spill Cause: Tank Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD

SPILL NUMBER 9905959 (Continued) **S104620381**

Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-08-18
CID:	388
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-08-18
Spill Record Last Update:	1999-10-27
Spiller Name:	JAMES MA
Spiller Company:	W P M V INC
Spiller Address:	200 E 61ST ST SUITE 4G
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	(914) 472-8779
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	97378
DEC Memo:	""
Remarks:	"caller reports they went to clean tank and they saw holes in the tank."

All Materials:

Site ID:	111332
Operable Unit ID:	1084404
Operable Unit:	01
Material ID:	553103
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

338
WSW
1/4-1/2
0.339 mi.
1791 ft.

SPILL NUMBER 9807488 **NY LTANKS** **S104619697**
8 ORCHARD PARKWAY **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
301 ft.

LTANKS:

Name:	COOLIER-DESALLIER
Address:	8 ORCHARD PARKWAY
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8706819 / 1989-11-29
Facility ID:	8706819
Site ID:	135632
Spill Date:	1987-11-10
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	Not reported
Cleanup Ceased:	1989-11-29

SPILL NUMBER 9807488 (Continued) **S104619697**

SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-10
CID:	Not reported
Water Affected:	NONE
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-18
Spill Record Last Update:	1989-11-29
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116463
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was / / : 11/10/87-WILL RETEST. "
Remarks:	"TTTF-1.5K TANK,HIGH VOLUME LEAK"

All TTF:

Facility ID:	8706819
Spill Number:	8706819
Spill Tank Test:	1532235
Site ID:	135632
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	135632
Operable Unit ID:	910699
Operable Unit:	01
Material ID:	465813
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

SPILL NUMBER 9807488 (Continued) **S104619697**

Recovered:	.00
Oxygenate:	Not reported
Name:	SPILL NUMBER 9807488
Address:	8 ORCHARD PARKWAY
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9807488 / 1998-11-20
Facility ID:	9807488
Site ID:	135633
Spill Date:	1998-09-18
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-09-18
CID:	384
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-18
Spill Record Last Update:	1999-03-15
Spiller Name:	CHARLES COOLER-DESOLLIERS
Spiller Company:	CHARLES COOLER-DESOLLIERS
Spiller Address:	8 ORCHARD PARKWAY
Spiller County:	001
Spiller Contact:	CHARLES COOLER-DESOLLIERS
Spiller Phone:	(914) 683-1718
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116463
DEC Memo:	""
Remarks:	"Renewal test. Tank removed by NES - no discharge."

All TTF:

Facility ID:	9807488
Spill Number:	9807488
Spill Tank Test:	1546271
Site ID:	135633
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills

SPILL NUMBER 9807488 (Continued) **S104619697**

Last Modified Date: Not reported

All Materials:
Site ID: 135633
Operable Unit ID: 1065052
Operable Unit: 01
Material ID: 318572
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

AW339 **VINTAGE RESTAURANT** **NY LTANKS** **S108059295**
North **171-173 MAIN STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.340 mi.
1796 ft. **Site 1 of 2 in cluster AW**

Relative: **Lower**
Actual: **205 ft.**

LTANKS:
Name: VINTAGE RESTAURANT
Address: 171-173 MAIN STREET
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0602861 / 2008-09-26
Facility ID: 0602861
Site ID: 365437
Spill Date: 2006-06-14
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2006-06-14
CID: 444
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2006-06-14
Spill Record Last Update: 2008-09-26
Spiller Name: JOHN HAMILTON
Spiller Company: SINGER TRUSTEE
Spiller Address: Not reported
Spiller County: 999
Spiller Contact: MIKE
Spiller Phone: (516) 924-3824
Spiller Extention: Not reported
DEC Region: 3

VINTAGE RESTAURANT (Continued) **S108059295**

DER Facility ID: 315576
DEC Memo: "6/14/06 Pro Test on site to test the 1500 gallon tank as ordered by the DEC. Tester couldn't get vacuum on the tank. Andre from ProTest said the cement on top of the tank needs to be removed to expose all of the bungs and piping. Once that is performed, then the tank can be isolated and tested. Visual observation revealed that the steel on the top of the tank was very heavily corroded. TG 06/29/06 AM - ProTest back on site retesting the lines and the tank. Andre reported that the vent line and the remote fill line both failed the test. The tank failed to hold a vacuum therefore, it also failed. Andre recommending unearthing the manway and checking that for a definitive answer on the tank failure. However this can't be accomplished until a refrigeration compressor is moved which will require a refrigeration mechanic. TG 06/29/06 John Leddy from ProTest officially reported that the tank failed and that the tank has lost two inches of oil since the 14th and the tank is not being used. Recommending emptying the tank to their client. TG 07/05/06 Joe Ostrosky from Petroleum Tank Cleaners (PTC) reported that PTC was hired to remove the oil from the tank. The tank has been emptied, cut open and cleaned. TG 11/15/06 New England Tank Services has completed the removal of the tank, allowing for an inspection. Substantial corrosion and numerous holes were observed. A letter was sent to the management company requiring the installation of two monitoring wells. 03/12/07 Monitoring well installation report submitted by JM Associates who were subcontracted by Fleet Environmental. No free product was detected in the wells. TG 07/30/07 New England Tank Services reported that they removed the tank along with 2.64 tons of petroleum contaminated soil. TG "
Remarks: ""

All TTF:
Facility ID: 0602861
Spill Number: 0602861
Spill Tank Test: 1550055
Site ID: 365437
Tank Number: 1
Tank Size: 1500
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Watchdog
Last Modified Date: Not reported

All Materials:
Site ID: 365437
Operable Unit ID: 1123455
Operable Unit: 01
Material ID: 2112912
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported

VINTAGE RESTAURANT (Continued) **S108059295**

Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	VINTAGE RESTAURANT
Address:	171-173 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0602861 / 2008-09-26
Facility ID:	0602861
Site ID:	365437
Spill Date:	2006-06-14
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2006-06-14
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-14
Spill Record Last Update:	2008-09-26
Spiller Name:	FREDERICK SASSE
Spiller Company:	SINGER TRUST C/O GEORGE A BOWNMAN INC
Spiller Address:	36 W 44TH ST. SUIT 810
Spiller County:	001
Spiller Contact:	MIKE
Spiller Phone:	(516) 924-3824
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	315576
DEC Memo:	"6/14/06 Pro Test on site to test the 1500 gallon tank as ordered by the DEC. Tester couldn't get vacuum on the tank. Andre from ProTest said the cement on top of the tank needs to be removed to expose all of the bungs and piping. Once that is performed, then the tank can be isolated and tested. Visual observation revealed that the steel on the top of the tank was very heavily corroded. TG 06/29/06 AM - ProTest back on site retesting the lines and the tank. Andre reported that the vent line and the remote fill line both failed the test. The tank failed to hold a vacuum therefore, it also failed. Andre recommending unearthing the manway and checking that for a definitive answer on the tank failure. However this can't be accomplished until a refrigeration compressor is moved which will require a refrigeration mechanic. TG 06/29/06 John Leddy from ProTest officially reported that the tank failed and that the tank has lost two inches of oil since the 14th and the tank is not being used. Recommending emptying the tank to their client. TG 07/05/06 Joe

VINTAGE RESTAURANT (Continued) **S108059295**

Ostrosky from Petroleum Tank Cleaners (PTC) reported that PTC was hired to remove the oil from the tank. The tank has been emptied, cut open and cleaned. TG 11/15/06 New England Tank Services has completed the removal of the tank, allowing for an inspection. Substantial corrosion and numerous holes were observed. A letter was sent to the management company requiring the installation of two monitoring wells. 03/12/07 Monitoring well installation report submitted by JM Associates who were subcontracted by Fleet Environmental. No free product was detected in the wells. TG 07/30/07 New England Tank Services reported that they removed the tank along with 2.64 tons of petroleum contaminated soil. TG "

Remarks: ""

All TTF:

Facility ID:	0602861
Spill Number:	0602861
Spill Tank Test:	1550055
Site ID:	365437
Tank Number:	1
Tank Size:	1500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	365437
Operable Unit ID:	1123455
Operable Unit:	01
Material ID:	2112912
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

340 **JANOWSKI RESIDENCE** **NY LTANKS** **S108059274**
WSW **2 RIDGEVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.341 mi.
1801 ft.

Relative: **Higher**

Actual: **285 ft.**

LTANKS:

Name:	JANOWSKI RESIDENCE
Address:	2 RIDGEVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0602736 / 2006-07-30

JANOWSKI RESIDENCE (Continued) **S108059274**

Facility ID:	0602736
Site ID:	365284
Spill Date:	2006-06-12
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2006-06-12
CID:	409
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2006-06-12
Spill Record Last Update:	2006-07-30
Spiller Name:	MANFRED JANOWSKI
Spiller Company:	JANOWSKI RESIDENCE
Spiller Address:	2 RIDGEVIEW AVE
Spiller County:	001
Spiller Contact:	MANFRED JANOWSKI
Spiller Phone:	(914) 428-4573
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	315434
DEC Memo:	"July 30, 2006: NES REMOVED AND DISPOSED OF TANK. NO EVIDENCE OF LEAK OR CONTAMINATION WAS FOUND. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"UNCOVER REPAIR AND RETEST."

All TTF:

Facility ID:	0602736
Spill Number:	0602736
Spill Tank Test:	1550047
Site ID:	365284
Tank Number:	1
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

Facility ID:	0602736
Spill Number:	0602736
Spill Tank Test:	1550048
Site ID:	365284

JANOWSKI RESIDENCE (Continued) **S108059274**

Tank Number:	Not reported
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	365284
Operable Unit ID:	1123297
Operable Unit:	01
Material ID:	2112765
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AT341 **28 MITCHELL PLACE** **NY LTANKS** **U003647993**
NE **28 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.345 mi.
1824 ft. **Site 4 of 4 in cluster AT**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Name:	SPILL NUMBER 9901259
Address:	28 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9901259 / 1999-05-13
Facility ID:	9901259
Site ID:	206822
Spill Date:	1999-05-03
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-05-03
CID:	382
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

28 MITCHELL PLACE (Continued) **U003647993**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-05-03
Spill Record Last Update:	1999-07-25
Spiller Name:	PHILLIPS
Spiller Company:	Not reported
Spiller Address:	28 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	PHILLIPS
Spiller Phone:	(914) 472-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	171695
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 5/13/99 TANK PASSED ISOLATION RETEST. LINES TO BE REPLACED. NFA"
	Not reported
Remarks:	"SYSTEM FAILURE. OWNER WAS ADVISED."

All TTF:

Facility ID:	9901259
Spill Number:	9901259
Spill Tank Test:	1547140
Site ID:	206822
Tank Number:	Not reported
Tank Size:	2000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	206822
Operable Unit ID:	1079959
Operable Unit:	01
Material ID:	304805
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	28 MITCHELL PLACE
Address:	28 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9903630 / 2001-11-14
Facility ID:	9903630

28 MITCHELL PLACE (Continued) **U003647993**

Site ID:	206823
Spill Date:	1999-06-29
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-06-29
CID:	388
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-29
Spill Record Last Update:	2003-06-02
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MMP DEVELOPMENT
Spiller Phone:	(914) 725-6858
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	171695
DEC Memo:	""
Remarks:	"CALLER REPORTS PULLING TANK AND THE TANK WAS LEAKING."

All Materials:

Site ID:	206823
Operable Unit ID:	1082559
Operable Unit:	01
Material ID:	303542
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AV342 **9 LAFAYETTE STREET** **NY LTANKS** **S105997345**
West **9 LAFAYETTE STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.345 mi.
1824 ft. **Site 2 of 2 in cluster AV**

Relative:
Higher

Actual:
233 ft.

LTANKS:

Name:	9 LAFAYETTE STREET
Address:	9 LAFAYETTE STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0208594 / 2012-08-13

9 LAFAYETTE STREET (Continued) **S105997345**

Facility ID:	0208594
Site ID:	322970
Spill Date:	2002-11-19
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	2002-11-19
CID:	204
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-19
Spill Record Last Update:	2012-08-13
Spiller Name:	DOROTHY JENSEN REALITY
Spiller Company:	9 LAFAYETTE STREET
Spiller Address:	9 LAFAYETTE STREET
Spiller County:	001
Spiller Contact:	KATHY MORGAN
Spiller Phone:	(845) 225-5240
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	260176
DEC Memo:	"7/28/10 Homeowner TTF JO'M 8/13/12 With Albany and regional approval all Homeowner Tank Test Failure with no impact older than 5 years will be closed. NFA JO M"
Remarks:	"TANK TEST FAILURE"

All TTF:

Facility ID:	0208594
Spill Number:	0208594
Spill Tank Test:	1527730
Site ID:	322970
Tank Number:	Not reported
Tank Size:	0
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Facility ID:	0208594
Spill Number:	0208594
Spill Tank Test:	1527731
Site ID:	322970

9 LAFAYETTE STREET (Continued) **S105997345**

Tank Number:	1
Tank Size:	550
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	322970
Operable Unit ID:	861580
Operable Unit:	01
Material ID:	515595
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AW343 **RESIDENCE** **NY LTANKS** **S102660217**
NNE **185- 187 MAIN ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.347 mi.
1832 ft. **Site 2 of 2 in cluster AW**

Relative:
Lower

Actual:
207 ft.

LTANKS:

Name:	RESIDENCE
Address:	185- 187 MAIN ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9708138 / 1997-11-10
Facility ID:	9708138
Site ID:	81930
Spill Date:	1997-10-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-10-10
CID:	369
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

RESIDENCE (Continued) **S102660217**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-10-10
Spill Record Last Update:	1998-01-29
Spiller Name:	STANLEY DRUCKER
Spiller Company:	Not reported
Spiller Address:	185- 187 MAIN ST
Spiller County:	001
Spiller Contact:	STANLEY DRUCKER
Spiller Phone:	(914) 937-7307
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	75659
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 10/10/97 SOIL TO BE STOCKPILED & DISPOSED; 10/13/97 LUZON TANK REMOVAL IN DOWNTOWN WHITE PLAINS; TANK LOCATED IN BUCK U/G VAULTED, UNDER THE SIDEWALK; ALL CONTAMINATION MATERIAL REMOVED; "
Remarks:	"contaminated soil uncovered during tank removal. tanks in u/g vault filled with dirt-about 4 yards worth. "

All Materials:

Site ID:	81930
Operable Unit ID:	1051362
Operable Unit:	01
Material ID:	330125
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

344 **GATEWAY BLDG** **NY LTANKS** **S100140904**
NNW **1 NORTH LEXINGTON AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.351 mi.
1855 ft.

Relative: **Lower**

Actual: **201 ft.**

LTANKS:

Name:	1 NORTH LEXINGTON AVE
Address:	1 NORTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9000726 / 1991-12-06
Facility ID:	9000726
Site ID:	131721
Spill Date:	1990-04-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1990-04-20
CID:	Not reported

GATEWAY BLDG (Continued) **S100140904**

Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1990-05-30
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	WTT CORP.
Spiller Address:	123 MAIN STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"PETRO-TITE -.344"

All TTF:

Facility ID:	9000726
Spill Number:	9000726
Spill Tank Test:	1536975
Site ID:	131721
Tank Number:	Not reported
Tank Size:	0
Material:	0008
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	131721
Operable Unit ID:	940390
Operable Unit:	01
Material ID:	439098
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

GATEWAY BLDG (Continued) **S100140904**

Name:	GATEWAY BLDG
Address:	1 NORTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9108659 / 1991-11-13
Facility ID:	9108659
Site ID:	255792
Spill Date:	1991-11-13
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	D3
Cleanup Ceased:	1991-11-13
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1991-11-13
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1991-11-18
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	EMERG ENV.
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/31/92: PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"OIL NOTICED IN MANWAY REPAIR AND RETEST HORNER EZ SYSTEM GROSS"

All TTF:

Facility ID:	9108659
Spill Number:	9108659
Spill Tank Test:	1539301
Site ID:	255792
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

GATEWAY BLDG (Continued) **S100140904**

All Materials:

Site ID:	255792
Operable Unit ID:	962707
Operable Unit:	01
Material ID:	420787
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	GATEWAY OFFICE BLDG
Address:	1 NORTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8908197 / 1990-01-29
Facility ID:	8908197
Site ID:	276348
Spill Date:	1989-11-16
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1990-01-29
SWIS:	6017
Investigator:	wxwadswo
Referred To:	Not reported
Reported to Dept:	1989-11-16
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1989-11-17
Spill Record Last Update:	2005-05-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	113491
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was W. WADSWORTH 01/29/90: TANK PASSED RETEST. "
Remarks:	"WILL PUMP OUT TANK (CAPITAL OIL)"

All TTF:

Facility ID:	8908197
Spill Number:	8908197
Spill Tank Test:	1536421

GATEWAY BLDG (Continued) **S100140904**

Site ID:	276348
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	276348
Operable Unit ID:	933238
Operable Unit:	01
Material ID:	559409
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	GATE WAY PLAZA
Address:	1 NORTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1112860 / 2012-06-06
Facility ID:	1112860
Facility Type:	ER
DER Facility ID:	113491
Site ID:	460825
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2012-02-09
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2012-02-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

GATEWAY BLDG (Continued) **S100140904**

Remediation Phase:	0
Date Entered In Computer:	2012-02-09
Spill Record Last Update:	2012-06-06
Spiller Name:	Not reported
Spiller Company:	GATE WAY PLAZA
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	TONY PEPE
DEC Memo:	"2/9/12 - Caller removed one 10K UST and one 2K UST. Post excavation sampling results showed contamination below soil guidance. A TCR will be prepared. Westchester County DOH was notified and was presented at the tank pull. KAB >>> Lalak, Chris >cjl1@westchestergov.com> 2/9/2012 10:56 AM >>> John, I am lead on this one pbs tank pull. Chris jod 06/06/2012: Update received from Chris Lalak of WCDoH PBS: John Please close this spill 1112860 1 North Lex. Ave, WP American pulled two tanks *DEC requires no further action at this time. jod"
Remarks:	"contamination based on lab results"

All Materials:

Site ID:	460825
Operable Unit ID:	1210927
Operable Unit:	01
Material ID:	2208599
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

Name:	GATEWAY BUILDING
Address:	1 NORTH LEXINGTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1213498 / 2013-01-08
Facility ID:	1213498
Facility Type:	ER
DER Facility ID:	113491
Site ID:	476685
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	2012-12-13
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2012-12-13
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False

GATEWAY BLDG (Continued) **S100140904**

Remediation Phase:	0
Date Entered In Computer:	2012-12-13
Spill Record Last Update:	2013-01-08
Spiller Name:	Not reported
Spiller Company:	PROPERTY OWNER
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	CHRIS LALAK
DEC Memo:	"12/13/12 Assitant Chief Engineer Joseph Rocuzzo reported that a contractor, DP Wolff (143 Bedford Rd, Katonah) was performing mechanical work and had 50 gallon of oil that needed to be pumped back into the diesel storage tank. They set the house pump on manual and turned on the pump. It was explained that the oil first gets pumped up to the 20th floor day tank and the excess then flows out the daytank return line back to the storage tank. However the daytank emergency vent relief valve is lower than the return line, so the oil released from that vent before it could be sent back to the tank via the return line. The oil drained down the glass curtain wall from the 19th floor to the 16th floor. Elite Environmental was on site removing oily insulation and cleaning oiled surfaces. A minor amount of oil escaped the interior of the building thru the glass curtain and landed on the sidewalk below. Some oil also entered a floor drain next to the day tank. WP sewer dept personnel reported that oil was observed in the sanitary sewer in the street but not in the storm drains. WCHD is requiring indoor air sampling before the 4 impacted floors can be reoccupied. TG "
Remarks:	"interior and exterior to sidewalk - cleanup in progress - spilled 14 thru 17 floor elite environmental on site"

All Materials:

Site ID:	476685
Operable Unit ID:	1226510
Operable Unit:	01
Material ID:	2223774
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	50.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AX345 **DATTORRE/REAL ESTATE - TTF** **NY LTANKS** **S117975702**
SE **73 LONGVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.352 mi.
1861 ft. **Site 1 of 2 in cluster AX**

Relative: **Higher**
Actual: **244 ft.**

LTANKS:

Name:	DATTORRE/REAL ESTATE - TTF
Address:	73 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1503444 / 2015-10-08
Facility ID:	1503444
Site ID:	509746
Spill Date:	2015-06-29

DATTORRE/REAL ESTATE - TTF (Continued) **S117975702**

Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6026
Investigator:	JBODEE
Referred To:	Not reported
Reported to Dept:	2015-06-29
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2015-06-29
Spill Record Last Update:	2015-10-09
Spiller Name:	Not reported
Spiller Company:	D'ATTORRE
Spiller Address:	71 BOLTON AVENUE
Spiller County:	999
Spiller Contact:	DATTORRE
Spiller Phone:	(914) 420-4786
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	464360
DEC Memo:	"6/29/15- Spoke to seller, Mrs. Dattorre. She will likely being retesting tank. Will call back after retest with results. Test being done for property transaction. DT 7-13-15 Owner called. She says she is trying to negotiate assistance from the potential buyer in regards to resolving this spill. She says her choice of remove or retest will be based on the outcome of that negotiation. She asked that anything we mail be sent to her home address, which she gives as 71 Bolton Avenue, White Plains, NY 10605. Input this address under potential spiller. Also input phone number that showed up on caller id. jc 10/9/15: NES disposed of the leaking UST and 121.37 tons of petroleum contaminated soil. Soil sample results submitted for review. Tank Closure Report entered into DecDocs system. Based upon the information provided, no further action is required at this time. jod"
	Not reported
Remarks:	"550 gal ust"

All Materials:

Site ID:	509746
Operable Unit ID:	1259026
Operable Unit:	01
Material ID:	2262262
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

AY346 **SPILL NUMBER 0108164** **NY LTANKS** **S105230064**
NE **32 MITCHELL PL** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.354 mi.
1871 ft. **Site 1 of 6 in cluster AY**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Name:	SPILL NUMBER 0108164
Address:	32 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0108164 / 2002-07-22
Facility ID:	0108164
Site ID:	255456
Spill Date:	2001-11-12
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-11-12
CID:	270
Water Affected:	Not reported
Spill Notifier:	Affected Persons
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-11-12
Spill Record Last Update:	2002-07-24
Spiller Name:	MITCH
Spiller Company:	M AND T DEVELOPEMENT
Spiller Address:	32 MITCHELL PL
Spiller County:	001
Spiller Contact:	MITCH
Spiller Phone:	(914) 472-5424
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 07/22/02 - NORTHEAST DISPOSED OF TANK AND 15.67 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"contaminated soil discovered from tank removal"

All Materials:

Site ID:	255456
Operable Unit ID:	845393
Operable Unit:	01
Material ID:	529414
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILL NUMBER 0108164 (Continued) **S105230064**

Name:	SPILL NUMBER 9611678
Address:	32 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9611678 / 1996-12-24
Facility ID:	9611678
Site ID:	255457
Spill Date:	1996-12-24
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-24
CID:	312
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-24
Spill Record Last Update:	1997-01-14
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	MITCHELL SAUNDERS
Spiller Phone:	(914) 421-1742
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209243
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 12/24/96 SPILL CONTAINED ON BLACKTOP WITH SPEEDI-DRI; CLEAN UP COMPLETE. "
Remarks:	"DRIVER OVERFILLED THE TANK - SUPPOSEDLY NO VENT ALARM"

All Materials:

Site ID:	255457
Operable Unit ID:	1043016
Operable Unit:	01
Material ID:	340329
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	18.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	APT COMPLEX
Address:	32 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9611679 / 1997-11-10

SPILL NUMBER 0108164 (Continued) **S105230064**

Facility ID:	9611679
Site ID:	255458
Spill Date:	1996-12-24
Spill Cause:	Tank Overfill
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6000
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1996-12-24
CID:	323
Water Affected:	Not reported
Spill Notifier:	Fire Department
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1996-12-24
Spill Record Last Update:	1997-12-10
Spiller Name:	Not reported
Spiller Company:	OIL COMPANY
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BOB LYONS
Spiller Phone:	(914) 422-6333
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	276053
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FD ON SCENE CLEANING UP SPILL."

All Materials:

Site ID:	255458
Operable Unit ID:	1043017
Operable Unit:	01
Material ID:	569601
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	15.00
Oxygenate:	Not reported

AZ347 **OFFICE BUILDING** **NY LTANKS** **S106385494**
NNE **14 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.355 mi.
1872 ft. **Site 1 of 3 in cluster AZ**

Relative:
Higher

Actual:
213 ft.

LTANKS:

Name:	OFFICE BUILDING
Address:	14 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9613653 / 1997-03-05
Facility ID:	9613653
Site ID:	284245
Spill Date:	1997-02-20
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-02-20
CID:	257
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-02-20
Spill Record Last Update:	2005-11-08
Spiller Name:	KEMPNER CORP
Spiller Company:	OFFICE BUILDING
Spiller Address:	14 NANARONNECK AV
Spiller County:	001
Spiller Contact:	KEMPNER CORP
Spiller Phone:	(914) 946-3030
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188973
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 03/05/1995 TANK PASSED A RETEST ON THIS DATE. NFA"
Remarks:	""

All Materials:

Site ID:	284245
Operable Unit ID:	1041238
Operable Unit:	01
Material ID:	338758
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

OFFICE BUILDING (Continued) **S106385494**

Name:	CELESTILA GROUP
Address:	14 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0313324 / 2004-04-22
Facility ID:	0313324
Site ID:	229197
Spill Date:	2004-03-04
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-03-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-03-04
Spill Record Last Update:	2004-04-22
Spiller Name:	Not reported
Spiller Company:	CELESTILA GROUP
Spiller Address:	14 MAMARONECK AVE
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(646) 935-1200
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	188973
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 04/22/04 TANK PASSED A RETEST ON 3-29-04. jbo"
Remarks:	"RECOMEND: EXCAVATE, AND RETEST "

All TTF:

Facility ID:	0313324
Spill Number:	0313324
Spill Tank Test:	1529019
Site ID:	229197
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

OFFICE BUILDING (Continued) **S106385494**

All Materials:

Site ID:	229197
Operable Unit ID:	880498
Operable Unit:	01
Material ID:	498477
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA348 **MAMARONECK AVENUE DRY CLEANERS** **NY SHWS S106970795**
ESE **359-369 MAMARONECK AVENUE** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY 10605**
0.362 mi.
1913 ft. **Site 1 of 4 in cluster BA**

Relative:
Higher

Actual:
235 ft.

SHWS:

Name:	MAMARONECK AVENUE DRY CLEANERS
Address:	359-369 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY 10605
Program:	HW
Site Code:	387008
Classification:	Not reported
Region:	3
Acres:	0.25
HW Code:	360102
Record Add:	09/10/2007
Record Upd:	08/28/2012
Updated By:	RXKEATIN
Site Description:	Location Description: The site is located at 359-369 Mamaroneck Avenue in a mixed use commercial and residential area in the southern part of the City of White Plains, Westchester County NY. Site Features: The site is on approximately 0.25 acres of land which is flat and contains a 6,763 square foot building with a full basement. Current Use: The building contains a drycleaner, a nail salon, an insurance agency, and two restaurants. The remainder of the site consists of a paved parking lot. Surrounding Use: The site is surrounded with businesses to the north and south of the site and residences to the east and west. Immediately to the east of the site is a municipal parking lot. Historical Sources of Contamination: Dry cleaner operated at this location is a potential source of PCE contamination. Site Hydrology: Groundwater flows though sand at only several feet below ground surface.
Env Problem:	Based upon investigations to date, the primary contaminants of concern at the site included tetrachloroetylene (PCE) and its associated breakdown products. After a thorough Site Characterization, as described in a final report dated July 2012, it was determined that this site did not qualify for the registry.
Health Problem:	Not reported
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported

MAMARONECK AVENUE DRY CLEANERS (Continued) **S106970795**

Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	Not reported
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	Not reported
Owner Address:	Not reported
Owner Addr2:	Not reported
Owner City,St,Zip:	Not reported
Owner Country:	Not reported
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	BUSINESS
Address:	359-369 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0505152 / 2005-10-04
Facility ID:	0505152
Facility Type:	ER
DER Facility ID:	296563
Site ID:	350119
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	2005-07-28
Investigator:	TDGHIOSA
Referred To:	DIV OF HAZWASTE
Reported to Dept:	2005-07-28
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-28
Spill Record Last Update:	2006-09-12

MAMARONECK AVENUE DRY CLEANERS (Continued) **S106970795**

Spiller Name:	ERIC HARVEY
Spiller Company:	BUSINESS
Spiller Address:	359-369 MARNAMEK AVE
Spiller Company:	001
Contact Name:	ERIC HARVEY
DEC Memo:	"08/23/05 Groundwater & Environmental Services, Inc. submitted a subsurface investigation report that documented the presence of chlorinated solvents at a dry cleaner. GES report forwarded to Paul John for a referral to Haz Waste Remediation. NFA by Spills. TG 09/01/06 Quarterly monitoring report for July to September 2006 submitted by GES. Sent to Paul John to forward to Haz Remediation. TG"
	Not reported
Remarks:	"FOUND CONTAMINATION IN SOIL WHILE DOING SOIL BORINGS:"

AY349 **APARTMENT BLDG** **NY LTANKS** **S105997251**
NE **37-43 MITCHELL PL** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.363 mi.
1918 ft. **Site 2 of 6 in cluster AY**

Relative: LTANKS:
Higher

Actual:
218 ft.

Name:	APARTMENT BLDG
Address:	37-43 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0208214 / 2003-04-07
Facility ID:	0208214
Site ID:	248365
Spill Date:	2002-11-07
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-11-07
CID:	390
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-07
Spill Record Last Update:	2003-09-08
Spiller Name:	PHIL GUSSACK
Spiller Company:	APARTMENT BLDG
Spiller Address:	37-43 MITCHELL PL
Spiller County:	001
Spiller Contact:	PHIL GUSSACK
Spiller Phone:	(914) 497-5310
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	203790
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/15/03: Letter to Philip Gussack from Marc Grazioli, WCHD, dated 4/7/2003. Site closure report has been reviewed. Soil sample

APARTMENT BLDG (Continued) **S105997251**

Remarks:	results satisfactory. WCHD recommend NFA at this time." "caller reporting 1000 gal storage tank failed - there is soil contamination - unk amount spilled yet - soil is being stockpiled "

All Materials:

Site ID:	248365
Operable Unit ID:	859738
Operable Unit:	01
Material ID:	515218
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY350 **BARGAM HOME** **NY LTANKS** **S106972377**
NE **36-38 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.364 mi.
1921 ft. **Site 3 of 6 in cluster AY**

Relative: **Higher**
Actual: **218 ft.**

LTANKS:

Name:	BARGAM HOME
Address:	36-38 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0505320 / 2005-12-18
Facility ID:	0505320
Site ID:	350305
Spill Date:	2005-08-01
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-08-01
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-01
Spill Record Last Update:	2005-12-18
Spiller Name:	GILL BARGAM
Spiller Company:	BARGAM HOME
Spiller Address:	36-38 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	GILL BARGAM
Spiller Phone:	(914) 310-1500
Spiller Extention:	Not reported

BARGAM HOME (Continued) **S106972377**

DEC Region: 3
DER Facility ID: 296750
DEC Memo: "Have ok to finish job. December 18, 2005: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 19.56 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks: " HOLES IN 1000 GALLON TANK, AND SOME CONTAMINATION IN SOIL; "

All Materials:
Site ID: 350305
Operable Unit ID: 1107882
Operable Unit: 01
Material ID: 2097770
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: G
Recovered: .00
Oxygenate: Not reported

AZ351 **SPILL NUMBER 0206130** **NY LTANKS** **S105996744**
NNE **203 MAIN ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.370 mi.
1952 ft. **Site 2 of 3 in cluster AZ**

Relative:
Higher

Actual:
211 ft.

LTANKS:
Name: SPILL NUMBER 0206130
Address: 203 MAIN ST
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0206130 / 2003-09-03
Facility ID: 0206130
Site ID: 176565
Spill Date: 2002-09-12
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2002-09-13
CID: 396
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2002-09-13
Spill Record Last Update: 2003-09-08
Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported

SPILL NUMBER 0206130 (Continued) **S105996744**

Spiller County:	999
Spiller Contact:	JOHN JANUS
Spiller Phone:	(914) 760-0257
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	148388
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - SCHNEIDER 09/03/03 TANK CLOSED IN PLACE, VAULT CLEAN."
Remarks:	"while doing an inspection of the tank oil was observed leaking back into the empty tank."

All TTF:

Facility ID:	0206130
Spill Number:	0206130
Spill Tank Test:	1527446
Site ID:	176565
Tank Number:	1
Tank Size:	2500
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	176565
Operable Unit ID:	857669
Operable Unit:	01
Material ID:	516742
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AX352 **SPILL NUMBER 0009714** **NY LTANKS** **S104877294**
SE **77 LONGVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.371 mi.
1960 ft. **Site 2 of 2 in cluster AX**

Relative:
Higher

Actual:
245 ft.

LTANKS:

Name:	SPILL NUMBER 0009714
Address:	77 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0009714 / 2000-12-26
Facility ID:	0009714
Site ID:	155379

SPILL NUMBER 0009714 (Continued) **S104877294**

Spill Date:	2000-11-16
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2000-11-27
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-11-27
Spill Record Last Update:	2001-01-08
Spiller Name:	MR SANCHEZ
Spiller Company:	Not reported
Spiller Address:	77 LONGVIEW AVE
Spiller County:	001
Spiller Contact:	MR SANCHEZ
Spiller Phone:	(914) 948-8087
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131619
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/26/2000 NES DISPOSED OF TANK AND 6.67 TONS OF CONTAMINATED SOIL. DEC REQUIRES NO FURTHER ACTION."
Remarks:	"during tank removal caller found contaminated soil"

All Materials:

Site ID:	155379
Operable Unit ID:	831965
Operable Unit:	01
Material ID:	543653
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA353 **COMMERCIAL PROPERTY** **NY LTANKS** **S118953491**
ESE **365 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.373 mi.
1968 ft. **Site 2 of 4 in cluster BA**

Relative: LTANKS:
Higher

Name:	COMMERCIAL PROPERTY
Address:	365 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY

Actual:
234 ft.

COMMERCIAL PROPERTY (Continued) **S118953491**

Spill Number/Closed Date:	0310423 / 2005-03-05
Facility ID:	0310423
Site ID:	156660
Spill Date:	2003-12-09
Spill Cause:	Tank Overfill
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	WESTCHESTER CNTY HEALTH D
Reported to Dept:	2003-12-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-12-09
Spill Record Last Update:	2005-03-05
Spiller Name:	DWAYNE MONACO
Spiller Company:	ROBISON OIL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	DWAYNE MONACO
Spiller Phone:	(914) 777-1930
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	132555
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-JACKSON 12/09/03 ROBISON OIL DELIVERED TO WRONG ADDRESS. SPILL IS IN BASEMENT. NO TANK AT SITE, ONLY FILL PIPE. 3/5/05 20gallons spilled in basement--close"
Remarks:	"spill is being cleaned up and weschester health dept is on site"

All Materials:

Site ID:	156660
Operable Unit ID:	875513
Operable Unit:	01
Material ID:	499282
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY354 **APARTMENT BUILDING** **NY LTANKS** **S105999478**
NE **40 MITCHELL PL** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.373 mi.
1970 ft. **Site 4 of 6 in cluster AY**

Relative:
Higher

Actual:
218 ft.

LTANKS:

Name:	APARTMENT BUILDING
Address:	40 MITCHELL PL
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0304394 / 2003-10-31
Facility ID:	0304394
Site ID:	151265
Spill Date:	2003-07-25
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2003-07-25
CID:	390
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-07-25
Spill Record Last Update:	2003-12-12
Spiller Name:	NORMAN TUNNELL
Spiller Company:	APARTMENT BUILDING
Spiller Address:	40 MITCHELL PL
Spiller County:	001
Spiller Contact:	NORMAN TUNNELL
Spiller Phone:	(914) 328-7511
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	128562
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-GOREAU 11/4/03: Letter to Toni Palancia, Yurik Enterprises from Stefan Goreau, WCDOH dated 10/31/2003. Site closure report has been reviewed. WCDOH recommends NFA at this time."
Remarks:	"leaking underground storage tank caused spill - tank is still in ground - more will be done next week -- tank has been abandoned and covered"

All Materials:

Site ID:	151265
Operable Unit ID:	871197
Operable Unit:	01
Material ID:	505252
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

APARTMENT BUILDING (Continued) **S105999478**

Recovered: .00
Oxygenate: Not reported

---

355 SW 1/4-1/2 0.374 mi. 1977 ft. **SPILL NUMBER 0108396** **NY LTANKS** **S105230073**
150 WEST POST RD **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 247 ft.

LTANKS:

Name:	SPILL NUMBER 0108396
Address:	150 WEST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0108396 / 2002-03-06
Facility ID:	0108396
Site ID:	69570
Spill Date:	2001-11-19
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-11-19
CID:	396
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2001-11-19
Spill Record Last Update:	2002-03-25
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	BOB KERZNER
Spiller Phone:	(631) 491-6504
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	66134
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 03/06/2002 CASTLETON DISPOSED OF TANK AND 35.58 TONS OF IMPACTED SOIL. NO FURTHER ACTION."
Remarks:	"old tank was removed and ground cont was found."

All Materials:

Site ID:	69570
Operable Unit ID:	845792
Operable Unit:	01
Material ID:	563110
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported

SPILL NUMBER 0108396 (Continued) **S105230073**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA356 **BASEMENT** **NY LTANKS** **S104620583**
ESE **369 MAMARONECK AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.379 mi.
2003 ft. **Site 3 of 4 in cluster BA**

Relative: **Higher**

Actual: **232 ft.**

LTANKS:

Name:	BASEMENT
Address:	369 MAMARONECK AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9908980 / 2005-02-26
Facility ID:	9908980
Site ID:	195010
Spill Date:	1999-10-23
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1999-10-23
CID:	246
Water Affected:	Not reported
Spill Notifier:	Local Agency
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-10-23
Spill Record Last Update:	2005-02-26
Spiller Name:	SERVICEMAN
Spiller Company:	RYE FUEL
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	DOUG BRITTINGHAM
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	162496
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/26/2005 spill in basement--close "
Remarks:	"caller notified to clean spill in basement of store at location - poss caused by over fill of tank by rye fuels"

All Materials:

Site ID:	195010
Operable Unit ID:	1087653
Operable Unit:	01
Material ID:	298074

BASEMENT (Continued) **S104620583**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

AY357 **MGH CO** **NY LTANKS** **S102674590**
NE **45 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.381 mi.
2014 ft. **Site 5 of 6 in cluster AY**

Relative:
Higher

Actual:
217 ft.

LTANKS:

Name:	SPILL NUMBER 9904849
Address:	45 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9904849 / 2000-01-11
Facility ID:	9904849
Site ID:	78194
Spill Date:	1999-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-07-23
CID:	322
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-07-23
Spill Record Last Update:	2000-02-04
Spiller Name:	JAY BRENNAN
Spiller Company:	Not reported
Spiller Address:	45 MITCHELL PLACE
Spiller County:	001
Spiller Contact:	JAY BRENNAN
Spiller Phone:	(914) 948-6068
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	""
Remarks:	"tank test failure "

All TTF:

Facility ID:	9904849
Spill Number:	9904849
Spill Tank Test:	1547407

MGH CO (Continued) **S102674590**

Site ID:	78194
Tank Number:	1
Tank Size:	3000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	78194
Operable Unit ID:	1079286
Operable Unit:	01
Material ID:	301173
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	MGH CO
Address:	45 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9510979 / 1995-12-12
Facility ID:	9510979
Site ID:	143584
Spill Date:	1995-11-29
Spill Cause:	Tank Overfill
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1995-12-12
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-12-01
CID:	349
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-12-01
Spill Record Last Update:	1999-07-25
Spiller Name:	PHIL MENDOLA
Spiller Company:	ROBISON OIL

MGH CO (Continued) **S102674590**

Spiller Address:	500 EXECUTIVE BLVD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	(914) 948-6068
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"DRIVER OVERFILLED TANK"

All Materials:

Site ID:	143584
Operable Unit ID:	1021528
Operable Unit:	01
Material ID:	358334
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	1.00
Oxygenate:	Not reported

AY358 **APT BUILDING** **NY LTANKS** **S112810131**
NE **45 MITCHELL PLACE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.381 mi.
2014 ft. **Site 6 of 6 in cluster AY**

Relative: **Higher**

Actual: **217 ft.**

LTANKS:

Name:	APT BUILDING
Address:	45 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1212688 / 2020-02-05
Facility ID:	1212688
Site ID:	475842
Spill Date:	2012-11-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2012-11-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-28
Spill Record Last Update:	2020-02-05

APT BUILDING (Continued) **S112810131**

Spiller Name:	ALEX HAY
Spiller Company:	M.G.H. CO. LLC
Spiller Address:	PO BOX 1755
Spiller County:	999
Spiller Contact:	UNK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	"11-28-12 Tank to be repaired and retested. 2010 WC database listes owner as MGH Co., LLC jc 04-04-14 WCHD request closure, DEC request TCR RDB 4/13/17 DEC requests retest documentation, not TCR. mt 05-11-17; no test results yet - RDB 01-23-20 Spoke to Ruby at Hayco and she will track down the tank test report and forward it. BTR 1-24-20 Yesterday (1/23) the office manager at Hayco Management emailed the tank testing reports for 2019 and 2018. I am still waiting for the 2012 and 2017 test reports. BTR 02-05-20 Requested the 2017 report again. January submittals are on D2. The tank was isolated and retested according to the white plains building inspector certificate. The tank has passed tightness testing the last two years. NFA. BTR"
Remarks:	"repair/retest pending - possible vent line issue"

All Materials:

Site ID:	475842
Operable Unit ID:	1225683
Operable Unit:	01
Material ID:	2222965
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	APT BUILDING
Address:	45 MITCHELL PLACE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1212688 / 2020-02-05
Facility ID:	1212688
Site ID:	475842
Spill Date:	2012-11-27
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	BTRANSOM
Referred To:	Not reported
Reported to Dept:	2012-11-28
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False

APT BUILDING (Continued) **S112810131**

Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2012-11-28
Spill Record Last Update:	2020-02-05
Spiller Name:	Alex Hay
Spiller Company:	HAYCO Management
Spiller Address:	PO BOX 747
Spiller County:	999
Spiller Contact:	UNK
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	72789
DEC Memo:	"11-28-12 Tank to be repaired and retested. 2010 WC database listes owner as MGH Co., LLC jc 04-04-14 WCHD request closure, DEC request TCR RDB 4/13/17 DEC requests retest documentation, not TCR. mt 05-11-17; no test results yet - RDB 01-23-20 Spoke to Ruby at Hayco and she will track down the tank test report and forward it. BTR 1-24-20 Yesterday (1/23) the office manager at Hayco Management emailed the tank testing reports for 2019 and 2018. I am still waiting for the 2012 and 2017 test reports. BTR 02-05-20 Requested the 2017 report again. January submittals are on D2. The tank was isolated and retested according to the white plains building inspector certificate. The tank has passed tightness testing the last two years. NFA. BTR"
Remarks:	"repair/retest pending - possible vent line issue"

All Materials:

Site ID:	475842
Operable Unit ID:	1225683
Operable Unit:	01
Material ID:	2222965
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

AZ359 **221 MAIN STREET** **NY BROWNFIELDS S106704121**
NNE **221 MAIN ST** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY 10601**
0.382 mi.
2015 ft. **Site 3 of 3 in cluster AZ**

Relative:
Higher

Actual:
213 ft.

BROWNFIELDS:

Name:	221 MAIN STREET
Address:	221 MAIN ST
City,State,Zip:	WHITE PLAINS, NY 10601
Program:	BCP
Site Code:	58997
Acres:	2.6
HW Code:	C360073
SWIS:	6017

221 MAIN STREET (Continued) **S106704121**

Town:	White Plains (c)
Record Added Date:	07/26/2004
Record Updated Date:	12/20/2007
Update By:	MJRYAN
Site Description:	Location Description: The site is located in an urban portion of Westchester County, occupying several city tax parcels, including 221 Main Street, in the City of White Plains. Current Use: The site is currently being redeveloped. The newly constructed complex will contain approximately 125 hotel rooms, 400 condominiums and approximately 10,000 square feet of street levels stores. Surrounding Uses: The site is surrounded by commercial properties with a mix of retail and office space. Historical Source(s)of contamination: The historical source of contamination at this site included multiple leaking underground storage tanks (USTs). Investigations revealed the presence of ten USTs. Investigations/Actions Performed to date: Previous environmental investigations include a Phase I Investigation in 2002 and a Petroleum Contamination Site Investigation completed in June of 1993. Under the Brownfield Cleanup Program, a Remedial Investigation was conducted in 2005-2006. Based on RI findings, an Interim Remedial Measure (IRM) was planned and implemented which included the removal of all USTs, and contaminated soil. Current Action: A Final Engineering Report which documents the remedial activities completed has been approved. On December 19, 2006 a Certificate of Completion was issued declaring remedial activities complete, and that a Track 1 cleanup (i.e., unrestricted use) has been achieved.
Env Problem:	Contaminant of concern: Petroleum-related compounds including volatile organic compounds (VOCs) and polycyclic aromatic hydrocarbons. Impacted Media: Soil and groundwater. Known SCGs exceedences: Investigation revealed benzene, toluene, ethyl-benzene and xylenes, however, as part of a site-wide remedial program (2005-2006) all contaminated media has been removed and properly disposed.
Health Problem:	The site is located in downtown White Plains, public water serves the area. Through the implementation of an IRM the site has been remediated and nearly all the soil has been removed to bedrock eliminating potential exposure to contaminated soil. Proposed redevelopment of the site will include a ventilated below-grade parking garage with foundation drainage which will effectively eliminate the potential for soil vapor intrusion to occur.
Dump:	Not reported
Structure:	Not reported
Lagoon:	Not reported
Landfill:	Not reported
Pond:	Not reported
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	Not reported
Record Upd:	Not reported
Updated By:	Not reported
Own Op:	1
Sub Type:	Not reported
Owner Name:	C/O CAPPELLI ENTERPRISES, INC.
Owner Company:	LC MAIN, LLC
Owner Address:	115 STEVENS AVE.

221 MAIN STREET (Continued) **S106704121**

Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	RENAISSANCE HOTEL PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	RENAISSANCE OFFICE PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	1
Sub Type:	E
Owner Name:	Steven Elghanayan
Owner Company:	EPIC Renaissance LLC
Owner Address:	15 Watts Street, 5th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	RENAISSANCE PARKING PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	RENAISSANCE RENTAL PARTNERS, LLC
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	RENAISSANCE CONDOMINIUM PARTNERS
Owner Address:	115 STEVENS AVENUE
Owner Addr2:	Not reported
Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	C/O CAPPELLI ENTERPRISES, INC.
Owner Company:	LC MAIN, LLC
Owner Address:	115 STEVENS AVE.
Owner Addr2:	Not reported

221 MAIN STREET (Continued) **S106704121**

Owner City,St,Zip:	VALHALLA, NY 10595
Owner Country:	United States of America
Own Op:	6
Sub Type:	Not reported
Owner Name:	Not reported
Owner Company:	EPIC Renaissance LLC
Owner Address:	15 Watts Street, 5th Floor
Owner Addr2:	Not reported
Owner City,St,Zip:	New York, NY 10013
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	BAR BUILDING ANNEX
Address:	221 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0413395 / 2005-05-12
Facility ID:	0413395
Facility Type:	ER
DER Facility ID:	292111
Site ID:	342486
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	C3
SWIS:	6017
Spill Date:	2005-03-24
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-03-24
CID:	410
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Local Agency
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-03-24
Spill Record Last Update:	2005-05-12
Spiller Name:	JOHN MANFREDI
Spiller Company:	NORTHEAST CORNER
Spiller Address:	BAR BUILDING ANNEX
Spiller Company:	001
Contact Name:	JOHN MANFREDI
DEC Memo:	"4/20/05 UST removal report rec'd from JM Associates. Based on the info contained in that report, NFA required. TG"

221 MAIN STREET (Continued) **S106704121**

Remarks: "after excavating found a 4000 gallon tank about 70 years old contact cell phone JOHN MANFREDI 9144475634 unknown if tank is intact or if any material has gotten out into soil it is possible caller states in process of removing cleaning and testing area now"

All TTF:

Facility ID:	0413395
Spill Number:	0413395
Spill Tank Test:	1548723
Site ID:	342486
Tank Number:	Not reported
Tank Size:	4000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	342486
Operable Unit ID:	1101213
Operable Unit:	01
Material ID:	581340
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL BUSINESS
Address:	221 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0504810 / 2008-06-17
Facility ID:	0504810
Facility Type:	ER
DER Facility ID:	292111
Site ID:	349725
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3
SWIS:	6017
Spill Date:	2005-07-21
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-07-21
CID:	444
Water Affected:	Not reported

221 MAIN STREET (Continued) **S106704121**

Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-07-21
Spill Record Last Update:	2008-06-17
Spiller Name:	JOHN MANFERI
Spiller Company:	COMMECRCIAL BUISNESS
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	JOHN MANFERI
DEC Memo:	"06/17/08 Spill addressed by the Brownfield Cleanup Program remedial action, as documented in the Final Engineering Report for site no. C3-60-073. JPC "
Remarks:	"2 1000 GALLON TANKS: FOUND CONTAMINATION:"

All Materials:

Site ID:	349725
Operable Unit ID:	1107313
Operable Unit:	01
Material ID:	2097204
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	CONSTRUCTION PROJECT
Address:	221 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0500820 / 2008-06-17
Facility ID:	0500820
Facility Type:	ER
DER Facility ID:	292111
Site ID:	343904
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	B3
SWIS:	6017
Spill Date:	2005-04-20
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2005-04-20
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported

221 MAIN STREET (Continued) **S106704121**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2005-04-20
Spill Record Last Update:	2008-06-17
Spiller Name:	JOHN MANFREDIE
Spiller Company:	CONSTRUCTION PROJECT
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	JOHN MANFREDIE
DEC Memo:	"3/20/05 John Manfredi reported that this spill was reported based on the results of a test pit dug in the vicinity of this tank which has already been removed. Gross contamination was found at the water table. Site is under active construction, so remediation will occur as the project progresses. Estimated time frame is a few months. TG 06/17/08 Spill addressed by the Brownfield Cleanup Program remedial action, as documented in the Final Engineering Report for site no. C3-60-073. JPC "
Remarks:	"5000 GALLON TANK, FOUYND WHILE EXCAVATING: HOLES IN TANK ALSO:"

All Materials:

Site ID:	343904
Operable Unit ID:	1102569
Operable Unit:	01
Material ID:	582786
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	COMMERCIAL SITE
Address:	221 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0706741 / 2008-07-31
Facility ID:	0706741
Facility Type:	ER
DER Facility ID:	292111
Site ID:	387315
DEC Region:	3
Spill Cause:	Human Error
Spill Class:	B3
SWIS:	6017
Spill Date:	2007-09-18
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2007-09-18
CID:	444
Water Affected:	Not reported
Spill Source:	Commercial Vehicle
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	2007-09-18

221 MAIN STREET (Continued) **S106704121**

Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2007-09-18
Spill Record Last Update:	2008-07-31
Spiller Name:	VENESSA
Spiller Company:	COMMERCIAL SITE
Spiller Address:	221 MAIN STREET
Spiller Company:	001
Contact Name:	VENESSA
DEC Memo:	"7/31/08: Spill closure report from JM Associates submitted to DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"OVERFILLED THE TANK AND IS SURFACE SPILL AND IS BEING CLEANED UP' CALLED ENVIRO WASTE TO PUMP"

All Materials:

Site ID:	387315
Operable Unit ID:	1144524
Operable Unit:	01
Material ID:	2134831
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

360 NE 1/4-1/2 0.389 mi. 2056 ft. **240 EAST POST RD** **NY LTANKS** **S103941435**
240 EAST POST RD **N/A**
WHITE PLAINS, NY

Relative: Lower
Actual: 208 ft.

LTANKS:

Name:	240 EAST POST RD
Address:	240 EAST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9903233 / 1999-12-15
Facility ID:	9903233
Site ID:	135983
Spill Date:	1999-06-21
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1999-06-21
CID:	205
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False

240 EAST POST RD (Continued) **S103941435**

Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-21
Spill Record Last Update:	2000-04-05
Spiller Name:	NATE GORHAM
Spiller Company:	240 EAST POST RD
Spiller Address:	240 EAST POST RD
Spiller County:	001
Spiller Contact:	CALLER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	116709
DEC Memo:	""
Remarks:	"TANK REMOVED AND CONTAMINATION FOUND IN SOIL."

All Materials:

Site ID:	135983
Operable Unit ID:	1082158
Operable Unit:	01
Material ID:	303161
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BA361 **WRCO MCOT** **NY LTANKS** **S102154027**
ESE **2 OLD MAMARONECK ROAD** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.395 mi.
2085 ft. **Site 4 of 4 in cluster BA**

Relative:
Higher

Actual:
236 ft.

LTANKS:

Name:	CAMEO COOP APTS.
Address:	2 OLD MAMARONECK ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9414514 / 1996-08-28
Facility ID:	9414514
Site ID:	279763
Spill Date:	1995-01-02
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1995-01-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported

WRCO MCOT (Continued) **S102154027**

Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1995-02-08
Spill Record Last Update:	1996-11-22
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	227184
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 11/07/95 HOLES DRILLED INTO TANK BOTTOM & OIL SEEPED BACK INTO TANK FURTHUR CLEAN UP NESSARY NEW WRG MANAGEMENT CONTACT IS GILL CARMUHAIL (914) 939-7100 X311 12/01/95 CLEAN UP BY A L EASTMAN WAS UNSATISFACTORY ADDITIONAL WORK REQUIRED CONTACTED NEIL TOMASETTI AND TOLD HIM MORE WORK WAS NECESSARY 01/02/96 A.L. EASTMAN CUT OUT THE BOTTOM OF THE TANKTO REMOVE REMAINING OIL TRAPPEDIN THE CONCRETE; PETE RUSSO OF WHITE PLAINS BUILDING DEPT. REPORTED THAT CLEAN UP WAS SATIFACTORY "
Remarks:	"LEAK FROM 7500 GAL #6 FUEL OIL TANK IN VAULT FUEL ON BOILER ROOM FLOOR NO OIL ENTERED ANY DRAINS"

All Materials:

Site ID:	279763
Operable Unit ID:	1012082
Operable Unit:	01
Material ID:	373248
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	100.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	WRCO MCOT
Address:	2 OLD MAMARONECK ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9005687 / 1990-08-30
Facility ID:	9005687
Facility Type:	ER
DER Facility ID:	227184
Site ID:	198613
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	Not reported
SWIS:	6017
Spill Date:	1990-08-27
Investigator:	tdghiosa

WRCO MCOT (Continued) **S102154027**

Referred To:	Not reported
Reported to Dept:	1990-08-27
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	1953-06-18
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1990-08-30
Spill Record Last Update:	1991-05-09
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY "
Remarks:	"FAULTY TANK GUAGE FUEL LEAKED FROM VENT PIPE WILL PICK UP AND DISPOSE"

All Materials:

Site ID:	198613
Operable Unit ID:	943218
Operable Unit:	01
Material ID:	433174
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

362
West
1/4-1/2
0.395 mi.
2087 ft.

WHITE PLAINS PROJECT LLC
179 WESTMORELAND AVE
WHITE PLAINS, NY

NY LTANKS **S110769273**
NY Spills **N/A**

Relative:
Higher

Actual:
215 ft.

LTANKS:

Name:	BENEROFE PROPERTIES INC
Address:	179 WESTMORELAND AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8800315 / 1988-11-25
Facility ID:	8800315
Site ID:	317805
Spill Date:	1988-04-08
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	1988-11-16
SWIS:	6017

WHITE PLAINS PROJECT LLC (Continued) **S110769273**

Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-04-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-11-16
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-05-02
Spill Record Last Update:	2012-01-11
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	401552
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON 11/25/88: RETEST PASSED. "
Remarks:	"10,000 GAL. TANK GROSS LEAK SPILLER TO CALL WITH UPDATE.RETEST NEEDED."

All TTF:

Facility ID:	8800315
Spill Number:	8800315
Spill Tank Test:	1533621
Site ID:	317805
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	317805
Operable Unit ID:	917150
Operable Unit:	01
Material ID:	463028
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G

WHITE PLAINS PROJECT LLC (Continued) **S110769273**

Recovered: .00
Oxygenate: Not reported

SPILLS:
Name: WHITE PLAINS PROJECT LLC
Address: 179 WESTMORELAND AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 1012728 / 2012-11-28
Facility ID: 1012728
Facility Type: ER
DER Facility ID: 401552
Site ID: 446944
DEC Region: 3
Spill Cause: Equipment Failure
Spill Class: A3
SWIS: 6017
Spill Date: 2011-03-22
Investigator: jbodee
Referred To: Not reported
Reported to Dept: 2011-03-22
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-03-22
Spill Record Last Update: 2012-11-28
Spiller Name: JOHN ARREDONDO
Spiller Company: WHITE PLAINS PROJECT LLC
Spiller Address: 179 WEFTMORELAND AVE
Spiller Company: 999
Contact Name: JOHN ARREDONDO
DEC Memo: "3-22-11 Building was demolished in Feb. There was suspected contamination in area of boiler room. While digging in that area, found contamination and unregistered 5000 gal tank. Denise H from WCHD was at site already. Contaminated soil being removed and taken to New Windsor. jc Update from WCDOH PBS: >>> Heinzinger, Denise ->dmh3@westchestergov.com> 11/21/2012 1:30 PM >>> Hi John, This spill resulted from an unknown underground storage tank at an empty lot at 170 Westmoreland Avenue, White Plains. They were removing a registered 10,000 gallon ust then found this second unregistered 5,000 gallon tank. Grave samples came back high for the 5,000 so 2,237.85 tons of contaminated soil was then removed. End samples look good. -Denise Heinzinger *Based open the information received, no further action is required at this time. jod "
Remarks: "an unknown tank was discovered during construction, believed to be 2000 gallons w/ either #2 or # 4 fuel, clean up and removal pending"

All Materials:
Site ID: 446944
Operable Unit ID: 1197080

WHITE PLAINS PROJECT LLC (Continued) **S110769273**

Operable Unit:	01
Material ID:	2193411
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BB363 **MCTERNANA RESIDENCE** **NY LTANKS** **S106971735**
SSE **91 DAVIS AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.407 mi.
2149 ft. **Site 1 of 3 in cluster BB**

Relative:
Higher

Actual:
263 ft.

LTANKS:

Name:	MCTERNANA RESIDENCE
Address:	91 DAVIS AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0501407 / 2005-12-18
Facility ID:	0501407
Site ID:	345543
Spill Date:	2005-05-04
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-05-04
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-04
Spill Record Last Update:	2005-12-18
Spiller Name:	TOM MCTERNANA
Spiller Company:	Not reported
Spiller Address:	91 DAVIS AVE
Spiller County:	001
Spiller Contact:	TOM MCTERNANA
Spiller Phone:	(914) 949-5735
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	291778
DEC Memo:	"December 18, 2005: ELITE ENVIRONMENTAL DISPOSED OF LUST AND 108.66 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, MONITORING WELL INSTALLED AND SAMPLED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"FOUND HOLES IN TANK WHILE REMOVING"

MCTERNANA RESIDENCE (Continued) **S106971735**

All Materials:

Site ID:	345543
Operable Unit ID:	1103261
Operable Unit:	01
Material ID:	583472
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

364 SSW 1/4-1/2 0.410 mi. 2165 ft. **SPILL NUMBER 0211763** **NY LTANKS** **S105998245**
13 HOWARD AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 302 ft.

LTANKS:

Name:	SPILL NUMBER 0211763
Address:	13 HOWARD AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0211763 / 2003-03-03
Facility ID:	0211763
Site ID:	89203
Spill Date:	2003-02-27
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2003-02-27
CID:	199
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2003-02-27
Spill Record Last Update:	2003-05-12
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	WAYNE LAFRANCO
Spiller Phone:	(914) 798-9116
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	81514
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was

SPILL NUMBER 0211763 (Continued) **S105998245**

	O'DEE 03/03/03: Tank passed retest. Second remote fill was not capped during initial test. NFA required at this time."
Remarks:	"WILL RECOMEND UNCOVER - REPAIR - RETEST"

All TTF:

Facility ID:	0211763
Spill Number:	0211763
Spill Tank Test:	1528047
Site ID:	89203
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	89203
Operable Unit ID:	862790
Operable Unit:	01
Material ID:	511547
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC365 **TORELLI** **NY LTANKS** **S106718922**
East **21 DEKALB AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.411 mi.
2170 ft. **Site 1 of 2 in cluster BC**

Relative:
Higher

Actual:
212 ft.

LTANKS:

Name:	TORELLI
Address:	21 DEKALB AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206319 / 2005-02-02
Facility ID:	0206319
Site ID:	253456
Spill Date:	2002-09-18
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee

TORELLI (Continued) **S106718922**

Referred To:	Not reported
Reported to Dept:	2002-09-18
CID:	257
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-18
Spill Record Last Update:	2005-02-02
Spiller Name:	MR TORELLI
Spiller Company:	Not reported
Spiller Address:	21 DEKALB AVE
Spiller County:	001
Spiller Contact:	MR TORELLI
Spiller Phone:	(914) 761-2423
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	207634
DEC Memo:	"02/02/05 ELITE ENVIRONMENTAL DISPOSED OF LUST AND 43.36 TONS OF CONTAMINATED SOIL. CLOSURE REPORT RECEIVED FROM HES. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"during removal caller found contaminted soil and holes in the tank "

All Materials:

Site ID:	253456
Operable Unit ID:	857806
Operable Unit:	01
Material ID:	516935
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

366
SE
1/4-1/2
0.412 mi.
2177 ft.

TIFFANY TOWERS
56 DOYER AVE
WHITE PLAINS, NY

NY LTANKS **S105997391**
N/A

Relative:
Higher

Actual:
255 ft.

LTANKS:

Name:	TIFFANY TOWERS
Address:	56 DOYER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0208738 / 2003-02-21
Facility ID:	0208738
Site ID:	272332
Spill Date:	2002-11-22
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial

TIFFANY TOWERS (Continued) **S105997391**

Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-11-22
CID:	322
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-11-22
Spill Record Last Update:	2003-03-17
Spiller Name:	PAUL
Spiller Company:	Not reported
Spiller Address:	56 DOYER AVE
Spiller County:	001
Spiller Contact:	PAUL
Spiller Phone:	(914) 760-4820
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	221656
DEC Memo:	""
Remarks:	"contaminated soil was found - 5000 gal tank was removed and soil is being excavated at this time "

All Materials:

Site ID:	272332
Operable Unit ID:	860159
Operable Unit:	01
Material ID:	515734
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BC367 **POLE #W6** **NY LTANKS** **S106699823**
ENE **18 DEKALB AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.417 mi.
2203 ft. **Site 2 of 2 in cluster BC**

Relative:
Lower

Actual:
206 ft.

LTANKS:

Name:	PRIVATE HOME
Address:	18 DEKALB AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0406991 / 2004-10-04
Facility ID:	0406991
Site ID:	195806
Spill Date:	2004-09-23

POLE #W6 (Continued) **S106699823**

Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	c3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	WCHD
Reported to Dept:	2004-09-23
CID:	64
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-09-23
Spill Record Last Update:	2005-01-05
Spiller Name:	ALAN BAKER
Spiller Company:	PRIVATE HOME
Spiller Address:	18 DEKALB AV
Spiller County:	001
Spiller Contact:	ALAN BAKER
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	163125
DEC Memo:	" 10/04/04 CLEAN UP COMPLETED BY TRI-STATE, BUT THERE ARE INDOOR AIR ISSUES BEING HANDLED BY COUNTY HEALTH DEPT."
Remarks:	"Caller states that the oil tank was leaking. Apparently the leak is controlled at this time and he is enroute for clean up. During call, call was lost due to a bad cell phone connection. Caller can be reached on cell - 914-424-0973. Caller called back."

All Materials:

Site ID:	195806
Operable Unit ID:	889588
Operable Unit:	01
Material ID:	484834
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	15.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	POLE #W6
Address:	18 DEKALB AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0104393 / 2001-07-25
Facility ID:	0104393
Facility Type:	ER
DER Facility ID:	163125

POLE #W6 (Continued) **S106699823**

Site ID:	215770
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2001-07-25
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2001-07-25
CID:	201
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2001-07-25
Spill Record Last Update:	2003-10-21
Spiller Name:	CALLER
Spiller Company:	CON ED
Spiller Address:	4 IRVING PL
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE "
Remarks:	"2 QTS ON GRASS AND CONCREAT. CLEAN UP CREW ON THE WAY. CON ED #138458. NON PCB OIL."

All Materials:

Site ID:	215770
Operable Unit ID:	841030
Operable Unit:	01
Material ID:	532888
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD368 **GLEASON RESIDENCE** **NY LTANKS** **S103824697**
SW **168 WEST POST RD** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.427 mi.
2252 ft. **Site 1 of 2 in cluster BD**

Relative:
Higher

Actual:
252 ft.

LTANKS:

Name:	GLEASON RESIDENCE
Address:	168 WEST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9813367 / 1999-04-14
Facility ID:	9813367

GLEASON RESIDENCE (Continued) **S103824697**

Site ID:	133051
Spill Date:	1999-02-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-02-01
CID:	371
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-02-01
Spill Record Last Update:	1999-04-16
Spiller Name:	MR GLEASON
Spiller Company:	GLEASON RESIDENCE
Spiller Address:	168 WEST POST RD
Spiller County:	001
Spiller Contact:	MR GLEASON
Spiller Phone:	(914) 946-2647
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114510
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 4/14/99 NES PULLED TANK AND 126.74 TONS OF CONTAMINATED SOIL. NFA"
Remarks:	"recommend isolate and retest."

All TTF:

Facility ID:	9813367
Spill Number:	9813367
Spill Tank Test:	1546800
Site ID:	133051
Tank Number:	1
Tank Size:	1000
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	133051
Operable Unit ID:	1073811
Operable Unit:	01

GLEASON RESIDENCE (Continued) **S103824697**

Material ID:	560770
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	THE SALVATION ARMY
Address:	168 WEST POST RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0808631 / 2009-02-09
Facility ID:	0808631
Site ID:	406032
Spill Date:	2008-10-30
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2008-10-31
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-10-31
Spill Record Last Update:	2009-02-10
Spiller Name:	GRAEME HEPBURN
Spiller Company:	THE SALVATION ARMY
Spiller Address:	168 WEST POST RD
Spiller County:	999
Spiller Contact:	LAURA CAPPILLI
Spiller Phone:	(800) 440-8265
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	114510
DEC Memo:	"10-31-08: 11:50AM : V.Mc.^ Mr.Hepburn : Left Mess: Req. Callbk. to dispt. or T.Gh. after today. 2/10/09: Tank passed a retest after piping was repaired. Based upon information provided, no further action is required at this time. jod"
Remarks:	"TANK TEST FAILURE ON A 1000 GALLON UST, UNK IF ANY PRODUCT WAS SPILLED."

All Materials:

Site ID:	406032
Operable Unit ID:	1162643
Operable Unit:	01
Material ID:	2153923
Material Code:	0001A

GLEASON RESIDENCE (Continued) **S103824697**

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

---

369 East 1/4-1/2 0.430 mi. 2269 ft. **MILLER CENTER FOR NURSING** **NY LTANKS** **S100136824**
37 DEKALD AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 248 ft.

LTANKS:

Name:	MILLER CENTER FOR NURSING
Address:	37 DEKALD AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8802117 / 1988-08-30
Facility ID:	8802117
Site ID:	211184
Spill Date:	1988-06-03
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1988-08-30
SWIS:	6017
Investigator:	dxtraver
Referred To:	Not reported
Reported to Dept:	1988-06-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-06-10
Spill Record Last Update:	1988-12-05
Spiller Name:	Not reported
Spiller Company:	DR MILLER
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	175055
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 08/29/88: TANK TO BE FILLED IN PLACE. SWITCHING TO GAS. "
Remarks:	"TANK TO BE TAKEN OUT OF SERVICE. NFA"

All TTF:

Facility ID:	8802117
Spill Number:	8802117
Spill Tank Test:	1534060

MILLER CENTER FOR NURSING (Continued) **S100136824**

Site ID:	211184
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	211184
Operable Unit ID:	919447
Operable Unit:	01
Material ID:	461242
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE370 **HAMILTON GREEN** **NY BROWNFIELDS S120958439**
North **200 HAMILTON AVENUE** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY 10601** **NY MANIFEST**
0.432 mi.
2279 ft. **Site 1 of 4 in cluster BE**

Relative: **Lower**

Actual: **201 ft.**

BROWNFIELDS:

Name:	HAMILTON GREEN
Address:	200 HAMILTON AVENUE
City,State,Zip:	WHITE PLAINS, NY 10601
Program:	BCP
Site Code:	570663
Acres:	3.74
HW Code:	C360177
SWIS:	6017
Town:	White Plains (c)
Record Added Date:	05/22/2018
Record Updated Date:	01/28/2020
Update By:	KJCARPEN
Site Description:	Location The Site is located at 200 Hamilton Avenue in the City of White Plains, Westchester County, New York and is legally defined as Tax Map ID Section 125.67, Block 5, Lot 1 on the City of White Plains tax map. The 3.74-acre Site is bounded by Barker Avenue to the north followed by offices, a hotel, and commercial development; Cottage Place to the east followed by a gasoline station and commercial buildings; Hamilton Avenue to the south followed by commercial and government buildings; and Dr. Martin Luther King Jr. Boulevard to the

HAMILTON GREEN (Continued) **S120958439**

west followed by commercial development. The surrounding area consists primarily of commercial and governmental uses, with residences further north of the Site. Site Features The Site is developed with a rectangular-shaped two-story shopping mall and an east-adjacent asphalt-paved parking lot, with additional parking on the building roof, accessed by a ramp on the northern side of the building. The topography surrounding the Site slopes downward to the west from approximately 200 feet along Cottage Place to approximately 190 feet along Martin Luther King Jr. Boulevard. Current Zoning and Land Use The Site is currently zoned as a Neighborhood Business (B-2) District, and was established and mapped to this location as a specific land use component of the City of White Plains Central Renewal Project (No. NY R-13), which was approved in 1964 and involved the redevelopment of 120 acres of downtown White Plains. The B-2 District, and resulting White Plains Mall construction in 1972, was intended to provide a relocation opportunity for retail and service businesses displaced by the Central Renewal Project. However, since that time the character of downtown White Plains has shifted. A component of the proposed Site development includes a change in the current zoning to a new Transit Development 1 (TD-1) District. This proposed new zoning district would allow for the construction of the mixed-use transit oriented community development consistent with the City of White Plains Strategic Plan to enable innovative development adjacent to the City of White Plains' transit hub, thus encouraging a more walkable and less vehicle dependent community. The current land use is commercial and the surrounding area consists primarily of commercial and governmental uses, with residences further north of the Site. Past Use of the Site A review of historic Sanborn fire insurance maps indicated that the Site was historically bisected by a public street (William Street) and contained several private residential dwellings, a candy manufacturer, and two gasoline stations. The gasoline stations included a facility with three gasoline tanks at 230 Hamilton Avenue (southeastern portion of the Site) on the 1930 through 1950 maps, and a facility with greasing operations and four gasoline tanks at 250 Hamilton Avenue (southern portion of the Site) on the 1950 map. The former on-site structures were likely present until construction of the current two-story shopping mall and east-adjacent asphalt-paved parking lot. Based on historic records and interviews, the shopping mall was constructed in 1972 and has operated as the White Plains Mall with a variety of tenants since its construction, including potential dry cleaners listed in historic City Directories. Surrounding uses included a brush factory west-adjacent to the Site that later became a carpet cleaning business and a laundry facility, a manufactured gas plant northwest of the Site that later became a substation, and a gasoline station east-adjacent of the Site. Site Geology and Hydrogeology The topography surrounding the Site slopes downward to the west from approximately 200 feet along Cottage Place to approximately 190 feet along Martin Luther King Jr. Boulevard. Subsurface soils encountered at the Site during previous environmental and geotechnical investigations indicated that the Site is underlain by a layer of fill extending from ground surface to depths ranging from 5 to 12 feet bgs. This fill layer included sand, silt, gravel, organics (wood/grass), brick, asphalt, and rubber. Apparent native soils composed of varying amounts of sand, silt, and gravel were identified underlying the fill layer. During a recent geotechnical investigation of the Site, bedrock was reported at depths ranging from

HAMILTON GREEN (Continued) **S120958439**

	approximately 13 feet below existing grade in the northeastern portion of the parking lot to approximately 37 feet below existing grade in the central portion of the parking lot, corresponding to approximate elevations of 183 and 165 feet, respectively. The water table was measured in the nine on-site groundwater monitoring wells at depths ranging from 9.58 to 23.90 feet bgs, at elevations ranging from 178.70 to 181.89 feet. The deeper groundwater depths were noted at higher elevations in the eastern portion of the Site (along Cottage Place) and at shallower depths in lower elevations in the southern and western portions of the Site (along Hamilton Avenue and Martin Luther King Boulevard). Contour maps indicate that groundwater generally flows in a southwesterly direction across the Site.
Env Problem:	Information submitted with the BCP application regarding the environmental condition at the site are currently under review and will be revised as additional information becomes available.
Health Problem:	Information submitted with the BCP application regarding the conditions at the site are currently under review and will be revised as additional information becomes available.
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	8/2/2018 3:32:00 PM
Record Upd:	5/28/2019 10:04:00 AM
Updated By:	SMQUANDT
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Brian Kenney
Owner Company:	White Plains Public Library
Owner Address:	100 Martine Avenue
Owner Addr2:	Not reported
Owner City,St,Zip:	White Plains, NY 10601
Owner Country:	United States of America
Own Op:	1
Sub Type:	NNN
Owner Name:	Not reported
Owner Company:	W.P. Mall Realty, LLC
Owner Address:	35 West Street, Suite 202
Owner Addr2:	Not reported
Owner City,St,Zip:	Spring Valley, NY 10977
Owner Country:	United States of America
Own Op:	6
Sub Type:	P03
Owner Name:	Kenneth D. Narva
Owner Company:	S-WD/WP LLC
Owner Address:	S-WD/WP LLC
Owner Addr2:	168-A Irving Avenue, Suite 200K
Owner City,St,Zip:	Port Chester, NY 10573
Owner Country:	United States of America
Own Op:	Document Repository
Sub Type:	NNN
Owner Name:	Not reported

HAMILTON GREEN (Continued) **S120958439**

Owner Company:	NYS Department of Environmental Conservation
Owner Address:	21 South Putt Corners Road
Owner Addr2:	Not reported
Owner City,St,Zip:	New Paltz, NY
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	Not reported
Waste Quantity:	Not reported
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

SPILLS:

Name:	SOUTHEAST SIDE OF PROPERTY
Address:	200 HAMILTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1706297 / Not Reported
Facility ID:	1706297
Facility Type:	ER
DER Facility ID:	514102
Site ID:	560605
DEC Region:	3
Spill Cause:	Unknown
Spill Class:	A1
SWIS:	6017
Spill Date:	2017-09-22
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-09-28
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	4
Date Entered In Computer:	2017-09-28
Spill Record Last Update:	2017-12-26
Spiller Name:	Not reported
Spiller Company:	UNKNOWN
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	BECKY
DEC Memo:	"9/28/17 AKRF was performing Phase II, noticed some sites where soil seemed odiferous and possibly contaminated. Took soil and gw samples, soil samples came back below CP-51. GW samples came back high in MTBE, benzene, and toluene in 3 areas. Site used to be old shopping mall. AKRF states that there was a gas station at site in 1970's, and there is currently a gas station across the road from the site. Will send in copy of soil and gw analysis. ga 10/05/17 Becky called and

HAMILTON GREEN (Continued) **S120958439**

said the report will be completed soon and she expects to submit it in a week or two. TG 12/21/17 AKRF submitted a Phase II Investigation Report (See report in DecDocs.) TG"

Remarks: "historic spill, found last week after samples were taken, just ground water impacted, clean up is pending"

All Materials:

Site ID:	560605
Operable Unit ID:	1308600
Operable Unit:	01
Material ID:	2315602
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

NY MANIFEST:

Name:	CON EDISON - VAULT 9075
Address:	200 HAMILTON AVE & COTTAGE PL
City,State,Zip:	WHITE PLAINS, NY 10601
Country:	USA
EPA ID:	NYP004937316
Facility Status:	Not reported
Location Address 1:	200 HAMILTON AVE & COTTAGE PL
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	WHITE PLAINS
Location State:	NY
Location Zip:	10601
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	NYP004937316
Mailing Name:	CON EDISON - VAULT 9075
Mailing Contact:	CON EDISON
Mailing Address 1:	4 IRVING PL 15TH FL NE
Mailing Address 2:	Not reported
Mailing City:	NEW YORK
Mailing State:	NY
Mailing Zip:	10003
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	Not reported

BF371 **SPILL NUMBER 0206302** **NY LTANKS** **S105996795**
SE **50 LINDA AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.432 mi.
2283 ft. **Site 1 of 3 in cluster BF**

Relative:
Higher

Actual:
250 ft.

LTANKS:

Name:	SPILL NUMBER 0206302
Address:	50 LINDA AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206302 / 2002-11-25
Facility ID:	0206302
Site ID:	155727
Spill Date:	2002-09-18
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-09-18
CID:	211
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-18
Spill Record Last Update:	2002-12-26
Spiller Name:	DON SCANLAN
Spiller Company:	Not reported
Spiller Address:	50 LINDA AV
Spiller County:	001
Spiller Contact:	DON SCANLAN
Spiller Phone:	(914) 684-6174
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	131843
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 11/25/02 NORTHEST DISPOSED OF TANK AND 57.79 TONS OF CONTAMINATED SOIL. CLOSURE REPORT FROM JM ASSOCIATES. 12/26/02 SECOND CLOSURE RECEIVED FROM NORTHEAST."
Remarks:	"CALLER REMOVING 550 UST AND DISCOVERED SOIL CONTAMINATION - SOIL BEING STOCKPILED"

All Materials:

Site ID:	155727
Operable Unit ID:	857792
Operable Unit:	01
Material ID:	516916
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00

SPILL NUMBER 0206302 (Continued) **S105996795**

Oxygenate: Not reported

372
ESE
1/4-1/2
0.433 mi.
2286 ft.

SUNOCO GAS S/S,WHITE PLAN
405 MAMARONECK AVENUE
WHITE PLAINS, NY

NY LTANKS **S100166178**
NY Spills **N/A**

Relative:
Higher

Actual:
228 ft.

LTANKS:

Name:	SUN OIL
Address:	405 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9004404 / 1990-09-18
Facility ID:	9004404
Site ID:	227021
Spill Date:	1990-07-20
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-07-20
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Responsible Party
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-07-23
Spill Record Last Update:	1990-09-28
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	400 EAGLESNEST ROAD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	152390
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 09/18/90: TANK REMOVED. "
Remarks:	"TANK PUMPED OUT (EIR) POSSIBLE REMOVE VACUTECH FAILED BOTH"

All TTF:

Facility ID:	9004404
Spill Number:	9004404
Spill Tank Test:	1537332
Site ID:	227021
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	227021
Operable Unit ID:	944769
Operable Unit:	01
Material ID:	435504
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

Name:	SUNOCO STATION #7-5465
Address:	405 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9710178 / 2005-02-12
Facility ID:	9710178
Site ID:	181736
Spill Date:	1997-12-04
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1997-12-04
CID:	266
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1997-12-04
Spill Record Last Update:	2005-02-12
Spiller Name:	LEVETTE PARISH
Spiller Company:	SUN OIL COMPANY
Spiller Address:	1801 MARKET STREET
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

DER Facility ID: 152390
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 2/12/05 same as 91 07439--close "
Remarks: "HOLE FOUND IN VENT LINE. NO PRODUCT LEAK. VENT LINE TO BE REPAIRED. TANK TO BE RETESTED FOLLOWING REPAIR."

All TTF:
Facility ID: 9710178
Spill Number: 9710178
Spill Tank Test: 1545504
Site ID: 181736
Tank Number: Not reported
Tank Size: 1000
Material: 0022
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 20
Test Method 2: USTest 2000/P/LL plus USTest 2000/U
Leak Rate: .00
Gross Fail: F
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 181736
Operable Unit ID: 1056565
Operable Unit: 01
Material ID: 328488
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Name: SUNOCO GAS S/S,WHITE PLAN
Address: 405 MAMARONECK AVENUE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 8709700 / 1995-02-14
Facility ID: 8709700
Site ID: 67631
Spill Date: 1988-02-17
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station or other PBS Facility
Spill Class: C3
Cleanup Ceased: 1995-02-14
SWIS: 6017
Investigator: dxtraver
Referred To: Not reported
Reported to Dept: 1988-02-17
CID: Not reported
Water Affected: Not reported

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1988-03-01
Spill Record Last Update:	1995-02-14
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	152390
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TRAVER 02/19/88: TANK HAS BEEN PUMPED OUT WILL CALL ABOUT RETESTED. L.R. "
Remarks:	"6K GROSS LEAK, TO EXC ISL & RET. TANK REMOVED."

All TTF:

Facility ID:	8709700
Spill Number:	8709700
Spill Tank Test:	1533244
Site ID:	67631
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	67631
Operable Unit ID:	915117
Operable Unit:	01
Material ID:	461495
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

SPILLS:

Name:	SUNOCO GAS STATION
Address:	405 MAMARONECK AVENUE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9202857 / 1998-09-23
Facility ID:	9202857
Facility Type:	ER
DER Facility ID:	152390
Site ID:	227022
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	1991-10-10
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	1992-06-09
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1992-06-11
Spill Record Last Update:	1998-09-23
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY SEE SPILL # 9107439"
Remarks:	"DID TANK REPLACEMENT IN OCT.10,1991 AND DEC WAS ON SITE DEC ASKED FOR ASSESSMENT AND SENT RESULTS TO KARL WEED APRIL 16,1992 LETTER FROM WEED ASKING WHEN TO DO FURTHER INVEST.AND TO CALL SPILL PHONE"

All Materials:

Site ID:	227022
Operable Unit ID:	970213
Operable Unit:	01
Material ID:	414089
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

Name:	SUNOCO S/S
Address:	405 MAMARONECK AVENUE

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9107439 / 2011-09-15
Facility ID:	9107439
Facility Type:	ER
DER Facility ID:	152390
Site ID:	147172
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	B3
SWIS:	6017
Spill Date:	1991-10-10
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	1991-10-10
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	DEC
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	True
Remediation Phase:	0
Date Entered In Computer:	1991-10-21
Spill Record Last Update:	2011-09-15
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 06/22/98 LETTER SENT NEED REMEDIAL PLAN 08/26/99 LETTER SENT RE: DEFINE EXTENT OF PLUME AT THIS SITE 11/10/99 LETTER SENT; SUBMIT SCHEDULE FOR SUBMISSION OF A REMEDIAL ACTION PLAN FOR THIS SITE 6/4/04: Letter to Karen Bourque, Groundwater & Environmental Services by J. Hardy. Reduce reporting to annual. 1/08 tanks and contaminated soil were removed in 7/07; groundwater contamination dropping quickly; site very close to closeable--minimal environmental risk 5/19/09 2/17/09 qmr all wells low except mw2 at approx 5500 ppb btex; new report due shortly jh 6/12 6/09 qmr shows approx .01 to a sheen of product fairly consistent in mw2--surfactant injection planned for june--asked via email for workplan--report and email in edocs jh 6/23/09 ges submitted workplan but there are a number of questions to be resolved prior to approval--workplan and jh email both in edocs. jh 9/25/09 by email asked for workplan from ges. email in edocs jh 10/2/09 chem ox workplan submitted and is in edocs jh 10/20/09 asked ges to address production of vapor by chem ox and their monitoring. directed ges to send info to wdoh. email in edocs jh 10/23/09 ges submits revised chem ox workplan with attempt to resolve DEC questions. wp in edocs jh 10/26/09 DEC raised additional questions via email which is in edocs. questions related to perceived contradictions in workplan as to chemical reactions. jh 10/26/09 GES responded to above but not completely jh 10/26/09 DEC asked for more information concerning chemical reactions, end products, and potential impacts jh 11/5/09 transmitted injection guidelines to ges jh 12/2/09 qmr shows levels relatively unchanged; transmittal notes

SUNOCO GAS S/S,WHITE PLAN (Continued) **S100166178**

they have put a hold on futher chem ox injections until they answer dec questions in a new chem ox workplan jh 2/22/10 ges submitted qmr and additional details re chem ox proposal. 3/22/10 reports above reviewed. levels still persistent in one well which is to recieve chem injection. calculations seem reasonable and since only 100 gallons are being injected my previous question concerning possible plume migration are resolved. approval email sent. jh 4/21/10 site in remediation because of chem ox above--unknown if spill is contained so that date not filled in jh 11/22/10 Project transferred to Mastro. 5/25/11 RegenOx injected in 8/10, 3/11. Will continue to monitor...mm 9/15/11 Based on the data contained in the 8/29/11 QMR prepared by CEA, no further action is required. The concentrations in MW-2 remain above standards. This well is located in a right of way and cannot be excavated because of underground utilities. This well has been vac'd, and there have been ORC and Chem Ox injections. The concentrations have been decreasing and there are no receptors....mm "

Remarks: "CONTAMINATION FOUND WHILE REMOVING TANK"

All Materials:

Site ID:	147172
Operable Unit ID:	961654
Operable Unit:	01
Material ID:	2096628
Material Code:	1213A
Material Name:	MTBE (methyl-tert-butyl ether)
Case No.:	01634044
Material FA:	Hazardous Material
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	147172
Operable Unit ID:	961654
Operable Unit:	01
Material ID:	419645
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	L
Recovered:	.00
Oxygenate:	Not reported

BF373 **DUBBS RESIDENCE** **NY LTANKS** **S106471855**
SE **52 LINDA AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.434 mi.
2290 ft. **Site 2 of 3 in cluster BF**

Relative:
Higher

Actual:
252 ft.

LTANKS:

Name:	DUBBS RESIDENCE
Address:	52 LINDA AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0402572 / 2004-08-09
Facility ID:	0402572

DUBBS RESIDENCE (Continued) **S106471855**

Site ID:	232412
Spill Date:	2004-06-09
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2004-06-09
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	2004-06-09
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2004-06-09
Spill Record Last Update:	2004-08-09
Spiller Name:	MR DUBBS
Spiller Company:	DUBBS RESIDENCE
Spiller Address:	52 LINDA AVE
Spiller County:	001
Spiller Contact:	MR DUBBS
Spiller Phone:	(914) 490-4158
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	191540
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 08/09/04 ENVIROSTAR DISPOSED OF LUST AND 48.07 TONS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jbo"
Remarks:	"550 GALLON TANK: HAVE CONTAMINTED SOIL: REMOVED TANK AND STOCK PILING THE DIRT"

All Materials:

Site ID:	232412
Operable Unit ID:	886278
Operable Unit:	01
Material ID:	490189
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

374
NNE
1/4-1/2
0.435 mi.
2296 ft.

WHITE PLAINS DEPT OF PUBLIC WORKS
255 MAIN STREET
WHITE PLAINS, NY 10601

NY LTANKS **S105912883**
NY MANIFEST **N/A**
NY SPDES

Relative:
Higher

Actual:
219 ft.

LTANKS:

Name:	CITY HALL
Address:	255 MAIN ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8707220 / 1988-03-14
Facility ID:	8707220
Site ID:	294455
Spill Date:	1987-11-21
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	D3
Cleanup Ceased:	1988-03-14
SWIS:	6017
Investigator:	RICCI
Referred To:	Not reported
Reported to Dept:	1987-11-21
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1988-03-14
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-11-27
Spill Record Last Update:	1988-12-05
Spiller Name:	Not reported
Spiller Company:	MR. BROCCHI
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	238304
DEC Memo:	""
Remarks:	"5K TANK SYSTEM -.1255 GPH"

All TTF:

Facility ID:	8707220
Spill Number:	8707220
Spill Tank Test:	1532403
Site ID:	294455
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 294455
Operable Unit ID: 911097
Operable Unit: 01
Material ID: 466187
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Name: WHITE PLAINS DEPT OF PUBLIC WORKS
Address: 255 MAIN STREET
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYD000877423
Facility Status: Not reported
Location Address 1: 255 MAIN STREET
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYD000877423
Mailing Name: WHITE PLAINS DEPT OF PUBLIC WORKS
Mailing Contact: DENNIS DEFILLIPIS
Mailing Address 1: 255 MAIN STREET ATTN TOM
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 914429214

NY MANIFEST:
Document ID: Not reported
Manifest Status: Not reported
seq: Not reported
Year: Not reported
Trans1 State ID: NJD986607380
Trans2 State ID: Not reported
Generator Ship Date: 12/26/2007
Trans1 Recv Date: 12/26/2007

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

Trans2 Recv Date:	Not reported
TSD Site Recv Date:	01/09/2008
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYD000877423
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSDF ID 1:	SCD036275626
TSDF ID 2:	Not reported
Manifest Tracking Number:	000397168JJK
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1870
Units:	G - Gallons (liquids only)* (8.3 pounds)
Number of Containers:	34
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1
Waste Code:	F001
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

SPDES:

Name:	CITY OF WHITE PLAINS
Address:	255 MAIN STREET
City,State,Zip:	WHITE PLAINS, NY 10601
Permit Number:	NYR20A230
State-Region:	3
Expiration Date:	Not reported
Current Major Minor Status:	Not reported
Primary Facility SIC Code:	Not reported
State Water Body Name:	Not reported
Limit Set Status Flag:	Not reported
Total Actual Average Flow(MGD):	Not reported
Total App Design Flow(MGD):	Not reported
UDF1:	Not reported
Lat/Long:	Not reported

WHITE PLAINS DEPT OF PUBLIC WORKS (Continued) **S105912883**

DMR Cognizant Official:	Not reported
UDF2:	Not reported
UDF3:	Not reported
FIPS County Code:	Not reported
Non-Gov Permit Affiliation Type Desc:	Not reported
Non-Gov Permit Org Formal Name:	Not reported
Non-Gov Permit Street Address:	Not reported
Non-Gov Permit Supplemental Location:	Not reported
Non-Gov Permit City:	Not reported
Non-Gov Permit State Code:	Not reported
Non-Gov Permit Zip Code:	Not reported
Non-Gov Facility Affiliation Type Desc:	Not reported
Non-Gov Facility Org Formal Name:	Not reported
Non-Gov Facility Street Address:	Not reported
Non-Gov Facility Supplemental Location:	Not reported
Non-Gov Facility City:	Not reported
Non-Gov Facility State Code:	Not reported
Non-Gov Facility Zip Code:	Not reported
State Water Body:	Not reported
Region Permit Processed:	Not reported
Dow Discharge Class Code:	Not reported
SPDES Class Description:	MS4
Affiliation Type Description:	Not reported
Name:	THOMAS M ROACH
Contacts Title:	MAYOR
Contacts Email:	Not reported
NOI Submission Date:	03/07/2003

375
SSE
1/4-1/2
0.437 mi.
2309 ft.

MEIER
83 LONGVIEW AVE
WHITE PLAINS, NY

NY LTANKS **S103941556**
N/A

Relative:
Higher

Actual:
248 ft.

LTANKS:

Name:	MEIER
Address:	83 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9903776 / 1999-09-29
Facility ID:	9903776
Site ID:	165399
Spill Date:	1999-07-01
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-07-01
CID:	351
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0

MEIER (Continued) **S103941556**

Date Entered In Computer:	1999-07-01
Spill Record Last Update:	1999-09-30
Spiller Name:	MR MEIER
Spiller Company:	MR MEIER
Spiller Address:	83 LONGVIEW AVE
Spiller County:	001
Spiller Contact:	MR MEIER
Spiller Phone:	(914) 428-2934
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	139409
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 7/19/99 - DEC PRESENT WHEN TANK WAS PULLED BY ABSOLUTE TANK REMOVAL (DAVID PANELLI). EXTENSIVE SOIL AND GROUND WATER CONTAMINATION FOUND. SOIL BEING STOCKPILED FOR DISPOSAL. AWAITING SAMPLES RESULTS TO DECIDE UPON FURTHER COURSE OF ACTION. 9/29/99 - ABSOLUTE TANK REMOVAL DISPOSED OF TANK AND 90.24 TONS CONTAMINATED SOIL. SOME CONTAMINATIN EXTENDED ONTO NEIGHBORING PROPERTY AT 81 LONGVIEW AND WAS REMOVED WITH OWNER'S CONSENT. SOME RESIDUAL CONTAMINATION AT 83 LONGVIEW COULD NOT BE EXCAVATED. PASSIVE SOIL VENT WAS INSTALLED. DEC INSPECTED SITE. NFA "
Remarks:	"TANK PASSED TEST HOWEVER THERE IS STAINING AT 72 INCHES "

All TTF:

Facility ID:	9903776
Spill Number:	9903776
Spill Tank Test:	1547331
Site ID:	165399
Tank Number:	1
Tank Size:	550
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	165399
Operable Unit ID:	1078286
Operable Unit:	01
Material ID:	303679
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BF376 **SPILL NUMBER 9909620** **NY LTANKS** **S104620625**
SE **2 GRANDVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.438 mi.
2315 ft. **Site 3 of 3 in cluster BF**

Relative: **Higher**

Actual: **249 ft.**

LTANKS:

Name:	SPILL NUMBER 9909620
Address:	2 GRANDVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9909620 / 2000-12-21
Facility ID:	9909620
Site ID:	280509
Spill Date:	1999-11-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	A3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	1999-11-08
CID:	382
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1999-11-08
Spill Record Last Update:	2000-12-22
Spiller Name:	ROBERT WEINSTEIN
Spiller Company:	Not reported
Spiller Address:	2 GRANDVIEW AVE
Spiller County:	001
Spiller Contact:	ROBERT WEINSTEIN
Spiller Phone:	(914) 948-7625
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	227764
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 12/21/2000 DUTCHESS ENVIRONMENTAL DISPOSED OF TANK AND 133.45 TONS OF CONTAMINATED SOIL. MONITORING WELLS INSTALLED AND SAMPLED BY E.C.C. FINAL CLOSURE RECEIVED. NO FURTHER ACTION REQUIRED. NFA"
Remarks:	"CONTAMINATED SOIL FOUND DURING A TANK ABANDONEDMENT"

All Materials:

Site ID:	280509
Operable Unit ID:	1084371
Operable Unit:	01
Material ID:	298697
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BE377 **WHITE PLAINS POLICE DEPT** **NY LTANKS** **S100139018**
North **279 HAMILTON AVENUE** **NY MANIFEST** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10601**
0.439 mi.
2317 ft. **Site 2 of 4 in cluster BE**

Relative:
Lower

Actual:
210 ft.

LTANKS:

Name:	POLICE
Address:	279 HAMILTON
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8606771 / 1989-11-29
Facility ID:	8606771
Site ID:	92789
Spill Date:	1987-02-04
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C3
Cleanup Ceased:	1989-11-29
SWIS:	6017
Investigator:	PATEL
Referred To:	Not reported
Reported to Dept:	1987-02-04
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-02-17
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-02-09
Spill Record Last Update:	2007-10-25
Spiller Name:	Not reported
Spiller Company:	WPPD
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	83302
DEC Memo:	"There is a 2007 Region 3 signed stipulation agreement for this site which can be found at: http://internal/home/rgenf/donepages/consent_orders/ mt10/25/07"
Remarks:	"TTTF"

All TTF:

Facility ID:	8606771
Spill Number:	8606771
Spill Tank Test:	1530547
Site ID:	92789
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown

WHITE PLAINS POLICE DEPT (Continued) **S100139018**

Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 92789
Operable Unit ID: 903611
Operable Unit: 01
Material ID: 472333
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

NY MANIFEST:
Name: WHITE PLAINS POLICE DEPT
Address: 279 HAMILTON AVENUE
City,State,Zip: WHITE PLAINS, NY 10601
Country: USA
EPA ID: NYP000877423
Facility Status: Not reported
Location Address 1: 279 HAMILTON AVENUE
Code: BP
Location Address 2: Not reported
Total Tanks: Not reported
Location City: WHITE PLAINS
Location State: NY
Location Zip: 10601
Location Zip 4: Not reported

NY MANIFEST:
EPAID: NYP000877423
Mailing Name: WHITE PLAINS POLICE DEPT
Mailing Contact: WHITE PLAINS POLICE DEPT
Mailing Address 1: 279 HAMILTON AVENUE
Mailing Address 2: Not reported
Mailing City: WHITE PLAINS
Mailing State: NY
Mailing Zip: 10601
Mailing Zip 4: Not reported
Mailing Country: USA
Mailing Phone: 9146824210

NY MANIFEST:
Document ID: PAB5062794
Manifest Status: K
seq: Not reported
Year: 1988
Trans1 State ID: PA-AH0287
Trans2 State ID: PA-AH

WHITE PLAINS POLICE DEPT (Continued) **S100139018**

Generator Ship Date:	10/13/1988
Trans1 Recv Date:	10/13/1988
Trans2 Recv Date:	/ /
TSD Site Recv Date:	10/13/1988
Part A Recv Date:	12/05/1988
Part B Recv Date:	12/20/1988
Generator EPA ID:	NYP000877423
Trans1 EPA ID:	NJD000603563
Trans2 EPA ID:	Not reported
TSDF ID 1:	PAD085690592
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	Not reported
Waste Code:	D001 - NON-LISTED IGNITABLE WASTES
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	04800
Units:	P - Pounds
Number of Containers:	012
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	100

BB378 **RESIDENCE** **NY LTANKS** **S107410432**
SSE **15 SMITH AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.439 mi.
2320 ft. **Site 2 of 3 in cluster BB**

Relative:
Higher

Actual:
258 ft.

LTANKS:

Name:	RESIDENCE
Address:	15 SMITH AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0506586 / 2005-12-18
Facility ID:	0506586
Site ID:	351821
Spill Date:	2005-08-29
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported

RESIDENCE (Continued) **S107410432**

Reported to Dept:	2005-08-29
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-08-29
Spill Record Last Update:	2005-12-18
Spiller Name:	LOPERA
Spiller Company:	RESIDENCE
Spiller Address:	15 SMITH AVE
Spiller County:	001
Spiller Contact:	LOPERA
Spiller Phone:	(864) 843-1641
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	299098
DEC Memo:	"-no known impacts - will report to O'Dee December 18, 2005: NES DISPOSED OF LUST AND 164.79 TONS OF CONTAMINATED SOIL. GROUND WATER WAS IMPACTED, MONITORING WELL INSTALLED AND SAMPLED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"tank removal, tank size 550 gallons."

All Materials:

Site ID:	351821
Operable Unit ID:	1109326
Operable Unit:	01
Material ID:	2099325
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

379 NNE 1/4-1/2 0.445 mi. 2348 ft. **HAMILTON MAIN PARKING STR** **NY LTANKS** **S100139680**
HAMILTON AVE & MAIN ST **N/A**
WHITE PLAINS, NY

Relative: Higher
Actual: 219 ft.

LTANKS:

Name:	HAMILTON MAIN PARKING STR
Address:	HAMILTON AVE & MAIN ST
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8707260 / 1989-11-29
Facility ID:	8707260
Site ID:	286661
Spill Date:	1987-11-23
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other

HAMILTON MAIN PARKING STR (Continued) **S100139680**

Spill Class:	Not reported
Cleanup Ceased:	1989-11-29
SWIS:	6017
Investigator:	UNASSIGNED
Referred To:	Not reported
Reported to Dept:	1987-11-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1987-11-27
Spill Record Last Update:	1989-11-29
Spiller Name:	RED BROCCHI
Spiller Company:	C/WHITE PLAINS
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	232336
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was "
Remarks:	"2K TANK SYSTEM -.5257 GPH, TO E, I & R"

All TTF:

Facility ID:	8707260
Spill Number:	8707260
Spill Tank Test:	1532412
Site ID:	286661
Tank Number:	Not reported
Tank Size:	0
Material:	0001
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	286661
Operable Unit ID:	911136
Operable Unit:	01
Material ID:	466224
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

HAMILTON MAIN PARKING STR (Continued) **S100139680**

Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

BE380 **FORMER WPPD** **NY LTANKS** **S106702646**
North **279 HAMITON AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.445 mi.
2350 ft. **Site 3 of 4 in cluster BE**

Relative: **Higher**
Actual: **211 ft.**

LTANKS:

Name:	FORMER WPPD
Address:	279 HAMITON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0405806 / 2007-07-06
Facility ID:	0405806
Site ID:	306552
Spill Date:	1987-01-01
Spill Cause:	Tank Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2004-08-27
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	2004-08-27
Spill Record Last Update:	2007-07-06
Spiller Name:	Not reported
Spiller Company:	WHITE PLAINS POLICE DEPT
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	247580
DEC Memo:	"7/6/07 Tipple met with Kahabka and conducted a final inspection of all remaining work as indicated in the STIP. Stip obligations for the installation of engineering controls have been met, continued inspections of those engineering controls to be conducted regularly by the NYPA as per the STIP."
Remarks:	"Area is going to be cleaned up."

All Materials:

Site ID:	306552
Operable Unit ID:	889358
Operable Unit:	01
Material ID:	486659

FORMER WPPD (Continued) **S106702646**

Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported
Site ID:	306552
Operable Unit ID:	889358
Operable Unit:	01
Material ID:	486658
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

381
SE
1/4-1/2
0.448 mi.
2364 ft.

APARTMENT BUILDING
10 OLD MAMARONECK ROAD
WHITE PLAINS, NY

NY LTANKS **S103558581**
NY Spills **N/A**

Relative:
Higher

Actual:
241 ft.

LTANKS:

Name:	WESTLEY HOUSE LIMITED
Address:	10 OLD MAMARONECK RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206840 / 2002-12-13
Facility ID:	0206840
Site ID:	263963
Spill Date:	2002-10-02
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	D3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-10-02
CID:	270
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-10-02
Spill Record Last Update:	2003-03-25
Spiller Name:	JOE FABRIS
Spiller Company:	WESTLEY HOUSE LIMITED
Spiller Address:	10 OLD MAMARONECK RD

APARTMENT BUILDING (Continued) **S103558581**

Spiller County:	001
Spiller Contact:	JOE FABRIS
Spiller Phone:	(914) 774-6733
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	215156
DEC Memo:	""
Remarks:	"1 - 2 in gap in tank where weld was not complete after tank cleaning"
	Not reported

All TTF:

Facility ID:	0206840
Spill Number:	0206840
Spill Tank Test:	1527521
Site ID:	263963
Tank Number:	Not reported
Tank Size:	7000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	263963
Operable Unit ID:	858600
Operable Unit:	01
Material ID:	517433
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	WESLEY APARTMENT BLDG
Address:	10 OLD MAMARONECK RD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9810881 / 2004-04-30
Facility ID:	9810881
Site ID:	263964
Spill Date:	1998-11-30
Spill Cause:	Tank Test Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD

APARTMENT BUILDING (Continued) **S103558581**

Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-30
CID:	312
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-30
Spill Record Last Update:	2004-04-30
Spiller Name:	JOYCE PARKER - MGR
Spiller Company:	WESLEY APARTMENT MGMT
Spiller Address:	10 OLD MAMARONECK RD
Spiller County:	001
Spiller Contact:	LOUIE BERISHA - SUPT
Spiller Phone:	(914) 761-2389
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	215156
DEC Memo:	""
Remarks:	"gross failure of tank - #4 oil IN THE TANK. Tank tested advised Louie Berisha, superintendent. WCHD to follow up."

All TTF:

Facility ID:	9810881
Spill Number:	9810881
Spill Tank Test:	1546581
Site ID:	263964
Tank Number:	001
Tank Size:	7500
Material:	Not reported
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

Name:	APARTMENT BUILDING
Address:	10 OLD MAMARONECK ROAD
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0910093 / 2010-04-29
Facility ID:	0910093
Site ID:	422835
Spill Date:	2009-12-11
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA

APARTMENT BUILDING (Continued) **S103558581**

Referred To:	WCDOH
Reported to Dept:	2009-12-11
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2009-12-11
Spill Record Last Update:	2010-04-29
Spiller Name:	LUIGI BERISHA
Spiller Company:	LUIGI BERISHA
Spiller Address:	10 OLD MAMARONECK ROAD
Spiller County:	999
Spiller Contact:	LUIGI BERISHA
Spiller Phone:	(914) 804-7076
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	371759
DEC Memo:	"12-11-09 Tester reports a wet leak. Tank has a remtoe fill that is below the liquid level of the tank. He is unsure if the leak is the tank, remote fill or the gauge. Tank has 48 of product and no measurable water. There is a gauge well near the tank. No signs of potential contamination. jc 4/29/10 Wesley House 10 Old Mamaroneck Rd White Plains ttf 12/11/09. passed retest 1/20/10 after tank cleaning. NFA JO'M "
Remarks:	"TANK TEST FAILURE."

All Materials:

Site ID:	422835
Operable Unit ID:	1178659
Operable Unit:	01
Material ID:	2172155
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

SPILLS:

Name:	10 OLD MAMARONECK
Address:	10 OLD MAMARONECK
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0311798 / 2004-03-11
Facility ID:	0311798
Facility Type:	ER
DER Facility ID:	182634
Site ID:	220818
DEC Region:	3
Spill Cause:	Other
Spill Class:	B3

APARTMENT BUILDING (Continued) **S103558581**

SWIS:	6017
Spill Date:	2004-01-20
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2004-01-20
CID:	403
Water Affected:	Not reported
Spill Source:	Private Dwelling
Spill Notifier:	Police Department
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-20
Spill Record Last Update:	2004-03-11
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	WHITE PLAINS FIRE DEPT
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD-MAGNUSON 03/11/04 CLEAN UP COMPLETED BY NORTHEAST ENVIRONMENTAL. CLOSED BY KAREN MAGNUSON OF WESTCHESTER COUNTY HEALTH DEPARTMENT."
Remarks:	"THE POLICE DEPARTMENT SAID THAT THERE WAS A FIRE ABOUT 20 MINS AGO. THEY PUT IT OUT. WHEN THEY PUT IT OUT THEY SAW THAT DIESEL FUEL HAD LEAKED OUT. THEY ARE PUTTING DOWN SPEEDY DRY."

All Materials:

Site ID:	220818
Operable Unit ID:	879390
Operable Unit:	01
Material ID:	497044
Material Code:	0008
Material Name:	diesel
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG382 **COMMERICAL BUILDING** **NY LTANKS** **S118953530**
NNW **10 NEW KING STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.452 mi.
2386 ft. **Site 1 of 7 in cluster BG**

Relative: **Lower**

Actual: **201 ft.**

LTANKS:

Name:	COMMERICAL BUILDING
Address:	10 NEW KING STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1006070 / 2010-10-28
Facility ID:	1006070
Site ID:	439407
Spill Date:	2010-09-01

COMMERICAL BUILDING (Continued) **S118953530**

Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JKOMARA
Referred To:	Not reported
Reported to Dept:	2010-09-01
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-09-01
Spill Record Last Update:	2010-10-28
Spiller Name:	KAREN GOMEZ
Spiller Company:	BENEROFE GROUP
Spiller Address:	10 NEW KING STREET
Spiller County:	999
Spiller Contact:	KAREN GOMEZ
Spiller Phone:	(914) 681-5100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	394398
DEC Memo:	"9-1-10 Spoke with Bob. He says the leak appears to be very minor. They will uncover tank and investigate cause of tank test failure - then repair and retest. This is a 10k UST. 10/28/10 Pased Retest 9/24/10 NFA JO'M"
Remarks:	"The tank is located underground and failed the tank test. Benerofe group is the responsible party."

All Materials:

Site ID:	439407
Operable Unit ID:	1190052
Operable Unit:	01
Material ID:	2185019
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BE383 **EXXON, WHITE PLAINS** **NY LTANKS** **S103571230**
North **274 HAMILTON AVE** **NY Spills** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.452 mi.
2386 ft. **Site 4 of 4 in cluster BE**

Relative:
Lower

Actual:
210 ft.

LTANKS:

Name:	EXXON, WHITE PLAINS
Address:	274 HAMILTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	8707486 / 1987-12-18
Facility ID:	8707486
Site ID:	190041
Spill Date:	1987-12-01
Spill Cause:	Tank Test Failure
Spill Source:	Gasoline Station or other PBS Facility
Spill Class:	D3
Cleanup Ceased:	1987-12-18
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1987-12-02
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1987-12-18
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	True
Remediation Phase:	0
Date Entered In Computer:	1987-12-02
Spill Record Last Update:	1988-02-12
Spiller Name:	Not reported
Spiller Company:	EXXON
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	93029
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON / / : 2-9-88 PASSED RET. ON 12-17-87. N.F.A. L.R. "
Remarks:	"4K TANK SYS. WOULD NOT HOLD COLUMN, TO ESCAVATE & LOCATE LEAK"

All TTF:

Facility ID:	8707486
Spill Number:	8707486
Spill Tank Test:	1532487
Site ID:	190041
Tank Number:	Not reported
Tank Size:	0
Material:	0009
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00

EXXON, WHITE PLAINS (Continued) **S103571230**

Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	190041
Operable Unit ID:	911639
Operable Unit:	01
Material ID:	466435
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	Not reported
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CUMBERLAND FARMS # 70324
Address:	274 HAMILTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0806742 / 2009-02-24
Facility ID:	0806742
Facility Type:	ER
DER Facility ID:	93029
Site ID:	404037
DEC Region:	3
Spill Cause:	Other
Spill Class:	C3
SWIS:	6017
Spill Date:	2008-09-15
Investigator:	TDGHIOSA
Referred To:	WCDOH / PBS 3-164135
Reported to Dept:	2008-09-15
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-15
Spill Record Last Update:	2009-02-24
Spiller Name:	BRAIN HAWE
Spiller Company:	CUMBERLAND FARMS # 70324
Spiller Address:	274 HAMILTON AVE
Spiller Company:	999
Contact Name:	BRAIN HAWE
DEC Memo:	"1K FUEL OIL TANK REMOVAL. NO EVIDENCE OF RELEASE UPON REMOVAL. LAB RESULTS CAME BACK WITH SVOC DETECTION. WILL SUBMIT REPORT. DT 02/2009 UST closure report submitted by Leggette Brashears & Graham. Based on

EXXON, WHITE PLAINS (Continued) **S103571230**

the information contained in that report, no further action required.
TG"

Remarks: "CALLER STATES THAT THEY WERE REMOVING TANKS AND NOTICED CONTAMINATED SOIL. CALLER STATES THAT LAB RESULTS CONFIRMED CONTAMINATION."

All Materials:

Site ID:	404037
Operable Unit ID:	1160714
Operable Unit:	01
Material ID:	2151889
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	EXXON SERVICE STATION
Address:	274 HAMILTON AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9707887 / Not Reported
Facility ID:	9707887
Facility Type:	ER
DER Facility ID:	93029
Site ID:	105471
DEC Region:	3
Spill Cause:	Other
Spill Class:	A3
SWIS:	6017
Spill Date:	1997-10-03
Investigator:	MBMASTRO
Referred To:	Not reported
Reported to Dept:	1997-10-03
CID:	282
Water Affected:	Not reported
Spill Source:	Gasoline Station or other PBS Facility
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	5
Date Entered In Computer:	1997-10-03
Spill Record Last Update:	2017-09-20
Spiller Name:	Not reported
Spiller Company:	EXXON SERVICE STATION
Spiller Address:	SAME
Spiller Company:	001
Contact Name:	MICHAEL MEOLA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was HARDY 06/08/98 LETTER SENT DEC REQUIRES SOIL AND INVESTIGATION OF SITE IN 6 MONTHS 02/09/01 LETTER SENT TO EXXONMOBIL BY J. HARDY; ADVISE AS TO THE SIGNIFICANCE OF THE WHITE PLAINS MALL DENIAL OF ACCESS. 03/15/01 LETTER SENT TO EXXONMOBIL BY J. HARDY; SCHEDULE FOR

EXXON, WHITE PLAINS (Continued) **S103571230**

SUBMISSION OF AN INVESTIGATION REPORT BY 4/30/01 IS APPROVED & REQUIRED. Letter to K. Bourque, Groundwater & Env. Svcs. from J. Hardy, dated 6/27/2003. Reduce monitor well sampling to semi-annually, report annually. 09/04/03: Letter to Eric Harvey, Groundwater & Env. Services, Inc from J. Hardy. Reduce monitor well sampling to semi-annually. Report annually. 6/22/09 2008 annual report shows persistent contamination of approximately 5k btex at mw1--sent email to lbg sirecting them to define extent of contamination in that vicinity within 45 days--email is in edocs jh 10/26/09 2009 annual report shows all wells stable (and low)except mw-1 which has gone down to approx 3k btex. 11/10/09 as a result of decrease in mw1 above gave cf option, by email, to start quarterly sampling and reporting instead of investigation at this time. In that case we would consider future action based on whether downward trend continues or not. email in edocs jh 4/21/10 jan 10 sampling shows levels approx same as last period jh 11/22/10 Project transferred to Mastro. 5/25/11 BTEX concentrations remain high in MW-1. Will continue to monitor...mm 5/7/12 See quarterly monitoring reports in edocs...mm 02/12/13 A workplan has been developed and approved to investigate the BTEX in MW-1. Four monitoring wells will be installed and soil samples will be collected for lab analysis. 7/2013 Four monitoring wells were installed..mm 3/30/2017 The BTEX concentrations in MW-1 and MW-4 remain high and unchanged. Off site wells are ND. The consultant, LBG, has been asked to develop a RAP...mm 8/01/17 The 2ndQMR report was submitted by LBG. RAP will be proposed by m10/31/17...mm"

Remarks: "WHILE REMOVING ABANDONED UNDERGROUND 1000 GALLON TANK ELEVATED PID HEAD SPACE READINGS WERE ENCOUNTERED "

All Materials:

Site ID:	105471
Operable Unit ID:	1051107
Operable Unit:	01
Material ID:	329872
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

BB384 **BASS HOME** **NY LTANKS** **S108299323**
SSE **98 DAVIS AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.453 mi.
2392 ft. **Site 3 of 3 in cluster BB**

Relative:
Higher

Actual:
261 ft.

LTANKS:

Name:	BASS HOME
Address:	98 DAVIS AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0611529 / 2007-06-25
Facility ID:	0611529
Site ID:	376177
Spill Date:	2007-01-17

BASS HOME (Continued) **S108299323**

Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2007-01-17
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2007-01-17
Spill Record Last Update:	2007-06-25
Spiller Name:	JOHN BASS
Spiller Company:	BASS HOME
Spiller Address:	98 DAVIS AVE
Spiller County:	001
Spiller Contact:	JOHN BASS
Spiller Phone:	(201) 832-5822
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	325772
DEC Memo:	"Northeast waiting for homeowner to sign contract for further cleanup. 6/25/2007: Spill closure report received and reviewed by DEC. Based upon information provided, this Department requires No Further Action at this time. jod"
Remarks:	"1000 gallon tank had holes and contaminated soil"

All Materials:

Site ID:	376177
Operable Unit ID:	1133780
Operable Unit:	01
Material ID:	2123602
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG385 **OFFICE BLDG** **NY LTANKS** **S103558242**
NNW **4 NEW KING ST** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.453 mi.
2392 ft. **Site 2 of 7 in cluster BG**

Relative: **Lower**

Actual: **201 ft.**

LTANKS:

Name:	OFFICE BLDG
Address:	4 NEW KING ST
City,State,Zip:	WHITE PLAINS, NY

OFFICE BLDG (Continued) **S103558242**

Spill Number/Closed Date:	9809692 / 2003-12-05
Facility ID:	9809692
Site ID:	170684
Spill Date:	1998-11-02
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-11-02
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-11-02
Spill Record Last Update:	2003-12-05
Spiller Name:	Not reported
Spiller Company:	OFFICE BLDG
Spiller Address:	4 NEW KING ST
Spiller County:	001
Spiller Contact:	TOM CAFFERTY
Spiller Phone:	(914) 697-7654
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	143629
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WCHD - MCDONALD 12/05/03 CLOSED BY BARBARA McDONALD OF WCHD. TANK REMOVED JANUARY OF 1999."
Remarks:	"REOMMEND UNCOVER TANK - ISOLATE FOR RETEST"

All TTF:

Facility ID:	9809692
Spill Number:	9809692
Spill Tank Test:	1546478
Site ID:	170684
Tank Number:	1
Tank Size:	2000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	F
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	170684

OFFICE BLDG (Continued) **S103558242**

Operable Unit ID:	1066903
Operable Unit:	01
Material ID:	313593
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BG386 **CE - WHITE PLAINS MGP** **NY ENG CONTROLS** **S106906513**
NNW **9 NEW STREET AND 12 WATER STREET** **NY INST CONTROL** **N/A**
1/4-1/2 **WHITE PLAINS, NY** **NY VCP**
0.459 mi.
2424 ft. **Site 3 of 7 in cluster BG**

Relative: **Lower**

Actual: **201 ft.**

ENG CONTROLS:

Name:	CE - WHITE PLAINS MGP
Address:	9 NEW STREET AND 12 WATER STREET
City,State,Zip:	WHITE PLAINS, NY
Site Code:	58617
HW Code:	Not reported
Control Code:	15
Control Type:	ENG
Date Record Added:	06/19/2008
Date Rec Updated:	04/02/2020
Updated By:	DJEATON
Site Description:	The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site

CE - WHITE PLAINS MGP (Continued) **S106906513**

management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem:	The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/18/2012 4:09:00 PM
Record Upd:	10/18/2012 4:09:00 PM
Updated By:	ldennist
Own Op:	6
Sub Type:	Not reported
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 6901
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

Name:	CE - WHITE PLAINS MGP
Address:	9 NEW STREET AND 12 WATER STREET
City,State,Zip:	WHITE PLAINS, NY
Site Code:	58617
HW Code:	Not reported
Control Code:	13
Control Type:	ENG
Date Record Added:	06/19/2008
Date Rec Updated:	04/02/2020
Updated By:	DJEATON
Site Description:	The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of

CE - WHITE PLAINS MGP (Continued) **S106906513**

contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem:	The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.
Health Problem:	Not reported
Dump:	False
Structure:	False
Lagoon:	False
Landfill:	False
Pond:	False
Disp Start:	Not reported
Disp Term:	Not reported
Lat/Long:	Not reported
Dell:	Not reported
Record Add:	10/18/2012 4:09:00 PM
Record Upd:	10/18/2012 4:09:00 PM
Updated By:	ldennist
Own Op:	6
Sub Type:	Not reported
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 6901
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

INST CONTROL:

Name:	CE - WHITE PLAINS MGP
Address:	9 NEW STREET AND 12 WATER STREET
City,State,Zip:	WHITE PLAINS, NY
Site Code:	58617
Control Name:	Soil Management Plan
HW Code:	Not reported
Control Code:	14
Control Type:	INST
Dt record added:	06/19/2008
Dt rec updated:	04/02/2020
Updated By:	DJEATON
Site Code:	58617
Site Description:	The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located

CE - WHITE PLAINS MGP (Continued) **S106906513**

over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.

Health Problem: Not reported

Dump: False

Structure: False

Lagoon: False

CE - WHITE PLAINS MGP (Continued) **S106906513**

Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/18/2012 4:09:00 PM
Record Upd: 10/18/2012 4:09:00 PM
Updated By: ldennist
Own Op: 6
Sub Type: Not reported
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 6901
Owner Country: United States of America
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: CE - WHITE PLAINS MGP
Address: 9 NEW STREET AND 12 WATER STREET
City,State,Zip: WHITE PLAINS, NY
Site Code: 58617
Control Name: Ground Water Use Restriction

CE - WHITE PLAINS MGP (Continued) **S106906513**

HW Code: Not reported
Control Code: 8
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/02/2020
Updated By: DJEATON
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.
Env Problem: The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by

CE - WHITE PLAINS MGP (Continued) **S106906513**

installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.

Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/18/2012 4:09:00 PM
Record Upd: 10/18/2012 4:09:00 PM
Updated By: ldennist
Own Op: 6
Sub Type: Not reported
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 6901
Owner Country: United States of America
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported

CE - WHITE PLAINS MGP (Continued) **S106906513**

Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: CE - WHITE PLAINS MGP
Address: 9 NEW STREET AND 12 WATER STREET
City,State,Zip: WHITE PLAINS, NY
Site Code: 58617
Control Name: Landuse Restriction
HW Code: Not reported
Control Code: 25
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/02/2020
Updated By: DJEATON
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related

CE - WHITE PLAINS MGP (Continued) **S106906513**

contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.
Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/18/2012 4:09:00 PM
Record Upd: 10/18/2012 4:09:00 PM
Updated By: ldennist
Own Op: 6
Sub Type: Not reported
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 6901
Owner Country: United States of America

CE - WHITE PLAINS MGP (Continued) **S106906513**

HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

Name: CE - WHITE PLAINS MGP
Address: 9 NEW STREET AND 12 WATER STREET
City,State,Zip: WHITE PLAINS, NY
Site Code: 58617
Control Name: Deed Restriction
HW Code: Not reported
Control Code: Not reported
Control Type: INST
Dt record added: 06/19/2008
Dt rec updated: 04/02/2020
Updated By: DJEATON
Site Code: 58617
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show

CE - WHITE PLAINS MGP (Continued) **S106906513**

any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.

Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported
Record Add: 10/18/2012 4:09:00 PM
Record Upd: 10/18/2012 4:09:00 PM
Updated By: ldennist
Own Op: 6
Sub Type: Not reported
Owner Name: Yelena Skorobogatov
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address: 31-01 20TH AVE
Owner Addr2: Not reported
Owner City,St,Zip: LONG ISLAND CITY, NY 11105
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 9 NEW STREET PROP
Owner Company: CONSOLIDATED EDISON COMPANY OF NY IN

CE - WHITE PLAINS MGP (Continued) **S106906513**

Owner Address: 4 IRVING PLACE
Owner Addr2: Not reported
Owner City,St,Zip: NEW YORK, NY 10003
Owner Country: United States of America
Own Op: 1
Sub Type: ZZZ
Owner Name: 12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company: PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address: 177 BROAD ST.
Owner Addr2: Not reported
Owner City,St,Zip: STAMFORD, CT 6901
Owner Country: United States of America
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: Not reported
Waste Type: COAL TAR
Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: Not reported

VCP:
Name: CE - WHITE PLAINS MGP
Address: 9 NEW STREET AND 12 WATER STREET
City,State,Zip: WHITE PLAINS, NY
Program Type: VCP
Site Code: 58617
HW Code: V00438
Site Class: Not reported
SWIS: 6017
Region: 3
Town: White Plains (c)
Acres: Not reported
Date Record Added: 02/22/2001
Date Record Updated: 03/11/2020
Updated By: DJEATON
Site Description: The site is located near the edge of downtown in the City of White Plains, Westchester County. The address of the central portion of the site is 12 Water Street. The site is bounded by Water Street to the north, New Street to the South, and North Lexington Avenue to the west. It is bounded to the east by a parking lot which is located over the former road bed of Spring Street. OU1 includes the Southern Relief Holder on the manufacture gas plant (MGP) site and the off-site area to the south which includes Saint John's Catholic Church. The Holder was removed by a 2004-2005 Interim Remedial Measure (IRM). There is no record of any MGP activity on the St. John s Property, but some MGP tar is present deep underground. A site

CE - WHITE PLAINS MGP (Continued) **S106906513**

management plan and monitoring plan is in place for the St. John's property. Operable Unit 2 addresses the remainder of the MGP site, located on the Water Street portion of the site. Nature of contamination: The Remedial Investigation identified the presence of coal tar in the subsurface soil. Contaminants of concerns in the tar include polycyclic aromatic hydrocarbons (PAHs) and the volatile compounds benzene, toluene, ethylbenzene and xylene (BTEX). Extent of contamination: Coal tar, a non-aqueous phase liquid (NAPL), is present in the subsurface of the plant site (OU2) in the proximity of historic MGP structures. This contamination appears to have migrated south, west and vertically down from these structures. The relief gas holder foundation, which is part of OU1, was heavily contaminated with MGP tar, and was removed through an excavation IRM in 2004-5. In addition to the excavation, a NAPL cutoff wall and NAPL recovery wells were installed. Monthly monitoring of these wells did not show any significant accumulation of NAPL, and the monitoring frequency for these wells was reduced to quarterly in May 2006. A site management plan (SMP) is in place, but will be superseded by a site-wide SMP and environmental easement following the completion of the OU1 remedy. The November 8, 2005 Remedial Investigation report indicates a thin seam of MGP tar has migrated through the subsurface and is present beneath the St John s property at a depth of approximately 36 to 43 feet below the basement floor (which is in turn at least 10 feet below grade) and 52-60 feet below ground surface south of the building. Groundwater sampling indicates that the deep groundwater in close proximity to the tar seam is impacted; however, shallow groundwater is not. Furthermore, site-related contamination was not detected in sub-slab soil vapor samples from directly beneath the basement slab of the school or the indoor air samples collected inside the school. No active remediation is proposed as part of the remedy presented in the 2007 Remedial Action Work Plan (RAWP). Coal tar is present under much of the parking area at 12 Water Street (OU-2). This area was remediated from December 2008 through June 2010 using in-situ solidification as described in the 2007 RAWP.

Env Problem: The site is impacted by manufactured gas plant (MGP) operations, including dense non-aqueous phase liquid (DNAPL) MGP tar at the site as well as off-site to the south. The off-site migration of tar was addressed during the 2004 interim remedial measures (IRM) by installing a down-gradient non-aqueous phase liquid (NAPL) cut-off wall. The southern gas holder was also removed during the IRM. NAPL south of the cut-off wall is sufficiently deep, and is located below clean groundwater, so exposure to environmental receptors is not likely. A Decision Document was finalized in Feb 2008, selecting in situ stabilization for the remaining portion of OU2. Field work was completed in 2010 and the Final Engineering Report was approved in May 2012.

Health Problem: Not reported
Dump: False
Structure: False
Lagoon: False
Landfill: False
Pond: False
Disp Start: Not reported
Disp Term: Not reported
Lat/Long: Not reported
Dell: Not reported

CE - WHITE PLAINS MGP (Continued) **S106906513**

Record Add:	10/18/2012 4:09:00 PM
Record Upd:	10/18/2012 4:09:00 PM
Updated By:	ldennist
Own Op:	6
Sub Type:	Not reported
Owner Name:	Yelena Skorobogatov
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	31-01 20TH AVE
Owner Addr2:	Not reported
Owner City,St,Zip:	LONG ISLAND CITY, NY 11105
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	9 NEW STREET PROP
Owner Company:	CONSOLIDATED EDISON COMPANY OF NY IN
Owner Address:	4 IRVING PLACE
Owner Addr2:	Not reported
Owner City,St,Zip:	NEW YORK, NY 10003
Owner Country:	United States of America
Own Op:	1
Sub Type:	ZZZ
Owner Name:	12 WATER ST PRO C/O CB RIC.ELLIS INC
Owner Company:	PRINCIPAL MUTUAL LIFE INSURANCE CO
Owner Address:	177 BROAD ST.
Owner Addr2:	Not reported
Owner City,St,Zip:	STAMFORD, CT 6901
Owner Country:	United States of America
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
HW Code:	Not reported
Waste Type:	COAL TAR
Waste Quantity:	UNKNOWN
Waste Code:	Not reported
Crossref ID:	Not reported
Cross Ref Type Code:	Not reported
Cross Ref Type:	Not reported
Record Added Date:	Not reported
Record Updated:	Not reported
Updated By:	Not reported

BG387 **WHITE PLAINS MGP SITE** **EDR MGP** **1008408071**
NNW **9 NEW STREET AND 12 WATER STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10601**
0.459 mi.
2424 ft. **Site 4 of 7 in cluster BG**

Relative: Manufactured Gas Plants:
Lower
No additional information available

Actual:
201 ft.

BG388 **NUCLEAR DEVELOPMENT CORP. OF AMERICA** **FUSRAP** **1016603375**
NNW **5 NEW STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.460 mi.
2429 ft. **Site 5 of 7 in cluster BG**

Relative: **Lower**
Actual: **201 ft.**

FUSRAP:

Site Name:	NUCLEAR DEVELOPMENT CORP. OF AMERICA
Site Id:	NY.32
Site Status:	Eliminated from consideration under FUSRAP
Designated Name:	Not Designated
Alternate Name:	None
Location Street Address:	5 NEW STREET
Location City:	WHITE PLAINS
Location State:	NY
Location County:	Not reported
Evaluation Year:	1987
Site Oprerations:	Conducted experiments involving uranium recovery from scrap.
Site Disposition:	Eliminated - No Authority - Facility was licensed to handle nuclear materials
Radioactice Materials Handled:	Yes
Primary Radioactivce Materials Handled:	Uranium
Radiological Survey(S):	None Indicated
Long Term Care Requirements:	Not reported
Historical Operations:	Not reported
Website URL:	www.lm.doe.gov/Considered_Sites/Nuclear_Development_Corp_of_America_-_NY_32.aspx

---

BG389 **COMMERCIAL** **NY LTANKS** **S109208790**
NNW **3 NEW KING STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY 10603**
0.460 mi.
2431 ft. **Site 6 of 7 in cluster BG**

Relative: **Lower**
Actual: **201 ft.**

LTANKS:

Name:	3 NEW KING ST
Address:	3 NEW KING STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0806330 / 2010-03-30
Facility ID:	0806330
Site ID:	403607
Spill Date:	2008-09-05
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH PBS
Reported to Dept:	2008-09-05
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2008-09-05
Spill Record Last Update:	2010-03-30

COMMERCIAL (Continued) **S109208790**

Spiller Name:	Not reported
Spiller Company:	JAM NEW KING HOLDING CORP
Spiller Address:	4 NEW KING ST
Spiller County:	999
Spiller Contact:	ALBERT LOPEZ
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	352839
DEC Memo:	"9/5/08: caller imformed owner about retest, etc.. awaiting answer...ra Unregistered PBS facility. jod 11/12/08: Passing retest on 9/26/08 after tightening fitting at boiler and repairing petrometer. NFA jod 3/30/10: As per Wayne Schneider: 0806330: 3 New king St, White Plains- passed retest after boiler fittings and petrometer were replaced NFA again! jod"
Remarks:	"Above company did a dry tank test and had a failure on the tank, but no product was lost."

All Materials:

Site ID:	403607
Operable Unit ID:	1160299
Operable Unit:	01
Material ID:	2151464
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Name:	COMMERCIAL
Address:	3 NEW KING STREET
City,State,Zip:	WHITE PLAINS, NY 10603
Spill Number/Closed Date:	1600651 / 2017-04-04
Facility ID:	1600651
Site ID:	525932
Spill Date:	2016-04-19
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	RDBENDEL
Referred To:	Not reported
Reported to Dept:	2016-04-19
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2016-04-19
Spill Record Last Update:	2017-04-04

COMMERCIAL (Continued) **S109208790**

Spiller Name:	TOM FITSGIBBONS
Spiller Company:	LORDAE PROPERTIES
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	DAVE GASTLE
Spiller Phone:	(631) 321-4670
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	480144
DEC Memo:	"4-19-16 Called and spoke with Dave and then left message for Tom to return call to dispatch desk. Two USTs were tested - 550 passed, 2k failed (small dry leak?). Toms email is tom@lordae.com. jm Recv'd callback from Tom Fitzsimmons. They have been in touch with Envirostar about removing both tanks and will proceed in this direction. PBS #3-800342 jm"
Remarks:	"Failed Tank Test."

All Materials:

Site ID:	525932
Operable Unit ID:	1274876
Operable Unit:	01
Material ID:	2279538
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

Site ID:	525932
Operable Unit ID:	1274876
Operable Unit:	01
Material ID:	2279539
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BG390 **SPILL NUMBER 0000953** **NY LTANKS** **S104621025**
NNW **1 NEW KING STREET** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.461 mi.
2433 ft. **Site 7 of 7 in cluster BG**

Relative: **Lower**

Actual: **201 ft.**

LTANKS:

Name:	SPILL NUMBER 0000953
Address:	1 NEW KING STREET
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0000953 / 2001-02-07
Facility ID:	0000953
Site ID:	272947

SPILL NUMBER 0000953 (Continued) **S104621025**

Spill Date:	2000-04-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2000-04-24
CID:	396
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2000-04-24
Spill Record Last Update:	2003-08-05
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	KAREN
Spiller Phone:	(914) 681-5100
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	222123
DEC Memo:	""
Remarks:	"tank test failure will retest later"

All Materials:

Site ID:	272947
Operable Unit ID:	822651
Operable Unit:	01
Material ID:	289183
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BD391 **COMMERCIAL BLDG** **NY LTANKS** **S109064330**
SW **2 SOUNDVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.464 mi.
2452 ft. **Site 2 of 2 in cluster BD**

Relative:
Higher

Actual:
258 ft.

LTANKS:

Name:	COMMERCIAL BLDG
Address:	2 SOUNDVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0801427 / 2008-11-12
Facility ID:	0801427

COMMERCIAL BLDG (Continued) **S109064330**

Site ID:	397346
Spill Date:	2008-05-06
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	WCDOH
Reported to Dept:	2008-05-06
CID:	444
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-05-06
Spill Record Last Update:	2008-11-12
Spiller Name:	DEBRA DAHL
Spiller Company:	Not reported
Spiller Address:	2 SOUNDVIEW AVE
Spiller County:	001
Spiller Contact:	DEBRA DAHL
Spiller Phone:	(718) 830-0130
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	346774
DEC Memo:	"5-6-08 Called and left message for Amy to return call. Spoke with Amy. They believe that there is a piping problem and are recommending to the RP that they repair the lines and call client back for retest. JMcC 11/12/08: Piping replaced. System passed retest on 6/18/08 NFA jod "
Remarks:	"MASA 2D:"

All TTF:

Facility ID:	0801427
Spill Number:	0801427
Spill Tank Test:	2486033
Site ID:	397346
Tank Number:	Not reported
Tank Size:	3000
Material:	Not reported
EPA UST:	Not reported
UST:	False
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Watchdog
Last Modified Date:	Not reported

All Materials:

Site ID:	397346

COMMERCIAL BLDG (Continued) **S109064330**

Operable Unit ID:	1154315
Operable Unit:	01
Material ID:	2145105
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	NETHERLAND GARDENS APT COMPLEX
Address:	2 SOUNDVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	2002195 / Not Reported
Facility ID:	2002195
Site ID:	606872
Spill Date:	2020-06-24
Spill Cause:	Tank Test Failure
Spill Source:	Non Major Facility > 1,100 gal
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JPCUMMIN
Referred To:	Not reported
Reported to Dept:	2020-06-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	1
Date Entered In Computer:	2020-06-24
Spill Record Last Update:	2020-07-01
Spiller Name:	K. MORGAN
Spiller Company:	McGrath Management
Spiller Address:	2 SOUNDVIEW AVE
Spiller County:	999
Spiller Contact:	NICK SALZARULO
Spiller Phone:	(845) 896-5444
Spiller Extention:	109
DEC Region:	3
DER Facility ID:	346774
DEC Memo:	"6/24/20- Spoke to Cathy: Tank test failure at Netherland Gardens. Building #2 Dripping sound coming from the return line triggered the failure. Repairs being done. WC PBS# 3-800363 Being addressed by McGrath Management Contact: Nick Salzarulo 845 896 5444 ext 109 -MS 6/25/20: From Chris Lalak at WCDoH: TTF 3K UST (tank ID 002) Tank is out of service, facility has switched to Gas. Oil tank has been run down to empty, but not pumped out. Tank to be pumped out immediately. Northeast Environmental is will removing tank. 2nd tank on site (tank ID 205) is also out of service and will be closed in place. 3-800363 Netherland Gardens owners inc 2 Soundview Ave, White Plains Contact

COMMERCIAL BLDG (Continued) **S109064330**

is Nick 845-896-5444 x-109 jod"
Remarks: "3000 ust . tank failure. bldg #2"

All Materials:
Site ID: 606872
Operable Unit ID: 1354032
Operable Unit: 01
Material ID: 2365079
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported

BH392 **RESIDENCE** **NY LTANKS** **S109829705**
SSE **27 SMITH AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.471 mi.
2489 ft. **Site 1 of 2 in cluster BH**

Relative: **Higher**
Actual: **265 ft.**

LTANKS:
Name: RESIDENCE
Address: 27 SMITH AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0906385 / 2010-12-21
Facility ID: 0906385
Site ID: 418719
Spill Date: 2009-09-02
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: TDGHIOSA
Referred To: Not reported
Reported to Dept: 2009-09-02
CID: Not reported
Water Affected: Not reported
Spill Notifier: Other
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2009-09-02
Spill Record Last Update: 2010-12-21
Spiller Name: KATHY MORGAN
Spiller Company: MILLS
Spiller Address: 27 SMITH AVE
Spiller County: 999
Spiller Contact: KATHY MORGAN
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 3

RESIDENCE (Continued) **S109829705**

DER Facility ID:	367817
DEC Memo:	"9/2/09 Tank is probably going to be removed, test was done for a prospective buyer...mm 12/10/09 Northeast Environmental has removed the tank and has reported a spill. The home owner's insurance has hired an environmental consultant, ECC to delineate the soil contamination by performing a Geo Probe survey. Survey expected to be performed during the week of Dec 14. Further work will be completed pending the results of the boring program. Contact at ECC is Cheryl Senczakiewicz 973-989-8010 x34. TG 04/27/10 NE replaced tank and disposed the old tank but didn't get the remediation work. Let message with Cheryl Senczakiewicz asking about remediation work. TG 10/2010 Closure Report submitted by ECC Horizon. Report documents the removal of the tank by Northeast Environmental and the subsequent impacted soil removal (42.17) tons by EnviroStar Contracting. NFA required. TG"
Remarks:	"Reporting tank test failure; no actual known spill at this time. 1000 gallon tank, underground."

All Materials:

Site ID:	418719
Operable Unit ID:	1174884
Operable Unit:	01
Material ID:	2167272
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

393
ENE
1/4-1/2
0.474 mi.
2502 ft.

CROWN PLAZA HOTEL
66 HALE AVE
WHITE PLAINS, NY 10601

NY LTANKS **S111836460**
N/A

Relative:
Lower

Actual:
168 ft.

LTANKS:

Name:	CROWN PLAZA HOTEL
Address:	66 HALE AVE
City,State,Zip:	WHITE PLAINS, NY 10601
Spill Number/Closed Date:	1105926 / 2020-04-30
Facility ID:	1105926
Site ID:	453595
Spill Date:	2011-08-24
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	C3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2011-08-24
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester

CROWN PLAZA HOTEL (Continued) **S111836460**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	False
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2011-08-24
Spill Record Last Update:	2020-04-30
Spiller Name:	HOTETON SMITH
Spiller Company:	CROWN PLAZA HOTEL
Spiller Address:	66 TALE AVE
Spiller County:	999
Spiller Contact:	HOTETON SMITH
Spiller Phone:	(914) 821-1349
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	408220
DEC Memo:	"8-24-11: V.Mc. call to H.Smith: Left Mess.:Req. Call to Dispt. 8-25-11 Mr Smith called. Will be meeting with NE Env to discuss repair and retest. Advised him to submit documentation to close spill. jc 4/11/12 Tank was repaired by Northeast and retested. It failed again. The tank's owner is contacting Northeast to have the tank removed...mm 4/29/20: Message sent to Northeast requesting status update. jod *Northeast reports this UST was located under the city sidewalk on Paulding Street and was being used for the hotel generator. Dwayne Monaco also states the UST was replaced by Barrier Fuel. jod 4/30/20: I spoke with Wayne Jeffers of Barrier. He confirms his company removed and replaced this UST sometime in 2012 and replacing it with a double wall Stip3. He states the tank was corroded but sound, there was no contamination evident. He was unaware of the open TTF spill number so no report was submitted. Wayne forwarded a photo of the UST taken in 2012, photo will be scanned to DecDocs system at a later date. NFA required at this time. jod"
Remarks:	"tank failure -"

All Materials:

Site ID:	453595
Operable Unit ID:	1203754
Operable Unit:	01
Material ID:	2200483
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BI394 **BART GOLDBERG APT. BLDG** **NY LTANKS** **S100141680**
NE **277 MARTINE AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.479 mi.
2529 ft. **Site 1 of 2 in cluster BI**

Relative:
Higher

Actual:
214 ft.

LTANKS:

Name:	BART GOLDBERG APT. BLDG
Address:	277 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9008032 / 1990-11-08
Facility ID:	9008032
Site ID:	255929
Spill Date:	1990-10-22
Spill Cause:	Tank Test Failure
Spill Source:	Commercial/Industrial
Spill Class:	Not reported
Cleanup Ceased:	1953-06-18
SWIS:	6017
Investigator:	WXWADSWO
Referred To:	Not reported
Reported to Dept:	1990-10-22
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1990-10-30
Spill Record Last Update:	1990-11-20
Spiller Name:	Not reported
Spiller Company:	SAME
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	209602
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was WADSWORTH 11/08/90: TANK PASSED RETEST. 09/27/95: This is additional information about material spilled from the translation of the old spill file: TANK TEST."
Remarks:	"TO E I R PETRO-TITE GROSS LEAK"

All TTF:

Facility ID:	9008032
Spill Number:	9008032
Spill Tank Test:	1537746
Site ID:	255929
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00

BART GOLDBERG APT. BLDG (Continued) **S100141680**

Test Method 2: Unknown
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 255929
Operable Unit ID: 948684
Operable Unit: 01
Material ID: 431865
Material Code: 0002A
Material Name: #4 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: Not reported
Recovered: .00
Oxygenate: Not reported

---

395 WNW 1/4-1/2 0.481 mi. 2542 ft. **BUSINESS** **NY LTANKS** **S105998813**
2-4 WASHINGTON AVE **N/A**
WHITE PLAINS, NY

Relative: Higher

Actual: 266 ft.

LTANKS:
Name: BUSINESS
Address: 2-4 WASHINGTON AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 0300993 / 2003-06-13
Facility ID: 0300993
Site ID: 86277
Spill Date: 2003-04-28
Spill Cause: Tank Test Failure
Spill Source: Commercial/Industrial
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 6017
Investigator: WCHD
Referred To: Westchester Cnty Health Dept
Reported to Dept: 2003-04-28
CID: 252
Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 2003-04-28
Spill Record Last Update: 2003-06-25
Spiller Name: MICHAEL
Spiller Company: BUSINESS
Spiller Address: 2-4 WASHINGTON AVE
Spiller County: 001

BUSINESS (Continued) **S105998813**

Spiller Contact: MICHAEL
Spiller Phone: (914) 674-6437
Spiller Extention: Not reported
DEC Region: 3
DER Facility ID: 79185
DEC Memo: ""
Remarks: "RECOMMEND TO UNCOVER AND RE-TEST"

All TTF:
Facility ID: 0300993
Spill Number: 0300993
Spill Tank Test: 1528312
Site ID: 86277
Tank Number: Not reported
Tank Size: 2000
Material: 0001
EPA UST: Not reported
UST: Not reported
Cause: Not reported
Source: Not reported
Test Method: 03
Test Method 2: Horner EZ Check I or II
Leak Rate: .00
Gross Fail: Not reported
Modified By: Spills
Last Modified Date: Not reported

All Materials:
Site ID: 86277
Operable Unit ID: 869078
Operable Unit: 01
Material ID: 509058
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

396
SSW
1/4-1/2
0.487 mi.
2569 ft.

BADDERS RESIDENCE **NY LTANKS** **S100140324**
14 SOUNDVIEW AVE **NY Spills** **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
284 ft.

LTANKS:
Name: BADDERS RESIDENCE
Address: 14 SOUNDVIEW AVE
City,State,Zip: WHITE PLAINS, NY
Spill Number/Closed Date: 8800187 / 1989-01-09
Facility ID: 8800187
Site ID: 313762
Spill Date: 1988-04-06
Spill Cause: Tank Test Failure
Spill Source: Private Dwelling

BADDERS RESIDENCE (Continued) **S100140324**

Spill Class:	Not reported
Cleanup Ceased:	1989-01-09
SWIS:	6017
Investigator:	jeokesso
Referred To:	Not reported
Reported to Dept:	1988-04-07
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	1989-01-09
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1988-04-28
Spill Record Last Update:	2005-04-02
Spiller Name:	Not reported
Spiller Company:	CHRIS BADDERS
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	252994
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was OKESSON "
Remarks:	"8K -.496GPH, TO EXC REPAIR & RET. UPDATE:4-7-88 CALLED NO ANSWER. J.OK.PBS TO FOLLOW"

All TTF:

Facility ID:	8800187
Spill Number:	8800187
Spill Tank Test:	1533591
Site ID:	313762
Tank Number:	Not reported
Tank Size:	0
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	00
Test Method 2:	Unknown
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	313762
Operable Unit ID:	915811
Operable Unit:	01
Material ID:	462908
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported

BADDERS RESIDENCE (Continued) **S100140324**

Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	IN THE SEWER
Address:	14 SOUNDVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1701551 / 2017-05-23
Facility ID:	1701551
Facility Type:	ER
DER Facility ID:	252994
Site ID:	548618
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	6017
Spill Date:	2017-05-17
Investigator:	TDGHIOSA
Referred To:	Not reported
Reported to Dept:	2017-05-17
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Transformer
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2017-05-17
Spill Record Last Update:	2017-05-23
Spiller Name:	PAUL WALSH
Spiller Company:	CON ED
Spiller Address:	14 SOUNDVIEW AVE
Spiller Company:	999
Contact Name:	DISPATCHER 614
DEC Memo:	"Contacted WP Fire and then spoke to FD Lt. on scene. He reports a transformer exploded and lost 60 gals., most of which entered storm drain. FD has deployed some sorbents to contain. FD did not know if there was any flow in drain or where outlet was. DEC requested FD to determine outfall area by contacting DPW. FD also stated Con Ed was on site and that a cleanup contractor, Clean Harbors, hired by Con Ed was enroute for cleanup. dt NRC# 1178618 05/18/17 Inspected the site. No Con Ed personnel on site but met with White Plains DPW drains supervisor Kevin Cullen who was on site last night during the incident. Kevin said that transformer oil entered the system but was stopped in a manhole on West Post Road near Sterling Ave. All catch basins and manholes were cleaned. During the inspection, Clean Harbors was preparing to remove impacted soil beneath the utility pole. TG 05/23/17 Excerpt from EMIS 258298/9, 5/18/2017 9:08 AM Clean Harbors, using absorbent and safe wash, double washed and rinsed the affected areas of the street, driveway and sidewalk. Clean Harbors

BADDERS RESIDENCE (Continued) **S100140324**

also removed the oily soil and vacuumed 3 catch basins.. Upon customer request, the driveway was double washed and rinsed a third time. The transformer has been replaced. Sample for PCB has been taken. Clean up treated as NONPCB. 6,000 Lbs of oily debris has been generated and will be disposed of at Clean Earth North Jersey. NFA. TG"

Remarks: "Spill to the drain. Fire Department and PD on scene. Con Ed on scene also. Con Ed called Paul Walsh 212-580-8383 stated 102 gallons did spill, unknown amount to the sewer. Clean Harbors is doing the clean up."

All Materials:

Site ID:	548618
Operable Unit ID:	1296749
Operable Unit:	01
Material ID:	2302848
Material Code:	0016A
Material Name:	non PCB oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	102.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported

397
SSE
1/4-1/2
0.487 mi.
2573 ft.

HIRSCHON HOME **NY LTANKS** **S106971907**
14 GRANDVIEW AVE **N/A**
WHITE PLAINS, NY

Relative:
Higher

Actual:
260 ft.

LTANKS:

Name:	HIRSCHON HOME
Address:	14 GRANDVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0502229 / 2005-08-28
Facility ID:	0502229
Site ID:	346546
Spill Date:	2005-05-25
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-05-25
CID:	444
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-05-25
Spill Record Last Update:	2005-08-28

HIRSCHON HOME (Continued) **S106971907**

Spiller Name:	DOUG HIRSCHON
Spiller Company:	HIRSCHON HOME
Spiller Address:	14 GRANDVIEW AVE
Spiller County:	001
Spiller Contact:	DOUG HIRSCHON
Spiller Phone:	(914) 428-2558
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	292806
DEC Memo:	"August 28, 2005: NEW ENGLAND TANK DISPOSED OF LUST AND 197.51 TONS OF CONTAMINATED SOIL. GROUND WATER IMPACTED AND SAMPLED. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"1000 GALLON TANK HAD HOLES :"

All Materials:

Site ID:	346546
Operable Unit ID:	1104315
Operable Unit:	01
Material ID:	584494
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BH398 **RESIDENCE** **NY LTANKS** **S107410606**
SSE **34 SMITH AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.493 mi.
2601 ft. **Site 2 of 2 in cluster BH**

Relative:
Higher

Actual:
268 ft.

LTANKS:

Name:	RESIDENCE
Address:	34 SMITH AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0507545 / 2005-12-03
Facility ID:	0507545
Site ID:	353014
Spill Date:	2005-09-23
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	JBODee
Referred To:	Not reported
Reported to Dept:	2005-09-23
CID:	407
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True

RESIDENCE (Continued) **S107410606**

UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2005-09-26
Spill Record Last Update:	2005-12-03
Spiller Name:	Not reported
Spiller Company:	MILLARD
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	MELANIE MILLARD
Spiller Phone:	(914) 831-5537
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	300314
DEC Memo:	"December 3, 2005: NORTHEAST ENVIRONMENTAL DISPOSED OF LUST AND 5 DRUMS OF CONTAMINATED SOIL. BASED UPON INFORMATION PROVIDED TO DEC, NO FURTHER ACTION IS REQUIRED AT THIS TIME. jod"
Remarks:	"Tank removal, tank size 550 gallons."

All Materials:

Site ID:	353014
Operable Unit ID:	1110484
Operable Unit:	01
Material ID:	2100514
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

---

399 South 1/4-1/2 0.496 mi. 2617 ft. **O'NEILL RESIDENCE** **NY LTANKS** **S110490763**
3 BRYANT AVE **N/A**
WHITE PLAINS, NY

Relative: Higher
Actual: 271 ft.

LTANKS:

Name:	O'NEILL RESIDENCE
Address:	3 BRYANT AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	1004584 / 2011-01-06
Facility ID:	1004584
Site ID:	437863
Spill Date:	2010-07-23
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2010-07-23
CID:	Not reported
Water Affected:	Not reported
Spill Notifier:	Other

O'NEILL RESIDENCE (Continued) **S110490763**

Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2010-07-23
Spill Record Last Update:	2011-01-06
Spiller Name:	TODD O'NEILL
Spiller Company:	HOMEOWNER
Spiller Address:	Not reported
Spiller County:	999
Spiller Contact:	TODD O'NEILL
Spiller Phone:	(914) 837-3673
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	392838
DEC Memo:	"7-23-10: V.Mc. to JEFF SOSINSKI/ECOLOGIC Enviro.: TTF with soil sammple confermation. 7-23-10: V.Mc. to TODD O'NEILL: Mother's house, she passed away. House is for sale, 1928 construction, orig. heated w/cosl, convereted to fuel oil, likely 1950's, UST poss. 50 to 70 years old. State Farm Ins. to be notified, for poss. coverage. Provided J.O'D.& Dispt. contact info for follow up as needed. 1/6/2011: Report from Tank Masters Environmental reviewed and entered into eDocs. Based upon the information provided, no further action is required at this time. jod"
Remarks:	"cleanup pending -"

All Materials:

Site ID:	437863
Operable Unit ID:	1188526
Operable Unit:	01
Material ID:	2183459
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported

BI400 **CEMMEL HOUSE BUILDING** **NY LTANKS S105996852**
NE **300 MARTINE AVE** **NY Spills N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.497 mi.
2623 ft. **Site 2 of 2 in cluster BI**

Relative: **Lower**
Actual: **207 ft.**

LTANKS:

Name:	SPILL NUMBER 0206553
Address:	300 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0206553 / 2002-12-13
Facility ID:	0206553
Site ID:	293177
Spill Date:	2002-09-24
Spill Cause:	Tank Test Failure
Spill Source:	Private Dwelling

CEMMEL HOUSE BUILDING (Continued) **S105996852**

Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	2002-09-24
CID:	211
Water Affected:	Not reported
Spill Notifier:	Tank Tester
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-09-24
Spill Record Last Update:	2003-03-25
Spiller Name:	Not reported
Spiller Company:	JAINE VOGHAN
Spiller Address:	209 GARTH RD
Spiller County:	001
Spiller Contact:	Not reported
Spiller Phone:	Not reported
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	147087
DEC Memo:	""
Remarks:	"gross leak coming from manhole cover - resealing manhole cover and retest"

All TTF:

Facility ID:	0206553
Spill Number:	0206553
Spill Tank Test:	1527492
Site ID:	293177
Tank Number:	1
Tank Size:	10000
Material:	0002
EPA UST:	Not reported
UST:	Not reported
Cause:	Not reported
Source:	Not reported
Test Method:	03
Test Method 2:	Horner EZ Check I or II
Leak Rate:	.00
Gross Fail:	Not reported
Modified By:	Spills
Last Modified Date:	Not reported

All Materials:

Site ID:	293177
Operable Unit ID:	858167
Operable Unit:	01
Material ID:	517155
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum

CEMMEL HOUSE BUILDING (Continued) **S105996852**

Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

SPILLS:

Name:	CEMMEL HOUSE BUILDING
Address:	300 MARTINE AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0311391 / 2004-01-08
Facility ID:	0311391
Facility Type:	ER
DER Facility ID:	147087
Site ID:	174952
DEC Region:	3
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	6017
Spill Date:	2004-01-08
Investigator:	tdghiosa
Referred To:	Not reported
Reported to Dept:	2004-01-08
CID:	402
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	True
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2004-01-08
Spill Record Last Update:	2004-01-13
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	JAMIE BARNABA
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was GHIOSAY 01/08/04: Mechanical failure from a fitting on boiler. Nick Barnaba reported cleanup completed tonight. NFA at this time."
Remarks:	"Crew on scene to clean it up. "

All Materials:

Site ID:	174952
Operable Unit ID:	879016
Operable Unit:	01
Material ID:	500202
Material Code:	0002A
Material Name:	#4 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	40.00
Units:	G
Recovered:	.00

CEMMEL HOUSE BUILDING (Continued) **S105996852**

Oxygenate: Not reported

---

401 North 1/4-1/2 0.497 mi. 2623 ft. **EDGAR** **NY LTANKS** **S103479696**
1 BARKER AVE **N/A**
WHITE PLAINS, NY

Relative: Lower

Actual: 187 ft.

LTANKS:

Name:	EDGAR
Address:	1 BARKER AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	9807932 / 1999-11-19
Facility ID:	9807932
Site ID:	330854
Spill Date:	1998-09-29
Spill Cause:	Tank Failure
Spill Source:	Institutional, Educational, Gov., Other
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	WCHD
Referred To:	Westchester Cnty Health Dept
Reported to Dept:	1998-09-29
CID:	351
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	1998-09-29
Spill Record Last Update:	1999-12-28
Spiller Name:	FRANK UZZO
Spiller Company:	WHITE PLAINS REALTY
Spiller Address:	Not reported
Spiller County:	001
Spiller Contact:	ROB EDGAR
Spiller Phone:	(973) 560-1400
Spiller Extention:	159
DEC Region:	3
DER Facility ID:	266099
DEC Memo:	""
Remarks:	"PBS #3-00999 TANK #001 - NOTIFIER ON SITE FOUND A HOLE IN OIL TANK - NO SOIL CONTAMINATION FOUND AS OF TIME OF THE CALL"

All Materials:

Site ID:	330854
Operable Unit ID:	1069116
Operable Unit:	01
Material ID:	315471
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00

EDGAR (Continued) **S103479696**

Units: G
Recovered: .00
Oxygenate: Not reported

BJ402 **SPILL NUMBER 0200263** **NY LTANKS** **S105995581**
SSE **97 LONGVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.500 mi.
2639 ft. **Site 1 of 2 in cluster BJ**

Relative:
Higher

Actual:
265 ft.

LTANKS:

Name:	SPILL NUMBER 0200263
Address:	97 LONGVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0200263 / 2002-05-13
Facility ID:	0200263
Site ID:	139618
Spill Date:	2002-04-08
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	C4
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-04-08
CID:	281
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-08
Spill Record Last Update:	2002-06-04
Spiller Name:	Not reported
Spiller Company:	MR DOYLE
Spiller Address:	SAME
Spiller County:	001
Spiller Contact:	JENEEN CIANFLONE
Spiller Phone:	(914) 741-5472
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	119281
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE ********ALSO SEE SPILL NUMBER 0200712********** 5/13/02 - NES DISPOSED OF LUST AND 12.10 TONS CONTAMIN. CLOSURE FROM JM ASSOCIATES. NFA"
Remarks:	"TANK FAILURE AT ABOVE LOCATION. TANK HAS BEEN REMOVED AND AREA HAS BEEN EXCAVATED AND SOIL STOCKPILED ON SITE."

All Materials:

Site ID:	139618
Operable Unit ID:	851271
Operable Unit:	01
Material ID:	525263

SPILL NUMBER 0200263 (Continued) **S105995581**

Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

BJ403 **RESIDENTS** **NY LTANKS** **S105995667**
SSE **97 LONVIEW AVE** **N/A**
1/4-1/2 **WHITE PLAINS, NY**
0.500 mi.
2639 ft. **Site 2 of 2 in cluster BJ**

Relative:
Higher

Actual:
265 ft.

LTANKS:

Name:	RESIDENTS
Address:	97 LONVIEW AVE
City,State,Zip:	WHITE PLAINS, NY
Spill Number/Closed Date:	0200712 / 2002-04-22
Facility ID:	0200712
Site ID:	256918
Spill Date:	2002-04-18
Spill Cause:	Tank Failure
Spill Source:	Private Dwelling
Spill Class:	B3
Cleanup Ceased:	Not reported
SWIS:	6017
Investigator:	jbodee
Referred To:	Not reported
Reported to Dept:	2002-04-18
CID:	282
Water Affected:	Not reported
Spill Notifier:	Other
Last Inspection:	Not reported
Recommended Penalty:	False
Meets Standard:	True
UST Involvement:	False
Remediation Phase:	0
Date Entered In Computer:	2002-04-18
Spill Record Last Update:	2002-04-30
Spiller Name:	SAME
Spiller Company:	MR DOYLE
Spiller Address:	97 LONGVIEW AVE
Spiller County:	001
Spiller Contact:	MR DOYLE
Spiller Phone:	(914) 428-9472
Spiller Extention:	Not reported
DEC Region:	3
DER Facility ID:	210384
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'DEE 04/22/2002 DUPLICATE REPORT. THIS SPILL NUMBER CLOSED OUT. SEE SPILL NUMBER 0200263."
Remarks:	"a leaking underground storage tank failed. "

All Materials:

Site ID:	256918

RESIDENTS (Continued) **S105995667**

Operable Unit ID:	851580
Operable Unit:	01
Material ID:	568705
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Count: 4 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
SCARSDALE	S118263554	FORECLOSED - TTF	949 POST RD		NY LTANKS
WHITE PLAINS	1007746007	WHITE PLAINS HOSPITAL MEDICAL CTR	DAVIS AVE & E POST RD	10601	US AIRS
WHITE PLAINS	S108146288	GEDNEY WAY LANDFILL	GEDNEY WAY	10601	NY SHWS, NY HSWDS
WHITE PLAINS	S126023349	MICA PRODUCTS LANDFILL	2238 NY-22		NY SWF/LF

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 3
Telephone 215-814-5418

EPA Region 4
Telephone 404-562-8033

EPA Region 5
Telephone 312-886-6686

EPA Region 10
Telephone 206-553-8665

EPA Region 6
Telephone: 214-655-6659

EPA Region 7
Telephone: 913-551-7247

EPA Region 8
Telephone: 303-312-6774

EPA Region 9
Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Federal Delisted NPL site list

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: N/A
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

Federal CERCLIS list

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 04/03/2019
Date Data Arrived at EDR: 04/05/2019
Date Made Active in Reports: 05/14/2019
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Quarterly

Federal CERCLIS NFRAP site list

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 87

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/18/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/18/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/18/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/18/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 08/06/2020
Date Data Arrived at EDR: 08/21/2020
Date Made Active in Reports: 11/11/2020
Number of Days to Update: 82

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 13

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 87

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Annually

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/01/2020
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/22/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/10/2021
Data Release Frequency: Quarterly

State and tribal leaking storage tank lists

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land

A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 04/15/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

LTANKS: Spills Information Database
Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

State and tribal registered storage tank lists

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 07/21/2020
Date Data Arrived at EDR: 09/03/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 83

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 10/01/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Varies

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 10/24/2005
Next Scheduled EDR Contact: 01/23/2006
Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 02/20/2002
Date Made Active in Reports: 03/22/2002
Number of Days to Update: 30

Source: NYSDEC
Telephone: 518-402-9549
Last EDR Contact: 07/25/2005
Next Scheduled EDR Contact: 10/24/2005
Data Release Frequency: No Update Planned

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 04/03/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/08/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/29/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 84

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/20/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 85

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/14/2020
Date Data Arrived at EDR: 05/26/2020
Date Made Active in Reports: 08/12/2020
Number of Days to Update: 78

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 10/23/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/09/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-9543
Last EDR Contact: 09/23/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

State and tribal institutional control / engineering control registries

ENV RES DECL: Environmental Restrictive Declarations

The Environmental Restrictive Declarations (ERD) listed were recorded in connection with a zoning action against the noted Tax Blocks and Tax Lots, or portion thereof, and are available in the property records on file at the Office of the City Register for Bronx, Kings, New York and Queens counties or at the Richmond County Clerk's office. They contain environmental requirements with respect to hazardous materials, air quality and/or noise in accordance with Section 11-15 of this Resolution.

Date of Government Version: 04/22/2020
Date Data Arrived at EDR: 06/18/2020
Date Made Active in Reports: 09/04/2020
Number of Days to Update: 78

Source: New York City Department of City Planning
Telephone: 212-720-3300
Last EDR Contact: 09/18/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Varies

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 12/16/2019
Date Data Arrived at EDR: 12/16/2019
Date Made Active in Reports: 03/02/2020
Number of Days to Update: 77

Source: NYC Department of City Planning
Telephone: 212-720-3401
Last EDR Contact: 09/18/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Varies

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9553
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 09/16/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

VCP NYC: Voluntary Cleanup Program Listing NYC

New York City voluntary cleanup program sites.

Date of Government Version: 07/24/2020
Date Data Arrived at EDR: 07/24/2020
Date Made Active in Reports: 10/12/2020
Number of Days to Update: 80

Source: New York City Office of Environmental Protection
Telephone: 212-788-8841
Last EDR Contact: 09/11/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9711
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Semi-Annually

State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9764
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Semi-Annually

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a $200 million Environmental Restoration or Brownfields Fund as part of the $1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/01/2020
Date Data Arrived at EDR: 06/02/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 7

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 09/15/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Registered Recycling Facility List

A listing of recycling facilities.

Date of Government Version: 07/01/2020
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/22/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8678
Last EDR Contact: 09/24/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

SWTIRE: Registered Waste Tire Storage & Facility List

A listing of facilities registered to accept waste tires.

Date of Government Version: 02/27/2018
Date Data Arrived at EDR: 04/06/2018
Date Made Active in Reports: 06/08/2018
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8694
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 10/20/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: No Update Planned

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-9622
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/18/2020
Date Data Arrived at EDR: 03/19/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 82

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 11/16/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Quarterly

PFAS: PFAS Contamination Site Location Listing

DEC surveyed select businesses, fire departments, fire training centers, bulk storage facilities, airports, and Department of Defense (DoD) facilities. The responses to the survey have helped to determine if these entities used or stored materials containing PFOA/PFOS including AFFF and dispersants used in Teflon coating operations. The results of this survey will be updated periodically as additional responses are received..

Date of Government Version: 01/16/2019
Date Data Arrived at EDR: 05/08/2019
Date Made Active in Reports: 06/24/2019
Number of Days to Update: 47

Source: Department of Environmental Conservation
Telephone: 518-402-9020
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database
These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/20/2006
Number of Days to Update: 48
Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 10/23/2006
Next Scheduled EDR Contact: 01/22/2007
Data Release Frequency: No Update Planned

Local Land Records

LIENS: Spill Liens Information
Lien information from the Oil Spill Fund.

Date of Government Version: 10/30/2020
Date Data Arrived at EDR: 10/30/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 3
Source: Office of the State Comptroller
Telephone: 518-474-9034
Last EDR Contact: 10/28/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information
A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20
Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System
Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/23/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 86
Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

SPILLS: Spills Information Database
Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 08/11/2020
Date Made Active in Reports: 11/05/2020
Number of Days to Update: 86

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002
Date Data Arrived at EDR: 07/08/2005
Date Made Active in Reports: 07/14/2005
Number of Days to Update: 6

Source: Department of Environmental Conservation
Telephone: 518-402-9549
Last EDR Contact: 07/07/2005
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 02/12/2013
Number of Days to Update: 40

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/18/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: (212) 637-3660
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/13/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 69

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Semi-Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018
Date Data Arrived at EDR: 04/11/2018
Date Made Active in Reports: 11/06/2019
Number of Days to Update: 574

Source: U.S. Geological Survey
Telephone: 888-275-8747
Last EDR Contact: 10/08/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/15/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 80

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88
Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 11/02/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73
Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2016
Date Data Arrived at EDR: 06/17/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 85
Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/18/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 08/14/2020
Date Made Active in Reports: 11/04/2020
Number of Days to Update: 82
Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/20/2020
Date Data Arrived at EDR: 07/21/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 79
Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/19/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20
Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Annually

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 07/24/2020
Date Data Arrived at EDR: 08/03/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 10/14/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 04/27/2020
Date Data Arrived at EDR: 05/06/2020
Date Made Active in Reports: 06/09/2020
Number of Days to Update: 34

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 10/09/2019
Date Data Arrived at EDR: 10/11/2019
Date Made Active in Reports: 12/20/2019
Number of Days to Update: 70

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 10/01/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System
MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/05/2020
Date Data Arrived at EDR: 08/10/2020
Date Made Active in Reports: 10/08/2020
Number of Days to Update: 59

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 01/31/2021
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 12/04/2019
Date Made Active in Reports: 01/15/2020
Number of Days to Update: 42

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 11/30/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 11/30/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 11/06/2021
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

RADINFO: Radiation Information Database
The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/24/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 01/02/2020
Date Data Arrived at EDR: 01/28/2020
Date Made Active in Reports: 04/17/2020
Number of Days to Update: 80

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/27/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2020
Date Data Arrived at EDR: 07/15/2020
Date Made Active in Reports: 07/21/2020
Number of Days to Update: 6

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 10/01/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2017
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 151

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 09/22/2020
Next Scheduled EDR Contact: 01/04/2021
Data Release Frequency: Biennially

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 10/06/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 08/08/2017
Date Data Arrived at EDR: 09/11/2018
Date Made Active in Reports: 09/14/2018
Number of Days to Update: 3

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 11/06/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 08/30/2019
Date Data Arrived at EDR: 11/15/2019
Date Made Active in Reports: 01/28/2020
Number of Days to Update: 74

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 11/20/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 10/28/2020
Date Data Arrived at EDR: 11/05/2020
Date Made Active in Reports: 11/25/2020
Number of Days to Update: 20

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 11/05/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data

A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 08/04/2020
Date Data Arrived at EDR: 08/25/2020
Date Made Active in Reports: 11/18/2020
Number of Days to Update: 85

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 11/23/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Semi-Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 09/10/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 66

Source: DOL, Mine Safety & Health Admi
Telephone: 202-693-9424
Last EDR Contact: 11/24/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: Quarterly

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 05/06/2020
Date Data Arrived at EDR: 05/27/2020
Date Made Active in Reports: 08/13/2020
Number of Days to Update: 78

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 06/22/2020
Date Data Arrived at EDR: 06/22/2020
Date Made Active in Reports: 09/10/2020
Number of Days to Update: 80

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 09/16/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 09/04/2020
Date Data Arrived at EDR: 09/15/2020
Date Made Active in Reports: 11/20/2020
Number of Days to Update: 66

Source: EPA
Telephone: (212) 637-3000
Last EDR Contact: 09/15/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Quarterly

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 07/26/2018
Date Made Active in Reports: 10/05/2018
Number of Days to Update: 71

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 11/17/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/27/2020
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/28/2020
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 10/06/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/17/2020
Number of Days to Update: 77

Source: Department of Defense
Telephone: 703-704-1564
Last EDR Contact: 10/08/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 08/17/2020
Date Data Arrived at EDR: 08/17/2020
Date Made Active in Reports: 10/21/2020
Number of Days to Update: 65

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Quarterly

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 08/14/2019
Date Data Arrived at EDR: 08/14/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 63

Source: Department of Environmental Conservation
Telephone: 518-402-8452
Last EDR Contact: 10/14/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 07/01/2020
Date Data Arrived at EDR: 07/02/2020
Date Made Active in Reports: 09/22/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 09/24/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

DRYCLEANERS: Registered Drycleaners
A listing of all registered drycleaning facilities.

Date of Government Version: 06/08/2020
Date Data Arrived at EDR: 06/12/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 82

Source: Department of Environmental Conservation
Telephone: 518-402-8403
Last EDR Contact: 08/31/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING
The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 02/27/2020
Date Data Arrived at EDR: 03/25/2020
Date Made Active in Reports: 06/10/2020
Number of Days to Update: 77

Source: New York City Department of City Planning
Telephone: 718-595-6658
Last EDR Contact: 09/18/2020
Next Scheduled EDR Contact: 12/28/2020
Data Release Frequency: Semi-Annually

Financial Assurance 1: Financial Assurance Information Listing
Financial assurance information.

Date of Government Version: 06/25/2020
Date Data Arrived at EDR: 06/25/2020
Date Made Active in Reports: 07/22/2020
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8660
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/11/2021
Data Release Frequency: Quarterly

Financial Assurance 2: Financial Assurance Information Listing
A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 06/11/2020
Date Data Arrived at EDR: 06/16/2020
Date Made Active in Reports: 09/02/2020
Number of Days to Update: 78

Source: Department of Environmental Conservation
Telephone: 518-402-8712
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Varies

HSWDS: Hazardous Substance Waste Disposal Site Inventory
The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003
Date Data Arrived at EDR: 10/20/2006
Date Made Active in Reports: 11/30/2006
Number of Days to Update: 41

Source: Department of Environmental Conservation
Telephone: 518-402-9564
Last EDR Contact: 05/26/2009
Next Scheduled EDR Contact: 08/24/2009
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/01/2019
Date Data Arrived at EDR: 04/29/2020
Date Made Active in Reports: 07/10/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/30/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 07/28/2020
Date Data Arrived at EDR: 08/06/2020
Date Made Active in Reports: 10/28/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8233
Last EDR Contact: 10/14/2020
Next Scheduled EDR Contact: 02/01/2021
Data Release Frequency: No Update Planned

VAPOR REOPENED: Vapor Intrusion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 12/01/2018
Date Data Arrived at EDR: 02/13/2019
Date Made Active in Reports: 06/13/2019
Number of Days to Update: 120

Source: Department of Environmenal Conservation
Telephone: 518-402-9814
Last EDR Contact: 11/13/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: Varies

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 08/30/2020
Date Data Arrived at EDR: 09/01/2020
Date Made Active in Reports: 11/23/2020
Number of Days to Update: 83

Source: Department of Environmental Conservation
Telephone: 518-402-8056
Last EDR Contact: 09/01/2020
Next Scheduled EDR Contact: 12/14/2020
Data Release Frequency: Quarterly

COOLING TOWERS: Registered Cooling Towers

This data includes the location of cooling towers registered with New York State. The data is self-reported by owners/property managers of cooling towers in service in New York State. In August 2015, the New York State Department of Health released emergency regulations requiring the owners of cooling towers to register them with New York State.

Date of Government Version: 07/07/2020
Date Data Arrived at EDR: 07/14/2020
Date Made Active in Reports: 09/30/2020
Number of Days to Update: 78

Source: Department of Health
Telephone: 518-402-7650
Last EDR Contact: 10/13/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Varies

NYC LEAD 2: Recent Lead Paint Violations

Pursuant to New York City?s Housing Maintenance Code, the Department of Housing Preservation and Development (HPD) issues violations against conditions in rental dwelling units that have been verified to violate the New York City Housing Maintenance Code (HMC) or the New York State Multiple Dwelling Law (MDL). Violations are issued when an inspection verifies that a violation of the HMC or MDL exists. It is closed when the violation is corrected, as observed/verified by HPD or as certified by the landlord.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 06/02/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 30

Source: New York City Department of Housing Preservation & Development
Telephone: 212-863-8200
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System

Mineral Resources Data System

Date of Government Version: 04/06/2018
Date Data Arrived at EDR: 10/21/2019
Date Made Active in Reports: 10/24/2019
Number of Days to Update: 3

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/08/2021
Data Release Frequency: Varies

NYC LEAD: Lead-based Paint Testing Results

The results of the inspections for all classrooms serving students under six in applicable buildings. Identifies all classrooms, whether there was observation of peeling paint, and if there was, standard response protocol was followed.

Date of Government Version: 05/28/2020
Date Data Arrived at EDR: 05/29/2020
Date Made Active in Reports: 07/02/2020
Number of Days to Update: 34

Source: New York City Department of Education
Telephone: 212-374-5141
Last EDR Contact: 10/26/2020
Next Scheduled EDR Contact: 02/15/2021
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 07/14/2011
Date Data Arrived at EDR: 08/05/2011
Date Made Active in Reports: 09/29/2011
Number of Days to Update: 55

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Semi-Annually

PCS INACTIVE: Listing of Inactive PCS Permits

An inactive permit is a facility that has shut down or is no longer discharging.

Date of Government Version: 11/05/2014
Date Data Arrived at EDR: 01/06/2015
Date Made Active in Reports: 05/06/2015
Number of Days to Update: 120

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Semi-Annually

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 10/02/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 12/30/2013
Number of Days to Update: 182

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Conservation in New York.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/10/2014
Number of Days to Update: 193

Source: Department of Environmental Conservation
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

AST - CORTLAND: Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

UST - CORTLAND: Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 08/20/2019
Date Data Arrived at EDR: 08/20/2019
Date Made Active in Reports: 10/16/2019
Number of Days to Update: 57

Source: Cortland County Health Department
Telephone: 607-753-5035
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Quarterly

NASSAU COUNTY:

AST - NASSAU: Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35

Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: No Update Planned

AST NCFM: Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

TANKS NASSAU: Registered Tank Database in Nassau County
A listing of facilities in Nassau County with storage tanks.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Department of Health
Telephone: 516-227-9691
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

UST - NASSAU: Registered Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 01/09/2017
Date Data Arrived at EDR: 01/11/2017
Date Made Active in Reports: 02/15/2017
Number of Days to Update: 35
Source: Nassau County Health Department
Telephone: 516-571-3314
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: No Update Planned

UST NCFM: Storage Tank Database
A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011
Date Data Arrived at EDR: 02/23/2011
Date Made Active in Reports: 03/29/2011
Number of Days to Update: 34
Source: Nassau County Office of the Fire Marshal
Telephone: 516-572-1000
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

ROCKLAND COUNTY:

AST - ROCKLAND: Petroleum Bulk Storage Database
A listing of aboveground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: No Update Planned

UST - ROCKLAND: Petroleum Bulk Storage Database
A listing of underground storage tank sites located in Rockland County. Rockland County?s Petroleum Bulk Storage (PBS) program is no longer in service. All related operations/duties are now wholly overseen by the New York State Dept. of Environmental Conservation (NYSDEC).

Date of Government Version: 02/02/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 09/22/2017
Number of Days to Update: 189
Source: Rockland County Health Department
Telephone: 914-364-2605
Last EDR Contact: 11/25/2020
Next Scheduled EDR Contact: 03/15/2021
Data Release Frequency: No Update Planned

SUFFOLK COUNTY:

AST - SUFFOLK: Storage Tank Database
A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63
Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: No Update Planned

TANKS SUFFOLK: Storage Tank Database

This county is not included in the state?s database. These are facilities that have no tank information in the storage tank database.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 02/05/2019
Date Made Active in Reports: 03/08/2019
Number of Days to Update: 31

Source: Department of Health Services
Telephone: 631-854-2516
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: Varies

UST - SUFFOLK: Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 06/28/2018
Date Data Arrived at EDR: 12/06/2018
Date Made Active in Reports: 02/07/2019
Number of Days to Update: 63

Source: Suffolk County Department of Health Services
Telephone: 631-854-2521
Last EDR Contact: 10/22/2020
Next Scheduled EDR Contact: 02/08/2021
Data Release Frequency: No Update Planned

WESTCHESTER COUNTY:

AST - WESTCHESTER: Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 06/09/2020
Date Data Arrived at EDR: 06/09/2020
Date Made Active in Reports: 08/18/2020
Number of Days to Update: 70

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/07/2021
Data Release Frequency: Semi-Annually

UST - WESTCHESTER: Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 06/09/2020
Date Data Arrived at EDR: 06/09/2020
Date Made Active in Reports: 08/18/2020
Number of Days to Update: 70

Source: Westchester County Department of Health
Telephone: 914-813-5161
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/07/2021
Data Release Frequency: Semi-Annually

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 08/10/2020
Date Data Arrived at EDR: 10/20/2020
Date Made Active in Reports: 11/02/2020
Number of Days to Update: 13

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 11/09/2020
Next Scheduled EDR Contact: 02/22/2021
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NJ MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 04/10/2019
Date Made Active in Reports: 05/16/2019
Number of Days to Update: 36

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 10/09/2020
Next Scheduled EDR Contact: 01/18/2021
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/07/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Annually

RI MANIFEST: Manifest information
Hazardous waste manifest information

Date of Government Version: 12/31/2018
Date Data Arrived at EDR: 10/02/2019
Date Made Active in Reports: 12/10/2019
Number of Days to Update: 69

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 11/11/2020
Next Scheduled EDR Contact: 03/01/2021
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data
Hazardous waste manifest information.

Date of Government Version: 10/28/2019
Date Data Arrived at EDR: 10/29/2019
Date Made Active in Reports: 01/09/2020
Number of Days to Update: 72

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 10/08/2020
Next Scheduled EDR Contact: 01/25/2021
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 09/02/2020
Next Scheduled EDR Contact: 12/21/2020
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: Endeavor Business Media
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data
Source: Endeavor Business Media
This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers
Source: Department of Health
Telephone: 212-676-2444

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

WHITE PLAINS - 5 PARCELS
42 EAST POST ROAD
WHITE PLAINS, NY 10601

TARGET PROPERTY COORDINATES

Latitude (North):	41.026718 - 41° 1' 36.18''
Longitude (West):	73.769558 - 73° 46' 10.41''
Universal Tranverse Mercator:	Zone 18
UTM X (Meters):	603444.2
UTM Y (Meters):	4542240.0
Elevation:	211 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	5939761 WHITE PLAINS, NY
Version Date:	2013
Northeast Map:	5641951 GLENVILLE, CT
Version Date:	2012

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).

TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General North

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Target Property Elevation: 211 ft.

Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property	FEMA Source Type
36119C0269F	FEMA FIRM Flood data

Additional Panels in search area:	FEMA Source Type
36119C0266F	FEMA FIRM Flood data
36119C0267F	FEMA FIRM Flood data
36119C0268F	FEMA FIRM Flood data

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property	NWI Electronic Data Coverage
WHITE PLAINS	YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

MAP ID	LOCATION FROM TP	GENERAL DIRECTION GROUNDWATER FLOW
Not Reported		

* ©1996 Site−specific hydrogeological data gathered by CERCLIS Alerts, Inc., Bainbridge Island, WA. All rights reserved. All of the information and opinions presented are those of the cited EPA report(s), which were completed under a Comprehensive Environmental Response Compensation and Liability Information System (CERCLIS) investigation.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT **GEOLOGIC AGE IDENTIFICATION**

Era:	Paleozoic	Category:	Stratified Sequence
System:	Ordovicias		
Series:	Lower Ordovician and Cambrian carbonate rocks		
Code:	OC *(decoded above as Era, System & Series)*		

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 06284645.2r



SITE NAME:	White Plains - 5 Parcels	CLIENT:	Barton & Loguidice, D.P.C.
ADDRESS:	42 East Post Road White Plains NY 10601	CONTACT:	Corinne Steinmuller
		INQUIRY #:	06284645.2r
LAT/LONG:	41.026718 / 73.769558	DATE:	December 01, 2020 12:26 pm

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 2

Soil Component Name: Urban land

Soil Surface Texture:
Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

No Layer Information available.

Soil Map ID: 3

Soil Component Name: Urban land

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class:

Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

Soil Layer Information							
	Boundary			Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil		
1	0 inches	5 inches	variable	Not reported	Not reported	Max: 1.4 Min: 0	Max: Min:

Soil Map ID: 4

Soil Component Name: Urban land

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 0 inches

No Layer Information available.

Soil Map ID: 5

Soil Component Name: Urban land

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

No Layer Information available.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Map ID: 6

Soil Component Name: Urban land

Soil Surface Texture: variable

Hydrologic Group: Not reported

Soil Drainage Class:
Hydric Status: Unknown

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

No Layer Information available.

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	USGS40000837239	0 - 1/8 Mile South
2	USGS40000837246	0 - 1/8 Mile East
3	USGS40000837264	1/8 - 1/4 Mile NNE
4	USGS40000837292	1/4 - 1/2 Mile NNE
5	USGS40000837243	1/4 - 1/2 Mile East
6	USGS40000839114	1/4 - 1/2 Mile NE
7	USGS40000837283	1/4 - 1/2 Mile NE
8	USGS40000837255	1/4 - 1/2 Mile West
9	USGS40000837302	1/4 - 1/2 Mile NNE
10	USGS40000837237	1/4 - 1/2 Mile ESE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
11	USGS40000837244	1/4 - 1/2 Mile West
A12	USGS40000837305	1/4 - 1/2 Mile NNW
A13	USGS40000837306	1/4 - 1/2 Mile NNW
B14	USGS40000837317	1/2 - 1 Mile North
B15	USGS40000837318	1/2 - 1 Mile North
C16	USGS40000837260	1/2 - 1 Mile East
C17	USGS40000837261	1/2 - 1 Mile East
18	USGS40000837356	1/2 - 1 Mile NW
19	USGS40000837368	1/2 - 1 Mile NNE
20	USGS40000837128	1/2 - 1 Mile SSW
21	USGS40000837348	1/2 - 1 Mile NE
22	USGS40000837362	1/2 - 1 Mile NNE

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
No Wells Found		

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	NYOG90000040376	1/2 - 1 Mile NNW
2	NYOG90000040377	1/2 - 1 Mile ENE

PHYSICAL SETTING SOURCE MAP - 06284645.2r



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons
- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells

SITE NAME:	White Plains - 5 Parcels	CLIENT:	Barton & Loguidice, D.P.C.
ADDRESS:	42 East Post Road White Plains NY 10601	CONTACT:	Corinne Steinmuller
		INQUIRY #:	06284645.2r
LAT/LONG:	41.026718 / 73.769558	DATE:	December 01, 2020 12:26 pm

Copyright © 2020 EDR, Inc. © 2015 TomTom Rel. 2015.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

1
South
0 - 1/8 Mile
Higher

FED USGS **USGS40000837239**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 94	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	302	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

2
East
0 - 1/8 Mile
Higher

FED USGS **USGS40000837246**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 95	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	495	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

3
NNE
1/8 - 1/4 Mile
Higher

FED USGS **USGS40000837264**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 96	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	725	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

4
NNE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837292**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 4	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Basement Complex
Aquifer Type:	Not Reported	Construction Date:	1912
Well Depth:	203	Well Depth Units:	ft
Well Hole Depth:	203.1	Well Hole Depth Units:	ft

5
East
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837243**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 305	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	484	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

6
NE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000839114**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 119	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	350	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

7
NE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837283**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 118	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	108	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

8
West
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000837255**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 133	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	500	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

9
NNE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837302**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 161	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	225	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

10
ESE
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837237**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 120	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	200	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

11
West
1/4 - 1/2 Mile
Higher

FED USGS **USGS40000837244**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE1064	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported

Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	508	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

A12
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000837305**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 121	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	310	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

A13
NNW
1/4 - 1/2 Mile
Lower

FED USGS **USGS40000837306**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 123	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	300	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

B14
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000837317**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 87	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	700	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

B15
North
1/2 - 1 Mile
Lower

FED USGS **USGS40000837318**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 88	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	250	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

C16
East
1/2 - 1 Mile
Lower

FED USGS **USGS40000837260**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 200	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	22
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

C17
East
1/2 - 1 Mile
Lower

FED USGS **USGS40000837261**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 220	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Sand and gravel aquifers (glaciated regions)		
Formation Type:	Sand and Gravel	Aquifer Type:	Not Reported
Construction Date:	Not Reported	Well Depth:	40
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

18
NW
1/2 - 1 Mile
Lower

FED USGS **USGS40000837356**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE1379	Type:	Well

Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	Not Reported	Well Depth Units:	Not Reported
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

19
NNE **FED USGS** **USGS40000837368**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 91	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	350	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

20
SSW **FED USGS** **USGS40000837128**
1/2 - 1 Mile
Higher

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 177	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	145	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

---

21
NE **FED USGS** **USGS40000837348**
1/2 - 1 Mile
Lower

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 93	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	250	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation | Database | EDR ID Number

22
NNE
1/2 - 1 Mile
Lower

FED USGS **USGS40000837362**

Organization ID:	USGS-NY	Organization Name:	USGS New York Water Science Center
Monitor Location:	WE 92	Type:	Well
Description:	Not Reported	HUC:	02030102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Not Reported	Formation Type:	Bedrock
Aquifer Type:	Not Reported	Construction Date:	Not Reported
Well Depth:	332	Well Depth Units:	ft
Well Hole Depth:	Not Reported	Well Hole Depth Units:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
NNW **OIL_GAS** **NYOG90000040376**
1/2 - 1 Mile

API Well #:	31119236850000	Well Name:	KCT B-4
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Type:	Stratigraphic
Well Status:	Plugged and Abandoned	Permit Date:	0
Drill Date:	0	Completion Date:	2006 913
Plug Date:	0	Field Name:	Not Applicable
Formation:	Fordham Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	700
True Depth:	560	Measured Length:	560

2
ENE **OIL_GAS** **NYOG90000040377**
1/2 - 1 Mile

API Well #:	31119236860000	Well Name:	KCT B-5
Owner:	New York City Dept. of Environmental Protection		
Operator:	2127	Well Type:	Stratigraphic
Well Status:	Plugged and Abandoned	Permit Date:	0
Drill Date:	0	Completion Date:	2006 921
Plug Date:	0	Field Name:	Not Applicable
Formation:	Yonkers Gneiss	Borehole Slant:	Vertical
State Owned Lease:	NA	Proposed Depth:	700
True Depth:	530	Measured Length:	530

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS
RADON

AREA RADON INFORMATION

State Database: NY Radon

Radon Test Results

County	Town	Num Tests	Avg Result	Geo Mean	Max Result
WESTCHESTER	BEDFORD	108	2.44	1.65	21.7
WESTCHESTER	CORTLANDT	169	5.15	2.22	95.4
WESTCHESTER	EASTCHESTER	76	2.89	1.75	41.9
WESTCHESTER	GREENBURGH	222	2.26	1.46	21.8
WESTCHESTER	HARRISON	69	3.3	2.07	42.3
WESTCHESTER	LEWISBORO	72	3.91	2.61	19.2
WESTCHESTER	MAMARONECK	123	4	2.42	35.9
WESTCHESTER	MT. KISCO	38	2.33	1.72	9.3
WESTCHESTER	MT. PLEASANT	172	2.13	1.43	17.1
WESTCHESTER	MT. VERNON	53	2.82	1.65	32
WESTCHESTER	NEW CASTLE	134	2.2	1.46	31.7
WESTCHESTER	NEW ROCHELLE	127	1.92	1.31	13.8
WESTCHESTER	NO. CASTLE	64	3.49	2.25	16.5
WESTCHESTER	NO. SALEM	56	3.78	2.56	25.7
WESTCHESTER	OSSINING	65	2.08	1.39	10.9
WESTCHESTER	PEEKSKILL	47	3.66	2.34	19.9
WESTCHESTER	PELHAM	26	2.5	1.91	9.1
WESTCHESTER	POUND RIDGE	34	3.37	2.22	18.5
WESTCHESTER	RYE	98	2.24	1.63	9.5
WESTCHESTER	SCARSDALE	138	2.35	1.63	22.4
WESTCHESTER	SOMERS	72	3.89	2.82	21.3
WESTCHESTER	WHITE PLAINS	132	2.76	1.48	65.2
WESTCHESTER	YONKERS	153	2.23	1.37	16
WESTCHESTER	YORKTOWN	181	2.7	1.72	27.2

Federal EPA Radon Zone for WESTCHESTER County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for WESTCHESTER COUNTY, NY

Number of sites tested: 650

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.930 pCi/L	97%	3%	0%
Basement	1.730 pCi/L	84%	13%	2%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)
Source: United States Geologic Survey
EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map
Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands
Source: Department of Environmental Conservation
Telephone: 518-402-8961

HYDROGEOLOGIC INFORMATION

AQUIFLOW^{R} Information System
Source: EDR proprietary database of groundwater flow information
EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit
Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database
Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)
Telephone: 800-672-5559
SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data
Source: EPA/Office of Drinking Water
Telephone: 202-564-3750
Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)
This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

New York Public Water Wells
Source: New York Department of Health
Telephone: 518-458-6731

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database
Source: Department of Environmental Conservation
Telephone: 518-402-8072
These files contain records, in the database, of wells that have been drilled.

RADON

State Database: NY Radon
Source: Department of Health
Telephone: 518-402-7556
Radon Test Results

Area Radon Information
Source: USGS
Telephone: 703-356-4020
The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones
Source: EPA
Telephone: 703-356-4020
Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

PHYSICAL SETTING SOURCE RECORDS SEARCHED

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

ATTACHMENT 9
Environmental Professional Qualifications

glesniak@bartonandloguidice.com

Years of Experience
24

Education
M.S., Hydrogeology, University of Toledo, 1995

B.S., Geology, State University of New York College at Brockport, 1992

Professional Registration
Professional Geologist NY & PA

Professional Advancement & Accreditations
OSHA 40-Hour HAZWOPER, and Annual Refresher Courses, 1995 to present
ASTM Risk Based Corrective Action Course, ASTM Environmental Statistics Course
NGWA Low Cost Remediation Techniques Course

Professional Affiliations
National Ground Water Association (NGWA)
NYS American Water Works Association – Hydro fracking Ad-hoc Committee

GREG V. LESNIAK, P.G.

Managing Hydrogeologist

Summary

Mr. Lesniak is a hydrogeologist/environmental project manager with a wide range of skills and experience. His extensive work history conducting Phase I/II ESA includes commercial/industrial sites throughout NYS and the Northeast/Mid-Atlantic regions. He has specialized expertise in groundwater investigations at community water supply wells, hazardous waste sites, and landfills.

His services have included:

- soil/groundwater contaminant investigations
- environmental due diligence services (Phase I/II ESAs)
- hazardous waste screenings, sampling, and remedial plan preparation
- environmental compliance
- groundwater exploration
- water supply resource management - aquifer protection

Relevant Project Experience

Phase I/II Environmental Site Assessments
Mr. Lesniak supervised or directly performed over 240 Phase I/II Environmental Site Assessments using the latest ASTM and all appropriate inquiry (AAI) guidelines. Integrated standard due diligence evaluations with environmental compliance audits at industrial parks, gravel processing facilities, wire plating facilities, asphalt plants, power-plants and Redi-mix plants.

Four Coal-Fired Power Plant Phase I and II ESAs, New York State
Mr. Lesniak performed Phase I ESAs at four power-plants and two ash mono-fill landfills in Upstate New York. The power-plants were in long-term cold storage. Regulatory status of coal residuals (bottom ash, fly ash and unburned coal) was a key issue in determining potential environmental liabilities. Limited Phase II Sampling was conducted to evaluate soil contaminant extent. Mr. Lesniak supervised a multi-year compliance groundwater sampling program to satisfy each of the facility's SPDES Permits.

USEPA Brownfield Assessment Project, City of Auburn, NY
Mr. Lesniak supervised or directly performed Phase II ESAs at four large former industrial properties under an assessment grant awarded to the City of Auburn. Phase II site activities included extensive soil and groundwater sampling, test pit excavation and geophysical scans. Mr. Lesniak is assisting the City with redevelopment plans at two of the facilities and community trail plans at the remaining two facilities. Communication between the USEPA, NYSDEC and the City has been a large component of this successful brownfield project.

The experience to
listen
The power to
solve℠

Barton
&Loguidice

www.bartonandloguidice.com